Available from

GPO Sales Program

Division of Technical Information and Document Control

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

and

National Technical Information Service Springfield, Virginia 22161

Title List of Documents Made Publicly Available

July 1-31, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	2
Domestic Licensing of Production and Utilization Facilities - Docket 50	12
Domestic Licensing of Special Nuclear Material - Docket 70	336
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	351
Nondocketed Items	361
10CFR — Commission Meeting Records	361
ACRS — Advisory Committee on Reactor Safeguards	362
COMMISSION — NRC Commissioners	364
CONTRACT — NRC Contracts and Modifications	367
DISCLOSURE - Financial Disclosure Information	371
FOIA — Freedom of Information Act Requests and Releases	371
GEN TECH IS — Generic Technical Issues	377
I&E — Inspection and Enforcement	377
MISC — Public Document Room Miscellaneous	378
NUREG — NUREG Reports and Related Correspondence	380
ORG — Correspondence with Other Organizations	383
PR — Proposed Rule	384
PRM — Petition for Rulemaking	395
PROJ — Projects - Predocket Licensing	396
PT21 — Noncompliance Reports and Related Correspondence	397
QA999 — Quality Assurance Inspections	397
REGGD — Regulatory Guides	401
RES — Research and Technical Assistance Reports	402
REVIEW GRP — NRC Research Review Groups	404
SECY — Position Papers Before the Commission	405
STATE PROG — State Programs	407
TOPREP - Vendor Reports and Related Correspondence	409
WASTE MGT — Nuclear Waste Management	412
XPORTLIC Export and Import Licenses	413
Personal Author Index	423
Corporate Source Index	459
Report Number Index	493
Cross Reference of Enclosures to Principal Documents	495
Appendix A - Definitions of Docket 50 Categories	513
Appendix B - Definitions of Nondocketed Categories	521

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- II. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q Inspection reports, IE Bulletins and correspondence
- R Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are:


(1)

P. Operating license stage documents & correspondence



7904170015 Forwards info on TMLJM Hendric 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations



- 1 NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO"

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT9 - Public Records

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

(4) "Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.

FIN A-2093. 78/11/30. 26pp. Available at NTIS. (7) (5) (8) (9) (10)

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document

10 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8056	Bronson Methodist Hospital,	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1	45.0400	Kalamazoo, MI	
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	l	40-8102	Exxon Minerals Co. USA, Exxon Corp.	б
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8200	Cleveland Cliffs Iron Co.	б
40-0215	S. F. Appliance, Ltd.	2	40-8304	Wyoming Mining Corp.	6
40-0299	Union Carbide Corp.	2	40-8329	Salem Hospital, Salem, MA	7
40-1162	Western Nuclear, Inc.	3	40-8380	Rocky Mountain Energy Co.	7
40-1341	Edgemont Uranium Mine, TVA, and	3	40-8438	Eastman Kodak Co.	7
	Mines Development, Inc.		40-8452	Bear Creek Uranium Co.	7
40-1852	Fisher Scientific Co.	4	40-8481	Boeing Co.	8
40-2061	West Chicago Facility, Kerr-McGee Corp.	4	40-8502	Irigaray Mine, Wyoming Mining Corp.	8
40-2259	Pathfinder Mines Corp.	4	40-8584	Union 76 Minerals Exploration Co.	9
40-2561	Zircoa Products, Corning Glass Works	4	40-8585	Wyoming Mining Corp.	9
40-2674	Univ. of Notre Dame	4	40-8602	United Nuclear Corp.	9
40-2940	NL Industries, Inc.	4	40-8647	Kerr-McGee Corp.	9
40-3392	Allied Chemical Corp.	· 4	40-8681	Energy Fuels Nuclear, Inc.	10
40-3453	Atlas Minerals	4	40-8693	Ogle Petroleum, Inc.	10
40-4337	Marquette Univ.	5	40-8697	Rocky Mountain Energy Co.	10
40-4492	Federal American Partners (Mining)	5	40-8698	Plateau Resources, Ltd.	10
40-4669	Case Western Reserve Univ.	5	40-8702	Dept. of the Army, Armament Materials Readiness Command	10
40-5021	Standard Oil Co.	5	40.0714		10
40-6622	Pathfinder Mines Corp.	5	40-8714	Cleveland Cliffs Iron Co.	10
40-6659	Petrotomics Co., Getty Oli	5	40-8721	Rocky Mountain Energy Co.	11
40-6789	Howard Univ.	5	40-8727	Kerr-McGee Nuclear Corp.	11
40-7402	Allegheny Ludlum Industries,	6	40-8728	Teton Exploration Drilling Co., Inc.	11
	Chemtron Corp.		40-8745	Ogle Petroleum, Inc.	11
40-7982	Honeywell, Inc.	6	40-8768	Kerr-McGee Nuclear Corp.	12
40-8027	Kerr-McGee Corp.	6	40-8771	Nuclear Assurance Corp.	12
40-8045	Suisman & Blumenthal, Inc.	6	50-2	Univ. of Michigan Research Reactor	12

Docket	Name	Page	Docket	Name	Page
50-3	Indian Point Station, Unit 1	12	50-134	Worcester Polytechnic Institute Research	22
50-5	Pennsylvania State Univ Research Reactor	13	50.125	Reactor	22
50-10	Dresden Nuclear Power Station, Unit 1	13	50-135	Walter Reed Research Reactor	22
50-13	Babcock & Wilcox Co. Critical Facility	16	50-139	Univ. of Washington Research Reactor	22
50-20	Massaschusetts Institute of Technology	16	50-142	UCLA Training Reactor	22
£0.27	Research Reactor	15	50-150	Ohio State Univ Research Reactor	22
50-27	Washington State Univ. Research Reactor	17	50-151	Univ. of Illinois Research Reactor	22
50-29	Yankee-Rowe Nuclear Power Station	17	50-152	Florida West Coast Nuclear Group Inc.	22
50-47	Army Materials Research Reactor	18	50-155	Big Rock Point Nuclear Plant	22
50-54	Union Carbide Research Reactor	18	50-156	Univ. of Wisconsin Research Reactor	25
50-57	State Univ. of New York Research Reactor	18	50-157	Cornell Univ. Research Reactor	25
50-59	Texas A&M Univ. Research Reactor	19	50-160	Georgia Institute of Technology Research Reactor	25
50-62	Univ. of Virginia Research Reactor	19	50-163	General Atomic Co.	25
50-67	McMaster Univ. Research Reactor	19	50-166	Univ. of Maryland Research Reactor	25
50-70	General Electric Test Reactor	19	50-170	National Naval Medical Center	26
50-73	General Electric Nuclear Test Reactor	19	50-171	Peach Bottom Atomic Power Station,	26
50-77	Catholic Univ. of America Research Reactor	20	30-171	Unit I	
50-83	Univ. of Florida Training Reactor	20	50-182	Purdue Univ. Research Reactor	26
50-87	Westinghouse Critical Experiment	20	50-184	National Bureau of Standards Reactor	26
50-89	General Atomic Co.	20	50-186	Univ. of Missouri Research Reactor	26
50-97	Cornell Univ. Zero Power Reactor	20	50-187	Space Radiation Research Reactor	26
50-99	Babcock & Wilcox Test Reactor	20	50-193	Rhode Island & Providence Plantations AEC	26
50-106	Oregon State Univ.	20	50-199	Manhattan College Research Reactor	27
50-111	North Carolina State Univ. Research Reactor	20	50-201	West Valley Reprocessing Plant	27
50-112	Univ. of Oklahoma Research Reactor	20	50-206	San Onofre Nuclear Station, Unit 1	27
50-116	iowa State Univ. Research Reactor	20	50-208	Columbia Univ. Research Reactor	30
50-123	Univ. of Missouri Research Reactor	20	50-213	Haddam Neck Plant	30
50-124	Virginia Polytechnic Institute Training	21	50-219	Oyster Creek Nuclear Power Plant	32
VU 12-7	Reactor	2.	50-220	Nine Mile Point Nuclear Station, Unit 1	35
50-128	Texas A&M Univ. Research Reactor	21	50-223	Univ. of Lowell Research Reactor	36
50-129	West Virginia Univ. Research Reactor	21	50-224	Univ. of California Research Reactor	36
50-133	Humboldt Bay Power Plant, Unit 3	21	50-225	RPI Critical Experiment	36

Docket	Name	Page	Docket	Name	Page
50-228	Acrotest Radiography & Research Reactor	37	50-278	Peach Bottom Atomic Power Station, Unit 3	82
50-236	Lockheed Airciaft Corp.	37	50-280	Surry Power Station, Unit 1	85
50-237	Dresden Nuclear Power Station, Unit 2	37	50-281	Surry Power Station, Unit 2	88
50-243	Oregon State Univ. Research Reactor	39	50-282	Prairie Island Nuclear Station, Unit 1	90
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	39	50-284	Idaho State Univ. Research Reactor	92
50-245	Millstone Nuclear Power Station, Unit 1	41		Fort Calhoun Station, Unit 1	92
50-247	Indian Point Station, Unit 2	43	50-285		
50-249	Dresden Nuclear Power Station, Unit 3	45	50-286	Indian Point Station, Unit 3	94
50-250	Turkey Point Plant, Unit 3	47	50-287	Oconce Nuclear Station, Unit 3	97
50-251	Turkey Point Plant, Unit 4	49	50-288	Reed College Research Reactor	99
50-254	Quad-Cities Station, Unit 1	50	50-289	Three Mile Island Nuclear Station, Unit I	99
50-255	Palisades Nuclear Plant	52	50-293	Pilgrim Nuclear Power Station, Unit I	107
50-259	Browns Ferry Nuclear Power Station,	55	50-294	Michigan State Univ. Research Reactor	109
	Unit 1		50-295	Zion Nuclear Power Station, Unit 1	109
50-260	Browns Ferry Nuclear Power Station, Unit 2	58	50-296	Browns Ferry Nuclear Power Station, Unit 3	112
50-261	H. B. Robinson Plant, Unit 2	60	50-297	North Carolina State Univ PULSTAR Reactor	114
50-263	Monticello Nuclear Generating Plant	61	50-298	Cooper Nuclear Station	114
50-264	Dow Chemical Co.	63	50-301	Point Beach Nuclear Plant, Unit 2	115
50-265	Quad-Cities Station, Unit 2	63	50-302	Crystal River Nuclear Plant, Unit 3	117
50-266	Point Beach Nuclear Plant, Unit 1	65	50-304	Zion Nuclear Power Station, Unit 2	119
50-267	Fort St. Vrain Nuclear Generating Station	67	50-305	Kewaunce Nuclear Power Plant	121
50-268	Midwet Fuel Recovery Plant	68	50-306	Praire Island Nuclear Station, Unit 2	123
50-269	Oconce Nuclear Station, Unit 1	68	50-309	Maine Yankee Atomic Power Plant	125
50-270	Oconee Nuclear Station, Unit 2	70	50-311	Salem Nuclear Generating Station, Unit 2	127
50-271	Vermont Yankee Nuclear Power Station	73		Rancho Seco Nuclear Generating Station	129
50-272	Salem Nuclear Generating Station, Unit 1	75	50-312	Arkansas Nuclear One, Unit 1	131
50-273	Beznau Nuclear Station, Switzerland	77	50-313		
50-274	U. S. Geological Survey Research Reactor	77	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	133
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	77	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	135
50-276	Georgia Tech Research Reactor	79	50-317	Calvert Cliffs Nuclear Power Plant,	136
50-277	Peach Bottom Atomic Power Station, Unit 2	80	•	Unit I	

			D 1.	Name	n
Docket	Name	Page	Docket	Name	Page
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	139	50-361	San Onofre Nuclear Station, Unit 2	215
50-320	Three Mile Island Nuclear Station, Unit 2	141	50-362	San Onofre Nuclear Station, Unit 3	217
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	152	50-363	Forked River Nuclear Station, Unit 1	219
	Shoreham Nuclear Power Station	156	50-364	Joseph M. Farley Nuclear Plant, Unit 2	219
50-322			50-366	Edwin I. Hatch Nuclear Plant, Unit 2	221
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	157	50-367	Bailly Generating Station	225
50-324	Brunswick Steam Electric Plant, Unit 2	159	50-368	Arkansas Nuclear One, Unit 2	226
50-325	Brunswick Steam Electric Plant, Unit 1	161	50-369	William B. McGuire Nuclear Station, Unit 1	228
50-326	Univ. of California at Irvine Research Reactor	163	50-370	William B. McGuire Nuclear Station, Unit 2	230
50-327	Sequoyah Nuclear Plant, Unit 1	163	50-373	LaSalle County Station, Unit 1	232
50-328	Sequoyah Nuclear Plant, Unit 2	169			
50-329	Midland Plant, Unit 1	172	50-374	LaSalle County Station, Unit 2	233
50-330	Midland Plant, Unit 2	174	50-375	Nuclear Examination Reactor	235
50-331	Duane Arnold Energy Center	177	50-376	North Coast Nuclear Plant, Puerto Rico	235
50-332	Barnwell Reprocessing Plant	179	50-378	Caorso Nuclear Station, Italy	235
50-333	James A. Fitzpatrick Nuclear Power Plant	179	50-382	Waterford Generating Station, Unit 3	235
50-334	Beaver Valley Power Station, Unit 1	181	50-387	Susquehanna Steam Electric Station, Unit 1	236
50-335	St. Lucie Plant, Unit 1	183	50-388	Susquehanna Steam Electric Station, Unit 2	239
50-336	Millstone Nuclear Power Station, Unit 2	186	50-389	St. Lucie Plant, Unit 2	241
50-338	North Anna Power Station, Unit 1	188	50-390	Watts Bar Nuclear Plant, Unit 1	242
		_	50-391	Watts Bar Nuclear Plant, Unit 2	243
50-339	North Anna Power Station, Unit 2	191	50-395	Virgil C. Summer Nuclear Station, Unit 1	244
50-340	Scabrook Nuclear Station, Unit 1	196	50-396	Univ. of Virginia Cavalier Reactor	246
50-341	Enrico Fermi Atomic Power Plant, Unit 2	196	50-397	WPPSS Nuclear Project, Unit 2	246
50-344	Trojan Nuclear Plant	197	50-400	Shearon Harris Nuclear Power Plant,	248
50-346	Davis-Besse Nuclear Power Station, Unit 1	201		Unit 1	
	arlev Nuclear Plant, Unit 1	205	50-401	Shearon Harris Nuclear Power Plant, Unit 2	250
	v 1Init 1	206	50-402	Shearon Harris Nuclear Power Plant,	252
	5	208	70 102	Unit 3	
		210	50-403	Shearon Harris Nuclear Power Plant, Unit 4	254
		211	50-404	North Anna Power Station, Unit 3	255
		213	50-405		256
		213	JU-4UJ	North Anna Power Station, Unit 4	230

Docket	Name	Page	Docket	Name	Page
50-406	Tuskegee Institute Research Reactor	256	50-460	WPPSS Nuclear Project, Unit 1	289
50-409	La Crosse Boiling Water Reactor	256	50-461	Clinton Power Station, Unit 1	290
50-410	Nine Mile Point Nuclear Station, Unit 2	258	50-462	Clinton Power Station, Unit 2	291
50-412	Beaver Valley Power Station, Unit 2	259	50-463	Fulton Generating Station, Unit 1	291
50-413	Catawba Nuclear Station, Unit 1	260	50-464	Fulton Generating Station, Unit 2	292
50-414	Catawba Nuclear Station, Unit 2	261	50-466	Allens Creek Nuclear Station, Unit 1	292
50-416	Grand Gulf Nuclear Station, Unit 1	262	50-467	Allens Creek Nuclear Station, Unit 2	294
50-417	Grand Gulf Nuclear Station, Unit 2	264	50-471	Pilgrim Nuclear Power Station, Unit 2	294
50-423	Millstone Nuclear Power Station, Unit 3	267	STN-50-482	Wolf Creek Generating Station	294
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	267	STN-50-483	Calloway Plant, Unit 1	297
50-425	Alvın W. Vogtle Nuclear Plant, Unit 2	268	STN-50-484	Tyrone Energy Park, Unit 1	299
50-433	Univ. of California at Santa Barbara	269	STN-50-485	Sterling Power Project Nuclear, Unit 1	300
0701.60.405	Research Reactor	260	STN-50-486	Calloway Plant, Unit 2	300
STN-50-437	Floating Nuclear Plant	269	STN-50-488	Perkins Nuclear Station, Unit 1	302
50-438	Bellefonte Nuclear Plant, Unit 1	270	STN-50-489	Perkins Nuclear Station, Unit 2	303
50-439	Bellefonte Nuclear Plant, Unit 2	271	STN-50-490	Perkins Nuclear Station, Unit 3	304
50-440	Perry Nuclear Power Plant, Unit 1	272	STN-50-491	Cherokee Nuclear Station, Unit 1	304
50-441	Perry Nuclear Power Plant, Unit 2	273	STN-50-492	Cherokee Nuclear Station, Unit 2	305
50-443	Seabrook Nuclear Station, Unit 1	275	STN-50-493	Cherokee Nuclear Station, Unit 3	305
50-444	Seabrook Nuclear Station, Unit 2	276	50-496	Montague Nuclear Power Station, Unit I	306
50-445	Comanche Peak Steam Electric Station, Unit 1	277	50-497	Montague Nuclear Power Station, Unit 2	306
50-446	Comanche Peak Steam Electric Station,	280	STN-50-498	South Texas Project, Unit 1	306
	Unit 2		STN-50-499	South Texas Project, Unit 2	309
50-448	Douglas Point Nuclear Station, Unit 1	282	50-500	Davis-Besse Nuclear Power Station, Unit 2	312
50-449	Douglas Point Nuclear Station, Unit 2	282	50-501	Davis-Besse Nuclear Power Station, Unit 3	312
50-452	Greenwood Energy Center, Unit 2	283	STN-50-502	Haven Nuclear Plant, Unit !	312
50-453	Greenwood Energy Center, Unit 3	283	STN-50-508	WPPSS Nuclear Project, Unit 3	312
50-454	Byron Station, Unit 1	283	STN-50-509	WPPSS Nuclear Project, Unit 5	313
50-455	Byron Station, Unit 2	284	50-513	WPPSS Nuclear Project, Unit 4	313
50-456	Braidwood Station, Unit 1	285	50-514	Pebble Springs Nuclear Plant, Unit 1	314
50-457	Braidwood Station, Unit 2	287	50-515	Pebble Springs Nuclear Plant, Unit 2	315
50-458	River Bend Station, Unit 1	288	STN-50-516	Jamesport Nuclear Station, Unit 1	315
50-459	River Bend Station, Unit 2	289		-	

Docket	Name	Page	Docket	Name	Page
STN-50-517	Jamesport Nuclear Station, Unit 2	316	50-599	Carroll Facility I	336
STN-50-518	Hartsville Nuclear Plant, Unit 1	316	50-600	Carroli Facility II	336
STN-50-519	Hartsville Nuclear Plant, Unit 2	317	50-754	General Electric Test Reactor	336
STN-50-520	Hartsville Nuclear Plant, Unit 3	318	70-0008	Battelle Columbus Laboratories	336
STN-50-521	Hartsville Nuclear Plant, Unit 4	319	70 0025	Rockwell International Corp.	336
STN-50-522	Skagit Nuclear Power Project, Unit 1	320	70 0027	Babcock & Wilcox Co	337
STN-50-523	Skagit Nuclear Power Project, Unit 2	321	70-0033	Texas Instruments, Inc.	337
STN-50-528	Palo Verde Nuclear Station, Unit 1	321	70-0036	Combustion Engineering, Inc.	338
STN-50-529	Palo Verde Nuclear Station, Unit 2	323	70-0135	Babcock & Wilcox Co.	338
STN-50-530	Palo Verde Nuclear Station, Unit 3	325	70-0143	Nuclear Fuel Services, Inc.	338
50-537	Clinch River Breeder Reactor	326	70-0157	Univ. of Texas	341
50-538	Memphis Station Univ. Research Reactor	327	70-0184	Westinghouse Electric Corp	341
STN-50-546	Marble Hill Nuclear Station, Unit 1	327	70-0203	Univ. of Notre Dame	341
STN-50-547	Marble Hill Nuclear Station, Unit 2	328	70-0364	Parks Township Site, Babcock & Wilcox Co.	341
50-549	Greene County Nuclear Power Plant	330	70-0371	United Nuclear Corp.	342
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	330	70-0398	Dept. of Commerce	342
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	331	70-0474	Upsala College	342
S1 N-50-556	Black Fox Station, Unit !	332	70-0572	Monsanto Research Corp.	342
STN-50-557	Black Fox Station, Unit 2	333	70-0625	Howard Univ.	342
STN-50-561	B-SAR-205	333	70-0687	Union Carbide Corp.	342
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	333	70-0734	General Atomic Co.	343
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	334	70-0754	Vallecitos Nuclear Center,	343
STN-50-568	NEP Nuclear, Unit I	335	15 5.47	General Electric Co.	
STN-50-569	NEP Nuclear, Unit 2	335	70-0820	United Nuclear Corp.	343
STN-50-580	Erie Nuclear Plant, Unit 1	335	70-0824	Babcock & Wilcox Co.	343
STN-50-581	Erie Nuclear Plant, Unit 2	335	70-0925	Cimmaron Facility, Kerr-McGee Corp.	344
50-582	Sundesert, Unit 1	335	70-0971	Oregon State Univ.	344
50-583	Sundesert, Unit 2	335	70-0984	Pacific Northwest Laboratory	344
STN-50-592	Palo Verde Nuclear Station, Unit 4	335	70-0997	Westinghouse Electric Corp.	344
STN-50-593	Palo Verde Nuclear Station, Unit 5	335	70-1062	Todd Shipyards Corp.	344
50-594	Ko-Ri, Units 3 & 4, Korea	335	70-1100	Combustion Engineering, Inc.	344
STN-50-596	New Haven, Unit 1	336	70-1113	General Electric Co.	345
STN-50-597	New Haven, Unit 2	336	70-1143	Westinghouse Electric Corp.	345

Docket	Name	Page	Docket	Name	Page
70-1151	Westinghouse Electric Corp.	346	70-2909	Westinghouse Electric Corp.,	351
70-1177	Davis & Elkıns College	346	70 2010	Power Systems	261
70-1193	Cimarron Facility, Kerr-McGee Corp.	346	70-2910	Tennessee Valley Authority	351
70-1201	UF-6 Conversion Facility, Babock & Wilcox Co.	347	71-0002	Chem-Nuclear Systems, Inc	351
70-1220	General Electric Co.	0.45	71-0005	Magnaflux Corp.	351
		347	71-0017	Rhode Island Atomic Energy Commission	351
70-1252	Edlow International Co.	347	71-0082	Kerr-McGee Nuclear Corp.	351
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	347	71-0109	Union Carbide Corp.	351
70-1278	Public Service of Colorado	348	71-0121	Neutron Products, Inc.	351
70-1308	Morris Operations, General Electric Co.	348	71-0139	Tulsa Gamma Ray, Inc.	352
70-1309	Morris Operations, Sources & Standards,	348	71-0143	Ranchers Exploration & Development Co.	352
	General Electric Co.		71-0170	General Electric Co.	352
70-1319	U.S. Nuclear, Inc.	348	71-0173	Battelle-Pacific Northwest Laboratory	352
70-1333	Metropolitan Edison Co.	348	71-01 7 9	Nuclear Containers, Inc.	352
70-1359	IRT Corp.	349	71-0189	Todd Shipyards Corp	352
70-1489	Goodyear Aerospace Corp.	349	71-0192	Nuclear Packaging, Inc.	352
70-1738	Pacific Gas & Electric Co.	349	71-0221	Allis Chalmers Corp.	352
70-1739	Tri-State Motor Transit Co.	349	71-0249	Nuclear Fuel Services, Inc.	352
70-1869	Radiation Management Corp.	349	71-0251	Westinghouse Electric Corp.	352
70-2000	Mt. Sinai Hospital, Hartford, CT	349	71-0252	Dayton X-Ray Co.	352
70-2153	United Nuclear Corp.	349	71-0271	Ridthalgh, Eggers & Associates	352
70-2175	United Nuclear Corp.	349	71-0346	Public Service Co. of Colorado	352
70-2375	Pacific Gas & Electric Co.	350	71-0368	Branch Radiographic Laboratories	352
70-2478	Transnuclear, Inc.	350	71-0370	Amersham Corp.	352
70-2574	Carlisle Hospital, Carlisle, PA	350	71-0371	Model: NNFD-10, Unified Nuclear Corp.	352
70-2609	Commonwealth Edison Co.	350	71-0381	E,L. Conwell & Co	352
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	350	71-0383	Model: NLI 1/2 LWT Cask,	353
70-2651	Manchester Memorial Hospital, Manchester, CT	350	71-0384	NL Industries, Inc. New England Nuclear Corp.	353
70-2838	Cincinnati Gas & Electric Co.	350	71-0387	Massachusetts Materials Research, Inc.	353
70-2860	South Carolina Electric & Gas Co.	351	71-0389	Univ. of Georgia	353
70-2885	Commonwealth Edison Co.	351	71-0391	Dept. of the Navy	353
70-2902	North Memorial Medical Center, Minneapolis, MN	351	71-0392	Baker Testing Services, Inc.	353

Docket	Name	Page	Docket	Name	Page
71-0393	Allis-Chalmers Corp.	353	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc	356
71-4824	Model: HA-10, Babcock & Wilcox Co.	353	71-671 <i>7</i>	Model. 6717 B	356
71-4888	Model: Sentinel-25A, B, C, C3, D, E, F, Teledyne Energy Systems	353	71-9009	Model: FL 10-1, General Electric Co.	356
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	353	71-9010	Model: NL1-1/2, NL Industries, Inc	356
71-5088	Model: D34710-1, U.S Nuclear, Inc.	353	71-9015	Model. TN-8, Transnuclear, Inc.	356
71-5341	Model: NFP-55, Babcock & Wilcox Co	354	71-9016	Model: TN-9, Transnuclear, Inc	356
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	354	71-9018 71-9019	Model: BU-6, General Electric Co Model: BU-7, General Electric Co.	357 357
71-5607	Model: GE T-2, General Electric Co.	354	71-9022	Model: CE-250-2, Combustion Engineering, Inc	357
71-5768	Model: BB-250-2, Combustion Engineering, Inc.	354	71-9027	Model: 741, Technical Operations, Inc	357
71-5862	Model: Sentinel-100F, Teledyne Energy Systems	354	71-9030	Model: Sentinal-8, 3, & MW-3000, Teledyne Energy Systems	357
71-5926	Model: 100, General Electric Co.	354	71-9032	Model: 650, Technical Operations, Inc	357
71-5942	Model: GE-700, General Electric Co.	354	71-9033	Model: 660 & 660E, Technical	357
71-5957	Model: BMI-i, Dept. of Energy	354	71 0075	Operations, Inc.	357
71-5971	Model: GE-200, General Electric Co.	354	71-9035	Model: 680, Technical Operations, Inc.	357
71-5979	Model: 5979, Alpha-Omega Services, Inc.	354	71-9039	Model: 715, Technical Operations, Inc.	357
71-5980	Model: GE-600, General Electric Co.	355	71-9044	Model: GE-1600, General Electric Co.	357
71-5998	Model: GE-400, General Electric Co.	355	71-9049	Model: GE-500, General Electric Co.	357
71-6078	Model; 927 A1 & C1, Combustion Engineering, Inc.	355	71-9053 71-9070	Model: 683, Technical Operations, Inc. Model: N-55, Dept. of Energy	357 358
71-6144	Model: 6144, Nuclear Engineering Co.	355	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	358
71-6294	Model: UNC-2901, Combustion Engineering, Inc.	355	71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	358
71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	355	71-9094		250
71-6387	Model: 60, Battelle Memorial Institute	355	71-3094	Model: CNSI-14-195-II, Chem-Nuclear Systems, Inc.	358
71-6400	Model: Super Tiger, Westinghouse Flectric Corp.	356	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	358
	Valley	356	71-9108	Model: AL-33-90, Atcor, Inc.	358
		356	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	358
		200	71-9132	Model: T-3, Nuclear Packaging, Inc.	358
		356	71-9136	General Electric Co.	358
	tric Co.	356	71-9139	Model: GE-589, General Electric Co.	358

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Acrotest Radiography & Research	50-228	37	Brunswick Steam Electric Plant, Unit 2	50-324	159
Reactor	£0.466	202	Byron Station, Unit 1	50-454	283
Allens Creek Nuclear Station, Unit 1	50-466	292	Byron Station, Unit 2	50-455	284
Allens Creek Nuclear Station, Unit 2	50-467	294	Calloway Plant, Unit 1	STN-50-483	297
Arkansas Nuclear One, Unit 1	50-313	131	Calloway Plant, Unit 2	STN-50-486	300
Arkansas Nuclear One, Unit 2	50-368	226	Calvert Cliffs Nuclear Power Plant,	50-317	136
Army Materials Research Reactor	50-47	18	Unit 1		
Duane Arnold Energy Center	50-331	177	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	139
B-SAR-205	STN-50-561	333	Caorso Nuclear Station, Italy	50-378	235
Babcock & Wilcox Co. Critical Facility	50-13	16	Carroll Facility I	50-599	336
Babcock & Wilcox Co. Test Reactor	50-99	20		Ž.	336
Bailly Generating Station	50-367	225	Carroll Facility II	50-600	
Barnwell Reprocessing Plant	50-332	179	Catawba Nuclear Station, Unit 1	50-413	260
Beaver Valley Power Station, Unit 1	50-334	181	Catawba Nuclear Station, Unit 2	50-414	261
Beaver Valley Power Station, Unit 2	50-412	259	Catholic Univ. of America Research Reactor	50-77	20
Bellefonte Nuclear Plant, Unit 1	50-438	270	Cherokee Nuclear Station, Unit 1	STN-50-491	304
Bellefonte Nuclear Plant, Unit 2	50-439	271	Cherokee Nuclear Station, Unit 2	STN-50-492	305
Beznau Nuclear Station, Switzerland	50-273	77	Cherokee Nuclear Station, Unit 3	STN-50-493	305
Big Rock Point Nuclear Power Plant	50-155	22	Clinch River Breeder Reactor	50-537	326
Black Fox Station, Unit 1	STN-50-556	332	Clinton Power Station, Unit 1	50-461	290
Black Fox Station, Unit 2	STN-50-557	333	Clinton Power Station, Unit 2	50-462	291
Braidwood Station, Unit 1	50-456	285	Columbia Univ. Research Reactor	50-208	30
Braldwood Station, Unit 2	50-457	287	Comanche Peak Steam Electric Station, Unit 1	50-445	277
Browns Ferry Nuclear Power Station, Unit 1	50-259	55	Comanche Peak Steam Electric Station, Unit 2	50-446	280
Browns Ferry Nuclear Power Station, Unit 2	50-260	58	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	133
Browns Ferry Nuclear Power Station, Unit 3	50-296	112	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	135
Brunswick Steam Electric Plant, Unit 1	50-325	161			

Name	Docket	Page	Name	Docket	Page
Cooper Nuclear Station	50-298	114	General Atomic Co.	50-163	25
Cornell Univ. Research Reactor	50-157	25	General Electric Test Reactor	50-70	19
Cornell Univ. Zero Power Reactor	50-97	20	General Electric Test Reactor	50-754	336
Crystal River Nuclear Plant, Unit 3	50-302	117	General Electric Nuclear Test Reactor	50-73	19
Davis-Besse Nuclear Power Station, Unit 1	50-346	201	Georgia Institute of Technology Research Reactor	50-160	25
Davis-Besse Nuclear Power Station, Unit 2	50-500	312	Georgia Tech Research Reactor	50-276	79
Davis-Besse Nuclear Power Station, Unit 3	50-501	312	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	39
Diablo Canyon Nuclear Power Plant,	50-275	77	Grand Gulf Nuclear Station, Unit 1	50-416	262
Unit 1	20 2.5	*.	Grand Gulf Nuclear Station, Unit 2	50-417	264
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	157	Greene County Nuclear Power Plant	50-549	330
Douglas Point Nuclear Station, Unit 1	50-448	282	Greenwood Energy Center, Unit 2	50-452	283
Douglas Point Nuclear Station, Unit 2	50-449	282	Greenwood Energy Center, Unit 3	50-453	283
Dow Chemical Co.	50-264	63	Haddam Neck Plant	50-213	30
Dresden Nuclear Power Station, Unit 1	50-10	13	Shearon Harris Nuclear Power Plant, Unit 1	50-400	248
Dresden Nuclear Power Station, Unit 2	50-237	37	Shearon Harris Nuclear Power Plant,	50-401	250
Dresden Nuclear Power Station, Unit 3	50-249	45	Unit 2	20	
Eric Nuclear Plant, Unit 1	STN-50-580	335	Shearon Harris Nuclear Power Plant, Unit 3	50-402	252
Erie Nuclear Plant, Unit 2	STN-50-581	335	Shearon Harris Nuclear Power Plant,	50-403	254
Joseph M. Parley Nuclear Plant, Unit 1	50-348	205	Unit 4		
Joseph M. Farley Nuclear Plant, Unit 2	50-364	219	Hartsville Nuclear Plant, Unit 1	STN-50-518	316
Enrico Fermi Atomic Power Plant,	50-341	196	Hartsville Nuclear Plant, Unit 2	STN-50-519	317
Unit 2			Hartsville Nuclear Plant, Unit 3	STN-50-520	318
James A. Fitzpatrick Nuclear Power Plant	50-333	179	Hartsville Nuclear Plant, Unit 4	STN-50-521	319
Floating Nuclear Plant	STN-50-437	269	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	152
Florida West Coast Nuclear Group, Inc.	50-152	22	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	221
Forked River Nuclear Station, Unit 1	50-363	219	Haven Nuclear Plant, Unit 1	STN-50-502	312
Fort Calhoun Station, Unit 1	50-285	92	Hope Creek Nuclear Station, Unit 1	50-354	210
Fort St. Vrain Nuclear Generating	50-267	67	Hope Creek Nuclear Station, Unit 2	50-355	211
Station			Humboldt Bay Power Plant, Unit 3	50-133	21
Fulton Generating Station, Unit 1	50-463	291	Idaho State Univ. Research Reactor	50-284	92
Fulton Generating Station, Unit 2	50-464	292	Indian Point Station, Unit 1	50-3	12
General Atomic Co.	50-89	20	Indian Point Station, Unit 2	50-247	43

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	94	Montague Nuclear Power Station,	59-497	306
Iowa State Univ Research Reactor	50-116	20	Unit 2	50 262	£1
Jamesport Nuclear Station, Unit 1	STN-50-516	315	Monticello Nuclear Generating Plant	50-263	61
Jamesport Nuclear Station, Unit 2	STN-50-517	316	National Bureau of Standards Reactor	50-184	26
Kewaunee Nuclear Power Plant	50-305	121	National Naval Medical Center	50-170	26
Ko-Ri, Units 3 & 4, Korea	50-594	335	NEP Nuclear, Unit 1	S FN-50-568	335
La Crosse Boiling Water Reactor	50-409	256	NEP Nuclear, Unit 2	S TN-50-569	335
LaSalle County Station, Unit 1	50-373	232	New Haven, Unit 1	SIN-50-596	336
LaSalle County Station, Unit 2	50-374	233	New Haven, Unit 2	STN-50-597	3 36
Limerick Generating Station, Unit 1	50-352	206	Nine Mile Point Nuclear Station, Unit 1	50-220	35
Limerick Generating Station, Unit 2	50-353	208	Nine Mile Point Nuclear Station,	50 410	258
Lockheed Aircraft Corp.	50-236	37	Unit 2		
Maine Yankee Atomic Power Plant	50-309	125	North Anna Power Station, Unit I	50-338	188
Manhattan College Research Reactor	50-199	27	North Anna Power Station, Unit 2	50-339	191
Marble Hill Nuclear Station, Unit 1	STN-50-546	327	North Anna Power Station, Unit 3	50-404	255
Marble Hill Nuclear Station, Unit 2	STN-50-547	328	North Anna Power Station, Unit 4	50 405	256
Massachusetts Institute of Technology Research Reactor	50-20	16	North Carolina State Univ. PULSTAR Reactor	50-297	114
William B. McGuire Nuclear Station, Unit 1	50-369	228	North Carolina State Univ. Research Reactor	50-111	20
William B. McGuire Nuclear Station, Unit 2	50-370	230	North Coast Nuclear Plant, Puerto Rico	50-376	235
	30-370		Nuclear Examination Reactor	50-375	235
McMaster Univ. Research Reactor	50-67	19	Oconce Nuclear Station, Unit 1	50-269	68
Memphis State Univ. Research Reactor	50-538	327	Oconee Nuclear Station, Unit 2	50-270	70
Michigan State Univ. Research Reactor	50-294	109	Oconce Nuclear Station, Unit 3	50-287	97
Midland Plant, Unit 1	50-329	172	Ohio State Univ. Research Renctor	50-150	22
Midland Plant, Unit 2	50-330	174	Oregon State Univ	50-106	20
Midwest Fuel Recovery Plant	50-268	68	Oregon State Univ. Research Reactor	50-243	39
Millstone Nuclear Power Station, Unit 1	50-245	41	Oyster Creek Nuclear Power Plant	50-219	32
Millstone Nuclear Power Station, Unit 2	50-336	186	Palisades Nuclear Plant Palo Verde Nuclear Station, Unit 1	50-255 STN-50-528	52 321
Millstone Nuclear Power Station,	50-423	267	Palo Verde Nuclear Station, Unit 2	S FN-50-529	323
Unit 3 Montague Nuclear Power Station, Unit 1	50-496	306	Palo Verde Nuclear Station, Unit 3 Palo Verde Nuclear Station, Unit 4	STN-50-530 STN-50-592	325 335

Name	Docket	Page	Name	Docket	Page
Palo Verde Nuclear Station, Unit 5	STN-50-593	335	RPI Critical Experiment	50-225	36
Peach Bottom Atomic Power Station, Unit I	50-171	26	Salem Nuclear Generating Station, Unit I	50-272	75
Peach Bottom Atomic Power Station, Unit 2	50-277	80	Salem Nuclear Generating Station, Unit 2	50-311	127
Peach Bottom Atomic Power Station, Unit 3	50-278	82	San Onofre Nuclear Station, Unit I	50-206	27
Pebble Springs Nuclear Plant, Unit 1	50-514	314	San Onofre Nuclear Station, Unit 2	50-361	215
Pebble Springs Nuclear Plant, Unit 2	50-515	315	San Onofre Nuclear Station, Unit 3	50-362	217
Pennsylvania State Univ. Research	50-5	13	Seabrook Nuclear Station, Unit 1	50-340	196
Reactor			Seabrook Nuclear Station, Unit 1	50-443	275
Perkins Nuclear Station, Unit 1	STN-50-488	302	Seabrook Nuclear Station, Unit 2	50-444	276
Perkins Nuclear Station, Unit 2	STN-50-489	303	Sequoyalı Nuclear Plant, Unit 1	50-327	163
Perkins Nuclear Station, Unit 3	STN-50-490	304	Sequoyalı Nuclear Plant, Unit 2	50-328	169
Perry Nuclear Power Plant, Unit 1	50-440	272	Shoreham Nuclear Power Station	50-322	156
Perry Nuclear Power Plant, Unit 2	50-441	273	Skagit Nuclear Power Project, Unit 1	STN-50-522 ·	320
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	330	Skagit Nuclear Power Project, Unit 2	STN-50-523	321
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	331	South Texas Project, Unit 1	STN-50-498	306
Pilgrim Nuclear Power Station, Unit 1	50-293	107	South Texas Project, Unit 2	STN-50-499	309
Pilgrim Nuclear Power Station, Unit 2	50-471	294	Space Radiation Research Reactor	50-187	26
Point Beach Nuclear Plant, Unit 1	50-266	65	State Univ. of New York Research	50-57	18
Point Beach Nuclear Plant, Unit 2	50-301	115	Reactor		
Prairie Island Nuclear Station, Unit 1	50-282	90	Sterling Power Project, Nuclear, Unit 1	STN-50-485	300
Prairie Island Nuclear Station, Unit 2	50-306	123	St. Lucie Plant, Unit 1	50-335	183
Purdue Umy, Research Reactor	50-182	26	St. Lucie Plant, Unit 2	50-389	241
Quad-Cities Station, Unit 1	50-254	50	Virgil C. Summer Nuclear Station,	50-395	244
Quad-Cities Station, Unit 2	50-265	63	Unit 1		
Rancho Seco Nuclear Generating Station	50-312	129	Sundesert, Unit 1	50-582	335
Reed College Research Reactor	en 100	00	Sundesert, Unit 2	50-583	335
	50-288	99	Surry Power Station, Unit 1	50-280	85
Rhode Island & Providence Plantations AEC	50-193	26	Surry Power Station, Unit 2	50-281 50-387	88
River Bend Station, Unit 1	50-458	288	Susquehanna Steam Electric Station, Unit 1		236
River Bend Station, Unit 2	50-459	289	Susquehanna Steam Electric Station,	50-388	239
H.B. Robinson Plant, Unlt 2	50-261	60	Unit 2		

Name	Docket	Page	Name	Docket	Page
Texas A&M Univ. Research Reactor	50-59	19	U.S Geological Survey Research Reactor	50-274	77
Texas A&M Univ Research Reactor	50-128	21	Vermont Yankee Nuclear Power Station	50-271	73
Three Mile Island Nuclear Station, Unit I	50-289	99	Virginia Polytechnic Institute Training	50-124	21
Three Mile Island Nuclear Station, Unit 2	50-320	141	Reactor	50 424	267
Trojan Nuclear Plant	50-344	197	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	
Turkey Point Plant, Unit 3	50-250	47	Alvin W Vogtle Nuclear Plant, Unit 2	50-425	268
Turkey Point Plant, Unit 4	50-251	49	Walter Reed Research Reactor	50-135	22
Tuskegee Institute Research Reactor	50-406	256	Washington State Univ. Research Reactor	50-27	17
Tyrone Energy Park, Unit 1	STN-50-484	282	Waterford Generating Station, Unit 3	50-382	235
UCLA Training Reactor	50-142	22	Watts Bar Nuclear Plant, Unit 1	50-390	242
Union Carbide Research Reactor	50-54	18	Watts Bar Nuclear Plant, Unit 2	50-391	243
Univ. of California at Irvine	50-326	163	Westinghouse Critical Experiment	50-87	20
Research Reactor	•••		West Valley Reprocessing Plant	50-201	27
Univ of California at Santa Barbara Research Reactor	50-433	269	West Virginia Univ. Research Reactor	50-129	21
Univ. of California Research Reactor	50-224	36	Wolf Creek Generating Station	ST N-50-482	294
	50-83	20	Worcester Polytechnic Institute Research Reactor	50-134	22
Univ. of Florida Training Reactor				50-460	289
Univ. of Illinois LOPRA Research Reactor	50-356	213	WPPSS Nuclear Project, Unit 1		
Univ. of Illinois Research Reactor	50-151	22	WPPSS Nuclear Project, Unit 2	50-397	246
Univ. of Lowell Research Reactor	50-223	36	WPPSS Nuclear Project, Unit 3	STN-50-508	312
Univ. of Maryland Research Reactor	50-166	25	WPPSS Nuclear Project, Unit 4	50-513	313
Univ. of Michigan Research Reactor	50-2	12	WPPSS Nuclear Project, Unit 5	STN-50-509	313
Univ. of Missouri Research Reactor	50-123	20	Yankee-Rowe Nuclear Power Station	50-29	17
Univ. of Missouri Research Reactor	50-186	26	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	333
Univ. of Oklahoma Research Reactor	50-112	20	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	334
Univ. of Virginia Cavalier Reactor	50-396	246	William H. Zimmer Nuclear Station, Unit 1	50-358	213
Univ. of Virginia Research Reactor	50-62	19	Zion Nuclear Power Station, Unit 1	50-295	109
Univ. of Washington Research Reactor	50-139	22	Zion Nuclear Power Station, Unit 2	50-304	119
Univ. of Wisconsin Research Reactor	50-156	25			

		,
		,

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

- 8006110736 Forwards Waste Packaging Insp Rept 80-20 on 800128-0201 of activities under license 19-17039-01 No nancompliance noted SMITH, G H Region 1. Philadelphia. Office of the Director 80/04/24 p
- --B006110739 Waste Packaging Insp Rept 80-20 on 800128-0201 No noncompliance noted Major areas inspected waste shipments & packages, vehicle plackarding, packaging conditions & labels BOOK.HE Region 5. San Francisco, Fuel Facility & Materials Bafety Branch BROWNE.H 9 Advanced Fuel & Spent Fuel Licensing Branch THOMAS.R D Region 5. San Francisco, Office of the Director 60/03/31 10pp
- 8007020202 Requests (posideration of having Atomic Energy Council of Taiwan visit facilities on 800728-30 (at Richland) & 800731-0801 (at Beatty) Council interested in observing waste mpt activities

 LAFLEUR; J D Assistant Director for International Cooperation 80/05/13 App
- 8007140453 Forwards Waste Packaging Insp Repts 15000027/80~31, 15000027/80-3B & 15000027/80-47 on 800319,21 & 0409 SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/21 2pp
- --8007140657 Waste Packaging Insp Rept 15000027/80-31 on 800321 Noncompliance noted bottom of wooden box for solid scrap containing U-236 was pulled away, revealing contents MODK, H E Region 1, Philadelphia, Fuel Facility & Materials Safety Branch THOMAB.R D , RLIDLINGER, B A Region 1, Philadelphia, Office of the Director 80/04/15 3pp
- --B007140663 Wasto Puckaging Insp Rept 19000027/80-38 on 800321
 Noncompliance noted side of wooden box containing solid
 scrap contaminated w/V-238 was pulling away from rest of
 container exposing plastic bag inside box
 BODK.H E. Region 1. Philadelphia. Fuel Facility & Materials Safety
 Branch THUMAS.R D. REIDLINGER, B A. Region 1. Philadelphia.
 Office of the Director 80/04/15 Spp
- --80071406/0 Waste Packaging Insp Rept 15000027/80-47 on 800409
 Noncompliance noted Drum 40.containing depleted U, found
 leaking & transport vehirle not properly placorded as
 radioactive shipment
 BOOK, H C Region 1. Philadolphia, Fuel Facility & Materials Sefety
 Branch THOMAS.R D . ZURAKUMEKI, P R Region 1. Philadelphia.
 Office of the Director 800/04/30 12pp
- B007:70545 Forwards Waste Packaging Insp Rept 18000027/80-46 on 800229 & notice of violation DAVIS.A N Region 3. Chicago. Fuel Facility & Materials Safety Branch B0/06/10 2pp
- --8007170550 Notice of violation from imap on 800227
 * Region 3, Chicago, Office of the Director 80/04/28 ip
- --BO07170536 Waste Packaging Insp Rept 15000027/80-46 on 800229
 Noncompliance noted no placard on shipment boxes
 DCKEN.T. (HOMAS: R D. Region 5, Ban Francisco, Office of the
 Director BOOK.H E Region 5, San Francisco, Fuel Facility &
 Materials Safety Branch GO/04/28 App
- DOCKET 27-039 SHEFF TELD, IL , NUCLEAR ENGINEFRING CO
- 8007070030 Notifies licensee that independent contractor will visit site to obtain info relative to facility
 MARTIN.J B Division of Waste Management 80/06/18 Ip

- 8007070012 Transcript of 800626 prehearing conference in Peoria IL Pe i13-172 Morning session * Atomic Safety and Licensing Board Panel 80/06/26 £0pp
- 8007150058 Submits issues to be litigated in waste disposal site proceeding per ASLB 800626 prehearing conference directive Guestions NRC 790320 order re absence of jurisdiction over entity no langer in possession of radioactive matl CONNER. F B Conner. Moore & Corber 80/07/08 2pp
- 8007230527 Submissions of issues to be litigated in proceeding, in response to ASLB 800626 order Questions illegality of license termination prior to determination of necessity of site maint for health & safety Certificate of Svc encl SCOTY, W.J., SEKULER, S.N. Illinois, State of 80/07/16 Spp
- 8007220149 Submits issues to be litigated in low level radwaste disposal site proceeding in response to ASLB 800626 directive Urges adoption of limbility issue along w/ technical issues H/site stabilization & closure conditions LESSY.R P Antitrust Division 80/07/17 App
- 8007290442 Brief urging dismissal of appeal due to Chicago Section of ANS untimely exceptions to ASLB 790503 order Appeal does not assert discernible injury No EIB required since order does not affect environ W/appearance & Certificates of Svc SCOTT, W J . SEKULER, S N . MURRAY, M J Illinois, State of 80/07/20
- 8007310133 Corrected Page 8 to State of 1L 800721 brief Includes addl wording corrections SEKULER, 8 N 1111nois, State of 80/07/25 2pp

DOCKET 27-047 BARNWELL, BC . CHEM-NUCLEAR SYSTEMS

- 8007010285 Forwards IE Waste Packaging Insp Rept 15000039/80-03 on B00227-27 No noncompliance noted BMITH:0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --B007010271 IE Wasto Packaging Insp Rept 15000039/B0-03 on B00227-29 No noncompliance noted Major areas inspected shipping paper requirements. DDT placarding requirements, radiation levels, removable contamination & external package features PEERV.W W. POTTER, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/18, 7pp
- 8007010277 Forwards IE Wasts Packaging Insp Rept 15000037/80-03 on 800227-27 No noncompliance noted SMITH, O H Region t, Philadelphia, Fuel Facility & Materials Safety Branch. 80/04/24 ip
- --8007010306 IE Waste Packaging Insp Rept 15000039/80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements. radiation levels, removable contamination & external package features PEERY. W W , POTTER, J P Region i. Philadelphia. Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 8007020189 Requests consideration of having Atomic Energy Council of Talwan visit facility on 800901-03 Council Interested in observing waste mag taivities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR.J D Assistant Director for International Cooperation 60/05/13 3pp
- B007020760 Forwards B00527-28 trip rept Chem-Nuclear briefed State of BC & NRC personnel re preliminary site stabilization & closure plan Current conditions & practices at site were observed BO/06/20 App.

- 7290395 Forwards Waste Packaging Insp Rept 15000039/80~21 on 800428 0501
 'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 007290401 Waste Packaging Insp Rept 15000039/80-21 on 800428 & 0501 Noncompliance noted radiation lovels on surface of closed, exclusive use vehicle in excess of regulatory limits TROUP.0 L. PEERY,W W. Region 2. Atlanta, Fuel Facility & Haterials Safety Branch 80/06/20 App
- 7290406 Forwards Waste Packaging Insp Rept 15000039/80~08 on 00803-06 No noncompliance noted TOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety ranch 80/06/20 3pp
- 007270410 Waste Packaging Insp Rept 150000097/B0-08 on B00603-06 No noncompliance noted Major areas inspected compliance ω/DOT & NRC regulations IRDUP, 0 L. MACARTHUR, T C Region 2, Atlanta, Fuel Facility & Materials SePety Branch B0/06/20 &pp
- 7300876 Forwards IE Insp Repts 50-321/80-14 & 50-366/80-14 on 00319-0427 & 30 Enforcement action discussed in NRC 800619 tr /REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/23
- 007300580 IE Insp Repts 50-321/80-14 & 50-366/80-14 on 800319.0429 & 3D Noncompliance noted radiation levels an vehicle cab in excess of regulatory limits STOHR, J P , HOODRUFF, R L Region 2. Atlanta, Fuel Facility & Haberials Safety Branch LACEY, L R Region 2. Atlanta, Office of the Director 80/06/19 8pp
- 7010482 Affidavit re support of request that Chem-Nuclear Sys.Incocument 6D-DP=005, "Process Control Program for CNSI Mobile olidification Units Using Dow Process." be withheld ref 10CFR2 790)
 SYNOLDS.L E Chem-Nuclear Systems, Inc. 80/06/25 3pp
- HET 27-04B RICHLAND, WA . NUCLEAR ENGINEERING CO
- 7100002 Forwards Waste Packaging Insp Rept 15000046/80-04 on 30107-18 No nuncompliance noted 41TH,G H Region 1. Philadelphia. Fuel Facility & Materials Safety ranch. B0/03/24 2pp
- 307100003 Waste Packaging Insp Rept 15000046/80-04 on B00107-18 No noncompliance noted Major areas inspected waste shipments for compliance w/D0T & NRC regulations including vehicle placarding, package marking & condition of packages THOMAS, R D . PECK. C C Region i, Philadelphia, Office of the Director B0DK HE Region 1, Philadelphia, Fuel Facility & Materials Safety Branch B0/03/25 7pp
- 7020202 Requests consideration of having Atomic Energy Council of ituan visit facilities on 800728-30 (at Richland) & 800731-01 (at Beatty) Council interested in observing weste tactivities
 **ALEUR.J D Assistant Director for International Cooperation 7/05/13 4pp
- 7140604 Forwards JE Insp Repts 27-004B/BO-01 & 1500046/79-36 on 10403 No moncompliance noted ITH.6 H Region J. Philadelphia. Fuel Facility & Materials Safety anch B0/05/21 2pp
- 10714060B IE lnsp Rept 27-0048/80-01 on 800403 No noncompliance noted Major areas inspected transportation program ROTH.J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80704/25 5pp
- NO7140609 IE Insp Rept 1500046/79-36 on 800403 No nuncompliance noted Major areas inspected Trailer 68-1832 SODK: HE Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/27 7pp
- /160700 Forwards Waste Packaging Insp Rept 15000046/80-60 on 800515 notice of violation WIS.A B. Region 3. Chicago, Fuel Facility & Materials Safety anch 80/06/27 2pp
- 107160710 Notice of violation from insp on B00515 * Region 5. San Francisco. Office of the Director 80/06/10 ip

- --B007160721 Waste Packaging Insp Rept 15000046/B0-06 on B00515 Noncompliance noted drum containing redwaste found to have gash, exposing cardboard or similar solid mot? BDDK.N E Region 5, San Francisco, Fuel Facility & Materials Safety Dranch THOMAS.R D Region 5, San Francisco, Office of the Director B0/06/10 Spp
- 8007300574 Forwards Whate Packaging Insp Rept 15000046/80-07 on 800131 Notice of violation forwarded under separate cover KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/27
- --8007300565 Waste Packaging Insp Rept 15000046/80-07 on 800131 Noncompliance noted radiation levels on surface of trailer in excess of regulatory limits BOOK.H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch CAIN.C L Region 4. Dallas. Office of the Director 80/02/27 /pp
- 80073i0335 Forwards Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 DAVIS, A B Region 3, Chicago, Fuel Fac)lity & Materials Safety Branch 80/06/30 Jpp
- --8007310339 Waste Fackaging Insp Rept 15000044/80-32 on 800222 & 26 Nancompliance w/DOT regulations noted max dose rate on surface of transport trailor was 220 millirem/h O'REILLY.L A Region 5, San Francisco, Office of the Director THOMAS.R D . BUOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/04/02 12pp
- B007280271 Forwards draft Waste Parkage Insp Repts 15000046/80-76 & 15000046/80-77 on 800623-27 & corresponding NRC-766 forms AVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch B0/07/14 9pp
- 8007220508 Responds to 800626 ltr re possible noncompliance identified during low level radwaste disposal site insp Radwaste container punctured during transport Radioactive mail not released Inspectors briefed re tight container requirements BAERTS Nuclear Engineering Co., lnc., (subs. of Teledyne, Inc.) 00/07/18 ip
- B007270350 PNO-V-BD-060 on B00723. Region 5 ofc was notified that Con Ed low level radwaste shipment was not properly packaged Based upon noncompliance, state of MA has canculted burial permit to banned util from use of site THOMAS.R D Region 3. San Francisco. Office of the Director B0/07/23 1p

DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40-0215 8 F APPLIANCE, LTD
- 8007080036 Responds to IE Bullstin 79-19 re shipment of low level radwaste Encl lists 800208 shipments of 29 55-gollun & 44 55-gollon drums of low level mantle radwaste Further shipments of waste will be placed in sealed steel drums JONESON.B J S F Appliance. Ltd 80/06/16 5pp
- DOCKET 40-0299 UNION CARBIDE CORP
- 8007310494 "Subsurface Investigation Clay Liner Mutl East Gas Hills, WY " RATHBUN.D J Inberg-Miller Engineering Co 80/03/10 85pp
- 8007290221 "Subsurface Investigation Clay Liner Exploration East Hills. WY." for Union Carbide Corp CORCORAN, T Inberg-Miller Engineering Co 80/04/17 42pp
- 8007170571 Forwards design memo & drawings for add1 spray evaporation sys.in compliance w/Consistion 9 of Amend 13 to License EUA-648 Brawings available in Central Files only WONG.T Union Carbido Corp. 80/06/04 5pp
- 80073002/9 Forwards "Field Compaction Test Results," 800609-16 RATHBUN.D J Miller Technical Services 80/06/18 1p
- --8007300285 "Firld Compaction Fest Results," 800609-16
 * Miller Technical Services 80/06/18 23pp
- B007220307 Describes field that of proposed evaporation pond at Fast Oas Hills site Areas inspected include entire crest of proposed dam, toe of cristing overburden spoil pile on which pand is being built const to RC program HANSON W W Barr Engineering Co 80/06/25 2pp

- BOO7220237 FOIA request for three categories of infa re NRC source mat)
 license requirements for Union Carbide, Qas Hills, WY U mill
 facility
 SALZBERO, H Black Hills Alliance 80/06/30 ip
- BOO73002BB Forwards "Field Compaction Test Results," 800617-26 RATHBUN,D J Miller Technical Services 80/06/30 ip
- --8007300287 "Field Compaction Test Results," 800617-26 * Miller Technical Services 80/06/30 19pp
- 6007080219 Bubmits analytical results from samples taken from two releases in restricted areas, to be included as addidata for 800028 ltr WANG, T Union Carbide Corp 80/07/01 in
- GD07140371 Forwards A12-B0-23, "Soil Sample Location Map," as required by Condition 7 of Bource Mati License BUA-648, Amend 15 Map shows location of areas affected by seepage from Sump C Map available in Central Files only WDNQ, T. Union Carbide Corp 80/07/07 1p
- --8007140380 "Soil Sample Location Map," for East Cas Hills area, Natrona JAMES, H E United Nuclear Corp 80/07/03 1p
- 8007220263 Partial response to FOIA request for three categories of JUNEAU203 PARTIAL response to rule request for three categors info re NRC source math license requirements for Union Carbide, Cas Hills, HY U mill facility Forwards documents listed in App A Search for other documents in progress FELTON, J M Division of Rules and Records 80/07/15 2pp.
- --B00722026B Confirms telcon that NRC position re regulation of in situ U extraction in HY remains as stated in JF Ahearne 800422 ltr NRC is prepared to accept HY in situ groundwater protection requirements in NEPA analyses of associated facilities BHAPAR.H X Office of the Executive Legal Director B0/07/07
- ---BOD7R20273 Discusses Governor's 800403 visit to discuss regulation of U milling & mill tailings in WY NRC will not act on license renewal until WY Dept of Environ Quality environ impacts availation results are received & reviewed AHEARNE.J F. Commission 80/04/22 Rpp

DOCKET 40-1142 WESTERN NUCLEAR, INC.

- 8007070099 Discusses 791003 onsite visit to Bplit Rock mill & mine
- 8008240081 Forwards tabulation of water level readings from piezometers in Sections A-A & B-B for 1979 to present Also forwards Drawing RM78-478-E2 showing plots of piezometer water level slevations vs time from Jul 1977 to present BAGBEN, O Western Nuclear, Inc. 80/05/28 2pp
- ---8006240082 "Piezometer Data Bheet " Figure 6-1
 * D'Appolonia Consulting Engineers, Inc. 79/01/15 ip
- 8007010261 Forwards, for review & comment, figure showing proposed location of groundwater monitoring wells Figure is mod to Figure 6 3 of FCB Requests comments by 800611 BCARAND, R A Urantum Recovery Licensing Branch 80/05/30 3pp
- BOO7010559 Forwards, for review & comment, figure showing proposed location of groundwater monitoring wolls Figure is mod to Figure 6 3 of FEB Requests comments by BOQ611
 BCARAND, R A. Uranium Recovery Licensing Branch 80/05/30 3
- ---8007010562 Responds to request for review of FES In order to minimize risk of Addl contamination caused by preferential movement of seepage along unknown high-permeability pathway, intensive monitoring network showed be installed WILLIAMS, R E Affiliation Unknown 80/04/03 5pp
- 8007010569 Discusses review of const rept submitted 800408 Requests add) info re survey results, settlement, piezometer & pond elevation data by 800613 Plan view of site showing final disposal locations for debris required LINEHAN, J J Uranium Recovery Licensing Branch 80/06/02 ip
- . 8007100447 Summary of 800508 meeting in Bethesda, MD re continuing safety review of series of raises to tailings dam QARCIA, P Uranium Recovery Licensing Branch 80/04/02 2pp

- 8007020446 Advises of need to increase amount of Williams-Robinstte contract due to estensive ongoing work frompt attention will be appreciated because of immediate nature of matter BCARAND, R.A. Uranium Recovery Licensing Branch 80/06/04
- B007240021 "Magnetic Survey Western Nuclear Split Ruck Tailings Impoundment.Joffrey City. HY. B00605 " * Williams-Robinotte & Associates. Inc. 80/06/12 17pp
- 8007100088 Summary of 800522 meeting w/Western Nuclear & D'Appolonia Consulting Engineers in Bilver Spring.MD re possible existence of dobris layer underlying tailings embankment & removal of debris from dump area GARCIA.P J Uranium Recovery Licensing Branch 80/06/16 3pp
- --B007100091 Summary of B00522 meeting w/Western Nuclear & D'Appolonia Consulting Engineers in Silver Spring, MD re possible existence of debris layer underlying tailings embankment & removal of debris from dump area LINEMAN, J J Uranium Recovery Liconsing Branch 8000EN.0 Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/05/22
- 8007290262 Forwards rept describing magnetometer survey conducted by NRC consultants at Western Nuclear, Inc Split Rock tailings dam on 800605 W/o encl Uranium Recovery Licensing Branch 80/06/20 lp QARCIA, P J
- BOO7220520 Amend to petition to intervene Paragraphs 6 & 27 re utilization of Sweetwater River waters for educational & recreational purposes & inaccuracy of FEB BOOKE, B L Wyoming Outdoor Council BOOKE, B L Booke, B L
- B007290600 Bubmits comments to monitoring well locations & design per NRC B00404 request Geologic description of Sweetwater River Valley by RE Williams Add 800430 & NRC 800530 ltrs provide considerable impetus & consistency w/previous comments GIEDT.J R Environmental Protection Agency 80/06/25 2pp
- B007220314 Forwards "Rept on Reinterpretation of Ground Magnetometer Burvey Data Western Nuclear Split Rock Tailings Impoundment Jeffrey City, MY " B00EM.O Mestern Nuclear, Inc. (subs of Phelps Dodge Corp.) B0/06/30 2pp
- ---8007220317 "Rept on Reinterpretation of Ground Magnetometer Survey Data Western Nuclear Split Ruck Tailings Impoundment Jeffrey City.WY " * Alian Spector & Associates.Ltd J231 80/06/30 10pp
- B007300358 Order directing appointment of ABLB to rule on WY Outdoor Council intervention & appointment of ABLAB to exercise Commission authority & functions CHILK:B J Office of the Secretary of the Commission 80/07/28
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC
- B007070042 Forwards Revision 4 to decommissioning plan environ rept MILLB.L M Tennessee Valley Authority 80/06/13 5pp
- --8007070045 Revision 4 to decommissioning plan environ rept * Tennessee Valley Authority 80/06/30 131pp
- 8007240099 Amend 3 to Source Matl License SUA-816, changing Condition 16 allowing receipt & storage of U mill tailings & mine waste rock from offsite locations BCARANO,R A Uranium Recovery Licensing Brench 80/06/04 lp
- B007230585 Forwards affigavit certifying that on B006i6 correspondence re Edgemont U mill decommissioning plan environ rept was served on individuals identified in attached list MILLS.L M Tennessee Valley Authority 80/06/23 5pp
- B007210150 Expresses concern re noncompliance w/dose stds for local residents noted in TVA B00613 ltr Objects to TVA request for variance from stds Midwest Environmental Protection Association 60/06/27
- 8007230054 Recommends radiological survey program for U mill tailing activities Grab working level measurements, gamma radiation measurements, radon progony integrating sampling unit & engineering assessment should be implemented EADIE.0 0 Uranium Recovery Licensing Branch 80/07/07 Spp

KET 40-1852 FISHER SCIENTIFIC CO

17290402 IE Insp Findings & Lirensee Ack dtd 800529 of Licenses 9-10211-01 & SMB-0201 Insp Findings on noncompliance noted STEARNS.C F Region i, Philadelphia, Office of the Director 0/05/29 lp

KET 40-2061 WEST CHICAGO FACILITY, KERR-MLGEE CORP

)7110025 Forwards application for amend of License STA-583 HELLEY,W J. Werr-McCoe Corp. 80/05/28 lp

007110027 Application for amend of License STA-593 authorizing installation of incinerator to reduce vol of combustble waste at facility incinerator will be equipped w/NRC-approved effluent cleaning equipment
* Korr-McGen Corp 80/05/28 lipp

7210108 Notifies of new moiling address for West Chicago facility at 98 Factory Street West Chicago II. 60185 ENNY, I L Kerr-HcGee Chemical Corp (subs of Kerr-McGee Corp) 0/06/11 ig

7210480 Summary of 800605 meeting w/Kerr-McGee re decommissioning ontractor performance IXON.W A Uranium Fuel Licensing Branch 80/07/11 3pp

7310271 Summary of 800610 meeting w/vendor in Chicago.IL re waste isposel & site decommissioning IXON.W A Uranium Fuol Licensing Branch E0/0//15 4pp

ET 40-2297 PATHFINDER MINES CORP

7010443 Notifies that mods to leach circuit planned Feed will be langed creating two circuits in parallel each containing a tanks in series Flow rate will remain unchanged No igluificant change to processing procedure represented JGENT.E L Pathfinder Mines Corp 80/06/25 1p

230131 Discusses Amend B to License SUA-672, which would permit BNWL obtain small quantity of tailings solution from mine site support of study re deterioration of clays due to acid tack Recommends approval of amend LLEN.D M . LINEHAN.J J Uranium Recovery Licensing Branch /06/26 p

'230171 Requests that IC conduct const insps of addition to Tailings bankment 4 Const authorized by Amends 5 & 7 to License A-622 Also requests notification of dates on which insp 11 be performed J Kane performed stability review ARANO.R A Uranium Recovery Licensing Branch 80/06/26 4pp

210163 Ack receipt of Permit to Construct BO-13R for addition to itings Reservoir 4 Owner has removed Chen & Associates om project MRCA E Chen & Associates Inc. BO/06/27 1p

CT 40-2561 FIRCUA PRODUCTS, CORNING GLASS WORKS

250343 Responds to IE Bulletin 79-19, "Packaging of Law Level dwasto for Transport & Bursal " Facility is in process of ing out of thoria business No matl sent for bursal since ne 1971.

-CHESKO.C M Corning Glass Works, Zircon Products Div BO/07/15

T 40-2674 NOTRE DAME, UNIV DF

010047 Ack receipt of 600028 ltr informing NRC of steps taken to rect nancompliance identified in 600313 ltr Discusses caused denial of noncompliance Item 10 Gix-month look test required Supporting documentation encl
PLER. J 0 Region 3. Chicago, Office of the Director 60/06/09

)7010960 Requests that provision for possession of Pu-beryllium be removed from Liconse SNM-198 Also requests designation of TJ dirent as course instructor & only person responsible for landling leak testing AY.N R Notre Dame. Univ of 61/12/21 ip

- --8007010067 Requests changes in provisions of License SUD-197 Authorized location of use should be Mechanical Engineering Dept lab on Old Juniper Road Radioactive math plannod for use in graphite moderated subcritical assembly GAY,N R Notre Dame, Univ of 61/12/21 ip
- --8007010077 Forwards response to NRC 800513 Itr re noncompliance identified in 800513 Itr Cor; ective actions personal authorization of tritium for investigator increased to 30 mCi on 770314 Internal correspondence encl MAGON: T J. Notre Dame. Univ. of 80/05/29 23pp
- --8007010083 Application for amend to Item 14 of License 13-01983-08, deleting statements, procedures & representations made in previously submitted documents Internal correspondence encl MADN.T J. Notre Dame: Univ. of 80/05/28 Spp
- --8007010091 Application for renewal of expired Source Matl License CBA-4087, authorizing possession of 1,900 kg natural U metal NEHMAN,M K Notre Dame, Univ of 41/04/10 3pp
- ---8007010097 Requests mod of Liconse Condition 14 permitting film badge of course instructor to provide documented record of possible exposure LUCEY.J W Notre Dame: Univ of 80/05/20 Spp
- B007210550 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations identified in NRC 800609 ltr KEPPLER.J O Region 3, Chicago, Office of the Director 80/07/10 ip
- --8007210358 Responds to NRC 800609 ltr re violation noted in IE Insp of License SUD-197 Corrective actions responsible investigator in charge of source motil advised mati must be wipe-tested before use MASON.T J. Notre Dame, Univ. of 80/04/23 2pp
- --8007210569 Requests amend to License SUD-197 to delete six-month leak testing requirement MASON.T J Notre Dame, Univ of 80/06/23 ip

DUCKET 40-2940 NL INDUSTRIES, INC

- 8007140633 Forwards Waste Packaging Insp Repts 15000027/60-31, 15000027/80-38 & 15000027/80-47 on 800319.21 & 0409 SMITH,0 H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/21 2pp
- ~-8007140657 Waste Packaging Insp Rept 15000027/80-31 on 800321
 Noncompliance noted hottom of wooden box for solid scrap
 containing U-238 was pulled away, revealing contents
 BDDK,H E Regium 1, Philadelphia, Fuel Facility & Materials Safety
 Branch THOMAS,R D , REIDLINGER,D A Region 1, Philadelphia,
 Office of the Director 80/04/15 3pp
- c-8007140663 Waste Packaging Insp Rept 15000027/80-38 on 800321
 Noncompliance noted side of wooden box containing solid
 scrap containated w/V-238 was pulling away from rest of
 container expasing plastic bag inside box
 BODK, H E Region 1. Philadelphia, Fuel Facility & Materials Safety
 Branch THOMAS:R D. REIDLINGER, B.A. Region 1. Philadelphia,
 Office of the Director 80/04/15 Spp
- ~~8007140670 Waste Packaging Insp Rept 15000027/80-47 on 800409 Noncompliance noted Drum 40, containing depleted U, found leaking & transport vehicle not properly placarded as radioactive shipment BODK, H E Region i, Philadelphia, Fuel Facility & Materials Safety Branch THOMAS, R D., ZURAKOWSKI, P R. Region i, Philadelphia, Dffice of the Director 80/04/30 12pp

DOCKET 40-3392 ALLIED CHEMICAL CORP

8007170613 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/06/24

DOCKET 40-9453 ATLAS HINERALS

8007150076 Summary of 800317 meeting w/Atlas Minerals in Bilver Spring. MD re final riprap design & inatallation prior to mill decommissioning GARCIA,P J Uranium Recovery Licensing Branch 80/04/25 3pp B007220291 Confirms recent teleons re various licensing conditions required prior to decommissioning facility Licensee proceeding w/addi talling disposal atternative studies Agreement needed on raising tallings structure SWANBY, G T Atlas Hinerals B0/06/26 1p

DOCKET 40-4337 MARQUETTE UNIV

- 8007250006 Ack receipt of 800606 ltr informing NRC steps taken to correct violations noted in IE insp of Licenses 48-02931-06. 48-02931-16 & 8UD-0231 on 800422 & 0508

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24
- 8007240249 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 48-02931-06, 48-02931-10 & SUD-231 KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/16 to
- --8007240258 Responds to NRC 800624 ltr re violations noted in IE insp of Licenses 48-02931-06 & 48-02931-10 & SUD-231 Provides add1 info re administrative authority licensing, recordseping & purchases PIACBEKID E , MINEN, L E Marquette Univ 80/07/09 3pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

- B007020013 Amends 791114 request for permission to construct & operate major mod & expansion of 950 dry ton per day U ore processing facility Reduces request from 2,950 to 2,000 short tons per day at average ore grade of 0 15% U oxide WRIGHT.K H Federal American Partners 80/04/25 ip
- 8007100084 Advises NRC that KH Wright has resigned from Federal-American Partners, effective 800701 All correspondence should be addrossed to GM Pierson WRIGHT, K H Federal American Partners, 80/06/ii ip
- 8007100087 Responds to NRC request for addl info re "Suppl to Environ Rept Subsurface Tailings Disposal " Date for submittal of addl info cannot be met Geotechnical work programs will require approx 26-27 wks.until approx Dec 1980 HRIGHT, K H Federal American Partners 80/06/il ip
- 8007140693 Submits contract costs incurred & manhours used in reviewing 781109 application Project status rept dtd 800610 encl OARCIA.P J. LINEHAN.J J. Uranium Rocovery Licensing Branch 80/06/13 2pp
- B007020200 Advises that review of mangower expenditures required rereview of 7Bii09 application for Amend 5 to License BUA-667 determined actual fee Refund will be forthcoming Apelogizes for delay MILLER, W O License Fee Management Branch 80/06/18 p
- BOO7210169 Forwards "Proposal Evaluation of Ground Water Impacts. Proposed Subsurface Disposal Project.West Oas Hills.WY " PIERBON.O W Federal American Partners 80/07/01 7pp
- ---8007210170 "Proposal Evaluation of Oround Mater Impacts,Proposed Bubsurface Disposal Project,West Gas Hills,WY " MURDOCK,L T Dames & Moore 80/03/03 lipp
- B007230050 Forwards request for addl info based on review of environ rept & suppl re subsurface tailings disposal Info form for radialogical assocsment & draft reg guide encl W/o info form & draft reg guide
 BCARAND,R A Uranium Recovery Licensing Branch 80/07/03 5pp

DOCKET 40-4669 CABE WESTERN RESERVE UNIV

7910150157 Responds to IE Bullatin 79-19 re packaging & disposal of low level radwaste Ten shipments, containing 4 82 C1 radwaste, were made from Jan 1978-Juna 1979 BOXICH.T A Case Wastern 79/09/26 2pp 8007030099 Forwards 790926 response to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial." in response to NRC request BOZICH, T A Case Western 80/06/12 1p

DOCKET 40-5021 STANDARD DIL CO

- 800709013) Provides annual rept on transfer of products containing exempt concentrations of hyproduct mail for License SMD-785 & License 12-13837-01 No transfers made Jul 1979-June 1980 BANAS.E M Standard Oil Cv of Indiana (see also AMDCO) 80/07/01
- DOCKET 40-6622 PATHFINDER MINES CORP
- 8007180131 Amend 1 to License 8UA-442, revising License Condition 28 to reduce amount of required cover for Dam 5 chimney drain from 5 ft to if t to approve gradation range of 1 ft of cover math All ether license conditions will remain same 8C/06/04 App
- 8007230576 Tabulates centract costs incurred & manhours used in revisuing 781227 license application PERSON.L. LINEHAN.J J Uranium Recovery Licensing Branch 80707703 2pp
- 8007280277 Informs of partial refund of fee accompanying 781120 application for Amend 1 to License SUA-0442 MILLER.W O License Fee Management Branch 80/07/16 ip

DOCKET 40-6659 PETROTOMICS CO . GETTY OIL

- 8007230020 Requests amend to Condition 16 of Licenso SUA-551 to read "mill taxings shell not be transferred from site w/o specific prior approval from NRC " Amend required to carry out research proglam on tailings mgt & reciamation PFAFF, B J Petrotomics, Inc 80/06/11 ip
- B007i40593 Requests roview of onel suppl info to licensee embankment final const rept Forwarde 800401 IE insp rept of completed tailings dam raise, authorized by Amends 1-5 to License BUA-551 M/o encls LINLHAN, J. Uranium Recovery Licensing Branch 80/06/13 ip
- 8007230193 Discussos proposed amend of License SUA-591 to upgrade efficient & environ monitoring program & to incorporate two minor revisions into radiation safety program Revisions will improve program Recommends approval of license amend ROTSCH.J.L. LINCHAN,J.J. Uransum Recovery Licensing Branch 80/06/20 App
- 8007310543 Amend 6 to License SUA-551 modifying effluent & environ monitoring proyram & revising radiation safety program Revised environ monitoring program encl BCARAND R A Uranium Recovery Licensing Branch 80/06/20 Spp
- 8007230245 Advises that Amend 6 for License SUA-551 was issued on 800620 & should be exempt from fees Amend was NRC-initiated & requires med of effluent & environ manitoring program ROTECH. J. L. LINEHAN, J. J. Uranium Recovery Licensing Dranch 80/07/10 1p
- B007300269 Amend 7 to License SUA-591 authorizing transfer of tailings samples & extending completion dates for new tailings impoundment menitor Woils RTH 1,2 & 3 from 800714 to 31 KOTSCH.J L., LINEHAN.J J Uranium Recovery Licensing Branch 80707714 2pp

DOCKET 40-6789 HOWARD UNIV

- 8007010180 Ack receipt of 800425 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 30-11063/80-01.
 30-01321/80-01.40-6789/80-01 & 70-0625/80-01
 9M17H, QH Region i, Philadelphia, Fuol Facility & Materials Safety Branch 80/05/28 ip
- --8007010185 Responds to NRC 800328 1tr re violations noted in IF Insp Repts 30-11063/80-01.30-01321/80-01.40-6789/80-01 & 70-0625/80-01 Corrective actions effluent concentrations evaluated & CF-252 source tested ALEXIS.C P Howard Univ 80/04/25 Spp

7010197 Discusses IE Insp Repts 30-1106J/80 01.30-01321/80-01. 0-6789/80-01 & 70-0625/80-01 on 800320-21 & forwards notice f violation

n Region 1, Philadelphia, Fuel Pacility & Materials th 80/03/28 2pp afety Branch

17010209 Notice of violation from insp on 800320-21 Noncompliance ated failure to conduct required surveys, CF-252 source tailed in unlocked roum & food stored in refrigerator w/

adioisotopes
Region 1, Philadelphia, Office of the Director 80/03/20 2pp

'T 40-7402 ALLEGHENY LUDLOM INDUSTRIES: CHENTRON CORP

40178 Regussts confirmation of planned actions discussed in 800623 our se requests confirmation or planned actions discuss con se redisactive matts disposed at McGlenn: Disposed p in Newburgh Heights.ON Tence will be repaired by 1825, patrol established & source of matt investigated PLEM.J G Region 3. Chicago, Office of the Director 80/06/25

30100 Confirms 800703 telean re McGean Disposal Dump in Newburg ohts. OH Requests extension to complete assessment of

ES.R S Chemtron Curp 80/07/03 lp

T 40-7902 HONEYHELL, INC

60700 Furwards Waste Packaging Insp Rept 15000046/80-60 on 800519 ottice of violation

19. A B Region G. Chicago, fuel facility & Materials Safety
ach 80/06/27 2pp

7160710 Notice of violation from insp on 600515 Region 5. Gas Francisco. Office of the Director B0/06/10 ip

7160721 Waste Packaging Insp Rept 17000046/80-06 on 800515 encompliance noted from containing radwaste found to have ash exposing careboard or similar sulid matl DOK.H.C. Region 5. San Francisco, Fuel Facility & Naterials afety Branch THOMAS.R.D. Region 5. San Francisco. Office of the irector 00/06/10 Spp

T 40-8027 KERR-MCLUE CORP.

10607 Enruerds remainder of license fee in resonate to NRC 800602 informing that request for amond to License GUB-1010 to mit disposal of reffinate sludge in below grade pit has i classified as major amend LiEY:H J Korr-McGeo Nuclear Corp 80/06/10

7010688 Application for amend to License 30B-1010 to permit isosal of raffinate sludge in below grade pit HELLEY.H J. Kerr-McOee Nuclear Cosp. 60/05/22 Lp.

7010bi5 Environ ropt for Dequoyah facility raffinate sludge laposal Three oversize drawings encl Kerr-AcOse Nuclear Corp 90/05/22 60pp

00117 Amend 11 to Source Matt License SUB-1010 authorizing use of ium-treated neutralized solvent extraction raffinate for tilizer on licensee-word property per 800129 application 00403 ltr.sub; lo NRC requirements E.R O Uranium Fuel Licensing Branch 80/05/17 2pp

50634 Ferwards proposal for continued monitoring in vicinity of upgah effluent outfall in accordance w/Condition is of ense 8UB-1010

LLLY.N J Kerr-McGeo Nuclear Corp BO/06/17 7pp

10320 Lists contract costs incurred & manhours expended in testing license amend application UNLW Λ . Uranium Recovery Licensing Branch -80/07/23 . Ip

. 40-8045 SUISMAN & BLUMENTHAL, INC.

10872 Discusses IE Insp Rept 40-8049/80-01 conducted on 800A16 No compliance moted Major areas inspected radiation safety, plance w/NRC rules/regulations & conditions of license corrective action on previous item NEMAN.J D Region 1. Philadelphia, Fuel Facility & Materials etg Branch 80/07/14 1p

DECKET 40-8056 BRONSON METHODIST HOSP KALAMAZOO, MI

8007080273 Forwards personnel monitoring rept for 1979 per (OCFR20 requirements BIMONS,C S Bronson Methodist Hosp Kalamazon,MI B0/06/27

--8007080278 Personnel monitoring rept for 1979 SIMDNS,C S Uronson Nethodist Hosp Kalamazoo,M1 80/06/27 ip

DOCKET 40-BLOR EXXON MINERALS CO. USA, EXXON CORP.

8007030332 Forwards Exxon commercial scale in situ amend application & related matl in response to NRC request
MATHISEN:R & Wyoming, State of 80/06/04 10pp

80071/0A79 Discusses proposed monitor wells for Area MB re application for Hining Permit 2:8C for solution mining at facility Brilling will bogin in June so that 2: wells can be completed & sampled during summer Location maps encl TRUSSCLL.H H Exxon Minerals Co , USA 80/06/13 4pp

8007070105 Forwards requests for add1 hydrologic info identified during review of FES re operation of U mill & U solution mining project LINEIAN, J J Uronium Recovery Licensing Branch 80/06/18 4pp

8007290231 Forwards IE Insp Rept 40-8102/80-01 on 800404-06 & notice of violation n Region 4, Dallas, Fuel Facility & Materials Safety /06/20 2pp DROWN, C D 00/06/50

---8007270237 Notice of violation from insp on 800404-04 * Region 4, Dallas, Office of the Director 80/04

--8007290244 TE Insp Rept 40-8102/80-01 on 800604-06 Nancompliance noted Worker exposed to excess airborne U BRDHN, G D , CAIN, C L Region 4. Dallas, Fuel Facility & Materials Bafety Branch 60/06/20 7pp

BOO7280047 Responds to NRC 800618 request for add1 info ro hydrageologic sys at site Preliminary analysis to Guestions 7-9 & response to Guestions 1-6 will be submitted by 800831 Addl comprehensive studies should be completed by 810930 DRILDFF. 4 D Exxon Minerals Co., USA 80/07/03 ip

DOCKET 40-8200 CLEVELAND-CLIFFB IRON CO

BOD7100DB2 Bummary of H00507 meeting w/Cleveland Cliffs Iron Co in Bilver Spring, MD re status of Licenses SUA-1197 & SUA-1352 & EADIE, 0, 0 Uranium Recovery Licensing Branch 80/06/11 3pp

8007230279 Sepecty evaluation re review of 800529 site final restoration plan Estimated schedule for completing restoration of site appears reasonable Proposed three-phase program shoud be initiated as soon as possible, w/820531 completion date EADIE, 0 0, ROTHFLEISCH.J., MILLER, H.J. Uranium Recovery Licensing Branch 80/07/02 2pp

8007230274 Amend 1 to License SUA-1197 authorizing proposed three-phase site final restoration program Pregram will permit termination of license BCARAND.R A Uranium Recovery Licensing Branch 80/07/07 1p

BOO7290849 Confirms plan to conduct Phase I water sampling at in situ solution mining test sits on 800721 LOUDERBACK, T E Cleveland-Cliffs Iron Co 80/07/14 lp

DOCKET 40-8304 HYOMING MINERAL CORP

8007010367 Advises that Dept of Environ Quality. Land Quality Div has not received showing of compliance w/In Situ Mining Act for 1(censee operations in District 4 Requests status rept remeasures to comply w/mining act MORRIS.D Wyoming. State of 80/06/05 ip

8007220303 Application for renewal of License SUA-1204 authorizing solution mining R&D activities in area Also forwards "Test Site 517 Test 6 i.2 & 3" & "Test Site 517 Test 4 "TIEPEL.E W Wyaming Mineral Corp. 80/07/07 ip

--8007220310 "317 Test Site Tests 1.2 & 3 "
t Wyoming Himeral Corp 78/04/14 is

--8007220319 "517 Test Site Test 4 "
* Wyoming Mineral Corp 78/04/15 1p

DOCKET 40-0327 SALEM HOSP BALCH, MA

8007280224 Notifies of expired License SUC-1215 & discusses actions to be taken by licenses MCCLINTOCK,R O Region 1, Philadeiphia, Office of the Director 80/01/14 2pp

DOCKET 40-8380 ROCKY HOUNTAIN ENERGY CO

8007210243 Bummary of 800313 meeting w/util in Silver Spring, MD to in situ solution mining operations RDTHFLEISCH, J E Uranium Rocovery Licensing Branch 80/04/30 4pp

B007020702 Corrects B00331 application to amend License SUA-1228 Licensee does not intend to use exident w/ca)benate lixiviant Figure 5 has been revised to show reverse asmosis brine stream going directly to evaporation reservoir NEUMANN.M R Rocky Mountain Energy Co B0/05/30 Spp

B007030002 Application for amend to Licenso SUA-1228, containing statements & commitments which supersede any potentially conflicting statements in B00331 amend application State of MY, Dept of Environ Quality Quadeline Number B encl NEUMANN, M R Rocky Mountain Energy Co 80/06/03 27pp

8007210166 Outlines items discussed & commitments made during 800530 mesting re reclamation & land & woter quality review process Requests concurrence on specific agreements NEUMANN.M R Rocky Mountain Energy Co 80/06/03 3pp

8007070115 Responds to 800603 ltr Concurs w/meeting summary w/three exceptions re-monitor Hell M-54.Reno Creek addendum & Pattern IV startup conditional approval WY Dept of Environ Guality 800610 internal memo encl
MORROW,D Wyoming, State of 80/06/10 2pp

BOO7220035 Provides WY Dept of Environ Quality w/results of sample analyses for lime overflow carcuit Reservoir A & B grab samples Requests approved of proposed monitoring program mods & revised discharge stds
NEUMANN, M R Rocky Mountain Energy Co BO/06/12 ilpp

B007030219 Responds to 800613 ltr re preliminary water quality data for Pattern IV Conditional authorization is granted to start Pattern IV panding completion of review of 800030 compliance submittal & receipt of add1 data MORROW,D Wyoming, Statu of 80/06/13 lp

8007170583 Safety evaluation supporting Amend 5 to License SUA-1228
Approval is recommended subj to Stated license conditions
RDTHFLEIBCH, J E. MILLER, H J Uronium Recovery Licensing Branch
BO/06/13 4pp

BD07180086 Amends License 5UA-1226 revising Condition B authorizing use of carbonate/bicarbonate lisiviant in Test Pattern 4
BCARAND, R A Uranium Recovery Licensing Branch 80/06/13 2pp

B007240100 Forwards preliminary water quality data Upper control limits for Well M-54 have been established for pH, bicarbonate, U & vanadium NEUMANN, H R Rocky Hountain Energy Co 80/06/13 3pp

BOO7220022 Forwards application to construct wastowater facility for proposed Reservoir C Corrects vanadium level resorted in BOO612 ltr.Table 2 Assay results for Reservoir B.Monitor Hell PH-3 encl NEUMANN.M R Rocky Mountain Energy Co BO/06/23 App

B007160390 Forwards results of B00505 & 0607 samplings of Pattern III monitor wells No significant change in well status & no change in pattern operation NEUHANNAM R Hacky Mountain Energy Co 80/06/26 5pp

BOO7210224 Clarifies BO0416 review of operations prepared to accompany license renawal request Differences in soils data U values attributable to different sampling & analytical techniques Discussion of Nov 1979 Pattern III excursion entl NEUMANN, M R Rocky Mountain Energy Co 80/06/30 34pp

8007300042 Outlines contract costs incurred & personnel hours expended in reviewing 800303 license application ROTHFLEIBCH, J, BCARANO, R A Uranium Recovery Licensing Branch 80/07/14 ip

DOCKET 40-8438 EASTMAN KODAK CO

8007010266 Application by Kodak for Amend 3 to renew export License (formerly BTB-8274) HARTER, E 8 Eastman Kodak Co 80/06/09 ip

DOCKET 40-8452 BEAR CREEK URANIUM CO

8007240007 Forwards add) info for amend to License SUA-1310 "Tailings Mpt Plan," Bear Croek Tailings Disposal into Mined-Gut Open Pit," & "Leachate Movement from B-3 Pit Tailings Disposal Area," encl MEDLOCK,R L Bear Creek Uranium Co 80/07/01 7App

--B007240011 "Key Plan & Site Plan " * Davy McKee Corp B0/06/30 1

--B007240013 "Pipe Line Haul Road Route - Graded"
* Davy McKee Corp 80/06/30 ip

--8007240022 "Underdrain Sys Plan & Details "
* Davy McKee Corp 80/06/30 lp

--B007240029 "Geological Cross Section A-A',B-3 Nine Area "
Hydrology Associates,Inc 80/07/02 1p

--8007240041 "Geological Cross Section B-D',B-3 Mine Area "
* Hydrology Associates,Inc 80/07/02 1p

--8007240048 "Geological Cross Sections"

* Hydrology Associates, Inc. 80/07/02 ip

8007280073 Submits preliminary questions needing clarification from review of supplemental environ rept re proposed tailings mgt pian Questions may be answered during 790320 site visit More detailed evaluation will be presented SHEPHERD, T A Calorado Stote Univ 79/03/14 3pp

B0072101B3 Discusses licensee revised tailings mgt plan presented during sate visit Revised plan includes extension of existing disposal Addl points require clarification NELSON, J D , SHEPHERD, T A Colorado State Univ 79/03/29 3pp

8007210177 Discusses responses to Rocky Mountain Energy Co questions re project Complete analysis of lung-term stability of proposed plan will be provided upon receipt of data noted in Questions 3 & 5 NELSON, J D Colorado Statu Univ 79/06/01 8pp

8007230135 Discusses review of responses to NRC 790927 questions, 790409 Question 2 ru differential settlement in tailings impoundment & Chen & Associates analysis Estimated differential settlement is acceptable NELSON.J D Colorada State Univ 79/10/05 ip

8007180303 Amend to License BUA-1310 authorizing raise of tailings dam to elevation 5,160 fl above muon see level SCARAND,R A Uranium Recovery Licensing Branch 80/07/10 3pp

B007230715 Discusses proposed Amend 7 to License SUA-1310 to authorize raising existing toilings retention embankment from elevation 5180 4 to 5160 Recommends approval of amend subj to listed conditions Drawing encl OARCIA.P J, GILLEN.D M, LINEHAN.J J Uranium Recovery Licensing Branch 80/07/10 Gpp

--8007230721 Forwards hydrologic engineering summary for U mill Proposed design for operational period meets hydrologic design criteria suggested in Reg Guide 3 11 Several issues should be addressed hefore long-term stability can be assured BIVINS.W 8 Hydrologic & Geotechn; cal Engineering Branch 80/06/18 6pp

--B007230725 Discusses questions re proposed tailings reclamation plan Expresses doubt that extensive cracking would extend through depth of cover if min thickness of 3m is adhered to All outstanding issues have been adequately addressed NELBON, J D Colorado State Univ 80/06/23 ip

DOCKET 40-8481 BOEINS CO

- 8007280218 Application by Buring Co for Amend 6 to export license, adding Angola, Cameroon & Libyan Arab Airlines as ultimate consignee
 MDRGAN, W E Boeing Co 80/06/11 ip
- DUCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP
- 8007140606 Expresses concern re immediate economic consequences Buffalo.NY will experience if work at U mine is halted NYGRON, J. Affiliation Unknown 80/04/25 tp
- 8007010591 Forwards licensee 800-129 ltr to State of MY re mine site, including weekly water quality analysts results pierometric contour maps & map of new shallow research well locations browling available in Central Files only MICHERS.D L. Wyoming Mineral Corp. 80/05/02 (5pp.
- 8007020079 Submits lept re 800413 results of weekly sample analysis from Shallow Monitor Well SM-12 exceeding upper control limit values for chloride & total alkalimity Diagnostic wells drilled to define extent of chloride majoration WICHERS.D L Hyoming Mineral Corp 80/09/20 Ip
- 8007210285 Summary of 800430 meeting w/State of MY officials & MY Minerals Corp in Cheyenne, MY re NRC order to show cause FONNER.R L Diffice of the Executive Legal Director SCARAND,R A Uranium Recovery Licensing Branch 80/05/21 Spp
- 8007030358 Forwards 800530 biweetly status rept re recent monitoring offents of shallow monitor rane Two oversize drawings encl WICHERS: B L Wyoming Mineral Corp 80/06/02 10pp
- ---B007030363 "Prezometric Contours Rescarch Well Locations, Production Units 1.2,3,4,5 & & " Sheet | of 1

 Hyoming Maneral Corp 80/09/13 1p
- --8007030364 "Pierametric Contours Research Well Locations, Production Units 1,2,3,4,5 & 6 " Sheet 1 of 1 Wyoming Mineral Corp. 80/05/19 1p
- 8007100445 Forward: 800521 surmary of 800430 meeting willconsed & State of My re 800421 show cause order BCARAND.R A Uranium Recovery Licensing Branch 80/06/03 1p
- --800710044& Summary of B00430 meeting w/licensee & State of WY re NRC B00421 older to show Cause issued to licensee Conditions for lifting of immediate effectiveness of order encl SCARANDLR A Uranium Hecovery Licensing Branch FONNER, R L Regulations Division B0/05/2) Spp
- 8007020694 Approves expansion into Production Unit 6 of U mine w/sodium bicarbonate lixiviant.contingent upon NRC approval
 Groundwater restriction after completion of mining
 shall be
 to average baseithe values using best pussible technology
 ACKERMAN.W C Wyoming, Btate of 80/06/04 3pp
- 8007010567 Advises that Dept of Environ Quality.Land Quality Div has not received showing of compliance w/in Situ Mining Act for licensee operations in District 4 Requests status rept re measures to comply w/mining act MORRIS, D Wyoming, State of 80/06/05 lp
- 8007070120 Bubmits data of 800603 & 05 samples taken from latest excursion into G field of Unit 5 RS-47 pumping authorized MORROW, D Myoming, State of 80/06/06 1p
- 8007070147 Forwards Trigaray site 800602 ltr to State of MY re assay data from SH-14 Wichers, D.L. Wyoming Maneral Corp 80/05/06 App
- 8007100452 Summary of 800428 meeting w/licenses to 8tate of MY in Silver Spring.MD se itcenses spendse to 800421 show cause order suspending solution mining operations & asking why suspension should not be permanent KAUFHANN.R S. Uranium Recovery Licensing Branch. 80/04/12 3pp
- 8007140600 Responds to 800609 memo by advising that NRC corrective action to date re-project has been issuance of 800421 & 0523 orders First order had effect of directing immediate suspension of normal activities at site W/o encl orders BCARAND.R A Uranium Recovery Licensing Branch 80/06/13 ip

- --8007140607 Discusses hackground for modifying license & terminating 800421 show cause order to licensee NRC has concluded that inxiviant & pollutants are being confined laterally to well field vicinity in designated hydrostratigraphic horizons KAUFMANN.R S Uranium Recovery Licensing Branch 80/06/13 2pp
- E007150644 Forwards latest communications between site & State of WY, dated 800613 Highers D. L. Wyoming Mineral Corp. B0/06/16 lp
- --B007150651 Submits biweekly status rept for Mine 478 Forwards paracometric contour maps of shallow zone based on static water level measurements from 800527 & 0602 samplings Two oversize drawings encl WICHERS.D.L. Wyoming Mineral Corp 80/06/13 10pp
- -- ROO7150A57 "Research Well Locations Pierometric Contours " Sheet 1 of
 - * Wyoming Mineral Corp 80/04/09 1p
- -- 8007150667 "Research Well Locations, Piezometric Contours " Sheet 1 of
 - * Wyoming Mineral Corp 80/04/09
- B007210066 Requests that all available water quality data from newly drilled shallow monitor wells be forwarded & that future data be entl w/blueskly status repts Also requests info respit tamples taken 800312-15
 MORROW D Hypming, State of 80/06/19 ip
- B007210542 Forwards correspondence w/8tate of WY re Irigarary site shallow 92nd monitor well data Oversize drawing encl WICHERS.D L. Wyoming Mineral Corp. 80/05/20 App
- --800721054B Provides WV Dept of Environ Quality w/water quality data & map identifying locations of exploration hole in area of Production Unit & Quersize map encl
 HIGHERS D L Hyoming Mineral Corp 80/06/18 7pp
- 8007210553 "Location of Exploration Hole in Production Unit & "
- Sheet 1 of 1 * Wooming Mineral Corp 80/05/05 ip
- 8007210086 Discusses concern re economic consequences that could be imposed on Buffela & Johnson County, HV w/curtailment of U solution mining project Modifying license order issued 800823 permitting limited operation for 90 days 5CARAND, R A Uranium Recovery Licensing Branch 80/06/23 ip
- B007230071 Addresses concerns re economic consequences of project curtailment NRC B00523 modified license order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation SCARAND-R A Uranium Recovery Licensing Branch B0/06/23 ip
- 0007R3007/ Addresses concerns re economic consequences of project curtailment NRC 000523 modified litense order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation BCARANG-R, A Uranium Recovery Licensing Branch 00/06/23 2pp
- B0072300B2 Addresses concerns re economic consequences of project curtailment NHC B005Z3 modified license order permits reswestion of limited operations Licensee must demonstrate environmentally acceptable operation SCARANG.R A Uranium Recovery Licensing Branch B0/06/23, lp
- BOO723D274 Advisus that NRC is sensitive to economic consequences of project curtailment to Town of Buffalo & Johnson County. MY NRC issued medifying license order on BOO523: allowing license to resume limited operations for 70-day period SCARAND-R A Uranium Recovery Licensing Branch BO/04/23 ip
- 8007230318 Advises that NRC is sensitive to economic consequences of project curtailment to Town of Buffalo & Johnson County, MY NRC issued modifying license order on 800523, allowing licensee to resume limited operations for 90-day period SCARAND-R A Uranlum Recovery Licensing Branch 80/04/23 ip
- 8007250642 Responds to concern about economic consequences of project curtailment NRC 800523 order will permit resumption of limited operations Public benith & safety will not be endangered SCARANO,A A. Uranium Recovery Licensing Branch 80/06/23 in
- 8007210145 Requests info re contaminants in aquifiers near Buffalo.WY DREY.K Affiliation Unknown 80/06/26 ip

- 8007210101 Notifies that on B00522 samples from shallow monitor well SM-14 indicated chloride & total alkalinity exceeded upper control limits Gaused by producing recovery well Addl monitoring underway HICHERS D L Myoming Mineral Corp 80/06/27 3pp
- 8007210191 Dutlines status of action items agreed on at 800616 meeting re authorization of Production Unit 6 & 1.600 gpm flow expansion request Technical support info has been submitted Lists addl environ studies
 TIEPEL.E W Wyoming Mineral Corp 80/06/30 3pp
- B007280054 Notifies that 800617 restoration plan & license request are acceptable w/following condition Surface reclamation is not complete until good vegetative cover is present MDRROW.D Wyoming, State of B0/07/03 lp
- BOOY210095 Forwards requested tabulated data on monitor well upper control limits & initial & current assays for research wells TIEPEL,E W Wyoming Mineral Corp BO/07/07 3pp
- B007210095 Forwards requested tabulated data on monitor well upper control limits & initial & current assays for research wells TIEFELLE W obsolete code B0/07/07 5pp
- 8007280200 Notifies that JM Corcoran has been appointed mine manager of Irigarary in situ mine site, Johnson County, WY HOHNE, F. C. Wyoming Mineral Corp. 80/07/09 1p
- B007280303 Bubmits analysis of ammonia in shallow sand monitor wells. Unit 6 MORROW, D Wyoming. State of 80/07/15 1p
- BOO7230063 Addresses concerns re economic consequences of project curtailment NRC BOO523 modified license order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation SCARAND.R A Uranium Recovery Licensing Branch BO/07/18 lp

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

- 8007020028 Advises of intention to occupy existing in situ camp facilities in Bection 21. Township 24 north:Range 93 west. Eweetwater County. HY for approx 2 yrs beginning in Hoy or June 1980 to canduct U exploration activities ACOBTA: A P Union Minerals 80/02/21 2pp
- 800701030B Notifies that fill placement has resumed on Cell C of subsurface tailings impoundment at Sweetwaler U project Submits tentative schedule for completing cell const Revised date for tailings cell liner installation is 800616 ACOBTA.A P Union 76 Minerals Exploration Co 80/05/08 lp
- 8007180601 Discusses proposed Amend 3 to License SUA-1330 involving mpds to tailings pond liner sys Recommends approval Const mods include removal of soil cover except in traffic areas, at disk top, at disk top, at disk top, at disk pench & at PVC/Hgpalon seam GI(LEN,D M Uranium Recovery Licensing Branch 80/06/03 4pp
- BOO7240103 Amends Bource Matl License BUA-1350 to add Paragraphs j,k & 1 to Condition 39 & modifies Condition 41.42 & Paragraph d of Condition 40.

 BEARANDER A Uranium Recovery Licensing Dranch 80/04/03 3pp
- B007210560 Submits add1 monitoring &/or clarifying data per RA Scarano 790216 request re "Preoperational Monitoring Rept " Oversize map encl ACOBTA:A P Union 76 Minerals Exploration Co B0/06/04 20pp
- --8007210366 "Preoperational Environ Monitoring Locations" * Union 76 Minerals Exploration Co 80/05/31 ip
- B007100450 Requests that two const insps be conducted of tailings impoundment. Insp of results of excavation by blasting should be performed during last we in June 1980 Insp of synthetic liner installation should be performed in mid-Jul 1980 BCARANO.R A Uranium Recovery Licensing Branch 80/06/19 2pp
- B0072306B0 Submits contract costs incurred & manhours used in reviewing 790713 license application GILLEN.D., LINEHAN.J J Uranium Recovery Licensing Branch 80/07/08 2pp

- 8007250197 Advises licensee that no add) fee is required in connection w/Amend 3 to License BUA-1350.issued on B00603 Licensee paid mak fee for minor safeby & environ amend MILLER,W () License Fee Management Branch 80/07/15 ip
- 8007290619 Refers to 800514 ltr re 800514 mill start-up notification Mill start-up expected 800910 instead of 800815, due to const delays ARCOSTA A P Union Minerals 80/07/29 1p

DOCKET 40-0505 WYOMING MINERAL CORP

- B007010214 Application for amend to License SUA-1315 revising Figure 3 2-1 estimates for flows through resin ion exchange columns Requests issuance of amend by 800902 Fee encl SCHENDEL, K R Wyoming Hineral Corp 80/05/27 2pp
- 8007230084 Discusses 800527 application to amend Condition 11 of License SUA-1315, altering flow rates from 6,666 to 10,000 gpm ion exchange feed & 6,710 to 10,070 gpm ion exchange tails Recommends approval of application HEYER, R S . LINEHAN, J J Uranium Recovery Licensing Branch 80/07/10 2pp
- 8007240300 Amend I to License SUA-1315, revising Condition 11 re release of process waste SCARAND, R A Uranium Recovery Licensing Branch 80/07/10 to

BOCKET 40-8602 UNITED NUCLEAR CORP

- 2007180288 Summarizes 800422 visit to main emborkment foundation & impoundment area preparation Recommends continued const Prof engineer should supervise monitor document & cortify all phases of const process

 ABT, S R United Nuclear Corp 80/04/27 3pp
- B0072B0046 Advises of recommendations made re increased documentation a certification of embankment const from 800422 insp. Forwards rept of initial work following NRC insp. Entire documentation will be examined during 10% insp. phase ABT, S.R. Colorado State Univ. B0/05/12 4pp
- B007170291 Forwards 1E Insp Rept 40~8602/80-03 on B00422 No noncompliance noted BROWN.0 D Region 4, Dallas. Fuel Facility & Materials Safety Branch B0/06/30 2pp
- --9007170297 IE Insp Rept 40-8602/80-01 on 800422 No nencompliance noted Major areas inspected NRC regulations & applicable civil engineering soil stds HARRISON.H C Region 4. Dallas, Office of the Director ABT.S R Colorado Stoto Univ BROWN.G D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/06 2pp
- --8007170302 Provides trip tept re 800422 site visit to main embankment foundation & impoundment area preparation Recommends United Nuclear Corp proceed w/main embankment const & prof engineer supervise all phases of const AUT.8 R Colorado State Univ 80/04/27 3pp
- --8007170308 Forwards consulting engineer rept of initial wark.re increased documentation & critification of ambankment const. following NRC 800422 insp ABT.B R Colorado State Univ 80/05/12 App

DOCKET 40-8647 KERR-MCGCE CORP

- BOD7030031 Forwards environ rept.Buppl 1 & Addendum 1.responding to NRC 791217 questions re proposed new U mill Includes three design drawings of proposed retention pond BHELLEY, W J Kerr-McGee Nuclear Corp BO/05/07 ip
- --8007030035 Environ rept.Suppl 1 & Addendum 1, responding to NRC 791219 questions * Kerr-McGee Nuclear Corp 80/05/09 8pp
- --8007030039 "Tailings Disposal Study Hillside Deposition W/Drainage to Excavated Pond 'P' " * Stearns-Roger, Inc. 60/03/05 1p
- --8007030047 "Tailings Disposal Study Hillside & Pond 'P' Sections "
 * Stearns-Roger: Inc 80/03/05 ip

- 8007030055 "Tailings Disposal Study Hillside & Pond P' Reclamation
 - Stearns-Roger, Inc 80/02/04 ip
- 007010570 Forwards addendum to 'Environ Rept.South Powder River Basin Mill." in response to NRC 800201 request Dose calculations used in initial rept wore modified to include milk pathway evaluation SHELLEY.W J Kerr-McGee Nuclear Corp 80/06/06 1p
- 8007010992 Addendum 2 to "Environ Rept, South Powder River Basin Mill " # Kerr-McGee Nuclear Corp 80/06/06 29pp
- OCKET 40-8A81 ENERGY FUELS NUCLEAR, INC
- 007180491 Summarizes 800415 safety insp of Dike 3 & placement of PVC liner in Cell 2 Rocommends continued const Consulting engineer should remain onsite to observe, check & document all activities re preparation, placement & insp of PVC liner AUT.B R Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.) 600/04/10 13pp
- 007280070 Forwards photos of iOX insp of Embankment 3 % lining of Cell 2 Requests that typographical error on Page 3.Paragraph h. Line 4 in 80041B rept be corrected to read "1B inches along embankment " Change critical for compliance W/o encl ABT.B R Colorado State Univ 50/04/30 1p
- 007180277 Summarizes 800424 70% insp of Dike 3 Recommends continued const Density recurds we sand drain on Embankment 2 should be checked for licensee compliance prior to final approval
 - United Nuclear Corp BO/05/15 3pp
- 007280175 Bafety evaluation recommending approval of Amend 3 to License SUA-1358 w/noted conditions Amend would involve addition of second crusher unit to one buying station circuit at mill OLLLEN,D M . LINEMAN, J J Uranium Recovery Licensing Branch 80/06/04 2pp
- 107170327 Forwards 1E Insp Rept 40-8681/80-01 on 800415 & 24 No noncompliance noted BROWN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/11 Spp
- 0007170327 IE Insp Rept 40-8681/80-01 on 800915 & 24 No noncompliance noted Major ureas inspected NRC regulations & applicable civil engineering soil stds
 HARRISON-H C Region 4. Dellas. Office of the Director ABT.S R
 Colorado State Univ BRDWN-O D Region 4. Dellas, Fuel Facility & Materials Safety Branch 80/06/06 2pg
- -8007170331 Bubmits trip rept re insp of Dike 3 & placement of PVC liner in Cell 2 Recommends that work conducted up to insp time be approved for continuation & that consulting engineer remain onsite to observer.check & document all activities ART.8 R Colorado State Univ 80/04/18 13pp
- -B007170332 Bubmits typographical correction for 800418 trip rept re placement of PVC liner in Cell 2.indicating that Energy Fuels Nuclear has complied w/license canditions ABT.8 R Colorado Btate Univ 80/05/05 ip
- -B007170335 Trip rept re B00424 70% insp of Dike 3 Recommends that work up to insp time be approved & that Energy Fuels Nuclear be allowed to continue const of embankment Also recommends that final approval be rendered for mill operation ABT.B R Colorado State Univ 80/05/09 3pp
- PO7100D19 Discusses actions taken by NRC in response to State of UT 800612 ltr is archaeological activities being porformed at facility Interagency Archaeological Svcs will check work for conformance w/memorandum of agreement 80ARANO.R A Uranium Recovery Licensing Branch 80/06/17 lp
- 007210090 Discusses Items 1-3 addressed in first lit to NRC & discussed at 800618 meeting to sibe Piecemeal approach to memo of agreement will have detrimental effect on archaeological analysis ENITH.N T Utah, State of 80/06/30 2pp
- 007230672 Submits contract costs incurred & manhours used in reviewing 800414 license application OILLEN.D., LINEHAN, J. Uranium Recovery Licensing Branch B0/07/08 Spp

- 8007230731 Forwards copy of NRC 800606 fee request for 800523 amend to License SVA-1358 for relief from License Conditions 41 & 47 Requests payment within 15 days WE188,D License Foe Management Branch 80/07/16 ip
- 8007280564 Informs of furthcoming refund re review of 800414 application for Amend 3 to License SUA-1358 MILLER: W D Licensu Fee Management Branch 80/07/14 ip
- DOCKET 40-8693 COLE PETROLEUM, INC
- 8007020293 Submits quarterly rept for 800201-0430 re pilot in situ U solution mining operation Neither U recovery plant nor restoration plant was in operation Thus no info re injection/recovery rates & vols & reverse osmosis available SAUNDERS.O A Ogle Petroleum, Inc. 80/05/09 8pp
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO
- 8007020083 Responds to 800506 request for written confirmation of agreements reached at 800502 meeting Land & Water Quality Divs are currently reviewing 800330 submittal re compliance w/ln Situ Act Wyoming, State of 80/04/12 ip MORROW, D
- 8007020064 Notifies that 800930 submittal does not demonstrate compliance w/In Situ Mining Act R&D activity at site will be permitted until groundwater restoration & other data are sufficient to support application
 MORROW.D Wyoming, State of 80/06/13 ip
- 8007180057 Summarizes proposed changes or additions to 800423 license amend request Mods correct omissions in original document provises procedures based on recent field experience IWANICKI,R Rocky Mountain Energy Co 80706/19 3pp
- HOO7210063 Suggests that state suspend Reno Creek license to mine after 30-day notice for failure to make application for commercial facility Orace period will provide facility w/add1 time to complete forms for in situ R&D license MORROW.D Hyoming, State of 80/06/20 2pp
- 8007290870 Forwards Form 5, "Application for In Situ Research Testing License," in response to State of WY Dept of Environ Guality 800613 request W/o enti IWANICKI.R E Rocky Mountain Energy Co 80/97/10 ip
- DOCKET 40-8698 PLATEAU RESOURCES, 1 TD
- 8007180074 Amend 14 to License SUA-1371 revising Condition 41 to change advance notification required prior to certain const milestoned from 3 to 6 wks BCARAND, R A Uranium Recovery Licensing Branch 80/05/09 2pp
- B007180480 Summarizes B00427 site visit & insp of embankment foundation & impoundment area Recommends continued const Vendor should formulate & implement design for insuring tight seal is formed between Zone i matl & grouves & overhang joint ABT.8 R United Nuclear Corp 80/05/20 7pp
- DOCKET 40-8702 ARMY, DEPT OF, ARMANENT MAT READINESS COMMAND
- 8007140627 Forwards IE Insp Rept 40-8/02/80-01 on 800422 No normaliance noted
 CNOCKER.H W Region 1. Philadolphia, Fuel Facility & Materials
 Bafety Branch 80/05/21 2pp
- --BOO7140631 II: Insp Rept 40-B702/80-01 on BO0422 No noncompliance noted Major areas inspected review of decentamination plans & facility tour CROCKER.H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch COSTELLO,F Region 1. Philadelphia. Office of the Director 80/05/20 2pp
- DOCKET 40-8714 CLEVELAND CLIFFS IRON CO
- 80071900B2 Bummary of 800509 meeting w/Cleveland Cliffs Iron Co in Silver Spring.MD re status of Licenses 8UA-1199 & 8UA-1352 & EADIE, 0 0 Uranium Recovery Licensing Branch, 80/04/11 3pp

- 8007230161 Safety evaluation re minor changes in supporting info submitted w/application for License 8UA-1352 Increasing project site to 42 5 acres should be authorized EIS, negative declaration or EIA need not be prepared EADIE:0 9, ROTHFLEISCH.J. HILLER.H.J. Uranium Recovery Licensing through 80/06/20 200
- E007310546 Amend 1 to License BUA-1352 increasing total permit area to 42 1/2 acres while actual woll field is unchanged SCARANDLR A Uranium Recovery Licensing Branch 80/06/20 lp
- 8007310457 Application to amend License SUA-1352, changing Condition 10 to authorize testing of oxygen &/or hydrogen peroxide w/ ammonium carbonate lixiviant to oxidize & liberate U from mineralized sand Fee oncl LDUDERBACK.T E Cleveland-Cliffs Iron Co 80/07/14 3pp

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

- 8007210243 Summary of 800313 meeting w/util in Bilver Spring.ND re in situ solution mining operations ROTHFLEEGCH.J E Uranium Recovery Licensing Branch 80/04/30 4pp
- B007020458 Responds to 800504 request for written concurrence re agreements reached at 800502 meeting Mining permit must be converted to in situ R&D license in order to conform w/code requirements MDRROH, D Hyoming, State of 80/05/12 1p

DOCKET 40-0727 KERR-MCGEE NUCLEAR CORP

- 8007300531 Provides Subcommittee on Energy & Power w/notice of issuance of License SUA-1378 W/o encl
 # Office of Nuclear Material Safety & Safeguards 80/04/16 1p
- B007300855 Provides Bubcommittee on Nuclear Regulation w/notice of issuance of License SUA-1378 W/o encl * Office of Nuclear Material Eafety & Bafoguards 60/04/16 lp
- 8007300557 Provides Bubcommittee on Environ.Energy & Natural Resources w/notice of issuance & negative declaration for License 8UA-1378
 - * Office of Nuclear Material Bafety & Bafeguards 80/04/16 ip
- --8007300560 Notice of issuance of License SVA-1378 & negative declaration.

 ECARANO, R A Uranium Recovery Licensing Branch 80/04/09 i
- 8007300563 Provides Subcommittee on Energy & Environ w/notice of issuance of License SUA-1378 W/n enc!
 # Office of Nuclear Material Safety & Gafeguards 80/04/16 ip
- 8007230620 Tabulates contract costs incurred & manhours used in roviewing 790611 license application MU.O., MILLER.M J. Uranium Recovery Licensing Branch 80/07/03 2pp

DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC

- 8007010129 Forwards "Embankment Info for North & South Levenberger Reservoirs," required by Stipulation 32 of Spurce Matl License SUA-1373 Fee oncl HERLIHY,D Tetan Exploration Drilling Co , Inc 80/02/01 2pp
- --8007010140 "Enbankment Info for North & South Levenberger Reservoirs " for Tetan-Nedco Levenberger in situ maning project HERLIHY,D Tetan Exploration Drilling Co . Inc 80/02/01 46pp
- BO07020335 Advises that reporting identification symbol "XWU" has been assigned to License SUA-13/3, to be used in completing all NRC transfer repts

 BPARMS, E Technical Planning & Information Branch 80/03/27 lp
- 8007280694 Forwards water levels for wells PNS-LS07 for first quarter of operation.per NRC 800207 request Omission of data in quarterly rept was oversight HERLIHY.D Teton Exploration Drilling Co , Inc 80/06/08 App
- 8007220063 Forwards 800606 ltr informing that to date outhor has not received info re continued operation of facility Operation has been put in holding pattern pending NRC decision re Levenberger Reservoirs Requests timely review HERLIHY.D. United Nuclear Corp. 80/06/17 ip

- --B007220070 Requests use of freuboard analysis for evaporation of presented in 800201 rept. "Embankment Info for North & South Levenbeiger Roservoirs " Timely review would be approcaited in order to demonstrate groundwater restoration HERLINY,D United Nuclear Corp. 80/06/04. App.
- B007010432 Submits evaluation for license SUA-1373 to direct exhausbove process equipment & tanks Above tank ventilation systemeduced concentrations of radon & radon daughters to which plant personnel were patentially expassed RIEGER.S N Teton Exploration Drilling Co., Inc. 80/06/20 (*p
- B0072B0702 Submits evaluation of need for direct exhausting above process equipment & tanks to reduce potentially high concentrations of radon & radon daughters
 RIEGER, S. N. Toton Exploration Drilling Co., Inc. 80/06/20
- 8007230667 Discusses 800617 application to amond License SUA-1373, authorize effluent waste levels in evaporation ponds to rise to 5,214 & ft Recommends approval of amend provided License Condition 32 is revised to permit 2 4 ft of freeboard MAUFMANN, R S GILLEN, D M , LINEHANN, J J Uranium Recovery License B0/07/07 3pp
- 0007230711 Amend I to License SUA-1373 authorizing increase in eff level in Oveporation ponds SCARAND, R A. Uranium Recovery Licensing Branch B0/07/07 Ip

DOCKET 40-0745 DOLE PETROLEUM

- 6007030226 Advises that application for permission to drill wells complete for publication is notification Wolls indicated in 80052/ltr should be drilled as soon as possible to get baselining further along FRANCIS.E Wyoming, State of 80/05/29 3pp
- B007170433 Forwards NUREC-0687, DE3 on environ consequences re Usion Basin Project & FR notice 5CARAND, R A Uranium Recovery Liconbing Branch 80/06/13 | Ip
- --8007170436 Notice of availability of DIS for Dison Basin Project SCARANO,R A Uranium Recovery Licensing Branch 60/06/09 4
- ---B007170440 DL9 for Bison Dason Project
 * Office of Nuclear Material Sneety & Safeguards NUREG-OAU7,
 80/06/30 175pp
- 8007300046 Provides Subcommittee on Energy & Power w/June 1980 DEG enci a Office of Nuclear Material Bafoty & Safaguerds - 00/06/13 - 1;
- ---8007300048 Provides Subcommittee on Nuclear Regulation W/June 19t W/o enc! * Office of Nuclear Natorial Bafety & Bafeguards 80/06/17
- --8007300051 Provides Subcommittee on Energy & Environ w/June 1940 W/o encl # Defice of Nuclear Natorial Safety & Safeguards - 80/06/13
- --8007300058 Providus Bubcommittee on Environ Energy & Natural Resp W/June 1980 DEG & related FR notice W/o DEG * Office of Nuclear Material Bafety & Bafoguards | 80/06/13
- ~-8007300062 Notice of issuance & availability of DES SCARAND, R A. Uranium Recuvery Licensing Branch 80/06/09 29
- 80072803JN Expresses appreciation for apportunity but has no common ref18 DICKSON.F S Agriculture, Dept of 80/06/17 ip
- E007170106 Atk receipt of DEB for U project & requests that M Amble & D Johnson be deleted from & O D'Oars added to list of interested citizens in Frement County WY EAST. D Myoming Outdoor Council 807/66/19 Ip
- B007220051 Submits review of DLS reproject compatability w/local & regional comprehensive planning & impacts on urban areas Detument is adequate for agency responsibility MCKINNEY, R D Housing & Urban Development, Dept of 80/06/25
- 8007210141 Hasponds to 800609 request for comments on DFS for tigle Petroleum, Inc. Bison Basin Project. Fremmit County, WY Council reviewed DES Declines comment at this time MALL. 8 Advisory Council on Historic Preservation 80/06/26

BCKET 40-8768 KERR-MCKEE NUCLEAR CORP

007210067 Confirms major points of 800620 teleon re setting groundwater quality basoline & evaluation of groundwater hydrology at R&D U site KAUFNANN.R S Uranium Recovery Licensing Branch 80/07/01 2pp

OCKET 40-8771 NUCLEAR ASSURANCE CORP

00722006B Forwards application for source matt license permitting use Of uranyl peroxids & ammonium diurante in in situ pilot scale testing to recover U Nuclear Assurance Corp will operate project for AZ Public Svc Co WARD, B Nuclear Assurance Corp 80/05/20 2pp

-8007220073 Application for source matt lirense permitting use of uranyl perroside & ammonium diurante in in situ pilot scale testing to recover U from underground mineralized zone Oversize drawings & supporting documentation encl BECKIM K Arizona Public Service Co WARD D Nuclear Assurance Corp 80/06/05 300pp

-8007220077 "Site Facility Layout Peterson In Situ U Extraction Project "
Drtlaff Mineral Services Corp (subs of Ortloff Corp) 88900 80/02/12

-8007220082 "Sular Evaporation Reservoirs Feterson in Situ U Extraction Project " JELINEH, J A Affiliation Unknown 80/02/15 ip

OMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DEKET 50-2 UNIO DE MICHIGAN RESEARCH REACTOR Inspection reports. IE Bulletins & correspondence

007170657 Forwards IE Circular 80-14, "Radioactive Cuntamination of Plant Demineralized Water Sys & Resultant Intornal Contamination of Personnel "No written response required KEPPLERIJ G Region 3, Chicago, Office of the Director 80/06/24

OCKET 50-3 INDIAN POINT STATION, UNIT 1 Adjudicatory correspondence

007020481 Forwards 800619 order revoking authority to operate facility & directing util to submit decommissioning plan within 120 days
DENTOR: H Office of Nuclear Reactor Regulation, Director Sab

-8007020485 Order revoking authority to operate facility
DENTON H R Office of Nuclear Reactor Regulation, Director
BO/06/19 29s

00731024] Forwards Commission B00527 momorandum & order containing decisions on UCS 780502 potation for reconsideration of 780413 memorandum & prefer UCS 771104 petition sought action refire protection for olectrical cables EISENHUT.D & Division of Licensing 80/06/25 899p

007090215 Order granting extension until 800725 for Commission to consider whether to review ALAB-436 t portions of ALAB-541 1997 'C Refice of the Becretary of the Commission 80/07/07

and extension until 800801 for Commission to ALAM-A36 & relevant portions of

tary of the Commission 80/07/10

esident Carter re Indian otest public r planned for

ion. Director

B007170259 Responds to B00206 ltr re status & responsibilities for emergency pisparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRIMES.D K Emergency Preparadness Program Office 60/Q7/07 2pp

B007290682 Requests documentation that future correspondence refacilities be addressed to P Zarakas Requests that HA Monti, MF Shatkousks & UM Makepeace be placed on distribution for ome correspondence Consolidated Edison Co of New York 80/07/24 1p

I Financial information

8007240127 Forwards Annual Financial Rept 1979 ZARAKAS,P Consolidated Edison Co of New York 80/07/15 ip

--B007240129 Annual Financial Rept 1979
-- Consolidated Edison Co of New York 60/02/26 43pp

D Advisory Committee on Reactor Bafeguards reports & correspondence

8007220308 Provides summary of 800507-08 meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents CATTON: I California, Univ of, Los Angeles 80/05/10 App

P Operating license stage documents & correspondence

B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Hudel Tech Specs which would provide acceptable resolution encl for guidance
EIBERMUT,D 0 Division of Licensing 80/06/11 42pp

8007010110 Notification of 800625 meeting w/utils & Sandia Labs in Bethesda,MD for presentation of overview of facilities risk study Agenda encl ISRAFLE L Reliability & Risk Assessment Branch 80/06/16 3pp

B007090277 Forwards info updating 800505 ltr re control room habitability Drawing available in Central Files only ZARAKAS.P Consolidated Edison Co. of New York 80/07/01. Spp

8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PMR Hodel Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance CISCNIUT.D 0 Division of Licensing 80/07/02 69pp

B007140372 Forwards "Program Plan for Performance Testing of PWR Bafety & Relief Valves." Revision 1, addressing NUREG-0578 Requirement 2 1 2 YOUNGDAIL. R C Consumers Power Co R0/07/08 1p

--8007140398 "Program Plan for Performance Testing of PWR Safety & Relief Values:" Revision 1 # Electric Power Research Institute B0/07/01 90pp

O Inspection reports, IE Bulletins & correspondence

8007020124 Forwards FE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required ORIFR.D H Rogson 1. Philadelphia. Office of the Director 80/05/28 1p

8007010722 Forwards IE Info Nutice 80-23, "Loss of Suction to Emergency Faedwate: Pumps " No written response required ORICR.D H Region 1. Philadelphia. Office of the Director 80/05/29 ip

80070100B1 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "All Unit 2 tanks that could contain primary sys water have adequate protection Bulletin nat applicable to Unit 1 CANALL W J Cunsolidated Edison Co of New York 80/06/06 Spp

80070209/7 Forwards response to IE Bulletin BO-12, "Decay Heat Removal Bys Operability " Bulletin not applicable to Unit 1 which is in defueled condition Existing Unit 2 procedures provide for adequate alternate means for removal of decay heat CAHRLL, W J Consolidated Edison Co of New York BO/06/Q6 5pp.

8007210555 Forwards IL life Nutice 80-26, "Evaluation of Contractor GA Programs" No written response required ORIER.D H Region 1. Philadelphia, Office of the Director 80765/10 ip

- BOO7140341 Forwards IE info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required ORIER.I H Region i, Philadelphia, Office of the Director 80/06/11 ip
- 8007170287 Forwards partial response to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls." for Unit 2 Unit 1 was shutdown 741031 & in defueled condition therefore bulletin not applicable CAHILLN J Consolidated Edison Co of New York 80/06/13 5pp
- B007020710 Forwards [E Bulletin 80-18, "Pussible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/06/18 ip
- 8007020497 Forwards 1E Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/20 1p
- BOO7180560 Responds to IE Bulletin BO-09 No Hydramotor actuators used in any Unit 2 sofutly-related sys Unit 1 presently in defueled condition CAHILL:N J Commonwealth Fdison Co BO/06/20 1p
- 8007180592 Responds to IE Builetin 80-10 Investigation revealed potential for nonradioactive sys to become contaminated through itsolation valve seal water/city water interface Double check valves installed Monitoring program described CAHILL.H J Commonwealth Edison Co 80/06/20 2pp
- 8007160688 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Daminaralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER B H Region i, Philadelphia, Office of the Director 80/06/24 | la
- 8007219172 Forwards IE Info Notice 80-24, "Low Lovel Radwaste Burial Criteria " No writton response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/86/25 ip
- 8007230106 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters #/Either A or D Output Codes " Written response required IE Circular 80-11 also encl No written response required ORIER.D # Region i, Philadelphia, Office of the Director 80/06/27 2pp
- R Periodic operating reports & related correspondence
- 8007170363 Forwards "Annual Environ Monitoring Rept.Part B Radiological Rept " CAHILL: H J Consolidated Edison Co of New York 80/06/30 lp
- --8007170365 "Annual Environ Monitoring Rept, Part D Radiological Rept "
 * Consolidated Edison Co. of New York 80/06/30 &&pp
- 8007130669 Submits daily fish counts from intake screens for June 1980 MONTI-W A Consolidated Edison Co of New York 80/07/10 17sp
- 8007210473 Forwards util 800613 ltr & "Guarterly Rept on Beismic Monitoring Network in Vicinity of Indian Point,NY, Con Ed Project Dec 1979-Feb 1980" of New York 80/07/14 Ppp DAVIS,J P Consolidated Edison Co of New York 80/07/14 Ppp
- 8007220523 Forwards "Daily Count from Intake Screens for June 1980 "
 ZARAKAS,P Conspirated Edison Co of New York 80/07/15 ip
- --8007220524 "Daily Count from Intake Screens for June 1980" * Consolidated Edison Co. of New York 80/97/15 4pp
- T Hearing transcripts on non-antitrust matters
- B007140084 Unofficial transcript of B00626 briefing on recommendations of Indian Point Task Force in Washington, BC Pp 1-62
 Viewgraphs encl
 * Commission 80/06/26 64pp
- 8007240164 Transcript of 800711 public meeting in Washington.DC Pp 1-6 * Commission 80/0//11 dpp

- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

 F Security, medical, omergency & fire protection plans
- 8007310383 Forwards physical security plan Plan withheld (ref 100FR2 790) CUNNINGHALLR Ponnsulvania State Univ 80/07/25 10
- Q Inspection reports, IE Bulletins & correspondence
- 8007;60806 Forwards 1E Circulai 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required CRIER, II H. Region 1. Philadelphia. Office of the Director 80/06/24 1p
- 8007210134 Forwards IC Info Notice 80-24. "Low Lovel Radwaste Surial Criteria" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/25 1p
- DOCKET 50-10 DRESDEN NUCLEAR FOWER STATION, UNIT 1

 D NRC Draft/final Environmental Statements, supply & correspondence
- 8007100218 Responds to 800530 ltr requesting comments on DES NRC contentrates review of other agencies' E18 on areas of electric power, natural gas & oil pipeline industries or where staff has special expertise in evaluating E18
 HEIMEMANN, J M Federal Energy Regulatory Commission 80/06/12
- B007070263 Submits comments re DFG for preliminary cooling sys chemical decontamination at facility Recommends that NRC appoint commissions to examine decontamination process Findings should be discussed at public hearings PLANTIR L. Affiliation Unknown 80/06/27 2pp
- 8007100215 Criticies NUREC-OΔβΔ.DES re primary cooling sys chemical decentamination DES totally deficient & fails to address problems w/refurbishing non-nuclear power plants for alongsted operating times.

 LEWIS.M 1 Affiliation Unknown 80/06/28 1p
- 8007070264 Provides review of DES, May 1980 NUREG-CAR6, re primary cooling sys chemical decuntamination Suggests environ monitoring section be added Personnel training adequately assures ALARA exposure levels
 WEAVER, C. L. HEW, Dept of, US Public Health Service 80/06/30 2pp
- 8007090269 Comments on NUREG 0686 re DES for decontamination of plant Where data is unavailable, programs should be undertaken to design & evaluate specific degradation procedures CREAAR, D.A. Princeton Univ. B0/07/01 2pp
- 8007160540 Ack receipt of DES rt primary cooling sys chemical decontamination Disappointed that rept restorates stems originally relised about dangers accompanying operation & contains no new info ro decontamination problem BANASZAK, L. J. Washington Univ. 80/07/01 4pp
- 800718036B Submits concerns re decommissioning of facility Disappointed that DES does not address any new problems project will create NRC should consider isotopy migration to adequate experimentation of amount on radionuclides removed BANASZAK, L. J. Washington Univ. 80/07/01 App
- 8007230649 FOIA requist for five tategories of documents re decontamination of facility GULDSHITH.R Citizens for a Better Environment 80/07/02 2pp
- 8007230932 Discusses DES re nrimary couling tys chemical decontamination at facility Folymer & ground are only containment for waites Response to leaching problems is not reassuring Many double exist wroublic safety at stake AYERS, P. J. Affiliation Unknown 60/07/08 2pp
- BO07280185 Forwards NUREG-0616 to DES for primary cooling sys decontamination t related FR notice Comments must be received by 800721
 EISERNUT, D.G. Division of Licensing 80/02/09 ip
- ---B007280205 Protests against proposed decontamination scheduled for Mar Urges C18 be prepared & public hourings be held immediately RDSENTHALIA J Affiliation Unknown 80/05/13 1p

- 10/22/0386 Comments on proposed NRC. DDE. DDM Chemical Co & util chemical decontamination demonstration project as described in draft E15. NURREG-OSB6 Fipressus concern To possibility of accident, effort on workers & public DREY. M Affiliation Unknown 80/07/16 9pp
- NOTE-20373 Comments on draft Elb on decontamination, NUREC-0696 Document is rehash of old responses Bafely of proposed operation not provon RUEKBLRO, B Affiliation Unknown BO/07/16 App
- 007.220889 Submits comments on NUREG-0686. DEG for decontamination of facility Comparative data on leach rates solidification & rates between BNL & DOW should be shown in tabular form Info is currently unclear von ZELLEN. B W Northern Illinois Univ 80/07/16 Spp
- 307220539 Comments on NUREG-0A86 draft environ statement re primary cooling sys chemical decontamination does not evaluate occupational or public radiation exposure vesulting from serious vehicle accident during transport of nuclear waste OUTH-R W RPF foological Associates 80/07/17 jp
- 007230513 Forwards questions re May 1980 DES concerning primary cooling sys chemical decontamination Expresses doubt re NRC safety evaluation of area volcanic & seismic activity, citing previously documented redictuelled magration MCCAULEY. B R Affiliation Unknown 80/07/17 5pp
- 007230644 Partial response to FOIA request for five categories of documents re decontamination of facility Documents re Item 2 can be found in IC inspiredts in FDR Bearch is currently undernway for documents under Items 3 & 4 FELTON.J M Division of Rules and Records 60/07/17 2pp
- -8007230563 Distussus proposed plans for disposal of wastes from facility decontamination operation Provides detailed description of disposal method Disposal method found acceptable
 MARTIN. J B Division of Weste Management 80/03/05 2pp
- --BOO7030A7B Provides NRC agenda for solidification demonstration at facility JANCEFK B B Commonwealth Edison Co BO/07/02 ip
- 1007220549 Forwards comments on DES re chamical decontamination of facility DES inadequate to serve as model for similar decontaminations
 ODLDBHITM Citiens for a Better Environment 80/07/18 26ee
- 3007230524 Comments on DES to primary copling systehemical decontamination at Pacility DES Palls short of being complete detailed & fully documented Public comment period should be extended Supportive into encl.

 SHINCFLUG.M.J. Illinois Safe Energy Alliance. 80/07/18 12pp
- BOO728053/ Comments on DES re chemical decontamination DES is deficient & superficial in analysis Coviron impact of future decontaminations should be considered since decontamination of plant will serve as model ODLOSHITI.R. OINBURG.R. Citizens for a Better Environment BO/07/18 24pp
- 8007300323 Comments on NUREC-0586, draft EIS Decument defective & does not adequately discuss possible alternatives to proposed action Retionals for need of proposed action not developed MONTAGUE.P National Campaign for Redipactive Hosto Safety BO/07/20 16pp
- B007280595 Comments on NUREQ-0696, "DEB for Primary Bys Chemical Decentemination " Questions neccessity of preparation of environ statement for action which has minor impact on public & environ, considering cost involved JANECEK, B F Commonwealth Edison Co 80/07/21 Bpp
- 8007220451 Refs LIS & requests info re positive & negative effects of using other decontaminating agents that might not contribute to increased isotomortism mobility LEVERING. R Affiliation Unknown 80/07/22 19
- 6007230349 Forwards comments on NURCG-8685 to proposed removal of radioactive crud from interior of facility No justification for conclusion that no significant environ impact will result from decruding OGGDL, E Citiens Against Nuclear Power 60/07/23 11pp

- 8007270621 Discusses NUREG-0686, DES Anticipates no significant effect on forested land from decontamination projects Shutting down reactly would result in const of alternate plant, w/ considerable effect on vegetation HERDOLDHEMICR Agriculture, Dept of Forest Service 80/07/23 1p
- 8007270694 Forwards comments, correcting several inaccuracies in DEG for primary cooling sys chemical decontamination Recommends that NRC prepare generic EIS identifying available waste treatment & disposal options for other plants
 HEDEMAN, W N Environmental Protection Agency 80/07/25 3pp
- F Security, medical, emergency & fire protection plans
- B007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR, 790)
 PEOPLES D L Cummonwealth Edison Co 80/06/27 ip
- B007240250 Discusoes review of fire protection mods Forwards evaluation status, evaluation of design details & review of Items 3 2 3, "Fire Water Sys Foeds" & 3 2 4. "Exposed Structural Stoel" Addit info requested within 30 days CRUTCHFIELD.D Operating Reactors Branch 5 80/07/09 9pp
- Q Adjudicatory correspondence
- 8007170323 Responds to 790920 petition re proposed chemical decontamination at facility & preparation of ETS Potition combined w/K Drey potition , due to similarities ETSENIUT.D 0 Division of Licensing 80/06/19 2pp
- --B007170330 Responds to 770319 petition requesting that EIS be prepared re-proposed chemical decontamination at facility Petition for action has been granted Public meeting will be held in vicinity of facility to discuss NRC findings DENTON-HR Office of Nuclear Reactor Regulation, Director R0706/26 2pp
- --8007170333 Director's decision under 2 206 determining that EI8 should be prepared for facility decontamination DENTON.H R Office of Nuclear Reactor Regulation, Director B0706/24 31pp
- --8007170336 Notice of issuance of director's decision under 10CFR2 206 rapruparation of EIS for proposed decontamination of facility DENION.H R Diffice of Nuclear Reactor Regulation, Director 80/06/26 2pp
- 1007180032 Responds to 800313 potition re proposed chemical facility decontamination & preparation of EIS Petition was combined w/similar potition filed by K Drey on 790319
 EISENDIOT.D 0 Division of Licensing 60/06/19 2pp
- ---BOO7180187 Forwards potition requesting preparation of EIS.
 OULDSMITH.R Citizens for a Better Environment. 80/03/13 2pp
- --BOO7iBO212 Petition for preparation of EIS on proposed chemical decontamination becontamination is major federal action & significantly affects human environ GOLDSHITHIR Citizens for a Better Environment BO/03/13 4pp
- B007310243 Forwards Commission B00827 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical tables E16ENHUT.D 0 Division of Licensing 80/06/25 B9pp
- 800/140337 Petition requesting hearings on ETB re chamical decontamination & on application for OL amend States interest of authors & K Drey, D Rorem & M Shineflug OOLDSMITH: R Citizans for a Datter Environment GOLDSMITH, R Prairie Alliance GOLDSMITH, R Illinois Safe Energy Alliance 80/07/00 5pp
- ii General correspondence
- E007020183 Responds to B00319 & 0414 ltrs re EIS preparation Recipient will receive director's decision under 10CFR2 206.EIS & NRC comments when available EISENIUT.D G Davision of Licensing 80/06/19 3pp
- ---800/020195 Submits questions re K Drey 790319 request & Citizens for Better Chysron 800313 petition for EIS on proposed decontamination COLDSHITEL Citizens for a Better Environment 80/03/19 3pp

- --8007020203 Requests to be notified when decision is made re Citizens for Better Environ & other groups' petitions for EIS on proposed decontamination GOLDSMITH,R Citizens for a Better Environment 80/04/14 2pp
- 8007140230 Responds to 800324 request for info re K Masterson 800318 ltr concerning burial of radwaste from plant in IL at disposal site in Deatty, NV Discusses disposal site conditions Draft EIS for decontamination encl W/o encl DIRCKS.W J Office of the Executive Director for Operations Орр 80/06/27
- ---8007140231 Forwards K Masterson 800318 ltr re burial of radwaste from plant in IL at disposal site in Beatty.NV Requests findings & views LAXALT.P Sonate 80/03/24 3pp
- 8007310022 Reaponds to E Gogek 800415 itr to IL state senator Forwards copy of MAC response
 EISENHUT, D.Q. Division of Licensing 80/07/10 ip
- --8007310025 Forwards DES & related FR notice in response to ltr to It. State Senator RM Daloy EISENHUT.D 9 Division of Licensing 80/07/10 ip
- P Operating license stage documents & correspondence
- 8007250558 Forwards NUREQ-0619. "NWR Feedwater Nozzlo & Control Rod Drive Return Line Nozzle Cracking," for review & communt CRUTCHFIELD.D M Operating Reactors Branch 9 80/06/04
- 8007010146 Forwards final rule published in 800507 FR amending 10CFR50 71 to require periodic updating of FGARs Compliance is not required until completion of BEP GRUTCHFIELD.D Operating Reacture Branch 5 80/06/10 5pp
- 8007020186 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/i1 2pp
- 8007010042 Forwards NRC evaluation of SEP Topic V-5 re RCPB leakage detection Requests info concorning util as-built facility differing from liconsing basis assumed in ossessment CRUTCHFIELD, D M Operating Reactors Bronch 5 80/04/12 80/06/12 5pp
- 8007010R17 Forwards NRC evaluation of GEP Indic VIII-4 re electrical penetrations of roactor containment Requests info concerning util as-built facility differing from licensing basis ssumed in assessment CRUTCHFIELD, D M Operating Reactors Branch 5 80/04/12 10pp
- 8007010292 Forwards evaluation of SEP Topic V-12 A re water purity of BMR primary coolant Review rempleted & resulting evaluation will form input to integrated sofety assessment unless changes are needed to reflect as-built Londitions GRUICHFIELD, D Operating Reactors Branch 5 80/06/12 3pp
- 8007100399 Responds to 800229 ltr which expressed opposition to ACRB recommendation to restructure SEP Role of licensees in program will expand the forwarded to Commissioners DENTON, H R Office of Nuclear Reactor Regulation, Director DENTON H R O BO/O6/18 4pp
- ---8007100420 Expresses apposition to ACRS recommendation to restructure BEP For BEP owners to perform makety analysis as outlined, cost in dollars & manpower would increase dramatically BCHAFFSTALL.R BEP Qumers Group 80/02/29 2pp
- 8007020479 Confirms arrangements for WA Williams to review Dow Chemical proprietary info re formula for NS-1 solvent Info is being made available w/undorstanding that info will be withheld (ref 10CFR2 790) CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/06/19 2pp
- 8007160459 Forwards "Loss of Offsito Powor Survey Status Rept " Requests views re causes & possible remedies within 120 days CRUTCHFIELD,D M Operating Reactors Branch 5 80/06/19 2pp
- --8007140443 "Loss of Offsite Power Survey Status Rept." Revision 1 BCHOLL, R F Systematic Evaluation Program Branch 80/06/19 9pp
- 8007070116 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV omergency power buscs supplying safety-related loads JANECEK,R F Commonwealth Fdison Co 80/06/26 App

- 8007080063 Responds to NRC 800513 request for add; info concerning adequacy of station electric distribution sys voltages JANECEK, R F Commonwealth Edison Co 80/06/30 4pp
- B0071B0435 Forwards evaluation of SEP Topic V-11 A to requirements for isolation of high & low pressure sys Requests notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/01 5pp
- 8007180438 Forwards evaluation of SEP Topic III-10 A re thermal overload protection for motor operated valves Requests notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD.D N. Operating Reactors Branch 5 80/07/01 Spp
- 8007240295 Forwards evaluation of "SEP Topic VIII-3.DC Power Sys Bus Voltage Monitoring & Annunciation " Requests that NRC be informed if as-built facility differs from basis assumed in CRUTCHFIELD, D Operating Roactors Branch 5 80/07/01
- B007250032 Forwards "Loss of Offsite Power Survey Status Rept " Replaces 800619 rept which omitted Table 4 CRUTCHFIELD.D N Operating Reactors Branch 5 80/07/08 3pp
- --8007250035 "Loss of Offsite Power Survey Status Rept SCHOLL,R F Plant Systems Branch (Pre 791030) 80/0 80/07/08 10pg
- B007280076 Responds to 600318 ltr to J Ahearne objecting on behalf of ID/288076 Responds to BUCSIU Itr to J America objecting, on bo owners of plants under SEP reviou, to current plans for expedited review of environ qualifitation of electrical equipment Forwards applicable memorandum & order DENTON, HR Défice of Nuclear Reactor Regulation. Director DENTON H R D 60/07/16 4pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007010606 Advises that IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." was sent to listed utils on 800116 CARROLL.D E Region 3. Chicago. Office of the Director 80/01/30
- 8007140945 Forwards 1E Dullotin 80-13, "Cracking in Core Spray Beargers " Writton response requires KEPPLER.J 0 Region 3, Chicage, Office of the Director 90/05/12
- 8007070072 Forwards IE Insp Repts 90-010/80-09.50-237/80-08 & 50-249/80-12 on 800407-0502 & untice of violation KEPPLER.J 9 Region 3, Chicago, Office of the Director 80/05/23
- --8007070074 Notice of violation from imap on 800407-0502 * Region 3, Chicago, Office of the Director 80/05/2
- -8007070080 IE Inap Repts 50-10/80-09.50-237/80-08 & 50-249/80-12 on 800407-0502 Noncompliance noted failure to adhere to GA program requirements Contaminated clothing found lying inside controlled contaminated area SPESSARD.R L., MARKER.J L., TUNDUE.T M. Region 3. Chicago, Office of the Director 80/05/23 7pp
- B007020065 Forwards IE Info Nutice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007010086 Forwards IC Info Notice 80-23, "Loss of Suction to Emorgency Feedwater Pumps " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007010150 Advises that 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps," was sent to listed utils on 800529 PAPPAB, H Region 3, Chicago, Office of the Director BO/05/30
- 8007020278 Advises that JE Info Notice 80-22. "Breakdowns in Contamination Control Programs," was sent to listed utils on 800528
 PAPPAS, H. Region 3, Chicago, Office of the Director 80/03/30
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/10

- B007020662 Forwards site-specific & generic questions re GE disc cracking indications per B00109 meeting & IE Info Natice 79-37 on Westinghouse low pressure turbines disc cracks Response requested within 30 days CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 5pp
- 8007140309 Forwards 1E Bulletin 80-14. "Degradation of BMR Scram Discharge Vol Capability " Written response required KEPPLER.J G Region 3. Chicago. Dffice of the Director 80/06/12
- 8007100004 Forwards response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies," No safety-iclated sys or component at Dresden 2 & 3 uses AH-90 or NH-90 scries hydramotor PEOPLES:D L. Commonwealth Edison Co. 80/06/16. 3pp
- 8007030037 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/06/18
- 8007030032 Advises that IE Dulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power," was sent to listed utils on 800618 PAPPAS.H Region 3, Chicago, Offsice of the Director 80/06/19
- B007110200 Ack receipt of B00607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-010/80-08 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/06/19 Ip
- ~-6007110206 Responds to NRC 800516 ltr re violations noted in IE Insp Rept 50-010/80-08 Corrective actions initiated daily sampling t analysis program for gross bota activity for svc water discharge from sphere PEOPLES.D.L. Commonwealth Edison Co. 80/06/09 3pp
- B007230371 Forwards 1E Insp Repts 50-010/80-10,50-237/80-09 & 50-249/80-13 on B00303-29 & notice of violation HEISHMAN.R F. Regson 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --B007230379 Notice of violation from insp on 800505-29 M Region 3, Chicago, Office of the Director 80/06/19 Ip
- --8007230388 IE Insp Repts 50-010/80-10.50-237/80-09 & 50-249/80-13 on 800505-29 Noncompliance noted failure to report events in accordance w/Tech Spocs MARKER, J L. SpessARD, R L. Region 3. Chicago, Office of the Director ' 90/06/19 9pp
- 8007020589 Forwards 1E Circular 8D-i5, "Loss of Reactor Copiant Pump Copiing & Natural Circulation Copidown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- 8007170430 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant internal Contamination of Personnal " No written response required KEFPLER. J 9 Region 3. Chicago. Office of the Director BO/04/R4 ip.
- 8007140566 Advises that IE Bulletin 80-16 % IE Circular 80-16 re Rosembunt pressure transmitters & trip units were sent to listed utils on 800627 PAPPAS,H Region 3. Chicago. Office of the Director BD/06/27 3pp
- B007230289 Forwards IE Bulietin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes " Written response required IE Circular 80-16 also enci No written response required RESPICE OF A STATE OF THE DIRECTOR BOYOGA27

ning NRC of steps taken to 50-010/80-09.

the Director BD/07/01

Repts 50-010/E0-09, 50-237/E0-08 & 50-247/E0-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED, C Commonwealth Edison Co & & & O/O6/13 App

- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR," will start at 12 01 AM on 80070B Test should be completed within 20 days Requests notification of malfunction KEPPLER.J Q Region 3. Chicago, Office of the Director 80/07/07
- 800725064: Responds to IE Bulletin EO-10. "Contemination of Nonreadioactive Sys & Rosulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES.D L. Commonwealth Edison Co. 80/07/07 2pp
- 8007280650 Forwards response to IE Bulletin GO-il, "Masonry Wall Design " Requested investigation not performed at Dresdon. Unit 1 due to extended outage Requirements will be mot prior to startup Wo end
- B007230638 Forwards response to IE Builetin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES, D L. Commenuealth Edison Co. 80/07/09 7pp
- 8007310432 Forwards response to NRC 600511 request for info re turbine disc design & previous inspirosults Provides only info which was available within requested response time Remaining info will be provided prior to startup

 JANECEK,R F Commonwealth Edison Co 60/07/28 2pp
- R Periodic operating reports & related correspondence
- 8007180333 Forwards menthly operating repts for June 1980 STEPHENSON, D.D. Commenwealth Edison Co. 80/07/09 1p
- --8007180336 Menthly operating repts for June 1980 CIESTIEWICZ:S Commenwealth Edison Co 80/07/02 23pp
- U Congressional/Executive Correspondence
- 8007020082 Responds to B00512 inquiry re long-term storage of solidified wastes resulting from decontamination of primary cooling sys Maste will be shipped to commercial low level waste burial site in olther NV or WA DIRCKS.H J Dffice of the Executive Director for Operations 80/06/26 in
- --8007020088 Requests info about NRC action re leng-term storage of solidified wastes resulting from decontamination of primary coping sys
 CORCORAN, T House of Rep 80/05/12 ip
- BOCKET 50-13 BABCOCK & WILCOX CD CRITICAL FACILITY

 G Inspection reports. IE Bulletins & correspondence
- 8007170137 Forwards IE Circular 80-14. "Radioactive Contemination of Plant Bushineralized Water Sys & Resultant Internal Contemination of Personnel " No written response required. O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/24
- DOCKET 50-20 MASSACHUSCTTS INST OF TECH RES REACTOR
- 8007160825 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel" No written response required GRIERS B Region 1, Philadelphia. Office of the Director 80/06/24 ip
- 8007210133 Forwards IE Info Notico 80-24, "Low Level Radwaste Durial Criteria " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director. 80706/25 1p

- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8007180254 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Persunnel" No written response required ENCLKEN.R H Region 5, San Francisco, Office of the Director 80/06/24 lp
- 8007210474 Forwards 1E Insp Rept 50-027/80-01 on 800609-10 No nencompliance noted Encl withhold (ref 10CFR2 790) NDRDERHAUG.L R Region 5: San Francisco. Safeguards Branch 80/07/10 2pp
- DOCKET 50-29 VANKEE-ROWE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8007080310 Requests clarification of NRC emergency plan concurrence schedule Facility revised draft emergency plan will be submitted by 800725
 KAY, J A Vankee Atomic Electric Co 80/06/30 lp
- 8007090233 Forwards Revision & to security plan Plan withheld (ref 100FR2 790) MOODY,D E Yankee Atomic Cloctric Co E0/07/01 1p
- 8007280492 Forwards finel revised emergency plan per NRC 800414 comments Requests prompt review KAY.J A Yanker Atomic Electric Co 80/07/25 lp
- Q Adjudicatory correspondence
- B007310243 Forwards Commission B00927 memorandum & order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 9 Division of Licensing 80/06/25 99pp
- I Financial information
- B007010404 Forwards util 1780 internal cush flow projections in order to meet retrospective premium guarantee requirements under Price-Anderson Act
 SDMCV.A R Yankon Atomic Electric Co. 60/06/29 4ea
- P Operating license stago documents & correspondence
- B007160421 Forwards Amend 60 to Lifense DPR-3 & notice of issuance & availability
 CRUTCHFIELD,D M Operating Roactors Branch \$ 80/06/02 Spp
- ---8007160425 Amond 60 to License DPR-3.adding surveillance requirements for auxiliary feedwater sys in Soction 3/4 7 2 CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 Opp
- --8007160427 Notice of issuance & availability of Amend 60 to License BPR-3 CRUTCHFIELD, D Operating Reactors Branch 5 80/06/02 2pp
- 8007010118 Forwards final rule published in 800309 FR amending 10CFR50 71 to require periodir updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD. D Operating Reactors Branch 5 80/06/10 5pp
- 8007230099 Requests submittel of proposed Tech Spec changes providing for redundancy in docay heat removal capability in all modes of operation Model Toch Specs which would provide acceptable resolution encl for guidance EISENHUT, D G Division of Licensing 60/06/11 62pp
- 8007180530 Confirms 800626 mgt meeting at sits re assessment of regulatory performance of facility GRICR,D H Rogion i. Philadelphia, Office of the Director 80/06/16 2pp
- B007280008 Requests addl info re NRC requirements for auxiliary feedwater sys Review status encl Requests response within 30 days of receipt of itr LAINAB. C Assistant Director for Safety Assessment B0/06/16

- 8007100379 Responds to 800229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON, H R Dffice of Nuclear Reactor Regulation, Director 80/06/18 4pp
- ~-8007100420 Expresses opposition to ACRS recommendation to restructure SEP for SEP owners to perform safety enalysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALLR SEP Gumers Group B0/02/29 2pp
- 8007180466 Forwards evaluation of SLP Topic VIII-4 re electrical penetrations of reactor containment Requests notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD. D. M. Operating Reactors Branch 5 80/07/01 [3pp
- 8007250001 Requests submittal of application for amend to license consisting of Yesh Spec changes & license conditions PWR Model Tech Specs & Model Lessons for TMI-2 Lessons Learned Category A items entl for guidance EISENHUT.D O Division of Licensing 60/07/02 69pp
- 8007080079 Pruvides specific life or auxiliary feedwater pump endurance test All parameters remained within normal operating ranges throughout test Drawings & charts encl MAY.J A Yankee Atomic Electric Co 80/07/03 8pp
- 8007140300 Submits results of review ro anchorage sys for safety-related electrical equipment listed in encl IE Info Notice 80-21 & observations heightened awareness of leaving free standing nonselsmic auxiliary items around when not in use KAY. J A Yankee Atomic Electric Co 80/07/09 Spp
- 8007140338 Forwards YOGAP--1-A.Revision 8.per NRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDER.L B Yankee Atomic Electric Co 80/07/07 2pp
- --8007140342 Advises that YBGAP-I-A.Revision B. is acceptable Programmatic changes should be submitted to NRC for review prior to implementation Requests that itr replace 800410 itr & rept be renumbered w/revision & submitted to NRC HAASS.W P. Quality Assurance Branch 80/07/02 jp
- 8007280076 Responds to 8003iO ltr to J Ahearne objecting on behalf of owners of plants under SEP review to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandom & order DENTON.N R Office of Nuclear Reactor Regulation. Director 80/07/16 4pp
- BOO7280621 Forwards rovised description of proposed vent sys for both reactor vossel head % pressurizer Vessel head went will be piped directly to containment atmosphere Equipment will be installed BIQIO1

 XAY, A Vankon Atomic Electric Co. 80/07/22 5pp
- BOO7280439 Submits alternate method of mitigation effects of grid dogradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDEMBURGH D Yanker Atomic Electric Co 80/07/24 7pp
- EQ07280586 Discusses commitment to install containment hydrogen monitor by 810101 Describes compliance w/NRC 791030 itr Sys will be composed of Bendix analyzer & Combin Inc. Hodgi K-11; thermal conductivity analyzer KAY, J A Yankee Atamic Electric Co. 80/07/P4 2pp
- B007280626 Requests that evaluation of proposed mods, re tessons Learned task force Category II items be completed by 800701 Further delays in evaluation may result in insability to meet 810101 deadline

 KAY.J A Yankee Atomic Electric Co 80/07/24 6pg
- Q Inspection reports. IE Buildtins & correspondence
- 8007020101 Forwards I& Info Notice 80 -22. "Breakdowns In Contamination Control Programs " No written response required GRIER,D H Region 1. Philadelphia, Offsee of the Director 80/05/28 ip
- 8007010289 Forwards IC Info Notice 80-2). "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER.B II Region 1. Philadelphia. Office of the Director 80/09/29 1p

- 00/18007/ Submits reply to IE Bulletin 80-12 re decay heat removal operability Plant procedures were analyzed for adequacy of safeguards against loss of redundancy & diversity of decay heat removal sys heat removal sys VANDENBURG.D E Yankee Atomic Electric Co 80/06/09 4pp
- 007010057 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Tanks used for low pressure process or holdup purposes are adequately protected egainst vacuum conditions MOODY, D E Vankee Atomic Electric Co 80/06/10 2pp
- 007210626 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required GRIER. B H Region 1. Philadelphia, Office of the Director B0/06/10 | Ip
- 007150370 Forwards IE info Notice 80-27, "Degradation of Reactor Coolant Pump Study" No specific action or response required GRIER, B H Region L. Philadelphia, Office of the Director 11/40/08
- 007170116 Forwards response to 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls "Circust made will be made to proclude automatic roset of safety-related equipment from emergoncy mode as result of resetting ESF signal VANDENBURGH, D.E. Yankee Atomic Electric Co. 80/06/12 3pp
- 007020705 Forwards IE Bullotin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written rosponse required GRIER, Bil Region 1, Philadelphia, Office of the Director 80/06/18 1p
- 0071705B2 Responds to IE Bylletin 80-09. "Hydramotor Actuator Deficiencies " No ITT General Controls AH-90 or NH-90 Series hydramotor actuators used in safety-related sys HOUDY.D E Yankee Abomic Electric Co 80/08/18 1p
- 007180144 Forwards reply to IE Bulletin 79-27 TV loss of non-Class IE instrumentation & control power Performed review & evaluation of power supplies which could affect ability to achieve could shotdown MOODY, D E Yankee Atomic Electric Co B0/06/18 15pp
- CO/D20530 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.9 II Region 1. Philadeiphia. Office of the Director
- 007160752 Forwards IE Circulat 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORICER DH Region I. Philadelphia. Diffice of the Director 80/06/24 1p
- 307210291 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.D II Region 1, Philadelphia, Office of the Director 80706/23 Ip
- 007210506 Informs of affirmative findings in response to IE Dulletin 80-08 re existence of flued head designed penetration connections Addl stems concerning penetration assemblies leo discussed MODDY. D E Yankee Atomic Electric Co 80/05/28 in
- 207230189 Forwards IE Dulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1132 Pressure Transmitters M/Either A or D Gutput Codes " Written response required IT Circular 80-16 also encl No written response required ORIER, D H Region 1. Philadelphia. Office of the Director 80/06/27 Rep
- 107210002 Advises that IE Builetin 79-17 reporting requirements for LER 80-12 re linear indications are no langer applicable. Internal liquid penetiant azaminations of internal surfaces confirm no through-wall defects.

 AUTIO.H A Yankee Atomic Electric Co. 80/07/02 1p
- 007250273 Submits reply to 1F Nulletin 80-10 re contamination of nonradioactive sys & potential for release Present sampling frequency will promptly identify any contamination MOODY.D F Yankoe Atomic Ejectric Co 80/07/07 2pp
- 007230278 Submits reply to IE Bulletin 60-11 re masonry wall design No further justification for use of codes as basis of re-evaluation criteria is required HEIDERs.L.H. Yankee Atomic Electric Co. 80/07/08. App

- R Periodic operating reports & related correspondence
- 8007210399 Forwards "Effluent & Waste Diaposal Semiannual Rept. Jan-June CRECE, R H Yanken Atomic Electric Co 79/08/29 1p
- ~~8007210405 "Effluent & Waste Disposal Semiannual Rept. Jan-June 1979 "
 * Yankeo Atomic Electric Co 79/08/29 lipp
- 8 Reportable occurrences. LERs & related correspondence
- 80070/0284 ND 80-12 during liquid penetrant examinations of piping.two linear indications were found on weld used to join valve to schedule 10 coupling Valve will be removed to examined AUTIB.H A Yanker Atomic Electric Co 80/06/27 ip
- DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR
- @ Inspection reports, IC Bulietins & correspondence
- 800/160832 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Domineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, Ol K Region). Philadelphia. Office of the Director 80/06/24 ip
- 8007210131 Forwards IE Info Notice 80-24, "Low Level Radweste Burial Criteria" No written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/06/25 Ip
- DOCKET 50-54 UNION CARRIDE RESEARCH REACTOR
- F Socurity, medical, emergency & fire protection plans
- 60072300Bi Requests resolution of outstanding fee issues for certain physical eccurity-related documents & emergency plans Memo dtd 770910 re 790220 guard training plan submitted by GA Co MILLED . W O License Fee Management Branch 80/07/16 2pp
- O Inspection reports. IE Bullotins & correspondence
- 8007140849 Forwards IF Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/24 p
- 800721014/ Furwards IE info Notice 00-24, "Low Lovel Radwaste Burial Criteria" No written response required CRIER.B H Region I, Philadelphia, Office of the Director 80/06/25 Ip
- 8007300036 Ack receipt of 800428 ltr in response to NRC 800407 notice of violation & notice of propused imposition of civil penalties Also forwards order imposing civil monetary penalty STELLG.V NRC Regional Offices 80/07/11 2pp
- --E007300040 Order imposing civil monutary psnalty re noncompliance noted in IE Insp of facility on 800102-29 App A, evaluation & conclusion encl STELLD, V NRC Regional Offices 80/07/11 Spp
- 8 Reportable occurrences. LERG & related correspondence
- 800723014B EN-80~012A on 800711, order imposing civil penalty of \$1,000 was issued Afte) consideration of licensee response, IE concluded that one item of noncompliance did occur BROCKETTIT W. THEMPSON, D. Office of Inspection & Enforcement, Office of the Director 60/07/11 1p
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR 0. Inspection reports, IE Bullotins & correspondence
- B007160827 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Deminoralized Water Bys & Resultant Internal Contamination of Personnel" No written response required GRIER, B II Region 1, Philadelphia, Office of the Director B0/06/24 | 1p

- 8007210140 Forwards IE Info Notice 80-24, "Low Level Rudwaste Burial Criteria " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 1p
- A Periodic operating reports & related correspondence
- 8007280654 Annual Tept of changes, tests & experiments for Jul 1979-June 1980 ORLOSKY, P. M. New York, State Univ. of, Buffalo 60/07/22 ip
- 8007290674 Provides rept for Jul 1979-June 1980 to changes experiments & tests conducted w/o prior NRC approval per License R-77 Nume conducted Official Conducted Official Provided Research Conficial Provided Research Conficia

ORLOSKY, P.M. New York, State Univ of, Buffalo BO/07/22 Ip

- DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

 R Periodic operating reports & seleted correspondence
- 8007210502 Forwards "Annual Operations Ropt of TY ASM Univ AGN-201M Training Reactor." For June 1979-May 1980 COCHRAN R O Texas A & M Univ 80/07/11 1p
- --8007210512 "Annuel Operations Rept of TX Atm Univ AGN-201M (raining Reactor," for June 1979-May 1980
 20LICZYNSKI, J D. CBCHRAN, R O Texas A & M Univ 80/07/11 9pp
- B007240038 Forwards "Annual Operations Rept of TX A&M Univ AGN-20kM Training Reactor" June 1979-May 1980 COCHRAN,R 0 Texas A & M Univ 80/07/11 1p
- DOCKET 50-62 UNIV OF VIROINIA RESEARCH REACTOR

 | Begurity, medical, emergency & fire protection plans
- 8007210429 forwards physical security plan & proposed changes to Tech Specs Plan withhold (ref 100782 790) SMRIVER.B L. Virginia, Univ of 80/07/15 2pp
- --B007210433 Tech Specs 3 3.4 1.4 2.4 8.6 2 & 6 3 re safety limits. limiting conditions for operation & surveillance requirements * Virginia, Univ of 80/07/15 9pp
- G Inspection reports. IE Bulletins & correspondence
- 8007170173 Forwards IE Circylar 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/24 to
- DOCKET 50-67 MCMABTER UNIV RESCARCH REACTOR

 R. Periodic operating reports & selected correspondence
- 8007020370 Responds to NRC 800502 request for plant personnel exposure & monitoring rept
 MAXWELL, L V Army, Dept of 80/05/14 ip
- --8007020375 Forwards 1979 personnel exposure & monitoring rept MAXMELL, L V Army, Dept of 80/03/19 ip
- --8007020382 Rept of recorded personnel whole body exposures for 1979
 Army Dept of 80/03/19 lp
- DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

 9 Adjudicatory correspondence
- BOO702046B Forwards May 1980 safety evaluation re GETR BHANBON D T Hearing Branch 1 DO/06/27 Ip
- O Advisory Committee on Reactor Baseguards reports & correspondence
- BOO71B0609 Comments on GETR data NRC & USGS have prepared studies which favor shutting down facility Most dangerous condition is assumed as being in existence, but no steps have been taken to correct condition PHILBRICK. B & Philibrick, S & BO/06/07 lp

- P Operating license stage documents & correspondence
- 8007160360 Advises that landslide investigation program began on 800623 & final rept will be submitted to NR(between B00815-29 Monitoring program not intended to provide data for evolution before issuance of landslide stability SER suppl DARMITZEL, R W General Electric Co B0/07/07 2pp
- 8007240399 Advises of NRC reorganization on 800428 which resulted in number of changes in oft titles.positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08 200
- 8007220349 Forwards response to NRC 800610 request for info demonstrating ability of GETR to meet loadings associated w/ design bases specified in NRC 800523 safety evaluation Six consultant repts enel DARHITZEL.R W General Electric Co 80/07/17 3pp
- ---8007220356 "Add1 Investigations to Determine Effects of Vibratory Hotions Due to Earthquake on Calavoras Fault," Revision 1 4 Engineering Decision Analysis Company, Inc EDAC-117-253 02 Ri 80/06/30 11pp
- ---B007220362 "Expanded Duscription of Boti Pressure Analyses." Suppl i to "Add1 Investigations to Determine Effects of Combined Vibratory Notions & Surface Repture Offest Due to Earthquake on Postulated Verona Fault." Revision 1 * Engineering Decision Analysis Company, Inc EDAC-117-253 OI R1 5 80/06/27 24pp
- --8007220366 "Evaluations for O 6 Gravity Ground Acceleration Case."

 Suppl 2 to "Addl Investigations to Determine Effects of

 Combined Vibratory Motions & Surface Rupture Offset Due to

 Earthquake on Postulated Verona Fault." Revision 1

 # Engineering Decision Analysis Company. Inc EDAC-117-203 01 R1

 8 80/06/30 15pp
- --8007220369 "Review of Seismic Adequacy of Piping & Equipment, GETR "

 * Engineering Decision Analysis Company, Inc EDAC-117-258 Ol 80/06/30 10pp
- ---B007220372 "Combined Parameter Probability Analysis, OETR "
 # Jack R Benjamin & Associatus, Inc. 111-017-02 80/07/18
 16pp
- 8007290007 Nutrification of 800730 meeting w/GE in Bethesda, MD for licenses presentation of addi GETR structural evaluations NELSON, C C Licensing Branch 3 80/07/23 3pp
- 8007280877 Forwards memo describing slope menitoring program initiated in Apr 1980 Monitoring sys designed to detect ground movements of several inches or more which might accompany reactivation of londslide complex Affidavit encl
 QILLILAND.D. L. General Electric Co. 80/07/25 7pp
- 8007280637 Discusses landslide stability investigation Field exploration phase complete Summary rept encl to verify that field work performed will provide satisfactory semples to determine adjacent hill stability under present conditions QILLILAND.D. Coneral Electric Co 80/07/25 4pp
- @ Inspection reports. IE Bulletins & correspondence
- 8007180305 Forwards IE Circula: 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5, Son Francisco, Office of the Director 80/06/24 | 10
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

 O Inspection reports, IE Sulietins & correspondence
- 8007220330 Forwards IE Insp Rept 50-073/80-02 on 800421-22 No noncompliance nated CREMS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/04 2pp

- -800/220J37 IE Into Rept 50-0/7/80-02 on 800421-22 No noncompliance nated Major artis inspected logs records review audit functions operator requalification training facility procedures surveillance 7, experiments ZWETZIG.G B Region 5, San Francisco, Office of the Director FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/03 6pp
- 1007180705 Forwards IE Circular 80-14. "Radioactive Contemination of Plant Demineralized Water Sys & Rosultant Internal Contemination of Personnel" Na written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80706/24 10
- DOKET 90-7/ CATHOLIC UNIV OF AMERICA RESEARCH REACTOR
- 007160/92 Forwards IE fircular 60-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIUR.B H Region 1. Philadelphia, Office of the Director 60706/24 10
- 207210126 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required ORIER.8 H Region 1, Philadelphia. Office of the Director 80/06/25 |
- RKET 50-83 UNIV OF FLORIDA TRAINING REACTOR
- Inspection reports, IE Bulletins & correspondence
- 107170166 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY J.P. Region 2. Atjanta, Office of the Director 80/06/24 to
- ICKET 50-HZ WESTINGHOUSE CRITICAL EXPERIMENT
- Inspection reports, IE Bulletins & correspondence
- 907280454 Forwards IE Insp Rept 50-087/80-04 on 600610-11 No noncompliance world DAVIG.A B Region 3, Chicago, Fuel Facility & Materials Bafoty Branch 80/06/23 2pp
- U00/280457 If Insp Rept 50-087/80-04 on B00610-il No noncompliance noted Major dreas inspected emergency planning including training drills alarms & evacuation procedures ORECR, V. F5960, T. H. Region D. Chicago, Office of the Director 80/06/19 App
- 07170626 Forwards 1E Circular 80-14, "Radipactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J 0 Region 3. Chicago. Office of the Director 80/06/24
- CHET 50-89 GENERAL ATOMIC CO
- Security, modical, emergency & fire protection plans
- OPENDORN Requests resulution of outstanding fee issues for certain physical solurity-related documents & weergency plans Med ded 790910 re 790220 gward training plan obboilted by GA Co never answered

 MILLER, N. D. License Fee Nanagement Branch 80/07/16 2pp
- Inspection reports, IE Bullotins & correspondence
- 07180274 Forwards It Circular 80-14, "Radioartive Contamination of Plant Demineral) rad Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELWEN.R H Rogion 5, San Francisco. Office of the Director BO/06/24 in

- DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
- @ Inspection reports: IE Bulletins & correspondence
- 8007160803 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " Nu written response required CRIER B H Region i. Philadelphia. Office of the Director 80/06/24 ip
- 8007210155 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.D H Region I, Philadelphia, Dffice of the Director 80/08/25 ip
- DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR
- O Inspection reports. IE Bulletine & correspondence
- 8007170137 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Rosultant Internal Contamination of Personnel " No written response required G'REILLY, J P. Region 2. Atlanta, Office of the Director 80/06/24
- DOCKET 50-106 OREODN STATE UNIV
- Q Inspection reports. IE Bulletine & correspondence
- 8007240361 Forwards IE Insp Repts 50-106/80-02.50-243/80-03 & 70-0971/80-01 on 800630-0701 No nuncompliance noted Encis withheld (ref 10CFR2 790) NORDERHAUO, L.R. Region 5, San Francisco, Safeguards Dranch 80/07/14 2pp
- 8007150599 Forwards "Final Decommissioning Rept.OR State Univ AON-201 Reactor, License R-51 " Describes changes to physical security plan required in conjunction w/decommissioning WANO, C II Oregon State Univ BO/07/10 3pp
- --B007150562 "Final Decommissioning Rept.OR State Univ AGN-201 Reactor license R-31" * Oregon State Univ B0/07/09 10pp
- DOCKET 50-111 NORTH CAROLINA BIATE UNIV RESEARCH REACTOR
- Q Inspection reports. IE Bulletins & correspondence
- 8007170164 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Dumineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/06/24 to
- DOCKET 50-112 UNIV OF OXLAHOMA REBEARCH REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8007180292 Forwards II Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required ENGELMENTRY Region 5, San Francisco, Office of the Director 80/06/24 ip
- DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- B007170629 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Deminaralized Water Sys & Rosultant Internal Contamination of Personnel" No written response required KEPPLER, J G Region 3. Chicago. Office of the Director B0/06/24 in
- DOCKET 30-123 UNIV OF MISSOURI RESEARCH REACTOR
- O Inspection reports. IE Bulletine & correspondence
- 8007170646 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEFPLER. J G Region 3. Chicago, Office of the Director 60/06/24

8007220122 Ack receipt of IE Circular 80-14 & distribution to deatheralized water sys staff PLANJE, T J Missouri, Univ of, Rolla 80/06/30 lp

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR
P Operating license stage documents & correspondence

8007230498 Forwards proposed Tech Specs & operator requalification program for research reactor per License R-62 CURTNER, A P Virginia Tech 80/0//18 3pp

~-8007230503 Proposed Tech Specs.App A, re safety limits & limiting safety sys settings.limiting conditions for operation, surveillance requirements, design features & administrative controls wirginia Tech 80/07/18 33pp

A Inspection reports: IE Bulletins & correspondence

B007170181 Forwards IE Circular 80-14, "Madicactive Contamination of Plant Demineralized Water 84s & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8007290468 Forwards ORO-4207-13, "Sixteenth Progress Rept of TX A&M Univ Nuclear Science Ctr." 1979 RANDALL.J D Texas A & M Univ 80/07/25 1p

--8007290475 "Bixteenth Progress Rept of TX A&M Univ.Nucleor Science Ctr." 1979 DATEB,C F , FELT1:D E , TAFT, J P Toxes A & M Univ ORO-4207-13 BO/06/30 BOpp

NOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

O Inspection reports, 16 Bullstins & correspondence

8007170185 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Bys & Resultant Internal Contamination of Personnel "No written response required D'REILLY, J P Region 2. Atianta, Office of the Director 80/06/24

DOCKET 50-133 HUMBULDT BAY PUMER PLANT, UNIT 3

8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for olectrical cables EISENHUT, D O Division of Licensing 80/06/29 89pp

8007300340 Renews 800606 request for all repts prepared by TERA Corp Related correspondence BROWN:L J Janes, Brown & Clifford 80/07/02 2pp

8007180398 Forwards Hoodward-Clyde Consultants 800701 itr outlining status of geologic & seismic invostigations re facility & status of work accomplished during May & June, 1920 per ASLB 790619 order Certificate of Svc encl FURBUSH, M. H., CRANE, P. A., LOCKE, R. F. Pacific Cas & Electric Co 80/07/15 App

80072903B6 Advises that info & ropts requested in 800606 & 0702 itrs were not included in agreement for informal discovery reached at 800603 hearing Info will be incorporated w/Woodward-Clyde filing to be made by 801001 LOCKE,R F Pacific Oas & Electric Co 80/07/18 2pp

P Operating license stage documents & correspondence

8007100049 Notification of 800507 meeting w/util in Rethesda.MD to discuss proposed continuation & examing preliminary results of seismic & geologic investigation ROUNEY.VL Uperating Reactors Branch 3 80/04/20 ip

8007010469 Responds to 800507 ltr re add1 TM1-2 requirements Schedule for meeting requirements will be proposed following resolution of selsmic issues

CRANE, F A Pecific Gas & Electric Co 80/06/26 lp

a Inspection reports, IE Bulletins & correspondence

BOD725066B Responds to 1E Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Behedule for submittal of info will be proposed when seismic issues currently under study have been resolved CRANE, P A Pacific Gas & Electric Co 80/03/05 ip

B007230662 Responds to IE Bulletin B0-03 Util does not use charcoal tray adsorber cells CRANE.P A Pacific Oas & Electric Co 80/03/31 in

8007230016 Forwards response to IE Bulletin 80-02 Feedwater spargers & thermal sloeves mfg by Marvin Engianeering Co are not used in facility CRANE, P A Pacific Gas & Electric Co 80/04/22 3pp

B007140584 Forwards IE Bulietin B0-13. "Cracking in Core Spray Spargers " Written response required ENGELKEN.R E Region 5. San Francisco, Dffice of the Directur B0/05/12 ip

8007020242 Forwards IE Info Notice 80-22, "Broakdowns In Contamination Control Programs " No written response required ENGELKRH,R II Region 5, San Francisco, Dffice of the Director BO/05/28 ip

BOO7220237 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No writton response required ENGELKEN, R H Region 5, Ban Francisco, Office of the Director BO/06/10 Ip

8007140412 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Voi Capability " Written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/12 Ip

B007170084 Forwards IE Insp Rept 50-133/80-02 on 800520-22 No noncompliance noted CREWS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/12 2pp

--800717008B IE Insp Rept 50-133/80-02 on 000520-22 No noncompliance noted Major areas inspected operations organization & administration, follows on IE bulietins & circulars & insependent insp.
CARLSON, J D , MOURILL, P J Region S, San Francisco. Office of the Director STERNOCRO, D Region S, San Francisco. Reactor Operations Nuclear Support Branch 80/06/10 App

BO07020474 Forwards IC Circular 80-15, "Less of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ENGELKEN.R H Region 5, San Francisco, Diffice of the Director BO/06/20 ip

8007180287 Forwards IE Circular 80-14, "Radioartive Contamination of Plant Demineralized Hater Bys & Resultant Internal Contamination of Personnel" No written response required ENGELKELR H Region 5, San Francisco, Office of the Director 80/Q6/24 ip

8007230387 Forwards IE Dulletin 80-16, "Potential Misapplication of Resembert Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-16 piso encl No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/27 1p

8007310468 Responds to 1E Bulietin 80-11 re masonry wall design Resolution of problems will be performed following completion of geologic investigation CRANE,P A Pacific Cas & Electric Co 80/07/10 lp

R Periodic operating reports & related correspondence

8007150568 Forwards monthly operating rept for June 1980 NECKS,E D Pacifir Gas & Electric Co 80/07/07 ip

--8007150573 Monthly operating rept for June 1980 BAUN,P W Parific Gas & Electric Co 80/07/03 App

OKET 50-134 WORKESTER POLYTECH 1995T RESEARCH REACTOR

07180B20 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No uritten lesponse required GMICR. 8 il Region I. Philadelphia. Office of the Director G0/06/24 lp

07210144 Forwards IE Info Notice 80-24, "Low Level Radwasto Bursal Criteria" No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/06/25 lp

CRET 50-135 WALTER REED RESEARCH REACTOR

Operating license stage documents & correspondence

07100399 Responds to 800229 lts which expressed opposition to ACRS recommendation to restructure SEP Role of licenaess in program will expand Ltr forwarded to Commissioners
DENTSOLAR Office of Nuclear Reactor Regulation. Director 80/06/18 4pp

8007100420 Expresses opposition to AFRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined, cost in dollars & manyower would increase dramatically SCHAFFSTALL, R SEP Owners Group B0/02/29 2pp

CKET 90-139 UNIV OF WASHINGTON RESCARCH REACTOR

Inspection reports: IE Bulletins & correspondence

07180269 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKENR H Region 5. San Francisco, Office of the Director 80/06/24 lp

07310523 Forwards IE Insp Rept 90-139/00-03 on 800641 No noncompliance noted Encl withhold (ref 10CFRZ 790) NORDERHAUG.L R Region 5, San Francisco, Safeguards Branch 80/07/22 2pp

ICKET 50-142 UCLA TRAINING REACTOR

Security, medical, emergency to fire protection plans

107160240 Forwards Amend 1 to physical socurity plan for protection of SNN of moderate strotegic significance Plan withheld (ref 10CFR2 790)

CATTON. I. WEOST, W. California, Univ. of, Los Angeles BD/07/03

Adjudicatory correspondence

NOTOPOLET Response to Committee to Bridge the Gap June 1980 potition to Intervene Patitioner relied on case law not wholly applicable to instant action Allegations re aspects are not specified w/clarity & detail W/Certificate of Eve HELMICKS. RIDHAARS D. L., HELMICKS, California, Univ of, Los Angelos 80/07/07 13pp

07290708 Order schuduling 800718 prehvaring conference in Los Angeles-CA Committee to Bridge the Cap suppl to 800592 petition to intervene must be served by 800888 & Univ of CA response by 800702 Public invited w/o limited appearance BOMERS-E S Atomic Safety and Licensing Deard Panel 80/07/21

Inspection reports. IE Bulletins & correspondence

107180261 Forwards IE Circular 80-(4, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELERNR H Region 5. Gan Francisco, Office of the Director 80/06/24 lp

DOCKET 50-150 ONTO STATE UNIV RESEARCH REACTOR
P Operating license stage decomonts & correspondence

8007020169 Advises that 800110 revision of security plan has been approved Forwards Amend 9 to License R-75 identifying currently approved security plan MILLER.J R Standardization & Special Projects Branch 80/06/16 2pp

--800/020174 Amend 9 to License R-75 identifying currently approved physical security plan MILLER, J R Standardization & Special Projects Branch 60/06/16 2pp

G. Inspection reports, IE Bulletins & carrespondence

8007170636 Forwards IE Circuler 80-14, "Radioactive Contamination of Plant Demineralized Hater Sys & Resultant Internal Contamination of Personnel "No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/06/24

8 Reportable accurrences. LERs & related correspondence

BOO70103B3 informs that reportable nomcompliance itom exists involving Tach Opec 2 1 Air conditioner for multichennel analyzer room not tied to emergency switch in control room Action initiated to have air conditioner tied to control room REDMOND. R F Obio State Univ 80/06/17 2pp

DOCKET 50-191 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports. JE Bulletins & correspondence

6007170644 Forwards IE Circular 80-15. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/24 lp

DOCKET 30-152 FLORIDA WEST COAST NUCLEAR GROUP INC
O Inspection reports. IE Bullotins & correspondence

8007170638 Forwards IE Circular 80-14. "Radinactive Contamination of Plant Deminerolized Mater Bys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/24 is

DOCKET 30-195 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8007220566 Forwards revised site emergency plan for final NRC approval All requested changes & revisions, including App M, have been made Revised Palisades site emergency plan will be forwarded within wh M/o oncl
JURY.M J Consumers Power Co 80/06/09 ip

0007230470 Forwards revised emergency plan. App M HARTMAN, C. J. Consumers Power Co. 80/06/12 ip

--8007230479 Revised emergency plan; App M * Consumers Power Co H0/06/01 18pp

8007170042 Notifies that FEMA/NRC steering committee reconsidered size of emergency planning zono for water cooled reactors of less than 250 kM thormal & adopted encl position Proposed rule & NUREQ/0.054/FEMA-HEP-1 will be modified in conformance CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/13 3pp

8007010473 Discusses proposed changs to 10CFR50 adding requirement for fire protection plan at facilities Farwards comments on rule, supplementing consultant comments Questions appropriateness of rule, since rule reopens resolved issues HOFFHAN.D P Gonsumers Power Co 80/06/27 Bpp

8007140391 Forwards Revision 2 to 790220 security plan Plan withheld (ref 100FRz 790) HOFFMAN D P Consumers Power Co 80/07/08 1p

- B007250406 Forwards scenario of emorgoncy exercise conducted on B00624 at Big Rock Point Util has agreed to critique exercise & provide action plan to identify deficiencies & indicate corrective actions

 AXELSON.W L Emergency Preparedness Licensing Branch 80/07/11
- 800722034! Forwards add! info re suitability, training & qualification plans in response to NRC 800515 & 0406 requests Info withheld (ref 10CFR2 790)
 HOFFFMAN D P Consumers Power Co 80/07/17 1p
- BOO7280570 Responds to 791129 request for info re evacuation time estimates in site emergency plan Evacuation clear time for O- to 10-mile area around Palisades estimated at approx 2 hrs in summer & winter HDFFMAN.D P Consumers Power Co 80/07/23 1p
- 8007300439 Forwards revised safeguards contingency plans Plans withheld (ref 100FR2 770)
 HOFFMAN,D P Consumers Power Co 80/07/24 1p

Q Adjudicatory correspondence

- B007310243 Forwards Commission 80052/ memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for eflectrical cables EISENHUT, D Q Division of Licensing 80/06/25, 89pp
- 8007100031 Forwards Christa Maria second set of interrogatories in spent fuel pool expansion proceeding M5 Jordan 800626 ltr to JORAN.W 8 Sheldon, Harmon & Weiss 80/06/26 Spp
- --8007100037 Becond set of interrogatories directed to util Requests identification of witnesses intended to be called recontentions of ASLB 800117 order & quostions of ASLB 800327 memorandum & order Related correspondence

 JORDAN, W B Christa-Maria JDRDAN, W S Bheldon, Harmon & Weiss 80/06/26 12pp
- 8007110556 Ack receipt of 800401 telegram submitted on behalf of Concerned Citizens for Charlevoix Aroa, requesting immediate shubdown of plant Notice of petition will be published in FR DENTON, D R Office of Nuclear Reactor Regulation, Director 80/06/24 2pp
- --B007110563 Notice of request for action on B0040i patition filed on behalf of Concerned Citizens for Charlevoix Area requesting immediate shutdown of plant for alleged failure to meet containment integrity requirements

 DENTON:HR Office of Nuclear Reactor Regulation, Director B0/06/26 2pp
- BO07150052 Becand set of interrogatories directed to J 0'Neill Requests identification of inadequacy alleged in Contention IIE-3 recriticality analysis PP Stepton B00708 ltr to J 0'Neill encl
 BTEPTOE, P. P. Consumers Power Co STEPTOF, P P Isham, Lincoln & Spale B0/07/09 3pp
- 8007170334 Response to Christa-Maria et al 800626 interrogatories Identifies witnesses intended to be called to Christa-Maria Contentions 2 & 3 & J O'Noill Contentions ID-5.11A.11B.11E-4 & IIF60 Whaffidavits.bibliographies & Certificate of Bvc MODRE.J E Hearing Branch 2 80/07/13 18pp
- --8007170355 Transcript of 800506 brinfing in Washington DC re BEP Pp 1-48 Key to topic status listing w/definitions encl * Commission 80/05/06 104pp
- 8007230612 Forwards NRC rules of discovery, JR Weeks rept re Christa Maria Contention 3 & Board notification re spent fuel pool and Emergency plan available at LPDR Other related document sent on 791115 W/o encl JDNEB, 8 W Hwaring Branch 2 80/07/22 ip
- 8007300468 Discusses NHC evaluation of util compliance w/certain THI-2 Lessons Learned Task Force requirements Evaluation in Section 2 1 6 b is irrelevant to O'Neill's Contention IIE-4 Clerifies statement to avoid contraversy at hearing QALLO, J Isham, Lincoln & Beale 80/07/23 2pp

- 8007300464 Requests that NRC furnish Refs 1.7-14 noted on Page / of NRC evaluation of several SEP issues refacility Evaluation is directly applicable to D'Noill Contention IID reflight of military arretaft near plant OALLO
- 9007310400 Notifies that responses to Set II interrogatories will be sent next wk O'NETILLIJ Affiliation Unknown 80/97/25 Ip

H General correspondence

- 8004300355 Comments on operation of power plant which is within ten-mile radius of residence Decisions re plant should be based on safety & health of people, not profit of util NEUMAN, R. F. Affiliation Unknown 80/04/22 ip
- 8006270181 Responds to 800429 request for info re M LeMiera inquiry about amount of nuclear waste disposed in State of MI Spent fuel from four operating MI reactors stored onsite NRC evaluated status of waste mgt in 1977 W/related FR excerpts DIRCKS.W J Office of the Executive Director for Operations 80/05/09 10pp
- 8007180180 Ack recoipt of RF Neuman 800422 lts re operation of plant NRC considers safety of public as paramount in evaluation of licensees CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/25 to
- B007140236 Responds to 800424 ltr re proposed expansion of spent fuel pool Describes NRC review process for mods proposed by licensee DOE efforts to select site for spent fuel storage underway CRUTCHFIELD.D Operating Reactors Branch 9 80706726 3pp
- 8007080255 Criticises safety practices at util re containment bldg dome & increased storage of spent fuel rods CALDHELL.E Affiliation Unknown 80/07/02 Ip
- 8007310532 Responds to 1tr re concerns of C Cox.of Indamer Co.about accuracy of local news article Facility granted exemption from 10CFR50 46 feilure criterion requirements on 760526 No other exemptions in effect Related order encl DIRCKS Office of the Executive Director for Operations 80/07/24 2no
- --B007310535 Hemorandum & order granting facility exemption from 10CFR50 46 failure criterion requirements Dissenting opinion of Commissioner Gilinsky enc)
 HDYLE, J C Office of the Secretary of the Commission 76/05/26
 1906

J Insurance & indemnity information

- B007150479 Forwards Endorsement 81 to ANI Policy NF-117 F0STER.5 C Merch & McLennan, Inc., M & M Nuclear Consultants, Inc Div B0/07/10 Ppp
- 8007280597 Requests revision of Indemnity Agreement B-22 Revision provides more detailed description of site location & is current description used by util in insurance policies w/Nuclear Mutual Ltd & American Nuclear Insurance HOFFMAN.D P Consumers Power Co. 80/07/22 Jpp
- 8007310422 Requests revision to Indomnsty Agreement N-22 to provide more detailed description of site location & current description used in insurance policies w/Nuclear Mutual Limited & American Nuclear Insurance HOFFMAN.D P Consumers Power Co 80/07/22 2pp
- --B007310425 "Big Roc? Point Site Property Survey," Sheet 3
 * Consumers Power Co 80/07/22 lp
- P Operating license stage documents & correspondence
- BOO703033 Advises that licensing activities will be coordinated by W Paulson, as result of reorganization of Offr of Nuclear Reactor Regulation Description of reorganization entil CRUTCHFIELD,D Operating Reactors Branch 5 80/06/02 28pp
- 8007290541 Forwards NUREG-0619. "BHR Fordwater Notice & Control Rod Drive Return Line Notice Cracking." for review & comment CRUTCHFIELD.D Deprating Reactors Branch 5 80/06/04 2pp
- BOO7010111 Forwards finel rule published in BO0509 FR amending 10CFR30 71 to require periodic updating of FSARs Compliance is not required until completion of REP CRUTCHFIELD. D Operating Reactors Branch 5 BO/06/10 App

- 107010700 Forwards info no util request to expand spent fuel storage capacity Info includes integrity of structural elements in event of boiling in pool 5 provision of makeup water to pool if containment cannot be entered HOLFMAN, D.P. Cunsumers Power (o. 80/06/20 P48pp
- 207010447 Application for amend to License DPR-6 to change Fech Specs to add operability & werveillance testing requirements for fire protection equipment (n 80/06/27 2pp Consumers Power (c 80/06/27 2pp
- 800/010451 Proposed changes to fech Apers 3 7 11 P & Table 3 3-8 to add operability & surveillance testing requirements for fire protection equipment # Consumers Power to 60/06/27 500 itection equipment Consumers Power Co - 80/06/27 - 5pp
- ADVOTOPIO Forwards response to NRC 800.208 requests for info necessary to calculate containment temp & pressure after accident & date re-protected tRAA mass & energy release Exion Rept XN-NP-78-93 contains most recent LOCA enalysis of accility ROTFHAND P Consumers Power Co 80/06/70 tipp
- O703026H Forwards response to NRC 800507 request 1e applicability of concerns addressed in GT 800221 ltr re generic post-accident operating conditions at LHRs $_{\rm HR}$ 1007FMAN, D $_{\rm P}$ Consumers Power Co. 100707/01 $_{\rm Pp}$
- 77290373 | arwards evaluation of SEP lapse VIII-9 re electrical penetrations of reactor containment Requests reply within 10 days if as-built facility differs from licensing basis
- imbumëd CRUICHFTELD,D M Operating Reactors Branch 5 80/07/01 12pp
- 2290,64 Farwards evaluations of SFP Tapics 111-10 A.VII-11 A & FIII-3 D re-electrical sys & components Requests reply within 60 days if au-built facility differs from licensing RUTCHFIELD. D M Operating Reactors Branch 5 80/07/03 11pp
- 7/110204 Forwards application to amend License DPR-6 Tech Specs & monded Tech Specs for enc! GPFMAN DP (onsumers Power to HO/0//07 ip
- 007110209 Application to amend license DPR 6 revising necessity of attaining rold shuddown while conducting containment spray systemetrical test test DEWITTER II Consumers Power (a. 80/07/07 Epp.
- 007110210 Tech Spech 11 3 3 4 5 11 4 3 4 8 Table 11 4 3 4 For containment spring sys ... Consumers Power Co. 80/07/07 ... Spp
- 2200076 Responds to 19000114 for to J Abpains objecting on behalf of where of plants under MP review, to current plans for specified review of environ qualification of electrical support forwards applicable meaning and a corder NTER, H R (Office of Nuclear Regulation, Director NTONAH R (H
- 7300 ToD Forwards NUE-1957. "Abroctural Analysis of Spent Fool Pool nor & Concrete Due to Conlant Sys Forlors," DP Hoffman 10620 ltr to DM CrottePteld & related NUT of Million rs in support of 794423 application for Of amend ALCO, J. Isbam, Jincolo & Beaic. 100/07/24. http
- PBOD33 Disturses status of testing re-dograded gold voltage & equacy of status of status of testing to substitution sys voltages.
 P 79073 5 BOD34 immilments firsting complete Evaluation data in progress Rougainess to open frem forthcoming FEMAN.D.P. Consumula Power Co. 80/07/75 1p
- nupertion reputes. If Bulletinu 4 correspondence
- 140917 Forwards It Hutletin (R) 1% "Cracking in Gore Spray argers " Unitten response required "PEER J O Region 3. Chirago Office of the Director 80/09/12
- 140485 Forwards II Insp Rept 90 154780-(% on 805505-08 No Tompetkane nuted

 ISHMAN, R.F. Region 3, Chicago, Reseto: Operations Nuclear Support

 19477 Epp
 - nup Rept 50 159/HO-OA On (MOSOS-OB No noncompliance rous inspitted followsp of stems in MARGO-OS78 trap BOARD-M-Weneting Bothewen NRC 5 licenses BARFR.K N Region 3. Chirago, Office of the Director

- 8007020051 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/05/28
- 8007010115 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written tesponse required KEPPLER, J O Region 3. Chicago. Office of the Director 80/05/29
- BOO722018B Forwards IC Info Notice 80-26, "Evaluation of Contractor Oh Programs" No written response required REPPLER.J O Region 3, Chicago, Office of the Director BO/06/10
- B007020676 Forwards site-specific & generic questions re QE disc cracking indications per 800109 meeting & IE Info Notice 79-37 on Westinghouse low pressure turbines discs cracks Response requested within 30 days W/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 5pp
- B007140317 Forwards IE Dulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/12
- 8007240004 Forwards IE Insp Rept 50-159/80-04 on 800303-14 & notice of violation re health physics appraisal Bignificant appraisal findings encl KEPPLER.J & Region 3. Chicago. Office of the Director 80/06/13
- --8007240006 Natice of violation from insp on 800303-14
 * Region 3, Chicago, Office of the Director 80/0 80/06/05 1p
- --8007240009 IE Insp Rept 50-i55/80-04 on 800303-14 Noncompliances noted inadequate affishift radiation protection coverage & inadequate high radiation area access controls GREGER.L R. CARBAUGH.E H. Region 3. Chicago. Office of the Biroctor Fisher.W.L. Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/06/05 39pp
- 8007030034 Forwards IE Bulletin 60~15, "Possible Loss of Emergency Notification 8ys (ENS) W/Loss of Offsite Power " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/1 Region 3. Chicago, Office of the Director 80/06/18
- B007020552 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Carculation Cooldown " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/20
- B007170474 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J Q Rogion 3. Chicago, Office of the Director 80/06/24
- 8007010313 Responds to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Actuation drawings for designated syshave been reviewed All equipment except for listed Items e & i meet acceptable criteria based on drawings HOFFMAN.ID P Consumers Power Co 80/06/25 3pp
- 8007140430 Ack receipt of 800609 ltr informing NRC of steps taken to correct violations noted in II Insp Rept 50-155/80-03 Region 3 comments re util response to Item I encl Util position not fully responsive HIND, J A Region 3, Chicago, Safeguards Blanch 80/06/26 ip
- 8007230312 Forwards IE Bulletin 80~16. "Potential Misapplication of Rosemount Inc Mudels 1151 & 1152 Pressure Transmitters WEither A or D Output Codes " Written response required IC Circular 80~16 also encl No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/2 80/04/27
- 8007180575 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR." will start at 12 01 AM on 800708 Test should be completed within 20 days Requests notification of malfunction KEPPLFR.J G Region 2. Atlanta, Offsce of the Director 80/07/07
- 8007140424 Forwards Bechtel Power Corp "Sixty-Day Response to IE Bulletin 80-11 " HOFFMAN, D.F. Consumors Power Co. 80/07/09 1p

- --B007140428 "Blity-Day Response to IE Bulletin 80-11 " * Bechtel Corp 80/06/30 32pp
- 8007140444 Responds to IE Builetins 80-08. "Examination of Containment Liner Penetration Welds " Penetrations w/flued head design & designs w/containment boundary butt welds between penetration sleeve & process piping total 114 HOFFMAN, D P Consumers Power Co 80/07/09 4pp
- 8007150664 Responds to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Design of scram discharge vol sys different from Browns Ferry Tests required by bulletin completed & acceptable WITHROW. G C Consumers Power Co 80/07/10 2pp
- 8007160458 Responds to IE Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ" Review of sys complete Documentation available during onsite insp HOFFMAN, D. P. Consumers Power Co. 80/07/11 ip
- 8007;80424 Forwards response to 1E Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Screen at BUR" Primary sys will not exceed design pressure in event of ATMS
 HOFFMAN.D P Consumers Power Co 80/07/14 15pp
- 8007220432 Forwards affirmation for 800710 response to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at 8WR " Affirmation should be attached to response HOFFHAN, D P Consumers Power Co 80/07/16 2pp
- 8007220472 Responds to NRC 800626 request for add1 info re IE Insp Rept 50-155/80-05 Requests issue of plant security sys operability be maintained as an open item pending resolution MOFFMAN, D P Consumers Power Co 80/07/16 14
- 8007230465 Submits add1 response to IE Insp Rept 50-155/80-05 Requests that plant security sys operability issue be maintained as open item pending resolution by NRC & licensee HOFFMAN, D P Consumers Power Co 80/07/16 ip
- 8007230516 Responds to NRC 800613 ltr re violations noted in IE Inap Rept 50-155/80-04 Corrective actions util will establish new supervisory training position to insure uppraded radiation protection training of plant staff HOFFHAN, D P Consumers Power Co 80/07/18 8pp
- 8007240017 Forwards affirmation inadvertently omitted from 800709 response to IE Bulletin 80-11, HOFFMAN D P Consumers Power Co 80/07/18 2pp
- 8007250373 Responds to IE Dulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Four pressure transmitters of identified type wist. One has output code in question HOFFMAN, D P Consumers Power Co 80/07/21 2pp
- B007290606 Responds to IE Bulletin 80-17. "Failure of 76 of 183 Control Rods to Fully Insert During Scram at BWR " Emergency operating procedures have been revised to assure appropriate operator actions in event of scram HQFFMAN,D P Consumers Power Co 60/07/23 3pp
- 8007290691 Responds to IE Bulletin BO-17. "Failure of 76 of IBS Control Rods to Fully Insert During Scram at BWR " Hod implemented to provide alternate vent path to containment bldg atmosphere HOFFRAN.D P Consumers Power Co 80/07/25 2pp
- R Periodic operating reports & related correspondence
- B007080346 Farwards monthly operating rept for June 1980 HARTMANIC J Consumers Power Co BD/07/01 ip
- --8007080348 Monthly operating rept for June 1980 HIMEBAUCH,N Consumers Power Co 80/07/01 3pg

- DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACIOR

 G Inspection reports, IE Bulletins & correspondence
- 8007170662 Forwards IE Cyrcular 80-14 "Radynactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region J. Chicago, Office of the Director 80/06/24 to
- R Periodic operating reports & related correspondence
- BOO7310403 Forwards "Annual Operating Rept for License R-74" For Jul 1979-June 1980 CASHMELL R J Misconsin. Univ of Hadison BO/07/11 1p
- --8007310405 "Annual Operating Rept for License R-74," for Jul 1979-June 1980 GABHMELL,R J. Wisconsin, Univ. of, Hadison 80/07/11 150pp
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

 Q Inspection reports, IE Bulletins & correspondence
- B007160B03 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/24 | Ip
- GD07210155 Forwards IC Info Notice 80-24, "Low Level Radwaste Burnal Criteria" No written response required ORIER.D H Region 1. Philadelphia, Office of the Director 6D/06/25 lp
- DOCKET 50-160 GEURGIA INST OF TECH RESEARCH REACTOR

 G Inspection reports, IE Bulletins *c correspondence
- B007170158 Forwards IE Circular 80-14. "Radinantive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24 to
- DOCKET SO-163 GENERAL ATOMIC COMPANY
- F. Socurity, medical, emergency & fire protection plans
- B0072300B1 Requests resolution of nutstanding fee issues for certain physical security-related documents & emergency plans demo dtd 770910 re 770220 quard training plan submitted by GA Co never answered MILLER, W O License Fee Management Branch 80/07/16 2pp
- O Inspection reports, IE Bulletins & correspondence
- 800/1802/4 Forwards IE Circular BO-14. "Radinactive (ontamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELMEN, R B Region 5, Sun Francisco. Office of the Director BO/06/24 ip
- DOCKET 50-166 UNIV OF MARYLAND REGEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- B007160813 Forwards IE Circular 80-14. "Rudspartive Contamination of Plant Demineralized Water Ays & Resultant Internal Contamination of Personnel " No written response required ORIER.D H Region I. Philadelphia, Office of the Director 80/06/24 ip
- 0007210143 Forwards IF Info Notice 80-24. "Inw Level Radwasts Durial Criteria" No written response required GRIER.B W. Region), Philadelphia, Office of the Director BD/06/25 1p
- R Periodic operating reports & related correspondence
- BD07230495 Submits operations rout for June 1979 to June 1980 BELGHER, R. L. Maryland, Univ. of B0/07/01 4pp

Inspection reports, IE Bulletins & correspondence

007160833 Porwards IE Gircular 60-14. "Madicattive (ontamination of Plant Seniografized Water Sys & Resultant Internal Contamination of Personnel " No written response required CRIER B H Region 1. Philadelphia, Defice of the Director 8070624 | Ip

007210296 Forwards It Info Notice 80-24. "Low Level Radwasto Burial Criteria " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/25 Lp

OCKET 50-171 PBACH BOTTON ATOMIC POWER STATION, UNIT ! Security, medical, emergency & fire protection plans

007140}61 Forwards input for fire protection review 10 fire detection, water suppression, combustible control, gas suppression, fire doors & interior hose stations
MALL.R E Brookhaven National Laboratory 80/06/20 Opp

General correspondence

107020147 Requests consideration of site visit by Atomic energy Council of Taiwan on 600825-26 Council interested in observing waste mgt activities Cooperation will be major contribution to NHC exchange arrangement LAFLEUR, J D Assistant Director for International Cooperation 80/03/13 3pp

07280549 Responds to 800320 ltr re JL & MS Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for facility emergency planning mosting issued on 800331 W/Randell ltrs BIRCKS.W J Office of the Executive Director for Operations B0/07/02 7pp

CKEY 30-182 PURDUE UNIV RESEARCH REACTOR

Inspection reports. IE Bulletins & correspondence

9717064: Forwards JE Circular BD-14, "Radivective Contamination of lant Demineralized Water Sys & Resultant Internal Lantamination of Personnel "No written response required (EPPLER, J G Region 3: Chicago, Office of the Director 90/06/24

MET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
Operating litense stage documents & correspondence

1719028 Forwards Amend 3 to License TR-5, matery evaluation & notice f issuance & availability ||ILLER.JR | Standardization & Special Projects Dranch | 80/06/30

007150035 Amend 3 to License TR-5, incorporating Tech Specs contained in App A re reactor core MILLER, J R Standardization & Special Projects Branch 80/06/30 4se

007150037 Gafety evaluation supporting Amend 3 to 1 iconst TR-5 * Office of Nuclear Reactor Regulation, Director 80/06/30 2pp

07150041 Notice of issuance & availability of Amend 3 to License TR-5 MILLER, J R Standardization & Special Projects Branch 80/06/30 2pp

Inspection reports. IE Bulletins & correspondence

7160829 Forwards IE Circular H0-14. "Radioartive Contamination of lant Demineralized Water Sys & Resultant Internal antamination of Personnel" No written response required SICR. I H Region I. Philadelphia, Office of the Director 3/06/24 ip

7210149 Forwards IC Info Notice 80-24. "Low Level Hadwaste Burial riteria" No written response required SIER.B H Region 1. Philadelphia. Office of the Director. 3708/25 1p

DOCKET 90-184 UNIV OF MISSOURI RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

B007170653 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written tesponse required KEPPLER. J G Raginn 3, Chicago, Office of the Director 80/06/24 1p

S Reportable occurrences. LERs & related correspondence

8007080266 #O on 800709, emergency generator failed to start when starting sequence initiated Caused by starter motor trip due to lack of fuel in emergency generator day tank Tank refilled & sight glass added to verify tenk fuel level MCK, IHBEN, J. C. BRUGGER, R. M. MISSOURI, Univ. of, Columbia 80/06/02

80070802A0 RO on B00516, automatic regulating blade drive mechanism failed Caused by which spot on drive gear Gear drive assembly replaced & blade cycled through full travel to assure proper operation MCKIBBEN, J. C. BRUGGER, R. M. Missouri, Univ. of, Columbia 80/06/04, 2pp b

B007140351 RO on 800616, while verifying sample loading of triple-tubed sample irradiated facility located in ctr test hole, one tube was found missing 2-inch long spacer No unreviewed safety question existed during period of operation MCKIBBEN. J C . ALGER, D M Missouri, Univ of, Columbia 80/07/07 2pp

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR
O Inspection reports, IE Bulletins & correspondence

B007180278 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Hoter Bys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director B0/06/24 1p

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC F Security, medical, emergency & fire protection plans

B007020490 Forwards Amend 7 to License R-95, reflecting state 790205 security plan MILLER, J R Btandard zation & Special Projects Branch 80/06/17

--B007020493 Amend 7 to License R-95, reflecting state 790205 security plan
MILLER, J.R. Standardization & Special Projects Branch B0/06/17

P Operating license stage documents & correspondence

8007020470 Forwards Amend 7 to License R-95, reflecting state 790205 security plan MILLER, J R Standard Pation & Special Projects Branch 80/06/17 2pp

--8007020493 Amend 7 to License R-95, reflecting state 790205 security plan MILLER, J. R. Standardization & Special Projects Branch 80/05/17 2pp

BOD7090272 Advises NRC that rept re nonpower reactor physical protection upgrado requirements will be submitted to NRC by BOD801 DIMEGLIO, A F Rhode Island, State of 80/07/01 ip

G Inspection reports. It Bulletins & correspondence

8007160837 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region I. Philadolphia, Office of the Director 80/06/24 ip

8007210161 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80708/25 ip

1

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

O Inspection reports, IE Bullstins & correspondence

8007160822 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region i, Philadelphia, Offace of the Director 80/06/24 ip

8007210127 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER/B H Region 1, Philadelphia, Office of the Director 80/06/25 ip

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

I Financial information

8007010001 Forwards audited financial statements consisting of statements as of 791231 & 781231 w/auditor rept Affidavit only encl CONTIP L Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/05/28 3pp

P Operating license stage documents & correspondence

8007020515 Ack receipt of Apr 1980 monthly rept & 800530 ltr re insp & evaluation of facility high level storage sys Copies will be dispatched to encl external distribution list HAUCHEV.C J. Advanced Fuel & Spent Fuel Licensing Branch 80/06/04 3pp

B007020078 Questions intentions, as colicensee, re NFS 760922 announcement of withdrawal from commercial reprocessing NRC considers plans for future of facility to be joint responsibility CUNNINOHAM, R. Division of Fuel Facility & Materials Safety 80/06/05 Spp

B007140580 Requests info re future licensing & operation of facility Requests reply within 30 days CUNNINGHAM, R. E Division of Fuel Cycle & Material Bafety B0/06/05

8007230117 Urges strong support & cooperation in Rockwell Hanford Operations program to insp & evaluate condition of high lavel liquid waste storage sys NFB insistence on prior agreement impedes gathering of necessary info DIRCKS.W.J. Office of Nuclear Material Safety & Bafeguards 80/06/26. 4pp

B007090384 Notification of B00813 meeting w/vendor in Silver Spring. MD to discuss progress of NFB efforts to process technical info needed to provide basis for future decontamination & decommissioning of facility
HAUCHREY, C. J. Advanced Fuel & Spent Fuel Licensing Branch
B0/06/27 3pp

B007140193 Bummary of 800618 meeting w/NFS & NY State Energy R&D Authority in Bilver Spring. HD re decontamination & decommissioning technical data processing & potential tornado generated missile consequences HAUD/NEY. C. J. Advanced Fuel & Spent Fuel Licensing Branch. B0/06/27. RSpp

8007280069 Notification of 800717 meeting w/NF8 & NY State Energy R&D Authority in Silver Spring.MD to discuss indemnification & liability issues associated w/implementation of work by Rockwell Hanford Operations HAUDHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80/07/09 ip

Q. Inspection reports. IE Bulletims & correspondence

B007020714 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Offsite Power " Written response required QRIER, B.H. Region 1, Philadelphia, Office of the Director, 80/06/18 lp.

8007140783 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required ORIER, B H. Region 1, Philadelphia, Office of the Director 80/06/24, ip

8007210159 Forwards 1E Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/06/25 tp

E0070B0246 Advises that emergency notification sys telephone does not require ansite auxiliary power supply in response to IE Builetin SC-15 Test to verify independent power will be conducted within next 30 days, during scheduled power outage DUCKHORTH, J P Nuclear Fuel Services. Inc., West Valley Reprocessing Plant 80/06/26 ip

800721002B Advises that onsite auxiliary power supply is not required in response to IE Bulletin 80-15 Insp revealed that emergency notification sys does not receive power from plant supply Test of emergency diesel generator will be conducted DUCHMORTHL P Nuclear Fuel Services. Inc (subs of Getty Oil Co) 80/06/26 1p

8007230441 Forwards response to NRC 800617 ltr re deficiency nated in IE Insp Rept 50-201/80-04 on 800519-21 Encl withheld (ref 100FR2 790)

BUCKWORTH, J P Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)
80/07/01 in

DOCKET 50-206 BAN ONDERS NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

BOO7080271 Advises that revisions to safeguards contingency plan will be submitted by 800718 BABKIN.K P Southern California Edison Co 80/07/02 19

O Adjudicatory correspondence

8007020426 Requests that entl listing of addl petitions, received from CA residents under lOCFR2 206 for Pacility seismic conditions, be added to 791213 ltr on file All have received NRC 791213 ltr wife notice of receipt of petition SMITH, H Decrating Reactors Branch 5 80/06/21 3pp

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 87pp

H General correspondence

8007020181 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800804-05 Council interested in observing waste mpt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR: J D Assistant Director for International Cooperation 80/05/13 3pp

8007170049 Forwards US map showing location of reactors licensed to operate, under const or planned in response to 800526 ltr M McCann added to mailing list of petitioners requesting facility shutdown CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/02 ip

--B007170051 "Nuclear Power Reactors in US "
* Energy Dept of 79/10/31 2pp

~-8007170057 Requests map of UB showing location of nuclear reactors licensed to operate, under const or planned Expresses opposition to facility operation MCCANN.M Affiliation Unknown 80/05/26 in

P Operating license stage documents & correspondence

BOO7110401 Forwards response to 790808 request for info re adequacy of offsite power sys & onsite distribution sys BABKIN, K P Bouthern California Edison Co 80/05/01 13pp

BOO7100097 Forwards Amend 49 to Livense DPR-13, safety evaluation & notice of issuance & availability
CRUICHFIELD, D M Operating Reactors Branch 5 80/05/29 8pp

--g007100102 Amend 49 to License DPR-Li, replacing ref to cycle-specific ejected red worths & predicted fuel centerline temps CRUYCHFIELD. DM Operating Reactors Dranch 5 607/05/29 Sap

--B007100105 Safety evaluation supporting Amend 49 to License DPR-13 * Office of Nuclear Reactor Regulation, Director 80/05/29 4pp

- 8007100107 Notice of issuance & Availability of Amend 19 to License
 - CRUTCHFIELD.D N Operating Reactors Branch 5 80/05/29 2pp
- JO701017/ Forwards final rule published in 800509 FR amending 1007830 71 to require periodic updating of FSARs Compliance is not required until completion of SEP GRUTCHFIELD, D Operating Reactors Branch 's 80/06/10 5pp
-)0/020190 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIFLD. D.M. Operating Reactors Branch 5 80/06/11 2pp
- 107230099 Requests submittal of proposed Tech Spec changes providing for redundancy in dociny heat removal capability in all modes of operation Model Tech Spect which would provide acceptable resolution oncl for guidance EISEMEUT, D O Division of Licensing 80/06/11 62pp
- 07100399 Responds to 400229 Itr which expressed apposition to ACRS recommendation to restricture SEP Role of licenses in program will expand Ltr forwarded to Commissioners UEATONIA R Office of Nuclear Reactor Regulation. Director 40/06/18 4pp
- B007:00420 Expresses upposition to ACN9 recommendation to restructure SEP for SEP numers to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCNAFFSTALL.R SEP Owners Group 80/02/29 2pp
- 17010465 Forwards add1 info re SEP Topic VI-4 & drawings re untaliment isolation sys.in response to NRC 800417 & 0612 the Drawings available in Central Files only 'ACKIN.K P Southern California Edison Co 80/06/23 4pp
- 7220158 Forwards Amend 50 to License DPR-13 % notice of issuance &
- RUICHFIELD, D Operating Resitors Branch 5 80/06/25
- 007220162 Amend 30 to License DPR-i3 revising certain provisions to reflect changes in corporate organizational structure CRUICHFIELD.D Decrating Reactors Branch 5 80/06/25 lipp
- 00/220163 Notice of issuance & availability of Amend 50 to License CRUTCHFIELD.D Operating Reactors Branch 5 80/06/25 2pp
- 7020362 Forwards Amend 91 consisting of Proposed Change 93 to Tech pers for Apps A & B of License DPR-13 Proposed Change 93 equests mod of Tree Spers to revise definition of operable to comply w/definition of STS IETCH, R Southern California Edison Co 80/06/30 ip
- 007020366 Application for Amend 91 to License DPR-13, consisting of Proposed Change 93 modifying Tech Specs to revise definition of "operable" to comply w/definition used in STS Certificate of Svc oncl
 DIETCH.R Southern California Edison Co 80/06/30 7pp
- 10/0203/2 Proposed Tech Spec 3 O for Limiting Conditions for Operation (General) & revision to Section 1 O re
- Bouthern California Edison Co E0/06/30 Spp
- 090734 Urges extension of comment period for NURE9-0577 & 800519 and until 800915 More stringent requirements broader pticability & EPRI study results worked addl time LMAN,D W. San Diego Gas & Electric Co. 80/06/30. Ip
- 170693 Advises of NRC acceptance of Amend 3 to Topical Rept, F-1-A, "QA Program " Topical rept must be referenced in apter 17 of SAR ASS.N P. Quality Assurance Branch 80/07/01 in Quality Assurance Branch 80/07/01 ip
- 200001 Requests submittal of application for amend to license nsisting of Tech Spec changes & ticense conditions PHR wel Tech Specs & Model license conditions for TMI=2 stong Loarned Cabeyory & items encl for guidance SFRNUT.D Q Division of Licensing 80/07/02 69pp
- 180172 Forwards NRC evaluation of SEP Topics III-10 A.V-II A. -7 C | & VIII-3 B Evaluation will be input to safety sessment unless changes needed to reflect as-built JTCHFIELD.D M Operating Reactors Branch 5 80/07/03

- 8007150579 Forwards "Post-Accident Sampling Sys, Capabilities & Description," & drawings, in response to open item identified in NRC 800502 ltr re implementation of THI lessons learned requirements Drawings available in Central Files only BASKIN, K P Southern California Edison Co 80/07/09 2pp
- --8007150587 "Post-Accident Sampling Sys, Capabilities & Description "
 * Southern California Edison Co 80/07/09 5pp
- B007280098 Forwards NRC evaluation of control rad guide thimble wear issue Based on review. issue is resolved for 14x14 fuel assemblies designed by Wastinghouse CRBFCHFIELD.D Uperating Reactors Brench \$ 80/07/10 4pp
- 8007210053 Notification of 800724 meeting w/util in Rosemead.CA to discuss results of Imperial Valley Dct 1979 earthquake analysis, using Unit i analytical modeling technique ROCD:H Licensing Dranch 3 80/07/11 2pp
- 8007280076 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review, to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON, HR Office of Nuclear Reactor Regulation, Director 80/07/16 4pp
- BOO7280486 Act receipt of NRC responses to Marine Review Committee 79:009 rept re facility radiological monitoring program evaluation Detailed response will be submitted following matl review FISCHER, N.L. California, State of 80/07/18 is
- 8007290706 Submits responses to Items 1.2 & 3 of NRC 800620 ltr re failure of saltwater cooling sys Response to Item 4 will be submitted by 800804 MAYNES,J O Bouthern California Eduson Co 80/07/24 5pp
- Q Inspection reports, IE Bulietins & correspondence
- 8007290883 Responds to IE Builetin BO-O4, "Analysis of PHR Main Steam Line Break W/Continued Feedwater Addition " Scoping studies will be completed by 800513 Studies include effect of auxiliary feedwater runout & impact of other energy sources OTTDSON.X L. Southern California Edison Co. 80/05/12 2pp
- 8007250636 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "Failure mode & effects analysis indicates loss of vital bus or util bus will not prevent achieving cold shutdown OTTOSON, H. L. Bouthern California Edison Co 80/05/15 5pp
- 8007280072 Suppls 800512 response to IE Dulletin 80-04, "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition" Results of scoping studies & reportability determination will be forwarded when available OTTOSDN, H L Southern California Edison Co 80/05/19 2pp
- 8007110174 forwards IE Inso Rest 50-204/60-13 on 800423-25 & notice Officiality & Materials Bafety BOOK.HE Region 5. Ban Francisco. Fuel Facility & Materials Bafety Branch 80/05/23 2pp
- --B007110179 Notice of violation from insp on B00423-25
 * Region 5. San Francisco. Office of the Director B0/05/23 1p
- --B007110184 IE Insp Rept 50-206/BD-13 on 900423-25 Noncompliance noted failure to follow radiation protection procedure required by Tech Specs BDOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch JDUKOFF.P., NORTH,H B Region 5, San Francisco, Office of the Director 80/05/23 22pp
- 8007180014 Forwards 1E Insp Rept 50-206/80-11 on 800421-25 No SPENCER.O 8 Region 5, Ban Francisco. Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8007180018 IE Insp Rept 50-206/80-11 on 800421-25 No noncompliance 007180018 1E Insp Rept 50-206/80-11 on 800421-35 No noncomplance noted Major areas inspected inservice inspectities and the frequency activities and pressurizer safety valves, licenses activities & personnel interviews activities & personnel interviews HAIST, D.P. NARBUT, P.P. Region 5, San Francisco, Office of the Director, DODDS, R.T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch, 80/05/23 7pp
- 8007020246 Forwards IE Info Notice BO-22, "Breakdowns in Contamination Control Programs " No written response required ENGELKEN,R H Region 5, App Francisco, Office of the Director 80/09/28 ip

- B007250355 Responds to IE Bulletin B0-12, "Decay Heat Removal Sys Operability " One event reported in LER 77-03, involved degradation of docay heat removal capability for several minutes Emergency & main procedures revised BASKIN, R P Southern California Edison Co
- 8007310162 Forwards review summary in response to IE Bullotin 80-05 re Vacuum conditions resulting in damage to chemical vol control sys holdup tanks Bys reviewed are adequately designed to protect against vacuum conditions BASKIN.K P Southern California Edison Co 60/06/09 3pp
- 8007220249 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 60/06/10
- 8007030010 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director R H Region 5. San Francisco. Office of the Director 1p 80/06/18
- B007020478 Forwards 1E Circular B0-13, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/04/20
- 8007240318 Forwards IE Insp Rept 50-206/80-15 on 800528-30 No SPENCER, O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 60/06/20 2pp
- --B007240326 IE lnsp Rept 50-206/80-15 on B00528-30 No noncompliance noted Major areas inspected insplantivities per IE Bulletin 79-13 recracking in feedwater sys piping HAIST, D P Region 5, Ban Francisco, Office of the Director DODDS, R T Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch B0/06/20 5pp
- 8007180292 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN,R H Region 5, Ean Francisco. Defice of the Director 80/06/24 ip
- GOO7230374 Forwards IE Bulletin GD-16. "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Cirtular GD-11 also encl No written response required ENGELKEN,R H Region 5, Ban Francisco. Office of the Director GD/06/27 1p
- 8007240267 Forwards IE Insp Rept 50-206/80-18 on 800519-22 No noncompliance noted
 CREW9.J L Region 5, San Francisco, Reactor Operations Nuclear
 Support Branch 60/06/27 2pp
- --8007240273 IE Insp Rept 50-206/80-18 on 800519-22 No noncompliance noted Major areas inspected surveillance of pipe support & restraint sys & IE bulletin/circular followup HARN, A J Region 5, San Francisco, Office of the Director FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/27 3pp
- BOO725035B Responds to IE Bulletin 79-03A: "Longitudinal Weld Defects in ASME 9A-312, Type 304 Stainless Steel Pipe " Review of piping revealed no piping sys exceeding code allowable design stresses OTTOSON, H L Southern Celifornia Edison Co BO/06/30 2pp
- B007170561 Ack receipt of B00616 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/80-12 CREWS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/01 ip
- ~8007170545 Responds to NRC 800528 ltr re violations noted in IE Insp Rept 50~204/80-12 Corrective actions instrument & test technicians cautioned that use of procedures necessary Required signs poated PAPAY,L T Southern California Edison Co 89/04/16 4pp
- --B007170369 Forwards 1E Insp Rept 30-206/80-12 on 800405-0502 & notice of violation CREMB.J L Region 5. San Francisco, Reactor Operations Nuclear Burport Branch 80/09/28 2pp
- --B007170573 Notice of violation from insp on 800405-0502
 * Region 5, San Francisco, Office of the Director 80/05/28

- --800/170579 IE Insp Rept 50-206/80-12 on 800405-0502 Noncompliance noted failure to follow procedure re source range instrumentation detectors & to implement fully IOCFR20 posting requirements for indication area MILIERIL Region 5. Sen Francisco. Office of the Director FAULKENDERRY. 8 Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/05/28 App
- 8007100217 Rotification of 800710 meeting w/util in Bethesda, MD to discuss results of steam generator insps & corrective actions
 - NOWICKI, 8 J Operating Reactors Branch 5 80/07/07 1p
- 8007300339 Forwards IE Imsp Rept 50-206/80-20 on 800616-19 No noncompliance noted CREWS, J L Region 5, San Francisco. Reactor Operations Muclear Support Branch 80/07/09 2pp
- ~-8007300343 JE Insp Rept 50-206/80-20 on 800616-19 No noncompliance noted Major areas inspected major maint major surveillance. IE bulletin & circular followup & independent insp effort HORN.A J Region 5. San Francisco. Office of the Director FAULKENDERRY.B Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/09 3pp
- 8007230282 Ack receipt of 600701 ltr informing NRC of steps taken to correct viplation noted in It Insp Rept 50-206/R0-14 BDOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 60/07/16 ip
- --8007230287 Responds to NRC 800611 ltr ie violation notod in IE (nsp Rept 50-206/80-14 Corrective actions frequency of air samples inside steam generators has been increased to once per shift PAPAY,L T Southern California Edison Co 80/0//01 2pp
- --8007230291 Forwards IC Imsp Rept 50-206/80-14 on 800415-18 & notice of violation Dork H E Region 5, San Francisco, Fuel Fucility & Materials Safety Branch 80/06/11 2pp
- --8007230295 Notice of violation from insp on 800415-18 * Region 5, San Francisco, Office of the Director 80/04/10 1p
- --8007230297 IE Insp Rept 50-206/80-14 on 800415-18 Honcompliance noted failure to perform airborne activity surveys DDOM: HE Region 5. San Francisco. Fuel Farility & Materials Safety Branch CURTISJ R. NURIGH. H. Region 5. San Francisco. Office of the Director 80/06/10 4pp
- R Periodic operating reports & related correspondence
- 8007010216 Forwards "1979 Annual Operating Rept. San Onofre Nuclear Openerating Station." Vol 5. Biological & Oceanugraphic Data Analyses Includes ETS for Unit 1. Const & preoperational monitoring programs for Units 2 & 3 BASKIN.X P Southern California Edison Co 80/06/25 ip
- --8007010225 "1979 Annual Operating Rept. San Undere Nuclear Generating Station," Vol 5, Biological & Oceanographic Data Analysis "Includes ETS for Unit 1, const & preoperational monitoring programs for Units 2 & 3 * Brown & Caldwell * Lockheed Environmental Sciences * Marine Biological Consultants. Inc., 80-AD-100 80/06/25
- B007100262 Forwards "Biological 3 Oceanographic Data Analyses ETS for Unit 1.Const Monitoring Program for Units 2 & 3. Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthoplankton." Vol 5 for 1979 OTTOSON. H.L. Southern California Edison Co. 80/06/30 2pp
- --8007100268 "Biological & Oceanogrophic Data Analyses ETS for Unit i.
 Const Monitoring Program for Units 2 & 3. Prooperational
 Monitoring Program for Units 2 % 3 & Special Study re
 Ichthyplankton: "Vol 5 for 1979
 AMBERG.P J Brown & Caldwell ANDERSON.D 7 Lockhoed
 Environmental Sciences ANGRAD.K Harine Biological Consultants,
 Inc. 80-RD-100 80/06/30 800pp
- 8007150599 Forwards monthly operating rept for June 1980 CURRAN.J M Southern California Eduson Co 80/0//08
- --8007150605 Monthly operating rept for June 1980 JOY, J. M. Southern California Edison Co. 807 80/07/08

- S Reportable occurrences, LERs & related correspondence
- 8004240300 PNO-V-80-18 on 800310, salt water cooling sys out-of-sve for approx 41 minutes due to broken pump shaft North pump started but discharge valve falled to open Auxiliary pump started but failed due to pump priming sys FAULKENDERRY. D. Region 5. San Francisco. Diffice of the Director 80/03/11 2pp
- 800703002; PNO-V-80-033 on 8005;9, film badge data of subcontractor employee indicated exposure exceeding quarterly limit Self-trading dosimeter readings indicated significantly lower exposure Validity of data being examined CURTIS; J. HENSLAHEKI, F. Region 3, San Francisco, Office of the Director ED/66/EO 1p
- 80072(059) Requests add1 info re failure of saltwater cooling sys on 800310 Info about events where multiple equipment failures occur & contributing factors would be beneficial LAINAS.G C Assistant Director for Safety, Assessment 80/06/20 4pp
- 8007010533 Forwards LER 80-027/03L-0 OTTOSON,H L Southern California Edison Co 80/06/23 2pp
- --8007010537 LER 80-027/03L-0 on 800528 radiographic examination of feedwater sys welds inside containment found seven unacceptable defects including lack of penetration porosity & slag inclusion Caused by original const
- 8007080403 Forwards LER 80-028/01T-0 QTTOSON,H L Bouthern California Edison Co 80/07/01 2pp
- --8007080410 LER 80-028/017-0 on 800612, during IE Bulletin 79-14 imap, inadequate pape guides discovered in safety injection sys injection innes caused by improper installation Guides will be modified before return to svc CURRAN.J 8 Bouthern California Edison Co 80/06/30 1p
- 8007280371 Forwards LER 80-024/01T-T OTTOSON.H L Southern California Edison Co 80/07/16 3pp
- --8007280396 LER 80-024/01T-T on 800516, while performing radiographic examination of main steam lines, six welds found w/indications in excess of code Apparently caused by const error Weld w/cracks in root repaired CURRAN, J M Southern California Edison Co 80/07/16 ip
- --8007230404 "Significance of Circumferential Weld Indications in 24-Inch Hain Steam Piping at San Onofre Nuclear Generating Station Unit 1 - Fracture Analysis " CIPOLLA.R C. GROVER.J L. EGAN.G R Aptech Engineering Services 80/07/31 44pp
- 2007280375 Forwards LER 80-029/01L-0 OTTOSON.H L. Southern California Edison Co. 80/07/21 2pp
- -8007280382 LER 80-029/01L-0 on B00708.RCS dilution inadvertently occurred while containment integrity was unestablished Caused by leaking inflatable plugs in generators Generator channel heads discontinued * Southern California Edison Co 80/07/21 1p
- COCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR
 Inspection reports, IE Bulletins & correspondence
- 007160796 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel " No written response required, GRIER, B. H. Region 1. Philadelphia, Office of the Director 80/06/24 ip
- 007210193 Forwards IE Info Notice 80-24, "Low Level Radwasto Ourial Criteria " No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/06/25 ip

- DOCKET 50-213 HADDAM NECK PLANT
- F Security, medical, emergency & fire protection plans
- B007180196 Forwards NRC 800425 itr to all power reactor licensees, in response to 800529 ltr re emergency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD,D M Operating Reactors Branch 5 80/07/07 2pp
- --8007180208 Requests copy of NRC 800425 ltr to utils updating requirements for emergency response facilities & technical support ctr List of plants w/approval to use closed-circuit supervision link w/technical support ctr requested HICKEY.A E American Institute for Research in the Dehavioral Sciences 80/05/29 ip
- 8007010337 Comments on proposed tule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Suggested revisions to App R w/justifications encl COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.N G Connecticut Yankee Atomic Power Co COUNSIL.N G Northeast Utilities 80/06/16 31pp
- 8007030356 Comments on proposed rule 10CFR50 requirements for exceed those necessary to resolve generic 188005 & are excessively specific k restrictive Forwards alternative App R fire protection program COUNSIL.W G Connecticut Yankso Atomic Power Co 80/06/16 16pp
- 8007090231 Forwards responses to NUREG-0654 criteria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withheld (ref 10CFR2 790) COUNSIL: 0 Connecticut Yankee Atomic Power Co COUNSIL: N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/30 2pp
- B007170425 Confirms position discussed in B00624 telcon re safeguards contingency plans NRC requested revisions are ill-advised & unnecessary Specifics of plan implementation can be detailed in procedures CDUNSIC.N G Connecticut Yankee Atomic Power Co COUNSIL.H G Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/07/01 2pp
- B007210445 Dutlines actions to be undertaken & completed per QH Smith & J White 800703 telcons w/MO Counsilire emergency preparedness capabilities identified in 800623-0703 appraisal NRC must be notified in 24-h if not agreeable ORIER, B H Region I. Philadelphia, Office of the Director 80/07/03 2pp
- O Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refire protection for electrical cobles
- I Financial information
- B007140355 Forwards estimated 1980 cash flows for facility O'CONPER, L.A. Connecticut Yankee Atomic Power Co. 80/06/27 4pp
- P Operating license stage documents & correspondence
- 8007010122 Forwards final rule published in 800509 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD, D Operating Reactors Branch 5 80/06/10 5pp
- GOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance

 EISCNHUT, D G Division of Licensing. GO/O6/11 62pp
- 8007240056 Informs that NRC has completed review of info provided in util 780626,791017 & 800423 ltrs re positive displacement vibrations Operation will not cause fatigue failures in chemical vol control sys NRC considers matter closed LAINAS, G C Assistant Director for Safaty Assessment 80/06/16
- --B007240061 Safety evaluation re charging pump vibrations Fatigue failures not anticipated by operation of metering pump * Assistant Director for Safety Assessment 80/07/16 ip

Ł

- BOO7100379 Responds to 800229 ltr which expressed opposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON, HR Office of Nuclear Reactor Regulation, Director 80/04/18
- ~-BOO7100420 Expresses opposition to ACRS recommendation to restructure BEP for BEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase drematically SCHAFFSTALLIR SEP Owners Oroup 80/02/29 2pp
- 8007020569 Clarifies 800506 response to NRC 791030 request for info concerning Lessons Learned Task Force Item 2 1 8 a.improved post-accident sampling capability Info ensures accurate NRC understanding of design philosophy & antent COUNSIL.W O Connecticut Yankee Atomic Power Co CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23. 3pp
- 8007250694 Advises that NRC has approved conceptual design of post-accident sampling sys Lists several addl areas which should CRUTCHFIELD, D M Operating Reactors Branch 5 BO/07/01 3pp
- BOO7280103 Forwards request for add1 info re adequacy of station alactric distribution sys voltages Response requested within 45 days of 1tr receipt CRUTCHFIELD, D Operating Reactors Branch 5 80/07/01 5pp
- 80072500Di Requests submittal of application for amend to license consisting of Tech 8pec changes & license conditions PWR Model Tech Specs & Model I license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIRENHUT, D O Division of Licensing 80/07/02 69pp
- 8007280150 Advises that NRC has completed review of plans to implement Item 2 1 4 of Category A leasons learned requirements Measures taken constitute acceptable resolution of concerns expressed in NRC 800507 itr GRUTCHFIELD.D Operating Reactors Branch 5 80/07/02 2pp
- 9007280180 Forwards request for add1 info re testing of reactor trip sys & engineered safety features Response requested by 801201.
- CRUTCHFIELD.D Operating Reactors Branch 5 80/07/07 3pp
- B007210239 Submits corrected Page 1 of Attachment 3 to util 800321 ltr re low pressure disc integrity, summery of arguments from B00328 meeting w/NRC re disc integrity & answers to sitespecific general questions COUNSIL, W G Connecticut Yankee Atomic Power Co 80/07/08 10pp
- 8007280206 Forwards NRC evaluation of SEP Topics III-10 A.V-11 A.VI-4. VI-7 C 1 & VIII-3 B Evaluations will be input to safety assessment, unless changes needed to reflect as-built conditions CRUTCHFIELD, D Operating Reactors Branch 5 BD/07/08 31pp
- BOO7250672 Forwards NRC evaluation of control rod guide thimble wear in PMR Issue resolved for 13X15 fuel assemblies designed by Heatinghouse CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/10 App
- B007300324 Discusses B00630-0701 site audit by NRC & Franklin Research Ctr re environ qualification of electrical equipment, SEP Topic III-12 Info provided & requested during audit enci Proprietary portion withheld (ref 100FRZ 790) COUNSIL, W 0 Connecticut Yankee Atomic Power Cp 80/07/14 23pp
- -8007300331 Forwards summary of results of evaluation of environ qualifications of safety-related electrical squipment Evaluation indicates that electrical equipment at facility would perform safety functions to allow safe shutdown SWITZER, D.C., FEE. W.F. Connecticut Yanker Atomic Power Co. 78/03/06 22pp
- --8007800338 Forwards "Special T4 Teledyne Valve Operator Performante of Unit in Steam Environ Indicated in Westinghouse Equipment Spec 0676258 "Rept updates & supplements Table A-1 attached to NRC 780306 ltr COUNSIL, W C Connecticut Yankee Atomic Power Co 78/07/27. 2pp
- --8007300342 "Special T4 Teledyne Valve Operator Performance of Unit in Steam Environ Indicated in Westinghouse Equipment Spec Q676288 "
 - Connecticut Yankes Atomic Power Co 69/10/20 | 11pp
- 8007240053 Application for amend to License DPR-61 re App A.safety Tech. Specs & App B.ETS, reflecting title changes within util organization COUNSIL, N G Connecticut Yankes Atomic Power Co 80/07/16 3pp

- ~~B00724005B Propused amended App A safety Tech Specs Section 6, reflecting title changes within util organization # Connecticut Yankee Atomic Powor Co B0/07/31 7pp
- ~-8007240062 Proposed amended App B.ETS Section 5 1 5, reflecting title changes within util organization
 * Connecticut Yankee Atomic Power Co 80/07/31 4pp
- B007240047 Application for amend to Licenso DPR-61 re ETS Section 2 4 3 1(1), modifying gaseous release rate limit to one averaged over 1-b period COUMSTL-N 0 Connecticut Yankee Atomic Power Co 80/07/16 3pp
- --B007240070 Proposed amended ETG Section 2 4 3L(1).modifying gaseous release rate limit to one averaged over 1-h period
 * Connecticut Yankee Atomic Power Co 80/07/31 2pp
- BOO72BOO76 Responds to BOO31B ltr to J Ahearne objecting on behalf of owners of plants under SEP revious to current plans for espedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON. HR Diffice of Nuclear Reactor Regulation, Director BO/07/16 4pp
- 8007280673 Requests extension of comment period re NUREG-0577.
 "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports." until COUNSIL.W G Northeast Utilities 80/07/21 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007020140 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs " No Written response required GRIER,B H Region i. Philadelphia. Office of the Director 80/05/28 ip
- B007010275 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required ORIER.B M Region 1. Philadelphia. Office of the Director B0/05/29 ip
- 8007170494 Responds to IE Dulletin 80-12. "Decay Heat Removal Sys Operability " Based on noted reviews of sys & procedures, no changes to existing procedures or hardware are considered necessary COUNSILUM Connecticut Yankee Atomic Power Co 80/06/09 3pp
- 8007210559 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required ORIER, B || Region 1, Philadelphia, Office of the Director 80/06/10 | ip
- 8007160344 Forwards IE Info Notice 80-27, "Degradation of Reactor Coplant Pump Stude " No specific action or response GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/06/11 ip
- 8007230361 Forwards 1E Insp Rept 50-213/80-10 on 800519-23 No noncompliance noted MARTIN.W G Region 1. Philadelphia. Safeguards Branch 80/06/41
- -8007230366 IE Insp Rept 50-213/80-10 on 800519-23 No noncompliance noted Major areas inspected security plan, security organization & protected & vital areas physical barriers Details withheld (ref 10CFR2 790)
 LADUM,R H Region i, Philadelphia, Diffice of the Director DEVLIN,J W Region 1, Philadelphia, Safeguards Branch B 80/06/02
- 80071703R0 Responds to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls "Three facilities will have completed mods per IE Bulletin 80-06 by 810101 List of equipment & status of criteria encl COUNBIL. W Connecticut Yankee Atomic Power Co COUNBIL. W G Northeast Utilities 80/06/13 43pp
- 8007020692 Forwards IE Dulletin 80-15, "Possible Loss of Emergency Notification 8ys (EMS) W/Loss of Offsite Power " Written response required GRIER.8 H Region 1, Philadelphia. Office of the Director GRIER, B H R B0/06/18 1p
- 8007180137 Submits reply to IE Bulletin 60-08 re examination of containment liner penetration welds Duo to absence of abnormal conditions no further action planned CQUNSIL.W 0 Northeast Utilities 80/06/19 lipp

- 8007020494 Forwards IE Circular 80-15, 'Loss of Reactor Coclant Pump Cooling & Natural Circulation Conlideum " No written response required
 GRIEGIB H Region L. Philadelphia. Office of the Director
 80/06/20 lp
- B007180578 Responds to 16 Bulletin 80-10 Plant design & operation reviewed to identify normalisative sys which could become radinactive through sys interface Routine sampling program exists for each sys to identify unmonitored releases COUNSIL, W G Connecticut Yankee Atomic Power Co 80/06/23 P BD/04/23 2pp
- 8007i60690 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel" No written response required GRIER, 8 H Region 1. Philadelphia. Office of the Director 80/06/24 tp
- 8007210174 Forwards IE info Notice 80-24, "Low Level Radwaste Borial Criteria " No written response required GRIER,B M. Region 1. Philadelphia. Office of the Director 60706/25 1p
- 8007230107 Forwards IE Bulletin 80-ib. "Potential Misapplication of Rusemount Inc Models \$i51 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-lb also encl No written response required GRIER, B H Region i, Philadelphia. Office of the Director 80/06/27 2pp
- 8007160347 Responds to teleph request for info re results of turbine inspiperformed during 1980 refueling outage Util intends to conduct next inspiduring 1981 outage based on submitted info Confirms that rated power for operation is appropriate COUNSIL.N G Connecticut Yankee Atomic Power Co 80/07/09 2pp
- 8007230411 Forwards rept on Core 9 fuel insp as part of jost-irradiation exam of fuel assemblies GRAVES,R H Connecticut Yanier Atomic Power Co BO/07/16 7pp
- " Periodic operating reports & related correspondence
- 8007180390 Forwards monthly operating rept for June 1980 GRAVES,R H Connecticut Yankee Atomic Power Co 80/0 80/07/11
- --8007180395 Monthly operating rept for June 1980 r Connecticut Yankee Atomic Power Co 80/07/11 12pp
- Reportable occurrences. LERs & related correspondence
- 1007020536 PNO-I-80-092 on 800616, while performing test on low pressure NO/20030 PNU-1-80-072 on 800416, while performing test on tow pressure safety injection pumps under runout conditions, partial vacuum was drawn on RWST Licensee investigating apparent cause Plant shut down for refueling until 800712 SMITH, RH , KEIMIG, RR , BRUNNER.E J Region 1. Philadelphia, Office of the Pirector 90/06/16 ip
- 00708007/ RD 80-04 on 800622 during draindown of refueling cavity to refueling water storage tank grab sample indicated radioactivity in tank exceeding ETS Caused by crud displaced into RMR conlant sys by testing GRAVES.R H Connecticut Yankee Atomic Power Co 80/07/01 2pp
- 007140359 RO on 800622 during draindown of refueling water storage tank cavity, grab sample indicated that curies exceeded ETS limit of 10 Caused by crud displacement into residual heat removal sys Tank placed on recirculation mode ORAVES,R H Connecticut Yankee Atomic Power Co 80/07/01 2pp
- 107090321 Forwards LER 80-010/017-0 ORAVES.R H Connecticut Yankee Atomic Power Co 80/07/04 1p
- 8007090325 LER 80-010/017-0 on 800621.per IE Bulletin 79-14.five seignactupe supports determined missing from two separate
 HPSI lines & two addl supports found w/excess gap Caused by
 failure to install restraints required by piping drawing
 HDMAS,R H Connecticut Yantee Atomic Power Co BO/07/04 2pp
 - tanned release occurred from waste % out stack Total of 3 9% of Tech Spec
 - Region 1, Philadelphia, Office

- B007270535 RO on B00717, while investigating reactor coolant pump seal water flow problems, seal water supply bypass Valve 2 failed, allowing full flow through valve Valve was clamped closed, coolfoum commenced & valves replaced GRAVES, R H Cannecticut Yankoe Atomic Power Co 80/07/21 2pp
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8007020D10 forwards summary of 790706 mgt meeting re status of schedule for upgrading facility radiation protection program Minutes do not contain proprietary info Neeting identified need for plant health physics audit program ORIER. Il H Region 1. Philadelphia. Office of the Director 80/06/04
- 8007030399 Forwards summary of 790830 mgt meeting re planned & completed improvements in licensee radiation protection program Licensee is on schedule for upgrading program Summary contains no proprietary info ORIER, BH Region i, Philadelphia, Office of the Director 80/06/04 3pp
- B00711011B Summary of B00422 meeting w/util re emergency planning NOWICKI/B J Operating Reactors Branch 5 B0/06/06 App
- 8007010399 Confirms 800413 mgt meeting in King of Prussia, PA to discuss actions taken & planned by licenses to improve radiation actions taken & planned by licensee to improve radiation protection program at facility GRIER, S.H. Region 1, Philadeiphia, Office of the Director GRIER, S H R 80/06/11 1p
- 8007020193 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD,D M Decrating Reactors Branch 5 80/06/11 2pp
- 8007070262 Notifies of delay in implementation schedule for installation of alternate water supply per safety evaluation Table 3 I Caused by engineering & manpower problems Alternate water supply will be completed by 801101 FINFROCK, I R Jersey Central Power & Light Co 80/07/02
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for alectrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- B0071B0060 Responds to B00311 request for info needed for fuel cost study Forwards excerpts of HASH-740, HASH-1224, HASH-1230, HASH-1400, NUREG-0020 (Vol 4, Number 1), NUREO-0480, NUREO-0512, NUREG-0517, NUREG-076R-1060 & FES DENTON, H R Office of Nuclear Reactor Regulation, Director DENTON, H R Off 80/05/14 153pp
- --- B007180063 Requests documents containing info needed for fuel cost study HILGER,W Affiliation Unknown 80/03/11 2pp
- P Operating license stage documents & correspondence
- B007230028 Summary of 800207 mpeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007100394 Forwards Amend 48 to License DPR-16, eafety evaluation & notice of issuance & availability CRUTCHFIELD, D Operating Reactors Branch 5 80/04/02 2pp
- --8007100401 Amend 48 to License DPR-i6 approving max average planar linear heat generation rate limits & multiplier for five & four recirculation loop operation & deleting specs for fuel no longer in core CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 14pp
- --8007100405 Safety evaluation supporting Amend 48 to License DPR-14 * Office of Nuclear Reactor Regulation, Director 80/06/02 4
- -- B007100408 Notice of issuance & availability of Amend 48 to License CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 2pp

- B007290954 Forwards NUREO-0619, "BWR Fredwater Nozzle & Control Rod Drive Roturn Line Nozzle Cracking," for review & cumment CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/04 2pp
- 8007010113 Forwards final rule published in 800909 FR amending 10CFR90 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD, D Operating Reactors Branch 9 80/06/10 9pp
- 8007030300 Urgss response within 30 days to 800303 request for add1 info re util 790925 & 1101 ltrs concerning degraded grid voltage & adequacy of electric distribution sys voltages Seven points need clarification
 LAINAS, O.C. Assistant Director for Safety Assessment 80/06/16-30p
- 8007100399 Responds to 800229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licensoes in program will expend Ltr forwarded to Commissioners DENTON, HR Defice of Nuclear Reactor Regulation. Director 80/06/18 4pp
- ---8007100420 Expresses opposition to ACRS recommendation to restructure SEP for SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically BCHAFFSTALL.R SEP Owners Group 80/02/29 2pp
- BO0701046B Notifies of intent to commit to implementation of addi TMI-2 related requirements when acceptance criteria is developed Forwards util initial assessment of applicability of 32 requirements
 FINFROCK.I R Jersey Central Power & Light Co 80/06/23 6pp
- B007140524 Notification of 800630 meeting w/util in Bethesda,MD to discuss util proposed action concerning visual indications of cracks in core spray piping at facility PAULSDN,W A Operating Reactors Branch 5 80/06/26 2pp
- B007030216 Submits schedule for mods to improve testability of plant sys as committed to in 781122 request for partial exemption from code requirements Instrument air/nitrogen sys & damineralized water sys mods completed FINFROCK, I R Jorsey Central Power & Light Co 80/06/27 1p
- B007070113 Forwards responses to questions raised at B00630 meeting re NRC evaluation of two possible cracks in core spray piping Also forwards suppl to util B00627 evaluation BARTNOFF,B Jersey Central Power & Light Co B0/07/02 App
- 8007180113 Notifies that 790921 & 1004 route approval request for spent fuel shipment is subj to license fee Review of requests was completed on 800416 MILLER, W O License Fee Management Branch 80/07/03 lp
- 8007250716 Forwards NRC evaluation of SEP Topics III-10 A, V-11 A, VI-7 C 1, VIII-3 B & VIII-4 Evaluation will be input to safety assessment unless changes needed to reflect as-huilt conditions GRUTCHFIELD. D Deprating Reactors Branch 5 80/07/03 23pp
- 8007160500 Forwards response to NRC 800507 itr re add1 THI-2 requirements per NVREG-0660 Generally agrees w/GE 800221 gamerac 8WR responses Questions 3 % 7 cannot be answered due to insufficient supporting documentation FINFROCK, I R Jersey Central Power & Light Co 80/07/08 Sp;
- 8007230691 Discusses crack in emergency core spray piping Agrees w/plan to complete quantitative evaluation on Iow-low-low water lavel by 800801 & provide for possible replacement of reducers Operation for one fuel cyclo pewmissible CRUICHFIELD, D M Operating Reactors Branch 5 80/07/09 3pp
- 8007310519 Summary of 800630 meeting w/util re visual indications of possible cracks in plant core spray sys
 PAULSDN,W A Operating Reactors Branch 5 80/07/09 12pp
- 8007250720 Forwards NRC current evaluation of SEP Topic III-5 B & request for addl info re pipe break outside containment CRUTCHFIELD.D Operating Reactors Branch 5 80/07/10 30pp
- 8007170279 Responds to NRC 800111 ltr & forwards addl info re failure of control rod to fully insert on scram signal FINFROCK, I Jersey Central Power & Light Co 80/07/14 2pp
- BOO7180409 Forwards Tech Bpsc Change Request 87 for amend to License DPR-16, App A. re add1 fire proctection ays installed during '1980 refueling outage Class III amend fee pnc1 FINFROCK, I R Jersey Central Power & Light Co 80/07/14 ip

- ~~8007180415 Tuch Spec Change Request 87 for amend to License DPR -16.
 App Aire addl fire protection sys installed during 1980
 refueling outage Certificate of Svc & lit to Lucey Township
 mayor end
 FINFROCK, I R Jersey Central Power * Light Co 80/07/14 3pp
- --B007180423 Tech Spec Change Request 87 for amond to License DPR-16.

 App A. re add1 fire protection sys installed during 1980 refueling outage Consists of replacement Sections 3 12 & 4 12

 * Jersey Central Power & Light Co. 80/07/14 15pp
- 80072800/6 Responds to 800318 ltr to J Ahearne objecting on behalf of numers of plants under SEP review, to current plans for expedited review of environ qualification of electrical equipment forwards applicable memorandum % order DENTON. HR Office of Nuclear Reactor Regulation. Director 80/07/16 App
- 9007290184 Forwards summary of results of leakage reduction program conducted during Spring 1980 outage, in response to NUREG-0578 Spring 2 l 68 FINFROCK, I R Jersey Central Power & Light Co 80/07/21 App
- B007310019 "Analysis of Populations of Boring & Fouling Organisms in Vicinity of Oyster Creek Nuclear Generating Station," qualterly rept June-Aug 1979 HOAGLAND, K E , CROCKET, L Lehigh Univ FIN B-5/44 NUREG/CR-1209 B0/07/31 41pp
- O Inspection reports, IE Bulletins to correspondence
- 8007010279 Forwards IE Waste Packaging Insp Rept 15000037/80-03 on 800227-29 No inpromptiance noted SMITH: G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/04/24 ip
- --000/010.106 JE Waste Packaging inmp Rept 15000039/80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements, radiation levels, removable contamination & external package features
 PEERY, W. W. POTTER, J. P. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 8007220050 Forwards IC Insp Rept 50-219/80-10 pn 800317-20 & notice of violation
 BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/09 2pp
- --8007220052 Notice of violation from insp on 800317-20

 * Region I. Philadelphia. Office of the Director 80/05/06 ip
- --8007220060 IE insp Rept 50-219780-10 on 600317-20 Noncompliance noted failure to implement inservice testing program & procedures per Tech Spec & B REKITOWA A Region 1, Philadelphia, Office of the Director CAPHION D. E. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/06 9pp
- 8007140445 Forwards iE Bulletin 80-13, "Cracking in Core Spray Spargers" Written response required GRIER, B H Region 1, Philadelphia, (Iffice of the Director 80/05/12 Lp
- 8007020165 Forwards IF Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required GRIER.B H Region I, Philadelphia. Office of the Director 80/09/28 ip
- 8007170688 Forwards JE Jusp Rept 50-219/80-13 on 800407-il No noncompliance noted DRUNRER, J. Region 1, Philadolphia, Reactor Operationo Nuclear Support Branch 80/05/28 2pp
- --80071/0492 IE Insp Rept 50-219/80-13 on 800407-11 No concempliance noted Major areas inspected GA/GC administration.design changes/mods & full moup on previously identified items NAPUDA.O., CONMAY.J. Region i, Philadelphia, Office of the Director GREENMAN, C.O. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/23 7pp
- BO07010318 Forwards IE Info Notice 80-27. "Loss of buttion to Emergency Feedwater Pumps " No written resonnee required ORIER, D H Region 1. Philadelphia, Office of the Director 60/05/27 ip

- 4 Addl response to FOIA request for records concerning Hittman & Development Corp.RAD Sycs.inc & Rediation Higt Fruards balance of documents (143 pages) listed in
- J M Division of Rules and Records 80/05/02 200
- 266 Discusses IE Insp Rept 50-219/75-01 on 751031-1105 & rds notice of violation N.P.R. Region I. Philadelphia, Fuel Facility & Materials y Branch 76/01/02 2pp
- 271 Notice of violation from insp on 751031-1105 Noncompliance failure to notify NRC of possession of byproduct matiling NRC Form 241 within 3 days prior to engaging divity given in Philadolphia. Fuel Facility & Materials Safety Branch 1702 | 1p
- 276 Ack receipt of 760127 ltr informing NRC of steps taken to rt violation noted in 1E inso on 751031-1105 Also ack pt of NRC Form 241, "Rept of Proposed Activities in reement States"

 4.P R Region 1. Philadeiphia, Fuel Facility & Materials
 4. Branch 76/03/02 ip
- 286 Informs NRC of steps taken to correct vaciation noted in IE Rept 50-219/75-01 on 751031-1105 Corrective actions nate personnel have been advised to file NRC Form 241 outline sycs in nonagreement states

 # T Hittman Nuclear & Development Corp (subs Hittman) 76/01/27 Spp
- Ack receipt of 800519 itr responding to NRC request for tion of several commitments Based on 800528 telcon, articands that environ air samples discussed in itr n calibrusing approved procedures H. Region J. Philadelphia. Office of the Director
- Forwards IE info Notice 80-26. "Evaluation of Contractor ams " No written response required H Region 1. Philadelphia, Office of the Director 10
- Forwards site-specific & generic questions re GE disc indications per 800109 mapting & IE Info Notice Westinghouse low prossure turbines disc cracks requested within 30 days W/o encl ELD.D Operating Reactors Branch 5 80/06/11 5p
- Forwards [E Dulletin BO-14, "Degradation of BWR Scrame Vol Capability " Written response required H Region i, Philadelphia, Office of the Director
- Forwards IE Insp Rept 50-219/80-06 on 800204-08 No tance noted ... T Region [, Philadelphia, Reactor Construction & ang Support Branch 80/06/13 2pp
- 28 IE Insp Rept 30-219/80-06 on 800204-08 No noncompliance Major areas inspected activities associated rvice insp program AN.E.P. Region i. Philadelphia. Office of the Director L.E. Region i. Philadelphia. Reactor Construction & ering Support Branch 80/06/ii 5pp
- Forwards IE Bulletin 80-15, "Possible Loss of Emergency tion Sys (ENS) W/Loss of Offsite Power " Written required
- Region 1. Philadelphia, Office of the Director
- Responds to IE Dulletin 80-06, "Engineered Safety Feature set Controls " Main steam isolation, containment isolation condenser sys will be tested within 45 r startup from 1980 refuelling outage Jersey Central Power & Light Cn 80/06/19 6pp
- Forwards IE Circular 80-19, "Loss of Reactor Coolant Pump Natural Circulation Coolfown " No written response
- Region 1. Philadelphia, Office of the Director
- Ack receipt of 800603 ltr re JE Insp Rept 50-219/80-10 vibration analysis sys understood to be ated & appears to exceed regulatory requirements closely monitor progress

 J. Region 1. Philadelphia, Reactor Operations Nuclear Back 80/06/23 1p

- --8007180451 Responds to NRC 800509 Itr re violations noted in IE Insp Rept 50-219780-10 Corrective actions implementation of inservice insp program delayed due to personnel & recruiting problems fetimated completion 801126 ROSS.D A Jorsey Central Power & Light Co 60/06/03 2pp
- 8007160699 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region I. Philadelphia. Office of the Director 80/06/24 lp
- B007210193 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/06/25 ip
- 8007020377 Forwards response to IE Dulletin 80-13, "Cracking in Core Spray Spargers " Rept enc! FINFROCK, I R Jersey Central Power & Light Co 80/06/27 17pp
- 8007230122 Forwards IC Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-14 aiso encl No written response required ORIER. B H Region I, Philadelphia, Office of the Director 80/16/27 2pp
- B0072i0042 Responds to IE Builetin BO-10 Required actions completed & results are on file at facility, available for review FINFROCK, I fi Jersey Central Power & Light Co B0/07/01 ip
- 8007070259 Updates 800627 itr re evaluation of possible cracks on segments of core spray piping within reactor vessel between inlet nozzle & vessel shroud Encl replacement pages discuss cyclic stresses induced by low level dynamic inputs FINTROCK. I R Jersey Cantral Power & Light Co 80/07/07 6pp
- 8007280170 Forwards reply to 1E Bullstin 80-08 re containment liner ponetration welds Response to Action Items i through 3 & 2b & 2c enci Addi weld info to be provided within 45 days RDSB, D A Jersuy Central Power & Light Co 80/07/07 7pp
- 800/280305 Forwards reply to IC Bulletin 80-ii re masonry wall design List of masonry walls & re-evaluation priority schedule encl No cases of safety-related piping attached to masonry wails have been found FINFROCK, IR Jersey Central Power & Light Co 60/07/07 7pp
- 8007210288 Discusses IE insp on 800318-19 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO,V Office of inspection & Enforcement, Office of the Director 80/07/08 4pp
- --8007210294 Notice of violation from insp on 800318-19 Noncompliance noted failure to establish radicactive work permit on 790702-0310 & failure to use preceptionary procedures during control rod blade tool cleaning * Office of Inspection & Enforcement, Office of the Director 80/07/08 Spp
- --8007210299 Notice of proposed imposition of civil penalty in amount of \$21,000 for item of noncompliance noted in IE insp on 800318-19 * Office of Inspection & Enforcement, Office of the Director #0/07/08 ip
- --8007210343 Order modifying DL immediately, by adding Section 6 3 2 to Tech Spec 6 3 re facility staff qualifications Request for hearing may be submitted within 25 days STELLO.V Defice of Inspection & Enforcement, Office of the Director 60/07/08 5pp
- 8007240356 Confirms oral notification made on 800707 that 20-day period for completing tests required by IE Bulletin 80-17, Itom 2. began at 12 01 AM on 800708 Also requests immediate notification of any malfunction found during tests GRIER, B H Region 1. Philadelphia, Office of the Director 80/07/09 2pp
- GOO7220586 Ack receipt of 800317 ltr informing NRC of corrective actions to items of noncompliance in IE Insp Rept 50-219/79-18 Based on responses to noncompliance & discussions at 800429 meeting specified parts are withdrawn STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/17 2pp

R Periodic operating reports & related correspondence

- EQ07150705 Forwards B00606 20th quarterly progress rept, "Woodbo Btudy Associated W/Oyster Creek Generating Station." for B00209-0510 FINFRDCK, I R Jersey Central Power & Light Co 80/07/08 ip
- --B007150712 Progress rept for 20th quarter, "Woodborer Study Associated w/Oyster Creek Generating Station." for period 800209-0510 MACIOLEK.N J , BELMORE.C I , HILLMAN.R E Dattelle Memorial Institute, Columbus Laboratories 80/06/04 24pp
- 8007220363 Forwards monthly operating rept for June 1980 RDSS, D A Jersey Central Power & Light Co 80/07/15
- --B007220364 Monthly operating lept for June 1980 HCCLAIN.C M Jersey Central Power & Light Co 80/07/10 lipp
- B Reportable occurrences, LERs & related correspondence
- 8004240221 PNO-I-80-37 on 800309. Licensee scheduled maint on fire protection sys due to cracked & loaking valve body on sys supply header fire protection during outage will be supplied by fire truck connected to Number 2 fire hydrant BRICOS, L. KEIMIG.R.R. DRUNNER.E. J. Region 1, Philadelphia, Diof the Director 80/03/07 lp Region 1, Philadelphia, Office
- 8007070259 Forwards LER 80-024/03L-0 FINFROCK, I R Jersey Central Power & Light Co 80/06/27
- --8007070265 LER 80-024/03L-0 on 800520, during investigation of LER 80-17/1T, "one rod free travel interlock" surveillance requirements not performed as required Causer by failure to perform procedure & schedule surveillance ROSS, D A Jersey Central Power & Light Co 80/06/27 2pp
- ~-8007i10373 LER 80-022/03L-0 on 800603, reactor high pressure isolation condenser initiation switch trip points found less conservative than specified Caused by unusual svc condition Pressure switches reset & exercised to ensure operation ROSS, D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007110375 Forwards LER 80-025/017-0 FINFROCK, I R Jersey Central Power & Light Co 80/07/01 1p
- ~~80071103B3 LER 80~025/01T-0 on 800618, during surveillance test, nonfunctioning operator discovered in valves V-9-12 & V-9-8 found leaking Caused by component failure Defective valves replaced & will be inspected Revised rept will follow ROSS, D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007140330 EN-80-030 notice of violation & proposed imposition of civil penalties will be issued to util by 800708 due to util failure to instruct workers, perform surveys of airborne radioactive matl & failure to follow protection procedures BROCKETT, T. THOMPBON, D. Office of Inspection & Enforcement, Office of the Director 80/07/03 2pp
- B007230570 Forwards RO 50-219/80-27-1P CARROLL.J T Jersey Central Power & Light Co 80/07/17 ip
- --B007230574 RQ B0-219/60-27-1P on B00716, reactor bldg to suppression chamber vacuum breaker sys inlot pipe was found blocked by plastic bag Caused by personnel error Plastic bag was removed from vacuum breaker inlet opening CROSBY.P J Jersey Central Power & Light Co 80/07/17 2pp
- 8007250197 PND-1-80-102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level scram Cold shutdown underway for further analysis of incident KEINIG,R R , BRUNNER,C J Region 1, Philadelphis, Dffice of the Director 80/07/18 2pp
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 mamorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D. Q Division of Licensing 80/06/25 89pp

- BQ07070089 Petition to amend 800221 confirmatory order to all operation w/o recirculation pump trip until Spring 1981 refueling outage Equipment needs to be inspected & prepared prior to installation Delay will be (commical % practical DISE-D P Niagara Mohawk Power (orp. 80/06/30 App
- BOO7280093 Ack receipt of 800630 petition to amend confirmatory order Response will be forwarded shortly IPPOLITO.T A Operating Reactors Branch 2 80/07/17 2pp
- H General correspondence
- B007280540 Notifies of changes within util mgt All correspondence pertaining to security-related matters should be sent to JJ Sunser IE Lempges is vice president in charge of nuclear Niagira Mohawk Power Corp 60/07/17 In
- I Financial information
- BOO7280275 Forwards util Annual Financial Rept for 1979 LEMPGLS, T.E. Niagara Mohawk Power Corp. 80/07/22
- P Operating license stage documents a correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Bethesda. MD re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program ORIMEB.C T Plant Systems Branch 80/02/21 Sipp
- B007070241 Forwards add1 info re util commitments to meet NUREG-05/8 Rocommendations 2 1 36.2 1 Ba % RCS venting Discusses inadequate core couling detection instrumentation & improved post-raccident sampling capability DISE.D P Niagara Mohawk Power Corp B0/06/26 5pp
- 8007)70393 Forwards application for amend to License DPR-43 consisting of changes to Tach Specs THOMAS.E B LeBoeuf, Lamb. Leiby & MetRao 80/07/16 2pp
- ~-B007170394 Application for amend to Lirense DPR-64 consisting of changes to Tuch Specs to heat treatment of circulating DISE, D P Nagara Nuhawk Power Corp 80/07/10 3pp
- --8007170397 Proposed changes to Tech Specs 2 0 for limiting conditions for operation & 2 1 5 for heat treatment of circulating water sys * Niagara Mohawk Power Corp 80/07/10 8pp
- ---8007170403 "Assessment of Biological Impacts of Increasing Temp Change Limitation at Nine Mile Point Unit 1" * Lawler, Matucky & Skolly Engineers 80/03/31 27pp
- @ Inspection reports. IL Bulletins & correspondence
- 8007140474 finewards IC Bulletin 80-13, "Gracking in Core Spray Spargers " Writton response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/05/12 Ip
- 8007020157 Forwards IE Info Notice 80-22. "Broakdowns In Contamination Control Programs" No written response required GRIER, B H Region I. Philadelphia, Office of the Director 60/05/28 ip
- B007010314 Forwards IC Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORICE, D H Region i. Philodelphia. Office of the Director B0/05/29 is
- 8007180073 Forwards reply to IF Bullotin 80-08 re examination of containment liner penetration welds No deficiencies reported LEMPOES, T.C. Niagara Mohawk Power (orp. 80/06/07
- 8007210100 Responds to Ik Rulletin 80 09, "Hydramator Actuaton Deficiencies" None of subjequipment in use or planned for use at Pacility LEMPGES.T E Hisgars Mohawk Power (Drp. 80/06/09 Ip
- 8007210585 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs " No written response required GRIER. B H Region i, Philadelphia. Office of the Director BO/O6/10 1p

- 7170264 Add1 response to fOIA request for records concerning Hittman welear & Dovelopment Corp.RAD Sycs.Inc & Radiation Mgt arp Forwards balance of documents (143 pages) listed in
- pp ELTCN, J M Division of Rules and Records 80/06/02 2pp
- 007170866 Discusses IT Insp Rept 90-219/75-01 on 751031-1105 & forwards notice of violation NFLSON.P & Region 1. Philadelphia, Fuel Facility & Materials Sofety Branch 76/01/02 Spp
- 307)702/1 Notice of violation from insp on 751031-1105 Noncompliance noted failure to notify NNC of pascosion of byproduct matl by filing NRC form 241 within 1 days prior to engaging to activity * Region 1. Philadelphia. Fuel facility & Materials Safety Dranch 76/01/02 ip
- P07170276 Ack receipt of 760127 ftr informing NRC of steps taken to correct violation noted in 1F insp on 751031-1105 Also ack receipt of NRC Form 201. "Rept of Proposed Activities in Honogreemont States."

 MELSON.P R Region I. Philodelphia, Fuel Facility & Materials Safety Branch 76/03/02 1p
- 07170286 Informs NRC of stops taken to correct violation noted in IE Insp Rept 30-219/78-01 on 791031-1105 Corrective actions approxiate personnel have been advised to file NRC Form 241 for routine uvcs in nonagreement states

 TUITE F T Hittman Nuclear & Development Carp (subs Hittman
- 76/01/2/ Ipn
- 010965 Ack receipt of 800017 its responding to ERC request for nfirmation of several commitments Hased on 800528 telcon. Conderstands that environ air samples discussed in itrospections calibrosing approved protedures. IER.O.H. Region i. Philadelphia. Office of the Director 706/05 lp
- R10564 Forwards IC Info Notice 80-26. "Avaisation of Contractor Programs " No written response required IER. B !! Region i. Philadelphia. Office of the Director /06/10 Ip
- J20866 Forwards site-specific & generic quostions re GE disc schang indications per 800109 masting & IE Info Notice -37 on Westinghouse low pressure turbines disc cracks sponse requested within 30 days W/o enc] JTCHTIZED.D Operating Reactors Branch 5 89/06/11 5p
- 40284 forwards IE Bulletin NO-14, "Degradation of BHR Geram Icharge Vol (apability ' Written response required ER.B.H. Region I. Philadelphia, Office of the Director O6/12 ip
- 00326 Forwards IE 1nsp Rept 50-219/80 06 on 800204-08 No icompliance nuted
 LEON.R T Region 1. Philadelphia. Reactor Construction & invering Support Grench 80/06/13 2pp
- 7300328 If. Insp Rept 50-919/80-06 on 900204-08 No noncompliance ofted Major areas inspected activities associated /inservice insp program ERNIGAN.F P Region 1. Philadelphia. Office of the Director RIFP.L F Region 1. Philadelphia. Reactor Construction & ngineering Support Branch 80/06/11 5pp
- 2069? Forwards II Bullstin 80-19, "Possible Loss of Emergency ification Sys (ENB) W/Loss of Offsite Power " Written page required Right Right Region 1. Philadelphia, Office of the Director
- 30599 Presponds to IE Sulleten 80-06. "Engineered Safety Feature F Reset Controls " Main steam isolation, containment y R isolation condenses sys will be tested within 45 after startup from 1200 refueling outage ,D A Jarkey Central Power & Light Co 80/06/19 dep
 - Jards IE Circular 80-18, "Loss of Reactor Coplant Pump Circulation Copidown " No written response
 - m 1. Philadelphin, Office of the Director
 - itpt of 600A03 ltr rs IE Insp Rept 50-219/80-10 in analysis sys understood to be preare to exceed regulatory requirements monitor progress ion 1. Philadolphia. Ronctor Operations Nuclear

- --8007180451 Responds to NRC 800509 ltr re violations noted in IE Insp Rept 50-219/80-10 Corrective actions implementation of inservice insp program delayed due to personnel & recruiting problems Estimated completion 801126 Jersey Central Power & Light Co 80/06/03 2pp
- BO07160699 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Hater Bys & Resultant Internal Contamination of Personnel " No written response required ORIER, B H Region i. Philadelphia, Office of the Director 80/06/24 ip
- B007210193 Forwards IE Info Notice B0-24, "Low Level Radwaste Burial Criteria" No written response raquired GRIER.B H Region 1. Philadelphia. Office of the Director B0/06/25 1p
- 8007020377 Forwards response to 1E Dulletin 80-13. "Cracking in Core Spray Spargers " Rept encl FINFROCK, 1 R Jersey Contral Power & Light Co 80/04/27 17pp
- BO07230122 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular BO-16 also sncl No written response required ORIER, U H Region 1, Philadelphia, Office of the Director BO/06/27, 2pp
- 8007210042 Responds to IE Bulletin 80-10 Required actions completed & results are on file at facility, available for review FINTROCK.IR Jersey Central Power & Light Co 80/07/01 ip
- 8007090259 Updates 800627 ltr re evaluation of possible cracks on segments of core spray piping within reactor vessel between inlet nozzle & vessel shroud Encl replacement pages discuss cyclic stresses induced by low level dynamic inputs FINFROCK. I R Jersey Contral Power & Light Co 80/07/07 6pp
- 8007250170 Forwards reply to IE Bulletin 80-08 re containment liner penetration welds Response to Action Items I through 3 & 2b & 2c encl Addl weld info to be provided within 45 days ROSS.D A Jersey Central Power & Light Co 80/07/07 7pp
- B007250305 Forwards reply to IC Bulletin 80-11 re masonry wall design List of masonry walls & re-evaluation priority schedule encl No cases of eafety-related piping attached to masonry walls have been found FINFROCK.IR Jersey Central Power & Light Co 80/07/07 7pp
- 0007210288 Discusses IE insp on 600318-17 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO, V Office of Inspection & Enforcement, Office of the Director 60/07/08 App
- --8007210294 Notice of violation from insp on 800319-19 Noncompliance noted failure to establish radioactive work permit on 790702-0318 & failure to use precautionary procedures during control rod blade tool cleaning a Office of Inspection & Enforcement, Office of the Director 80707/08 Jpp.
- --B007210299 Notice of proposed imposition of civil penalty in amount of \$21,000 for item of noncompliance hoted in IE insp on 800318-19 # Office of Inspection & Enforcement, Office of the Director 80/07/00 ip
- --B007210343 Order modifying OL immediately, by adding Section 6 3 2 to Toch Spec 6 3 re facility staff qualifications Request for hearing may be submitted within 25 days BTELLO.Y Office of Inspection & Enforcement, Office of the Director 80/07/08 5pp
- B007240356 Confirms oral notification made on E00707 that 20-day poriod for completing tests required by IE Bulletin 80-17. Item 2.began at if 01 AM on 800708 Also requests immediate notification of any malfunction found during tests GRIER, B H Region 1. Philadelphia. Office of the Director E0/07/09 2pp
- 8007220886 Ack receipt of 800317 ltr informing NRC of corrective actions to items of noncompliance in IE Insp Rept 50-219779-10 Based on responsor to noncompliance & discussions at 800429 meeting, specified perts are withdrawn STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/17 2pp

R Periodic aperating reports & related correspondence

- B007150705 Forwards 800404 20th quarterly progress rept, "Woodborer Study Associated w/Oyster Creek Generating Station," for 800209-0510
- FINFROCK, 1 R Jersey Central Power & Light Co 80/07/08
- ---8007150712 Progress cept for 20th quarter, "Hondborer Study Associated w/Dyster Creek Conerating Station," for period 800209-0510 MACIOLEK, N J. BELMDRE, C I , HILLIMAN, R E Battello Memorial Institute, Columbus Laboratories 60/04/04 24pp
- 8007220363 Forwards monthly operating rept for June 1980 ROSS, D. A. Jersey Central Power & Light Co. 80/07/15
- --8007220344 Monthly operating rept for June 1980 MCCLAIN.C M Jersey Central Power & Light Co 80/07/10 11pp
- 9 Reportable occurrences. LERs & related correspondence
- 8004240221 PND-I-80-37 on 800309.licensee schedulad maint on fire protection sys due to cracked & leaking valve body on sys supply header Fire protection during outage will be supplied by fire truck connected to Number 2 fire hydrant BRIOGS.L, KCIMIG.R R. BRUNNER.C J Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8007070259 Forwards LER 80-024/03L-0 FINFRDCK, I R Jersey Central Power & Light Co 80/06/27
- --8007070265 LER 80-024/03L-0 on 800920.during investigation of LER 80-17/1T. "one rod free travel interlock" surveillance requirements not performed as required Caused by failure to perform procedure & schodule surveillance R055.D A Jersey Central Power & Light Co 80/06/27 Opp
- 8007110370 Forwards LER 80-022/03L-0 FINFRDCK.I R Jersey Central Power & Light Co 80/07/01 1p
- -B007110373 LER 80-DR2/O3L-O on 800603, reactor high pressure isolation condensor initiation switch trip points found less conservative than specified Caused by Unusual svc tondition Pressure switches reset & exercised to ensure operation ROSB.D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007110375 Forwards LER 80-025/01T-0 FINFROCK, I R Jersey Central Power & Light Co 80/07/01 1p
- ~~B007110383 LFR 80-025/01T-0 on 80061B, during serveillance test nonfunctioning operator discovered in valves V-9-12 & V-9-8 found leaking Caused by component failure Defective valves replaced & will be inspected Revised rept will follow.

 R099,D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007140550 EN-80-030 notice of violation & proposed imposition of civil penalties will be issued to util by 800708 due to util failure to instruct workers, perform surveys of airborne radioactive matl & failure to follow protection procedures BROCKET, T, THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/07/03 2pp
- B007230570 Forwards RD 50-219/B0-27-iF CARRDLL:J T Jursey Central Power & Light Co B0/07/i7 1p
- --B007230574 RG 50-219/G0-27-1P on B00716, reactor bldg to suppression chamber vacuum breaker sys inlet pipe was found blocked by plastic bag Caused by personnel error Plastic bag was removed from vacuum breaker inlet opening CROBBY, P J Jersey Central Power & Light Co B0/07/17 2pp
- 8007250197 PNO-1-80-102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level screm Cold shutdown underway for further analysis of incident KEIMIG,R R , BRUNNER,E J Region i, Philadelphia, Office of the Director 80/07/18 2pp

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1 G Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protection for electrical cables EISENHUT, D. O. Division of Licensing 80/06/25 89pp

- 8007070089 Petition to amend B00221 confirmatory order to all operation w/o recirculation pump trip until Spring 1981 refueling outage Equipment needs to be inspected & prepared prior to installation Delay will be economical & practical DISC.D P Niagara Mohawk Power Corp 80/06/30 4pp
- 8007280073 Ack receipt of 800630 petition to amend confirmatory order Response will be forwarded shortly IPPOLITO.T A Operating Reacture Branch 2 80'07/17 Zpp
- H General correspondence
- 8007280540 Notifies of changes within util mgt All correspondence pertaining to security-related matters should be sont to JJ Sunsor TE Lempges is vice president in charge of nuclear generation BARTLETT, J Niagara Mohawk Power Corp. 80/07/17 1p
- l Financial information
- 8007280275 Forwards util Annual Financial Rept for 1979 LEMPGES,T E Niagara Mohawk Power Corp 80/07/22
- P Operating license stage documents % correspondence
- B007B3002B Summary of B00207 meeting w/Mark I owners group in Bethesda. MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I cuntainment long-term program GRIMEB.C T Plant Systems Branch 80/02/21 Jipp
- 8007070261 Forwards add1 info re util commitments to meet NURC9-057B Recommendations 2 1 36.2 1 8a & RCS venting Discusses inadequate core couling detection instrumentation & improved post-accident sampling capability DISE.D P Niagara Mohauk Power Corp 80/06/26 5pp
- 8007170393 Forwards application for amend to License DPR-43 consisting of changes to Tech Specs THOMAS,C B LeBoeuf, Lamb, Leiby & MacRae 80/07/14 2pp
- ---8007i70394 Application for amend to Lirense BPR-64 consisting of changes to Tech Opecs re heat treatment of circulating water sys DISE, D P Niagara Mohawk Power Corp 80/07/10 3pp
- --BO07170397 Proposed changes to Tech Specs 2 O for limiting conditions for operation & 2 1 5 for heat treatment of circulating
 - water'sys * Niegare Mohawk Power Corp 80/0//10 8pp
- --8007i70403 "Assessment of Biological Impacts of Increasing Temp Change Limitation at Nine Mile Point Unit 1" * Lawler, Matusky & Skelly Engineers 80/03/31 27pp
- Q Inspection reports, IC Bullotins & correspondence
- 6007140474 Forwards IE Bulletin 60-13, "Cracking in Core Spray Spargers" Written response required GRIER, B H. Region 1, Philadelphia, Gffice of the Director 60/05/18 1p
- 8007020157 Forwards IE Info Nutice 80-22, "Breakdowns In Contamination Control Programs " No written response required GRIER, B.H. Region 1, Philadelphia, Office of the Director Control ... ORIER, B.H. R.
- 8007010314 Forwards IE Info Notice H0~27, "loss of Suction to Emergency Foodwater Pumps " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/05/29 lp
- 8007180073 Forwards reply to 1E Bulletin 80-08 re examination of containment liner penetration welds No deficiencies LEMPOSS, T C Niagara Mohawk Power Corp 80/06/09 5pp
- 8007210100 Responds to IE Rulletin 80-69. "Hydramotor Actuator Deficiencies." None of subjequipment in use or planned for Deficiencies " None of sub; equipment in use or plan use at facility LEMPGCS, T E Niagara Mohawk Mower Corp 20/06/09
- 8007210889 Forwards IC Info Notice 80°26, "Fvaluation of Contractor GA Programs" No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/06/10 ip

07110272 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Capability " Written response required GRIER.D H Region I. Philadelphia. Dffice of the Director 80/06/12 lp

ì

07020686 Forwards IE Bulletin (10:15. 'Possible Loss of Emergency Notification Sys (ENS) M/Loss of Offsite Power " United response required GRIER, BH Region 1. Philadelphia. Office of the Director 80/06/18 Ip 80/06/18

07020489 Forwards IE Carcular 80-15. Loss of Reactor (malant Pump Cooling & Natural Carculation Cooldown "No written response required d I H. Region J. Philadelphia. Office of the Director O: 1p 90/06/20

17160720 Forwards IE Circujar BO-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required RIER, D II Region 1. Philadelphia. Office of the Director 30/06/24 ip

7210211 Forwards IE info Notice 80-24, "Low Level Radwaste Burial riteria" No written response required REER. H Region 1, Philadolphia. Office of the Director 0/06/25

7230149 Forwards IE Bulletin 80-16. "Potential Misapplication of osemount Inc Models 1151 & 1152 Pressure Transmitters /Either A or D Output Codes " Written response required E Circular 80-16 also encl No written response required RIER.B H Region 1. Philadelphia. Office of the Director 0/06/2/ 2pp

7280471 Forwards response to 18 Bulletin 80-08. "Examination of intainment Liner Penetration Welds" No flued head enetrations utilized Penetrations used are end plates;
ellows type & cartridge type
AYNE, J P Power Authority of the State of New York B0/06/27

7280465 Responds to 16 Bulletin 80-10, "Contamination of records respons to the belief in Section . Contemination or arradicactive Sys & Resulting Potential for Undantitared. controlled Refeese of Radioactivity to Environ "Istrument & house six air sys added to analysis program MPCES. T E Niagara Mchawi Power Corp 80/07/02 ip

'250192 Submits reply to 1E Bulletin BU-17 re failure of control ids to insert Verified scram discharge vol sys was free of istructions
MPGES.TE Niagara Hohawi Power Corp 80/07/08 3pp

250241 Ack receipt of B00627 ltr informing NRC of steps taken to rrect violations noted in IE Insp Rept 50-220/80-04 UNNER.E J Region 1. Philadelphia. Reactor Derrotions Nuclear proct Granch B0/07/08 ip

07250298 Forwards IE Insp Rept 50-220/80-04 on 800905-09 & notice of Violation
BRUNNER, E. J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 40/06/45 2pp

07250262 Notice of violation from insp on 800505-09
" Region 1, Philadelphia, Office of the Director 80/06/03 ip

0725026J IE lasp Rept 50-220/80-04 on 800503-09 Noncompliance noted failure to document site operations review committee

reviews (ISTER,H D Region I, Philadelphia, Reactor Operations Nuclear upport Branch BAUNACK,H , HUDSON,S D Region I, Philadelphia,)ffice of the Diroctor 80/06/03 7pp

10119 Confirms that 20-day period for tests in Item 2 of IE letin 80-17. "Failure of 75 of 169 Control Rods to Fully ert Dusing Scram at 8WR." started at 12 01 AM on 800708 uests notification of malfunction & estimated manpower ER.B H Region 1. Philadelphia. Derice of the Director 07709 2pp

rindic operating reports & related correspondence

70360 Forwards monthly operating ropt for June 1980 PGES, T.E. Niagora Mohawi Power Corp. H0/07/11 2

7170361 Monthly operating rept for June 1980 MAN. TW Niagara Mohawk Power Corp 60/07/11

S Reportable occurrences, LERs & related correspondence

8007270010 PNO-1-80-100 on 800711, normal reactor shutdown was conducted to investigate internal arcing in main transformer Source of arcing has not yet been found BANNACK, W., KISTER, H., DRUNNER, E. Region 1, Philadelphia, Office of the Director 80/07/14 1p

8007270586 Forwards LER 80-011/04L-0 LEMPGES, T E Niagara Mohawk Power Corp 80/07/22 tp

--8007290600 LER 80-011/04L-0 on 800623,recolder review showed condenser inlet/Circulating water discharge delta temp had exceeded Tech Sper limit on 800420-23 Btation load reduced, recorder scale expanded & Tech Sper change initiated HARRISON.P Ningara Mohawk Power Corp 80/07/22 2pp

DOCKET SO-223 UNIV OF LOWELL RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

8007160828 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8gs & Rosultant Internal Contamination of Personnel " No written response required GRIER, D H Region 1, Philadelphia, Office of the Director 80/06/24 1p

B007210142 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/25 ip

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

H General correspondence

8007090277 Advises NHC that V Schrock is no longer reactor administrator 5 Keplan has been reactor administrator since 791005 LIM.T H California, Univ of Berkeley 80/07/03 ip

O Inspection reports, IE Bulletins & correspondence

8007230350 Forwards IE Insp Rept 50-224/80-02 on 800516 No noncompliance noted

BOOKH E Region 5, Ban Francisco, Fuel Facility & Materials Safety
Branch 60/05/09 2pp

--8007230355 IE Insp Rept 50-224/80-02 on 800514 No noncompliance nated UU/20/353 IE IRSP Rept 30-224/40-02 on 800516 No noncompliance to Major areas inspected, unplanned accidental release of airborne radioactive matla, YUIABLO P Repion 5. Ban Francisco. Fuel Facility & Materials Safety Branch MENSLAWSKI.F A . BDOK.H E Region 5, San Francisco. Office of the Director 80/06/09 4pp

8007210099 Forwards IE Insp Rept 50-224/80-01 on 800506-09 No noncompliance noted CREMS.J L Repion 5, Ban Francisco, Reactor Operations Nuclear Support Branch 80/06/11 2pp

--8007210107 IE Insp Rept 50-224/80-01 on 800506-09 No noncompliance noted Major areas inspected facility organization.logs & records & requalification training JOHNSON.A , CHAFFEE.A Region 5. San Francisco, Office of the Director FAVLKENBERRY.D Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/11 3pp

BOO7180P59 Forwards IE Circular 80-14, "Radioactive Contamination of Flant Demineralised Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEINR H Region 5. San Francisco, Office of the Director BO/06/24 Ip

DUCKET 50-225 RPI CRITICAL EXPERIMENT

Q Inspection reports. If Bulletins & correspondence

BOO7160809 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Fersonnel" No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/06/24 ip

- 800721013B Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESCARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8007180272 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required EMSELKENR H Region 5. San Francisco. Office of the Director 80/04/24 lp

DOCKET 50-236 LOCKHEED AIRCRAFT CORP

- F Security, medical, embrgoncy & fire protection plans
- 8007100123 Requests add1 time for completion of work re fire brigade medical svaluation program Completion date of 801031 established MAYER, L D Northern States Power Co 80/06/27 1p
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards rontingency plan amend Plan withheld (ref 100FR2 770)
 PEOPLES D L. Commonwealth Edison Co. 80/06/27 1p
- B007290562 Bubmits results of mini-review of safe shutdown analysis No reasonable assurance that licensees fire protection will allow safe shutdown of Units 2 & 3 As minirecommends requirement for alternate shutdown sys or dedicated sys HALL.R E Brookhaven National Laboratory B0/07/09 7pp
- G Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/06/25 E9pp
- 8007010331 Forwards safety evaluation & EIA re spent fuel pool mods W/o encls CDDDARD.R J Hearing Branch 2 80/06/27 ip

H General correspondence

- 8007300013 Responds to 770405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in enci excerpt from util annual rept President 791207 statement re Kemeny Commission Rept encl DENTON:H R Office of Nuclear Reactor Regulation, Director 800/06/20 20pp
- P Operating license stage documents & correspondence
- B007230028 Summary of 800207 meeting w/Mark I owners group in Dethesda. MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES, C T Plant Systems Branch 80/02/21 Sipp
- 8007250558 Forwards NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." for review & comment CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/04 2pp
- BOO7010003 Forwards safety evaluation & EIA supporting proposed facility mods to increase spent fuel storage pool capacity Final approval cannot be granted until ASLB resolves legal issues

 CRUTCHFIELD, D. M. Operating Reactors Branch 2 80/06/05 2pp
- --B007010011 EIA supporting proposed facility mods to increase spent fuel storage pool capacity

 * Office of Nuclear Reactor Regulation, Director 80/06/06
 10pp

- BOQ7010146 Forwards final rule published in 800509 FR amending 100FR90 71 to require periodic updating of FBARs Compliance is not required until completion of SFP CRUTCHFIELD. D Operating Realtors Branch 5 B0/06/10 5pp
- 8007020186 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFICED: D M Operating Reactors Branch 5 80/06/11 2pp
- 8007010042 Forwards NRC evaluation of SEP Topic V-5 re RCPB leakage detection Requests info concerning util as-built facility differing from litensing basis assumed in assessment CRUTCHFIELD. D M Operating Reactors Stanch 5 80/06/12 5pp
- BOO7010217 Forwards NRC evaluation of SEP Topic VIII-4 re electrical penetrations of reactor containment Requests info concerning util as-built facility differing from licensing basis assumed in assessment CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/12 10pp
- 8007010292 Forwards evaluation of SEP Topic V-12 A re water purity of BMR primary coolant Review completed & rosulting evaluation will form input to integrated safety assessment unless changes are needed to reflect as-built conditions GRUTCHFIELD, D Operating Reactors Branch 5 80/06/12 3pp
- 8007010050 Forwards request for add1 info on SEP Topic XV-16 re radiological consequences of small lines carrying primary coplant outside containment Response requested within 30 days of receipt of itr LAINAB.G C Assistant Director for Safety Assessment 80/06/16
- 8007100399 Responds to 800229 Its which expressed apposition to ACRS recommendation to restructure SEP Role of licenses in program will expand Ltr forwarded to Commissioners DENTON. If R Office of Nuclear Reactor Regulation, Director BO/06/18 4pp
- --B007100420 Expresses opposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALL.R SEP Duners Group B0/02/27 2pp
- BOO7160499 Forwards "Loss of Offsite Power · Survey Status Rept "
 Requests views re causes & possible remedies within 120
 days
 CRUTCHFIELD.D M Operating Reactors Branch 5 BO/06/19 2pp
- --8007160463 "Loss of Offsite Power Survey Status Rept," Revision 1 SCHOLL,R F Systematic Evaluation Program Branch 80/06/19 9pp
- BD0701019D Responds to SSRT concerns re control rod drive sys lacking seismic analysis Guad Cities 1 & 2 seismic design of control rod drive sys calculations performed for facility while under const encl

 JANECEK.R F Commonwealth Edison Co 80/04/24 App
- --B007010193 "Quad Cities i & 2 Sersmit Data on Control Rod Drive Sys "
 * Reactor Controls, Inc 70/07/10 200pg
- BOO7070116 Submits revised responses to NRC 770603 ltrs resecond level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads

 JANECEK.R F Commonwealth Edison Co BO/06/26 4pp
- 8007080063 Responds to NRC 800515 request for add1 info concerning adequacy of station electric distribution sys voltages JANECEK,R F Commonwealth Edison Co 80/06/30 App
- BCO7070345 Forwards revised schedule & status info for Mark I program, feedwator sparger replacement & general work planned for Guad Cities I outage Proceeding on priority basis w/mods providing largest safety increase margine REED, C Commonwealth Edison Co 80/07/02 18pp
- BOO7250032 Forwards "Loss of Offsite Power ~ Survey Status Rept " Replaces BOO619 rept which omitted Table 4 CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/08 3pp
- --8007230035 "Loss of Offsite Power Survey Status Rept "
 8CHOLL, R f Plant Systems Branch (Pre 791030) 80/07/08 10pp
- BOO7ZIOZIO Responds to HRC request for addl info te turbine disks Applicable turbine missile analysis was presented in Amend 2 to Quad Cities CF application Analysis applies to Dresden due to similarity of general arrangement JANECEM.R F Commonwealth Edison Co 80/07/15 ip

- 8007280074 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/16 4pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007140545 Forwards le Bulletin 60-13, "Cracking in Core Spray Spargers " Written response required MEPPLER.J G Region 3, Chicago, Office of the Director 80/05/12 to
- 8007070072 Forwards IE Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 on 800407-0502 & notice of violation KEPPLER, J 9 Region 3, Chilago, Office of the Director 80/05/23 200
- --8007070074 Notice of violation from insp on 800407-0502 • Region 3. Chicago. Office of the Director 80/05/23 2pp
- --8007070080 IE Insp Repts 50-10/80-09,50-237/80-08 & 50-249/80-12 on 800407-0502 Noncompliance noted failure to adhere to GA program requirements Contaminated clothing found lying inside controlled contaminated area SPESSARD.R L . DARKER.J L . TONGUE,T M Region 3. Chicago, Office of the Director 80/05/23 7pp
- 8007020065 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 90/05/28 ip
- 1007010086 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/05/29 ip
- 3007220156 Forwards IE Info Notice 80-26, "Evoluation of Contractor GA Programs" No written responsy required **EPPLER.J G Region 3. Chicago. Office of the Director 80/06/10
- 3007020662 Forwards site-specific & generic questions re GE disc cracking indications per 800109 meeting & IE Info Notice 77-37 on Hestinghouse low pressure turbines disc cracks Response requested within 30 days CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 5pp
- 1007140309 Forwards IE Bulletin B0-14. "Degradation of DHR Scram Discharge Vol Capability " Written response required MEPPLER. J G Region 3. Chicago. Office of the Director B0/06/12 15
- 007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Drasden 2 & 3 uses AH-90 or NH-90 series hydramotor PEDPLES,D L. Commonwealth Edison Co. 80/06/16 3pp
- 007030037 forwards IC Bulletin B0-15, "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Written response required KEPFLCR.J 9 Region 3, Chicago, Office of the Director B0/06/18
- 007230371 Forwards IE Insp Repts 50-010/80-10,50-237/80-09 & 50-249/80-13 on 800305-29 & notice of violation HEIBIMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/19 2pp
- -8007230379 Notice of violation from insp on 800305-29 N Ragion 3. Chicago. Office of the Director 80/06/19 ip

010/80-10:50-237/80-09 & 50-249/80-13 on ted Pailure to report events in

rejen 3. Chicago, Office of the

or Coulant Pump response

tor 80/06/20

- 8007170430 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24 ip
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models li51 & 1152 Pressure Transmitters W/Either A or D Output Codes " Hritten response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27 ip
- 8007180003 Ack receipt of 800613 itr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-010/80-09, 57-237/80-08 & 50-249/80-12 KEPPLER, J @ Region 3, Chicago, Office of the Director 80/07/01 to
- --8007180010 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED. C Commonwealth Edison Co 80/06/13 6pp
- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Fatiure of Control Rods to Insert Buring Scram at BWR," will start at i2 01 AM on B00708 Test should be completed within 20 days Requests notification of malfunction KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/07/07 ip
- 8007250641 Responds to IE Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any afforted sys will be restricted if contamination found PEOPLES,D L. Commonwealth Edison Co. 80/07/07 2pp
- 8007290650 Forwards response to IE Bulletin 80-11, "Masonry Hall Design " Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be met prior to startup W/o encl PEOPLES.D L. Commonwealth Edison Co. 80/07/07 200
- B007250638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit i designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit roturned to svc PEOPLES.D L. Commonwealth Edison Co. 80/07/09 7pp
- B007160630 Responds to IE Bulletin 80-17 re results of tests required by Item 1 No significant amount of water in scram discharge vals Vent & drain lines also verified free of obstructions by performing dynamic air test

 JANICEK.R F Commonwealth Edison Co B0/07/10 2pp
- 8007300485 Responds to IE Bulletin 79-14, "Seasmic Analysis for As-Built Safety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria" JANFCEK,R F Commonwealth Edison Co 80/07/16 ip
- --8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations." Revision 2 8NYDER, T.K. EDS Nuclear, Inc. 80/03/07 iipp
- --8007300508 "Engineering Criteria Procedure for Application of Blume Curves Criteria " SNYDER,T K EDS Nuclear, Inc 80/03/07 20pp
- --8007300508 "Engineering Criteria Frucedure for Application of Blume Curves Criteria" SNYDER, T. E. EDS Nuclear, Inc. 80/03/07 20pp
- R Periodic operating reports & related correspondence
- 8007180333 Forwards monthly operating repts for June 1980 STEPHENSON, D B Commonwealth Edison Co 80/07/09 1p
- --8007180336 Monthly operating repts for June 1980 CleB71EWIC2.8 Commonwealth Edison Co 80/07/02 23pp
- B Reportable occurrences. LERs & related correspondence
- BOO7010497 Forwards LER 80~022/01T~0 STEPHENSON, B D Commonwealth Edison Co 80/06/24 ip

1

- --8007010505 LER 80-022/01T-0 on 800611, found that control rod driveline screw discharge piping did not meet FBAR seismic requirements Caused by design deficiency New correct seismic supports are being designed

 ** Commonwealth Edison Co 80/06/24 2pp
- 8007010344 Forwards LER 80-019/03L-0 STEPHENSON, D B Commonwealth Edison Co 80/06/24 1p
- --8007010351 LER 80-019/03L-0 on 800528, at steady state power operation, C main steam line rad monitor tripped Caused by electronic component failure Assembly replaced BADRAN, 8 Commonwealth Edison Co 80/06/24 ip
- 8007100179 Forwards LER 80-021/03L-0 STEPHENSON, B. B. Commonwealth Edison Co. 80/07/02 ip
- ---8007100189 LER 80-021/03L-0 on 800607, during normal operation, while performing drywell-torus pumpback dp instrument surveillance drywell-to-torus dp dropped below i psi for 2-hr Cause not stated Personnel informed of requirement re dp MADROW, R Commonwealth Edison Co 80/07/02 ip
- 8007100187 Forwards LER B0-020/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/07/02 lp
- --800/100192 LER 80-020/03L-0 on 800405, during surveillance DOB 1400-9, torus-to-drywell vacuum broaker 2-1401-32D failed to give redundant open indication Caused by stuck switch Bracket was tightened & DOB 1400-9 was repeated successfully DUNBAR. J. Commonwealth Edison Co. 80/07/02 2pp
- 8007220557 Forwards LER 80-023/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/07/14 ip
- --B007220572 LER B0-023/03L-0 on 800228, during attempt to vent torus, valves A0-2-160i-60 & -6i failed to open Caused by ioss of instrument air to air operated valves Air supply valved back in & valves demonstrated operable
 MAORDW.R Commonwealth Edison Co B0/07/14 2pp
- BOO7230339 LER 80-005 has been cancelled, COLLINS, M Commonwealth Edison Co. 80/07/22 ip
- DOCKET 50-243 DREGON STATE UNIV RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8007150649 Advises of procedural inadequacy re radiography of unauthorized explosive matl on 800626 Caused by inadequacy in applying administrative or procedural controls Separate cover sheet indicating approved matls will be issued. WANO.C. H Oregon State Univ 80/07/11 App
- Q Inspection reports, IE Bullatins & correspondence
- 8007180247 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralised Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/24 1p
- 8007240361 Forwards IE Insp Repts 50-106/80-02,50-243/80-03 & 70-0971/80-01 on 800630-0701 No noncompliance noted Encls withheld (ref 100FR2 790) NRNDERHAUO, R R Region 5, Ban Francisco, Safeguards Branch. 80/07/14 2pp
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8007110129 Notification of 800605 meeting w/util in Batheada, MD to discuss fire protection plans NOWICKI.8 J Operating Reactors Branch 5 80/06/02 2pp
- B007100214 Summary of 800A05 meeting w/util in Bethesda.Md re proposed rule concerning fire protection program for nuclear power plants operating prior to 790101.
 NOWICKI.S J. Operating Reactors Branch 2 80/06/26 41pp
- 8007070342 Summarizes Gilbert & Associates, Inc study re active & passive aus to control fires in areas of exposed structural stael, in response to NRC 770214 fire protection safety avaluation, Item 3 2 8 Rochester Gas & Electric Corp 80/06/30 App

- 9007300050 Ack receipt of 791210 ltr transmitting changes to security plan Second change is not consistent w/provisions of 10CFR50 54(p) Add info encl Encl & ref ltr withheld (ref 10CFR2 790) CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/07/17 2pp
- B007310350 Submits security plan info,per NRC 800717 ltr Info withheld (ref 100FRZ 790)

 HMITE,L D Rochester Gas & Electric Corp 80/07/24 3pp
- 8007310378 Forwards security contingency plan Plan withheld
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 87pp
- P Operating license stage documents & correspondence
- B0070:0124 Forwards final rule published in 800509 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD, D Operating Reactors Branch 5 80/06/10 5pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D 0 Division of Licensing 80/06/i1 62pp
- 8007140623 Forwards Amend 33 to License DPR-18, safety evaluation & notice of issuance & availability
 CRUTCHFIELD,D Derating Reactors Branch 5 80/06/13 2pp
- --8007140628 Amend 33 to License DPR-18.approving secondary water chemistry monitoring program implementation Effective on 800639 CRUTCHFIELD.D Operating Reactors Branch 5 80/06/13 2pp
- --8007140632 Safety evaluation supporting Amend 33 to License DPR-18
 * Operating Reactors Branch 5 80/06/13 2pg
- --8007140636 Notice of issuance & availability of Amend 33 to License CRUTCHFIELD, D Operating Reactors Branch 5 80/06/13 3pp
- 8007100399 Responds to 800229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON.H R Office of Nuclear Reactor Regulation. Director HO/06/18 App
- --B007100420 Expresses apposition to ACRS recommendation to restructure BEP For SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically BCHAFFBTALL, BEP Owners Group 80/02/29 2pp
- B007280107 Forwards "SEP Review of Pipe Break Outside Containment, Topic III-5 B. for Oinna Nuclear Power Plant " & five staff positions Requests addl info to complete review CRUTCHFIELD.D Operating Reactors Branch 5 80/06/24 3pp
- --8007280113 "SEP Review of Pipe Break Gutside Containment.Topic 111-5 | for Ginna Nuclear Power Plant "
 # Operating Reactors Branch 5 80/06/24 26pp
- BOO7240067 Requests addl info to continue review of SEP Topic VIII-i.A.
 "Isolation of Reactor Protection Sys From Nonsafety Sys.
 Including Qualification IO Isolation Devices"

 CRUTCHFIELD,D M Operating Reactors Granch 5 80/06/25 3pp
- BOO7080272 Comments on NRC requirement re installation of reactor vessel water level instrument at faculity Requirement is unreasonable due to amount of development work necessary to implement reliable vensel level instrument

 WHITE.L D Rachester Oas & Electric Corp 80/07/02 3pp
- BOO7250001 Requests submittal of application for amond to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 49pp

- 7180109 Notifies that NODEOB request for route approval to cover hipments of mixed oxide fuel rods to Dinne Station is subj., license fee Review of request was completed on 800213
 ILLER.W () License Fee Management Branch 80/07/03 ip
- 7230057 Responds to util 600208 request for route approval covering imments of mixed axide fuel rods Review of licenses route approval requests subj to license fee schedule in 100FR170 ltteR.W D license Fee Management Branch 60/07/03 ip
- 7240144 Forwards evaluation of actions taken to sutisfy Category A tems of NRC recommendations resulting from TMI-2 lessons earned recommendations Category A items have been attacked the experience of items 2 1 b & 2 1 3 b RUTCHFIFLD.D M Operating Reactors Branch 8 80/07/07 11pp
- /180397 Responds to 800/03 inquiry re process whereby draft /olivation performed by Franklin Inst & containing possibly reprietary info could be released to Rochestor Cas & actric Hestinghouse has proprietary agreement double ESEMANNAR A Westinghouse Electric Corp. 80/07/07 ip
- 200135 Forwards NRC review of control rod guide thimble wear in Rs Based on roview issue is respired for 14x14 fuel semblies designed by Westinghouse UYCHFIELD.D M Operating Reactors Branch 5 80/07/10 4pp
- 220403 Forwards response to NRC 791022 ltr requesting addl info re xiliary feedwater sys flow requirements Response to quest for info re evaluation of auxiliary feedwater sys quirements was provided 79128

 ITE, L. D. Rochoster Oas & Electric Corp. 80/07/14 14pp
- 07220407 "Feedwater Sys Flow Diagram "
 * Rochester Gas & Electric Corp 80/05/30 ip
- 200074 Responds to 000318 itr to J Ahearne objecting on behalf of ners of plants under ECP review to current plans for pedited review of environ Qualification of electrical uipment Forwards applicable memorandum & order 410N/H R Defice of Nuclear Reactor Regulation, Director /07/16 4pp
- '90740 Forwards comments on NAC assessment of SEP Topic VIII-4 ansmitted by DL Ziemann 800324 itr Also, forwards responses add questions raised by review Oversize drawings silable to Central Files only ITE.L D Rochester Gas & Electric Corp 80/07/21 29pp
- 310401 Advisos that design criteria for selsmic upgrade program, matted for 800/15 will be delayed until 800013 Delay 1 not impact submittal of analysis packages on schedule scribed in 800530 ltr
 TTR.L D Rochester Cas & Electric Corp 80/07/24 in
- ispection reports. IE Bulletins & correspondence
- 120134 Forwards IC Info Notice 80-22. "Breakdowns In Contamination strol Programs " No written response required ER, B H Ragion I. Philadelphia. Office of the Director 703/28 ip
- 10296 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency dwater Pumps" No written response required 68.6 H. Region i, Philadelphia. Office of the Director 05/29 ip
- 10157 Forwards IC Insp Rept 30-244/80-03 on 800421-25 No compliance nobed
 NNEILE J Region 1, Philadelphia, Reactor Operations Nuclear port Branch 80/05/27 Epp
- 7210165 IC Insp Rept 50-244/80-03 on 800421-25 No noncompliance oted, Major areas inspected refueling & outage activities scluding preparations for refueling & previous insp insings DHNSON, D.F. Region 1, Philadelphia, Office of the Director ISTER, H. D. Region 1, Philadelphia, Reactor Operations Nuclear upport Branch 80/03/27 3pp
- 90176 Forwards IE Inap Rept 30-244/80-05 on 800421-24 No compliance noted IIN.W O Region 1. Philodelphie. Bafeguards Branch 80/05/30

- --B007290199 IE Insp Rept 50-244/B0-05 on 800421-24 No noncompliance noted Major areas inspected security plan, security program audit, protected area physical barriers & access control to vital areas Details withhold (ref 100FR2 790)

 MADDEN, H. Region 1, Philadelphia, Office of the Director DEVLIN, J. W. Region 1, Philadelphia, Safeguards Branch, 80/05/27 to
- 8007020018 Responds to IE Bulletin 80-06. "Engineered Bafety Feature IESF) Reset Controls " No inconsistencies were found between schematics & actual installations No areas were identified that require mod or design change

 HHITE.L D Rochester Gas & Electric Corp 80/06/03 3pp
- B007210619 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIEF.B H. Region 1, Philadelphia, Office of the Director 80/06/10 ip
- BO07140364 Forwards IE Info Notice BO-27, "Degradation of Reactor Coolant Pump Stude" No specific action or response required GRIEFALH Region i, Philadelphia, Office of the Director GO/O6/11 ip
- 8007020713 Forwards IE Bultetin BO-15. "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required CRIER.B H Region 1, Philadulphia, Office of the Director. BO/06/18 1p
- 8007020487 Forwards IE Circular 80-15, "Loss of Reactor Coclant Pump Cocling & Natural Circulation Cooldown" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/06/20 1p
- B007160747 Forwards IE Circular B0-14, "Radioactive Contemination of Plant Demineralized Mater Bys & Resultant Internal Contemination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/24 1p
- 8007180141 Submits reply to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for release Based upon review of sys, no addl sampling or monitoring program need be established WHITE, L.D. Rochester Pas & Electric Corp. 80/06/24 2pp
- 8007210286 Forwards lE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response requires. GRIER.B H Region i. Philadelphia. Office of the Director 80/86/23 ip
- 8007230005 Ack receipt of B00523 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-244/78-24, BRUNNER.E J Region i. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/26 ip
- --800723000B Responds to NRC 790919 Itr re violations noted in IE Insp Rept 50-244/78-24 Corrective actions storage room will be built to comply W/NRC Reg Guide | 188 WHITE.L D Rochester Gas & Electric Corp 80/05/23 2pp.
- --8007230007 Ack receipt of 790907 ltr informing NRC of steps taken to correct violations noted in IR Insp Rept 50-244/78-24 BRP Paragraph 12 4 is acceptable atternative to Reg Guide 1 88 HAAS.W P Quality Assurance Branch 79/09/19, 1p.
- 8007230183 Forwards IE Dulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Hritten response required IE Circular 80-16 also encl No written response required. GRIER, B H Region i, Philadelphia, Office of the Director 80/06/27 2pp.
- 8007230498 Forwards response to Items 1,2a & 3 of IE Bulletin 80-11, "Masonry Hall Design " All walls surveyed except svc bldg which is not safety-related All walls will be re-evaluated to determine adequacy to perform design function.

 WHITE,L D Rochester Gas & Electric Corp 80/07/07 24pp.
- GOG7280142 Forwards NRC evaluation of Apr 1980 steam generator insp results Agrees that plant should return to power after insp & concurs w/proposed mid-cycle insp Insp program & comments should be submitted 40 days prior to scheduled shutdown CRUTCHFIELD.D Operating Reactors Branch 5. 80/07/08. 4pp

- R Periodic operating reports & related correspondence
- 8007130584 Forwards monthly operating rept for June 1980 SNOW, B. A. Rochester Gas & Clectric Corp. 80/07/09 ip
- --8007150590 Monthly operating rept for June 1980
 MCNAMARA.A Rochester Gas & Electric Corp 80/07/07 5pp
- 8 Reportable accurrences, LERs & related correspondence
- B007160637 RO B0-06 on 9007ii.chemical analysis indicated boric acid storage tanks below Tech Specs for vol & percent weight borlc acid Cause not stated Orderly power reduction & batching operations begun to restore tanks to specs SNDW, B A Rochester Gas & Clectic Corp 80/07/11 in
- 8007210443 RD 80-04 on 800714, chomical analysis indicated boric acid storage tanks out of spec for vol & % weight of boric acid Caused by inadvertent dilution of concentration determining chemical reagents Tanks restored to required specs SNOW, B A Rochester Gas & Electric Corp 80/07/14 2pp
- 8007280633 Forwards LER 80-006/017-0 WHITE, L D Rochester Gas & Electric Corp 80/07/24 lp
- --8007280639 LER 80-006/017-0 on 800711, during routine analysis of baric acid tank samples, concentration exceeded Tech Spec Ilmit on three occasions Caused by untry of ascertte Into tank Reagent check now performed w/sampling FILKING, D Rochester Gas & Electric Corp 80/07/24 2pp
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 900425 ltr to all power reactor licensees, in response to 800529 ltr re omorgancy response facilities et reactor sites Sites w/approval to usu closed-circuit television link w/technical support ctr listed CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/07 2pp
- 8007010337 Comments on proposed rule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Buggested revisions to App R w/justifications oncl COUNSIL, N O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, N O Connecticut Yankoo Atomic Power Co COUNSIL, N O Northeast Utilities 80/06/16 31pp
- 8007030356 Comments on proposed rule IOCFRSO requirements far exceed those necessary to remotive generic lisues & are excessively specific & restrictive Forwards olternative App R fire protection program COUNBIL, W O Connecticut Yankee Atomic Power Co COUNBIL, W O Northeast Nuclear Energy Co (bubs of Northeast Utilities) 80/06/16 16pp
- 8007090231 Forwards responses to NUREG-0654 criteria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withheld (ref 10CFR2 790) COUNSIL.W O Connecticut Yankes Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (Bubs of Northeast Utilities) 80/06/30 2pp
- B007170425 Confirms position discussed in 800624 telcon to safeguards contingency plans NRC requested revisions are ill-advised & unnecessary Bpscifics of plan implementation can be detailed in procedures
 COUNSIL.W G Connecticut Yankoe Atomic Power Co COUNSIL.W G
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 B0/07/01 2pp
- Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 polition for reconsideration of 780413 memorandum & order UCB 771104 polition sought action re fire protection for electrical tables EISENHUT, D G Division of Licensing 80/06/25 87pp
- I Financial information
- 8007150622 Forwards 1980 cash flow estimates for CT Light & Power Co. Hartford Electric Light Co & Hostern MA Electric Co Cash flows are adequate to meet potential promium requirements for 1975 amends to Price-Anderson Act

- P Operating license stage documents & correspondence
- 800/2300/28 Summary of BCO207 meeting w/Norv I owners group in Bethesda, MD.re revision, to NRC, acceptance criteria & outstinding issued relative to Mark I containment long-torm program GRINES.CT Flant Systems Branch 80/02/21 31pp
- B007R50546 Forwards NUREG-0617, "BHR Fredwater North & Control Rod Drive Roturn Line North Cracking," for leview & comment CRUTCHFIELD,D Operating Reactors Branch 5 80/06/04 2pp
- G007010130 Forwards final rule published in 800509 FR amending iOCFR30 71 to require perodic updating of FSARs Compliance is not required until completion of SEP CRUTCHTIELD, Departing Reactors Branch 5 B0/06/10 5pp
- 8007010028 Advisors that alternate inspr will be performed in lieu of ABME visual crams for 1980 retueling, per WG Counsil 800409 ltr to DL Ziemann Formal docketed waiver of requirement still requested COUNSIL. W G Mortheast Nuclear Energy Co (subs of Northeast Utilities) 80/06/10 2pp
- 8007100399 Responds to 800289 itr which expressed apposition to ACRS recommendation to restructure BEP Role of licenses in program will expand Ltr forwarded to Commissioners DENTON IR Office of Nuclear Reactor Regulation, Director 80/06/18 4pp
- --8007100420 Expresses apparation to ACRE recommendation to restricture SEP for SEP numbers to perform safety analysis as outlined, cost in dollars & manquier would increase dramatically BCHAFFSTALLR SEP Owners group 80/02/29 2pp
- G007020567 Clarifies 800506 response to NRC 771030 request for info concerning Lassons Learned Task Force Item 2 1 8 a. improved post-accident sampling capability Info ensures accurate NRC understanding of dusing philosophy & Intent COURSIL. W G Connecticut Vankee Atomic Power Co COUNSIL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23 Spp
- 8007240073 Requests addl info to continue review of adequacy of station electric distribution sys voltages Response requested within 45 days of receipt of the CRUTCHFICLD D M Operating Reactors Branch 5 80/06/27 Spp
- 8007070251 Notifies of change to schedule described in B00314 ltr re environ qualification of safety-related equipment Unscheduled facility outage portponed scheduled start of 1780 refueling nutage for approx 2-4 wks CDWREIL 4 Q Northeast Nucleur Energy Co (subs of Northeast Utilities) 60/06/30 2pp
- B007170319 Summary of B00612 meeting w/utile in Bethusda,MD re interim reliability evaluation program QLSHAN,L N Spurating Reactors Branch 1 80/06/30 3pp
- BOO7230iil Forwards NRC "SEP Technical Evaluation Topic VIII-4, Electrical Popultrations of Reactor Containment " Assessment compares facility w/criteria corrently used by regulatory passonnel for liconsing new facilities CRUTCHFIELD.D Operating Reactors Branch 9 80/07/01 2pp
- --800/230324 "SEP Technical Evaluation Topic VIII-4, Electrical Panetrations of Reactor Containment "
 Operating Reactors Granch 5 86/07/01 9pp
- BOO7280694 Advises that IMC has approved conceptual design of postaccident sampling sys Lists soveral addl areas which should be addressed CRUTCHTIFED.D M Operating Reactors Branch 5 BO/07/01 Jpp
- 800/100200 Forwards response to NRC 9000507 requests for add1 info re-proposed revisions to ETS State of CT Dept Environ Protection 800611 Itr approving Thermal Plume Study Rept and1 COUNSIL.W G Northeast Utilities 90/07/03 27pp
- 8007210387 Forwards info re priving qualification of electrical equipment info supprendes info provided by 800602 ltm & reflects additions & deletions from original listing COUNSIL W G. FRE. W F. Northeast Orlay Chorgy Co. (subs. of Northeast Utilities).

- 800/220457 Application for amend to Licenses DPR-21 % DPR-65 to incorporate changes to Tech Specs re organizational title Class I fee encl COUNBILLUGG. FEELUF Northeast Muclear Energy Co (subs of Northeast Utilities) 80/07/14 3pp
- --8007220467 Promosed revised fech Specs.incorporating organizational * Northeast Nuclear Energy Co (subs of Northeast Utilities)
- 8007250300 Application to amend licenses DPR-21 to DPR-65-clarifying Tech Specs to reflect recent organizational title changes License fee transmitted 800714 Affidavit encl CDUNSLIF Contreast Nuclear Energy Co (Subs of Northeast Utilities) 80/07/15 2pp
- --8007250303 Proposed revisions to ETS Pages 5 1-2 & 5 1-5, reflecting recent organizational title changes
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/15 3pp
- 8007280076 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review, to current plans for expedited review of environ qualification of ejectrical equipment Forwards applicable memorandum & order DENTON.H R 80/07/16 4pp
- 8007280574 Application for amend to License BPR-21, providing further assurance of adequacy of electrical distribution sysvoitages Class III fee encl COUNSILN G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/16 3pp
- 8007280673 Requests extension of comment period re NUREG-0577.
 "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Egolant Pump Supports," until COUNSIL N O Northeast Utilities 80/07/21 2pp
- @ Inspection reports, IE Bulletins & correspondence
- B007140452 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director B0/05/12 lp
- 8007020146 Forwards IE Info Notice 80-22. "Breakdowns In Contemination Control Programs " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/85/28 ip
- 8007010312 Forwards 1E info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required ONIER.B M Region i. Philadelphia, Office of the Director 80/05/29 ip
- 8007210580 Forwards 1E 1nfo Nutroe 80-26, "Evaluation of Contractor GA Programs" No written response required GRICR.B H Region 1. Philadelphia, Office of the Director 80/06/10 ip
- 8007020669 Forwards site-specific & generic questions re QC disc cracking indications per 800107 meeting & IE Info Hotlice 79-37 on Westinghouse low pressure turbines disc cracks Response requested within 30 days W/o encl CRUTCHFIELD.Q Operating Reactors Branch 5 80/06/11 5ep
- B007140260 Forwards IE Bulletin NO-14, "Degradation of DWR Scram Discharge Vol Capability " Written response required GRIER.B H. Region 1. Philadelphia. Defice of the Director 80/06/12 lp
- 8007170320 Responds to 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls "Three facilities will have completed mods per 1E Rulletin 80-06 by Bioldi List of equipment & status of criteria encl COUNSIL, W 0 Connecticut Yankes Atomic Power Co COUNSIL, W 0 Northeast Utilities 80/06/13 43pp

- B007020700 Forwards IE Bulletin 80-15, "Possible Less of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER,B H Region 1, Philadelphia, Office of the Director B0/06/18 ip
- B007160137 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Due to absence of abnormal conditions no further action planned CDUNSIL-W G Northwast Utilities 80/06/19 llpp
- B007310361 Forwards IX Insp Repts 50-245/80-07 & 30-336/80-05 on 800501-31 No noncompliance noted BRUNNER E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --8007310365 IF Insp Repts 50-245/80-07 & 50-336/80-05 on 800501-31 No moncompliance noted Major areas inspected control rooms & accessible portions of Unit i reactor turbine; radwaste; gas turbine generator & intake bidgs
 SHEDLOSKY.J T., ZIMMERMAN.R P. Region i, Philadelphie, Office of the Director KEIMIG.R R, Region i, Philadelphie, Reactor Operations Nuclear Support Branch SO/06/18 9pp
- 8007020494 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response bearings. SRIER, B.H. Region i, Philadelphia, Office of the Director 80/04/20 in
- 8007160714 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/06/24 jp
- 8007210207 Forwards IE Info Notice 80-24. "Low Level Radwaste Burlal Critoria " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/25 ip
- 8007230146 Forwards IE Dulletin 80-16. "Potential Misapplication of 30/220146 Forwards IE Bulletin 80-16. "Potential Misapplica Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codas " Written response required IE Circular 80-16 also encl No written response required GRIEG.O H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- 8007210071 Confirms that 20-day period for tests in Item 2 of IE Bulletin BO-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR," started at 12 01 AM on 800708 Requests notification of malfunction & estimated manpower GRIER, B H Region 1. Philadelphia, Office of the Director BO/07/09 2pp
- 8007290697 Submits additesponse to 1E Sulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at GWR" Manual scram tost revealed test connection wiring error Hiring corrected & Functional test performed MRDCZKA, E.J. Northeast Utilities 80/07/21 2pp
- R Periodic operating reports & related correspondence
- B007160676 Forwards monthly operating rept for June 1980 MROCZKA.E J Northeast Utilities 80/07/09 ip
- --8007160680 Monthly operating rept for June 1980 HARRAN.O Northeast Utilities 80/07/07 9
- 8007180409 Forwards monthly operating rept for June 1980 MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/09 ip
- ~~8007180413 Monthly operating rept for June 1980 HURRAN, G Northwast Nuclear Energy Co (subs of Northwast Utilitaes) 80/07/07. 19pp
- S Reportable occurrences, LERs & related correspondence
- BOO5230131 PNO-I-80-071 on 800505, significant number of security force personnel, contracted from Interstate Security Sycs, Inc. began taking leave at start of mid-shift Security supervisors working 12-h shifts will maintain full coverage ZIMMERMAN, R P. KEIMIG, R R. DEVLIN, J W. Region 1, Philadelphia, Dffice of the Director 80/05/05 ip
- B007100157 Forwards LER B0-009/03L-0 MROCZKA E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/02 ip

- --8007100164 LER 80-009/03L-0 on 800605, during routine surveillance, found pressure switch 263-596 tripped outside allowable sotpoint Caused by setpoint drift Pressure switch reset to required setpoint

 **Northeast Nuclear Energy (o (subs of Northeast Utilities)
 BO/07/02 3pp
- 8007100167 Forwards LER 80-008/03L-0 MROCZKA,E J Northeast Nuclean Energy Co (subs of Northeast Utilities) 80/07/02 1p
- --8007100172 LER 80-008/03L-0 on 800609, dwring routine surveillances, found pressures surtches 263-52C & 263-54A tripped outside allowable Tech Spec Coused by estpoint drift Pressure switches reset to required setpoints
 BIGIARELLIAM J Northeast Nuclear Energy (o (subs of Northeast Utilities) 80/07/02 3pp
- 8007110465 Forwards LER 80-009/03L-0 MRDCIKALE J Northeast Utilities 80/07/02 lp
- --8007i10474 LER BD-009/OJL-O on 800605, during reactor vessel high pressure scram functional & calibr test, pressure switch 263-55C tripped at 1105 psig Caused by setpoint drift Switch reset to required setpoint & matisfactorily tested * Northeast Utilities 80/07/O2 3pp
- 8007230212 PNO-I-80-098 on 800709, Chem-Nuclear truck carrying solidified radwaste developed crack in main I-boam of trailer Truck was repaired & released 800710 ROTH. J. CROCKER, H. W. EMITH, G. H. Region 1. Philadelphia. Office of the Director 80/07/10 2pp
- 8007180298 Forwards LER 80-010/03L-0 RROCZKA, E J Northwast Utilities 80/07/11 2pp
- --8007180307 LER 80-010/03L-0 on 800613, during tosting of panetration anchor X-45 base plate bolts, one bolt broke & others found improperly installed Cause not stated Bolts removed & replaced.

 * Northeast Utilities 80/07/11 tp
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Security, medical, emorgency & fire protection plans
- B0071B0196 Forwards NRC B00425 ltr to all power reactor licensess, in response to B00529 ltr re emergency response Pacilities at reactor sites Sites w/approval to use closed~circuit television link w/technical support ctr listed CRUTCHFIELD, D M Operating Reactors Branch 5 80/0//07 2pp
- 8007170245 Forwards request for add1 info for review of training & qualiffication plan Request withheld (ref 100782 770)
 VARGA:S A Operating Reactors Branch 1 80/06/20 2pp
- 800721007B Advises licenses that design for reactor collant pump oil collection sys (Item 3 i i3 of NRC 770131 fire protection safety evaluation) is acceptable VAROA.E A Operating Reactors Brench 1 00/06/30 2pp
- o Adjudicatory correspondence
- 8007310243 Forwards Commission 80092/ memorandum & order containing decisions on UCS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISCHMUT,D & Division of Licensing 80/06/25 89pp
- 8007090215 Order granting extension until 800725 for Commission to consider whether to review ALAB-436 & portions of ALAB-561 HOYLE, J.C. Dffice of the Secretary of the Commission 80/07/07 in
- 8007220140 Response in opposition to USC motion for disqualification of Chairman Hendrie re UCS 790917 patition seeking shutdown of facility. Motion failed to show bias defined by Bupreme Court in Hithrow vs. Larkin proceeding PRATT. C. M. Power Authority of the State of New York BRANDENBURG, I L. Cansolidated Edison Co. of New York 80/07/08 499
- 8007140363 Order granting extension until 800801 for Commission to elect whather to review ALAB-436 & rolevant portions of ALAB-541
 HOYLEJ C Office of the Secretary of the Commission 80/07/10

- 8007150711 Response stating whence of pending proceeding in which NY State Energy Ofc petitions to participate as interisted state No petitions to intervene were filed in spent foul pool mod issue Certificate of Svc encl MOORE. J E Hearing Branch 2 80/07/14 3pp
- 8007290522 Motion for reconsideration of Commission 800530 order reportion instituting adjudicatory hearing before ASLB Interim Operations Task Force ropt, 9ECY-283, eliminates basis for commoncement of investigation BRANDENBURG, B. Consolidated Edison Co. of New York PRATT, C.M. Power Authority of the State of New York 80/07/25 12pp
- H General correspondence
- 800721020B Responds to encl 80041B lir to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities surrently operating or planned for operation Village Voice news article cocl DENTON.H R Office of Nuclear Reactor Regulation. Director 80/05/21 10pp
- 8007170259 Responds to 800206 itr re status % responsibilities for emergency preparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRIMES.B K Emergency Preparedness Program Office 80/07/07 2pp
- 8007290682 Requests documentation that future correspondence refacilities be addressed to P Zarakas Requests that WA Monti, MF Shatkouski & JM Makepeace be placed on distribution for some correspondence ZARAKAB, P Consolidated Edison Co of New York 80/07/24 1p
- I Financial information
- 8007240127 Forwards Annual Financial Rept 1979
 ZARAKAS.P Consolidated Edison Co of New York 80/07/15 1p
- --8007240127 Annual Financial Rept 1979
 * Consolidated Edison Co. of New York 80/02/24 43pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BOO7220308 Provides summary of BOO507-08 meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents
 CATTON, I California, Univ nf. Los Angeles 80/05/10 6pp
- P Operating license stage documents % correspondence
- B007020109 Forwards notice of propused issuance of amend to DL Notice concerns 790907 application for increase in spent fuel storage capacity VAROALS A Operating Reactors Branch 1 80/05/19 2pp
- --8007020357 Notice of proposed issuance of amend to facility OL. increasing spent fuel storage capacity VARGA.B A Operating Reactors Branch 1 80/05/19 5pp
- 8007830099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal cupability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISERMUT, D O Division of Licensing 80/06/11 62pp
- B007100393 Summary of B00520 Technology Exchange Meeting 2 w/utils in Bothesda MD to discuss accident mitigation features for your plants LONG, JK Division of Systems Integration 80/06/12 75pp
- 8007140182 Submits rept of task force on interim operation of facilities Rept includes accident risk considerations, social & economic impact considerations & summary of public comments MANRAMANNE | Office of Policy Evaluations BICKWIT-L Office of the General Counsel SECY-80-283 80/06/12 ABpp
- --BOO/140170 Summarizes views of Economic Regulatory Administration, Div of Power Supply & Reliability re electric sys reliability impact of operation of facilities as described in NRC 800428 itr WEINER, R. E. Energy, Dept. of 80/05/15 4pp
- 8007010192 Forwards interim safety evaluation of auxiliary feedwater sys reliability Requests addl info to complete NRC review of Lessons Learned Task Force Items 2 1 7 a & b VARGA.S A Operating Reactors Branch 1 80/06/13 2pp

. ,*

- 007010199 Interim sufety evaluation re implementation of recommendations for auxiliary feeduater sys * Operating Reactors Branch 1 80/06/13 17pp
- Oldilo Notification of 800425 meeting w/utils & Bandia Labs in thosdaiMD fur presentation of overview of facilities risk udy Agenda ent] RAELIS L. Reliability & Risk Assessment Branch 80/06/16 39p
- 010075 Notification of 800624 mosting w/otil to discuss NRC -evaluation of operational GA program for Pacility NMAY.J T Quality Associance Branch 80/06/17 2pp
- 170447 Forwards request fur addl info to complete review of octric distribution sys voltages RGA,9 A Operating Reactors Dranch 1 B0/06/20 App
- 110357 Summary of 800530 meeting w/util in Bethesde.MD re status of tion plan SHANL N Operating Reactors Branch 1 80/06/23 3pp
- 010408 Notification of 800417 meeting w/utils in Bethesda.HD to scuss containment structural response follure pressures & ilure modes for facilities as described in NRC 800410 ltr Camm Ed
- YER. J F Reactor Systems Branch 80/05/26
- 090228 Forwards "Endurance Tosting of Auxiliary Boiler Feedwater mps." per Bulletins & Orders Task Force Short-Term commendation 2 HILLIH J Consolidated Edison Co of New York 60/06/30 13pp
- 090291 Forwards detailed info for implementation of NUREG-0578, tagory B requirements,per 791231 responso to commendation 2 1 6(b) One illegible auxiliary bldg drawing
- HLL.W.J. Consolidated Edison Co. of New York 60/05/30 lipp
- 170314 Bummary of 800612 meeting w/utils in Detherda.MD re interim liability evaluation grogram BIANLEN Operating Reactors Branch 1 80/06/30 3pp
- 210099 Requests that util submit revised schedule & justification, completion of ATHS mods within 30 days Util is requested improve upon Fall 1982 completion date because of risk presented by facility ROASBA Operating Reactors Branch 1 HO/O6/30 2pp
- 210498 "Evaluation of Impingement Lestes of White Perch at Indian int Nuclear Station & Other Hodson River Power Plants "
 HINKLE, W., DARNTHOUSE, L. W., MIRN, D. C. Gak Ridge National arabony FIN R-0427 NUREG/CR-1100 90/06/30 152pp
- 170241 Forwards request for addition to backfitting of sovere ident mitigation features Response requested within 30
- PARAT M Assistant Director for Operating Reactors 80/07/02
- '50001 Requests submittal of application for amend to license sisting of Tech Spec changos & license conditions PWR lel Tech Specs & Model license conditions for TMI-2 states for TMI-2 states for the for goldance sense Learned Colegory A thems end if for goldance SEMHUT.D Q Division of Licensing 80/07/02 A9ps
- 170598 Summary of 800625 mouting w/Pickard, lowe & Garrich, Inc. re k study including modeling for plume tragectory, realment event tree & modeling.use of plant data & saideration of external events RAELS L. Reliability & Rick Association Dranch 80/07/0/ Opp
- 230446 Summary of 80050/-00 terhnology exchange meetings w/utits Chirage IL ru cure melt accident sequences to associated momentalogy for facilities MRC perceives real argency to answers to key technical questions ZERJF Reactor Systems Branch EN/07/09 12pp
- 120454 Forwards addl 111fb re effects of flooding due to failure of Inclass 1 saisant equipment, per NRC 800570 request resize drawings avoilable in Central Files only MAB.P Convolidated Edison Co. of New York 80/07/14 24pp
- 20504 Forwards response to NRC 800523 request for addl info rs GA gram & revised response to Question 10, originally witted by util 800523 fer IAMAS.P Convolidated Edison (o of New York 80/07/15 23pp

- 8007230471 Forwards final response to request for addi info re electrical override/bypass aspects of containment purge sys, per A Schwencer 800423 ltr ZARAMAS.P Consolidated Edison Co of New York 80/07/15 17pp
- G inspection reports, IE Bulletins & correspondence
- 8007020124 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8007010322 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required CRIER, B M Region i. Philadelphia. Office of the Director 80/05/29 1p
- 8007010081 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVC8) Holdup Tanks "
 All Unit 2 tanks that could contain primary sys water have adequate protection Bullotin not applicable to Unit 1
 CAHILL, W J Consolidated Edison Co of New York 80/06/06 Spp
- 8007020077 Forwards response to IE Builetin 80-12, "Decay Heat Ramoval Bys Operability " Bulletin not applicable to Unit 1 which is in defueled condition Existing Unit 2 procedures provide for adequate alternate means for removal of decay heat CANILL, H J Consolidated Edison Co of New York 80/06/06 5pp
- 8007210555 Forward: IE Info Notice 80-26, "Evoluation of Contractor GA Programs " No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 40/66/10 ip
- B00716034) Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required
 GRIER, D H Region 1. Philadelphia, Office of the Director
 BO/06/11 ip
- G007170287 Forwards partial response to IE Bulletin 80~04. "Engineered Bafety Feature (ESF) Reset Controls." for Unit 2 Unit 1 was shutdown 741031 & in defueled condition, therefore bulletin not applicable CAHILL, W J Consolidated Edison Co of New York 80/06/13 5pp
- 8007020710 Forwards IE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/06/18 ip
- BOO7310499 Forwards IE Inap Rept 50-247/80-06 on BOO513-16 No noncompliance noted BRUNNER:E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch BO/06/18 2pp
- --8007310504 lE Insp Rept 50-247/80-06 on 800513-16 Nd noncompliance noted Major areas inspected LOCA procedures & training of litensed operators in use of LOCA procedures HIQQING.J C Region i. Philadelphia. Office of the Director XISTER.H B Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/16 Spp
- B007020497 Forwards IE Circular 80-15, "Loss of Reactor Coolent Pump Cooling & Natural Circulation Cooldown "No written response raquired CAIER.8 H Region 1, Philadelphia, Office of the Director B0/06/20 ip
- 8007:80360 Responds to IE Bulletin 80-09 No Hydramotor actuators used in any Unit 2 safety-related sys Unit 1 presently in defuelod condition
 CAHILL: H J Commonwealth Edison Co 80/06/20 ip
- 8007180592 Responds to iR Bulletin 80-10 Investigation revealed potential for nonradioactive sys to become contaminated through isolation valve seal water/city water interface Double check valves installed Monitoring program described CAHILL.W J Commonwealth Edison Co 80/06/20 2pp
- 9007160688 Forwards IE Circular 80-14, "Redicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel." No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip

- 8007210172 Forwards IE Info Notice 80~24. "Low Level Radwaste Burial Criteria " No written response required CRIER,B H Region 1, Philadelphia, Office of the Director 80/06/25 1p
- 8007230106 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes" Written response required IE Circular 80-11 also encl No written response required ORIER.8 H Region i, Philadelphia. Office of the Director 80/06/27 2pp
- R Periodic operating reports & related correspondence
- BOO7170363 Forwards "Annual Environ Monitoring Rept.Part D Radiological Rept." CAHILL-W J Consolidated Edison Co. of New York BO/06/30 ip
- --8007i70355 "Annual Environ Monitoring Rept, Part 8 Radiological Rept "
 * Consolidated Edison Co of New York 80/06/30 66pp
- 8007130669 Submits daily fish counts from intake screens for June 1980 MONTI.W A Consolidated Edison Co of New York 80/07/10 17pp
- 8007210473 Forwards util 800613 ltr & "Quarterly Rept on Seismic Monitoring Natwork in Vicinity of Indian Point,NY, Con Ed Project Dec 1979-Feb 1980" DAVIS,J P Consolidated Edison Co of New York 80/07/14 2pp
- 8007220476 Forwards monthly operating rept for June 1980
 IARAKAS,P Consolidated Edison Co of New York 80/07/15 ip
- ---8007220479 Monthly operating rept for June 1980 EICH E Consolidated Edison Co of New York 80/07/08 7pp
- 8007220523 Forwards "Daily Count from Intake Screens for June 1980 "
 ZARAKAS,P Consulidated Edison Co of New York 80/07/15 ip
- --8007220524 "Daily Count from 1ptake Screens for June 1980 "
 * Consolidated Edison Co of New York 80/07/i5 4pp
- B Reportable occurrences, LERs & related correspondence
- 8007020i45 PNO-I-80-093 on 8006i7.util workers Union Local 1-2 authorized strike on 8006i8 Senior operators are excluded Required IE prestrike inaps have been completed OREENNAN,E G. BRUNNER,E J. Region i. Philadelphio, Office of the Director 80/06/i7 1p
- 8007110396 Forwards LER 80-005/03L-0

 YARAKAB, P Consolidated Edison Co of New York 80/07/07 ip
- --8007ii0404 LER 80-005/03L-0 on 800507, perturbation in secondary blowdown piping associated w/stram generator 21 resulted in failure of pipe clamp associated w/subber 46-8R-3 Gaused by failure of water hammer Pipe clamp repaired MAKEPEACE, J M Consolidated Edison Co of New York 80/07/07 2pp
- 8007240169 Forwards LER 80-007/03L-0 ZARAKAS,P Consolidated Edison Co of New York 80/07/17 ip
- --B007240172 LER B0-007/03L-0 on B00421, found control for auxiliary feedwater pump 23 transferred to local Caused by unauthorized actuation of pump transfer switch Responsible personnel disantsed HAKEPEACE, J M Consolidated Edison Co of New York 80/07/17
- T Hearing transcripts on non-antitrust matters
- 8007140084 Unofficial transcript of 800626 briefing on recommendations of Indian Point Task Force in Washington, DC Pp 1-62 Viewgraphs encl 4 Commission 80/06/26 64pp
- 8007240164 Transcript of 800711 public meeting in Washington DC Pp 1-6 * Commission 80/07/11 6pp
- B007250347 Unofficial transcript of B00717 discussion on Indian Point in Washington.DC Pp 1~72 Draft memorandum & order encl + Commission, 80/07/17 B0pp

- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8007010'347 Forwards safeguards contingincy plan amend Plan withheld (ref 10CFR2 790) PEOPLES:D L Commonwealth Edison to 80/06/27 tp
- B007290562 Submits results of mini-icvice of safe shutdown analysis No reasonable assurance that licensees fire protection will ailou safe shutdown of Units 2 % 3 As min.rccommends requirement for alternate shutdown sys or dedicated sys HALL.R E Brookhaven National Laboratory 80/07/09 7pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 Memorindum & Older containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISERHUT, D.C. Division of Licensing 80/06/25 89pp
- B007010331 Forwards safety evaluation & EIA re spent fuel peo) mods M/o encis CDDDARD.R J Hearing Branch 2 80/06/27 ip
- P Operating license stage documents & correspondence
- B007230028 Summary of B00207 meeting w/Mark I Gwners group in Bethesda, MD,re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program ORIMEB,C T Plant Systems Branch B0/02/21 31pp
- 80070i0003 Forwards safety evaluation & EIA supporting proposed facility mods to increase spent fuel storage paul capacity Final approval cannot be granted until ASLB resolves legal issues CRUTCHFIELD, D.M. Operating Reactors Branch 2 80/06/05 2pp
- --800701000B Rafety evaluation supporting proposed famility mods to increase spent fuel sturage pool capacity

 * Office of Nuclear Reactor Regulation, Director 80/06/06 14pm
- --8007010011 EIA supporting proposed facility mads to increase spent fuel storage pool capacity

 # Office of Nuclear Reactor Regulation, Director 80/06/06
 10on
- B007020196 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/31 2pp
- 8007010070 Responds to FDIA request for 57 documents referenced in M Tokar memo to ACRG concerning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTON, J M Davision of Rules and Records 110/06/20 2pp
- --B007010088 Discusses similarities in fuel fod failures for BHRs resulting from control blade movements Failure pattern W/Drosden & LACBHR fuel rods was associated W/location of fuel rods relative to control rods SIEGEL, B L. Atomic Energy Commission. Directorate of Licensing 702/09/20 Don
- --B0070i0i03 Forwards summary of NRC 750F19 meeting w/util GE.Comm Ed & BNHL to discuss fuel failure detection bys & AD which resulted in pellyte-cladding mechanical interaction fuel failure Discussion outline & list of attendues encl BIEGEL, R L., MAGEN, H., FIEND, D. Core Performance Branch 75/03/03 9pp
- B007070ii6 Bubmits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECEK.R F Commonwealth Edison Co 80/06/26 4pp
- B007080063 Responds to NRC B00515 request for add1 info concerning adequary of station electric distribution sys voltages JANECEK, R F Commonwealth Edison Co 80/06/30 4pp
- BOO7070345 Forwards revised schedule * status info for Mark 1 program, foedwater sparger replacement *; general work planned for Guad Cities i outage Proceeding on priority basis w/mods providing languagest safety intrens marging REED.C Commonwealth Edison Co 80/07/0° 19pp

- B007210212 Responds to NRC request for addlinfoire turbine disks Applicable turbine missile analysis was presented in Amend 2 to Guad Cities (Plapplication Analysis applies to Directed due to similarity of general arrangement JANECEM.R F. Commonwealth Edison Co. 80/07/15. Ip
- O Inspection reports IE Bulletins & correspondence
- BD07140545 Forwards lE Bulletin 80-13, "(racking in Core Spray Spargers " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/05/12 to
- 8007070072 Forwards 1E Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 on 800407-0502 & notice of violation KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/23 2pp
- --B007070074 Notice of violation from insp on 800407-0502 * Region 3. Chicago, Office of the Director 80/05/23 2pg
- ---B007070080 IL Insp Repts 50-10/80-09.50-237/60-08 & 50-249/80-12 on B00407-0502 Noncompliantice noted failure to adhere to GA program requirements Contaminated clothing found lying inside controlled contaminated area SPESSARD.R L. BARKER.J L. IDNOUE.T M. Region 3. Chicago, Office of the Director B0/05/23 7pp
- 8007020065 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/28 Ip
- 8007010086 forwards if Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/05/29 lp
- 8007020756 Forwards revised response to 1E Bulletin 79-018. "Environ Qualification of Class IE Equapment" Identifies areas where effort is continuing in identification of equipment qualifications W/o encl
 JANECEK.H F Commonwealth Edison Co 80/06/02 1p
- 8007020074 Forwards revised response to JE Bulletin 79-018, "Environ Qualification of Class IE Equipment" W/o encl PEOPLES.D L. Commonwealth Edison Co 80/06/10 lp
- 8007220136 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/10
- 8007140309 Forwards IE Duiletin 80~14, "Degradation of BWR Scram Discharge Vol Cupability " Written response required XEPPLER.J G Region 3, Chicago, Office of the Director 80/06/12
- B007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Beficiencies." No safety-rolated sys or component at Bresden 2 & 3 uses AH-90 or MH-90 series hydramotor PEOPLES.D L Commonwealth Edison Co B0/04/16 3pp
- B007030037 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago, Offsice of the Director 80/06/18 Ip
- 8007230371 Forwards IE Insp Repts 50-010/80-10,50-237/80-09 & 50-249/80-13 on 800505-29 \ notice of violation HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --8007230379 Notice of violation from insp on 800505-29 * Region J. Chicago, Office of the Director 80/06/19 ip
- --B0072303BB IE Insp Repts 50-010/80-10.50-237/80-09 & 30-249/80-13 on B00305-29 Noncompliance noted failure to report events in accordance w/Tech Specs BARKER, J. L. SPESSARD, R i Region 3, Chicago, Diffice of the Director B0/06/19 9pp
- 8007020389 Forwards IC Circular 80-15. "Loss of Avactor Coolant Pump Cooling & Natural Circulation Cooldnum " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/20

- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Hater Bys & Rosultant Internal Contamination of Personnel " No written response required KEPPLER, J G Rogion 3, Chicago, Office of the Director 60/06/24
- 8007230289 Forwards IE Bulletin 80-16, "Potential Misappilcation of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/27
- B007180003 Ack receipt of 800613 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-010/80-09. 59-237/80-08 & 50-249/80-12 KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/01
- ---8007180010 Responds to NRC 800523 ltr re violations noted in 1E Insp Repts 50-010/80-09, 50-237/80-08 t 50-249/80-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED.C Commonwealth Edison Co 80/06/13 6pp
- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17.
 "Failure of Control Rods to Insert During Scram at DHR."
 will start at 12 01 AM on 800708 Test should be completed
 within 20 days Requests notification of malfunction
 KEPPLER.J Q Region 3, Chicago. Office of the Director 80/07/07
- B007250641 Responds to IC Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactlyity to Environ " Any affected sys will be restricted if contamination found PEQPLES.D L Commonwealth Edison Co 80/07/07 2pp
- B007250630 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be met prior to startup H/o encl
 PEDPLES,D L Commonwealth Edison Co B0/07/07 2pp
- G007250638 Forwards response to 1E Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co 80/07/09 7pp
- 8007140630 Responds to IE Bulletin 80-17 re results of tests required by Item 1 No significant amount of water in scram discharge vols Vent & drain lines also verified free of obstructions by performing dynamic air test

 JANECEKAR F Commonwealth Edison Co 80/07/10 Epp
- 8007310490 Forwards final inservice insp rept for 800103-0424 inservice insp of reactor pressure vessel & primary sys piping STEPHENSON B Commonwealth Edison Co 80/07/10 1p
- --8007310486 Final inservice insp rept for 800103-0424 inservice insp of reactor pressure vessel & primary sys piping * Commonwealth Edison Co 80/07/10 27pp
- 8007300485 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys." by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria" JANECEK, R F Commonwealth Edison Co 80/07/16 ip
- --8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations," Revision 2 SNYDER.T K EDS Nuclear, Inc 80/03/07 ilpp
- ---B007300508 "Engineering Criteria Procedure for Application of Blume Curves Criteria" SNYDER:T K. EDS Nuclear, Inc. 80/03/07 20pp
- 0007240291 Ack receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-249/80-09 KEPPLER.J G Region 3, Chicago, Office of the Director 80/07/17 200
- --8007240298 Aesponds to NRC 800426 ltr re violations noted in IE Insp Rept 50-249/80-09 Corrective actions reactor water cleanup water hammer damage repaired & control red drive sys seismic design proved adequate FEOPLES.D.L. Commenwealth Edison Co. 1 80/06/13 46pp

- R Periodic operating reports & related correspondence
- BOO7180333 Forwards monthly operating repts for June 1980 STEPHENBON, B B Commonwealth Edison Co 80/07/09 1p
- --8007180334 Monthly operating ropts for June 1980 CIESZIEWICZ, 8 Commonwealth Edison Co 80/07/02 23pg
- 8 Reportable occurrences: LERs & related correspondence
- 8007220455 Forwards LER 80~026/03L-0 STEPHENSON B B Commonwealth Edison Co 80/07/09 tp
- --B007220459 LEB 80-026/03L-0 on B00620 abnormal amount of water was being added to sys Caused by thirteen leaking tubes Tubes were subsequently plugged * Commonwealth Edison Co 80/07/09 ip
- BOO7220377 Forwards LER 80-027/01T-0 STEPHENSON, 8 B Commonwealth Edison Co 80/07/15 ip
- ---BOD72205B3 LER BO-027/01T-O on GOO707, engineering evaluation of control pod drive scram discharge pining revealed failure to meet FBAR seismic requirements Caused by design deficiency Analysis performed.

 HOLLAND, P Commonwealth Edison Co BO/07/16 2pp
- BOO7230359 LER 79-024 has been concelled COLLING.M Commonwealth Edison Co 80/07/22 ip
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- C Utility Environmental Report (CR), amends & correspondence
- 8007290406 Forwards Waste Packaging Insp Rept 15000037/80-08 on 800603-06 No noncompliance noted 8TOHR, J. P. Region 2. Atlanta, Evel Facility & Materials Safety Branch 80/06/20 3pp
- --8007290410 Waste Packaging Insp Rept 150000039/80-08 on 800603-06 No noncompliance noted Najor areas inspected compliance w/DOT & NRC regulations
 TROUP, G. L. MACARTHUR, T. C. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/06/20 6pp
- F Security, medical, emergoncy & fire protection plans
- 8007140518 Summary of 800619 meeting w/util in Bethesda.MD re proposed App R to 10CFR50 on fire protection GROTENHUIS.M Operating Reactors Branch 1 80/04/23 2pp
- BOO7E3044E Forwards facility evacuation time estimates in response to NRC 791129 request UMRIO, R E Florida Power & Light Co BO/07/17 Spp
- 8007230454 Forwards facility evacuation time estimates in response to NRC 791127 request UHRIO, R E Florida Power & Light Co 80/07/17 7pp
- @ Adjudicatory correspondence
- 8007070279 Requests parmission to make comments at hearing to be held in Miami on steam generators repair PETERSON, A F Affiliation Unknown 80/06/24 ip
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action so fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 87pp
- 8007070094 Advises of NRC estimates that DES re proposed amands to QLs parmitting steam generator repair,will be issued by 800901 & FES by 801201
 COLDDERO,S C Hearing Branch 2 80/07/D2 ip
- H General correspondence
- 8007150808 Forwards responses to first 31 questions raised in 800402 correspondence re facility. Includes two pertinent repts & one page each from facility Tech Specs & STB Remainder of questions will be answered at later date VARGA.S A Operating Reactors Branch 1 80/06/24 8pp

- M Antitrust coricspandence
- 8007150/19 Response stating no objection to Orlando Utils Commission 800620 withdrawal of intervention FL Cities 800707 comments relegion treatment will be addressed in Unit 2 antitrust proceeding Cretificate Section 60/07/11 4pp
- P Operating license stage documents & correspondence
- 8007230097 Requests submittal of pinposed lech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance CISENNUT, D.G. Division of Licensing 80/06/11 62pp
- 8007210311 Forwards Amends 58 % 51 to Licenses DPR-31 & DPR-41, respectively, sufety evaluation & notice of issuance & availability
 VARGA: S.A. Operating Reactors Dranch 1 80/00/12 2pp
- --0007210314 Amends 58 & 51 to licenses DPR-31 t DPR-41, respectively, incorporating results of revised ECCS analysis for steam generator plugging level of 25% & permitting rontinued operation of Unit 4 VARGALS A DEFILE of Nuclear Reactor Regulation, Director 60/06/12 15pp
- --8007210319 Safety evaluation supporting Amends 98 & 51 to Licenses DPR-31 & UPR-41, respectively # Office of Nuclear Reactor Regulation, Director 80/06/1P
- --8007210323 Notice of issuance > availability of Amends 58 & 51 to Licenses DPR-31 & DPR-41.respectively VARGA.8 A Operating Reactors Branch 1 80/06/12 2pp
- B007110199 Advises NRC that NUREG-05/8 requirement to measure chlorides & dissolved gasus in RCS following accident is excessive & involves unnecessary personnol exposure to radiation Requests that NRC reconsider position UHRIO.R E Florida Power & Light Co 60/06/27 lp
- BOD7080140 Requests permission to delay schoduled shutdown for steam generator insp until 801006 Delay needed to accommodate peak load demand for Jul-Ang 1980 Updated generating capacity, expected load demand into & Class III fee encl
 UHRIO.R E Florida Power & Light Co 80/06/30 12pp
- BQ07250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model Trense conditions for TMI-2 Lessons Luarned Category A Items on I for guidance EISCNHUT.D Q Division of Licensing 80/07/02 67pp
- 8007110261 Notifies that commitment date for completion of plant parameter display in interim technical support ctr is revised to 800831 URRIO.R E Florids Power & Light Co 80/07/03 lp
- BOO7110256 Advises that Westinghouse "ubmittal of WCAP-9748 & WCAP-9740 completes Phase C augmentric LDCA loads analysis MCAP-955B & WCAP-955D provide add1 info requested at BOO226 meeting UHRIO.R E Florida Power & Light Co 80/07/07 2pp
- BOO7150710 Responds to NRC BOO619 request re endaugered, threatened or proposed to be listed species in plant area Jacksonville ofc will provide list after review Advises of change in consultation procedures

 BIJEOLITZ, W. O. Interior, Dept. of, Fish & Wildlife Service 80/07/09
- 8007210368 Responds to NRC 800619 ltr ie util fil amend request Provides list of potentially threatened & endangered species in proximity to facility Compilete biological assessment should be provided fullines info to be included in assessment HANKLA-D J Interior, Dept of. Fish & Wildlife Service 80/07/14
- BOO72203BO Advises that Henry Pratt (a torque & strass analyses re containment purge have been dolayed Upon completion & receipt of analyses, util util review & prepare issponse demonstrating valve ability to close during DBA-LOGA UHRIG.R E Florida Power & Light Co 80/0//th lp
- 0007300767 Bummary of 800630 menting w/all reviewers on steam generator repair program re overview of event chronology ORDIENHUIS.M Operating Reserve Beauth 1 80/07/16 3pp

- 8007280531 Forwards responses to questions re proposed installation of condensate polishing demineralizers Responses suppl info previously submitted in 800318 & 0527 ltrs Oversize drawings encl
- UHRIGAR E Florida Power & Light Co 80/07/22 21pp
- --9007280551 "Sys Flow Diagram Condensate Polishing Demineralizer Sys "
 + Bechtel Corp 80/05/02 1p
- --8007280554 "Site Plan " # Bechtel Corp 74/09/21 1p
- B0072B0562 Responds to B00530 ltr requesting info on auxiliary feedwater sys Attachment 2 provides addl info to suppl 791220 response UHRIGRE Florida Power & Light Co 80/07/22 7pp
- B007310377 Informs that American crocodile & bald eagle inadvertently omitted from 800714 endangered species list OBERHEU, J C Interior, Dept of, Fish & Wildlife Service 80/07/25 to
- Q Inspection reports, IE Bullatins & correspondence
- 8007240206 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode." No response required O'REILLY.J P Region 2, Atlanta, Office of the Director 60/05/08
- 8007020231 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007210458 Forwards IE Circular 80-12, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/28 is
- 8007010305 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Fasdwater Pumps" No written response required D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/29
- B00710012B Forwards response to Items 1.2 & 3 of 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment" UHR10.R E Florida Power & Light Co 80/06/02 600pp
- B007220062 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10, 2pp
- 9007160265 Forwards IE Info Notice 80-27. Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/11 1p
- 8007020752 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/06/18
- 8007020454 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20,
- 6007100025 Forwards response to IE Builetin 80-04, "Engineered Safety Features (ESF) Reset Controls " Lists aquipment which dues not remain in emergency mode upon reset of ESF signal. Followup response will be each by 800801 UHRIO.R.E. Florida Power & Light Co 80/06/20 App
- 8007170109 Forwards IE Circular HO-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel " No written response required D'REILLY, J P Region 2, Atlanta, Dépice of the Director. 80/06/24

- 8007230243 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Hodels 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Hritten response required. IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27 in
- 8007210064 Forwards two vol Phase II response to IE Bulletin 79-01B re environ qualification of Class IE equipment Supersedes 800602 Phase I response. Wo sncl UHRIO, R E Fioride Power & Light Co 80/07/03 2pp
- 8007140373 Advises that add1 info ra inservice insp will be submitted by 800915 per NRC 800414 request
 나채대G,R E Florida Power & Light Co 80/07/09 1p
- 8007250282 Responds to IE Bulletin 80-11. "Masonry Wall Derign " Rept not complete but safety-related walls have been identified & re-evaluation program developed Rept will be submitted by 800723 UMRIO, R. Florida Power & Light Co 80/07/09 ip
- 8007300559 Advises that final response to IE Bulletin 80-10 will be submitted by 600801 UHRIO.R E. Florida Power & Light Co 80/07/09 1p
- 8007310084 Advises that full response to IE Bulletin 80-08 will be submitted by 801031 UHRIQ.R E Florida Power & Light Co 80/07/09 ip.
- 8007240261 Ack receipt of 800626 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-16 & 50-251/80-14 LENTB, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/07/11 1p
- --8007240263 Responds to NRC 800529 itr re violations noted in IE Insp Repts 50-250/80-16 & 50-251/80-14 Corrective actions tracked open noncompliance items & hired addl GC personnel URRIGR E Florida Power & Light Co 80/06/26. 3pp
- --8007240266 Forwards IE Insp Repts 50-250/80-16 & 50-251/80-14 on 800401-30 & notices of violation & deviation LEHIS.R.C Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 2p.
- --B007240272 Notice of violation from insp on 800401-30 * Region 2, Atlanta, Office of the Director 80/05/29 ip.
- --B907240276 Natice of deviation from insp on 800401-30
 * Region 2, Atlanta, Office of the Director B0/05/29 ip,
- --8007240281 IE Insp Repts 50-250/80-16 & 50-251/80-14 on 800401-30.
 Noncompliance noted: failure to track implementation of corrective action & to meet corrective action deadline, VOOT-LOHELLR J Region 2. Atlanta, Office of the Director MARTINER D Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/05/29 &pp
- R Periodic operating reports & related correspondence
- 8007240075 Forwards semiannual radioactive effluent & environ Monitoring rapts for Jan-June 1978 W/o environ monitoring rept rept UHRIGARE Florida Power & Light Co 78/08/30 ip
- --B007240086 "Semiannual Radioactive Effluent Rapts for Jan-June 1978 * Florida Power & Light Co. 78/08/30. 13pp
- 8007220343 Forwards "Semiannual Radioactive Effluent Rept," & "Semiannual Monitoring Rept." For Jul-Dec 1978 per Tech Spec 6.9.4
 UHRIG.R.E Florida Power & Light Co 79/03/01. 1p
- --B007220550 "Semiannual Rapt of Radioactive Effluent Releases," Jul-Dec 1978 * Florida Power & Light Co 79/03/01 25pp.
- 8007240174 Forwards monthly operating repts for June 1980 SCHMIDT.A D Florida Power & Light Co 80/07/05, ip
- --B007240177 Monthly operating repts for June 1980 CHILBON, V. T Florida Power & Light Co 80/07/05 10pp

- 8 Reportable accurrences. LERs & related correspondence
- GOO7220419 Forwards LER 80-014/01T-0 SCHMIDT, A D Florida Power & Light Co 80/07/10 ip
- --G007220421 LFR B0-014/01T-0 on B00626.AE advised that insp/evaluation in progress per IE Bulletin 79-14 revealed deficiency involving auxiliary feedwater sys pump suction piping Cause net stated PACE.P L Florida Power & Light Co 80/07/10 2pp
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- C Utility Environmental Report (ER), amends & correspondence
- 8007270406 Forwards Waste Packaging Insp Rept 15000037/80-08 on 800603-06 No noncompliance noted STOHR.J P Region 2 Atlanta, Fuel Facility & Materials Safety Branch 80/06/20 3pp
- --8007290410 Waste Packaging Insp Rept 150000039/80-08 on 800603-06 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations TROUP.0 L . MACARTHUR.T C Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/20 App
- F Security, modical, emergency & fire protection plans
- 8007140518 Summary of 800619 meeting w/util in Bethesda,MD re proposed App R to 10CFR50 on fire protection GROTENHUIS,M Operating Reactors Branch 1 80/06/23 2pp
- G007230442 Forwards facility evacuation time estimates in response to NRC 791129 request UHRIG.R E Florida Power & Light Co 80/07/17 8pp
- BOO7230454 Forwards facility evacuation time estimates in response to NRC 791129 request UHRIG-R E Florida Power & Light Co 80/07/17 7pp
- G Adjudicatory correspondence
- 8007070279 Requests permission to make comments of hearing to be held in Mlami on stoam generators repair PETERSON,A F Affiliation Unknown 80/06/24 ip
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D 0 Division of Licensing 80/04/25 89pp
- 8007070094 Advises of NRC estimates that DES re proposed amends to OLs permitting steam generator repair.will be issued by 800901 & FEB by 801201 GOLDBERG-B C Hearing Brench 2 80/07/02 ip
- H. General correspondence
- B007160B0B Forwards responses to first 31 questions raised in 800402 correspondence re facility Includes two pertinent repts & one page each from facility Incl Speck & STS Remainder of questions will be answered at later date VARGA.S A Operating Reactors Branch 1 80/06/24 8pp
- M Antitrust correspondence
- 8007130719 Response stating no objection to Drlando Utils Commission 800620 withdrawal of intervention FL Cities 800707 comments re equal treatment will be addressed in Unit 2 antitrust proceeding Certificate Svc encl DEWEY.L 8 Antitrust Division 80/07/11 4pp
- P. Operating license stage documents & correspondence
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
 EISENHUT, D O Division of Licensing 80/04/11 62pp
- BOO7210311 Forwards Amends 58 % 51 to Licenses DPR-21 % DPR-41, respectively, safety evaluation & notice of issuance & availability VAROA.S A Operating Reactors Branch 1 80/06/12 2pp

- --B007210314 Amends 58 & 51 to Licenses DPR-31 % DPR-41, respectively, incorporating results of revised ECCS analysis for steam generator plugging level of 25/ & permitting continued operation of Unit 4 VARGA. S A Office of Nuclear Reactor Regulation, Director B0/06/12 | 15pp
- --B007210319 Safety evaluation supporting Amends 58 % 51 to Licenses
 DPR-31 & DPR-41, respectively
 * Office of Nuclear Reactor Regulation Director 80/06/12
- --8007210323 Notice of issuance & availability of Amends 58 & 51 to Licenses DPR-31 & DPR-41, respectively VARGA, S.A. Operating Reactors Branch 1 80/06/12 2pp
- B007110199 Advises NRC that NUREG-0578 requirement to measure chlorides & dissolved gases in RCS following accident is accessive & involves unnecessary personnel exposure to Tadintion Requests that TRC reconsider passition UHRIG.R E Florida Power & Light Lo. 80.06/27 ip
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes % license conditions PWR Model Tech Specs & Model license conditions for TM1-2 Lessons Learned Category A items entil for guidance EISENHUT, D G Division of Licensing 80/07/0, 69pp
- B007i1026l Notifies that commitment date for completion of plant parameter display in interim technical support Ltr is revised to B0083i UHRIG.R E Florida Power & Light Co B0/07/03 Ip
- 8007110256 Advises that Westinghouse submittal of MCAP-9748 & MCAP-9749 completes Phase C asymmetric LOCA loads analysis MCAP-9558 & MCAP-9570 provide addl info requested at 800226 meeting UHRIG.R E Florida Power & Light Co 80/07/07 2pp
- B007150710 Respands to NRC B00619 request to endangered threatened or proposed to be listed species in plant area vacksonville afc will provide list after review Advisos of change in consultation procedures
 STIEGLITZ.W D Interior.Dept of, Fish & Wildlife Service 80/07/08
- 8007210368 Responds to MRC 800617 itr re util DL amend request Provides list of putentially threatened & endangered species in proximity to facility Complete biological assessment should be provided Outlines info to be included in assessment HANKLA.D J Interior.Dept of Fish & Wildlife Service 80/07/14
- 8007220380 Advises that Henry Pratt Co turque & stress analyses to containment purgs have been dulayed Upon completion & receipt of analyses util will review & prepare response demonstrating valve ability to close during DBA-LOCA UHRIG.R E Florida Power & Light Co 80/07/15 1p
- 8007300567 Summary of 800630 meeting w/all leviewers on steam generator repair program re overview of event chronology GROTENHUIS.M Operating Reactors Branch 1 80/07/14 3pp
- 8007280531 Forwards responses to questions re proposed installation of condensate polishing demineralizers Responses suppl info previously submitted in 800318 & 0527 ltrs Oversize drawings encl UMRIOR E Florida Power & Light Co 80/07/2g 21pp
- --8007280556 "Site Plan" # Bechtel Corp 76/09/21 1p
- 8007280762 Responds to 800530 ltr requesting info on auxiliary feedwater sys Attachment 2 provides addl info to suppl 791220 response UHRIO.R E Florida Power & light Co 80/07/22 7pp
- BOO7310377 Informs that American crucodile & buld eagle inadvertently omitted from 800714 endangired species list OBERHEU, J C Interior Dept of, Fish & Wildlife Service 80/07/25 in

ł

- Inspection reports. If Bulletin' & correspondence
- 00/240206 Forwards II Info Notice 80-20. "Loss of Decay Heat Removal (apphility at David Bassa Unit 1 While in Refueling Mode "Na response required 0/861117 J.P. Region 2. Atlanta. Office of the Director 80/05/08
- 00/070,"It forwards It into Notice 80-22. "Dreakdowns in Contamination Control Programs ' No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 100/210458 Forwards || Circular 80-13, "Grid Strap Damage in Westinghouse fuel Assemblies," No written response required D'AFILLY, | P. Region 2, Atlanta, Office of the Director
- 8007010206 Forwards IF Info Notice 80-23. "Loss of Suction to Emergency Foedwater Pumps" No written response required U'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/29
- NOTIO0055 Foraids IC Insp Rept h0-251/80-16 on 800515-16 No noncompliance insted HUMPHY/C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 /Pp
- --8007100060 IE Insp Rept 50-251/80-16 on 800515-16 to nontempliance noted Hayer areas inspected stram generator faedwater line radiography per IE Bulletin 79-13
 HERDIAR Region 2. Atlanta. Reactor Construction & Engineering Ouppurt Branch CROMETY, B.R. Region 2. Atlanta Office of the Director 60/05/29 3pp
- 800/100128 forwards response to Items 1.2 % 3 of 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment"

 UMBIG.R t I lorida Power & Light Co 80/06/02 600pp
- 8007220062 Forwards 16 Info Notice 80:26. "Evaluation of Contractor GA Programs" No written response required GARCILIA DP Region 2. Atlanta. Office of the Director 80/06/10
- HOD/1602A5 Forwards If Info Natice (No-77, "Degradation of Reactor Coolant Pump Studs Na apecific action or response O'RELLY, J.P. Region P. Atlanta, Defice of the Director 80/06/11
- 9007020752 Forwards IF Bullotin 80-15, "Pussible Loss of Emergency Notification Sys (ENS) W/Loss of Office Power " Written response required O'Britty, J P. Region 2, Atlanta, Office of the Director 80/06.
 - Region 2, Atlanta, Office of the Director 80/06/18
- 800/020454 Europeds If (previar 60-15, "loss of Reactor Collect Pump Cooling & Matural (previation (notdown " No written response required O'RETILY J.P. Region C. Allanta, Office of the Director 80/06/20
- 8007100029 Forwards response to IC Bulletin NO Co. "Engineered Bafety Features (FST) Reset Controls "Lists equipment which does not remain in merejancy mode upon roset of EST signal Followup response will be sent by 8000004 UNRIGER! Florida Power & Light to 80706/20 App
- 800/1/0107 Forwards IE Circular 60-14. "Madicactive Contamination of Plant Demineralized Water Figs & Recultunt Internal Contamination of Personnel" for mixtee response required U.R.Filty, P. Region 2. Atlanta, Office of the Director 80/06/24
- 8007230243 forwards If Bulletin 80-16. "Potential Hisapplication of Resemburt Int Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80 16 also ently no written response required G/REHIYVA P Region 2, Atlanta, Office of the Director 80/05/27
- 8007210064 forwards two voi Prace 11 response to II Bulletin 79-018 re environ qualification of Clara 18 repriment Supersides 800662 Phase I response Mu encl UMRIG R F Plorida Fower & Light to 80/07/03 2pp

- 9007250202 Responds to IE Bulletin 80-11. "Masonry Wall Design " Rept notice interpolate to it bulletin 80-11. "Masonry Wall Des not complete but safety-related walls have been identifier re-realization program developed Rept will be submitted by 800723 UHRIG.R E Florida Power & Light Co 80/07/09 ip
- 8007300558 Advises that final response to IE Bulletin 80-10 will be submitted by 800801 UHRIG,R E Florida Power & Light Co 80/07/09 ip
- 8007310084 Advises that full response to IE Bulletin 80-08 will be submitted by 801031
 UHRIG.R E Florida Power % Light Co 80/07/09 ip
- 8007240261 Ack receipt of 800626 ltr informing NRC of steps taken to correct viulations noted in IE Insp Repts 50-250/80~16 & 50-251/80~14 LEMISR C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/11 1p
- ~-8007240263 Responds to NRC 800529 ltr re violations noted in IE Insp Repts 50~250780-16 & 80-251/80-14 Corrective actions tracked open noncompliance items & hired addl GC personnel URRIG.R E Florida Power & Light Co 80/06/26 3pp
- --8007240266 Forwards IE Insp Repts 50-250/80-16 & 50-251/80-14 on 800401-30 & notices of violation & deviation LEMIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/05/27 2p
- --8007240272 Notice of violation from imag on 800401-30 * Region 2. Atlanta, Office of the Director 80/0 80/05/29
- --8007240276 Notice of deviation from insp on 800401-30
 * Region 2. Atlanta, Office of the Director 80/05/29
- --8007240281 IE Insp Repts 50-250/80-16 & 50-251/80-14 on 800401-30 Nancewell le insp Repts 50-250/80-16 % 50-251/80-14 on 800401-30 Nancompliance noted failure to track implementation of carrottive action & to meet corrective action deadline VOOT-LOWELL.R J. Region 2. Atlanta. Office of the Director PARTIN.R D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/29 App
- R Periodic operating reports & related correspondence
- 8007240075 Forwards semiannual radioactive offluent & environ monitoring repts for Jan-June 1978 W/o environ monitoring UHRIG.R E Finrida Power & Light Co 78/08/30
- --8007240086 "Bemiannual Radioactive Effluent Repts for Jan-June 1978 * Florida Power & Light Co 78/08/30 15pp
- 8007220543 Forwards "Semiannual Radioactive Effluent Rept." & "Semiannual Monitoring Rept." for Jul-Dec 1978 per Tech Spec 6 9 4 UHRIO, R F. Florida Power & Light Co 79/03/01 ip
- -- 8007220550 "Semiannual Rept of Radioactive Effluent Releases." Jul-Dec Florida Power & Light Co 79/03/01 25pp
- 8007240174 Forwards monthly operating repts for June 1980 SCHMIDT.A D Florida Power & Light Co 80/07/05 1p
- --8007240177 Nonthly operating repts for June 1980 CHIL90N,V T Florida Power & Light Co 80/07/05 10pp
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1
- F Becurity, medical, emergenry & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 100FR2 790)
 PEOPLES,D L Commonwealth Edison Co 80/06/27 1p
- O Adjudicatory correspondence
- 8007310247 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp

- J Insurance & indemnity information
- 8007130616 Forwards Endorsement 63 to NELIA Policy NF-187 OSTER, J. Commonwealth Edison Co. 80/07/09 App
- 8007290709 Forwards Endorsements 62 & 64 to NELIA Policy NF-187 OBTER: J Commonwealth Edison Co 80/07/23 3pp
- P Operating license stage documents & correspondence
- B00723002B Summary of B00207 meeting w/Mark I owners group in Dethesda. MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program ORIMES.C T Plant Systems Branch 80/02/21 3ipp
- 8007290217 "Measurement of Xe~1.33.C-14 & Tritium in Air & [-13i in Vegetation & Milk Around Guad Cities Nuclear Power Stations."

 KELLER, J H , AKERS, D W , DUCE, S W | Idaho National Engineering Laboratory | FIN A~6078 | NUREO/CR-1195 | 80/03/3i | 400pp
- BOG7010190 Responds to SSRT concerns recontrol rod drive sys lacking seismic analysis Quad Cities 1 & 2 seismic design of control rod drive sys calculations performed for facility while under const encl
 JANECEK.R F Commonwealth Edison Co 80/06/24 4pp
- --8007010193 "Guad Cities 1 & 2 Spismic Data on Control Rod Drive Bys "
 * Reactor Controls: Inc 70/07/10 200pp
- B007070114 Submits revised responses to NRC 770603 ltrs resected level of undervoltage protection for 4 kV emergency power bases supplying safety-related loads

 JANECEK-R F Commonwealth Edison Co 80/06/26 4pp
- B007140500 Forwards Amend 56 to License DPR-29, safety evaluation & notice of issuance & availability IPPULITO.T A Operating Reactors Branch 2 80/06/26 2pp
- --8007140505 Amend 56 to License DPR-27 authorizing operation of reactor beyond previously approved end-of-cycle coastdown conditions
 IPPOLITO.T A Operating Reactors Branch 2 80/06/26 2pp
- --B007140909 Safety evaluation supporting Amend 56 to License DPR-29
 * Operating Reactors Branch 2 80/06/26 3pp
- ~~8007140514 Notice of issuance & availability of Amend 56 to License DPR-27 IPPOLITO.T A Operating Reactors Branch 2 80/06/26 2pp
- G0070B0063 Responds to NRC G00515 request for addl info concerning adequacy of station electric distribution sys voltages JANECCK, R F Commonwealth Edison Co 80/06/30 4pp
- 8007070345 Forwards revised schedule & status lnfo for Mark 1 program, feedwater sparger roplacement & general work planned for Guad Cities I outage Proceeding on priority basis w/mods providing largest safety increase margins.

 RCED.C Commonwealth Edison Co 80/07/02 18pp
- B007100142 Application for amend to App A. Tech Specs of Licenses DPR~29 & DPR~30.implementing fire protection mods JANECEK.R F Commonwealth Edison Co 80/07/03 2pp
- --8007100147 Proposed changes to Tech Specs 3 12/4 12-1 through 3 12/4 12-9, implementing fire protection mods
 * Commanwealth Edison Co 80/07/03 18pp
- BOO7210212 Responds to NRC request for addl info re turbine disks Applicable turbine missile analysis was presented in Amend 2 to Quad Cities CP application Analysis applies to Drosden due to similarity of general arrangement JANECEK.R F Commonwealth Edison Co 80/07/15 ip
- O Inspection reports, IE Bulletins & correspondence
- 8007140345 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/35/12 ip
- 8007020065 Forwards IE Info Notice 80-22, "Breatdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28 ip

- B007010086 Forwards IE Info Notice 80-23 "lass of Suction to Emergency Feedwater Pumps No written response required KEPPLER J G Region 3, (hicago, Office of the Director 80/05/F9 lp
- B007020756 forwards reviewd (Espaines to 1E Bulletin /9-018, "Environ Qualification of Class 1E Equipment" Identifies areas where effort is continuing in identification of equipment qualifications W/O entl

 JANECEK.R F Commonwealth Edison (6 80/06/02 1p
- 8007220156 Forwards It Info Natice 80-26. 'Evaluation of Contractor GA Programs ' No written risponse required KEPPLFR.J G. Region J. Chicago. Office of the Director 80/06/10 Ip
- B007140309 Forwards IE Bulletin B0-14. 'Degladation of BWR Scrom Discharge Vol Capability " Written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director B0/06/12 Ip
- 8007100004 Forwards response to IC Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators

 PEDPLES D L. Commonwealth Edison (p. 80/06/16. 3pp
- B007030037 Forwards IF Dulictin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsile Power " Written response required KEPPLER. J G Region), Chicago, Office of the Director B0/06/18
- 8007020389 Forwards IE (ircular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Cisculation Conidown" No written response required KEPPLFH, J O Region 3, Chirago, Office of the Director 80/04/20
- B007110131 Forwards notice of yielation % notice of proposed imposition of civil penalties arising from IE 800171 insp SYELLO.V Office of Inspection & Enforcement, Office of the Director 80706/20 Spp
- --8007110136 Notice of yiolation from insp on 800131 Noncompliance noted surface radiation of transporting vehicle exceeded ment allowable millinem per hour perfect of Inspertion & Cufortement. Office of the Director 80/01/31 isp
- ---8007ii0145 Notice of imposition of rivil penalties based on item of noncompliance recressive surface radiation on transport vehicle

 N Office of Inspection & Enforcement, Office of the Director NO/O6/20 Ip
- 8007i40147 Notice of proposed imposition of civil penalties in amount of \$4,000 for item of noncompliance to radiation levels on waste shipments exceeding regulatory limits * Office of Inspection & Enforcement, Office of the Director 80/06/20 ip
- 8007170430 Forwards IE Circular 80-14. "Radioartive Contamination of Plant Demineralized Mater Sys ? Recoltant Internal Contamination of Personnel ? No written leganse required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/24
- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters, W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region), Chicago, Diffice of the Director 80/06/27
- 8007300574 Forwards Weste Packaging Insp Rept 15000046/80-07 on 800131 Notice of violation forwarded under separate cover KEPPLER, J & Region 3, Chicago, Office of the Directur 80/06/27
- --8007300585 Haste Puckaging limp Rept 1500046/R0-07 on 800131
 Noncompliance noted radiation levels on torface of trailer
 in excess of regulatory limits
 BOOK.H E Region 5. San Francisco, Fuel Facility 4 Materials
 Safety Branch (AIN.C.L. Region 4, Dallas, Office of the
 Director 80/02/27 7pp

OCTIONON Notafies that time clock of Item 2 of IE Bulletin 80-17, "failure of Control Rods to Insert During Scram at BMR." will start at IP Of AM on BOOTOE Test should be completed within 20 days Requests notification of malfunction KEPPLER.J G Region 3, Chicago, Office of the Director 90/07/07

107230441 Responds to IE Bulletin B0-10, "Contamination of Nonradinactive Sys & Resulting Potential for Unmonitored, Uncontralled Roleans of Radioactivity to Environ" Any affected sys will be restricted if contamination found PLOPLES, D L Commonwealth Edison Co B0/07/07 2pp

007250650 Forwards response to IE Bulletin 80-li, "Masonry Hall Design " Requested investigation not performed at Dresden, Unit I due to extended outage Requirements will be met prior to startup W/o enci PFGPLES,D L. Commonowealth Edison Co. 80/07/07 2pp

00/230A3B Forwards response to iE Bulletin 80-08. "Examination of Cantainment Liner Penetration Welds " Dresden Unit i designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PLUPLES:D L. Commonwealth Edison Co. 80/07/09. 7pp

OD/160630 Responds to IE Bulletin 80-17 re results of tests required by Item I No significant amount of water in screm discharge vols Vent & drain lines also verified free of obstructions by performing dynamic air test JANICCEK.R F Commonwealth Edison Co 80/07/10 2pp

007280074 Forwards add1 response to 1E Bulietin 80-17. Items 2,3.4,5.ba & 6b New procedure has been written to cover actions necessary when control reds fail to fully insert during

PEOPLES, D L Commonwealth Edison Co 80/07/11 Spp

00/310397 Responds to NRC 800620 notice of proposed imposition of civil penalties by forwarding payment PEOPLES.D L. Commonwealth Eduson Co. 80/07/14 ip

00/310373 Forwards response to violation noted in IE insp on 800131 Corrective actions procedure now requires under-trailer check of radwaste shipments & pre survey of articles at shipment origin to assure packages are within dose limits JANECEK.R F Commonwealth Edison Co. 80/07/15 3pp

007300485 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Sefety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria" JANECEK.R F Commonwealth Edison Co 80/07/16 ip

8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations." Revision 2 ENYDER.T K ED9 Nuclear, Inc. 80/03/07 lipp

8007300508 "Engineering (riteria Procedure for Application of Blume Curves Critoria " SNYDER.T K EDB Nuclear, Inc. 80/03/07 20pp

007290869 Forwards IE Insp Rept 50-254/80-16 on 800709-11 & notice of violation HIND, J A Region 3, Chicago, Safeguards Branch 80/07/21 2pp

-800/270871 Notice of violation from insp on 800709-il * Region 3. (hitago, Office of the Director 80/0//21 lp

-800/290H75 [E] Insp Rept 50-254/80-16 on BUR709-11 Noncompliance noted failure to update fuel assembly locations on fuel location & expansure records loss of fission due to insufficient SNM procedures Details withheld (ref 10CFR2 790)
FIREY. A G , PATTERSON J P Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Safeguards Branch 80/0//21 10

Periodic operating reports & related correspondence

190619 Forwards monthly operating repts for June 1980 IVIANARIS, N Commonwealth Edison Co 80/07/01 1p

07190625 Monthly operating repts for June 1980 MATERA, T Commonwealth Edison Co 80/07/01 4p;

sportable occurrences, LERs & related correspondence

940105 Forwards LER 80-016/03[-0 IVIANAKIG: N Commonwealth Edison Co 80/07/16 1p --8007240109 LER 80-016/03L-D on 800621, during startup & shutdown, valve J-203-2C failed to close while testing Caused by improper adjustment of exhaust restrictor on pilot valve Pilot valve dismantled & adjusted + Commonwealth Edison Co 80/07/21 2pp

V Operator Examinations

8007020319 Responds to 800512 ltr requesting extension until Fail 1980 for completion of annual requalification exam due to addition work load Exam date may be delayed until 800930 CDLLINS.P F Operator Licensing Bronch 80706/18 1p

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

80070i0473 Discusses proposed change to 10CFR50 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Questions appropriateness of rule, since rule reopens resolved issues HOFFMAN, D.P. Consumers Power Co. 80/06/27 Gpp

8007140391 Forwards Revision 2 to 790220 security plan Plan withheld {ref iOCFR2 790} HOFFMAN, D P Consumers Power Co 80/07/08 1p

B007220341 Forwards add1 info re sustability, training & qualification pians, in response to NRC 800515 & 0606 requests Info withheld (ref 10CFR2 790)
HOFFMAN D P Consumers Power Co B0/07/17 lp

8007240402 Provides info re access of NRC & NRC contractor personnel to facilities for conducting appraisal of health physics program List of personnel requiring picture badges which specify "no escart required" encl
KEPPLER, J & Region 3, Chicago, Office of the Director 80/07/18

8007280570 Responds to 7911P9 request for info re evacuation time estimates in site emergency plan Evacuation clear time for O- to 10-mile area around Failsades estimated at approx 2 hrs in summer & winter HDFFMAN.D P Consumers Power Ca 80/07/23 1p

8007300439 Forwards revised safeguards contingency plans Plans withheld (ref 10CFR2 790) HOFFMAN,D P Consumers Power Co 80/07/24 19

G Adjudicatory correspondence

8007090316 Forwards Document E, "Equipment Outage Request.Maint Order 78-VA9-064," as followup to util 800623 response to NRC interrogatories & document requests Related correspondence MURPHY.P H Isham, Lincoln & Beale 80/06/25 2pp

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/04/25 89pp

B007070126 Rept on discovery status re civil penalty proceeding NRC will respond to util supplemental motion to compel discovery on 800703 Need for further discovery requests under consideration

BURNS, 8 0 Rulemaking & Enforcement Division 80/07/01 ip

8007210446 Forwards util 800702 ltr & Revision 1 to "Environ: Assessment - Paiisados Plant - Steam Generator Replacement " GIBUS:M E Isham, Lincoln & Geale 80/07/14 ip

8007230810 Response in apposition to NRC 800703 motion for protective order re CPC 800221 interrogatories & requests for production of documents Relief not warranted per ALAB-594 H/Certificate of 8vc MILLER, M I , MURRHY, P M , BIELAHSKI, A P Consumers Power Co 80/07/18 19pp

8007250578 Memorandum & order ruling on licenses 800514 & 0613 motions to compel NRC answers to 800221 requests Deliberative data leading to hearing privileged & exempt from production per traditional privilege tests Discusses & rules on other data SMITH, I W Atomic Safety and Licensing Board Panel 80/07/22

- 8007310319 Motion for proposed corrections to administrative law judge 800722 memorandum & order re licensee motion to compel discovery Interrogatory 13 was answered by NRC on 800331 & should be omitted from order Certificate of Svc encl BURNS:S G Rulemaking & Enforcement Division 80/07/29 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B007110299 Forwards Revision 8 to FSAR
 FDGC.W Consumers Power Co 80/07/07 200
- --8007i10301 Revision 8 to FSAR.consisting of replacement Page 9-2 re critical sys supplied by svc water sys # Consumers Power Co 80/07/07 ip
- P Operating license stage documents & correspondence
- BOO7010289 Forwards evaluation of opened bypass lines in containment based on licensee accident assumptions Licensees DBA represents realistic accident consequences BLAND.J B Environmental Engineering Branch 79/11/07 App
- 8007100295 Forwards Amend 57 to License DPR-20, safety evaluation & notice of issuance & availability CRUTCHFIELD.D Operating Reactors Branch S 80/06/06 2pp
- --B007100299 Amend 57 to License DPR-20, changing Tech Specs to include addl radial peaking factor limit CRUTCHFIELD, D Operating Reactors Branch 9 B0/06/06 13pp
- --8007100307 Safety evaluation supporting Amend 57 to Licenso DPR-20 * Office of Nuclear Reactor Regulation, Director 80/06/06 3pp
- --8007100310 Notice of issuance & availability of Amend 57 to License DPR-20 LAINAB.C C Assistant Director for Safety Assessment 80/06/06
- B007110247 Forwards Amend 58 to License DPR-20, safety evaluation & notice of issuance & availabilty
 CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/06 2pp
- --8007110254 Amend 58 to License DPR-20.modifying total radial peaking for Type H fuel during Cycle 4 CRUTCHFIELD.D M Operating Reartors Branch 5 80/06/06 5pp
- --8007110264 Notice of issuance & availability of Amend 58 to License DPR-20
 LATNAS.0 C Assistant Director for Safety Assessment 80/06/06
- 8006260145 Gafety evaluation tupporting Amend 58 to License DPR-20 Changes involve H-design reload in Cycle 4 only * Office of Nuclear Reactor Regulation. Director 80/06/06 5pp
- 8007010111 Forwards final rule published in 800507 FR amending 10CFR50 7i to require periodic updating of FSARs Compliance is not required until completion of EEP CRUTCHFIELD. D Operating Reactors Branch 5 80/06/10 6pp
- 8007110126 Notification of 800610 meeting w/otil in Bethesda.MD to discuss shift technical advisor WAMBACK.T V Operating Reactors Branch 5 80/06/10 2pp
- E007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution and for guidance EISENHUT, D G Division of Licensing 60/06/11 A2pp
- 8007100399 Responds to 800229 ltr which expressed opposition to ACRS recommendation to restructure BEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/18 4pp
- ~-8007100420 Expresses apposition to ACR9 recommendation to restructure SEP For SEP owners to perform sefety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALLR SEP Owners Group 80/02/29 2pp
- BOO7180289 Requests comments on causes for & possible remedies for events re site identified in encl rept. "Loss of Offsite Power Survey Status Rept." within 120 days of receipt of ltr CRUTCHF(ELD.D M Operating Reactors Branch 5 80/06/19 2pp

- B007250666 Requests add1 info re adequacy of station thectric distribution sys voltages Requests response within 45 days of itr recept CRUTCHFIFLD.D M Operating Reartors Branch 5 80/06/19 4pp
- B0072B0il4 Forwards NRC "Draft Interim Technical Evaluation Rept on Equipment Environ Qualification " Ript will be used as input for safety assessment for Topic Ill-12 Request comments by 800-500 W/o encl
 MAMDACH.T V Operating Reactors Branch 5 80/06/19 2pp
- 8007010722 Summary of 800606 meeting w/util & Eixon Noclear Co in Bethesda, MD re-outstanding issues from wtil request to change facility Tech Speck to increase total radial peaking factor for Cycle A relaad w/H-design feel LQIS, L. Core Performance branch 80/06/20 3pp
- B007020557 Forwards "RCS Asymmetric Luads Evaluation Program," final rept in response to NRC 780125 ltr to PHR licensees re asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withhold (ref 10CFR2 790) LUNDVALLA E C-E Operating Plants Owners Group 80/06/30 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program." final rept. Vol 1 * C-E Power Systems 80/06/30 20pp
- --B007020581 "RCS Asymmetric Loads Eviluation Program," final rept. Vol 2 « C-E Power Systems B0/06/30 300pp
- --B007020588 "RCS Asymmetric Loads Evaluation Program." final rept. Vol
- 3 * C-E Power Systems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program," final rept.App A, numerical results, evaluation of C-E fuel Nonpioprietary version App A.Palisades foel analysis, encl w C-E Power Bystems 80706/30 26pp
- --8007020599 "RCS Asymmetric Loads Evaluation Program," App C, pipe whip restraints & App D, plan for fracture analysis of util cold leg piping Final rept # C-E Power Systems 80/06/30 16pp
- --8007020600 "RC5 Asymmetric Loads Evaluation Program," App E.ECCS analysis approach w/reduced area coolant channels in peripheral astemblies Final rapt * C-E Power Bystems 80/06/70 9pp
- 8007030270 Forwards "Rept on Endurance Testing of Auviliary Feedwater Pumps" HDFFMAN D P Consumers Power Co 80/07/01 ip
- --8007030251 "Rept on Endurance Testing of Auxiliary Feedwater Pumps "
 # Consumers Power Co BD/G7/01 1/4pp
- 8007080338 Notifies that fuel evaluation 's cavity wall analysis requested by NRC 791120 ltr.still in progress Progress of fuel evaluation provided in 800701 App B. Final ropt Rept will be completed by 800829 HOFFMAN.D P Consumers Power Co 80/07/01 lp
- 8007250693 Forwards request for add) info re SFP design basis events Requests response within 45 days of ltr receipt CRUTCHCIELD.D Operating Reactors Branch 5 80/07/01 4pp
- G007090008 Forwards Revision 1 to "Environ Assessment Steam Generator Replacement " HUBTON R W Consumers Power to 80/07/02 3pp
- ---B007090010 Replacement Pages 5-5.6-1.6-19.8-1 % 8-2. submitted as Revision 1 to "Environ Assessment Steam Generator Replacement"
 * Consumpts Power Co 80/05/31 7pp
- B007250001 Requests submittal of application for amend to license consisting of Trih Spec changes & license conditions PWR Model Tech Bpecs & Model license conditions for MM-2 Lessons Learned Category A stems entl for guidance EISFNHUT,D G Division of Licensing 80/07/02 69pp
- 8007100197 Forwards application for amend to License DPR-20 consisting of changes to fock Specs FROST.S R Consumers Power (o. 80/07/03 2pp

- --8007100201 Application for amend of ticense OPR-20 consisting of changes to Tech Specs DEWLIFF R B Consumers Power Co 80/07/03 2pp
- --8007100204 Changes to Tech Spics 3 9 for effluent release & 4 11 for environ monitoring program a Consumers Power Co. U0/07/03 14%pp
- 8007110358 Responds to NRC 800419 request for communis on "Draft Interim Technical Evolvation Rept on Equipment Environ Qualification for Palissides Station Equipment capable of required function Resolution of issue can proceed HOFFMAN.D P—Consumers Power Fo—80407/07—2pp
- 800/28016| Potwards "Loss of Offsite Power Survey Status Rept," to replace rept forwarded u.o Table 4 CRUYCHFIELD.D M. Operating Reactors Branch 5 80/07/08 2pp
- 8007160705 Responds to NRC RO0211 request for add1 info re SEP Topic VI-4, containment collated sys Specific info & list of drawings encl W/o drawings HOFFMAN.D P Consumers Power (o B0/07/14 lipp
- 8007280076 Responds to 800318 ltr to J Ahvarne objecting on behalf of owners of plants under SEP review to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order Devices of Nuclear Reactor Regulation, Director BO/07/16 4pp
- 800723047.3 Submits verification test results in response to NRC 770808 ltr re adequacy of ansite distribution of power from offsite circuits Results of analytical model asmulating worst rase conditions correlated well w/previous results FROST-S R Consumers Power Co 80/07/18 App
- 8 Inspection reports: IE Bulletins & correspondence
- 8007010178 Forwards 1E Insp Rept 50-255/80-06 on 800401-0502 No noncompliance noted
 HEISHIAM, R.F. Region 3, Chirago, Reactor Operations Nuclear Support
 Branch 80/05/22 2pp
- --8007010393 IE lnsp Rept 50-255/80-04 on G00401-0502 No nancompliance noted Major areas inspected activities during long-term shutdoun, cleanliness, preparations for startup & action on provious insp findings BOYD, C. DAKER, K.R., JORGENSEN, B.L. Region 3, Chicago, Office of the Director BOYOS/21 Gpp
- 8007020051 Forwards 1E Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required KEPPLER.J G. Region 3. Chicago, Office of the Director 80/05/28
- 8007210358 Forwards IE Circular NO-13, "Grid Strap Damage in Mastinghouse Fuel Assumblier" No written response required KEPPLER. J. G. Region 3: Chicago, Office of the Director 8 60/05/28
- 8007010115 Forwards IE Info Notice 80-23. Luss of Suction to Emergency Feedwater Pumps "No written response required KEPPLER.J G. Region & Chicago, Uffice of the Director 80/05/29
- 800722018B Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs' No unitten response required #EPPLER.J G Region 3. (histage, Office of the Director 80/06/10
- 8007160173 Forwards JE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study" No specific action or response required KEPPLER, J O Region 3. Chirago, Office of the Director 80/06/11
- 8007030004 Farwards IC Bulletin HO-15, "Possible Loss of Emergancy Notification Sys (CMS) W/Loss of Officite Power" Written response required KEPPLFR, J. G. Reginn G. Chicago, Offico of the Director 80/06/18
- 8007020992 Forwards IE Circular (10-15, "loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown 'No written response required REPPLER. J G Region 3. Chicago, Office of the Director 90/06/20

- 8007170474 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Recultant Internal Contamination of Personnel 'No written response required KEPPLFR.J G Region 3. Chicago. Office of the Director 80/06/24
- 8007230J12 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosempunt Inc Models 1151 to 1152 Prossure Transmitters W/Either A or D Gutput Codes" Written response required IE Circular 80-14 also encl No written response required KEPPLER.J G Region 3, Chicago, Diffice of the Director 80/06/2
- B007310177 Responds to 1E Bulletin B0-12 re decay heat removal sys Consultant levicu unacceptable Review & response will be submitted by B00730 HUFFMAN,D P Consumers Power Co 80/07/01 ip
- 8007140350 Responds to IE Bulletin BO-10. "Contamination of Nonradioactive Sys & Rosulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Domineralized water sys isolated from storage tank at al HOFFMAN.U P Consumers Power Co HO/07/08 3pp
- 6007140310 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Wolds" Fenetrations w/fluod head design & designs w/containment boundary butt welds between penetration slueve & process piping total 95 HOFFMAN.D P Consumers Power Co 80/07/09 App
- B007150803 Forwards "Sirty-Day Response to NRC IE Bulletin 80-ii " HDFFMAN D.P. Consumors Fower Co. 80/07/09 ip
- --8007150806 "Sixty-Day Response to NRC IE Bulletin 80-11 "
 # Rechtul Corp 80/06/30 92pp
- B00/220513 Informs of compliance w/order modifying license Insp completed June 1980 Results of insp showed that plant was in compliance w/limiting condition of operation requirements of HOFFMAN, D.P. Consumers Power (a. 80/07/16
- B007230460 Notifies NRC of compliance w/791109 order requiring licensee to inspacconsible valves & other controls for engineered safety sys on monthly basis lasp completed in June 1980 Plant is in compliance w/limiting conditions for operation NDFFMAN.D P Consumers Power Co 80/07/16 ip
- 8007230395 Forwards required affirmation inadvertently omitted from 800709 response to 16 Bulletin 80-11. "Masonry Wall Design " HOFFMAN.D P Consumers Power Co 80/07/18 2pp
- 8007290630 Responds to items of noncompliance noted in IE Insp Rept 50-255780 OB Corrective actions administrative control procedures have been implemented to assure min instrument operability requirements are maintained HOFFMAN.D P Consumers Power to 80/07/23 3pp
- A Periodic operating reports & related correspondence
- 8007210427 Forwards "Palisades Nuclear Power Plant Radioactive Effluent Release Semiannual ReptiJan-June 1978 " HDFFMAN.D P Consumers Power Co 79/08/29 lp
- ---8007210440 "Palisades Nuclear Power Plant Radioactive Effluent Release Semiannual Rept.Jan-June 1978 " * Consumers Power Co 79/08/29 9pp
- 8007110409 Forwards monthly operating rept for June 1980 MEINCKE, J.A. Consumors Power Co. 80/07/03 1p
- --8007110414 Nonthly operating rept for June 1980 BODTKE,P J Consumors Power Co 80/07/02
- 8007210394 Submits status rept for June-Jul 1980 Bechtel is preparing final design for long-term cooling mods scheduled for 1981 refueling outage
 HOFFMAN D P Consumers Power Co 80/07/15 ip
- S Reportable occurrences. LERs & related correspondence
- 8007080169 Forwards tER 80-019/01T-0 80/07/01 In HOFFMAN. D. P. Consumers Power Co.

- --8007080199 LER 80-019/017-0 on 800609, during fech Spec review. Toch Spec 3 3 datermined to provide too little borated water for safety injection caused by imprecise wording of Tech Spec Low level alarm setpoint changed. Tech Spec under evaluation 4 Consumors Power Co 80/07/01 lp
- 8007090314 Forwards updated LFR 80-017/03X-1 HUSTON, R W Consumers Power Co 80/07/03 1
- --B007090319 Updated LER 80-017/03X-1 on 800blo.PS tosting procedures review revealed setpoint of PS-J801 through 1804 to be lower than permitted by Tech Spocs Caused by faulty procedure Procedures revised to tonform w/Tech Specs # Consumers Power Co 80/07/03 1p
- B00722047B Forwards NPDES noncompliance notification re exceeding of daily max limit for nil & grease on 800630
 HOFFMAN,D P Consumers Power Co 80/07/16 ip
- --B0072204B4 NPDES noncompliance notification on B00630, daily max limit for oil & grease of less than 20 mg/l was exceeded Weekly grab sample indicated 26 2 mg/l oil Caused by failure of F20/M13 filter elements Filters replaced FOBES, R L. Consumers Power Co B0/07/14 lp
- 8007270614 Forwards NPDEB noncompliance notification HOFFMAN, D P Consumers Power Co 80/07/23 ip
- --B007290616 NPDES noncompliance notification on B00703-07. bil & grease accumulation exceeded daily max & monthly average limitations Caused by burst welded seam on generator seal oil strainer Seam rewelded FDBES.R L Consumers Power Co B0/07/16 3pp
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & Fire protection plans
- 8007210024 Forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printbut containing supporting data for vital area analysis Encls withheld (ref 10CFR2 790)

 IPPOLITO, T A Operating Reactors Branch 2 80/06/30 2pp
- 8007220028 Confirms that LASL will conduct vital area analysis of Units 2 & 3 on 800714 E Claibourne & J Rand will conduct visit IPPOLITO.T A Operating Reactors Branch 2 80/07/03 2pp
- 8007300061 Requests confirmation of agreement to participate in program to examine north wall of reactor bldg & review records retests on fire protection sysper Commission Order CLI-80-21 Also requests that listed info be available for NRC visit EISENNUT, D O Division of Liconsing 80/07/16 3pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780802 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007170380 Expresses concern re plans to construct low level waste storage & incineration facility Proposed facility would present significant health risks to highly populated area Requests public hearing & CIB HOLLINGSHORTH Affiliation Unknown 80/07/09 ip
- J Insurance & indomnity information
- 8007010516 Forwards Endorsement 51 to ANI Policy NF-198 FIELDER, J. Marsh & McLennan, Inc., M & M Nurlear Consultants, Inc Div 80/06/23 2pp
- BO07310434 Forwards Endorsement 43 to MARLU Policy NF-64 FIELDER, J. Marsh & McLennan, Inc., M & N Nuclear Consultants, Inc Div B0/07/21 2pp
- P. Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Bethosda. MD. re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES, C T Plant Systems Branch 80/02/21 31pp

- 8007070268 Responds to 800123 ltr re use of NOVN code in determining operating limit min critical power ratio Util requests further clarification of expected penalties that may be imposed on top of ODYN calculations
 MILLS.L M Tennessee Valley Authority NO/05/28 2pp
- 8007020711 Responds to 800422 Its selow level waste mgt at plant Ultimate util objective is to provide for ansite radwaste storage No target date has been established by TVA for submitting application for inclineration approval NOVAK.T M Assistant Director for Operating Reactors 80/06/25
- 8007080286 Responds to NRC 800521 request for facility participation in phase two Interim Reliability Evaluation Program Urges definitive conclusion of phase are before continuing Outline of critical areas to be resolved encl
 MILLS:L M Tennessee Valley Authority 80/06/30 3pp
- B007170319 Summary of 800612 meeting w/etils in Bethesda.MD re interior reliability evaluation program
 OLSHAN,L N Operating Reactors Branch 1 80/06/30 3pp
- B0070B0300 Responds to NRC 791002 ltr to all BWR licensees & 791031 ltr to util Util funds allocated for Mark I owners group full-scale test facility program Schedule for completion of plant-unique analysis forthcoming MILLS.L M Tennessee Valley Authority 80/07/03 lp
- 8007210026 Forwards request for addl info to complete review of containment purging & venting at facilities NOVAK.T M Assistant Director for Operating Reactors 80/07/08 500
- 8007220376 Forwards proposed changes to EYS Section 2 1 re thermal discharge limits
 HILLS.L M Tennessee Valley Authority 80/07/11 1p
- --B007220377 Proposed thange to ET9, Section 2 1 re thermal discharge limits * Tennessee Valley Authority 80/07/14 1p
- 8007240225 Forwards Amends 61.56 & 33 to Licenses DPR-33.DPR-52 & DPR-68.respectively & notice of insuance & availability IPPOLITO.T A Operating Reactors Branch 2 80/07/15 3pp
- --B007240231 Amends 61.56 % 33 to Licenses DPR-33.DPR-52 % DPR-68, respectively, changing Tech Specs re thermal discharge limits
 IPPOLITO, T A Gperating Reactors Branch 2 80/07/15 13pp
- --BOO7240234 Notice of issuance % availability of Amends 61.56 & 33 to Licenses DPR-33,DPR-52 & DPR-68,respectively IPPOLITO,T A Operating Reactors Branch 2 89/07/15 2pp
- 8007220561 Advises of error in responses for Site Specific Question I. Parts B & C. submitted in 800616 ltm.in response to questions re low turbine disc cracking Correct responses encl PARKER. H D Duke Power Cn 80/07/1/ 2pp
- 8007300284 Responds to entl 800602 memo re low level waste mgt at facility Util plans to construct two separate low level waste facilities onsite Const on first four cubicles began recently NRC approval of plans necessary DENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/23 Spp
- --BQ07300291 Requests summary of util plans to build low level waste storage facility Alsa requests whether NRC approval is required & whether public hearings have been requested BRADFURD.P A Commission 80/04/02 lp
- Q Inspection reports. 1E Bulletins & correspondence
- B007240087 Forwards IE Info Notice B0-20. "Loss of Decay Heat Removal Capability at Davis-Resse Unit 1 While in Refueling Made"
 No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
 3pp
- 8007140476 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required O'RETLLY.J P Region 2, Atlanta. Office of the Director 80/05/12 tp
- 8007020192 Followeds IE Into Notice 80 22, "Breakdowns to Contraction Control Pingroms" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Diliping Control Pingrom 2, Atlanta Control Pingrom 2,

- 0223 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency water Pumps " No written reaponse required ILLY, J P Region 2. Atlanta, Office of the Director 80/05/27
- .0029 Forwards IE Info Notice 80-26, "Evaluation of Contractor rograms " No written response required ILLY, J P. Region 2. Atlanta, Office of the Director 80/06/10
- 0306 Forwards IE Bulletin B0-14. "Degradation of BWR Scram Marge Vol Capability " Written response required ILLY.J P Region 2. Atlanta, Office of the Director 80/06/12
- 0499 Forwards response to IE Bulletin 80-07 transmitted by 'Reilly 800417 ltr Final rept for Hartsville & Phipps plants will be sent on or before 801017
 S.L M Tennessee Valley Authority 80/06/16 2pp
- 0267 Forwards notices of violation & proposed imposition of civil lty re IE insp on 800428 & 050i of transport volicle for carrying radwaste LO.V J Uffice of Inspection & Enforcement. Office of the rtor 80/06/18 2pp

- 020275 Notice of proposed imposition of civil penalty in amount of 0000 re insp on 800420 & 0501 Office of Inspection & Enforcement, Office of the Director /06/10 ip
- 1761 Forwards IE Bulletin BO-15, "Possible Loss of Emergency Fication Bys (CND) W/Loss of Offsite Power " Written hose required ILLY,J P Region 2, Atlanta, Office of the Director GO/06/18
- 1153 Discusses 800425 & 20 radiation survey which revealed ation lovels on vehicle surface exceeding regulatory ts forwards notice of vallation & notice of proposed sition of civil penalty

 -0.V Office of Inspection & Enforcement. Office of the ctor 80/06/18 2pp
- 140155 Notice of violation from insp on 800428 & 0901 Noncompliance ed radiation levels on packages of licensed moti seeded regulatory limit.
 Office of Inspection & Enforcement, Office of the Director
 - 10
- 40161 Notice of proposed imposition of civil penalties in amount \$5,000 for items of noncompliance re radiation levels on react of packages exceeding regulatory limits of fine of Inspection & Enforcement, Office of the Director 704/18 12
- 0391 Forwards IF Circular 80-19. "Loss of Reactor Coolant Pump ng & Natural Circulation Cooldown " No written response ired
- LLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 1395 Forwards Waste Parkaging Insp Rept 150000.19/80-21 pm 800428 LLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 290401 Wastu Packaging Insp Rept 15000039/80-21 on 800428 & 0501 scompliance noted radiation levels on surface of closed. clusive use vehicle in excess of regulatory limits MP-0 L. PEERY. W Region 2 Atlanto, Fuel Facility & erials Eafety Branch 80/06/20 App
- 9344 Forwards 1E Insp Repts 50-259/80-29.30 260/80-19, 6/80-20 & 50-327/80-22 LLY, J.P. Region 2, Atlanta, Office of the Director 80/06/23
- 10351 IE Inap Repts 50-259/80-25.50-260/80-19.50 296/80-20 t-327/80-22 on 800521 Inap consisted of allforcament meeting Atlanta. On to discuss exceeding DOT radication limits ing shipment of radwarts from Drowns Ferry ICE.H C Region 2, Atlanta, Reactor Operations Nuclear Support nch 80/06/20 2pp

- 8007170070 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required D'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/24
- 8007180523 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Fower Sys Bus During Operation," & to 800404 confirmatory orders Feedwater pump turbine & main turbine trip circuitry will be upgraded MILLS,L. M. Tennessee Valley Authority 80/06/26 Spp
- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/6
- 800721009) Forwards response to IE Bulletin 80-10 Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradicactive & radioactive sys Routine sampling & analysis program established MILLS,L M Tennessee Valley Authority 80/07/07 3pp
- 8007230726 Forwards monthly status rept re IE Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys." presenting status of work as of B00701 MILLS.t. H Tennessee Valley Authority 80/07/07 29pp
- G007280615 Responds to IE Bulletin 80-08, "Examination of Containment Penotration Welds " Results of investigation encl MILLS.L M Tennessee Valley Authority 80/07/07 5pp
- 8007210103 Forwards response to IE Bulletin 90-11 Identifies masonry walls that support or are mear safety-related sys Bubmits schedule for re-evaluation program
 CROSS.J L Tennessee Valley Authoraty 80/07/08 3pp
- 8007280460 Ack receipt of B00616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-29780-20, 50-260/80-15 & 50-296/80-16 LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/07/09 259
- --0007280468 Responds to NRC 800520 ltr re violations noted in Insp Repts 50-259/80-20, 50-260/80-15 & 50-296/80-16 Corrective actions calibr valve prientation corrected Justifies decision re nonreporting of deisel genrator failure MILLS.L M Tennessee Valley Authority 80/06/16 App
- --B0072H0475 Forwards IE Insp Repts 50-259/80-20,50-260/80-15 & 50-294/80-16 on 800405-0502 & notice of violation LEMIS.R C Region 2, Atlants, Reactor Operations Nuclear Support Branch 80/05/20 2pp
- --B007280478 Notice of violation from Insp on B00405-0502
 * Region 2, Atlanta, Office of the Director 80/05/20
- --B007280484 IE Insp Rupts 50-259/80-20,50-260/80-15 & 50-296/80-16 on B00405-0502 Noncompliance noted failure to adhere to survaillance instructions & to make prompt rept to NRC SULLIVAN,R F. CHASC, J H. Rogion 2. Atlanta. Office of the Director DANCF,H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 7pp
- 8007250576 Forwards response to Item 1 of IF Bulletin 80-17 re water in scram discharge vol No significant amount of water was found in discharge vol & associated piping Scram discharge vent valves are operable CROSS.J L. Yennessee Valley Authority 80/07/11 2pp
- 8007310067 Forwards second interim rept in response to 1E Bulletin BO-06 Since B00612 interim rept.util completed review of primary containment systreactor protection sys. RHR sys & core spray sys Evaluation of other sys underway CR089.J L Tennessee Valley Authority 80/07/11 2pp
- 8007310339 Forwards response to NRC 800616 notice of violation & notice of proposed imposition of civil penalties to IE 800428 & 0501 insy Corrective actions radwaste shipping procedure revisor Civil penalty fee forwardod separately MILLS.L M Tennessee Valley Authority 80/07/11 4pp
- 8007220522 Requests extension until 800811 for performing manual & automatic stram required by IE Bulletin 80-17 Extension needed because of rurrent heat wave HILLS.L M Tennessee Valley Authority 80/07/16 2pp

- 6007310208 Forwards response to Items 2 (Unit 3),4,5,6(c) & 7 of IE Bulletin 60-17 Present standby liquid control sys design is unable to support two-pump flow but sys is equipped w/interlocking contacts Item 2 for Units 1 & 2 will be sent MILLS,L M Tennessee Valley Authority 60/07/16 10pp
- 8007290337 Grants extension of time to 800Bl1 for performing scram tests per IE pulletin 80-17 EISENHUT, D.Q. Division of Licensing 80/07/18 2pp
- 8007300572 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Summaries of equipment qualification evaluations based on Encl 4 criteria, encl Full response will be forwarded when evaluations complete MILLE, L M Tennessee Valley Authority 80/07/18 54pp
- R Periodic operating reports & related correspondence
- BOO7220443 Forwards "Effluent & Waste Disposal Semiannual Rept," supplemental info for second half 1978 DEHEASE, J Q Tennesser Valley Authority 79/02/15 1p
- --8007220462 "Effluent & Waste Disposal Seminnoval Rept." supplemental info for second half 1978 # Tennessee Valley Authority 79/02/15 15pp
- BOO7220342 Forwards "Effluent & Waste Disposal Semiannual Rept," supplemental info first half 1979
 ABERCROMBIE.H Tennessee Valley Authority 79/08/17 1p
- ---8007220346 "Effluent & Waste Disposal Semionnual Rept." supplemental info.first balf 1979
 * Tennesses Valley Authority 79/08/17 16pp
- 8007220481 Forwards "Effluent & Haste Disposal Semiannual Rept, Supplemental Info Second Half 1979 " ABERCROMBIE.H Tennessee Valley Authority 80/01/31 tp
- ~~B007220491 "Effluent & Hasto Disposal Semiannual Rept.Supplemental Info,Second Half 1979 " * Tennessee Valley Authority 80/01/31 16pp
- BOO7160552 Forwards monthly operating repts for June 1980 AMERCROMBIE, H. L. Tennessee Valley Authority BO/07/10
- --8007160536 Monthly operating repts for June 1980 THOM.T. GREEN.D Tennessee Valley Authority 80/07/02 32pp
- 8 Reportable occurrences, LERs & related correspondence
- E007080293 Forwards LER 80-045/09L-0
 CALHOUN, J R Tennessee Valley Authority 80/06/27 1p
- --BOO7080297 LER BO-045/03L-0 on BOO602, at BOX power, HPCI failed to meet flow requirements because turbine stop valve tripped Caused by worn mechanical overspeed trip piston New parts installed & tested # Tennessee Valley Authority BO/06/27 2pp
- B007080301 Forwards LER 90-044/00L-0 CALHOUN, J. R Tennesses Valley Authority 80/06/27 ip
- --B0070B0B0B LER 80-046/03L-0 on B00605, during power operation, while performing surveillance test, core spray ρump discharge pressure switch.PB-75-44, exceeded satpoint Caused by instrument drift Sultch was inspected, callbr & tested * Tennessee Valley Authority 80/06/27, Ppp
- BOO7:240455 Part 21 rept re defective Terry Turbine Co HPCI turbine Caused by machining error in fabrication of mechanical overspeed trip valve body assembly which resulted in HPCI remaining in trapped condition Valve body replaced PARRIS, H & Tennesses, Valley Authority 80/06/30 3pp
- BOO7OBO313 Forwards LER 80-047/034-0 CALHONN, J R, Tennesses Valley Authority 80/07/01 1p
- --8007080333 LER 80-047/03L-0 on 800604, during power operation, while testing drywell air sampling sys, vacuum pump associabed w/ RM-1-90-236 failed Caused by normal wear Pump was replaced * Tennessee Valley Authority 80/07/01 2pp
- BOO7690003 Forwards LER BO-048/03L-0 CALHOUN, J.R. Tennessee Valley Authority BO/07/01 lp

į

- --B007090006 LER 80-048/03L-0 on 800602, at steady state power, leak , between root valve & main fire header on sensing lime PB-26-44 during running of \$1.4 if A Caused by crack in half inch schedule 40 carbon steel hipple threads due to corrosion * Tonnessee Valley Authority 80/07/01 2pp
- B007290864 RD on 80070B.during toutine surveillance instruction,PCV 73-43, which controls cooling water to gland seal condensor & lube oil cooler, was found stuck in closed position Cause unknown Equipment expected to be returned to sec by 80070B ABERCROMDIE.N Tennesser Valley Authority 80/07/08 ip
- 8007150570 Forwards updated LER 79-025/01X-1 GALHOUN, J.R. Tennessee Valley Authority 80/0//10 19
- --8007150574 Updated LER 79-029/01X-1 on 790926, main steam lines not isolated after high temp logic actuation Caused by misinterpretation of Tech Specs Tech Spec revision proposed * Tennøssee Valley Authority 80/07/10 2pp
- B007230445 Forwards RO 50-259/8054
 MILLS, L M Tennessee Valley Authority B0/07/15 lp
- ---8007230452 RO 50-259/8054 on 800706, river temp exceeded max limita for over 1-h at downstream monitor Caused by computer error Predictive computer program underestimated max downstream temp by 2 F Cooling towers used, station load reduced a Tennessee Valley Authority 80/07/15 2pp
- B007230470 Forwards LER 80-047/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/15 Ip
- --8007230474 LER 80-049/03L-0 on 800620, during surveillance check, TI pressure increase detected on shell side of i-C AHR heat exchanger Caused by loosened nots due to thermal cycling & vibration Heat exchanger reassembled % tested # Tennessee Valley Authority 80/07/15 2pp
- E007230490 Forwards LER 80-051/0JL-0 GALHOUN, J R Tennesses Valley Authority 80/07/18 lp
- --8007230491 LER 80-051/03L-0 on 800626, scram discharge vol high wate Hevel switch LS-84-45A foiled Caused by float lodged in BL-305-E3-X level switches float chamber flushed

 * Tennessee Vallay Authority B0/07/18 2pp
- 8007230523 Forwards LER 80 050/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/18 Ia
- --8007230531 LER 80-090/03L-0 on 800624, during performance check, foun pressure switch PS-47-144 miswired Caused by personnel failure to follow proper procedures for working on CSSC equipment Pressure switch rewired correctly

 * Tennessee Valley Authority 80/07/18 3pp
- 8007290657 Forwards LER 80-054/04T-0 CALHOUN, J R Tennessee Valley Authority 80/07/18 ip
- --8007290664 LER 80-054/04T-0 on 800706 during normal operation,U-2 & U-1 were placed on cooling towers Tomp continued to rise River temp peaked at 90 2 l & then declined Caused by inaccurate rive; temp predictions due to solar heating * Tonnessee Valley Authority 80/07/18 2pp
- 8007290737 Forwards LER 80-059/0.H.-O CALHOUN, J R Tennessee Valley Authority 80/0//25 ip
- --8007290744 IER 80-052/03L-0 on 800628, during normal operation, 4tV Si B tripped on dograded voltage initiating auto start of diesel generator B Diesel generator tripped again on degraded voltage Caused by impraper switch alignment * Tennessee Valley Authority 80/0//25 2pp
- T Hearing transcripts on non-antitrust matters
- B007240091 Transcript of 800715 briefing on status of facilities in , Washington, DC Pp 1-21 # Commission 80/07/15 2ipp

1

- Security, medical, emergency & fire protection plans
- 107210024 forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printest containing supporting data for vital area analysis Encis withheid (ref 10/18/2790)

 IPPOLITO, T.A. Operating Real Lurs Branch 2 80/06/30 2pp
- 00/220028 Confirms that LASE will conduct vital area analysis of Units 2 & 3 on 800/14 & Chalbourne & 3 Rand will conduct visit IPPOLITORY A Operating Reacture Branch 2 80/07/03 2pp
- 00/300061 Requests confirmation of agreement to participate in program to examine north wall of reactor hidy it review records retests on fire protection syspec Commission Dider C.1 80-21 Also requests that listed into be available for NRC visit LIGENHUT.D O Division of licensing 80/07/16 App
- Adjudiratory currespondence
- 007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780902 petition for reconsideration of 700418 memorandum % order UCS 771104 petition sought action refere fire protection for electrical cables EISENINJ.D G Division of Licensing, 80/06/25 G9pp

Oeneral correspondence

- 007176380 Expresses concern to plans to construct low level waste storage & incineration facility Proposed facility would present significant health ricks to highly populated area Requests public hearing & E13
 HOLLINGSHORTH Affiliation Unknown G0/07/07 1p
- Insurance & indomnity information
- 07010316 Forwards Endorsement 51 to ANI Policy NF-178 FIELDER, J. March & Milennam inc., M & H Nuclear Consultants, inc Div 60706723 App
- 07310936 Forwards Endorsement 43 to MAELU Policy MF-66 FIELDER.J Marsh & McLauman.Inc . M & M Nuclear Consultants.Inc Div 80/07/21 2pp
- Operating license stage documents & correspondence
- 07230028 Summary of 600,707 meeting w/Mark I owners group in Duthesda, HD. Te revisions to NRC acceptance criteria & ovtstanding issues relative to Mark I containment long-turm program GRIMES, C.T. Plant Systems Branch 80/02/21 31pp
- 97070268 Responds to 800123 ltr me use of OBYN code in determining aperating limit min critical power rotto Util requests forther clarification of expected penalties that may be imposed on top of OBYN calculations of the BOVO9728 Epp MILLS: I M Tennessee Valley Authority 80/09/28 Epp
- 07020711 Responds to 800422 Itr re low level waste mgt at plant Vitimate ottl objective is to provide for unsite radwaste storage No target date has been established by TVA for submitting application for incineration approval NOVAK.T H Assistant Director for Operating Reactors 80/06/25
- 07080286 Responds to NRC 800523 request for facility participation in phase two Interim Reliability Evaluation Program Urges definitive rontusion of phase one before continuing Outline of critical areas to be resolved which HIIIS-L M Tennessee Velley Authority 80/06/30 3pp
- 07080300 Responds to NRC 791002 ltr to All BHR licensoes & 791031 ltr to util Util funds allocated for Mark I owners group full-scale test Pocility program Schedule for completion of plant-unique analysis forthiuming flutBit M fennesses Valley Authority BO/0//Ot 1p
- 07210026 Forwards request for addit info to complete review of containment purging & venting at farilities NOVAK.T M. Assistant Director for Operating Reactors 60/07/08 Sop

- 8007170560 Application to amend Licenses DPR-52, changing Tech Specs to accommodate Reload D.Cycle 4 operation Requests that approval of proposed change be given by 801010 to avoid impacting scheduled startup MILLS.L M Tonnessee Valley Authority 80/07/14 2pp
- --8007170966 Proposed Tech Spec changes for License DPR-52 to accommodate Reload 3,Cycle 4 operation 4 Virginia Electric & Power Co BO/07/14 18pp
- --8007170574 Supplemental Reload Litersing Submittal for Browns Ferry Nuclear Power Station, Unit 2. Reload 3 " HILF.C L . ENGEL., R E General Electric Co . Y1003J01A12 80706/30 20pp
- B007220376 Forwards proposed changes to ETS Section 2 i re thermal discharge limits
 MILLS.L M Tennessee Valley Authority 80/07/14 1p
- --8007220377 Proposed change to ETS.Section 2 1 re thermal discharge limits * Tennessee Voiley Authority 80/07/14 1p
- 8007240225 Forwards Amends 61.36 % 33 to Licenses DPR-33.DPR-92 & DPR-6B.respectively & notice of issuance & availability IPPDLITO.T A Operating Reactors Branch 2 80/07/15 3pp
- --8007240231 Amends 61.56 & 33 to Licenses DPR-33.DPR-52 & DPR-68, respectively, changing Tech Specs to thermal discharge limits IPPCLITG.T A Operating Reactors Branch 2 80/07/15 13pp
- --8007240234 Notice of issuance & availability of Amends 61,96 & 33 to Licenses DPR-33.DPR-52 & DPR-68.respectively IPPOLITO.T A Deerating Reactors Granch 2 80/07/15 2pp
- 6007300284 Responds to oncl 600602 memo re low level waste mgt at facility (til plans to construct two separate low level waste facilities onsite Const on first four cubic)es began recently NRC approval of plans necessary UENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/23 Bpp
- --8007300291 Requests summary of util plans to build low level waste storage facility Also requests whether NRC approval is required & whether public hearings have been requested DRADFORD P A Commission 80/06/02 ip
- Q Inspection reports, IE Bulletins & correspondence
- B007240089 Forwards IC Info Notice 80-20, "Loss of Decay Heat Removal Capability at Dayls-Desse Unit 1 While in Refueling Mode "
 No response required
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
 3pp
- B007140476 Forwards IE Bulletin 80-13, "Cracking in Core Byray Spangers" Written response required D'REJLLY.J P Region 2, Atlanta. Office of the Director 80/05/12 ip
- 8007020192 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/29 ip
- B007220027 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs" No written response required O'NEILLY, J P Region 2. Atlanta, Office of the Director 80/06/10 3pp
- D007140306 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Bischarge Vol Capability " Written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/12 Ip
- 8007020499 Forwards response to IE Bulletin 80-09 transmitted by JP D'Reilly 800417 1tr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp

- 8007020761 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power" Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/16 to
- B007020391 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/2
- 8007310344 Forwards IE Insp Repts 50-259/80-25,50-260/80-19, 50-296/80-20 & 50-327/80-22 D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/23 308
- --B007310351 IE Insp Repts 50-259/B0-25,50-260/B0-19,50-296/80-20 & 50-327/B0-22 on B00521 Insp consisted of enforcement meeting in Atlanta, 6A to discuss exceeding DDT radiation limits during shipment of radwaste from Browns Ferry DANCE,HC Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/06/20 2pp
- 8007170070 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY-J P Region 2. Atlanta, Office of the Director 80/06/24 in
- 8007180523 Forwards response to IE Bullotin 79-27. "Loss of Mon-Class IE Instrumentation & Control Power Sys Bus During Operation." & to 800404 confirmatory orders Feedwater pump turbine & main turbine trip circuitry will be upgraded MILLS,L M Tennossee Valley Authority 80/06/26 8pp
- 8007230293 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount inc Models 1151 t 1552 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also and No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/27
- B007210091 Forwards response to IE Bulletin B0-iO Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradioactive & radioactive sys Routine sampling & analysis program established MILLS.L M Tennessee Valley Authority 80/07/07 3pp
- B007230726 Forwards monthly status ropt re | E Bulletin 79-14, "Seismic Analysis for As-Built Bafety-Related Piping Sys," presenting status of work as of 800701 HILLB. L Work as of 800701 HILLB. L Workersee Valley Authority 80/07/07 29pp
- 8007280104 Forwards response to IE Bulletin 80-ii Response includes general arrangement drawing indicating masonry walls of concern & equipment in approximate area of wall W/o encl FURB.B J. Carolina Power & Light Co 80/07/07 lp
- B0072B0&15 Responds to IE Rulletin 80-08, "Examination of Containment Penetration Helds " Results of investigation encl MILLS,L M Tennessee Valley Authority 80/07/07 5pp
- 8007210103 Forwards response to 1E Bulletin 80-il Identifies masonry Walls that support or are near safety-related sys Submits schedule for re-evaluation program CROSS.J L Tennessee Valloy Authority 80/07/00 3pp
- 8007280460 Ack receipt of 800616 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-20, 50-226/80-15 & 50-276/80-16 LEHIB, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/09 2pp
- --8007280468 Responds to NRC 800520 ltr re violations noted in Insp Repts 50-259780-20.50-260/80-15 & 50-296/80-16 Corrective actions calibr valve orientation corrected Justifies decision re nonreporting of deisel geneator failure MILLS.L M Tennessee Valley Authority 60/06/16 App
- --8007280475 Forwards IE Insp Repts 50-259/80-20,50-260/80-15 & 50-296/80-16 on 800403-0502 & notice of violation LEWIS,R C. Region 2: Atlanta, Reactor Operations Nuclear Bupport Branch 80/05/20 2pg
- --B007280478 Notice of violation from insp on B00405-0502 * Region 2, Atlanta, Office of the Director B0/05/20 ip

- --8007280484 IE Insp Repts 50-279/HO-20, 50-260/HO-15 & 50-296/HO-16 an 800405-0502 Noncompliance noted failure to adhere to surve(i)lance instructions to make prompt rept to NRC SULLIVAN R F., CMASE, J W. Region 2, Atlanta, Office of the Director DAMCE, H C. Region P. Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 /pp
- B007250594 Forwards response to Item t of IE Bulletin 60-17 re water in scram discharge vol No significant amount of water was found in discharge vol % associated piping Scram discharge vent valves are operable CROSS.J L Tennessee Valley Authority 80/07/11 2pp
- 8007310067 Forwards second interim rept in response to IE Bultetin 80-06 Since 800612 interim rept, util completed review of primary containment sys. reactor protection sys. RHR sys & core spray sys Evaluation of other sys underway CROSS.J L. Tennessee Valley Authority 80/07/11 2pp
- 8007220522 Requests extension until 800811 for performing manual & automatic scram required by IE Bulletin 80-17 Extension needed because of current heat wave MILLS.L M Tennessee Valley Authority 80/07/16 2pp
- 8007310208 Forwards response to Items 2 (Unit J), 4, 5, 6(c) & 7 of IE Bulletin 60-17 Present standby liquid control sys design is unable to support two-pump flow but sys is equipped w/interlocking contacts Item 2 for Units 1 & 2 will be sent HILLS, L M Tennessee Valley Authority 80/07/16 10pp
- B007270357 Grants extension of time to 800811 for performing scram tests per 1E Bulletin 80-17 EISENHUT, D G Division of Licensing 60/07/18 Rpp
- 8007300572 forwards response to IE Qulietin 79-010, "Environ Qualification of Class IE Equipment " Summaries of equipment qualification evaluations based on Encl 4 critoria, encl Full response will be forwarded when evaluations complete MILLS.L N Tennesses Valley Authority 80/07/18 54pp
- A Periodic operating reports & related correspondence
- BOO7220443 Forwards "Effluent & Haste Disposal Semiannual Rept." supplemental info for second half 1978
 DEWEASE, J G Tennessee Valley Authority 79/02/15 1p
- ---B007220463 "Effluent & Waste Disposal Semiannual Rept," supplemental info for second half 1970

 * Tennessee Valley Authority 79/02/15 15pp
- 8007220342 Forwards "Effluent & Haste Disposal Semiannual Rept," supplemental info.first half 1979 ABERCROMBIE,H Tennossee Valley Authority 79/08/17 ip
- --8007220346 "Effluent & Waste Disposal Sommanual Rept," supplemental info.first half 1979

 * Tennessee Valley Authority 79/08/1/ 16pp
-
- BOO7220481 Forwards "Effluent & Haste Disposal Semiannual Rept. Bupplemental Info, Second Half 1979 " ADERCROMBIE.H Tennessee Valley Authority 80/01/31 lp
- --8007220491 "Effluent & Waste Disposed Semiannual Rept.Supplemental Info.Second Half 1979 " * Tennessee Valley Authority 80/01/21 16pp
- BO07160552 Forwards monthly operating ropts for June 1980 ABERCROMBIE.H L. Tennessee Valley Authority 80/07/10 1p
- --B007160556 Monthly operating repts for June 1980
 THOM.T, GREEN.D Tennessce Valley Authority 80/07/02 32pp
- 5 Reportable occurrences, LERs & related correspondence
- 8007110291 RU-BFRU-50-260/8025 on R00617. Dresser Industries safety valves identified as possibly having guides w/cracks Condition identified in similar valves loaned to another util from Browns Forry Care unknown ADERCROMBIE. H. Tennessee Valley Authority 80/06/17 ip
- 8007080394 Forwards LER 80-023/03L-0 CALHDUN, J R Tennessee Valley Authority 80/06/27 ip

- ~-8007080399 LFR 80-023/03L-0 on 8(10607, during normal operation, 2A reactor recirculation motor generator set tripped due to generator staton temp high relay actuation Probable cause was fonce wire caused by vibration

 * Tennessee Valley Authority 80/06/27 Jp
- 3007080405 Forwards LER 80-022/03L-0 CALHOUN.J R Tennessee Valley Authority 80/06/27 ip
- ~8007080411 LER 60-027/031-0 on 800402. while performing S [4 [A-14, turbine first stage pressure permissive pressure switches PS-1-91 A & II & PS-1-91 A & B setpoints exceeded Tech Spec limits Caused by switch drifting

 * Tennessee Valley Authority 80/06/27 2pp
- 007080370 Forwards LER 80-025/017-0 CALHDUN, J R Tennessee Valley Authority 80/06/30 Ip
- -8007080373 LER 80-025/017-0 on 800617.during normal discovered that spare Dresser Industries safety valve bad guide w/cracks Caused during initial pouring of casting & subsequent cooling Addl valves will be inspected for cracks * Tennessee Valley Authority 80/06/30 2pp
- 07290720 Forwards LER 80-024/03L-0 CALHOUN, J.R. Tennessee Valley Authority B0/07/22 1p
- 8007290726 LER 80-024/03L-0 on 800624.during rod sequence exchange w/
 unit at 40% power.control rod 30-27 failed to latch after
 insertion & drifted out when insert rod released Caused by
 failure of directional valve 85-40C Valve replaced
 w Tennessee Valley Authority 80/07/22 2pp
- Hearing transcripts on non-antitrust matters
- 0724009: Transcript of 800715 briefing on status of facilities in Vashington.DC Pp 1-21 Commission 80/07/15 21pp
- CKET 50-241 H D ROBINSON PLANT, UNIT 2
- Security, modical, emergency & fire protection plans
- 7020330 Forwards request for addl into & revisions for safeguards ontingency plan submitted on 790323 Info should be provided ithin 30 days of receipt of itr Request withhold ref 10CFR2 770)
 AROA, S.A. Operating Reactors Branch i 80/05/2i 2pp
- 7010307 Responds to NRC 800521 request for add1 info re 790323 afeguards contingency plan info will be submitted by 10801
- TLEY, E E Carolina Power & Light Co 80/06/27
- 7010514 Responds to B00604 request for addl info re administrative introls for fire protection Util will develop program thering to requirements
 FLEY, E E Carolina Power & Light Co 80/05/27 2pp
- djudicatory correspondence
- 310243 Forwards Commission B00727 memorandum % order containing veisions on UCS 780502 pottition for reconsideration of O413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables SENRUT.D 0 Division of Licensing 80/06/25 89pp
- inancial information
- 1200/1 Responds to 800300 request for comment an util 8-7 gistration statement Review identified no inaccurate atements in NRC regulatory inquirements or financial info led W/NRC RISTENBURY, E Hearings Division 80/05/27 ip
- verating license stage documents & correspondence
- 90126 Responds to 8003t8 ltr re NRC position on util approach of lying AIF position paper for procurement of off-the-shalf ms NRC does not concur w/util approach Procurement of ire or replacement parts vbj to QA controls is SS.W P Quality Assurance Branch 80/05/23 2pp

- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D G Division of Licensing 80/06/ii 62pp
- 8007100150 Forwards Amend 47 to License DPR-23, safety evaluation & notice of issuance & availability
 VARGA.S A Operating Reactors Branch 1 80/06/12 2pp
- --8007100156 Amend 47 to License DFR-23.allowing blockage of channels when RCS pressure less than 2.000 psig VARGA:S A Operating Reactors Branch 1 80/06/12 4pp
- --B007100162 Safety evaluation supporting Amend 47 to License DPR-23 EGRO technical rept encl # Office of Nuclear Reactor Regulation. Director 80/06/12 9pp
- --B007100165 Notice of issuance & availability of Amend 47 to License VARGA,S A Operating Reactors Branch 1 80/06/12 2pp
- 8007010384 Forwards responses to DG Eisenhut 800507 info request re final recommendations of Bulletins & Orders Task Force UTLEY.E E Carolina Powor & Light Co 80/06/27 2pp
- 8007250001 Requests submittal of application for amend to consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items end for guidance EISENHUT. D O Division of Licensing 80/07/02 69pp
- 8007130626 Responds to ARC 800602 request to modify administrative procedures to limit auxiliary feedwater flow Util will revise procedures to limit pump operation following postulated steam line break & prior to isolating component UTLEY.E E Carolina Power & Light Co 80/07/09 2pp
- 8007250420 Corrects inaccuracies in NRC 800410 evaluation of Category A.TMI-2 Lessons Learned Tosk Force items implementation No equipment is required to implement interlamenerus sampling procedures
 UTLCY.E C. Carolina Power & Light Co. 80/07/22 2pp
- 8007280679 Submits schedule for refueling facility for Cycle 8 operation ECCS analysis being performed to allow for up to 10% steam generator tube plugging in event steam generator innp program indicates addl tubes need to be plugged UTLEY.E C Carolina Power & Light Co 80/07/22 2pp
- 8007290690 Notifies that revised radiological effluent Tech Specs will be submitted by 801022 per NRC B00602 comments & 800701 meeting discussions UTLEY.E E Carolina Power & Light Co 80/07/22 lp
- 8007270686 Forwards addl info re adequacy of station electric distribution sys voltages. In response to 800602 ltr Describes undervoltage relay trip setting for Class iE 480 volt buses spare startup transformer & offsite sources UTLEY.EE Carolina Power & Light Co 80/07/23 7pp
- BOO7310517 Summary of BOO701 meeting w/util in Bethesda.MD re proposed radiological E79 NEIGHBORS,D Operating Reactors Branch 1 80/07/23 3pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007240ii3 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Dease Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, JP Region 2, Atlanta, Office of the Director 80/05/08
- 8007020187 Forwards IE Info Notice BD-22, "Dreakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007210422 Forwards 1E Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/28
- 8097010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2: Atlanta, Office of the Director, 80/05/29

- B0070200B7 Responds to 1E Bulletin 80-06 Review of control wiring diagrams of safety-related functions confirmed that emergency equipment would remain in emergency mode upon reset FURR.D U Carolina Power & Light Co 80/06/10 3pp
- 8007220043 Forwards IE info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 200
- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response regulated D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- B007020745 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/18
- 8007100031 Submits revised schedule for response to IE Dulletin 79-01B.
 "Environ Qualification of Class IE Equipment " Rept will now
 be completed as soon as all available info is obtained
 FURR. B J Carolina Power & Light Co 80/06/19 ip
- BOO7020440 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director BO/06/20 to
- 8007100093 Forwards IE Insp. Rept 50-261/80-12 on 800610-12 No noncompliance noted Details withheld (ref 10CFR2 790) KENNA,W D Region 2, Atlanta, Bafeguards Branch 80/06/20 1p
- --B007100095 JE Insp Rept 50-261/80-12 on G00610-12 No noncompliance noted Major areas inspected security organization Details withheld (ref 100FR2 790)

 GILLEBPIE.F P. MOORE.D E., VORSC.J Y. Reglon 2, Atlanta. Office of the Director B0/06/20 Ip
- 8007150087 Ack receipt of 800609 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-261/80-09 KENNA, H B Region 2, Atlanta, Bafeguards Branch 80/06/24 jp
- --B007150097 Responds to NRC B00514 ltr re violations noted in IE Insp. Rept 50-261/80-09 Attachment A describing corrective action withheld (ref 10CFR2 770)
 FURR.B J Caroline Power & Light Co B0/06/09 ip
- ~~8007150101 Forwards IE Insp Rept 50-261/80-09 on 800421-25 & netice of violation Notice of violation withheld (ref 10CFR2 790) KENNA H B Region 2, Atlanta, Safequards Branch 80/05/14 2pp
- ---B007150107 IE Insp Rept 80-261/80-09 on B00421-25 Nencempliance noted insecure grates & hatches provided unauthorized access into vital area Details withheld (ref 10CFR2, 790)
 GILLEBPIE, F P Region 2, Atlanta, Office of the Director B0/05/14
- 8007160800 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24
- 8007230220 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl Np written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 10
- BOO7220254 Responds to IE Bulletin BO-10 Review of facility design & operation complete Sampling, analysis & monitoring program established New or revised procedures implemented FURR.B J Caralina Fower & Light Co BO/07/01
- 800722027 Responds to IE Bulletin 80-08 Facility has no flued head prnetrations in containment Welds are fillet & were examined by magnetic particle method during const FURR.B J Carolina Power & Light Co 80/07/03 ip

- G007210022 Forwards second response to IC Bulletin 79-018 Includes environ qualification data hased upon investigation to date Efforts to obtain available data from NSSS supplies are underway H/o encl
 EURY-L W Carolina Power & Light Co 80/07/0/ ip
- R Periodic operating reports & related correspondence
- 8007;50629 Forwards monthly operating rept for 1980 STARKEY.R B Carolina Power & Light Co 80/07/10 ip
- ~-8007150633 Monthly operating rept for June 1980 WATFORD, M. Carolina Power & Light Co. 80/07/02 Spp
- S Reportable occurrences, LERs & related correspondence
- 8007010401 LER 79-027 has been rancelled * Carolina Power & Light Co 80/06/30 ip
- 8007010408 LER 79-023 has been cancelled * Carolina Pawer & Light Co 80/06/30 1
- 8007010410 LER 79-022 has been cancelled * Carolina Power & Light Cu 80/06/30 1g
- 8007010461 LER 79-013 has been cancelled * Carolina Power & Light Co 80/06/30
- 8007010466 LER 79-021 has been cancelled * Carolina Power & Light Co 80/06/30 ig
- 8007220440 Forwards LER 80-014/01T-0 STARKEY, R B Carolina Pawer & Light Co 80/07/16 1p
- --B007220445 LER B0-014/017-0 on 800702 determined no certification of qualification available for PVC electric cable pigtails per IE Bulletin 79-018 Cause not stated Test to be conducted assuring pigtails ability to perform required function STARKEY,R B Carolina Power & Light Co B0/07/16 5pp
- V Operator Examinations
- B007220426 Forwards revised training programs for instructor requalification program & operator requalification program STARKEY, R B Carolina Power & Light Co 80/07/11 2pp
- --8007220429 Training Instruction 201.Revision 4, "HB Robinson Plant Operator Replacement Training Program" * Carolina Power & Light Co 80/05/19 9pp
- ---8007220433 Training Instruction 201A Revision 4. "Training of Replacement Reactor Operators for NRC Examination H/o Reactor Startup Demonstration " * Carolina Power % Light Co 80/06/27 japp
- --8007820435 Training Instruction 203.Revision O. "Senior Reactor Operator Replacement Training Program " * Carolina Power & Light Co 80/05/25 10pp
- --8007220438 Training Instruction 902.Revision O. "Instructors Requalification Program" * Carolina Pawer & Light Co 80/05/29 iOpp
- DOCKET 50-263 MONIFICELLO NUCLCAR GENERATING PLANT

 F Security, medical, emergency & fire protection plans
- 8007010372 Forwards BNL fire protection review re diesel generator room automatic water suppression sys & cable spreading room gas suppression sys for facility HALL, R E Brookhaven National Laboratory 80/06/24 3pp
- 80070103B1 Submits description of motor generator set room vent duct fire proofing required by fire protection safety evaluation Halm vent duct & duct branching into main duct will be covered with 2-inch layer of Pyrorrete 241 MAYER, L. O. Northern States Power Co. 80/06/25 ip
- 8007010325 Submits description of fire stops between Fire Zones 13C & 19C; required by fire protection safety evaluation Comments on proposed design should be conveyed by 800815 to comply w/work schedule MAYER, LO Northern States Fower Co 80/06/26 2pp

- 8007010311 Describes thanges planned for fire protection safety evaluation sections re commitment to provide capability to cool filts pump seal coolers via emergency syr water sys forwards drawing of interconnection schematic MAYER, L. O. Northern States Power Co. 80/06/27 3pp
- BOO7280444 Forwards add1 info re fire protection safety evaluation Control room fire detectors, have stations add1 have & fire pumps are addressed MAYER.L Q Northern States Power Co 80/07/18 App
- B0072B03B1 Submits design change to five protection safety evaluation. Item 3 i 12(2). "Fire Suppression Bys Interconnection "Turbine bidg end of interconnection line will remain pressurized as supply for sprinkler curtain MAYER.L () Northern States Power Co. 80/07/21 lp
- 8007280488 Discusses licensee review of alternate 250 volt do power source in HPCI & reactor core isolation cooling sys independent source for HPCI is required to assure HPCI operability in event of fire in existing battery sys MAYER.L D Northern States Power Co 80/07/22 ip
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D & Division of Licensing 80/06/25 B7pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark 1 comers group in Bethesda, MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31p
- B007030222 Notifies NRC of intention to ship residective math from facilities using Model HN-600 HAYER,L O Northern States Power Co 80/06/13 1p
- B007010335 Submits description of battery room ventilation air flow monitoring installation Diagram encl
 HAYER, L. O. Northern States Power Co. 60/06/24 2pp
- 8007080291 Responds to GE 800221 Itr re list of concerns from ACRS consultant HPCI & reactor core isolation cooling described Completes commitment re NUMEG-0560. Item II K 3 46 MAYER, L O Northern States Power Ca 80706/20 2pp
- 8007100067 Advises that time-motion study & dost rate calculation using relevant dost rates completed per NUREG-0578, Item 2 1 8 a New post-accident sempling station will be installed MAYER.L D Northern States Power Co 80/06/30 ip
- 8007220038 'Electrical, Instrumentation & Control Sys Support," technical evaluation rept for June 1980 CLEVELAND.C J EG&G Idaho. Inc FIN A-6256 8007220030 80/06/30 Idapo
- 8007080255 Forwards summary of test data re completion of EDC 7 fuel insp & DOC 8 startup physics test MAYER, L O Northern States Power Co 80/07/02 4pp
- 6007210186 Forwards "Yest Rept EOC 7 Fuel Insp & BOC 8 Startup Physics" MAYER.L O Northern Statos Power Co 80/07/02 1p
- --B007210196 "Fest Rept EOC 7 Furl Insp & 200 B Startup Physics "
 * Northern States Power Co 80/97/02 3pp
- 8007280056 Advises of intention to ship radioactive matls from listed active matls from listed

nalysis tode for 1981 e code Addl 1 BWR

1/07/07 Rpp

for comments on Drive Return

300

- 8007180700 Forwards Revision 6 of "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Reliaf from ASME Code Section XI Requirements " MAYERL D Northern States Power Co 80/07/16 2ap
- ---8007180306 Revision & of "ABME Code Section XI Inservice Insp & Testing Program & Infu Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " • Northern States Fower Co 80/07/16 24pp
- 8007280410 Forwards comments in NUREG-0577. "Fracture Toughness & Susceptibility to Stress Corrosion Cracking of Equipment Bupports," in response to NRC 800319 request Addl analysis for stress corrosion cracking is unnecessary MAYER.L 0 Northern States Power Co 80/07/21 5pp
- 6007280489 Forwards NUTECH evaluation of low pressure turbine roll Results confirm earlier belief that present sys limitations associated w/intermediato range monitors cause 600 psi turbine roll Made under review CLARITY, M II Northern States Power Co. 80/07/21 16pp
- G Inspection reports, IE Bullatins & correspondence
- 8007140532 Forwards JE Bulletin 80-13, "Cracking in Core Spray Spargers " Hritten response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/12 ib
- 8007020054 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28 ip
- 80070i0127 Forwards IE Info Notice 80~20. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/29 in
- 6007140487 Forwards IE Inep Rept 50-263/80-09 on 800428-0502 No noncompliance noted HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/30 2pp
- --B007140494 IE Insp Ropt 50-263/80-09 on B0042B--0502 No noncompliance noted Najor areas inspected plant operations, torus-dyrwell vacuum breaker med & recirculation pump seal failures WARNICK, R F, BROWN, C, MADISON, A Region 3. Chicago, Office of the Director B0/05/20 Opp
- 8007110044 Forwards IE Insp Rept 50-263/80-06 on 800324,27-30,0424-25 & 0506-07 No nancompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --B007i10049 IC lnsp Rept 50-243/80-06 on B00324,27-30,0424-25 & 0506-07
 No noncompliance noted Major areas inspected containment
 integrated look rate test & local teak rate testing
 HEISIMAN.R F Region 3. Chicago. Reactor Operations Nuclear
 Bupport Branch CHOM.E T . HOPMINE, J B Region 3. Chicago. Office
 of the Director 80/06/03 7pp
- 8007220212 Forwards lE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director R0/06/10 lb
- 8007140321 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required KEPPLER: J G Region 3. Chicago, Office of the Director 80/04/12 ip
- 8007020162 Responds to IC Bulletin 80-05. "Engineered Safety Feature Roset Controls " All safety-related equipment remains in emorgency made upon roset of actuation signal w/listed exceptions
 OLDERTS, D E Northern States Power Co 80/05/16 3pp
- 8007030043 Forwards IE Bullatin 80-15, "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power " Written response required KEPPLEN, J 0 Region 3, Chicago, Office of the Director 80/06/18 ip
- 8007020573 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/06/20, ip

- 8007300307 Forwards IE Insp Rept 50-263/80-10 on 800520-22 No noncompliance noted HEIBHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/23 2pp
- --8007300309 IE Insp Rept 50-263/80-10 on 800520-22 Ne noncompliance noted Major areas inspected fire protection prevention, IE bulletin followup, calibr & review of plant operations BR(MN), C H, WARNICK, F Region 3, Chicago, Office of the Director 80/06/20 4pp
- 800717050& Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Rosultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24 to
- 8007210501 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/80-08
 DAVIS A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/06/24 ip
- --8007210509 Responds to NRC B00508 ltr re violations noted in 1E Insp Rupt 50-263/80-08 Currective actions labels reinforced w/ tage: redundant labels applied & extra set of labels provided w/instructions OILBERTS: D E Northern States Power Co 80/05/28 lp
- BOO7230336 Forwards IE Bulletin BO-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular BO-16 also uncl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director BQ/06/27
- B007210182 Responds to IE Bulletin 80-10, "Centamination of Neuradioactive Sys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Actions re Items 1 & 2 completed as of 800625 GILBERTS, D. C. Northern States Power Co. 80/06/30 1p
- 8007240104 Forwards IE Insp Rept 30-263/80-13 on 800609-13 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND, J A Region 3. Chicago, Safeguerds Branch 80/07/02 2pp
- ---B007240107 IE Insp Rept 50-263/80-13 on B00609-13 No noncompliance noted Details withheld (ref 10CFR2 790) HIND.J A Region 3, Chicago, Safeguards Branch CHRISTOFFER. 9 M. MADEDA.T J Region 3. Chicago, Office of the Director 80/07/01 200
- B007210132 Responds to 1E Bulletin 60-08, "Examination of Containment Liner Penetration Welds " Lists flued head penetrations & provides into re design & nondestructive examination of penetrations GILBERTS, D E Northern States Power Co 60/07/03 9pp
- 8007180566 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR," will start at 12 01 AM on 800708 Test should be completed within 20 days Requests notification of malfunction KEPPLER, J 9 Region 2. Atlanta. Office of the Director 80/07/07 ls.
- B007250365 Responds to 1E Bulletin B0-11 Bechtel Power Corp contracted to identify & rs-evaluate masonry walls Surveys of inaccessible areas will be performed at earliest opportunity w/rssults provided in fullowup rept OILBERTB.D E Northern States Power Co 80/07/07 114pp
- 8007280057 Responds to IE Bulletin 80-17 Surveillance tests performed on 800704 Pound no dotectable water in sys Daily ultrasonic tests are being performed to monitor for residue water Item 7 not applicable
 OILDERTB.D E Northorn States Power Co 80/07/09 2pp
- 8007290841 Submits Add1 response to IE Bulletin 80-17 Appropriate ravisions of operating procedures issued on 800711 No water datected re Itum 5 Reporting requirement 1s Itum 6a accomplished Yurbal requirement per 6b made on 800703 OILBERTS.D E Northern States Power Co 80/07/17 3pp
- R Periodic operating reports & related correspondence
- 8007130511 Forwards monthly operating rept for June 1980 MAYER, L D Northern States Power Co 80/07/09 2pp
- --8007150614 Monthly operating rept for June 1980
 MYRADD.A L. Northern States Power Co. 80/07/03 3pp

- S Reportable occurrences, LERs & related correspondence
- 8007010531 Forwards LER 80-0-2/03L-0
 MAYER, L 0 Northorn States Power Cu 80/04/24 19
- --8007010542 LER 80-022/03 0 on 800529, primary containment orygen concentration exceeded 5/ by weight Teck Spec limit Caused by open svc air isolation valve to drywell Procedures have been revised to assure proper valve positioning SHURTS, 5 J Northern States Power to 80/06/26 lp
- 8007100190 Forwards LCR 80-023/03L-0 MAYER, L O Northern States Power Co 80/07/01 1p
- --8007100195 LER 80-023/03L-0 on 80/601, at a spector offgas radiation moniturs dropped to about 20% nursal for about 40 minutes Caused by mechanical vacuum jump offgas cample valve being incorrectly opened Valve now wired shut JACOBSON, R D Northern States Power Cu 80/07/01 1p
- DOCKET 50-264 DOW CHEMICAL CO
- F Security, medical, emergency % fits protection plans
- B007280699 Discusses uproming review of physical socurity plan Encl 790628 ltr w/Amend 4 to License R-108 incorporated 781020 security plan Pending review of current plan submittal of changes is not necessary MILLER. J R Standardization & Special Projects Branch 80/07/09 2pp
- Q Inspection reports. 16 Bulletins & correspondence
- BQ07170617 Forwards IE Circular 80 14, "Radioactive Contamination of Plant Demineralized Water Sye & Resultant Internal Contamination of Personnel "No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/24 in
- DOCKET 50-265 GUAD-CITICS STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- B007010047 Forwards safeguards contingency plan amend Plan withheld fref 10CFR2 790)
 PEDPLES,D L. Cummnnwealth Edison Co. 80/06/27 ip
- G Adjudicatory correspondence
- BQ07310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771004 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing G0/06/25 89pp
- P Operating license stoge documents & correspondence
- B00723028 Summary of 800207 meeting w/Mark 1 owners group in Dethesda. MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I cuntainment long term program GRIMES,CT Plant Systems Branch 80/02/21 3)pp
- 6007270217 "Measurement of Xe-13),C-14 & Tritium in Air & 1-131 in Vegetation & Milk Around Gund Cities Nuclear Power Stations." KELLER,J H , AKERS,D W , DUCC,S W ldaho National Engineering Laboratory FIN A-6078 NUREG/CR-1195 80/03/31 400pp
- 8007010070 Responds to FOIA request for 97 documents referenced in M Tokar memo to ACR8 concerning pollet-cladding interaction Forwards documents Missing records are duplicative. Superseded or available elsewhere FELTON.J M Division of Rules and Records 80/06/20 2pp
- --8007010119 Forwards description of causes of 750522 off-gas release at facxlity Release appears to be caused by flux peaking SEGELUS Core Performance Branch 75/06/05 3pp
- 8007010190 Responds to SERT Lancerns to control rod drive sys lacking trismic analysis Quad Cities 1 & 2 separic design of control rod drive sys calculations performed for facility while under const encl
 JANECEKLR F Commonwealth Losson Cu 80/06/24 App

- B00701019} "Guad Citips 1 გ ქ 9eismic Data on Control Rod Drive Sys " ო Reactor Controls. Inc 70/07/10 200pp
- 10/070)16 Bubmits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-rulated loads JANECEK.R F Commonwealth Edison Co 80/06/26 App
- 007080069 Responds to NRC 800519 request for addl info concerning adoquacy of station plectric distribution bys voltages JANECFK.R F Commonwealth Edison Co 80/06/30 App
- 007280470 Forwards "Reactor Containment Bidg Integrated Loak Rate Test," & related app describing Type A test Neit Type A test will be performed during shutdown scheduled for 1983 KALIVIANAKIS.N Communuealth Edison Co 80/07/01 ip
- -8007280474 "Reactor Containment Bidg Entegrated Leak Rate Test " « Commonwealth Edison Co BO/OJ/i2 37pp
- 107070345 Forwards revised schedule % status info for Mark I program, feedwate, spanyor replacement & general work planned for Quad Cities I outage Proceeding on priority basis w/mods providing languat safety increase margins REED.C Commonwealth Edison Co 80/07/02 18pp
- 007(00142 Application for amond to App A. Tech Specs of Licenses DRR-29 & DPR-30, implementing fire protection mods JANECEK,R F Commonwealth Edison Co 80/07/03 2pp
- 800710014/ Proposed changes to Tech Specs 3 12/4 12-1 through 3 t2/4 12-9, implementing Fire protection mods 4 Commonwealth Edison Co. 60/07/03 18pp
- 007210212 Responds to NRC request for additinfore turbine disks Applicable turbine missile analysis was presented in Amend 2 to Quad Cisties CP application Analysis applies to Dresden due to similarity of general arrangement
 JANECEK.R F Commonwealth Edison Co 80/07/15 ip
- Inspection reports. IE Bulletins & correspondence
- 07140545 Forwards IC Bulletin 80-i3. "Cracking in Core Spray Spargers " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/12 ip .
- 07020065 Forwards IC Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J.O. Region D. Chicago, Office of the Director 80/05/28
- 07010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/05/29
- 07020756 Forwards revised response to IE Bulletin 79-018, "Environ Qualification of Class IC Equipment " Identifies areas where affort is continuing in identification of equipment qualifications W/o encl JANECEK,R F Commonwealth Edison Co 80/06/09 ip
- 07220156 Forwards IE Info Nutice 80-26. "Evaluation of Contractor OA Programs " No written responso required KEPPLER.J O Region 3. Chicago. Office of the Directur 80/06/10
- 07140309 Forwards IE Bulletin 80-14. "Degradation of BHR Scram Discharge Vol Capability " Written response required REPPLER.J Q Region 3. Chicago. Office of the Director 80/06/12
- 97100004 Forwards response to 1E Bulletin 80-09, "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-70 or NM-90 series hydramotor ictuators "ECPLEB.D L Commonwealth Edison Co 80/06/16 3pp
-)/030037 Forwards IE Bulletin 80-15, "Possible Loss of Emergency detification 8ys (ENS) W/Loss of Offsite Power " Written response required (EPPLER. J Q Region 3, Chicago, Office of the Director 80/06/18

- 8007020589 Forwards IE Carcular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required required

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- 8007110131 Forwards notice of violation & notice of proposed imposition of rivil penalties arising from IE 800131 insp STELLO,V Office of Inspection & Enforcement, Office of the Director B0/06/20 2pp
- --8007110136 Notice of violetion from insp on 800131 Noncompliance noted surface radiation of transporting vehicle exceeded max allowable millirem per hour * Office of Inspection & Enforcement, Office of the Director 80/01/31 ipp
- --B007110145 Nutice of imposition of civil penalties based on item of noncompliance re excessive surface radiation on transport vehicle Office of Inspection & Enforcement, Office of the Director 80/06/20
- G007140147 Notice of proposed imposition of civil penalties in amount of \$4,000 for item of noncompliance re radiation levels on waste shipments exceeding regulatory limits # Office of Inspection & Enforcement. Office of the Director 90/06/20 ip
- 8007170430 Forwards IE Circular 80-14. "Radicactive Contamination of Plant Demineralized Water Sys. & Resultant Internal Contamination of Personnel "No written response required KEPPLER(J O Region 3) Chicago. Office of the Director 80/04/24
- 6007230289 Forwards IE Bulletin 60-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 60-16 also encl No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/06/2"
- 8007300574 Forwards Waste Packaging Insp Rept 15000046/80-07 on 800131 Notice of violation forwarded under separate cover KEPPLER.J O Region 3, Chicago, Office of the Director 80/06/27
- --8007300585 Waste Packaging Insp Rept i5000046/80-07 on 800131 Noncompliance noted radiation levels on surface of trailer in excess of regulatory limits BOOK.H E Region 3. San Francisco. Fuel Facility & Materials Bofety Branch CAIN.C t. Region 4. Dellas. Office of the Director 80/02/27 7ρρ
- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BHR." will start at 12 OI AM on 800708 Test should be completed within 20 days Requests notification of malfunction KEPPLFR.J 0 Region 3. Chicago. Office of the Director. 80/07/07
- 8007250641 Responds to IE Bulletin RO-10, "Cantamination of Nonradicattive Sys & Resulting Patential for Unmonitored. Uncontrolled Release of Radicactivity to Environ " Any affected sys will be restricted if contamination found. PEOPLES.D L. Commonwealth Edison Co. 80/07/07 2pp
- B007250650 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Requested investigation not performed at Dresden, Unit I due to extended outage Requirements will be met prior to startup W/o encl PEOPLES,DI Commonwealth Edison Co 80/07/07 2pp
- 8007250638 Forwards response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " Dresden Unit 1 designs will be reviewed % feasibility of performing radiographic examinations will be assessed before unit returned to svc PEGPLES.D L Commonwealth Edison Co 80/07/09 7pp
- 8007140630 Responds to IE Bulletim 90-17 re results of tests required by Item 1 No significant amount of water in scram discharge vols Vent & drain lines also vorified free of obstructions by parforming dynamic air test

 JANECEK.R F Commonwealth Edison Co 80/07/10 2pp
- B007280074 Forwards add1 response to IE Bulletin 80-17. Items 2.3.4.5.6a & 6b New procedure has been written to cover actions necessary when central rods fail to fully insert during PEOPLES, D.L. Commonwealth Edison Co. 80/07/ii 5pp

- 8007310307 Responds to NRC 8006,0 notice of proposed imposition of civil penalties by forwarding payment
 PEOPLES, D. L. Commonwealth Edison Co. 80/07/14 1p
- 8007310353 Forwards response to violation noted in IE imsp on 800131 Corrective actions procedure now requires under-trailer check of radwaste shipments & pre survey of articles at shipment on assure package, are within dose limits JANECEK, R. F. Commonwealth Eduson Co. 80/07/15. 3pp
- B007300485 Responds to IE Builetin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria" JANECEK, R.F. Commonwealth Edison to 80/07/16 lp
- --8007300498 "Engineering Criteria/Procedure for Review & Rusalution of As-Built Deviations," Revision 2 SNYDER.T K EDS Nuclear, Inc. 90/03/07 lipp
- R Periodic operating reports & related correspondence
- 8007150619 Forwards monthly operating repts for June 1980 KALIVIANAKIS,N Commonwealth Edison Co 80/07/01 1p
- --8007150625 Monthly operating repts for Juno 1980 HAFERA,T Commonwealth Edison Co 80/07/01 4pp
- 8 Reportable occurrences, LERs & related correspondence
- BD070B0162 Forwards LER B0-015/03L-0 KALIVIANAKIB,N Commonwealth Edison Co B0/06/26 1p
- --B0070B0172 LER B0-015/O3L-0 on B00604, leak found in HPCI steam supply line Caused by thermal cyrling during normal operation, weakening small section of fillet world HPCI sys taken out of syc. weld ground out & welded Sys returned to Syc XOPAC2, J Commonwealth Edison Co 80/06/26 ip
- 8007240112 Forwards LER 80-014/03L-0 KALIVIANAKIS, N Commonwealth Edison Cu 80/0//15 lp
- --8007240114 LER 80-014/03L-0 on 800623 during surveillance check on HPCl emergency oil pump, found oil leak on discharge line Caused by cracked threads on pipe nipgle Pipe nipple cut & rethreaded

 * Commonwealth Edison Co 80/07/22 2pp
- 8007230397 LER 79-021 has been cancelled COLLING, M Commonwealth Edison Co 80/07/22 ip
- V Operator Examinations
- B007020319 Responds to 800512 ltr requesting extension until Foll 1980 for completion of annual requalification exam due to addl work load Exam date may be delayed until B00930 CDLLING.P F Operator Licensing Branch 80/06/18 lp
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007300440 Forwards emergency plan, revised draft, Jul 1980 FAY, C W Wisconsin Electric Power Co 80/07/25 ip
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 89pp

- 800773060/ Preliminary contentions alteging possibility of steam generator tube repture during science LOGA (ontends that continued operation wisignificant tube degradation poses threat to public Certification of Sichen
- B007290070 Response in apposition to WI Environ Decado supplemental potition to intervine & contention. Intervet not afforted injury in fact test into met Volid contentions not submitted Hearing as of right must be defined (ortificate of Socienci CYR.K D. Kulemaking & Enforcement Division. 80/07/25, 15op.
- 8007300381 Response to WI Environ Decade Inc 800715 supplemental Filing Hearing is not warranted because intervener Failed to state intervener Failed to state one contention addressing issues of NRC 791130 order CHARNOFF.0 Wisconsin Electric Egwer Co CHARNOFF.0 Shaw. Pittenn. Potts & Trowbridge 80/07/28 15pp
- -8007300390 Motion to deny WJ Physican Docado Inc 79121/ request for hearing is NRC 791330 order Intervenur and entitled to hearing as matter of right Discretionary hearing unwarranted Curtificate of Syc & notice of appearance encl MURRAY, J P. CYR, K. LIEDERMAN, J. Rolemaking & Enforcement Division 80/02/11 18pp
- H General correspondence
- 8007290678 Urges NRC to conduct full probe of facility operation during 800730 prehearing conference Safety assurances should be given to community [pcal newspapers deficient in detailing concerns SPRING.C A . SPRING.W Affiliation Unknown 80797/14 lp
- B007290631 Requests that facility not be allowed to continue operating w/faulty & defective steam generator tubes Defective & deteriorated tubes should be replaced now Situation presents potential for another Thi 2 insident KRACHT.W El Affiliation Unknown 80/07/22 ip
- 80073103/3 Opposes util request for amend to moder on grounds that seriogeness of tube degradation problem demands complete review of 90 effective full power day insperesults by NRC before opporation permitted to resume FALK.K N Wisconsin's Environmental Decade 80.02/26 1p
- P. Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed lech Spec changes providing for redundancy in decay bent commonal capability in all modes of operation Model Forb Specs which would provide acceptable resolution and for guidance EISENHUT, D. G. Division of Licensing 80/06/11 67pp
- \$8007170500 Forwards evaluation of control rod golde thimble wear in facilities designed by Westinghouse Based on review inside is resolved CLARK.R A. Operating Reactors Branch's E0/07/01 4pp
- 8007230001 Requests submittal of application for amend to license consisting of Toch Spec changes % license conditions PMR Model Tech Specs & Model License conditions for IMI-P Lessons Learned Category A items, entil for guidance EISENHUT D O Division of Licenseing 80/07/02 69pp
- 8007150440 Requests extension of comment period on NUREO-05/7 until 800715,due to other work efforts Requests notification only if extension found unacceptable FAY.C W Wiscomsin Floctric Power Co 80/07/03 ip
- BOD/150682 Bubmits comments on NUREG-0654 Two objectionable items 15minute time frame proposed to complete public metification & propriety of min shift staffing requirements proposed in Table 8-1 FAY.C W Wisconsin Electric Power Co. 80/07/07 6pp
- 8007210034 Confirms achedule for 800708 meeting at site to discuss recent increase of personnel errors at facilities KEPPLER.J G Region 3. Chicago, Office of the Director 40/0//03
- 8007150453 Advises that plant will be taken off-line on 800725 for scheduled outage to conduct hydrostetic tosts to inservice inspired 90-day offective full power requirement FAY.C W. Historian Electric Power Co. 80/07/1/

- BOO7210408 Forwards revised forh Sper 15 3 4 for steam * power conversion *up & four 72-h test repts for auxiliary feed pump in response to NRC 800516 request for add1 info re auxiliary feedwater *up FAY.C W Wisconsin Flectory Power Co 80/07/08 4pp
- --8007250438 Revised Tork Spot 15 3 4 for steam & power conversion sys * Wisconsin Electric Power Co 80/07/08 3pp
- --B007210492 "Schenty-Two Hour Test of Turbine-Driven Auxiliary Feed Pump "
 - + Misconsin Electric Power (n. WMTP 11 21 RO 79/12/28 10pp
- --8007210460 "Seventy-lup Hour Test of Turbine-Driven Auxiliary Feed
 - Pump "

 # Wisconsin Electric Power Co. UMTP 11 21 RO. 79/12/07 10pp
- --8007210465 'Seventy-Two Hour Test of Electrically-Driven Auxiliary Feed Pomp' * Misconsin Electric Power to WMTP in 22 RO 77/12/26 10pp
- --8007210469 "Seventy-Two Hour Test of Electrically-Dilven Auxiliary Feed Pumps '
- * Historian Electric Power (o LIMTP 11 22 RO 79/12/23 10pp
- 6007240330 Advises of NRC reorganization on 900428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR NDVAN. T.M. Assistant Director for Operating Reactors 80/07/08
- BOO7250480 Discusses potential welding deficiencies in tanks fabricated by Graver Tank & Mfg Co Requests determination whether weldments in safety-related Graver tanks meet design specs & Fabrication requirements MOSELEY, N C Division of Reactor Operations Inspections 80/07/08
- G Inspectson reports. IE Dulletins % correspondence
- 8007020037 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required KEFFLER, J C Region 3. Chicago, Office of the Director 80/05/28 In
- 8007210409 Forwards IE Circular 80-13. "Orld Strop Dømage in Høstinghouse Fuel Assemblies " No written response required KEPPLER. J O Region 3. Chirago. Office of the Director 80/05/28
- 8007010080 Forwards IE Info Notice 80-23, "Lost of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29
- 8007010030 Responds to 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Respt Controls " Control of solehold valve will be modified such that total recirculation of control room air will continue after reset of contament isolation FAY,C W Wisconsin Electric Power Co 80/06/06 2pp
- 8007010062 Responds to 1E Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Cuntrol Sys (CVCS) Holdup Tanks "
 Hod will be implemented to prevent operation of holdup tank recirculation pump w/u positive prevente in tank FAY.C W Wiscussin Electric Power (a 80/06/06 Spp
- 8007160757 Responds to IE Bulletin 80-06 Review conducted of schematic drawings to determine actions resulting from engineered safety feature actuation signal 7 whether equipment returned to nonempropency mode upon removal of actuation signal FAY.C N Misconsin Electric Power Co 80/06/06 2pp
- 8007010043 Updater #00307 response to IE Bulletin 79-14. "Beismic Analysis for As-Built Safety-Related Piping Sys " Piping analysis completed for 84 NF B5 previously tabulated frawlings as of 800523 Status of revious entl FAY, C N Disconsin Flectric Power Co 80/06/09 5pp
- B007220226 Forwards SE Info Mutice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/06/10
- 8007160195 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study " No specific action or response required KEPPLER. J O Region J. Chicago, Office of the Director 80/06/11

- 8007030030 Forwards IE Bulletin 80~15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power "Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/18
- B007020949 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written rusponse ruquired KEPPLER J G Region 3. Chicago. Office of the Director 80/06/20
- REPPLER. J G Region 3, Chicago, Office of the Director 90/06/20 ip
- 9007170324 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director BG/05/24
- B007230346 Forwards IE Bulletin B0-15. "Potential Misapplication of Resemburt inc Models 1151 & 1192 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular B0-16 also encl No written response required KEPPLER, J G Region 3. Chicago, Office of the Director B0/06/27
- 8007310304 Forwards IE Insp Repts 50-266/80-11 & 50-301/80-11 on BOO616-17 No noncompliance noted FIORCLLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Deanch 80/06/30 2pp
- E007170526 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " All containment welds either have leak chase channel or penetration has closure cap or expansion bellows welded outside containment FAY, C W Wisconsin Electric Pawor Co E0/07/03 Opp
- 9007220071 Submits reply to IE Bulletin 80-10 re contamination of nonradinactive sys & potential for releases Completion of bulletin review not anticipated until 800831 FAY.C W Wisconsin Electric Power Co 80/07/07 2pp
- B007240342 Responds to IE Bulletin B0-15 re power supply to emergency notification sys telephones Charger supplied by telephone company is connected to safeguards Bus 2842 Phones verified aperational wiless of ac to charger FAY.C W Wisconsin Electric Powor Co G0/07/08 2pp
- 8007300456 Forwards drawings for revised pump & valve inservice insp & testing program.replacing 770520 program Program & drawings available in Central Files only FAV.C W Misconsin Electric Power Co 80/07/25 ip
- R Persodic operating reports & related correspondence
- 8007150610 Forwards monthly operating repts for June 1980 FAY: C W Wisconsin Electric Power Co 80/07/10 is
- --8007150618 Monthly operating repts for June 1980 FAY.C W Wisconsin Electric Power Co 80/07/08 App
- 8 Reportable occurrences, LFRs & related correspondence
- 8007010409 Forwards LER BO-007/017-0
 FAY.C W Wisconsin Electric Power Co 80/06/25 ip
- ---B007010420 LER 80-007/01T-0 on 800611, blue instrument bus 1Y02 was de-energised, resulting in de-energisation of 3 containment pressure channels Caused by personnel error Power restored & instrumentation returned to normal FAY, C W Wisconsin Electric Power Co 80/06/25 2pp
- 9007110333 Forwards LER 60-008/03L-0 FAY.C W Wisconsin Electric Power Co 80/07/03 ip
- ~-8007ii0340 LER GO-008/09L-D on 800606.during normal operation, testing revealed that relay 1-247/AN2X in train B would not drop out to initiate undervoltage trup function Cause not determined Relay replaced & tested satisfactorily FAY.C W Wisconsin Electric Power Co 80/07/03 2pp

V Operator Examinations

- 8007240085 Responds to 800604 request for info re requirement that operator & senior operator linense applicants spend 3 months on-shift in training Variance to requirement cannot be permitted NDVAK.T M Assistant Director for Operating Reactors BO/07/08 380
- DOCKET 50-267 FORT SI VRAIN NUCLEAR GENERATING STATICH
 F Security, medical, emorgency & fire protection plans
- 8007180194 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re-embrgency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- B007180150 Requests util participation in study re people-related problems in nuclear safeguards Portion of study involves collection of data on licensee security forces & practices NRC to contact security mgt to schedule visit EISENHUT, D © Division of Licensing 80/07/09 lp

9 Adjudicatory correspondence

- B007310243 Forwards Commission B00327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re firs protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 89cp
- J Insurance & indemnity information
- 8007290629 Forwards Endorsement 32 to ANI Policy NF-192 & Endorsement 45 to MAELU Policy NF-69
 OASCHLER,J A Public Service Co of Colorado 80/07/22 3pp
- P Operating license stage documents & correspondence
- BOO7020251 Requests invoice for fee for shipping route approval PSC of CO 770822 application MILLER.W D licenso Fee Management Branch BO/06/06 ip
- B007090333 Submits info re thorium purification facility Proposes that processing take place in separate bldg adjacent to facility site & outlines purification process Requests response to ltr by B00800!

 BMART, F E Public Service Co of Colorado 60/07/02 App
- BD07280493 Forwords GA Co B00620 memo re inside/out oxidation of graphite in relation to reactor Phenomenon will not occur at facility Oxidation was not observed in profiles generated in lab under representative reactor conditions BNART.F E Public Service Co of Colorado B0/07/18 3pp
- O Inspection reports, IE Bulletins & correspondence
- B007020309 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe" Piping specs do not allow use of spamed stainless steel piping in any sys

 BHART, F E Public Service Co of Colorado 80/04/23 lp
- 8007020272 Forwards IE Info Notice 80-22, "Dreakdowns in Contamination Control Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 8007010044 Forwards IE Info Notice 80-23, "Loss of Siction to Emergency Feedwater Pumps" No written response required 8EYFRIT.X V Region 4, Dallas, Office of the Director 80/05/29
- B007190083 Forwards JE Insp Rept 50-247/B0-10 on 800501-31 & notice of violation MADBEN, G L Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --B0071800BB Natice of violation from insp on B00501-31 * Region 4. Dallas, Office of the Director B0/06/06 ip

- --B007150091 IE lasp Rept 50-267.6(i 10 on 800501-4) Nentumpliance noted failure to meet fire watch & citinguisher requirements? failure to obtain procedure change approval HESTERIAN I F , DICKERSON, I W . COULTINS, R E . Region 4, Ballas, Office of the Director B0.06/06 | Lapp
- BOO7220126 Forwards IV Info Notice BU-26, "Evaluation of Contractor GA Programs" No written response sequired SEYFRITER V Acgion 4, Dalla Office of the Director 80/06/10 to
- B007100223 Forwards IF Insp Rept 50-267/80-11 on 800527-28 No noncompliance noted MELLY, J A F Region 1, Dalla Office of the Director 80/06/17 Roo
- --B007100225 IF Insp Rept %0-767,8(r-1) on 800527-78 No noncompliance noted Major areas inspected physical protection of irradiated fuel in transit Botail's withhold (ref 10CFR2 790)
 CALDWELL, R A . KELLY, J A F Region 4, Dallow. Office of the Director B0706/16 ip
- 8007010231 Ack receipt of 800607 ltr informing NRC of steps taken to correct violations noted in IF Imap Rept 50-267/80-08
 MADSEN.G L. Region 4. Dallas. Office of the Director 80/06/20
- --8007010274 Responds to NRC 800506 Iti is violations noted in [E lisp Rept 50-267/RC OB Corrective actions maint of proper diesel generator day tunk level was re-emphasized to all operators [EE.O R Public Service to of Colorado 80/06/02 2pp
- 8007240094 Forwards IE Circular 8/1-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation (unidown " No written response required SEYFRIT.K V Region 4, Dallas, Uffice of the Director 80/06/20
- 8007280645 Forwards reactor auxiliarly conting water tys inservice insp & testing requirements analysis includes draft Revision 3 to Tech Spec surveillance requirements for reactor auxiliary conting water systattackment to rept CF-46-0004 FULLER.F.K. Public Service (o. of Culorado 80/07/16 22pp
- ---BOO728()652 "Inservice Insp % firsting Program Surveyllance Requirements Review for Ruactor Auxiliary Cooling Water Sys " * Public Service Co. of Columnato EE-46-0004 80/06/24 45pp
- R Periodic operating reports to related correspondence
- BOO7010344 Forwards monthly operating lept for May 1980
 WAREMODURG, D Public Service (co. of Colorado 80/06/23 299
- --8007010346 Monthly Operating Rept 77 for May 1980 CAHMed W Public Service to of Colorado 00/06/92 9pp
- 6007080406 Forwards munthly operating rept for June 1780 WAREMDOURG.D Public Service Co. of Colorado 80/07/01 ip
- --8007080409 Monthly operating sept for Jone 1980 GARM J W Public Service in of Colorado 80/07/01 Spp
- S Reportable occurrences. LLHs & related correspondence
- BOO42402B1 PND-1V-80-12 on BOO311 apparent failure occurred on circulating water cooling tower distribution header Reactor & turbine manually tripped while at 36% power Repair time unknown MESTERMAN, T. F. MADSEN, C.L. Region 4, Dallas, Office of the Director 80/03/11 by
- BOO70B0254 Forwards LER BO-028/OUL-0 WAREMBOURG, D. Public Service to of Culorada BO/05/19 5pp
- --B0070R0262 LER 80-02R/03L 0 on R005/0 duing circulating water sys chlorination, total chlorine residual exceeded limit Caused by chlorinate demand decrease Politowing steady increase Chlorination & bloodown reduced QAMM, JW Public Service Co. of culorado 80/06/19 ip
- 8007080268 Forwards LFR 80-025/03L-0
 WAREMBOURG, D. Public Service (o. of Cuiorado 80/06/19 Sap

- 80070802"5 LER 80-025/03L-U on 800523, during 800523-30, total primary toolant oxidant, were greater than 10 ppm w/average core outlet temp above 1.200 F on 511 occasions Caused by moisture increase & carbon monoxide & docide combination GAMM.J W Public Service Co of Colorado 60/06/19 1p
- 07080422 forwards LER 80-026/(3L-0 WAREMBOURG, D. Puhl): Service Co. of Colorado 80/06/19 6pp

ŧ

- B0070B04#5 IFR B0-026/OJL-O on B00524 during testing, helium circulator seal malfunction pressure differential switch units tripped outside fech Spor limits Caused by dirt accumulation in electrical switches Trip points readjusted OAHM, J W Public Service Co of Colorado B0/06/19 ip
- 97010476 Forwards LER 80-020/03X-1 #AREMBOURG.D Public Service Co of Calorado 80/06/23 5pp
- 007010506 FER 80-020/03X-1 on 80041B during testing two of 12 helium circulator seal malfunction pressure differential switch units tripped outside Fech Sper limits Caused by dirt accumulation in electrical switch Switches readjusted GAHM. J W Public Service Co of Colorado 80/06/23 ip
- 77080210 Forwards LER 60~0≥7/03L=0 |AREHBOURG.D Public Service Co of Colorado 80/07/01 5pp
- 0070B0215 LER B0-027/O3L-0 on B03603 to 11, three separate instances of reactor operation took place w/inoperable Class 1 shock suppressors Caused by retated reservoir. low oil level due to cracked fitting & piston rod seal leak GANN.J W Public Service Co of Colorado 80/07/01 1p
- 7080289 Forwards LER BD-029/03L-0
 AREHDOURG, D. Public Service Co. of Cotorado. 80/07/01 4pp
- 007080304 LER 80-029/03L-0 on 800602, at approx 40% power, reactor bldg pressure chuld not be maintained subatmospheric Caused by Prozen air line to reactor bldg louver pneumatic actuator due to liquid mitrogen proximity

 QANM.J W Public Bervice Co of Colorado 80/07/01 1p
- 7100173 Forwards LER 80-030/03L-0 AREMBOURG,D Public Service Co of Colorado 80/07/02 App
- 107100176 LER NO-030/03L-O on 800604, white performing leakage test, discovered that loop 2 steam generator penetration leakage exceeded allowable limit Cause unknown Temporary relief from allowable limit received from NRC DAMM.J W Public Service Co of Colorado 80/07/02 lp
- '150690 LER 79-063 has been cancelled JLLING.M Public Service Co of Colorado 80/07/14 lp
- 230543 Forwards LER 80-032/03L-0 REMBBOURG.D Public Service Co of Colorado 80/07/15 5pp
- JO/230595 LER 80-032/03L-0 on 800617. w/plant operating at approx 68% thermal power & 19384.PV-21243 was not controlling at appropriate setypint Caused by defective Hasoneilan PV Devcon applied to seal ring dasket stopped valve leakage OAIM, J H Public Service Co of Colorado 80/07/15 1p
- 230548 Forwards LER 60-034/07L-0 REMBOURD,D Public Service Co. of Culorado 80/07/15 5pp
- 07230554 IER 80-034/03L-0 on 800619, two helium circulator seal malfunction pressure differential switches tripped outside limits Caused by dirt accumulation in electrical switches Buttches readjusted Settings to be checked monthly GARN, J W Public Service Co of Colorado 80/07/15 In
- 230534 Forwards LER 80-033/03L-0 REMDOURG.D Public Service Co of Colorado 80/07/18 5pp
- O7230539 LER 80-033/03L O on 800620. w/reactor operating at powerreactor despoint exceeded limits Caused by moisture ingress accurring during IA circulator buffer-mid-buffer upset & circulator trip OAHM, J W Public Service Co of Colorado 80/07/18 ip

- DDCKET 50-268 MIDWEST FUEL RFCOVERY PLANT

 P Operating license stage documents & correspondence
- 8007020417 Forwards LC Rouse 740115 ltr to GE re OL schedule, per 800422 telcon CLARK.T A Advanced Fuel & Spent Fuel Licensing Branch 80/04/23 ip
- --8007020423 Discusses schedule for preoperational testing & licensing OL could be issued 740315 One month is needed to review preoperational test info ROUSE.L.C. Atomic Energy Commission, Directorate of Licensing 74/01/15
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 6007010205 Forwards security plan re in-transit requirements for SNM of low strategic significance Plan withheld (ref 10CFR2 790) PARKER, N D Duke Power Co 80/06/24 lp
- 8007230070 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mpt personnel at facilities ETSENRAT, D.Q. Division of Licensing 80/07/11 2pp
- G Adjudicatory correspondence
- 8007140461 Statement of Roard of Commissioners' position in apposition to raduaste transportation through Gaston County,NC Urges transportation via Interstates 77 & 85 Encourages expending onergy & money for recycling W/Correspondence 9 Gaston County,NC 80/04/28 6ipp
- --E007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not uppose shipment if adequate safeguards are provided GABYON. H B Gaston County. NC 80/04/25 2pp
- --B007140488 Forwards position of Gaston County Board of Commissioners. NC.opposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNE:C A Gaston County.NC 80/04/15 ip
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D O Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- BOD6240237 Responds to technical assistance request for proposed Tech Spec changes for B&W operating plants Forwards requirements for add1 info ISRAEL.9 L TMI-2 Bulletins & Orders 79/08/29 13pp
- 8007240209 Forwards B&W litensees' responses to 790907 request for review of schedulo for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115 CAPRAIR A TMI-2 Bulletins & Orders 79/10/24 ip
- 8007140397 Refers to 800701 ltr requesting info re insp of fuel assembly hold-down springs Reviewed concern & documented results in 800506 ltr forwarding RO 30-269/80-15 & safety evaluation No further info required PARKER. W O Dake Power Co 80/06/08 1p
- E007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution and for guidance EISENHUT.D & Division of Licensing 80/06/11 62pp
- B007160429 Forwards Amends B3,83 & 80 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/06/12 2pp

- --B007160434 Amends 83.83 & 80 to Licenses DPR-38.DPR-47 % DPR-55, respectively, revising Tech Specs to support operation of Unit 2 at Full rated power during Cycle 5 REID.R W Operating Reactors Branch 4 80/06/12 23pp
- --B007160445 Safety evaluation supporting Amends B3.83 & B0 to Licenses DPR-3B, DPR-47 & DPR-55, respectively

 * Office of Nuclear Reactor Regulation, Director 60/06/12

1

- ---B007160453 Notice of issuance & availability of Amends 83.83 & 80 to Licenses DPR-38.DPR-47 & DPR-55.respectively REID.R W Operating Reactors Oranch 4 80/06/12 2pp
- 8007020314 Notifies of NRC conclusion that util did not provide sufficient info to justify 780608 proposed increase in Tech Spec steam generator tube leak rate limit Evaluation NDVAK.T Assistant Director for Operating Reactors 80/06/16 3pp
- BOD7010360 Advises that installation of addl spent fuel coding train will be completed in Apr 1981 No more than 342 assemblies will be stored in pool until completion of installation or M/O NIC approval
 PARKER, W O Duke Power Co 60/06/24 ip
- 8007070035 Forwards safety evaluation re postulated fuel handling accident inside containment REID.R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Safety evaluation re postulated fuel handling actident inside containment * Operating Reactors Branch 4 80/06/24 1p
- 8007020575 Summarizes actions undertaken by util re inadequate core cooling NRC review of previously submitted operator guidelines should be completed prior to util committing to install new instrumentation PARKER.W O Duke Power Co 80/06/27 2pp
- 8007080223 Advises that response to NUREG-0667 is in final review & will be submitted by 800723 PARKER, H D Duke Power Co 80/07/01 1p
- 800709027i Forwards safety evoluation & environ appraisal for proposed Tech Boer revision re reracking of spent fuel pool.which will be submitted later Class I & IV amend fees encl PARKER.W D Duke Power Co 80/07/01 3pp
- --8007090274 "Units i & 2 Spent Fuel Pool Polson Relack Licensing Submittel " Duke Power Co 60/07/3i 5ipp
- BOD7210004 Forwards questions re fuel assembly hoiddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days
 NDVAN/T M Assistant Director for Operating Reactors BO/07/01
- 800725000) Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- 8007180104 Notifies that 800317 request for route approval to cover spent fuel shipments to B&W Lynchburg Research Ctr is subj to license fee Review of request was completed on 800414 MILLER, W O License Fee Management Branch 80/07/03 lp
- BOO7230052 Responds to util BOO317 request for route approval covering shipments of spent fuel to B&M Lynchburg Research Ctr Review of licensee route approval requests subj to license fee schedule in 10CFR170 MILLER,W O License Fee Munagement Branch 80/07/03 tp
- 8007110294 Forwards application to amond Tech Specs to incorporate test frequency requirements of 10CFR30.App J
 PARKER.W O Duke Power Co 80/07/07 2pp
- --8007110331 Application to amend Tech Spec 4 4 1 2 5 incorporating test frequency requirements of 1007830.App J Existing Tech Spec unacceptable for extended cycle lengths for which current & future cycles are/will be discensed # Duke Power Co 80/07/07 2pp

- B00723070B Provides info to new ord titles positions is assignments of personnel resulting from B004/8 realgablehood of Ofc of Nuclear Reactor Regulation NUCVAK/T N Assistant Director for Operating Reactors 80/07/10 2pp
- 8007150575 Forwards "Generic Startup Physics Test Program, Jul 1980 " Rept supersedes in cutivety (ept) submitted 800604 v [1 PARKER, W D Duke Power Co 90/07/11 lp
- --B007150583 "Generic Startup Fhysics lest Program, Jul 1980 " Rept supersedes in entirety previously submitted repts forwarded by QOOAG4-11 ltrs * Duke Power Co | BO7077/f1 | 14pp
- 8007220477 Forwards "Unit 1. Lycle & Startup Testing Summary " PARKER, W.O. Duke Power Co. 80/0//11 1p
- --8007220483 "Unit 1.Cycle & Startup Testing Summary "
 * Duke Power Co 80/07 31 13pp
- 8007280437 Forwards proposed levision to lech Specs & amend to OL Proposal clarifies insp requirements after space & among Proposal clarifies insp requirements after primary to secondary leak specified in Erch Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKERING Duke Power Co HO/O7/15 3pp
- --8007280438 Proposed Tech Spec revision Page 4 17-3 clarifying insp requirements after primary to secondary leak * Duke Power Co = 80/07/15, 2pp
- 8007310551 Forwards NURED-1368 & NUREG 1769 detailing development of checklist for evaluating maint test & calibe procedures used in nuclear plants Ack while cooperation in study W/o encls encis LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch BO/07/15 1p
- 8007280944 Forwards response to recommendations in NUREG-0667. "Transient Response of BAW Designed Reactors" Dased on review no action is necessary for majority of ecommendations ARKER, W.O. Duke Power Co. 80/07/23 70pp
- E007310379 Application to amend licenses DPR-38 & DPR-47, changing Tech Specs to reflect assumptions used in util 800701 itr re spent fuel pool expension PARKER, N O Duke Power Co 80/07/25 3pp
- ---B00731038i Proposed Tech Specs 38 13 a.3 8 15 & 5 4 2 i to pormit expansion of spent fuel pool storage capacity by recacking spent fuel pool w/poison racks * Duke Power Cn BD/07/29 App
- --8007310382 Revised pages to "Units 1 t 2 Spent Feel Pool Poison Rerack Licensing Submittal" * Duke Power Co 80/0//25 5pp
- O Inspection reports, IE Bulletins & correspondence
- 8007240122 Forwards & Info Notice 80-20. "Loss of Decay Heat Removal Capability at Dayis-Busse Unit I White in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/05/08 200
- B007100144 Forwards IE 105p Repts 50-269/80-14.50-270/80-09 & 50-287/80-09 on 800428-0501 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/27 2pp
- --8007100151 IE lose Repts 50-249/80-14.50-770/80-09 5 50-287/80-09 an 800428-0501 Nu noncompliance noted Major areas inspected CON.ON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Dranch MillER.W H Region 2. Atlanta, Office of the Director 80/03/23 10pp
- 8007020204 Forwards JE Info Notice 80-22 "Broaddown: In Contamination Control Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Uffice of the Director 80/05/28
- BOO7210449 Forwards IE Circular 80 13. "Arid Strap Damage in Westinghouse Fuel Assemblies " Ne written response required O'REILLY, J.P. Region 2. Atlanta, Defice of the Director B0/05/28

- 8007010213 forwards IE Into Notice 80-25. Loss of Suction to Emergency Foedwater Pumps ' No written assemble required D'REILLY J & Rugion 2. Allanta, Office of the Director 80/09/29 to
- B007220048 Forwards IE Info Notice 80-26, 'Evaluation of Contractor GA Programs ' No written response required O'REILLY, I P Region 2, Atlanta, Office of the Director B0/06/10 2nd
- B007010065 Forwards update of info to 791026.1106.1207 & 890324 ltrs in response to 1E Bullotin 79-14.Items よん 3 PAHKER.U D Duke Power Co 80/06/11 app
- 3007160255 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action of response
- o'aguired
 O'aguar 2, Atlanta Office of the Director 80/06/18
- 3007020763 Forwards It Bulletin HO-15, 'Possible Loss of Emergency Notification Sys (ENS) Wiches of Offsite Power " Written
- response required
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- 1007020499 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Coping & Natural carculation Cooldown " No written response required
- O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/20
- 007150015 Ack receipt of EE Insp Repts 50~269760-18.50~270780-13 & 50~287780-12 on 800513-15 No proprietary info PARKER.W D Duke Power Co 80706723 ip
- -BOO7150019 Forwards IE Insp Repts 50-249/80-18.30-270/80-13 & 50-287/80-12 on 600913-15 No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BO/05/29 2pp
- 8007130021 IE insp Repts 30-269/80-18,50-270/80-13 & 50-287/80-i2 on 800913-13 No noncompliance noted Major areas inspected structural concrete for standby shutdown facility HARRIS.J R Region 2 Atlanta. Office of the Director CONLON,T E Region 2 Atlanta. Reactor Construction & Engineering Support Granch 80/05/20 3pp
- 307170104 Forwards IE Circular 80-14, "Redicactive Contamination of Plant Dominoralized Water Sus & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24 to
- 107160533 Responds to JE Bulietin 79-03A. "Longitudinal Wald Defects in ASME 8A-312. Type 304 Stainlass Steel Pipe " No Type 300 piping in use for pressure piping Future use of piping will be reviewed PARKER. H O Duže Power Co 80/06/24 ip
- 107220192 Advises that hanger they required by IE Bulletin 79-13 was not addressed in response to bulletin Hangers visually inspected as part of response to IE Bulletins 79-02 & 79-14 PARKER, H (I) Duke Power Co. 80/06/27 ip
- 07230235 forwards IC Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Carrulan 80-16 also nor! No written response required 1'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 07280068 Confirms receipt of NRC 800617 ltr transmitting IE Insp Rept 50-269780-22 Concurs w/NRC decision that info contained in **ept is security-related % whould not be placed in PDR PARKER-W O Dute Power Co 80/Q6/30 ip
- 07220245 Forwards response to 1E Bulletin 60-08 Approx 50 senetrations concerned Weid defects classified as inclusion he repaired for cracking Dasign meets all requirements of MSKE PARKER, H. O. Dute Power Co. 80/07/01 App
- 17140a63 Forwards 800/04 Revision 2 to response to 1E Bulletin '9-01B, "Environ Qualification of Class IE Equipment" eplaces previous submittal b 800519 revision entirely neludes corrections of minor orrers HICG, A C Duke Power Co 80/07/07 36pp

- 8007250166 Forwards response to Items 1.2a % 3 of 1E Bulletin 80-11. "Masonry Wall Design " Lists all masonry walls which are in proximity to or have attachments from safety-related piping or equipment PARKER.W U Dute Power Co 80/07/07 21pp
- S Reportable occurrences, LERs & related correspondence
- 8007070319 Forwards LER 80-018/03L-0 PARKER, N O Duke Power Co 80/06/30 3pp
- --8007070323 LCR 80-018/03L-0 on 800601.high pressure svc water pump II declared inoperable due to motor cooler tube leak. Caused by crosion & corrosion resulting from constant flow of lake water Leaking tubes soldered & cooler pressurized PHILPOTT.F T Duke Pawer Co 80/06/30 1p
- 8007110360 Forwards LER 80-020/01T-0 PARKER. 0 0 Duke Power Co 80/07/03 3pp
- --8007/10362 LER 80-020/01T-0 on 800619.at 74% power.backup 125-volt de power to instrumentation & control power sys removed from syc to investigate ground aiarm isolating transfer diodes not reconnected within Tech Spec 24-h limit PHILPDTT,FT Duke Power Co 80/07/03 tp
- 8007210417 Forwards LER 80~021/03L-0 PARKER, W D Duke Power Co 80/07/11 4pp
- --B007210A21 LER B0-02i/O3L-0 on B00612.8 high pressure injection makeup liner found excessively hot Apparently caused by IMP-152 check valve not seating properly, allowing water to flow into IBI cold leg PHILPOTT, FT Duke Power Co 80/07/11 ip
- 8007210459 Forwards LER 80-017/03L-0 PARKER, W D Duke Power Co 80/07/11 3pp
- --B007210470 LER 80-017/031-0 on B00529.at 73% full power. CDAST pump was removed from svc for preventive maint constituting operation in degraded mode Procedure was in violation of Tech Specs Tech Specs or procedure changes under evaluation PHILPDIT, F T Duke Power Co 80/07/i1 ip
- 8007230239 Part 21 rept re cracked steam generator manway stude
 Batisfactory operating experience forms constitute
 reasonable basis for continued operation while
 investigations proceed
 TAYLOR. J H Babcock & Wiicox Co 80/07/11 5pp
- 8007220563 RO on 800709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged from upper sump of safe shutdown facility const Const personnel advised of discharge limits PARKER, W O Duke Power Co 80/07/16 2pp
- 8007220424 Forwards LER 80-019/03L-0 PARKER,W 0 Duke Power Co 80/07/17 ip
- ---B007220427 LER 80--019/03L-0 on 8006iB.concentrated boric acid storage tank pump found inoperable according to Tech Bpmc requirement Caused by failed vacuum compensator within yalva pump Vaive diaphragm & motor replaced PHILPOTT.F 7 Duke Power Co 80/07/17 2pp
- DUCKET 50-270 DODNEE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8007010205 Forwards security plan re in-transit requirements for SNM of low strategic significance Plan withheld (ref 10CFR2 790) PARKER.W O Duke Power Co 80/06/74 ip
- 8007230090 Requests participation in study of people-related problems in nuclear safeguords Study involves collection of data on licensee security forces & practices NRC wishes to interview security may personnel at facilities EISENHUT, D G Division of Licensing 80/07/11 2pp
- O Adjudicatory correspondence
- 8007140461 Statement of Brard of Commissioners' position in opposition to radwaste transportation through Gaston County, NC Urges transportation via Interstates 77 & 85 Encourages expending energy & money for recycling M/correspondence * 9aston County, NC 80/04/28 6lpp

- --8007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON, H B Gaston County NC 80/04/25 2pp
- ---8007140488 Furwards position of Gaston County Board of Commissioners. NC oppusing spent nuclear fuel shipment through county % two proposed alternate routes W/o encl RHYNE, C A Gaston County, NC 80/04/15 1p
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 publicum for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protection for electrical cables
 E16ENNUT.D C Division of Licensing B0/06/2% 89pp
- P Operating license stage documents & correspondence
- B007240208 Forwards B&W licensees' responses to 790907 request for review of schedule for installing safety-grade anticipatory reactor trip for loss of feedwater 7, turbine trip Review should be completed by 791115
 CAPRA
- BO07140397 Refers to B00701 ltr requesting info re insp of fuel assembly hold-down springs Reviewed concern & documented results in B00604 ltr forwarding RD 50-269/80-17 & safety evaluation No further info required PARKER.W O Duke Power Co B0/06/08 1p
- GOO7R30099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D G Division of licensing BD/06/11 62pp
- 8007160429 Forwards Amends B3.83 % B0 to Licenses DPR-3B.DPR-47 % DPR-55, respectively, safety evaluation % notice of issuance % availability REID.R W Dperating Reacture Branch 4 B0/06/12 2pp
- --B007i&0434 Amends B3.83 & 80 to Licenses DPR-38, DPR-47 & DPR-35, respectively, revising Tech Specs to support operation of Unit 2 at full rated power during Cycle 5 REID,R W Operating Reactors Dranch 4 80/06/12 23pp
- --8007160445 Bafety evaluation supporting Amends 87,83 & 80 to Licenses DPR-3B, DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 80/06/12
- 8007010340 Advises that installation of addl spent fuel coding train will be completed in Apr 1981 No more than 342 assemblies will be stored in pool until completion of installation or w/o NRC approval PARKER, W II Duke Power Co 80/06/24 1p
- B007070035 Forwards safety evaluation re postulated fuel handling accident inside containment REID,R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Bafety evaluation re postulated fuel handling accident inside containment * Operating Reactors Branch 4 80/06/24 1p
- BOD7020575 Summarizes actions undertaken by utll re inadequate core cooling NRC review of previously submitted operator guidelines should be completed prior to util committing to install new instrumentation
 PARKER, W O Duke Power Co 80/06/27 2pp
- 8007080223 Advises that response to NUREG-0667 is in final review & will be submitted by 800723 PARKER, W () Duke Power Co 80/07/01 ip
- 8007070271 Forwards safety evaluation & environ appraisal for proposed Tech Spec revision re reracking of spent fuel pool, which will be submitted later Class I & IV amend fees encl PARKER.W O Duke Power Co 80/07/01 3pp

- 8007210004 Firmards questions refuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days. NOVAK, T.M. Assistant Director for Operating Reactors. 80/07/01 4pp.
- B007290001 Requests submittal of application for amend to license consisting of Tech Spec changes illerise conditions PWR Model Tech Specs t Model License conditions for TMI-P Lessons Learned Lategory A stome end for guidance EISENHUT, D.G. Division of Licensing B0/07/02 G9pp
- B007170647 Forwards Reactor bys Branch evaluation of facility fuel load for Cycle 5 operation & associated fech bypes Review considered effects of normal operation anticipated transions to be postulated accident 6/0 encl
 SPEIS.T P Reactor Systems Branch 80/07/03 ip
- ~-800/170456 Forward: Reactor Suferty Branch evaluation of facility fuel load for Cycle 5 operation & associated fech Specs Util has not submitted acceptable startup text program as of BOO430 U/o encl
 CMECK.P 5 Assistant Director for Plant Systems BO/46/30 1p
- 8007110294 Forwards application to amend Toch Specs to secarporate test frequency requirements of 10CFR50 App J
 PARKER, W G Duke Power Co #10/07/67 2pp
- --8007110391 Application to amend Tech Spec 4 4 1 2 5 incorporating test frequency requirements of 1006ABO. App J Existing Tech Spec unacceptuable for extended cycle lengths for which current & futon cycles acc/will be licensed * Duke Power Co 80/07/07 Ppp
- 8007230708 Provides into renew of titles, positions & assignments of personnel tesulting from GOIDFR reorganization of Ofc of Nuclear Reactor Regulation NDVAK.T M Assistant Director for Operating Reactors 80/07/10
- 8007150575 Forwards "Generic Startup Physics Test Pingram. Jul 1980 "Rept supersudes in entirety repts submitted 800604 % 11 PARKER. W. D. Duke Power Co. 80707/11 ip
- --800/150583 "General Startup Physics Test Program, Jul 1980 " Rept supersides in entircty previously submatted repts forwarded by 800604-til Itrs P Duke Puwer Co 80/07/31 14pp
- B007280437 Forwards proposed revision to Tech Specs & amend to OL Proposal clarifies lasp requirements after primary to secondary leak specified in Tech Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKER.W O Duke Power to (10/07/15 Spp
- --B007280438 Proposed Tech Spot revision Page 4 1/-3 clarifying insprequirements after permany to secondary look
 # Duke Power Cn B0/07/15 2pp
- 8007310551 Forwards NUMEG-1360 & NUMEG-1769 detailing development of checklist for evaluating animal test & calibr procedures used in nuclear plants Ack will couperation in study W/o encis
 LEWIS, R.C. Region P. Atlanta Reactor Operations Nuclear Support Branch 60/07/15 tp
- 8007210425 Applacation for amend to OI revising (ech Spec 3 3 i c allowing continued operation of Unit 2 at full rated power, while maint continues on $i \Theta I$ pump until 800718 PARKER, W O Duke Power Ca 80/07/16 App
- ~~9007210426 Proposed revision to Tech Spec 3.3.1 c allowing continued operation of this 2 of Full rated power while maint continues on HP1 pump until H0071R

 # Duke Power to H0/07/16 tp
- B007220061 Advases of error in tispensis for Site Specific Question I parts B & C. submitted in B00a16 linin response to questions re low turbine diss cracking (oriect responses and PARKER: M O Dute Power Co. 97/07/17 2pp
- B007280119 Conforms 800716 toldon to temporating emend Tech Spec 3 3 1 c(2)(b) by adding HPT Pump Riper 800716 request Amend package including safety evaluation to notice will be forwarded shortly NOVAKITM Assistant Director for Operating Reactors 80/07/17

- 800728042/ Forwards proposed lech Spec 3 ! 2 revision, changing pressure temp limits Class I ? It! iscense amend fee roct PARKER, W O Duke Power Co 80,07/22 3pp
- --8007280430 Proposed Tech Spec 3 1 2-10-15king prossure temp limits * Dute Power Co 80/07/22 7pp
- 8007280544 Forwards response to recommendations on NUREC-0667, "Transient Response of DAW Designed Reacture" " Dased on review no action is necessary for majority of ecommendations Duke Power to 80/07/23 70pp
- 8007310379 Application to amend Licenses DPR-08 in DPR-47 changing Tech Specs to reflect assumptions used in util 800701 ltr re spent fuel pool expansion PARKER. W O Duke Power Co 80/07/25 3pp
- --8007310381 Proposed Tech Specs 3 8 13 a.3 B 15 & 5 4 2 1 to permit expansion of spent fuel pool storage capacity by reracking spent fuel pool u/poison racks
 - Duke Power Co 80/07/25 App
- --B007310382 Revised pages to "Units I & 2 Spont Fuel Pool Poison Rerack Licensing Submittel" * Duke Power (a B0/07/25 Spp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice H0-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit I While in Refueling Mode" No response required U-REILLY.J P Region 2. Atlanta, Office of the Director 80/05/08
- B007100144 Forwards IE lnsp Repts 50-269/80-14 '0-270/80-09 & 50-287/80-09 on D00428-0501 No noncompliance moted MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/27 2pp
- --800710015: 1E Insp Repts 50-269/80-14.50-270/80-09 & 50-287/80-09 on 800428-0501 No noncompliance noted Major assess inspected fire protection/prevention CONLOW.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch MILLER, H H Region 2, Atlanta, Office of the Director 80/05/23 10pp
- 8007020204 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required G'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28
- 8007210449 Forwards IE Circular 80-13. "Grid Stiap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY. J P Region 2. Atlanta, Office of the Director E 80/05/28
- 800701021.) Forwards IE Info Notice 80-23. "Tosh of Suction to Emergency Foedwater Pumps." No writton response require!

 O'REILLY. J. P. Region 2. Atlanta, Office of the Director. 80/05/29
- 8007220048 Forwards 1E Info Natice 80-26. "Evaluation of Contractor QA Programs " Na written response required D'REILLY, J.P. Region & Atlanta, Office of the Director 80/06/10
- 8007010065 Forwards update of info to 791026,1106,1207 & 800124 ltrs in response to IE Bulletin 79-14,1tems 2 & 3 PARKER, W O Duke Power Co 80/06/11 App
- 8007160255 Forwards IC Info Notice 80-27, "Degradation of Reactor Coplant Pump Stude " No specific action or response D'REILLY, J.P. Region P. Atlanta, Office of the Director BO/06/11
- 8007020763 Forwards IE Bulletin 80-13, "Fossible Loss of Emergency Notification bys (ENS) W/Loss of Officite Power " Written response required O'REJLLY. J P Region 2, Atlanta, Office of the Director 60/06. Region 2, Atlanta, Office of the Director 80/06/18
- 3007100139 Responds to IE Bulletin 79 13. "Cracking in Feedwater Sys Piping "Radiographic examinations required by Item 2 completed & unacceptable indications found not associated w/concern of bulletin Indications purder review PARKER.W O Duke Power Cv 80/06/19 Spp

- 6007180349 Responds to Item 2 in IE Dulletin 79-13 All weld joints considered acceptable for continued svc Util intends to restent Unit 2 Considers that NRC concurs w/position & that no further insps are expected PARKER. U D Duke Power Co |
- 8007020459 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007150015 Ack reteipt of 1E Insp Repts 50-269/80-18,50-270/80-13 & 50-287/80-12 an 800513-15 No proprietary info PARKEN,W O Duke Power Co 80/06/23 lp
- --B007150019 Forwards IE Insp Repts 50-269/80-18.50-270/80-13 & 50-287/80-12 on 800513-15 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/29 2pp
- --8007150021 IE Insp Repts 50-269/80-18.50-270/80-13 & 50-287/80-12 on 20/150021 It Insp Repts 30-28/900-18.30-2/0/20-13 & 30-28//80-12 on BOD518-15 No noncompliance noted Major areas inspected structural concrete for standby shutdown facility HARRIS. J R Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch BO/05/28 3pp
- B007170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/2-80/06/24
- 8007180533 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainlass Steel Pipe" No Type 300 piping in Use for pressure piping Future use of piping will be reviewed
 PARKER, W.O. Duke Power Co. 80/06/24 lp
- B007220192 Advises that hanger insp required by IE Bulletin 79-J3 was not addressed in response to bulletin Hangers visually inspected as part of response to IE Bulletins 79-02 & 79-14 PARKER, W D Duke Power Co 80/06/27
- 8007230235 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Int Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular 80-16 also enci No written response required O'REJLLY, J P Region 2, Atlanta, Offics of the Director 80/06/2 B0/04/27
- B007220245 Forwards response to IE Bulletin 80-08 Approx 53 penetrations concerned Weld defects classified as inclusion One repaired for cracking Design meets all requirements of ASME PARKER, W.O. Duke Power Co. 80/07/01 4pp
- B007140463 Forwards 800704 Revision 2 to response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" Replaces previous submittal & 800519 revision entirely Includes corrections of minor errors THIES.A C Duke Power Co 80/07/07 34pp
- B007250166 Forwards response to Items 1.2a & 3 of IE Gulletin 80-11.
 "Masonry Wall Design " Lists all masonry walls which are in
 proximity to or have attachments from safety-related piping or equipment PARKER,W G Duke Power Co 80/07/07 2ipp
- 800728D416 Ack rocespt of IE lnsp Rept 50-270/80-16 Rept does not contain proprietary info PARKER.W O Duke Power Co 80/07/09 ip
- --8007280418 Forwards IE Insp Rept 50-270/80-16 on 800428-30 & notice of violation LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/30 App
- --8007280421 Notice of violation from insp on 800428-30
 * Region 2. Atlanta, Dffice of the Director 80/0 80/06/27 lp
- --8007280425 IE Insp Rept 50-270/80-16 on 800428-30 Noncompliance noted failure to unuap vent & diain lines & to provide adequate records re sys draining procedures HHITENER, H. L., MOON, B.T. Region 2: Atlanta, Office of the Director UPRICHT, C.M. Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/06/27 5pp

- B007290267 Forwards further response to iE Bulletin 79-i3. "Cracking in Feedwater Sys Piping " H Thielsch B00531 final rept, "Exam of Radiographic Films & Weld Integrity of Pipe Butt Weids in 3-Inch OD by 0 300-Inch Austliary Feedwater Piping," enci PARKER, W O Duke Power Co B0/07/iO 50pp
- 80073i0491 Ack receipt of IE Insp Rept 50-270/80-19 on 8006i7-i8 Nu proprietary info PARKER, W O Duke Power Co 80/07/16 lp
- ---B007310475 Forwards 1E Insp Ropt 50-270/B0-19 on B00417-1B No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/02 2pp
- --8007310501 IC Insp Rept 90-270/80-19 on 800617-18 No noncompliance noted Major areas inspected feedwater sys piping as outlined in IE Bullatin 79-13 CROWLEY, B R Region 2. Atjanta, Defice of the Director HERDT. A R Region 2. Atjanta, Reactor Construction & Engineering Support Branch 80/07/01 4pp
- S Reportable occurrences, LERs & related correspondence
- B007070317 Forwards LER B0-018/03L-0
 PARKER, W D Duke Power Co 80/06/30 3pp
- --8007070323 LER BO-018/03L-0 on BOO601.high pressure svc water pump D declared inoperable due to motor cooler tobe leaks Caused by erosion & corrosion resulting from constant flow of lake water Leaking tubes soldered & cooler pressurized PHILPOTT.F T Duke Power Co 80/06/30 1p
- 8007080201 Forwards LER 80-005/01T-0 PARKER.W 0 Duke Power Co 80/07/02 2pp
- --8007080207 LER B0-009/017-0 on 800617, during RCS heatup, inconsistent boron concentration measurements obtained Caused by poor mixing in care flood tant Unit cooled down & boric acid added Methods under evaluation re maintaining concentration PHILPOTI,F T Duke Power Co 80/07/02 lp
- 8007180321 Forwards LER 80-007/01T-0 PARKER.W 0 Duke Power Co 80/07/10 3pp
- --8007180326 LER 80-007/01T-0 on 800626, w/unit at 40% power, humidity in penetration room found to be above 70% Caused by steam leak on feedwater valve Humidity reduced to 50% & sys declared operable within 3 5-h PHILPOTT, F T Duke Power Co 80/07/10 tp
- 8007220563 RO on 800709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged from upper sump of safe shutdown facility const Const personnel advised of discharge limits PARKER. W O Duke Power Co 80/07/16 2pp
- 8007270824 Forwards LER 80-004/03L-0 PARKER, W D Duke Power Co 80/07/25 2pp
- --B007290B30 LER B0-006/03L-0 on B00625.nt 407 full power.valve 2LP21 failed to open electrically on command Caused by loose setscrew on motor driven pinion Screw repaired JUNES, J. L. Duke Power Co. B0/06/26 pp
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

 F. Security, medical, omergency & Pire protection plans
- 8007070247 Advisos that revised draft emorgency pian in responso to NUREO-0.654 Will be submitted by 800725 Requests clarification of NRC schedule for emergency plan concurrence SMITH.R L Vermont Yankee Nuclear Power Corp 80/07/01 ip
- 8007210049 Requests mod of provision for adequate shutdown capability to meet entl fire protection sofety evaluation critoria Status summary of open issues & evaluation of safe shutdown capability following fire in three plant areas entl IPPOLITO.T A Operating Reactors Branch 2 80/07/03 i5pp
- B0072B0661 Forwards final revised emergency plan which addresses comments described in encl to DL Ziemann 800414 ltr to JA Kay & RL Bmith Emergency plan available in Central Files only BMITH.R L Vermont Yankee Nuclear Power Corp 80/07/25 ip

- 9 Adjudicatory correspondence
- 8007020432 Forwards Director r decision under 106FR2 206 denying 800429 request for revocation of DL * institution of hearings on plant decommissioning DENTON H R Office of Nuclear Reactor Regulation, Director 80706711 | 19
- ****B007020437 Director's decision under 10CFR2 206 denying SF Thomas B00429 request for revocation of Ut institution of bearings on plant decommissioning Allegation of unsafe waste disposal being treated in proposed culemokings 10CFR50.51 DENTON.H R Office of Nuclear Reactor Regulation, Director B0/06/11 Jpp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refere protection for electrical cables EISENHUT D 0 Division of Licensing 80/06/25 89pp
- 8007020627 Order granting extansion until 800717 for Commission to elect whether to review Director's 800611 denial under 100FR2 206
 CHILK.S J Office of the Secretary of the Commission 80/06/27 to
- H General correspondence
- 8007020117 Responds to 800428 ltr encouraging NRC to meet w/VT Yankee Decommissioning Alliance (VYDA) NRC meet w/VYDA on 800429 & received petitions requesting immediate plant shutdown DIRCKEN & J. Office of the Executive Director for Operations 80/06/18 | Ip
- B00702045i Advises that NRC knows of no plans or proposals by util to change type or quantities of releaser from facility into CT River Releaser remain within limits Mods required on lang-term basis to increase safely in LOCA NOVAKITM Assistant Director for Operating Reactors 80/06/18 2nm
- --8007020455 Requests that NRC demand util hold public hearing repossibility of util dumping more wastes into CT River COX.S Affiliation Unknown 80/04/10 3pp
- 8007\$10082 Responds to 800419 ltm referred to NRC by Senator E Kennedy re environ & water safety in CT Rivor Valley Forwards supporting info Radsulogical releases are within acceptable limits Any abnormal releases should be reported W/o enci DENTON: H R Office of Nuclear Reactor Regulation, Director 80/06/25 App
- --8007110093 Forwards D Kont 800419 Itr is requesting info on environ a water safety re util mange of CT River for radiological releases Requests response KENNEDY:E M Benate 80/04/24 2pp
- B007210448 Requests address change for NRC correspondence to License DPR-20 from JM Abbey in Rutland, VT to MF Conway in Vernon, VT SMITH, R L. Vormont Yankoe Nuclear Power Corp. 80/07/16 lp
- PULLIFIE T ABEMOUT ASURDS WAS LEAST LONG COLD CONTAINE TO
- B007300394 Advises that time period for consideration of Director's decision to deny request for liconse revocation & public hearings for finitity has elapsed w/o Commission taking any review action Therefore decision is final NRC action CHILK.S J. Office of the Sucretary of the Commission 80/07/24
- 1 Financial information
- 8007010397 Forwards cash flow info by calendar quarters for company & cash info for sponsor companies for CYBO CAREY. W W. Vermont Yankee Nuclear Power Corp. 80/06/24 4pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark | owners group in Dethesda. MD.re revisions to NRC acceptance criteria & outstanding issues relative to Nark | contolliment iong-term program GRIMES.C T Plant Systems Branch 80/02/Pi Sipp
- 8007160777 Confirms 800627 agt meeting to be hald at facility ro regulatory performance of facility Agenda encl GRIER.B H Region I. Philodelphia, Office of the Director 80706/11 2pp

- 80070/0346 Responds to NRC 800507 ltr.ltpm 1: K 3 45.re IHI-2 related requirements & adequacy of GE 800221 ltr GE ltr is adequate & applicable to feculity SHIFILR ! Vermont fankes Nuclear Power Corp 80/06/30 ip
- 8007140525 Summary of BOOAP4 meeting w/util in Bethesda.MD re-possible proposal of radwaste incinerator Process info bulletin encl ROONEY.V L Operating Reactors Branch 2 80/07/02 9pp
- 8007140338 Forwards VDBAP-I-A, Revision 8, per NRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDER: L N Vanter Atomic Fluttic Co 80/07/09 2pp
- B007250499 Comments on NUREC-0619, "BNR Feedwater Nortle & Control Rod Drive Return Line Nortle Cracking " Disagrees w/position reinterference fit spargers No cracking of nortle regions experienced Date of Dec 1985 recummended for sparger mod BNITH-R L. Vermont Yankee Nuclear Power Corp. 80/07/18 ip
- 8007280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURCH & Vankee Atomic Electric Co 80/07/24 7pp
- 8007310385 Outlines proposed schedule for torus modesper 800625 telcon Last two items listed will be implemented only if further analysis & testing shows need Mode whold not be completed until fall 1981 refueling outage BMITH:R L Vermont Yankee Nuclear Power Corp 80/07/25 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8007090370 Forwards IE Insp Rept 50-271/80-03 on H00221 One item of noncompliance noted GRIER, B H Region i, Philadelphia, Office of the Director B0/05/09 2pp
- ---8007090373 IE Insp Rept 50-271/R0-03 on 600221 Noncompliance noted failure to package low apecific activity waste package so that radiation levels from surface of package were within given limits KINNY. W W . RAYMOND, W J Region 1, Philadelphia. Office of the Director (ROCKER.H W Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 80/03/74 29pp
- 0007140433 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" Written response required CRIER.B M Region 1, Philadelphia, Office of the Director 60/03/12 19
- 8007230695 Responds to notice of violation & notice of proposed imposition of civil penalties, transmitted by NHC 800507 ltr Util administrative procedure for raduaste shipments revised to require instrument surveys Penalty payment encl CONMAY. W F Vermont Yanker Nuclear Power Corp 80/05/27 2pp
- 8007020125 Forwards IE info Notice 80-22. "Breakdowns in Contemination Control Programs " No written response required ORIER. B H Region i. Philadelphia. Office of the Director 80/05/28 ip
- 8006260362 Ack receipt of 800429 ltr informing NRC of steps taken to correct vlolation noted in IF lnsp Rept 50-271/79-14 SMITH.G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/29 lp
- 8007010286 Forwards IC Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response regulard ORIER, B H Region 1. Philadelphia, Diffice of the Director 80/05/29 ip
- R007210623 Forwards IE Info Notice 80 26, "Evaluation of Contractor GA Programs " No written response required GRIER, D H Region 1, Philadelphia. (Office of the Director 80/06/10 1p
- 8007140275 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Capability " Written response required GRIER, B H Region 1. Philadelphia. Office of the Director 60/06/12 ip

- 8007170325 Forwards response to IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " All safety-related equipment remains in emergency mode upon reset of ESF actuation signal w/listed exceptions
 TRIBBLE.J E Vermont Yankee Nuclear Power Corp 80/06/13 2pp
- 8007020704 Forwards IE Bulletin 80-19, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsito Power " Written response required ORIER, B H Region I. Philadelphia, Office of the Director B0/06/18 1p
- 8007020528 Forwards 1E Circular BO-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director BO/05/20 1p
- 8007180949 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Facility does not use actuators CDNHAY,W F Vermont Yankee Nuclear Power Corp 80/06/20 1p
- B007iB0594 Responds to IE Bulletin B0-10 Measures described to prevent uncontrolled releases or contamination of nonradioective sys Administrative controls, hardware mods & process radiation monitors added Sampling program expanded CONWAY.W F Vermont Yankee Nuclear Power Corp. 80/06/20 tp
- 8007i60750 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Porsonnel " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/24 1p
- 8007210290 Forwards IE Info Notice 80-24. "Low Level Radwaste Burlai Criteria " No writton response required GRIER.B H Region 1, Philadelphia. Office of the Director BD/06/25 ig
- 8007230186 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007080292 Forwards Revision 4 to inservice insp program
 8MITH-R L. Vermont Yankee Nuclear Power Corp. 89/07/01 ip
- --G007080296 Revision 4 to inservice insp program # Vermont Yankee Nuclear Power Corp 60/07/01 3pp
- 8007110460 Responds to NRC 800610 1tr re violations noted in IE Insp Rept 50-271/80-06 Appropriate personnel reinstructed on importance of completing all items on forms Correct data for Scram Test 94 recorded on necessary data sheet HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 80/07/03 2pp
- 8007210577 Responds to IE Builetin BO-08 Util uses flued head design for penetration conjections & other designs w/containment boundary butt welds ABME Code. Section III. 1968 edition, applied to fabrication & installation HEIDER. L. H. Vermont Yankee Nuclear Power Corp. 80/07/07 Opp
- 8007250173 Forwards reply to IE Bulletin BO-il re masonry wall design Prioritized list for further evaluation encl No further justification is required for codes used as basis of re-evaluation HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 80/07/07 Spp.
- 8007250188 Submits reply to 1E Bulletin 80-17 re failure of control rods to insert Required tests were performed & scram discharge vol & associated piping are free of obstructions HEIDER, L H. Vermont Vankee Nuclear Fower Corp. 80/07/08 2pp
- B007240422 Confirms and notification that 20-day period for completing tests required by Item 2 of IE Bulletin 80-17 started on 800708 NRC licensing project manager should be notified if test would cause severe impact on power reliability, GRIER, B H Region 1. Philadelphia, Office of the Director 80/07/09 2pp
- B007300044 Ack receipt of 800527 ltr forwarding payment of civil penalty & discussing corrective actions, in response to NRC 800507 ltr
 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/15 2pp

- R Periodic operating reports & related correspondence
- 8007210456 Forwards "Effluent & Waste Disposal Semiannual Rept. Radiological Impart on Man for First 4 Second Quarters 1979 "
 - CROCE, R H Vermont Yankee Nuclear Power Corp 79/08/31 1p
- --8007210467 "Efficent & Waste Disposal Semsannual Rept.Radiological Impact on Man for First & Socond Quarters 1979 " * Vermont Yankee Nuclear Power Corp 79/08/31 47pp
- 8007180398 Forwards monthly operating rept for June 1980 COMMAY.W F Vermont Yankes Nuclear Power Corp 80/07/08 1p
- --8007180400 Monthly operating left for June 1980 BURGER.F.J. DEERS.F.C. Vermont Yankee Nuclear Power Corp 80/07/08 App
- B Reportable occurrences, LERs & related correspondence
- 8007020540 PND-1-80-091 on BOO611.planned drywell entry was conducted to investigate suspected reactor coolant leaks investigation revealed leakage originated from gasketed mechanical joint Tech Spec criteria lowered Plant shut down RAYMOND.W J. MARTIN, T T, BRUNNER, C J Region 1. Philadelphia. Office of the Director 80/06/13 Rpp
- 8007010317 RO 77-205/17. Suppl 1 encl GE loose parts analysis addresses possibility that water red lower end plug could wear to extent that shank would break Licensee concurs w/conclusion that generation of loose part is unexpected W/o encl MURPHY. W P Vermont Yankee Nuclear Power Corp 80/06/25 1p
- BOD7010391 Forwards LER 80-018/017-0 MURPHY,W P Vermont Yankee Nuclear Power Corp 80/06/25 ip
- --8007010405 LER 80 018/017-0 on 800611.feedwater lines found leaking directly into torus & bypassing detection sys Caused by drywell leakage detection sys design inadequacy Tech spec leakage limits reduced Limits & detection sys under review MURPNY.W P Vermont Vankee Nuclear Power Corp 80/06/25 2pp
- 8007070260 Suppl 1 to RD 79-25/1T concurs w/conclusions of encl GE proprietary info on loose parts analysis that water rod lower end plug would wear & cause shank to break GE info withheld tref 10CFR2 790)
 MURPHY.W P Vermont Yankow Nuclear Power Corp 80/06/25 ip
- B0072304BB Forward's LER 80-020/03L-0 MURPHY.W Vermont Yankee Nuclear Power Corp B0/07/17 1p
- --B007230489 LER 80-020/03L-0 on 800617.PC15 valve FS0~109-76A failed to close after stram Cousad by dirt on plunger assembly Valve cleaned & returned to svc MURPHY.N Vermont Yenkee Nuclear Power Corp B0/07/17 ip
- DDCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007080068 Forwards Submittal 4 to 800627 security contingency plan Bubmittal withheld (ref 100FR2 790) LIBRIZZI.F P Public Service Riectric & Gas Co. of New Jersey 80/06/30 in
- BO07140429 Requests approval to proceed w/interim use of training facility in Quinton, NJ as near-tite emergency operations facility
 SCHMEIDER, FW Public Service Electric & Qas Co of New Jersey 80/07/03 Ann
- Q Adjudicatory correspondence
- 8007280555 Requests placement on sys list as friend of court in order to receive copy of all papers issued WEBB.M Affiliation Unknown 80/05/16 2pp
- 8007300332 Requests inclusion in Salem avo list to receive all post-800222 documents & presenting testimony responding to NRC witnesses' claim against RE Webb tectimony WEBB,R E Affiliation Unknown 60/05/16 2pp

- 800711011. Correction to inter that 400al's proposed findings of fact & conclusions of law surrect Finibit bit civil Action 79-1129, encl
 VALORE, C. J. tower Alloway- steps NU VALORE (* Valore, * 80706/2") 73pp
- 8007310243 Firmards Cummission NO527 memoranduri & order containing decisions on UFS 780902 printion for incommideration or 780413 memorandum # order UCL 771504 printion sought action for Figure protection for electrical cable EISCNIF/T D 8 02/15100 DE LICENSING 80/06/25 N9pp
- B007100175 Responds to 809509 order < 10 FM; ,54 * 2 710 by forwarding intervenor coleman proposed findings of fact & conclusions of law on Contentions 2 & 6, aways irron-reactor alternatives & Board Question 5

 AYRES 8 T New Jersey, state of 89 06726 Tep
- --8007180178 Intervinor Colemans purposed findings of fact & conclusions of law on Contentions & factor Board unestion 5 & away-From-reactor alternatives in accordance w/Board 800509 order & 100782 754 & 7 /10

 VAN NESS 6 C New Jersey, 'state of 80706/26 20ph
- B007150509 Reply findings of ract & conclusions of law in form of partial initial difficult substituting for licensee 800513 findings. In response to ASLR B00509 order & ASLR B00626 Question 5 an away-from-reactor issues W/Certificate of Svc WETTERMANN.M J. FRYLING R. Public Service Cictiic & Gas Co. of New Jersey WETTERMANN.M J. FRYLING R. Public Service Cictiic & Gas Co. of New Jersey WETTERMANN.M J. Connet. Moore & Corber. 80/07/11 96pp
- J Insurance to indemnity information
- 8007010523 Forwards Endorsement 39 to AN1 Policy No -230 CORREALM A Marsh & McLobadh Inc., M & M Norleam (onsultants) inc Div 80705725 2pg
- 8007310342 Forwards Endorsement 32 to NAFLV Policy NF-90 CORREALM A Marsh & McLeman.inc . N 4 M Nuclear Consultants.inc Div 80/07/21 2pp
- 8007310376 Forwards Endotsement 46 to ANS) Policy NF-230 CORREA,M A North & Melenman, Inc. (M. & M. Northar Consultants, Inc. Div. 80/07/2) 2pp
- P Operating liconse stage documents & correspondence
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat commonly capability in all modes of operation Model Tech Specs which would provide acceptable resolution entil for guidance EISENIUT.D 0 Division of Licensing 80/05/11 67pp
- 6007110456 Informs that second interim rupt, per facility 316(b) plan of study, will be distributed to technical advisory group by 800625 Delay raised by computer problem Submittal date should allow enough time for review before 800709 meeting 8HISSA19. J A Public Service Flection & Gas Co of New Jersey 80/06/13 2pp
- 8007030249 Forwards response to 800004 confirmatory orders re loss of non-Class IE instrumentation & control power bus linfo written for Unit 1.but also applicable for Unit 2.except as noted includes response to 16 Circular 79-02 Affidavit enci SCHNEIDER:F W Public Service Cleater: & Gas Co of New Jersey 80/06/27 33pp
- 8007070289 Forwards responses to full power license requirements identified at NRC BOOG19 meeting HITLLR L Public Service Electric & Gas Co. of New Jersey 80/06/27 14pp
- --8007070289 Tech Spec Pages 3/4 7-5 through 7 7 for autiliary feedwater sys & auxiliary feedwater sys & auxiliary feedwater encl # Public Servery Electric & Gas Co. of New Jersey 80/06/27 Soo
- B007030thi Forwards addl info in response to MRC 800618 request to auxiliary feedwater sys for both units are identical in design including equipment % automatic initiation logic hard. I fullic Service Electric * Gas Co of New Jorsey 80/07/01 | 13pp
- B007250001 Requests submittal of application for amend to license constituting of Tech Sper changes, ". license conditions PMR Model Tech Spers is Model license conditions for TMI-2 Lessons Learned Category A steins ensi for muldance LISENHUT.D & Division of Licensiny 89777.02 69pp

- 00/08034) Notification of 80062, meeting w/util in Santuis Opispo.CA to discove task action plan items BUCKLEY B C Licensing Branch \gtrsim 80/06/20 4pp
- 007020394 Forwards nonproportetory versions of previously submitted gomeric Nestinghous proprietory litts to support position on good tube were characteristics Requests acknowledgement of recorpt CRANC, P. A. Pacific Gas & Electric Co. 80/06/23 1p
- 007230001 forwards statement of policy re requirements to be met for current 0L applications, as derived from NUREC-0660 & Found in NUREC-0669.
- FISEMANT, D.G. Division of Licensing 80/08/26 2pp
- 10072306.35 Forwards std order for DOE work MATTSONIR J Division of Safety Fechnology FIN A-1121-0 80/06/30 1pp
- --80072J0652 Std order for DOE work "Review of Auxiliary Feedwater Sys Reliability Evaluation Studies for Diable Lanyon i, ReQuire I. Summer 1 & San Ordere 2 & ECC9 Reliability Analysis of Hanual ve Antomatic " Issued to Sandia Lobs GRENIER, R I Division of Bafety Technology FIN A-1121-0 00/06/27 9pp
- 300/070197 Forwards Revision I to "Description of Sys Interaction Program for Seismically-Induced Events," originally submitted 800527 submitted 800927 CRANCIP A Pacifix Gas & Electric Co 80/07/01
- --8007070206 Revision i to "Description of Sys Interaction Program for Soismically-Induced Eventa " Pacific Gas % Electric Co 80/05/10 79pp
- 3007160392 Forwards Std Order for DN. Work, "Sys Interaction Support for Diable Compon," issued to Ltt. ROS9.8 F Division of Systems Integration FIN A-0248-0 90/07/07
- --800/160395 5td Order for DOE work "Sys Interaction Support for Diable Cangon " (stude to LLL GRENICK-B Office of Stondards Development, Director FIN A-0748-0 80/07/01 App
- 3007230829 Notification of 800718 meeting w/utst in Bethesda,MD to review nuxiliary fordwater eys reliability studi BUCHLEY.B C licensing Branch 1 80/07/08 4
- 100/280089 Summary of 600617-19 site visit w/NRC, util & two intervenors re audit of sys interaction program for seismically-induced events Program is sound & can be satisfactorily completed Independent walkdown description encl
 THOMAS, C.D. Systems Interaction Branch 80/07/09 Opp
- 300/160920 Forwards draft Operating Procedure (PP-38, "Anticipated Transient W/s Trip:" per AC Thadani request Procedure should not be considered part of docket file supporting OL opplication
 CRANE,P A Pactfit Gas & Flectric Co GO/07/10
- --B007160521 "Anticipated Transient W/o Trip." emergency operating
 - procedure
 * Pacific Gns % Clusters Co 90/06/07 5pp
- 1007.230208 Discusses augmented low power startup test program for near-term OL applicants Each applicant must perform tests similar to TVA proposed program President Carter 791207 statement on Krmony Commission reft Prof E19CNIUT-D & Division of Licensing 60/07/11 App
- 8007180340 Forwards Revision 2 of "Description of Sys Interaction Program for Voismically-Induced Events " CRANE.P A Pacific Gas & flectric Co 80/07/15 lp
- --8007180344 Revasion 2 to "Description of Sys Interaction Program for Seignifical Undered Events " # Pacific Gar & Cientric Lo 80/07/09 77pp
- 800/250090 Notification of 600725 wheting w/util in Betheada MD to discuss Auxiliary feedwater sq. Meeting originally scheduled for 800/18 BUCKLEY, B.C. Licensing Dianch 'S 80/0//17 Spp
- 8007310397 Advises that R McMolten response to Question 9 of ASLAB-598 accurately reflects USOS position Ambiguities in location of cartaquake require conservative artumption that all faults have earthquake potential Interior Dept of Geological Survey 80/07/29 Ip MORRIS, R II

- E NRC Safety Evaluation Report (SER), supple & correspondence
- B007110033 Forwards Suppl 9 to facility SER SCHWENCER, A Licensing Branch 2 80/06/13 Spp
- --80071(0036 Suppl 9 to facility SER * Office of Nuclear Reactor Regulation, Director NUREG-0675 89 80/06/30 86pp
- F Security, medical, emergency & fire protection plans
- 8007150377 Forwards Revision I to security training & qualification plan Revision i withheld (ref 10GFRZ 770)
 CRANE,P A Pacific Gas & Flectric Co BO/07/11 ip
- 9 Adjudicatory correspondence
- 8007030048 Request for participation in security plan hearing per ABLB 791116 order admitting State of CA in DL proceeding Participation will assist in adequacy & workability assessments Notice of appearance & Certificate of Syc encl BROWN, H H. KLINE, J A. California, State of BROWN, H H. Hill Christopher & Phillips 80/06/11 7pp
- 9007140026 Ack receipt of Commission 800611 memorandum & order.CLI-80-24.on behalf of Snn Luis Obispo Mothers for Peace Adheres to prior position re Commissioner Hendrie participation in all aspects of DL proceeding re seismic & safety issues JONES, Y I Jones, Grey & Bayley 80/06/18 2pp
- 8007100198 Expresses appreciation for NRC permission allowing joint intervenor representatives to participate in 800617-19 sys interaction audit at util NRC has demonstrated willingness to assure public participation Related correspondence FLEISCHAKER, D S Fleischaker, D S 80/06/25 1p
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UGB 771104 petition sought action re fare protection for electrical cables
 EISENHUT, D O Division of Licensing 80/06/25 89pp
- 8007300419 Notice of appearance in proceeding Certificate of 8vc encl QEORQIQU.B S California, State of 80/06/30 4pp
- BOO7070123 Advises of stipulation in OL proceeding, eliminating legal argument re wording of affidavit of nondisclosure & public dissemination of info Governor Brown of State of CA did not take part in stipulation TOURTELLOTTE. J. Hearing Branch 4 JONES, Y. NORTON, B. Pacific Gas & Electric Co. BO/07/02 2pp
- 8007114002 Order granting extension until 800722 for Commission to stact to review decision on enforcement action request. DD-80-22 HDYLF, J C Office of the Secretary of the Commission 80/07/08
- 8007180405 Motion for OLs permitting fuel loading, initial criticality process & low power testing Proposed operation may be conducted during appeal from ALSE 770727 partial initial decision W/documentation, affidavit & Certificate of Svc GRANS, P A Pacific Gas & Electric Co GEHR, A C Snell & Wilmer NORTON, B Bruce Norton 80/07/14 13pp
- BOO7220092 Hemorandum & order amending & reissuing ASLAB 800403 protective order re security plan Governor of CA request for participation as interested state granted w/cortain conditions Bets timetable for future proceedings BISHDP,C J Atomic Safety and Licensing Appeal Panel 80/07/13 22pp
- --8007220103 Amended protective order permitting limited access to Ban Luís Obispo Mothers for Peace & Governor of CA ressecutity plan info Amended affidavit of nondisclosure encl IBHOP,C J Atomic Safety and Licensing Appeal Panel BO/07/15
- BD07230508 Request for reconsideration of ASLAB B00624 decision, ALAB-590, or certification of M Trifanac & E Luco testimony on 791015 Imperial Valley earthquake Urges appropriation of funds to facilitate testimony Certificate of Svc enci FLEISCHAKER, D S, JOHNSTON, M P. PHILLIPS, J San Luis Gaispo Mothers for Peace 80/07/17 App

- 8007230536 Motion to change lead counsel designation from JR
 Tourtellotte to WJ Dinstead Notices or WJ Olmstead % LL
 Bwart; appearances, JR Tourtellotte withdrawal & (ertificate
 of Svc encl
 ULMSTEAD, WJ , TOURTELLOTIE, J Hearing Branch 4 80/07/21 6
- BOO7300110 Notice of appearance in proceeding LANPHER.L C California State of LANPHER.L C Hill Christopher & Phillips 80/07/21 ip
- 8007290429 Statement in support of joint intervenors' 800717 request for reconsideration of ALAB-998, or for certification of question ro Mihailo, Trufunac & Enrique independent views, to Commission Urges funding for Trifunac & Luco BROWN, H H . KLINE, J A . GEORGIOU. B S California. State of 80/07/24 2pp
- 8007300096 Request by joint intervenors for extension until 800804 to respond to applicant motion for luw power testing license Counsol out of town Certificate of Svc enci FLEISCHAKER, D S Ban Luis Obispo Mothers for Peace FLEISCHAKER, D S Fleischaker, D S JOHNSTON, H P Center for Law in the Public Interest 80/07/25 4pp
- B007310451 Discusses handling & delivery of sensitive security mat) between parties

 OLMSTEAD.W J. Hearing Branch 4 80/07/28 Upp
- H General correspondence
- 8007140016 Ack receipt of uncl & informs recipient about progress & sypectation of required cultural & historical mitigation program Ltr forwarded to NRC for consideration NIELBEN.A D Interior.Dept of 80/06/18 7pp
- 8007010063 Expresses regret that failure to add Society for Environ Awareness to mailing list for weekly public ampoincements on facility, resulted in necessity to duplicate request Addition made to distribution list
 INGRAM.F L Office of Public Affairs 80/06/20 Ip
- BOO7010457 Opposes granting license for low level testing far util, due to health & safety concerns re emergency planning, radiation monitoring & safety issues hasud on TMI No testing should be allowed until conversion possibilities explored CLUCAS, J A Loague of Women Voters of Bantuis Obispa CA 80/06/24 to
- BOOTOTORIB Requests that NRC deny OL to facility Too much emphasis placed on possible purthquakes along Hosgri Fault & not enough centern on entire area of instability (antitions treate distinct possibility for formation of more volcances SNAPP.C Affiliation Unknown 80/0//01 1p
- 8007230277 Responds to 800608 ltr re RH leddy concerns about proximity of Hasgri Fault to site & obtility of farcility to withstand severe earthquake Fault is 1.5 miles from site Matter of saismic situation currently pending before ASLAH DIRCKS.M J. Office of the Executive Director for Operations 80/07/02 App
- ---8007250284 Requests ruspouse to oncl RH Loddy concerns about proximity of site to Hasgr: Fault LAGDMARSING.R J. House of Rep., Foreign Affairs 80/06/07 3pp
- B007290647 Urgss that NRC deny (NLs for facility due to proximity to Hosgri fault & to protect health, nafety & welfare of people of CA ALLEN, B D Affiliation Unknown \$60/07/Pl 2pp
- a Inspection reports, IE Dulletins & correspondence
- 900728069/ Forwards response to JE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Loss of power to Class IE buses is audibly & visually indicated by Control room annunciator CRANE.P A Pacific Ops & Fluctric Co 00/04/15 12pp
- 8007240187 Responds to IE Bulletin 80-04. "Analysis of PWR Hain Steam Ling Break W/Continued Esodwater Addition " Review results indicate no potential for containment overpressure or worsening of return to power response CRANE.P A Pacific Gas & Electric Co 80/04/30 2pp

- BOOTORDPAd Forwards IE Info Notice 80-2d. "Breakdowns In Contamination Control Programs" No written response required ENGELKEN, R H Argion 5, San Francisco Office of the Director BO/05/2B ip
- B0072R0237 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs 'No writton response required ENGELKEN,R H. Hogion 5, Sen Franci La. Office of the Director B0706/10 1p
- 8007270086 Furwards 1E Info Notice 83-20 Prompt Reporting of Info in Accordance W/IGCFR50 55(e) ' Ho written itsponer required ENGELIGH R H Region 5 Sam Francisso Office of the Director 80/02/13 1p
- B007290658 Responds to LE Bullitin 79-25, "Failures of Westinghouse BFD Relays in Gafery Related Sus 1 Subj relays not used or planned for use in safety-related sus at plant CRANE, P.A. Pailfix Gas V.Linctric Co. 90/05/16
- 8007030017 Forwards 1E Hulletin 80-15, "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power "Written response required ENGCLKEN,R H Region 5, Sun Francisco, Office of the Director 80/06/18 to
- B0072403B5 Forwards (E Insp Rept 50-275/B0 13 on 800501-30 No noncompliance noted CREMS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/18 2pp
- ~-8007240395 1E Insp Rept 50~75/80~13 on 600501 30 No noncompliance noted Major areas inspected fire protection/prevention, operator training % witnessing of testing in progress YDUNG, F Region 5, San Francisco, Office of the Director STERMBERG, D.11 Region 5, San Francisco, Office of the Director Support Branch 80/06/17 4pp
- B007020474 Forwards IE (inculus 80-15, "Loss of keactor Comlant Pump Cooling & Natural (inculation (boldown ' No written response required FNOELKEN,R II Region 5, San Francisco. Office of the Director 80/06/20 ip
- B007180287 Forwards 1E Circulus 80-14, "Redioactive Contamination of Plant Demineralized Water bys & Resultant Internal Contamination of Personnol ' Ho written response required ENGELKEN.R H Region 5, Son Francisco, Office of the Director 80/06/24 ip
- 8007230385 Forwards IE Bulletin 80 16, "Potential Hisupplication of Rosemount Inc Models 1151 & 1152 Prosence Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also entl Nu written response required ENGELMEN.R H. Region 5, San Francisco. Office of the Director 80/06/27 | 1p
- 8007300200 Responds to 1E Bulletin 80-05 re vacuum damage to chemical vol control tank typ All five tanks protected against failure under vacuum conditions RC5 drain tank designed to withstand external pressure of 15 peig
- 8007310321 Forwards IE Insp Ropts 50-775/80 14 % 50-323/80-07 on 800601-20 No noncompliance noted CREMB, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/10 Spp
- --B007310327 IE then Repts 90 2/5/80-14 to 50-32/80 07 on 800601-20 No noncompliance nuted Major areas inspected propperational testing, plant tops, feel storage, operator training & witnessing of testing in progress YOUNG, T., BAGAGI JU.M. Region 5, San Francisco, Office of the Director STERNERG, DM Region 9, San Francisco, Can Reactor Operations Nuclear Support Branch 80/07/03 3pp
- DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

 Q Insportion reports, SE Bulletins & correspondence
- 8007170198 Forwards IE Circular 80-14, 'Radioartive Contamination of Plant Demineralized Water '99 & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P. Region 2. Atlanta, Office of the Director 90/06/24

OCKET 50-277 PEAUS BOTTOM ATOMIC POWER STATION, UNIT 2 Security, medical, emergency & fire protection plans

007140361 Forwards input for fire protection review re fire detection, water suppression, combustible control, gas suppression, fire doors & interior base stations
HALLER E Brookbasen National Laboratory 89/06/20 8pp

1007.230018 Forwards summary of 600403 meeting woutil in Ming of Prussia.PA is proposals to meet Tech Spec requirement in health physics staffing area SMITM. OH Region i. Philadelphia. Fuel Facility & Materials Safety Branch 80/05/27 3pp

--B007230021 Summary of 800603 meeting w/util in King of Prussia.PA re proposals to meet Toch Spec requirements in health physics staffing area SERABIAN.J A Region 1. Philadelphia, Diffice of the Director 80/06/03 1p

3007230126 Requests participation in sludy of people-related problems in nuclear safeguards Sludy involves collection of data on licenses security forces & plantices MRC wishes to interview security myt personnel at facilities EISENHUT. D G Division of Licensing 80/07/11 2pp

4 Adjudicatory correspondence

3007080086 Proposed findings of fact & conclusions of law responding to ASLAB questions on Battelle rept Findings are adopted by THI-2/Peachbottom Intervenors & Ecology Action Urges suspension of OLs Certificate of Svc encl KEPFORD.C Environmental Coalition on Nuclear Power 80/06/18 1200

8007080046 Response to ASLAD request re Deficiency i Orges reversal of decision rejecting deficiency re correlation between U mine radon releases % amount of U fuel Portion of Perkins decision re correlation must be varated CAPLANIR Ecology Action of Oswego 80/06/20 2pp

8007080048 Proposed Findings of fact endorsing Citizens for Bafe Environ filing he radiation source terms from U mining & milling Rojects Pertins rationals & orges development of further evidence re failure mochanisms & human factors CAPLAN.R Ecology Action of Downgo 80/06/20 App

B007310243 Forwards Commission B00827 memorandum & order containing decisions on UES 780502 potation for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D C Division of Licensing 80/06/25 89pp

BOO7080001 Proposed findings of fact & conclusions of iau in form of nemorandum & order affirming ASLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK.B # Hearing Branch 4 80/07/03 58pp

--B007080000 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp

--800708000A Motion to include do minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order inclusion is consistent w/ALAB-509, ALAB-540 & ALAB-540 Certificate of Svc encl BURDENIC, K Heaving Dramb 4 80/07/03 7pp

8007100258 Order granting Ecology Action of Oswego motion to file 800620 submission to generic radon issue BISHDP.C J. Atomic Safety and Licensing Appeal Panel 80/07/07 208

BOO7310128 Response in support of MRC BOO703 pleading asserting validity of Perkins second on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from rome ideration Supporting news articles encl CAPLANIR Erology Action of Usweep 80/07/16 13pp

John Marin

BOD7250353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fait submitted by other parties filed BOO718 Revised pages required to correct typographical errors SVC list enci

H General correspondence

800702017/ Requests consideration of site visit by Atomic energy Council of Toiwan on 800825-26 Council interested in observing waste mot activities Cooperation will be major contribution to NRC exchange arrangement LATLEUR, J D. Assistant Director for international Cooperation 80/05/13 | 3pp

8007i40l15 Ack recorpt of B00423 ltr re public announcement for recent meeting at facility FEMA will be holding public meeting later in the year at which time public will have opportunity to express views re emergency plans GRIMES, B K Emergency Proparedness Program Office 80/06/09 ip

--8007140118 Ack receipt of 800424 ltr expressing concern re arrangements for recent meeting at facility FEMA has responsibility for assessing emergency planning & will conduct meeting when plans are finalized DINCKS.W J. Office of the Executive Director for Operations 80/04/02 2pp

B007110917 Ack receipt of GL Becker B00430 ltr re concerns about emergency planning Forwards NUREG-0694 & NUREG-0396 W/o encl
GRIMES, B Fmergency Preparedness Program Office 80/06/12 ip

8007280549 Responds to 800520 ltr re JL & WS Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for Pacifity emergency planning meeting issued on 800331 W/Randeli ltrs DIRCWB, W J Office of the Executive Director for Operations 80/07/02 7pp

l Financial information

8007010138 Responds to 800405 ltr to 9 Cunningham transmitting util 9-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY.E Hadrings Division 80/04/19 ip

P Operating licenso stage documents & correspondence

B007230028 Summary of B00207 meeting w/Mark I dwners group in Bethesda. MD.re ravisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMEB.C T Plant Systems Branch 80/02/21 31pp

8007140641 Advises that dates of responses to 790927 generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Match 1 & 2 Rept on valve operability program required only for plants desiring to justify infinited purging VERRELLI.D M Operating Reactors Bronch 4 80/06/05 1p

B0071705B1 Confirms B00619 mgt meeting to be held at facility re regulatory performance GRIER.B H Region i, Philadelphia, Office of the Director B0/06/16 ip

B007020B10 Advises that Clast III fee is required for review of B00603 application for amond of Licones DPR-44 & DPR-56 Request involves redistribution of health physics functions & is considered to be at safety significance DIGOS,R M Licones Fee Management Branch B0/06/18 ip

8007100155 Requests technical assistance for review of 800523 & 0603 proposed Tech Ripec changes re executive mgt & ansite health physics functions Current Tech Ripec & util ltrs ent NOVAK:T Assistant Director for Operating Reactors 80/06/19 ip

--8007100158 Current Tech Specs Pages 243 through 246 re administrative controls
4 Philadelphia Electric Co 79/09/20 App

8007020435 Confirms licensee voluntary cooperation w/team of NRC rosearch contractors during visit to facility in Sept 1980 Visit is related to NRC sponsored study re status monitoring of ingineered safety features REID:R W Operating Reactors Branch 4 80/06/24 2pp

9007180119 Requests that util propose amends to facility Tech Specs to incorporate currently installed setamic instrumentation & associated surveillance requirements Sample Tech Specs reflecting current NRC tequirements oncl NDVAK.T M Assistant Director for Operating Reactors 80/07/01

- ---B0071B0123 Sample Tech Specs Pages 3/4 3-46 through 3/4 3-48 for seismic monitoring instrumentation

 * Operal Electric Co 7B/04/01 3pp
- 8007280342 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation
 NDVAK.T M Assistant Director for Licensing 80/07/10 2pp
- 8007240238 Forwards Amonds 71 & 69 to Licenses DPR-44 & DPR-56. respectively, safety & evaluation & notice of issuence & availability REID, A W Operating Reactors Branch 4 80/07/15 2pg
- --8007240242 Amends 71 & 69 to Licenses DPR-44 & DPR-56, respectively, clarifying definition of operable & adding general limiting conditions for operation & action statements for Tech Specs Operating Reactors Branch 4 B0/07/15 30np
- --8007240249 Safety avaluation supporting Amends 71 & 69 to Licenses
 DPR-44 & DPR-56 respectively
 * Office of Nuclear Reactor Regulation, Director 80/07/15 3pp
- --8007240251 Notice of issuance & availability of Amends 71 & 69 to Licenses DPR-44 & DPR-56 respectively REID.R W Operating Reactors Branch 4 80/07/15 2pg
- BOO7180443 Forwards application for amend of facility QLs Application requests changes to Tech Specs re control rod drive return line mode, containment isolation valve mode & correction of typographical error Check onci to cover fee for application URADLEY.E J Philadelphia Electric Co 80/07/14 ip
- --8007180446 Application for amend of facility OL requesting that Tech Brees in App A of OL be amended by revising control rod drive return model containment isolation valves & typographical error in Tech Brees Cortificate of Svc enci KEMPER.J B Philadelphia Electric Co 80/07/16 18pp
- 8007220551 Forwards addl fee for application for amond to Licenses DFR-44 & DPR-56, in response to 800618 ltr BRADLEY: E. J. Philadelphia Electric Co. 80/07/17 2pp
- @ Inspection reports: IE Bulleting & correspondence
- 8007140462 Forwards IE Bulletin 80-13, "Gracking in Core Spray Spargars" Written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/05/12 ip
- 8007020035 Ack receipt of B00513 itr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-277/80-06 &
- --B007020041 Responds to NRC 800421 itr re violations noted in IE lnsp Repts B0-277/80-06 & 30-278/80-06 Corrective actions, personnel reminded of work documentation importance & Tech Specs data recorded GALLADHER, J. W. Philadelphia Clectric Co. B0/05/13 3pp
- --8007020049 Forwards iE Insp Repts 30-277/80-06 & 90-278/80-06 on 800317-21 & notice of violation BRUNNER,C J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch. 80/04/21 2pp
- --8007020060 Natice of violation from insp on 800317-21 * Region i, Philadelphia, Office of the Director 80/04/18 2pp
- --B007020070 IC insp Repts 50-277/80-06 & 50-270/80-06 on B00317-21 Nancompliance noted util failed to document two surveillance tests & corrective maint & failed to record Tech Specs data BLUMMBERG, N Region 1. Philadelphia, Office of the Director GREENMAN, E O Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch B0/04/18 12pp
- 8007020143 Forwards iE Info Notice 80-22, "Breakdowns II Contamination Control Programs." No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- 8007010310 Forwards IE Info Notice 80-23, "Loss of Suction to Emurgency Fredwater Pumps" No written response required GRIER, B. M. Region 1, Philadelphia, Office of the Director 80/03/27 ip

- B00701037B Responds to IE Bulietin 79-14, "Spismic Analysis for As-Built Safety-Related Piping Sys" Bechtel Power Corp is purforming engineering review & analyses for safety-related piping Unit 3 rept will be rubmitted by 800615
 DALTROFF.S L. Philadelphia Electric Co. 80/06/03 lp
- B007210600 Forwards lE lnfo Notice B0-26, "Evaluation of Contractor GA Programs " No written response required GRIER, B H Region i, Philadelphia, Office of the Director B0/04/10 ip
- BOO7020D72 Responds to 1E Bulletin 80-04. "Engineered Safety Features (ESF) Reset Controls "Encl App A identifies any corrective action planned for safety-related equipment which does not remain in emergency mode upon reset of signal DALTROFF, & L. Philadelphia Electric Co. 80/06/11. Spp
- B007140267 Forwards [E Bulletin B0-14, "Degradation of BWR Scram Discharge Vol Capability "Written response lequired GRICR.B K Region 1, Philadelphia, Office of the Director B0/06/12 ip
- 8007180106 Bubmits reply to IE Bulletin 80-13 re cracking in core spray sprayers No cracks were found in insp of Unit 2 Insp of Unit 3 will be performed during next refueling outage DALTROFF, 8 L Philadelphia Electric Co 80/06/13 2pp
- BOO7iBO117 Bubmits reply to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys All Unit 3 safety-related piping is operable in present condition
 DALTROFF-S L Philadelphia Electric Co 80/06/13 3pg
- 8007170507 Updates 800415 environ qualification rept for Class IE electrical equipment in response to IE Bulletin 79-018 Forwards revised pages & info ie high energy/one break profiles & LOCA profiles for reactor blugs W/o encls DALTROFF.S L Philadelphia Electric Co 80/06/17 2pp
- 8007020700 Forwards is Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required ORIER.B H Region 1, Philadelphia. Office of the Director GRIER, B H R
- 0007020492 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ORIER, D H R Region i, Philadelphia, Office of the Director 80/06/20
- B007160836 Forwards IE (incular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIGE, 0 & Region 1, Philadelphia, Office of the Director B0/06/24 ip
- BOO721022B Forwards IR info Notice 80-24, "Low Level Radwasto Burial Criteria " No written response required ORIER.D H Region 1, Philadelphia, Office of the Director 60/06/25 ip
- 8007310061 Forwards 1E Insp Rept 50 277/80-17 on 800604-05 No CARLEON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/26 2pp
- --B007310063 IE insp Rept 50-27//80-17 on 800604-05 No noncompliance noted Major areas inspected MSIV pnoumatic control manifolds & mainsteam & feedwater sys FINMEL.A. BASSANI.A. Region i, Philadelphia. Office of the Director EUNETER.S D. Region i, Philadelphia. Reactor Construction & Engineering Support Branch 80/06/18 5pp
- 8007230163 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/06/27 2pp
- 8007250631 Responds to 1E Bulletin 80-08. "Examination of Containment Liner Penetration Holds " Each unit has 24 flued head penetrations w/total of 40 containment boundary butt welds between penetration sleeve & process piping DALTROFF: S L Philadelphia Electric Co 80/06/30 13pp
- 800723071A Ack receipt of 800512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-30 & 50-278/79-33 ORIER, BH R Region 1. Philadelphia, Office of the Director

- /230/22 Responds to NRC 800421 ltr re violations noted in IE losp upts 50-27//9-30 & 50-278/79-33 Corrective actions -ctures conducted u/persunnel & procedure for data sheet -vised
- ALLAGIER. + W Philadelphia Electric Co 80/05/12 5pp
- 7330/30 forwards IE Insp Repts 50-277/79-30 & 50-2/8/79-33 on 91201-11 & notice of violation. Apps A A B RHHER. F. J. Region I. Philodelphia. Reactor Operations Nuclear upport Branch 80/04/21 . Eq.
- 7770792 Notice of violation, App A. from insp on 791201-31 Region 1. Philadelphia, Office of the Director 80/04 80/04/16 ip
- 7230/34 Hutice of violation.App D.from insp on 791201-31 Portions 1thheld (ref 107fR2 770) Region 1. Philadelphia, Office of the Director 80/04/16 1p
- 7230736 IE Insp Repts 50-2/7/79-30 & 50-2/8/79-33 on 791201-31 loncompliance noted failure to follow radiation protection equiroments & to record reactor water chloride data scientarity Portions withhold (ref 10CR2 790) REEMMANT G . BLOUGHA R Region i, Philadelphia, Gefice of the irector MCCAME.E. C Region 1, Philadelphia, Reactor Operations luciear Support Branch 80/04/16, 10pp
- 10197 Ack receipt of 800509 ltr informing NRC of steps taken to rect violations noted in IE Insp Repts 50-277/79-09 & 278/79-10 Region 1. Philadolphia, Office of the Director
- 7210215 Responds to NRC 800416 ltr ro violations & deviation oted in IE Insp Repts 30-277/79-09 & 50-278/79-t0 orrective actions meetings hold on each shift to inform sperators of plant status & any unusual plant conditions ALTRO-1.8 L. Philadelphia Electric Co. 60/05/09 Opp
- 7.10226 Forwards If Imap Repts 50-277//9-09 % 50-2/8/79-10 on 9019 50 % notices of violation & deviation RICR.II H Region i. Philadelphia, Office of the Director 0/44/16 2pp
- 7210232 Notice of violation from insp on 790319-30 Region 1, Philadelphia, Office of the Director
- 72102.15 Natice of deviation from insp on 790717-30 Region L. Philadelphia, Office of the Ourector E0/02/14 in
- ·/RIG307 II. Insp Repts 50-277/79-09 & 50-2/8/79-10 on 790319-30 encompliance noted Pailure to provide adequate retraining regram for nonlicensed personnel & failure to perform GA undits NNTFR, D. R. MARTIN, T. T. GAOL LARDD, T. I. Region i. Philadelphia. Iffice of the Director 80/02/14 71pp
- 10547 Responds to IC Bulletin 80 ii Masonry walls in proximity to having attachments from safety-rolated piping & equipment oblined in App A Justification for re-evaluation criteria I be nubmitted within 160 days Affidavit encl TROFF, U.L. Philadelphia Clectric Co. 80/07/08 18pp
- 250811 Responds to IE Bulletin 80-10 re contamination of tradioactive sys & resulting potential for unmonitored, ontrolled release of radioactivity to environ Mod gram initiated for listed filehilfied sys TROFF-5 L Philadelphia Electric Co 80/07/02 5pp
- 40430 Confirms oral antification that 20-day period for completing to required by Item 2 of IF Bullwith 80-17 started 1708 NRC lirebeing project menager should be notified if t woold cause sewere impact on power reliability ER.B H. Region 1. Philadelphia. Office of the Director 200000 0//09
- 200560 Requests extension until 200809 for outage to perform acram ts on Unit 3. required by 18 Dullstin BO-17, "Failure of of 183 Control Rods to Fully linert During Stram at BHR " LAMMER, J.W. Philadelphia Electric Co. 20/07/23 2pp
- priodic operating reports & related correspondence
- 110414 Forwards "Environs Radiation Monitoring Program, 1979 & isological Regional Environ Monitoring Program Rupt 15, 19 "
- LSEY, W B Philadelphia Clertric Co 80/07/08 ip

17310417 "Environa Radiation Monitoring Program, 1979 " Interex Corp 80/05/31 102pp

- --8007310420 "Radiological Regional Environ Monitoring Program Rept 15, * Radiation Management Corp 80/05/31 110pp
- 8007180419 Forwards monthly operating repts for June 1980 COONEY.H J Philadelphia Electric Co 80/07/10 ip
- --BOO7180433 Monthly operating repts for June 1980 ALDEN.W M Philadelphia Electric Co 80/07/10 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007080216 RO on 800329, RHR motor failed Caused by failure of lower guide bearing Instructions issued to operate RHR sys at full flow conditions Fans on motor shaft ends being replaced Failed motor replaced w/new motor COONEY. M J Philadelphia Electric Co 80/06/30 2pp
- 8007210403 RO-2-80-11/1P on 800714 diesel generator cardox sys vapor pilot valve was found ciosed Caused by failure to properly clear safoty permit on 800730 Vapor pilot valve locked open ULLRICH.N T Philadelphia Electric to 80/07/15 2pp
- 8007280649 RD 2-80-12/1P on 800721, while testing Unit 2 during refueling outage, scram backup valves in air supply to control rod drive scram valves failed Caused by design error Manual venting provided ULLRICH, W T Philadelphia Electric Co 80/07/22 2pp
- 8007300275 Discusses deficiency reported 800721 re installed solenoids of backup scram valves No immediate licensing or enforcement action required Deficiency should be corrected as soon as possible EIGENHUT, D Q Division of Licensing BO/07/22 2pp
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 F Becurity, medical, emergency & fire protection plans
- 8007140361 Forwards input for fire protection review re fire detection, water suppression, combustable control, gas suppression, fire doors to interior hose stations
 IMALLR E Brookhaven National Laboratory 80/06/20 Spp
- 8007230018 Forwards summary of 800603 meeting w/util in King of Prussia.PA re proposals to moet Tech Spec requirement in health physics staffling area SMITH-9 H Region 1. Philodelphia. Fuel Facility & Materials Safety Branch 80/06/27 3pp
- --B007230021 Summary of B00603 meeting w/util in King of Prussia,PA re progussis to meet Tech Spec requirements in health physics staffing area SERADIAN.J A Region 1. Philadelphia, Office of the Director B0/06/03 lp
- 8007230126 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mpt personnel at Pacilities EIBENHUT.D @ Division of Licensing 80/07/11 2pp
- O Adjudicatory correspondence
- 8007080086 Proposed findings of fact & conclusions of law responding to ASLAB questions on Battelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges suspension of OLs Gertificate of Svr encl KEPFORD.C Environmental Coalition on Nuclear Power 80/06/18 12pp
- B0070B00A6 Response to ASLAB request re Deficiency i Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated.

 CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- BOO708004B Proposed findings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Perkins rationals & urges development of further evidence re Pallure mechanisms & human factors CAPLAN,R Ecology Action of Obwege BO/04/20 App
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 6 Division of Licensing 80/06/25 89pp

- 80070B0001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ASLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK, B M Hearing Branch 4 80/07/03 58pp
- ~-B0070B0003 Preposed corrections to B00226 transcript BORDENICK.O M Hearing Branch 4 B0/07/03 2pp
- ~-B0070B0006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order inclusion is consistent w/ALAB-509.ALAB-340 & ALAB-362 Certificate of Svc encl BORDENIC, K Hearing Branch 4 80/07/03 7pp
- 8007i00258 Order granting Ecology Action of Oswego motion to file 800620 submission re generic radon issue BIGHOP.C J Atomic Safety and Licensing Appeal Panel 60/07/07
- 8007310128 Response in support of NRC E00703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLAN.R Ecology Action of Oswego 80/07/16 13pp
- 8007250353 Forwards revised Pages 7 & 16 to liconsees reply to proposed findings of fact submitted by other parties filed B0071B Revised pages required to correct typographical errors Svc list encl TRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge 80/07/21 1000

H General correspondence

- 8007020197 Requests consideration of site visit by Atomic energy Council of Taiwan on 800825-24 Council interested in observing waste mat activities Copperation will be major contribution to NRC exchange arrangement LAFLEUR, J D Assistant Director for International Copperation 80/05/13 Spp
- 8007140115 Ack receipt of 800423 ltr re public announcement for recent meeting at facility FEMA will be holding public meeting later in the year at which time public will have opportunity to express views re emergency plans GRIMES.B K Emergency Preparedness Program Office 80/06/09 1p
- ~-8007140118 Ack receipt of 800424 ltr expressing concern re arrangements for recent moeting at facility FEMA has responsibility for assessing emergency planning & will conduct meeting when plans are finalized DIRCKB, U J Office of the Executive Director for Operations 80/04/02 2pp
- 8007110517 Ack receipt of GL Berker 800430 1tr re concerns about amergency planning Forwards NUREG-0654 & NUREG-0396 M/o GRIMES, B Emergency Preparodness Program Office
- 8007280549 Responds to 800520 ltr re JL & WB Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for facility emergency planning meeting issued on 800331 W/Randell ltrs DIRCKB, W J Office of the Executive Director for Operations 80/07/02 7pp

I Financial information

- 8007010138 Responds to 800605 ltr to Q Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, R Hearings Division 80/06/19 lp
- P Operating licenso stage documents & correspondence
- 8007230028 Bummary of 800207 meeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance critoria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Bystems Branch 80/02/21 31pp
- 8007140641 Advises that dates of responses to 790927 generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Hatch 1 & 2 Rept on valve operability program required only for plants desiring to justify unlimited purging VERRCULI.O M Operating Reactors Branch 4 80/06/05 1p

- 8007170581 Confirms 800619 mgt meeting to be held at Carility to regulatory Appformance
 GRIER, B H Region 1, Philodelphia, Office of the Director
 BO/06/16 1p
- 8007020510 Advises that Class III fec is required for review of HQO&L application for amond of licenses DPR-44 & DPR-56 Request involves redistribution of health physics functions & is considered to be of safety dignificance DIGGS.R M. License Fee Management Branch 80/06/18 1p
- B007100155 Requests technical assistance for review of 800523 & 0607 proposed Tech Spec changes re electrive mgt & obsite health physics functions (urrent Tech Specs & util 1trs ent.)
 NOVAK,T Assistant Director for Operating Reactors 80/06/19 to
- --- BO0710015B Current forh Specs Pages 247 through 846 re administrati Philadelphia Electric Co 79/09/20 App
- 8007170054 Dutlines NRC understanding of status of use of hafnium to control rod blades Amend 70 to License DPR-44 authorized use Util withdrew 790921 request following amend issuance REID.R W Operating Reacture Branch 4 80/05/25 2pp Operating Reactors Branch 4
- 8007180119 Requests that util propose amends to facility Tech Specs 'incorporate currently installed seismic instrumentation & associated surveillance requirements Sample Tech Specs reflecting current NRC requirements encl NOVAK.T M Assistant Director for Operating Rooctors 80/07/01
- --8007180123 Sample Tech Specs Pages 3/4 3-46 through 3/4 3-48 for seismic monitoring instrumentation # General Electric Cn 78/04/Q1 3pp
- 8007280342 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation NOVAK,T M Assistant Director for Excensing 80/07/10 2pp
- 8007240238 Forwards Amends 71 & 67 to Licenses DPR-44 & DPR-56, respectively, safety & evaluation & notice of issuance & availability REID,R W Operating Renoters Branch 4 80/07/15 2pp
- --8007240242 Amends 71 % 69 to licenses DPR-44 % DPR-96 respectively, clarifying definition of operable % adding general limiting conditions for operation % action statements for Tech Specs REID.R W Operating Reactors Branch 4 80/07/15 30pp
- --8007240249 Safety evaluation supporting Amends 71 & 69 to Licenses DPR-44 & DPR-56 respectively * Office of Nuclear Reactor Regulation, Director 60/07/19 3
- --B007240251 Notice of issuance & availability of Amonds /; & 69 to Licenses DPR-44 & DFR-56 respectively REID.R W Operating Reactors Branch 4 RO/O//th 2pp
- B007180443 Forwards application for amend of facility OLs Application requests changes to Tech Specs recontrol tod drive return line mads containment isolation value mode & correction of typographical error Check encl to cover fee for application URADLEY. C.J. Philadelphia Electric Co. 80/07/16 ip
- 8007280384 Forwards application to amend OL & proposed temporary tha to fach Specs
 BRADLEY,E J. Philadelphia Clastric Co. 80/07/29 1p
- --8007280388 Application to amend License DPR-56, authorizing tempora change to Tech Specs which would allow relief from requirement to remove unit from svc if inoperable snubbor cannot be repaired within 72-h (Pritirate of Syr pocises) KEMPER, J 9 Philadelphia Electric Gu 80/07/10 6pp

- B007300553 Confirms NR(B00719 oral authorization to temporarily amend Tech Spec 3 11 02 (honge allows inoperability of snubber 10-08-5-44 for 10 days to permit repair Formal amend, safety evaluation & notice will be forwarded NOVAK.T M Assistant Director for Operating Reactors B0/07/R2
- o Inspection reports: IE Bulletins & correspondence
- 8007140462 Forwards IE Dulletin 80-13 "Cracking in Core Spray Spargers" Written response required ORIER, B H Region 1, Philodolphia, Office of the Director BD/05/12 1p
- 8007020035 Ack recespt of BOUS13 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 90-277/80-06 k 50-278/80-06 BRUNNER, E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/28 ip
- --8007020041 Responds to NRC 800421 ltr re violations noted in 1E Insp Repts 50-277/80-06 % 50-278/80-06 Corrective actions personnel reminded of work documentation importance & Tech Specs data recorded OALLAGHER, J. W. Philadelphia Electric Co. 80/05/13 ... 3pp
- --8007020049 Forwards IE Insp Repts 50-277/80-06 % 50-278/80-06 on 800317-21 % notice of violation 8RUNNER, E J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/21 29
- --8007020060 Notice of violation from insp on 800317-21
 Region 1, Philadelphia, Office of the Director 80/04/19 200
- ---B007020070 IE Insp Repts 50-277/80-06 & 50-278/80-06 on B00317-21
 Noncompliance noted util failed to document two surveyllance
 tests & corrortive maint & failed to record Tech Specs data
 BLUMMBERG.N. Region i. Philodelphia. Office of the Director
 GREENMAN.E G Region L. Philadelphia. Reactor Operations Nuclear
 Support Branch 80/04/18 12pp
- 8007020143 Forwards IR Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required GRIER.D H Region I. Philadelphia. Office of the Director 80/05/28 lp
- 8007010310 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER, B H Region I. Philadelphia, Office of the Director 80/03/29 lp
- 8007010378 Responds to 1E Bulletin 79-14, "Grismle Analysis for As-Bullt Safety-Related Piping Sys "Bechtel Power Corp is performing engineering review & analyses for safety-related piping Unit 3 rept will be submitted by 800615 DALTROFF, S.L. Philadelphia Electric Co. 80/06/03 1p
- 8007210600 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No writton response required ORIER, B H Region I. Philadelphia, Office of the Director 80/06/10 lp
- 8007020072 Responds to IE Bulletin RO-O6. "Engineered Bafety Features (ESF) Reset Controls " Encl App A identifies any corrective action planned for safety-related equipment which does not remain in emergency mode upon reset of signal OALTROFF, S.L. Philadelphia Electric Co. 80/06/11 Spp
- 8007140267 Forwards IE Bulletin 80-14. "Degradation of BWR Scrom Discharge Vol Capability " Written response required GRIER.B H Region 1. Philodelphia, Office of the Director 80/06/12 ip
- 8007180105 Submits reply to IE Aulirtin 80-13 re tracking in core spray spragers No crarks were found in insp of Unit 2 Insp of Unit 3 will be performed during next refueling outage DALTROFF, S. L. Philadelphia Electric Co. 80/06/13. 2pp
- 8007180117 Submits reply to 1E Bulletin 79-14 re seismic analysis for as-built safety-related piping sys All Unit 3 safety-related piping is operable in present condition DALTROFF S.L. Philadelphia Electric Co. 80/06/13 3pp
- 8007170307 Updates 800413 environ qualification rept for Class 1E electrical equipment in response to IE Oulletin 79-01B forwards revised pages & info re high energy/one break profiles & LOCA profiles for reactor bldgs W/o ancis DALTROFF, S.L. Philadelphia Electric Co. 80/06/17 2pp

- 8007020703 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (CNS) W/Loss of Offsite Power " Written response required ORIER, B.H. Region 1, Philadelphia, Office of the Director BO/04/18 ip
- B007020492 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ORIER, I H. Region 1, Philadelphia, Office of the Director B0/06/20 ip
- B007160836 Forwards IE Circular SO-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region i, Philadelphia, Office of the Director B0/06/24 lp
- 8007210228 Forwards IE Info Notice 80-24, "Low Level Radwaste Burlal Criteria" No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/04/25 ip
- B007230163 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosembunt inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.I H Region I. Philadelphia. Office of the Director 80/06/27 2pp
- 8007230631 Responds to 1E Dulletim BO-OB. "Examination of Containment Liner Penetration Welds " Cach unit has 26 flued head penetrations w/total of 40 containment boundary butt welds between penetration sleeve & process piping DALTROFF,S L Philadelphia Electric Co BO/O6/30 13pp
- B007230716 Ack receipt of B00512 ltr informing NRC of steps taken to correct violations noted in IE lnap Repts 50-277/79-30 & 50-278/79-33 ORIER, II H Region i, Philadelphia, Office of the Director 80/07/01 ip
- --8007230722 Responds to NRC BO0421 ltr re violations noted in IE Insp Repts 50-277/79-30 & 50-278/79-33 Corrective actions lectures conducted w/personnel & procedure for data sheet GALLAGHER, J W Philadelphia Electric Co 80/05/12 5pp
- --8007230730 Forwards 1E Insp Repts 50-277/79-30 & 50-278/79-33 on 791201-31 & notice of violation. Apps A & B BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/21 Spp
- --8007230732 Notice of violation. App A. From insp on 791201-31
 * Region 1, Philadelphia, Office of the Director 80/04
- --B007230734 Notice of violation. App B, from insp on 791201-31 Portions withheld (ref 10CFR2 790)

 * Region 1, Philadelphia, Office of the Director 80/04/16 ip
- --8007230736 IE Insp Repts 50-277/79-30 & 50-278/79-33 nn 791201-31 Nuncompilance noted failure to follow radiation protection Nuncompilance noted failure to follow radiation protection requirements & to record reactor water chloride data accurately Portions withheld fref 100FR2 790 GREENHANLE G. DLDUGH.A R. Region 1. Philadelphia. Defice of the Director MCCABE.E C. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/16 10pp
- 8007210197 Ack receipt of 800309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-09 & 50-278/79-10 GRIER, B H Region 1, Philadelphia, Office of the Director 80/07/02 ip
- --8007210215 Responds to NRC 800416 ltr re violations & deviation noted in IE insp Repts 30-277/79-09 & 30-278/79-10 Corrective actions meetings held on each shift to inform operators of plant status & any unusual plant conditions DALTROFF,S L Philadelphia Electric Co 80/05/09 8pp
- --8007210226 Forwards IE Insp Repts 50-277/79-09 & 80-278/79-10 on 790319-30 & notices of violation & deviation GRIER.B H Region 1, Philadelphia. Office of the Director 80/04/16 2pp
- --8007210232 Notice of violation from insp on 790319-30
 * Rogion 1. Philadelphia, Office of the Director 80/02/14 Дрр,
- --8007210235 Notice of deviation from insp on 790319-30 * Region 1, Philadelphia, Office of the Director

- --8007210307 IE Insp Ropts 50-277/79-09 & 50-278/79-10 on 790319-30 Noncompliance noted failure to provide adequate retraining program for nonlicensed personnel & failure to perform GA audits
 HUNTER.D R , MARTIN.T T , QAGLIARDD.T E Region i. Philadelphia. Office of the Director BO/Q2/14 71pp
- BOO7210547 Responds to IE Bulletin BO-li Masonry walls in proximity to or having attachments from safety-related piping & equipment identified in App A Justification for re-evaluation criteria will be submitted within 160 days Affidavit encl DALTROFF, & L Philadelphia Electric Co GO/Q7/Q2 18pp
- B007250511 Responds to IE Bulletin 80-10 re contamination of nonradioactive sys & resulting potential for unmonitored, uncontrolled release of radioactivity to environ Mod program initiated for listed identified sys DALTROFF.8 L Philadelphia Electric Co 80/07/02 5pp
- 8007240430 Confirms oral notification that 20-day period for completing tests required by Item 2 of IE Bulletin 80-17 started 800708 NRC licensing project manager should be notified if test would cause severe impact on power reliability ORICE, B H Region 1, Philadelphia, Office of the Director 80/07/09 2pp
- B007280560 Requests extension until 800807 for outage to perform scram tests on Unit 3.required by IE Bulletin 80-17. "Faiture of 76 of 105 Control Rods to Fully Insert During Scrom at BHR "OALLAGHER, J W Philadelphia Electric Co 80/07/23 2pp
- A Periodic operating reports & related correspondence
- ROD7310414 Forwards "Environs Radiation Monitoring Program, 1979 & Radiological Regional Environ Monitoring Program Rept 15, 1979 "
 WILLEY, W. B. Philodelphia Electric Co. 80/07/08 ip
- ~~8007310417 "Environs Radiation Monitoring Program, 1979 "
 # Interex Corp 80/05/31 102pp
- --B007310420 "Radiological Regional Environ Monitoring Program Rept 15, 1979 "
 - # Radiation Management Corp 80/05/31 110pp
- 8007180419 Forwards monthly operating ropts for June 1980 COONEY, M J Philadelphia Electric Co 80/07/10 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8007070332 LER 80-031/03L-0 on 800605, during surverilance test, pressure switch P8 3 5 12C found 0 3 psig above Tech Spec limit.
 Caused by setpoint drift Switch recalibr, tested & returned to suc CORNEY, M J Philadelphia Electric Co 80/06/30 lp
- 8007080216 RD on 800329,RHR motor failed Caused by failure of lower guide bearing Instructions issued to operate RHR sys at full flow conditions Fana on motor shaft ends being replaced Failed motor replaced Whee motor CO
- 8007210378 LER 80-014/03L-0 on 800608, while performing 9T 6 9, valve MO 3-10-268 failed to close after stroked open Caused by mechanical problem in valve, MD 3-10-268 to be disassembled & repaired COONEY, M J Philadeiphia Electric Co 80/07/14 ip
- B007280649 RD 2-80-12/IP on 800721, while testing Unit 2 during refueling outage, scram backup valves in air supply to control rod drive scram valves failed Caubed by design error Manual venting provided ULLRICH, H. T. Philadelphia Electric Co. 80/07/P2 2pp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr resemps ency response facilities at reactor situs Sites w/approval to use closed-circuit televiston link w/technical support ctr listed GRUTCHFIELD, D.M. Operating Reactors Branch 5 80/07/07. 2pp

- BOO7030184 Forwards revised emergency plan Plan is based on existing metorological capabilities & reflects critoria of NUREG-0654 York County-VA emergency plan enci Plans withhold per Privacy Act & nivaliable in Central Files only BAUM.E A Virginia Electric & Power Co HO/06/30 2pp
- 8007170412 Forwards revised huclear security personnel training & qualification program in response to 800515 lt: Program withheld (ref 100FR2 790)
 SYLVIA, B R Virginia Electric & Power Co 80/0//14 ip
- 9 Adjudicatory correspondence
- BO07310243 Forwards Commission B00327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action referre protection for electrical cables EISENHUT, D G Division of Licensing B0/06/25 89pp
- 80075i0339 Order granting extension until 800723 for Commission to elect whether to review decision taken under 100FR2 206 on request for enforcement action, DD-80-23 MOYLE, J.C. Office of the Secretary of the Commission 80/07/09 to
- 80073004i2 Advisus that effective 80080i, address for coalition will be 1505-C Dilve St. Oreensboro, NC 2780i Related correspondence ALLEN, J North Anna Environmental Coalition 80/07/15 ip
- H Generai correspondence
- B007150047 Responds to B00327 itr to President Carter re granting VEPCD authority to build another nuclear plant Discusses util plants.operating & under const & relative costs of coal vs nuclear energy YOUNGBLOOD. B J Operating Reactors Branch i 80/05/13 Spp
- B007070039 Forwards B00620 Director's Decision DD-80-23 denying B0021B.P2.0425 & 0525 requests for action FR notice and DENTON H R Office of Nuclear Reactor Regulation, Director B0/06/20 Epp
- --8007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON: H R Office of Nuclear Reactor Regulation, Director 80/06/20 25pp
- --8007070069 FR notice of issuance of 800620 Director's Decision DD-80-2 denying 800218,22,28,0425 & 0525 requests by North Anna Environ Coalition for action DENTON: HR Office of Nuclear Reactor Regulation, Director 80/04/20 2pp
- --8007070075 Requests amend to 800218 ltr following discovery of addl problems in stamm generator Facility should be kept shut down pending resolution of noise, secondary chemistry, turbine cracks & formineralizer problems ALLEN, J. North Anna Environmental Coulition 80/02/22 ip
- --8007070079 Requests action concerning defective demineralizer dusign, related corrosion & cracking in stoom generators & turbing discs Commends NRC decision to require EIS re experimental replacement of steam generators
 ALLEN.J North Anna Environmental Coalition 80/02/18 4pp
- J Insurance & indemnity information
- 8007150490 Forwards Endorsements 28 & 27 to NFLIA Policy NF-240 PIERCE, D A Marsh & McLennon, Inc., M & M Nuclear Consultants, inc Div 80/07/10 3pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Teth Spec Changes providing , for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution anci for guidance EISENHUT.D Q Division of Licensing 80/06/11 62pp
- B007010422 Responds to NRC B00507 its re loss of offsite power Review of history reveals two partial losses of offsite power occurred
 BYLVIA, B R Varginia Electric & Power Co #80/06/26 3pp
- 8007010430 Confirms agreement w/NRC re review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur THOMAB, N N Virginia Electric & Power Co 80/06/26 App

- 17030171 Application for amend to Licenses DPR-32 & DPR-37 consisting if proposed changes to Tork Specs ERQUSON, J.H. Virginia Electric & Power Co. 80/06/30 3pp
- 007030ilD Ivaluation & proposed changes to Tech Specs Sections 3 3, 4 4 5 6 4 1,4 5 & 4 ti re containment spray bys * Virginia Clectric & Power Co HO/O6/30 62pp
- 17230001 Requests submittal of application for amend to license ensisting of fech Spoc changes & license conditions PAR lodel Tech Spocs & Model License conditions for TMI-2 essens tearned Lotegory A items encl for guidance IGENERATION OF LICENSING 80/07/02 69pp
- 7080419 Forwards addl info re new fuel storage area for proposed hango 85 to Yerh Specs.por recent telcon YLVIA.B.R. Virginia Electric & Power Co. 90/07/03 3pp
- 7100273 Submits addl info re implementation of short-term Lessons carned requirements Status of remaining Category A items, id-up status of design & installation of Category B mads & chedule for smillementation encl Forwards drawings
 YEVIA.D R Virginia Electric & Power Co 80/07/07 180pp
- 0071002/7 "bump Pump Discharge Piping Auxiliary Bldg to Containment " * Stone & Webster Engineering Corp 79/05/15 1p
- 007100200 "Sump Pump Discharge Piping Auriliary Bldg to Containment " * Stons & Wobster Engineering Corp 77/10/24 lg
- 007100204 "Flow Diagram Doron Recovery Sys " Sheet 1 M Stone & Webster Engineering Corp 80/07/07 Ip
- 007100288 "Fine Diagram Containment Atmosphere Cleanup Sys " w Stone & Webster Engineering Corp 77/10/22 11p
- 007100293 "Flow Diagram Waste Disposal Sys " Sheet * Stone & Webster Engineering Corp 80/07/07
- 107100298 "Flow Diagram Waste Disposal Sys " Shet # Stone & Webster Engineering Corp 80/07/07
- 307100303 "Ventilation Thermal Recombiner"
 # Blone & Webster Engineering Corp 80/04/07 1p

- 10/100313 "P&ID liquid Sampling Coolers " Sheet 3 of 5 v NUS Curp 80/05/05 ip
-)0/1007R1 "PMID Liquid Sampling Panel " Sheet 4 of 5 m NUS Corp (00/05/05 ip
- 10/100323 "PhiD:liquid Sampling " 5 of 5 * NUS Corp 80/05/05 1p NUS Corp
- NOTIOOJ29 "PRID Containment & Air Sampling Sys " Sheet 1 of 1 * NUB Corp (80/05/05 1p
- 107100335 "Process Flow Diagram Liquid Sampling " Sheet 1 of 2 * NUS Corp 80/05/29 1p
- #07100338 "Process Flow Diagram Liquid Sampling " Sheet 2 of 2 * NUS Corp 40703722 1p
- 07100347 "Protuss Flow Diagram Containment Air Sampling " * NUS Corp 80/04/14 Ip
- 0/100351 "Qeneral Arrangement Auxiliaty Bldg.Drumming Room Plan. Elevation 274 Ft " Bheet 1 * NUS Corp #D/05/29. 1p
- 07100059 "General Arrangement Auxiliary Bidg Drumming Room Section & Details " Sheet 2" NUS Corp 80/05/29 Ip

- --8007100365 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps. Plan Elevation 244 ft, & Inches & Section " Sheet 1 * NUS Corp 60/05/29 Ip
- --8007100371 "F&ID Liquid Sampling " Sheet 1 of 5 4 NUS Corp 80/05/05 1p
- --8007100375 "P&ID Liquid Sampling " Sheet 2 of 5 * NUS Corp 80/05/05 ip
- --8007100380 "P&ID Liquid Bampling Program " Sheet 3 of 5 * NUS Corp 80/05/05 1p
- --B0071003B2 "P&ID Liquid Sampling Panel " Sheet 4 of 5 * NUS Corp B0/05/05 lp
- --8007100387 "P&ID Liquid Sampling Panel " Sheet 5 of 5 # NUS Corp 80/05/05 ip
- --8007100391 "P&ID Containment Air Sampling Sys " Sheet 1 of 1 * NUS Corp 80/05/05 1p
- --8007100403 "Process Flow Diagram Liquid Sampling " Sheet 2 of 2 * NVS Corp 80/05/22 ip
- --B007100407 "Process Flow Diagram Containment Air Sampling " Sheet 1 of
 - * NUS Corn 80/04/14 1p
- --BO07100409 "General Arrangement Auxiliary Bldg. Drumming Room Plan. Elevation 27 Ft. 6 Inches " Sheet 1 * NVS Corp 80/05/29 1p
- --8007100414 "General Arrangement Auxiliary Bldg, Drumming Room, Section & Details " Shert 2 * NUS Corp 80/05/29 1p
- --8007100415 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps Plan.Elevation 27 Ft. 6 Inches & Section " Sheet 1 + NUS Corp 80/05/29 1p
- 8007210435 Bubmits update to status of evaluation of asymmetric LOCA loads on reactor pressure vessels & references Phase-C results.WCAP-9748, submitted by Westinghouse on 800430 SYLVIA.D R Virginia Electric & Power Co 80/07/14 2pp
- 8007310421 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Requosts extension of review period to 800915 to review stress corrosion cracking BRDMN:8 C Virginia Electric & Power Co 80/07/21 App
- G Inspection reports, IE Bulletins & correspondence
- 8007240230 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/05/08 2рп
- 8007020200 Forwards 1E Info Natice 80-22. "Breakdowns In Contamination Control Programs " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 8007:40169 Discusses 800422-23 radiation survey which revealed radiation levels on trunk surface exceeding regulatory limits Forwards notice of violation & notice of proposed imposition of civil penalties STELLD.V. Office of Inspection & Enforcement. Office of the Director 80/05/28 3pp
- --8007140174 Notice of proposed imposition of civil penalties in amount of \$8.000 for item of noncompliance re radiation levels on truck surface exceeding regulatory limits

 ** Office of Inspection & Enforcement, Office of the Director 80/05/28 lp
- 8007210477 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28,

- 8007010239 Forwards [E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response Jequired O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29 is
- 8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 20p
- 8007160307 Forwards IE Info Notice B0-27. "Degradation of Reactor Coolant Pump Studs " No specific action of response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/11
- 8007090057 Forwards revision to Page 2 of 800611 response to §E Bulletin 80-12, "Decay Heat Removal Sys Operability " BYLVIA, B R Virginia Electric & Power Co 80/06/16 2pp
- B007090423 Responds to IE Bulletin 79-018, "Environ Classification of IE Equipment " Class IE electrical equipment reviewed to ensure functioning during postulated accident Review of Action Items 1,2 & 3 provided in encl repts W/o encl repts BYLVIA, B R Virginia Electric & Power Co B0/06/16 3pp
- 8007020757 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power " Written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/19
- 8007020434 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- B007150462 Ack receipt of IE lnsp Repts 50-280/80-16 & 50-281/80-i7 No proprietary info Corrective actions to Enforcement Action 80-28 strengthened radwaste monitoring program implemented Radwaste section restaffed BYLVIA,D R Virginia Electric & Power Co 80/06/20 Spp
- --B00715046B Forwards IE Insp Repts 50-280/80-14 & 50-280/80-17 on 800425 No noncompliance noted
 O'REILLY, J P Region 2, Atlanta, Office of the Director B0/05/28 2pp
- ---8007150471 IE Insp Repts 50-280/80-16 & 50-281/80-17 on 800423-25. No noncompliance noted Major areas inspected shipment of radwaste for burial including shipping paper requirements, labeling.placarding & raduation levels BROWN,R A. POTTER.J P. STOHR.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/05/08 9pp
- 8007160543 Forwards payment of civil penalty per NRC 800528 notice of proposed imposition of civil penalties re IE Insp Repta 50-280/80-16 & 50-281/80-17 Viplations based on radwaste shipment arriving at site, w/excessive radiation SYLVIA.B R Virginia Electric & Power Co 80/06/20 tp
- 8007170119 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required, D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 ip
- 8007230270 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007210030 Responds to unresolved items in IE Insp Repts 50-280/80-i4 & 50-281/80-i5 Relieves weld repair of Limitarque enclosure on MOV-FW-I510 was performed per specified procedures Nondestructive test exam will be performed SYLVIA, B R Virginia Electric & Power Co 80/07/01 Spp
- BOO71101B9 Forwards reactor coolant pump support drawings & description of pump support disassembly & insp procedures in response to NRC BOO707 ltr SYLVIA.B R Virginia Electric & Power Co 80/07/07 2pp
- ---8007110173 "Reactor Coalant Pump Supports General Arrangement "
 * Stone & Webster Engineering Corp 78/07/20 1p

- --9007(10194 "Real for Coulent Pump Supports Detoils" Sheet 2 * Stone & Webster Engineering Corp. 79/07/30 - IA
- --8007110196 "Reactor (volant Pump Support Details " Sheet l * Stone & Webster Engineering Corp 70/07/30 Ip
- BOO7170334 Forwards "IE Bulletin An-Day Review." in response to ac required by Item 4 of IE Bulletin BO-LL. "Hasonry Wall Design " Rept available in Central Files only BYLVIA:B R Virginia Electri: & Power Co BO/07/07 Ip
- 8007250345 Forwards response to TE Bulletin 80-00, "Exam of Contai Liner Penetration Welds" Penetration ussemblies of flued head forging design were used for politrations listed in Tables 1 & 2 for North Anna SYLVIA, B R Virginia Electric & Power (o 80/0//07 7pp
- BOO7290840 Responds to IE Bullotin 80-10 re contamination of normalizative sys Lists sys considered normalizative but potentially redicactive through interfaces w/radicactive sys All discharge paths are sampled or monitured BYLVIA, B R Virginia Electric & Power Ce 80/07/0/ 2pp
- 6007:10336 Responds to Items ? & 3a of 1° Bullntin /9-27. "Loss of Class IE Instrumentation & Control Power Sys Bus During Operation " Unit 1 inverter trip was not related to fullure modes described in Bulletin SYLVIA.B R Virginia Electric & Power Co. 10/0//09 2pp
- B007;70529 Forwards response to NRC 80061B ltr re violation noted i 1E Insp Repts 50-280780-17 % 50-281780-23 Response withheld (ref 10CFR2 790) BYLVIA,R R Virginia Electric & Power Co 80707714 ip
- 8007290220 Forwards response to NRC 800627 ltr re violations noted IE lnsp Repts 50-280779-70 & 50-281779-80 Corrective action all release procedures reviewed & changed, as necessary Attachment 2 withheld (ref 100 FR2 790)

 SYLVIA, B R Virginia Electric & Power Co 80707721 4pp
- R. Periodic operating reports & related correspondence
- BOO7170389 Forwards monthly operating repts for June 1980 SYLVIA.B R Virginia Electric & Power Co 80/07/14 tp
- --8007170391 Monthly operating ropts for June 1980
 DUNN:8 D Virginia Electric & Power Co 80/07/07 41pp
- S Reportable occurrences, LERs & related correspondence
- B007230362 PNO-II-ED-09B on B00603, unit tripped when fire disabled one of four instrument buses Plant in hot shutdown while licensee replaces transformer & dilutes boron concentration for restart Licensee issued prass release HEUSTER, E H. KELLOGG, P. J. Region 2. Atlanta, (Iffice of the Director B0/06/03 ip
- 8007010429 Forwards LER 80-032/03L-0 WILSON, J.L. Virginia Electric & Power Co. 80/06/26 ip
- --8007010442 IER 80-032/03L-0 on 800329, during testing of air ejector divert valve TV-5V-202, max operating air differential pressure exceeded rating of ASCO solenoid valve Caused by use of improper design criteria dering valve installation WILSON, J i Virginia Electric & Power Co 80/06/26 2pp
- 8097070389 Forwards LER 80-038/031-0 WILBON, J.L. Virginin Electric & Power Co. 80/07/03 1p
- --8007070397 LER BO-038/03L-0 on BO0610, during 100% power operation, isolation valve for IBR-TK-28 lepked during release of I-BR-TK-26 cousing unsampled release from tank B Caused by deterioration of valve disphragm Valve repaired.

 WILSON, J. L. Virginia Electric & Power Co. 80/07/01 Epp.
- 8007070224 Forwards LER BO-059/0,4L-0 WILSON J L Virginia Stectric & Power Co 80/07/0m 1p
- ---B007070229 LER 80-029/03L-0 on B0060's during normal operation vital 4 Sola failed, initiating automatic turbine rusbace Caused by failure of filtering capacitor in Gola transforme re-energized fransformer rophiced WIL60N.J. Virginia Electric & Power Co 8()

- B007210092 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FSAR Caused by use of incorrect sys vol Review will be performed to identify & analyse addl accidents
 SYLVIA.B R Virginia Ejectric & Power Co 80/07/02 4pp
- 8007140249 Forwards LER 80-039/01T-0
 WILSON, J L Varginia Electric & Power Co 80/07/08 ip
- --8007140259 LER 80-039/0)T-D on 800626, potential discovered for boron contentration nonconservatism during dilution accident w/RCS at reduced vol Analysis of boron dilution at cold & hot shutdown being evaluated by reactor vendor WILSON J L Virginia Electric & Fower Co 80/07/09 2pp
- 8007280507 Forwards LERs 80-043/03L-0 & 80-041/03L-0 W1L50N.J L Virginia Electric & Power Co 80/07/2 80/07/24 1p
- --8007280618 LER 80-043/03L-0 on 800703 during normal operation condenser inlet valve MOV-CW-106C would not close when operated from control room Caused by broken study allowing motor stator to back out WILEON, J. L. Varginia Electric & Power Co. 80/07/24 2pp
- 8007280629 LER 80-041/03L-0 on 800625,pipe stress re-anelysis indicated baseplate anchor bolts on hanger H-2 on line 12 inch -CC-27-121 & hanger H-9 on line 12 inch-CC-33-121 overstressed Mods to anchor bolts complete WILSDN.J L Virginia Electric & Power Co 80/07/24 2pp

V Operator Examinations

- 8007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructors are required to participate in program to maintain proficiency
 8YLVIA, B R Virginia Electric & Power Co 80/07/15 ip
- --8007170350 Revised. "Liconsed Operator Requalification Program " R Virginia Electric & Power Co 80/07/31 11pp
- DOCKET 50-201 SURRY POWER STATION. UNIT 2 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re emergency response facilities at reactor sites 91tes w/approval to use closed-circuit television link w/technical support ctr listed GRUTCHFIELB, D.M. Operating Reactors Branch 5 80/07/07 2pp
- 8007030184 Forwards revised emergency plan Plan is based on existing metorological capabilities & roflects criteria of NUREG-0454 York County, VA emergency plan encl Plans withheld per Privacy Act & evallable in Central Files only BAUN, E A Virginia Electric & Power Co 80/06/30 2pp
- B007170412 Forwards revised nuclear security personnel training & qualification program in response to B00515 ltr Program withheld (ref. ICCFR2 790)
 SYLVIA B R Virginia Electric & Power Co. B0/07/14 1p

O Adjudicatory correspondence

- B007310243 Forwards Commission B00527 memorandum % order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum % order UCB 771104 petition sought action re fare protection for electrical cables EIGENHUT.D © Division of Licensing B0/06/25 B9pp Division of Licensing
- 8007110339 Order granting extension until 800723 for Commission to effect whether to review decision taken under 100FR2 206 on request for enforcement action. DD-80-83 HDYLE-J C Dffice of the Secretary of the Commission 80/07/09
- 8007300412 Advises that effective 800801, address for coalition will be 1105-C Olive St. Greensboro. NC 27401 Related currespondence ALLEN.J North Anna Environmental Coalition 80/07/15 ip

H General correspondence

B007190047 Responds to B00927 ltr to President Carter re granting VEPCO authority to build another puclear plant Discusses util plants.operating & under const & relative costs of coal vs nuclear energy YOUNGDLOOD.B J Operating Reactors Branch 1 80/05/13 5pp

- 8007070059 Forwards 800620 Director's Decision DD-80-23.denying 800218, 22,0423 & 0529 requests for action FR notice encl DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/20 2pp
- --8007070064 Decision DD-80-23 denying 800218.22.28.0425 & 0525 requests by North Anna Environ coalition for action DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/20 25pp
- --8007070069 FR notice of issuance of 800620 Director's Decision DD-80-23 denying 800218.22.28.0425 & 0525 requests by North Anna Environ Coalition for action DENTON, H R Office of Nuclear Reactor Regulation. Director 80/06/20 2pp
- --8007070079 Requests action concerning defective demineralizer design, related corrosson & cracking in steam generators & turbine discs Commends NRC decision to require EIB re experimental replacement of steam generators ALLEN.J North Anna Environmental Coalition 80/02/18 4pp
- 8007020698 Responds to HB McDonald 1tr directed to DOE North Anna full power license issuance will be discussed w/Commission in Jul-Aug 1980 Burry is in shutdown condition due to seism piping supports mods & will return to power in Aug 1980 YDUNOBLDOD, B J Licensing Branch 1 80/04/25 1p
- operation of facilities
 DETANCOURT, B Energy, Dept of 80/06/05 2pp

J Insurance & indemnity information

- 8007:30490 Forwards Endorsements 28 & 27 to NELIA Policy NF-240 PIERCE, D A Harsh & McLennam, Inc . M & M Nuclear Consultants, Inc Div 80/07/10 3pp
- P Operating license stage documents & correspondence
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in docay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EIBENHUT.D G Division of Licensing 80/06/11 62pp
- B007210037 Advises that 790820 safety evaluation re Unit i mode correcting underpower capacity conditions on 480 volt emergency buses applies equally to Unit 2 Mode are acceptable VARGA:S A Operating Reactors Branch 1 80/06/20 2pp
- 8007010422 Responds to NRC 800509 ltr re loss of offsite power. Review of history reveals two partial losses of offsite power occurred BYLVIA, B R Virginia Electric & Power Co 80/06/26 3pp
- 8007010430 Confirms agreement w/NRC re review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur
 THOMAS.W N Virginia Electric & Power Co 80/06/26 App
- 8007030131 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Specs
 FERGUSDN.J H Virginia Electric & Power Co 80/06/30 3pp
- --8007030135 Evaluation & proposed changes to Tech Specs Sections 3 3. 3 4.3 6.3 8.4 1.4 5 & 4 11 re containment spray sys rformance Virginia Electric & Power Co 80/06/30 62pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spac changes & litense conditions PWR Madel Tech Speca & Madel license conditions for TMI-2 Lessons Learned Category A stems encl for guidance EISENHUT, D O Division of Licensing 80/07/02 49pp
- 8007080417 Forwards add1 info re new fuel storage area for proposed Change 85 to Tech Specs.per recent telcon BYLVIA.B R Virginia Electric & Power Go 80/07/03 3pp
- 8007100273 Submits addl info re implementation of short-term Leasons Learned requirements Btatus of remaining Category A items, mid-yr status of design & installation of Category B mods & schedule for implementation encl forwards drawings

 SYLVIA:B R Virginia Electric & Power Co 80/07/07 180pp

07230270 Forwards IE Bulletin 80-16. Potential Misapplication of O/2302() Orders it obtacts & 1152 Pressure Transmitters Weither A or D Dutput Codes ' Written response required O'REILLY, J P Region 2. Atlanta Office of the Director 80/06/27

07210030 Responds to unresalved items in 1E Insp Repts 50-280/80-14 & 50-281/80-15 Believes weld repair of Limitorque enclosure on MOV-FM-151D was performed per specified procedures. Nandestructive test exam will be performed SYLVIA.8 R Virginia Electric & Power Co 80/07/01 3pp

07:110:189 Furwards reactor containt pump support drawings & description of pump support disastembly & insp procedures. In response to NRC 800707 ltr SYLVIA,B R Virginia Electric & Power Co 80/07/07 2pp

-8007110193 "Reactor Coolant Pump Supports General Arrangement "
* Stone & Webster Engineering Corp 78/07/20 ip

-8007110194 "Reactor Coolant Pump Supports Details " Sheet 2 # Stone & Webster Engineering Corp 79/07/30 tp

-8007410196 "Roactor Coolant Pump Support Details " Sheet 1 * Stone & Webster Engineering Corp 70/07/30 1p

107170334 Forwards "IE Bulletin 60-Bay Review," in response to action required by Item 4 of IE Builotin 80-ii. "Masonry Wali Besign " Rept available in Central Files only SYLVIALB R Vieginia Electric & Power Co 80/07/07 ip

007250545 Forwards response to 1E Bulietin 80-08, "Exam of Containment Liner Penetration Helds" Penetration assemblies of flued head forging design were used for penetrations listed in Tables i & 2 for North Anna SYLVIA.B R Virginia Electric & Power Co BO/07/07 7pp

O07290840 Responds to IE Builetin BO-10 re contamination of nonradioactive sys Lists sys considered nonradioactive but potentially radioactive through interfaces w/radioactive sys Ail discharge paths are sampled or monitored SYLVIA.B R Virginia Electric & Power Co BO/07/07 2pp

3007i60664 Identifies proposed actions to be taken in response to IE Builetin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." Screening process will be used for Tech Spec sys. to identify significantly averstressed supports SPENCER: W.C. Virginia Electric & Power Co. 80/07/08. 3pp

3007110336 Responds to Items 2 & 3a of IE Bulletin 79-27, "Lose of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Unit i inverter trip was not related to failure modes described in bulletin BYLVIA.B R Virginin Electric & Power Cn 80/07/09 2pp

B007iB037i Submits clarification & addi info to 600708 ltr responding to LE Buljetin 79-id Approx 294 supports needed Screoning process will accompany determination of overstressed supports for mode exceeding 30 days BRCMN.S C Virginia Electric & Power Co 60/07/11 2pp

8007290365 Responds to 800708 discussions w/NRC re 800708 response to IE Bulletin 79-i4, "Seismic Analysis for As-Built Bafety-Reisted Piping Sys " Approx 294 supports identified to require installation BROWN.8 C Virginia Electric & Power Co 80/07/11 2pp Virginia Electric & Power Co BO/07/11 2pp

B007170329 Forwards response to NRC 800618 ltr re viblation noted in IE Insp Repts 50-280/80-1/ % 50-281/80-23 Response withheld (ref 100782 790)
SYLVIA:R R Virginia Electric % Power Co 80/07/14 ip

8007290720 Forwards response to NRC 800A/7 itr re violations noted in IE Insp Ropts NO-280/79-70 % SU-281/79-80 Corrective action all release procedures reviewed & changed as necessary Attachment 2 withhold (ref 10CFR2 790)

BYLVIA B R Virginia Electric & Power Co 80/07/21 4pp

6007110390 Submits info re actions proposed upon startup per IE Bulietin 79-14 Proposal predicated on provious procedents & commitments set for facility 's scansistent w/mutuol concern for safe operation. Requests prompt confirmation SPENCEH.W.C. Virginia Electric & Power Co. 80/08/08 3pp

R Perindic operating reports & related correspondence

8007170389 Forwards monthly operating repts for June 1980 SYLVIA:B R Virginia Electric & Power Co 80/0//14 1

~-B007170391 Monthly operating tepts for June 1980 DUNN.S D Virginia Electric & Power Co 80/07/07 41pp

S Reportable occurrences, LERs & related correspondence

8007010340 Forwards LER 80-007/03L-0 WILSON, J.L. Virginia Electric & Power Co. 80/06/26 lp

--B007010394 LEA B0-007/03L-0 on B00606, w/unit in cold shutdown, smake detectors found inoperable Caused by breaker trip at motor control ctr which feeds detectors Cause of breaker trip WILSON, J L. Virginia Electric & Power Co 80/06/26 2pp

B007210092 Part 21 rept re existence of nonconservative assumption in coid shutdown design basis boron dilution accident analysis in FBAR Caused by use of incorrect sys vol Review will be performed to identify & analyze add i accidents
SYLVIA.B R Virginia Electric & Power Co 80/07/02 4pp

8007180319 Forwards LER 80-008/03L-0 WILBON,J L Virginia Electric & Power Co 80/07/11 ip

--8007180327 LER 80-008/03L-0 on 800623, while performing periodic test 26 i found air ejector monitor alarm setpoint above Tech Spec requirement Caused by instrument drift Alarm setpoint recallbr WILSON, J.L. Virginia Electric & Power Co. 80/07/il 2pp

V Operator Examinations

B007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC B0032B request All training instructors are required to participate in program to maintain proficiency SYLVIA.B R Virginia Electric & Power Co 80/07/15 lp

--8007170350 Revised. "Litensed Operator Requalification Program "
• Virginia Electric & Power Co 80/07/31 lipp

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT I F Security, medical, emergency & fire protection plans

8007020235 Forwards request for limited revisions & addl info re 790323 plant safeguards contangency plan Encl withheld (ref 10CFR2 790) CLARK.R A Operating Reactors Branch 3 80/06/10 2pp

8007110i15 Forwards response to NRC 800618 questions re safe shutdown in event of fire
MAYER.L D Northern States Power Co 80/07/08 3pp

G Adjudicatory correspondence

B007100208 Ack receipt of NRC 800619 1tr to G Charnoff re nonreceipt of State of MN 800424 contentions Cartificate of Svc encl DL80N.J.F Minnesota, State of 80/06/23 3pp

B0073i0243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 7804i3 memorandum & order UCS 771i04 petition sought action re fire protection for electrical cables EIGENHUT, D O Division of Licensing 80/06/25 89pp

8007250422 Amended Contentions 1 & 2 & withdrawal of Contention 3 Amend DV/220422 Amenaed Contentions 1 % 2 % withdrawal of Contentions request does not contain safety analysis of spent fuel storage & does not contain analysis of spent fuel pool expansion consequences Certificate of Bvc encl QL4GN.J F , SENECHAL,M E , SPANNAUS,W Minnesota, State of BO/07/21 7pp

8007310493 Confirms ASLB request for hearing space at federal bidg in Baint Paul, MN on 800806 to conduct 1-day prehearing conference re facility STEPHENS,C R Docketing & Services Branch 80/07/22 ip

8007230683 Comments stating no objection to admission of State of MN BOQ721 Contentions 1 & 2 re cask drop accident & loss of water accident in spent fuel pools Reserves rights re substance & validity of contentions Certificate of Svc enci BARTH.C A Hearing Dranch 3 80/07/25 2pp

- 8007300463 Responds to State of MN 800424 suppl to petition to intervene & 800721 amended contentions Supporting documentation, notices of appearance of JE Siberg & DL Bernstein on behalf of util & Certificate of Svc encl BILBERG. J E Northern States Power Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/07/25 24pp
- H General correspondence
- B007310526 Responds to B00226 ltr re constituent concern about evacuation routes around facilities NRC & FEMA engage in program to upgrade emergency preparedness including evacuation planning DIRCKS.N J Office of the Executive Director for Operations B0/07/24 2pp
- --8007310528 Requests info re encl constituent itr about evacuation routes around facilities
 BOSCHWITZ.R Senete 80/02/26 App
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
 EISENHUT, D 0 Division of Licensing 80/06/11 42pp
- 80070302R2 Notifies NRC of intention to ship radioactive math from facilities using Model HN-600 MAYER, L D Northern States Power Co 80/06/13 lp
- 8007010591 Responds to 800513 ltr re containment purge info by forwarding related correspondence MARTIN.R A Operating Reactors Branch 3 80/06/18 2pp
- --B007010583 Responds to E0%G 800513 questions LOCA dose calculations not completed Monitors are redundant gas & particulate monitors provided, each giving isolation signal MUSDLF, D Northern States Fower Co 80/06/03 ip
- ---B0070103B5 Requests preliminary evaluation of licenses response to NRC 791027 "Interim Resition for Containment Purge & Vent Valve Operation Pending Resolution of Isolation Valve Operability." Generic Item B-24 Evaluation form encl REEVER, E A Operating Reactors Branch | (Pre 80042B) 79/12/27 6pp
- 8007170076 Summary of 800520 meeting w/util re TOPROD feel design MARTIN, R Operating Reactors Branch 3 80/07/01 7pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec thanges & license conditions PWR Model Tech Specs & Model license conditions for TM3-2 Lessons Learned Cotegory A items encl for guidance EISENHUT, D O Division of Licensing 80/07/02 69pp
- 8007280036 Advises of intention to ship radioactive matls from listed facilities using Package Model CNBI AL-33-50 MAYER.L D Northern States Power Co 80/07/03 lp
- 8007240388 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, poslitions & assignments of personnel Also submits info for GETR NDVAK, T.M. Assistant Director for Operating Reactors 80/07/08 200
- 8007280410 Forwards comments on NUREO-0577. "Fracture Toughness & Busceptibility to Stress Corrosion Gracking of Equipment Bupports," in response to NRC 800519 request Addl analysis for stress corrosion cracking is unnecessary MAYER.L O Northern States Power Co 80/07/21 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007070051 Forwards IE Insp Repts 50-282/80-04 & 50-306/80-07 on 800401-30 & notice of deviation HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/21 2pp
- --B007070056 Notice of deviation from insp on 800401-30 * Region 3, Chicago, Office of the Director 80/05/16 1
- --R007070061 IE Insp Repts 50-R82/B0-06 & 50-306/80-07 on 800401-30 No noncompliance noted failure to complete insp required by IE Bulletin 78-05 B0Vb, C. FEIERABEND, C. D. Region 3. Chicago, Office of the Director 60/05/16 7pp

- B007020054 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/28 ip
- 8007210362 Forwards 1E Circular 80-1J, "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/2B
- 8007010127 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Foodwater Pumps' No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29 to
- B007240185 Forwards IE Insp Repts 50-282/80-09 & 50-206/80-10 on B00501-31 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Muclear Support Branch 80/06/06 Ppp
- --8007240210 IE Insp Repts 50-202/80-09 % 50-304/80-10 on 800501-31 No noncompliance noted Major areas inspected maint, surveillance security, radiation protection followup of licensee reported eyents & followup to IE circulars FEIERAMEND, C D , BURGESS N L , BOYD, D C Region 3. Chicago, Office of the Director 80/04/05 App
- B007010260 Responds to 1E Bulletin 79-17.Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at FWR Plants " Visual Insp required by Item 2(a) was completed on Unit 1 w/no corrective actions necessary QILBERTS,D E Northern States Power Co 80/06/09 ip
- B007010267 Responds to IL Bulletin R0-06. "Engineered Safety Feature Reset Controls" Bafety sys schematics reviewed Test demonstrating safety equipment remains in emergency mode after reset will be completed at next refueling outage GILBERTS,D E Northern States Power Co B0/Q6/09 2pp
- 8007010549 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol (ontrol Sys (CVCS) Holdup Tanks "Chemical & vol control sys & components & gaseous & liquid waste disposal sys & components were reviewed GILBERTS,D E Northern States Power Co 80/06/09 2pp
- 8007160707 Responds to IE Bulletin 80-05 Review of chemical & vol control sys indicates holdup tank volnerability to collapse Low suction pressure trip to be installed on holdup tank transfer & recirculation pumps by 810101 QILBERTS,D E Northern States Power Co 80/06/09 2pp
- 8007220212 Forwards IR Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response requised KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/06/10 in
- B007160182 Forwards IE Info Notice B0-27, "Dogradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J G Region 3, Chicago, Effice of the Director B0/06/11
- 8007030043 Forwards IE Bulletin 80-15. "Possible Coss of Emergency Notification Bys (FNS) W/Loss of Offsite Power " Written response required KEPPLER, J. G. Reginn 3. Chicago, Office of the Director 80/06/18
- 8007020973 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Conldown " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director B0/06/20
- 8007140094 Ack receipt of encl 800A17 ltv informing NRC of steps taken to correct violations noted in NRC 800972 ltr Encl withhold traf 100FR2 790)
 HIND. J.A. Region G. Chicago, Rafoquards Branch 80/08/24 1p
- B007170806 Forwards IE Corculat 80-14, "Reducative Contamination of Plant Demineralized Mater 3ym & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago: Office of the Director B0/06/24 to
- 8007i40186 Ack receipt of 800A12 ltr informing NRC of steps taken to correct deviation noted in IF Insp Repts 50-282/80-06 & 50-306/80-07 forwarded by 800521 ltr Sensor resident inspector will follow remaining testing HEISHMAN.R F Region 3. Chicago. Resident Operations Nuclear Support Branch 80/06/25 ip

- --8007140192 Responds to deviation noted in iE Insp Repts 50-282/80-04 & 50-306/80-07 forwarded by 800521 ltl Special insps of two out of four power apprated relief isolation valve mater starters have been completed Two others will be performed GILBERTS.D E Northern States Power Co 80/06/12 lp
- 8007230336 jorwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 t 1152 Pressure Transmitters W/Tither A or D Butput Codes 'Misitten response required IE Circular 80-16 also one! No written response tequired REPPLER, J G Region 3. Chicago: Office of the Director 80/06/27
- B007310106 Responds to 1E Bulletin B0-10 re contamination of nonradioactive sys Requested actions complete Specifics available at site OllBERTS.D E Northern States Power Co B0/07/03 Ip
- B0071504B1 Advises that demonstration of ultrasonic insp method for detecting underclad cracking in reactor vessel noizle region for Unit 1 is scheduled for B00723 Unit 2 insp will take place during 1981 refueling outage
 MAYER.L () Northern States Power Co 80/07/07 lp
- 8007250077 Forwards response to IE Bulletin 80-11, "Masonry Well Design " Concrete block walls are not in same design philosophy as design of Trojan plant masonry walls Walls were generally designed as partition walls or shield walls OllBERTS, D E Northern States Power Co 80/07/08 51pp
- 8007220090 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Review of Unit 1 revealed two deficient welds Further response will be sent by 800810 GIBERTS, D.E. Northern States Power Co. 80/07/10 lp
- 8007220542 Submits reply to IF Bulletin 79-01B re environ qualification of Class IE equipment Gualified limit switches have been ordered 4 are scheduled for replacement during future outages Worksheets encl GLEERTS, D E Northern States Power Co 80/07/10 8pp
- B0072302il Submits reply to JF Bulletin 79-17 re pipe cracks in borated water sys Visual inspired by bulletin was satisfactorily completed for Unit 1 No corrective actions necessary OllDERTS.D E Northern States Power Co B0/07/10 ip
- R Periodic operating reports & related correspondence
- 8007030178 Forwards "1979 Fiviron Monitoring & Ecologica) Studies Program Rept: " Vois 1 & 2 WARD: E C Northern States Power Co 80/06/30 ip
- ---8007030160 "1979 Environ Monitoring & Ecological Studies Program Rept."
 Vol 1
 - * Northern States Power Co 80/06/30 325pp
- --B007030183 "1979 Foviron Monitoring & Ecological Studies Program Rept," Vol. 2
 - * Northern States Power Co 80/04/30 325pp
- 8007160538 Forwards monthly operating repts for June 1980 MAYER.L O Northern States Power Co 80/07/11 1p
- --8007160562 Monthly operating tepts for June 1990 HUNSTAD, A A Northern States Power Co 80/07/01 9pp
- B Reportable occurrences, LERs & rolated correspondence
- 8007140640 RO 80-18 on 800629, steam generator 12 experienced minor primary-to-secondary leakage of about 0 000 gallons per minute Loakage was carefully monitored & showed increase facility is shutdown Couldown is plenned TIERNEY,F P Northern States Power Co 80/07/01 lp
- 8007210437 Forwards LER 80-018/017-0 MAYER.L B Northern States Power Co 80/07/15 ip
- --8007210444 LER 80-018/017-9 on 800/01, unit was shut down due to loaking tube in hot log of yertical steam genorator 12. Westinghouse Series 5: Cause not stated Defertive tute will be plugged HUNSTAD.A A Northern States Power Co 80/07/15 2pp

- B007250340 R0 B0-20 on B00715. w/Unit 2 at i007 power & Unit i at cold shutdown, menn generator separated from grid & one offsite source was lost, tripping reactor & collent pumps Caused by severe electrical storm Transformer restared TIERNEY, F.P. Northern States Power Co. B0/07/16 ip
- 8007290669 Forwards LER 80-019/03L-0
 MAYER.L D Northern States Power Co 80/07/24 ip
- --8007290677 LER 80-019703L-0 on 800630.two power range high power trip setpoints were over Tech Spec limit Caused by personnel error Rept reviewed & technicians cautioned HNNSTAD.A A Northern States Fower Co 80/07/24 1p
- DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

 Q Inspection reports, IE Bulletins & correspondence
- 8007070157 Forwards 1E Insp Rept 50~284/80-01 on 800529-30 No nancompliance noted KELLY, A F Region 4. Dellas, Office of the Director 80/06/20 200
- ---8007070161 IE Insp Rept 50-284/80-01 on 800529-30 No noncompliance noted Major areas inspected security plans alarm sys, keys, locks, hardware, communications. & surveillance Details withheld (ref 10CFR2 790)
 CALDMELL, R A , KELLY, A F Region 4, Dallas, Office of the Director 80/06/18 lp
- DOCKET SO-285 FORT CALHDUN STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007230530 Forwards addl info supporting security contingency plans & revised page to Chapter 3 of site security plan Info & revision withhold (ref 100FR2 790)

 JUNES, W C Gmaha Public Power District 80/07/09 ip
- 9 Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 memorandum & order UCB 771104 patition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 89pp
- Advisory Committee on Reactor Bafeguards reports & correspondence
- 7906220186 Summarizes responses to IE Bulletin 79-060 Operating manuals are being scrutinized Operational personnel are being trained Radioactive gases & liquids transfer lines are interlocted w/containment isolation &/or radiation signals TAM, P Division of Site Safety & Environmental Analysis 79/05/08 Boo
- P Operating license stage documents & correspondence
- B005170062 Notification of 800507 meeting w/util in Betheeds.MD to discuss analyses required & methods used in evaluating asymmetric loads WAGNER.PC Operating Reactors Branch 3 80/05/05 ip
- 8007030194 Forwards "Technical Evaluation of Electrical, Instrumentation & Control Dosign Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Feature Bignals for Fort Calhoun Nuclear Power Plant " CLARK.R A Operating Reactors Branch 3 80/06/04 3pp
- --8007030208 "Technical Evaluation of Electrical, Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Feature Signals for Fort Cathoun Nuclear Power Plant"

 HACKETT, D. B. RADDSEVIC. J. R. BRODERICK, N. E. EG&G. Inc. URCL-15172 80/01/31 15pp
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D @ Division of Licensing 80/06/11 62pp.
- 8007020067 Summary of 800610 meeting w/util re work performed after 800507 meeting on asymmetric loads analyses WAGNER, P.C. Operating Reactors Branch 2 80/06/18, Spp

- 8007010471 Forwards results of leak tate tests performed in response to Item 2 1 6 a of NUREG-0578

 JONES.W C Ommha Public Power District 80/06/25 1p
- ~~8007010477 "Integrity of Sys Outside Containment Likely to Contain Radioactive Mati " * Omaha Public Power District 80/04/25 2pp
- 8007300078 Comments on proposed rule 10CFR50 re fire protection installation of Stand pipe & hose station inside containment presents potential safety concern re boron dilution in event
- of pipe rupture
 JONES, W C Omaho Public Power District 80/06/25 3pp
- B007020557 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 780125 ltr to PWR licensess re asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withhold (ref 10CFR2 790) LUNDVALL, A E C-E Operating Plants Owners Group B0/06/30 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program," final rept.
 - C-E Power Systems 80/05/30 20pp
- --B0070205Bi "RCS Asymmetric Loads Evaluation Program," final rept.
 - C-E Power Systems B0/06/30 300pp
- --8007020588 "RC8 Asummetric Loads Evaluation Program," final rept. Vol
 - * C-E Power Bystems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program," final rept.App A, numerical results, evaluation of C-E fuel Nonproprietary version App B.Patisades fuel analysis, enci
 * C-E Power Bystems 80/06/30 2App
- ---8007020399 "RCS Asymmetric Loads Evaluation Program." App C,pipe whip restraints & App D.plan for fracture analysis of util coid imp piping Final rept # C-E Power Systems 80/06/30 Lopp
- --8007020600 "RCS Asymmetric Loads Evaluation Program," App E.ECCS analysis approach w/reduced area coolant channels in periphoral assemblies final rept

 # C-E Power Sustems 80/04/30 0--
 - C-E Power Bystems
- 8007080364 Provides update re evaluation of asymmetric loads por Jan 1978 request Several approaches considered to substantiate util position that safety problem does not exist Detailed discussion of plan due no later than 800901 JONES.H C Omaha Public Power District 80/06/30 2pp
- 8007170658 Confirms teicon re NRC contract personnel 800708-11 site visit to perform engineering analysis to identify vital areas at plant Contractors will require access to plant info & areas Proprietary info will be protected HAGNER, P C Operating Reactors Branch 3 80/06/30 2pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items enci for guidance EISENHUT, D @ Division of Licensing 80/07/02 67pp
- 8007240335 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of parsonnel Also submits info for GETR NOVAN.T M Assistant Director for Operating Reactors 80/07/08
- 80072B0530 Responds to NRC request for evaluation of plant RCS susceptibility to overpressurization events Mass input & energy input analyses sections were re-evaluated using new valve discharge coefficients

 JONES, W.C. Omaha Public Power District 80/07/15 App
- Q Inspection reports, IE Bulletins & correspondence
- 8007020299 Responds to IE Bulletin 80-04, "Analysis of PMR Main Steam Ling Break w/Continued Feedwater Addition" Reamalysis of reactivity increase will be submitted by 800516 Containment pressure response analysis is being performed by vendor JONES.W C Omaha Public Power District 80/05/08 2pp
- BOD7020075 Forwards response to open Item 5.Encl 13 of IE Bulletin 79-010 W/o response JONES.W C Omaha Public Power District BO/05/13 1p

- 9007210187 Advises that response to IF Bullitin 80-12. 'Datay Heat Removal Sys Operability," will be delayed approx 3 whs.until 800630
- JONES, W C Omaha Public Power District 80/05/21
- 8007020430 Responds to 1E Bulletin 80-09. 'Hydramotor Actuator Deficiencies' 'No ITT General actuators are installed at facility
 JONES, W.C. Omaha Public Power District 80/05/22 ip
- 8007020263 Forwards IE Info Notice 80-22 "Breakdowns in Contamination Control Programs " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/28
- 8007210350 Forwards IE (incular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies 'No written response require BEYFRIT.K V Region 4, Dallas, Office of the Director B 80/05/28
- 8007010033 Forwards IE Info Notice 80-23, "loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT.M. V. Region 4, Dallas, Office of the Director 80/05/29
- 8007190165 Fowards 1E insp Rept 50-285/80-09 on 800505-08,12-15 & 22-23 No noncompliance noted MADSEN, 0 L Region 4, Dailas, Reactor Construction & Engineering Bupport Branch 80/06/04 2pp
- --8007150171 IE Insp Rept 50-285/80-09 on 800505-08,12-15 & 22-23 No DOISON IN THE PARTY REPUBLISHED OF THE BUSINESS OF THE BUSINESS OF THE BUILDING THE BUILDING AREAS THE BUSINESS OF THE BUSINES
- 8007020419 Forwards response to iE Bulletin 80-05, "Engineered Safety Feature (ESF) Reset Controls "Summery of equipment deviations during resetting of engineered safety features actuation sys enci JONES.H C Omaha Public Power District 80/06/06 Spp
- 8007220124 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs" No written response required BEYFRITIK V Region 4. Dallas, Office of the Director 89/06/10
- 8007160331 Forwards 1E Info Notice HO-27, "Degradation of Reactor Comiant Pump Studs " No specific action or response SEYFRITAK V Region 4, Dallas, Office of the Director 80/06/11
- B007110086 Ack receipt of 800°40 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-285/80-03 MADSEN & L Region 4. Dailas, Reactor Operations Nuclear Support Branch 80/06/20 lp
- -8007i10096 Responds to NRC 8004i5 ltr re violations noted in 1E Insp Ropt 50-285/80-03 Corrective actions Maint Protedure MP-RV-1 will be revised to indicate specific valves procedure JONES W C Omaha Public Power District 80/05/08
- 8007240047 Forwards IE Circular 80-15, "loss of Reactor Comiant Pump Cooling & Natural Circulation Couldown" No written response required. required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/04/20
- 8007180112 Ack receipt of 800613 ltr informing NRC of steps taken to correct violation noted in it linsp Rept 50-289/80-10 BROWN, 0 D Region 4, Dallus, Fuel Facility & Materials Safety Branch 80/07/01 ip
- --8007180122 Responds to NRL 800523 ltr (p violation noted in IE Insp Rept 50-285/80-10 Corrective actions technicians reinstructed on requirement to conduct full survey Fire door alarm repaired JONES.W C Omaha Public Power District 80/06/13 2pp
- 8007230558 Advises NRC of inspiresults of containment recirculation piping check valve.31-159 Valve was found in "like now" condition who valve degradation observed % leturand to operation who nave for maint JONES.W C Dmaha Public Power District 60/07/09 in

07310324 Updates into re admittance of NRC inspectors to facility Discusses entrance procedules & types of identification required Requests site ofientation SCYPRIT.R V Region 4. Dallas, Offsie of the Director 80/07/14 2pp

07280601 Forwards summary of irradiated fuel insp following Cycle 5 operation performed during 1980 refueling outage No major abnormalties observed in six irradiated fuel assemblies inspected No failed fuel pins were observed JONES.W C Omaha Public Power District 80/07/15 3pp

Periodic operating reports & related correspondence

07170376 Forwards monthly operating rept for June 1980 JONES.W C. Omaha Public Power District 80/07/09 ip

8007170379 Northly operating tept for June 1980
HICKLE, B. J. Dmaha Public Power District 80/07/09 9pp

Reportable occurrences. LERs h related correspondence

30070703B5 LER BO-011/03] -O on 80052B during 1980 refueling outage type B & C containment leak late tests total leakage exceeded 0 6Lo lent Coused by leaking fuel transfer tube, electrical mechanical sleeve & piping penetrations CORE, N. CONNOLLEY, J. Comaha Public Power District 80/06/16 7pp

007240134 LER 80-016/03L-0 on 600621.weld on suction side of pump CH-1B in deminerallized water flush line cracked Caused by vibration of piping in svc Clack was ground out & rewelded using certified procedure & line tested JEMELL.W A Omaka Public Power Obstrict MO/06/25 App

KET 50-286 INDIAN POINT STATION, UNIT 7 Security, medical, emergency 5 fire protection plans

7030294 Forwards security contingency plan lan withheld (ref 100FR2 790) AYNE, J P Power Authority of the State of New York 80/06/20 1p

7290735 Notifies NRC that 791109 & 800221 revised emergency plans ill become effortive on 800801 & procedures to implement lan will become effective within 90 days of plan effoctive date

AYNE. J P Power Authority of the State of New York 80/07/24 ip

Adjudicatory correspondence

7310243 Forwards Commission B00527 Memorandum & order containing ecisions on UCS 780502 patiation for reconsideration of B0413 memorandum & order UCS 771104 petition sought action of fire protection for electrical cables ISENHUT, D G Davision of Licensing 80/06/25 87pp

7090215 Order granting extension until 800725 for Commission to posider whether to review ALAB-436 & portions of ALAB-541 OYLE, J.C. Office of the Secretary of the Commission 80/07/07

7220160 Response in appusition to UBC motion for disqualification of lairman Hendrik re UCS 790917 pritition seeking shutdown of cility Motion failed to show hims defined by Supreme Court i Withrow ys Larxin proceeding

ATT-C M Power Authority of the State of New York
RANDENBURG.B I Consolidated Edison Co of New York 80/07/08

7140363 Order granting extension until B00801 for Commission to lect whether to review ALAB-4.16 % relevant portions of .AB-561
3YLE.J C Office of the Secretary of the Commission B0/07/10

8007290572 Motion for reconsideration of Commission 800530 order reportion instituting adjudicatory hearing before ASLB Interim Operations Task Force rept. SECY-283, eliminates basis for commencement of investigation BRANDENBURG. B L Consolidated Edison Cu of New York PRATT, C Market Authority of the State of New York 80/07/25 12pp

H General correspondence

B00721020B Responds to encl B0041B ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article encl DBNTCN.H R Office of Nuclear Reactor Regulation, Director B0/05/21 10pp

BO07170259 Responds to B00206 ltr re status & responsibilities for emergency preparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRINES, B K Emergency Preparedness Program Office B0/07/07 2pp

I Financial information

BO072B0461 Forwards Annual Financial Rept 1979
BAYNE.J P Power Authority of the State of New York 80/07/24 1

--B0072B0463 Annual Financial Rept 1979

* Power Authority of the State of New York 80/07/24 41pp

O Advisory Committee on Reactor Bafeguards reports & correspondence

BOO722030B Provides summary of BO0507-0B meeting w/utils re core melt accident sequences Utils appear to expect NRC to repolve problems & do nothing to mitigate consequences of Class 9 accidents

CATTON 1 California, Univ of, Los Angoles BO/05/10 App

P Operating license stage documents & correspondence

BOO42404BO Forwards add1 info re review of unresolved safety issues, trip rept of Lessons Learned implementation team, & task action plan in view of high population density surrounding plants

DENTON, H R Office of Nuclear Reactor Regulation, Director BO/04/09 33pp

8007220084 Responds to 800609 telcon re NRC concerns over operability of control room ventilation sys in emergency mode Initiating air flow measurements in emergency mode to determine control room habitability is not in accordance w/ectual plans GRIER/B H Region i, Philadelphia, Office of the Director 800/06/11 ip

BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution enci for guidance

EISENHUT, D 0 Division of Licensing 80/06/11 62pp

8007100393 Summary of B00520 Technology Exchange Meeting 3 w/utils in Bethesda.MD to discuss accident mitigation features for power plants LONG, J K Division of Systems Integration 80/06/12 75pp

8007140182 Submits lept of task force on interim operation of facilities Rept includes accident risk considerations, social & economic impart considerations & summary of public comments
HANRAHAN, E. J. Defice of Policy Evaluations BICKMIT, L. Office of the General Counsel BECY-80-283 80/06/12 68pp

--BO07140170 Summarizes views of Economic Regulatory Administration, Div of Power Supply & Reliability to electric sys reliability impact of operation of facilities as described in NRC BO0428 ltr WEINFR, R E Energy, Dept of 80/05/15 4pp

8007100103 Forwards Amend 30 to License DPR-64, safety evaluation & notice of issuance & availability
VARGA.S A Operating Reactors Branch 1 80/06/13 3pp

--8007100106 Amend 30 to License DPR-64, adding surveillance requirements for containment vent % purge sys VARGA,S A Operating Reactors Branch 1 80/06/13 7pp

--B007100110 Safety evaluation supporting Amend 30 to License DPR-64
* Office of Nuclear Reactor Regulation, Director B0/06/13 App

- --8007100114 Notice of issuance & availability of Amend 30 to License DPR-64 VARGALS A Operating Reactors Branch i 80/06/13 2pp
- B007010110 Notification of B00625 meeting w/utils & Sandia Labs in Bethesda.MD for presentation of overview of facilities risk study Agenda encl IBRAEL.5 L Reliability & Risk Assessment Branch B0/06/16 Jpp
- 8007110557 Summary of 800530 meeting w/util in Bethesda, MD re status of
- action plan
 OLSHAN, L N Operating Reactors Branch 1 80/06/23 3pp
- B007010608 Notification of 800617 meeting w/utils in Dethosda.MD to discuss containment structural response. Failure pressures & failure modes for fatilities as described in NRC 800410 ltr to Comm Ed MEYER.J F Reactor Systems Branch 80/06/26 2pp
- B007180044 Forwards Amend 31 to License DPR-64, safety evaluation & notice of issuance & availability
 VAROA.S A Deprating Reactors Branch i 60/06/27 3pp
- --Boo7iBoo45 Amend 3i to License DPR-54, revising Tech Specs to add midcycle insp of one steam generator & end-of-cycle insp of all four steam generators VARGA:S A Operating Reactors Branch i BO/05/27 i3pp
- --8007180051 Safety evaluation supporting Amend 31 to License DPR-64
 * Operating Reactors Branch 1 80/06/27 9pp
- --8007180053 Notice of issuance & availability of Amend 31 to Liconse DPR-64 VARQA.5 A Operating Reactors Branch 1 80/06/27 2pp
- 8007210055 Requests that util submit revised schedule & justification for completion of ATWS mods within 30 days Util is requested to improve upon Fall 1982 completion date because of risk represented by facility VARQA.S A Operating Reacture Branch i 80/06/30 2pp
- 8007210498 "Evaluation of Impingement Losses of White Perch at Indian Point Nuclear Station & Other Hudson River Power Plants "
 VAN WINKLE, W. BARNTHOUSE, L. W. KIRK, B. L. Dak Ridge National Laboratory FIN B-0423 NOMEG/CR-1100 80/06/30 152pp
- B0070B0367 Provides method by which derivative action was removed from proportional integral derivative controller per 800616 ltr.

 Item II K 3 9:responding to TMI-related requirements Feature eliminated by placing rate control to min BAYNE.J P Power Authority of the State of New York B0/07/02 1p
- G007170241 Forwards request for addl info re backfitting of severe accident mitigation features Response requested within 30 days
 NOVAK.T M Assistant Director for Operating Reactors 80/07/02
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D @ Division of Licensing 80/07/02 69pp
- B007170598 Summary of 800625 meeting w/Pickard.Lowe & Garrick.Inc re risk study including modeling for plume tragectory. containment event tree & modeling use of plant data & consideration of external events IBRAEL.B L Reliability & Risk Assessment Branch 80/07/07 App
- B007230646 Summary of B00507-OB technology exchange meetings w/utils in Chicago, IL re core melt accident sequences & associated phenomenology for facilities NRC perceives real urgency to for answers to key technical questions
 MEYER.JF Reactor Systems Branch 80/07/09 12pp
- B007070101 Notification of change in location B00625 meeting w/util in Bethesda,MD to discuss re-evaluation of operational GA program BELKE,W L Guality Assurance Branch 80/07/17 2pp
- 8007300092 Notification of 800724 meeting w/util in Rethesda:MD to discuss sys interactions study OLSHAN:L N Operating Reactors Branch 1. 80/07/17 2pp
- B007270728 Forwards Revision 2 to steam generator operating history questionnaire & attached supplementary info BAYNE, J P Power Authority of the State of New York B0/07/23 50pp

- 8007310514 Summary of 800625 meeting woutil re GA program OLSHANIHAL N - Operating Reactors Dranck 1 - 80707723 - App
- B007270580 forwards comments on NUMEG 02/1 re bondin Labs analyses on potential susceptibility or alread generator 5 reactor coolant pump supports to law fraction chapters 3 in ittle failure Analyses but technically justified BAYNE, J.P. Power Authoraty of the State of New York. 60/07/44 2pp
- G. Inspection reports: 16 Belieting & correspondence
- 8007170606 Forwards IE Insp Rept 50 286780 04 on 800 H2 14 No noncompliance noted CARLSON.R T. Region I. Philadelphia Office of the Director 80705/21 Epp
- --B00/170614 IF loop kept 50 /86/49 04 on (100312-14 No noncompliance noted Major areas inspected fire providing proceeding pertaining to fire protection made in Amend 49 to License DPR-64
 KDLYAY-P S Region 1, Philadelphia, Office of the Director EBNETER'S D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/16 4pp
- 8007020194 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required GRIER,B II Region 1 Philadolphia. Office of the Director 80705/28 ip
- B007010303 Forwards IE Info Notice (80%), "Lost of Sutton to Emergency Feedwater Pumps" No written response required ORIER, I H. Region 1. Philadelphia (After of the Director 80/05/29)
- 8007180111 Forwards reply to IE Bulletin (60-05 te varuum condition resulting in damage to holder tanks Results of review did not identify any corrective arrivan required EARLY(P) I Power Authority of the state of New York 180/06/07/4pp
- 8007210599 Forwards IC Info Notice UO 25. "Evaluation of Contractor GA Programs "No written response trapticed GRIER B II Region 1. Philadelphia. Office of the Director BO/06/10 IP
- 0007160358 Forwards II Info Notice 80-27. "Degradation of Reactor Coplant Pump Study " No specific action of response required GRICROB H Region to Philadelphia, Office of the Director 60/06/11 to
- 8007170316 Forwards response to IF Bulletto 80-06, "Ingineered bafety Feature (ESF) Resol Controls," All safety related equipment remains in emergency mode open result of the attraction signal except as listed

 BAYNE J P Power Authority of the State of New York BO/06/17 App
- 8007020687 Forwards IE Bulletin (8) 15 "Proteible Lune of fineigenry Notification Sys (ENS) W/Lors of Definite Power " Written response required ORIFE B Region 1. Philadelphia, Office of the Director 80/04/10 1p
- 2007020491 Forwards If Carculat 10 (b) "Loss of Rearter Lociant Fump Cooling & Ratural Circulation Couldown "No writton response required ORIER B 1 Region I, Philadolphia, Diffice of the Director 80/06/20 ip
- 8007180597 Peaponds to IF Bulletin 80 09, "Hydramator Actuator Deficiencies" Examination of project valve drawings about no hydramotor actuators furnished BAYNE, J.P. Power Authority of the State of New York 80/06/Pb 2pp
- 8007160726 Forwards IE Circular 80 14 "Redicartive Contamination of Plant Deminsralized Water Sys & Resultant Internal Contamination or Personnel " No written response required ORICE H Region 1. Philosophylas (Office of the Director 80/06/24)
- 8007210272 Forwards It Info Hotice 80 24, "Low Level Radwasta Burial Criteria" No written response required ORIFR B Region 1. Philadelphia. Uffice of the Arrector BO/04/25 ip

- 8007140347 forwards response to NRC request for additinfo reinservice BAYNE, J P Power Authority of the State of New York 80/06/27
- 8007270156 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemmint Inc Models 1151 % 1152 Pressure Transmitters W/Either A or D Gutput Codes ' Mritten response required IE Circular 60-16 Also entl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- B0072:0456 Responds to IE Dulletin B0-10 re potential nonradioattive sys contamination % uncontrolled radioactive releases Actions required by Items i & 2 inmpleted 2ULLA-S S Power Authority of the State of New York 80/07/03 ip
- 80072503i3 Ack receipt of 8006i3 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-286/79-29 GRIER, B H. Region i. Philadelphia, Office of the Director 80/07/03 ip
- -8007250317 Responds to NRC B005i4 ltr re violations noted in IE Insp. Rept 50-286/79-29 Corrective actions personnel instructed to evaluate surveillance results more carefully Program. Instituted to resulva discrepancies TULLASS Power Authority of the State of New York 80/06/13
- --8007250325 Forwards IE Insp Rept 50-286/79-29 on 791125-800119 & notice GRIER, B.H. Region L. Philadelphia, Office of the Director 80/05/14 2pp
- --8007250329 Notice of violation from inso on 791125-800119 * Region i, Philadelphia, Office of the Director 80/ 80/05/05 2pp
- --8007250302 le insp Rrpt 50-286/79-29 on 7914/3-800119 Noncompliance noted failure to evaluate surveillance results properly & to resulve discrepancies noted during containment insp Kister, H. Rogion i, Philadelphia, Reactor Operations Nuclear Support Branch REBELOWSKI T., JOHNSON, J. Region i, Philadelphia, Office of the Director 80/05/05 20pp
- R Periodic operating reports & related correspondence
- 8007170363 Forwards "Annual Environ Monitoring Rept.Part & Radiological CANILL, W. J. Consolidated Edison Co. of New York 80/05/30 1p
- ---8007170765 "Annual Environ Monitoring Rept, Part B Radiological Rept " * Consolidated Edison Co. of New York 80/06/30 66pp
- 8007150669 Submits dwily fish counts from intake screens for June 1980 MONTI.W A Consolidated Edison Co of New York B0/07/i0 17pp
- 0007210376 Forwards monthly operating rept for June 1980 ZULLArS S Power Authority of the State of New York B0/07/14 to
- --8007210377 Monthly operating rept for June 1980 CONNELL.C Power Authority of the State of New York 80/07/02
- 8007210473 Forwards util 800A13 ltr & "Guarterly Rept on Seismic Monitoring Nutwurk in Vicinity of Indian Point, NY. Con Ed Project Dec 1979-Feb 1980 " DAVIS.JP Consolidated Edison Co of New York 80/07/14 2pp
- 8007220923 Forwards "Daily Count from Intake Screens for June 1980 " ZARAKAS.P Consoladated Edison Co of New York 60/07/15 ip
- --B007220324 "Daily Count from Intake Screens for June 1980 "
 * Consuladated Edison Co. of New York 80/07/15 4pp
- 5 Reportable occurrences. LtRs & related correspondence
- BOD4240212 PNO-1-80-35A oil samples from hydraulic control sys storage tanks & both main feed pumps found out of specs for particulates increase in main feed pump oil micron particle size possibly due to filter overload & breakdown MCCABE.E. BRUNNER.E. Region J. Philadelphia. Office of the Director 80/937/07 2pp

- 8007020145 PND-I-80-093 on 800617.util workers Union Local i-2 authorized strike on 800618 Senior operators are excluded Required IE prestrike insps have been completed GREENHAN.E O. BRUNNER.E J. Region I. Philadelphia. Office of the 80/06/17 1 p Director
- 800715008) PND-1-80-094 on 800624, while performing maint on incore detector drives, three individuals sustained possible whole body radiation exposure & internal & external radioactive contamination Awaiting dosimetry results
 NIMITZ, R, KNAPP, P, MARTIN, T Region 1, Philadelphia, Defice of the Director 80/06/24 2pp
- 8007010452 Submits info to 800624 radiation exposure in excess of permissible limits During routine containment entry to effect repairs to E drive, repair team withdrew severed drive cable wincore detector Contamination within I limits IULLA.S B Power Authority of the State of New York 80/06/25
- 8007010448 Forwards LER 80-004/017-0
 2ULLA S S Power Authority of the State of New York 80/06/27 ip
- -- B007010455 LER 80-006/01T-0 on 800614, while operating at full power. test of control room air filtration sys indicated total filter flow above Yech Specs Caused by drifting of Allen-Bradley 802T-A damper Sys balanced GUMBLE.F W Power Authority of the State of New York 80/06/27
- B0072100i9 Confirms B00627 telcon re util actions following B00624 personnel exposure incident Approved procedure for maint & repair of incore flux monitoring drive components will be implemented by B007i1 & addl guidance by B00702 GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/27 2pp
- 8007080350 Forwards LER 80~008/03L-0 ZULLA,8 5 Power Authority of the State of New York 80/07/02 ip
- --8007080354 LER 80-008/03L-0 on 800403, while operating at 60% power. outside power to 138 kV foeder was lost Diesel generators 32 & 33 were activated Caused by transmission tower ground lead which fell across feeder after being struck by lightning GUMBLE,F H Power Authority of the State of New York 80/0 HO/07/02
- B007080355 Forwards LE^c 80-009/03L-0 TULLA, S S Power Authority of the State of New York 80/07/02
- -80070B0362 LER 8C-009/03L-0 on 800604.while operating at 100% power, boric acid heat tracing test 3PT-08 indicated no continuity on circuit 39 Caused by failed Chromolox 120 volt. 300 watt strip heator Heater replaced * Fower Authority of the State of New York 80/07/02 ip
- 8007140333 Responds to concerns re control room ventilation sys operability in emergency mode noted in LER 80-006/QI-O Dampers readjusted charcoal filters replaced & thyroid dose rate calculations reanalyzed ZULLA, B Power Authority of the State of New York 80/07/03 2pp
- 8007290052 RO on 800424, poisonnel overexposed to radiation Occurrence re-enacted Rept expected soon from dosimetry contractor Intake evaluation completed Results indicate no exposure in excess of IOCRICO 103 limits W/o encl ZULLA: 8 8 Power Authority of the State of New York 80/07/11
- B00721041B Provides supplemental info to B00625 & 0711 ltrs re B00624 overexposure, in rusponse to NRC request Encl table provides radiation exposure history In all cases, radiation exposure is within legal limits for annual exposure ZULLA, S S Power Authority of the State of New York 80/07/16
- 8007270098 PNO-1-80-101 on 800715 plant tripped from 100% power due to water leakage on coolant pump penetrations Possible damage to coolant pumps & penetrations is being investigated REBELOMEKI.T. MARTIN.T., BRUNNER, E. Region i. Philadelphia. Office of the Director 80/07/16 ip
- 8007310424 Forwards LER 80-010/03L-0 ZULLA,S 8 Power Authority of the State of New York, 80/07/25 ip

- ---8007310430 LER 60-010/03L-0 on 800629, while operating at 100, power, upon completion of trip test operator was unable to reset trip lever on 32 diesel generator Caused by unsecured trip latch spring having lost attaching screw PABSMAN, N A Power Authority of the State of New York 80/07/28
- T Hearing transcripts on non-antitrust matters
- B007140084 Unofficial transcript of B00626 briefing on recommendations of Indian Point Task Force in Washington, DC Pp 1~62 Viewgraphs encl * Commission 80/06/26 64pp
- 8007240164 Transcript of 800711 public meeting in Washington, DC Pp 1-6 * Commission 80/07/il 6pp
- 8007250347 Unofficial transcript of 800717 discussion on Indian Point in Washington, DC Pp 1-72 Draft memorandum & order encl * Commission 80/07/17 80pp

V Operator Examinations

8007080303 Notifies NRC of commitment to enroll employees who do not sucessfully complete any portion of roactor operator exam in accelerated requalification program Declines to commit employees to Item B if of NPC 800328 request BAYNE, J. P Power Authority of the State of New York 80/07/01 200

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

- F. Becurity, medical, emergency & fire protection plans
- 8007010205 Forwards security plan re in-transit requirements for SNM of low strategic significance Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/05/24 ip
- 8007230090 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security may be presented at facilities EIBENHUT, D & Division of Licensing 80/07/11 2pp

O Adjudicatory correspondence

- 8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Gaston County, NC Urgss transportation via Interstates 77 & 85 Encourages expending energy & money for recycling W/correspondence # Gaston County, NC 89/04/28 dipp
- --B007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided QABTON:H B. Qaston County.NC 80/04/25 2pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action we fire protection for electrical cables.
 EISENHUT, D Q Division of Licensing 80/05/25 87pp

P Operating license stage documents & correspondence

- 8007240208 Forwards B&W licensees' responses to 790907 request for review of schedule for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115
 CAPRA, R A TMI-2 Bulletins & Orders 79/10/24 1p.
- BO07140397 Refers to B00701 Itr requesting info re insp of fuel assembly hold-down springs, Reviewed concern & documented results in B00606 Itr forwarding RO 50-269/80-15 & safety evaluation No further info required PARKER, W O Duke Power Co B0/06/08 ip
- 8007230097 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance.

 EIBENHUT.D G. Division of Licensing 80/06/li 62pp

- 8007160429 Forwards Amends 83,8,3 & 80 to Licenses DPR-38,DPR-47 & DPR-35,respectively, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 80/06/12 2pp
- --8007160434 Amends 83,83 & 80 to incenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to support operation of Unit 2 at full rated power during Cycle 5 REID,R H Operating Reactors Branch 4 80/06/12 23pp
- ~-B007160445 Safety evaluation supporting Amends 83.83 & 80 to Licenses DPR-38, DPR-47 & DPR-55, respectively * Office of Nuclear Heactor Regulation, Director 80/06/12
- ~-8007160453 Notice of issuance & availability of Amends 83,83 & 80 to Lirenses DPR-38,DPR-47 & DPR-55,respectively REID,R W Operating Reactors Dianch 4 80/06/12 2pp
- 8007070035 Forwards safety evaluation re postuloted fuel handling accident inside containment REID:R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Safety evaluation re postulated fuel handling accident inside containment
 * Operating Heactors Branch 4 80/06/24 lp
- 8007020375 Summarizes actions undertaken by util re inadequate core cooling NRC review of previously submitted operator guidelines should be campleted prior to util committing to install new instrumentation PARKER, W O Duke Power Co 80/06/27 2pp
- B0070B0223 Advises that response to NUREG-06A7 is in final review & will be submitted by 800723
 PARKER, W O Duke Power Co 80/07/0i ip
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days NOVAK.T M. Assistant Director for Operating Reactors 80/07/01
- B007110294 Forwards application to amend Tech Specs to incorporate test frequency requirements of 10CFR50.App J PARKER, W.Q. Duke Power Co. 80/07/07 2pp
- --8007ii0331 Application to amend Tech Spec 4 4 1 2 5 incorporating test frequency requirements of iOCFR50, App J Existing Tech Spec unacceptable for extended cycle lengths for which current & future cycles are/will be licensed * Duke Pawer Co 80/07/07 2pp
- 8007230708 Provides info re new ofc titles, positions & assignments of personnel resulting from 80042H reorganization of Ofc of Nuclear Reactor Regulation NDVAK.7 M Assistant Director for Operating Reactors 80/07/10
- 8007150575 Forwards "Generic Startup Physics Test Program. Jul 1980 " Rept supersede: in entirety repts submitted 800604 & 11 PARKER. W O Duke Power Co 60/07/11 ip
- --8007150383 "Generic Startup Physics Test Program, Jul 1980 " Rept supersedes in entirety previously submitted repts forwarded by 800604-11 ltrs 4 Duke Power to 80/07/31 14pp
- BOO72BO437 Forwards proposed revision to Tech Apecs & amend to OL Proposal clarifies, inspirequirements after primary to secondary leak specified in Tech Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKER.W O Duke Power Co 80/07/15 3pp
- --8007280438 Proposes Tech Spec revision Page 4 17-3 clarifying insprequirements after primary to secondary leak
 # Duke Power Co 80/07/15 2pp
- 8007310851 Forwards NUREG-1368 & NUREG 1367 detailing development of checklist for evaluating maint test & railbr procedures used in huclear plants Ack util thoperation in study M/o encis
 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 ip
- B0072B0427 Forwards proposed feth Spec 3 i R revision.changing pressure temp limits Class I & III license amend fee encl PARKER.H O Duke Power Co 80/07/22 3pp

Ş

- --8007280430 Proposed Tech Spec 3 i 2 revising pressure temp limits
 Dute Pouer Co 80/07/22 7pp
- 8007280544 Forwards response to recommendations in NUREG-0667, "Transjent Response of DEW Designed Reactors," Based on review, no action is necessary for majority of recommendations
 PARKER, NO Duke Power Cu 80/07/23 70pp
- Q Inspection reports. It Bulletins > correspondence
- 9007.240122 Forwards IE Info Notice 80-20 "Lost of Docay Heat Removal Capability at Devis-Desse Unit 1 While in Refueling Node "No response required G'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/08
- B007100144 Forwards iE lnsp Nepts 50-269/80-14,50-2/0/80-09 & 50-287/80-09 on 800128-0501 No Moncompliance noted MURPHY.C E Region 2. Atlanta, Roactor Construction & Engineering Bupport Branch 80/05/27 Ppp
- --8007100151 IE Insp Repts 50-269/80-14,50-270/80-09 & 50-287/80-09 on B0042D-0501 No nuncompliance noted Major areas inspected fire protection/prevention CONLODE,T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch Mitter.W H Region 2. Atlanta. Office of the Director 80/05/23 10pp
- 8007020204 Forwards 1E Info Notice 80-22. "Breakdowns in Contamination Control Programs" No written response required O'REILLY, J.P. Rigion 2, Atlanta, Office of the Director 80/05/28 to
- 8007210449 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY. J.P. Region 2. Atlanta. Office of the Director 80/05/28 to
- 8007010213 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/05/29 in
- B007F2004B Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY. J.P. Region 2. Atlanta. Office of the Director B0/06/10-200
- 8007010065 Forwards update of info to 791026, 1106, 1207 to 800124 ltrs in response to 1E Bulletin 79 14, ltems 2 & 3
 PARKER, H Q Dute Power Co 80/06/11 App
- 8007160255 Forwards IE Info Nutrice 80-27, "Degradation of Reactor Coolant Pump Stude" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11 ip
- 8007020763 Forwards 1E Dulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required 0'REILLY, J P Region 2, Alianta, Office of the Director 80/06/18 ip
- 8007020459 Forwards IL Circulat HD-15, "Loss of Reactor Coolant Pump Cooling & Hatural Circulation Cooldown" No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007150015 Ark receipt of IC lines Repts 50-269/80-18,50-270/80-13 & 50-287/80-12 on 800513-15 No proprietary info PARKER, W O Duke Power Co 80/06/23 ip
- --B007150019 Forunids 1E Insp Repts 50-269/80-18, 30-270/80-13 & 90-287/80-12 on 800513-13 No nuncompliance noted NURPHY.C E Rugion 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 2pp
- --8007150021 IE line Repts 50-269/00-18,50-270/80-13 & 50-287/80-12 on 800313-15 No noncompliance noted Najor areas inspected structural tuncrete for standby solutions facility HARRIS.J R Region 2. Atlanta. Diffice of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/at 3pp

i. Ki iš

- G007170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required D'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/24 1p
- 8007180533 Responds to 1E Bullotin 79-03A. "Longitudinal Weld Defects in ASMF SA-312, Type 304 Stainless Stool Pipe " No Type 300 piping in use for pressure piping Future use of piping will be reviewed PARKER. W O Duke Power Co 80/06/24 1p
- B007220192 Advises that hanger anap required by IE Bulletin 79-13 was not addressed in response to bulletin Hangers visually inspected as part of response to IE Bulletins 79-02 & 79-14 PARKER, W O Duke Power Co 80/06/27 1p
- BOD7230235 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codos " Writter rosponse required IE Circular 80-16 also encl No written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/2:
- B007220249 Forwards response to IE Bulletin B0-08 Approx 53 ponetrations concerned Weld defects classified as inclusion One repaired for cracking Design meets all requirements of ASME PARKER.W O Duke Power Co 80/07/01 App
- 8007140463 Forwards 800704 Revision 2 to response to IE Bulletin 79-018, "Environ Qualification of Class IC Equipment" Replaces previous submittal & 800519 revision entirely Includes corrections of minor errors THIES.A C Duke Power Co 80/07/07 34pp
- 8007250166 Forwards response to Items 1.2a & 3 of IE Gulletin 80-11.
 "Masonry Wall Design " Lists all masonry walls which are in groximity to or have attachments from wafety-related piping or equipment
 PARKER.W O Duke Power Co 80/07/07 21pp
- BG0731053B Provides shipping instructions for deficient steam generator mainway buits set aside for independent metallurgical analysis per NRC BG0627 request Requests nutification when buits have been shipped LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/0//18 ip
- B Reportable occurrences, LERs & related correspondence
- B007070319 Forwards LER B0-018/03L-0 PARKER, N D Duke Power Co B0/06/30 3pp
- ---8007070323 LER 80-018/03L-0 on 800601, high pressure svc water pump B declared inoperable due to motor cooler tube leaks Caused by erosion & corrosion resulting from constant flow of lake water Leaking tubes soldered & cooler pressurfixed PHILPOTT, F T Duke Power Co 80/06/30 1p
- 8007180417 Advises that 800610 incident involving loss of power to reactor protection sys Channel B does not constitute RO, as reported on 800611 Review indicates Tech Spec 3 5 i requirements were met Input fuse blew due to loose wires PARKER, W O Duke Power Co 80/07/10 2pp
- 800/210607 Forwards LER 80-010/01T-0 PARKER, W O Duke Power Co 80/07/11 3pp
- --BOO7210617 LER 80-010/017-0 on BOD614.at 100% full power, increase in condensor air ejector off-gas count rate indicated that once-through steam generator A had developed tube loak Probably caused by recent main steam stop valve testing PHILPOTT.F T Duke Power Co 80/07/11 ip
- 8007220563 RD on 800709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged Prom Upper sump of safe shutdown facility const Const personnel advised of discharge limits
 PARKER, W O Duke Power Co 80/07/16 2pp
- 8007290640 LER 80-007/01T-0 on 800710 during normal operations, breaker Which supplies control power A phase of emergency power switching logic tripped, due to burned out relay coil Caused by coil clearing contract failing to clear PHILPOTT.FT Duke Power Co 80/07/24 ip
- 8007290635 Forwards LER 80-009/01T-0 PARKER, H O Duke Power Co 80/07/24 3pp

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

- q. Inspection reports, IE Bulletins & correspondence
- 8007180251 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/06/24 lp
- 8007310163 Forwards IE lnsp Rept 50-288/80-02 on 800130-31 No noncompliance noted BOOK.H E Region 5, Ban Francisco. Fuel Facility & Materials Safety Branch 80/06/26 2pp
- --B007310168 IE Insp Rept 50-288/80-02 on 800130-31 No noncompliance noted Major areas inspected tour of facility, examination of logs & records of surveys, monitoring & personnel exposure HENBLAHBKI, FA, CURTIS, JR Region 5, San Francisco, Office of the Director BUOK, HE Region 5, San Francisco, Fuel Facility & Materials Safety Branch B0/06/26 App
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
 F. Security, medical, emergoncy & fire protection plans
- 800701038B Forwards Revision 6D of TMI modified amended physical security plan Plan withheld (ref 10CFR2 770)
 HERBEIN, J Q Metropolitan Edison Co 80/06/27 lp
- 8007080244 Forwards 790619 ltr of agreement between Radiation Mgt Core & Met Ed for insertion into 800601 TMI emergency plan. App C HERBEIN.J Q Metropolitan Edison Co 80/06/30 3pp
- 8007140647 Forwards State of PA authorization for open burning to train firsfighters
 HERBEIN J Q Metropolitan Edison Co 80/07/11 2pp
- BOO7ZRO553 Forwards revised fire protection program plan, replacing previous plan submitted Apr 1977
 HERBEIN, J. G. Metropolitan Edison Co. 80/07/11 lp
- B007220471 Forwards "Independent Assessment of Evacuation Time for TMI Nuclear Power Plent" in response to NRC 800510 ltr HERBEIN, J Q Metropolitan Edison Co 80/07/17 ip
- ---8007230195 "Independent Assessment of Evacuation Times for THI Nuclear Power Plant: " Vol 10 Prepared for FEMA THOMP80N, W E Affiliation Unknown 80/04/30. 42pp
- BO073]0340 Forwards Suppl 3 to fire protection safety evaluation supporting deletion of requirement to install thermal insulation on decay heat removal valves REID,R W. Operating Reactors Branch 4 80/07/21 5pp
- --B007310341 Suppl 3 to fire protection safety evaluation supporting deletion of requirement to install insulation on decay heat removal valves

 * Operating Reactors Branch 4 80/07/21 App
- Adjudicatory correspondence
- BOO71404BB Forwards position of Gaston County Board of Commissioners, NC; opposing spont nuclear fuel shipment through county & two proposed alternate routes W/o oncl RHYNE, G. A. Gaston County, NC BO/O4/15 ip
- BOO7230142 Forwards UBGB photographs of exhibit panel featuring TMI computer-plotted land use map. JR Wray 800429 memo re restart hearing map exhibit needs full size copies W/o photos.

 WHAY, J. R. Interior, Dept of, Geological Survey 80/06/04 11pp.
- --BD07230144 Forwards data dutlining spaces for prototype hazard mitigation maps, Compilations will be completed by 800430 WRAY, J. R. Interior, Dept. of, Ospological Burvey, 80/05/29 2pp
- --8007230168 Forwards description of maps for use in restart hearing LARDCHE, 0 · Environmental Engineering Branch 80/05/27 12pp

- 8007020651 Reconsideration of contentions, withdrawing prior Contentions 2,7,10 & 12, modifying Contentions i.S.6.8.7,i1,i4.16.2 17 & retaining Contentions 3.4,13 & 15 Draft of revised contentions & Certificate of Svc encl SHOLLY/S C Affiliation Unknown 80/06/05 15pp
- 8007020648 Mution speking extension of discovery period re Commission 800316 memorandum & order.CLI-80-16.% ASLB response concerning hydrogen control contentions Certificate of 8vc encl SHOLLY.S C Affiliation Unknown 80/06/09 9pp
- B007010269 Forwards time & attendance records for Ofc of Nuclear Reactor Regulation personnel, updated through B00419, in response to UCS Interrogatory 210 Copies available in PDR & LPDRs SWARTZ-L L Hearing Branch 1 B0/06/10 lp
- BOO7930057 Hotion to withdraw Contention 16 due to negotiations w/ licensee which solved Intervenor concerns re security Supporting documentation & Certificate of Sec encl SHULLY.S C Affiliation Unknown BO/06/10 9pp
- 8007280265 Forwards York County Industrial Development Corp 800610 resolution Urges NRC to expedite restart of TMI-1 BELL.J J Affiliation Unknown 80/06/12 App
- BOO714000B Response in opposition to licensee reply to TMI Alert 800529 motion to compel followen discovery Motion was filed within period prescribed in regulations for mailing Certificate of Svc ontl ADLER.TA Three Mile Inland Alert ADLER.TA Widoff Reager. Belkowitz & Adler 80/06/18 3pp
- ---B007140009 Second ret of followup Interrogatories directed to licensee Requests work-related accident documentation involving personal or property injuries Responses to THS Alert Interrogatories 5-6 must be updated Certificate of Svc encl ADLER, T A Three Mile Island Alert ADLER, T A Widoff, Reager, Selkowitz & Adler 60/06/18 4pp
- 8007310243 Forwards Commission B00527 memorandum & order centaining decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT,D 0 Division of Licensing 80/06/25 89pp
- 8007080043 Forwards UCS affidavit of RD Pollard Requests svc on partics in restart proceeding WEI88.E R Bholdon, Harmon & Weiss B0/06/26 ip
- --8007080050 Affidavit submitting add1 answers to Tourtellotte questions at RD Pollard 800411 deposition States that NRC approach in 800331 response to UCS interrogatories 150-153 is inadequate & unacceptable Certificate of Svc encl PDLLARD,R D Union of Concerned Scientists 80/04/26 App
- 8007020616 Supplemental rept on search for suitable TMI-1 hearing facilities re restart proceeding Identifies three possible places in Harrisburg.PA SvC list encl # Metropolitan Edison Co 80/06/27 4pp
- 8007020633 Response in opposition to TMI Alert second set of followup interrogatories due to untimely filing & irrelevance Argument re application of new info per ASLO 800505 order is w/o merit Certificate of Svc encl ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/06/27 6pp
- 8007010332 Response stating no opposition to SC Sholly 800610 motion to withdraw Contention 16 re security Issues Certificate of Svc oncl SHANSON,D T Hearing Granch i 80/06/30 3pp
- 8007070278 Forwards PA Emorgency Mgt Agency 800104 directives & circulars, suppl to hazard analysis matls & "RAC Comments on Annex E to Disaster Operations Plan," w/800519 cover ltr W/o attachments Cortificate of Suc encl
- 8007080004 Forwards People Against Nuclear Energy request for ASLB guidance on scheduling of psychological distress issue 8vc to parties in restart proceeding requested JORDAN, W. B. Sheldon, Harmon & Weiss 80/06/30 10
- --B0070B0005 Request for ABLR guidance re preparation of case in absonce of Commission decision, per present schedule of psychological distress issue Issues may be added to end of bearing or may be subj of srparate schedule W/Certificate of Svc UDRDAN, W 8 People Against Nuclear Energy UDRDAN, W 8 Bheldon, Harmon & Walso B0/06/30 Spp

- B007140005 Interrogatories directed to licensee & NRC Requests technical info re bypass capability around filter unit, vantilation sys mod in NUREG-0690 & restart evaluation Certificate of Syc and LENIS, M Affiliation Unknown B0/06/30 3pp
- 8007030290 Second set of interrogatories directed to UCS Requests identification of all pertinent info intended to be used in intervenor direct case & cross-examination on Contentions 1-14
 - SWARTZ, L. L. Antitrust Division 80/07/01 5pp
- --8007030293 Second set of interrogatories directed to MI Lewis Requests identification of all pertinent info intended to be used in intervenor direct case & cross-eramination on contention Demands statements re gaseous raduaste sys capability SWARTZ.L L Antitrust Division 80/07/01 4pp
- --8007030294 Second set of interrogatories directed to TMI Aiort, Inc Requests spec of alleged violations in safety evaluation to identification of all pertinent info intended to be used in intervenor direct case & cross-eramination on contentions SHARTZ.L L Antitrust Division 80/07/01. 7pp
- --8007030297 Second set of interrogatories directed to Cheeopeake Energy Alliance Requests statements on NRC review of separation of TMI-i & 2 operations & identification of all pertinent info intended to be used in intervonor direct case SHARTZ.L L Antitrust Division 80/07/01 7pp
- --8007030299 Becond set of Interrogatories directed to MM Aemodt Requests statments on technician teet performance & identification of ell pertinent info intended to be used in intervenor direct case & cross-eramination on Contentions 2.4,5 & 8
 SWARTZ.L L Antitrust Division 80/07/01, 6pp
- --8007030301 Second set of interrugatories directed to BC Shoily Requests etatements on safety evaluation of emergency plan offsite monitoring & identification of all pertinent info intended to be used in intervenor direct case & cross-examination SWARTZ.1. L Antitrust Division 80/07/01 10pp
- ---B007030302 Second set of interrogatories directed to Antinuclear Group Representing York Requests statements on State of PA emergency plan & identification of pertinent info intended to be used in intervenor direct case EMARTZ.L.L. Antitrust Division 80/07/01 6pp
- ~~B007030303 Second set of interrogatories directed to Newberry Township Requests statements on emergency plan as reviewed by NRC & identification of all pertinent info intended to be used in intervenor direct case & cross-examination SHARTZ-L L Antitrust Division 80/07/01 4pp
- --8007030304 Second set of interrogatories directed to Environ Coalition on Nuclear Power Requests all pertinent info intended to be used in intervenor direct case & cross-examination on Contentions I(a)(c)(d)(e), 2 & 4 Certificate of Svc enci SCHRTZ.L. L. Antitrust Division 80/07/01 7pp
- 8007140003 Follows safety evaluation interrogatories directed to NRC, re mpt & technical capability.operational GA program & Tech Specs per IE Bullatin 79-05A ref Certificate of Svc & supporting documentation encl HIDOFF.M P Three Mile Island Alert WIDDFF.M P Widoff, Reager, Belkowitz & Adler 60/07/01 ilpp
- BC07090220 Memorandum & order granting extension until E00707 for UCS to hand deliver safety evaluation discovery in restart proceeding SMITH.I W Atomic Safety and Licensing Board Panel 80/07/03 28pp
- 8007070212 Clarifies confusion in NRC 800701 second set of interrogatories directed to parties Intended to inquire how safety evaluation will be used in direct case & cross-examination SHART2.1 L. Antitrust Division 80/07/07 3pp

1 set of interrogatories re NRC restart
/07/07 is

TC re new info test to ater encl R. Shaidon,

- BOO7250680 Foilowup interrogatorise directed to licensee Requests complete harration of events leading to 800627 accident involving leak of 10,000 gailons of contaminated water Certificate of Svc encl ADLER.T A Three Mile Island Alert ADLER.T A Widoff, Reager, Selkowitz & Adler 80/07/07 5pp
- 8007250689 Hotion to compel licensee responses to second set followup interrogatories Intervenor complied w/ASLE 800505 order reschedule for discovery based on new info Interrogatory 2 will elicit new swidence. Cartificate of 8vc encl ADLER, T A Three Mile leland Albert ADLER, T A Hidoff, Reager, Selkowitz & Adier 80/07/07 App
- 8007310138 Response in opposition to NRC second eet of interrogatories NRC satablished no justification for untimely filing Certificate of Byc pnci Related correspondence SHOLLY/S C Affiliation Unknown 80/07/07 7pp
- 8007i60594 Forwarde memorandum & supporting documents re ASLB request for assistance in obtaining USGB special maps for TMI-i restart hearing Maps will be distributed in Jul 1980 when completed W o enci TOURTELLOTTE.J Hearing Branch 4 80/07/08 ip
- BOO7220203 Notion to compel production of licensee emergency plan implementing document Meane by which licensee intends to effectuate plan must be reviewed BRADFORD.9 P. Anti-Nuclear Group Representing York 60/07/08 2pp
- --R007220209 Responses to NRC second set of interrogatories Includes info re state plan review role of local agencies in emergency response test exercise & absence of offsite monitoring devices in safety evaluation BRADFORD, 0 P Anti-Nuclear Group Representing York. 80/07/08
- --B007220217 Response in opposition to majority of NRC 800701 second set of interrogatories due to generality of questions.

 Gertificate of 8vc ancl
 BRADFDRD, 0 P Anti-Nuclear Group Representing York 80/07/08.
- BO072B0130 Ack receipt of ltr to President Carter requesting intervenor funding for activities re restart hearings Consumer Advocate of PA request for intervenor funding denies Petition filed on 800330 REID.R W Operating Reactors Branch 4 80/07/08 10
- --8007280140 Forwarde D Hoesler ltr to Precident re intervenor funding for reply ROTHROFF,C L Energy, Dept of 80/01/22 2pp
- 8007i10324 Memorandum on People Against Nuclear Energy request for ASLB guidance re psychological stress issue hearing preparation Present situation reveals no problem for fifing testimony by end of Oct Future schedule will solve uncertainties SMITH.I W Atomic Safety and Licensing Board Panel 80/07/09. 3pp
- 8007140224 Response in opposition to Antinuclear Group Representing York 800630 motion for reconsideration of ASLE 800125 order rejecting Contention IIIC Commission apparently doss not intend to revise emergency cone Certificate of Svc encl IAHLER, R E Hetropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/07/09 Spp.
- B007170210 Response to NRC B00701 interrogatories re restart proceeding Alleges inadequate training of potential radiation monitoring team members & poor celibr preparedness Certificate of Box encl.
 BHDLLY.B C Affiliation Unknown B0/07/09, lipp.
- BOO7170370 Response to Chesapeake Energy Alliance Interrogatory 6-9 on Contention 6 re identification of TMI-2 event sequences that could result in eubstantial reactor coolant loes. W/unsignad & Unsubscribed affidavits & Certificate of Svc BMARTZ, L L Antitrust Division BO/07/09 7pp
- 8007220001 Hotion for reconsideration of ASLB 800625 memorandum & order denying TMI Alert motion to compet licensee answers to interrogatories Info is necessary to determine if pipe cracking resulted from deferred meint W/Certificate of Syc. ADLER, T A Three Hile Island Aiert. ADLER, T A Widoff, Reager, Belkowitz & Adler 80/07/10 5pp.
- 8007300035 Forwards complete set of correspondence re hearing ABLAB request for aesistance in obtaining special maps for TMI-1 restart hearing from GB Maps being developed will serve as models for establishing base map requirements within NRC.

 BALLARD.R L Environmental Engineering Branch 80/07/10 2pp

- 8007220002 Response in opposition to NRC second set of Interrogatories 1,2 & 3 due to untimeliness & irrelevancy Certificate of Svc
 - ADLER,T A Three Mile Island Alert ADLER, A Hidoff, Reager, Belkowitz & Adler 80/07/11 200
- 8007170150 Response in support of licensee 800623 motion for order requiring Environ Coalition on Nuclear Power to specify Contentions 2-2 & 2-4 Opposes request for imposition of sanctions. W/notice of appearance & Cortificate of Svc QRAY, J R Hearing Branch 1 80/07/14 9pp
- 8007180391 Response in opposition to TMI Alert 800707 motion to compel licensee responses to second set of followon interrogatories intervenor position re availability of info is contradictory to prior statements W/Certificate of Svc ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trombridge 80/07/14 Spp
- B007180421 Requests lifting of suspension of prehearing activities
 Repts on B00711 emergency planning meeting Revisions made
 after briefing & discovery on scope of emergency plan issues
 may generate addl contentions Certificate of Bvc encl
 AFTER BRIEFING Hatropolitan Edison Co ZAMLER.R E Bhaw, Pittman,
 Potts & Trowbridgs 80/07/14 9pp
- 8007210487 Forwards UCS objection to second set of NRC interrogatories Svc on parties requested MEISS, E R Bholdon, Harmon & Welss BO/07/14 ip
- --8007210475 Objection to second sot of NRC interrogatories Questions are not based upon how info in SER Certificate of Svc encl HEI89.E R Union of Concerned Scientists HEI89.E R Sheidon, Harmon & Welss 80/07/14 2pp
- --8007210503 Second set of intorrogatories directed to UCS Requests identification of Info relevant to Contentions 1-i4 w/names of witnesses intended to be called SHARTZ. L. Diffice of the Executive Legal Director 80/07/01
- 8007180376 Advises that licensee identified two addit possibilities for hearing space since 800627 filing of supplemental rept on search for suitable hearing facilities. Further delay may preclude scheduled commencument of hearing in Oct # Metropolitan Edison Co 80/07/15 3pp
- GOO7220085 Memorandum & order requesting resumption of prehearing activities re emergency planning Specific discovery requests must be made within 10 days Objections must be received in five days from svc of requests & responses in 15 days SMITH.I W Atomic Safety and Licensing Board Panol 80/07/15 3pp
- B007310137 Rept on search for switable hearing facilities Two addl possibilities ldentified in Harrisburg, PA Further davelopment will be reported Certificate of Bvc encl Related correspondence * Hetropolitan Edison Co 80/07/15 3pp
- 8007180374 Motion for dismissal of TMI Alert Contention 5 from restart proceeding due to deliberate refusal to ensuer licensee 800613 interpropatories. Intervenor refused to give facts in support of contention Certificate of Bvc encl BLAKE, EL Metropolitan Edison Co BLAKE, EL Shaw, Pittman, Potts & Troubridge 80707716 32pp
- BOO7220529 Forwards request on behalf of People Against Nuclear Energy requestion of whether psychological distress contentions are admissable in TMI restart proceeding JORDAN, W. 8 People Against Nuclear Energy JORDAN, W. 8 Sheldon, Harmon & Welss 60/07/16, jp
- ---8007220930 Requests Commission decision on psychological distress issues. Suggests that matter be first item of business for new chairman JORDAN.W S People Against Nuclear Energy JORDAN.W S Bheldon. Hermon & Helss 80/07/16 7pp
- ---8007220533 Mamorandum re People Against Nuclear Energy request for ASLB guidance Unable to rule whether filing of direct testimony by Pnd of Dot will be timely BHITH. I N Atomic Bafety and Licensing Board Panel 80/07/09
- BOO7220585 Requests that ABLB issue subposes to MOR-TV for tape or transcript of "What's Happening, America " Program broadcast on BOO324 & revealed facts re util maint practices Cartificate of Syc enc. Related correspondence ADLER.T A. Widoff, Reager, Selkowitz & Adler 80/07/16 Spp

- BOO7310143 Response to second set of interragatories Questions preheater role on filter sys as described in safety evaluation & restart repts Certificate of Svc encl LEWIS.M 1 Affiliation Unknown 80/07/16 2pp
- BO07220562 Advises that, despite late recoipt of UCS third set of interrogatories.NRC responses will be hand delivered to UCS 4 ASLE on B00728 SWARTZ L L Antitrust Division B0/07/17 2pp
- B007220564 Forwards signed affidavits identifying authors of NRC response to Chesapeake Energy Alliance Interrogatory 6-9 RHARTZ, L L Antitrust Division B0/07/17 3pp
- 8007230921 Response in opposition to TM1 Alert 800707 followup interrogatories re 800627 look of contaminated water Relation to remaining contentions not shown Certificate of Syc encl Rejated correspondence BLAKE, EL Metropolitan Edison Co BLAKE, EL Shaw, Pittman, Potts & Trowbridge 80707/17 Spp
- 8007230500 Response to MI Lewis 800630 interrogatories on SER Includes explanations on absence of investigation re lack of auxiliary bldg ventilation sys bypass Affidavits, prof qualifications & Certificate of Svc encl
 SHARTZ.L L Antitrust Division 80/07/18 15pp
- 8007230506 Forwards licensee response to interrogatories re TMI-(
 restort Related correspondence
 ZAHLER.R E Shaw. Pittman. Potts & Trowbridge 80/07/18 1p
- --BOO72303i4 Response to Intervenor MI Lewis interrogatories on NUREG-OSBO, "TMI-i Restart Evaluation "Related correspondence ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 90/07/18 App
- 8007230610 Response in opposition to Antinuclear Group Representing York 8007079 motion to compet set of emergency plan implementing document Mation inconsistent u/production groundrules Certificate of Sec encl
 2AHLER.R E Metropolition Edison Co ZAHLER.R E Shew, Pittmon, Paths & Trombridge 80/07/18 App
- 8007230604 Response in support of Peopio Against Nuclear Energy 8007i6 request for Commission decision on psychological distress issue Urges striking Section III of motion re opportunity for reply briefs Certificate of Svc onci
 TRCMBRIDGL 6 F Metropoiitan Edison Co TROMBRIDGE 6 F Shaw,
 Pittman, Potts & Troubridge 80/07/2i 5pp
- 8007230609 Forwards WL Jensen 800721 affidavit re NRC responses to BC Sholiy safety evaluation interrogetories 9-10 SWARTZ, L L Antitrest Division 80/07/21 2pp
- --8007230614 Response to SC Sholly 800630 Interrogatories on restart safety evaluation re steam generator level instrumentation designed to meet safety grade requirements & other issues Affidevits.prof qualifications & Certificate of Svc onel EWARTZ.L L Antitrust Division 80/07/2i 33pp
- --8007230617 Response to TMI Alert 800701 followup interrogatories re safety evaluation Explains suggested changes re improved mgt capability & technical expertise Certificate of Svc oncl SWANSON.D T Hearing Branch 1 80/07/21 20pp
- 8007250446 Ferwards ASLS 800721 Subpoons directed to R Fennimore of WDR-TV Ack requested SHITH.I W Atomic Safety and Licensing Courd Panel 80/07/21 1p
- --B007250492 Subpoens commanding R Fennioure of MOR-TV to appear on behalf of THI Alert on B00804 in Dethesds MD.re Fennioure B00324 television interview SMITH,I W Atomic Safety and Licensing Doard Panel 80/07/21
- BOO7290779 Response to NRC interrogatories based on safety evaluation Bubmits atems supporting allegation that licensee is not technically qualified Intervenor will rely on current financial statements re Contention 6 W/Cortificate of Svc HIDDFF.M P Three Mils Island Alart MIDDFF.M P Widoff. Reager, Selkowitz & Adlar BO/07/21 9pp
- B007230426 Memorandum & order ruling on TMI Alert 800707 motion to compel licenses responses to interrogatories Interrogatories 1.3 & 4 must be answered within 15 days Interrogatory 2 need not be answered BMITH.I W Atomic Safety and Licensing Board Panel B0/07/22 Spp

- 97.39 Memorandum advising that ASLB 800715 memorandum & order has purpose of setting scope of Commission discovery reity & establishing schedule for litigation of sency planning issues LIM Atomic Safety and licensing Board Panet 80/07/23 2pp
- 068; Forwards documents sent to SC Shally in response to 890630 regatories Copies avoitable in Local PDR H/o encls FZ,L L. Antitrust Division 80/07/24 ip
- M37 Response in apposition to THI Aloit 800710 motion for sideration of ASLO 800725 order denying intervenor in to compol Affirms licenses 800515 % 0604 responses to blert discovery & motion to compol W/Certificate of Byc S.C.L. Hetropolitan Edison Co. DLAKE, C.L. Shaw, Pittman, Potts subridge 80/07/24 10pp
- 0219 Forwards II Silver.AR Keimig.JW Gilray & FR Allenspach davits & prof qualifications re NRC 800721 response to slart fellowe interrogatories 5DN.D T Hearing Branch L 80/07/25 11pp
- 2315 Nesponds to UCS third set of interrogatories re new info in ty evaluation Functional test not expected prior to ing Adequate means for prevention of steam generator fill demonstrated Myaffidavits & Certificate of Syc TZ.L.L. Antitrust Division 80/07/28 42pp
- ral correspondence
- D282 Responds to 800320 ltr re BC Ames concerns about delays in lity restart Commission 770804 order identifies itams must be resolved prior to restart Time required to lye items will delay restart until late 1980 CRER.C Office of Congressional Affairs 80/04/02 2pp
- CORA Responds to 600414 lir re CN Leveau concerns about util actal condition PA Public Utile Commission should be acted Dacision on facility restart could not be expected re end of 1980 due to proceeding scope & other factors GREA.C Office of Congressional Affairs 60/04/18 Rpp
- 0343 Responds to 800414 ltr re E Clark concerns about util icial condition PA Public Utils Commission should be acted Decision on facility restart could not be expected re and of 1980 dus to proceeding scope & other factors IRFR.C Office of Congressional Affairs 80/04/18 2pp
- 142B Heaponds to ltr re Sf Argubright concerns about delays in lity restort Decision on restart will not be made until 178D due to time required to complete tasks re ission 770B09 order ERCR.C Affice of Congressional Affairs 80/05/05 2pp
- DIGS Responds to 800321 questions re possible financial failure vil Financial failure provides grounds for immediate cotion of license Contingency plans under development vill ensure protection of public hoalth RNE.J F Commission 80/05/07 2pp
- 0655 Urgas NRC approval of venting at TMI .A.A. Affiliation Unknown 80/06/04 1
- 0027 Urges expeditions restart of facility due to continuous case of power cost resulting from indecisions & delays STER, C.F. Affiliation Unknown 80/04/24 ip
- 0013 Urges efforts to resiart unit at early date due to rete pase approved by PA Public Util Commission for Met Ed omers INGER.C W Affiliation Unknown 60/06/26 2pp
- 0385 Respends to 800603 invoice & forwards insp fees for period or 1979 to Mar 1980 per 1007R170 W/o encl EIN.J 0 Hetropolitan Edison Co 80/07/02 Spp
- 0031 Responds to £00612 ltr forwarding recent recolution adopted out County Industrial Development Corp advocating return accility to svc. Hearing ordered to determine whather lity should be operating & under what conditions (RAFIR, Office of Nuclear Reactor Regulation, Director 7/00 18
- 220033 Forwards resetution unanimously adopted by York County dustrial Development Corp on 800610 Hesplution urges NAC expedite return of facility to svc LL.J J York, PA 80/06/12 2pp

- 8007180154 Responds to 800319 ltr re delay in placing TMI-1 back into svc Public hearing scheduled to begin Fall 1980 to determine whether facility should be operated & under what conditions Questions re nuclear R&D activities should be sent to DDE. REID.R W Operating Reactors Branch 4 80/07/09 ip
- --8007180160 Expresses support for nuclear power to replace imported oil & urges expediting return of TMI-1 to svc
 RIPLEY, H 1 Affiliation Unknown 80/03/19 2pp
- B007180457 Responds to G00622 ltr re restart at TMI-1 Public meeting scheduled for Fall 1980 to determine whether facility should be operated & under what conditions NRC primary responsibility is assurance of public health & safety RCID.R W Operating Reactors Branch 4 80/07/09 Ip
- --8007180461 Questions when TMI-1 will be allowed to restart & what is required of util by NRC SAWYER, E. E. Affiliation Unknown 80/06/22 2pp
- BOO7210084 Forwards NUREO-0591 & NUREO-0454 in response to request Advises that App A to NUREO-75/087 does not exist Several individual SARs identified in SRP have App A H/o encls.
 BOUDER.J L Division of Rules and Records BO/07/07 lp
- G007210121 Responds to 790709 ltr to NRC re concerns about facility & actions being taken by Concerned Citizens of Londonderry NRC has ordered public hearing to determine whether Unit 1 shoulf be operated Unit 2 feasibility studies are underway SNYDER. D J TH1 Program Office B0/07/09 2pp
- --8007210131 Expresses appreciation for 790629 visit to Middletown,PA Concerned Citizens of Londonderry,who have collected 750 signatures, are dedicated to closing facility NRC status regts would be of great benefit to area residents STREET.P A Affiliation Unknown. 79/07/09 2pp
- 8D07220320 Responds to 800401 ltr to President Carter expressing concerns over financial impact as stockholder w/licensee NRC is concerned w/economic impact Responsibility is limited to public health & safety RFIDJR W Operating Reactors Branch 4 80/07/09 2pp
- 8007230344 Responds to encl 800302 ltr to President Carter re delay in returning TMI-i to svc NRC has ordered public hearing to be conducted to determine whether facility should be operated to if to under what conditions
 REID.R W Operating Reactors Branch 4 80/07/07 2pp
- 8007240304 Responds to 800328 ltr to President Carter requesting that facility be returned to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980. NRC review of technical issues underway itr enc!
 REID.R W Operating Reactors Branch 4 80/07/09 Spp
- 8007240371 Responds to 800328 ltr re delay in returning facility to svc Public hearing scheduled for Fall 1980 re issues appropriate to assure public health & safety NRC review of technical issues underway Restart not expected before 1981 REID,R W Operating Reactors Branch 4 80/07/09 1p
- --8007240378 Requests that facility be returned to svc BARTMAN.V Affiliation Unknown, 80/03/28 1p
- 8007240392 Responds to 800329 ltr to President Carter re delay in returning facility to svc. Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of tochnical issues underway Ltr encl.
 REID:R W Operating Reactors Branch 4. 80/07/09. 2pp
- 8007240398 Responds to 800321 ltr to President Carter re delay in returning facility to svc Public hearing re issues to assure public health & sefety scheduled for Fall 1980 NRC review of technical issues underway. Ltr encl REID.R W Operating Reactors Branch 4 80/07/09. 3pp
- BOO7240404 Responds to 800420 ltr re delay in returning facility to svc Public hearing scheduled for Fall 1980 re issues appropriate to assure public health & safety NRC review of technical issues underway Restart not espected before 1981 REID.R W Opprating Reactors Branch 4 80/07/09. 1p
- 8007240412 Responds to 800420 ltr to President Carter re delay in returning facility to svc.Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr enci REID.R W Operating Reactors Branch 4. 80/07/09. 2pp

- 8007240416 Responds to 800306 ltr to President Carter is delay in returning facility to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID:R W Operating Reactors Branch 4 80/07/09 2pp
- 8007240419 Responds to 800323 ltr to President Carter re delay in returning facility to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID.R W Operating Reactors Branch 4 80/07/09 2pp
- B007240423 Responds to B00226 ltr to President Carter re delay in returning facility to svc Public heoring re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID.R W Operating Reactors Branch 4 80/07/09 3pp
- 8007240428 Responds to 8003i8 ltr to President Carter re delay in returning facility to svc.Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID.R.W Operating Reactors Branch 4 80/07/09 2pp
- EO07300006 Responds to 1tr re accident at TMI-2 Public hearings will be conducted to determine whether Unit 1 should be operated & under what conditions Licensee has not submitted proposal for overall plant recovery for Unit 2

 GNYDER, B J TMI Program Office 80/07/09 2pp
- 8007230624 Responds to 800619 itr to J Aboarne ro resulution adopted & comments re THI-1 restart NRC has ordered that public hearing be conducted to detormine if facility should be operated & under what conditions DENTON, H. R. Office of Nuclear Reactor Regulation, Director 80/07/10 p
- 8007270031 Responds to 800618 ltr to Commissioner Hendrie urging expedited proceedings to return TMI-1 to svc Development of record re restart is not expected before early 1981 Primary Commission responsibility is for public health DENTON. H R Office of Nuclear Reactor Regulation. Director 80/07/14 ip
- --8007290035 Urges NRC to expedite proceedings on TMI-1 on behalf of constituents serviced by JCP&L Requests are prompted by rate bikes New Jersey, State of 80/06/18 5pp QALLO, D A
- 8007310393 Urges restart of facility ADAM.L D Affiliation Unknown 80/07/19 ip 1
- 8007310398 Requests action in restoring svc to facility Economic burden to electricity users has been substantial LAMPE. W F Ecolaire Condenser, Inc. 80/07/21 ip
- 8007310375 Forwards MB Hayden 800717 1tr urging facility restart Requests reply
 QDODLING. II House of Rep 80/07/22 3pp
- I. Financial information
- 8007150730 Confirms 600626 telcon & forwards graph illustrating market price of General Public Utils Corp common stock for period Jan 1979 to mid~June 1980 HCHEDN, T G General Public Utilities GPU Service Corp 80/06/26 20pp.
- J Insurance & indemnity information
- 8007110011 FDIA request for all indemnity agreements, insurance policies & associated info between util, NRC &/or AEC refacility KEARNEY.R. W Affiliation Unknown 80/05/29 App
- 8007i10009 Responds to FDIA request for all indemnity agreements.
 Insurance policies & associated info between util NRC &/or
 AEC re facility Forwards documents listed in App A
 FELTON. J M Division of Rules and Records ED/06/23 7pp
- --B007110017 Confirms that NELIA has bound Insurance Policy NF-220 at limit of one million dollars issued to Mat Ed. JCP&L & PEPCO covering Pacifity Includes policy site description. GUATTROCCHI, J Nuclear Energy Liability Insurance Association 73/12/06 p
- --B00711002B Executed Amend 3 to Indemnity Agreement B-44.changing amount of financial protection BALTZMAN, J Antitrust & Indemnity Group 75/04/04 2pp

- ---B007110030 Executed Amend 5 to indomnity Agreement B-44.changing amount of financial protection SALTZMAN.J Antitrust & Indomnity Group ARRIDLD.R C Metropolitan Edison Co 77/05/20 2pp
- --8007110032 Executed Amend & to Indomnity Agreement 8-64, changing 2071 10032 EJECUTED AMBRO & to Indomnity Agreement & G., liternse numbers SALTZMAN.J Antitrust & Indomnity Group HERBEIN, J Q Metropolitan Edison Co 60/02/24 ip
- ~-B007i10037 Amend 9 to Indemnity Agreement 8-64, changing amount of financial protection
 SALTZHAN, J Antitrust & Indemnity Group 79/05/01 2pp
- ---B007110040 Executed Amond 9 to Indomnity Agreement B-64, modifying profatory language of Paragraph 5, Article 1, re course of transportation NELIA Policy (facility form) encl SALTZHAN, J. Antitust's Indomnity Group HERBEIN, J. G. Metropolitan Edison Co. 80/01/03 Spp
- --8007110046 Endorsement 2 to NELIA Policy NF-220 designating annual premium Declaration encl * Nuclear Energy Liability Insurance Association 79/01/12 2pp
- -- B00711005; Amend to Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsument 2 HARRONE J Nuclear Energy Liability Insurance Association 73/12/14 ip
- --8007110032 Amend to NELIA Policy NF-220 Constitutes Endorsement 4 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- ~-8007110057 Amend to industry credit rating plan premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 5 MARRONE, J. Nuclear Energy Liability Insurance Association 73/12/14 2pp
- ~--B00711Q060 Endossement 6, wasver of defenses endorsement (END), to NELI Policy NF-220 MARRONE, J Nu 73/12/14 2pp Nuclear Energy Liability Insurance Association
- --8007110062 Endorsement 7 to supplementary endorsement waiver of defenses for reactor const to NELIA Policy NF-220 MARRONE.J Nuclear Energy Liability Insurance Association 73/12/14
- ---B00711QD6B Amend to Insuring Agreement IV of NELIA Policy NF-220, "Application of Policy " Constitutes Endorsement & MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 lp
- --8007110072 Amend to advance premium & std premium endorsement of NELI Policy NF-220 Constitutes Endorsement 9 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 1p
- -8007110077 Endorsement 10 to advance promium & std premium endorsemen w/changes in subscribing companies & proportionate liability endorsement to NELIA Policy NF-920 MARRONE, J Nuclear Energy Liability Insurance Association 73/11/01 ip
- -8007110084 Endorsoment ii, assignment of interest in return premium & in reserve premium refund, to NELIA Policy NF-220 MANRONE, J Nuclear Energy Liability Insurance Association 74/07/15 2pp
- --8007110089 Amend to Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 12 MARRONE.J Nuclear Energy Liability Insurance Association 74/01/15
- --B007110091 Amend to Endorsement 10.advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 13 MARRONE, J Nuclear Energy Liability Insurance Association 74/02/15 ip
- ---B007110075 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 14 MARRONE, J Nuclear Energy Liability Insurance Association 74/03/15 ip
- --800711009B Endorsement 15 to NELIA Policy NF-220 increasing liability limits

 MARRONE, J Nuclear Energy Liability Insurance Association
 74/04/26 is

- --6007110103 Amend to Endorsement 13 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 16
 HARRONE, J. Nuclear Energy Liability Insurance Association 74/04/24 1p
- --B007110107 Amend of std premium endorsement w/changes in subscribing companies & proportionate liability endorsement Constitutes Endorsement in BANDES.C R Nuclear Energy Liability Insurance Association 74/12/12 ip
- --BC07110125 Amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 17 BARDES,C R Nuclear Energy Liability Insurance Association 75/01/01 1p
- --80D711012D Endorsement 20 to NELIA Policy NF-220, increasing limit of liability endorsement BARDES.C R Nuclear Energy Liability Insurance Association 75/03/21 1p
- --8007110132 Amend to Endorsement 18 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 21 BARDES, C.R. Nuclear Energy Liability Insurance Association 75/03/21 | 10
- --BO07110135 Amond to Endorsement 17 of advance promium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 22 BARDES C R Nuclear Energy Liability Insurance Association 75/04/22 ip
- --8007;10140 Endorsement 23 to advance premium & std premium endorsement to NELIA Policy NF-220 w/changes in subscribing companies & proportionate liability endorsement BARDESIC R Nuclear Energy Liability Insurance Association 75/12/01 ip
- --8007/10143 Amend to Endorsement 23 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 24 BARDES:C R Nuclear Energy Liability Insurance Association 76/07/09 10
- --8007110147 Amend to Condition 2.insp & suspension, to NELIA Policy NF-220 Constitutes Endorsoment 26 BARDES.C R Nuclear Energy Liability Insurance Association 76/12/15 ip
- --8007il0151 Endorsement 27 to waiver of defenses endorsement (ENO) to NELIA Policy NF-220 Constitutes Endorsement 27 BARDED.C R. Nuclear Energy Liability Insurance Association 76/12/15 2pp
- ---B007110185 Amend to definition of nuclear unergy hazard to NELIA Policy NP-220 Constitutes Endorsement 28 BARDEB,C R Nuclear Energy Liability Insurance Association 76/12/15
- --BOO7110160 Endorsement 29 to advance premium & std premium endorsement to NELIA Policy NF-220 BARDES, C R Muclear Energy Liability Insurance Association 76/12/31 2pp
- --8007110167 Amend to Cundition 4 % amend in 1977 subscribing companies & proportionate liability andorsement to NELIA Policy NF-220 Constitutes Endorsement 30 BANDES, C R Nuclear Energy Liability Insurance Association 77/01/31 2pp
- **8007110176 Amend to Endursement 29 to advance premium & std premium endorsement to NFL1A Policy NF-220 Constitutes Endorsement 32 BARDES, C. R. Nuclear Energy Liability Insurance Association 77/05/06 ip
- --B007i10178 Amend to Endorsement 32 to advance premium & etd premium endorsement to NCLIA Policy NF-P20 Constitutes Endorsement 33
 BARDES,C R Nuclear Energy Liability Insurance Association 77/08/17 1p

- --B007110201 Amend to Endorsement 34 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 35
 BARDES, C.R. Nuclear Energy Liability Insurance Association. 79/03/06 ip
- ~-B007ii020B Amend to advance premium & std premium endorsement & amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 36 BARDES, C R Nuclear Energy Liability Insurance Association 79/01/03 ip
- --8007110212 Amend to Endorsement 35 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 37
 BARDES, C. R. Nuclear Energy Liability Insurance Association 79/01/16 1p
- --8007110217 Endorsement 38 to NELIA Policy NF-220.w/changes in subscribing companies & proportionate liability endorsement BARDES,C R Nuclear Energy Liability Insurance Association 79/01/20 1p
- --BO07110222 Amend to Insuring Agreement 3 to NELIA Policy NF-220 Constitutes Endorsement 1 MARRONE. J Nuclear Energy Liability Insurance Association 73/12/14 lp
- --8007i10224 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 3 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 tp
- 8007i10043 Endorsement 1 to NELIA Policy EB-65

 * Nuclear Energy Liability Insurance Association 78/09/18 1p
- B0071B0404 Responds to B00413 request for add1 info re compliance Wfinancial protection provisions of Atomic Energy Act Forwards proposed Endorsements 43 & 44 to NELIA Policy NF-220 HERBEIN, J G Hetropolitan Edison Co 80/07/14 App
- 8007220584 Responds to NRC 800613 ltr re compliance w/financial protection requirements Proposed endorsement provides max protection available from private sources Restoration of limit of liability endorsement enci
 HERDEIN.J.O Metropolitan Edison Co 80/07/14 7pp
- P Operating license stage documents & correspondence
- B007240208 Forwards D&W licensees' responses to 790907 request for review of schedule for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115 CAPRA-R A TMI-2 Bulletine & Orders 79/10/24 1p
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resulution encl for guidance EIGENHUT, D Q Division of Licensing 80/06/11 62pp.
- 8007020017 Discusses licensee consideration of increased onsite radwaste storage Requests reviews for onsite storage additions in monthly operating repts Draft licensing position re onsite storage safety considerations encl REID.R W Operating Reactors Dranch 4 80/06/12 12pp
- BOO7140413 Submits info detailing leak testing operation plans, per BOO527 telcon Test to be performed BOO705-15 & 0725-0804, pending PaDER approval KLINOAMAN.R M Metropolitan Edison Co BO/06/16 2pp
- 8007140123 Forwards revised Tech Specs Table 4 1-2 from which footnote was inadvertently unitted per 800603 Amend 55 to License DPR-50 Footnote is not related to Amend 55 but to 761217 Amend 12 REID:R W Operating Reactors Branch 4 80/06/20 3pp
- --8007140125 Revised Tech Spec Table 4 1-2 from which footnote was inadvertently omitted * Dperating Reactors Branch 4 80/06/20 1p
- 8007010460 Requests NRC concurrence in use of Mine Safety Appliances, Co OMR-I & Scott TEDA-R respiratory protection cannisters against airborne radioactive matis Lists add precautions for use of cannister Related correspondence and HOVEY, & K Metropolitan Edison Co 80/06/26 Bpp

- BOO7170309 Requests implementation of recommendations contained in NUREQ-0612 "Control of Heavy Loads at Nuclear Power Plants-Resolution of Task Action Plan A-36" Guidelines for control of heavy loads encl EIBENHUT.D Q Division of Licensing BO/06/26 47pp
- BOO7240141 Requests licensee action to begin implementation of recommendations to assure safe handling of heavy loads Also requests review of control for handling heavy loads the datermine extent to which encl guidelines are satisfied EIBENHUT, D O Division of Licensing 80/06/26 47pp
- B007010326 Forwards simplified logic of degraded grid voltage, in response to questions raised during 800605 conference call Revised Tech Specs Change Request 60 will be submitted by 800627 HERBEIN, J Q Metropolitan Edison Co. 80/06/27 3pp
- B007070201 Responds to NRC B00202 request for revised submittel date re inadvertent reactor scram/safety injection Review of safety sys surveillence procedures & most policies & procedures scheduled for completion by Jan 1981
 HERBEIN, J. Q Metropolitan Edison Co B0/06/30 lp
- B007070294 Responds to NRC B00307 ltr re TM1-2 related requirements Items I A 1 3.I A 3 1.I C 5.II K 3 & III D 3 4 currently under review for TM1-1 Items for TM1-2 will be reported under separate cover HERBEIN-J Q Metropolitan Edison Co 80/06/30 2pp
- BOO7070343 Informs that due to relationship of tests to Crystal River 3 avent & IE Bullatin 77-27 response, tests verifying effects of combination of power loss on instruments & control functions will be provided by 800930

 HERBEIN, J O Metropolitan Edison Co 80/06/30 ip
- 8007080074 Forwards resolutions to long-term generic issues re May 1979 Commission orders & add1 info requested concerning small break LDCA. HERBEIN-J G Metropolitan Edison Co 80/06/30 100pp
- 8007170651 Forwards questions re fuel assembly holddown spring failures first observed at Davis-Besse 1 & under investigation by B&W Results of holddown spring insps at facility as well as safety significance required within 60 days NOVAK, T. M Assistant Director for Operating Reactors 60/07/01.
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core. Requests response within 60 days NOVAK.T M Assistant Director for Operating Reactors 80/07/01 486
- B007080358 Forwards 800616 info ltr to PADER, requesting approval to leak test two new tanks at TMI per ETB 5 6 HERBEIN, J 0 Metropolitan Edison Co 80/07/02 3pp
- B007140419 Forwards info ltr submitted to PaDER, requesting new tank leak test approval per ETS 5 & 2 4 2 M/o encl HERBEIN. J G Metropolitan Edison Co B0/07/02 2pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for THI-2 Lassons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 67pp
- BO07100215 Responds to B00625 1tr requesting correspondence from NRC in response to B00321 1tr from Chairman Bhanaman to J Abearne, Forwards Abearne B00507 1tr to Bhanaman W/o encl BWANBUN,D T Hearing Branch 1 B0/07/07 ip
- BOO7140670 Notifies that drawings have been forwarded in response to NRC request for info re containment bldg reinforcing steel & prestressed tendons
 SLEAR, D O General Public Utilities GPU Service Corp B0/07/08 in
- BD07140346 Requests exemption from requirements of iOCFR90.App H, concerning reactor vessel mati surveillance program Encl justification provides basis for request MERBEIN.J 0 Hetropolitan Edison Co 80/07/09 2pp
- BOO7140365 Comments on NUREG-0577 re inclusion of facility as Class i susceptibility Unit will be reclassified based on encl info Oversized drawings available in Central Files only HERBEIN J G Metropolitan Edison Co BO/07/09 24pp

- 8007180414 Provides info omitted from response to NUREG-0577 due to lack of info Info re lateral support of steam generator, reactor coolant & identification of min operating temps should result in lower susceptibility classification HERBEIN, J O Metropolitan Edison Co E0/07/09 5pp
- B007280345 Advises of personnel changes resulting from reorganization of Ofc Nuclear Reactor Regulation NDVAK.T M Assistant Director for Licensing 80/07/10 App
- 8007150589 Forwards response to 800819 ltm re discovery of cracks in keyway & bore sections in Westinghouse low pressure turbines MERBEINJ G Metropolitan Edison Co 80/07/11 25pp
- B007210372 Forwards description of control room design & guidelines for control room review Guidelines will be expanded Agrees to discuss progress at B00721 opening session of NRC control room design review HERBEINJ G Metropolitan Edison Co 80/07/14 29pp
- 8007220561 Advises of error in responses for Site Specific Question l, Parts B & C. submitted in 800616 ltr. in response to questions re low turbine disc cracking Correct responses encl PARKER. W D Duke Power Co 80/07/17 2pp
- 8007280023 Forwards list of YMI program ofc staff members to be used for ref in future correspondence CDLLINB,R C TMI Program Office 80/07/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007100009 Forwards combined lE Insp Repts 50-320/79-29 & 30-289/79-2i on 791023-1127 & notice of violation GRIER, B H Region i, Philadelphia. Office of the Director 80/01/09 3pp
- ---B007100012 Notice of violation from insp on 791023-1127
 * Region 1, Philadelphia, Diffice of the Director 79/12/20 ip
- --8007100014 Combined IE Insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 Noncompliance noted failure to store & control licensed matts in unrestricted areas WHITC.JR , YUMAS.G P , MCGAUGHY,R W Region 1, Philadelphia. Office of the Director 79/12/20 16pp
- 8007020161 Forwards 1E 1nfo Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- 8007010315 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/27 ip
- 8007230301 Forwards 1E Insp Rept 50-289/B0-12 on 800423-25 No nancompliance noted MARTININ 0 Region 1, Philadelphia, Safeguards Branch 80/05/30 200
- --B007230308 IE Insp Rept 50-289/80-1; on B00423-P5 No noncompliance noted Major areas inspected physical barriers, accoss control, assessment aids, communications & records Details withheld (ref 10CFR2 790) LADUN, R H Region 1, Philadelphia, Office of the Director DEVLIN, J W Region 1, Philadelphia, Gafeguards Branch B0/09/22
- 800701019B Responds to IE Bulletin 79 27, "Loss of Non-Class 1E Instrumentation & Control Power Gys Bus During Operation" Requests extension until 800730 to submit remaining required info HERBEIN, J @ Netropolitan Eduson Co 80/06/02 lp
- B007210572 Forwards IE Info Notice B0-26. "Evaluation of Contractor GA Programs " No written response required CRIER. B H. Region 1, Philadelphia. Office of the Director B0/06/10 ip
- 8007160349 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study No specific action or response required GRIER. B H Region 1. Phyladelphia. Office of the Director 80/06/11 ip

- 8007230130 Forwards IE insp Rept 50-289/80-11 on 800428-0502 No noncompliance noted BRUXNEB.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/12 2pp
- --8007230137 IE Insp Rept 50-289/80-11 on 800428-0502 No noncompliance noted Hajor areas inspected QA program implementation in areas of design changes, mode, audits, QA/QC surveillance & restart program
 NAPUBA 0 Region 1. Philadelphia, Office of the Director GREENHAM, E 0 Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/11 5pp
- B007020715 Forwards 1E Bulletin 80-15. "Possible Loss of Emergency Notification 9ys (ENS) W/Loss of Offsite Power " Written response required GRIER, B H Region 1. Philadelphia. Office of the Director R0/05/18 to
- 6007020526 Forwards lE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.O H Region 1. Philadelphia. Office of the Director 80/06/20 | p
- 8007210120 Confirms 800701 mgt meeting w/util in King of Prossia.PA to discuss planned near-term)icensee mgt reviews/appraisals which will augment routine NRC insp program GRIER.B H Region i, Philadalphia, Office of the Director 80/06/20 ip
- 8007160708 Forwards 1E Circular 60-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internat Contamination of Personnel" No written response required GRIER, B H Region 1, Philadelphia, Dffice of the Director 80/06/24 ip
- B007020535 Notifies that response to iE Bulietsn 80-12. "Decay Heat Removal Sys Operability," will be provided by 800630 HERBEIN, J G Metropolitan Edison Co 80/06/25 2pp
- 8007210202 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required CRIER.B H Region I. Philadelphia. Office of the Director 80/06/25 1p
- BO07070266 Responds to IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Review of bulletin is still underway Response will be provided by BO0725 HERBEIN.J & Matropolitan Edison Co 80/06/27 2pp
- 8007230129 Forwards IE Bullstin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 aiso enci No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/86/27 2pp
- BCD7110446 Forwards response to IE Bulletin 80-06 Elementary diagrams for all engineered safety features revealed some sampling valves not remaining in emergency mode Resetting containment isolation signal will close valves
 HERDEIN, J. O. Metropolitan Edison Co. 80/07/02 4pp
- 8007080375 Responds to 1E Builetin 80-12 re decay heat removal sys operability Dayly logs & weekly & monthly surveillances monitor performance capabilities of decay heat removal sys Discrepanties corrected by corrective maint program HERBEIN, J G Motropolitan Edison CO 80/07/03 3pp
- 8007150/2i Responds to iE Builetin 80-12 rr decay heat removal loss Provides procedural changes from review re adequacy of safeguarding agoinst redundancy ioss & diversity of decay heat removal capability & adequacy of loss event response HERBEIN.J G Metropolitan Edison Co 80/07/03 App
- BO0714038: Requests formal resolution to settle disagreement between util & Region 1 re use of ultrasonic cellbr blocks, as discussed in JE lasp Rept 50-289/80-09, Item 2 Util disagrees w/interpretations of ASME Boller & Pressure Yessel Code HERBEIN.J Q Metropolitan Edison Co 80/07/09 lipp
- 8007280336 Forwards response to IE Builetin 80-il. "Masonry Hali Design " Halls located in reactor auxiliary fuel handling & turbine bldgs have been identified as being in prolimity or having attachments from safety-related equipment HERBEIN.J Q Metropolitam Edison Co 80/07/il 34pp

- 8007210378 Forwards response to deviation noted in IE Insp Rept 50-289/80-05 Corrective action issued GAI/GPUNC TMI project mgt manual & GPUNC ES-009 to ensure that all GAI work is done per RRR KERDEIN, J G Metropolitan Edison Co 80/07/16 2pp
- 8007250504 Responds to deviation noted in IE Insp Rept 50-289/80-05 Corrective actions GAI/OPUNC TMI project mpt manual Revision 0 dtd 800430 & OPUNC EB-009.Revision 0 dtd 800708 issued to ensure ail GAI work is completed par util document HERBEIN.J Q Matropolitan Edison Co 80/07/16 2pp
- 8007220592 Advises that review of IE Bulletin 80-10 re contamination of nonradinactive sys & resulting potential for unmonitored uncontrolled environ releases has not been completed Response will be submitted by 800815
 HERBEIN.J G Metropolitan Edison Co 80/07/17 1p
- 8007220492 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Containment penetrations were shop fabricated, examined & pressure tosted prior to shipment to site for installation HERBEIN.J G Metropolitan Edison Co 80/07/18 lp
- 8007250401 Forwards final master list of Ciass 1E electrical equipment required to function under postulated accident conditions in response to 1E Builetin 79-018, Item 1 Final response to incomplete items will be provided by 800901 HERBEIN.J 0 Metropolitan Edison Co 80/07/18 32pp
- B007290617 Responds to noncompliances noted in 791025 notice of violation Corrective action procedures extensively reviewed & revised-radiation protection plan revised & review organization under study HERBEIN.J O Metropolitan Edisan Co B0/07/21 i3pp
- A Periodic operating reports & related correspondence
- 8007020182 Forwards TMT Program Ofc weekly status rept for wk of 800614-20. COLLING.J T TMI Program Office 80/06/23 App
- B007180539 Forwards TM1 Program Ofc weekly status rept for wk ending 800709. COLLINS J T TMI Program Office 80/07/07 20pp
- BOO72507i9 Forwards status rept for wk of 800706-12 COLLINS.J T M1 Program Defice 80/07/14 6pp
- 8007310136 Forwards wookly status rept for B00713-i9 Liquid effluents from Unit 1. released to Busquehanna River, were within Tech Spec limits No ilquid effluents discharged from Unit 2 COLLINS. J T THI Program Office 80/07/2i 3pp
- 8007290799 Forwards monthly operating rept for June 1980 HERBEIN.J Q Metropolitan Edison Co 80/07/24 ip
- ~~8007270B05 Monthly operating rept for June 1980 MITCHELL, D 0 Metropolitan Edison Co 80/07/15 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007250223 PNO-TMI-80-025 on 800627, inadvertent emergency safaguards sys signal was actuated while in coid shutdown w/RCS partially drained Opened valve caused 10,000 gallons of water to be spilled in reactor bldg HAVERRAMP.D. FASAND.A Region 1. Philadeiphia. Diffice of the Director COLLINS.J T TMI Program Office 80/06/27 ip.
- 8007230615 RO 80-12/IP during review of equipment required by IE Bulletin 79-DiB, found that post-accident pressure & temp would be higher than postulated in NBC 730705 rept Short & long-term action to be discussed in followy rept TODLE, R J Metropolitan Edison Co 80/06/27 ip
- 8007070248 Forwards LER 80-010/01T-0 HERBEIN.J & Metropolitan Edison Co 80/06/30 2pp
- ----B007070236 LER 80-010/01T-0 on 800606 licensee received itr stating FBAR does not assume that radioactive release paths exist via main safety valves or emergency feed pump turbine exhaust Caused by implementation of small break guidelines MITCHELL, D 0 Metropolitan Edison Co 80/06/30 ip
- BOO7070302 Forwards LER BO-008/99X-0 HERBEIN.J G Metropolitan Edison Co 80/06/30 ip

- --8007070313 LER 80-008/99X-0 on 800430, during annual imp of A emergency diesel gomerator, bearing insulation determined deteriorated Caused by normal aging or heating bearing lube oil Insulation replaced & luber viscosity oil used MITCHELL, D 0 Motropolitan Edison Co 80/06/30 3pp
- 8007080211 Forwards revised LER 80-004/01T-1 HERBEIN, J G Metropolitan Edison Co 80/07/03 lp
- --8007080214 Revised LER 80-004/017-1 on 800306, errors found in seismic analysis of common decay heat suction pinning associated w/valves DH-V1 & DH-V2 Seismic analysis corrected & mods made to DH-V2 Mods to DH-V1 to be completed by 801015 MITCHELL, D G Metropolitan Edison Co 80/07/03 2pp
- B007230158 PNS-1-B0-018 on B00709, licensee received telephone bomb threat Licensee conducted full scale search w/negative results BAILEY, R., HARTIN, W. Region 1, Philadelphia, Office of the Director B0/07/09 1p
- B007160524 Forwards LER 80-012/017-0 HERBEIN, J G Metropolitan Edison Co B0/07/i1 ip
- --B007160526 LER B0-012/017-0 on B00627 during review of environ qualification of equipment required to operate during main steam line break per IE Bulletin 79-01B, found that post-actident analysis exceeded previous figures
 MITCHELL,D G Metropolitan Edison Co B0/07/11 2pp
- 8007160618 Forwards LER 80-011/03L-0
 HERBEIN, J Q Metropolitan Edison Co 80/07/11 1p
- --B007160623 LER 80-011/03L-O on 800610 reactor bldg spray sys compressed air test exceeded late date Caused by incorrect date being entered into surveillance data tracking sys Info corrected Review of infrequent surveillances will be performed HITCHELL.D 9 Metropolitan Edison Co B0/07/11 2pp
- B007230239 Part 21 rept re cracked steom generator manway studs Batisfactory operating experience forms constitute reasonable basis for continued operation while investigations proceed TAYLOR.J H Babcock & Wilcox Co 80/07/i1 5pp
- 8007240133 PNO-80-002 on 800716, during NRC operations ctr drill, large number of difficulties were experienced w/telephone sys. primarily due to cutting of telephone cable MEIBS,D H. THOMPSON,D Office of Inspection & Enforcement, Office of the Director 80/07/18 19
- 8007280483 RD 80-i5/4P confirming 800722 telcon,on 800721,river water discharge temp was more than 3 F below inlet river water temp for approx 6-h incident will be reviewed to determine corrective action Review to be included in followup rept TOOLE,R J Hetropolitan Edison Co 80/07/22 1p
- U Congressional/Executive Correspondence
- 8007110363 Expresses interest of Environ Energy & Natural Resources Bubcommittee in TMI accident implications Commissioners are invited to B00702 public hearings to present NRC policy statement & discuss intervenors' limitations MOFFETT, T Congress (Juint & Rotating Committees, etc.) B0/04/24
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 800701020B Forwards updated table of incomplete fire protection issues as of 800612 Preliminary fire protection review rept identifies supplemental info/mods for items requiring additinfo IPFOLITO.T A Operating Reactors Branch 2 80/06/19 2pp
- 8007030142 Forwards draft revision to radiological emergency plan Plan withheld per Privacy Act & available in Central Files only ANDOGNINI, 9 C Boston Edison Co 80/07/01 1p
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT. D 9 Division of Licensing 80/06/25 89pp

- P Operating license Stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Hart 1 duniers group in Bethesda.

 MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I contaminment long-term program ORIMES, C T Plant Systems Branch 80/02/21 Sipp
- BOO7010070 Responds to FOIA request for 57 documents referenced in M Tokar memo to ACRS concerning pellet-cladding interaction Forwards documents Missing records and duplicative, supersoled or available elsewhere FELTONJ M Division of Rules and Records 80/06/20 2pp
- --B007010134 Forwards DM Steinberg 750/23 memo re plant problems due to poor fuei performance Factors identified in memo are sufficient cause for NRC to re-examine requirements applicable to fuei 0'RELLY. J P Region 2, Atlanta, Office of the Director 75/07/25 2p
- --8007010141 Discusses facility problems due to poor fuel performance Includes inforce releases to environ, usposure to site personnel operational limitations plans for future & impact on Region i
 STERNBEROLD M Region i, Philadelphia, Office of the Director 75/07/23 3pp
- 8007210057 Advises that Class [II fee is required for review of 800403 ltr requesting Tech Spec changes to permit operation in Cycle 5 w/core spray sparger cracks
 MILLER, W O License Fee Management Branch 80/07/02 ip
- GOO7:50:557 Discusses review of facility Tech Spec definition of term, "operable." applying to single failure criterion for safety sys Current definition of operable will be modified to be consistent w/model Tech Spec version
 ANDOGNINI, C. G. Doston Edison (a. 80/07/03. 2pp
- BOO7180393 Forwards secondary containment lenk rate test data Test was performed 800423 to verify that secondary containment was not violated by work performed during refecting MCGUIRE, P. J. Boston Edison Co. 80/07/07 ip
- --B007180402 Secondary containment leak rate test data Includes test conditions, base reading & standby Gas Treatment Sys A & B performance * Boston Edison to 80/04/23 in
- 8007290576 Requests extension until 800919 for comment period for NVREG-0577. "Potential for Low Flacture Toughness & Lamellar Tearing on PHR Stuam Generator & Reather Coolant Pump Supports " NVREG-0577 experienced distribution difficulties ANDOGNINI, G C Boston Edison Co 80/07/21 1p
- A Inspection reports. IE Bulleting & correspondence
- 8007;40440 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers " Written response required ORIER. B M Region i. Philadelphia. Office of the Director 80/05/12 lp
- 8007180077 Forwards IE Insp Rept 50-293/80-11 on 800310-14 No noncompliance noted BRUNNERE J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --B0071B010) IE Insp Rept 50-293/80-11 on B00310-14 No noncompliance noted Major areas inspected GA annual raview GA/GC administration program design changes, mod program & plant mods NAPUDA, G. ROBERTB, K. Region i. Philadelphia. Office of the Director GREENMANE Region i. Philadelphia. Reactor Operations Nuclear Support Branch B0/05/20 Jipp
- 8007020116 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required ORIFR, B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- BOO7010277 Forwards IE Info Nutice 80-23, "Loss of Sultion to Emergency Feedwater Pumps" No written rosponse required ORIER.D H Region I. Philadelphia. Office of the Director BO/05/29 1p
- BOO710006B Ack receipt of 800520 1th informing NRC of stops taken to correct violations noted in IF Imap Rept 50-293/80-08 ftr withheld (ref 100FR2 790) MARTIN.W G Region 1. Philadelphia, Safeguerds Branch 60/06/04 in

- --B007100071 Forwards IE Insp Rept 50-293/80-09 on B00227-29 & notice of violation Notice of violation withheld fref ICCFR2 790) HARTIN W G Region L. Philadelphia, Safeguards Branch 80/04/24 20p
- --B007i00074 IE Insp Rept 50-293/B0-08 on 800227-29 Noncompliance noted failure of security organization to follow response procedures in security contingency plans Details withheld (ref 10CFR2 790)
 LADUN.R R Region I. Philadelphia. Office of the Director DEVLIN.J W Region I. Philadelphia. Sateguards Branch 80/04/17
- 800721055; Forwards IE Info Notice 80~26, 'Evaluation of Contractor GA Programs " No written response required CRIER, B M. Region 1. Philadelphia, Office of the Director 80/06/10 ip
- 8007140257 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Whitten response required GRIER, B M Region 1, Philadelphia, Office of the Director E0/06/12 ip
- 8007250267 Forwards IE losp Rept 50-293/80-24 on 800409-10 No noncompliance noted CARLSONR T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --8007230270 IE Insp Rept 50-293/80-24 on 800409-10 No noncompliance noted Hajo: areas inspected routine insp of installed main steam automatic depressurisation sys relief valve & solenoid valves

 ENRITER.S D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch FINMEL.A E Region 1. Philadelphia, Office of the Director 80/06/13 3pp
- B007280401 Forwards 1E Investigation Rept 50-293/80-19 on B00428-0502 No noncompliance noted GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/17 2pp
- --B007280408 IE Investigation Rept 50-293/80-19 on B00428-0502 No noncompliance noted Major areas inspected allegations contained in B00320.0403 & OB newspaper articles re security guard misconduct ALLAN,J M. SMITH.R H. Region I. Philadelphia. Office of the Director B0/06/13 17pp
- 8007020693 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offbite Power " Written response required GRIER. U M Region 1. Philadelphia, Office of the Director 80/06/18 1p
- 8007020486 Forwards IE Circular 80-15, "loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required CRIER, D.H. Region 1. Philadelphia. Office of the Director 80/06/20 tp
- 8007160683 Forwards 1E Circular EO-14, "Radioactive Contomination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER. 1 Ht Region 1. Philadelphia. Office of the Director 80/06/24 ip
- B007210164 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required CRIER B H Region 1. Philadelphia. Office of the Director 80/06/25 ip
- B007140415 Responds to 1E Bulletin 79-14 re as-built safety-related piping sys seismic analysis Safety-related piping sys physical inspicompleted & inspicoviations resolved Heismic analyses input documents reviewed & most mode completed ANDOGNIN1.0 C Boston Edison Cp 80/06/27 Ppp
- 8007210006 Submits summary of insp % analysis results w/status of mods per util overall commitment, in response to IF Bulletin 79-14 Final rept re procedures % uniteria will be submitted by 801231 Support mods expected to be completed by 800901 ANDUGNIBLO C Boston Edison to 90/06/27 2pp
- B007210301 Responds to 1E Dulletin 80-06 me engineered safety feature reset controls Components assigned to two categories items requiring single operator action & items requiring two operator actions to reset initiating ownerpency signal ANDGONINI. 0 C Boston Edienn Co 80/06/2/ 4pp

- 800723009) Forwards IE Dulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-11 also encl No written response required GRIER, B H Regium 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007230182 Ack receipt of 800604 ltr informing NRC of steps taken to correct violation moted in 1E lnsp Rept 50-293/80-14 BRUNNER: J. Region 1: Philadelphia, Reactor Operations Nuclear Support Branch 80/06/27 1p
- --8007230176 Responds to NRC 800315 ltr re violation noted in IE Insp Rept 50-293/80-14 Corrective actions records of all licensed operators being reviewed to bring Forms 0-3 up to date ANDGONINI.9 C Boston Edison Co 80/06/04 2pp
- --8007230202 Forwards IE Insp Rept 50-293/80-14 on 800408-11 & notice of violation BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/15 2pp
- --B007230209 Notice of violation from insp on 800408-11 # Region 1, Pholadeiphia, Office of the Director 80/05/09 ip
- --B00723022i IE Insp Rupt 50-293/B0-14 on B0040B-11 Nuncompliance noted failure to keep requalification program records as required by licensee manual BETTENHAUSEN.L , KEHOE, D V Region 1, Philadelphia, Office of the Birector CAPHTON.D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/09 Spp
- 8007220174 Forwards notice of violation notice of proposed imposition of civil penalties & ltr of reprimand re 800308 incident of irradiated fuel being moved w/o secondary containment integrity
 BTELLD,V Office of Inspection & Enforcement, Office of the Director 80/07/08 3pp
- --8007220179 Notice of violation from insp on 800303-21 # Office of Inspection & Enforcement, Office of the Director 80/07/08 2pp
- --8007220181 Notice of proposed imposition of civil penalties in amount of \$13,000 re 800308 moving of irradiated fuel w/o secondary containment integrity

 * Office of Inspection & Enforcement, Office of the Director 80/07/08 ip
- --8007220187 Expresses concern re conduct during 800308 incident at facility future violations may result in stringent NRC enforcement actions including license mod, revocation or suspension &/or civil penalty STELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/08 lp
- --8007220191 Forwards notice of violation reactions during 800308 moving of irradiated fuel w/o secondary containment integrity at facility
 BIELLO,V Defice of Inspection & Enforcement, Defice of the Director 80/07/08 200
- --800722019? Notice of violation for License SOP-1585-4, based on insp on 800303-21 re J Alukonis activities during 800308 moving of irradiated fuel w/o secondary containment integrity * Office of Inspection & Enforcement, Office of the Director 80/07/08 1p
- 8007240372 Confirms oral notification made on B00707 that 20-day period for completing tests required by 16 Bulletin 80-17. Item 2,began at 12 01 AM on B00708 Also requests immediate notification of any malfunction found during tests ORIER, B M Region 1. Philadelphia, Office of the Director 80/07/09 2pp
- BOO7Ri0373 Responds to Item 1 & provides comments re Item 2 of IE Bulletin 80-17, "Failure of 75 of 185 Control Rods to Fully Insert During Scram at BMR " Examinations showed insignificant amount of water in 6-inch discharge header HOWARD, J C Boston Edison Ca BO/07/10 3pp
- 8007250309 Bubmits reply to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for release to environ Bampling, analysis & monitoring programs determined to be adequate ANDOONINI.G C Boaton Edison Co 80/07/11 1p
- BOO7280248 Ack receipt of BOO619 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-293/BO-18 BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch BO/07/ii ip

- --B007280252 Responds to NRC 800527 ltr re violation noted in 1E lnsp Rapt 50-293/80-18 Corrective actions covers installed on feedwater check valves when work not being performed ANDOONINI.0 C Boston Edison Co B0/06/19 2pp
- --8007280256 Forwards IE Insp Rept 50-293/80-18 on 800422-30 & notice of violation BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/27 2pp
- --8007280258 Notice of violation from insp on 800422-30
 * Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/22 ip
- --8007280262 IE Insp Rept 50-293/80-18 on 800422-30 Noncompliance noted failure to control foreign matl in accordance w/maint procedure requirements JOHNSON.J., ROBERTB.K. Region 1. Philadelphia. Office of the Director MARTIN.T T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/22 Bpp
- 8007210280 Ack receipt of 800310 ltr informing NRC of steps taken to correct violation noted in 800215 notice of violation BTELLO,V Office of Inspection & Enforcement, Dffice of the Director 80/07/14 2pp
- A Periodic operating reports & related correspondence
- BOO7130699 Forwards monthly operating rept for June 1980 MCQUIRE, P J Boston Edison Co 80/07/08 ip
- ---B007150704 Monthly operating rept for June 1980 WHITNEY. G G Boston Edison Co 80/07/07 App
- 8 Reportable occurrences, LERs & related correspondence
- 8004240228 PND-1-80-38 on 800308, two irradiated fuel assemblies lifted & rotated in spent fuel pool w/o meeting Tech Specs for secondary containment & diesol generator operability Fuel movement halted until Tech Specs met LAZARUS; M J. BRUNNER, E. Region i, Philadelphia, Office of the Director 80/03/10 ip
- B007010540 Forwards LER 80-022/03L-0 MCQUIRE, J.P. Boston Edison Co. 80/04/25 lp
- --8007010545 LER 80-022/03L-0 on 800527, during performance of surveillance test re RCIC steam line high temp, temp switch 1360-17A was found out of callbr Caused by setpoint drift MCLOUGHLINM T Boston Edison Co 80/04/25 IP
- 8007070378 Forwards LER 80-021/04T-0 MCGUIRE,P J Boston Edison Co 80/06/25 ip
- --8007070382 LER 80-021/04T-0 on 800508, algae sample from discharge outfall area contained reportable concentration of Co-60, according to Yankee Environ Lab 800616 analysis rept Cause not stated MCL009HLIN.M T Boston Edison Co 80/06/25 2pp
- 80070302B7 Forwards LER B0-024/03L-0 MCQUIRE, P J Boston Edison Co B0/07/01 tp
- --8007030287 LER 80-024/03L-0 on 800930 reactor core isolation cooling sys was declared inoperable Caused by faulty auto flow control Unit repaired & returned to svc MCLQUOHLIN,M T Boston Edison Co 80/07/01 ip
- 8007070357 Forwards LER 80-023/03L-0 HCGUIRE.P J Boston Edison Co 80/07/01 ip
- --8007070388 LER 80-023/03L-0 on 800526.during surveillance testing.
 Channel B of rod block monitor sys determined to be out of calibr Caused by misinterpertation of Tech Specs
 Requalification program will include sys review
 MCLOUGHLIN,M T Boston Edison Co 80/06/26 2pp
- 8007080182 Forwards LER 80-025/03L-D MCGUIRE, P J Boston Edison Co 80/07/02 1p
- --B0070B0192 LER B0-025/03L-0 on B00602, fire detection alarm from HPC1 quadrant sounded in control room on panel C-94 Roving fire patrol initiated & immediate investigation conducted Caused by leak at flange on HPC1 drain line valve AD2301-29 WHITNEY, G O Boston Edison Co 80/07/01 1p

- 8007080196 Forwards LER 80-026/03L-0 MCGUIRE,P J Boston Edison Co 80/07/02 1p
- --8007080200 LER HO-026/03L-0 on ROU6P3, reactor scram initiated by reactor low water lovel switcher of reactor protection sys NRC not notified within required time Caused by operations personnel error Requirements in-emphasized MCLQUOHLIN, M I Baston Edison Co B0/0//02 ip
- B0070B0202 Forwards LER 80-027/03L-0 MCGUIRE, P. J. Boston Edison Co. 80/07/03 1p
- --8007080205 LER 80-027/03L-0 on 80060%, stack gas grab sample pump PI4 tripped Caused by hinding in pump due to accumulation of dirt Pump refurbished & returned to svc KCLOUGHLIN, M T Buston Edison Co 80/07/02 ip
- B007160641 Forwards updated LER 77-009/03L-1 MCGUIRE,P J Boston Edgen Co B0/07/03 lp
- --B007160648 Updated LER 77-009/03L-i on 7/0323 during standby operation HPCI was inoperable for 5-h Caused by burnt out undervoltage coll in broaker for motor operated valve MD 2301-3 steam supply valve to HPCI Caused by overheating MCLQUOHLIN, M T Doston Edison Co 20/07/03 2pp
- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACIDR

 O Inspection reports, IE Bulletins & correspondence
- 8007170633 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Demineralized Water 9ys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/24
- DDCKET 50-295 210N NUCLEAR POWER STATION, UNIT 1
- F Security, medical, umorgency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withhold (ref 10CFR2 790)
 PEOPLES,D I Communwealth Edison Co 80/06/27 ip
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 89pp
- 8007020646 Memorphidum specifying issues to be discussed at 800701 oral argument, re State of IL contention that applicant commitments should be integrated in litense Tech Specs, in storage pool mod proceeding TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 80/06/26 200
- B007100022 Farwards "Tech Specs for Nutlear Power Reactors." 10CFR50 advance notice of rulemaking for which counsels' attention is invited by ASLB Comments may be submitted to Commission re B00701 oral argument B1SHDP.C J. Atumic Safety and Litensing Appeal Panel 80/07/03
- --R007100026 "Tech Specs for Nuclear Power Reactors.' 100FR50 advance notice of rulemaking Establishes and for deciding which items from SAR must be incorporated into Tech Specs & modifies definitions of spec categorias.

 CHILKIS J Office of the Secretary of the Commission 80/06/30
- 8007300036R Updates certain projected load & capacity estimates which appear in record of proceeding per applicant obligation to keep ASLAB appraised of development. Related contespondence STEPTOE:PP Isham, Lincoln & Beale 80/07/08 2pp
- H General correspondence
- 8007110533 Responds to 8002/8 request to reject util lifense to increase storage capacity or facility apont fuel pool Actions initiated 791010 to assure that emergency plans are implemented at all licensed operating reactor sites DENTON-H R Office of Nuclear Reactor Regulation. Director 80/05/04 200

- 8007210208 Responds to encl 800418 ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article encl DENTON H R Office of Muclear Reactor Regulation, Director 10pp 80/05/21
- 800731035B Responds to encl 800401 telegram to President Carter urging closing of facility & all nuclear plants near populated areas NRC 800229 confirmatory order required immediate short-term actions to assure public safety EISENHUT.D G Division of Licensing 80/07/17 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 800722030B Provides summary of 800507-09 meeting w/utils to core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accident: CATTON, I California, Univ of, Los Angeles 80/05/10 App
- P Operating livense stage documents & correspondence
- 8004240480 Forwards add1 into 19 review of unresolved safety issues. trip rept of Lessens Learned implementation team & task action plan in view of high population density surrounding plants DENTON.H R Office of Nuclear Reactor Regulation, Director 80/04/09 33pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entl for guidance EISENHUT.D O Division of Licensing 80/06/11 62pp
- 8007100393 Summary of 800920 Technology Exchange Meeting 3 w/utils in Bethesda.HD to discuss accident mitigation features for
 - power plants LONG.J K Division of Systems Integration 80/06/12 75pp
- 8007010110 Notification of 800625 meeting w/utils & Sandia Labs in Bethesda.MD for presentation of overview of facilities risk study Agenda encl IBRAEL.S.L. Reliability & Risk Assessment Dranch 80/06/16 3pp
- 8007110557 Summary of 800530 meeting w/util in Dothesda, MD re status of action plan ULSHAN,L N Operating Reactors Branch 1 80/06/23 3pp
- B00701042B Forwards Drawing RRE-1-4B50 re reactor, turbine & generator trip protection, in response to B00619 discussion concerning automatic initiation of auxiliary feedwaler sys Brawing available in Central Files only NAUGHTON, W.F. Commonwealth Edison Co. B0/06/24 1p
- 8007010211 Forwards response to 800229 confirmatory order requiring review of key plant sys vulnerability areas, possible operator dependent areas & control room emergency procedures NAUGHTON.W F Communwealth Edison Co 80/06/26 49pp
- 8007010608 Notification of 800617 meeting w/utils in Bethesda.MD to discuss containment structural response failure pressures & failure modes for faculities as described in NRC 800410 ltr to Comm Ed HEYER. J F Reactor Bystems Branch 80/06/26 2pp
- B007070116 Submits revised responses to MRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECER.R F Commonwealth Edison Co 80/06/26 4pp.
- 8007170319 Summary of 800612 meeting w/utils in Bethesda.MD re interim reliability evaluation program OLSHAN.L N Operating Reactors Branch 1 80/06/30 Dpp
- 800717024; Forwards request for odd) info re backfitting of severe accident mitigation features Response requested within 30 days MOVAK, T M Assistant Director For Operating Reactors 80/07/02
- B007230001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tach Specs & Model License conditions for TMI-2 Lessons Learned Category A items encl for guidants EIBENHUF.D & Division of Licensing 80/07/02 A9pp

- 8007190476 Submits add1 info re 10CFR30. App J.exemption Mod to install flowmeter w/high flow alarm on penetration pressurization piping to personnel air lock door seals completed Includes marked set of drawings W/o drawings
 NAUGHTON.W F Commonwealth Edison Co 80/07/07 4pp
- B00717059B Summary of B00625 meeting w/Pickard.Lowe & Gerrick, Inc re risk study including modeling for plume tragectory, containment event tree & modeling, use of plant data & consideration of external events ISRAEL.S L Reliability & Risk Assessment Branch B0/07/07 Bpp
- 8007230646 Summary of 800507-08 technology exchange meetings w/utils in Chicago, IL re core melt accident sequences & associated phonomenology for facilities NRC perceives real urgency to for answers to key technical questions
 MEYER, J F Reactor Systems Branch 80/07/09 12pp
- B007280605 Notifies that PG Stoddart, primary NRC reviewer for Zion, has requested add1 info to complete review, as result of discussions re NUREG-0578 Item 2 1 8a on improved post-accident sampling capability Lists drawings sent NAUGHTON.W F Commonwealth Edison Co 80/07/21 2pp
- O Inspection reports, 1E Bulletins & correspondence
- 8007020065 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/28
- B007210396 Forwards 1E Circular 80-13, "Grid Strep Damage in Westinghouse Fuel Assemblies " No written response required KEPFLER, J G Region 3. Chicago, Office of the Director 8 80/05/28
- 8007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director. 80/05/29
- 8007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVGS) Moldup Tanks "Three Zion heldup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES, D.L. Commonwealth Edison Co. 80/06/04 3pp
- 8007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/10
- 8007020199 Forwards IE Insp Repts 50-295/80-09 & 50-304/80-09 on B00512-15 & 19-20 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND. J A Region 3. Chicago, Sefeguards Branch 80/05/11 2pp
- --B00702021) IE Insp Repts 50-299/80-09 & 50-304/80-09 on 800512-15 & i9-20 Noncompliance noted failure to conduct proper personnel screening to secure & estend doors of vital areas & to test alarm sys Details withheld (ref 10CFR2 790) MADEDA:T J. CHRISTOFFER:O. Region 3, Chicago, Office of the Director HIND, J.A. Region 3, Chicago, Safeguards Branch B0/06/10. 2pp
- 8007160165 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response PLER, J 0 Region 3, Chicago, Office of the Director 80/06/11
- 8007020076 Forwards response to IE Bulletin 80~12, "Docay Heat Removal Sys Operability " Review of RHR degradation events found nume similar to Davis-Besse incident DELGEDROE, L O Commonwealth Edison Co 80/06/16 Spp
- B007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AN-90 or NH-90 series hydramotor actuators
 PEOPLES, D.L. Commonwealth Edison Co. 80/06/16 3pp
- 8007030037 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/18

- 8007020589 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown "No written response required MEPPLER.J Q Region 3. Chicago. Office of the Director 80/06/20
- 8007230754 Forwards IE lnsp Repts 90-295/80-00 & 90-304/80-00 on 800421.0515-20,30 & 31.No noncompliance noted FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- ---B007230758 IE Insp Repts 50-275/80-08 & 50-304/80-08 on 800421,0515-20.
 30 & 31 No noncompliance noted Major areas inspected Bergen-Paterson large bore hydraulic snubbers on Unit 2 steam generators
 BANIELBON,D H Region 3. Chicago, Reactor Constitution & Engineering Support Branch YIN.1 T Region 3. Chicago, Office of the Director 80/06/18 3pp
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/24 io.
- 8007230268 Forwards IE Imap Repts 50-273/80-il & 50-304/80-il on 800327-29 & notice of violation DAVIS,A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/04/24 2pp
- --B007230272 Notice of violation from insp on B00527-29
 * Region 3, Chicago, Office of the Director 80/06/20 ip
- --B007230276 IE Insp Repts 50-295/80-11 & 50-304/80-11 on 800527-29
 Noncompliance noted excess pH of waste water roleased &
 failure to standardize sodium hydroxide solution during
 baric acid titration
 ESSIO.T H., DESTHANN, H.J., ROYTEK, C. Region G., Chicago, Office of
 the Director 80/06/20 9pp
- BOO7230289 Forwards IR Bulletin BO-16, "Potential Misapplication of Reseasont Inc Models 1191 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular BO-16 also enci No written response required KEPPLER.J O Region 3. Chicago, Office of the Director BO/06/27 ip
- BOO7310507 Forwards IR Health Physics Appraisal Repts 50-275/80-05 & 50-304/80-04 on 800310-21, notice of violation & significant appraisal findings REPPLER.J G Region 3. Chicago, Office of the Director BO/06/27 and
- --807310510 Notice of violation from health physics appraisal on 800310-21
 * Region 3. Chicago, Office of the Director 80/06/27 2pp
- ---8007310515 IE Health Physics Appraisal Repts 30-295/80-05 & 50-304/80-04 on 800310-21 Noncompliance noted significant weaknesses found in areas reflecting on mgt & mgt support Weaknesses in emergency response & access tontrol BCHUMACHER, M.C. MILLER, D.E. Region 3. Chicago, Office of the Director FISHER; N.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/06/23 58pp
- 6007310335 Forwards Waste Packaging Insp Rept 15000046/80-32 on 600222 & 26 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 60/06/30 3pp
- --8007310339 Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 Noncompliance w/DDT regulations noted max dose rate on surface of transport trailer was 220 millinem/h O'REILLY,L A Region B, Ban Francisco, Office of the Director THOMAS.R D , BOOK.H E Region 5, Ban Francisco, Fuel Facility & Haterials Bafety Brench 80/04/02 12pp
- BOO7310339 Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 Noncompliance w/DOT regulations noted max dose rate on surface of transport trailer was 220 millirem/h O'REILLYL A Region 5, Ban Francisco, Office of the Director BO/04/02 12pp
- BOO7250441 Responds to IE Bulletin 80-10, "Contamination of Nonradioactive 8ys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES, D. L. Commonwealth Edison Co BO/07/07 2pp.

- 8007230650 Forwards response to LE Dulletin BO-11. "Masonry Wall Design " Requested investigation not performed at Dresden. Unit 1 due to extended outage Requirements will be met prior to startup M/a encl.
 PEDPLES:D L. Commonwealth Edison to 80/07/07 2pp
- 8007250638 Forwards response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds." Dresden Unit 1 designs will be reviewed it feasibility of performing radiographic examinations will be assessed before unit returned to svc. PEGPLES.D.L. Commonwealth Edison Co. 80/07/09. 7pp
- A Periodic operating reports & related correspondence
- 8007140327 Forwards monthly operating tents for June 1980 GRAESSER. K. L. Commonwealth Edison Co. 80/07/07 ip
- --8007(4003) Monthly operating repts for June 1980 CODK, J M Commonwealth Edison Co B0/07/07 lipp
- B Reportable occurrences, LERs & related correspondence
- 8007170230 Part 21 rept re defective Westinghouse Type W-2 switch Caused by intermittent contact clusure w/switch in automatic start position Utils notified of potential problem NSD technical bullotin encl
 ANDERSON.T M Westinghouse Electric Corp 80/06/18 Spp
- 8007010484 Forwards LER 80-028/03L-0
 WANDKE,N E Commonwealth Edison Co 80/06/23 19
- --8007010408 LER 80-028/03L-0 on 800524.while performing diesel generator loading test on 10 diesel generator engine tripped after running 5 minutes at full load Caused by air leak on supply line fitting to fuel shutoff pistons Fitting replaced KRAHCZAK, A T Commonwealth Edison Co 80/06/23 ip
- 8007010493 Forwards LER 80-029/03L-0
 WANDRE,N E Communwealth Edison (a 80/06/26 ip
- --B007010500 LER NO-029/O3L-O on B00931.while removing insulation to repair leak on discharge line to buric acid filter i heat trace on circuits OME 190/205 were damaged Caused by numerous nicks III heat trace by personnel effecting repair MAZELRIGG.S Commonwealth Edison Co B0/06/26 1p
- 8007160655 Forwards LER 80-030/03L-0 GRAESSER, K.L. Commonwealth Edison Co. 80/07/07 ip
- --8007160662 LFR 80-030/031-0 on 800612, during normal operation, condenser air ejector offgas rad monitor, IRT-FTR6, failed low Caused by worn contacts inside photohelic rapparently worn down through normal use Photohelic replaced OST, F Commonwealth Edison Co 80/07/07 ip
- 8007220449 Forwards LER 80-032/03L-0 GRAESSER, K. L. Commonwealth Edison Co. 80/07/15 1p
- --8007220453 LER 80-032/03L-0 on 800616, fuel all storage tank leve) found 300 gallons less than 40,000 gallon limit Causad by engineering assistant not anticipating fuel consumption associated widesel generator testing every three days KRAMCZAK, A T Commonwealth Eduson Co 80/07/16 ig
- 8007220399 LER 80-007 has been cancelled COLLINS M Commonwealth Edison Co 80/07/21 1p
- 8007220400 LER 80-006 has been cancelled COLLINS: M Commonwealth Edison Co 80/07/21 is
- 8007220401 LER 80-004 has been tancelled COLLINS.M Commonwealth Edison Co. 80/07/21 in
- 8007220402 LER 79-075 has been cancelled COLLING.N Commonwealth Edison Co 80/07/21 I
- B007220404 LER 79-047 has been cancelled CULLINB, M Commonwealth Edison Co 80/07/21 ip
- 8007220405 LER 79-064 has been cancelled COLLING.M Commonwoalth Edison Co 80/07/21 ip
- BOO7230345 LER BO~003 has been cancelled COLLING, M Commonwealth Edison Co 80/07/22 in

- 8007230347 LER 79-089 has been cancelled COLLINS.M Commonwealth Edison Co 80/07/22 ip
- 8007230351 LER 79-088 has been cancelled COLLINS.M Commonwealth Edison Co 80/07/22 ip
- 8007230332 LER 79-086 has been cancelled COLLINS.M Commonwealth Edison Co 80/07/22 is
- 8007230357 LER 79-080 has been rancelled COLLINS.M Commonwealth Edison Co 90/07/22 1p
- T Hearing transcripts on non-antitrust matters
- 8007150024 Transcript of 800701 morning hearing in Bethesda, MD Pp 1-120
 - * Atomic Safety and Licensing Board Panel 80/07/01 123pp
- DOCKET 50-296 BROWNS FERRY NUCLEAR PONER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8007210024 Forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printout containing supporting data for vital area analysis Encis withheld (ref 10CFR2 790)
 IPPOLITO
- 8007220028 Confirms that LASL will conduct vital area analysis of Units 2 & 3 on 800714 E Claibourne & J Rand will conduct visit IPPOLITO T A Operating Reactors Branch 2 80/07/03 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENRUT, D.G. Division of Licensing 80/06/25 87pp
- H General correspondence
- 8007170380 Expresses concern re plans to construct low level waste storage & incineration facility Proposed facility would present significant health risks to highly populated area Requests public hearing & FIS
 HOLLINGSWORTH Affiliation Unknown 60/07/09 ip
- J Insurance & indemnity information
- B007010516 Forwards Endorsement 51 to ANI Policy NF-178 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div E0/06/23 2pp
- B00731043A Forwards Endorsement 43 to MAELU Policy MF-66 F1ELDER.J Marsh & McLennan.Inc . B & M Nuclear Consultants.Inc Div B0/07/21 2pp
- P Operating license stage documents & correspondence
- B00723002B Summary of B00207 meeting w/Hark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & gustending issues relative to Mark I containment long-term program GRIMEB.C T Plant Bystems Branch 80/02/21 31pp
- 8007070269 Responds to 800123 ltr re use of ODYN code in determining operating limit min critical power ratio Util requests further clarification of expected penalties that may be imposed on top of ODYN calculations
 MILLS.L M Tennesses Valley Authority 80/05/28 2pp
- BOO7020711 Responds to BO0422 ltr rs low level wasts mgt at plant Ultimate util objective is to provide for onsite raduate storage No target date has been established by TVA for submitting application for incineration approval NOVAK, T M Assistant Director for Operating Reactors 80/06/25
- 8007080285 Responds to NRC 800523 request for facility participation in phase two Interim Reliability Evaluation Program Urges definitive conclusion of phase one bufore continuing Outline of critical areas to be resolved encl MILLS, L M Tennessee Valley Authority 80/06/30 3pp

- B007080380 Responds to NRC 791002 ltr to all BWR licensess & 791031 ltr to util Util Funds allocated for Mark I owners group full-scale test facility program Schedule for complotion of plant-unique analysis forthcoming MILLS.L M Tennessee Valley Authority 80/07/01 ip
- 8007210026 Forwards request for additinfo to complete review of containment purging & venting at facilities NOVAK.T M Assistant Director for Operating Reactors 80/07/08
- B007220376 Forwards proposed changes to ETS Section 2 1 re thermal discharge limits
 MILLS.L M Tennossee Valley Authority 80/07/14 ip
- --B0072203/7 Proposed change to ETS, Section 2 i re thermal discharge limits * Tennessee Valley Authority 80/07/14 ip
- 8007310531 Confirms 800712 concurrence w/util schedule for returning to power operation Concurrence based on util completion of corrective actions re failure of control rod sys following manual trip C/REILLY, J P Region 2, Atlanta, Office of the Director 80/07/14 2pp
- 8007240225 Forwards Amends 61,96 & 33 to Licanses DPR-33,DPR-52 & DPR-68 respectively & notice of issuance & availability IPPOLITO,T A Operating Reactors Branch 2 80/07/15 3pp
- --8007240231 Amends 61.36 & 32 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs re thermal discharge limits PPOLITO, T A Operating Reactors Branch 2 80/07/15 13pp
- --B007240234 Notice of issuance & availability of Amends 61.56 & 33 to Licenses DPR-32, DPR-52 & DPR-68, respectively 1PP0L170, T A Uperating Reactors Branch 2 80/07/15 Zpp
- BOO7300284 Responds to encl BO0602 memo re low level waste mgt at facility Util plans to construct two separate low level waste facilities onsite Const on first four cubicles began recently NRG approval of plans necessary DENTON.HR Diffice of Nuclear Reactor Regulation, Director BO/07/23 Gpp
- O Inspection reports. IE Bulletins & correspondence
- 8007240089 Forwards JE Info Notice 80-20, "Loss of Decay Meat Removal Capability at Davas-Besse Unit 1 While in Refueling Mode" No response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/08 30s
- 8007140476 Forwards IE Bulletin 80-13. "Cracking in Core Spray Bpargers " Written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/12
- B007020192 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28 in
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/29 1p
- 8007220029 Forwards IE Info Notice 80-25, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 3na
- BOO7140306 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/12 ip
- 8007020479 Forwards response to IC Bulletin 80-09 transmitted by UP D'Reilly 800417 ltr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLGL M Tennessee Valley Authority 80/06/16 2pp

- 8007020761 Forwards IE Bulletin 80-15, "Postible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Offsite of the Director 80/06/18
- B007020391 Forwards IF Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response regulated O'REILLY, J.P. Region 2. Atlanta, Office of the Director E0/06/20
- B007310344 Forwards IE Insp Repts 50-239/80-25,30-260/80-19, 50-296/80-20 % 50-327/80-22 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/23
- --B007310351 IE Insp Repts 50-259/80-25.50-260/80-19.50-296/80-20 & 50-327/80-22 on 800521 Insp consisted of anforcement meeting in Atlanta. GA to discuss exceeding DOT radiation limits during shipment of radwaste from Browns Ferry DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/20 2pp
- BOO7170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/24 1p
- BOO7180523 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," & to 800404 confirmatory orders Feedwater pump turbing & main turbine trip circuitry will be upgraded MILLBL M Tennessee Valley Authority 80/06/26 Spp
- 8007230233 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters WEither A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Rogion 2, Atlanta, Office of the Director 80/06/27
- BOO7210091 Forwards response to IE Bulletin BO-10 Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradioactive & radioactive sys Routine sampling & analysis program established MILLB.L.M Tennessee Valley Authority BO/07/07 Spp
- 8007230726 Forwards monthly status rept re IE Bulletin 79-14, "Seismic Analysis for An-Built Hafety-Related Piping Bys." presenting status of work as of 800701 MILLS.L. M Tennessee Valloy Authority 80/07/07 29pp
- B007280615 Responds to IE Bulletin 80-08. "Examination of Containment Penatration Wolds " Results of investigation encl MILLS.L. M | Fannessee Valley Authority | 80/07/07 | 5pp
- 8007210103 Forwards response to IE Bulletin 80-11 Identifies mesonry walls that support or are near safety-related sys Submits schedule for re-evaluation program CRDSB,J L Tennessee Volley Authority 80/07/08 3pp
- 8007280460 Ack receipt of 800616 ltr informing NRC of steps laken to correct violations noted in IE Insp Repts 50-259/80-20, 50-260/80-15 & 50-296/80-16 LEWIB,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/09 2pp
- --B0072B046B Responds to NRC B00520 ltr re violations noted in lnsp Repts 50-259/B0-20,50-260/B0-15 & 50-296/B0-16 Corrective actions calibr valve orientation corrected Justifies decision re nonreporting of deisel genrator failure MILLS.L M Tennessee Vailey Authority B0/06/16 4pp
- --8007280475 Forwards IE Insp Repts 50-259/80-20.50-260/80-15 & 50-296/80-16 on 800405-0502 & notice of violation LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 2pp
- --8007280478 Notice of violation from insp on 800405-0502

 * Region 2, Atlanta, Office of the Director 80/05/20 ip

- B007250596 Forwards response to Item i of IC Bulletin 80-17 re water in scram discharge vol No significant amount of water was found in discharge vol & associated piping Scram discharge vent valves are operable.

 CROSS,J L Tennessee Valley Authority 80/07/11 2pp
- B007310047 Forwards second interim rept in response to IE Bulletin B0-04 Sinle B00412 interim rept, util completed review of primary containment sys. reactor protection sys. RMP sys *core spray sys Fvaluation of other sys underway CROSS.J L Tennessee Valley Authority B0/07/11 2pp
- 8007220522 Requests extension until 800811 for performing manual & automatic scram required by IC Bulletin 80-17 Extension needed because of current heat wave MILLS-L M Tennessee Valley Authority 80/07/16 2pp
- 8007310208 Forwards response to Items 2 (Unit 3).4.5.6(c) & 7 of IE Bulletin BO-17 Present standby liquid control sys design is unable to support two-pump flow but sys is equipped w/ interlocking contacts Item 2 for Units 1 & 2 will be sent MILLS.L M Tennessee Valley Authority 80/07/16 10pp
- 8007270357 Orents extension of time to 800811 for performing scram tests per 1E Bulletin 80-17 EISENMUT.D 0 Division of Licensing 80/07/18 2pp
- BOO7300972 Forwards response to IF Bulletin 79-018. "Environ Qualification of Class IE Equipment "Summaries of equipment qualification evaluations, based on Fact 4 criteria, encl Full response will be forwarded when evaluations complete MILLS, L H Tennessee Valley Authority 80/07/18 54pp
- R Periodic operating reports & related correspondence
- 8007220443 Forwards "Effluent % Waste Disposal Semiannual Regt," supplemental info for second half 1978
 DEWEASE, J G Tennessee Valley Authority 79/02/15 ip
- --B007220462 "Effluent & Waste Disposal Semiannual Rept." supplemental info for second half 1978 * Tennessee Valley Authority /9/02/15 15pp
- 8007220342 Forwards "Effluent & Waste Disposal Semiannual Rept." supplemental info, first half 1979 ABERCROMBIE.H Tennessee Valley Authority 79/08/17 1p
- --B007220346 "Effluent & Wasto Disposal Semiannual Rept." supplemental info.First half 1979
 * Tennessee Valley Authority 79/08/17 16pp
- 8007220481 Forwards "Efficent & Waste Disposal Semiannual Rept. Supplemental Info.Second Half 1979 " ABERCROMBIE.H Tennessee Valley Authority 80/01/31 1p
- --BO7720491 "Effluent & Waste Disposal Semiannual Rept. Supplemental Info. Becond Half 1979" "
 * Tennesses Valley Authority 80/01/31 16pp
- BO07160552 Forwards monthly operating repts for June 1980 ABERCROMBIE.H L. Tennessee Valley Authority 80/07/10 1p
- --B007160556 Monthly operating repts for June 1980 THOM.T., GREEN.D Tennessee Valley Authority 80/07/02 32pp
- B Reportable occurrences, LERs & related correspondence
- 8007010370 Forwards LER 80-019/03L-0 CALROUN, J R Tennessee Valley Authority 80/06/25 ip
- --B0070103/7 LER B0-019/03L-0 on B00527 during normal operation, discovered drywell sump flow transmitter FY-77-14 had output signal shift Cause unknown Transmitter replaced % instrument loop calibr

 * Tennasse Valley Authority 80/06/25 2pp
- 8007080415 Forwards LER 80+023/017-0 CALHOUN, J R Tennessee Valley Authority 80/05/30 [p
- --8007080416 LER BO-023/01T-0 on 800617, during normal operation, spare Dresser Industries safety valve was discovered w/crarks in guide Caused by initial pouring of cesting & cooling Spare valves will be inspected for crarks

 * Tennessee Vallay Authority 60/06/30 2pp

- B007110425 RO-BERO-10-296/8024 on B00628, during routine maint shutdown, approx 68 of 18% control rods failed to fully insort when reactor was manually tripped Unit is shut down until cause determined & corrective action taken
 ABERCROMSIE, H i Tennessee Valley Authority B0/06/30 ip
- 8007240256 PND-II-80-119 on 800628.76 control roos failed to fully insert during routine shufdown Manuel strams failed to effect repair Auto scram caused full insertion Cause being investigated Confirmation of action ltr issued JULIAN.C. LEMIS.R C. Region 2, Atlanta, Office of the Director 80/06/30 2pp
- B00711037B Forwards LER B0-020/03L-0 CALMOUN.J R Tunnessee Valley Authority B0/07/03 in
- --8007110380 LER 86-020/03L-0 on 800409, during normal operations. 38 diesel generator auxiliary oil pump motor tripped twice Caused by failure of Moover Model 6203; sealed bearings Notor replaced Bearings replaced every two yrs s Tennessee Valley Authority 80/07/03 2pp
- 8007110388 Forwards LER 80-021/03L-0 CALHDUN, J R Tennessee Valley Authority 80/07/03 1p
- --B007110394 LER B0-021/03L-0 on B00609. during normal operation, reactor core isolation cooling turbine tripped on overspeed due to loss of speed control Caused by failure of voltage suppressor CR-1, type B-240. In F6N box # Tennossee Valley Authority 80/07/03 2pp
- B007240260 PNB-II-B0-iI7A updates PNB-II-B0-iI7 Cause of 76 control rods not fully inserting after B0052B routine shutdown still not determined No blockage found in scram discharge piping Addi flow tests will compare drain capabilities JULIAN, C. LEMIS, R.C. Region 2, Atlanta, Office of the Director 80/07/03 ip
- BC07180301 Forwards LER B0-022/03L-0 CALHOUN, J R Tennessee Valley Authority 90/07/14 1p
- --BOO71BO314 LER 80-022/07L-0 on BOO616, while performing SI 4 i A-14, turbine first-stage pressure permissive & pressure switches PS-1-9) A & B exceeded limits Caused by setpoint drift Switches recalibr a Tennessee Valley Authority BO/07/14 2pp
- 8007290820 Forwards LFR 80-024/01T-0 CALHOUN,J R Tennesses Valley Authority 80/07/18 ip
- --8007290829 LER 80-024/01T-D on 800528, when reactor was manually scrammed.72 of 195 control rods failed to fully insert Probable cause due to water in screen discharge vol Investigation in progress to determine corrective action * Tennessee Valley Authority 80/07/18 2pp
- 8007290695 Forwards LER 80-025/03L 0 CALHOUN, J. R. Tennesser Valley Authority 80/07/24 ip
- --BC07290702 LER BO-025/03L-O on 800625, during normal operation, continuous heat detector damaged & caused false alarm Caused by accidental damage to heat detector by personnel performing mods in area Craftsmen cautioned

 * Tennessee Valley Authority 80/07/24 2pp
- T Hearing transcripts on non-antitrust matters

Maria

- B007240271 Transcript of B00703 briefing by NRC on facility Pp 1-54 * Commission 80/07/03 Blpp
- 800724009) Transcript of H00715 bracking on status of facilities in Hashington DC Pp 1-21 * Commission H0/07/15 Alpp
- DOCKET 50-297 NORTH CAROLINA STATE UNITY PULSTAR REACTOR

 G Inspection reports, JE Bulletins & correspondence
- 8007170164 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internet Contamination of Personnel" Mo written response required O'REHLLY. J.P. Region 2. Atlanta, Office of the Director 80/06/24 ip
- B007140542 Forwards IR losp Rept 50-297/80-01 on 800605 No noncompliance noted KENNA-W B Region 2. Atlanta, Safeguards Branch 80/06/25 lp

- --8007140555 IE Insp Rept 50-297/80-01 on B00405 No noncompliance noted Major areas inspected licensee security plan.security organization.access control, surveillance & protection against sabutage Details withheld (ref 10CFR 2790) HOMELL, J C. GILLESTIE.F F Region 2. Atlanta. Office of the Director 80/06/25 1p
- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- BOO7230713 Ack receipt of util 800326 ltr transmitting Revision 9 to physical security plan Encl to util ltr withheld (ref 100FR2 790)
 1PPDELTO.T A Operating Reactors Blanch 2 80/07/07 2pp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UC5 780502 petition for reconsideration of 780413 memorandum & order UC5 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D 0 Division of Licensing 80/06/25 69pp
- P Operating license stage documents & correspondence
- B00723002B Summary of 800207 meeting w/Mark I owners group in Bethesda, ND, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES, C T Plant Systems Grant 80/02/21 31pp
- 8007140480 Forwards Amend 63 to License DPR-46 & notice of issuance & availability
 IPPDLITO, T A Operating Reactors Branch & 80/06/24 3pp
- ---8007140486 Amend 63 to License DPR-46 modifying App B of Tech Specs to delete Section 2 1 1/3 1 1 Section Is superfluous to requirements in Section 2 1 2 ro max thermal discharge temp IPPULITG.T A Operating Reactors Branch 2 80/06/24 Spp
- --8007:40492 Notice of issuance & availability of Amend 63 to License DPR-46 IPPOLITO,T A Decrating Reactors Branch 2 80/06/24 2pp
- B007160440 Submits status & schedule for completion of Mark 1 program mods at facility per NRC teleon request PlLANY, J M Nebraska Public Power District 80/07/10 2pp
- B007240255 Forwards Pages 193 & 194 to be inserted in facility Tech Specs Pages 1938 & 194a issued w/Amends 43 & 45 are redundant & should be removed IFPOLITO.T A Operating Reactors Branch 2 80/07/14 2pp
- --B007240237 Tech Specs Pages 193 & 194 re limiting conditions for operation & surveillance requirements for auxiliary electrical sys # Nobraska Public Power District 78/05/02 2pp.
- 8007280452 Application for amend to License DPR-46 deleting Tech Spec 2 1 2/3 1 2 re max discharge temp. In response to Region 4 request Amend foe was submitted w/previous Tech Spec change request PILANT, J M Nebraska Public Power District 80/07/16 3pp
- --8007280467 Revised Tech Specs deleting Section 2 1 2/3 1 2 re max discharge temp State pollutant discharge permit encl * Nebraska Public Power District 80/07/16 5pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007140553 Forwards IE Bulletin 80-13, "Cracking in Core Spray Bpargers " Written response required BEYFRIT.K V Region 4, Dailas, Office of the Director 80/05/12 19
- 8007030199 Responds to IE Bulletin 80-09 re hydramotor actuator deficiencies 8:x Model AH-90 &/or NH-90 Beries hydramotor actuators are used at facility, None uses springs made &/or installed between Rept 1975 & Jan 1978
 PILANT, J M Nebraska Public Power District 80/05/20 ip
- BOO7100016 Updates response to 1E Bulletin BO-07, "BWR Jet Pump Assembly Failure " Licensee will perform surveillance required by Tech Specs & surveillance recommended by GE instead of program outlined in 1E Bulletin BO-07 PILANT, J M Nebraska Public Power District 80/05/21 2pp

- 800702026B Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs "No written response required EEYFRIT.K V Region 4, Dallos, Office of the Director 80/05/28 ib
- 8007010048 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/05/29 in
- 8007210152 Responds to IE Bulletin BO-13. "Cracking in Core Spray Spergers "No cracking found during insp of spargers & segment of piping between inlet noticle & vessel shroud PILANT, J H Nebrasia Public Power District 80/05/31 ip
- B007020333 Responds to IE Builbtin, 79-02, "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts " Lists hangers to be repaired LESSOR.L C Nebraska Public Fower District 80/06/03 3pp
- 8007130125 Forwards IE Insp Rept 30-298/80-08 on 800506-09 & 19-23 No noncompliance noted MADSEN, O.L. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- GOOTRROIRO Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 60/06/10 is
- B007140410 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability "Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director B0/06/12
- 8007240051 Forwards IE Circular 80-15, "Loss of Reactor Coelant Pump Conling & Natural Circulation Coeldown" No written response required. BEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/20
- A Periodic operating reports & related correspondence
- BOO7080391 Forwards monthly operating rept for June 1980 LESSOR, L C Nebraska Public Power District BO/07/01
- --B007080375 Monthly operating rept for June 1980
 BALLINGER,P L Nebraska Public Power District 80/07/01 9pp
- BOO7250421 Forwards corrected monthly operating rept for June 1980 LEBEOR.L C Nebraska Public Power District 80/07/18 1p
- --BOO7230423 Corrected monthly operating rept for June 1980
 BALLINGER, P.L. Nebraska Public Power District 80/07/01 2pp
- S Reportable occurrences, LERs & related correspondence
- 8007080295 Forwards LER 80-012/03L-0 LESEDR, L C Nabraska Public Power District 80/06/12 App
- --8007080302 LER 80-012/03L-0 on 800521, during local leak rate test, nine penetrations found leaking excessively Caused by normal wear Beal ring replaced, seats polished, packing tightened & ring seal cleaned PHILLIPB, D. L. Nebraska Public Power District 80/06/12 ip
- 8007090005 Forwards LER 80-013/03L-0 LESSOR,L C Nebraska Public Power District 80/06/13 2pp.
- --8007090007 LER 80-013/03L-0 on 8005i6 during surveillance procedure on primary containment isolation valve timing, RHR discharge to radwaste inboard isolation failed to close in time Caused by failure to check struke time after maint DOAN, P F Nebraska Public Power District 80/06/i3 ip
- 8007080365 Forwards LER 80-014/03L-0 LESSOR, L C Nebraska Public Puwer District 80/06/16 2pp

- --BOO70BO368 LFR BO-014/03L-0 on BOO51B, while performing SP 6 3 13 1, relay 14A-K28 was found dr-chergized, preventing start of core spray pump to normal power Superflows inited is were inadvertently left connected in Lore spray pump circuits BEDNAR, L F Nobraska Public Power District 80/06/14 1p
- B0072805B4 Forwards LER 80-015/03L-0 LESSOR.L C Nibraska Public Power District B0/07/02 2pp
- --8007280592 LER 80-015/03L-0 on 800606 during control rod scramtime testing, full-in control rods incorrectly scrammed % fully withdrawn Cauled by personnel urror Rod returned to correct position Procedure modified BORER.P J Nebraska Public Power District 80/07/02 29p
- 8007150702 LER 79-031 has been concelled COLLINS.M Nebraska Public Power District 80/07/14 lp
- 8007250501 Confirms 800710 telcon re temp exceeding limit of [0] F in facility discharge canal on 800709 Periodic noncompliances expected as long as hot weather creates increased demand for full power operation Tabulations for 800709-16 oncl CODPER.L J Nebraska Public Pawer District 80/07/18 3pp
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency % fire protection plans
- 8007300440 Forwards emergency plan, revised draft, Jul 1980 FAY, C W Wisconsin Electric Power Cu 80/07/25 1p
- Q Adjudicatory correspondence
- B007310R43 Forwards Commission B00527 memorandum & order containing decisions on UCS /80502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cobles EISENHUT.D C Division of Licensing 80/06/25 870p
- B0072i0A43 Corrected notification that 800312 petition is denied Forwards B00Ai0 FR notice. Director's decision under 100FR2 206 & related SERs DENION. H R Office of Nuclear Reactor Regulation. Director 80/07/10 1p
- --B007210445 Notice of issuance of Director's decision under 10CFR2 206 denying WI Environ Decade Inc 800312 petition DENTON: If R Office of Nuclear Reactor Regulation. Director 80/06/10 ip
- ---8007210647 Director's decision under 100FR2 206 denying MI Environ Decade, Inc 800312 petition for show cause order to order enjoining operation of facility due to steam generator tube degradation DENTON. H R Office of Nuclear Reactor Regulation, Director 80/06/10 Spp
- --8007210649 Safety evaluation to Steam generator tube degradation supporting continued operation of facility

 + Office of Nuclear Reactor Regulation, Director 80/07/10
 10pp
- 8007280477 Ack receipt of directors' 800710 decision to facility Attachments to decision jumbled Requests complete set of attachments FALKIM Wisconsin's Environmental Decade 80/07/14 ip
- P Operating license stage documents & correspondence
- 8007230079 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Bapes which would provide acceptable resolution encl for guidance EISENHUT.D Q Division of Licensing 80/06/11 62pp
- 8007090230 Notifies that four Westinghouse demonstration optimized fuel assemblies will be loaded in Cycle 8 core during Mai 1981 refueling shutdown Reload safety evaluation to be performed per HCAP-922s.including assessment of core impact FAY.C W Wisconsin Electric Power Co 80/07/01 2pp
- BOO7170588 Forwards evaluation of control rod guide thimble wear in facilities designed by Westinghouse Based on review, issue is resolved CLARK.R A Operating Reactors Branch 3 80/07/01 4pp

- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Fech Specs & Model license conditions for TMI-2 Lessons Learned Category A items enci for guidance EISENHUT.D O Division of Licensing 80/07/02 69pp
- BOO7150648 Requests extension of comment period on NUREO-0577 until BOO915.due to other work efforts Requests notification only if extension found unacceptable FAY.C W Hisconsin Electric Power Co 80/07/03 lp
- BOO7150682 Submits cumments on tWREG-0654 Two objectionable items 19minute time Frame proposed to Complete public notification & propriety of min shift staffing requirements proposed in Table B-I FAY.C W Wisconsin Electric Power Co 80/07/03 6pp
- B007210034 Confirms schadule for 800/09 meeting at site to discuss recent increase of personnel errors at facilities KEPPLER.J G Region 3. Chicago. Office of the Director 80/07/03
- B007210408 Forwards revised Tech Spec 15 3 4 for steam & power conversion sys & four 72-h test repts for auxiliary feed pump in response to NRC 800516 request for addl info re auxiliary feedwater sys FAY:C W Wisconsin Electric Power Co 80/07/08 4pp
- --BOO7210438 Revised Tech Spec 15 3 4 for steam & power conversion sys

 * Wisconsin Electric Power Co 80/07/08 3pp
- --8007210452 "Seventy-Two Hour Test of Turbine-Driven Auxiliary Feed Pump " * Wisconsin Flectric Power Co - WMTP 11 21 80 79/12/28 10pp
- --8007210460 "Seventy-Two Hour Test of Turbine-Driven Auxiliary Feed
 - * Wisconsin Electric Power Co WMTP 11 21 RO 79/12/07 10pp
- -~B007210465 "Seventy-Two Hour Test of Electrically-Driven Auxiliary Feed Pump " * Wisconsin Electric Power Co WMTP 11 22 RO 79/12/26 10pp
- --8007210469 "Seventy-Two Hour Test of Electrically-Driven Auxiliary
 - * Wisconsin Electric Power Co WMTP 11 22 RO 79/12/23 10pp
- 007240330 Advises of NRC reorganisation on 800428 which resulted in number of changes in afc titles, positions & assignments of personnel Also submits info for OETR NOVAK, T.M. Assistant Director for Operating Reactors 80/07/08
- 3007250480 Discusses potential wolding deficiencies in tanke fabricated by Oraver Tank & Mfg Co Requests determination whether weldmonts in safety-related Graver tanks meet design specs & Pabrication requirements MOSELEY, N C Division of Reactor Operations Inspections 80/07/08 Bap
- inspection reports, IE Oulletins & correspondence
- 007020037 Forwards IC Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/05/28 Ip
- 1007210409 Forwards IC Circular 80-13. "Grid Strap Damage in Wastinghouse Fuel Assemblies " No written response required MEPPLER.J Q Region 3. Chicago. Office of the Director 80/09/20 ig
- QO7010080 Forwards IE Info Notice 80-23, "Loss of Auction to Emergency Feedwater Pumps" No written rasponse required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/29 Ip
- 007010030 Responds to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Control of solenoid vaive will be modified such that total regirculation of control room air will continue after reset of containment isolation.

 FAY, C H Hisconsin Electric Power Co 80/06/06 2pp
- O07010062 Responds to IE Builetin 80-05. "Vacuum Condition Resulting in Damage to Chemical Val Control Sys (CVCb) Holdup Tanks " Mod will be implemented to prevent operation of holdup tank recirculation pump w/o positive pressure in tank FAY. C W Wisconsin Electric Power Co 80/06/06 7pp

- 8007:60757 Responds to IE Bulletin 80-06 Review conducted of schematic drawings to determine actions rosulting from engineersd safety feature actuation signal & whether equipment returned to nonemergency mode upon removal of actuation signal FAY.C W Wisconsin Electric Power Co. 80/06/06 2pp
- 8007240012 Forwards IE Insp Rept 50-301/80-09 on 80.0527-29 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Granch 80/05/05 2pp
- ~~800724001B (E Insp Rept 50-301/80-09 on 800527-29 No noncompliance noted Major areas inspected core power distribution limits. reactor shutdown margin determination & isothermal temp coefficient of reactivity measurement CMULE T. HOPKINS.J B., STREETER.J F. Region 3. Chicago, Office of the Director 80/06/06 App
- 8007010047 Updates 800307 response to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys " Piping analysis completed for EA an 85 proviously tabulated drawings as of E00323 Status of review encl FAY.C W Wisconsin Electric Power Co 90/06/09 5pp
- 8007220226 Forwards IE Info Nutice 80-26. "Evaluation of Contractor GA Programs " No written response required REPPLER, J. G. Region 3. Chicago. Office of the Director 80/06/10 is
- 8007160195 Forwards IE Info Notice 80-27, "Degradation of Reactor Conlant Pump Studs " No specific action or response required KEPPLEN.J G Region 3, Chirago, Office of the Director 80/06/11 Ip
- 8007030030 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/18
- B007020349 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director. 80/06/20
- 8007i70524 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Dominaralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J 9 Region 3, Chicago. Office of the Director 80/06/24
- 8007230345 Forwards IE Builetin 80-16, "Potential Misapplication of Rosemount Inc Models 115; & 1152 Pressure Transmitters W/Either A or D Output Codes " Hritten response required IE Circular 80-16 also oncl No written response required. KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/27
- 8007310304 Forwards IE Insp Repts 50-266/80-11 & 50-301/80-11 on 800616-17 No noncompliance noted FSORELLI,G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/30 2pp
- --8007310356 IE Insp Repts 50-265/80-11 & 50-301/80-11 on 800616-17. No noncompliance noted Major areas inspected licensee actions re IE Bulietin 79-14
 YIN.1 T. BRICKLEY.R H. Region 3. Chicago, Office of the Director DAMIELEON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/30 5pp
- 8007170526 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Heids " All containment welds wither have leak chase channel or penetration has closure cap or sypansion bellows welded outside containment FAY, C W Wisconsin Electric Power Co 80/07/03 Spp
- 6007220071 Submits reply to IE Bulletin 80-10 re contamination of nonradioactave sys & potential for releasos, Completion of bulletin review not anticipated until 800831 FAY.C W Masconain Electric Power Co 80/07/07. 2pp
- 0007240342 Responds to IE Bulletin 80-15 re power supply to emergency notification sys telephones Charger supplied by telephone company is connected to safeguerds Bus 2842 Phones verified operational w/loss of ac to charger FAY.C W Wisconsin Electric Power Co 80/07/08. 2pp

- 8007300430 Forwards drawings & revised pump & valve inservice insp & testing program.replacing 770219 program Program & drawings available in Central Files only FAY.C W Wisconsin Electric Power Co 80/07/25 ip
- R Periodic operating reports % related correspondence
- 8007150610 Forwards monthly operating repts for June 1980 FAY.C II Wisconsin Electric Power Co 80/07/10 ip
- --B0071506iB Monthly operating repts for June 1980
 FAY, C W Wisconsin Electric Power Co 80/07/08 App
- B Reportable occurrences. LERs & related correspondence
- 80070803Bi Forwards LER 80-005/03L-0 FAY,C W Wisconsin Electric Power Co 80/06/27 ip
- ---B0070B03B4 LER B0-005/03L-0 on B00607.during training walkdown of safeguards electrical supply cabinets, noted that tie breaker between ADS & AO6 safeguards buses was shut Probably caused by improper electrical lineup after loss of ac test FAY.C W Wisconsin Electric Power Co B0/06/27 3pp
- 8007110342 Forwards LER 80-006/017-0 FAY.C W Wisconsin Electric Power Co 80/06/30 lp
- --8007110349 LER BO-006/01T-O on B00617.during safeguards logic test w/
 one emergency dissel generator out of 5vc, auto containment
 spray pump actuation threatoned during loss of ack highhigh containment prossure Caused by personnol error
 FAY.C W Wisconsin Electric Power Co B0/06/30 3pp
- B007110353 Forwards LER B0-007/01T-0 FAY,C W Wisconsin Electric Power Co B0/07/03 ip
- --8007110357 LER 80-007/01T-0 on 800619. At full power, test IT-04 was performed w/emergency diesel generator 3D out of svc Emergency safeguards train equipment would have been inoperable on loss of ac power Caused by personnel error FAY.C W Wisconsin Electric Power Co 80/07/03 2pp

V Operator Examinations

- 8007240085 Responds to 800404 request for info re requirement that operator & senior operator lirense applicants spend 3 months on-shift in training Variance to requirement connot be permitted NOVAK.T M Assistant Director for Operating Reactors 80/07/08 30a
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8007020467 Forwards site emergency plan review & list of deficiencies per NUREG-0654 NRC site emergency plan review indicates that addl into & commitments are required to meet evaluation criteria stated in NUREG-0654 NOVAK.T M Assistant Director for Operating Reactors 80/06/24
- 8007080259 Forwards add1 info re safeguards contingency plan in response to NRC 800522 ltr Plan withheld (ref 1007R2 790) BRIGHT,R M Florida Power Corp 80/07/01 2pp
- BOO7230184 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mpt personnel at facility EISENHUT.D G Division of Licensing 80/07/11 2pp
- B0072B0373 Updates status of fire protection mode identified in 790727 safety evaluation Requests expeditious review of previously submitted items in Table 3
 BAYNARDLP Y Florida Power Corp 80/07/23 App
- O Adjudicatory correspondence
- BOO7310243 Forwards Commission BOO327 memorandum & order containing decisions on UCS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D G Division of Licensing 80/06/25 87pp

- H General correspondence
- B007110144 FOIA request for documents to facility & info concerning clothing & cloaning procedures for rouse of clothing & washing procedures for clothing used at facility WAGNER.D. Wagner, Cunningham, Vaughan, Gonders & McLaughlin B0/06/13 2pp
- 8007230237 FOIA request for three categories of documents re facility GIVEL.M Affiliation Unknown 80/06/23 ip
- 8007110139 Responds to FDIA request for documents re facility & infoconcerning clothing & cleaning procedures for reuse of clothing & washing procedures for clothing used at facility Forwards documents listed in App A W/o encls FELTON, J M Division of Rules and Records 80/07/08 2pp
- 800718009B Partial response to FOLA request for three categories of documents re facility Response to Item in may be found in util semiannual repts in local PDR Forwards NUREO-0594 & draft personnel exposure chart Chart only encl FELTON, J M Division of Rules and Records 80/07/15 2pp
- 8007230232 Add1 response to FOIA request for three categories of documents re facility Info sought in 1tom 12 of request con be found in LER identified in NRC 800611 response to 1tems 13-22
 FELTON, J M Division of Rules and Records 80/07/16 1p
- J Insurance & indemnity information
- 8007310435 Forwards executed Endorsement 31 to MAELU Policy MF-91 F1ELDER,J Marsh & McLennan.Inc , M & M Nuclear Consultants, Inc Div 80/07/14 2pp
- P Operating license stage documents & correspondence
- BOOA240237 Responds to technical assistance request for proposed Tech Spec changes for D&W operating plants Forwards requirements for add1 info IBRAEL,S L 7M1-2 Bulletins & Orders 79/08/29 13pp
- 8007240208 Forwards D&W licensees' responses to 790907 request for review of schedulo for installing safety grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115 CAPRA, R A TMI-2 Bulletins & Orders 79/10/24 1p
- 8005270617 Forwards NUREC-0645.Vols 1-2, "Rept of Builetins & Orders Task Force" & NUREC-0626, "Generic Evaluation of Feeduater Transishts & Small Break LOCAs in GE-Designed Operating Plants & Near Term OL Applications "Wo encl REID,R W Operating Reactors Branch 4 80/05/13 2pp
- 8007100207 Advises of concurrence w/Ofc of Policy Evaluation conclusions re impact of NRC post TMI-2 requirements for D&W reacturs & facility transient forwards recommendations & comments
 DENTON.H R Office of Nuclear Reactor Regulation. Director 80/05/20 4pp
- --B007100211 Requests cumments on Dfc of Palicy Evaluation paper on impact of NRC post TMI-2 requirements on D&W reactors & facility transient Requests submittal by B00515, w/inclusion of Program Ofc Views

 AHEARNE, J F Commission 80/04/27 lp
- BOO7230099 Requests submittal of proposed fech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution and for guidance EISENHUT, D @ Division of Licensing 80/06/11 62pp
- 8007100}ii Forwards Amend 31 to License DPR-72.safety evaluation 5 notice of issuance & availability REID.R W Operating Reactors Branch 4 80/06/18 2pp
- --B007100115 Amend 31 to License DPR-72, deleting requirements for maintaining containment test pressure when inspecting tondon end anchorages RFID.R W Operating Reactors Branch 4 80/06/18 5pp
- --8007100118 Safety evaluation supporting Amend 31 to License DPR-72
 * Diffice of Nuclear Reactor Regulation, Director 80/06/18 2pp
- --8007100121 Notice of issuance & availability of Amend 31 to Licenso DPR-72 REID.R W Operating Reactors Branch 4 80/06/18 dpp

- 8007030242 Responds to NRC 800302 request for info re pressurizer safety valves includes data taken during 800226 incldent to assist in determining flow rates & conditioners in RCV-B relief train Test results will be sent when available BRIGHT.R M Florida Power Corp 80/06/25 175pp
- E007010355 Application for agend to License DPR-72 granting waiver from certain ASME Section XI tosting & insp requirements
 Cartificate of Svc encl
 BRIGHT:R H Florida Power Corp 80/06/26 4pp
- 8007020397 Application for amend to License DPR-72, revising operator retraining requirements includes 1-wk simulator training course each yr & 5 days shift work per 4-month interval for backup licensees nut at Unit 3 Certificate of Svc enc3 8AYNARD.P Y Florido Power Corp 80/06/27 App
- G007070343 Informs that due to relationship of tests to Crystal River 3 event & IE Bulletin 79-27 response, tests verifying effects of combination of power loss on instruments & control functions will be provided by B00730

 HERBEIN J & Metropolitan Edison Co 80/06/30 ip
- 8007210004 Forwards questions re fuel assembly holddown spring inseps & safety significance of operating w/broken springs in core Requesto response within 60 days NDVAK-T M Assistant Director for Operating Reactors 80/07/01
- 8007210110 Requests response to encl questions re fuel assembly holdown springs Several holdown spring failures have recently occurred at Davis-Besse, Unit 1 NRC wishes to obtain results of holdown spring inspect other facilities NOVAK, T.M. Assistant Director for Operating Reactors 80/07/01 3ao
- 8007210581 Forwards questions refuel assembly holddown spring failure NRC is interested in knowing results of spring inspetus safety significance of operating w/broken springs in core Response requested within 60 days of itr receipt NOVAW-T M Assistant Director for Operating Reactors 80/07/01 300
- 6007290001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PAR Hadel Toch Specs & Hodel license conditions for THI-2 Lessons Learned Category A items encl for guidance EISENHUT, D O Division of Licensing 80/07/02 &9pp
- 8007080075 Notifies that evaluation of BAV-1621 re overall asymmetric LOCA loads, will be submitted by 800805 MODRE OC Florida Power Corp 80/07/03 3pp
- 8007150484 Requests extension of comment period re NRC 800519 ltr forwarding NUREG-0577 For review Facility in extended outage implementing TMI commitments Extension until 800715 will permit adequate analysis of iasue MOORE, O C Fibrida Power Corp 80/07/03 1p
- 8007:00193 Clarifies util 8002;5 ltr re compliance w/Category A requirements of NURCG-0578 Bilver realite cartridges will be used to collect samples under accident conditions Single channol analyzer will be utilized BRIGHF.R M Florida Power Corp 80/07/07 2pp
- 8007110122 Notifies that listed guidelines & changes.submitted for NRC info & review on 800923 were used to revise Emergency Procedures 101.104-106.108 & 113 8AYNARD.P Y Florida Power Corp 80/07/08 3pp
- 8907240037 Notification of 800711 meeting w/util in Bethesda.MD to discuss status of 51 corrective actions following 800226 incident FARTILE.M B Operating Reactors Branch 4 80/07/09 2pp
- 800725027B Provides info ro new ofc titles positions & assignments of personnel resulting from 80042B reorganization of Ofc of Nuclear Reactor Regulation NOVAK.T H Assistant Director for Operating Reactors 69/07/10
- 8007190385 Forwards add1 info re containment purge & vent sys, per NRC 800227 request Response prepared by B&W answers Questions ic & le Response to Questions ia. ib. 1d & if were submitted on 800420 Affidavit enct MOORE. G C Florada Power Corp 80/07/11 9pp
- 8007210203 Notifies NRC that containment isolation valve.CAV-1 is functional effective 800712 Past provisions of Tech Spec 3 0 4 are applicable BAYNARD.P Y Florida Power Corp 80/07/15 2pp

- B007180294 Advisos that restart w/o completion of Item 31 is justified as original FBAR is still valid for present design All Items will be completed prior to Mode 2 operation Affidavit encl BAYARD P V Florida Power Corp
- 8007180313 Submits addl info re implementation of short-term lessons learned requirements, to supplement 800411 ltr Contract consultants will assess operating experience from 800101 until technical advisors hired Certificate of Sv. encl BAYNARD.P Y Florida Power Corp 80/07/16 3pp
- 8007180384 Responds to Recommendation 22 of NUREO-0667, requesting analysis of LERs attributed to licensed personnel error Tabular & graphic response prepared by Inst of Nuclear Power Operations encl BAYNARD P Y Florido Power Corp 80/07/16 26pp
- 8007220333 Responds to NRC 800502 request for info re pressurizer safety valves Forwards Gilbert Associates, Inc 800630 "Analysis of 800226 Pressurizer Transient Relief Valve Discharge " Supporting Itrs encl BAYNARD, P V Florida Pawer Corp 80/07/17 9pp
- --8007220385 "Analysis of 800226 Pressurizer Transient Relief Valve Discharge " ARAUZ: G A . BUNKER, P L. Gilbert/Commonwealth Cos 80/06/30
- 8007240074 Forwards schedule for commitments to TMI-2 related requirements.per NRC 800507 request Affidavit encl BAYNARD.P Y Florida Power Corp 80/07/21 4pp
- B007250326 Revision to Toch Spec Change Request 61 correcting simplifying assumption made by BRW in reanalysis of Cycle 3 that alloued utilization of flux/flow ratio of rounded-off i 04 Certificate of Svc & affidavit encl
- --8007250330 Proposed revisions to Tech Specs,Pagos 2-3,-5,-7,8 2-5 & 8 2-6, changing flux/flow ratio
 * Floride Power Corp 80/07/22 5pp
- BOO72B0127 Application to amend License DPR-72 deleting power level cutoff requirement of Tech Spec 3/4 i 3 8. "Reactivity "
 Affidavit.Cortificate of Bvc & Tech Spec Chango Request 66 encl
 BAYNARD.P Y Florida Power Corp 80/07/23 App
- --8007280133 Tech Spec Change Request 66 for amend to License DPR-72, deleting power lovel cutoff requirement embodied in Tach Spec S/4 i 3 8, "Reactivity" = Florida Power Corp 80/07/23 App
- Q Inspection reports. 1E Bulletins & correspondence
- B0072402DZ Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "
 No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director B0/05/08
- 8007020179 Forwards IE Info Nutice 80-22, "Breakdowns In Contamination Control Programs." No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28 ip
- 8007210462 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010251 Forwards IE Info Notice 80~23, "Loss of Syrtion to Emergency Feedwater Pumps " No wratten response required O'REILLY, J P Region 2. Atlanta, Office of the Director 90/05/29 to
- 8007220075 Forwards IE Info Notice 80-25, "Evaluation of Contractor OA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/10

- 8007140262 Forwards IC Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007020743 Forwards IC Bulletin 80-15, "Possible Loss of Emergency Notification Sys (EMS) W/Loss of Offizte Power " Written response required O'REILLY, J P Region 2: Atlanta, Office of the Director 80/06/18
- 8007020409 Forwards 1E Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/20
- 8007160774 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required G'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/24
- 8007190499 Ack receipt of 800611 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-302/80-19 LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/28 ip
- ---B007150503 Responds to NRC 800515 ltr re violations noted in IC Insp Rept 50-302/80-19 Corrective actions meetings recorded an microfilm new drawings ordered & vendar manuals maintained & controlled HANCDCK: J A Florida Power Corp 80/06/11 3pp
- --8007150510 Notice of violation from insp on 800421-25 * Region 2, Atlanta, Office of the Director 80/05/14 2pp
- --8007180511 IE Insp Rept 50-302/80-19 on 800421-23 Noncompliance noted failurs to provide adequate document control program for vendor manuals PRICE.D 8 Region 2. Atlanta. Office of the Director UPRICHT,C M Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/05/14 9pp
- 8007180340 Forwards response to IE Bulletin 80-10 Program to prevent unmonitored, uncontrolled liquid & geneous releases to environ described Operation of sys as radioactive sys is acceptable Provisions made to monitor & control releases BRIGHT, R M Florida Power Corp 80/06/25 App
- 8007230210 Forwards IE Bulletin 80-16. "Potential Misspplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/27 to
- 8007240392 Forwards meeting minutes in response to IE Insp Rept 50-302/80-19 Records now incorporated into plant quality files POOLE.D C Florida Power Corp 80/06/27 ip
- 8007070329 Forwards rept responding to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment " Outstanding items in Sections 2 & 3 will be further evaluated as info becomes available W/o enct.
 BRIGHT.R M Florida Power Corp 80/06/30 ip
- 8007150598 Forwards response to IE Bulletin 80-11. "Masonry Wall Design " Licenses will develop re-evaluation acceptance criteria for walls based on conservative design assumptions consistent w/schedule in Itam 2s BRIGHT,R M Florida Power Corp 80/07/07 App
- 8007230562 Forwards response to open items of IE Bulletins 79-02 re pipe support base plate designs & 79-14 re seismic analysis of safety-related piping sys identified in IE Insp. Rept 50-302/80-02 BAYNARD, P Y Florida Power Corp. 80/07/16 7pp
- --8007230573 "Earthquake Intensity for Piping Analysis & Pipe Support Design " EARR except one! FERRARELLO.8 Floride Power Corp 79/10/11 9pp

- R Periodic operating reports & related correspondence
- E007150708 Forwards monthly operating rept for June 1980 BAYNARD.P Y Florida Power Corp 80/07/09 ip
- --8007150713 Monthly operating rept for June 1980 CULVER.M W Florida Powel Corp 80/07/01 3pp
- S Reportable occurrences. LERs 5 related correspondence
- B007010463 Advises that B00530 Part 21 rept ra mainstream safety valve cracking in valve disc guides has been dispositioned Forwards analyses determining parts acceptable for use HANCOCK. J A Florida Power Corp B0/06/24 i7p
- B007110402 Forwards LER 80-025/03L-0 HANCOCK, J A Florida Power Corp 80/07/07 1p
- --8007110410 LER 80-025/03L-0 on 800609, while performing SP-112 calibr of reactor protection sys, count rate amplifier for channel A source range neutron flux monitor found out-of-tolerance Caused by defective pulse & output amplifier cards LANCASTER.K F Florida Power Corp 80/07/03 2pp
- 8007290874 Forwards safety evaluation re 800226 incident Corrective actions taken are sufficient to pormit restert & to ensure safe aperation REID.R W Operating Reactors Branch 4 80/07/18 2pp
- DOCKET 30-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 6007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES, D. L. Commonwealth Fdison Co. 80/06/27 ip
- G Adjusticatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS /71104 petition sought action re fire protection for electrical cables
 EISENHUT, D & Division of Licensing B0/06/25 89pp
- 8007020646 Nemerandum specifying issues to be discussed at 800701 oral argument, re State of II contembon that applicant commitments should be integrated in license Tech Specs in storage pool mad proceeding TOMPKING. B A Atomic Safety and Licensing Appeal Panel 80/06/26 2pp
- 8007100022 Forwards "Tech Specs for Nuclear Power Reactors," 10CFR50 advance notice of rulemaking, for which counsels' attention is invited by ASLB Comments may be submitted to Commission re 800701 oral argument DIBHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/03
- --BOD7100026 "Tech Specs for Nuclear Power Reactors," 10CFR80 advance notice of rulemaking Establishes std for deciding which items from BAR must be incorporated into Tech Specs & modifies definitions of spec categories CHILK.S. J. Office of the Berretary of the Commission BO/04/30 Spec.
- BOO7300362 Updates certain projected load & capacity estimates which appear in record of procoeding per applicant obligation to keep ASLAD approised of developments Related correspondence STEPTOC.P P Isham, Lincoln & Boale BO/07/00 Zpp
- H General correspondence
- GOO7110533 Responds to SOO229 request to reject util license to increase storage capacity of facility spent fuel pool Actions initiated 791010 to essure that energency plans are implemented at all licensed operating reactor sites DENION. H R Office of Nuclear Reactor Regulation, Director SO/05/05 2pp
- 8007210200 Responds to pncl 800418 ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article and DENTON-HR Office of Nuclear Reactor Regulation, Director E0/05/21 10pp

- 8007310358 Responds to encl 800401 telegram to President Carter urging closing of facility & all nuclear plants near populated areas NRC 800227 confirmatory order required immediate short-term actions to assure public safety EISENHUT.D & Division of Licensing 80/07/17 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8007220308 Provides summary of 800507-08 meeting woutlis recore melt accident sequences Utils appear to expect MRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents
 CATION, I California, Univ of. Los Angeles 80/05/10 6pp
- P Operating license stage documents & correspondence
- 8004240480 Forwards addi info re review of unresolved safety issues, trip rept of Lessons Learned implementation team.& task action plan in view of high population density surrounding plants

 DENTON.H R Office of Nuclear Reactor Regulation, Director, 80/04/09 33pp
- B007230097 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resulution Encl for guidance EISENHUT.D 0 Division of Licensing 80/06/11 62pp
- 8007100393 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda.HD to discuss accident mitigation features for power plants LONG-J K. Division of Systems Integration 80/06/12 75pp
- B007010110 Notification of B00625 meeting u/utils & Sandia Labs in Bethesda.MD for presentation of overviou of facilities risk study Agenda encl ISRACL-S L Reliability & Risk Assessment Branch B0/06/14 3pp
- 8007110557 Summary of 800530 meeting w/util in Bethesda.MD re status of action plan OLSMAN.L N Operating Reactors Branch 1 80/06/23 3pp
- 8007010428 forwards Drawing 22E-1-4850 re reactor, turbine & generator trip protection in response to 800619 discussion concerning automatic initiation of auxiliary feedwater sys Drawing available in Central Files only feedwater (NAUGHTON, W.F. Commonwealth Edison Co. 80/06/24 [p
- 80070102ii Forwards response to 800227 confirmatory order requiring review of key plant sys vulnerability areas.possible operator dependent areas & control room emergency procedures
 NAUGHTON.W F Commonwealth Edison Co 80/06/26 49pp
- 8007010608 Notification of 800617 meeting w/utils in Bethands,MD to discuss containment structural response, failure gressures & fallure modes for facilities as described in NRC 800410 ltr to Comm Ed MEYER.J F Reactor Systems Branch 80/06/26 2pp
- 8007070116 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads
 JANECEK.R F Commonwealth Edason Co 80/06/24 4pp
- 8007170241 Forwards request for add1 info re backfitting of severe accident mitigation features Response requested within 30 days

 NOVAK.T M Assistant Director for Operating Reactors 80/07/02
 7pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PNR Model Tech Specs % Model lacense conditions for TMI-2 Lessons Learned Category A items encl for guidance ELSENHUT, D G Division of Licensing 80/07/02 69pp.
- B007190476 Submits add1 info re 10CFR90, App J. exemption Mod to install flowmeter w/high flow alarm on penetration pressurization piping to personnel air lock door seals completed includes marked set of drawings M/O drawings NAUGHTON. W F Communwealth Edison Co 80/07/07 4pp
- B00717059B Summary of B00625 meeting w/Pickardilowe & Garrick, Inc re risk study including modeling for plump trajectory containment event tree & modeling, use of plant data & consideration of external events ISBAEL, S. L. Reliability & Risk Assessment Branch B0/07/07 Epp

- 8007210646 Summary of 800907-08 technology exchange meetings w/utils in Chicago. IL re core melt accident sequences & associated phenomenology for facilities NRC perceives real urgency to for answers to key technical questions
 MEYER.J F Reactor Systems Branch 80/0//09 12pp
- 8007280605 Notifies that PG Stoddart, primary NRC reviewer for Zion, has requested addl info to complete review, as result of discussions re NUREO-0578 Item 2 i Bs on improved post-accident sampling capability Lists drawings sent NAUGHTUN, H F Commonwealth Edison Co 80/07/21 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007020065 Forwards IE lnfo Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/28
- 8007210356 Forwards IE Circular 80~13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/20 10
- B007010086 Forwards IE Info Notice B0-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J G. Region 3, Chicago, Office of the Director 60/05/29 in
- 8007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damagd to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEUPLES, D.L. Commonwealth Edison Co. 80/06/04 3pp
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/06/10
- 8007020199 Forwards IE Insp Repts 50-299/80-09 & 50-304/80-09 on 800312-15 & 19-20 & notice of violation Notice of violation withheld (ref lOCFR2 790)
 HIND. J A Region 3. Chicago, Bafeguards Branch 80/04/11 2pp
- --B00702021; IE Insp Repts 50-295/80-09 & 50-304/80-09 on B00512-15 & 19-20 Noncompliance noted failure to conduct proper personnel screening to secure & attend doors of vital areas & to test alarm sys Details withheld (ref 10CFR2 790) HADEDA:T J . CHRISTOFFER:0 Region 3. Chicago. Office of the Director HIND.J A Region 3. Chicago. Bafeguards Branch 80/06/10 2pp
- 8007160165 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/11
- G007020075 Forwards response to IE Bullatin 60-12, "Decay Heat Removal Bys Operability " Review of RHH degradation events found none similar to Davis-Besse incident DELGEORGE, L O Commonwealth Edison Co 60/05/16 Spp
- 8007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEOPLES D L. Commonwealth Edison Co. 80/06/16 Spp
- B007030037 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/18
- 8007230369 Forwards IE Insp Rept 50-304/80-07 on 800429-30,0519-21 & 0603-04 No noncompliance nated FiDRELLiro Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230375 IE Insp Rept 50-304/80-07 on 800429-30, 0519-21 & 0403-04 No noncompliance noted Major areas inspected review of inservice insp program & observation of examination activities & results
 AEY, HJ Region 3. Chicago. Office of the Director DANIELSON, DH Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/18 7pp

- BOO7020589 Forwards IE Circular BO-13, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required KEPPLERJ G Region 3, Chicago, Office of the Director BO/06/20
- 8007230754 Forwards IE Insp Repts 50-275/80-08 & 50-304/80-08 on 800421,0515-20,30 & 31 No noncompliance noted FIDRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- --B007230758 IE Insp Repts 50-295/80-08 & 50-304/80-08 on B00421,0515-20, 30 & 31 No noncompliance noted Major areas inspected Bergen-Paterson large bore hydraulic snubbers on Unit 2 steam generators DAMIELSON,D H Region 3, Chicago, Reactor Construction & Engineering Support Branch VIN.1 T Region 3, Chicago, Office of the Director 80/06/18 3pp
- B007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J O Region 3, Chicago. Office of the Director 80/06/24 fo.
- 800723026B Forwards IE Insp Repts 50-295/80-11 & 50-304/80-11 on 800527-29 & notice of violation DAVIG.A B Region 3. Chicago. Fuel Facility & Materials Safety Beanch 80/06/24 2pp
- --B007230272 Natice of violation from insp on B00527-29
 * Region 3, Chicago, Office of the Director 90/06/20 ip
- --8007230276 IE insp Repts 50-299/80-ii & 50-304/80-ii on 800527-29 Noncompliance noted excess pH of worte water released & failure to atendardize sodium hydroxide solution during boric acid titration ESSIG.T H. OESTMANN.H J. ROYTEK, C. Region 3, Chicago, Office of the Director 80/06/20 9pp
- 8007230289 Forwards IE Bulletin 80-16, "Putential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/27 is.
- BOOT310507 Forwards IE Health Physics Appraisal Repts 50-295/BO-05 & 50-304/B0-04 on BOO310-21, notice of violation & significant appraisal findings KEPPLER, J O Region 3, Chicago, Office of the Director BO/06/27
- --8007310510 Notice of violation from health physics appraisal on 800310-21 * Region 3, Chicago, Dffice of the Director 80/06/27 2pp
- 8007310335 Forwards Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 DAVIBA B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/30 3pp
- --BOO7210339 Waste Packaging Insp Rapt 15000046/80-32 on 800222 & 26 Noncompliance w/DOT regulations noted may dose rate on surface of transport trailer was 220 millirem/h O'REILLY,L A Region 5, Ban Francisco, Office of the Director THOMAS.R D . BOOK.H E Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch BO/04/02 12pp
- BOO7250641 Responds to IE Bulletin BO-lo. "Contamination of Monradioactive Bys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES,D L. Commonwealth Edison Co. 80/07/07 2pp
- B007250650 Forwards response to IE Bulletin B0-i1, "Masonry Wall Design " Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be mat prior to startup W/o encl PEOPLES.D L Commonwealth Edison Co 80/07/07 2pp

- 8007250638 Forwards response to IE Bulletin 80-08, 'Examination of Containment Liner Penotration Helds " Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES, D. L. Commonwealth Edison Co. 80/07/09.
- R Persodic operating suports & related correspondence
- 8007140327 Forwards monthly operating repts for June 1980 GRAESSER.K L. Commonwealth Eduson Co. 80/0//07 1p
- ---B007140331 Monthly operating repts for June 1980 CDDK, J M Communucalth Edison Co 80/07/07 lipp
- 8 Reportable occurrences, LERs & related correspondence
- BOO7220307 Forwards LER 80-009/03L-0 WANDKE,N E Commonwealth Edison Co 80/03/03 tp
- --B007220391 LEN 80-009/03L-0 on 800202, steam generator level transmitter 2LT-53B had shifted high by 2 25% Caused by transmitter drift due to natural component aging Transmitter recallor & channel returned to svc JENKINS.R V Commonwealth Edison Co 80/03/03 lp
- 8007160668 Forwards LER 80-022/017-0
 WANDKE, N E Commonwealth Edison Co 80/06/27 lp
- ---B007160672 LER 80-022/01T-0 on 800618, during integrated leak rate test on Unit 2, accommitators for power operated relief valves vented & instrument air isolated Coursed by air isolation Procedure change to block valves upon during test made GAJIC.Z Commonwealth Edison Co 80/06/27 2pp
- BOO7220387 Forwards LER RO-023/03L-0 GRAESSER,K L. Commonwealth Edison Co. BO/07/16 lp
- --B007220593 LER E0-027/O3L-0 on 800627. Approx 4,000 gallons of OH lake discharge tank reloased w/o verification of dilution flow to discharge canal w/one svc water pump in svc Caused by personnel oversight Tech Spec requirements reviewed GURUNATHAN. S Commonwealth Edison Co 80/07/16 2pp
- B007220406 LER 80-007 has been cannolled COLLINS.N Commonwealth Edison Co B0/07/21 19
- 800722040B LER 80-005 has been cancelled CQLLINS: M Commonwealth Edison Co 80/07/21 1
- 8007220409 LER 80~003 has been cancelled COLLINS, M Commonwealth Edison Co 89/07/21 1;
- 8007220411 LER 79-048 has been cancelled COLLING.M Commonwealth Edison Co 80/0//2i i
- 8007220412 LER 79-047 has been cancelled COLLINS.M Communicalth Edison Co 80/07/21 i
- 8007220413 LER 79-046 has been cancelled COLLINS: M Commonwealth Edison Co 80/07/21 1;
- 8007220414 LFR 79-045 has been cancelled COLLINS.M Communication Education Co. 80/07/21 in
- T Hearing transcripts on non-antitrust matters
- 8007150074 Transcript of 800701 morning hearing in Bethesda.MD Pp 1-120 * Atomic Safety and Licensing Board Panel 80/77/01 123pp
- DOCKET 50-305 KEHAUNEE NUCLEAR PUNER FLANT

 F Security, medical, emergency & fire protection plans
- 8007280414 Forwards Draft 4 of facility radiological emergency response plan Plan available in Central Files only MATHEM8.E R Wisconsin Public Service Corp 80/07/23 lp

G Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protectson for electrical cables EISENHUT.D © Division of Licensing 80/04/25 87pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D C Division of Licensing 80/06/11 62pp
- 8007010224 Notifies of BOO616 meeting w/Westinghouse, Fluor Power Syc Carp & util in Betheads, ND to discuss steam generator support bolt anomalies HERMANN, R A Division of Reactor Operations Inspections BO/06/13
- 8007220229 Lists actions taken by util after 800928-31 inop of steam generator bolts determined that leg 1 of steam generator B had four long bolts & two short bolts Attempt to replace bolts will be made during next refusing outage MATIKENS, E R Wisconsin Public Service Gorp 80/06/20 3pp
- --8D07220234 "Safety Evaluation of Steam Generator Support Pad Connections Having Vascomax Bolts in Helicoil Inserts " PARIMI.S R. INDUGE, S., SETLYUR, A V. Fluor Power Service, Inc BO/O6/18 20pp
- E007080206 Forwards "Nuclear Purge Valve Stress Analysis." in support of reactor bldg vont valve mod MATHEMS.E R Wisconsin Public Service Corp 80/07/02 ip
- --8007080208 "Nuclear Purge Valve Stress Analysis "
 * Pioneer Service & Engineering Co 60/06/25 16pp
- 800725000: Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Hodel Incense conditions for TMI-2 Lessons Learned Calegory A items encl for guidance EISENBUT.D O Division of Licensing 80/07/02 69pp
- Q Inspection reports. 1E Bulletins & correspondence
- 8007020029 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required KEPPLER. J. G. Region 3. Chicago. Office of the Director 80/05/28 ip
- 8007210412 Forwards IE Circular 80-13, "Grid Strap Damage in Wastanghouse Fuel Assemblies" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/28 ip
- B007010078 Forwards IE lnfo Notice 80-23, "Loss of Suction to Emergancy Feedwater Pumps" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007010036 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Review of sys demonstrated that adoquate protection is included in design Table of sys reviewed enc!
 MATHEMS.E R Hisconsin Electric Power Co 80/06/09 2pp
- 800722028 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER.J G Region 3. Charago, Office of the Director BO/06/10 in
- 8007020714 Advases NRC that ultrasonic inep of Vascomax 250 CVM steam generator bolts was performed on 800928-31 to resolve steam generator reactor coolant pump support lamellar tearing issue Existing Log 1 support bolting is adequate MATHEMS.E R Misconsin Public Service Carp 80/06/11 2pp
- 8007160203 Forwards 1E Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response Tequired KEPPLER, J G Region 3. Chirago, Office of the Director RO/06/11, is

- BOO7020032 Responds to JE Bulletin 80-12, "Decay Heat Removal Sys Operability " Licensee review indicates that current design is adequate Further response will be submitted within 1 wk MATHEMS,E R Wiscomsin Public Service Corp 80/06/12 1p
- B007020256 Responds to IE Bullatin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Review of schematic & logic diagrams indicates that all applicable equipment operates in intended manner after reset
 MATHENS, ER Wisconsin Public Service Corp B0/06/17 2pp
- B007030026 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/18 to
- 8007230314 Forwards IE Insp Rept 50-305/80-10 on 800507 & 19-23 & notice of violation HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/18 2pp
- --B007230317 Notice of violation from insp on B00507 & 19-23 * Region 3, Chicago, Office of the Director 80/06/17 2pp
- --8007230328 IE Insp Rept 50-305/80-10 on 800507 & 19-23 Noncompliance noted failure to follow procedures & failure to rept loss of offsite power event within 1-h HARNICK,R F. CHULLESIN C. NELBON,R L. Region 3, Chicago. Office of the Director 80/06/17 7pp
- BD07020558 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/06/20
- 8007170528 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Hater Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER. J G Rogion 3, Chicago, Office of the Director 80/06/24
- B007230356 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models ii51 & 1152 Pressure Transmitters W/Bither A or D Output Codes " Hritten response required IE Circular 80-16 also encl No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/27
- 8007240321 Responds to IE Bulletin 80-10 re contamination of nunradioactive sys & resulting potential for unmonitored, uncontrolled release of radioactivity to environ Several sampling & monitoring points have been added to program MATHEWS.E R Wisconsin Public Service Corp 80/07/07 ip
- BOO7240334 Responds to IE Bullotin BO-OB, "Examination of Containment Liner Penetration Welds " Welds repaired as necessary, when unacceptable results were indicated by nondestructive insp Welds acceptable by final rediopraphic insp MATHEWS, ER Wisconsin Public Bervice Corp 80/07/07 3pp
- 8007240415 Responds to IE Bulletin 80-11, "Mesonry Wall Design " Four masonry walls have been identified w/potential for interaction w/safety-related equipment Walls were designed Seismar Class I & further investigation is not warranted MATHEWB, E R Wisconsin Public Service Corp 80/07/09 2pp
- 8007310261 Forwards IE Insp Rept 50-305/80-13 on 800623-27 & natice of violation Notice of violation withheld (ref 10CFR2 770) H1ND, J A Region 3. Chicago, Safeguards Branch 80/07/11 2pp
- --8007310267 IE Insp Rept 50-305/80-13 on 800623-27 Noncompliance noted guards not qualified, inadequete screening & improper barrier control Details withhold (ref 100FR2 790)
 BELANGER, J. L. CREED, J. R. Region 3, Chicago. Office of the Director HIND, J. A. Region 3, Chicago. Safeguards Branch BO/07/11 2pp
- B007240396 Advises that util 800613 response to NRC 800520 ltr is unsatisfactory Results of review will be communicated as soon as possible HEISHMAN, R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/18 ip
- R Periodic operating reports & related correspondence
- 8007160544 Forwards monthly operating rapt for June 1980 MATHEWS, E R Wisconsin Public Service Corp 80/07/09

- --8007160548 Monthly operating rept for June 1980 RUITER, G H Wisconsin Public Service Corp 80/07/09 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007080386 Forwards LER 80-024/03L-0
 MATHENS E R Wisconsin Public Service Corp 80/07/02 lp
- --B0070B0390 LER 80-024/03L-0 on B00619.at hot shutdown.white steam generator was in operation.blowdown radiation monitor R-19 was not sampling blowdown for approx 6-h Caused by isolation of monitor during performance of prostartup checklist NALEPKA, D & Wisconsin Public Service Corp 80/07/03 ip
- 8007110317 Farwards LER 80-024/03L-0 MATHEWS, E R Wisconsin Electric Power Co 80/07/02 1p
- --BO07110326 LER BO-024/03L-O on BO0619 at hot shutdown, w/steem generator blowdown in operation, radiation monitor R-19 not sampling blowdown for approx 6-h Cause not stated Sampling sys being reviewed for initial conditions
 NALEPKA,D S Wisconsin Electric Power Co BO/07/03 1p
- BOO7:60464 Forwards LER 80-026/01T-0 MATHEWS,E R Wisconsin Public Service Corp 80/07/07 1p
- --B007160474 LER B0-026/01T-0 on B00624; refueling water storage tank level fell below Tech Spec limit Cause unidentified Makeup was initiated immediately & Tech Spec level was restored Investigation in progress & updated rept will be submitted NALEPKA, D S . SMOKER. C S Wisconson Public Service Corp B0/07/08 19
- 8007160485 Forwards LER 80-025/03L-0 & updated LER 80-019/03L-i MATHEMS, E R Wisconsin Public Service Corp 80/07/1i ip
- --8007160502 LER 80-025/03L-0 on 800617, five containment isolation valves found w/unacceptable leakage Causes unspecified Two valves replaced two seats cleaned. & one stroke adjusted Subsequent leaknates below Tech Borc limits
 NALEPXA,D B Wisconsin Public Bervice Corp 80/07/11 1p
- --BOO7160510 Updated LER 80-019/03L-1 on BOO611, shield bldg ventilation sys check damper SBV-10A failed to Pully open Caused by controller setpoint drift Setpoint adjusted & design change study initiated NALEPRA, D. 8 Wisconsin Public Service Corp 80/07/11 ip
- 8007280665 Forwards LER 80-027/03L-0
 MATHEWS,E R Wisconsin Public Service Corp 80/07/21 ip
- --B0072B0674 LER B0-027/03L-0 on B0062; during cooldown, diesel generator 18 fatled to start on occurrence of inadvertent safety injection signal Caused by air start motor solenoid valve containing moisture & containments Tanks blown dry NALEPKA D S Wisconsin Public Service Corp B0/07/21 ip
- 8007280675 Forwards LER 80-028/03L-0 MATHENS E R Wisconsin Public Service Corp 80/07/22 ip
- --8007280685 LER 80-028/03L-0 on 800623, during hot shutdown, condensate storage tank was twice drawn below 75,000 gallons through normal water usage for plant startup Caused by normal high water vage during startup following refueling NALEPKA, D 8 Wisconsin Public Bervice Corp 80/07/23 lp
- DDCKET 50~304 PRAIRIE 18LAND NUCLEAR STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- B007020235 Forwards request for limited revisions & add1 info re 790323 plant safeguards contingency plan Entl withheld tref 10CFR2 790)
 CLARK.R A Operating Reactors Branch 3 80/06/10 2pp
- B007110115 Forwards response to NRC 800618 questions re safe shutdown in event of fire MAYER,L.O Northern States Power Co 80/07/08 3pp
- O. Adjudicatory correspondence
- BOO710020B Ack receipt of NRC BOO619 ltr to 0 Charmoff re nonreceipt of Btate of MN 800424 contentions Certaficate of Bvt encl OLBONJ F Hinnesotas Bate of B0/06/23 3pp

- 8007310243 Forwards Commission 800527 memorandum & order containing ducisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action te fire protection for electrical cables
 EISENHUE, D. Q. Division of ilcensing 80/06/25 87pp
- 8007250422 Amended Contentions 1 & 2 & withdrawal of Contention 3 Amend request does not contain safety analysis re spent fuel storage & does not contain analysis of spent fuel pool expansion consequences Certificate of Svc encl OLBON.J F. SEMECHAL.M E. BPANNAUS.H Minnesota. State of BO/07/21 7pp
- BOO7310473 Confirms ASLB request for healing space at federal bldg in Baint Paul.NN on 800806 to conduct 1-day prehearing conference re facility STEPHENS.C R Dotteting & Services Branch 80/07/22 ip
- BOO7250688 Comments stating no objection to admission of State of MN 800721 Contentions 1 % 2 re cask drop accident & loss of water accident in spent foul pools Reserves rights re substance & validity of contentions Cortificate of Svc encl BARTH C A Hearing Aranch 3 80/07/25 2pp
- B007300463 Responds to State of MN 800424 supplite petition to intervene & 800721 amended contentions Supporting documentation, notices of appearance of US Siberg & DL Bernstein on behalf of util & Certificate of Svc encl BILBERG.J E Northern Status Power Co SILBERG.J E Shaw Pittman, Potts & Troubridge B0/07/23 24pp
- H General correspondence
- 8007310526 Responds to 800226 ltr re constituent concern about evacuation routes enound facilities NRC & FEMA engage in program to upgrade emergency preparedness including evacuation planning DIRCKS.W J Office of the Executive Director for Operations 80/07/24 | Spp
- --B007310528 Requests info re cnrl constituent ltr about evacuation routes around facilities
 B05CHW17Z,R Senate 80/02/26 App
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tork Spec changes providing for redundancy in docay heat removal capability in all modes of operation Model Tuck Specs which would provide acceptable resolution encl for guidance EISENHUT.D O Divinsum of Licensing 80/06/11 62pp
- 8007030222 Notifies NRC of intention to ship radinactive math from facilities using Model HN-600 MAYER. L O Northern States Power Co 80/06/13 ip
- 8007010581 Responds to 800513 ltr re containment purge info by forwarding related correspondence MARTIN.R A Operating Reactors Dranch 3 80/06/18 2pp
- --B0070103B3 Responds to E010 800513 questions LOCA dose calculations not completed Monitors are redundantiges & particulate monitors provided, each giving isolation signoi MUSOLF:D Northern States Power Co 80/06/03 ip
- --800/010985 Requests preliminary avaluation of licensee response to NRC 791029 "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Englation Valve Operability," General Item B-24 Evaluation form and REEVES E A Operating Reactors Branch 1 (Pre 800428) 79/12/27 App
- 8007010374 Forwards Westinghouse rept 80-509-PRAIR-RI, "Examination at Prairie Island 2 Income: Alloy 600 Steam Generator Tube." resulting from 800212 meeting re Jan 1980 into Rept withhold (ref 1001R2 790) Util 800627 it proif MAYER.L O Northern States Power Co 80/06/27 ip
- --8007010381 Submits application to withhold Hestinghouse research rept 80-507-PRARI-RI. "Examination at Prairie Island 2 Inconel Alloy 600 Steam Generator Tube." (ref 10CFR2 790) Affidavit tupporting request encl MAYER.L O Northern States Power Co 80/06/27 3pp
- B007170076 Summary of B00820 meeting w/util re TOPROD fuel design MARTIN.R Operating Reactors Branch 3 80/07/01 7pp

- 8007230001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model License conditions for TM1-2 Leasons Learned Category A items pocl for guidance EISENHUT, D G Division of Licensing 80/07/02 69pp
- B007280054 Advises of intention to ship radioactive matls from listed facilities using Package Model CNSI AL-33-90
 MAYER,L O Northern States Power Co H0/07/03 1p
- 8007240388 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for OETR NDVAK.T M Assistant Director for Operating Reactors 80/07/08
- B807280410 Forwards comments on NUREG-0577, "Fracture Toughness & Susceptibility to Stress Corrosson Cracking of Equipment Supports," in response to NRC 800519 request Add1 analysis for stress currosion cracking is unnecessary MAYER.L O Northern States Power Co 80/07/21 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007070051 Forwards IE Insp Repts 90-202/80-06 & 50-306/80-07 on 800401-30 & notice of deviation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 60/05/21 2pp
- --8007070056 Notice of deviation from insp on 800401-30 * Region 3. Chicago. Office of the Director 80/05/16 ip
- 8007020054 Forwards IC Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J O Region J, Chicago, Office of the Director 80/05/28
- B007210362 Forwards IE fireviar 80-13, "Grid Strap Damage in Westinghouse fuel Assemblies" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/28 to
- 8007010127 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required REPPLER.J G Region 3. Chicago, Office of the Director 80/05/29 ip
- 8007240183 Forwards IE Insp Repts 50-282/80-09 & 50-306/80-10 on 800301-31 No noncompliance noted HEISIMAN.R F flegion 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/06 2pp
- --8007240210 IE insp Repts 50-282/80-09 /, 50-306/80-10 on 800501-31 No noncompliance noted Major areas inspected maint, servoillance, security, radiation protoction, followip of licenses reported events & followip to IE circulars FELERAMENDLO TO . BURGES. I I . BUYD. D C Region 3. Chicago, Defice of the Director 80/06/05 App
- 8007010260 Responds to IE Builetin /9-17, Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " Visual insp required by Item 2(a) was completed on Unit 1 w/no corrective actions necessary OILBERTS, D E Northern States Power Co 80/06/09 1p
- 8007010267 Responds to IF Bulletin 80-06. "Engineered Safety Feature Reset Controls" Safety sys schematics reviewed Test demonstrating safety equipment remains in emergency mode after reset will be completed at next refueling outage GILBERTS.DE Northern States Power Co 60/06/09 2pp
- B007010549 Responds to IE Bulletin HO-Ob, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Chemical & vol control sys & components & gaseous & liquid waste disposal sys & components were reviewed GILBERTS,D E Northern States Power Co B0/06/09 2pp
- G007146707 Responds to IE Bulletin 80-05 Review of chemical & vol control sys indicates holdup tank vulnorability to collapse Low systian pressure trep to be installed on holdup tank transfer % recurrulation pumps by 610101 OILDERTS, D. E. Northorn Statts Puwei Co. 80/06/09 2pp
- 8007220212 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required KEPPLER. J G Region 3, Chicago, Office of the Director 80/06/10 in

- 8007160182 Forwards IE Info Notice 80-27, "Degradation of Reactor Copient Pump Stude " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11 to
- 8007030043 Forwards IE Bulletin 80~15. "Possible Lose of Emergency Notification Sys (ENS) W/Loss of Offsito Power "Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/18
- B007020573 Forwards IE Circular B0-15. "Loss of Reactor Coblant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLERIJ 6 Region 3. Chicago, Office of the Director 60/06/20
- 8007140094 Ack receipt of encl 800617 ltr informing NRC of steps taken to correct violations noted in NRC 800522 ltr Encl withheld (ref 100FR2 790)
 HIND, J.A. Region 3, Chicago, Safeguards Branch 80/06/24 ip
- 8007170506 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24 in
- B007140186 Ack receipt of B00612 ltr informing NRC of steps taken to correct deviation noted in IE lnsp Repts 50-282/80-06 & 50-306/80-07 forwarded by B00321 ltr Senior resident inspector will follow remaining testing HEISHHAN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/25 lp
- --8007140192 Responds to deviation noted in 1E Insp Repts 50-282/80-06 & 50-306/80-07 forwarded by 800521 itr Special insps of two out of four power operated relief isolation valve motor starters have been completed Two others will be performed GILBERTS, D E Northern States Power Co 80/06/12 ip
- 8007230336 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27, ip
- B007170186 Ack recript of B00523 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-306/78-24 F10RELLI.O Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/06/30 ip
- --8007170194 Responds to NRC 790123 ltr re violation noted in IE Insp Rept 50-306/78-24 Corrective actions replacement of snubbers planned for refueling shutdowns, unless earlier cold shutdown occurs. OILBERTS, D E Northern States Power Co 80/05/23 1p
- 8007150481 Advises that demonstration of ultrasonic insp method for detecting underclad cracking in reactor vessel noticle region for Unit 1 is scheduled for 800723 Unit 2 insp will take place during 1981 refueling outage MAYER, L D Northern States Power Co 80/07/07 lp
- B007250077 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Concrete block walls are not in same design philosophy as design of Trojan plant masonry walls Walls were generally designed as partition walls or shield walls OLLERTS.D E Northern States Power Co 80/07/08 51pp
- 8007220090 Submits raply to JE Bulletin 80-08 re examination of containment liner penetration welds Review of Unit 1 revealed two deficient welds Further response will be sent by 800810 OILDERTS.D.E. Northern States Power Co. 80/07/10 ip
- BOO7220542 Submits reply to IE Bulletin 79-01B re environ qualification of Class IE equipment Qualified limit switches have been ordered & are scheduled for replacement during future subtages Worksheets one!

 OILBERTS.D E Northern States Power Co BO/07/10 App
- B007230211 Submits reply to IE Rulletin 79-17 re pipe cracks in borated water sys Visual insp required by bulletin was satisfactorily completed for Unit 1 No corrective actions necessary GLDERTS.D C Northern States Power Co 60/07/10 ip.

- R Periodic operating reports & related correspondence
- BOO703017B Forwards "1979 Environ Monitoring & Eculogical Studies Program Rept," Vols 1 & 2 WARDLE C Northern Status Power Co 80/06/30 ip
- --8007030180 "1979 Environ Monituring & Ecological Studios Program Rept."
 - Vol i

 * Northern States Power Co HO/06/30 325pp
- --B007030183 "1979 Environ Monitoring & Ecological Studies Program Rept."
 - Vol 2 # Northern States Pawer Co 80/06/30 325pp
- 8007160558 Forwards monthly operating repts for June 1980 MAYER.L O Northern States Power Co 80/07/11 ig
- ~~8007160562 Monthly operating repts for June 1980 HUNSTAD, A. A. Northern States Power Co. 80/07/01 9pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007010524 Forwards LER 80-016/031-0 MAYER,L D Northern States Power Co 80/06/27 in
- --8007010529 LER 80-016/03L-0 on 800529, during instrument calibr.
 instrument was dropped on trip throttle valve linkage,
 tripping valve k making pump inoperable for 3 minutes
 Caused by personnel error
 HUNSTAD, A A Northern States flower Co 80/06/27 in
- 8007210379 Ferwards LER 80-017/03L-0 MAYER,L 0 Northern States Power Co 80/07/14 lp
- ~-8007210380 LER 80-017/03L-0 on 800615 during normal operation, found one charging pump out of svr Charge pump 23 started & shut down Caused by air leaks on speed control unit due to broken packing ring Packing ring replaced
 HUNSTAD, A A Northern States Power Co 80/07/14 ip
- 8007250340 RD 80-20 on 800715, w/Unit 2 at 1007 power & Unit 1 at cold shutdown, main generator separated from grid & one offsite source was lost tripping reactor & coolant pumps Caused by severe electrical storm Transformer restored TIERNEY, F P Northern Btates Power Co 80/07/14 1p
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8007100455 Forwards request for add1 info for review of util 790323 security contingency plan Encl withheld (ref 100FR2 770) MOVAK,T M Assistant Director for Operating Reactors 80/08/19 2nd
- BOO7170444 Forwards NRC comments on emergency plan Responses to comments must be submitted by BOO630 NOVAK-T M Assistant Director for Operating Reactors BO/06/26
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89ap
- B007020607 Response in apposition to applicant motion to postpone special prehearing conference re spent Puel pool mod proceeding Urges scheduling at earliest convenience due to significant benefit to all parties, including applicant MILLER, D S Sensible Maine Power MILLER, D S, Miller, D S B0/06/26 2pp
- --8007020610 Memorandum of points & authorities in support of intervenor apposition to applicant motion to postpone special prahearing conference Public interest is better served by rapid decision, per case law Certificate of Svc enci MILLER, D S Sensible Maine Power MILLER, D S Miller, D S 80/06/26 App

- 8007030240 Response in opposition to licensee motion to postpone prehearing conference until after 601001 Suggests moderate delay until mid-Aug 1980 for licensee to consider amend resite spent fuel storage Cirtiricate of Svc encil REIS, E.J. Hearing Branch 3 (10/07/02 Spp.
- 8007300122 Appeals ASLB 800714 memorandum & order on schoduling prehearing conference Urges reversal of order & convening of special probleming conference Certificate of Svc encl MILLER, D S Sensible Maine Power MILLER, D S Miller, D S 80/07/26 3pc
- --8007300127 Brief in form of pleading in support of intervenor 800726 appeal from ASLB 800714 memorandum & order on scheduling prehearing conference Alleges denial of procedural due process per case law Urges holding of special prehearing MILLER.D S Sensible Mainc Power MILLER.D S Miller.D 9 80/07/26 10pp
- 8007310463 Memorandum & order.ALAB-602.dismissing Sensible ME Power appeal from ASLB 800714 order which postponed prehearing conference in spent field pool compaction proceeding BISHOP.C J Atomic Safety and Lirensing Appeal Panel 80/07/29 Rob
- H Ganeral correspondence
- BOO6230378 Ack receipt of NRC BO0609 ltr & encl evacuation time estimates for facility Estimates do not adequately define risk in terms of total population Multiplier of 3 4 for Boothay region is much too low GARRETT, E. G. Affiliation Unknown 80/06/14 3pp
- BOO71104B1 Requests that name of RR Radcliffe be replaced w/TH Macdonald on ME Dic of Chergy Resources mailing list for Correspondents re utils MACDONALD.TH Haine, State of BO/07/01 Ip
- 1 Financial information
- 8007080217 Forwards company statument of capita) requirements & sources for CYBO CRABTREE,R A Maine Yankee Alomic Power Co 80/07/01 2pp
- P Operating license stage documents & correspondence
- BOO7110325 Notification of 600005 menting w/util in Rethesda, MD to discuss effect of automatic initiation of auxiliary feedwater sys upon consequences of steam line break accident NELSON, C.C. Operating Reartors Branch 3 80/05/01 2pp
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Hodel Tech Specs which would provide acceptable resolution enci for guidance
 EISENNUT, D. G. Division of Licensing 80/06/11 62pp
- 6007110123 Notification of 800623 meeting w/etil in Bethesda.MD to discuss NRC version of ETS REGUA.G Operating Reactors Branch 3 80/0A/19 2pp
- B007010070 Responds to FOIA request for 97 documents referenced in M Tokar memo to ALRS concenning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTON.J M Division of Rules and Records 80/06/20 2pp
- --8007010099 Forward, summary of 741112 meeting w/util in Bethesda.MD to discuss examination of Core 1 furl assemblies & Core 1A reassembly pracedures List of attenders encl HOUSTON, M D Atomic Energy Commission, Directorate of Licensing 74/12/15 10pp
- B007140465 Notification of 800/15 meeting w/litensee to discuss shortnose sturgeon taken from intere structure on 800602 & 13 & to discuss details of incidents transmitted by NRC B00624 ltr REQUARY Operating Reactors Branch 3 80/06/64 2pp
- B007170060 Forwards request for addl infort details of 800602 & 13 discoverios of whathose sturiped endangered spectos, in facility intoke structure Druft responses will be discussed at 800715 site visit Formal response due 20 days from visit NOVAKIT M Assistant Director for Operating Reactors 80/06/26 3pp

- 8007030225 Submits responses to NRC 60070A request for add1 info re adequaty of station electrical distribution sys voltages OROCE.R H Maine Yankee Atomic Power Co. 80/06/30 i5pp
- B007090275 Advises NRC of completion of evaluation of effects of asymmetric LOCA loadings Design basis & safety evaluations described in FSAR are not adversely affected by asymmetric loadings resulting from postulated LOCA GRACE.R H Haine Yankee Atomic Power Co. B0/07/01 2pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & intense conditions PAR Model Tech Specs & Model Intense conditions for TMI-2 Lessons Learned Category A items enci for guidance EISENHUT.D © Division of licensing 80/07/02 69pp
- 8007090388 Notification of 800715-16 meeting w/otil in Wiscasset.ME to discuss answers to NRC 800701 questions re inservice test program REGUA.O Operating Reactors Branch 3 80/07/03 1p
- B007240346 Advises of NRC reorganization on B00428 which resulted in number of changes in oft titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08
- 8007140338 Forwards YOOAP-I-A.Revision 0, per MRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDER.L H Yankre Atomic Electric Co 80/07/09 2pp
- --8007140342 Advises that YUGAP-1-A, Revision 8, 1s acceptable Programmatic changes should be submitted to NRC for review prior to implementation Requests that ltr replace 800410 ltr & rept be renumbered w/revision & submitted to NRC HAASS, 4 P Guality Assurance Branch 80/07/02 lp
- 9007210020 Forwards request for add1 info.re inservice testing program, to complete review Draft responses will be discussed during 800715-16 meeting Responses should be forwarded by 800816 NOVAK, T.M. Assistant Director for Operating Reactors 80/07/07 22pp
- B007250404 Application for amend to App A of License DPR-36, consisting of proposed Change 77 to modify Tech Spec 3 10 11 re reactor protection sys setpoints
 JOHNSON & P Haine Yonkee Atomic Power Co 90/07/16 3pp
- --8007250400 Revised Figure 3 10-3 of Tach Spec 3 10 11 re reactor protection sys subpoints, submitted as proposed Change 77

 Maine Yankee Atomic Power Co. 80/07/16 1p
- BOO7280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH.D Yankee Atomic Electric Co 80/0//24 7pp
- O Inspection reports. IR Bulletins & correspondence
- B007020163 Forwards IE Info Notice B0-22, "Breakdowns In Contamination Control Programs " No written response required ORIER.B H Region 1. Philadelphia. Office of the Director BD/05/28 1p
- B007010316 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER.B H. Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 8007180070 Submits reply to 1F Bulletin 80-05 re vacuum condition resulting in 64mage to holdup tanks Measures described are adequate to protect against excessive vacuum conditions No corrective actums are planned MODDY.D F Maine Yankee Atomic Power Co 80/06/06 2pp
- 8007230339 Forwards 1E Insp Rept 50-309/N0-06 on 800407-11 & 21-24 No moncompliance muted BRUNNERF J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/09 2pp
- --B007230398 IE lasp Rept 50-309/80-06 pn 800407-11 & 21-24 No noncompliance puted Major areas impacted accessible areas, logs & records & licensee action on selected previous inspiring findings
 1.AZARUS. H. MARTIN. T. Region J. Philadelphia, Reactor Operations Nuclear Support Branch: BMRTLAND.P. Region J. Philadelphia, Office of the Director 80/06/07 Spp

- B007210575 Forwards 1E Info Notice 80-26, "Evaluation of Contractor GA Programs " No written responso required GRIER, B H Region 1. Philadelphia, Office of the Director B0706/10 ip
- 8007160352 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pumps Stude " No specific action or response required GRIER. B H Region i. Philadelphia, Office of the Director BO/06/11 19
- B007230377 Forwards IE Insp Rept 50-309/80-07 on B00505-09 No noncompliance noted BRUNNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/12 2pp
- --8007230383 IE insp Rept 50-309/80-07 on 800505-07 No noncompliance noted Major areas inspected followup on selected LERs & licensee action to limit online containment purging & ventilation
 LAZARUS, W Region 1, Philadelphia, Office of the Director MARTIN.T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/96/11 5pp
- 8007170321 Forwards response to IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Changes were made to preclude automatic loss of containment isolation as result of resetting containment isolation signals VANDENBURG.D Maine Yankee Atomic Power Co 80/06/13 9pp
- B007020709 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/18 1p
- 8007020301 Forwards IE Circular 80-19. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/20 1p
- 8007140711 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1. Philadolphia. Office of the Director 80/06/24 1p
- 8007910204 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/06/25 Ip
- 8007280458 Responds to IE Duiletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys "Twenty-two piping sys reanalyzed due to pape &/or support function or location differences identified in field effort MODDY.D E Maine Yankee Atomic Power Co 80/06/25 App
- 8007230132 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Elther A or D Qutput Codes " Written response required. IE Circular 80-16 also encl No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- B00721060: Forwards response to 1E Bulletin 80-1: Masonry walls in proximity to safety-related sys described in enc. table JOHNSON, W.P. Maine Yankee Atomic Power Co. 80/06/30 Spp.
- 8007140403 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds." Flued head designs w/containment boundary butt welds not used & containment penetration weld repairs not required during facility const MDGDY, D E Maine Yankee Atomic Power Co 80/07/01 2pp
- A Periodic operating reports & related correspondence
- 8007210367 Forwards. "Effluent & Waste Disposal Semiannual Rept. Jan-June 1979 " GROCE, R H Maine Yankee Atomic Power Co 79/08/29 1p
- ---8007210369 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1979 "
 # Maine Yankee Atomic Power Co 79/08/29 9pp
- BOO7110385 Forwards discharge monitoring rept for May 1980 GARRITY, J H Maine Yankee Atomic Power Co 80/07/07 2pp

- ~~8007110389 Discharge monitoring root for May 1980 FLANDERS.W Maine Yankee Atomic Power Co 80/05/22 5pp
- 8007280604 Forwards discharge monitoring rept for June 1980, submitted to ME Dept of Environ Protection Transmittal ltr entl OARRITY, J H Maine Yankee Atomic Power Co 80/07/24 2pp
- B Reportable occurrences, LERs & related correspondence
- BOO7010339 RO 80-15/01T-0 during engineering review discovered that Cycle 5 analysis did not consider four-step, long-term insertion of control element assemblies allowed by Tech Specs, which would permit less conservative operation HOOD, E.C. Maine Yankes Atomic Power Co. BO/06/25 1p
- B0070B04i3 Forwards LER B0-016/03L-0
 WDDD.E C Maine Yankes Atomic Power Co B0/07/02 ip
- --B007080417 LER 80-016/03L-0 on 800602, during startup at 15% power, steam generator 1 outlet steam pressure found higher than other two pressures Caused by math failure in heat affected ione of guide to disc weld Pieces welded BRINKLER, J E Maine Yankee Atomic Power Co 80/07/02 1p
- E007210428 Forwards LER 80~015/017-0
 W00D, E C Maine Yankee Atomic Power Co 80/07/09 1p
- ---BOD7210431 LER BO-015/01T-O on 800625, analysis performed for Cycle 5 did not consider four-step, long-term insertion allowed by Tech Beer Reanalysis completed Tech Spec change will be submitted BRINKLER, J E Maine Yankee Atomic Power Co BO/07/09 lp
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8007070109 Informs that, as stated in Suppl 4 to SER, manual ECC8 switchover approved in Suppl 1 to SER has been ra-evaluated NRC requires that manual switchover actions be replaced by automatic design complying whencl criteria SCHMENCER. A Licensing Branch 3 90/06/18 3pp
- F. Security, medical, emergency & fire protection plans
- 8007080068 Forwards Submittal 4 to 800627 security contingency plan Submittal withheld (ref 10CFR2 790) LIBRIZZI,F P Public Service Flectric & Gas Co of New Jersey 80/06/30 lp
- 8007210277 Notification of 800701 meeting w/util in Bethesda.MD to discuss emergency preoperedness KERRIOAN.J Operating Reactors Branch 3 80/07/01 3pp
- BOO7140429 Requests approval to proceed w/interim use of training facility in Quinton, NJ as nearsite emergency operations facility

 BCHNEIDER, F.W. Public Service Electric & Gas Co. of New Jersey
- 9 Adjudicatory correspondence
- BD07310243 Forwards Commission 800527 memorandum & order containing dacisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT. D & Division of Licensing 80/06/25 87pp
- J Insurance & indemnity information
- 8007010323 Forwards Endorsement 39 to ANI Policy NF-230 CORREALM A March & McLennan. Inc . M & M Nutlear Consultants. Inc Div 80/06/25 2pp
- 8007310342 Forwards Endorsement 32 to MAELU Policy MF-90 CORREA, H A Harsh & McLennan, Inc., H & H Nuclear Consultants, Inc Div 80/07/21 2pp
- 8007310376 Forwards Endorsement 40 to ANSI Policy NF-230 CORREA,M A Harsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/07/21 2pp

- P Operating license stage documents 4 correspondence
- 8007010363 Forwards NRC reorganization chart for Dfc of Norlear Reactor Regulation, effective 800428 Considerations Te activities should be made through assigned mgt representatives Areas of disagreement may be discussed through Informal Appeal TEDESCO,R L Assistant Diroctor for Licensing 80/06/13 2pp
- 8007110456 Informs that second interim rept.per facility 316(b) plan of study.will be distributed to technical advisory group by 800625 belay caused by computer problem Submittal date should allow enough time for review before 800709 meeting 9HISSAIS, J.A. Public Service Floctric & Gas Co. of New Jersey 80706713 2pp
- B007160416 Notification of 800000 meeting w/util in Bethesda.MD to discuss NRC position on steam generator tube plugging & installation of inspigorts KERRIGANIU Licensing Branch J B0706/13 2pp
- 8007020086 Forwards request for add1 info needed to complete timely review of TMI-2 Leosons Learned Task Force short-torm items Response requested within 20 days

 BCHMENCER, A Licensing Branch 3 80/06/20 5pp
- 8007110554 Summary of 800610 meeting w/util in Bethesda, MD re control rod position indicator sys license amend request Lists three possible solutions to problem w/indicator Attendee list encl
 KERRIGAN, J Licensing Branch 3 80/06/24 3pp
- B007110561 Bummary of 800605 meeting w/util & Wostinghouse in Bethesda,MD re-proposed conceptual design of automatic ECCS switchover sys List of attenders & meeting handout encl KERRIGAN,J Licensing Branch 3 80/06/24 16pp
- BOQ723000) Forwards statement of policy is requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUI, D. G. Division of Licensing BO/06/26 2pp
- 6007030249 Forwards response to 800404 confirmatory orders re loss of non-Class IE instrumentation & control power bus lines written for Unit 1 but also applicable for Unit 2.except as noted includes response to IE Circular 79-02 Affidavit encl BCHNETDER, F. W. Public Service Electric & Gas Co. of New Jersey B0/06/27. 35pp
- 8007070110 Submits plan to replace long-term contractor personnel w/committed staff of licensee employees.in accordance w/Item 7 4(4) of Toch Spets & commitment to NRC Licensee expects to start plan on 800801 Schedule & graph and LIBRIZILF P Public Service Electric & Cas Co of New Jersey 80/04/27 4pp
- B007070285 Forwards responses to full power license requirements identified at NRC 800619 meeting MITTLR L Public Service Electric & Gas Co of New Jersey 80/06/27 14pp
- ---B007070289 Tech Spec Pages 3/4 7-5 through 7-7 for auxiliary feedwater sys & auxiliary feed storage tank Related documentation encl

 * Public Service Flertric & Gas Cu of New Jersey B0/04/27
- 8007030161 Forwards addl into in response to NRC 800618 request re auxiliary feedwater sys Auxiliary feedwater sys for both units are identical in design, including equipment & automatic initiation logic HITELRI Public Service Liectric & Gas Co. of New Jersey 80/07/01 13pp
- 8007030229 Forwards addl into te full power license requirements identified at 800619 meeting Into supplements 800627 ltr MITEL. Public Service Electric & Gas Co. of New Jersey 80/07/01 65pp
- B007030244 Forwards response to 800620 request for Addl info re TMI Lessons Learned requirements MITTLER L Public Service Electric & Gas Co of New Jersey B0/07/02 App
- 8007140628 Forwards test procedure SUP 8/1 1.App 9. "Feedwater Hommer Test," for review & approval Procedure provided per requirement in Tech Spec 9 3 MITTLIR L. Public Bervice Electric & Gas Co. of Now Jersey 80/07/07 ip

- --8007160633 Test procedure SUP 80 1 Foodwater Hammer Test "

 * Public Service Electric & Gay Co of New Jersey 80/07/07
- BG07210365 Forwards revised page: to BO0102 lessons loarned implementation submittal Addl info inflects discussion at BO0408 meeting w/NRC LIGHTZTIFF Public Service Flectric & Gas Co. of New Jersey BO/07/08 54pp
- 8007230616 Discusses required performance of augmented low power startup test program Near-term OL applicants should perform tests similar to tests proposed by TVA prior to exceeding 5% of rated thermal power EISENNUT.D C Division of Licenzing 80/07/11 2pp
- BOD72400Bl Requests that encl list of inforce possibility that longterm water source for autiliary feedwater sys may contain salt-be provided to complete full-power requirements SCHWENCER.A Licensing Branch 3 80/07/11 3pp
- 8007280006 Notification of 800723 meeting w/otils in Bethesda, MD to discuss matters or THI~2 dated requirements DROMFRICK.A U Licensing Branch 1 KERRIGAN.J D , STABLE.C R Licensing Branch 2 80/07/16 App
- 8007280442 Requests that 800317 request to amend License DPR-70 apply to License DPR-75 Requests authorization to lower individual cell min voltages on 125 & 28 volt batteries to 2 13 volts Battery manufacturer 800627 ltr % fee encl LIBRIZZILF P Public Service Ciectiic & Gas Co of New Jersey 80/07/16 4pp
- --B007280443 Proposed change to Tech Sper Pages 3/4 B-il & 14 resurveillance requirement, for electrical power sys at Unit 2

 # Public Service Electric & Gas Co of New Jersey B0/07/16
 3pp
- B007210219 Forwards proposed conteptual design for automatic switchover of ECCS from injection phase to recirculation phase of operation Final design package will be submitted for NRC review % approval by 800901

 HITTLER L Public Service Electric & Gas Co of New Jersey 80/07/17 23pp
- 8007210389 Submits addl info re containment sump model test program Objective is to confirm existing sump design or if improvements are indicated to develop suitable mode Check tosting of final design will be performed MITTL.R L. Public Solvice Electric & Gas Co. of Now Jorsey 80/07/17 3pp
- 8007310460 Forwards request for add1 info re effects of debris on containment emergency sump performance under post-LOCA conditions Concerns related to containment sump hydraulic performance have been accoptably resolved GCHMENCER.A Licensing Branch 3 80/07/21 7pp
- O Inspection reports: 1E Bulletins & correspondence
- 8007020133 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required ORIER B H Region 1, Philadelphia, Office of the Director G0/05/28 |p
- 8007010300 Forwards TE info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/05/29 ip
- 8007210610 Forwards IE Info Notice 60-26, "Evaluation of Contractor On Programs " No written response required (PIER.D H Region 1, Philadelphia, Office of the Director 60/66/10 ip
- 8007160352 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRIER.B R Region is Philadelphia, Affice of the Director 80/06/11 ip
- BOO7170570 Responds to IE Bulletin BO-05. "Engineered Safety Feature (ESF) Reset Controls "Describes instances discovered in fire protection, Feedwater & steam line isolations Design changes scheduled BCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey BO/06/13 6pp

- 8007170642 Responds to IE Bulletin 80-10. "Contamination of Nonracioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Rulease of Radioactivity to Environ "Requirements 1 & 2 were completed on 800612 SCHNEIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/13 10
- B007020603 Forwards IE Bulletin B0-15, "Pussible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, U H Region 1, Philadelphia, Office of the Director 80/06/18 ip
- 8007020519 Forwards IE Circular 80-i5. "Loss of Reactor Coolant Pump Conling & Natural Circulation Cooldown" No written response required GRIER, B H Region i. Philadelphia. Office of the Director 80/06/20 ip
- 8007160736 Forwards IE Circular 80-i4, "Adjoactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIERS B H Region 1, Philadelphia, Office of the Director 80/06/24 19
- B007210274 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.D H Region 1. Philadelphia, Office of the Director B0/06/25 Ip
- 8007310052 Forwards IE Insp Repts 50-272/80-ii & 50-31i/80-07 on 800501-31 No noncompliance noted BRUNNER, E.J. Regiun I. Philadelphia. Reactor Operations Nuclear Bupport Branch 80/06/26 2pp
- --8007310059 IE lasp Repts 50-272/80-11 & 30-311/80-07 on 800301-31 No noncompliance noted Major areos inspected tours of facility, lag & record reviews. reviews of licensee events & operational safety verification NDRAHOLM.L J., HILL.N M Region I, Philadelphia, Office of the Director KERHNG,R R Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/23 17pp
- 8007230173 Forwards 1E Bullotin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007210608 Forwards response to IE Bulletin 80-08 Both units have containment boundary butt welds Ail welds fabricated to Section VIII of ASME boiler & pressure vessel code SCHNEIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/30 400
- 8007210268 Forwards final response to confirmatory orders issued on 800404 in reply to 18 Bulletin 79-27 re loss of Nonclass 18 instrumentation & control power sys bus during operation Response submitted per util 800326 ltr Waffidavit & memo. 8CHMEIDER.F W Public Service Electric & Oas Co of New Jersey 80/07/01 39pp
- B007210528 Returns documents re Item 10 of IE Insp Rept 90-31i/78-51 on possible sensitization of safety injection pump piping M/o encl CARLBON.R.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 60/07/01 Ip
- 8 Reportable occurrences. LERs & related correspondence
- 8007170437 Forwards LER 60-004/03L-0 LIBR1221.F P Public Service Electric & Gas Co of New Jarsey 80/07/10 3pp
- --B007170448 LER 80-004/03L-O on 800610, during routine surveillance, both safety injection pumps were made operable at less than 312 F in RCS Caused by lack of procedure to limit max number of operable safety pumps MNRPHY.M J Public Service Electric & Oas Co of New Jersey, B0/07/10 ip

- --8007280632 LER 80-005/03L-0 on 800622 during preparation for heatup, position indication & mechanical operation of pressurizer overpressure protection valves gave faise indication & failed to respect Possibly caused by foreign matl in valve MURPHY, M J Public Service Clectric & Oas Co of New Jersey 1 p 80/07/21
- 8007270694 Forwards LER 80~006/03L-0 LIBRIZZI,F P Public Service Electric & Cas Co of New Jersey 80/07/23 ip
- ~-B00729071i LER B0-006/03L-0 on B00625, residual heat removai pump was discovered to have been previously improperly assembled Caused by either personnel eiror or procedural inadequacy Pump inspected, repaired & reassembled NURPHY, H J Public Service Electric & Gas Co of New Jersey B0/07/23 2pp
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plans
- BOO7230093 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security agt personnel at facility EIRENHUT, D 0 Division of Licensing 80/07/ii 2pp

Q. Adjudicatory correspondence

- B007020243 Forwards 800519 itr to Friends of the Earth forwarding Director's decision DD-80-22 in response to 791024 petition DENTON,H R Office of Nuclear Reactor Regulation, Director 80/06/19 3pp
- 8007310243 Forwards Commission 800527 memorandum & order containing NO/310/43 Forwards commission 30002/ memorandum & order cont. decisions on UCB /80502 potition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action ra fire protection for electrical cables EIBENHUT, D O Division of Liconsing 80/06/25 87pp
- 8007110002 Order granting extension until 800722 for Commission to plet to review decision on enforcement action request, DD-80-22 HOYLE.JC Office of the Secretary of the Commission 80/07/08
- 8007150927 Forwards licenses 800711 proposed findings of fact & conclusions of law in form of initial derision Assumes ASLB approval to parties' 800930 proposed transcript corrections per 900809 stipulotion Centrificate of Svc encl BAXTER.T A Shaw, Pittman, Potts & Trowbridge 80/07/11 4
- --8007150555 Proposed findings of fact & conclusions of law in form of initial decision Long-term mods w/undertaken add1 changes provide reasonable assurance that plant will resond safely to feedwater transients Exceptions must be filed in 10 days BAXTER.T A . TRAVIEGO-DIAZ Sacramento Municipal Utility District MAXTER.T A Shaw. Pittman, Potts & Trowbridge 80/07/11 252pp
- 8007310389 Requests filing date be revised from 800801 to 04 to allow opportunity to make changes in findings LANPHER, C California, State of LANPHER, C Hill Christopher & Phillips 80/07/25 2pp

H General correspondence

j

- 8007290236 Responds to 790405 ltr re nuclear power Nuclear plants generated 13% of electrical energy in 1979 Rancho Seco can resume operation when mode are completed Excerpts re GA, radioblological hazards of Pu & environ effects encl DENTON, H R Office of Nuclear Reactor Regulation, Director GA00457 2007 DENTON, H R OF 80/06/27 26pp
- --B007290253 Requests info re percentage of electricity produced by nuclear plants, whether Hancho Soco will be closed down & cases where fuel rods or valves were found faulty UPTON:R T Affiliation Unknown 79/04/05 3pp
- 8007300370 Advises of change of address from 520 Capital Mall, Buite 700 to 455 Capital Mail, Buite 265 Related correspondence HURSM.Q Sacramento Municipal Utility District 80/07/02 ip

- P Operating license stage documents % correspondence
- 800724020B Forwards B&W licthsers' re-ponses to 790907 request for review of schedule for instabiling tafety-grade anticipatory reactor trip for ioss of Spedwater & tulbine trip Review should be completed by 791115

 CAPRAIR A TM1-2 Builetins & Orders 79/10/24 Ip
- 8007230079 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution end for guidance ELSENHUT. D C Division of Livensing 60/06/11 62pp
- 8007010575 Discusses licensee consideration of increased onsite raduaste storage Requests reviews for onsite storage additions in monthly operating repts Draft licensing position se onsite storage safety considerations end REID, R W. Operating Reactors Branch 4 80/06/j.c.
- B007100203 Application to amend License DPR-54 by incorporating proposed Amend 68 for Tech Specs based on fire protection STB Forwards proposed Amend 68 to Tech Specs Sections 3 14 & 4 18 MATTIMOE, J J Sacramento Municipal Utility District 80/06/19
- --8007100206 Propused Amend AH to Tuch Specs, Sections 3 i4 & 4 iB, based on fire protection sts * Bacramento Municipal Utility District 80/06/19 11pp
- ROD7170667 Forwards questions to fuel assembly holddown spring failures first observed at Davis-Besse 1 & under investigation by B&W Results of holddown spring insps at facility as well as safety significance required within 60 days NDVAK.T M Assistant Director for Operating Reactors 80/07/01
- 8007210004 Forwards questions to fuel assembly holddown spring inspt & safety significance of operating w/broken springs in core Requests response within 60 days
 NOVAK: Y M Assistant Director for Operating Reactors 80/0//01
- BOO7240244 Requests response to encl questions re-fuel assembly holddown spring failures NRC is interested in results of holddown spring insps at facility & safety significance of operating whiteen springs in core NOARLT M Assistant Director for Operating Reactors 80/07/01
- B007250001 Requests submittal of application for amend to license consisting of Yeth Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D & Division of Licensing 80/0//02 69pp
- GOO7080183 Responds to NRC 780125 ltm requesting all PWR licenses to evaluate LOCA loads BAM-1597 % BAM-1621 submitted BGO214 % O701/respectively. demonstrate ability of facility to maintain core cooledility in event of asymmetric LOCA MATTIMOE, J J Sacramento Municipal Utility District BO/07/03 l 80/07/03 1p
- BOO7230432 Application for Amend 67 to License DPR-54 clarifying Tech Specs re plant organization chart & surveillance regulirements when reactor is critical MATTIMOE, J.J. Sarraments Municipal Utility District. 80/07/09
- --8007230443 Revised Tuch Specs Page 4-1 & Figure 6 6-2 clarifying plant organization chart & surveillance requirements when reactor is critical
 - Bacramento Municipal Utility District 80/07/09 200
- B00723065) Provides info re new off titles positions to assignments of personnel resulting from 800428 reorganization of DFc of Nuclear Reactor Regulation NOVAK, T M Assistant Director for Operating Reactors 80/07/10
- 8007240123 Submitt addl info to complete response to 791119 request for addl info re containment purge & vent sys WALBRIDGE, W C Barramento Municipal Utility District BO/07/11
- BOO7290622 Requests correspondence between NRC & util re seismic investigation Requests meeting wheth in it is derived in review progress of studies & present expertise in residuing seismic data

 DAVIS.J F California, State of ER/07/11)p

- 8007250J45 Forwards licensee 800721 ltr re safety grade anticipatory reactor trip Scc list end!

 BAXIER, T A Shaw, Pittman, Potts & Trowbridge 80/07/22 2pp
- ---B007250348 Notifies that equipment being added to learter protection sys cabinets is of sufficient mass as to require new seismic analysis of cabinets Analysis requires approx 20 wks info will be provided in time to allow for final design approval WALBRIDGE, W.C. Sacramento Municipal Utility District 80/07/21 to
- G Inspection reports. IE Bulletins & correspondence
- 8007240198 Responds to IE Builetin 80-03. "Loss of Charcoal from Type II. Two-Inch. Tiay Adsorber Cells " Const of trays does not utilize rivets for securing perforated screen to casing Screen is spot welded at approx one-inch intervals MATTIMOS. J Sacramento Thomasipal Utility District 80/03/06 2pp
- BOO7250370 Forwards response to IE Bulletin /9-27, "Loss of Non-Class IE Instrumentation: / Control Power Sys Bus During Operation: Describes power upsit events on NRI/ICS Buffer cord installations will be checked WALGRIDGE, N (Sacrimento Nunicipal Utility District BO/03/12 18pp
- 8007180541 Responds to IE Bulletin 79-17. Revision 1. "Pipe Cracks in Bitagnant Borated Water Sys at PWR Plants "Three recordable Indications noted in two welds determined to be geometric reflections caused by weld inou
- BO07240192 Forwards response to IE Dulletin 80-04, "Analysis of FWR Hain Steam Line Break H/Continued Foedwater Addition " Plant sys & structures designed to respond to double ended guillatine steam line break inside containment MATTINORF, J Sacramento Municipal Utility District 80/05/06
- 8007020240 Forwards lE Info Notico 80-22. "Breakdowns In Contamination Control Programs " No written response required ENGELKEN.R H Region 5. San Francisco. Défice of the Director 80/93/28 lp
- BOO7250676 Responds to [E Bulletin BO-12, "Decay Heat Removal Bys Operability " Operational assessment indicates similar occurrence not likely at facility because of differences in decay heat removal syst & ECCS
 HATTIMOE. J J Saciamento Municipal Utility District 80/06/04
- 9007290847 Responds to 1E Dulletin 80-05 Sys that could be valved directly to primary sys water reviewed RCS drain tank. Flash tank & makeup tank may be subjected to vacuum conditions Other tanks can withstand conditions win inward buckling MATTIMDE. J J Sacramento Municipal Utility District 80/06/09 2pp
- 8007220250 Forwards IE Info Notice 80-25, "Evaluation of Contractor GA Programs" No written response required ENGELKEN.R H Region 9. San Francisco, Office of the Director BO/06/10 Jp
- 8007310477 Responds to IE Bulletin 80~06 Review of electrical drawings made to insure safety-related equipment remains in emergency mode upon reset Testing completed for all equipment that can be tested while plant is in operation RALBRIDGE.W C Sacramento Municipal Utility District 80/06/10 200
- 8007030014 Forwards IE Dulletin 90-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ENGLERING M Hagion 5. San Francisco. Office of the Director 80/06/18 1p
- B007240407 Forwards IE Insp Rept 50-312/80-17 on 800501-30 No noncompliance noted CREMS.J L Regton 5. San Francisco. Reactor Operations Nuclear Support Branch B0/06/18 2pp
- --8007240420 IF insp Rept 50-312/80-;7 on 800301-30 No noncompliance noted Major areas inspected followup on items of noncompliance k headquarters requests CANTER.H L. Region 5. San Francisco. Office of the Director FAULKENBERRY.8 Region 5. San Francisco, Reactor Operations Nuclear Bupport Branch 80/06/17 Bpp

- B0070204BD Forwards IE Circular B0-15, "Loss of Reactor Coolent Pump Cooling & Natural Circulation Cooldown "No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director
- 8007180295 Forwards IE Circular 80~14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required EMSELKEN,R H Region 5, San Francisco, Office of the Director 80/06/24 ip
- 8007230379 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Qutput Codes "Written response required IE Circular 80-16 also shal No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/27 10
- 8007310294 Forwards 1E Insp Rept 50-312/80-13 on 800505-09 No noncompliance noted CREMS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/02 2pp
- ~~8007310301 IE Insp Rept 50-312/80-13 on 800303-09 No noncompliance noted Major areas inspected document control program, onsite review committee operations reactor operator requalification program & IE Bullstin 79-27 followup ZMETZIO. 0 B Region 5. San Francisco. Office of the Director FAULKENBERRY. B Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/02 7pp
- R Periodic operating reports & related correspondence
- E007150588 Forwards monthly operating rept for June 1780 RDDRIGUEZ.R J Sacramento Municipal Utility District 80/07/07 1p
- --B007150592 Monthly operating rept for June 1980 GOLOMED.R W Sacramento Municipal Utility District 80/07/07
- S Reportable occurrences, LERs & related correspondence
- 8004240284 PND-V-80-17 senior resident inspector informed that spacer grads on five Cycle 3 fuel assemblies damaged during fuel movements Cause of damage due to contact between spacor grads w/bourd fuel & adjacent assemblies during refueling FAULKENEERRY, B Region 5. San Francisco, Office of the Director 80/03/11 2pp
- 6007080270 Forwards LER 80-030/03L-0
 MATTIMDE. J J Sacramento Municipal Utility District 60/06/24
- --B0070B0277 LER B0-030/03L-0 on B00623, while performing I-10BC, reactor protection sys channel C test, overpower bistable voltage setting was found drifted out of spec Caused by maifunctioning of semiconductor voltage regulator COLOMOD, R W Sacramento Municipal Utility District 80/05/26
- E007230165 PNG-V-80-057 on 800709, licensee reported that two direct radiation monitors on perimeter fence of restricted area showed results above reporting level of Tech Specs High values may be result of baste storage FISH: Region 5, San Francisco, Office of the Director 80/07/10
- 8007230154 PNS-V-80-004 on 800403, employee denied access to vital areas because of personnel-related matter On 800604 employee again denied access to site because of behavior 80HUSTER.M D. NORDERHAUG.L R Region 5, San Francisco, Office of the Director 800/07/11 2pp
- E0073104:0 Forwards LER 80-031/03L-0 MATTIMDE, J Sacramento Nunicipal Utility District E0/07/17 2pp
- --B007310416 LER 80-031/03L-0 on 800703 during review of IE Bulletin 77~14 work found stress analysis for nonconforming pipe support was overlooked Caused by design documentation & const drawings not conforming to soismic analysis COLOMBO R W Sacramento Municipal Utility District 60/07/16

- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007010369 Forwards "Rept on Wall Penetration Fire Stops" & "Fire Test Criteria for Penetration Boals in Concrete Floors & Walls " TRIMBLE.D C Arkansas Power & Light Co 80/06/19 ip
- --8007010373 "Rept on Wall Penetration Fire Stops "
 * Underwriters Laboratory 80/04/30 i45pp
- --8007010380 "Fire Test Criteria for Penetration Seels in Concrete Floors & Walls " Four illegible drawings enci Arkansas Power & Light Co 80/06/04 Spp
- GOO7O70148 Documents NRC telcon & approval of temporary exemption to existing emergency plan. Section 4 3 i i-C requiring decontamination shower facilities in omergency control ctr TRIMBLE. D C Arkansas Power & Light Co 80/06/27 2pp
- 9007170281 Forwards Amend 60 to emergency plan TRIMBLE, D. C. Arkansas Power & Light Co. 80/07/11 lp
- --8007170283 Amend 60 to emergency plan consisting of Figure 3.instial notification in event of accident

 # Arkansas Power & Light Co 80/07/31 ip
- 8007230073 Notification of 800722 meeting w/AR Power & Light Co in Hethesda, MD to review proposed early warning sys VIBSING, 0 8 Operating Reactors Branch 4 80/07/16 2pp
- Q Adjudicatory correspondence
- ### BIO07310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cobles EIHENHUT.D 0 Division of Licensing 80/06/25 89pp
- H General correspondence
- BOO7110449 Requests response to encl R Lacewell ltr re plans to increase facility spent fuel storage pond site BETHUNE.E House of Rep 80/04/30 2pp
- BD07010024 Submits updated info re admittance of NRC personnel to facility Requests that permanent nonemplayee picture badges & site orientation be provided W/o encl
 SEVFRIT, K V Region 4, Dallas, Office of the Director 80/06/16
- 8007070020 Requests that util provide IE headquarters w/microfiche copy of listed P&IDs MADSEN. C.L. Region 4, Dallas, Office of the Director 80/06/16
- BO07250070 Responds to encl 800504 itr to President Carter re nuclear anargy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 prass reloase & energy plan encl DENTON: HR Office of Nuclear Reactor Regulation. Director 80/06/27 22pp
- EDO7100148 Requests removal of TB Conner from list of correspondence recipients & addition of N Reynolds Licensee has changed legal representation
 TRIMBLE.D C. Arkanses Power & Light Co 80/07/03 1p
- BD07310331 Respones to 800625 ltr re B00510 event at Unit i Forwards LER 80-015/01-0 & IE Insp Repts 30-313/80-07 & 50-368/80-07 Discusses treatment of spilled water & radioactive content of water M/o encl BEYFRITAK V Region 4. Dallas, Office of the Director 80/07/15
- P Operating license stage documents & correspondence
- BOO6240237 Responds to technical assistance request for proposed Tech Space changes for B&W operating plants Forwards requirements for add1 info IBRAEL.B.L. TMI-2 Bulletins & Orders 79/08/29 13pp

- 8007240208 Forwards littl licensers' responses to 79090/ request for review of schedule for installing safety-grade anticipatory reactor trip for loss of feedwater & turbing trip Review should be completed by 791115

 CAPRAIR A TMI-2 Dulleting & Orders 79/10/24 lp
- B007020210 Responds to NRC B00401 request for info re potential failure of once through steam generator auxiliary feedwater sizeve/collar welds Probable cause & failure mode of weld cracking not get determined
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/05 3pp
- 8007230099 Requests submittel of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EIBENHUT.DG Division of Licensing 60/06/11 42pp
- 80070i0356 Forwards abnormal transjonts operating guidelines program outputs Draft guidelines scheduled for submittal in Aug 1980 Copy numbers assigned to event tree drawings Requests controlled copies be withheld (ref iOCFR2 790)
 TRIMBLE.D C Arienses Pawer & Light Co 80/06/16 ip
- 8007030371 Forwards request for addI info no waste gas sys NOVAK.T M Assistant Director for Operating Reactors 60/06/23
- 80071504B9 Application to amend Licenses DPR-5t & NPF-6.deleting requirement for testing reactor bldg smoke detectors while reactors remain critical Suggested changes to Tech Spec pages & Class III fee encl CAVANAUGH.W Arkansas Power & Light Co 60/06/26 2pp
- ~~8007150494 Buggested changes to Tech Spec Pages 3/4 3-43 & 110p re-fire detection instrumentation * Arkansas Power & Light Co = 80/06/26 = 2pp
- 8007170319 Summary of 800612 meeting w/utils in Bethesda.MD re interim reliability evaluation program DLSHAN,L N Operating Reactors Branch 1 80/06/30 3pp
- 8007290186 "Electrical, Instrumentation & Control Aspects of Low Temp Overpressure Mitigation Sys.AR Nuclear Dne.Unit 1 " WEBER, D A E080 Idaho, Inc FIN A-6296 8007250186 80/06/5 16pp
- 8007070253 Responds to NRC 800410 Itr requesting that all licensees amend Tech Bpers so that definition of term "operable" would be consistent w/NRC STS Revision will require at least TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/01 2pp
- 8007090287 Forwards small break w/failed power operated relief valve analysis in response to ltem 2D of NRC 790821 ltr Analysis demonstrates that present operator guidelines are adequate to mitigate consequences of valve failure
 TRIMBLE:D C Arkansas Power & Light Co 80/07/01 14pp
- 8007180429 Informs that util is interested in participating in NRC research program for interim reliability evaluation program, discussed in B00612 meeting
 TRIMBLE.D C Arkansas Power & Light Co 80/07/01 3pp
- 8007210004 Forwards questions re fuel assembly holddown spring anaps & safety significance of operating w/broken aprings in core Requests response within 60 days NOVAK.T M Assistant Director for Dyorating Reactors 80/07/01
- B007210589 Forwards questions to fuel assembly holddown spring failures NRC is interested in knowing results of insps & safety significance of operating w/broken springs in core Requests response within 60 days of itr receipt NOVAKITM Assistant Director for Operating Reactors 80/07/01 3pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items and for guidance EISENHUT, D G Division of Licensing 80/07/02 69pp
- 8007210023 Requests info to 800624 loss of offsite power transient at Unit 1 Info ancludes description of switchyard operation, process computer printouts of alarms during transient & strip charts for primary & secondary sys
 NBVAK.T M Assistant Director for Operating Reactors 80/07/08

- 8007150394 Advises of continued compliance O/current regulations re hydrogen production from clad-water reaction after installation of RCF vents per NUREG-0578 Procedural guidelines will be submitted 810101 TRIMBLE,D C Arkansas Power & Light Co 60/07/10 2pp
- B007280350 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation
 NDVAM,T N Assistant Director for Licensing 80/07/10 2pp
- 8007270603 Reiterates util position re need for addl instrumentation for detection of inadequate core cooling No addl instrumentation is needed Util 800131 ltr summarized position No responses received to date TRIMBLE.D C Arkansos Power & Light Co 80/07/11 2pp
- 8007240120 Discusses NRC 800616 ltr se reactor vessel surveillance program Questions necessity for immediate change of Tech Spec 4 2 8 Current procedure is adequate to maintain reactor vessel mail surveillance program
 TRIMDLE, D C Arkansas Power & Light Co 80/07/14 ip
- 8007290040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement power on to ratepayers PRC would present any info at formal hearing No investigation planned VDEGELI, R J Office of the Executive Legal Director 80/07/18
- @ Inspection reports, lE Bulletins & correspondence
- 8007020194 Responds to IE Bulletin 80-04, "Analysis of PWR Hain Steam Line Break w/Continued Feedwater Addition " Sufficient time would exist for operator to isolate effected oncethrough steam generator in event of overpressurisation TRIMSLE.D C Arkansas Power & Light Co 80/05/27 Spp
- B007020269 Forwards IE Info Notice 80~22. "Breakdowns In Contamination Control Programs " No written response required BEYFRIT.K V Region 4. Dallos. Office of the Director 80/05/28
- 8007210342 Forwards IE Circular 80-13. "Grid Strap Damuge in Hestinghouse Fuel Assemblies "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/28
- 8007010040 Forwards IE Info Notice 80-20. "Loss of Suction to Emergency Feedwater Pumps " No written response roquired SEYFRIT.K V Region 4. Dallas. Office of the Director 60/05/29 ip
- 8007220177 Forwards IE Insp Repts 50-313/80-07 k 50-368/80-07 on 800422-0521 & notice of violation HADSEN.O L Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/05 2pp
- --8007220185 Natice of violation from insp on 800422-0521
 * Region 4. Dallas, Office of the Director 80/06/04 1
- --B007220197 1E Insp Repts 50-313/80-0/ & 50-368/80-07 on 800422-0521
 Noncompliance noted incomplete written procedures,
 Insufficient adherence to procedures & poor housekeeping
 measures
 WESTERMAN.T.F., JCHNSON.W.D., CALLAHAN.L.J., Region 4, Dallas,
 Office of the Director B0/06/04 1Bpp
- 8007020201 Responds to IE Dulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Only Unit 1 reactor coolant make-up tank & Unit 2 vol control tank could contain appreciable amounts of hydrogen TRINGLE.D C Arkansas Power & Light CO 80/06/10 5pp
- 8007220074 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs " No written response required SEYPRIT.K V Region 4. Dallas. Office of the Director 80/05/10 in
- 80/06/11, V Region 4, Dallas, Office of the Director 80/06/11
- 8007300349 Forwards IC Insp Repts 50-313/80-09 & 50-368/80-09 on 800827-30 & notice of violation MADERN 6 L Region 4. Dallas, Reactor Operations Nuclear Eupport Branch 80/06/12 2pp

- --B007300353 Notice of violation from insp on 800527-30 • Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/06/11 1p
- --B007300354 lE Insp Repts 50-313/80-09 & 50-368/80-09 on B00527-30 Noncompliance noted failure to adhere to procedures for handling temporary mods to jumpers & bupasses YANDELLIL A , WEGIERMAN, T F Region 4, Dallas, Office of the Director 80/06/11 Spp
- 8007070172 Ack receipt of 800529 ltr informing NRC of steps taken to correct violations noted in TE Insp Ropts 50-313/80-06 & 50-365/80-06 MADSEN.O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/06/17 1p
- 8007230244 Forwards 1E Investigation Ropts 50-313/80-08 & 50-368/80-09 on 800510-12 No noncompliance noted BROWN, 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/06/20 2pp
- --B007230257 IE Investigation Repts 90-313/80-08 & 50-368/80-08 on 800510-12 No noncompliance noted Major areas inspected radiological conditions & environ impact associated w/main coolant pump seal failure BROWN, 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch WILDORN,L Region 4, Dallas, Office of the Director 80/06/18 5pp
- BOD7240031 Forwards 1E Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response regulated BEYFRIT,K V Region 4, Dallas, Office of the Director BO/06/20
- BOO7220495 Notifies that memo, reprocedure for retention & performance of safety evaluation & notice of violation for deficiency in IE Insp Rept 50-313/80-05, has been forwarded to Licensing Bection personnel involved in design change package reviews TRIMBLE, D.C. Arkansas Pawer & Light Co. 80/07/11 1p
- 800/300320 Ack receipt of 800527 ltr informing NRC of steps taken to correct violation noted in 1E insp Repts 50-313/80~07 & 30-366/80-07 MADSEN.0 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/07/22 lp
- -~8007300325 Responds to NRC 800605 ltr re violation noted in IE Inap Repts 50-313/80-07 & 80-366/80-07 Corrective actions Junction box cover replaced & door on end closed TRIMBLE,D C Arkansas Fower & Light Co 80/06/27 2pp
- 8007300329 Ack receipt of 800702 itr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-313/80-09 & 50-368/80-09 MABSENIG L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/07/22 ip
- --8007300335 Responds to NRC 800612 ltr re violation noted in IE Insp Repts 50-313/80-09 & 50-368/80-09 Corrective actions, entries in Jumper & bypass log were cleared Completed pages of log were forwarded to filten TRIMBLE: D C Arkansas Power & Light Co 80/07/02 2pp.
- R. Periodic operating reports & related correspondence
- 8007210450 Rept on radioactive effluent release, Jan-June 1978, s Arkansas Power & Light Co 78/03/31 10pp
- 8007010470 Forwards corrected page for monthly operating rept for May 1980 TRIMSLE,D C Arkansas Power & Light Co 80/06/25 ip.
- --8007010480 Corrected page to monthly operating rept for May 1980 BRAMLETT.L 8 Arkansas Power & Light Co 80/06/13 ip
- B007100143 Forwards results of impingement monitoring at intake during May 1980, submitted in accordance w/ETS 4 1,2 a(2) Set of computer cards encl
 TRIMBLEID C Arkansas Power & Light Co 80/06/30 14pp
- 8007210420 Forwards monthly operating rept for June 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/15 Ip
- --8007R10432 Monthly operating rept for June 1980 BRANLETT, L 8 Arkansas Power & Light Co 80/07/15. 5pp

- S Reportable occurrences. LERs & related correspondence
- 8007140621 PND-IV-80-023 on 800624.all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of syc for maint ANNICUTI.D Region 4. Dallas. Office of the Director 80/06/25
- 8007200346 RDs 50-313/80-22 & 50-368/80-042 on B00624, events occurred on 500 kv power lines which resulted in loss of all 500 kv power lines & reactor trips of both units Cause not stated Both units stable Followup rept will be transmitted O'HANLON.J P Arkansas Power & Light Co 80/06/26 2pp
- 8007150641 Forwards LER 80-022/01T-0
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/07 1p
- --8007150650 LER 80-022/01T-D on 800624. w/Hayflower 500 kV transmission line but of svc & unit operating at full power, 500 kV Habelvale line tripped Caused by ground fault & overload Lutrout relays were reset & 500 kV bus re-energized SHIVELY, C N Arkenses Power & Light Co 80/07/07 5pp
- B007150593 Forwards LER 80-016/03L-0
 TRIMBLE.D C Arkansas Power & Light Co 80/07/10 1p
- 8007150530 Forwards updated LER 80-011/03L-3
 TRIMBLE, D C Arkansas Power & Light Co 80/07/11 1p
- 8007310334 Discusses 800706 routine surveillance test on emergency steam driven feedwater pump during which steam leak developed Requests that one of five failed studs be delivered to Perameters, Inc for analyses MADEEN 0 L Region 4, Dallas, Roactor Operations Nuclear Support Branch 80/07/15 2pp
- 8007210406 Forwards LER 80-020/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/07/16 1p
- --B007210413 LER 80-020/03L-0 on 800621, during makeup pump test, rod index limits exceeded Caused by operator inadvertently opening imlet to standby demineralizer All operators reviewed accurrence ERAMLETT, L S Arkansas Power & Light Co 80/07/16 ip
- BD07240176 Responds to NRC 800607 request for into re reactor coolant pump seal Failure analysis in progress Oversize drawing awailable in Central Files only TRIMBLE,D C Arkansas Power & Light Co B0/07/16 97pp
- B007180312 Forwards LER 80-021/03L-0
 TRIMBLE, D C Arkansas Power & Light Co 80/07/17 1p
- --8007180318 LER 80-021/03L-0 on 800624, during reactor trip steam driven emergency feedwater pump automatically statted per design but tripped on overspeed Cause undetermined Pump proved operable before returning to power BRAMLETT.L S Arkansas Power & Light Co 80/07/17 lp
- BOO724014B Forwards updated LER 80-015/01X-1
 TRIMBLE, D C Arkansas Power & Light Co B0/07/17 ip
- --B007240150 Updated LER 80-015/01X-1 on B00510, during steady state power operation, step increase in RCS leakage observed Caused by seal failure All four RCB seal cartridges replaced or rebuilt
 SHIVELY, C. N. Arkansas Power & Light Co. 80/07/17 App
- E00729033; PNO-TV-80-024 on 800716, plant was shut down due to primary to secondary lask Max radioactivity detected was below Tech Epec limit
 JOHNSON, N D. HUNNICUTT, D M. MADSEN, G Region 4, Dallas, Office of the Director. 80/07/17 1p
- 8007280504 Forwards LER 80-019/03L-0
 TRINGLE, D C Arkansas Power & Light Co 80/07/18 Ip

- --8007280511 LER 80-019/03L-0 on BOUGL9, Bulling fire sys test fire pump PGA could not be stupped from control room Caused by low fire sys pressure resulting from leaking fire sys relief valve Valve adjusted BRAMLETT, U.S. Arkansas Powrl % Light Co. BU/07/18 1p
- DOCKET 50-315 DONALD C FOOK NUCLEAR PUMER PLANT, UNIT 1
 F Security, medical, emergency & file protection plans
- 8007210080 Forwards request for additinfolis safeguards contingency plan Format should be revised to conform wifermat for Reg Ouide 5 54 W/o and NOVAKAIM Assistant Director for Operating Rewiters 80/06/30 2nb
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum % order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum % order UCS 771004 potition sought action re fire protection for electrical cables EISENHUE, D.C. Division of Lirensing 80/06/25 89pp
- H General correspondence
- 8007020177 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800807-08 Council Interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR. J D Assistant Director for International Cooperation 80/05/13 3pp
- P Operating license stage documents & correspondence
- 8007110580 Advises that Class I & III licensing fees, requested in 800409 Itr re review of request to employ divers to cut stude in spent pool fuel, have not been reveived Requests that fees be submitted within IS days of receipt of Itr MILLER.W Q successe Fee Management Branch 80/06/02 ip
- 8007010546 Notification of 800779-31 ombits meeting w/util to discuss inservice testing program for pumps & valves MINER, 9 Operating Reactors Branch 1 80/06/09 26pp
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Speis which would provide acceptable resolution entil for guidance EISENHUTID G Division of Licensing B0/06/(1 62pp
- 80070R0591 Forwards response to request concerning addl info on responses to NRC short-term requirements for auxiliary feedwater sys BDLAN.J E Indiana & Michigan Flectric Co 60/06/26 4pp
- 8007110595 Requests determination whether weldments in safety-related tanks fabricated by Graver Tank meet design specs Reply requested within 20 days
 MOSELEY,N C Division of Reactor Operations Inspections 80/06/27
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes % license conditions PWR Model Tech Specs & Model Incense conditions for TM1-2 Lessons Learned Category & items encl for guidance EISENHUT.D 0 Division of Licensing 80/07/02 69pp
- 8007280064 Informs that requested exemption from Class I fee requirement for 800374 submittal for approval to employ divers in spent feel pool is granted Refend will be forwarded when processed MILLER,W D License Fee Management Granth 80/07/11 ip
- 8007250493 Responds to MRC 800677 for responding deficiencies in tanks fabricated by Gravir Tank & Mfg Co Facilities have four Graver tanks Insp. confirmed that full penetration weld prists & welds agree w/requirements of design drawings HUNTER, R S Indiana & Machigan Electric Co 80/07/18 3pp
- G Inspection reports. IE Bulletins & correspondence
- 8007220095 Forwards IE lusp Repts 50-315/60-01 & 50-316/80-01 on 800114-18,21-25,29-31.0211-12.0303 05 & 0415 & notice of violation HEISHMAN.R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 2pp

- --8007220100 Notice of violation from insp on 800(14-18.21-25.29-3). 021(-12.0303-05 & 0415 # Region 3. Chicago, Office of the Director 80/05/02 2pp
- --8007220112 IE Insp Repts 50-315/80-01 & 50-316/80-01 on 800114-18, 21-25.29-31.0211-12.0303-05 & 0415 Noncompliance noted deficiencies te equipment classification, housekeeping, surveillance & infractions re audit findings & program STREETER, J.F., JACKIN, I.N. Region 3. Chicago, Office of the Director HEISHMAN, R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/02 21pp
- B007020043 Forwards IE info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required KEPPLER.J G. Region 3. Chicago, Office of the Director 80/05/28
- 8007210353 Forwards IE Circular 80-13, "Grid Strap Damage in Wastinghouse Fiel Assemblies" No written response required KEPPLER, J. G. Region J. Chicago, Office of the Director BC BO/05/2B
- 8007010068 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedbater Pumps" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007170545 Forwards Waste Packaging Insp Rept 15000027/80-46 on 800229 DAY/19949 Foreners waste rackeying inspirete 1990002790-46 on 60 to 20 t
- --8007170550 Notice of violation from insp on 800227 * Region 3. Chicago, Office of the Director 8 80/04/2B 1a
- --8007170556 Waste Packaging Insp Rept 15000027/80-46 on 800229
 Roncompliance noted no placard on shapment boses
 BECKER.T. JHDMAGR D. Region 5. Sao Francisco. Office of the
 Director RODK.H E. Region 5. Sao Francisco. Fuel Facility &
 Materials Safety Dranch 80/04/28 App Materials Safety Branch
- 8007220148 Forwards 1E Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/06/10
- 800714015B Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response REPPLER, J G Region J. Chicago. Office of the Director BO/06/11
- 8007110465 Forwards response to IE Bulletin 80-05. "Vacuum Condition Resulting in Demage to Chemical Vol Control Sys (CVCS)
 Holdup Tanks " Design review made of all sys containing low pressure tanks or holdup tanks "Protoctive measures adequate DGLANJE Indiana & Michigen Electric Co 80/06/i3 App
- 6007030206 Responds to IE Bulletin 60-09. "Hydramotor Actuator Deficiencies " ITT Opneral Controls Series AH-90 & NH-90 hydramotor actuators are not used in safety-related sys pr components Indiana & Michigan Electric Co 80/06/16 ip
- 8007020245 Responds to 1E Bulletin 80-12, "Decay Heat Removal Sys Operability " Incident described in 1E Info Notice 80-20 is not likely to occur at plant, based on reasons listed RKR sys redundancy & diversity were reviewed DOLAN, J F Indiana & Michigan Electric Co 80/06/17 Spp
- 8007030042 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Lors of Offsite Power "Written response required KEPPLER.J G Region J. Chicago, Office of the Director, 80/06/1 Region J. Chicago, Office of the Director, 80/06/18
- B00702056B Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldnum " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/20
- 8007180324 Responds to 800318 itr forwarding IE Sulletin 80-06 Energization of reactor trip breakers closing coils is strictly manual operation Equipment foes not change emergency mobe because of trip signal reset HUNTER.R 8 Indiana & Michigan Flertric Co 80/06/20 Spp

- 8007170426 Forwards It Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel " No witten response required KEPPLER.J G Region J. Chicogo. Defice of the Director 80/06/24
- 8007230305 Forwards IE Bulletin 80-16, "Putential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmittors W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G Region J. Chicago, Office of the Director 80/06/2
- 80071603B4 Remits fee to cover NRC insps for period Mar 1979-Mar 1980 per NRC 800603 invoice HALONEY.G P Indiana & Michigan Electric Co 80/07/09 Ip
- 8007)50696 Submits reply to IE Builetin 80-10 re contamination of nonradioactive sys & potential for releases Adequate monitoring is performed routinely on sys to preclude release problems No further action required MALONEY, 8 P Indiana & Michigan Electric Co 80/07/10 2pp
- 8007220080 Bubmits reply to IE Bullstin 80-10 re contamination of nonradioactive sys & potential for releases Adequate menitoring is performed routinely on sys to proclude release problems No further action required MALONEY. & P Indiana & Michigan Electric Co 80/07/10 2pp
- G007230267 Forwards reply to IE Bulletin 80-11 re masonry wall design Structural integraty evaluation of masonry walls is underway Full evaluation will be completed MALONEY.0 P Indiana & Michigan Electric Co 80/07/10 31pp
- B007300252 Corrects typographical error made in transcribing data to Table I of response to IE Wulletin 80-05 re damage to chemical vol control sys tanks Amended Table I enci HUNTER, R 8 Indiana & Michigan Electric Co 80/07/15 2pp
- 8007310278 Ack receipt of 800530 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-315/80-04 & 50-315/80-04 MEISHMAN, R.F. Region 3. Chicago, Reactor Operations Nuclear Support RF Region 3. Chicago, Reactor Operations Nuclear Support 80/07/25 ip
- --8007310284 Forwards response to NRC 800502 ltr re violations noted in IE Imap Repts 50-315/80-04 & 50-316/80-03 Corrective actions procedure changed to probibit use of hoses for making up water to spent fuel pit & valves locked closed DDLAN, J E Indiana & Michigan Electric Co 80/05/30 3pp
- R Periodic operating reports & related correspondence
- BOO7150342 Forwards monthly operating rept for June 1980 SHALLER, D. V. Indiana & Michigan Power Co. 80/07/09
- --8007150547 Monthly operating rept for June 1980 OILLETT, W T Indiana & Michigan Power Co & B0/07/03 6pp
- 9 Reportable occurrences. LERs & related correspondence
- B007280510 RD during Apr 1980, estimated weight of fish impinged was substantially above level normally experienced Preliminary estimated weights for May indicate above normal fish impingement level final environ impact rept pending SHALLER. D V Indiana & Michigan Electric Co 80/07/03 [p
- B007150586 Forwards LERS B0-012/03L-0 & 80-013/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/07/08
- --B007150997 LER B0~012/03L-0 on B00609, two check valves, R-154 & R-157, discovered utilized as containment isolation valves Valves were not included in type C leak test prior to Nov 1978 Type C leak test performed & check valves added RISCHLING, J L Indiana & Michigan Electric Co 80/07/08 #2pp
- --9007150623 LER 80-013/03L-0 on 800616, transmitter for steam generator level loop 4 (BLF 142) found to be out of spec low Cause attributed to instrument drift Transmitter, Barton Model 764 recalibr & returned to syc DELONG, S.D. Indiana & Michigan Electric Co. 80/07/08 ip
- 8007150696 Forwards LER 80-014/03L-0 8HALLER, D V Indiana & Michigan Electric Co 80/07/10 lp.

ŀ

--8007150703 LER 80-014/03L-O on 800612 during divider barrier seal inspiseveral areas of seal found cracked & split Couse of seal failure unknown Design change request submitted to investigate alternate matls
BROWN.M S Indiana & Michigan Electric Co 80/07/10 ip

V Operator Examinations

8007310399 Forwards revised licensed operator requalification program, per NRC 800328 request Only major change is in control manipulation section now requiring annual simulator training as well as increased manipulation requirements.

SHALLER, D V Indiana & Michigan Electric Co 80/07/25 i2pp

BOCKET 50-316 DONALD C CODE NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8007210088 Forwards request for addl info re safeguards contingency plan Format should be revised to conform w/format for Reg Quide 3 54 H/o encl MOVAK.T M Assistant Director for Operating Reactors 80/06/30

Q Adjudicatory correspondence

8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refire protection for electrical cables
EISENHUT.D C Division of Licensing 80/06/25 89pp

H General correspondence

8007020177 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800807-08 Council interested in observing waste mgt activities Cooperation will be major contribution to NMC oxchange arrangement LAFLEUR.J D Assistant Director for International Cooperation 80/05/13 3pp

8006270181 Responds to 800429 request for info re M LeMiere inquiry about amount of nuclear waste disposed in State of Mi Spent fuel from four operating MI reactors stored onsite NRC svaluated status of waste mgt in 1977 W/related FR excerpts DIRCKS:H J Office of the Executive Director for Operations 80/06/09 10pp

P Operating license stage documents & correspondence

8007110580 Advises that Class 1 % III licensing fees, requested in 800409 itr re review of request to employ divers to cut studs in spent pool fuel, have not been revolved Requests that fees be submitted within 15 days of receipt of itr MILLER, W O License fee Management Branch 80/06/02 ip

8007010546 Notification of 800729-31 onsite meeting w/util to discuss inservice testing program for pumps & valves MINER, 8 Operating Reacturs Branch i 80/06/09 26pp

B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D @ Division of Licensing 80/06/11 62pp

8007170423 Forwards Amend 21 to License DPR-74, safety evaluation & notice of issuance & availability
VARGA.S A Operating Reactors Branch i 80/06/18 2pp

---B007170427 Amend Ri to Licensø DPR-74, adding motor driven auxiliary feedwater pump to each unit to separate shared operation of motor driven auxiliary feedwater pumpn VARGA:8 A Operating Reactors Branch 1 B0/06/18 Spp

--8007170931 Safety uvaluation supporting Amend 21 to License DPR-74
* Operating Reactors Branch 1 80/06/18 App

--8007170434 Notice of issuance & availability of Amend 21 to License DPR-74 VAROA:B A Operating Reactors Brunch 1 80/06/18 2pp

BOO7020591 Forwards response to request concerning additinfor on responses to NRC short-term requirements for auxiliary feedwater systematics of BO/06/26 4pp

8007)10555 Requests determination whether weldments in safety-related tanks fabricated by Graver Fank meet design spect Reply requested within 20 days
MOSELEV.N C Division of Reactor Operations Inspections 80/06/27

8007250001 Requests submittal of application for anothe to license consisting of Inch Spec changes & license conditions PWR Model Tech Specs & Midel License conditions for TMI-2 Lessons Learned (ategur A libons Mrt for guidance EISENHUT, D G Division of Licensing 80/07/02 69pp

8007280064 Informs that requested exemption from Class 1 fee requirement for 800324 submittal for approval to employ divers in spent fuel pool ir granted Refund will be forwarded when processed MILLER.W O License Fee Management Granch 80/07/11 ip

8007250493 Responds to MRC 8006-7 ltr is potential celding deficiencies in tanks fabricated by Graver lank & Mfg Co Facilities have four Graver tanks linsp confirmed that full penetration weld exists & welds agree w/requirements of design drawings HUNTER.R B indiana & Michigan Electric Co 80/07/18 3pp

O Inspection reports, (E Bulletine & correspondence

8007220095 Forwards IE Insp Repts 50-315/80-01 & 50-316/80-01 on 800114-18,21-25,29-31,0211 12 0303-05 % 0415 & nutice of violation HEISHMAN.R F Region 3. Chicago, Reactur Construction & Engineering Support Branch 80/05/05 2pp

--890/220100 Notice of violation from insp on 800114-18/21-25,29-31. 0211-12,0303-05 & 0415 * Region 3. (bicago, Office of the Director 80/05/02 2pp

---B007220ii2 IE Insp Repts 50-715/80-01 & 50-716/90-01 on B00114-18, 21-25,27-31,0211-12,0303-05 & 0415 Noncompliance noted deficiencies re equipment classifications housekeeping, surveillance & infractions re and it findings & program STREETER, J. F. JACKIH-I N. Region 3. Chicago, Uffice of the Director MEISHMAN, F. Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/05/02 21pp

8007020043 Forwards IE Info Notice 80 22, "Breakdowns In Contamination Control Programs" No written response required KRPPLER.J G Region 3, Chicago, Office of the Director 80/05/28 to

B007210353 Forwards IE Circular 80-13, "Glid Strap Damage in Westinghouse Fuel Assemblies " No written response required MEPPLER.J G Region J. Chicago. Uffice of the Director B0/05/28 to

8007010069 Forwards 1E Info Natice 80-23, "Loss of Soction to Emergency Feedwater Pumps" No written response required KEPPLCR, J. G. Region 3, Chicago, Office of the Director 80/05/29

B007170545 Forwards Waste Packaging Insp Rept 15000027/80-46 on 800229 & notice of violation
DAVIS:A Region 3, Chicago, Fuel Pacility & Materials Safety
Branch B0/06/10 2pp

---B007170350 Notice of violation from imag on 800225 * Region 3. Chicago, Office of the Director B0/04/28 ip

--B007170556 Waste Portaging Insp Rept in000027/00 4A on B00229
Noncompliance noted no placerd on shipment boxes
DECKER, J. IHUMAD, R.D. Region i Ban Francisco, Diffice of the
Director DUOK, H.E. Region S. San Francisco, Fuel Facility &
Materials Safety Branch 80/04/28 App

8007220148 Forwards IF Info Notice 80-74, "Evaluation of Contractor GA Programs" No written required KEPPLER, J O Region 3, Chicago, Office of the Director G0/06/10

8007i60158 Forwards IE Info Notice 80-27, "Degradation of Reactor Coplant Pump Study " No specific action of response requested MEPPLER,) 9 Region 3, Chicago, Office of the Ditertor 80/06/11 to

8007)10445 Forwards response to 1E Bulletin RO-U5, "Vacuum Condition Resulting in Damage to Chemical Vol control Sqs (CV/S) Holdup Tanks "Deeign review mode of all sys containing low pressore tanks or holdup tanks Protoctive measures adequate DOLAN, J. E. Indiana & Michigan Riectric Co. 80/96/13 App

- 8007030206 Responds to IE Bulletin 80-09, "Agdramotor Actuator Deficiencies" ITT General Controls Series AH-90 & NH-90 hydramotor actuators are not used in safety-related sys or components
 DDLAN, J E Indiana & Michigan Electric Co 80/06/16 ip
- 8007020245 Responds to IE Bulletin RO 12 "Decay Heat Removal Sys Operability " Incident described in 1E Info Notice BO-20 is not likely to occur at plant-bosed on reasons listed RMR sys redundancy "c diversity were reviewed DDLAN.JE Indiana". Michigan Electric Co. 80/06/17 8pp
- 8007030042 Forwards JE Bulletin 80-jb, "Possible tuss of Emergency Notification Sys (ENS) M/Loss of Offsite Power " Hritten response required KEPPLER, J. G. Region 3, Chicago, Offsice of the Director 80/06/18
- B00702056B Forwards IF Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, 'G Region 3, Chicago, Office of the Director 80/06/20 ip
- 8007180324 Responds to 800318 itr forwarding IE Dulietin 80-06 Energization of reactor trip breakers closing coils is strictly meanual operation Equipment does not change emergency made because of trip signal reset HUNTER.R'S Indiana & Michigan Electric Co 80/06/20 8pp
- B007170426 Forwards | L Cyrcular B0-14, "Radicattive Contamination of Plant Demineralized Mater Sys 2, Resultant Internal Contamination of Personnel" No written response required MEPPLER. J G Region 3. Chitags, Office of the Director B0/06/24 in
- 8007230305 Forwards IE Bulietin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required MEPPLER.J G Region 3. Chicago. Office of the Director 60/06/27 in
- BD07160384 Remits fee to cover NRC insps for period Mar 1979-Mar 1980 per NRC 800603 invoice MALONEY, G P Indiana & Michigan Flettric Co 80/07/09 1p
- 8007250016 Forwards response to IE Bulletin 60-08. "Examination of Containment Liner Penetration Welds "Facilities contain flued head design for containment ponetration connection as illustrated in figure NE-1120-1 of ASME 8 & P V code MALONEY, G P Indiana & Michigan Electric Co 80/07/09 2pp
- 8007220080 Submits reply to 1E Bulletin 30-10 re contamination of nonradioactive sys & potential for releases Adequate monitoring is performed routinely on sys to preclude release problems No further action required MALONEY. 0 P Indiana & Michigan Electric Co GO/07/10 2pp
- B007230269 Forwards reply to 1E Dulletin 80-11 re masonry wall design Structural integrity evaluation of masonry walls is underway Full evaluation will be completed MALONEY.G P Indiana & Michigan Electric Co 80/07/10 31pp
- 8007300272 Corrects typigraphical error made in transcribing data to Table I of response to IS Bulletin 80-05 re damage to chemical vol control sys tanks Amended Table I enci HUNTER:8 9 Indiana 2 Michigan Floctric Co 80/07/15 2pp
- 8007310278 Ack receipt of 800930 itr informing NRC of steps taken to correct violations noted in IE Inap Ropts 50-315/60-04 t 50-315/90-03 HE1SIMAN.R F Region 3, Chicago, Roactor Operations Nuclear Support Branch 60/07/25 ip
- --8007310284 Ferwards response to NRC 800502 its se violations noted in IE Insp Repts 50-315/80-04 & 50-316/80-03 (prective actions procedure changed to prohibit use of hoses for making up water to spent fuel pit & valves locked closed DCLAN-JE Indiana & Michigan Electric Co. 80/05/30. 3pp
- R Periodic operating reports to related correspondence
- 8007(50555 Forwards monthly operating rept for June 1980 SHALLER.D V Indiana & Michigan Power for 60/07/09 lp
- --8007190561 Monthly operating rept for June 1980 GILLETT.W T Indiana & Michigan Cower Co 80/07/03 6pg

- S Reportable occurrences, LERs & related correspondence
- 8007090289 Forwards LER 80-025/03L-0 SHALLER,D V Indiana & Michigan Electric Co 80/07/02 ip
- --B007090292 LER B0-025/03L-O on B00603 during normal operations, engineered safety feature vent fan HV-AES-1 circuit breaker tripped rendering ventilation sys inoperable Caused by failure of wring insulation in connection boxes

 EROWN M S Indiana & Michigan Electric Co 80/07/02 ip
- BOO7280510 RQ during Apr 1980, estimated weight of fish impinged was substantially above level normally experienced Proliminary estimated weights for May indicate above normal fish impingement level Final environ impact rept pending SHALLER, D V Indiana & Michigan Electric Ca 80/07/03 ip
- 8007150684 Forwards LER 80-026/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/07/08 ip
- --B007150695 LER 80-026/03L-O on B00609, check valves R-156 & R-157, utilized as containment isolation valves, found omitted from Type C leak test Valve R-156 installed backwards Caused by omission in procedure Valve R-156 resnetalled & tested RISCHLING, J L Indiana & Michigan Electric Co 80/07/08 2pp
- B007210537 Forwards LER B0-027/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/07/14 ip
- --9007210941 LER BO-027/03L-O on B00613, during piping modehand shutoff valve in suction line to motor driven auxiliary feed pump 1 was closed to stop leakage interfering w/welding Pump was inoperable until completion of welding LEASE,R S Indiana & Michigan Electric Co 80/07/14 ip

V Operator Examinations

800731037? Forwards revised licensed operator requalification program.

per NRC 800328 request Only major change is in control
manipulation section now requiring annual simulator training
as well as increased manipulation requirements

SHALLER, D V Indiana & Michigan Electric Co 80/07/25 12pp

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), supple & correspondence

- 8007210416 Submits Dept of Public Safety commonts on NRC review & safety evaluation of fire protection & life safety Licenses should be required to provide fire doors & automatic suppression sys as necessary RIDDLE.M W Calvert County, MD 80/07/14 2pp
- F Security, medical, emergency & fire protection plans
- B007160245 Forwards response to NRC comments re security training & qualification plan Response & revised plan withheld (ref 10CFR2 790)

 EVANS.V R Baltimore Gas & Clectric Co B0/07/14 ip
- G007220590 Informs that scheduled date for conducting additable tray penetration fire tests will be B00730 at Southwest Lab. Ban Antonio.TX Tests are designed to verify addit design of cable tray fire stops NRC has apportunity to witness fire tests LUNDVALL.A E Baltimore Gas & Electric Co 80/07/16 ip
- 8007280481 Submits correction to util 800402 submittal of facility modified amended security plan. Revision & Encls 1 & 3 incorrectly reflected Revision 5 Encls should be changed to Revision & EVANS. V R Baltimore Oas & Electric Co 80/07/22 ip
- @ Adjudicatory correspondence
- BOO7310243 Forwards Commission 800927 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 memorandum & order UCB 771104 patition sought action re fire protection for elektrical cables
 EISENHUT, D G Division of Licensing 80/06/25 89pp

H Osnaral correspondence

- 8007250251 Responds to 800515 ltr re JA Hay questions about facility 800327 radioactive gas leakage Leak caused by poor gasket seal on Unit 2 degassifier relief valve W/safety evaluation of util post-THI changes DIRCKS, W J Office of the Esecutive Director for Operations 80/07/07 2pp
- --B007250264 Requests response to enc.) JA May ltr requesting info to recent incident at facility
 SPELLMAN, 0 N House of Rep 80/05/15 lp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906220186 Summarizes responses to IC Bulletin 79-06B Operating manuals are being scrutinized Operational personnel are being trained Radioactive gases & liquids transfer lines are interlocked w/containment isolation &/or radiation signals TAM.P Division of Site Safety & Environmental Analysis 79/05/0B
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entl for guidance EISENHUT, D 0 Division of Licensing 80/06/11 62pp
- B007010568 Notification of B00715 meeting w/util in Bethesda.MD to discuss Chalk Point 500 kV transmission line LI.C.Y Operating Reactors Branch 3 (Pre B00428) B0/06/14 1p
- 8007170066 Notification of cancellation of 600715 meeting w/util in Bethesda.MD.to discuss agenda re 500 kV transmission line LI.C Y Operating Reactors Branch 3 80/06/16 ip
- --8007170071 Confirms telcon re tancellation of 800715 meeting w/util in Bethesda,MD re 500 kV transmission line FAUST.R. Plant Systems Branch (Pre 791030) 80/07/02 ip
- 9007020469 Summary of 800605 meeting w/util in Bothesda, MD re offsite Operating Reactors Branch 3 80/06/18 4pp
- 8007020349 Discusses 790729 application to amend Tech Specs,including proposed revisions to organization chart & safety committee membership Forwards supplemental changes to current organization & safety committee membership OLSON.R C Baltimore Gas & Electric Co BO/06/24 ip
- ~8007020354 Suppiementary organizational changes to Sech Specs for administrative controls # Baltimore Gas & Electric Co 80/06/24 Spp
- B007010329 Discusses concerns w/interim reliability evaluation program as outlined at B00612 meeting w/NRC Includes problems w/scheduling, methodology, timing, itcensee participation & regulatory ratcheting Buggests licensee methodology input LUNDVALL. A E Baltimora Gas & Eisctric Co B0/06/25 4pp
- 8007090324 Forwards proprietary & nonproprietary revisions of C-E margin improvement repts justifying recovery of margin inherently available in design Affidavits encl Proprietary rept withheid (ref 10CFR2 790)

 LUNDVALL, A E Baltimore Gas & Electric Co 80/06/26 2pp
- ~-8007090332 "Bass Use of Incore Detector Sys to Monitor DNB-LCO on Calvert Ciiffs Units 1 & 2," nonproprietary version * C-E Power Systems CEN-119(B)-NP 79/11/30 21pp
- ~-B007070341 "CEAH Method of Analyzing Sequential Control Element Assembly Group Withdrawal Event for Analog Protected Bys," nonproprietary version, # C-E Power Bystems CEN-121(B)-NP 79/11/30 125pp
- ~-B007090346 "FIESTA One Dimensional Two Group Space Time Kinetics Code for Colculating PNR Scram Reactivities " * C-E Power Systems CEN-133(8) 79/11/30 75pp
- ~-8007090352 "Statistical Combination of Uncertainties.Part 1." monproprietary varaion # C-E Power Systems CEN-124(B)-NP PT1 79/12/31 65pp

- --8007090361 "Statistical Combination of Uncertainties, Part 2." nonproprietary version

 * Combustion Engineering, Inc. LEN-124(B)-NP PT2 80/01/31 75pp
- --8007090369 "Statistical Combination of Uncertainties.Part 3."
 nonproprietary version
 * (-E Power Systems CEN-124(B)-NP P13 80/03/31 85pp
- 8007020436 Forwards proposed fech Spec, Changes 1 & 2 to ahend OLs Change i clarifies definition of "operable" allows substitution of installed 69 to offset power source in event of transfermer failure Fre encl
 LUNDVALL.A E Baltimore Oat & Electric Co 80/06/27 2pp
- --8007020442 Proposed Tech Spec Change 1 Clarifies definition of "operable" • Baltimore Oas & Electric Co - 80/06/27 - 6pp
- --B007020448 Proposed Tech Spec Change 2 Allows substitution of installed by kV offsite power source, instead of 500 kV offsite power sources, in event of transformer failure * Baltimore Gas & Electric Co B0/06/27 3pp
- B007020557 Forwards "RCS Asymmetric Lunds Evaluation Program," final rept in response to NRC 78/125 ltm to PWR licensess re asymmetric LOCA loads C-E offidavit for withholding encl Proprietary version of App A withheld (ref IGCFR2 790) LUNDVALLIA E C-E Operating Plants Owners Group 80/06/20 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program." final rept. Vol I * C-E Pawer Systems AD/06/30 20pp
- --8007020581 "RCS Asymmetric Loads Evaluation Program," final rept. Voi 2 * C-E Power Systems B0/06/30 300pp
- --8007020588 "ACS Asymmetric Loads Evaluation Program." final rept. Voi
 - * C-E Pawer Sustems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program." final rept. App A. numerical results, evaluation of C-E fuel Nonproprietary version App B.Palisades fuel analysis.eerl **

 C-E Power Systems BD/08/20/ 74pp
- --B007020400 "RCS Asymmetric Loads Evaluation Program." App E.ECCS analysis approach w/reduced area coolent channels in periphoral assemblies Final ropt * C-E Power Systems B0/06/30 9pp
- 8007170319 Summary of B00612 weeting w/utils in Bethesda,MD re interim reliability evaluation program DLSHAN,L N Operating Reactors Branch 1 80/06/30 3pp
- 8007250001 Requests submittal of application for amond to license consisting of Toch Spec Changes & license conditions PMR Model Tech Specs & Model License conditions for TME-2 Lessons Learned Category A stems entl for guidance EISENHUT.D & Division of Licensing 60/07/02 69pp
- 8007180076 Notifies that C-E //1203 request for route approval to cover spent fuel shapments to BMI is subj to licenso fee Review of request was completed on 800226 HILLER, W O License Fee Hanagement Branch 80/07/03 ip
- BOO7070291 Submits add) info requested by NRC /90721 ltr re 770703 request for amend to Licenses DPR-53 % DPR-69 concerning spent feel poul mod Structural % liner plate analysis encl LUNDVALL.A & Baltimore Gas % Electric Co 80/07/07 21pp
- 8007230176 Summary of 800618 meeting w/otil.Nuclear Energy Svc & Bechtel Power Corp re spent fuel pool and structure design LLC Y Degrating Reactors Branch is 80/07/88 Sep
- 80072403BA Advises of NRC reorganization on 800A28 which resulted in number of changes in ofe titles positions & issignments of personnel Aiso submits info for AETR NDVAK, T.M. Assistant Director for Approximg Reacture 80/07/08 20 a
- 8007210069 Notafication of FRANTIS meeting whitel in Bethesda.MD to discuss 18-manth fuel cyrles for facility Util & C-E with present previou of focumentation to be used in facility Cycle 5 reload analysis Operating Reactors Dranch 3 80/07/09 2pp

- 8007170354 Application for amend to Licenses DPR-59 & DPR-A9, revising Paragraph 4 5 ! b % adding Paragraph 4 5 ! f to Tech Specs re ECCS surveillance requirements LUNDVALL A F Baltimore Gas & Electric Co 80/07/14 3pp
- --BOO7170353 Proposed Tech Specs re ECCS surveillance requirements, revising Paragraph 4.5 i b & adding Paragraph 4.5 i F e Baltimore Cas & Electric Co. BO/07/14 ip
- O Inspection reports, JE Bulletins & correspondence
- B007090356 Forwards update to util B00417 response to IE Bulletin 79-01B. 'Environ Qualification of Class IE Equipment " Evaluation of available qualification data for components expected to be completed by B00430 LUNDVALLIA E Baltimore Gas & Electric Co B0/05/27 200pp
- --B007090359 Forwards corrected response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." replacing incomplete version forwarded by AE Lundwell 800303 ltr
 ASH.R F Baltinore Gas & Electric Co 80/03/05 200pp
- 8007020120 Forwards IE Info Notice 80-22, "Greatdowns In Contamination Control Programs" No written response required GRIER, 8 H Region 1. Philadelphin. Office of the Director 80/05/28 Ip
- 8007010279 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER, B H flegson 1, Philadelphia. Office of the Director 80/05/29 1p
- BD07170111 Responds to IE Bulletin B0-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Continued operation, even during interim period of natrogen sys setpoint mod, justified for listed reasons LUNDVALL, A E Baltimore Gas & Electric Co 80/06/04 2pp
- B007210241 Forwards IE Insp Repts 50-317/80-05 & 50-318/80-05 on B00407-30 No noncompliance noted BHUNNER,E J. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 60/06/04 2pp
- --BOO7210247 IE Insp Repts 50-317/80-05 & 50-318/80-05 on 800407-30 No nontempliance noted Major areas inspected control room & accessible portions of auxiliary turbine svc & intake bldgs, radiation protection & physical security ARCHITELLR Region 1. Philadelphia. Office of the Director MCCABE.E C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/30 20pp
- B007220278 Forwards 1E Insp Rept 50-317/80-07 on 800429-0501 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007220285 [E Insp Rept 50-317/80-07 on 800429-052] No noncompliance noted Major areas inspected pipe support activities performed to comply wite Bulletin 79-02 & radiation safety procedures DURR.JP. SERABIAN.J A Region 1. Philadelphia. Office of the Director TRIPP.L E Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/23 13pp
- 8007210554 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- 8007160337 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/11 in
- 9007170576 Responds to IE Bulletin RO-05, "Engineered Safety Feature (ESF) Reset Controls " Test to verify that actual installed controls are consistent w/schematics reviewed will be completed during Fall 1980 & early 1981 refueling outages LURIDVALL A E Saltimore Gas & Electric Co 80/06/17 4pp
- 8007020614 Forwards JE Bulletin 80-15. "Possible Loss of Emergency Notification Sqs (ENSI W/Loss of Offsite Power " Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/10 Ip

- 8007180600 Responds to IE Bulletin 80-10 Review of nonradioactive systemicided valve lineups, leaking valves & points of contact between radioactive & nonradioactive phases Addl surveillance of nonradioactive systemic be implemented LUNDVALL, A E galtimore Gas & Electric Co 80/06/19 ip
- 8007020483 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/04/040 10
- BOD7160ABS Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER, B H Region 1. Philadelphia, Office of the Director BO/06/24 19
- 8007210171 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H. Region I, Philadelphia, Office of the Director 80/06/25 Ip
- B007230076 Forwards IE Bulletin B0-16, "Potential Misapplication of Roseagunt Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes "Written response required IE Circular B0-16 also encl No written response required GRIER, B H Region I, Philadelphia. Office of the Director B0/06/27 2pp
- 8007250662 Corrects 800604 response to 15 Bulletin 80-05 Operating experience has shown that even if reactor coolant drain tank is pumped to max flow rate tank pressure remains greater than atmospheric pressure
 LUNDVALL.A E Baltimore 8as & Electric Co 80/06/27 2pp
- E007100228 Submits info re fluid head design penetration connections or other designs w/containment boundary butt welds between sleeve & process piping.per IE Bulletin 80-08 LUNDVALL.A E Baltimore Gas & Electric Co 80/07/03 Spp
- B007210044 Submits status of extensive survey program initiated in response to IE Bulletin B0-11 Accounts for half of masory walls requiring insp Remaining items will be covered in final rept to be submitted after completion of surveys LUNDVALL, A E Baltimore Gas & Electric Co B0/07/03 32pp.
- B007210574 Responds to IE Bulistin 80-08 Each unit contains five penetrations w/flued head design Penetrations N-stamped per requirements of Paragraph N-153 of ASME Code, Section III, Bummer 1979
 LUNDVALL, A E Pacific Gas & Electric Co 80/07/03 4pp
- B007250016 Forwards response to IE Dulletin 80-08, "Examination of Containment Liner Penetration Welds" Facilities contain flured head design for containment penetration connection as illustrated in figure NE-1120-1 of ABME 5 & P V code MALGNEY. Q P Indiana & Michigan Electric Co 0/007/09 2pp
- R Periodic operating reports & related correspondence
- 8007010389 Forwards monthly operating rept for May 1980 MERSON, 8 D Baltimore Gas & Electric Co 80/06/13 1
- --8007010390 Hunthly operating rept for May 1980 HERSON, S D Baltimore Oas & Electric Co 80/06/12 Spp.
- --8007010392 Monthly operating rept for May 1980
 MERSON: S D Baltimore Gas & Electric Co 80/04/12 9pp
- B007220351 Forwards monthly operating repts for June 1980 MERSON, S D Baltimore Gas & Electric Co 80/07/15 lp.
- --8007220355 Menthly operating repts for June 1780 HERSON, S D Baltimore Gas & Electric Co 80/07/15 18pp
- S Reportable occurrences. LERs & related correspondence
- 800728045) Forwards LER 80-031/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/07/18 ip
- --8007280453 LER 80-031/03L-0 on 800625, high oil temp alarm received on 4 kV unit syc transformer Caused by failure of cooling fame due to blown fuse in control circuit Fan did not transfer to backup power supply Cause unknown Fuse replaced DAVIS.8 M , DAVFR.E R Baltimore Cas & Electric Co 8D/07/10 to

- 8007280664 Forwards LER 80-029/03L-0 RUSSELL.L B Baltimore Cas & Electric Co 80/07/18 ip
- --8007280676 LER 80-029/03L-0 on 800616, control room air conditioning Unit ii placed out of svc to repair broken damper linkages Apparent cause was excessive wear due to inadequate linkage lubrication Periodic Lubrication Instituted DAVIS,8 N. HUSEBY,D E Daltimore Que & Electric Co 80/07/18 to
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 E NRC Bafety Evaluation Report (SER), suppls & correspondence
- BOO7R10416 Submits Dept of Public Safety comments on NRC review & safety evaluation of fire protection & life safety Licensee should be required to provide fire doors & automatic suppression sys as necessary RIUDLE.M W. Crivert County, MD 80/07/14 2pp
- F Security, medical, emergency & fire protection plans
- BD07i60245 Forwards response to NRC comments re security training & qualification plan Response & revised plan withheld (ref iOCFR2 790)

 EVANS,V R Baltimore Oas & Electric Co 80/07/14 ip
- BOO7220570 Informs that scheduled date for conducting add1 cable tray penstration fire tests will be BOO730 at Southwest Lab.San Antonio.TX Tests are designed to verify add1 design of cable tray fire stops NRC has opportunity to witness fire tests LUNDVALL.A E Baltimore Ost & Electric Co 80/07/16 ip.
- B007280481 Submits correction to util 800402 submittal of facility modified amended security plan. Revision 6 Encls 1 & 3 incorrectly reflected Revision 5 Encls should be changed to Revision 6 EVANS. V R Baltimore Cas & Electric Co 80/07/22 ip
- Q Adjudicatory correspondence
- BOO7310243 Forwards Commission BO0527 memorandum & order containing dicisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENRY, D. O Division of Licensing BO/06/25 89pp
- H General correspondence
- 8007230251 Responds to 800515 ltr re JA May questions about facility 800327 radioactive gas leakage Leak caused by poor gasket swal on Unit 2 degassifier relief valve W/safety evaluation of util post-TMI changes DIRCKS, W J Office of the Executive Director for Operations 80/07/07 2pp
- ---B007250264 Requests response to encl JA May 1tr requesting info re recent incident at facility
 SPELLHAN. O N House of Rep 80/05/15 ip
- P Operating license stage socuments & correspondence
- ECO7230079 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entil for guidance EISENHUT, D O Davision of Licensing 80/06/11 62pp
- 8007010568 Notification of 800718 meeting w/util in Dethesda. HD to discuss Chalk Point 500 kV transmission lins LI.C Y Operating Reactors Branch 3 (Pre 800428) 80/06/16 1p.
- 8007170066 Notification of cancellation of 800715 meeting w/util in Bethesda HD. to discuss agenda re 500 kV transmission line LI.C.Y. Operating Reactors Branch 3 80/06/16 ip
- ---8007170071 Confirms telcon re cancellation of 800715 meeting w/util in Bethesda.MD re 500 kV transmission line FAUST.R. Plant Systems Branch (Pre 791030). 80/07/02 ip

1

8007020449 Bummary of 800605 Apating w/util in Bathesda, HD re offsite power sources.

LI,C Y Operating Reactors Branch 3 80/06/18 4pp

- 8007020349 Discusses 790729 application to amend Tech Specs, including proposed revisions to organization chart & safety tommittee membership Forwards supplemental changes to current organization & safety committee membership QLBON.R C Baltimore Gas & Electric Ca BO/06/24 ip
- --R007020354 Supplementary organizational changes to Tech Specs for administrative controls + Baltimore Cas & Electric Co B0/06/24 Bpp
- 8007090324 Forwards proprietary & nonproprietary revisions of C-E margin improvement repts justifying recovery of margin inherently available in design Affidavits encl Proprietary rept withheld (ref 10CFRZ 790)

 LUNDVALL.A E Baltimore Gas & Electric Co 80/06/26 2pp
- ~-8007090332 "Bass Use of Incore Detector Sys to Monitor DNB-LCO on Calvert Cliffs Units 1 & 2." homproprietary version
 * C-E Power Systems CEN-119(B)-NP 79/11/30 21pp
- --8007070341 "CEAU Nethod of Analyzing Sequential Control Element Assembly Group Withdrawal Event for Analog Protected Gys," nanproprietary version * C-E Power Systems CEN-121(B)-NP 77/11/30 125pp
- --8007090346 "FIFBTA One Dimensional, Two Group Space Time Kinetics Code for Calculating PNR Scram Reactivities " * C-E Power Systems CEN-133(B) 79/11/30 75pp
- ---B007090332 "Statistical Combination of Uncertainties, Part 1,"
 nonproprietary vorsion
 * C-E Power System CEN-124(0)-NP PT1 79/12/31 65pp
- --8007090361 "Statistica) Combination of Uncertainties.Part 2,"
 nonproprietary version
 + Combustion Engineering, Inc. CEN-124(8)-NP PT2 80/01/31
 75pp
- --800709036B "Statistical Combination of Uncertainties.Part 3," nonproprietary version * C-E Power Systems CEN-124(B)-NP PTD 80/03/31 B5pp
- B007020434 Forwards proposed Tech Spec.Changes 1 & 2 to amend OLs Change 1 clarifies definition of "operable" allows substitution of installed 40 kV offsite power source in event of transformer failure Fee anci LUNDVALL.A E Boltimore Gas & Electric Co B0/06/27 2pp
- --8007020442 Proposed Tech Spec Change : Clarifies definition of "operable" * Daltimore Cas & Electric Co 80/06/27 App
- --8007020448 Proposed Tech Spec Change 2 Allows substitution of installed 49 kV offsite power source.instead of 500 kV offsite power sources, in event of transformer failure * Baltimore Oas & Electric Co 80/06/27 3pp
- 8007020557 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 7801P5 ltr to PMR licenses re asymmetric LOCA loads C-F affidavit for withholding encl Proprietary version of App A withheld tref 10CFR 790) LUNDVALL.A E C-E Operating Plants Owners Group 80/06/30 2pp
- ---8007020574 "RCS Asymmetric Loads Evaluation Program," final rept, Vol 1 * C-E Power Systems 80/06/30 20pp
- --B0070205B1 "RCS Asymmetric Loads Evaluation Program," final rept. Vol 2 * C-E Power Bystems 80/04/30 300pp
- --8007020588 "RCS Asymmetric loads Evaluation Program," Final rept, Vol 3 * C-E Power Systems 80/06/30 300pg
- ---8007020593 "RCS Asymmetric Loads Evaluation Program," final rept.App A. numerical results, evaluation of C-E fuel linn proprietery Version App B.Palisadus fuel amalysis-enrl + C-E Power Systems 80/06/30 Zapp
- ---8007020600 "RCS Asymmetric Loads Evaluation Program." App E.ECCS analysis approach w/reduced area toolant channels in peripheral assemblies Final rept # C-E Power Systems 80/06/20 9pp

- 8007.250001 Requests submittal of application for amend to license consisting of lech Spec changes & license conditions PMR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT.D C Division of Licensing 80/07/02 69pp
- 8007180076 Notifies that C-E 791203 request for route approval to cover spent fuel 'hipments to BMI is subj to license fer Review of request was completed on 800226 MILLER, W O License Fee Management Branch 80/07/03 ip
- B007090291 Submits addl info requested by NRC 790921 ltr re 790703 request for amend to Licenses DFR-53 & DFR-49 concerning spent fool pool mod Structural & liner plate analysis encl LUNDVALL.A E Baltimore Gas & Electric Cu B0/07/07 Zipp
- 8007230176 Summary of 800618 moeting w/util.Nuclear Energy Syc & Bechtel Pawer Corp re spent funl pool mod structure design L1.C Y Operating Reactors Branch 1 80/07/08 5pp
- 8007240380 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR
 NOVAK, T. H. Assistant Director for Operating Reactors 80/07/08
 Zon
- B007170352 Application for amend to Licenses DPR-53 & DPR-69, revising Paragraph 4 5 1 b & adding Paragraph 4 5 1 f to Tech Specs re ECCS surveillance requirement.
 LUNDVALL.A E Baltimore Gas & Electric Co 80/07/14 3pp
- ~~8007170353 Proposed Tech Specs re ECCS surveillance requirements, revising Paragraph 4 5 1 b & adding Paragraph 4 5 1 f # Baltimore Oos & Electric Co = 80/07/14 Ip
- O Inspection reports. IE Bulletins & correspondence
- 8007090356 Forwards update to util 800417 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Evaluation of available qualification data for components expected to be completed by 800630 LUNDVALLIA E Baltimore Gas & Electric Co 80/05/27 200ap
- --8007090359 Forwards corrected response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," replacing incomplete version forwarded by AE Lundvall 800303 ltr
 ASH R F Baltimore Gas & Electric Co 80/03/05 200pp
- 8007020120 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs ' No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/05/28 ip
- 8007010279 Forwards IE Info Nutice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No writtn response required GRIER.O B Region 1. Philadelphia. Office of the Director 80/05/29 1p
- 8007170111 Responds to IE Dulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 Continued operation, even during interim period of nitrogen sys selpoint mod, justified for listed reasons LUNDVALL, A E Baltimore Gas & Electric Co 80/05/04 2pp
- B007210241 Forwards JE Insp Repts 50-317/80-05 & 50-318/80-05 an 800407-30 No noncompliance noted DRURNER-E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --8007210247 IE Insp Repts 50-317/80 05 & 50-318/80-05 on 800407-30 No noncompliance noted Major areas inspected control room & accessible portions of auxiliary turbine svr & intake bldgs, radiation protection & physical security ARCHITZEL® Region 1. Philadelphia. Office of the Director INCAGE, E & Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/30 20pp
- 8007210354 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs ' Na written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/10 1p
- 8007160737 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study " No specific action or response required ORIER.D M Region 1. Philadelphia, Office of the Director 80/06/11 | p

- BOO7170376 Responds to IE Bulletin BO-O6, "Engineered Safety Feature (EBF) Reset Controls " Test to verify that actual instabled controls are consistent w/schematics reviewed will be completed during Fall 1980 & early 1981 refueling outages LUNBVALL:A E Daltimore Oas & Electric Co 80/06/17 App
- 8007020614 Forwards IE Bulletin 80-15, "Possible Lose of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER.J H Region 1, Philadelphia, Office of the Director. 80/06/18 1p
- B007180600 Responds to 1E Bulletin 80-10 Review of nonradipactive sys included valve lineups, leaking valves & points of contact between radioactive & nonradioactive phases Addl surveys lance of nonradioactive sys will be implemented LUNDVALL. A E Baltimore Gas & Electric Co 80/06/19 ip
- B007020483 Forwards IE Circular B0~15, "Loss of Reactor Coplant Pump Cooling & Natural Circulation Cooldown " No written response required. GRIER.B H Region 1, Philadelphia, Office of the Director B0/06/20 ip
- 8007160695 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/06/24 lp
- 8007210171 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required ORIER.B H Region 1. Philadelphia, Dffice of the Director 80/06/29 19
- 8007230096 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.D H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007250662 Corrects #00604 response to 1E Bulletin 80-05 Operating experience has shown that even if reactor coalant drain tank is pumped to max flow rate tank pressure remains greator than atmospheric pressure LUNDVALL.A E Baltimore Gas & Electric Co 80/06/27 2pp
- 8007100228 Bubmits info re fluid head design penetration connections or other designs w/containment boundary butt welds between sleeve & process piping.per IE Dultetin 80-08
 LUNDVALL, A E Daltimore Oas & Electric Co 80/07/03 5#p
- 8007210044 Submits status of extensive survey program initiated in response to IE Oulletin 80-11 Accounts for half of masonry walls requiring insp Remaining items will be covered in final rept to be submitted after completion of surveys LUNDVALL. A E Baltimore Gas & Electric Co 80/07/03 32pp
- 8007210574 Responds to IE Bulletin 80-08 Each unit contains five panetrations w/flued head design Penetrations N-stamped per requirements of Paragraph N-153 of ASME Code, Section III. Summer 1979
 LUNDVALL, A E Pacific Cas & Electric Co 80/07/03 App
- R Periodic operating reports & related correspondence
- 8007010389 Forwards monthly operating rept for May 1780 MERSON, S D Galtimore Qas & Electric Co 80/06/13 ip
- --B007010332 Monthly operating rept for May 1980
 MERSON S D Baltimore Oas & Electric Co 80/06/12 9pp.
- B007220351 Forwards monthly operating repts for June 1980 MERSON, S.D. Baltimere Oas & Electric Co. B0/07/19 1p
- --8007220355 Monthly operating repts for June 1980
 MERSON, S D Baltimore Gas & Electric Co 80/07/15 18pp
- S Reportable occurrences. LERs & related correspondence
- 8004240215 PNO-1-80-36 on 800307, licensee reported via hot line that small fire occurred in diesel generator Room 21 Fire extinguished in one minute Caused by fuel oil accumulation in exhaust manifold BRIGGS.L., NCCABE.E. BRUNNER.E Region 1. Philadelphia. Dffice of the Director 80/03/07 lp

0152 Forwards LER 80-030/03L-0 ELL.L B Baltimore Gas & Electric Co 80/07/18 ip

240153 LER BO-030/03L-O on BOO618, primary sample valve 1 CV-5467 dicated intermediate position & fully shut position could tbe verified Cause cannot be determined by remote means rrective action to be performed during shutdown VIS.S M., RIZZO,P G Baltimore Gas & Electric Co BO/07/18

0351 RD 80-32 on 800723, charging pumps 22,23 & 24 were placed of svc for mechanical reasons leaving charging pump 21 margency power Caused by operator failure to verify ty-related sys out of svc Corrective action forthcoming ELL.L B Baltimore Oas & Electric Co 80/07/24 1p

50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 urity, medical, emergency & fire protection plans

0063 Forwards revised Pages 1-14 & new Page 148 for proposed 10CFR50 "Fire Protection Program for Nuclear Power ts Operating Prior to 790101." transmitted by NRC 800519 Page 14a not encl NMUT.D C Division of Licensing 80/05/22 73pp

0388 Forwards Revision AD of TM1 modified amended physical rity plan Plan withheld (ref 10CFR2 790) EIN.J G Metropolitan Edison Co 80/06/27 ip

0667 Forwards State of PA authorization for open burning to train fighters FIN. J Q Metropolitan Edison Co 80/07/11 2pp

0553 Forwards revised fire protection program plan.replacing flows plan submitted Apr 1977
ElN.J Q Metropolitan Edison Co 80/07/11 ip

220555 Revised fire protection program plan Hatropolitan Edison Co 80/07/11 9pp

O713 Informs that during site/general emergency, NRC personnel manitoring plant evaluations are to rept to ensite NRC ler complex or observation of Accountability will be applished there & results provided INS. J T TMI Program Office 80/07/15 ip

udicatory correspondence

'0094 Urges R Hayhurst to respond to 800429 ltr re alleged 24 Flight 170 over plant Answer needed to avoid issuante ubpoens to compel DLER.L J Hearing Branch 1 BO/06/06 ip

0060 Forwards Director's 800613 decision under 100FR2 206 & ted FR notice denying 790809 petition that Commission are EIS prior to authorizing venting of radioactive on Transfer bldg

ON.H R Office of Nuclear Reactor Regulation, Director 16/13 1p

'140066 Notice of issuance of Director's decision under 100FR2 206 mying Antinuclear Group Representing York 790809 petition set Commission prepare EIS prior to venting of radioactive isses from reactor bidg the set of Nuclear Reactor Regulation, Director 1706/13 tp

/149071 Director's decision under 10CFR2 206 denying Antinuclear top Representing York 790809 petition that Commission sue EIS prior to authorizing venting of radioactive gases tom reactor bldg 18E.EO Office of Nuclear Reactor Regulation, Director 1704/13 5pp

20550 Forwards Federal Republic of Germany energy & environ earth rept. "Radiation Exposure Due To Venting TMI-2...tor Bidg Atmosphere" due to concern re 800612 order for sonary mod of license to vent radioactive metl ER.R Affiliation Unknown 80/Q6/16 lp

7020554 "Radiation Exposure Due To Venting TMI-2 Reactor Bldg lmosphere " Royet, D Germany, Federal Republic of 80/06/12.

B0070B00B6 Proposed findings of fact % conclusions of law responding to ASLAD quostions on Battelie rept Findings are adopted by Thi-A/Peachbottom Intervenors & Ecology Action Urges suspension of Ols Certificate of Byt encl MEPFORD. C Environmental Coalition on Nuclear Power 80/06/18

B007i1007b Final contentions supplementing petition to intervone in UL amend proceeding Alleges inadequacy of RCS pressure Provisions to neutron monitoring instrumentation are insufficient to protect public Certificate of Sive encl SHOLLY, S.C. Affiliation Unknown 80/06/19 7pp

8007080046 Response to ASLAB request re Onficiency 1 Urges leversal of decision rejecting deficiency is correlation between U mine radon releases & amount of U fuel Portion of Porkins decision recorrelation must be vacated CAPLAN,R Ecology Action of Oswego 80/06/20 2pp

8007080048 Proposed findings of fact endorsing Citizens for Safe Environ filing re radiation source torms from U mining & milling Rejects Perkins rationale & urges development of further evidence re failure mechanisms & human factors CAPLAN, R Ecology Action of Oswego 80/04/20 4pp

8007070275 Suppl to 600315 request for hearing re-proposed change to Tech Specs in reply to NRC 600404 response Specifies interest & standing & clarifies aspects of proceeding in which intervention is sought Cartificate of Syr encl JOHNSRUD. J D Environmental Coalition on Nuclear Power 60/06/23

8007070276 Petition to intervene re Commission 800612 memorandum & order Alleges that util is inept at handling nucleor reactor & controlling cuntainment venting
LEHIS.M I Affiliation Unknown 80/06/24 2pp

8007080007 Motion before DC Court of Appuals requesting argument & hearing on panding 800623 & 24 motions for review of 800662 orders to satisfy notice requirement Evidence available Certificate of Svc entl Related correspondence 8HOLLY:8 Affiliation Unknown SMECHAN, D.P. Sheenan, D.P. 80706/24 3pp

B007100240 Requests that NRC cure defects in B00612 memorandom & urder by allowing enough time for litigants to seek administrative remedies before venting NRC should look litto various objections before proceeding whony further action LEWIS.M I Affiliation Unknown 90/06/24 App

8007310243 forwards Commission 800927 memorandum to order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum to order UCS 771104 petition sought action re fire protection for electrical cablus EISENHUT.D G Division of Licensing 80/06/20 89pp

8007020482 Matter to move 800707 prehenting conforming to who of 800728 Licenses arranged 800707 meeting w/petitioners Shally & Lochsted during which simplification or olimination of issues re OL amend may take place fortificate of Svc encl TROMBRIDGE.O f Metropolitan Edison Co. TROMBRIDGE.O f Shaw. Pittman. Potts & Troubridge 800/06/76 4pp

BOO7020621 Response in upposition to Mil Douglas 800624 ltr requesting hearing re Commission 900612 under for temporary mod of () Order reflects careful consideration of record including public comments W/Douglas ltrs % Certificate nP Syc TROMBRIDGE, O F Mutropolitan Edison Co ROMBRIDGE, O F Shaw. Pittman, Potts & Trowbridge 80/06/26 Opp

8007070211 Forwards NRC 800626 order denying intervenors SC Sholly, Paople Against Nuclear Energy & Newberry Township TMI Steering Committee 800623 joint motion for reconsideration of CLI-80-25 SNYDER, D J TMI Program Office 00/06/26

8007020654 Requests for adjudicatory hearing re Cummission 800612 order Amending OL Urges that no redinactive atmosphere vonting be allowed until completion of hearing States interest & suggests B Frankel J Beyork & Leas in witnesses SHOLLY-S , HOSSLER.D E Affiliation Unknown 80706/P7 10pp

8007070337 Motion before UB Court of Appeals for DC. Case 80-1691, requesting on hant rehearing on putitioners' 800623 24 motions: re 30-day prior motice for License amend 8HOLLY, 9 . HOSSLER, D E Affiliation Unknown SHEFHAN, D p Sheenan, D P 80/06/27 2pp

- ---8007070333 Brief in lieu of pleading, in support of petitioners' motion. For en banc rebearing on 800623-24 motions re 800612 orders. Requests that NRC comply w/statutory requirement for 30-day prior notice to license amend effectiveness. SHOLLY.B., NOSSLER, D.E. Affiliation Unknown SHEEHAN.D.P. Sheenan.D.P. 80/06/27 12pp
- --B007070365 Motion to file oversize brief in support of motion for an banc rehearing Court roled on pactitioners' filings w/o hearing argument re right to 30-day pilor notice for license amend

 SMOLLY.S., MOSSLER.D.E. Affiliation Unknown SMEEHAN.D.P.
 Shapman.D.P. B0706/27 2pp
- --8007070371 Hotion requesting espeditions consideration of patition for rehearing Certificate of Svc enci SHOLLV.S , HOSSLER, D E Affiliation Unknown SHEEHAN, D P Sheenan, D P 80708/27 2pp
- B007020523 Order denying licenses motion to reschedule OL amend B00707 prehearing conference Parties may confer & submit proposals to simplify or eliminate issues WOLF, JF Atomic Safety and Licensing Board Panel B0/06/30
- B0070B0002 Hemorandum & order advising that ASLB has received further delegation, per Commission B00612 order, for temporary license moduto rule upon hearing requests & to conduct evidentiary proceedings on ventung issue
 MOLF, J.F. Atomic Safety and Licensing Board Pane; B0/06/30 2pp
- 8007070104 Notices of appearances in OL amend proceeding Certificate of Svc encl GOLDBERO, 6 C . SINGER, L N Hearing Branch 2 CHANDLER, L J Hearing Branch 1 80/07/01 5pp
- 8007280579 Forwards Director's decision under 10CFR2 206 (DD-80-21) damping Antinuciear Oroup Representing York request for EIB & related FR notice SNYDER.D J TM1 Program Office 80/07/02 2pp
- --8007280593 Director's decision under tOCFR2 206 denying Antinuclear Group Representing York 790809 request for EIS prior to venting of radiactive gases from containment bldg Action does not constitute significant environ impact DENTON. BR Office of Nuclear Reactor Regulation, Director, 80/06/13 4pp
- 8007080001 Proposed Findings of fact & conclusions of law in form of memorandum & order affirming ASLD 780714 partial initial decision & advising that radon releases associated w/U fuol tycle are insignificant in striking cost/benofit balance BORDENICK, B M. Hearing Branch 4. 80/07/03. 58pp
- --8007080003 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp
- --8007080006 Motion to include de minimus theory of health effects in NRC 600703 findings of fact & conclusions of law presented in form of mmorrandum & order inclusion is consistent w/ALAB-509. ALAB-562 Cortificate of Svc enci BURDENIC. K Blearing Branch 4 80/07/07 7pp
- B0070B0061 Response in opposition to KL Miller,MH Douglas & partions of SC Sholly & RE Hossier requests for hearing re Commission 800612 orders for temporary mod of AL W/Certificate of Byc & 800620 opposition to matter for injunction in Case 80-1691 CHANDLER,L J Hearing Branch 1 SINGER,L Hearing Branch 2 80/07/03 34pp
- 8007100238 Order granting Ecology Action of Oswego motion to file 800620 submission re generic radon issue 818HOP.C J. Atomic Safety and Lirensing Appeal Panel 80/07/07 2pp
- 8007170337 Response in upposition to SC Shoily 800703 motion for temporary suspension or deferral of containment venting pending hearing AGLB has no jurisdiction to consider issue Urges prompt referral to ASLAB if ASLB declines denial CHANDLER.L J. Hearing Branch & OCLOBERG, B.C. Hearing Branch & 80/07/07 10pp
- --BOD7170359 Affidavit re alleged lack of consideration by NRC of doses due to particulate radiomuclides cesium & strontium No new info presented that would lend to change in FSS conclusions Wibibliographies & Cortificate of Svr CONOELLF J. Assistant Director for Radiation Protection WELLER, R. A. Assistant Director for Fournamental Tachnology 80/07/07 9pp

- 8007280613 Putition & other pleadings before US Court of Appeals for Third Gircuit, seeking declaratory judgment against NRC & stay of 800612 orders authorizing atmospheric venting Certificate of Svc encl Related correspondence SHEEHAN.DP . HAGER.R People Against Nuclear Energy 80/07/08 32ee
- BOO7160591 Advises of considerable progress made during BOO711 meeting W/licenses & petitioners to intervone re advanced contentions Addl BOO818 meetings will be held & ABLB will be informed of contrate results GOLDBERG.
- 8007180411 Forwards NURE9-0557 "Evaluation of Long-Term Post-Accident Core Cooling of TMI-2," per 800711 negotiation session Decument sent to intervenor Sholly under separate cover M/o enc!

 SINGER, L. N. Hearing Branch 2 80/07/15 ip
- 800722000A Memorandum & order setting matters discussed & decisions made during Harrisburg.PA 800707 prehearing conference State of PA participation as interested party granted Decision re standing & acceptability of contentions held in abeyance PARIS.O H. SHON,F J. HOLF.J.F. Atomic Bafety and Licensing Board Panel. 80/07/15. App
- 800731012B Response in support of NRC 800703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issue from consideration Supporting news articles enci CAPLAN, R Ecology Action of Dawega 80/07/16 13pp
- BOO7250353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fact submitted by other parties filed 800718
 Revised pages required to correct typographical errors
 Byc list enci
 TRAVIEBO-DIAZ Shaw. Pittman. Potts & Trowbridge 80/07/21 10pp
- 8007310467 Forwards RB Hayburst 800601 ltr re Johnsrud testimony on behalf of intervenors concerning 800124 US Air Flight 170 Bubstance consistent w/record Formal evidentiary consideration need not be given CHANDLER, L J Hearing Branch 1 90/07/28 1p
- --8007310469 Responds to telcon & 800429 ltr re 800124 US Air Flight 170 Contrary to Lines il & 12 of hearing transcript, author 41d not operate flight in question directly over facility on 800424 HAYHURST, R S Affiliation Unknown 80/06/0; ip
- H Ganaral correspondence
- 8005160109 Responds to 800226 ltr re K Menges concerns about venting radioactive gases from containment bldg Public comments are being solicited on NRC environ assessment & racommendations Krypton gas venting not permitted until final declaion KAMMERER, C Defice of Congressional Affairs 80/04/01 2pp
- 8007240406 Ack receipt of 800401 ltr concerning possible means of disposing of radioactive matl from facility NRC officials will review comments Ltr encl HAMMERSCHMIDT, J House of Rep 80/04/09 3pp
- 8005160225 Responds to 800408 itr rp D Miller concerns about venting krypton gas from containment bldg Controlled venting recommended by NRC environ assessment No venting permitted pending review of public comments & consequent decision KAMMERER. C Dffice of Congressional Affairs 80/04/16 ip
- B005200319 Responds to B00331 ltr re J Piccolo concerns about venting krypton gas from containment bldg Controlled venting rescamended by NRC environ assessment No venting permitted pending review of public comments & consequent decision KAMMERER. C Office of Congressional Affairs. B0/04/16 2pp
- 8005160124 Responds to 800418 ltr re M McGarrity interast in venting krypton from containment bldg No decision has been made to permit venting IF decision favora venting, residents will be given ample notice.

 KAMMERER. C UPPice of Congrussional Affairs 80/04/28, ip
- 8005200357 Responds to 800415 ltr re constituent concern about Kemeny Commission "secret findings" Commission recommendations on facility accident made available to public in 791030 rept to President Carter List of supplementary documents encl KAMMERER, C Office of Congressional Affairs 80/04/28 2pp

- SOC5200454 Responds to 800414 ltr re D Hossler comments on environ assessment of venting radioactive gas from containment bldg Comment will be considered prior to any Commission decision on venting MAMMERER, C Office of Congressional Affairs 80/04/29 ip
- 8007030372 Confirms telcon re US Air Flight 170 on 800124 Forwards **Renscript eicerpt re J Johnsrud testimony about experience on #1ight into Harrisburg Intl Airport CHANDLER.L J Hearing Branch 1 80/04/29 4pp
- BOO507051Q Requests repts by PA Medical Society & Natl Cancer Instine impact of venting on public health & safety, discussed during BOO424 meeting in Lebanon. BA MECKLING, M. Affiliation Unknown 80/04/30 ip
- BOG6120212 Responds to 800498 1tr re constituent inquiry about fatility NRC & EPA are monitoring plant releases Results of EPA aonitoring made public twice weekly via local media NRC flotdetown ofc selected to facilitate public needs XAMMERER, C Office of Congressional Affairs 80/00/05 28 80/05/05 2ep
- BOO-6120437 Responds to BOO428 ltr re constituents concerns about vehting radioactive gases from containment bldg NRC 800312 environ assessment recommended that venting be permitted Vinting not permitted pending final decision XAMMERER, C Office of Congressional Affairs 80/05/05 2pp
- BOO6120484 Responds to 800416 ltr re AS Howard ltr urging that cleanup activities & Kr-B5 venting be conducted as repidly as possible Decision on proposed venting will be made in near future MARMERER, C Diffice of Congressional Affairs 80/05/05 1p
- BOO723010B Responds to 800321 questions re possible financial failure of util. Financial failure provides grounds for immediate revocation of license Contingency plans under development HRC will ensure protection of public health AHEARNE. J F. Commission BO/OD/O7 2pp
- 8007180463 Responds to 1tr postmarked 800324 re nuclear power plants NRC has found that actions to improve safety, plant design & siting & health effects are necessary & feasible Plants found to be unsafe will not be allowed to operate DENTON.H R Office of Nuclear Reactor Regulation, Director lp.
- 8007180468 Responds to 1tr postmarked 800327 re waste products of nuclear power plants Presidential 800212 message to Congress re redwaste egt program encl DENTON, RR Office of Nuclear Reactor Regulation, Director 80/05/08 6pp.
- BOO7180067 Responds to encl 800306 ltr to President Carter re nuclear power plants Presidential 791207 statement on Kemeny Cosmission rept on TMI-2 & excerpts from NUREQ-0662 & NUREQ-0709 encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/12 16pp
- 8007180474 Responds to 790816 itr to J Hendrie re nuclear power plants & disposal of radwaste Commissioners have approved licenses for three nuclear plants to load fuel & begin low power levels for testing Presidential 800212 message entl OCHTON.H R Office of Nuclear Reactor Regulation. Director 80/05/12 App
- --B007180478 Urges govt financing of research projects to resolve nuclear waste disposal, generate synthetic fuels & nuclear fuelon WHATLEY, H E Chamtron Corp 79/08/16 2pp
- 800718D492 Responds to encl 800323 ltr to President Carter re processions to prevent another nuclear accident such as TMI— 2 Efforts made to ensure public health & safety at all nuclear plants. Unsafe plants will not be allowed to operate DENTON.H R. Office of Nuclear Reactor Regulation, Director BO/05/12 3pp
- 9006120501 Discusses status of venting krypton from containment bldg in response to 800416 ltr re A Donley concerns Public comments are being solicited on environ assessment Krypton gas venting not permitted pending final decision KAMMERER, C. Office of Congressional Affairs 80/05/14 lp.
- B007180182 Responds to B00327 ltr to President Carter re nuclear power plants & nuclear wastes Carter B00212 message to Congress & 791207 stetament on Kemeny Commission rept encl DENTON HR Office of Nuclear Reactor Regulation, Director, B0/03/14. 11pp

- 8007160731 Responds to 800317 ltr to President Carter re 800309 editorial in San Diego Which newspaper Forwards excerpt on nuclear power from "Second Natl Energy Plan." & 791207 statement by President on Kemeny Commission Rept on TMI DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/15 12pp
- B007210046 Responds to 790316 ltr re nuclear accidents before THI NUREG-0572 & excerpts from 'Past Accidents in Nuclear Reactor Facilities & Nuclear Power Plant Airborne Radioactivity Releases." & "Procursor Events THI." encl DENTON.H R Office of Nuclear Reactor Regulation. Director Ээрр
- --8007210047 Requests info re nuclear accidents defore TMI incident MDRRISON, J R Affiliation Unknown 79/05/16 ip
- 8007250063 Responds to BOO213 ltr re effects of radiation on children Allowable radiation doses have been evaluated for all age groups Acceptable radiation dose stds allow for special sensitivity of young children MULLER, D R Assistant Director for Environmental Technology BO/05/13 2pp
- 8007180546 Responds to 800129 itr to President Carter re licensing nuclear power plants TM1 accident created need for changes in approach to safety Due to need for power NRC has granted licenses for three units to begin low level power testing DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/19 3pp
- 8007180553 Responds to 790402 ltr to President Carter re nuclear power plants Addi containment structure as suggested not considered necessary or feasible State of PA Emergency Mgt Agency pamphlet on radiation incidents enci DENTON, M R Office of Nuclear Reactor Regulation, Director BOADS-LIB.
- 8007210208 Responds to encl 800418 ltr to President Carter re Indian Point facility Describes NRC offents to protect public health at facilities currently operating or planned for operation Village Voice news article encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/21 10pp
- 8007020059 Responds to 790410 ltr to President Carter re safety of nuclear plants Plants designed to provent accidents through presence of protective sys.engineered safety features & safety evaluations of site suitabality D Lawe ltr encl DENTON.H R Office of Nuclear Reactor Regulation. Director 80/05/27 Gpp
- B007020455 Urges NRC approval of venting at TMI WILD: A A Affiliation Uninown 80/06/04 1;
- 8007010246 Ack receipt of Westmoreland County Board of Supervisors' 800514 resolution No new multer plants will be licensed until improved safety criteria developed Certain plants allowed to operate for testing Winnel DENTON, H R Office of Nuclear Reactor Regulation, Director 80/04/06 10pp
- 8007020657 Buggests venting of krypton gas into helium balloon SONNEBORN, M.R. Affiliation Unknown 80/04/06 Ip
- 8007020677 Ack receipt of Lancaster County Board of Supervisors 800429 resolution Forwards President Carter 800212 message to Congress re establishment of comprehensive radioactive waste mpt program

 DENTON H R Office of Nuclear Reactor Regulation, Director Врр 80/06/06
- 80071104B3 Discusses NRC post-TMT actions to safety at nuclear power plants in response to encl Richmond County, VA Board of Supervisors 800508 resolution supporting use of nuclear power President Carter 800212 message and DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/06 9pp
- 8007170548 Responds to encl 800417 ltr to President Carter re nuclear power plants Every effort is being made to ensure public health & safety at all nuclear facilities White House press release & excerpt from NUREG/CR-0130-Vol 1 encl
 DENTON H R Office of Nuclear Reactor Regulation, Director DENTON, H R OF 80/06/06. 22pp
- 8007210530 Forwards President Carter's statement on Kemeny Commission rept on TMI-2 & Chapter 5 from Second natl energy plan per 800421 request for into on nuclear power DENTON, H.R. Office of Nuclear Reactor Regulation, Director 80/06/06 19pp

- B007020229 Responds to B00409 ltr reidi Hocker concern about health & financial custs associated w/facility accident & cleanup Utilinut federal govt is responsible for cleanup costs Portion of costs cuvered by util insurance policy DIRCRS.W.J. Office of the Esecutive Director for Operations 80/06/09 2pp
- --8007020237 Requests response to encl HM Hocker 800402 re financial costs associated w/facility accident & cleanup GBDDLING.W House of Rep 80/04/09 4pp
- B007110346 Ack receipt of 800329 ltr expressing concern about proposed facility purging Decision on how to best remove Kr-85 contained in reactor bidg not reached Review of mechanism for selecting panelists for advisory panel underway AMEARNE.J F Commission 80/06/09 5pp
- B007170551 Responds to encl 900418 ltr to President Carter re nuclear power plants Every effort is being made to ensure public health & safety at all nuclear power plants White House press release & excerpt from NURCO/CR-0660 encl DENTON, H R Office of Nuclear Reactor Regulation, Director B0/06/09 7pp
- 8007100456 Responds to 800521 ltr suggesting means of improving nuclear power plant safety Accident at TMI was result of operators overriding automatic actions rather than allowing too much MATTSON, R J Division of Safety Technology 80/06/11 3pp
- 800714023B FOIA request for info is release of kryptom gas into atmosphere from facility TROMESTAR AFfiliation Unknown 80/06/12 2pp
- B00701050B Requests that NRC re-evaluate decision to release Kr-B5 gases from Facility when alternative for storage & isolation from environ is available WASSERBACK.A C New York Federation for Safe Energy 80/06/13
- 8007080226 Expresses concern re venting of krypton gas into environ Discusses health hazards of noble gases & magnitude of release DREY.K Affiliation Unknown 80/06/15 4pp
- 8007290047 Forwards Commissioner biographies in response to 790426 JULY/2004/ I DEWARD LOMDISSIONER BLOGRAPHIES IN RESPONSE to 75 request for info on background of Commission No info developed to indicate that sabbtage contributed to intiation of accident or in subsequent response DEMYON, HR Diffice of Nuclear Reactor Regulation, Director 80/06/17 dpp
- -8007290051 Forwards analysis of possible subotage involved in TMI-2 accident Also requosts info on professional background of NRC staff SDXMAN.K A Affillation (Inknown 79/04/26 7pp
- 8007100145 Responds to 800313 itr re radiation effects on mutation rate & problem of radwoste storage less than one mutation expected to result from effect to f TMI radiation to public compared w/60-970 from natural radiation sources DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/18 1p
- 8007290064 Responds to 800527 Its re THI-2 accident & precautions to prevent such accidents NRC action plan developed to provide comprehensive basis for actions necessary to correct or improve regulation Chapter 7 from NRC 1979 Annual Rept encl DENTON. H R Office of Nuclear Reactor Regulation, Director 80/06/18 23pp
- --B007290D67 Requests info on TMI-2 atcident & NRC precautions taken to prevent such accidents Every individual has right to know who is looking out for American interests & how well HENRY.L. Affiliation Unknown 80/05/22 ip
- 8007070151 Responds to 80051R request for info on availability of repts Kemeny Commission Rept may be purchased from OPO W/o encl repts in security & sabotage SNYDER, B J TMI Program Dffice 80/06/17 ip
- --80070/0162 Requests price & availability of repts on TMI sabotage event analyses, pre & post-accident security status at TMI & Remony Commission Rept ROBERTS, N J Affiliation Unknown B0/05/12 ip
- 8007230684 Forwards General Assembly of State of PA 800429 House Resolution 185 Organ rapid formulation by NRC of criteria which will be used as guidelines for decontamination of facility Certificate of Nev encl
 MEBUS.C F Penn-glvania. State of 80/06/19 App

- 8006300220 Add1 response to FOIA request for written communications between NRC & Congress since 800322 concerning facility Forwards documents in App A FELTON.J H Division of Rules and Records 80/06/20 3pp
- --8007)00438 Ack receipt of 800422 ltr forwarding D Griffith correspondence No decision made re venting of containment KAMMERER, C Office of Congressional Affairs 80/05/05 ip
- 8007010304 Forwards 790720 order for license mod, NUREG-0600, NUREG-0578 & NUREG-0585, in response to 800619 tolcon re QL amend proceeding W/o encls CHANDLER, L J Hearing Branch 1 80/06/23 1p
- 8007020091 Responds to 800416 ltr re H Doniey request for info about 800320 release of radioactive gases Air-exhaust duct effiuent monitors did not detect radioactive matls above normal plant release rates
 DIRCKS,W J Defice of the Executive Director for Operations
 80/06/23 1p
- B007020653 Opposes krypton gas venting Newspaper article encl KIENLE,D , KIENLE,K M , MCCARTNEY,R M Affiliation Unknown B0/06/23 1p
- 80072B0129 Responds to 800615 ltr Decision to purge 57,000 Ci krypton gas from containment bldg was traumatic for all Forwards final EIA & Commission memorandum & order for better understanding of how & why decision was made W/o encl INGRAM.F L Office of Public Affairs 80/06/23 ip
- ---8007280i36 Requests decision to purge krypton gas be reconsidered Policy reflects lack of responsibility MOODY,C J Affiliation Unknown 80/06/i3 3pp
- B007140619 Addl FOIA request for all written communications between NRC & Congress since B00322 concerning facility FiDELL.E R LeBoguf, Lamb, Leiby & MacRae B0/06/24 2pp
- 8007290096 Discusses human factors engineering issues associated w/ accident Offers svcs to NRC w/assurance that firm will provide key insight into conduct & application of post-TMI human factors research MAURG,C L Affiliation Unknown 80/06/25 2pp
- 8007i60i45 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMI-2 accident NRC benefitted from excellent communication capabilities of agency Certificate of appreciation enci W/o encl WEISB, B H Office of Inspection & Enforcement, Defice of the Director 80/06/26 ip
- 8007160155 Expresses appreciation to Boise Interagency fire Ctr for assistance during IMI-2 accident NRC benefitted from excellent communication capabilities of agency Certificate of appreciation encl W/o encl MEISS.B H Diffice of Inspection & Enforcement. Office of the Director 80/06/24 ip
- 8007160160 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMI-2 accident NRC benefited from excellent communication capabilities of agency Certificate of appreciation encl W/o encl WEIBB.B H Dffire of Inspection & Enforcement, Office of the Director 80/06/26 |p
- 8007160167 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMT-2 accident NRC benefitted from excellent communication capabilities of agency Certificate of appreciation encl W/o encl WEISB.8 H Office of Inspection & Enforcement, Office of the Director 80/06/26 ip
- B007140170 Expresses appreciation to Boise Interagency Fire Ctr for assistance during IMI-2 accident NRC benefitted from excellent communication capabilities of agency. Certificate of appreciation encl W/o encl
 WEISB.B H Office of Inspection & Enforcement, Office of the Director B0/06/26 ip
- B007160183 Expresses appreciation for assistance during TMI-2 accident NRC benefitted from execllent communication capabilities of agency Contificate of appreciation encl W/p encl. WEISS-B H Dffice of Inspection & Enforcement, Office of the Director 80/06/26 ip

- B007180237 Forwards Section B 0 & draft Addendum 2 to NUREQ-0662 rodecontamination of TM1-2 reactor bldg atmosphere NRC will use real-time environ & meteorological data during purging W/o encl
 SNYDER, B J TMI Program Office B0/06/26 1p
- --8007180250 Requests copy of Addendum 2 to NUREO-0662 re decontamination of TMI-2 reactor bldg atmoshpere Inquires whether actual site monitoring was done downwind of Kr-85 releases MASSERBACH.A E Affiliation Unknown 80/05/22 lp
- B007230225 Responds to B00508 ltr to President Carter re reliability of const of nuclear power plants Purpose of NRC insp program is to assure adequate QA Forwards excerpts from NRC 1979 annual rept & Becond Natl Energy Plan DENTON, HR Office of Nuclear Reactor Regulation, Director B0/06/26 2pp
- 8007230626 Responds to 790405 request for info re nuclear energy Due to TMI incident NRC decided not to license new plants until improved safety criteria had been developed Excerpt re production of nuclear energy encl DENTON; HR Office of Nuclear Reactor Regulation, Director 80706/26 10pp
- --8007230630 Requests info re nuclear energy & process by which energy is produced CDLT:S Affiliation Unknown 79/04/05 lp
- B007280122 Forwards President Carter statement on Remeny rept.in response to encl B00512 ltr to President Carter re safety of nuclear power plants DENTON.H R Office of Nuclear Reactor Regulation, Director B0/06/26 Spp
- 8007270054 Responds to 800512 ltr to President re status of nuclear power plants President 791207 statement on Remany Commission rept on TMI enci Action plan developed to provide comprehensive & integrated basis for future actions DENTON.HR Office of Nuclear Reactor Regulation, Director 80/06/24 4pp
- 8007300013 Responds to 790405 ltr re nuclear power State of IL has saven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kenny Commission Rept and DENTON, H R Office of Nuclear Reactor Regulation. Director 80/06/26 28pp
- B007250070 Responds to entl 800504 ltr to President Carter re nuclear energy Use of both coal & nuclear power necessary to Free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENTON.HR Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- BO072300B1 Responds to 790420 request for info re nuclear energy Rediation doses from power plants is small fraction of dose from makunal environ sources FEB excerpt & White House BO0212 message to Congress encl UENTON.H R Office of Nuclear Reactor Regulation, Director B0706/27 18pp
- 8007140516 Appeals denial of FOIA request for info concorning venting of krypton gas from facility
 TROMBETTA,R Affiliation Unknown 80/06/30 lp
- 8007140383 Responds to 800403 invoice & forwards insp fees for persod of Mar 1979 to Mar 1980 per 1007R170 W/o encl HERBEIN, J Q Metropolitan Edison Co 80/07/02 2pp
- 8007140616 Responds to FOIA request for written communications between NRC & Congress since 800022 concerning facility Forwards items listed in Documents i & 2 of App A in NRC 800616 ltr & updated App A w/explanatury notes FELTON, J M Division of Rules and Records 80/07/02 9ap
- ---8007140525 Determines that EJ Sternglass 800125 paper, "Infant Mortality Changes Following TMI Accident." is w/o scientific merit Gites examples of data manipulation Questions refacility encl QDLDBMITH.R Radiological Health Standards Branch 80/04/29.
- ~~8007140529, "Analysis of Infant Mortality Following TNI Accident "PA Dept of Health 800402 press release encl OOLDSMITH, R Radiological Health Standards Branch B0/04/29

- 8007180107 Forwards microfiche copy of "Logbook of Radiological Data." in response to request W/o encl SNYDER.D J THI Program Dffice 80/07/02 ip
- --8007180:10 Ack receipt of "Logbook on Radiological Data"
 Reproduction on many pages is poor Requests microfiche copy
 BARLEY.S R Affiliation Unknown 90/03/02 1p
- B007140233 Responds to FGIA request for info re release of krypton gas into atmosphere from facility Forwards documents listed in App A W/o encls FELTONJ M Division of Rules and Records B0/07/03 2pp
- 6007280182 Responds to 600509 ltr expressing concern because no notice to airmen was issued in conjunction w/release of Kr-85 on 800423 Assuming poor meteorological conditions, totalbody exposure would have been 0 008 millirem DENTON, H R Office of Nuclear Reactor Regulation, Director 800070707 jp
- --8007280188 Forwards FR Romano B00509)tr re venting Kr-85 from reactor containment bldg SNYDER, C L. Region J. Philadelphia. Office of the Director B0/05/14 | Ip
- ~~8007280195 Expresses concern because no notice was issued to pilots or passengers prior to entering Harrisburg airport area notifying of danger of concentrated krypton gas ROMANG.P R Affiliation Unknown 80/05/09 2pp
- 8007210121 Responds to 790709 ltr to NRC re concerns about facility & actions being taken by Concerned Citizens of Londonderry NRC has ordered public bearing to determine whether Unit 1 should be operated Unit 2 feasibility studies are underway BNYDER.D J TMI Program Office 80/0//09 2pp
- --B007210131 Expresses oppreciation for 790629 visit to Middletown.PA Concerned Citizens of Londonderry,who have collected 750 signatures, are dedicated to closing facility NRC status repts would be of great benefit to area residents BTREET,P A Affiliation Unknown 79/07/09 2pp
- 8007220920 Responds to 800401 ltr to President Carter expressing concerns over financial impact as stockholder w/licensee RRC is concerned w/economic impact Responsibility is limited to public health & safety REID.R W Operating Reactors Branch 4 80/07/09 2pp
- 8007230286 Responds to encl 800508 ltr to President Carter expressing concern about TMI-2 cleanup process & surge of Kr-85 in reactor blog Onsite NRC team is monitoring cleanup effort NUREQ-0673 & NUREQ-0662, Vol 1, encl W/o encls DENTON, H R Office of Nuclear Reactor Regulation, Director BO/07/09 5pp
- 8007230293 Responds to encl It's to US Public Health Svc & DDE re research project on nuclear power plants in May 1977 NRC adopted resident insp program Na water leak was implicated in initiating accident at TMI-2 reactor SNYDER, B J TMI Program Uffice 80/07/09 App
- 8007230278 Responds to 790514 lit to FRDA to info about TMI-2 accident Plant was never in danger of blowing up because no oxygen could have accumulated in hydrogun bunble under existing conditions Accident caused by human & mechanical errors BNYDER:B J TMX Program LPF1co 80/07/09 App
- B007230311 Responds to encl 790428 Itr to President Carter re TMI~2 accident Util customers will not have to pay for any damages or for restoration of facility Customers will however, pay costs associated Mypurchasing replacement power BNYDER.B J TMI Program Office 80/07/09 App
- 8007270032 Responds to 800430 ltr to HR Denton requesting two medical records NUREO-0262. "Final Environ Assessment for Decontamination of TMI-2 Reactor Bidg Atmosphere." "Low Level Radiation" & PA Medical Society rept encl W/o encl SNYDER.D J TMI Program Office 80/07/09 2pp
- 8007300006 Responds to ltr is accident at IMI-2 Public hearings will be conducted to determine whether Unit 1 should be operated by under what conditions Licensee has not submitted proposal for overall plant recovery for Unit 2 SNYDER.D J TMI Program Office 80/07/09 2pp
- B007140511 Responds to appeal re-denial of FOIA request for info reventing of Arypton gas from facility NRC completed action on initial request by providing documents subj to request on B00703 No further action will be taken FELTON J N Division of Rules and Records B0/07/10 ip

- 8007;70362 Comments on 800609 review of "Nethod for Calculating Doses to Population from Xe-137 Releases During TMT Accident "Derivation values & accuracy of calculations discussed FAIROBENT.J E Affiliation Unknown 80/07/10 3pp
- 8007230569 Responds to 790403 ltr to President Carter re nuclear power Forwards President Carter 791207 statement on Kemeny Commission rept on THI & excerpt from NRC 1979 annual rept re developmental of radiological energency plans Ltr encl DENTON.H R Office of Nuclear Reactor Regulation, Director 807/07/10 10pp
- B007250167 Responds to B00509 ltr re JB Hurst comments & questions about reactor bldg decontamination Hurst comments were considered in preparation or final environ assessment Hurst B00411 ltr to NRC entl B1RCHS.H J Office of the Executive Director for Operations B0/07/10 lp
- --B007250174 Comments on environ assessment of reactor bldg
 decontamination health impacts should be determined by
 objective.independent data collected & analyzed over
 substantial period of time Related news article encl
 HURST.J B Affiliation Uninown 60/04/11 App
- BOO7250190 Responds to BOO514 ltr re D Mattson concerns about encl article in Paxton Herald on problems affecting farm animals near facility Issue under investigation Field studies completed & data being evaluated Rept to be issued soon KAMMERER, C Office of Congressional Affairs 80/07/10 7pp
- BOO7210481 Questions why BOO41) telegram does not appear in NUREQ-0662, Vol 2, environ assessment le venting of krypton gas at facility CHONG.L.R Affiliation Unknown BO/07/14 ip
- 8007250062 Provides info on facility incident, in response to 800623 itr re E Dobson inquiry Includes containment design strength & typical containment design pressure DIRCKS.W J Office of the Ciecutive Director for Operations 80/07/15 2pp
- --8007250067 Requests response to E Dobson inquiry about facility incident BAUCUS:M Senate 80/06/23 1p
- 8007230727 Ack receipt of 800623 ltr offering to help resolve some of human factors engineering issues raised by accident NRC has organized new Div of Human Factors Safety to address precisely these issues
 BUDNITZER J Office of Nucleor Regulatory Research, Director 80/07/16 jp
- 8007300010 Responds to 900521 ltr re 800324 newspaper article on release of Kr-BJ gas from reactor bldg Purging of atmosphere considered to be safest & most expeditious way of offecting decontamination
 8HYDER.B J TMI Program Office 80/07/16 2pp
- --8007300012 Requests info re encl 800324 newspaper article on release of Kr-85 gas from reactor bldg MARSHALLE N York. PA 80/05/21 2pp
- 8007280105 Ack receipt of B00504 ltr re purging TM1-2 containment atmidsphere Forwards NUREG-0573 W/o entl DENTON.H R Office of Nuclear Reactor Regulation, Director B0/07/18 1p
- --B007280116 Requests booklet re qualities of krypton gas & six copies of NUREQ-0573 HUBER, J.E. Lancaster County, PA B0/05/04 19
- 8007300369 Advises that Director's decision re request that E18 be prepared prior to authorizing venting of radioactive gases from reactor bldg is final NRC action in proceeding Commission has taken no action for review or to extend time CHILK.S J. Office of the Secretary of the Commission 80/07/24

I Financial information

8007150730 Confirms 800626 telon & forwards graph illustrating market price of General Public Utils Gorp common stock for period Jan 1979 to mid-June 1980 HOMSON.T G General Public Utilities - GPU Service Corp 80/06/26

- J Insurance & indemnity information
- BOO71100il FDIA request for all indomnity agreements insurance policies & associated info between util NRC &/or AEC refacility MEARNEY.R W Affiliation Unknown 80/05/29 2pp
- BOO7110009 Responds to FOIA request for all indemnity agreements, insurance policies & associated info between util NRC &/or AEC re facility Forwards documents listed in App A FELTON J M Division of Rules and Records BO/06/23 7pp
- --B007110017 Confirms that NELIA has bound Insurance Policy NF-220 at iimit of one million doilars issued to Net Ed. JCP&L & PEPCO covering facility Includes policy site description GUATTRUCCHI. J Nuclear Energy Liability Insurance Association 77/12/06
- --8007i10032 Executed Amend 6 to Indomnity Agreement B-64, changing iicense numbers SALTMAN.J Antitrust & Indomnity Group HERBEIN.J G Metropolitan Edison Co 80/02/24 lp
- ---B007110037 Amend B to Indemnity Agreement B-64, changing amount of financial protection SALTZMAN, J Antitrust & Indemnity Group 79/05/01 2pp
- --B007il0040 Executed Amend 9 to Indemnity Agreement E-64, modifying prefatory language of Paragraph 5. Article i, re course of transportation NELIA Policy (facility form) encl SALTZMAN, J. Antitrust & Indemnity Group HERBEIN. J. Q. Metropolitan Edison Co. 80/01/03 5pp
- --8007110046 Endorsement 2 to NELIA Policy NF-220 designating annual premium Declaration encl
 * Nuclear Energy Liability Insurance Association 79/01/12 2pp
- --8007110051 Amend to Condition 4 endorsement to NELIA Policy NF-220, Constitutes Endorsement 2 HARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 ip
- --B007110052 Amend to NELIA Policy NF-220 Constitutes Endorsement 4 MARRONE.J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- --8007110057 Amend to industry credit rating plan premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 5 MARRONE.J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- --8007110060 Endorsement 6.waiver of defenses endorsement (ENG), to NELIA Policy NF-220 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- --8007110062 Endorsement 7 to supplementary endorsement waiver of defenses for reactor const to NELIA Policy NF-220 MARRONE. J Nuclear Energy Liability Insurance Association 73/12/14 lp
- --8007110072 Amend to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 7 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 bp
- --B0071i0077 Endorsement 10 to advance premium & std prsmium endorsement, w/changes in subscribing companies & proportionate liability endorsement to NELIA Policy NF-220 MARRONE, J Nuclear Energy Liability Insurance Association 73/11/01 ip
- --8007110084 Endorsement ii.assignment of interest in return premium & in reserve premium refund to NELIA Policy NF-220 MARRONE, J Nuclear Energy Liability Insurance Association 74/07/13 2pp
- --8007i10089 Amend to Condition 4 endorsement to NELIA Pulicy NF-220 Constitutes Endorsement i2 MARRONE, J Nuclear Energy Liability Insurance Association 74/01/13 ip

- ----B007110091 Amend to Endorsement 10, advance premium & std premium andorsement of NELIA Policy NF-220 Constitutes Endorsement 13 HARRONE, J Nuclear Energy Liability Insurance Association 74/02/15 ip
- --B007i10095 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 14 MARRONE. J Nuclear Energy Liability Insurance Association MARRONE, J N 74/03/15 1p
- --- B00711009B Endorsement 15 to NELIA Policy NF-220.increasing liability limits
 HARRONE.J Nuclear Energy Liability Insurance Association
 74/04/26 ip
- --8007110103 Amend to Endorsement 13 to advance premium & std premium andersement of NELIA Policy NF-220 Constitutes Endorsement 14 16 MARRONE, J Nuclear Energy Liability Insurance Association 74/04/26 ip
- ---B007110107 Amend of std premium endorsement w/changes in subscribing companies & proportionate liability endorsement Constitutes Endorsement 19 BARDES,C R Nuclear Energy Liability Insurance Association 74/12/12 ip
- --BO07110125 Amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 19 BARDES, CR Nuclear Energy Liability Insurance Association 73/O//O1 1p
- 8007110128 Endpresement 20 to NELIA Policy NF-220, increasing limit of liability endorsement BARDEB,C R Nuclear Energy Liability Insurance Association 73/03/21 ip
- ---B007i10i32 Amend to Endorsement 18 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 21 BARDES/C.R Nuclear Energy Liability Insurance Association 75/03/21 ip
- ---8007110135 Amend to Endorsement 17 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement ez BARDES.C R Nuclear Energy Liability Insurance Association 75/04/22 ip
- ---8007ii0140 Endorsement 23 to advance premium & std premium endorsement to NELIA Policy NF-220 w/changes in subscribing companies & proportionate liability endorsement BARDEB.C R Nuclear Energy Liability Insurance Association 73/12/01 lp
- --8007110143 Amend to Endorsement 23 to advance premium & std premium andorsement of NELIA Policy NF-220 Constitutes Endorsement 24. BARDES, C. R. Nuclear Energy Liability Insurance Association 76/07/09 ip
- --8007110147 Amend to Condition 2, insp & suspension, to NELIA Policy NF-220. Constitutes Endorsement 26 BARDES, C. R. Nuclear Energy Liability Insurance Association 76/12/15 ip.
- ---8007110151 Endorsement 27 to waiver of defenses endorsement (ENO) to NELIA Policy NF--220 Constitutes Endorsement 27 BARDEB, C. R. Nuclear Energy Liability Insurance Association 74/12/15 2pp.
- --BO07i10154 Amend to definition of nuclear energy hazard to NELIA Policy NF-220 Constitutes Endonsement 28 BARDEB.C.R. Nuclear Energy Liability Insurance Association 76/12/15 ip
- --8007110160 Endorsement 27 to advance premium & std premium endorsement to NELIA Policy NF-220.

 EARDES, C R Nuclear Energy Liability Insurence Association 76/12/31. 2pp
- ~~8007110167 Amend to Condition 4 & emend in 1977 subscribing companies & proportionate liabililty endorsement to NELIA Policy NF-ERO Constitutes Endorsement 30. SARDEG, C.R. Nuclear Energy Liability Insurance Association 77/01/31 Zpp.

- --B007i10i73 Endorsement 3i to NELIA Policy NF-220 increasing limit of liability endorsement

 * Nuclear Energy Liability Insurance Association 77/05/06 ip
- --8007110176 Ampnd to Endorsement 29 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 32 SARDES,C R Nuclear Energy Liability Insurance Association 77/05/06 10
- --8007110178 Amend to Endorsement 32 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 33 BARDES,C R Nuclear Energy Liability Insurance Association 77/08/17 ip
- --B007110201 Amend to Endorsement 34 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 35 BARDES,C R Nuclear Energy Liability Insurance Association 78/03/04 in
- --800711020B Amend to advance premium & std premium endorsement & amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 36 BARDES.CR Nuclear Energy Liability Insurance Association 79/01/03 ip
- --8007110212 Amend to Endorsement 35 of advence premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 37 37
 BARDES, C. R. Nucleer Energy Liability Insurance Association
 79/01/16 ip
- --8007110217 Endorsement 38 to NELIA Policy NF-2PO, w/changes in subscribing companies & proportionate liability endorsement BARDEB.C R Nuclear Energy Liability Insurance Association 79/01/20 ip
- --B007ii0222 Amend to Insuring Agreement 3 to NELIA Policy NF-220 Constitutes Endorsement i MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 ip
- --8007i10224 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 3 MARRONE.J. Nuclear Energy Liability Insurance Association 73/12/14 p
- 8007110043 Endorsement 1 to NELIA Policy EB-65
 * Nuclear Energy Liability Insurance Association 78/07/18, 1p
- 8007180404 Responds to 800613 request for addi info re compliance w/financial protection provisions of Atomic Energy Act Forwards proposed Endorsements 43 & 44 to NELIA Policy HERBEIN. J O Metropolitan Edison Co 80/07/14 App
- B007220584 Responds to NRC 800613 ltr re compliance w/financial protection requirements Proposed endurament provides max protection available from private sources Restoration of limit of liability enforsement encl HERBEIN.J 0 Metropolitan Edison Co 80/07/i4 7pp
- P Operating license stage documents & correspondence
- 8007170083 Reports measured tritium concentrations above background levels in groundwater monituring wells around TMI-2 reactor containment bldg DENTON.HR Office of Nuclear Reactor Regulation, Director SECY-80-181 80/04/08 Opp
- 8007170309 Requests timely review & response to British Nuclear Installations Inspectorate Dec 1979 request for info re TMI-2 reactor pressurizer water level instrumentation LAFLEUR, J D Office of International Programs, Director, 80/04/28
- 8006090165 Forwards addl THI-2 related requirements to operating reactors Licensees requirements for THI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Responso requested within 30 days EIBENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8005190626 Responds to 800421 request for comments on "Environ Assessment for Decontamination of THI-2 Reactor Bldg Atmosphere," Kryptun gas should be vented into atmosphere on controlled basis w/sufficient advance notice to public APPLEYARD, M H. Harrisburg Hosp Harrisburg, PA 80/05/13 lp

- BOOA130122 Requests comments un NUREG-0577. Potential for Low Fracture Toughness & Lamellar Tearing on PWR Stvam Generator & Reactor Collant Pump Supports "Proposed review procedure & implementation schedule enci EISENHUT.D G Division of Licensing 80/05/19 /2pp
- 1007110505 FOIA request for 790401-800530 documents re-boron water maintaining subtritticality of Facility core & processing & storage of boron water referred to in otil 800130-0228 documents
 PARSONS. R Friends of the Earth 80/05/30 ip
- B007180004 Discusses approval of release of Kr-85 from teactor bldg atmosphere by controlled purging Recommends authorization for controlled aurging Draft negative declaration re purging & pross release encl DENTON.H R Office of Nuclear Reactor Regulation. Director SECY-80-132E 80/05/30 lipp
- --8007180007 "Final Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere," final NRC rept Errata sheet enci b TMI Program Office NURFC-0662 VI 80/05/31 104pp Available at NTIS
- --BOO7180012 Correction notice to SE(Y-BO-132C, adding Table 1 re components presently being used # Office of the Secretary of the Commission SECY-80-132C BO/05/19 3pp
- B007010547 Responds to B00429 ltr expressing concern re proposed Kr-85 venting at TMI Method of Kr-85 removal not decided Forwards NUREO-0662. "Final Environ Assessment for Decontamination of TMI Unit 2 Reactor Didg Atmos
- ---8007010555 Requests plans to vent hypton be suspended until UCS study completed
 REED.S R Pennsylvania. State of 80/03/29 2pp
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in docay heat removal capability in all modes of operation Hodel Yech Specs which would provide acceptable resolution encl for guidance EISTMUT.D G Division of licensing B0/06/11 62pp
- 8007190042 "Radiation Exposure Due to Venting THI~2 Reactor Dldg Atmosphere " FRANKE, B. TEUFEL, D. Institute for Energy & Environmental Research Heidelberg, W. Oermany 80/06/12 23pp
- BO07140413 Submits info detailing leak testing operation plans, per 800529 toleon Test to be performed 800705-15 & 0725-0804, pending PaDEK approval RLINGAMAN, R M Metropolitan Edison Co 80/06/16 2pp
- B007010290 Forwards comments on rept by Inst for Energy & Environ Research, Heidelberg, Federal Republic of Germany Major conclusions are based on highly inflated estimates of radionuclide releases Supports NURFG-0662 data SNYDER, B J TMI Program Office KREGER, U E Assistant Director for Hadiation Protection B0/06/23 Spp
- 8007020399 Forwards response to United Kingdom Nuclear Installations Inspectorate request for technical info on reactor grassurizor water level instrumentation DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/24 8pp
- BO07110272 Forwards Amend 11 to License DPR-73, safety evaluation & notice of issuance & availability BNYUER, B J Thi Program Office B0/06/24 4pp
- --BO071102B0 Amend 11 to License DPR-73, permitting hypass of interlocks from reactor hidg exhaust monitors to dampers while purging to reactor hidg atmosphero SNYDERA B J TMI Program Office B0/06/24 3pp
- --8007110286 Safety evaluation supporting Amend 11 to License DPR-73 # Office of Nurlear Reactor Regulation, Director 80/06/24 4p
- --80071(0292 Notice of issuance & availability of Amend II to License DPR-73 SNYDER.B J TMI Program Office 80/06/24 2pp
- B007170089 Comments on B01612 rept. "Radiation Exposure Due to Venting TMI-2 Reactor Didg Atmosphere," by B Frank & D Teufel BEYEA, J National Auduborn Society, Central Midwest Reg Office B0/06/24 Spp

- 8007020534 Requests that site discharge water composite sampling frequencies be changed to once every 24-h for continuous composite sample & once per month for long-term composite sample Bate of PA concurs w/change
 HOVEY, 8 K Netropolitan Edison Co 80/06/25 2pp
- 8007010460 Requests NRC concurrence in use of Mine Safety Appliances, Co OMR-I & Scott TEDA-R respiratory protection cannisters against airborne radioactive matls Lists addl precautions for use of cannister Related correspondence encl HDVEY, O K Metropolitan Edison Co 80/06/26 Spp
- 8007100183 Forwards T Gerusty 800624 ltr re water disposal in sampling wells at facility Based on Itr.water may be placed in storm water drainage sys after sampling for analysis Related correspondence
 COLLINS.J T THI Program Office 80/06/26 4pp
- ---B007100186 Advises NRC that water in sampling wells may be placed in storm water drainage sys after sampling for analysis Water discharges into ensite drainage pend Related correspondence GERUSKY, T M Punnsylvania, State of 80/06/24 ip
- 8007110.293 Forwards PA Dept of Environ Resources 800624 ltr Water from sampling may be placed in storm sewer drainage sys COLLING, J T THI Program Office 80/06/26 App
- 8007110478 Responds to FDIA request for 790401-800530 documents reboron water maintaining subcriticality of facility core & processing & storage of boron water referred to in util 800130-0228 documents Forwards documents in App A FELTON, J M Division of Rules and Records 80/06/24 3pp
- --B0071104B5 Summarizes discussions re recommendations concerning boron concentration in facility RCS Boron concentration should be minimized due to possible problems w/valve seating, JG Herboin draft ltr encl
 NEWBERRY, S NRC Three Mile Island Task Force 79/08/31 7pp
- --8007110493 "Criticality Analyses of Disrupted Core Models of TMI-2"
 Excerpts from "Technical Btaff Analysis Rept on Alternative
 Event Sequences to President's Commission on Accident at
 TMI." & GE Kolynych 790501 ltr to util ancl
 WESTFALL,R H , WEST,J T , WHITEBIDES.O E Oak Ridge National
 Laboratory 79/10/31 118pp
- --B007110501 Discusses nonconservative ref Keff of (MI-2 core as given in special task force rept. "Evaluation of Cleanup Activities at TMI" (Questions re TM1 encl MAROTTA.C R Transportation Branch B0/04/01 App
- 800/100193 Approves 8006R5 Operating Procedure 2104-4 62 re Unit 2 reactor bldg atmosphere cleanup & mode to hydrogen control & containment bldg purge sys per 800612 order for temporary mnd of license BNYDER.B J TMI Program Office 80/06/27 4pp
- 8007240158 Advises of approval of proposed procedure & mod to sys for purging reactor bldg SNYDER B J TMI Program Diffice 80/06/27 4PP
- 8007070287 Responds to NRC 800528 ltr re contaminated water in facility containment bldg Clarifies util position on issues re submerged demineralizer sys, solid waste disposal & contingency plan for transfer of untreated water ARNDLD, R C Metropolitan Edison Co 80/06/30 App
- 8007070294 Responds to NRC B00507 ltr re TMI-2 related requirements Items 1 A i 3.1 A 3 1.1 C 5.11 K 3 K III D 3 4 currently under review for TMI-1 Items for TMI-2 will be reported under separate cover HERBEIN.J G Metropolitan Edison Co B0/06/30 2pp
- 8007310299 FD1A request for info re mods to alarm sys in facility reactor bldg venting sys TROMBETTA.R Affiliation Unknown 80/06/30 2pp
- B007220129 Requests participation in recovery activities at site recontaminated water Options presently involve discharge of tritium into atmosphere No practical means of decontaminating tritium DENTON.HR Office of Nuclear Reactor Regulation, Director B0/07/01 2pp
- BOO7070320 Forwards "EPICOR-II Radwasto Sys Linear Integrity & Resin Stability, Proliminary Evaluation, " h info summarizing EPICOR-II operation as of BOO604, in response to NRC 800515 ltr HOVEY, O K Metropolitan Edison Co 80/07/02 13pp

- --B007070322 "EPICOR-II Radwaste Sys Linear Integrity & Resin Stability, Preliminary Evaluation " * Metropolitan Edison Co 80/07/01 35pp
- 8007080358 Forwards 800616 info ltr to PADER, requesting approval to lask test two new tanks at TM1 per ETS 5 6
 HERBEIN.J @ Metropolitan Edison Co 80/07/02 3pp
- 8007110422 Submits evaluation of EPICOR II waste in response to NRC 800818 ltr Forwards summary rept layout of protective barriers data for liners, evaluation of liners & resins & drawings W/o encl HOVEY, G K Metropolitan Edison Co 80/07/02 3pp
- 8007140352 Forwards info re EPICOR-II radwaste sys, in response to NRC 800515 ltr Info ancludes summary rept of sys, layout of protective barriers re liner retention & discussion of liners & resins in use HOVEY. Q K Metropolitan Edison Co 80/07/02 49pp
- 8007140419 Forwards info ltr submitted to PaDER, requesting new tank lask test approval per ETS 5 6 2 4 2 W/o snc1 HERBEIN, J G Metropolitan Edison Co 80/07/02 2pp
- 8007230001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- 8007170373 Forwards water processing & processed water disposition plan for 1980, Revision 2 & 1981, Revision 1, supplementary to rept submitted 800130 M/o plan Dversize drawing, "TMI-1981, Mater Processing Schedule." in Central Files only HOVEY, 0 K Metropolitan Edison Co 80/07/03 1p
- BOO718037A Submits suppl to BOO130 water processing & processed water disposition plan for 1980 (Revision 2) & 1981 (Revision 1) One oversize drawing available in Central Files only HOVEY, O K Metropolitan Edison Co BO/07/03 ip
- SOD7170456 Discusses preparation of draft programmatic EIS for cleanup & recovery activities at TMI Requests meeting between NRC.

 ANL & util to exchange technical info for input to EIS

 ARNOLD,R C Metropolitan Edison Co 80/07/07 2pp
- 8007230643 Responds to 800624 itr re change in site discharges water composite sampling frequencies Concurs w/recommendations to raduce sampling frequency of RML-7 continuous composite sampling to 24-h period COLLINS.J T TMI Program Office 80/07/07 App
- 8007i30499 Forwards recovery operations plan Change Request 2 reauxiliary bldg & fuel handling bldg ventilation syssurveillance requirements
 HOVEY.Q K Metropolitan Edison Co 80/07/08 1p
- --B0071B0502 Tech Spec Change Request 2 for auxiliary bldg & Fuel handling bldg ventilation sys flow rate surveillance testing requirements, subsequent to supplementary ventilation sys removal from svc # Metropolitan Edison Co 80/07/08 4pp
- BOO717033B Forwards recovery operations plan Change Request 2 re surveillance requirements of auxiliary bldg & fuel handling bldg ventilation sys HDVEY.G K Metropolitan Edison Co 80/07/08 2pp
- --BO07170340 Proposed Tech Specs Pages 4 9-1 & 2 re surveillance requirements of auxiliary bldg & fuel handling bldg ventilation sys % Metropolitan Edison Co 80/07/08 2pp
- 8007180907 Responds to NRC/TMI-80-89 ltm dtd 800516 requesting addl info me submerged demineralizor sys technical evaluation mept Specific responses and MOVEY. G K Metropolitan Edison Co 80/07/07 88pp
- 8007170442 Forwards add1 info rp submerged demineralization sys,per NRC 800516 Itr Pipling & instrumentation & general arrangement oversize drawings enc1 HOVEY, 0 K Metropolitan Edison Co 80/07/09 BSpp
- --8007170446 "Piping & Instrumentation Drawing Supply Manifold Submerged Ion Exchangers "
 * Cham-Nuclear Bystems, Inc. 80/01/16 ip 4 1 1

- --8007170452 "Piping & Instrumentation Drawing Contaminated Feedwater Sys " * Chem-Nuclear Systems, lnr 80/01/16 1p
- --B007170455 'Piping & Instrumentation Drawing Monstoring Tank Sys "
 6 Chem-Nutlear Systems, Inc. 80/01/16 ip
- --8007170458 "Piping & Instrumentation Drawing Offgas & Liquid Separation Chem-Nuclear Systems Inc 80/01/16 ip
- --8007170464 "Ion Exchange Flow Sheet" # Chem-Nuclear Systems, Inc. 80/6 80/01/16 to
- --8007170466 "Piping & Instrumentation Drawing 527-A-03/Intermediate Sampling Sus
- Chem-Nuclear Systems. Inc 80/01/14 1p
- ---8007170473 "General Layout Plum Ion Exchange Equipment "
 * Chem-Nuclear Systems, Inc 80/03/05 ip
- ---8007170478 "Util Flow Diagram "
 * Chem-Nuclear Systems: Inc 79/10/17 ip
- --8007170482 "Piping & Instrumentation Drawing 527-A+02/Beta Monitoring
 - Chem-Nuclear Systems, Inc 80/01/07 ip
- --8007170488 "Inn Fichanger Support Assembly Drawing "
 * Chem-Nuclear Systems. Inc 80/01/23 ip
- -8007170490 "Piping & Instrumentation Drawing Dewatering Station "
 * Chem-Nuclear Systems. Inc 80/03/11 ip
- --8007170499 "Pump Removal Instructions For Offgas Pump & Feed Pump "
 * Chem-Nuclear Systems, Inc 80/03/12 1p
- Chem-Nuclear Systems, Inc. 80/05/05 to
- --8007170505 "Prefilter 125 Micron " * Chem-Nuclear Systems, Inc. 80/03/18 ip
- --B007170511 "Final Filter 10 Macron "

 * Chem-Nuclear Systems, Inc 80/03/18
- --8007170521 "Prefilter/Final Filter Details * Chem-Nuclear Systems, Inc. 80/01/21 1
- ~-8007170533 "Ion Exchanger W/Agitator " * Chem-Nuclear Systems. Inc 80/01/22 ip
- --8007170535 "General Arrangement Solidification Facility TMI Recovery " * Chem-Nuclear Bystems, Inc. HO/OJ/10 ip
- BOO7170395 Responds to NRC 800587 ltr re RCS water chemistry & corrosion control Control of dissolved oxygen is maintained by hydrogen overpressurization to ensure that free hydrogen exists in solution to control excessive amounts of oxygen HOVEY,O K Metropolitan Edison Co 80/07/11 lp
- BOO72103B3 Forwards Recovery Operations Plan Change Request 4 Request permits operation of standby pressure control sys w/lower nitrogen bank pressures to avoid overpressurization of exposed decay heat sys piping
 HDVEY.0 K Metropolitan Edison Co 80/07/15 App
- BOO7220323 Responds to FOIA request for "Submerged Demineralizer Bys Technical Evaluation Rept " Document available in DC FDR FELTON.J M Division of Rules and Rucords BO/07/15 to
- 8007220442 Advises NRC of intention to enter reactor hide during wk of 800721 to verify inner door operability & gather data on radiation levels & contamination near door NRC will be notified of subsequent entries HOVEY. O K Metropolitan Educan Co 80/0//15 2pp
- 8007310406 Forwards Attachment 13.EP100R II resum irradiation data, as promised in util 800702 ltr info withheld (ref 1007R2 790) HOVEY, G K Metropolitan Edison Co 80/07/16 2pp

- B007280023 Forwards list of TMI program ofc staff members to be used for ref in future correspondence CDLLING.R C TMI Program Office B0/07/17 2pp
- 80073D0271 Comments on draft, preliminary ElS on cleanup list of all preparers & qualifications should be included Costs should be presented in quantified terms to extent possible, including economic & environ costs

 CHANDLER.L J. Hearing Branch 1 80/07/27 3pp
- B007310336 Responds to util B00/15 ltr describing changes proposed to reactor bldg entry program following reactor bldg purge Entry preparations are satisfactory NRC approves entry as planned COLLING. J T MM Program Office 80/07/22 4pp
- E007310498 Concurs w/use of orbisphere as method to obtain more reliable dissolved oxygen values for RCS Concurrence withheld re-control of dissolved oxygen by hydrogen overpressurlitation CDLLING.J T TMI Program Office B0/07/22 4pp
- 8007300447 Advisos of intent to purge reactor bldg atmosphere on routine basis Purge will be conducted d/Procedure 2104-4 91, using modified purge sys Total weekin releases will not acced 72 C. K.P-85
 HOVEY. 0 K. Metropolitan Edison Co. 80/07/24 1p
- BOO7310285 Responds to FOIA request for info re mods to alarm sys in facility reactor bidg venting sys Forwards document detailing info mubj to request FELTON.J M Division of Rules and Records 80/07/25 lp
- --8007310310 Describes preparation for & procedures used to purge Kr-85 from facility reactor bidg atmosphere Purging continued at various sys flow rates based on meteorological conditions

 Commission 80/07/25 2pp
- 8007310439 Forwards "TB1-2 Radiation Protection Plan.Revision 2." for final NRC approval Revised plan sets forth radiation protection policies & philosophies of Met Ed & General Public Utils Curp radiological controls program W/o encl ARNOLD.R C Metropoliton Edison Co 80/07/25 2pp
- 8007280087 "NRC Plan for Cleanup Operations at TM1 Unit 2 " * TM1 Program Office NUREG-0498 80/07/31 25pp
- O Inspection reports. 1E Bulletins & correspondence
- 6007100009 Forwards combined IE Insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 & notice of violation GRIER, B M Region 5. Philadelphia. Office of the Director 80/01/09 3pp
- --B007100014 Combined IE Insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 Nonrompliance noted failure to store & control licensed matls in unrestricted areas tHITEL JR , YUMAS, 0 P , MCGAUGHY, R & Region i, Philadelphia, Office of the Director 79/12/20 15pp
- 8007100002 Forwards Waste Packaging Insp Rept 15000046/80-04 on 800107-88 No noncompliance noted BHITH,Q H Region I. Philadelphia, Fuol Facility & Materials Safety Branch 80/03/24 2pp
- --B007100003 Waste Packaging Insp Rept 15000046/80-04 on 800107-18 No noncompliance noted Hajor areas Inspected waste shipments for compliance w/D07 & NRC regulations Including Vehicle placarding, package marking & condition of packages THOMASIR D. PECK.C C Region I. Philadelphia, Office of the Director BODM HE Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/25 7pp
- 8007020161 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs " No written response required ORIER, D H Region 1, Philodelphia, Office of the Director 80/05/28 lp

- B007010315 Forwards JE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/29 ip
- BOD7210572 Forwards IE Info Notice BO-26, "Evaluation of Contractor GA Programs " No written response required GRIER BH Region 1, Philadelphia, Office of the Director BO/06/10 | 1p
- 8007160349 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs No specific action or response required ORIER.O H Region 1, Philadelphia, Office of the Director 80/06/11 lp
- 8007020715 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Lass of Offsite Power " Written response required GRIER, D H Region 1, Philadelphia, Office of the Director 80/06/18 ip
- 8007020526 Forwards IE Circular 80-i5. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ORIER. II H Reglon i. Philadelphia, Office of the Director BO/06/20 lp
- B007i60708 Forwards IE Circular 80-i4, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER, B H Region i, Philadelphia, Office of the Director B0/06/24 ip
- 8007210202 Forwards IE Info Notice 80-24, "Low Lavel Radwaste Durial Criteria " No written response required CRIER.B H. Region 1. Philadelphia, Office of the Director 80/06/25 ip
- B007230129 Forwards IE Bullstin B0-16, "Potential Hisapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Writton response required IE Circular 80-16 also encl No written response required ORIER, B H Region 1, Philadelphia, Office of the Director B0/06/27 2pp
- B00716043i Forwards evaluation & submittal schedule for all IE bulletin responses per util B00529 ler & in response to NRC B00647 request Responses to 1E Bulletins 79-10 & 80-09 encl. HDVEY, 0 K Metropolitan Edison Co 80/07/09 7pp
- 8007220485 Forwards list of recovery mode surveillance procedures reviewed & results per util 800519 commitment Sufficient administrative controls to assure compliance present in all but 8P4303-M3
 ARNOLD-R C Metropolitan Edlson Co 80/07/10 iOpp
- R Periodle operating reports & related correspondence
- B0070201B2 Forwards THI Program Off weekly status rept for wk of 800614-20 COLLINS.J T TMI Program Office 80/06/23 App
- B007i50053 Forwards status rept for wk of B0062i~28 GOLLINS.J T TMI Program Office B0/06/30 7pp
- 8007180102 Forwards status rept for wk of 800621-28 COLLINS,J T TMI Program Office 80/06/30. Bpp
- 8007170442 Forwards status rept for wk of 800629-0705 COLLINS.J T TMI Program Office 80/07/07 7pp
- B0071B0539 Forwards TMI Program Off weekly status rept for wk ending 80070B CDLLINS.J T TMI Program Office B0/07/07 20pp
- 8007250719 Forwards status rept for wk of 800706-12 COLLING.J T TMI Program Office 80/07/14 App
- 8007210359 Forwards "TMI-E Recovery Quarterly Progress Rept," for period ending 600630 Rept available in Central Files only HOVEY, C K Metropolitan Edison Co 80/07/15 ip
- 8007310134 Forwards weekly status rept for 800713-17. Liquid effluents from Unit 1, released to Busquehanna River.were within Tech Spec Ilmits No liquid effluents discharged from Unit 2. COLLINS.J T TMI Program Office 80/07/21. Spp

- 8 Reportable occurrences, LERs & related correspondence
- B007010454 Forwards LER 80-020/01L-0 HBVEY, C K Metropolitan Edison Co 80/06/26 1p
- --800701045B LER 80-020/01L-0 on 800522, during containment entry, violation of containment integrity occurred via bulkhead makeup valve E Caused by procedural deficiencies Procedures revised CHAPLIN.8 D Metropolitan Edison Co 80/06/26 App
- B007250207 PNG-TMI-B0-036 on B0062B, purging of reactor bldg is scheduled to start at 8 00 AM CONTE, R J , FABANO, A Region 1, Philadelphia, Office of the Director COLLINB, J T TMI Program Office B0/06/27 lp
- 8007250201 PNO-TMI-80-037 at 8 00 AM on 800628, purging of reactor bldg atmosphere was started Purge was stopped after 4 minutes due to high particulate alarms CONTE.R J. FAGANO.A Region 1, Philadelphia, Office of the Director COLLINS.J T TMI Program Office 80/06/29 ip
- B007140522 Forwards LER 80-024/03L-0 H0VEY.O K Metropolitan Edison Co 80/06/30 ip
- --B007i60525 LER 80-024/03L-0 on 800527, while in recovery mode of operations, pressure transducer used to monitor RCB pressure was isolated from RCS w/o control room knowledge Caused by deficient SDP Valve reopened within Tech Spec action period CHAPLIN B D Metropolitan Edison Co B0/06/30 2pp
- 8007250214 PNO-TMI-80-038 on 800629, purging of reactor bldg atmosphere was resumed To intrease sensitivity of stack monitor for particulates, addl instrumentation was installed CONTE.R.J., FAGANO.A Region 1. Philadelphis, Office of the Director COLLINS, J.T. TMI Program Office 80/06/30 ip
- 8007250231 PND-TMI-80-038A on 800701.purging of reactor bldg atmosphere continued at various flow rates based on matsorological conditions Momentary shutdowns also occurred due to stack monitor filter changeouts
 GUNTE.R.J. FABAND.A Region 1: Philadelphia, Office of the Director COLLINS.JT TMI Program Office 80/07/01 ip
- 8007250237 PNO-TMI-80-0388 on 800702.purging of reactor bldg atmosphere continued at various flow rates based on meteorological conditions Scheduled shutdown lasting 5-h occurred for computer maint CONTE,R J , FASAND, A Region i, Philadelphia, Office of the Director. COLLINS, J T TMI Program Office 80/07/02 ip
- 8007170547 PND-TMI-BO-038C on 800703, purging of reactor bldg atmosphere continued Shutdown occurred due to loss of sample pump for effluent monitor, Replacement pump was installed to purging resumed CONTE, R J , SHANBAKY, M M Region i, Philadelphia, Office of the Director COLLINS, J T TMI Program Office 80/07/03 1p
- BOO7170540 PNO-TMI-BO-D3BE on BOO707, purging of reactor bldg atmosphere continued Momentary shutdowns occurred due to stack monitor filter changeouts CONTER J. SHANBAKY, M.M. Region 1, Philadelphia, Office of the Director COLLINB, J.T. TMI Program Office 60/07/07 ip
- BOO7160596 RD 80-27/1P deluge valve closed to preclude actuation of modified hydrogen purge filters & reactor pldg purge exhaust filter fire protection deluge Caused by omission of footnote from Tech Boecs allowing closing.

 HOVEY, G K Matropolitan Edison Co 80/07/08 1p
- 8007170553 PNO-TMI-80-038F on 800708, purging of reactor bldg atmosphere continued At approx & 20 AM, sys was shut down due to high alarm on purge sys monitor noble gas channel Reason for alarm is under review CONTE, R J , SHANBAKY, M M. Region 1, Philadelphia, Office of the Director COLLINS, J T TMI Program Office, 80/07/08, 1p
- B007;50513 Forwards LER 80~025/03L-0 HDVEY, G K Metropolitan Edison Co B0/07/09. ip
- ---BC07150514 LER BO-OPD/CGL-O on BO0407, reactor coolant inlet temp meter on remote shutdown monitoring instrument panel found inoperable Caused by instrument failure, Replacement ordered a quitmeter temporarily installed CHAPLIN.B.D Metropolitan Edison Co BO/07/07 2pp
- B007150515 Forwards LER 80-023/03L-0 HQVEY, G. K.: Metropolitan Edison Co B0/07/09 ip.

- ~-8007150519 LFR 80-023/03L-0 on 800403, boron concentration in boric acid mix tank found exceeding Tech Specs Caused by evaporation from use of temporary air sparyor mixing apparatus Boron solution diluted & regular tank mixer returned to syc CHAPLIN,S D Metropolitan Edison Ca 80/07/03 2pp
- B007170964 PNO-THI-BO-0380 on B00709, purging of reactor bldg atmosphere continued at various flow rates Momentary shutdowns occurred due to stack monitor filter changeouts CONTE, R J , SHANDAKY, M M Region i, Philadelphia, Dffice of the Director COLLING, J T TMI Program Dffice 80/07/09 ipp
- B007230158 PNS-I-80-018 on 800709, licensic received telephone bomb threat Licensec conducted full scale search w/negative results
 BAILEY, R., MARTIN, W. Region 1, Philadelphia, Office of the Director 80/07/09 ip
- BOO7170557 PND-TM1-80-03BH on BOO710, purging of reactor aldg was shut down at 1 45 AM so that reactor bldg air samples could be taken CONTE, R J . SHANBAKY, M M Region 1, Philadelphia, Office of the Director COLLINS, J T TMI Program Office BO/07/10 1p
- B007230239 Part 21 rept re cracked steam generator manway studs Satisfactory operating experience forms.constitute reasonable basis for continued operation while investigations proceed TAYLORJ H Babcock & Wilcox Co 80/0//11 5pp
- BOO7240203 PND-TMI-BO-301 on BO0711, purging of reactor bldg atmosphere continued until approx 10 00 AM when purge sys was shutdown because licenses declared purge complete. CONTE, R J . SHANDAKY, M M . COLLING, J T TMI Program Office BO/07/11 ip
- BOO7240118 PMO-TMI-BO-040 on BOO716, inner door for reactor bldg personnel airlick 2 was sucessfully opened Upon closure of door, seal rings for door failed loakage test CONTER J , COLLINS, J T TMI Program Office 80/07/16 is
- BOO7230218 PND-TMI-HO-D40A on BOO716, reactor bldg personnel airlock inner door failed seal leakage test While inner door was open Radiation surveys were taken inside reactor bldg near inner door CONTE,R J , FARAND,A N , COLLINS,J T TMI Program Office 80/07/17
- 8007230434 RO 80-30/iP on 8007i7, surveillance testing of inner personnel airlock containment door indicated that leakage past inner door seals exceeded Tech Spec limit Bubsequent surveillance testing of outer door was satisfactory HOVEY, O K Metropolitan Edison Co B0/07/17 lp
- B007230439 RD B0-29/IP on B00714, while performing surveillance procedure 4303-Mi6, Gray balance of plant diesel generator failed to start Caused by problem w/100 speed switch Replacement parts have been ordered HOVEY, O Metropolitan Edison Co 60/07/17 2pp
- 8007290811 Forwards LER 80-026/03L-0 HOVEY, G K Metropolitan Edison Co 80/07/18 1p
- --B007R90817 LER 60-026/03L-0 on 800618, during recovery mode, Unit 2 fire pump removed from svc Unit 1 pump discovered unaligned to fire suppression header Caused by personnel error Procedures revised to reflect permanent valve lineau change CHAPLIN, S D Metropolitan Edison Co 80/07/18 2pp
- T Hearing transcripts on non-antitrusi matters
- 8007030345 Transcript of 790803 intervaled of D Sternberg in Bethesda. MD Pp 1-86 BTERNBERGO, D Region 5. San Francisco, Office of the Director 79/08/03 86pp
- 8007030334 Deposition of RW Heward, of General Public Utils, by NRC/TMI Special Inquiry Group on 790925 in Parsippany, NJ Pp 1-55 HEWARD, R W ' Guneral Public Utilities - GPU Gervice Corp 79/09/25
- 8007030342 Transcript of 800610 continuation of discussion of facility vanting in Washington, DC Pp 1-25 Marning session Related draft memorandum & orders enci & Commission 80/06/10 43pp

- 7140005 Transcript of 800630 conference call between parties issuesing public hearing requests re-800642 order for temporary mod of license to allow reactor bidg purging NLF. J.F. Atomic Safety and Licensing Board Panel TROMBRIDGE, G. Estropolitan Edison Co. CHANDLER, L. J. Hearing Branch 1 80/06/30 lpp
- 7140222 Transcript of 800707 prehearing conference in Harrisburg,PA p 1-85 Atomic Safety and Licensing Board Panel 80/0//07 87pp
- 718004i Transcript of 800707 public meeting in Washington.BC to iscuss TM1 action plan.Chapter V Pp 1-37 Supporting mat)
- iscuss TMI action plan.Chapter V Pp 1-37 Supporting matl mcl Commission 80/07/07 58pp
- 7140219 Transcript of 800/08 prehearing conforence in Harrisburg. A Pp 1-34 Atomic Safety and Licensing Board Panel 80/07/09 36pp
- 7240254 Corrected transcript of 800708 prehearing conference in arrisburg.PA Pp 86-119 Atomic Safety and Licensing Board Panel 80/07/08 36pp
- Congressional/Executive Correspondence
- 9240333 Responds to 790423 Itr to President re TMI-2 accident everal groups are investigating TMI-2 accident & huclear ower Assures that NRC will take necessary actions to nsure public afety
 ENDRIE-J M Commission 79/08/02 9pp
- 5200252 Responds to 800404 request for info re FJ Sternglass paper. Infant Mortality Changes Following TMI Accident "Analysis fradiobiological aspects of the first paper of the first p
- 7020303 Discusses status of actions re cleanup activities in esponse to 800327 it concerning proposed Kr-85 release HEARNE, J F Commission 80/06/04 2pp
- 0070P03i3 Comment: on proposal to vent Kr-85 from containment bldg should identify all future problems & possible solutions that may arise in other phases of cleanup operation Offers support in Seeking technical or scientific advice THDRNBURGH, D. Pennsylvania, State of 80/05/16 3pp
- 007020323 Exploses concern that NRC may permit venting of krypton gas from reactor in manner that may endanger public physical & mental health NRC should establish independent panel of scientists to evaluate decisions re facility cleanup MENNEDY.E M Senato 80/03/27 2pp
- 7110363 Expresses interest of Environ, Energy & Natural Resources ubcommittee in TM1 accident implications Commissioners are noticed to B00702 public hearings to present NRC policy tatement & discuss interveners' limitations (OFFETT.T Congress (Joint & Rotating Committees, etc.) 80/06/24
- 17140050 Provides Subcommittee on Energy & Water Development w/info o roprogramming actions for approval Includes priorition & tatus items.roprogramming analysis.neur-term Oi tooks & YBO base table M/o encl HEARNE.J F Commission 80/06/25 2pp
- 007140062 Provides Subcommittue on Energy & Hater Development w/infore reprogramming actions for approval Includes priorities & status items.reprogramming analysis.near-term OL tasks & FY80 base table M70 encl
 AMEARME.J F Commission 80/06/25 52pp
- 17230559 Supple previous responses to FOIA request for written ownunications between NRC & Congress since 800322 reacility Forwards A Myers 800503 ltr to V Stella Info artially withheld list of questions (ref FOIA Exemption 7) ELTON-J N Division of Rules and Records 80/07/17 1p
- 007230565 Forwards questions concerning failure of util employees to provide govt officials w/certain significant info during early stages of facility incident Questions withheld (ref FDIA Fremption 7)
 MYERS-H House of Rep . Interior & Insular Affairs 80/05/05

- DOCKET 90-32) EDWIN I HATCH NUCLEAR PLANT. UNIT I

 F Security, medical, emergency & fire protection plans
- 8007020488 Forwards request for add1 info re 800528 revised guard training & qualification plan Enci withheld (ref 10CFR2 770)
 REID.R W Decreting Reactors Branch 4 80/06/19 20p
- BOO7230104 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mgt personnel at facilities EISENHUT, D O Division of Licensing 80/07/11 2pp
- 8007280514 Advises that 800718 emergency plan upgrading per NUREO-0654 uill be delayed until 801001 Requests rept from 800422-23 Emergency Preparedness Team review WIDNER:WA Georgia Power Co 80/07/21 lp
- 9 Adjudicatory correspondence
- BOD7310243 Forwards Commission BOO327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of B00207 meeting w/Mark I owners group in Rethreda, MD,re revisions to NRC acceptance criteria & outstanding issues relative to Mari I containment long-torm program GNIMES,C T Plant Systems Dranch 80/02/21 Jipp
- 8007140641 Advises that dates of responses to 790927 generic ltr wore 791025 for Peach Bottom 2 % 3 % 791115 for Hatch 1 % 2 Rept on valve operability program required only for plants desiring to justify unlimited purging VERRELLI.D M Operating Reactors Branch 4 80/06/05 lp
- 8007010474 Advisos that util will comply w/800507 ltr issuing five addl TMI-2 related requirements for operating reactors When implementation criteria is developed.NIC will be notified of any variation from schedule Reserves three options WIDNER.W A Georgia Power Co 80/06/20 ip
- 8007020628 Advises that review has been completed on 800513 rept of calibr results on seismic instrumentation Triaxial Time-History Accelerograph. 21.51-ND21 was returned to vendor for repair as recommended MANRY. M Georgia Power Co. 80/06/25 ip
- B007090389 Notification of 800703 meeting w/util in Bethesda.ND to discuss util basis for delayed schedule for installing T-quenchers VERRELLI.D Operating Reactors Branch 4 80/06/26 2pp.
- BOO7080287 Discusses applicability of GE response to questions raised by C Mithelson in response to NRC 800507 request Automatic isolation may occur for breats outside or inside containment depending on break size & location WIDNER, W A Georgia Power Co 80/06/30 2pp
- BOO70BO322 Application for amend to App A of License DPR-57, submitted as proposed changes to Tech Specs to diagnostic test program for HPC1 sys

 WIDNER, W A Georgia Power Co BO/07/02 3pp
- --8007080327 Proposed amend to Tech Specs 3 5 D 2 & 4 5 D 1.allowing one time diagnostic test program of HPCI sys

 * Georgia Power Cp 80/07/02 1p
- BOD7180506 Confirms D Verrelli BO0702 telcon w/CT Moore authorizing temporary amend to Tock Specs revising limiting conditions for operation of HPCI sys to perform operation BO0702-09 w/inoperable HPCI for diagnostic & reliability testing NOVAK.T M Division of Licensing BO/07/03 2pp
- GOD7180484 Confirms utal commitments at 800703 meeting re schedule for completing mods for resolution of Mark I containment longterm program Meeting summary encl REID.R W Operating Reactors Branch 4 80/07/07 2pp
- --8007180487 Summary of 800703 meeting w/util re licensee schedule for completing muse for resolution of Mark I containment longterm program VERRELLI.D M Operating Reactors Branch 4 80/07/07 6pp

.

- 8007230656 Provides info re new ofc titles, positions & assignments of personnel resulting from 800428 reorganization of Ofc of Nuclear Reactor Regulation Assistant Director for Operating Reactors 80/07/10
- B007280634 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs re torus water temp If water temp connot be restored within 24-h, reactor shall shutdown using normal shutdown WIDNER, W A Georgia Power Co 80/07/17
- --8007280642 Proposed Tech Specs Sections 1 0 & 3 7 re torus water temp 1f water temp cannot be restored within 24-hiteactor shall shutdown using normal shutdown procedures * Georgia Power Co 80/07/17 9pp
- B007310336 Requests written confirmation of 800718 telcon re-critical situation concerning electrical power generation in region served by util NOVAKIT M Assistant Director for Operating Reactors 80/07/22
- 9 Inspection reports. IE Bullstins & correspondence
- 8007240213 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" No response required CAREILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007140490 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers " Written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/12
- B00702017B Forwards IE Info Notice B0-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28
- B007010220 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Ferdwater Pumps" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007100064 Forwards IE Insp Repts 50-321/80-22 & 50-366/80-22 on 800412-0512 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 2pp
- -8007100066 IE Insp Repts 50-321/80-22 & 50-366/80-22 on 800412-0512 No noncompliance noted Major areas inspected Tech Spec compliance. ROs. housekeeping, plant operations, GA plactices & IE Bulletin 79-26
 DANCE: H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch RODERS, R F Region 2. Atlanta, Defice of the Director 60/05/30 5pp
- 8007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- 8007140294 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/12
- 8007020736 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification 89s (ENS) W/LBSS of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- B007020298 Forwards notices of violation & proposed imposition of civil penalty re IE insp on B00319
 STELLO,V Office of Inspection & Enforcement, Office of the Director B0/06/19 2pp
- --800702030] Notice of violation from insp on 800319 Noncompliance noted packages of licensed maths shipped on 800318 w/radiation levels in truck cab exceeding regulatory limit # Office of Inspection & Enforcement, Office of the Director 80/06/19
- --8007020305 Notice of proposed imposition of civil penalty in amount of #4.000 re violation noted during 800319 insp # Office of Inspection & Enforcement, Office of the Director

- 8007090074 Requests extension to BOD/III to complete response to Items I & 2 of IE Holletin 80 10 "confiamenation of Noon adjustive Sys & Resulting Policitial for Unionistated Union of Note adjustive Roleage of Radioarthylight to Ecology WIDNER, R.A. Georgia Power Co. 80206/19 to
- 8007140180 Discusses 800319 imindent which revenled radaction levels exceeding limits on truck cab arriving at Barowell with Forwards notice of violation ! notice of propored imposition of civil penalty STFLLO.V (Affice of inspection & Inforcement, office of the Director 80706/19 dpp
- 8007020450 Forwards 16 (irrulin 80 15 Tuss of Reartin (noight Pump Conling & Natural (irrulation (puldown No written required required O'RETELY, J.P. Region is Atlanto Office of the Director 80706720
- B007110250 Ack correspt of 1809cod for informing NRC of steps taken to correct violation noted in 15 four Repts 50 54780 19 5 50-346780-19 BTOHR, J.P. Region 2, Actanta, fuel Lacinty 5 Materials Dafoty 80/05/24 10
- --BO07110259 Responds to NRC HDONEP Its to violation nated in IC lump Repts 50-327/80-19 & 90-306/80 19 Corrective actions full audit of emergency plan *c implementing procedure; completed WIDNER W A Goorgia Power (a. 10/06/04 1p
- --8007110262 Forwards If Insp Repts 50 \$27780 19 % 50 466/80 19 ms 800421-25 & sottre of variation STORGJP Region 5 Atlanta, fool largity & Motorials Navely Branch 80709712 dpp
- ---8007110260 Notice of violation from in p on 8004-1
 * Region 2: Atlanta. (Iffice at the Darvitor D 00705743
- -8007110276 IF Insp Ropts to Silvin 19 5 to maygo 19 on 000429 is Noncompliance moted factors to midst emisquity implementing procedures every 2 yra under tagestime of makety states PERROTTIO J., IRUJANDUSKIA Region 2. Atlanta, Office of the Director JERKINS O R. Rogion 2. Atlanta, fuol lacility b Materials Sofety Branch BOZCCZIP Spp
- 8007300576 Forwards IF Insp Repts 50 321780 14 5 50 366780 14 on 800319,0427 & 10 Enforcement action discussed in NRC (800419 O'RETILY, JP Rogion P. Attanta, diffice of the Director
- ~-8007300980 If laws Repts to delike 14 % 50 tobile 14 an HOB 11% base 1 30 Noncompliance noted radiation tevels an vehicle cab in excess of regulatory limits 570HR. J. F. HOBBELLER C. Region 2. Atlanta, Lord Larchity & Materials Safety Granch (Addy.) H. Region 2. Atlanta, Office of the Director (80/06/19) Bpp
- BOO/170115 Forwards II (ficular 80-14 "Radium tive (animation of Plant Demineralized Water 99s & Recultant Internal Contamination of Personnel " Ne written temporar required O'RETILLYJ P Region 2: Atlanto Office of the Director BOOMAST
- 6007230247 Furwards II. Welletin HO 36. "Patential Disapplication of Resemble Inc Models 1151 b 1152 Prisonic framewitters."
 WESTER A OF D Output Code: "Spritter response required IK Circular 80-16 also one No written response required O'RESTITATE Region 2. Attenta Office of the Director 160464 110706721
- 8007220,81 Submits final response to B Rulietin 70 ID Shike evaluations performed for floor evaluation are explicitly as a full instead installation of evaluation wigners Visual Marining lights will be installed during Full 1980 resulting notage HIDNER, W.A. Georgia Power on GOZADZAN in
- 8007070347 forwards into in response to Items to the P. s required by H. Bultotin BO-11. "Masonry Wait Devices" flow (As to be addressed in final rapt. History Walter) in 1027073. High
- B007140784 Responds to 18 Bulletin 60 of in rotationment liner penetration weld cram Requerts 30 day intention for influent submittal due to targe number of flued food containment liner penetrations to beave bigh priority work load WIDNER, WA Georgia Power to 10/07/07 ip

```
07280126 Ack receipt of 800623 ltr informing NRC of steps taken to
correct deviations noted in IF Insp Repts 50-321/80-02 &
50-366/80-02
HURPHY, C E Region J. Atlanta. Reactor Construction & Engineering
Support Branch 80/07/09 ip
```

8007280128 Responds to NRC 800208 & 0411 ltrs rc deviations noted in IE Insp Repts 50-321/80-02 & 50-366/80-02 Corrective actions submitted encl draft engineering roview of GA fire protection program at NGC 800602 meeting WIDNER.WA Opengia Power Co 80/06/23 42pp

07240252 Ack receipt of 800A12 ltr informing NRC of steps taken to correct windations noted in IE lnsp Repts 50-321/80-17 & 50-364/80-17 D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/11

8007240264 Responds to NRC 800719 ltr re violations noted in iE Insp Repts 50-321/80-17 & 50-366/80-17 Corrective actions new airlock acheme installed Actions to event & deviation reportability justified WIDNER.W A Georgia Power Co 80/06/12 App

8007240277 Forwards IE Insp Repts 50-321/80-17 & 50-366/80-17 on 800308-0411 & notice of violation LEHIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/19 2pg

8007240285 Natice of yielation from insp on A00308-04il * Region 2. Atlanta. Dffice of the Director 80/05/ 80/05/19 2pp

B007240292 IE Insp Repts 50-321/80-17 % 50-366/80-17 on 800308-0411 Noncompliance noted failure to maintain secondary containment door integrity & to meet NRC reporting

requirement acor integrity a to meet not reporting requirements

ROGERS.R F Region 2, Atlanta, Office of the Director DANCE Region 2, Atlanta, Reactor Operations Nuclear Support Granch 80/03/19 Spp

07230272 Responds to IE Bulietin 80-17, "Failure of Control Rods to ully Insert " Screm discharge vol (5DV) vent & drain operability verification test performed All drain & vent valves verified operable No residual water found in SDV WILDER, W A Georgia Power Co 80/07/11 1p

07310273 Responds to NRC B00619 notice of violation re excessive radiation exposure rate inside cob of raduaste transport vehicle Radiation survey indicated radiation levels within code requirements Requests mitigation of violation severity WIDNER.W A Georgia Power Co 80/07/14 2pp

BOO7310287 Responds to NRC 800619 notice of proposed imposition of civil penalty Radiation survey of vehicle indicated levels within code requirements Requests mitigation of severity of violation & reduction of civil penalty MIDNER.W A Georgia Power Co BO/07/14 2pp

07310597 Submits summary of events in response to IE Bulletin 80-17 PCI inverter R44-5003 declared imagerable twice Normal supply breaker to 4 kV bus IF tripped, placing bus on alternate feed IANRY, M Georgia Power Co 80/07/14 2pp

07220422 Responds to IE Bulletin 79-14, "Spismic Analysis for As-Juilt Safety-Related Piping Sy: "Requests extension until BoiOOI to complete verification of srismic analysis, based on spogress made & number of ROs 4IDNER, W A Georgia Power Co 60/07/15 2pp

07280538 Advises of proposed compensatory measures re 2-wk extension for scram testing required for IF Bulletin 80-17 ltil will perform tests as soon as possible should critical load situation ease HIDNER, W.A. Georgia Power Co. 80/07/19 ip

0728054] Advises of completion of liems 1 & 2 of IE Bulletin 90-10, "Contamination of Norradioartive Sys " Complete Jocumentation of Affected sys & associated monitoring Intocedures available for leview during Auture onsite insps AIDNER.W A Georgia Power Co 80/0//18 ip

07290618 Requests delay in performing scram tests required by IE Bulletin 80-17 dup to high temps in region Romaving large units from see would place severe strain on electric generating capacity of region HIDNER, W.A. Georgia Pawer Co. 50/07/18 2pp

```
8007280678 Forwards monthly operating repts for June 1980 MANRY.M Georgia Power Co 80/07/10 lp
 --8007280680 Monthly operating rept for June 1980
BLACKWELL,R M Georgia Power Co B0/07/10
 --B007280686 Forwards monthly operating repts for June 1980 MANRY: M Ocorgia Power Co 80/07/10 1p
 --8007280692 Monthly operating repts for June 1980
BLACKWELL.R M Georgia Power Cn 80/07/10 7pp
 S Reportable occurrences, LERs & related correspondence
 8007110285 RO-50-321/1980-61 on 800622, while preparing to run RHR sys, "B" RHR loop min flow manual valves were discovered closed Caused by failure to return to open position after loop was taken out of shutdown cooling mode Valves locked open MANRY, M Georgia Power Co 80/04/23 lp
 8007030276 Forwards LER 80-065/03L-0
MANRY, M Georgia Power Co 80/06.
                                                                          80/06/24 tp
 --B007030278 LER 80-045/03L-0 on B00414, while inerting primary containment mitrogen storage tank was found to contain less than 2,000 gallons nitrogen Caused by increased use of
          mitrogen
BAXLEY.8 X Georgia Power Co 80/06/24 2pp
8007030261 RD on 800522, licensee reviewed Kinemetrics, Inc 800513 calibr
rept re seismic instrumentation Trioxial Time-History
Accelerograph 2L51-NO21 calibr indicates excessive change
in longitudinal channel characteristics
MANRY,M Georgia Power Co 80/06/25 ip
 8007030284 Forwards LER 80-062/01T-0
MANRY, M Georgia Power Co 80/06/25 1p
 --8007030286 LER 80-062/01T-0 on 800612.w/Unit i in cold shutdown,
         investigation was begun to determine cause of pavement deflection which occurred beneath crane outrigger pad Caused by improper compaction of localized area COGOIN.C L. Georgia Power CO. 80/06/25 2pp
8007020638 Forwards LER 80-056/03L-0
MANRY.M Georgia Power Co 80/06/27 19
 --B007020442 LER 80-056/03L-0 on B00205, standby gas treatment sys
ventilation & valve operability procedure changed on B00122,
had not been PRB reviewed or approved within 14 days as
required by Tech Spec Caused by person
8007:10307 RO 50-321/1980-069 on 800626. following auto initiation signal. HPCI failed to inject to reactor pressure vessel due to isolating on steam line high DP isolation signal Cause under investigation Reset isolation & opened inboard valve MANRY. M Georgia Power Co 80/06/27 ip
8007110400 Forwards revised LER 80-055/01X-1
MANRY, M Georgia Power Co 80/06/30 1p
 --B007il0403 Revised LER 80-055/01X-1 on 800531.while performing insp of
snubbors.45 out of 61 were found locked up Caused by
internal corrosion Snubbers replaced
* Georgia Power Co 80/06/30 2pp
8007110304 Forwards LER 80-060/03L-0
MANRY, M Georgia Power Co 80/07/01 ip
 --B007ii03i3 LER 80-060/03L-0 on 800603, w/reactor in cold shutdown, insp
revealed two hanger mods to HVAC room sprinkler required for
seismic qualification were incomplote Caused by failure to
implement hanger mod sketches contrary to procedure HNP-809
COGGIN,C L Geargia Power Co 80/07/01 2pp
```

8007110432 Forwards LER 80-061/01T-0 MANRY,M Georgia Power Co 60/07/01 1p

~~8007110442 LER 80~061/0iT~0 on 800422, while preparing to run RHR sysper HNP~i~6006, operator discovered loop B min flow manual valves Eii-F018 B & D closed Caused by operator closing valves to prevent reactor water from going to torus BAXLEY.S X Georgia Power Co GO/07/01 3pp

1 1

R Periodic operating reports & related correspondence

```
B00711036B RD 50-321/80-076 while reviewing as-bullts submitted per IE Bulletin 79-14, util discovered hangers IE11-RHRH-196 & IE11-RHRH-313 would not adequately support loads during DBE Caused by faulty design in incorrect valve weights MANRY, M Georgia Power Co B0/07/02 2pp
                                                                                                                                                                                                                      8007170414 Forwards LER 80-067/01T-0
MANRY,M Georgia Power Co 80/07/10 1p
                                                                                                                                                                                                                           -8007170419 LER 80-069/01T-0 on 800626, after reactor scram, HPCI failed
                                                                                                                                                                                                                                  to inject to reactor pressure vessel per auto initiation signal due to isolating on eterm line high DP Caused by turbine controls being out of dynamic calibr COOGIN, C L Georgia Power Co 80/07/10 2pp
B007110455 Forwards LER 80-072/03L-0
MANRY, M Georgia Power Co 80/07/02 ip
--B007110463 LER 80-072/03L-0 on 800624, reactor bldg went radiation monitor sample pump failed in run mode at 2426 MWt Caused by swelled carbon wanes Pumps will be switched out more often to minimize moisture buildup & improve reliability ROOERB,W H. Georgia Power Co. B0/07/02 2pp
                                                                                                                                                                                                                       8007210370 Forwards LER 80-076/017-0
MANRY.M Georgia Power Cu 80/07/14 Ip
                                                                                                                                                                                                                       --B00721037; i.ER 80-076/017-0 on B00701, while reactor was at hot standby for HPCI/reactor core isolation cooling testing, site notified by AE that listed RHR supports would not adequately support all design based loads CO001N.C L. Georgia Power (o. 80/07/14 App
8007110415 Forwards LER 80-063/031-0
MANRY, M Georgia Power Co 80/07/03 1p
~-8007110426 LER BO-063/03L-O on 800612, while performing surveillance procedure HNP-1-3102, reactor high propsure shutdown cooling mode switch 1931-N018B found to actuate higher than limit Caused by setpoint drift Switch recalibr NIX.R T Georgia Power Co 80/07/03 2pp
                                                                                                                                                                                                                      B0072103B4 RO on B00711. Unit 1 LPCI inverte: tripped & Unit 2 4-kV bus 2F supply breaker & HPCI tripped Supply breaker trip caused by jumper missing from neutral leg Nator valve on HPCI replaced making it operable Events submitted per IEB 80-17 MANRY, M Georgia Power Co 80/07/14 2pp
8007150539 Forwards LER 80-059/03L-0
HANRY, M Georgia Power Co 80/07/03 1p
                                                                                                                                                                                                                      B007210484 Forwards LER 80-078/03L-0
MANRY, M Georgia Power Co 80/07.
                                                                                                                                                                                                                                                                                                      60/07/14 1m
--B007190544 LER 80-059/03L-0 on 800617, approx 2-h after performing suppression chamber to drywell vacuum breaker sys operability test closed indicating light for valve IT48-F323F found extinguished Cause unknown Testing continues NIX,R T Georgia Power Co 80/07/03 2pp
                                                                                                                                                                                                                      --8007210492 LER 80-078/03L-U on 800630 & O/01, during hot standby aperation, primary containment oxygen concentration exceeded limit Coused by reactor bidg to torus vacuum breaker valve opening & oxygen analysers not callbr Monitoring increased BAXLEY, S X Georgia Power (a 80/07/19 2pp
8007150476 Forwards LER 80-064/03L-0
MANRY, M Georgia Power Co 80/07/08 1p
                                                                                                                                                                                                                      8007220514 Forwards LER 80-080/00T-0
MANRY-M Georgia Power Co 80/07/17 ip
--8007150508 LER 80-064/03L-0 on 800513, during startup, reactor core isolation cooling sys initiated to maintain reactor water isosolibut failed to respond to speed control Caused by EGR not responding & ilmit switch being out of adjustment NIX, R T Georgia Power Co 80/07/08 2pp
                                                                                                                                                                                                                       reactor water cleanup in normal operation,water found
coming from cleanup line insulation, due to crack in heat
affocted unne of spool piece Cause unknown Piece replaced
COOGIN.C L Georgia Power Co 80/07/17 2pp
8007150666 Forwards LER 80-066/03L-0
MANRY, M Georgia Power Co 80/07.
                                                                                                                                                                                                                       8007280448 Forwards LER 80-067/03L-0
                                                                                   80/07/08 1p
                                                                                                                                                                                                                                                                                                      60/07/17 1p
                                                                                                                                                                                                                                                     Georgia Power Co
                                                                                                                                                                                                                       --8007280449 LER 80-067/03L-O on 800629 during diesel generator manual start procedure. B generator tripped Cause undertermined Probable raute is spurious alarm or crankcase gressure Generator proved operable & returned to svc NIX.R T Georgia Power Co 80/07/17 2pp
--B007150574 LER B0-056/03L-0 on B00615, diesel generator 10 declared inoperable when low air pressure alarm received w/reactor in run mode Caused by valves faiting in unloaded mode. Unloader valves replaced & air receivers returned to proper pressure NIX,R T Georgia Power Co B0/07/08 2pp
8007170382 Forwards LER 80-058/03L-0
MANRY, M Georgia Power Co 80/07.
                                                                                                                                                                                                                      B007280445 Forwards LER 80-075/03L-0
MANRY.M Georgia Power Co 80/07
                                                                                   80/07/08 1p
                                                                                                                                                                                                                                                                                                      80/07/22 10
~~8007170337 LER 80-058/03L~0 on 800616 three addi control rod driveline accumulators deciared inoperable Caused by hydraulic control units not maintaining nitrogen pressure due to cartridge valve iCil-Fiil leaking at stem packing NIX.R T Georgia Power Co 80/07/08 2pp
                                                                                                                                                                                                                       --8007280446 LER 80-075/03L-0 on 800626, w/mode switch in run, primary containment temp recorder, [147-R61], found to be intermittently fealing to print Caused by commutation motor gearbox fealibre Balancing arm megnetic switch tegaired NIX.R T Deorgi. Power Co. 80/07/22 2pp
8007170392 Forwards LER 80-068/03L-0
MANRY,M Georgia Power Co 80/07/08 ip
                                                                                                                                                                                                                      B007280572 Forwards LER 80 081/03L-0
MANRY, M Georgia Power Co 89/07/22 10
                                                                                                                                                                                                                      --BOO72BO56B LER 80-(B)/031-0 on 800/05 w/mode switch in run.drgwell pressure recorder IT48-R60B found inoperative Redundant recorder IT48-R609 was operable Caused by component failure Transmitter repaired, recalibr & returned to svi.

NIX.R T Omorgia Power (o 80/0//22 ip
 --B007170408 LER 80-048/03L-0 on 800419, 1P33-R601 drywell dihydrogen/
           digide recorders observed reading abnormally high augent content Caused by water present in digide analyzer sample line Design change implemented NIX,R T Georgia Power Co 80/07/08 2pp
                                                                                                                                                                                                                      8007280629 Forwards LCR 80-07//07L-0
MANRY: M Georgie Power Co 80/07/RP 1p
8007170491 Forwards LER 80-073/03L-0
MANRY, M. Georgia Power Co. 80/07/08 1p
 --B007170463 LER 80-073/03L+0 on B00624.w/reactor at 100% power, dryweil to torus temp recorder noted not stamping or changing position Caused by faulty stepping advance & chart drive motors Repaired & replaced motors
NIX.R T Gaorgia Power Co 80/07/08 Ppp
                                                                                                                                                                                                                       ~~8007280640 LTR 60~077/03L O on Ann/0/08 during high reactor pressure instrumentation functional test % calibr, found that pressure switch 1021~ND248 actuated in excess of Tech 9pacs Caused by setpoint durif Suitch recalibr & successfully tested NIX/R T Quargia Power Co 80/07/22 Zpp
                                                                                                                                                                                                                      8007280682 Forwards 1ER 80-0/0/0/82-0
MANRY,M Georgia Power Go 80/07/22 1p
B007170481 Forwards LER 80-071/03L-0
MANRY, M Ogorgia Power Co 80/07/08. 1p
 --8007280640 IER 60-070/03 U on B00696, during hanger insp on class one piping, snubber 1141-HPSt H13 discovered to have oil leak Caused attributed to seal leakings on snubber laited snubber
```

NIX.R T Gentala Power to RO/07/22 200

- 107300372 Forwards LLR 80-074/03L-0 MANRY, M. Georgia Power Cu. B0/07/24 ip
- B007300513 iER 80-0/4/03L-O on B00626, following reactor scram reactor core isolation cooling failed to inject to reactor pressure vessel when manually started Laused by intermittent operation of NAMCO DI2006 limit switch or GE NFA relay COGGIN.C L Georgia Pawer Co B0/07/24 2pp
- DOKET 50-322 SHOREHAM NUCLEAR PRIVER STATION
- Application/construction stage documents & correspondence
- 007030239 Natification of 800702 meeting w'BWR licensing review group in Bethesda. MD to discuss consensus position on reactor see bidg open issue MILSON J N Licensing Branch I 80/06/18 9pp
- 007010397 Summary of 800613 meeting w/utils.KMC.Inc.OE.Bechtel.StW & Sargent & Lundy in Bethesda.MD re conscisus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Salie docket Status repts encl
 WILSON.J N Assistant Director for Licensing 80/06/19 46pp
- 007210176 Forwards NRC evaluation of GE tept.NFDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Bquares (SRSS) Nethod for Combining Dynamic Loads for Mark 11 Plants "Rept acceptable subj to certain roostraints MATTSDN.R J Davision of Safety Technology 80/06/25 3pp
- -8007210189 Inpital rept evaluation of NEDE-24010-P t Supple 1-3,
 "Technical Basis for Use of Square-Root-of-Sum-of-Squares
 (SRSS) Method for Combining Dynamic Loads for Mark II
 Plants "Rept succeptable o/exception of Criteria |
 * Mechanical Engineering Branch 80/09/31 8pg
- 007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISCHNUI-D G Division of Licensing 80/06/26 2pp
- cromments a minimum as produced delication who
- 007170475 Summary of B00m13 menting w/Mark 11 lead plant applicants re definition of T-quencher load spec following safety/ relief value authoriton Viewgraphs enti SU-T-M Containment Systems Branch B0/06/27 4pp
- 007230232 Summary of 800613 meeting w/Mark II lead plant applicants re methodology proposed by applicants to define T-quencher load spec following safety relief valve actuation New methodology will be applicable to all Mark II lead plants SU.T M. Generic Issues Branch. 80/06/27. 3pp
- 007170339 Notification of rescheduling of B00702 meeting w/BHR licensing review group in Dethesda.MD to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for 800709 WILSON.J N Assistant Director for Licensing 80/07/03 lp
- -8007170347 Natification of 800722 meeting w/RWR licensing review group in Bothesda.MD to discuss TNJ issues required for CL issuence
 - WILSON, J N Assistant Director for Licensing 80/07/03 ip
- ~8007170351 Notification of 800724 meeting w/BWR licensing review group in Bethesda.ND to introduce BWR licensing review group & present consensus positions for Power Sys Branch.Containment Sys Dranch & Equipment Qualification Branch
 WILSON.J N Assistant Director for Licensing 80/07/03 9pp
- NOO7210188 Forwards requests for addl info in connection w/util application for OL Info needed in areas of mechanical engineering.power sys & instrumentation & control TEDESCO.R L Assistant Director for Licensing 80/07/03 24pp
- 007230621 Summary of ROOMA meeting m/Mark II owners group in Bethesda, ND re land plant closure & long-term program Mods should be made to generic lead plant condensation oscillation by hugging not boundary loads Viewgraphs encl ANDERSON.C J. Generic Issues Brabch 80/07/03 57pp
- 1007150655 Submits comments on NUREC-0619, "DWR Feedwater Noiste & Control Red Drive Return Line Noiste Cracking " Mod should be made in Table ... "Routine Into Intervals" re two piston ring smals & Clad removal on Page is NDVARPO, J.P. Long Island Lighting Co. 80/07/08 3pp
- 3007240466 Notifargians of 800722 meeting w/util in Bethesda.MD to discuse status of non-TMI open resues WILSON, J. M. Licensing Branch I. 80/07/09 - 3pp

- B007230133 Notification of 800725 meeting w/BWR Licensing Review Group in Bethesda.ND to discuss concensus positions of BWR - Licensing Review Group on ICSB apen issues WILEDN-J N Licensing Branch 1 80/07/16 10pp
- B007250569 "Final Rept on Reactor Vessel Repair" * Long Island Lighting Co B0/07/17 120pp
- B007230458 Forwards "Design Criteria & Description. Technical Support Ctr " NOVARROJ P Long Island Lighting Co 80/07/21 1p
- --8007230462 "Design Criteria & Description Technical Support Ctr "
 + Long Island Lighting Co 11600 02 80/07/22 19pp
- B007250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago. II. to discuss lead Mark II plants chugging & C/Q load specs ANDERSON.C Generic Issues Branch 80/07/23 2pp
- F Socurity, medical, emergency & Fire protection plans
- 8007140519 Notification of 800801 meeting w/util in Silver Epring.MD re-evaluation of recent revisions to facility security plan WILSON, J N Licensing Branch 1 80/06/26 3pp
- Q Adjudicatory correspondence
- 8007030083 Notice of appearance in proceeding Certificate of Svc encl FARLEY-A F Long Island Lighting Co FARLEY,A F Hunton & Hilliams 80/06/12 3pp
- 8007070304 Response to NRC & Bhoreham Opponents Coalition 800604 stipulation Contentions 2 & 8 are adequately particularized Contentions 1 & 12 must be modified Contentions 7(a)(ii).10 & 11 inadequate Certificate of 9vc encl REVELEY,W T EARLEY,A F Long Island Lighting Co REVELY,W T Hunton & Williams 80/06/17 9pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protoction for electrical cables EISENHUT, D G Division of Licensing 80/06/25 87pp
- 8007020384 Drder rejecting NRC & Shoreham Dpponents Coalition 800606 stipulation as submitted on 800612 States status of OL proceeding Contentions 1.2.7(a)(ii), B.10 & 12 Joint request for sytemsion until 800606 granted BDMERS.C 8 Atomic Safety and Licensing Board Panel 80/06/26 3np
- 8007020606 Order accepting util, NRC & Buffolk County third stipulation re certain of Buffolk County contentions Agrees w/NRC 800611 interpretation of Footnote 2 BOWERS, E S Abomic Safety and Licensing Board Panel 80/06/26 ip
- 8007080204 Order admitting Shoreham Opponents' Coalition Contention 12. Subpart 3 in OL proceeding as within guidelines of Commission 800316 memorandum & order issued in TMI-1 restart proceeding. CLI-80-16 BOMERS. C.S. Atomic Safety and Licensing Board Panel 80/07/02 2pp
- B0070B0059 Forwards documents on loan basis in response to request made during Shoreham B00617 meeting TREE-NUREO-1200.BNL-NUREO-23364.NUREO/CR-0274 presently unavailable but will be provided when located W/o encl BCRDENICK.B M Hearing Branch 4 80/07/03 4pp
- B007i60601 Forwards LER printput re passive mechanical valve failures, in response to Dec 1979 request concerning County Contention 4a(xi) Forwards ACRB latest repts on generic issues re County Contention 3(a)(i) & (ii) M/o encl BORDENICK, B M Hearing Branch 4 80/07/11 2pp
- 8007170384 Motion to defer briefs re Commission 800620 policy statement, in response to ASLB 800626 order, until 801031.

 Process re particularization of contentions, should continue prior to writing briefs Certificate of Svc ancl REVELEY.W T Long Island Lighting Co REVELEY.W T Hunton & Williams, 80/07/11 7pp
- 8007160593 States no objection to applicant 800711 motion to deferbriefs on Commission 800620 statement!
 BDRDENICK.B M Hearing Branch 4 80/07/14 1p

1

H General correspondence

- 8007180042 Responds to 800123 ltr ro NRC approach to emergency planning around nuclear plants Commission endorsed NUREG-0394 for development of state & local radiological plans Exact configuration of zones will be decided during plant review DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/03 2pp
- --8007180047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed 10-mile radius is unworkable for people of Long Island Responsible plan should be developed DEHAN, J L. New York, State of 60/01/23 ip
- 8007210032 Respands to 800520 ltr re NRC reneging on agreement to send representatives to Suffolk County Legislature 800528 meeting Fiscal limitations & other priorities may occasionally prevent requested attendance
 EISCNHUT, D G Division of Licensing 80/06/13 1p
- BOD7240008 Forwards NUREO/CR-1215.NUREO/CR-1263 & NUREO/CR-0131.in response to 800617 verbal request Kemeny rept not available for distribution Cleanup EIS not yet issued NUREO-0662.Vols 1 & 2 & NUREO-0588 sent separately H/o encls EORDENICK.D M Hearing Dranch 4 80/07/22 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007090243 Forwards Amend 36 to OL application, submitted as Revision iB to FSAR Affidavit encl NDVARRO, J F Long Island Lighting Co 80/06/27 2pp
- ---B007090245 Revision 18 to FBAR, incorporating responses to NRC requests submitted in 1trs SNRC-465.-469.-473 & -480 & clarifying portions of FSAR * Long Island Lighting Co 80/06/27 275pp
- B00723057B Certifies syc of Amend 36 to OL application in form of Revision 18 to FBAR, on 800707 MORIN.J P Long Island Lighting Co B0/07/14 ip
- O. Inspection reports. IE Bulletins & corrospondence
- 8007140458 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/05/12 ip
- 8007010280 Forwards IE Info Notice 80~23, "Loss of Suction to Emergency Feedwater Pumps " No writton response required QRIER.O H Region 1, Philadolphia, Office of the Director 80/09/29 ip
- B007170283 Forwards IE insp Rept 50-322/B0-07 on B00422-24 No noncompliance noted. CARLSON.R.T Region i. Philadelphia, Reactor Construction & Engineering Support Branch B0/05/30 2pp
- --- 8007170288 IE Insp Rept 50-322/80-07 on 800422-24 No noncompliance noted Major areas inspected GC program for work progress, outstanding items & bulletins & circulars status NARROH, L. Region 1, Philadelphia. Office of the Director MCGAUCHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch 80/05/28 4pp
- 8007210571 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIER.B H Region i, Philadelphia, Office of the Director. 80/86/10 1p
- 8007140278 Forwards IE Bulletin 80-14, "Degradation of DWR Scram Discharge Vol Capability " No written response required CRIER, B. H Region 1, Philadelphia. Office of the Director 80/06/12 ip
- 8007280394 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 35(m)," No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/06/13, 1p
- 8007020509 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required. GRIER, B H Region i. Philadelphia. Office of the Director 80/06/20, ip

- 8007160704 Forwards II. Corrular 80-14, "Radioartive (ontamination of Plant Demineralized Moter Sys & Resultant Internal Contamination of Personnel " No written response required ORIER, D.H. Hegion i Philadelphia, Office of the Director 80/06/24 ip
- 8007160863 Ack receipt of 800602 ltr informing NRC of steps taken to currect violations noted in IE Investigation Rept 50-322/79-32 (ACC) (ACC)
- --8007160967 Responds to NRC (30042H Itr re violations moted in IE Investigation Rept 50-3.2//9-24 Corrective actions defective welds were identified & removed WDFFORD.A H Long Island Lighting Co 80/06/02 2pp
- 8007210199 Forwards JE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.D H. Region J. Philadelphia. Office of the Director 80/06/25 | 1p
- 8007230128 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 % 11%2 Pressure Transmitters W/Eithur A or D Output Coder " Written response required IE Circular 80-16 also encl No written response required GRIERA H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- B007210033 Ack receipt of 800416 ltr informing NRC of steps taken to correct violations noted in 1E. Insp. Rept 30-322/79-07 Analysis of raceway/cable steps atten requested due to continued noncompliance CARLSON, R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/01 2pp
- --8007210040 Responds to NRC 791226 ltm re violation noted in IE Insp. Rept 50-322/79-07 Corrective action independent analysis performed to ensure prevention of feather shuddown or decay heat removal Takes exception to insp finding NOVARRO.JP Long Island Lighting Co. 80/04/16. 3pp
- 8007310527 Submits summary of events in response to 1E Bulletin 80-17 LPC1 inverter R44 5003 declared inoperable twice Normal supply breaker to 4 kV bus 2f tripped.Placing bus on alternate feed MANRY.M Georgia Pawer Co. 810/07/14 2pp
- ii Reportable occurrences. LERs to related correspondence
- B007020066 Ack receipt of 700822 final significant deficiency rept re OE 4160 volt rircuit breaters CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 78/09/14 2pp
- --B007020073 Final significant deficiency rept re failure to electrically close circuit breaker Caused by wearing of driving pawl sleeve bearing All breaker mechanism Tuf-loc sleeve bearings will be replaced widownhow-bronze bearings BURKE.Y J. Long Island Lighting Co. 78/08/22 3pp
- 8007290448 Part 21 rept re putential interference in full function of Borgen-Paterson strut assembly w/Parific Scientific Co mechanical shock arrostor (uslumers will be notified of affected items & recommended solution BECKSTED.W F Bergen-Patterson Pipe Support Corp 80/06/20 Spp
- B007140390 Followup deficiency rept to louse limit switches on GC circuit broakers Caused by mounting screws backing out Screws will be secured w/std strength lock-tite & insp will be revised NOVARRO, J.P. Long Island Lighting Co. 80/07/01 3pp
- A Application/construction *tige documents & correspondence
- B007080343 Notification of 800623 meeting w/util in San Luis Opispa.CA to discust task action plan item
 BUCKLEY.B C Licensing Branch 2 80/06/20 4pp
- 8007020374 Forwards nonproposetary versions of previously submitted general Westinghouse proprietary little to support position on guide tube wear characteristics Requests administration of receipt CRANE, P.A. Parific Gas & Flectric Co. 00/06/23 lp

8007230001 Forwards statement of pulicy re requirements to be met for current OL applications.as derived from NUREG-0A60 & found in NUREG-0694 EISENHUT,D G Division of Licensing 80/06/26 2pp

B007070153 Forwards Revision 1 to "Description of Sys Interaction Program for Saismitally-Induced Events," originally submitted B00527 CRANE,P A Pacific Gas & Electric Co 80/07/01 1p

--8007070206 Revision 1 to "Description of Sys Interaction Program for elsmically-Induced Events " Pacific Gas & Electric Co 80/06/i0 79pp

8007160392 Forwards Std Order for DOE Work, "Sys Interaction Support for Diablo Canyon," issued to iLL ROSS.D F Division of Systems Integration FIN A-0248-0 80/07/07

--8007160395 9td Order for DOE work "Sys Interaction Support for Diable Canyon," issued to LLL GRENIER, B Office of Standards Development, Director FIN A-0248-0 80/07/01 App

8007230029 Notification of B00718 meeting w/util in Bethesda.MD to review auxiliary feedwater sys reliability study BUCKLEY.B C Licensing Branch 3 80/07/08 4pp

8007280089 Summary of B00617-19 site visit w/NRC.util & two intervenors re audit of sys interaction program for seismically-induced events Program is sound & can be satisfactorily completed Independent welldown description enci
THOMAS.C O Systems Interaction Branch 80/07/09 Bpp

B007i60520 Forwards draft Operating Procedure OP-30, "Anticipated Transient W/n Trip," per AC Thadani request Procedure should not be considered part of docket file supporting OL application CRANE,P A Pacific Gas & Electric Co 80/07/i0 ip

--8007160521 "Anticipated Transient W/o Trip," mmergoncy operating procedure * Pacific Qas & Electric Co BO/06/07 5pp

800723020B Discusses augmented low power startup test program for near-term OL applicants Each applicant must perform tests similar to TVA proposed program President Carter 791207 statement on Komeny Commission rept enci EISENHUT.D G Division of Licensing 80/07/ii 6pp

8007180340 Forwards Revision 2 of "Description of Bys Interaction Program for Beismically-induced Events " CRANE, P A Pacific Gas & Electric Co 80/07/15 ip

--8007180344 Revision 2 to "Description of Sys Interaction Program for Seismically-Induced Events" * Pacific Gas & Electric Co 80/07/09 77pp

8007250550 Notification of 800725 meeting w/uti) in Bethesda.MD to discuss auriliary feedwater sys Meeting originally schedules for 800718

BUCKLEY. B C Licensing Branch 3 80/07/47 5pp

B007310397 Advises that R McMeilen response to Question 9 of ASLAB-398 accurately reflects USGS position Ambiguities in location of carthquake reguire conservative assumption that all faults have earthquake potential MORRIS,R H Interior,Dept of, Geological Survey B0/07/29 tp

eport (SER), suppls & correspondence

in 5pp

irector NUREG-0675 89

on plans

ning & qualification

/1i 1o

G Adjudicatory correspondence

B007030040 Request for participation in security plan hearing per ABLB 791116 order admitting State of CA in OL proceeding Participation will assist in adequacy & workshility assessments Notice of appearance & Certificate of Svc encl BROWN, H H , KLINE, J A California, State of BROWN, H H Hill Christopher & Pallilips B0/06/11 9pp

8007:40026 Act receipt of Commission 8006:11 memorandum & order, CLI-80-24, on behalf of San Luis Obispo Mothers for Peace Adheres to prior position re Commissioner Hendrie participation in all aspects of OL proceeding re solsmic & safety issues

JONES, V 1 Jones, Grey & Bayley 80/06/18 2pp

800710019B Expresses appreciation for NRC permission allowing joint intervenor representatives to participate in 800617-19 sys interaction audit at util NRC has demonstrated willingness to assure public participation Related correspondence FLEISCHARER, D S Fleischaker, D S 80/06/25 1p

80073i0243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D @ Division of Licensing 80/06/25 89pp

6007300419 Notice of appearance in proceeding Certificate of Svc encl GEDRGIOU, B S Colifornia, State of 80/06/30 4pp

8007070123 Advises of stipulation in DL proceeding, eliminating legal argument re wording of effidavit of nondisciosure & public dissemination of info Queernor Brown of State of CA did not take part in stipulation TOURTELLOTTE. J Hearing Branch 4 JONES, Y , NORTON, B Pacific Gas & Electric Co 80/07/02 2pp

6007ii0002 Order granting extension until 600722 for Commission to alect to review decision on enforcement action request, ND-80-22 HOYLE, J C Office of the Secretary of the Commission 80/07/08

BOQ7180405 Motion for OLs permitting fuel loading initial criticality process & iow power testing Preposed operation may be conducted during appeal from ALBG 790787 partial initial decision W/documentation.affidavit & Certificate of Svc GRANE, P A Pacific Ons & Electric Co OCHR.A C Bneil & Wilmer NORTON. II Bruce Norton 80/07/14 13pp

B007220092 Memorandum & order amending & reissuing ABLAB B00403 protective order re security plon Governor of CA request for participation as interested state granted w/certain conditions Sets timetable for future proceedings
BIBIOP.C J Atomic Safety and Licensing Appeal Panel 80/07/15

--8007220103 Amended protective order permitting limited access to Ban Luis Obispo Mothers for Peace & Governor of CA re security plan info Amended affidavit of nondisclosure encl BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/07/15.

B00723050B Request for reconsideration of ASLAB B00624 decision.ALAB-59B.or certification of M Trifanac & E Luco testimony on 791019 Imperiol Vailey earthquake Vrges appropriation of Funds to facilitate testimony Certificate of Byc encl FLEISCHAKER.D B. JOHNSTON.M P. PHILLIPB.J San Luis Obispo Mothers for Peace 80/07/17 App

8007310466 Notice of PC Valentine & YI Janes withdrawal & WA Baldwin designation as lead counsel in proceeding Certificate of 9vc VALENTINE, P.C., JONES, Y I San Luis Obispo Mothers for Peace B0/07/18

800723D536 Motion to change lead counsel designation from JR Tourtellotte to MJ Dimstead Notices of MJ Dimstead & LL Bwartz appearances, JR Tourtellotte withdrawal & Cortificate of Svc encl OLMSTEAD, W J . TOURTELLOTTE, J Hearing Branch 4 80/07/21 6pp

8007300110 Notice of appearance in proceeding LANPHER, L C California, State of LANPHER, L C Hill Christopher & Phillips 80/07/21 ip

1

, 1

- 8007250429 Statement in support of joint intervenors' 8007;7 request for reconsideration of ALAB-598,or for certification of question re Mihailo.Trufunac & Enrique independent views, to Commission Urges funding for Trifunac & Luco BROWN,H H , KLINE.J A , GEORGIOU,B S California, State of 80/07/24 2pp
- BD07300096 Request by joint intervenors for extension until 800804 to respond to applicant motion for low power testing license Counsel out of town Certificate of Svc encl FLEISCHAKER. D S San Luis Obispo Mothers for Peace FLEISCHAKER. D S Fleischaker, D S JOHNSTON, M P Center for Law in the Public Interest 80/07/25 4pp
- B00731046i Discusses handling & delivery of sensitive security mat1 between parties DLMSTEAD.W J Hearing Branch 4 80/07/28 2pp

H General correspondence

- 8007140024 FOIA request for NRC insp rept for Atomics Intl,info concerning TM1 incident & status of licensing proceedings for facility Newspaper articles encl MILLER.T Affiliation Unknown 80/05/08 App
- 8007140016 Ack receipt of encl & informs recipient about progress & expectation of required cultural & historical mitigation program Ltr forwarded to NRC for consideration NIELSEN, A D Interior, Dept of 80/06/18 3pp
- 8007010063 Expresses regret that failure to add Society for Environ Awareness to mailing list for weekly public announcements on facility, resulted in necessity to duplicate request Addition made to distribution list

 INORAM.F L. OPPice of Public Affairs 80/06/20 1p
- 8007140021 Responds to FDIA request for NRC insp rept re Atomics Intl. info concerning TM1 incident & status of licensing processings for facility Forwards of Stein 800228 memo. Sept 1977 EIA & 770980 BER W/EIA & BER caver sheets only DENION.H R Office of Nuclear Reactor Regulation, Director 80/06/23 2pp
- 8007010457 Opposes granting license for low level testing for util, due to health & safety concerns re emergency planning, radiation monitoring & safety iseuss based on TMI No testing should be allowed until conversion possibilities explored CLUCAS, J A League of Momen Voters of San Luis Obispo, CA BO/Q6/24 ip
- 8007090218 Requests that NRC deny OL to facility Too much emphasis placed on possible earthquakes along Hosgri Fault & not enough concern on entire area of instability Conditions create distinct possibility for furmation of more volcances SNAPP, C Affiliation Unknown 80/07/01 lp
- BOO7250277 Responds to BOO605 ltr re RH Leddy concerns about proximity of Hosgri Fault to site & ability of facility to withstand severa earthquake Fault is 3 5 miles from mite Matter of smissic situation currently pending before ASLAB DIRCKS.W.J. Office of the Executive Director for Operations 80/07/02 App
- ---8007250284 Requests response to entl RH Leddy concerns about proximity of site to Hosgri Fault LAGDMARBINO,R J House of Rep , Foreign Affairs 80/06/05 3pp
- 8007270647 Urges that NRC dany DLs for facility due to proximity to Hoepri fault & to protect health, safety & welfare of people of CA ALLEN, B D Affiliation Unknown 80/07/21 2pp
- G. Inspection reports: IE Bulletins & correspondence
- 8007280697 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Loss of power to Class IE buses is audibly & visually indicated by control room annunciator CRANE,P A. Pacific Gas & Electric Co 80/04/15 12pp
- BOO7R40187 Responds to IE Bulletin 80-04, "Analysis of PWR Main Stram Line Break W/Continued Feedwater Addition " Review results indicate no potential for containment overpressure or worsening of return to power response CRANE,P A. Pecific Gas & Electric Co 80/04/20 2pp
- 8007020242 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required ENGELKEN,R.H Region 5. San Francisco. Office of the Director 80/05/28 ip

- B007220237 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required FNGELKEN,R H Region 5. San Francisco. Office of the Director 80/66/10 1p
- 8007290006 Forwards 16 Info Notice 80-20. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required ENOELKEN.R H Region 5. San Francisco. Office of the Director 80/06/13 ip
- 800725065B Responds to IE Iluiletin 79-25, "Failures of Mestinghause BFD Relays in Safety-Related Sys " Subj relays not used or planned for use in safety-rolated sys at plant CRANE,P A Pacific Gas 'v Electric Co 80/06/16 ip
- 8007030017 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power" Written response required ENGELKEN,R H Region 5, San Francisco Office of the Director 80/06/18 ip
- 8007020474 Forwards IE Cirrular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Cirrulation Cooldown " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/20 | Ip
- 8007180287 Forwards IE Circular BO-14, "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/24 ip
- 8007.230385 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters Wielther A or D Dutput Codes "Written response required IE Circular 80-16 also encl No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80.00.27 in
- BOO73002BO Responds to IE Bulletin BO-03 re vacuum damage to chemical vol control tank sys All five tanks protected against failure under vacuum cenditions RCS drain tank designed to withstand external pressure of 15 psig CRANE.P A Pacific Gas & Electric Co 80/07/07 2pp
- 8007310321 Ferwards IE Insp Repts 50-275/80-14 & 50-323/80-07 en 800601-20 No mencompliance noted CREWG.J t. Region 5. San Francisco, Reacter Operations Nuclear Support Branch 80/07/10 2pp
- --8007310327 IE Insp Repts 50-275/80-14 & 50-323/80-07 on 800601-20 No noncompliance noted Major areas inspected preeperational testing, plant tour, fuel storage, operator training & witnessing of testing in progress
 YOUNG, T., BAGAOLID, M. Region 5, San Francisco, Office of the Director STERNERGO, DM Region 5, San Francisco, Reactor Operations Nuclear Support Dranch 80/07/03 3pp
- DOCKET 50-024 BRUNSWICK STEAM ELFCIRIC PLANT, UNIT 2 F Security, medical, emergency thre protection plans
- B007010324 Informs NRC that util will submit revised emergency plan in Aug 1980 Implementing procedures for emergency plan will be developed by B01201 & complete plan implemented by B10101 per NURG-0654 requirements

 UTLEY.E C Carolina Power & Light Co 80/06/27 ip
- 8007010342 Advises that add1 info re safeguards contingency plan which was requested in NRC 800327 itr will be submitted by 800801.
 UTLEY-E C Carelina Power & Light Co 80/06/27 tp
- 8007170555 Notifies that intuke structure basement areas at Pacilities have been selected as possible test budy to conduct tests on fire protection sys in response to NRC 800523 order Requests agreement to participate in program EISENHUT. D O Division of licensing 80/07/08 Opp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition, sought action re fire protection for electrical cables EISENHUT, D.O. Division of tirensing 80/04/25 89pp.

H General correspondence

- 8007020198 Responds to 800516 ltr re Mudiu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Director for threat to public DIRCKS N U Office of the Executive Director for Operations 80/09/18 5bb BINCK8 M 1 0
- --BOD702021/ Requests response to encl Kudiu Alliance 800512 ltr commenting on ability of util to safely utilize nuclear ANDREWS, 1 House of Rea 80/05/15 2on
- P Operating license stage deluments & correspondence
- 8007230028 Summary of 800707 meeting w/Mark I owners group in Betheada. MD, we revisions to MBC acreptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007010423 forwards responses to NRC 600507 request for evaluation of applicability to facilities of GE 600221 responses to concerns provided by ACRS consultant C Hichelson, re-add 1 MH-2 related requirements

 UTLEY, E.F. Carolina Power & Light Co. 80/06/27 App
- G007210415 Discusses 790531 commitment to installation of mods required by Mark I containment program during 1980 & 81 Complete incorporation of NRC input into GE load definition rept scheduled for mid-Jul 1980 UTLEY.E E Carolina Power & Eight Co 80/07/14 2pp
- 8007290723 Submits add1 info re adequacy of station electrical distribution sys voltage in response to NRC 800916 Itr II for incomplete Items 2 & 3 will be submitted by 801024 & UTLEY. E E Carolina Pouler & Light Co B0/07/24 7pp
- 8007290163 'Electrical, Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals. Bruniwick Steam Electric Plant Unit 2 " UDV.A C E600 Idaho.inc FIN A-6796 8007290163 80/07/31 13pp
- 9 Inspection ruports. IE Bulletins & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required D'REILLY, J P Region 2 Atlanta, Office of the Director 80/05/08
- 8007140489 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spergers " Written response required B'REILLY.J P Region 2. Atlanta, Office of the Director B0/05/12
- 8007020187 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs 'No written response required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/28
- 8007010179 Forwards IF Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps ' No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/05/29
- 8007170420 Forwards 1E Insp Repts 50-324/80-16 % 50-325/80-19 on 800512-16 No poncompliance noted LEWIS.R C Region 2. Atlanta Reactor Operations Nuclear Support Branch 80/08/06 2pp
- --8007170429 IE Insp Repts 50-324/80-16 & 50-325/80-19 on 800512-16 No own/10ner to insp Kepts 30-34480-16 to 50-32580-19 on 800512-16 No noncompliance noted Major areas inspected maint surveillance & calibr of Tech Spec-related equipment & support equipment MESSIT() B R Region 2. Atlanta. Office of the Director UPRIGHT, C R Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/05 6pp
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/10
- 8007140289 Forwards IE Dulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability" Hritten response required O'REILLY J P Region 2. Atlanta, Office of the Director BO/06/12 2pp

- 8007020745 Forwards 1E Rulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Luss of Offsite Power" Written response required D'REILLY./P Region 2, Atlanta, Office of the Director 80/06/18
- B007020440 Forwards IE Circular 80-15, "Loss of Roactor Coolant Pump Cooling & Natural Circulation Cooldown" No written rosponse required required O'REILLY, J P Region 2. Atlanta, Offica of the Director
- B007100354 Ack recorpt of B00610 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-324/80-10 & 50-325/80-11 MRPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/24 ip
- ---8007100367 Atk receipt of 800512 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 30-324/80-10 & "0-325/80-11 Per 800522 talcon, supplemental response should be provided by 800613 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/23 lp
- ~-B007100377 Responds to NRC B00418 ltr re violations noted in IE Insp Repts 50-324/60-10 % 50-325/80-11 Corrective actions diesel engine insp was purformed by manufacturer Periodic test implemented & scheduled for fire doors TOLLISON, A C Carolina Power & Light Co 80/05/12 4pp
- --8007100384 Forwards IE Insp Repts 50-324/80-10 & 70-325/80-11 on 800331 & 0401-03 & notice of violation MURPHY.C E Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/18 2pp
- --B007100375 Notice of violation from insp on B00331 & 0401-03
 * Region D. Atlanta, Office of the Director B0/04/18
- --8007100378 Notice of deviation from insp on 800331 & 0401-03 * Region 2, Atlanta, Office of the Director 80/04/18
- --B007100413 IE Insp Repts 50-324/B0-10 % 50-325/B0-11 on 800331 & 0401-03 Noncompliance noted inadequate surveillance procedures for fire protection sys & inadequate review of fire protection Tech Spec violations
 CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch MILLER, W H Region 2. Atlanta. Office of the Director 80/04/18 9pp
- 8007160800 Forwards IE Circular 80~14, "Radioactive Contamination of Plant Demaneralized Mater Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P. Rogion 2, Atlanta, Office of the Director 80/06/24
- B007010425 Forwards corrected Pages II-35 & II-36 for revised inservice insp program for pump & valvo testing.submitted on 800527 UTLEY.E E Carolina Power & Light Co 80/06/25 ip.
- --8007010431 Corrected Pages 11-35 & II-36 for "Inservice Insp Program, Program & Value Testing " * Carolina Power & Light Co 80/06/25 2pp
- B007230220 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/1 80/06/27
- 8007220260 Responds to IR Bulletin 80-10 Routing sampling, analysis & monitoring program established to promptly identify contaminating events that could lead to uncontrolled releases to environ FURR.8 J Carolina Power & Light Co 80/07/01 tp
- 8007170516 Responds to 16 Aulletin 80-08. "Examination of Containment Liner Penetration Welds" All final wolds radiographed & results of const nondestructive examination acceptable as FURR. B J Carolina Power & Light Co 80/07/03 2pp
- GOO7240187 Responds to BOO611 notice of violation & notice of proposed imposition of civil genalties Boiler removed from svc for decontamination, repair & mods Radiological operating limits stabilished Civil penalties fee encl FURR.8 J Carolina Power & Light Co 80/07/03 7pp

- ---8007240196 Responds to NRC request for info re 780426 occurrence which resulted in onsite contomination of area around radwaste bldg Calculations indicate apprex 200 galions of waste was drawn into steam line TOLLISON, A C Carolina Power & Light Co 78/04/28 2pp
- 8007310449 Forwards response to NRC 800611 notice of violation & notice of proposed imposition of civil penalties re onsite contamination of area around radwaste bldg Corrective actions boiler decontaminated & repaired Penalty fee encl FURR.B J Carolina Power & Light Co 80/07/03 3PP
- 8007280iii Forwards response to IE Bulletin 80-ii Response includes general arrangemont drawings indicating masonry walls Also forwards data sheets re each wall W/o oncis FURR'S J Caroline Fower & Light Co 80/07/07 ip
- 8007250296 Responds to IE Builetin 80-17, "Failure of Control Rods to Fully Insert " No water observed in screen discharge vol Timing of vent & drain valves completed FURRY,8 J Carolina Power & Light Co 80/07/10 2pp
- 8007190492 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions ISI program reorganized & future submittals will be accurate & complete GA Procedure 23 written & approved to correct ltems 2 & 4 TOLLISON, A C Carolina Power & Light Co 80/07/11 3pp
- 8007300561 Responds to IE Bulletin 80-13 No crecking indications noted in Unit 1 care spray sparger or in-vessel piping Unit 2 inspuill be performed at next refueling butage FURR.B J Garolina Power & Light Co 80/07/15 lp
- B00/310206 Bubmits supplemental response to IE Bulletin 80-07 re DWR jst pumps No Indications discovered either by visual or ultrasonic insp FURR.B J Carolina Power & Light Co 80/07/15 lp
- 8007310306 Responds to IE Bulletin 79-03A. "Longitudinal Weld Dufects in ASME SA-312. Type 304 Stainless Steel Pipe "Piping specs do not permit use of A-312. Type 300 series fusion weldod pipe in safety-related sys FURR. D J Ceroline Power & Light Co 80/07/15 ip
- R Pariodic operating reports & related correspondence
- 8007110405 Forwards monthly operating repts for June 1980 TOLLISON, A.C. Carolina Power & Light Co 80/07/03 2p
- --B007i10404 Monthly operating repts for June 1980 WILLIS,E Carolina Power & Light Co 80/07/03 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007020334 Forwards LER 80-046/01T-0
 TOLLISON, A.C. Carolina Power & Light Co 80/06/24 ip
- --8007020361 LER 80-046/01T-0 on 800611, while performing insps per IE Bullstin 79-01B, aplices connecting nuclear grade cables to solenoid pigtail leads for valves found not environmentally qualified Nuclear grade splices being installed TOLLISON, A C Carolina Power & Light Co 80/06/24 2pp.
- 8007180632 RO 2-80-47 while replacing nonqualified splices connecting mafety relief valve splonaid pigtails to nuclear grade cable, discovered that pigtails on splenoids were brittle & that insulation cracked when handled Splenoids unqualified TOLLISON, A C Carolina Power & Light Co 80/06/24 1p
- 8007020560 LER 79-107 has been cancelled * Caroline Fower & Light Co 80/07/01, 1p
- 8007020363 LER 79-108 has been cancelled % Caroline Power & Light Co. 80/07/01 i
- 8007140375 Forwards LER 80-047/01T-0
 TOLLISON: A C. Carolina Power & Light Co 80/07/08 ip
- ---8007140399 LER 80-047/01T-0 on 800624 while replacing nonqualified aplices connecting safety relief valve solenoid pigtails to nuclear grade cable, brittle pigtails discovered Caused by adverse reaction to tape address solenoids replaced TOLLISON, A C Carolina Power & Light Co. 80/07/08. 2pp
- 8007220464 Forwards LER 80-048/03L-0 TOLLISON A C Carolina Power & Light Co 80/07/16 ip

- --8007220470 LER 80-040/03L O on 800623 low level switch 2-021-LIS-NO31Ai would not reset when hormal reactor water level was simulated Coused by stuck contacts Defective switch replaced & calibr TOLLISON.A C Curolina Power & Light Co 80/07/16 ip
- BOO/22092) RO 1-80-59 confirms 800716 teleon re notification by GE of incorrect use of total peaking factor for adjusting gain of average power range monitors Caused by incorrect ref value. Tech Spec values to be changed TOLLISON, A C. Carolina Power & Light Co. 80/07/1/ 3pp
- 8007250334 Forwards LER 80-049703L-0 TULL150N, A C Cafolina Power & Light Co 90/07/17 ip
- --8007250341 LER 80-049/03L-0 on 800701 during performance of high drywell pressure channel pressure & functional test, technicians found pressure suitch 2-(72-98-80028 actuating out of tolerance Caused by instrument drift TOLLISON. A C Garulina Power & Light Co 80/0//1/ 1p
- DOCKET 30-325 BRUNSWICK STEAM CLECTRIC PLANT, UNIT 1

 F Security, medical, emergency % fire protection plans
- B007010324 Informs NRC that util will submit revised emergency plan in Aug 1980 Implementing procedures for emergency plan will be developed by 801201 & complete plan implemented by 810101 per NUREO-0654 requirements

 UTLEY.E E Carolina Power % Light fo 80/06/27 ip
- 6007010342 Advises that add1 info re safeguards contingency plan which was requested in NRC 600527 Itr will be submitted by 800801
 UTLEY,E E Carolina Power & Light Co 80/06/27 In
- 8007170959 Notifies that intake structure basement areas at facilities have been selected as possible test subj to conduct tests on fire protection sys in response to NRC 800523 order Requests agreement to participate in program CISENHUT, D Ø Division of Licensing 80/07/08 3pp

O Adjudicatory correspondence

- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 760502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action for filectrical cobles EISENHUT, D G Division of Liconsing 80/06/25 89pp
- H General correspondence
- 8007020198 Responds to 800516 ltr is Kudiu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public DIRCKS.W J Dffice of the Executive Director for Operations 80706/18 2pp
- --B007020217 Requests response to encl Kudio Alliance 800512 ltr commenting on ability of util to safely utilize nuclear power ANDREMS, I House of Rep 80/05/16 2pp
- P Opprating laconse stage documents & correspondence
- 80072J0028 Summary of 800207 meeting st/Mark I owners group in Bethesda-MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mart I containment long-term program GRIMES, C T Plant Systems Branch 80/02/21 3lpp
- G007010416 Confirms B00619 confirence tall w/BML NRC, GE & util re Fuel Cycle 3 Util will perform startup physics testing on Unit 1 during startup from current outage GE has confirmed that both units are equipped w/thermal power monitors

 UTLEY.C E Carolina Power & Light Co 80/06/25 2pp
- 8007010423 Forwards responses to NRC 800507 request for evaluation of applicability to facilities of GE 800221 responses re concerns provided by ACRS consultant, C Michelson, re add1 TM1-2 related requirements UTLEY.E E Carolina Power & Light Co 80/06/27 App
- 8007140605 Forwards Amend 29 to Liten-e DPR-71, safety evaluation & notice of issuance & availability
 IPPOLITO.T A Operating Reactors Branch 2 80/07/01 4pp

- -8007140614 Amend 29 to License DPR-71, changing Tech Specs to establish revised safety % operating limits for Cycle 3 operation t safety relief valve pressure settings to provide min nominal lift setting differential of 20 ps; IPPOLITO.T A Operating Reactors Branch 2 80/07/01 23pp
- -8007140418 Safety evaluation supporting Amend 29 to License DPR-71
 * Operating Reactors Branch 2 80/07/01 10pp
- -8007140624 Notice of issuance & availability of Amend 29 to License IPPOLITO, T A Operating Reactors Branch 2 80/07/01 2pp
- 007210415 Discusses 790931 commitment to installation of mods required by Mark 1 containment program during 1980 & 81 Complete incorporation of NRC input into GE load definition rept scheduled for mid-Jul 1980 UTLEY.E E Carolina Power & Light Co 80/07/)4 2pp
- 007240427 Forwards corrected Page 3/4 2~7 of Tech Specs attached to 800701 Amend 29 to License DPR-71 Amend should ref Fuel Type PEDRB265H Also forwards corrected safety evaluation to Amend
- IPPOLITO, T A Operating Reactors Branch 2 80/07/15 3pp
- -8007240433 Revised page to Amend 29 to License DPR-71, correcting ref to Fuel Type P80R8245H IPPOLITO.T A Operating Reactors Branch 2 80/07/15 1p
- -BD07240441 Corrected safety evaluation supporting Amend 29 to License DPR-71 Corrects incorrectly numbered pages

 * Operating Reactors Branch 2 80/07/01 lipp
- 007290723 Bubmits addi info re adequacy of station electrical distribution sys voltage, in response to NRC 800516 Itr Info for incomplete Items 2 & 3 will be submitted by 801024 &
- 0926, respectively UTLEY, E E Carolina Power & Light Co 80/07/24 7pp
- 007250306 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals Brunswick Steam Electric Plant Unit : " UDV.A C EG&G Idaho.Inc FIN A-A256 B007250306 B0/07/31 13pp
- Inspection reports, IE Bulletins & correspondence
- 007240il3 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/QB,
- 007140489 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers " Written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/12
- 007020187 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 007010179 Forwards 1E Info Nutice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY: J P Region 2. Atlanta, Office of the Director 80/05/29
- 007170420 Forwards lE Insp Repts 50-324/80-14 & 50-325/80-19 on 800512-16 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/06 2pp
- -8007170427 IE insp Repts 50-324/80-16 & 80-325/80-19 on 800512-16 No noncompliance noted Major areas inspected maint surveillance & calibr of Tech Spec-related equipment & support equipment MESSITY BR Region 2. Atlanta, Defice of the Director UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/06/05 App
- 107220043 Forwards IE Info Notice 80-24. "Evaluation of Contractor GA Programs " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director B0/06/10
- 007140289 Forwards JE Bulletin BO-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/12

- 8007020745 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/18
- 8007020440 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/20
- G007100396 Ack receipt of 800610 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 80-324/80-10 & 50-325/80-11 HARPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/06/24 ip
- --8007100367 Ack receipt of 800512 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-10 & 50-325/80-11 Per 800522 telcon, supplemental response should be provided by 8000613
 MURPHY, C E Region R. Atlanta, Reactor Construction & Engineering Support Branch 80/05/23 Ip
- --B007100377 Responds to NRC B0041B ltr re violations noted in IE
 Insp Repts 50-324/80-10 & 50-325/80-11 Corrective actions
 diesel engine insp was performed by manufacturer Periodic
 test implemented & scheduled for fire doors
 YOLLISON.A C Carolina Power & Light Co B0/05/12 4pp
- --B007100384 Forwards 1E Insp Repts 50-324/00-10 & 50-325/80-11 on B00331 & 0401-03 & notice of violation MURPHY.C E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/04/18 2pp
- --8007100395 Notice of violation from insp on 800331 & 0401-03 * Region 2, Atlanta, Office of the Director 80/04/18
- --B007100398 Notice of deviation from insp on B00331 & 0401-03 * Region 2, Atlanta, Office of the Director B0/04/18
- --8007100413 IE Insp Repts 50-324/80-10 & 50-325/80-11 on 800331 & 0401-03 Noncompliance noted inadequate surveillance procedures for fire protection sys & inadequate review of fire protection Tech Bysec violations CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch MILLER.H H Region 2, Atlanta, Office of the Director 80/04/18 9pp
- B007160B0D Forwards IR Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel * No written response required O'REILLY.J F Region 2, Atlanta, Office of the Director 80/06/24
- BG07010425 Forwards corrected Pages II-35 & II-36 for revised inservice insp program for pump & valve testing, submitted on 800527. UTLEY.E E Carolina Power & Light Co 80/06/25 ip
- --8007010431 Corrected Pages II-35 & II-36 for "Inservice Insp Program, Program & Value Testing " * Caroline Power & Light Co. 80/06/25 2pp.
- 8007230220 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-14 also encl. No written response required. O/REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/27
- E007220260 Responds to IE Bulletin 80-10 Routine sampling, analysis & monitoring program established to promptly identify contaminating events that could lead to uncontrolled releases to environ
 FURR: B J Carolina Power & Light Co 80/07/01 1p
- B007170516 Responds to IE Bullstin 80-08, "Examination of Containment Liner Penetration Welds " All Final welds radiographed & results of const nondestructive examination acceptable as FURR, B J Carolina Power & Light Co 80/07/03 2pp
- BO07240189 Responds to BO0511 notice of violation & notice of proposed imposition of civil penalties Boiler removed from svc for decontamination, repair & mode Radiological operating limits established Civil penalties fee encl
 FURR.B J Carolina Power & Light Co B0/07/03 7pp

- --B007240196 Responds to NRC request for info re 780426 occurrence which resulted in onsite contamination of area around radwaste blig. Celculations indicate approx 200 gallons of waste was drawn into steam line TOLLISON, A C Carolina Power & Light Co 78/04/28 2pp
- 9007310449 Forwards response to NRC 8006ii notice of violation & notice of proposed imposition of civil penalties re onsite contamination of area around radwaste bidg. Corrective actions boiler decontaminated & repaired Penalty fee encl FURRE J Carolina Power & Light Co 80/07/03 5PP
- BOO7280111 Forwards response to IE Bulletin 80-11 Response includes general arrangement drawings indicating masonry walls Also forwards data sheets re each wall M/o encis. FURR.B J Carolina Fower & Light Co 80/07/07 ip
- 8007250294 Responds to IE Bullstin 80-17, "Failure of Control Rods to Fully Insert" No water observed in scram discharge vol Yiming of vent & drain valves completed. FURRY, B. J Carolina Power & Light Co 80/07/10 2pp
- BOO7150492 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions IBI program reorganized & future submittals will be accurate & complete. GA Procedure 23 written & approved to correct Items 2 & 4 TOLLIBON, A C Carolina Power & Light Co 80/07/11 3pp
- 8007300561 Responds to IE Bulletin 80-13 No cracking indications noted in Unit 1 core spray sparger or In-vessel piping.Unit 2 lnsp will be performed at next refuelling outage FURR, B J Carolina Power & Light Co 80/07/15 ip
- 8007310206 Submits supplemental response to IE Bulletin 80-07 re BHR jet pumps No indications discovered either by visual or ultrasonic insp.
 FURR.B J Carolina Power & Light Co B0/07/15 ip
- 8007310306 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 8A-312.Type 304 Stainless Steel Pipe " Plping specs do not parait use of A-312.Type 300 series fusion welded pips in sefety-related sys.

 FURR.B J Carolina Power & Light Co 80/07/15. ip
- R Periodic operating reports & related correspondence
- BOC7110405 Forwards monthly operating repts for June 1980, TDLLIBON, A C Carolina Power & Light Co 90/07/03 2pp
- --B007i10406 Monthly operating repts for June 1980, WILLIB,E Carolina Power & Light Co B0/07/03 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007010556 Forwards updated LER 80-041/01T-1 TOLLISON, A C Carolina Power & Light Co. 80/06/20 ip
- ---B007010354 Updated LER B0-041/01T-1 on B00525, during review of environ qualification of electrical equipment, nylon insulating sleave portions of compression-type terminator lugs did not pass qualification test. Caused by sleave deterioration TOLLIBON, A.C. Carolina Power & Light Co B0/06/20 2pp.
- 8007010501 Forwards LER 80-032/03L-0 TOLLISON, A.C. Caroline Fower & Light Co. 80/06/23. ip
- --B007010509 LER B0-032/03L-0 on B00525, when rod was selected, rod block munitur B inoperable light on rod block monitor panel illuminated, Gause unknown Problem could not be reproduced or identified when troubleshooting sys.

 TOLLISON, A C Carolina Power & Light Co B0/06/23 ip
- B007010513 Forwards LER B0-033/03L-0 TOLLIBON: A C. Carolina Power & Light Co. B0/06/24. 1p
- --B007010B21 LER B0-033/03L-0 on B00526, while performing genetrant test
 1 10, count rate for source range monitors B & C did not
 decrease when detectors were removed from core. Caused by
 blown fuses & height discriminator maladjustment.
 TOLLIBON, A. C. Carolina Power & Light Cp. B0/06/24. 2pp.
- 8007070234 Forwards LER 80-050/03L-0 TOLLIBON: A C. Careline Power & Light Co. 80/06/27. ip.

- --8007070237 IER 80-050/03L-0 on 800605, while performing reactor bl ventilation radiation monitoring sys test monitor DIR-RN-NO10B failed to trip ventilation sys & start standby gas trains Coused by stuck relay 3DA TOLLISDN: A C Caroline Power & Light Co 80/06/27 ip
- 8007080180 Forwards LER 80-037/03L-0 TOLLISON, A C Carolina Fower & Light Co 80/06/27 ip
- --B0070B01B5 LER B0-037/03L-0 on B0052B during containment integrit check-required negative pressure not reached Gaused by leaks in pipe & cable penetrations & steam line boots Penetrations repacked & boots replaced Test procedures revised TOLLISON.A C Carolina Power & Light Co B0/06/27 268
- 8007150654 Forwards LER 80-050/03L-0 TOLLISON, A C Carolina Power & Light Co 90/07/11 1p
- --BO07150665 LER BO-053/03L-O on B00607, during normal reactor bldg during refueling, inner & outer doors of 50-ft air lock found open Caused by burned coil in inner door interlock solenoid Coil replaced & air lock access restored TOLLIBON, A C Carolina Fower & Light Co B0/07/11 lp.
- B00722052: RO 1-80-59 confirms 800714 telcon re notification by Gi incorrect use of total peaking factor for adjusting gain of average power range monitors Caused by incorrect ref value. Tech Spec values to be changed TOLLISON.A C Carolina Power & Light Co 80/07/17. 3pp
- 8007270826 Forwards LER 80-056/03L-0 TOLLISON, A C Carolina Power & Light Co 80/07/23 ip
- --8007270833 LER 80-096/03L-0 on B00701, average nower range monitor (APRM) B & F determined inoperative due to lack of eleven low gower range monitor (LPRM) inputs per monitor Caused by LPRM connectors that feed into APRM being pulled louse TOLLISON, A C Carolina Power & Light Co 80/07/23 2pp
- 8007290823 Forwards LER 80-059/01T-0
 TOLLISON, A C Carolina Power & Light Co 80/07/25 2pp
- --B007290B31 LER B0-059/01T-0 on B00710, util informed by GE that pr computer was not using correct fuel lengths when calculating max total peaking factor Cause not stated Procedures revised to correct TPP ref value TOLLIBON. A C Caroline Power & Light Co 80/07/25 ip
- DOCKET 50-026 UNIV OF CALIFORNIA AT INVINE RES REACTOR

 G Inspection reports, 18 Dullstine & correspondence
- B007180266 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELMENTH Region 5. Ban Francisco, Office of the Director 80/06/24 lp.
- R Periodic operating reports & related correspondence
- 8007130615 Forwards "Annual Rept for Period 790701-000630" MILLER, Q. E. Celifornia, Univ. of, Irvine 80/07/08 ip
- --8007150620 "Annual Rept for Period 790701-800630 "
 MILLER, 9 E California, Univ of, Irvine, 80/07/08 10pp.
- DOCKET 50-327 BEQUOYAH NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8007220460 Natifies that contract for additiontracter support to provide operational experience during low power test, garfuel loading k low power testing requirement, will not be renewed. Existing contract terminates w/NRC concurrence.

 MILLS,L. M Tennessee Valley Authority 80/07/(7 ip
- 8007230511 Notifies that initial performance of Special Yest 7 on 800716 demonstrated that power operated relief valve can be manually operated to provide cooldown capability during abnormal conditions
 MILLS.L M Tennessee Valley Authority 80/07/18 (p.

- NRC Safety Evaluation Report (SER), supply & correspondence
- 307300052 Forwards status rept on facility SER imputs Inputs on 24 items are still outstanding SER will not be ready in im for commission 800728 briefing unless approximput dates are improved KENYON,T Assistant Director for Licensing 89/07/18 lp
- Security, medical, emergency & fire protection plans
- 07160643 Forwards revised commitment for fire protection program re-evaluation. Section A 3(b) re locking of fire protection water sys valves Revision was made in response to IE Insp. Repts 50-027/80-10 v. 50-328/80-06 Tennessee Valley Authority 80/07/03 Spp
- 07230479 Farwards fire protection and schedule, per NRC 800702 request Requests approval Seven ands have completion dates after 801001 Tennessee Valley Authority 80/07/17 15pp
- 07230575 Forwards revised radiological emergency plan w/crosq-rpf between plan & NUREO-0654 & App F. IN radiological emergency response plan Encls available in Central Files only MLLS-L M Yennessee Valley Authority 80/07/21 3pp
- 17280548 Advises that Westinghouse reviewed power-accension test rocedures per Task Action Plan Item 1 C 7 Review of mergency procedures documented by B00428 ltr to LS ubenstein ILLS.L M Tennessee Valley Authority 60/07/23 (p
 - Tennessee Valley Authority 80/07/23 Lp
- 7300434 Agrees as intorim step decided at NRC 800725 meeting to spand near site press facility to provide for command introl function for emergency response Contral emergency esponse ctr.per util 800721 itr.requires add1 discussion RLB.L M Tennossee Valley Authority 80/07/28 1p
- Adjudicatory correspondence
- '290275 Ack receipt of petition requesting that NRC revoke limited wer DL Petition is being treated under 10CFR2 206 & action 11 be taken within reasonable time NTON-JR Office of Nuclear Reactor Regulation, Director /06/24 2pp
- 07290287 Notice of request for action under 100FR2 206 by NRC per B00528 petition to revoke low power (AL DENTON.1) R Office of Nuclear Reactor Regulation. Director 30706/24 1p
- 17270296 Requests NRC revoke limited CL of util to perform low youer testing of facility because public health & safety is
- The Nuclear Regulatory Commission 80/05/28 3pp
- 10243 Forwards Commission 800527 memorandum & order containing issions on UCS 780502 petition for reconsideration of 413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables ENHUT, D & Division of Licensing 80/06/25 89pp
- ilıty Final Safety Analysis Report (FSAR) & amends
- 00374 Amend to OL application, consisting of Amend 66 to FSAR, taing Chapters 2.3.5.6 & 15 FSAR documentation of items ramitted by LM Mills 800613 itr & responses to NRC stions encl
- Tennessee Valley Authority 80/07/25 lp 38. J L
- 300376 Amend 66 to FSAR revising Chapters 2,3.5.6 & 15 Tennessee Valley Authority 80/07/28 92pp
 - ommittee on Reactor Bafeguards reports & correspondence
 - ce of ACRS Subcommittee on Sequeyah Nuclear Plant 800709 shington, DC to review OL request

 ffice of the Secretary of the Commission 80/06/18
 - usses review conducted at 243rd ACRS mosting on 800710-plication to operate at full power Facilities ed at levels up to full power w/o undus risk ined are considered ACRS Advisory Committee on Reactor Safeguards

- 8007210531 Responds to 800710 request re particular aspects of facility Applicant committed to expedite installation of distributed agnition sys No practical need to hold up issuance of DL pending completion of proposed sys PLESSET.N S ACRS Advisory Committee on Reactor Bafeguards 80/07/15 1p
- B007290022 Forwards Ahearns B00715 ltr re AGRB review of application for authorization to operate SCHNENGER, A Licensing Branch 2 80/07/17 3pp
- P Operating license stage documents & correspondence
- 8007020228 Forwards NRC Dfc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCOLR L Assistant Director for Licensing 80/06/13 2pp
- B007020747 Forwards requests for add1 info re shielding review & containment sump Responses should be submitted by B00701 Includes summary of shielding design review required by NRC 791109 itr implementing Item R 1 6 b of NREG-0578 SCHWENCER, A Licensing Branch 2 80/06/19 10pp
- 8007020042 Confirms 800520 prai authorization to proceed w/heatup b/ inoperable hanger on pressurizer line Deficiency will be corrected before initial criticality Formal amand to license will be processed in near future 90/06/23 2pp
- BOO7020722 Forwards commitments re-steam generator insp ports & Row 1 steam generator tubes NRC requires commitment within 5 days re-performance of required actions described in encl Insp-ports must be installed just above upper support plate SCHWENGER, A Licensing Branch 2 80/06/23 3pp
- 8007030195 Forwards request for addl info re Table 17 2-1, "Critical Structures, Bys & Components," For FSAR, which identifies items subj to operational GA program Info requested by SCHWENCER, A Licensing Branch 2 80/04/24 3pp
- E007010327 Forwards add1 info re safety ovaluation of facility special test program, Provides add1 assessment of potential upset conditions associated w/postulated rod withdrawal events Fuel clad failure is not spected MILLS, L M Tennessee Valley Authority 80/06/25 11pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NURE9-0660 & found in NURES-0640 Division of Licensing 80/06/26 2pp
- 8007070347 Requests that 800624 FR notice be reissued to correct implication that farm (TMRC) owns facility & allegation that plant is unable to withstand hydrogen burn pressure BATES, A K. Affiliation Unknown 80/07/01 3pp
- 8007170496 Forwards Amend 3 to License DPR-77, safety evaluation & notice of issuance & availability
 SCHWENCER, A Licensing Branch 2 80/07/01, 2pp
- --BO07170303 Amend 3 to License DPR-77 changing pages to App A Tech Specs re surveillance requirements for taking radioactive liquid & gaseous samples SCHMENCER A licensing Branch 2 80/07/01 22pp
- --8007170508 Safety evaluation supporting Amend 3 to License DPR-77
 * Office of Nuclear Reactor Regulation, Director 80/07/01
- --- BO07170517 Notice of issuance & availability of Amend 9 to License DPR-77 SCHWENCER, A. Licensing Branch 2 80/07/01, 2pp
- 800718006: Forwards safety evaluation supporting Amend 2 to License DPR-77 SCHWENCER, A Licensing Branch 2 B0/07/01 2pp
- --8007180070 Safety evaluation supporting Amend 2 to License DPR-77
 * Licensing Branch 2 80/07/01 2pp
- BOO7180595 Forwards Amend 2 to License DPR-77, safety evaluation & notice of issuance & availability
 BCHWENCER, A Licensing Branch 2 80/07/01, 2pp,

- --8007180593 Amend 2 to License DPR-77, changing Page 8-1 to App A Tech Specs to permit entry into Modes 3 & 4 Wunresolved piping support or restraint deficiencies SCHWENCER.A Licensing Branch 2 80/07/01 4pp
- --8007180599 Notice of issuance & availability of Amend 2 to License BCHWENCER, A Licensing Branch 2 80/07/01 200
- 8007150472 Forwards response to NUREG-0578. TMI-2 Lessons Learned Task Force status rept & short-term recommendations Consolidates previous ltrs Includes revisions to containment isolation & Tennessee Valley Authority 80/07/03 ip
- C007280001 "TVA Response to MUREG-0378, Short-Term Lossons Learned Regulrements "
 # Tennessee Valley Authority 80/07/03 500pp
- G007190640 Advises that response to FSAR. Guestion 2 78, will not be organized & prepared for submittal until 600801 MILLS.L M Tennessee Valley Authority 80/07/08 ip
- 8007130692 Bubmits recommundations to facility steam generators, in response to NRC 800623 ltr Camera device will be designed & tested for remote insp of tube supports in lieu of addiparts Hax active tube surface margin will be maintained MILLS, L M Tennosume Valley Authority 80/07/08 2pp
- 8007150921 Forwards info re Category I masonry wolls, in response to NRC 800421 ltr Results of investigation of inplace attachments to masonry walls will be submitted by 801017 Oversize social available in Central Files (31 pp) MILLB-L M Tennessee Valley Authority 80/07/09 App
- ---BOO7150322 "Design Criteria for Reinforced Concrete Block Halls "
 STDNC,F A. CANNON.R W., LACY,F P. Tennessee Valley Authority
 72/04/07 29pp
- 8007210618 Natification of 900714 meeting w/util in BethesdarMD to discuss emergency operating instructions
 STAHLErC R Licensing Branch 2 80/07/10 2pp
- 8007240297 Forwards Amend 4 to License DPR-7/, safety evaluation & notice of issuance 2 availability DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/10 3pp
- --B007240302 Amend 4 to License DPR-77.modifying Tech Specs for law power testing DENION.H R OF Office of Nuclear Reactor Regulation, Director
- --8007240312 Notice of issuance & availability of Amend A to License DPR-77 BCHWENCER,A Licensing Branch 2 BO/07/10 2pp.
- R007150571 Forwards Revision 2 to util response to Item 2 i &s.NUREQ-0578 Revision incorporates leak testing procedures for waste gas sys (App E) & results of leak reduction program for liquid & gas sys (App F) HILLS.L M. Tennessee Valley Authority 80/07/11 App
- --8007150578 Surveillance Instruction SI-656.Revision 1. "Waste Gas Sys Gross Leakage Tast " KUEHN-L B Tennessee Valley Authority 80/06/12 14pp
- --8007150582 Liquid sys leak test data CHURCH.J W Tennessee Valley Authority 80/07/01 9pp
- 8007140471 Responds to J Spraul informal questions re FSAR Table 17 2-1 & forwards operations) GA manual.App A.re critical sys & Part 9. Section 2.re matl & spare parts
 MILLS.L M Tennessee Valley Authority 80/07/11 5pp.
- --8007160478 Operational GA manual. App Aire critical structures, sys & components list
 GREEN, H. J. Tennessee Valley Authority 78/08/15 50pp.

- ~-8007160484 Operational GA manual Part 3. Section2, re mati & spare parts * Tennessee Valley Authority 78/08/29 33pp
- 8007280006 Notification of 800723 meeting w/utils in Dethesda.ND to discuss matters re TMI-2 dated requirements DROMERICK.A W. Licensing Branch 1 KERRIGAN.J D., STABLE.C R Licensing Branch 2 80/07/16 6pp
- 8007R20532 Advises that util proposes installation & implementation of interim sys of distributed ignitors which would limit offects of large amounts of hydrogen Sofety analysis, drawings & FSAR revisions will be submitted by 800815 MILLS.L M Tonnessee Valley Authority 89/07/17 Spp
- 8007230467 Forwards response to NRC 800507 request for commitment to most requirements & associated schedules in Fave specific TMI items includes shift membring licensing examinations & licensed dissemination of operating experience MILLB.L II Tennessee Valley Authority 80/07/18 4pp
- B007230477 Forwards response to NRC B00619 request for additinfo re shielding design review high range containment radiation monitor & access control of areas adjacent to spent fuel transfer tubes Tennessee Valley Authority 80/07/18 8pp MILLS, L M
- 8007230480 Forwards "ECOPAC Solidification Sys Process Control Program," Revision 4. in response to NRC 800324 request MILLS.L M Tennessee Valley Authority 80/07/18 1p
- --8007230481 "ECOPAC Solidification Sys Process Control Program," Revision 4
 - Tonnessee Valley Authoraty 80/07/18 20pp
- --8007230483 "Technical Rept on Urea Formaldehyde " Marked-up Amefco rept on procedure for onsite solidification of low level radwaste at facility onc! 4 Amefco.lnc 80/07/18 45pp
- 8(07230533 Forwards response to H Mendonca 800627 questions re reactor vessel head venting sys Hestinghouse is developing procedures for inadequate core cooling for recommended use of vent sya by utils HILLB, L M Tennossee Valley Authority BO/07/18 11pp
- 8007J00092 Forwards status rept on Pacility SER inputs Inputs on 24 items are still outstanding SER will not be ready in time for Commission 800720 briefing unless approx input dates ard improved KENYON, T Assistant Director for Licensing 80/07/18 1p
- 800/230408 Forwards addl info per NRC 800619 request re control of containment sump debris
 MILLB.L M Tennesseo Valloy Authority 80/07/21 14pp
- 8007290724 Forwards description of program, "Training for Mitigating Core Damage " Program was developed to ensure that all incensed operating employees are properly trained to use available info should accident occur involving core damage MILLS,LM Tennessee Valley Authority 80/07/22 Spp
- 8007280623 Advises NRC of evaluation of potential hazards in vicinity of plant & of main control room habitability sys for protection from radioactive & toxic gas releases Plant operators are adequately protected from possible hazards MILLS.L M Tennessee Valley Authority 80/07/24 lp
- 8007290651 Forwards evaluation of design & equipment delivery schedules MYXTUGGI FORWARDS WALLDAYING OF USUSIN K EQUIPMENT OF WORK for mods in response to RUREG-0694 All equipment for Work requiring power outage will be available Mar-June First refuelbing outage cheduled for early 1902 PARRIBH G Tennessee Valley Authority E0/07/25 App
- 8007270679 Forwards proliminary assessment of potential for harge tow heading upstream impacting new essential raw cooling water pumping station Blation not required for safe operation of Unit 1 MILLS, L M Tennessee Valley Authority 80/07/28 2pp
- 8007290757 Forwards data & drawings resettlement monitoring Revised Questions SNP 02 84 & SNP 02 73 will be incorporated into FBAR in next amend No significant settlement observed Drawings available in Central Files only NIELS.L M Tennossee Valley Authority B0/07/28 12pp
- B007310396 Advises that short-term items & two long-term items listed in NUREG-0011 re main control room design review have been corrected Util committed to investigate feasibility of correcting remaining items of first refueling outage MILLS, L. M. Tennessee Valley Authority 80/07/28 App

- 310412 Forwards revised summary page for 800616 response to REG-0568
 - Tennessee Valley Authority B0/07/28 2pp
- 310323 Forwards "Unit 1 Special Startup Test Rept LLS.L M Tennessee Valley Authority 80/07/29
- 07310325 "Unit 1 Special Startup Test Rept " MACH.S R Tennessee Valley Authority 80/07/28 3pp
- 310411 Submits test results of plant auxiliary bldg gas treatment per requirements of SER. Suppl 1 Negative pressure equal or more negative than minus i/4-inch water gauge lative to outside atmosphere was achieved in pump rooms LLS:1 M Tennessee Valley Authority 80/07/29 1p
- 310416 Forwards addl info on temp control for main steam valve oms.por O Parr request LLB.L M Tennessee Valley Authorsty 80/07/29 2pp

napaction reports, 1E Bulletina & correspondence

- 240089 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal sability at Davis-Besse Unit 1 While in Refueling Mode "response required REILLY, J.P. Region 2, Atlanta. Office of the Director 80/05/08
- D20192 Forwards IE Info Notice 80-22. "Breakdowns In Contamination ntrol Programs " No written response required REILLY, J.P. Region 2. Atlanto. Diffice of the Director 80/05/28
- 00127 Forwards 1E Insp Rept 50-327/80-18 on 800512-13 No
- J7100131 IE Insp Rept 50-327/80-18 on 800512-13 No noncompliance inted Major areas inspected seismic analysis for as-built lafety-related piping sys per IE Dulletin 79-14 HERDIA R Region 2. Atlanta, Reactor Construction & Engineering upport Branch MODENOS. L Region 2. Atlanta, Office of the irector 80/05/27 3pp
- '10488 Forwards IE Circular 80-10, "Grid Strap Damage in tinghouse Fuel Assemblies " No written response required. 'ElLLY,J P Region 2, Atlanta, Office of the Director 80/05/28
- 180225 Forwards IE Info Notice 80-23. "Loss of Buction to Emergency dwater Pumps " No written response required EILLY.J P Region 2. Atlanta. Office of the Director 80/05/29
- 70219 Forwards 1E Insp Rept 50-327/80-16 on 800408-30 & notice of Istion
 IS.R C Region 2, Atlanta, Reactor Operations Nuclear Support
 nch 80/06/02 2pp
- 7170221 Notice of violation from insp on 800408-30 Region 2. Atlanta. Office of the Director 80/0 80/04/02 1p
- 7170224 1E loss Rept 50-327/80-14 on 600408-30 Noncompliance noted arilore to maintain vital area barrier integrity

 OTTLE.W T Region 2. Atlanta, Office of the Director DANCE, H C
 Region 2. Atlanta, Reactor Operations Nuclear Support Branch

 0/06/02 12pp
- 30005 Forwards IE Insp Repts 50-327/80-19 & 50-328/80-12 on #13-16 No noncompliance noted 18.R C Region 2. Atlants. Reactor Operations Nuclear Support 10 BO/06/05 2pp
- 7180011 IE Insp Repts 50-327/80-19 & 50-328/80-12 on 800613-16 No. //HUDIT is insp weeks 50-32//HD-19 & 50-32/HD-12 on BOU619-12
 Inscomplishers noted Major areas inspected preoperational
 isting, program review & implementation & followup of
 reviously identified items
 HENDEN.M C. BUTLER, B D. Region P. Atlanta, Office of the
 irector UPRIGHT, C H. Region 2. Atlanta, Reactor Operations
 iclear Support Branch BO/06/04 App
- 20029 Forwards 1E Info Notice 80-25. "Evaluation of Contractor rograms " No written response required ILLY, J P Region 2, Atlanta, Office of the Director. 80/06/10

- 8007160287 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/04/11
- 8007020740 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " List of safety-related equipment which will not remain in swergency mode after reset of actuation signals encl CROSS, J L Tennessee Valley Authority 80/06/12 3pp
- 8007020347 Forwards response to IE Bulletin 80-04, "Analysis of FMM Main Stram Line Break w/Continued Feedwater Addition " Lists relevant assumptions used in all core transient analyses Assumptions further explained in FSAR HILLS.L N Tennesses Valley Authority 80/06/16 3pp
- 8007020761 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification 8ys (ENS) W/Loss of Offsite Power * Written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/04. Region 2, Atlanta, Office of the Director 80/06/18
- 8007020391 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pusp Cooling & Natural Circulation Cooldown " No written response required required D'AEILLY, J.P. Region 2, Atlanta, Office of the Director, \$0/06/20.
- 8007310344 Forwards IE Insp Rept's 50-259/80-25,50-260/80-19, 50-296/80-20 & 50-327/80-22 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/23
- --8007310351 lE Insp Repts 50-259/80-25.50-260/80-19.50-296/80-20 & 50-327/80-22 on 800521. Insp consisted of enforcement meeting in Atlanta, GA to discuss exceeding BDT radiation limits during shipment of radwaste from Browns Ferry DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/20 2pp
- B007110034 Ack receipt of 800523 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-327/80-14 & 50-328/80-08 MKPPLY C E Region 2, Atlante, Reactor Construction & Engineering Bupport Brench 80/06/24 ip
- --B007110039 Submits add1 response to NRC 800501 ltr re violation noted in IE Insp Repts 50-327/80-14 & 50-328/80-08. Corrective ections ell Section 3 surveillance instructions comply w/ Section in of ABME boller code MILLB, L M Tennessee Valley Authority 80/06/09 ip
- 8007170070 Forwards IE Circuler 80-14, "Redicactive Contamination of Plant Dymineralized Water Sys & Resultant Internal Contamination of Personnel." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/06/24
- B007020627 Advices NRC that followup rept to B00612 response to IE Insp Rept 50-327/80-15.containing one infraction.will be submitted by B00630 MILLS,L M Tennessee Valley Authority B0/06/26 ip
- 8007080220 Forwards rept on insp program re sys performance which was initiated in response to IE lnsp Rept 50-327/60-15 lnsp program should ensure sys performance will not be degraded. HILLB,L H Tennessee Valley Authority 80/06/27 12pp
- BOO7230253 Forwards IE Bulletin 80-16. "Petential Misapplication of Roseacount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required. IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 80/06/27,
- 800708033i Forwards response to Deviation litem 80-327/80-17-01.noted in IE Insp Repts 80-327/80-17 & 50-328/80-10 re inadequate fire barriers, Required insulation installed on seven conduits, & cover plates reinstalled on three conduit fittings MILLB.L M. Tennessee Valley Authority 80/06/30. 3pp.
- 8007210036 Forwards response to IE Bulletin 80-08're-examination of containment liner penetration welds Penetrations at Bequovah, Wetts Dar & Bellefonte contain flued head design Design for Yellow Creek not yet completed.
 MILLS.L M Tennessee Valley Authority. 80/07/08 5pp.

1 0

- 8007210594 Responds to IE Bulletin 80~10 re contamination of nonradioactive sys Routine sampling & analysis program established Hill comply w/requirements should identified sys become contaminated MILLS.L H Tennessee Valley Authority 80/07/08 ip
- B007310056 Forwards response to IE Bulletin 79-27 reliose of nonclass IE instrumentation & control power sys bus during operation No deficiencies discovered MILLB.L H Tennessee Valley Authority B0/07/15 3pp
- B007290479 Forwards response to NRC B00626 ltr re violetions noted in IE Insp Rept 50-327/80-20 Response withheld tref 100FR2 790)
 MILLS.L H Tennessee Valley Authority 80/07/21 1p
- 8007280498 Forwards Addl response to IE Bulletin 80-06, "Engineered Bafety Feature (EGP) Reset Controls " Present control schemes adequate Equipment evaluation encl MILLB/L M Tennessee Valley Authority 80/07/24 Spp
- R. Periodic operating reports & related correspondence
- 8007220358 Forwards monthly operating rept for June 1980, BALLENTINE, J M Tannessee Valley Authority 80/07/14 1
- --- B007220360 Monthly operating rept for June 1980 HALKER, F M Tennesses Valley Authority 80/07/02 9pp.
- 8. Reportable occurrences, LERs & related correspondence
- 8007010069 PN8-II-80~007 on 800304, util employee gained unauthorized entry to protected area & further access to reactor bidg Employee observed photographing fueling operation Search of areas entered revealed no contrab
- BO04240250 PNO-II-BO-39, two issues currently under review by TVA which may result in delay in startup of unit. First issue covers replacing of split positioning pins used in mounting control rod guide tubes in upper core support assembly HARTIN.R., DAUCE, H Region 2. Atlanta, Office of the Director, 80/03/12, 1p
- B007010382 Forwards LER B0-073/03L-0 GALHOUN.J.R Tennessee Valley Authority B0/06/R3 ip
- ---B0070103B5 LER B0-073/03L-0 on B00520, during support & hanger insp, discrepancies discovered between as-built & as-analyzed configurations that could cause failure in piping during saissic event Deviations will be modified as required.

 8MEARINGEN, J. D. Tannessee Valley Authority B0/04/23 5pp
- BO07010435 Forwards LER BO-065/03L-0 CALHOUN, J R Tennessee Valley Authority. BO/06/23 1p.
- 8007010528 Forwards LER 80-082/03L-0.
 CALHOUN, J. R. Tennessee Valley Authority. 80/06/23. Ip
- --8007010339 LER 80-082/03L-0 on 800526, w/unit in Mode 4, pressurizer heatup rate exceeded max allowable rate Caused by safety injector creating insurge into pressurizer. Level restored during recovery phase temp restored to limits ROBINSON, F Tennessee Valley Authority 80/06/23 2pp
- 8007010417 Forwards LER 80-076/03L-0 CALHOUN J.R Tennessee Valley Authority. 80/06/25, ip
- ---8007010419 LER 80-076/03L-0 on 800526, during normal operation, output circuit breaker on vital inverter 2-I tripped, cauxing 120 yolt ac vital instrument power board 2-I to become inogerable. Caused by thermostat being out of calibr. ROMINE, D.R. Tennessee Valley Authority 80/06/25 ip.
- B007010479 Forwards LER B0-053/03L-0, CALHOUN, J R Tennessee Valley Authority, B0/06/25, 1p.

- --B007010502 LER 80-053/03L-O on 800526, syc blig vent monitor G-RM-90-1320 declared inoperable due to loss of flow Caused by inoperative radiation monitor sample vacuum pump Other monitor sample pump valved in & monitor returned to syc HEREFORD. J M Tennessee Vailey Authority 80/06/25 ip
- 8007010525 Forwards LER 80~078/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/25 ip
- --8007010532 LER 80-070/03L-0 on 800526, during Mode 4 operation, boron concentration in RWST measured 2124 ppm Caused by boron concentration makeup being too high Boron diluted to proper concentration RECORD.D J Tennessee Valley Authority 80/04/24 2pp
- 8007010534 Forwards LER 80-081/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/25 tp
- --8007010541 LER 80-081/03L-0 on 800527, during timing of 1-FCV-72-20, containment sump to train 8 of containment spray, for surveillance test 166 i.valve would not open Caused by switch controlling FCV-72-20 being out of adjustment ROMINE, D Tennessee Valley Authority 80/06/25 ip
- 8007010490 Forwards LER 80-083/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/26 ip.
- --8007010515 LER 80-083/03L-0 on 800529 pump motor on 0-RM-90-134 bur out causing common circuit breaker on 0-RM-90-134/141 & 1-RM-90-112 to trip Cause unknown Motor replaced ROMINE,P F Tennessee Valley Authority 80/06/26 2pp
- 8007010312 Forwards LER 80-080/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/26 1p
- --8007010522 LER 60-080/03L-0, on 800527, during test on 8 train of auxiliary bldg gas treatment systemated fuse failed & tripped fam motor supply breaker Cause unknown Fuse replaced & sys declared spenable ROMINE.D Tennessee Valley Authority 80/06/26 1p
- 8007080283 Forwards LER 80-040/01T-0 CALHOUN, J. R Tennessee Vnlloy Authority 80/06/27 ip
- --8007080288 LER 80-040/017-0 on 800531.upon preoperational testing o safety injection pumps found that 6,900-volt breakers would lockout preventing pump start Cause unknown Problem is being evaluated ROMINE, D Tennessee Valley Authority 80/06/27 ip
- 8007080334 Forwards LER 60-086/01T-0 GALHOUN, J R Tennessee Valley Authority 80/06/27 1p
- --8007080341 LER 80-086/017-0 on 800613. w/unit in Mode i, centrifugal charging numps could fail due to insufficient flow delivery during postulated secondary side high energy line rupture w/coincident failure of power operated relief valve LOREK, M J Tannossee Valley Authority 80/06/27 2pp
- 8007110372 Forwards LER 80-087/031-0 CALHOUN, J R Tennesses Valley Authority 80/06/27 ip
- ---B007110376 LER 80-087/03L-0 on 800602.while in Mude 5 after inadver BI,diesel generators would not shut down normally All lockout relays damaged during shutdown attempt Caused by relay piunger malfunction Relay colla replaced i CURTIB,J W Tennessee Valley Authority 80/06/2/ Epp
- 8007080281 Forwards LER 80~085/01T-0 CALHQUN, J R Tennessee Valley Authority 80/06/30 19.
- --B0070B0291 LER B0-0B5/01T-0, on B00530 during review of E0TB & ABOTS equipment qualifications, sys solenoid valves found rated for 77 F normal systemp Ambient temp may reach 104 F Cause not stated, New valves being purchased ROMINE.D Tennessee Valley Authority 80/06/30 1p
- 8007080400 Forwards Special Rept 80-01 CALHOUN, J R Tennessee Valley Authority 80/07/01 ip
- --B0070B0402 Special Rept B0-01 on 800605, firestop penetration MKIR1 support clearance reported excessive during piping configuration insp Seven-day time requirement exceeded prior to penetration remeasurement & closing on 800606 Tennessee Velley Authority 80/07/01 1p

i

```
-8007250499 Special Rept 80-02 on 800705, moderator temp coefficient measured less positive than limit established in Tech Specs during low power physics testing Control rod withdrawel limit determined as shown in encl graph * Tennessee Valley Authority 80/07/15 2pp
7090249 Forwards revised final deficiency rept re spent fuel pool
ates
||LLS.L M | Tennessee Valley Authority | B0/07/02 | 1p
007090258 Revised final deficiency rept ro spent fuel pool gates
Gates are not designed to Seismic Category 1 requirements
per Reg Guide 1 13 GA aspects of gate integrity will be
verified for all three plants
# Tennessee Valley Authority 80/07/02 2pp
                                                                                                                                                                                                               8007270633 RO 80-2 on 800706 during low power physics testing at all-
control rods out configuration moderator temp coefficient
found out of spec Control rod withdrawal limits determined
# Tennessee Valley Authority 80/07/15 3pp
7150455 Forwards LER 80-093/017-0
ALHOUN,JR Tennesser Valley Authority 80/07/07 1p
                                                                                                                                                                                                                8007220568 Forwards LER 80-098/03L-0
CALMOUN, J R Tennessee Valley Authority 80/07/18 1p
007150466 ter 80-093/017-0 on 800625, vent duct in temporary air lock discovered breaching aux bldg integrity Caused by unauthorized instaliation of duct by const workers Duct removed, hole patched & sealed WILBOURN. © R Tennossee Valley Authority 80/07/07 2pp
                                                                                                                                                                                                               ---8007220574 LER 80-098/03L-0 on 800624, during heat-up, twe fitting on pressurizer pressure sensing line for instrument 1-PI-68-323 failed, allowing primary coalent to leak into containment Caused by improper installation of ferrole ring on twe EMRATHLR M Tennessee Valley Authority 80/07/18 ip
7150504 Forwards LER 80-084/0;T-0
ALHOUN,J R Tennessee Valley Authority 80/07/07 ip
                                                                                                                                                                                                               8007250418 Forwards LER 80-081/03L-0
CALHOUN, J R Tennessee Valley Authority 80/07/18
007150512 LER 80-084/01T-0 on 800623, control room integrity was breached by removal of donr C-49 for maint & removal of taps from C-37 & C-50 for access Doors repaired or replaced Personnel reinstructed SULLIVAN J H Tennessee Vailey Authority 80/07/07 2pp
                                                                                                                                                                                                               8007290646 Forwards LER 80-087/03L-0
CALHOUN, J R Tennessee Valley Authority 80/07/18 is
                                        Tennossee Valley Authority 80/07/07 2pp
                                                                                                                                                                                                                 --B007290659 LER 80-0B7/03L-0 on B00602, while in Mode 5 after inadvertent BI, diesel generators would not shut down normally after starting While attempting restart.lock out relays damaged Cause not stated Relays replaced CURTIS, J W Tennessee Valley Authority 80/06/27 2pp
7150470 Forwards LER 80-092/017-0
ALHOUN.J R Tennessee Valley Authority B0/07/08 ip.
007180488 LER 80-092/01T-0 on 800626.8R 4 8 1 1 1 a & 8R 4 8 1 1 2 a 4 were performed w/o ±ubsequent 8-hour surveillance requirement being met Caused by personnel error due to shift change Shift & relief turnover procedure being changed RECORD.B J Tennessee Valley Authority 60/07/08 lp
                                                                                                                                                                                                               8007270790 Forwards LER 80-102/03L-0
GALHOUN, J R Tennessee Valley Authority 80/07/18 ip
                                                                                                                                                                                                               --8007270800 LER 80-102/03L-0 on 800622, while in Mode 3, operator observed 1-L1-3-110, steam generator 4 narrow range level. reading high Cause not stated Transmitter sense lines refilled & transmitter calibr checked REYNGLD9.R H Tennessee Valley Authority 80/07/18. 1p.
7180380 Forwards updated LER 80-041/03L-1
ALHOUN.J R Tennessee Vallay Authority 80/07/09. 1p.
007150595 Updated LER 80-041/03L-1 on 800430,1-FCV-32-i10 isolated on nonessential air pressure causing six valves providing flow to containment upper & lower compartment radiation monitors to close Cause unknown
MCGRIFF.J M Tennessee Valley Authority 80/07/09 2pp
                                                                                                                                                                                                               B007290822 Forwards LER B0-101/03L-0
CALHOUN.J R Tennessee Valley Authority 80/07/21 ip
                                                                                                                                                                                                                --8007290827 LER 80-101/03L-0 on 800422. steam generator level indicator
1-L1-3-51 was reading 10% higher than other two indicators
Caused by defective transmitter Defective transmitter was
7150491 Forwards LER 90-090/03L-0
ALROUN.J R Tennessee Vailey Authority 80/07/10 ip
                                                                                                                                                                                                                         REYNOLDB.R H Tennessae Valley Authority 80/07/21 2pp
OCTISOSDI LER 80-090/03L-0 on 800613.discrepancy discovered between as-built & as-analyzed support & hanger configurations Full rept will be provided to NRC before initial criticality Daviations which could cause pips failure will be modified SHEARINGEN.J D Fennessee Valley Authority 80/07/10 3pp
                                                                                                                                                                                                               8007250414 Forwards LER 80-091/03L-0
CALHOUN, J R Tennessee Valley Authority 80/07/22 ip
                                                                                                                            De modified
80/07/10 3
                                                                                                                                                                                                                  -8007250416 LER 80-091/03L-0 on 800623, while in Mode 3, containment sump level, i-LI-63-179, indicated approx 10% w/other three indicators reading zero Caused by defective loop transmitter. Transmitter replaced & calibr REYNOLDS, R H Tennessee Valley Authority. 80/07/22 2pp
7160519 Forwards LER 8D-097/03L++0
ALHDUN,J R Tennesses Valley Authority 80/07/11 ip
007160323 LER 80-097/031-0 on 800616, cooling tower blowdown line effluent munitur (O-FR-27-175) declared inoperable Flow monitor recorder indicated incorrect flow Flow element recaling the design change in progress
EMITHSON, J D Tennessee Valley Authority 80/07/11 ip
                                                                                                                                                                                                              8007270636 Forwards LER 80-049/03L-0
GALHOUN, J R Tennessee Valley Authority 80/07/22 1p
                                                                                                                                                                                                              --8007290639 LER 80-099/03L-0 on 800623, valve 1-FCV-72-39 failed surveillance testing, rendering one train of containment spray sys inoperable Caused by limit switches being out of adjustment, not allowing proper closure Switches adjusted BIRCHELL, R. C Tennessee Valley Authority 80/07/22 ip.
7210461 Forwards LER 80-095/03L-0
ALHOUN,J R Tennessee Valley Authority 80/07/11. ip
007210475 LER 80-095/03L-0 on 800614, auxillary vent radiation monitor declared inoperable due to spurious high rad spikes. Caused by defective microswitch w/monitor inadvertently left in continuous advance mode
HEREFORD. J M Tennessee Valley Authority 80/07/11 1p
                                                                                                                                                                                                              B007290669 Forwards LER B0-107/03L-0
CALHOUN: J R Tennessee Valley Authority B0/07/22. 1p
                                                                                                                                                                                                                --BOO7290672 LER BO-107/03L-O on BO0623, while in Mode 3, steam generator 3 level indication, loop i-1-3-97, indicated approx 10% higher than two marrow range channels Caused by defective transmitter on panel in-1-185 in accumulator room 4 REYNOLDB, R, H Tennessee Valley Authority BO/07/22 2pp
220469 Forwards LER 80~089/03L-0
%LHOUN, J.R. Tennessee Valley Authority 80/07/14 1p
107220474 LER 80-089/03L-0 on 800609, contract review revealed local control station salector switches (C-H type 102507) used in Class IE circuits lack environ qualification for operation following high energy line break ROMINE.D Tennessee Valley Authority 80/07/14 2pp
                                                                                                                                                                                                             8007290810 Forwards LER 80-100/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/22, 1p.,
                                                                                                                                                                                                             --8007270B18 LER 80-100/03L-0:on 800423, containment isolation & purge exhaust valves FCV-30-37 & FCV-30-40 found to have excessive leakage. Caused by debris under seating surface Debris was blown out & valves restested BIRCHELL.R.C Tennessee Valley Authority 80/07/22, 1p.
```

230435 Forwards Beetial Rept BO-02 re positive moderate temp sefficient measured during low power physics testing at 1 control rods out of configuration MHDUNJR Tannessee Valley Authority 80/07/15 ip

- B007290762 Forwards LER B0-10B/03L-0 CALHOUN.J R Tennessee Valley Authority 80/07/23 1p
- --B007290770 LER B0-10B/03L-0 on B00524, during normal operations, fuse in switching bridge circuit failed on vital inverter 2-I which rendered 12D volt at vital instrument power board 2-I inoperable Cause unknown Fuse replaced RDMINE, D Tennessee Valley Authority B0/07/23 ip
- BO07290485 Forwards LER 80-110/03L-0 CALHOUN, J R Tennossee Valley Authority 80/07/24 1p
- --8007290693 LER 80-110/03L-0 on 800625, main steam flow loop, 1-F-28A, declared inoporable due to maint requiring removal of loop from svc Caused by loop current disturbance Loop functioned property w/n test recorder & roturn to svc LAFEVER, C W Tennessee Valley Authority, 80/07/24 1p
- BO0729057B Forwards add1 copies of LER 80-041/03L-1 CALHOUN, J R Tennessee Valley Authority 80/07/25 ip
- BOO7270649 Forwards LER 80-106/03L-0 GALHDUN, J. R Tennessee Valley Authority 80/07/25 lp
- ---B007290656 LER B0-106/O3L-0 on B00626, train B ERCW to turbine driven auxiliary feedwater pump isolation velve, 1-FCV-3-179B, found leaking excessively from tell-tale drain Caused by valve leaking through, Pump removed from svc & valve repaired B0LES, Q, B Tennessee Valley Authority 80/07/25 1p
- 9007290662 Forwards revised LER 80-068/01T-1 CALHOUN.J R Tennessee Valley Authority 80/07/25 In
- ---B007290673 Revised LER B0-068/01T-1 on B00530, while in Mode 5, informed that wide range steam generator level transmitters i-LT-3-43,-56,-98 k -lii not qualified to withstand post-accident environ Caused by use of improper transmitters REYNOLD8, R H Tennessee Valley Authority 80/07/25 2pp.
- 8007290675 Forwards LER 80-109/03L-0 GALHOUNJU R. Tennesses Valley Authority 80/07/25 ip
- ---8007290681 LER 80-109/03L-0 on 800626, during 81-166, containment spray pump discharge check valve.1 A-A, found to leak excessively Caused by valve leaking through Pump removed from syc & valve repaired BDLE8, G 8 Tennessee Valley Authority 80/07/25 ip
- B00729070B Forwards LER 80-111/03L-0 CALHOUN, J. R Tennessee Valley Authority 80/07/25 ip
- --8007290719 LER 80-111/03L-0 on 800626, during normal operation, 1-FCV-62-136 (8 train to suction of charging pump from RWST) would not open from main control room Caused by valve operator torque spring being out of adjustment Bpring readjusted ROMINE, D Tennessee Vailey Authority 80/07/25 1p.
- T. Hearing transcripts on non-antitrust matters
- BOO7220061 Transcript of ACRS Subcommittee on Bequoyah Nuclear Plant BOO709 meeting in Washington DC Pp 1-266 * ACRS - Advisory Committee on Reactor Bafeguards 80/07/09 325pp
- DOCKET 50-328 BEQUOYAH NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020228 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO,R L Assistant Director for Licensing 80/06/13 2pp
- 8007020747 Forwards requests for add1 info re shielding review & containment sump. Responses should be submitted by 800701.
 Includes summary of shielding dealign review required by NRC 791107 itr implementing Item 2 1 6 b of NREG-0578
 BCHMENCER, A Licensing Branch 2 80/06/19 10pp
- 8007020722 Forwards commitments to steam generator insp ports & Row 1 steam generator tubes. NRC requires commitment within 5 days re performance of required actions described in encl. Insp ports must be installed just above upper support plate BCHMENCER.A. Licensing Branch 2 80706/23 3pp

- BOD7030195 Forwards request for addl info re Table 17 2-1. "Critical Structures, Sys & Components." for FBAR, which identifies items subj to operational GA program Info requested by BOD030 BOHMENCER, A Licensing Branch 2 BO/06/24 5pp
- 8007010386 Advises that util has received no response to 790928 request for extensions until Mar & Dec 1981 for Watts Dnr 1 & 2 Addl safety requirements may result in completion by Jan 1981 for Sequegah 2. May 1981 for Watts 1 & Feb 1982 for Watts 2 MILLS.L M Tennessee Volley Authority 80/06/26 1p
- BOD7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EIGENHUT, D Q Division of Licensing 80/06/26 2pp
- 8007150472 Forwards response to NUREO-057B, THI-2 Lessons Loarned Task Force status rept & short-term recommendations Consolidates previous ltrs includes revisions to containment isolation & shielding items MILLS.I. M Tunnessee Valley Authority 80/07/03 lp
- 8007280001 "TVA Response to NUREO-0578, Short-Term Lessons Learned Regulrements" * Tennessee Valley Authority 80/07/03 500pp
- 8007150640 Advises that response to FBAR.Guestion 2 78.will not be organized & prepared for submittal until 800801 MILLS.L M Tennessee Valley Authority 80/07/08 1p
- 8007190892 Submits recommendations re facility steam generators, in response to NRC 800823 ltr Camera dovice will be designed & tosted for remote insp of tube supports in lieu of addiparts Max active tube surface margin will be mainLained MILLB,L M Tennessee Valley Authority 80/07/08 2pp
- 8007180521 Forwards info re Category 1 masonry walls, in response to NRC 800421 ltr Results of investigation of implace attachments to mesonry walls will be submitted by 801017 Dversize encis available in Central Files (31 pp)
 MILLB.L M Tennessee Valley Authority 80/07/09 4pp
- ---BD07150922 "Design Criteria for Reinforced Concrete Block Walls "
 STONE, F. A., CANNON, R. W., LACY, F.P. Tennessed Valley Authority
 72/04/07 29pp
- 8007150571 Forwards Revision 2 to util response to item 2 1 da, NUREO-0578 Revision incorporates leak testing procedures for waste gas sys (App E) & results of leak reduction program for liquid & gas sys (App E)
 MILLB.L M Tennessee Valley Authority 80/07/11 App
- --8007150978 Surveillance Instruction BI-455.Revision 1. "Weste Gas Bys Gross Leakage Test " KUEHN-L B Tennessee Valley Authority 80/06/12 14pp
- ---B0071505B2 Liquid sys leak test data CHURCH, J W Tennessee Valley Authority B0/07/01 9pp
- 8007160471 Responds to J Spraul Informal questions re FSAR Table 17 2-1 & forwards operational GA manual.App A.re critical sys & Part 3.9ection 2.re matl & spare parts
 MILLS.L M Tennessee Valley Authority 80/07/11 5pp
- --8007160478 Operational GA manual.App A.re critical structures, mys & components list
 OREEN.H J Tennessee Valley Authority 78/08/15 50pp
- ---BD071604B4 Operational QA manual,Part 3,Bection2,re mat1 & spare parts * Tennessee Valley Authority 78/08/29 33pp
- 8007280006 Notification of 800723 meeting w/utils in Bethesda,MD to discuss matters re TMI-2 dated requirements DROMERICK.A W. Licensing Branch 1 KERRIDAN,J D., STABLE.C R Licensing Branch 2, 80/07/16 6pp
- 8007230467 Forwards response to NRC 800507 request for commitment to meet requirements & associated schedules in five specific TMI items includes shift manning.lirensing examinations & licensed dissemination of operating experience MILLS.L M Tennesses Valley Authority 80/07/18 4pp
- 8007230477 Forwards response to NRC 600417 request for add1 info re shielding design review high renge containment radiation monitor & access control of areas adjacent to spent fuel transfer tubes MILLS.L M Tennessee Valley Authority 80/07/10 8pp

- 007230480 Forwards "ECOPAC Bolidification Sys Process Control Program." Revision 4.in response to NRC 800324 request MILLS.E.M. Tennessee Valley Authority 80/07/18 ip
- -8007230481 "ECOPAC Solidification Sys Process Control Program" Revision 4 * Tennessee Valley Authority 80/07/18 20pp
- -8007230483 "Technical Rept on Urea Formaldehyde" Marked-up Amefco rept on procedure for unsite solidification of low level radwaste at facility encl # Ansfco.lnc 80/07/18 43pp
- 007230533 Forwards response to N Mendonce B00627 questions re reactor vessel head venting sys Nestinghouse is developing procedures for inadequate core cooling for recommended use of vent sys by utils MILLS,L M Tennessee Valley Authority B0/07/18 lipp
- 007230408 Forwards add1 info per NRC 800619 request re control of containment sump debris MILLS.L M Tennessee Valley Authority 80/07/21 14pp
- 007290724 Forwards description of program, "Training for Mitigating Core Damage " Program was developed to ensure that all licensed operating employees are properly trained to use available info should accident occur involving core damage MILLG.L M Tennessee Valley Authority 80/07/22 5pp.
- 007280523 Advises NRC of evaluation of potential hazards in vicinity of plant & of main control room habitability sys for protection from radioactive & toxic gas releases Plant operators are adequately protected from possible hazards MILLS, L. H. Tennessee Valley Authority 80/07/24 1p
- 007290757 Forwards data & drawings re settlement monitoring Revised Questions SNP 02 84 & SNP G2 73 will be incorporated into FBAR in next amend No significant settlement observed. Drawings available in Contral Files only MILLB.L N Tennesses Valley Authority B0/07/RB 12pp
- 007310394 Advises that short-turm items & two long-term items listed in MUREO-0011 re main control room design review have been corrected Util committed to investigate feasibility of correcting remaining items of first refueling outage MILLS,L M Tennessee Valley Authority 80/07/28 4pp
- 007310411 Submits test results of plant auxiliary bldg gas treatment sys per requirements of SER, Suppl 1 Negative pressure equal to or more negative than minus 1/4-inch water gauge relative to outside atmosphere was achieved in pump rooms MILLG, L. M. Tennessee Valley Authority 80/07/29, ip
- 007310416 Forwards add1 info on temp control for main steam valve rooms.per O Parr request MILLS.L M Formseee Valley Authority 80/07/27 2pp
- Security, medical, emergency & fire protection plans
- 007160643 Forwards revised commitment for fire protection program re-evaluation, Section A 3(b), re locking of fire protection water sys valves Revision was made in response to IE Insp Repts 50-0327/80-10 & 50-328/80-06 MILLB, L M Tennessee Valley Authority 80/07/03 3pp
- 007230375 Forwards revised radiological emergency plan w/cross-ref between plan & NUREO-O454 & App F.TN radiological emergency responso plan Encis available in Central Files only MILLS,L M Tennessee Valley Authority 80/07/21 3pp
- 00728054B Advises that Westinghouse reviewed power-ascension test procedures par Tosk Action Plan Item 1 C 7. Review of emergency procedures documented by B0042B 1tr to LB Rubenstein.
- Tennessee Valley Authority 80/07/23 ip
- 007300434 Agraes, as interim step decided at NRC 800725 meeting, to expand near sits press facility to provide for command control function for emergency response Central emergency response ctr.per util 800721 ltr.requires addidiscussion MILLS, L.M. Tennessee Valley Authority. 80/07/28, ip
- Adjudicatory correspondence
- 007310243 Forencis Comission CCCPT manifed in A other containing decisions on the Medical action at the Medical manifest of 780913 memorals in Americal 1 / 121 points a soly traction rating protect in for steel call all all actions and the Medical All actions of t

- K Utility Final Bafety Analysis Report (FBAR) & amends
- BOO7300374 Amend to OL application, consisting of Amend 66 to FSAR, revising Chapters 2.3.5.6 & 15 FBAR documentation of items transmitted by LM Mills BOO613 ltr & responses to NRC questions encl CROSS.J.L Tennessee Valley Authority BO/07/25 is.
- --B007300376 Amend 66 to FBAR, revising Chapters 2,3,5,6 & 15.
 * Tennessee Valley Authority B0/07/28 92pp
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- BO07230013 Notice of ACRB Bubcommittee on Bequoyah Nuclear Plant B00709 meeting in Washington, DC to review DL request HOYLE, J C Office of the Becretary of the Commission 60/04/18.
- 8007210248 Discusses review conducted at 243rd ACR8 meeting on 800710-12 of util application to operate at full power Facilities can be operated at levels up to full power w/o undue risk if items outlined are considered PLESSET.M 8 ACR8 Advisory Committee on Reactor Bafeguards, 80/07/15 3pp
- BOO7210331 Responds to BOO710 request re particular aspects of facility Applicant committed to expedite installation of distributed ignition sys. No practical need to hold up issuance of GL pending completion of proposed sys. PLEBBET.M B ACRS Advisory Committee on Reactor Gafeguards BO/07/15 ip
- B007270022 Forwards Ahearne B00715 ltr re ACRB review of application for authorization to operate BCHWENCER, A Licensing Branch 2. B0/07/17 3pp
- P. Operating license stage documents & correspondence
- 8007290679 Forwards preliminary assessment of potential for herge tow heading upstream impacting new essential raw cooling water pumping station Station not required for safe operation of MILLE, L M Tennessee Valley Authority 80/07/28 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode."
 No response required.
 D'REILLY, J P Region 2, Atlanta, Diffice of the Director. 80/05/08.
- BOO7020192 Forwards IE Info Notice BO-22, "Breakdowns In Contamination Control Programs " No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director, BO/05/20
- 8007210488 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/28.
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/29,
- BO07180005 Forwards IE Insp Repts 50-327/80-19 & 50-329/80-12 on B00513-16. No noncompliance noted. LEHIB:R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/06/05 2pp
- ---B007180011 IE Insp Repts 50-327/B0-19 & 50-328/B0-12 on B00613-16. No noncompliance noted, Mejor areas inspected: preoperational testing, program review & implementation & followup of previously identified items
 ABHENDEN.M. C. BUTLER.B. D Region 2, Atlanta, Office of the Director. UPRIGHT.C M. Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch B0/06/04. App
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs, "No written response required, D'REILLY, J. P. Region 2, Atlanta, Diffice, of the Director. 80/06/10.

1

- 8007160287 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Stude" no specific action or response required O'REILLY, J.P. Region 2. Atlanta. Defice of the Director 80/06/11 to
- B007250384 Forwards IE Info Notice B0-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/13
- 8007290846 Forwards IE Insp Rept 50-328/80-13 on 800922 & 23 No noncompliance noted STOHR, J P Region 2. Atlante, Fuel Facility & Materials Safety Branch 80/06/19 2pp
- -- G007270B53 IE Insp Rept 50-328/80-13 on B00522 & 23 No noncompliance noted Hajor areas inspected preporational & operational environ monitoring programs

 -- ENKING, G Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch CUNNINGHAM, A L. Region 2, Atlanta, Office of the

 Director 80/06/17 App
- 800702039i Forwards IE Carcular 80-15. "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown " No writton response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/20
- 8007110034 Ack receipt of 800523 Itr informing NRC of steps taken to carrect violation noted in IE Insp Repts 90-327/80-14 & 50-328/80-08 MRPHY, CE Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/24 ip
- --8007110039 Submits add1 response to NRC 800501 ltr re violation noted in IE Insp Repts 50-327/80-14 & 50-328/80-08 Corrective actions all Section 3 surveillance instructions comply w/ Section ii of ASME boiler code
 MILLS,L. H Tennessee Valley Authority 80/06/09 1p
- 8007170070 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Hater Bys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 to
- B007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 60/06/R7
- 8007080331 Forwards response to Deviation Item 50-327/80-17-01, noted in IE Insp Repts 50-327/80-i7 & 50-328/80-i0 re inadequate fire barriers Required insulation installed on seven conduits. & cover plates reinstalled on three conduit fittings HILLS,L M Tennessee Valley Authority 80/06/30 3pp
- 8007210036 Forwards response to IE Bulletin 80-69 re-examination of containment liner penetration welds Penetrations at Sequoyah Watts Bar & Bellefonte contain flued head design Design for Yellow Creek not yet completed MILLG, L M Tennessee Valley Authority 80/07/08 5pp
- 8007230494 Responds to NRC 800625 ltr re deviation in IE Insp Rept 50-328/80-11 Corrective actions nondestructive examiners were cautioned & reminded that any & ail failures to obtain complete scans must be documented MILLS, L M Tennessee Valley Authority 80/07/17 2pp
- 8007280498 Forwards addI response to IE Bulletin DD-06. "Engineered Safety Feature (ESF) Reset Controls " Prosent control schemes adequate Equipment evaluation encl MILLS.L M Tennessee Vallay Authority 60/07/24 Spp
- 8 Reportable occurrences, LERs & related correspondence
- 8007160571 Forwards final deficiency rept re chemical & voi control system centrifugal charging pumps
 MILLS,L M Tennessee Valley Authority 80/06/10 ip
- --8007i60378 Final deficiency rept re potential for degradation of one or more chemical & vol control sys centrifugal charging pumps Dasign & plant emergency operating procedures will be modified, as recommended by Hestinghouse * Tennessee Valley Authority 80/06/18 2pp

- 8007170664 Part 21 final reptire Westinghouse chemical & vol control systematic formal reptire with a secondary side high energy line rupture & associated reactin trip, min flow may not be met Emergency operating procedures modified MILLS.L.M. Tonnessee Valley Authority 80/06/18 App
- 8007020543 Forwards final deficiency tept re safety-related cable inside containment
 MILLS.L.M. Tomosyer Valley Authority 80/06/26 1p
- --8007020545 Final deficiency trpt re-safety related cable inside containment Util will currect exposed coble & terminal boses by running cables in conduct, which will privide sufficient shielding for qualification to remain valid a Tennessee Vailey Authority 80/06/26 2pp
- BD07020944 Forwards final deficiency rept re dide stude generator level transmittors MILLS; I H Tennessee Valley Authority 80/06/26 ip
- --B00702055i Final deficiency rept to wide range steam generator lovel transmitters Transmitters will be replaced by qualified transmitters Installation will be completed before preparational testing of sys M Tennessee Vailey Authority 80/06/26 lp
- Q007090P49 Forwards revised final deficiency rept to spent feel pool gates
 MILLBL M (ennossee Valley Authority 80/D7/0,' ip
- ~~8007090256 Revised final deficiency rept re spent fuel paul yates Oates are not designed to Scismic Category I inquirements per Reg Ouide i 13 GA aspects of gate integrity will be verified for all three plants * Tennessee Valley Authority 80/0//02 2pp
- 8007140943 Forwards first interim deficiency rept re solution switches environ quairfication Wili submit next rept by 800812 MILLS.L M Tennessee Valley Authority 80/07/67 tp
- ---B007140496 First interim deficiency rept re gelectes switches environ qualification During review of switch contract documents: documentation not on file to substantiate that awitthes are environmentally qualified to switched temp * Tennessee Valley Authority B0/07/07 lp
- BOD7140666 Gecond interim deficiency rept re environ qualification of Class II instruments in valve room All instruments are being evaluated Next rept will be submitted by BOD912 MILLBLH Tennessoe Valley Authority 180/0//9/ ip
- 8007230431 First interim deficiency rept re environ qualification of Class It equipment Util cherking files & petitioning manufacturers of components for required environ decumentation

 MILLS, L. M. Tennossee Valley Authority 80/67/16 App
- 8007230486 First interim deficioncy rept re safety injection pump breaker lockout, initially repurted 800619 No visual or audial indication when lockout condition exists Problem under investigation Next rept to be submitted by 8000129 MILLS.L M Tennessee Voiley Authority 80/07/to Ppp
- 8007270632 Third interim deficiency rapt so UH hydraulic implantion valve accumulator weighing by: Util & Wattinghouse are pursuing solution to problem Next rept will be rubmitted by 801001
 MILLS.L M Tennessee Vailey Authority 18070/23 tp
- B007270610 Second interim delictoring rept re defective suarter venses upper internais guids tube support pins Westinghouse has not completed evaluation of piny taken from operating plant Next rept will be forwarded by 800911 0'REILLY. J P Tonnessee Valley Authority 80/0//24 1p
- T Hearing transcripts on non-ostations matters
- 800722006) Transcript of ACRS Subcommitter on Sequerah Nuclear Plant 800709 meeting in Hashington BC Pp 3-26/2 4 ACRS - Advisory Committee on Reactor Suferguards 180/07/09 32556

- OCKET 50-329 MIDLAND PLANT, UNIT 1
- Application/construction stage documents & correspondence
- 007020159 Discusses D Hood 791031 memo re potential for post-LOCA flow blockage for PHR plants caused by containment sump screen deficiency Assessment needed to determine whether Board notification pecessary VARGA, S A Assistant Director for Light Water Reactors 79/11/24
- -8007020167 Discusses 79103) teleon w/util re 790917 trip rept of containment sump screen deficiency & 920 concern re potential for post-LOCA flow blockage Review requested to determine whether Board notification necessary HOOD,D Light Water Reactors Branch 4 79/10/31 lp
- 007020151 Requests info from CP & OL applicants re SA Varga 791126 memo on post-LDCA flow blackage for PMR plants, based on insulation type & suon screen mesh size Evaluation necessary to determine whether Board notification necessary MATTSON.R J Division of Systems Safety 79/12/13 2pp
- OD7310386 Forwards TR-3887-2, "Acceptability for Svc of Midland Reactor Pressure Vessel Anchor Studs." Revision 1 Related correspondence DDBSON.W 0 . CODPER.W E Teledyne Engineering Services 80/05/15
- -8007310387 "Acceptability for Svc of Hidland Reactor Pressure Vessel Anchor Studs," Revision 1 Related correspondence # Teledyne Engineering Services TR-3887-2 Ri NO1 80/05/20
- 007010397 Ferwards NRC reoganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 007070119 Forwards "Model Testing of Containment Bump ECCS Recirculation Intakes," prepared by Western Canada Hydraulic Labs.Ltd.for Bechtel Power Co Comments on NRC 790917 trip rept encl
 COOK, J W Consumers Power Co 80/06/26 10pp
- -8007070130 "Model Testing of Containment Sump ECCS Recirculation Intakes," prepared for Bechtel Power Co & util * Western Canada Hydraulic Laboratories, Ltd 80/04/30 92pp
- 007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0560 & found in NUREG-0574 EISENHUT,D C Division of Licensing E0/04/26 2pp
- 0071B0081 Forwards request for addi info re plant fill to support required geotechnical engineering studies for review of responses to NRC 791119 request SCHMENCER(A Licensing Branch 3 80/06/30 9pp
- 007280060 Responds to NRC 800522 ltr requiring two actions prior to resumption of safety-related work by Zack Co Limited work that is performed will be evaluated & if acceptance level of confidence is attained then full production can resume CDCK.JW Consumers Power Co 80/06/30 Bpp
- DO7230116 Advises that util is not exempt from fee requirements for 791219 application for CP amends Any CP amends to be issued by NRC are not seen as resulting from 791206 order MILLER, W O License Fee Management Branch 80/07/03 ip
- 007280041 Submits revised facility project schedule Integrated 2-unit startup program retained Bept 1980 NRC Yellowbook update transmittal will reflect milestone dates based on listed completion dates.

 MILLER.D B Consumers Power Co 80/07/03 1p
- 007140476 Summary of 800023 meeting w/util.Bechtei.B&W & Teledyne in Bathesda.MD re three reactor vessel hold-down studs preservice failure HODD-D S Licensing Branch 3 80/07/07 10pp
- ROO7180019 Forwards guidelines for selamic & structural design analysis audit planned as part of review of OL application Info should be filled in on guideline forms prior to audit Audit will take fave working days
 SCHWENCER.A Licensing Branch 3 80/07/07 187pp

- 8007230507 Lists drawings & sketches submitted by util found to be partially illegible Independent confirmatory piping analysis requested by NRC cannot be performed until better copies are obtained BATES, JO Rockwell International Corp. Energy Systems Div BO/07/07 2pp
- 8007150497 Comments on proposed addi guidance on potential for low fracture toughness & lamellar tearing of LWR component support structures NRC generic guidance invalidates many support designs developed per past applicable codes & stds CODK.JW Consumers Power Co 80/07/08 4pp
- B007240040 Notification of 800805 meeting w/util in Bethesda, HD to discuss schedules for const & licensing review H00D, D S Licensing Branch 3 80/07/09 App
- 8007210483 Forwards updated FBAR Pages 3 8-24 through 3 8-26s,Pages 17 1-11 through 17 1-14 & Question & Response Pages 17 1-1 through 17 1-4 in response to NRC 800522 1tr M/o encl CODK, J W Consumers Power Co 80/07/14 2pp
- 8007300104 Notification of 800731 meeting w/util & Bechtel in Bethesda, MD to discuss addl info on plant fill HOOD, D S Licensing Branch 3 , 80/07/21 4pp
- BD07300261 Notification of B00728 & 29 meetings & plant tour w/util & Bechtel to assess const completion schedules Meeting agenda & FR exempt encl
 H000.0 B Licensing Dranch 3 80/07/21. 7pp
- BOO7290036 Notification of BODB21 open westing w/util in Bethesda.MD, originally scheduled BOO805, to discuss const & licensing review schedules
 HODD.D B Licensing Branch 3 80/07/22 Spp
- 8007270701 Objects to exclusion of proposed amends from 10CFR170 22, Footnote 2.which excepts such amends from license fee requirements Requests reconsideration BRUNNER.J E Consumers Power Co 80/07/22 3pp
- --8007290707 Responds to 800403 itr objecting to fees for 791219 application for amend to CPs Commission 791206 order does require application therefore exemption to 10CFR170 22 is not applicable

 MILLER.H O License Fee Management Branch 80/07/03 ip
- F Security, medical, emergency & fire protection plans
- BOO7010473 Discusses proposed change to 10CFR30 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Guestions appropriateness of rule, since rule reopens resolved issues HOFFMAN, D. P. Consumers Power Co. 80/06/27 8pp
- 8007090393 Summary of 800611 meeting w/util & Bechtel in Bethesda,MD re-security plans to protect against radiological sabotage HOOD,D Licensing Branch 3 80/06/30 4pp
- O Adjudicatory correspondence
- BOO7080051 Patition to intervane me order for CP modualleging that mod will result in unsafe & inefficient exercise of atomic energy use & will create adverse environ affects
 Centificate of Svc encl
 WILSON, C C Affiliation Unknown 80/06/24 3pp
- 8007070282 Petition to intervene in CP mod proceeding alleging that unresolved soil suttlement problems will create adverse safety problems Certificate of Bvc encl MILLER.T R Affiliation Unknown 80/06/25 3pp
- 8007080039 Petition to intervene in CP mod proceeding, alleging that unresolved soil settioment problems will adversely affect safety & will create inefficient exercise of atomic energy use Questions integrity of const. Certificate of Syc encl RACE. H A Affiliation Unknown 80/06/25 3pp
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/06/25 89pp
- 8007080054 Petition to intervene re order for CP modualleging that unresolved soil settlement issue will treate adverse safety problems & will result in inefficient exercise of atomic energy use Certificate of Svc encl
 REIST.S D Affiliation Unknown 80/06/26 3pp

- BOO70205B2 Memorandum & order granting NRC GOO616 request to postpone response to GPC BOO527 motion seeking consolidation of soil conditions & plant fill matts issues re DL & order for license mod proceedings BHITH. I W Atomic Safety and Licensing Board Panel BO/06/2/ ip
- 6007010333 Ack receipt of 800617 ltr re recent containment bldg
 publicity Util ltr re inconsistent cross-referencing between
 M&H & Bechtel encl Further rept on issue will be provided
 when available Representation status requested
 PATON, N D Hewring Branch 4 80/06/30 2pp
- BO07140017 Patition in opposition to util motion for consolidation re 791206 order modifying CPs Urges postponement of response & requests that activities be stopped due to deficiencies in const & safety-related structures HARSHALL, H H Hapleton Intervenors B0/06/30 2pp
- BOO7090045 Response stating no present opposition to WA Thibodeau.TR Miller.PA Race.B Stamiris & C Oilbert patitions to intervane Reserves right to oppose participation in future development & urges consolidation Curtificate of Svc encl MILLER.M I . FARNELL.A S. Consumers Power Co MILLER.M I Isham. Lincoln & Beale 80/07/01 Dpp
- B007070005 Response in support of C Gilbert B00616 petition to intervene in CPs mod proceeding. Standing requirement satisfied Ruling on contention requirement premature Cartificate of Svc encl PATON.W.D Hearing Branch 4.
- BO07140020 Response stating no present opposition to SK Warren. SD Reist, QC Wilson & MA Race patitions to intervene relicense mod Reserves right for future objection & urges representation by single spokesman Certificate of Svc encl MILLER. M I , FARNELL. A B. Gonsumers Power Co MILLER. M I Isham, Lincoln & Beale. B0/07/08 6pp
- 8007170226 Response in support of WA Thibodeau, TR Hiller, GC Wilson, BD Raist, PA Race, B Warren, MA Race & B Stamiris petitions to intervene re 791206 order modifying CPs Ruling on adequacy premature Certificate of Svc encl PATON, W D Hearing Branch 4 80/07/14 App
- 9007170232 Response in support of WH Marshall 800623 petition to intervene re 791206 order modifying CPs Ruling on adequacy preseture. Certificate of Evc encl PATON, N D. Hearing Branch 4 80/07/14 App
- 8007220194 Response to Mapleton Intervenors 800630 petition Argument ra consolidation untimaly frequest to postpone NRC response to CPC motion most Soil-related issues are within scope of CL proceeding & NRC 791206 order Certificate of Svc encl. HILLER, M I Consumers Power Co HILLER, M I Isham, Lincoln & Beals 80/07/15 Spp
- 8007170385 Advises that HH Harshall of Mapleton Intervenors 800430 patition to AilD should not be given consideration at present stage since intervenor not yet admitted in proceeding PATCM H D Hearing Branch 4 80/07/16 ip
- BOO7180242 Responds to 800410 ltr urging NRC action to stop const Issue will be submitted to ASLD who has proper jurisdiction over matter in controversy Reminds of MRC position that Willeman Marshall has standing to intervens PATON, W D Hearing Branch 4 80/07/17 2pp
- 8087300421 Advises that util & Bechtel Power Corp have reached agreement on revised schedule re commercial operation of Units 1 & 2.Unit 2 acheduled for commercial operation in Dec 1903 & Unit 1 in Jul 1984 OIBBB, H E Isham, Lincoln & Beale 80/07/22 ip
- BOO7290730 Order & notice of BOD910 special prehearing conference in Midland, MI re identification of issues ruling upon intervention petitions & other related issues Public invited to attend w/o active participation SMITM, I. W. Atomic Safety and Licensing Board Panel BO/07/24 3pp
- 8007270752 Order denying Hapleton Intervenors' 800630 petition urging ASLB not to consider CPC motion for consulidation Intervenor may respond directly to motion.

 BHITH I W. Atomic Safety and Licensing Board Panel. 80/07/24 2pp
- BOO7270766 Hemorandum & order ruling that petitioners PA Race.D Blemaris, SD Reist, SK Herren, TR Miller, MA Race.GC Milson, WA Thibedeau & C Gilbert have satisfied interest & aspect requirements Conference re DL will be set for BOO710 SMITH, I. W Atomic Safety and Licensing Board Panel BO/07/24 Sps

- H General correspondence
- 8007180148 Opposes const of facilities Great Lakes region would be destroyed if TMI-type accident occurred * Affiliation,Unknown 80/05/16 lp
- 8007i10488 Responds to 800605 ltr re NRC insps of reactor vessel anchor bolts Belts are susceptible to cracks in thread area due to original bolt specs, selection of matls & method of heat treating NRC reviewing revised design to determine adequacy STRASMA. J. Regiun 3. Chicago. Office of the Director 80/06/23 ip
- 8007280523 Responds to 800521 ltr requesting info re PA D'Archangel request that NRC expedite facility licensing Addl NRC effort resulting from TM1-2 accident caused delays in licensing Development of schedule for review of application underway DIRCKS.W J Dffice of the Executive Director for Operations 80/07/02 Spp
- --8007280536 Requests response to encl PA D'Archangel ltp requesting that NRC expedite facility licensing SAMYER.H S House of Rep 80/05/Pl 2pp
- 8007160634 Requests response to each WH Marshall itr re Oct 1979 request for info about facility Request unanswered ALBOSTA:D House of Rep 80/07/09 2pp
- --B007i60649 Provides list of conditions for which info is requested re safeguards for public health & safety Aiso requests resolutions re cracking dewatering bldg settlements & caisons problems per NRC 790223 & 0305 meetings in IL MAREHALL.H H Maploton Intervenors 79/09/04 2pp
- BOO7230190 Responds to 800605 ltr re frequency of correlation strength test sampling on new safety-related concrete NRC position reflects increased testing during periods of low vol placement SCHMENCER, A Licensing Branch 3 80/07/09 9pp
- 8007130697 Forwards current rules of practice W/g enci PATON.W D Hearing Dranch 4 80/07/li ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007240146 Updated FBAR Pages 3 B-P4 through 3 B-P6a.FBAR Pages 17 1-11 through 17 1-14b & Question & Response Pages 17 1-1 through 17 1-4 to be included in FSAR.Revision 2.in response to NRC 800522 itr 8 Consumers Power Co 80/07/14 14an
- Q Inspection reports. IE Bulletins & correspondence
- 8006300114 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on B00301-31 No nuncompliance noted FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/14 2pp
- --8006300138 IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas insperted exam of site conditions & detensioning reactor vessel holddown bults COOK, R J , KNOP, R C Region 3. Chicago, Office of the Director 80/05/13 9pp
- 8007210360 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/03/28 16
- 8007010144 Forwards 1E Info Notice 80 23. "Loss of Suttion to Emergency Fadwater Pumps" No written response required KEPPLER, J 9 Region 2. Chicago. Office of the Director 80/05/29 ip
- 8007020649 Forwards status of actions to provide corrected response to IE Dulletin 79-02 Final response or status rept will be submitted by 801031 CDDK.J W Consumers Power Co 80/06/09 4pp
- 8007220183 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/06/10

- 40178 Forwards IE Info Notice 80-27, "Degradation of Reactor lant Pump Stude " No specific action or response
- PLER. J Q Region 3, Chicago. Office of the Director 80/06/11
- 80707 Forwards IE info Notice 80-28, "Prompt Reporting of Info in ordance W/IOCFR50 55(e) " No written resonnse required PLER.J G Region 3. Chicago. Office of the Director 80/06/13
- 20306 Responds to IE Bulletin 80-09, "Hudramotor Actuator iciencies " Vendors evaluating which actuators will wire mod or replacement to which will meet spec wirements re spring & sizing nomograph problem W.J W. Consumers Power to 80/06/17 2pp
- 30402 Forwards IE Insp Repts 50-329/80-16 & 50-330/80-17 on MOI-30 No nontumpliance noted

 RELLIG Region 3, Chicago, Reactor Construction & Engineering
 port Branch 80/06/17 2pp
- 07230412 IE Insp Repts 50-329/80-16 & 50-330/80-17 on 800401-30 No oncompliance noted Major areas inspected site conditions, seactor vessel holddown bolts & Unit I reactor comlant CODK, R I Region J. Chicago. Office of the Birector HAYES, D W legion J. Chicago. Reactor Construction & Engineering Support Branch 80/06/05 4pp
-)20562 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump pling & Natural Circulation Cooldown "No written response quired "PLER.J G Region 3, Chicago, Office of the Director 80/06/20
- 170467 Forwards IE Circular 80-14. "Radioactive Contamination of nt Demineralized Water Sys & Resultant Internal stamination of Personnal "No written response required spLERJ g Region 3. Chicago. Uffice of the Director B0/06/24
- 300300 Forwards IE Insp Repts 50-329/80-10 & 50-330/80-19 on 5501-31 No noncumpliance noted MRELLI, Q Region 3, Chicago, Reactor Construction & Engineering sport Branch 80/04/26 2pp
- 17300304 IE Insp Repts 50-329/80-18 & 50-330/80-19 on 800501-31 No noncompliance noted Major areas inspected suspect pips whip restraint bolting const activities of Zeck Co. detensioning if reactor vessel holdown bolts & audit of Peabody Testing COOK.R J. KNOP.R C Region G. Chicago, Office of the Director 80/06/24
- 230358 Forwards IE Bulletin Bü-16. "Petential Misapplication of semount inc Models ii51 & 1152 Prossure Transmitters ither A or D Gutput Codes " Hritten response required Circuiar BO-16 also enci No written response required PPLER.J O Region J. Chicago. Office of the Director 80/06/2 80/06/27
- 170625 Forwards IE 1msp Repts 50-329/80-15 & 50-330/80-16 on 0602-05 No noncompliance noted ORELLIG Region 3. Chicago, Reactor Construction & Engineering pport Branch 80/06/30 2pp
- 07170635 IE Inap Repts 50-329/80-19 & 30-330/80-16 on 800602-05 No noncompliance noted Major areas inspected records & test results of steam generator anchor bolts & pape restraint
- bolts VANDEL.TE , ERB.C M , MAIDU.K R Region 3. Chicago, Office of the Director 80/06/26 12pp
- '160612 Provides interim response to IE Bulletin 80-08 re amination of liner penetration welds includes list of netration info un joint type, flued head math, sleeve math & ameter type of examination performed & repair info IOK, J W Consumers Power Co 80/07/11 lipp
- '310521 Ack receipt of 800630 ltr informing NRC of steps taken to preet const problems noted in IE Insp Repts 50-329/80-14 & -330/80-15
 - Region 3. Chicago, Office of the Director 80/07/25
- 007310529 Forwards response to NRC BO0522 ltr re const problems noted in IE losp Repts 50-329/80-14 & 50-330/80-15 Corrective actions Jack Co QA manual & QC control procedures were reviewed for adequacy & clarity CDOK.J N Consumers Power Co 80/06/30 App

- R Periodic operating reports & related correspondence
- 8007280124 Forwards Bechtel nonconformance repts GA audit finding rept, mgt corrective action rept, B&W repts of nonconformity & util nonconformance repts, audit finding repts & corrective action repts for June 1980 COOK, J W Consumers Power Co 80/07/21 360pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007310386 Forwards TR-3887-2. "Acceptability for 8vc of Midland Reactor Pressure Vessel Anchor Studs." Revision 1 Related correscondence DOUSON, W G . COOPER, W E Teledyne Engineering Services 80/05/15
- -8007310397 "Acceptability for Svc of Midland Reactor Prassure Vessel Anchor Studs," Revision 1 Related correspondence #_ Teledyne Engineering Services TR-3887-2 RI NOI 80/05/20.
- 8007160807 Part 21 rept re defective fastener matls A490 & A540 supplied by Southern Dolt & Fastener Gorp for site assembly & installation of pipe whip restraints Possibly caused by improper heat treatment or wrong matls supplied HARBISON D NPS Industries, inc 80/06/16 11pp
- 8007070197 Act receipt of 800613 interim deficiency rept re component qualification test documentation re-review FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/06/23 ip Support Branch
- 8007150032 Ack receipt of 800612 interim deficiency rept re broken reactor vessel anchor boits Will review final rept upon receipt FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Rusport Branch 80/06/24 ip
- 8007170320 Act receipt of 800619 interim deficiency rept re letdown cooler supports
 FIORCLLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/01 ip
- 8007240353 Interim Part 21 rept rp defective ITT actuators in dampers. Customer notification encl Jobs classified nonnuclear safety-related are not reportable, Actuators supplied for other jobs are considered purchaser responsibility SLOAN, D.E. American Warming & Ventilating, inc. 80/07/08 50pp,
- 8007270206 Final deficiency rept re emergency core cooling actuation sys digital Subsystem 2 logic circuitry drawings B&W will correct drawings by 800930 Facilities will be in conformance bu 800930 Consumers Power Co 80/07/17 5pp

DOCKET SO-330 MIDLAND PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8007020159 Distusses D Hood 791031 memo re potential for post-LOCA flow blockage for PHR plants caused by containment sump screen deficiency Assessment needed to determine whether Board notification necessary
 VARGA.S A Assistant Director for Light Water Reactors 79/11/26.
- ---8007020167 Discusses 791031 telcon w/wtil re 790917 trip rept of containment sump screwn deficiency & B&W concern re potential for post-LOGA flow blockage Review requested to determine whether Board notification necessary, HOOD.D Light Water Reactors Branch 4 79/10/31 1p
- B007020151 Requests info from CP & OL applicants re SA Varge 791126 memo on post-LOCA flow blockage for PWR plants, based on insulation type & sump screen mesh size Evaluation nacessary to dotermine whather Board hotification necessary MATTRON R J Division of Systems Bafety 79/12/13 2pp
- 8007310386 Forwards TR-3887-2. "Acceptability for 8vc of Midland Reactor Pressure Vessel Anchor Studs," Revision 1. Related correspondence DOBBON, W 9 , COOPER, W E. Seledyne Engineering Services 80/03/15
- --B0073103B7 "Acceptability for Bvc of Midland Reactor Pressure Vessel Anchor Studs." Revision 1. Related correspondence # Teledyne Engineering Services TR-38B7-2 R1 ND1. 80/05/20.

- BOO7010557 Forwards NRC reoganization chart for Ofc of Nuclear Reactor Regulation, effective B00428 Considerations re activities about the made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing B0/06/13 2pp
- 8007070119 Forwards "Model Testing of Containment Sump ECCS Recirculation Intakes," prepared by Western Canada Hydraulic Labe, Ltd. for Bechtel Power Co Comments on NRC 790917 trip rept encl CDOM, J W Consumers Power Co 80/06/26 10pp
- --8007070130 "Model Testing of Containment Sump ECCS Recirculation Intakes," prepared for Bothtel Power Co & util * Nestern Canada Hydraulic Laboratories, Ltd 80/04/30 92pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREO-0660 & found in NUREO-0694
 EISENMUT.D 0 Division of Licensing 80/06/26 2pp
- BOO71800B1 Forwards request for addl info re plant fill to support required geotechnical engineering studies for review of responses to NRC 791119 request BCHMENCER: A Licensing Branch 3 60/06/30 9pp
- 8007280060 Responds to NRC 800522 ltr requiring two actions prior to resumption of safety-related work by Zark Co Limited work that is performed will be evaluated & if acceptance level of confidence is attained, then full production can resume CDOK, J. N Consumers Power Co 80/06/30 Spp.
- BOO7230116 Advises that util is not exempt from fee requirements for 791219 application for CP amends Any CP amends to be issued by NG are not seen as resulting from 791206 order MILLER, N. O License Fee Management Branch 80/07/03 ip
- 8007280041 Submits revised facility project schedule Integrated 2-unit startup program retained Sept 1980 NRC Yellowbook update transmittal will reflect milestone dates hosed on listed completion dates
 MILLER, D. B. Consumers Power Co 80/07/03 ip
- BO07140496 Bummary of B00523 meeting w/util, Bechtel, B&W & Teledyne in Bathesda. HD re three reactor vessel hold-down studs praservice failure HO00.D B Licensing Branch 3 80/07/07 10pp
- BOO7180019 Forwards guidelines for Beismir & structural design analysis audit planned as part of review of GL application Info should be filled in on guideline forms prior to audit Audit will take five working days
 BCHMENCER, A Licensing Branch 3 80/07/07 187pp
- BOO7230507 Lists drawings & skotches submitted by util found to be partially illegible Independent confirmatory piping analysis requested by NRC cannot be performed until better copies are obtained BATES, J.O. Rockwell International Corp. Energy Systems Div 80/07/07 Zpp
- 8007150497 Comments on proposed add1 guidance on potential for low fracture toughness & lamellar tearing of LWR component support structures NRC generic guidance invalidates many support designs developed per past applicable codes & stds COORTJ W Consumers Power Co 80/07/08 4pp
- B007240040 Natification of B00B05 meeting w/util in Bethesda. HD to discuss schedules for const & licensing review H000, D S Licensing Branch 3 B0/07/09 4pp
- BOO7210483 Forwards updated FBAR Pages 3 8-24 through 3 8-26#, Pages 17 1-11 through 17 1-145 & Question & Response Pages 17 1-1 through 17 1-4 in response to NRC BOO522 ltr M/o encl COCK, J W Consumers Power Co 80/07/14 2pp
- 8007300104 Notification of 800731 meeting w/util & Bechtel in Bethesda. MD to discuss addl info on plant fill HOOD, D. S. Licensing Branch 3 80/07/21 4pp
- B007300261 Notification of B00728 & 27 meetings & plant tour w/util & Bschtel to assess const completion schedules Meeting agenda & FR exempt encl HCAD.D. B Licensing Branch 3 B0/07/21 7pp
- 8007270036 Notification of 800821 open meeting w/util in Bethesda, MD, originally scheduled 800805, to discuss const & licensing rayiew schedules HOOD, D 8 Licensing Branch 3 80/07/22 8pp

- 8007290701 Objects to exclusion of proposed amends from 10CFR170 22, Footnote 2.which excepts such amends from license fee requirements Requests reconsideration BRUNNER, J E Consumers Power Co 80/07/22 3pp
- --8007290707 Responds to 800403 ltr objecting to fees for 791219 application for amend to CPs Commission 791206 order does require application, therefore exemption to 100FR170 22 is not applicable HILLER.W O License Foe Management Branch 80/07/03 1p
- F Security, medical, emergency & fire protection plans
- 8007010473 Discusses proposed change to iOCFR50 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Questions appropriateness of rule; since rule reopens resolved issues HOFFMAN, D P Consumers Power Co 80/06/27 Bpp
- 800/090393 Bummary of 800áil meeting w/util & Bechtel in Bethesda, MD re security plans to protect against radiological sabotage HDQD,D Licensing Branch 3 80/06/30 4pp
- O Adjudicatory correspondence
- 8007080051 Petition to intervene re order for CP mod, alleging that mod will result in unsafe & inefficient exercise of atomic energy use & will create advorse environ effects Certificate of Bvc encl HILSON, G C Affiliation Uninown 80/06/24 3pp
- B007070282 Petition to intervene in CP mod proceeding, alleging that unresolved soil settlement problems will create adverse safety problems Certificate of Svc encl MILLER.T R Affiliation Unknown 80/06/25 3pp
- 8007080039 Potition to intervene in CP mod proceeding, alleging that unresulved soil settlement problems will adversely affect safety & will create inefficient exercise of atomic energy use Questions integrity of const Certificate of Sv. encl RACE, M.A. Affiliation Unknown 60706/25 3pp
- 800/310240 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 77104 petition sought action to fifthe protection for electrical cables CISENHUY, D O Division of Licensing 80/06/25 89pp
- B0070B0054 Petition to intervene re-order for CP mod.alleging that unresolved soil settlement issue will create adverse safety problems & will result in inefficient exercise of atomic energy use Certificate of Svc encl
 REIBT, B D Affiliation Unknown 80/06/26 Jpp
- 8007020592 Memorandum & order granting NRC 800616 request to postpone response to CPC 800527 motion seeking rensolidation of soil conditions & plant fill matts issues re CL & order for license mod proceedings.

 SMITH, I W Atomic Safety and Licensing Board Panel 80/06/27 ip
- 8007010333 Ack receipt of 800617 ltm re recent containment bldg publicity Util ltm re inconsistent cross-referencing between 8kW & Bechtel enci Further rept on issue will be provided when available Representation status requested PATON.W D Hearing Branch 4 80/06/30 2pp
- 8007140017 Petition in opposition to util motion for consolidation re 791206 order modifying CPs Urgrs postponement of response & requests that activities be stopped due to deficiencies in const & safety-related structures MARSHALL, H H Mapleton Intervenors 80/06/30 2pp
- BOO7090045 Response stating no present opposition to MA Thitodeau, TR Miller, PA Race, B Stamiris & C Gilbert petitions to intervene Reserves right to appose participation in future development & urgeo consolidation Certificate of Svc encl MILLER, M I , FARNELL, A B Consumers Power Co MILLER, M I Isham, Lincoln & Beale 80/07/01 Spp
- 8007090055 Response in support of C Gilbert 800616 petition to intervene in CPs mod proceeding Standing requirement satisfied Ruling on contention requirement premature Certificate of Svc encil PATON.W D Hearing Branch 4 80/07/07 App

- 3007140020 Response stating no present opposition to SK Warren, 9D Reist, GC Wilson & MA Race petitions to intervene relicense mod Reserves right for future objection & urges representation by single spokesman Certificate of Svc enci MILLER, M I . TARNELL, A S Consumers Power Co MILLER, M I Isham, Lincoln & Beale 80/07/09 App
- B007170226 Response in support of WA Thibodeau.TR Miller,OC Hilson, SD Reist:PA Race, S Warren,MA Hace & B Stamiris petitions to intervene re 791206 order modifying CPs Ruling on adequacy premature Cortificate of Svc encl PATCN,W D Hearing Branch 4 B0/07/14 6pp
- 0007170232 Response in support of WH Marshall 800623 petition to intervene re 791206 order modifying CPs Ruling on adequacy promature Certificate of Svc encl PATON.W D Hearing Dranch 4 80/07/14 6pp
- 8007220194 Response to Mapleton Intervenors 800630 petition Argument re consolidation untimely Request to postpone NRC response to CPC motion most Sqil-related issues are within scape of OL proceeding & NRC 791206 order Certificate of Svc encl MILLER.M I Consumers Power Co MILLER.M I Isham, Lincoln & Beale 80/07/15 8pp
- 8007170385 Advises that WH Marshall.of Mapleton Intervenors 800630 patition to AGLB should not be given consideration at prasent stage since intervenor not yet admitted in proceeding PATON, V D Hearing Branch 4 80/07/16 19
- BOD7180242 Responds to BOO410 ltr urging NRC action to stop const Issue will be submitted to ASLD who has proper jurisdiction over matter in controversy Reminds of NRC position that WH Harshall has standing to intervence PATON, W D Hearing Branch 4 BO/07/17 2pp
- B007300421 Advises that util & Dechtel Power Corp have reached agreement on revised schedule re commercial operation of Units 1 & 2 Unit 2 scheduled for commorcial operation in Dec 1983 & Unit 1 in Jul 1984 GIBUS, HE I Sham, Lincoln & Deale B0/07/22 ip
- B007290730 Order & notice of B00910 special prehenring conference in Midland.HI re identification of issues, ruling upon interventions petitions & other related issues Public invited to attend w/o active participation SNITH, I W Atomic Safety and Licensing Board Panel B0/07/24 3pp.
- B007290792 Order denying Mapleton Intervenors' 800630 potition urging ASLB not to tensider CPC motion for consolidation Intervenor may respond directly to motion SMITH I W Atomir Safety and Licensing Board Panel 80/07/24 2pp
- 8007290766 Memorandum & order ruling that petitioners PA Race, B 8Tamaris, 8D Reist, 8K Warren, TR Miller, MA Race, OC Wilson, WA Thibadeau & C Gilbert have satisfied interest & aspect requirements Conference re QL will be set for 800910 8MITH, I W Atomic Sofety and Liconsing Board Panel 80/07/24 5p;

H General correspondence

- 800-7180168 Opposes const of facilities Oreat Lakes region would be destroyed if TMI-type accident accurred * Affiliation Unknown 80/05/16 1p
- BOO7GB0523 Responds to BOO5G1 ltr requesting info re PA D'Archangel request that NRC expedite facility licensing Addl NRC effort resulting from TMI-2 accident caused delays in licensing Development of schedule for revisu of application undorway DIRCKS, N J Diffice of the Executive Director for Operations BO/07/O2 5pp
- --8007280934 Requests response to encl PA D'Archangel 1tr requesting that NRC expedite facility licensing BANYER.46 B House of Rep 80/09/21 2pp
- 8007160634 Requests response to entl UH Marshall ltr re Oct 1979 request for anno about facility Request unanswered ALEOSTA.D House of Rep. 80/07/09 Rpp
- ----B007i60649 Provides list of conditions for which into is requested re safeguards for public health & safety Also requests resolutions re cracking dewatering, bldg settlements & caisons problems per NRC 790222 & 0305 metangs in IL MARSHALL. W H Hapleton Intervenors 79/09/04 2pp

- 8007230190 Responds to 800609 ltr re frequency of correlation atrangth test sampling on new safety-related concrete RRC position reflects increased testing during pariods of low vol placement
 8CHWENCER.A Licensing Branch 3 80/07/09 5pp
- B007130697 Forwards current rules of practice 4/o encl PATON W D Hearing Branch 4 E0/07/11 1p
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8007240146 Updatod FSAR Pages 3 8-24 through 3 8-26a.FSAR Pages 17 1-11 through 17 1-14 to Question & Response Pages 17 1-1 through 17 1-4 to be included in FSAR.Revision 2. in response to NRC 800922 ltr Consumers Power Co 80077/14 14p.
- G Inspection reports. IE Bulletins & correspondence
- 8006300114 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted FIDRELITO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8006300138 IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas inspected, exam of site conditions & detensioning reactor vessel holdown bults CODK,R J. KNOP,R C. Region 3, Chicago, Office of the Director. 80/05/13 Spp
- 8007210360 Forwards IE Circular 80-13, "Orid Strap Damage in Mestinghouse Fuel Assemblies " No written response required. KEPPLER, J.O. Region 3, Chicage, Office of the Director 80/05/29 in
- B007010144 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPFLER.J O Rogion 3, Chicago. Office of the Director. B0/05/29 in
- 8007220183 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director. 80/05/10 to
- 8007160178 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required KEPPLER.J O Region 3. Chicago. Office of the Director 90/06/11 1p
- 8007280707 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 95(s) " No written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/06/13
- 8007020306 Responds to IE Bulletin 80-09. "Mydramotor Actuator Deficiencies " Vendors evaluating which actuators will require mod or replacement & which will meet spec requirements re spring & sizing nomograph problem CDOK.J W Consumers Power Cn 80/06/17 2pp.
- G007230402 Forwards IE Insp Repts 50-329/80-16 & 50-330/80-17 on B00401-30 No noncompliance noted FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Gupport Branch G0/06/17 2pp
- --B007230412 IE Insp Repts 50-329/B0-14 & 50-330/B0-17 on B00401-30. No noncomplience noted, Major areas inspected; sits conditions, reactor vessel holddown bolts & Unit i roactor coolant CODW.R T. Region 3, Chicago, Office of the Director HAYEB,D,W Region 3, Chicago, Reactor Construction & Engineering Support Drench B0/06/05 4pp
- 8007020362 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown "No written response required KEPPLER, J O Region 3. Chicago, Office of the Director \$00/06/20.
- 8007170467 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/24 in

- 8007300300 Forwards IE Insp Repts 50-329/80-18 & 50-330/80-19 on 800801-31 No moncompliance noted FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/26 2pp
- --8007300304 IE Insp Repts 50-329/80-18 & 50-330/80-19 on 800501-31 No noncompliance noted Major areas inspected suspect pipe whip restraint bolting, const activities of Zack Co. detensioning of reactor vessel holdown bolts & audit of Peabody Testing CODM.R J . KNOP.R C Region 3. Chicago, Office of the Director EO. 46/24 7pp
- 8007230358 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J Q Region 3. Chicago. Office of the Director 80/06/27 is
- 8007170625 Forwards IE Insp Repts 50-329/80-15 & 50-330/80-16 on 800602-05 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/30 2pp
- --B007170635 IE Insp Repts 50-329/B0-15 & 50-330/B0-16 on B00602-05 No noncompliance noted Major areas inspected records & test results of steam generator anchor bolts & pipe restraint bolts VANDEL, T E , ERB. C M , NAIDU, K R Region 3. Chicago. Office of the Director B0/06/26 12pp
- 8007160612 Provides interim response to IE Bulletin 80-08 re examination of liner penetration welds Includes list of genetration info on joint type.flued head math.sleeve math & diameter, type of examination performed & repair info COOK, J W Consumers Power Co 80/07/11 11pp
- 8007310521 Ack receipt of 800630 ltr informing NRC of steps taken to correct const problems noted in IE Insp Repts 50-327/80-14 & 50-330/80-15 KEPPLER, J O Region 3, Chicago, Office of the Director 80/07/25
- --R007310329 Forwards response to NRC 800322 1tr re const problems noted in IE Insp Repts 50-329/H0-14 & 50-330/H0-15 Corrective actions Zack Co GA manual & GC control procedures were reviewed for adequacy & clarity COOK.J W Consumers Power Co 80/06/30 App
- R Periodic operating reports & related correspondence
- 8007280124 Forwards Bachtel nonconformance repts GA audit finding rept, mgt corrective action rept.B&W repts of nonconformity & util nonconformance repts, audit finding repts & corrective action repts for June 1980 GDOK, J W Gansumers Power Co. 80/07/21 360pp
- 8 Reportable occurrences. LERs & related correspondence
- B007160807 Part Zi rept re defective fostener matis A490 & A540 supplied by Bouthern Bolt & Fastener Corp for site assembly & installation of pipe whip restraints Possibly caused by improper heat treatment or wrong matis supplied HARBISON,D NPB Industries, Inc. 80/06/16 iipp
- 8007070197 Ack receipt of 800613 interim deficiency rept re component qualification test documentation re-review FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/23 ip
- 8007150032 Ack receipt of 800612 interim deficiency rept re broken reactor vessel enchor bolts Will review final rept upon raceipt Final Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/06/24 ip
- 8007170520 Ack receipt of 800619 interim deficiency rept re letdown cooler supports FIGRELLIP Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/01 ip
- 8007290205 Final deficiency rapt to amergency core cooling actuation sys digital Subsystem 2 logic circuitry drawings B&H will correct drawings by 800930 Facilities will be in conformance by 800930 COOK. J W Gonsymers Power Co 80/07/17 5pp

- DOCKET 50-331 DUANC ARROLD ENERGY CENTER

 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 8004,55 ltr to all power reactor licenseds, in response to 800529 ltr re emergency response facilities of reactor sites Sites w/approval to use closed-liceust television link w/tochnical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- 8007070207 Advises that review of safeguards contingency plan indicates need for add1 mode Encl NRC Lomments withhold (ref 10CFR2 790) IPPOLITO,T A Operating Reactors Branch 2 80/06/10 1p
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEMIUT, D.Q. Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners yroup in Botheeda. MD,re revisions to NRC acceptance criteria & autotanding issues relative to Mark I containment long-term program GRIMCS,C T Flant Systems Branch 80/02/21 'lipp
- 8007010453 Responds to NRC 800507 ltr re add1 TMI-2 requirements Intel assessment of collective impact not yet conducted Possible alternatives to requirements include equal or better sarvty mods & exception to unnecessary recommendations ROOT, L D I lowe Electric Light & Power Co 80/06/23 to
- 8007230733 Describes Cycle 5 restart testing program & results of all tests were satisfactory AddI testing proved that newly installed recirculation pump trip meets applicable criteria
 MINECK, D. L. Iowa Clectric Light & Power Co. 80706/23. App
- 8007070142 Application to reinstate Amend 60 to App A of License DPR-47 Amend will allow reactor stertup & operation for greater than 24-h w/one recurrulation loop out of svt Category II amend fee encl
 ROOT.L D Town Floctric Light & Power Co. RO/06/20 ip
- 8007180341 Confirms 800628 telcon authorization to amend Tuch Specs as requested in 800628 application License DPR-49 is amended effective 800628 by reinstating Amend 60 until 800702 NOVAKITM Assistant Director for Operating Reactors (80704/30 200
- BOO7070252 Forwards "Verification Test of Station Flectric Distribution Sys Voltage for Duane Arnold Energy Gtr." in final response to NRC 790808 ltr restation electric distribution bys ROOTAL D lows Electric Light & Power Co 80/07/01 ip
- --8007070254 "Verification Test of Station Electric Distribution Sys Voltages for Duane Arnold Energy Ctr " Oversize diawing encl # Bechtel Associatos Professional Curp 80/06/30 14pp
- --8007070255 "Single Line Diagram Station Connections "
 * lower Electric Light & Power Co 7884 75/04/19 to
- 8007140624 Forwards proposed mods to NRC /80807 request for info re design of voltage regulator says of motor galarator sets which supply power to reactor protection says implementation will depend upon furthor communication to agreement w/NRC RODT, LD Jown Electric Light & Power Co 80/07/01 App
- B007140434 Forwards "Alternate Shutdown Capability Analysis" (73 oversize drawings in response to NRC 791022 ltr Analysis conclusions identical to those transmitted in 600605 ltr is need for procedural & design muds R007,1, D Town Electric Light & Power Co 90/07/03 ip
- --8007140442 "Alternate Shutdown Capability Analysis "
 * lowa Electric Light & Power Co 80/06/30 55pp
- --8007140450 Package of 73 electrical drawings to be recalled at later date of microfilming
 * General Electric Co 77/06/22 ip

- '140366 Application to reinstate Amend 60 to App A (Tech Specs) to icense DPR-49 re reactor startup & operation for greater ian 24-h w/one recirculation lonp out of svc IDT.LD Ioww Electric Light & Power Co 80/07/07 ip
- 17055B Confirms 600707 telcon authorization of util 600707 iplication for change in Tech Space License DPR-49 is lended by reinstating Amend 60 until 800714 Documentation 11 be forwarded NAK.T M Assistant Director for Operating Reactors 80/07/08
- 210156 Requests payment of add1 fee in connection w/800628 iplication for reactor startup & operation greater than —h w/one recirculation losp out of svc GOS.R M License Fee Management Branch 80/07/09 lp
- 220394 Forwards "Reactor Containment Local Leakage Rate Testing,
- NECK.D L Iowa Electric Light & Power Co 80/07/15 ip
- 07220396 "Reactor Containment Local Leakage Rate Testing, 1980 FLOYD, S.O. Bechtel Corp. 80/04/22 21pp
- 230482 Forwards rept. "Reactor Containment Local Leakage Rate sting.1980 Outage " NECK.D L lowa Electric Light & Power Co 80/07/15 1p
- 07230484 "Reactor Containment Local Leakage Rate Testing, 1980 FLOVD, S.O. Bechtel Corp. MINECK.D.L. Consumers Power Co 80/07/11 21pp
- 310215 Forwards Amend 61 to License DPR-49, safety evaluation & tice of issuance & availability
 POLITO, T A Operating Reactors Branch 3 80/07/17 2pp
- 07310222 Amend 6) to License DPR-49, revising Tech Specs to allow interim operation w/one recirculation loop out of svc from 800620-0702

 JPPOLITIO, T A Operating Reactors Grench 3 80/07/17 7pp
- 07310226 Safety evaluation supporting Amend 61 to License DPR-47 Office of Nuclear Reactor Regulation, Director 80/07/17 5
- 07310229 Notice of issuance & availability of Amend 61 to License)PR-49 | IPPOLITO,T A | Operating Reactors Branch 3 | 80/07/17 | 2pp
- lowa Electric Light & Power Co BO/07/22 1p
- B0377 Forwards response to NRC 800405 ltr re effect of dc power poly failure on ECC9 performance Plant design assumptions OE analysis are conservative re facility JT.L D Iowa Clectric Light & Power Co 80/07/23 12pp
- aspection reports. IE Bulletins & correspondence
- 140535 Forwards IE Bulletin 80-13, "Cracking in Core Spray orgers " Written response required
 PLER.J G Region 3, Chicago, Office of the Director 80/05/12
- 100283 Forwards 15 Insp Rept 50-331/80-07 on 800324-26.0410-12 & -25 No noncompliance moted ISHPAN,RF Region 3. Chicago. Reactor Deerations Nuclear Support nch 80/05/20 2pp
- 7100291 IE Insp Rept 50-331/80-07 on 800324-26,0410-12 & 22-25 No /1002/1 12 Insp Rept 30-331/80-07 an S00324-8, 0410-12 & 26-25 No oncompliance noted Major areas inspected small break LOCA igh energy line break outside containment, procedures & mods follower of IE Bullstins 79-05, -06, -08 & -01D
 ITTLE.W B . CLARDY.L . CHRIBTSANSON,W Region S. Chicago, Office /05/15 10pp
 - Notice 80-22, "Breakdowns In Contemination en response required o. Office of the Director 80/05/28
 - , 80-23, "Loss of Suction to Emergency ponse required
 Office of the Director 80/05/29

- 8007220201 Forwards IE Info Natice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10
- 8007140319 Forwards IE Bulletin 80-14, "Degradation of 8MR Scram Discharge Vol Capability " Written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/06/12
- 8007020719 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" No hydramotor actuators as described by bulletin are installed at facility RDOTL D lows Electric Light & Power Co 80/06/13 ip
- 8007030027 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/18
- 8007230296 Forwards IE insp Rept 50-331/80-08 on 800520-22 No noncompliance noted
 HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support
 Branch 80/06/18 2pp
- --8007230303 IE Insp Rept 50-331/80-08 on 800520-22 No noncompliance DUTENUOUS IE INSPIRED SO-331780-OB ON BOOS20-22 No noncompli-noted Hajor areas inspected Tech Spec compliance.containment vent & purge line isolation valves & followup on outstanding inspitems LITTLE, HS, WRIGHT.9 C Region 3, Chicago, Office of the Director BO/06/13 3pp
- 8007020576 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response REPPLER, J G Region 3. Chicago. Office of the Director 80/06/20
- 8007170489 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater 89s & Resultant Internal Contamination of Personnel" No written response required MEPPLERIJ G Region 3, Chicago, Office of the Director, 80/06/24
- 8007070272 Responds to IE Bulletin 80-10, "Contamination of Nonradicactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Routine sampling/enallyis program has been implemented ROOT,L D Iowa Electric Light & Power Co 80/06/25 2pp
- 8007300132 Forwards IE Insp Rept 50-331/80-09 on 800616-17 No noncompliance noted
 FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/06/25 2pp
- --8007300136 IE Insp Rept 50-331/80-09 on 800616-17 No noncompliance noted Mejor areas inspected outstanding items & followup to IE Bulletin 79-02, LERs on pipe supports & concrete cracks in floor under torus
 GALLAGHER.E J Region 3, Chicago. Office of the Director
 HAYES, D H Region 3, Chicago. Reactor Construction & Engineering
 Support Branch 80/06/24 4pp
- 8007230329 Forwards IE Bulletin 80-i4, "Potential Misepplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-i4 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director. 60/06/27
- 8007160259 Responds to IE Bullstin 80-15, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power" All telephone equipment fed power from single 240-volt ac line ROOT, L I low Electric Light & Power Co 80/07/01 2pp
- 8007180497 Notifies that time clock on Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Screm at BHR," will start at 12 01 AM on 80070B Test should be completed within 20 days Requests notification of malfunction KEPPLER, J. G Region 3, Chicago, Office of the Director 80/07/07
- 8007250675 Forwards response to Items 1,2m & 3 of IE Bulletin 80-11 Bafety-related sys in proximity to maxonry block walls will be surveyed & identified only if analyses indicate potential wall failure List of subj walls encl ROOT, L, D I swa Electric Light & Fower Co 80/07/07 43pp.

- 8007230677 Forwards response to 1E Bulletin 80-09 re examination of containment liner penetration walds All walds, except for double & triple flued heads: examined by radiography or by combination of radiography & liquid penetrant examinations RDG7.L D lows Electric Light & Power Co 80/07/08 5pp
- 8007170363 Responds to IE Bulletin 80-17 No significant amount of water in scram discharge vol & associated piping. Vent valves operable & sys free of obstruction Results of addl required review will be reported in subsequent correspondence ROOT, L D lower Electric Light & Power Co 80/07/09 2pp
- 0007220494 Notifies that results of inservice insp performed during 1980 refueling outage & summary of pump & valve operability testing will be submitted by 800725 rather than 800715 as previously scheduled ROOT, L D Iowa Electric Light & Power Co 80/07/15 lp
- 8007220544 Responds to IE Bulletin 80-17, "Failurs of Control Rods to Fully Insert During Scram at BWR" Preliminary training of operators completed full training will be completed by 800803 Items 8,3 % & a will be discussed in subsequent ltr ROGT, L D I lows Electric Light & Power Co 80/07/17 App
- R Periodic operating reports & related correspondence
- 8007220367 Forwards monthly operating rept for June 1980 MINECK, D L Iowa Electric Light & Power Co 80/07/15 ip
- 8 Reportable occurrences, LERS & related correspondence
- 8007030212 Forwards LER 80-024/03L-0 MINECK, D. L. Iowa Electric Light & Power Co 80/06/26 ip
- --8007030217 LER 80-024/031-0 on 800603, during surveillance testing, bodyte-bonnet & packing leak discovered on pressure point isolation valve on reactor care isolation cooling turblne steam supply line. Caused by normal water Gasket replaced RAGER, M Iowa Electric Light & Power Co 80/06/24 ip
- 8007030224 Farwards LER 80-023/03L-0 MINECK.D L lows Electric Light & Power Co 80/06/26 ip
- --8007030235 LER 80-023/03L-0 on 800529, during surveillance testing, pressure differential switches controlling rooctor bidg to suppression chamber vacuum breakers tripped at out-of-spec values. Caused by instrument drift Buitches recallbr RAGER, M Iowa Electric Light & Power Co 60/05/26 1p
- 9007030238 Farwards LER 60-022/03L-0 MINECK, D. L. Towa Electric Light & Power Co 80/06/26 lp
- --B007030241 LER 80-022/03L-0 on 800528, during normal operation, control room alarm indicated high/low oil level in 18 recirculation pump motor Gaused by low oil level in lower motor bearing No leakage found 0il restarted to normal level RAOER, M I low a Electric Light & Power Co 80/06/26 ip
- 8007110411 Forwards LCR 80-026/03L-0. MINECK, D. L. IDWA Electric Light & Power Co 80/07/03 1p
- ---8007110419 LER 80-026/03L-0 on 800617.one undervoltage relay found to have time delay during surveillance test Caused by instrument drift Relay recalibr & functionally tasted RAGER.M lows Electric Light & Power Co 80/07/03 ip
- 8007110471 Forwards LER 80-025/03L-0 HINECK, D L lows Electric Light & Fower Co 80/07/03, ip.
- --8007110482 LER 80-025/03L-0 on 800404, during survaillance testing of mein steam line leak detection sys. found temp switch T18-4478 setpoint was 208 degrees, Caused by instrument drift Instrument recalibr RAGER, M. Iowa Electric Light & Power Co 80/07/03 ip
- 8007220599 Submits special rept re repairs on Fire Pump IP-49 which resulted in pump being out of svc longer than Tech Spsc limit. Repair work more extensive than anticipated when shaft & spiders found to be worn Pump repaired MINECK, D L Iowa Electric Light & Power Co 80/07/10 2pp.

- 8007220497 RO on 800612, during use of reactor core indiation cooling sys to control reactor pressure following shutdown, suppression chamber water level was inadvertently reduced to below Tech Specs Coused by failure of alarm MINECK,D L Towa Electric Light & Power Co 80/07/14 ip
- DOCKEY 50-332 DARNHELL REPROCESSING PLANT

 G. Inspection reports, JE Bulletins & correspondence
- 8007220020 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/86/10 in
- B007020739 Forwards IE Bulletin B0-19, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director B0/05/10
- B007170126 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Damineralized Water Bys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/08/24 lp.
- 8007310139 Responds to IF Bulletin 80-15 re emergency nutlification mys failure w/loss of offsite power Licensing proceedings terminated facility is presently utilized in DOI R&D activities Bulletin days not apply HOLDEN.R B Allied General Nuclear Services 80/0///55 lp
- DOCKET 90-33'3 JAMES A FITZPATRICK NUCLEAR PRHER PLANT F Becurity, medical, emergency & fire protection plans
- 8007070212 Forwards security contingency plan & addl info requested in NRC 800528 ltr Plan & addl info withheld (ref 100782 790) BAYNE.JP Power Authority of the State of Naw York 80/06/20 1p
- 9 Adjudicatory correspondence
- B007310243 Forwards Commission 800927 memorapidum & order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables EIBENHUT, D O Division of Licensing B0/06/25 19pp
- I. Financial information
- --8007280463 Annual Financial Ropt 1979 * Pawar Authority of the State of New York H0/07/24 41pp
- P Operating license stage documents & correspondence
- 8007230028 Bummary of 800207 meeting w/Hark I owners group in Sethesda. Mb.re revisions to NRC acceptance crituria & autstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 60/02/21 Jipp
- 8007080332 Forwards responses to NRC 800808 request for add1 info re Adequacy of electric distribution sys voltage BAYNE.J P Hower Authority of the State of New York 00/07/01 lipp
- BOOTEBORE? Forwards Amond 49 to Liverse DPR-59, safety evaluation a notice of issuance & availability IPPOLITO, TA Operating Reactors Branch & 40/47/LL 3pp
- ~~BOOTRBORAY Amend 49 to License DPR-D9, consisting of changes to Tach Brecs resentor operator responsibilities during refusing & replacement of fuel assemblies for refueling during Cycle 4 IPPOLITO:T A Operating Reactors Branch 2 BO/07/11 29pp

- 2007280251 Bafety evaluation supporting Amond 49 to License DPR-59 a Operating Reactors Branch 2 80/07/li 8pp
- 300/280277 Notice of issuance & availability of Amend 49 to License POLK.P J Operating Reactors Branch 2 80/07/11 2pp
- 07290692 Submits info re effect of dc nower supply failure on ECCS performance, in rusponso to NRC 800425 ltr (AYNE, J.P. Power Authority of the State of New York 80/07/25
- Inspection reports. IE Bulletins & correspondence

ı

- 171404:00 Forwards IE Bulletin BO-13, "Cracking in Core Spray Spargers " Written response required RIFR.U M Negion 1. Philadelphia, Office of the Director O/05/12 1p
- 7010302 Forwards IF Info Notice BO-23, "Loss of Suction to Emergency Pumps " No written response required Region 1. Philadelphia. Office of the Director O/05/29 ip
- 7010251 Forwards IF Inep Ropt 50-333/BO-OB on 800519-23 No oncompliance noted RUNNERL J Region 1. Philadelphia, Rooctor Operations Nuclear upport Branch BO/Os/O9 2pp
- 007210395 IE Insp Rept 70-333/80-08 on 800519-23 No nuncompliance noted Major areas inspected foul recurst handling & insp & fueling activities in control room & on fuel floor BAUNACK & TROMAGEN M. Region I. Philadelphia, Defice of the Director KISTER & Region J. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/64 Rep
- /310595 Forwards IE Info Notice 80°26, "Evaluation of Contractor A Programs " No written response required RIER.B H Region J. Philadelphia. Dffice of the Director 0/06/10 fp
- 7010164 Porwards "Response to IF Bulletin 79-018 Por JA Fitzpatrick uclear Power Plant " ASTERNAM.A J. Power Authority of the State of New York 80/06/11
- 10/010172 "Response to If Dulletin 79-018 for JA Fitzpatrick Nuclear Power Plant " Stone & Webster Engineering Corp 80/05/30 500pm
- 7180128 Forwards reply to IL Bulletin 79-01B re environ ualification of Class IE equipment W/o ancl ASTERNAK.R J. Power Authority of the Btate of New York 80/06/11
- 7140257 Forwards IE Bulletin ED-14, "Degradation of BWR Boram ischarge Vul Capability " Written reaponse required RIR.D H Region 1, Philadelphia, Office of the Director 3/06/12 1p
- 72800/1 Forwards II insp Rept 50-3.3/80-10 on 800514 No Incompliance noted WH.EDN.R T Region i. Philadelphia. Roactor Construction & Iginswring Support Branch 80/06/17 2pp
- 007280000 IL Insp Rept 80-333/60-10 on 600514 No noncompliance noted Hajor areas inspected RHR sys components addressed in facility response to IE Bulletin /9-018, FINKEL.A E Region 1. Philadelphia, Office of the Director. EBNCICK.& D Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/16 3pp
- 020717 Forwards If Bulletin 80-15, "Possible Loss of Emergency tification Bys (FNS) W/Loss of Offsite Power " Written appose required IER.B H Region 1, Philadelphia, Difice of the Director 1006/10 to
- 020521 Forwards 1E Circular 80-15. "Loss of Reactor Coolant Pump oling & Natural Circulation Couldown " No written response quired 11ER. B.H. Region 1. Philodelphia. Offico of the Director MO6/20 ip

- 8007160723 Forwards IE Circular 80-14, "Radioactive Contomination of Plant Demineralized Mater Sys & Resultant Internal Contomination of Personnel "No written response required GRIER.B H Region 1. Philadelphia. Office of the Director ROCAL (2011)
- 80072:02:8 Forwards IE Info Notice 80-24, "Low Level Radwasts Burial Criteria" No written response required GRIER, 8 H Region i. Philadelphia, Office of the Director 80/06/25 ip
- 8007250669 Responds to IE Bulletin 80-06. "Engineered Bafety Feature Reset Controls " Training sessions w/licensed operators held to assure awareness of potential problem re unwented closing of autometic depressurization sys valves PASTERNAK.R J Power Authority of the State of New York 80/07/01
- G007210526 Responds to IE Bulletin 60-08 re examination of containment liner penetration welds Liquid penetrant & weld joints magnetic particle examinations met applicable ASME code requirements

 PASTERNAKIR J Power Authority of the State of New York 60/07/03
- 8007250270 Submits reply to IE Bulletin 80-10 re contamination of nonradioactive sys Sampling & analyzing procedures implemented for sanitary waste sys PASTERNAK, R J Power Authority of the State of New York BO/07/07
- 8007240323 Confirms oral notification made on 800707 that 20-day peried for completing tests required by IE Bulletin 80-17, Item 2, began at 12 01 AM on 800708 Also requests immediate notification of any malfunction found during tests GRIER.8 H Region 1, Philadelphia, Office of the Director 80/07/09 2pp
- 8007310474 Forwards responses to IE Bulletin 80-ii Items 1,2a % 3 remasonry wall design Scheduled completion dates are tentative W/a encl
 PASTERNAK,R J Power Authority of the State of New York 90/07/10
- R Periodic operating reports & related correspondence
- B007090192 Forwards monthly operating rept for June 1980 PASTERNAK, R J Power Authority of the State of New York 80/07/03
- --8007090195 Monthly operating rept for June 1980

 * Power Authority of the State of New York 80/07/03 1400
- 9 Reportable occurrences, LERs & related correspondence
- 8007010486 Forwards LER 80-052/03L-0 PABTERNAK.R J Power Authority of the State of New York 80/06/25
- --B007010495 LER 80-052/03L-0 on 800528, during refueling operations, refuel bridge movement to over core area did not generate control rod withdrawal block per Tech Specs Caused by drift at bridge position sensing limit switch Buitch adjusted CHILDS, W V Power Authority of the State of New York 80/06/25
- BD07010511 Forwards LER B0-053/03L-0
 PASTERNAK:R J Power Authority of the State of New York 80/06/23
- --B007010519 LER B0-053/03L-0 on 800529, during normal refueling, review revealed that temporary changes to instrument maint procedure made on B00417 had not been reviewed by PORC Caused by administrative error PORC reviewed changes.

 CHILDS, W. V. Power Authority of the State of New York 80/06/25
- 8007010481 Forwards LER 80-054/04L-0 PASTERNAK, R J Power Authority of the State of New York 80/04/27
- -8007010485 LER 60-054/04L-0 on 800530.during normal shutdown.both recorders for gaseous release rate from reactor bldg ventilation sys & plant process computer were out of order during same 14-h period Caused by personnel error * Power Authority of the State of New York 80/06/27 2pp

- 2007/40368 Forwards LER 80-035/03L-0 PANTERNAK, R J Power Authority of the State of New York 80/07/07
- -- d007140374 LER 80-095/03L-0 on 800607, surveillance revealed intermediate range monitor. A indicating 120 when reading of 125 was required Caused by instrument drift Adjustment & callbr restured instrument to operable status CHILDS, N V Power Authority of the State of New York 80/ 80/07/07
- B007140383 Forwards updated LER 80-046/03X-1 PABIERNAK.R J Power Authority of the State of New York 80/07/07
- ~800/140374 Updated LER 80~046/03X-1 on 800430, surveillance testing revealed shutdown inaling permissive switches set in excess of 73 paig limit Gaused by pracedural error instruments recallfur traturned to sv.

 CHILDEN & V Pawer Authority of the State of New York 60/07/07
- 8007150707 Forwards LER 80-056/03L-0
 PARTERRANGR J Power Authority of the State of New York 80/07/10
- ~~800/150718 LEB 80 096/03L~0 on 800610.during normal shutdown & surveillance testing, emergency direct generator C tripped on high circulating current Caused by dirty or defective contact an voltage regulator droop switch CHILDS.W V Power Authority of the State of New York 80/07/10
- 8007280D15 Farwards LER 00-059/03L-0
 PABTERNAK, R J Power Authority of the State of New York 80/07/22
- --BOOTRBOOR4 LER GO.039/03L-0 on BOOTOS, during normal shutdown surveillance, level switches & pressure indicator showed 128 instruments but of callby or not properly operating Caused by instrument drift Instruments recaliby Two replaced CHILDS.H V Power Authority of the State of New York 80/07/22
- G007280610 Forwards LER B0-088/08L-0 FABTERNAK, R J Power Authority of the State of New York 80/07/22 1p
- ---BOO72880617 LFR 80-058/03L-0 on 800628, during normal chutdown operations, functional tests of average power range monitor instruments found not conducted gen Tech Bases Caused by Manual scheduling of computer outage CHILUB, N V Power Authority of the Blate of New York 80/07/22
- 600/200662 Forwards LER 00-057/03L-0 PADIERNAK,R J Power Authority of the State of New York B0/07/22.
- --BOO72HOA69 LER HO-057/O3L-O on BOO628, during normal shutdown, one call in wach 24 volt battery for dissel fire pump failed to meet min specific gravity requirements of surveillance test Caused by charger boing out of svc during surveillance CHILDB, U V Power Authority of the State of New York ED/07/22
- V Operator Examinations
- BOOTOBOSHS Notifies NRC of commitment to enrall employees who do not successfully complete any portion of reactor operator examin accelerated requalification program Dactines to commit employees to Item D 1 P of NRC 800328 request BO/07/01 BOYNE, J P fower Authority of the State of New York BO/07/01
- DOCKET SO-334 BEAVER VALLEY POWER STATION, UNIT 1 C Utility Environmental Report (ER), amends & correspondence
- 7404100136 Summary of sits visit on 790323 w/util re pipe stress analysis & Manger reevaluation afforts for Beaver Valley Power Station. Unit 1. HIPOINTUN. D. Operating Reacture Branch 1 (Pre 790625) 79/03/28

- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & 01 doc & containing decisions on UCS 780502 petition for reconsideration of \$\frac{1}{2}\$ stan 780413 memorandum & order UCS 771104 petition streight of \$\frac{1}{2}\$ to refer efter gratection for electrical cables \$60/05/25\$ (1700)
- P Operating license stage documents & correspondence
- 7904160256 Notification of 790325 mgt meeting wJutil to 目をもいる HD, STELLO-V Division of Operating Reactors 7970ほんご ほかり
- 8007230172 "Electrical Instrumentation & Control Funtures of Quench Spray Sys Hods ~ Beaver Valley Nuclear Station Unit () MAYS:S E 8040 Idaho, Inc. FIN A-6256 8007230172 (1074072) }
- 8007230099 Requests submittal of proposed Tech Spot change a providing for redundancy in decay heat removal capability in all modes of operation Model Tech Spots which would provide missing testing resolution encl for guidance EISENHUT, D.Q. Division of Licensing 90/06/51 45290
- B007180191 Recommends that analysis be made of impact of emi-average dynamic settlement on equipment & pipe consuctions within turbine bldg Info needed for review of util 79091022 "Boil Analysis of Turbine Bldg & Northern Yard Area" VARQAS.A Operating Reactors Branch 1 80/05/20 Opt erm 1 imaini
- B007010375 Forwards response to NUREG-0578 Procedures down input issued that utilize temp & pressure indication in rosate of room along wisteam tables to colculate subcooling in three one oversite dreamy available in Central Filos unit DUNN, C N Duquesne Light Co B0/06/26 64pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & Dicense conditions Filth Model Tech Spec & Model license conditions for TMT Al Lessons Learned Category A items ently for guidance EISENHUT, D & Division of Licensing 80/07/02 & Ppp
- BOO7080080 Forwards revision to proposed Tech Spot ther Lints (3/4 6 %) 3 & 2 1 & 4 & 2 1, for NPSH mods to low head safety trajer tion tracirculation appay pumps DUNN, C N Duquesne Light Co SD/07/03 Epp
- ---BOO70BOOSA Revision to proposed Teth Spec Sections 13/9 & 2.1.18 & 4 4 2 1.for NPSH mods to low head safety injection for recirculation spray pumps # Duquesme Light Co 80/07/03 3pp
- 8007080186 Forwards logic diagrams, elementary drawitijio & with their descriptions for bypass & resot of engineered and oty features, in response to NNC 800404 ftr Drawings awailely in Central Files only Item 20 and awailely by EQQH(is DUNN, C N Duquesne Light Co 80/07/03 34pp
- 800/7160450 Forwards util 800/707 ltr re NUREG-0577, "Potemittent for time Fracture Toughness & Lamellar Tearing on PWR Stoam Gopperator & Reactor Coolent Pump Supports," as replacement for unidated itr forwarded to NRC on 800/709 M/o enci
- 8007160555 Informs that date was inadvertiently omitted from \$1400/6/ | the extension of comment period for NUREG-0577 Requests that date be added or original be replaced whenci BUNNIC N Duquesne Light Co 80/07/09 ip
- --B007160564 Requests extension until B00915 for comments ton busico (14 responsible) for low fracture toughness & lamellat toar using on PMR steam generator & reactor coolant pump supports | BUNN, C N Duquesne Light Co B0/07/07 in
- 8007150480 Requests extension of comment period for NURECL-Chy / Position NRC 800519 its is much stronger than original document to Extension to 800715 should be cufficient to address tomics to DUNNIC N Duquesna Light Co 80/07/15 ip

- 90643 Decuments verbal responses to NRC questions re station svc undervoltage relays N.C N Duquesne Light Co 80/07/24 3pp
- apection reports, IE Bulletins & correspondence
- 10285 Forwards IE Waste Packaging Insp Appt 15000039/80-03 on 227-29 No noncompliance noted THLO H. Rogson i. Philadeiphia. Fuol Facility & Materials Safety nch 80/04/24 2pp
- 7010291 IE Waste Packaging Insp Ropt 15000039/80-03 on 800227-29 No oncompliance noted Major arras inspected shipping paper equirements. DBT placarding requirements. radiation levels, amovable contamination & external package features EERY. W. W. POTTER. J. P. Region 2. Atlanta, Fuel Facility & ateriols Safety Branch 80/03/18 7pp
- 20216 Forwards IE Insp Rept 50-934/80-10 on 800408-09 No compitance noted LEDN,R T Region i, Philadelphia, Reactor Construction & insering Support Branch 80/05/08 2pp
- 7020225 IE Insp Ropt 50-334/80-10 on 800408-09 No noncompliance oted Major areas inspected two allegations re electrical ubcontractor weld rod control & work practices URR.J P . REYNOLDS, S D Region 1. Philadelphia, Office of the irector TRIPP-L E Region 1. Philadelphia, Reactor Construction Engineering Support Branch 80/05/02 9pp.
- 20110 Porwards IE Info Notice BO-22. "Breakdowns In Contamination trol Programs " No writton response required EA:D N Region 1. Philadelphia. Office of the Director 05/20 tp
- 1032) Forwards IC Infa Notice 80-23, "Loss of Guction to Emergency dwater Pumps " No written response required ER.B H Region 1. Philadelphia. Office of the Director 03/29 19
- 10361 Forwards IE Info Notice 80-26, "Evaluation of Contractor Programs " No written response required ER.B.H. Region i. Philadelphia. Office of the Director 06/10 ip
- 60378 Forwards IE Info Notice 80-27, Degradation of Reactor with Pump Stude " No specific action or response wired ER.O H Region 1, Philadelphia, Office of the Director 06/11 ip
- 30660 Responds to IE Dulletin BO-05, "Vacuum Condition Resulting Damage to Chemical Vol Control Bys (CVCB) Holdup Tanks," saurifer relief tank,vol control tank & one primary in transfer tank designed for full vacuum conditions &C.N Duquesne Light Co BO/D&/16 2pp
- 20676 Forwards IE Bulletin 80-15, "Possible Loss of Emergency ification Sys (CNS) W/Loss of Offsite Power " Written ponse required ER.D H. Region 1, Philadelphia, Office of the Director 36/18 Ip
- 20498 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump ling & Natural Circulation Cooldown " No written response wired ER.O H Region 1, Philadelphia, Office of the Director 06/20 ip
- 60896 Forwards II Circular 80-14, "Radioactive Contamination of nt Demineralized Water Bys & Resultant Internal tamination of Personnel " No written response required ER.D.H Region 1, Philadelphia. Office of the Director 16724 Ip
- 1018: Forwards IE Info Notice 80-24, "Low Level Redwaste Burial teria." No written response required "R.B.H. Asgion 1, Philadelphia, Office of the Director 06/25 ip
- 30343 Refers to 800629 teleon re review & evaluation of constiction less in refusiing water storage tank & demineralized er storage tank Corrective actions should be taken to ure adequacy of const of containment liner & additanks. ER.B H Region 1. Philodelphia. Office of the Director 06/26 2pp

- 8007230113 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also ancl No written response required GRIER, D H Region I, Philodelphia, Office of the Director 80/06/27 2pp
- B007210011 Advises of review completion in response to IE Bulletin 80-10 re radioactive sys contamination & resulting uncontrolled release potential Documentation re Items 1 & 2 responsive actions available at station DUNN-C N Duquesne Light Co 80/07/01 ip
- 8007230140 Ack receipt of 800618 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/80-06
 BRUNNER, E J Region 1, Philadelphie, Reactor Operations Nuclear Support Branch 80/07/01 ip
- ~~B007230150 Responds to NRC 800521 ltr re violation noted in IE Insp Rept 50-334/80-06 Corrective actions maint work request initiated to repair identified fire doors Closure linkage adjusted & replaced w/heavy-duty mechanisms DUNN:C N Duquesne Light Co 80/06/18 3pp
- --8007230157 Forwards IE Insp Rept 50-334/80-1; on 800211-0307 & notice ef violation

 BRUNNER, E J Region i, Philadelphia, Reactor Operations Nuclear

 Bupport Branch 80/05/21 Zpp
- --8007230162 Notice of violation from imap on 800211-0307.
 * Region 1: Philadelphia: Office of the Director 80 80/05/16 1n
- --8007230174 IE Insp Rept 50-334/80-06 on 800211-0307 Noncompliance noted failurs to meintain fire protection barrier integrity.

 BECKMAN, D A . HEGNER, J. D Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/16 23pp
- 8007080276 Responds to NRC 800402 ltr re violations noted in IE Insp Rept 50-334/80-03 Corrective actions option of station superintendent to waive formal housekeeping tours will be deleted from housekeeping procedure DUNN.C N Duquesne Light Co 80/07/02 2pp
- 8007080424 Submits addl info re insp & maint of iA & iB inside recirculation spray pumps in response to NRC request Includes info re modal analysis of pump column mating faces of pump coupling & pump alignment S&B diagrams encl DUNN.C N Duquesne Light Co 80/07/03 iBpp
- 8007130643 Advises that documentation in response to IE Bulletin BO-10 re-contamination of nonradioactive sys, will be available at facility DUNN.C N Duquesne Light Co 80/07/07 ip
- 8007160575 Notifies that date was umitted on 1tr sent 800707 re completion of review of IE Bulletin 80-10 DUNN.C N Duquesne Light Co 80/07/09 1p
- 8007i40647 Requests that date 800707 be added to response to IE Sulletin 80-11: previously submitted w/o date Encl response includes date & may replace original DUNN: C N Duquesne Light Co 80/07/07 2pp
- --BOO7160654 Responds to IE Bulletin 80-11 re masonry wall design Replaces original response w/o encl DUNN.C N Dequesne Light Co 80/07/07 1p
- 80071504B3 Forwards "Final Rept IE Bulletin 79-02 Beaver Valley Power Station Unit 1 " Rept available in Central Files only DUNN:C N Duquesne Light Co 80/07/10 ip
- 8007180367 Forwards final rept in response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts" Rept summerizes analytical insp & testing programs & incorporates applicable info previously submitted DUNN.C N Duquesna Light Co 80/07/10 120pp
- 8007220588 Responds to IE Bulletin BO-08 Flued head design for panetration connections w/butt weld between genetration sleeve & process pipe were used Lists pipe penetrations utilizing flued but head weld const DUNN.C N Duquesne Light Co 80/07/15 3pp
- 8007170546 Forwards "Rept for 60-Day Response to IE Builetin 80-11. Masonry Walk Design." in response to bulletin Items 1.2a 3 Response available in Central Files only DUNN.C N Duquesne Light Co 80/07/17 ip

- BO07250294 Forwards reply to IE Bulletin BO-11 re masonry well design W/o encl
 DWNN.C N Duquesne Light Co BO/07/24 1p
- 8007290680 Updates 790918 ltr that responded to 188-79-18, "Temp Effects on Level Measurement" Revision of emergency procedures completed, steam generator low-low trip setpoint set at 12% t insulation applied to ref leg water columns DMW.C N Duquesne Light Ca 80/07/24 2pp
- R Periodic operating reports & related correspondence
- 8007020546 Forwards NPDES monthly rept for May 1980 MODRE, G W Duquesne Light Co 80/06/25 2pp
- --8007020547 NPDES monthly rept for May 1980 No flow from Discharge 102 during May 1980 MIGNE: 0 W Duquesne Light Co 80/06/25 12pp
- BOO7180418 Forwards monthly operating rapt for June 1980 DUNN.C N Duquesna Light Co 80/07/11 1p
- --B007180422 Monthly operating rept for June 1980 TIMKO D R Dequesne Light Co 80/07/11 App
- 8 Reportable occurrences, LERs & related correspondence
- 8007010376 Forwards LERs G0-039/03L-0 & 80-042/03L-0 WERLING, J A Duquesne Light Ca 60/06/24 2pp
- --B007010400 LER 80-042/03L-0 on B006i9.contractor notified util that river water lines grouted w/four inch space between adjacent bldg walls Lines could be severed during seismic event Orouting will be replaced w/sutable fire seal HERLING.J A Duquesne Light Co 80/06/24 ip
- --8007010456 LER 80-039/03L-0 on 8005R4; w/plant in Mode 5, power lost to vitel bus inverter 3, due to blown main power supply fuse fuse replaced & inverter returned to svc HERLING, J A Duquesne Light Co 80/06/24 ip
- BOO7140615 PNO-I-BO-016 on BO0625, watchman observed individual inside protected area Search was completed w/no suspect identified DEVELIN.J N , MARTIN.W O , BRUNNER Region 1, Philadelphia, Office of the Director BO/06/25 1p
- B007010526 Forwards LER 80-041/03L-0 WCRLING, J. A. Duquesne Light Co. 80/06/26 2pp
- ---B007010536 LER B0-041/03L-0.on B00502 during test supplementary leak collection & exhaust fan tripped Apparently caused by loose lead Motor lead reconditioned MERLING.J A Duquesne Light Co 80/06/26 ip
- 8007070295 RO 80-044/01T design for steam generator enubber embedment found not to reflect as-constructed condition, resulting in nonconservative loads for anchors Caused by assumption that load was applied to normal surface HERLING. J A Duquesne Light Co 80/06/30 2pp
- 8007090334 Forwards LER 80-043/03L-0 Lmm.ING. J A Duquesne Light Co 80/07/02 2pp
- --BO0709033B LER 80-043/03L-0 on 800605, one source range channel was last Caused by high voltage power supply failure New power supply installed & tested successfully LACEY, W B Duquesne Light Co 80/07/02 1p
- 8007090340 Forwards LER 80-037/017-0 WERLING. J. A Duquesne Light Co 80/07/02 2pp
- --B007090348 LER 80-037/017-0 on 800620, one of original radiographs made by vendur of reactor containment seal welds found code rejertable Cause unknown Four radiographs w/ questionable indications under syaluation LACEY, W B Duquesne Light Co 80/07/02 ip
- 8007180317 Forwards LER 80-044/017-0 PERLING J A Duquesne Light Co 80/07/11 2pp
- ---8007180322 LER 60-044/017-0 on 800650 review showed existing steam generator snubber embedment design does not reflect asconstructed embedment condition Cause not yet determined LACEY. W. J. Duquesne Light Co. 80/07/11

- 8007220506 Forwards "Investigation of Graver Records of Field Erected Tanks (BVC-198) & Reactor Containment Liner (BVC-65), " as following to LERs 80-025 & 80-037 Rept available in Central Files only DUNN, C N Duquesne Light Co 80/07/14 2pp
- 8007220430 Forwards L.R 80-033/03L~0 WERLING, J.A. Duquesne Light Co. 80/07/15 2pp
- --8007220434 LER 80-033/03L-0 on 800417, diesei generator i governor control motor failed Caused by tytling of governor while attempting to shut down diesei w/fast start signal still applied Motor replaced LACEY.W S Duquesne Light Co 80/07/15 ip
- 8007250315 Forwards LERs 80-049/01T-0 & 80-050/01T-0 WERLING, J. A. Duquesne Light Co. 80/07/21 2pp
- --B007250324 LER B0-049/01T-0 on 800718 during investigation per IE Bulletin 79-14 determined that support on component cooling water supply line to IA residual heat removal heat exchanger has high probability of failure during saismit event LACEY.H S Duquesne Light Co 80/07/21 ip
- ~~8007250331 LER 80-050/01T-0 on 800718, during investigation per IE Bulletin 79-14, found undersized snubber was installed on recirculation spray line from IA exchanger to 180 degree spray header Snubber to be replaced LACEY, W 5 Duquesne Light Co 80/07/21 ip
- 8007300383 Forwards LER 80~051/017-0 WERLING J A Duquesne Light Co 80/07/24 2pp
- --8007300386 LER 80-051/01T-0 on 800724, per 1E Bulletin 79-14 review, found significant overstress condition would exist during soismic event on B low head safety injection pump recirculation line Cause unknown LACEY, W S Duquesne Light Co B0/07/24 1p
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B007010379 Forwards BNL fire protection review re upgrading existing fire pumps, cable spreading room, fire barrier, smake detectors, reactor collant pump oil collection sys & automatic sprintier sys for facility HALL, R E Grookhaven National Laboratory 80/06/24 App
- B007280647 Advisus that evacuation time estimates were submitted in 800717 ltr per 800702 request UMRIG.R E Florida Power & Light Co 80/07/22 1p
- G007290624 Forwards proposed revision to emergency plan Apps will be forwarded under separate cover Complete implementation will depend on availability of essential resources Enc. (140 pages) available in Central Files only

 UNRIG.R E Florida Power & Light Co 80/07/23 ip
- G Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reronsideration of 780413 memorandum & order UCS 771104 petition sought action refire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp
- H General correspondence
- B007110306 Responds to B00512 ltr re enci L Starr itr concerning plant problems Nuclear plant safety design approach involves use of multiple physical borriers to provent release of radioactivity to environ DIRCKS.W J Office of the Executive Director for Operations 80/06/30 Spp
- --8007110314 Requests response to L Starr its concerning plant problems CHILES, L J Sonate 80/05/12 ip
- 8007240444 Responds to A00521 ltr re 5 Corbin inquiry about plant safety aspects Safety design approach involves use of multiple physical barriers to prevent release of radioactivity to environ DIRCKS, W. J. Office of the Exercitive Director for Operations 80/07/15 3pp

- --8007240468 Requests response to encl 8 Corbin inquiry about pient safety aspects
 SIONE, R Senate 80/05/2i 2pp
- M Antitrust correspondence
- 8007130719 Response stating no objection to Orlando Utils Commission 800420 withdrawal of intervention FL Cities 800707 comments re equal treatment will be addressed in Unit 2 antitrust proceeding Certificate Svc encl DEWEY.L G Antitrust Division 80/07/11 4pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Bpec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D © Division of Licensing 80/06/11 62pp
- BOO/10013P Forwards Amend 35 to License DPR-67, safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 BO/06/13 2pp
- --BO07100136 Amend 33 to License DPR-67, allowing Unit 1 to proceed from Made 4 to Mnde 3 to allow steam turbine driven auxiliary feedwater gump surveillance to be postponed CLARK, R A Operating Reactors Branch 3 80/06/13 Spp
- --B00/100138 Rafety evalvation supporting Amend 35 to License DPR-67
 * Dffice of Nuclear Reactor Regulation, Director 80/06/13 2p
- ---BOO7100141 Notice of issuance & availability of Amend 35 to License DPR-67 CLARK R A Operating Reactors Branch 3 80/06/13 2pp
- 8007100i61 Summary of B00620 meeting w/util & C-E in Bethesda,MD re 800611 reactor trip & cooldown on natural circulation NEL90N,C C Operating Reactors Branch 3 80/06/25 2ipp
- 0007030221 Requests NRC approval of encl plans to implement 910101 requirements of Leusons Learned Task Force Item 2 | 0 b Licensee will install four SPING-4 samplers by 810101 to monitor normal & high range noble gas at vent stack UNRIO.R E Fimida Power & Light Co 80/06/27 3pp
- GOO/110199 Advises NRC that NUREC-0978 requirement to measure chlorides & dissolved gases in RCB following accident is excessive & involves unnecessary personnel exposure to radiation Requests that NRC reconsider position

 WIRIO.8 F Florido Power & Light Co BO/06/27 1p
- 8007250001 Hequests submittal of application for amend to license consisting of Tuch Spec changes & license conditions PWR Model Tech Specs & Model Ticense conditions for TMI-2 Lessons Learned Category A items ently for guidance EISERMUT, D.Q. Division of Licensing 80/07/02, 69pp
- 8007090286 Forwards explanation of selection of undervoltage relay & setpoint, in response to NRC 800529 request for add1 info re grid valtage Discussion of consequences of spurious actuation of relays also Encl.
 UNRIG.R E Florids Power & Light Co. 80/07/03 3pp
- 8007240280 Requests that response to Item 1 of encl request for add1 info re probable steam bubble created in reactor vessel on E00611 be submitted within 10 days of receipt of Itr Response to Items 2-5 should be submitted within 50 days MOVAK. The Assistant Director for Operating Reactors 80/07/08 488
- 0007240338 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR NDVAX, T.M. Assistant Director for Operating Reactors 80/07/08 2no
- BOO7220374 Advises that Henry Pratt Co torque & stress analyses re containment purge have been delayed Upon completion & receipt of analyses.util will review & prepare response demonstrating valve ability to ciose during DBA-LOCA UMRIG.R E Florida Power & Light Co 80/07/15 tp

- G Inspection reports. IE Bulletins & correspondence
- 8007240206 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Bosse Unit i While in Refueling Mode" No response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp
- BD07020231 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Centrol Programs " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 60/05/28
- 8007210458 Forwards IE Circular 80-13. "Grid Strap Damage in Wastinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28
- 8007010206 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 90/05/29 is
- B007100059 Forwards IE Insp Rept 50-335/B0-12 on 600429-0502 No noncompliance noted LENIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/05/29 2pp
- --B00710006i IE Insp Rept 50 335/B0-12 on 800427-0502 No noncompliance noted Major areas inspeceted pipe support & restraint sys including surveillance & test results UPRIONTC M Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch JOHNSON, A H Region 2, Atlanta, Office of the Director 80/05/27 4pp
- 8007020321 "Environ Gualification of Electrical Equipment in Harsh Environ Which is Required for Accident Mitigation/ Monitoring" * Florida Fower & Light Co 80/06/01 20pp
- --B007020326 "Baint Lucie Unit i NRC IE Bulletin 79-01B, Phase i," master list & component evaluation sheets # Ebasco Services, Inc (subs of Enserch Corp) B0/06/01
- B007220062 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/10
 Zpp
- 8007140265 Forwards IE Info Notice 80-27, Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- 8007020752 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (CNS) W/Loss of Offsite Power " Written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/18 ip
- B007110102 Forwards 1E Insp Rept 50-335/80-14 on B00403-05 No noncompliance noted KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/04/17 ip
- ---B007110113 IE Insp Rept 50-335/80-16 on 800603-05 No noncompliance noted Major areas inspected security & health physics control Details withheld (ref 10CFR2 790)
 TOBIN.W J. TILLMAN.A Region 2. Atlanta. Office of the Director. GILLESPIE.F P Region 2. Atlanta. Safeguerds Branch 80/06/18 in
- 8007290369 Forwards IE Investigation Rept 50-335/80-15 on 800410-0514 No noncompliance noted LONG.F J. Region 2. Atlanta. Office of the Director 80/06/19 200
- --B007270380 IE Investigation Rept 50-335/80-15 on 800410-0514. No noncompliance noted Major areas investigated allegations re ASME code requirements for valves & installation of containment penetrations
 LDNG: J. HARBH: R J. Region 2, Atlanta, Office of the Director.
 HERDT: A R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch.

1

- 8007020454 Forwards IE Circular 80"15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required U'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/20
- 6007100021 Responds to iE Bulletin 80-06. "Engineered Safety Feature Recet Controls " Sys identified as returning to normal position after resot Safety injection tank isolation & check valve leak-off valves returned to normal position UHRIO,R E Florida Power & Light Co 80/06/20 3pp
- 8007070097 Ack receipt of 800511 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-10 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/24 ip
- --8007070100 Responds to NRC 800512 ltr re violations noted in IE Insp Rept 50-335/80-10 Corrective actions examiner passed eye exam & schedule for recertification of vision tests extablished UHRIG:R E Florida Power & Light Co 80/06/11 2pp
- --8007070102 Forwards 1E Insp Rept 50-335/80-10 on 800408-11 & notice of violation HMPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/05/12 2pp
- ~~8007070103 Notice of violation from ansp on 800408-11 * Region 2, Atlanta, Office of the Director 80/04/30 lp
- --8007070107 IE Insp Rept 50-335/80-10 on B00408-11 Noncompliance noted examiner failed to meet eye exam requirements.
 HERDT.A Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch CROWELY.B R Region 2. Atlanta, Office of the Director 80/04/30 Bpp
- B007170109 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 is
- B007220059 Ack receipt of 800612 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-07 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/06/27 ip
- --8007220069 Responds to NRC 800518 ltr re violations noted in IE Imap Rept 50-335/80-07 Corrective actions procedures will be changed to require signatures for disconnected lead & temporary jumper log reviews UHR10,R E Florida Power & Light Co 80/06/12 3pp
- ---B007220075 Forwards IE Insp Rept 50-335/80-07 on B00415-18 & notice of violation LEHIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/05/16 2pp
- --8007220079 Notice of violation from insp on 800415-18
 Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/15 1p
- --8007220088 IE Inep Rept 50-335/80-07 on 800415-18 Noncompliance noted disconnected lead & temporary jumper log not reviewed by operations superintendent prior to refueling & response to joint util mgt audit not received within 30 days UPRICHT,C M. RUHLMAN, H. A. BELISLE, G. A. Region 2, Atlanta, Office of the Director 80/05/15 19pp
- 8007230243 Forwards IE Bulletin 80-16, "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-16 also enci No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- B007160777 Ack receipt of B006/2 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/80-14
 LEWIB,R C Region 2. Atlanta. Reactor Operations Nuclear Support
 Branch 80/06/30 ip
- --8007160810 Responde to NRC 800316 ltr re violation noted in IE Insp. Rept 50-335/80-14 Corrective actions LER being prepared to report results of integrated test of engineered safety features
 URICR E Florida Power & Light Co. 80/06/12 2pp

- --8007160817 Forwards IE Insp Rept 50-335/80-14 on 800430-0502 & notice of violation
 LEWIS,R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/05/16 2pp
- --8007160826 Notice of violation from insp on 800430-0502 * Region 2. Atlanta. Office of the Director 80/05/16 ip
- --8007160830 IE Insp Rept 50-335/80-14 on 800430-0502 Noncompliance noted failure to rept emergency diesel generator load sequence timers that did not meet Tech Speck during routine surveillance testing MESSITI.B R Region 2. Atlanta. Office of the Director UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/16 5pp
- 8007250312 Forwards response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Containment boundary butt welds identified Fiold welds were made during const Shop welds were made by penetration assembly Fabricator UHRIG.R E Florida Power & Light Co 80/07/08 12pp
- 8007250272 Responds to 1E Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential For Unmonitored, Uncontrolled Release of Radioactivity to Environ " No addi routine sampling or monitoring program, are required UHR10.R E Florida Power & Light Co 80/07/09 1p
- 8007220379 Responds to 1E Builetin 80-11. "Masonry Wall Design " Info is incomplete due to identification work still in progress Safety-related walls have been identified & evaluation program developed Rept with be provided by 800723 UMRIGIR E Fiorida Power & Light Co 80/07/16 lp
- A Periodic operating reports & related correspondence
- 8007080330 Forwards "Semiannual Radioactive Efficient Roleage Rept for Jul-Dac 1978 " UHRIG.R E Ftorida Power & Light Co. 79/03/01 1p
- --8007080335 "Semiannual Radioactive Effluent Release Rept for Jul-Dec 1978 "
 * Florida Power & Light Co 79/03/01 27PP
- 5 Reportable occurrences, LERs & related correspondence
- B0070104B3 Forwards LER 80-022/03L-0 SCHMIDT.A D Florida Power & Light Co B0/06/19 ip
- --B007010491 LER B0-0,22/03L-0 on B00520, digital data processing sysmalfunctioned during power operation Caused by computer programing error Sys ropaired & returned to svc Program will be revised to corroct software problem SCHOPPMAN,M A Florida Power & Light Co B0/04/20 tp
- 8007080284 Forwards LER 80-029/017-0 SCHMIDT, A D Florida Pawer & Light Co 80/06/25 ip
- ---B0070B0290 LER B0-029/01T-0 on B00611.at 100% power, ground occurred in circuit of valve HVC-14-6 causing valve to fail classed Caused by steam condensing on valve colenaid w/moisture invading terminal box Solenaid & terminal board replaced SCHOPPMAN.M A Florida Power & Light Co 60/06/25 2pp
- 8007140382 Forwards LER 80-026/03L-0 ECHMIDT, A D Florida Power & Light Co 80/06/29 1p
- --8007140389 LER BO-026/O3L-O on B00930, during normal power operations, noted that 31-day fire station insp required by Tech Spec had been exceeded Caused by personnel anadvertently overloaking insp
 BCHDPPMAN,M A Florida Powet & Light Co B0/06/29 ip
- 8007140364 Ferwards LER 80-028/03L-0 SCHMIDT, A D Florida Power & Light Co 80/06/30 lp
- ---B007140372 LER B0-02B/O3t-0 on 800531.during normal operations, channel A of 1A steam generator low pressure trip failed Caused by failure of power supply associated w/channel A Vendor contacted % now power supply installed & tested SCHOPPMAN.M A Florida Power & Light Co B0/06/30 1p
- 8007150627 Forwards LER 80-030/07L-0 SCHMIDT, A D Florida Power & Light Co 80/07/03 ip

- -8007130636 LER 80-030/03L-0 on 800603 during full power operation, CRT rad position display (metrascope) was briefly de-energized to permit replacement of failing power supply Control element assembly black circuit also disabled 9CHDPPMAN. M A Florida Power & Light Co 80/07/03 ip
- -8007150536 LER 80-025/09X-1 on 800512, during planned secondary plant shutdown for turbine maint, main steam header would not depressurize following steam stop closure Cause unknown Valve stems were replaced & verifiled operable BCHOPPMAN, N A Florida Power & Light Co 80/07/07 2pp
- OCKET 50-0:16 MILLBTONE NUCLEAR POWER STATION, UNIT 2

 Security, medical, emergency & fire protection plans
- DO71B0196 Forwards NRC 800425 ltr to all power reactor licenses, in response to 800529 ltr re emergency response facilities of reactor sites Bites w/approval to use closed-circuit televisien link w/technical support ctr listed CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/07 2pp
- CO7010337 Comments on proposed rule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Suggested revisions to App R w/justifications encl COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G Connecticut Yanker Atomic Pewer Co COUNSIL.W G Northeast Utilities 80/06/16 3ipp
- 007030336 Cemments on proposed rule iOCFR50 requirements for exceed those necessary to resolve generic issues & are excessively specific & restrictive Forwards alternative App R fire protection program COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Nuclear Energy Co (subs of Nertheast Utilities) 80/06/16 16pp
- 007090231 Forwards responses to NUREG-0654 criteria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withheld (ref 10CFR2 770)
 CGUNSIL.W O Connecticut Yankee Atomic Power Co CDUNSIL.W, 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/30 2pp
- JO7170425 Confirms position discussed in 800624 telcon re safeguards centingency plans NRC requested revisions are ill-advised & unnecessary Specifics of plan implementation can be detailed in procedures
 GDUNSIL.H G Connecticut Yankee Atomic Pewer Co COUNSIL.H G
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/07/01 20p

Adjudicatory correspondence

207310243 Forwards Commission 200527 memorandum & order containing decisions on UCB 780302 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables E18ENHUT, D G Division of Licensing 80/06/25 89pp

Financial information

NOTIBOAR2 Forwards 1980 cash flow estimates for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co Cash flows are adequate to meet potential premium requirements for 1975 amends to Price-Anderson Act

Operating license stage documents & correspondence

- 107230079 Requests submittal of proposed Tech Spec changes providing for redundancy in deray heat removal capability in all modes of operation Model Tech Spers which would provide acceptable resolution encl for guidance EIEENHUI.D G Davision of Licensing 80/06/11 62pp
- O7140027 Summary of 800604 mepting w/vtil in Bethesda: MD re Cycle 4 reload at facility w/Westinghouse fuel List of attendees & agenda and CQNNERB.E L Operating Reactuse Branch 3 80/06/16 3pp

- B007030362 Requests response to encl questions re fuel design & physics calculations to complete review of basic safety rept supporting Cycle 4 reload Requests that addl info be provided by B0640 to meet review schedule CLARK.R A Operating Reactors Branch 3 B0/06/20 5pp
- 8007020569 Clarifies 800506 response to NRC 791030 request for info concerning Lessens Learned Task Force Item 2 1 B a, improved post-accident sampling capability Info ensures accurate NRC understanding of design philosophy & intent COUNSILN O Connecticut Yankse Atomic Power Co COUNBILN O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23 3pp
- B007110541 Forwards request for add1 info re adequacy of station electric distribution sys voltages.per review of 791115 submittal Response requested within 60 days NDVAR.T M Assistant Director for Licensing B0/06/25 5pp
- 8007080164 Application to amend License DPR-65, consisting of proposed revisions to Tech Specs re containment electrical penetrations Procedure for fuel handling accident inside containment encl
 COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/26 App
- ~~8007080169 Preposed revisions to Tech Specs 3 9 4 & 4 9 4 re containment electrical penetrations * Northeast Nuclear Energy Co (subs of Northsast Utilities) 80/06/06 2pp
- --B0070B0176 Procedure for Puel handling accident inside containment * Northeast Nuclear Energy Co (subs of Northeast Utilities) 77/06/08 4pp
- B007020557 Ferwords "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 780125 ltr to PWR licensees re asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withheld (ref i0CFR2 770) LUNDVALL, A E C-E Operating Plants Owners Group 80/06/30 2pp
- --B007020574 "RC9 Asymmetric Loads Evaluation Program," final rept. Vol I 4 C-E Power Bystams B0/06/30 20pp
- --8007020581 "RCS Asymmetric Loads Evaluation Program," final rept,
- Vol 2 * C-E Pawer Systems 80/06/30 300pp
- --8007020988 "RC8 Asymmetric Loads Evaluation Program," final rept.Vol 3
 * C-E Power Bustems 80/06/30 300pp
- --B007020593 "RCS Asymmetric Loads Evaluation Program," final rept,App A, numerical results, evaluation of C-E fuel Non proprietary version App B.Palisades fuel analysis, encl # C-E Power Systems 80/06/30 Zépp
- --8007020600 "RCS Asymmetric Loads Evaluation Program: App E.ECCB analysis approach w/reduced area coolant channels in peripheral assemblies.Final rept * C-E Power Systems 80/06/20 9pp
- 800728000i Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for THI-2 Lessons Learned Category A items encl for guidance EISENHUT.D O Division of Licensing 80/07/02 69pp
- 800710020D Forwards response to NRC 8000507 requests for addl info re proposed revisions to ETS State of CT Dept Environ Protoction 800611 ltr approving Thermal Plume Study Rept enc1 CGUNSIL, W O Northeast Utilities 80/07/03 27pp
- 8007140344 Forwards addl info re fuel design & physics calculations per RA Clark 800620 request Response to Guestion 10 withheld (ref 100FRZ 790)

 CDUNGIL, M G Northeast Utilities, 80/07/07 14pp
- B007240350 Advises of NRC reorganization on 800428 which resulted in number of changes in off titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08

- 8007210238 Application for amend to License DPR-45, revising Tech Spec door numbers in Table 3 9-1 & position of certain doors in auxiliary bldg during fuel movement in spent fuel area or crane operation over spent fuel pool CKKNSIL, W 0 . FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/10 3pp
- BOO7220457 Application for amend to Licenses DPR-21 & DPR-65 to incorporate changes to Tech Specs re organizational title Class I fee encl CDRNSIL.W.O. FEE.W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/14 3pp
- BO07250300 Application to amend Licenses DPR-21 & DPR-65, clarifying Tech Specs to reflect recent organizational title changes License fee transmitted 8007:4 Affidavit encl COUNBILH 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/15, 2pp
- ---8007250303 Proposed revisions to ETB.Pages 5 1-2 & 5 1-5.reflecting recent organizational title changes 6 Northeast Nurlear Energy Co (subs of Northeast Utilities) 80/07/15 3pp
- 9007280673 Requests extension of comment period re NUREG-0377, "Potential for Low Fracture Toughness & Lamallar Tearing on PMR Bleam Generator & Reactor Coolent Pump Supports." until 800915, COUNSIL, H O Northeast Utilities 80/07/21 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007020146 Forwards IE Info Notice 80-22, "Breakdouns In Contamination Control Programs " No written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/05/28 ip
- B007010312 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps," No written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/05/29, ip
- B007020039 Advises that full response to IE Bulletin 80-12. "Decay Heat Removal Bys Operability." will be submitted by 800701 Delay necessitated by current heavy demand on operations gersonnel COWNBILLY 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/04 2pp
- 8007210580 Forwards 1E Info Notice 80-26, "Evaluation of Contractor A Programs " No written response required ORIEN, B H Region 1, Philadelphia, Office of the Director 80/06/10 1p
- 8007160357 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required ORIER, B. H. Region 1. Philadelphia, Office of the Director 80/06/11. | 19.
- 6007170320 Responds to IE Bullstin BO-O6, "Engineered Safety Feature (ESF) Reset Controls "Three facilities will have completed mods per IE Bullstin 80-O6 by 810101 List of equipment & status of criteria ancl.

 COUNSIL, W. G. Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Utilities 80/06/13 43pp
- 8007020700 Forwards IE Bulletin 80-18, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Offsite Power " Written response required ORIER, B H Region 1. Philadelphia. Office of the Director 60/06/18, ip
- BOO7180197 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Due to absence of abnormal conditions, no further action planned CDUMSIL, N. O. Northeast Utilities 80/06/19 lipp

- 8007310361 Forwards 1E Insp Repts 50-245/80-07 & 50-336/80-05 on 800801-31 No noncompliance noted BRUNNER, E J. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --B007310365 1E Insp Repts 50-245/80-07 & 50-336/80-05 on B00501-31 No noncompliance noted Major areas inspected control rooms & accessible portions of Unit i reactor, turbine, radwaste, qas turbine generator & intake bldgs
 SHEDLOSKY, J T, ZIMMERMAN, R P. Region I, Philadelphia, Office of the Director KEIMIG, R R. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/18 7pp
- 8007020494 Forwards 1E Circular 80-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/20 ip
- 8007160714 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region i, Philadelphia, Office of the Director BO/06/24 ip
- 8007210207 Forwards IE Info Notice 80-24, "Low Level Radwaste Durial Criteria " No written response required ORIER.D H Region i, Philadelphia, Office of the Director 80/06/23 ip
- 8007230146 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- R Pariodic operating reports & related correspondence
- 8007210374 Forwards monthly operating rept for June 1980 MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/11 1p
- --8007210375 Monthly operating rept for June 1980 HOWLETT.G H Northeast Nuclear Energy Co (subs of Northeast Utilities) E0/07/02 Spp
- 8 Reportable occurrences. LFRs & related correspondence
- 8009230131 PNG-I-80-071 on 800905, significant number of security force personnel, contracted from Interstate Security Svcs. Inc. began taking leave at start of mid-shift Security supervisors working 12-b shifts will maintain full coverage ZIHMERMAN, R P. KEIHIG.R R., DEVLIN, J.W. Region 1, Philadelphia, Office of the Director 80/09/05 ip
- 8007010445 Forwards updated LER 80-011/03L-P MRDC2KALE J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/24 lp
- --8007010450 Updated LER 80:011/03L-2 on 800313, following two plant trips & shutdown, daddle clamp boits for two hangars were found broken Both hangers are hydraulic snubbors Fallores caused by combination of fatigue & high impact loading CLEMENT, C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/06/24. 2pp
- B00707031B Forwards revised LER 80-01B/01X-1 MRQC7KA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/27 ip
- ---8007070324 Revised LER 80-018/01X-1 on 800508, during ongoing hanger base-plate analysis both svc water headers declared inoperable Coused by supports not providing factor of safety greater than two Redesign & mods completed 800621 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/27 2pp
- B007070361 Forwards LER 80-022/03L-0 MR0CZKA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/27 ip
- ---B007070372 LER 80-022/03L-U on B00529; during engineered safeguards actuation sys test; iA actuating module placed in tripped condition Fans did not shift to low speed Cause suspected to be sticking of module output relay K515A CLEMENT. C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/27 lp

- B007140556 PND-1-80-076 on 800701.72 new fuel bundles discovered fabricated w/design error in one dimension Cause Unstated New Fuel bundles being prepared for shipment back to Hestinghouse for mod Press release will be issued a Office of Inspection & Enforcement, Office of the Director 80/07/02 ip
- BOO7250409 Forwards LER 80-023/03L-0 MRDCZKA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/18 ip
- --B007250410 LER 80-D23/03L-0 on B00425, core barrel munitor declared inoperative when computer would not respond to input cummends Caused by natural end of life of two circuit boards Circuit boards replaced CRISCIONE, J L Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/10 lp
- DUCKET 50-338 NORTH ANNA POWER STATION, UNIT 1 E. NRC Bafety Evaluation Report (SER), suppls & correspondence
- B007300297 Forwards discussion of util B00711 & 10 responses to deficiencies listed in SER Full-power operation should be authorized upon obtaining FEMA approvable of state & local emergency plans
 ORIMES, B.K. Emergency Preparedness Task Force 80/07/22 5pp
- F Security, medical, emergency & fire protection plans
- 8007240005 Forwards amended physical security plan Plan withheld (ref 10CFR2 790) SYLVIA,B R Virginla Electric & Power Co 80/06/03 1p
- B007170601 Forwards revised nuclear security personnel training qualification program & response to NRC B00519 ltr Program & response withheld (raf iOCFR2 790)
 BYLVIA, B R Virginia Electric & Power Co 80/07/14 ip
- B00724009P Forwards security info re 800509 ltr Info withheld (ref 10CFR2 790) BYLVIA, B R Virginia Electric & Power Co 80/07/18 1p
- 8007220579 Forwards amergency plan Revision 4 in response to request made during 800715 meeting w/FEMA & State of VA.to support full power license request NAUM.E A Virginia Electric & Power Co 80/07/22 22pp
- --B007220582 Facility emergency plan Revision 4

 * Virginia Electric & Power Co B0/07/15 13pp
- BOO7280136 Forwards emergency preparedness requirements for full power license per review of BOO419.0606.20 & 25 submittals Requests schedule for meeting requirements TEDESCO.R.L. Assistant Director for Licensing BO/07/22 App
- 800/280432 Forwards revised emergency plan implementing procedures Procedures available in Central Files only BAUM.E A. Virginia Electric & Power Co. BO/07/22 1p
- 8007300297 Forwards discussion of util 800711 & 18 responses to deficiencies listed in 9ER Full-power operation should be authorized upon obtaining FFMA approvable of state & local emergency plans
 QRIMES.B K Emorgency Preparedness Task Force 80/07/22 Spp
- B007310193 Requests that ltr. similar to encl draft ltr. be forwarded to util re enci review of emergency action levels for facility emergency plan PAGANO. F O Emergency Preparedness incoming Branch 80/07/22
- 8007250383 Forwards Revisson 5 to station emergency plan.completing response to BK Grimes 800715 comments
 BAUM: E A Virginia Clettric & Power Co 80/07/24 2pp
- --8007250385 Emergency plan. Revision 5
 * Virginia Electric & Power Co 80/07/24 2pp
- @ Adjudicatory torrespondence
- 8007910743 Forwards Commission 800527 memorandum & order containing decisions on UC9 780502 patition for reconsideration of 780413 momorandum & order U/S 771104 petition sought action re fife protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 89pp

- 8007:10339 Order granting extension until 800723 for Commission to elect whether to review decision taken under 10CFR2 208 on request for enforcement action. DD-80-23 HOYLE, J C Office of the Secretary of the Commission 90/07/09 ip
- B007300442 Advises that effective B00B01, address for coalition will be: 1105-C Olive St. Greensborp, NC 27401 Related correspondence.
 ALLEN, J North Anne Environmental Coalition 80/07/15 ip
- H General correspondence
- 8007150047 Responds to 800327 itr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants, operating & under const & relative costs of coal vs. nuclear energy YOUN080,000,8 J Operating Reactors Branch 1 80/05/13 5pp
- 8007070039 Forwards 800620 Director's Decision DD-80-23, denying 800218, 22,0425 & 0525 requests for action FR notice encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/20 | 2pp
- ---B007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON:H R Office of Nuclear Reactor Regulation, Director 80/06/20 25pp
- --B007070069 FR notice of issuance of B00620 Director's Decision DD-00-23 denying B00218.22, 28,0425 & 0525 requests by North Anna Environ Coalition for action DENTON-H R Defice of Nuclear Reactor Regulation, Director B0/06/20 2pp
- --8007070075 Requests amend to 800218 ltr following discovery of eddl problems in steam generator. Facility should be kept shut down pending resolution of noise, secondary chemistry, turbine cracks & demineralizer problems
 ALLEN, J North Anna Environmental Coalition 80/02/22 ip
- --B007070079 Requests action concerning defective demineralizer design, related corrosion & cracking in steam generators & turbine discs Commends NRC decision to require EIS re experiments; replacement of steam generators ALLEN, J North Anna Environmental Coalition 80/02/IB 4pp
- J Insurance & indemnity information
- 8007150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE, D A Marsh & McLennan, Inc., M & H Nuclear Consultants, Inc Div 80/07/10 Spp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D Q Division of Licensing 80/06/11 62pp
- 8007100078 Forwards request for add1 info re adequacy of station electric distribution sys voltages por review of 791009 & 791128 submittals Requests response within 45 days CLARK.R A Operating Reactors Branch 3 80/06/25 5pp
- B007010422 Responds to NRC B00507 ltr re loss of offsite power, Review of history reveals two partial losses of offsite power occurred, SYLVIA-B R Virginia Electric & Power Co 80/06/26 3pp
- B007010430 Confirms agreement w/NRC to review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur THOMAS, W N Virginia Electric & Power Co E0/06/26 App
- B007020494 Forwards add1 info re corrective actions for steam generator chemistry & corrosion, per NRC B00408 request SYLVIA, B R Virginia Electric & Power Co 80/06/30 19pp
- 8007020392 Forwards "North Anna Unit 1.Cycle 2 Startup Physics Test Rept " THOMAS.W N Virginia Electric & Power Co 80/06/30 ip
- --8007020598 "North Anne Unit 1. Cycle 2 Startup Physics Test Rept "
 KUNSITIS: T J , LEBERSTIEN, J H , LOZITO, E J Virginia Electric &
 Power Co VEP-FRD-35 80/06/30 110pp

- 8007070368 Forwards request for info re bypass & reset of engineered safety features Request revised per 800528 discussions GARFAGNO.8 P Franklin Institute/Franklin Research Center NRC-03-79-118 80/06/30 3pp
- BOO7250001 Requests submittal of application for amend to license consisting of Tech Spec Changes & license conditions PWR Model Tach Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT,D O Division of Licensing 80/07/02 69pp
- BOO70H0069 Application for amend to License NPF-4, adding requirement that ECCB subsystems be demonstrated operable by verifying that manual valves in Tech Spec 4 5 2 g 2 are locked tagged in proper position following maint Fee encl FERGUSON, J H Virginia Electric & Power Co 80/07/03 3pp
- ---BOO7080072 Proposed revised Tech Spec 4 5 2 gladding requirements that ECCS subsystems be demonstrated operable by verifying that manual valves are locked & tagged in proper position Pollowing maint
 # Virginia Electric & Power Co 80/07/03 2pp
- 9007100280 "Bump Pump Discharge Piping Auxiliary Bldg to Containment" # Stone & Webster Engineering Corp 77/10/24 ip
- -8007100284 "Flow Diagram Boron Recovery Sys " Sheet 1 # Stone & Webster Engineering Corp 80/07/07 1p
- --B007100288 "Flow Diagram, Containment Atmosphere Cleanup Sys "
 * Stone & Webster Engineering Corp 77/10/22 ilp Stone & Webster Engineering Corp
- ---B007100298 "Flow Diagram, Waste Disposal Sys " Sheet i # Stone & Webster Engineoring Corp 80/07/07 1p
- --8007100303 "Ventilation Thermal Recombiner * Stone & Webster Engineering Corp 80 80/04/07 ip
- --8007100309 "P&ID Liquid Bampling " Sheet 1 of 5 * NVS Corp 80/05/05 1p NUS Corp
- --B007100311 "P&ID Liquid Sampling " Sheet 2 of 5 w NUS Corp 80/02/19, 1p
- ---B007100315 "P&ID Liquid Sampling Coolers " Bheet 3 of 5 * MVS Corp. 80/05/05 ip
- --8007100323 "P&10 Liquid Bampiing " 5 of 5 NUS Corp 80/05/05
- --8007100329 "P&ID Containment & Air Bampling Sys " Sheet i of i 80/05/05 1 p
- ---8007100335 "Process Flow Diagram. Liquid Sampling " Sheet i of 2 * NUS Corp 80/05/22 ip
- ~-8007100338 "Process Flow Diagram' Liquid Bampling " Sheet 2 of 2 * NVB Corp 80/05/22 ip
- --8007100347 "Process Flow Diagram Containment Air Sampling " w NUS Corp 80/04/14, ip
- --8007100351 "General Arrangement Auxiliary Bldg. Drumming Room Plan. Elevation 274 Ft " Sheet i * NVS Corp 80/05/29 ip
- --8007100359 "General Arrangement Auxiliary Dldg, Drumming Room, Section & Details, " Sheet 2 * NUS Corp. 80/05/29 Jp
- --8007100365 "General Arrangement High Radiation Sampling Bys Waste Tank & Pumps.Plan Elevation 244 Ft.6 Inches & Section " Sheet 1 * NUS Carp 80/05/29 1p

- 8007280169 Advises of 800428 reorganization of DFc of Nuclear Reactor Regulation Lists personnel responsible for facility NDVAK.T M Assistant Director for Operating Reactors
- 8007140393 Application to amend License NPF-7 consisting of changes to Tech Spec setpoints & allowable values FCROUSON.J H Virginia Electric & Power Co 80/07/11 3pp
- --B007i4040D Revised Tech Specs Table 2 2-1 for leactor trip sys instrumentation trip sotpoints & Table 3 3-4 for engineered safety feature actuation sys instrumentation trip setpoints # Virginia Electric & Power Co B0/07/11 4pp
- BOO7150567 Notifies that util is using dual sys of notification for site & general emergencies in cooperation w/local counties at insistence of VA State Ofc of Emergency & Energy Sycs Tentative implementation schedule for NUREG-0654 oncl BAVM.E A Virginia Electric & Power Co 80/07/ii 20pp
- 8007210102 Notification of 800724 meeting w/vtii in Bethesda.HD to discuss analysis of quadrant tilt CHATTERTON.M Core Performance Branch 80/07/11 2pp
- 8007240204 Notification of 800724 meeting w/vtil in Dethesda.HD to discuss quadrant tilt in plant CHATTERTON.M Core Performance Branch 80/07/il 2pp
- 8007310421 Comments on NUREO-05/7. "Pritential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Requests extension of review period to 800915 to review stress corres
- 80072504i3 Requests time extension to replace Barton Transmitters to third refueling outage of Unit 1.Lot 1 Replacement of Unit w/refueling consistent w/current transmitter availability as previously discussed BYLVIA.B R Virginia Electric & Power Co 80/07/22 2pp
- BOO728065i Provides summary of results of Phase I of multiple structure advance record sys evaluation of piping sys design Final detailed rept Will be submitted upon completion of Phase II effort Category listing attacked GYLVIA.B R Virginia Electric & Power Co 80/07/25 3pp
- 8007290700 Summarizes results of Phase i of multiple structure amplified response spectra evaluation of North Anna 1 piping sys design as described in 800606 ltr Finel detailed rept will be submitted upon completion of Phase il effort BYLVIA,8 R Virginia Electric & Power Co 80/07/25 Spp
- Q Inspection reports. IE Bulietins % correspondence
- 8007240230 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 While in Refueling Mode " No response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/08 Region 2, Atlanta, Office of the Director 80/05/08
- 8007020200 Forwards IE info Natice 80-22. "Mreakdowns in Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- B007210477 Forwards IE Circulur 80-13. "Grid Strap Damage in Westinghouse Feel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director
- B007010239 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007160732 Forwards IE Insp Repts 50-338/80-23 % 50-339/80-23 on norsacracraments in inspring to the construction & Engineering
 BOOS12-15 No noncompliance noted
 MURPHY, C E Region 2. Atlants, Reactor Construction & Engineering
 Support Branch BO/O6/09 2pp
- --8007160742 IE Insp Repts 50-338780-23 & 50-339780-23 on 800512-15 No noncompliance noted Major areas impected seismic analysis for as-built safety-related piping sys & licensee actions on licensee identified items COMPTON.R M Region 2. Atlanta. Office of the Director HERDIAR Region 2. Atlanta. Reactol Construction & Engineering Support Branch 80/06/04 5pp

- Forwards IE info Notice 80-26. "Evaluation of Contractor ams "No written response required J P. Region 2. Atlanta. Office of the Director — BO/06/10
- Forwards IE info Notice 80-27, "Dogradation of Reactor Cump Atuds " No specific action or response
- JP Region 2, Atlanta, Office of the Director #80/05/11
- Forwards revision to Page 2 of 800611 response to 1E 80-12. "Decay Meat Hemoval Bys Operability " R Virginia Electric & Power Co 80/06/16 2pp
- Responds to It Bulletin 79-01B, "Environ Classification of nent" Class IE electrical equipment reviewed to inclining during postulated accident Review of ems 1,2 4 3 provided in worl repts W/o encl repts R Virginia Clectric & Pawer Ca 80/06/16 3pp
- Forwards IE Bulletin NO-15, "Possible Luss of Emergency ion Sys (ENS) W/Lops of Offsite Power " Nritter
- JP Region 2, Atlanta, Office of the Director 80/04/18
- Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Natural Circulation Couldown " No written response
- JP Region P. Atlanta, Office of the Director 80/06/20
- Forwards IE Circular 80-14, "Redinactive Contamination of the alized Waker 89t & Resultant Internal tion of Personnel" No unition response required JP Region 2, Atlanta, Office of the Director 80/06/24
- Responds to IF Bulletin 79-14. "Goismit Analysis for Safoty-Related Piping Sys " Const work complete on imited completion date for Unit 1 is 8000.31 Virginia Electric & Power Co 98/06/27 Spp
- Torwards IE Rulletin 60-16. "Potential Misapplication of Inc Models 1991 & 1992 Pressure Transmitters For B Output Codes " Britten response required F 60-16 also onel No written response required FP Region 2, Atlanta, Office of the Director 80/06/27
- orwards IE Insp Repts 50-410/80-24 & 50-339/80-24 on Na noncompliance nated Details withheld 2 790:
- Region 2. Atlanta. Safeguards Branch 80/0//01 Ip
- lt Insp Repts 96-498/80-24 % 90-339/80-24 on 600611-12 No lento noted Major areas inspected vital area, searches & vital area access Betails withheld 1982 700
- .TP Region 2. Atlanta, Safeguards Branch FOBIN.W J. Atlanta, Office of the Director B0/07/01 1p
- urwards response to violation noted in II. Insp Repts 2 & 50-319/00-18 Corrective actions review of test control program & atotion mpt will lite to periodic tost scheduling requirements Virginia Electric & Power Co. 80/07/02 2pp
- irwards "If Bullptin 60-Day Roview." in response to action i Item 4 of 16 Dullotin 60-li, "Masonry Wall opt available in Contral Files only Virginia Electric & Power (a 80/07/07 ip
- Hwards response to IF Dulletin 80-08, "Exam of Containment ration Welds " Penetration essemblies of flued g design were used for penetrations listed in 2 for North Anna Virginia Elettric & Power Co. 80/07/07 7pp
- sponds to IC Dulletin 80-10 to contamination of ive age Lists sys considered numradinactive but radioactive through interfoces w/radioactive charge paths are sampled or monitored Virginia Riectric & Power Co 80/07/07
- sponds to items (' % On of IE Bulletin 79-27. "Loss of Nonstrumentation & Control Power Sys Bus During Unit 1 inverter trip was not related to failure ibed in hullotin Virginia Electric & Power Co 80/07/09 2pp

- 8007230447 Forwards response to notice of violation item reported in JE Insp Repts 50-338/80-25 & 50-339/80-26 Infraction is not correct as stated Point-by-point rebuttal provided Insp repts contain no proprietary info
- R Periodic operating reports & related correspondence
- 8007220431 Forwards monthly operating repts for June 1980 SYLVIA, B R Virginia Electric & Power Co 80/07/15 ip
- --8007220434 Monthly operating repts for June 1980 HADISON, W.R. Virginia Electric & Power Co. 80/07/09 9pp
- 9 Reportable occurrences, LERs & related correspondence
- BOD7030265 Forwards LER 80-032/03L-0 CARTHRIGHT, H R Virginia Electric & Power Co 80/06/30 ip
- 8007030270 Fuswards LER 80-050/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/06/30 ip
- ~~8007030271 LER 80~050/03L-0 on 800531 during steam generator 1A channel 3 narrow range level transmitter recalibr determined that transmitter had drifted 3A high Caused by normal instrument drift. Transmitter recalibr immediately CARTMRIGHT, 47 R Virgania Electric & Power Co 80/06/30 2pp
- B007090345 Forwards LER B0-046/03L-0 CARTURIONT, W R Virginia Electric & Power Co B0/07/02 ip
- --8007090363 LER 80-046/03L-B on 800612, Made 1 level indicator, LI-1474, on A steam generator read 5% higher than other indicators Caused by steam leak on upper transmitter isolation root valve Steam leak treated w/furmanite CARTURIGHT, H R Virginia Electric & Power Go 80/07/02 2pp.
- 8007210092 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FSAR Caused by use of incorrect sys vol Review will be performed to identify & analyse addi accidents BYLVIA,B R Virginia Electric & Power Co 80/07/02 4pp
- 8007070373 Foruands LER 80-054/03L-0 CARTHRIGHT: R Virginia Electric & Power Co 80/07/03 ip
- --B0070703B1 LER E0-054/03L-0 on B00603, containment internal air partial pressure exceeded Tech Spec limit Caused by air laskage past containment purge supply valve Valve subsequently verified closed & leak tested CARTWRIGHT, N R Virginia Electric & Power Co B0/07/03 2pp
- BOO71304B4 Forwards LER BO-057/03L-Q CARTWRIGHT, W R Virginia Electric & Power Co 80/07/07 ip
- --B007150701 LER B0-057/03L-0 on B00618 during Mode 2 operation, greater than twolve step disagrowment was noted between individual & group position indication for rod 0-9 Caused by voltage drift in signal conditioning card CARTURIONT, W.R. Virginia Electric & Power Co. 80/07/07 2pp
- BOO7150767 Forwards LFR BO-055/01T-0 CARTWRIGHT.W R Virginia Electric & Power Co BO/07/10 ip
- --8007150777 LER 80-055/01T-0 on 800626, review of FBAR cafety analyses for boron dilution accidents determined that nonconservative RCS vols were used for cold shutdown condition Cause undetermined Belution pending further evaluation CARTHRIGHT.W R Virginia Electric & Power Co 80/07/10 3pp.
- 8007110300 RD 80-95/017-0 during review of FSAR safety analyses for boron dilution accident potential, nonconservatism in cold shutdown analysis determined Cause unknown Accident analysis review initiated * Virginia Electric & Power Co 80/07/11 tp
- BOO7220575 Forwards LER BO-058/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co BO/07/16 lp

- ---8007220580 LER 80-058/03L-0 on 800619, while in Mode 1, post-accident hydrogon analyzer declared inopurable after surveillance texting performed Caused by dihydrogen analyzer T/C bridge failure to energize due to sample line low back pressure CARTHRIGHT, W R Virginia Electric & Power Co 80/07/16 2pp
- S007220007 Forwards LER 80-056/03L-0 CANTERIONT, W.R. Virginia Electric & Power Co. 80/07/17 1p
- --\$00/8"4012 LER 80-056/03L-0 on 800626, after trip caused by false ova..emp delta T signal, false delta T output discovered in channol II DELTA T/TAVO protection sys Caused by summing amp card & load/log derivative card Cards replaced CARTARIOH(, W R Virginia Electric & Power Co 80/07/17 3pp
- 8007230493 Forwards LER 80-061/017-0 CARTWRIGHI,N R Virginia Electric & Power Co 80/07/17 ip
- CARNARIGHT, W R Virginia Electric & Power Co 80/07/22 1p

V Operator Examinations

- 8007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructors are required to participate in program to maintain proficiency

 BYLVIA, BR Virginia Electric & Power Co 80/07/15 1p
- ---B007170350 Revised, "Licensed Operator Requalification Program " # Virginia Electric & Power Co B0/07/31 11pp

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 8007240049 Responds to NRC B00718 request for add1 info re GA list Air makeup for control room air conditioning sys is provided by vent fans No makeup fan motors erist in sys Diesel generator blig ventilation is provided by normal intake air BAM.E A Virginia Electric & Power Co 60/07/22 ip
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8007070200 Reaponds to SER Suppl 10, Section 15 2 request for commitment requestions on analysis of postulated steam line & feedwater line breaks Westinghouse will provide requested info which is not directly applicable to facility BYLVIA, D.R. Virginia Electric & Power Co. 80/07/01 1p
- BO07300297 Forwards discussion of util 800711 & 18 responses to deficiencies listed in SER Full-power operation should be authorized upon obtaining FEMA approvable of state & local smergency plans.

 WRINGS B K Emergency Preparedness Task Force 80/07/82 Spp
- 8007280444 Forwards supplemental info re full power SER Evidence of safety & relief valve capability from tests performed in EPRI/NSAC sefety & relief valve test program will be forwarded by 810701
 BYLVIA, B R Virginia Electric & Power Co 80/07/25 2pp
- F. Security, medical, emergency & fire protection plans
- BOO7240005 Forwards amended physical security plan. Plan withheld (ref 100FR2 790) BYLVIA.B.R Virginia Electric & Power Co 80/06/03 ip
- 8007170601 Forwards revised nuclear security personnel training qualification program & response to NRC 800519 ltr Program & response withheld (ref 10CFR2 790) SYLVIA.S R. Virginia Electric & Power Co 80/07/14 Jp

- 8007240092 Forwards security info re 800609 ltr info withheld (ref 100FRR 790) SYLVIA B R Virginia Electric & Power Cp 80/0//18 ip
- 8007220579 Forwards emergency plan Revision 4 in response to request made during 800715 meeting w/TEMA & State of VA.to support full power license request BAUM, E A Virginia Electric & Power Co 80/07/22 22pp
- --B0072205B2 Facility emergency plansRevision 4
 * Virginia Electric & Power Co 80/07/15 13pp
- B007280156 Forwards emergency preparodness requirements for full power license per review of 800419.0606.20 & 25 submittals Requests schedule for meeting requirements B0/07/22 4pp
- B0072B0432 Forwards revised emergency plan implementing procedures Procedures available in Central Files only BAUM, E.A. Virginia Electric & Power Co. B0/07/22 1p
- B007310193 Requests that ltr.similar to entl draft ltr.be forwarded to util re entl review of emergency action levels for facility emergency plan
 PAGANO,F O Emergency Preparedness Licensing Branch 80/07/22
- 8007280383 Forwards Revision 5 to station emergency plan.completing response to BK Orimes 800715 comments
 BAUH.E.A. Virginia Electric & Power Co. 80/07/24 2pp
- --B0072803B5 Emergency plan, Revision 5
 * Virginia Electric & Power Co 80/07/24 2pp
- 8007250388 Advises that 800630 ltr contained error in describing date of most recent evercise of emergency plan itr stated that exercise conducted in Oct 1979 Correct history of emergency plan drills contained in 800711 ltr
 SYLVIA.B R Virginia Electric & Power Co 80/07/24 ip
- 8007280440 Submits schedule for completion of fire protection mods Smoke detections sys & reactor conlant pump oil collection sys will be completed during 801101 outage Charging pump cross-connect will be completed during 800401 outage SYLVIA. IR Virginia Electric & Power Co. 80/07/25 1p
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCB 780802 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/06/29 87pp
- 8007110339 Order granting extension until 800723 for Commission to elect whether to review decision taken under 10CFR2 206 on request for enforcement action, DD-80-23 HOYLE, J C Office of the Secretary of the Commission 80/07/07 ip
- 8007300412 Advises that effective 800801, address for coalition will be 1105-C Dive 8t. Greensboro. No 27401 Related correspondence ALLEN.J. North Anna Environmental Coalition 80/07/15 1p

H General correspondence

- 8007150047 Responds to 800327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants.operating & under const & relative costs of coal vs nuclear energy YOUNOBLOOD, B J Operating Reactors Branch 1 80/05/13 5pp
- BO0718045B Responds to 791203 ltr re licensing new nuclear power plants Licensing of new plants stopped after TM1 until criteria for improved safety could be developed Three units have been authorized to begin low level power testing DENTON.H R Office of Nuclear Reactor Regulation, Director BO/09/14 ip
- --B007180464 Forwards misdirected 791203 ltr re licensing of new nuclear power plants RATHKOPF, C Energy, Dept of 80/01/21 2pp
- 8007070059 Forwards 800620 Director's Decision DD-80-23 denying 800218,22,0425 & 0525 requests for action FR notice encl DENTON-H R Office of Nuclear Reactor Regulation, Director 80/06/20 2pp

- 8007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTEN.H R Office of Nuclear Reactor Regulation, Director 80/06/20 23pp
- 8007070069 FR notice of issuance of 800620 Director's Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ Coalition for action DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/20 2pp
- 8007070079 Requests action concerning defective demineralizer design, related corrosion & cracking in steam generators & turbing discs Commends NRC decision to require EIB re experimental replacement of steam generators ALLEN.J North Anna Environmental Coalition 80/02/IB 4pp
- NOTO205BB Responds to HB McDonald ltr directed to DDE North Anna full power license issuance will be discussed w/Commission in Jul-Aug 1980 Surry is in shutdown condition due to seismic piping supports mads & will return to power in Aug 1980 YDUNGDLADD. B J Licensing Branch 1 80/06/25 1p
- 8007020693 Forwards HB McDonald ltr expressing concerns re continued operation of facilities
 BETANCOURT, B Energy, Dept of 80/06/06 2pp
- Insurance & indemnity information
- 07150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE,D A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. 01v 80/07/10 3pp
- Operating license stage documents & correspondence
- 07090053 Notification of 800627 site visit to perform selsmic design margin evaluation of safety-related equipment DROMERICK, A W. Licensing Branch 1 80/06/23 4pp
- 77100140 Discusses 800405 site visit NRC personnel found no visual wall cracks resulting from uneven settlements or shrinkage furing tours of svc bldg, turbine bldg, auxiliary bldg & fuel
- bldg ROTHEERO, D. CHOMSHI, N., RONNEY, N. Structural Engineering Branch 80/06/24 Spp
- J7070203 Forwards request for addl info re FSAR Info is required to omplete NRC evaluation of QA list info requested by 800702 QUNGBLQQD.B J Licensing Branch 1 80/06/25 7pp
-)7080371 Lists topical repts for which responses to outstanding juestions will be provided to allow SER to proceed & to avoid delays in approval of full power operation Includes (CAP-9226, -9230 & -9236 WDERSON, T M Westinghouse Electric Corp. 80/06/25 ip
- 17010430 Confirms agreement w/NRC re review criteria to be used to evaluate results of rod swap tests & administration of shysics testaprogram should deviations occur.

 [HOMAS.W N Wirginia Electric & Power Co B0/06/26 App.
- 17230001 Forwards statement of policy re requirements to be met for urrent DL applications as derived from NUREC-0660 & found n NUREC-0694
 ISENHUT, D © Division of Licensing 80/06/24 2pp
- 17030156 Responds to request for add1 info re revision to Tech Spec 7-4 Low head safety injection sys piping mods on Unit 2 are different from mods on Unit 1 as result of experience ained during reanalysis of Unit 1 to 180706/27 3pp.
- I7030151 Forwards summary of response to NUREG-0660 full power & 980 requirements Items which apply to operator training & itemsing have been implemented Work is proceeding to omplete items w/810101 implementation dates
 YLVIA, B R Virginia Electric & Power Co 80/06/30 i2pp
- 17070369 Forwards request for info re bypass & reset of engineered afety features Request revised per 800528 discussions /NRC ARFAGNO.8 P Franklin Institute/Franklin Research Center RC-03-79-118 80/06/30 3pp
- 7070201 Forwards response to NRC 800625 request for info re GA list. AUMLE A Virginia Electric & Power Co 80/07/02 31pp

- BOO7180039 Requests addl info re addition of 15 snubbers Info needed to complete review of FSAR YOUNGBLOOD, B J Licensing Branch 1 80/07/02 4pp
- 8007:70439 Forwards Amend 1 to License NPF-7.safety evaluation & notice of issuance & availability
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/03 3pp
- ---B007170443 Amend 1 to License NPF-7, authorizing special low power test program DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/03 3pp
- --8007:70445 Safety evaluation supporting Amend 1 to License NPF-7 # Office of Nuclear Reactor Regulation. Director 80/07/02 40pp
- --8007170449 Notice of issuance & availability of Amend 1 to License NPF-7 YOUNGBLOOD,B J Licensing Branch 1 80/07/03 2pp
- 8007100273 Submits add1 info re implementation of short-term Lessons Learned requirements Status of remaining Category A items, mid-yr status of design & installation of Category B mods & schedule for implementation encl Forwards drawlings SYLVIA.B R Virginia Electric & Power Co 80/07/07 180pp
- --8007100277 "Sump Pump Discharge Piping Auxiliary Bidg to Containment "
 * Stone & Webster Engineering Corp 79/05/15 ip
- --8007:00280 "Sump Pump Discharge Piping Auxiliary Bldg to Containment "
 * Stone & Webstor Engineering Corp 77/10/24 ip
- --8007100284 "Flow Diagram Boron Recovery Sys " Sheet i * Stone & Webster Engineering Corp 80/07/07 1p
- --B007100288 "Flow Diagram Containment Atmosphere Cleanup Bys."

 * Stone & Hebster Engineering Corp 77/10/22 lip
- --8007100293 "Flow Diagram Waste Disposal Sys " Sheet 2 Btone & Webster Engineering Corp 80/07/07 ip
- --B007100298 "Flow Diagram Waste Disposol Sys " Sheet i * Stone & Webster Engineering Corp 80/07/07 ip
- --B007100303 "Ventilation Thermal Recombiner" * Stone & Webster Engineering Corp 80/04/07 ip
- --8007100321 "P&ID Liquid Sampling Panel " Shoet 4 of 5 * NVS Corp 80/05/05 ip
- --8007100323 "P&ID Liquid Sampling " 5 of 5 # NUS Corp 80/05/05 ip
- --8007100329 "P&ID Containment & Air Sampling Sys " Sheet 1 of 1 * NUS Corp 80/05/05 ip
- --8007100338 "Process Flow Diagram Liquid Sampling " Sheet 2 of 2 $\,$ NUS Corp. $\,$ 80/05/22 $\,$ ip
- --B007100347 "Process Flow Diagram Containment Air Sampling "
 * NUS Corp 80/04/14 1p
- --8007100351 "General Arrangement Auxiliary Aldg. Drumming Room Plan, Elevation 274 Ft " Sheet 1 * NUS Corp 80/05/29 1p
- --8007100359 "Oeneral Arrangement Auxiliary Bldg, Drumming Room, Section & Details " Shmet 2 * NUS Corp 80/05/29 ip
- --8007100365 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps.Plan Elevation 244 Ft.6 Inches & Section " Sheet 1 * NVS Corp 80/05/29, 1p
- BOO7110202 Provides summary of results of control room habitability review, in accordance w/NUREO-0694 % in response to NRC BOO702 request Control room masts specs set forth in applicable SRP sections & reg guides
 BYLVIA.B R Virginia Electric & Power Co BO/07/07 ip

- 8007100139 Notifies that Hestinghouse 8005i6 comments on power ascension procedures have been incorporated into procedures Action satisfies NURGO-0660. Item I C 7 requirements SYLVIA, B R Virginia Electric & Power Co 80/07/08 1p
- 8007110364 Forwards "Steam Generator Hater Hammer Demonstration Test," per Tech Spec 8 i FERCUSON,J H Virginia Electric & Power Co 80/07/09 4pp
- --8007110365 "Steam Cenerator Water Hemmer Demonstration Test "
 * Virginia Electric & Power Co 80/06/24 23pp
- BOO7110359 Forwards response to NRC BOO310 request for info re auxiliary feedwater sys design basis info & pump flow verification, for Unit 2 Unit 1 info will follow shortly BYLVIA:B R Virginia Electric & Power Co 80/07/10 15pp
- 8007110361 Forwards descriptive info for Action Item II B 1 roquested by NRC for full-power licensing review Response to NRC 800701 request for addl info re RCS vents will be provided as soon as possible SYLVIA.B R Virginia Electric & Power Co 80/07/10 App
- 8007140158 Forwards add1 info requested in NRC 800618 ltr re use of safety-grade equipment to achieve cold shutdown SYLVIA.B R Virginia Electric & Power Co 80/07/10 i6pp
- 8007140187 Lists addl TMI-related requirements which will be completed by 8i0101.in response to NRC request
 SYLVIA,B R Virginia Electric & Power Co 80/07/10 2pp
- B007140393 Application to amend License NPF-7 consisting of changes to Tech Opec setpoints & allowable values FERGUBON.J H. Virginia Electric & Power Co. 80/07/11 3pp
- --8007140400 Revised Tech Specs Table 2 2-1 for reactor trip sys instrumentation trip setpoints & Table 3 3-4 for engineered safety feature actuation sys instrumentation trip setpoints a Virginia Electric & Power Co 80/07/11 6pp
- B007140406 Responds to NRC 791214 ltr & forwards. "Bummary of Unit 2 Motor Driven Auxiliary Feedwater Pump Endurance Test " BYLVIA:B R Virginia Electric & Power Co 80/07/11 1p
- --8007140411 "Bummary of Unit 2 Motor Driven Auxiliary Feedwater Endurance Tests" * Virginia Electric & Power Co 80/07/11 9pp
- 8007130369 Notifies that util is using dual sys of notification for site & general emergencies in cooperation w/local counties at insistence of VA State Ofc of Emergency & Energy Sycs Tantative implementation schedule for NUREG-0694 encl BAUM.E A Virginia Electric & Power Co 80/07/11 20pp
- 8007160307 Bubmite addl info requested by NRC re util 800618 request for amend of Tech Specs to include addl safety-related snubbers Design & const of safety injection sys where snubbers added is discussed One oversize drawing encl BYLVIA, D R Virginia Electric & Power Co 80/07/ii 34pp
- 8007160671 Responds to NRC request for add1 info re residual heat removal sys Addresses use of pressurizet power-operated relief valve for pressure reduction of RCS & advises of blown rupture discs Precaution will be added BYLVIA:R R Virginia Electric & Pawer Co 80/07/14 2pp
- 8007170175 Forwards Operating Procedures 2-OP-12 1 & 2-OP-12 2 re interim post-accident sampling in response to NUREO-0660 Action Plan Item II B 3 SYLVIA:B R Virginia Electric & Power Co 80/07/14 2pp
- ---B007170183 Operating Procedure 2-OP-12 i.Revision 1. "Sampling Sys "
 HARVEY, S L Virginia Electric & Power Co B0/07/il. 30pp
- --BO07170189 Operating Proceduro 2-DP-12 2, "Post-Accident Containment Atmospheric Sampling Sys " HARVEY.8 L Virginia Electric & Power Co BO/07/11 Spp
- 8007220497 Forwards proprietary version of App A info re turbine disc matls properties, per NRC request Westinghouse application for withholding encl Turbine disc into withheld (ref 10CFR2 790) BYLVIA:B R Virginia Electric & Power Co 80/07/15 9pp

- 8007210244 Forwards revised Table 2-1 of 800710 response to NRC requestion info re outsiliary feedwater sys requirements Info available in Section 15 4 2 d of FSAR does not include Westinghouse analysis of limited feedwater break SYLVIA. B R Virginia Electric & Power (a. 80707/16. 17pp
- 8007280006 Notification of 800723 meeting w/utils in Bethusda, MD to discuss matters re Tiff-2 dated requirements
 DROMERICK, A W Licensing Branch i 80/07/16 5pp
- 8007300099 Summary of 600630 site visit to observe special low power test program ANDERSON:N R Procedures & fest Review Branch 60/07/16 7pp
- 8007210377 Provides urrliminary summary of special tests intended to characterize plant parameters during natural circulation conditions info will improve aporator training program & upgrade simulator facility Tist rept to be furwarded SYLVIA: IR Virginia Electric & Pawer Co 80/07/17 3pp
- B00721034/ Responds to NRC 800701 request for add1 info re full power licensing approval Detailed info & drawings to RCS vents enc! SYLVIA.B R Virginia Electric & Power Co 80/07/17 App
- B007220384 Forwards add1 info to util B00719 ltr re RHR sys Bimulation of use of pressurizon power-operated telling valve to depressurizo RCB performed satisfactorily on B00717 & demonstrates alternate method of sys condition SYLVIA.B R Virginia Electric & Power Co 80/07/18 2pp
- 8007310421 Comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Requests extension of review period to 800915 to review stress corrosion cracking BROWN.S C Virginia Electric & Power Co RD/07/21 2pp
- 8007240115 Forwards suggested Terh Sper changes for administrative controls established as program to identify, second & ropt failures of or challunges to power operated relief valves Program outlined in util 8006/00 response to NAREG-0660 SYLVIA.B R Virginia Electric & Power Co 60/0//22 1p
- --8007240116 Suggested Tech Spec changes for administrative controls * Virginia Electric & Power Co 80/04/11 Spe
- 8007240149 Forwards add) info to dusign data for low hand safety injection pump discharge piping Oversite drawings out!

 BYLVIA, B. R. Virginia Electric & Power Co. #80/07/22 14pp
- --8007240156 "10x8xi0 Number 5390-1DDA6A Series 1500, Weiding Ends Outside Screw & Yoke Cato Valve W/Lip Seal & SMD-2-60 Limitorque Valve Control "
 * Parling Valve & Mfg /2/05/05 tp
- --8007240157 "10:9x10 Number 5.390-IDDASA Series 1500. Welding Ends Outside Screw & York Oate Valve W/Lip Seal & EMB-2-AQ Limitorque Valve Control " * Darling Valve & Mfg /2/02/23 tp
- --BO07240161 "300 ib Cast Allog Steel Motor Operated Gate Valve W/Outsid Screw & Yoke Spiit Wodge Disc & Dumpet Joint for Seal Welding-Ceneral Assembly & Dimensions " * Stone A Webster, Inc. * Crane Co. 11715 72703707 1p
- ---8007240156 "Safety Injection Bys Seismix Mathematical Hodel " * Stone & Webster Engineering Corp. 78/12/04 Ip
- 8007250415 Requests time extension to replace Borton Transmitters to third refueling outage of Unit 1.Lot 1 Replacement of Unit W/refueling consistent W/current transmitter availabilisty as previously discrete transmitter availabilisty as previously discrete 8 FOWOR CO 80/07/20 2pp
- 8007280395 Forwards "Natural Circulation Test Rapt." conducted 800703-16, which completes requirements for NURFG-0640, Item 10
 BYLVIA:B R Virginia Flettix & Power & 80/07/22 tp
- --8007280400 "Natural Circulation Test Rept." conducted 800703-16 KANN, G A Virginia Electric & Power Co 80/07/27 30pp
- 8007250379 Informs of completion of full power requirements of SFR. Baction 10-2 & TMI action plan.NURE 6-0660. Items 11 B 4 All licented operators received training for degraded conscionalitions
 BYLVIA.B R Virginas Electric & Power (o. 80/07/24 ip.

- 8007290430 Submits listing of two groups of items yet to be resolved based on review of Class IE electrical equipment qualification using NUNEO-0588 guidance Harked-up R Tedesco 780228 memo ie fecility equipment qualification encl SYLVIA.8 R Virginia Electric & Power Co 80/07/P4 i3pp
- B007280367 Forwards nonproprietary version of Westinghouse low pressure turbine disc info Suppls proprietary info transmitted by licensee B00715 ltr SYLVIA.B R Virginia Electric & Power Co B0/07/25 21pp
- BOO7280404 Forwards current installation schedule for NUREG-0540 items identified in NUREG-0594 Discussion of items that may be delayed beyond filolol and shell SYLVIA. B R Virginia Electric & Power Co 80/07/25 7pp
- BOO72B0423 Forwards add1 info requested re periodic leak testing of pressure isolation valves SYLVIA.B R Virginia Electric & Power Co 80/07/25 2pp
- BOO7280651 Provides summary of results of Phase 5 of multiple structure advance record sys evaluation of piping sys design Final detailed rept will be submitted upon completion of Phase II affort Category listing attached SYLVIA, B R Virginia Electric & Power Co BO/07/25 3pp
- B007290700 Summarizes results of Phase I of multiple structure amplified response spectra evaluation of North Anna 1 piping sys design as described in 800606 ltr Final detailed rept will be submitted upon completion of Phase II offort SYLVIA B R Virginia Electric & Power Co 80/07/25 Spp
- 8007300498 Submits list of add) design data re low head safety injection pump discharge piping stress problem in response to NRC request Info will be forwarded by 800730 SYLVIA B R Varginia Electric & Power Co 80/07/25 2pp
- BOO7300183 Requests that facility be granted Full-power license w/o final verification of remaining fUREG-0588 items Items will perform intended functions under accident conditions pending completion of ongoing qualification review SYLVIA.B R Virginia Electric & Power to 80/07/28 2pp
- BOO7300450 Notifies that of 40 items identified in response to NUREG-088B most fall into categories which are used in safeguards sys & 907 of items are located outside containment BYLVIA: B R Virginia Electric & Power Co BO/07/28 1p
- 8007310346 Forwards info in response to NRC questions re applicable codes & Fracture toughness requirements for ferritic steel parts of containment pressure boundary not supported by concrete hold info re carbon steel plates will be forwarded SYLVIA.O R Virginia Electric & Power Co 80/07/39 63pp
- 8007310384 Forwards info supplementing 800722 design data for low head safety injection pump discharge piping analysis info includes model of sys showing mar temp conditions within pipe & selsmic displacements for each support point SYLVIA. B R Virginia Electric & Power Co 80/07/30 24pp
- @ Inspection reports. IE Bulletins & correspondence
- B007240230 Forwards IE Info Notice B0-20, "Loss of Decay Heat Removal Gapability at Pavis-Besse Unit 1 While in Refueling Mode " No response required D'REJILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp
- 8007020200 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required D'REILLY. J P Region 2. Atlanta, Office of the Director 80/05/28 1p
- 8007210477 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Furl Assemblies " No written response required O'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/05/28 1p
- 8007010239 Forwards IF Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No writton response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/05/29 1p
- 8007160732 Forwards IE Insp Repts 50-338/80-23 & 50-339/80-23 on 800912-19 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/05 2pg

- --B007160742 IE Insp Repts 50-338/80-23 & 50-339/80-23 on B00512-15 No noncompliance noted Najor areas inspected spismic analysis for as-built safety-related piping sys & licensee actions on licensee identified itoms COMPTOURR M Region 2. Atlanta. Office of the Director HERDT-A R Rogion 2. Atlanta. Reactor Construction & Engineering Support Branch B0/06/04 5pp
- B007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/10
- ED07160307 Forwards IE Info Notico 80-27. "Degradation of Reactor Coolant Pump Btuds " No Specific action or response required O'REILLY.J P Rogion 2. Atlanta. Office of the Director 80/06/11
- B007090057 Forwards revision to Page 2 of 800611 response to IE Bulletin B0-12. "Datay Heat Romoval Sys Operability "
 SYLVIA:B R Virginia Electric & Power Co 80/06/16 2pp
- 8007020757 Forwards 1E Bulletin 80-15, "Possible Loss of Emergency Notification 8ys (EMB) W/Loss of Offsite Power " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007020434 Forwards 1E Circular 80-13, "Loss of Reactor Coplant Pump Cooling & Natural Circulation Cooldown" No written response required U'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007170117 Forwards IE Circular 80-14, "Radioactive Contamination of Plont Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 to
- 8007010413 Responds to 1E Bulletin 79-14, "Seismic Analysis for As-Built Bafety-Related Piping Sys " Const work complete on Unit 2 Estimated completion date for Unit 1 is 800031 BROWN, 8 C Virginia Electric & Power Co 80/06/27 Spp
- 8007230270 Forwards IE Bulletin 80-16, "Potential Misspelication of Rosembunt inc Nodels 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Writton response required IE Circular 80-16 also encl No writton response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27 in
- BOO716074B Forwards IE inep Ropts 50-338/80-24 & 50-339/80-24 on BOO611-12 No noncompliance noted Details withheld (ref 100FR2 790)
 KENNA, W B Regian 2. Atlanta, Safeguards Branch BO/07/01 1p
- --B007160761 IE Insp Repts 30-338/80-24 & 30-339/80-24 on 800611-12 No noncompilance noted Major areas inspected vital area harriers searches & vital area access Details withheld (ref 10CFR2 790)
 GLLESPIE.F F Region 2. Atlanta, Bafeguards Branch Region 2. Atlanta, Office of the Director 80/07/01 ip
- 8007070283 Forwards response to violation noted in 1E Insp Repts 50-338/80-22 & 50-339/80-13 Corrective actions review conducted of test control program & station mgt will distribute itr re periodic test scheduling requirements SYLVIA.B R Virgania Electric & Power Co 80/07/02 Rpp
- 8007170334 Forwards repts submitted in reponse to action required by Item 4 of 1E Bulistin 80-11, "Masonry Wall Design " Repts prepared in compliance w/Bulletin requirement for submittal of 60-day rept SYLVIA.B R Virginia Electric & Power Co 80/07/07 201pp
- 8007250545 Forwards response to 1E Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Penetration assemblies of flued head forging design were used for penetrations listed in Tables 1 & 2 for North Anna BYLVIA,B R Virginia Electric & Power Co 80/07/07 7pp
- 8007290840 Responds to IE Sulletin GO-10 re contamination of nonredioactive sys Lists sys considered nonredioactive but potentially redioactive through interfaces w/redioactive sys All discharge paths are sampled or monitored BYLVIA, B R Virginia Electric & Power Co E0/07/07 2pp

- BOO7110336 Responds to Items 2 & 3a of IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Unit i inverter trip was not related to failure sodes described in bulletin SYLVIA,B R Virginia Electric & Power Co 80/07/09 2pp
- B007150671 Responds to B00630 teleph re commitments made in response to IE Bulletin B0-06, "Engineered Safety Feature (ESF) Reset Controls " Bubmits info re protection sys design conformance w/Items 1,2 & 3 criteria BYLVIA:B R Virginia Electric & Power Co 80/07/11 5pp
- 8007230447 Porwerds response to notice of violation item reported in IE Insp Repts 50-338/80-25 & 50-339/80-26 Infraction is not correct as stated Point-by-point rebuttal provided Insp repts contain no proprietary info BYLVIA:B R Virginia Electric & Power Co 80/07/18 2pp
- R Pariodic operating reports & related correspondence
- 8007220431 Forwards monthly operating repts for June 1980 BYLVIA.8 R Virginia Electric & Power Co 80/07/15 lp
- 8 Reportable occurrences, LERs & related correspondence
- 8007010333 Forwards LER 80-021/03L-0 CARTURIONT.W R Virginia Electric & Power Co 80/06/24 ip
- --8007010375 LER 80-021/03L-0, on 800504, during Mode 3 operation, leaking valve on radiation monitor RMS-257 resulted in low flow to monitor Caused by routine failure of valve bonnet New valve bonnet installed.

 CARTHRIGHT.W R Virginia Electric & Power Cb 80/06/24 2pp
- 8007010398 Forwards LER B0-028/99T-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/06/26 ip
- ---B007010413 LER B0-028/99T-0 on B00624, during beginning of core life, hot zero moderator temp coefficient found more positive than required Caused by positive moderator temp coefficient discovered during startup physics testing

 * Virginia Electric & Power Co B0/06/26 3pp
- B007110420 RD-80-029/01T-0.on B00427 pressurizer power operated relief Valve PCV-2456 inadvertently opened in Mode 3 following valve maint activities. Corrective action will be taken pending completion of investigation # Virginia Electric & Power Go B0/06/27 ip
- 8007030262 Forwards LER 80-024/01T-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/06/30 1p
- --B007030267 LER 80-024/01T-0 on B00619, during low power physics testing in Mode 2, discovered that main feedwater flow transmitters FT-476,477,487,497 were isolated Gause could not be determined. Transmitters valved in & returned to svc # Virginia Elactric & Power Co 80/06/30 3pp.
- BOO7030273 Forwards LER BO-017/03L-0 GARTWR19HT,W R Virginia Electric & Power Co 80/06/30 ip
- ---B007030275 LER 80-017/03L-0 on B00601.inner containment hatch door leaked air past seals during test performance Caused by dirty seals Beels cleened & air lock tested satisfactorily CARTWRIGHT.W R Virginia Electric & Power Co B0/06/30 2pp
- BOO7030281 Forwards LER 80-019/03L-0 CARTHRIGHT,W R Virginla Electric & Power Co BO/06/30 ip
- B007030285 Forwards LER 80-018/03L-0 CARTWRIGHT:W R Virginia Electric & Fower Co 80/07/01 ip
- ---B0070302BB LER B0-018/03L-0 on 800602, loss of C reserve station svc transformer occurred rendering C normal station ave & 20 intake structure buses inoperable Caused by open breakers Emergency buses penegized & breakers closed CARTHRIGHT, H R Virginia Electric & Power Co. 80/07/01 Rpp

- 8007140585 Part 21 rept re containment electrical penetrations fault current protection devices Devices would not limit current to values below thermal limit Devices were changed or adjusted to protect penetrations
 HILD,P A Stane & Wabster, Inc. 80/07/01 4pp
- 8007:40601 Part 21 rept re Colt Industries diesel generator battery racks which do not meet selsmit design criterion Inadequate components replaced to meet design criterion MILD.P A Stone & Webstor. Inc. 80/07/01 4pp
- 8007070358 Forwards LER 80-016/03L-0 CARTHRIGHT: W Virginia Electric & Power Co 80/07/02 1p
- --B007070363 LER 80-016/03L-0 on 800607, during hot standby, steam supply to steam driven auxiliary (seedwater pump was inclated Caused by attempt to repair cap to body leak on mainsteam check valve Valve repaired & steam supply to pump restored CARTWRIOHT, W R Vitginia Electric & Power Co 80/07/02 2pp
- 8007070374 Forwards LER 80-029/017-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/07/02 1p
- --B007070379 LER E0-029/01T-0 on B00624, during Mode 3 aperation, power operated relief valve RCV-2456 opened inadvertently & failed to reclose Caused by rocked bearing in valve actuator Upstream MOV-2335 closed to terminate relief flow CARTWRIGHT, W R Virginia Electric & Power Co B0/07/02 2pp
- B00/090296 Forwards LER 80-027/03L-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/07/02 ip
- --8007070304 LER BO-027/OJL-O on 800620, w/unit at startup condition, one main steam flow transmitter found insperable Caused by loose connection, resulting from stripped strew Borew replaced, connection tightened & transmitter callbr GARTHRIGHT, W R Virginia Electric & Power Co 80/07/02 ip
- B007070308 Forwards LER 80-022/03L-0 CARTNRIGHT.W R Virginia Electric & Power Co 80/07/02 1p
- --B007090312 LER HO-()22/03L-0 on B00609, w/plant in Mode 3, containment sump flow indicator, FTO-DA-215, stopped measuring flow correctly Caused by clugged strainer located within instrument, preventing proper rotation of flow sensor CARTWRIGHT, W R Virginia Electric & Power Co B0/07/02 2pp
- 8007090317 Forwards tER 80-026/03-0 CARTWHIGHT, W. R. Virginia Electric & Power Co. 80/07/02 1p
- --B007090423 LER 80-026/03L-0 on 8006F0,w/reactor in Mode 2 & as part 9 2-BU-31.channel F-497 was observed to require adjustment in order to lower feedwater flow indication Caused by zero shift in multiplier-divider card of feedwater thannel F-497 CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/07/02 Rpp
- 8007090335 Forwards LER 80-014/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/07/02 in
- --8007090342 LER 80-014/031-0 on 800606, emergency diesel generator removed from svc for replacement of transformer Caused by failed transformer Transformer & relay replaced CARTWRIGHT.W R Virginia Electric & Power Lo 80/07/02 2pp
- 8007210092 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FBAR Caused by use of incorrect sys vol Roview will be performed to identify a mallyze add accidents

 BYLVIA.B R Virginia Electric & Power Co 80/07/02 App
- 8007140209 Forwards LER 80-030/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/07/07 1p
- --8007140223 LER BU-030/03L O an 800424-25 on three accasions rod position indication disagreed more than 12 steps between individual position & demand position Caused by instrument drift for each event-sys realigned & returned to svc CARTWRIGHT.W R Virginia Electric & Power Co 80/07/07 2pp ,
- 8007150808 Forwards LER 80-023/03L-0 CARTHRIGHT: H R Virginia Electric & Power Co 80/07/07 ip
- --B007150815 LFR BU-023/03L O on B00610.A LCCS subsys was rendered inoperable by isolation of A LHGI pump Guesed by need to repair leaking water fitting Seal water fittings reinstalled to pump returned to svc CARTWRIGHT.W R Virginia Electric & Power Co B0/07/07 2pp

- 8007150810 Forwards LER 80-031/01T-0 CARTHRIGHT W R Virginia Electric & Power Co 80/07/07 ip
- --BOOTISOBIT LEP BO-ORI/OIT-O on BOOS26, while performing channel calibrs on pressurizer press protection channels. Channels 1,2 & 3 eaund to indicate values below actual RCD pressure Caused by pressure set of bourdon tube within transmitters CARTHRICHT.W R Virginia Electric & Power Co. 80/07/07 Rep.
- 8007110300 RO 80-55/DIT-O during review of FSAR safety analyses for boron dilution accident potential nonconservatism in cold shutdown analysis determined Cause unknown Accident analysis review initiated

 * Virginia Electric & Power Co. 80/07/11 1p
- 9007220601 Forwards LER 80-012/03L-0 CARTHRIGHT, H R Virginia Electric & Power Co 80/07/17 lp
- --B007220611 LER B0-012/03L-0 on B00018 while in Hode 2:control rod demand position indication noted 19 steps higher than associated rod position indication Caused by drift of rod position indicator channel Channel recalibr CARTURIGHTOUR Virginia Electric & Power Co B0/07/17 Rpp
- V Operator Examinations
- BD0717034B Forwards revised. "Licensed Operator Requalification frogram." in response to NRC 80032B request All training instructors are required to participate in program to maintain proficiency SYLVIA.B R Virginia Electric & Power Co 80/07/15 Ip
- --8007170350 Revised, "Licensed Operator Requalification Program "

 Virginia Electric & Power Co 80/07/31 llpp
- BOO7250379 Informs of completion of full power requirements of GER. Section 10-2 & TMI action plan. NUREG-0660, Items II B 4 All licensed operators received training for degraded core conditions SYLVIA.B R Virginia Electric & Power Co BO/07/24 Ip
- DOCKET 50-340 SEABROOM NUCLEAR STATION, UNIT 1
- Q Adjudicatory correspondence
- BO07310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/23 29pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8007030239 Not191(ation of 800702 meeting w/BWR licensing review group in Betheada, MD to discuss consensus position on reactor svc bldg oppn issue WILSON, J N Licensing Branch 1 80/06/18 9pp
- BD07010297 Supmary of B00613 meeting w/utils.KMC, Inc. GE. Nochtel. BtM & Sargent & Lundy in Bethesda.MD re consensus positions on reactor swc bldg & isolation cooling sys bldg open issues from La Salle decket Status repts entl
 HILSON.J N Assistant Director for Licensing 80/06/19 46pp
- 8007230001 Forwards statement of golicy re requirements to be met for current DL applications as derived from NUREG-0640 & found in NUREG-0694 EISENHUT, D Q Division of Licensing 80/06/26 2pp
- 8007170339 Notification of rescheduling of 800702 meeting w/BWR licensing review group in Betherda.MD to discuss consensus positions on Reactor Sys Branch open lesues Meeting rescheduled for 800709 HILBON, J N Assistant Director for Licensing 80/07/03 Ip
- --8007170347 Notification of 800722 meeting w/UHP licensing teriew group in Bethesda.HD to discuss TMI issues required for QL issuance MILSON.J N Assistant Director for Licensing 80/07/03, lp
- --8007170351 Notification of 800724 meeting w/BWR licensing review group in Bethesda. MD to introduce BWR licensing review group t present consensus positions for Power Byp Branch, Containment Sys Branch & Equipment Qualification Branch by Branch & Equipment Qualification Branch WILSON. J N Assistant Director for Licensing 80/07/03 9pp

- COOTIGOROT Forwards FOAR function 5 d tafs COLDERT.N F Detroit Edison to 60/07/08 ip
- --B007160674 Responds to //idi7 ltr to fracture toughness requirements.
 Tests on matts of reactor coolent pressure boundary comply
 W/App O Ambiguity re calibriqualification & record retention
 functions will be clarified
 MINDOUE: R B Office of Standards Development, Director 70/02/14
- --BOOTIAD709 Revision 3 to nurveillance test program for 25t-inch Mar vesset e General Electric Co. 70/02/28 30pp
- GOO7230133 Notification of BOO725 meeting w/BMR Licensing Review Order in Bethoeds.MD to discuss concensus positions of BMR Licensing Review Order on ICBB open issues HILBON,J N Licensing Branch (100/07/16 10pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 100537 membrandum & order containing decisions on UCB 780802 petition for reconsideration of 780413 momorandum & order UCB 7/1104 petition enught action to fire protection for electrical collect EIDEMINT, D.O. Division of ticonstag 80/06/25 199pp
- B007100043 Joint nutice of CP Woodbad appearance & Ri Dlack withdrawal from proceeding Contificate of Not encl WOODBEAD C P Hearing Branch 3 BLACK, R t Hearing Branch 1, B0/07/03 Upp
- H General correspondence
- 8007020183 Requests consideration of having Atomic Energy Council of Taluan visit facility on 800038:-9 Gouncil Interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR.J D. Assistant Director for International Cooperation 80/09/13: 3pp
- 8007270005 Responds to 800.028 itr from Lawson.H() school students to President Cartor re adoquacy of qualifications of personnel designing plant Cartein design activities failed to mast NRC requirements (Itil corrective actions under review DIRCKS.H J Office of the Executive Director for Operations 500.08330 in
- P Operating license stage doruments & correspondence
- BOO7230020 Bummary of (100207 merting w/Mark | owners group in Bethesda, MD re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMED, C Y Plant Bystems Branch HO/02/21 Tiep
- G. Inspection reports. IE Bulletine & correspondence
- 8007140510 Forwards IE Bullstin HO-13, "Cracking in Core Spray Spargars" No written response required REPPLER, J.O. Region 3: Chicago, Office of the Director BO/05/12
- 8007140357 Forwards IC Bullstin 80-13, "Cracking in Core Opray

 Beatgara "No written response required

 KEPPLER, J O Region 3, Chicago, Office of the Director 80/07/12
- BDD7010107 Forwards IR Into Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written responso required, KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/29, in
- 8007020081 Ack receipt of 800513 ltr informing NNC of steps taken to correct violation noted in IE Insp Rupt 80-341/80-02 FIDRELLI, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 80704/09 ip
- 8007220198 Forwards 1E Info Notice 80-26. "Evaluation of Contractor DA Programs" No written response required. KEPLEN.J G Region 3. Chirago, Office of the Director 80/06/10 to

- BOO714033B Forwards IE Bulletin 80~14, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEFPLER, J Q Region 3, Chicago: Office of the Director 80/06/12
- 8007280644 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/06/13
- 8007230059 Forwards IE Insp Rept 50-341/80-06 on 800430,0501.02 & 28-30 No noncompliance noted FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/17 2pp
- -8007230066 IE Insp Rept 50-34i/80-06 on 800430,050i,02 & 28-30 No noncompliance noted Hajor areas inspected action on previous insp findings.organization & design change control KNOP, R C , BARRETT, P A Region 3. Chicago, Office of the Director 80/06/16 6pp
- 8007020559 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/20
- BOO7170486 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Porsonnal" No written response required MEPPLER, J. G. Region 3, Chicago, Office of the Director BO/06/24 in
- BOO7140470 Ack receipt of 800607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-341/79-25 FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/06/23 lp
- --80071404B1 Responds to NKC B00324 ltr re violations noted in IE Insp. Rept 50-341/77-25 Corrective actions controlling procedure to notify GC personnel of needed pipe weld repair has been HINES, E Detroit Edison Co 80/06/09 Bpp
- 8007230323 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosamount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dubput Codes " Written response required IE Circular 80-16 aiso encl No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27
- B007140425 Forwards "Summary Rept Number EF2-49,457 of Response to IE Bulletin B0-08," in response to IE Bulletin B0-08, "Exam of Containment Liner Penetration Helds "
 HINES,E Datroit Edison Co 80/07/07 9pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007070095 Ack receipt of 800605 ltr ro final deficiency rept on Agastat relay base problem FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/17 1p
- --8007070098 Interim deficiency rept re Agastat relay base problem Subsequent investigation revealed that relay base is also used in five add1 OE panels Final rept will be forwarded by 800806 FAHRNER, W.J. Detroit Edison Co. 80/06/05 in
- B00717049B Ack receipt of 800613 final deficiency rept re defective Westinghouse switches Final rept enci FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/07/01 ip
- 8007210128 Ack receipt of 800512 interim deficiency rept re nonseismic equipment installed over seismic FIGRELLI, G Region S. Chicago, Reactor Construction & Engineering Support Branch 80/07/01 ip
- ----8007210136 Interim deficiency rept re nonseismic equipment installed over seismic Affected equipment includes pieces of heating, ventilation & air conditioning ducts in reactor & auxiliary bldgs Final rept to be submitted by 800915 FAHRNER, W J Detroit Edison Co 80/06/12 ip
- B007140326 Final deficiency rept re damaged penetration assemblies at facility Problem assembly ongineering evaluation completed & changes made to penetration X-17 Bellows life not to be reduced below design specs Bellows have been leak tested FAHRNER, W J Detroit Edison Co 80/07/02 ip

- 8007170406 Final deficiency rept re problems w/terminations to receptacies in main control roum Panels 601,602 & 603 GE investigation complete Problems caused by improper crimping Puil-tests will be performed to assure satisfactory crimps FAHRNER.W J Detroit Edison Co 80/07/03 2pp
- B007210008 Ack receipt of B00610 final deficiency rept re seismic Category I instrumentation 4 control testing FIDRELLI, G Region 3. Chicago, Reacter Construction & Engineering Bupport Branch B0/07703 ip
- 8007220545 Interim deficiency rept re notification by Comsip of pump malfunction on similar containment gas monitoring eys Caused by deadheading resulting in excessive pressure Vendor has agreed to provide kit for adding by-pass FAHRNER, H J Detroit Edison Co 80/07/10 ip
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 itr to all power reactor licensess in response to 800529 ltr re emergency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Granch 5 80/07/07 2pp
- 8007010334 Forwards comments on proposed rule iOCFR50 re fire protection program for nuclear plants Proposed rule is far too vague for effective implementation, lacking definitions in particular Rule 1s subj to individual interpretation ODDDNIN.C Portland General Electric Co 80/06/27 iOpp
- 8007090300 Forwards draft App 1-B, "Description of Public Notification Bys for Trojon Nuclear Plant," for radiological emergency plan procedures manual Review of adequacy of sirens in sys requested Draft & draumas aveilable in Central Files only GOODHIN,C Portiand General Electric Co 80/07/01 29p
- 8007140527 Nutifiration of 800728 meeting w/util in Prescott. OR to discuss results of NRC emergency proparadness review team analysis of util 800516 draft radiological emergency response plan & to conduct site tour TRAMMELL. C M Operating Reactors Branch 3 80/07/07 2pp
- O Adjudicatory correspondence
- 8007100051 Discusses licensee 800519 rept re inadequately connected wall & forwards DJ Broehl & WH White affidavits in response to 800602 order issued in control bidg proceeding JOHNBON R W Portland General Electric Co 80/06/16 2pp
- --8007100058 Affidavit re LER 60-007/017-0, describing cause of auxiliary bldg wall inadequate connection & extent of deficiencies at top-of-wall interfaces Identifies manner & schedule of corrective action Description of deficiency encl BROEHL, B J Portland General Electric Co 80/06/16 7pp
- --B007i00062 Affidavit describing limited significance of auxiliary bldg wall connection deficiency as related to structural adequacy of complex before 2, after completion of corrective actions Certificate of Svc encl Related correspondence HHITE.W H Bechtel Power Corp (subs of Bechtel Corp) WHITE.W H Purtland general Electric Co B0/06/16 7pp
- 8007310243 Forwards Commission 80052/ memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT,D O Division of Licensing 80/06/23 89pp
- 8007020594 Affidavit in response to IE Info Natice 80-21 re control blidg proceeding Licensee will conduct systematic insp program for safuty-related plectrical equipment supports & anchorages, within 12 months BROEML, D J Portiand General Flectric Co 80/06/27 App
- BOO7100039 Forwards iirensee 800628 itr to Region 5 documenting resolution of wall problem re control bldg proceeding Util program will constitute full compliance w/Region 5 800417 itr re action requirement Certificate of Svc encl JOHNSON, R H Portland General Electric Co 80/06/30 4pp
- 8007300333 Forwards list of requests for design changes re mod program in "Rept on Design Mods for Control Bidg," PGE-1020 ASLB will be informed of activities pur 790330 prehearing conference Certificate of Svc enci Reinfed correspondence MCCARREL(S F Portland General Electric Co 80/07/03 4pp

Į

- 8007300357 Notice of appearance & substitution of counsel in proposed amend for storage pool mod proceeding Certificate of Svc encl
 - DSTRANDER, F W Gregon, State of 80/07/03 2pp
- 8007100029 Forwards R Clark 800703 itr to util transmitting IE Bulletin 80-11 & seeking util response to Items 2 b & 3 re masonry wall design problem Action requirements are no different from actions stated in control bldg proceeding record GRAY.J R Hearing Branch 1 80/07/07 2pp
- --8007100034 Transmits IE Sulletin 80-11, requesting response to Items 2 b & 3 re design criteria for walls & lung-turn confirmatory test program w/associated completion schedule Suggests specific items for test program CLARK, R A Licensing Branch 3 80/07/03 3pp
- 8007290789 Initial decision modifying GL immediately Exceptions may be filed within 10 days, briefs within 30 days & supporting or objecting briefs within 30 days of original briefs Decision shall constitute final action within 45 days (MCCOLLON, KA, PAYTON, HC, MILLER, HE Atomic Safety and Licensing Soard Panel 60/07/11 80pp
- 8007280503 Forwards State of OR Dept of Energy rept re util issues related to Mount St Helens Based on rept. Energy Facility Siting Council denied petitions to reveke site certificate DIXON.B Oregon, State of 80/07/14 18pp
- 9007250428 Forwards NRC motions for extension of time to file exceptions to ASLB 800711 initial decision & other related requests NRC will issue license amend per ASLD order issued w/initial decision due to desire to restore seismic margins GRAY, J R Hearing Branch 1 80/07/23 2pp
- ~-8007250493 Notion for 10-day extension to file exceptions to A BO0711 initial decision authorizing control bldg mods.NRC position re taking exceptions is dependent upon ASLB action on each motion for clarification Contificate of Syc encl. CRAY.JR Hearing Branch 1 80/07/23 App to AELB
- --8007290437 Motion for clarification of ASLB 8007(1 initial decision authorizing mods of control bldg Requests ASLB intent reCondition 2 C 11 concerning restoration of originally intended design margins Certificate of 8vc encl
 GRAY, J R Hearing Branch 1 80/07/23 7pp
- 3007300481 Forwards motion for reconsideration of initial decision, mamorandum of points & authorities in support of motion for reconsideration & proposed findings of fact & conclusions of law re design mode for control bidg OBTRANDER, F. W. Oregon, State of 80/07/23 ip
- -8007300490 Motion for reconsideration of ASLB 800711 initial decision Decision does not provide ASLB findings.conclusions & rulings on mati issues in State of DR 800519 proposed findings of Pact & conclusions of law USTRANDER, F W Oregon, State of 80/07/23 1p
- -8007300494 Memorandum of points & authorities in support of motion for reconsideration of initial ducision Decision does not discuss issues raised in State of OR proposed findings of fact & conclusions of law Certificate of Svc enc!

 OSTRANDER, F W Oregon, State of 80/07/23 4pp
- 8007300500 Proposed findings of fact & conclusions of law re design mods for control bldg If ASLB will include proposed suppls & additions in initial decision, appealant will concur in licenses proposed findings & conclusions OBTRANDER: F W Oregon, Baste of 80/07/23 5pp
- B007300506 Memorandum of points & authorities in support of State of OR proposed findings of fact & conclusions of law Findings & conditions proposed by appellant will increase likelihood that mods will meet seismic safety atds
 OSTRANDER.F W Oregon, State of 80/07/23 4pp
- 17300408 Order granting satematon of date for filing exceptions to ASLE 800711 initial decision to mode to control bldg lacutive Legal Director requested to remind staff of Pacesaity for compliance w/App A requirements OHPKING.E A Atomic Safety and Licensing Board Panel. 80/07/24
- 7310160 Order authorizing ASLB to act on merits of State of DR otion for reconsideration of ASLB 800711 initial decision tats of DR supporting brief on exceptions is toiled until 6 days after ASLB rules on motion
 IBHOP, C J Atomic Safety and Licensing Appeal Panel 80/07/28

- H General correspondence
- 8007300364 Advises of withdrawl as counsel for State of OR in matters re facility Requests that name be deleted from NRC general sec 1,3st for doctet & replaced w/name of ful distrander BANDVIKAR M Gregon. State of 80/07/03 ip
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D G Division of Licensing 80/06/11 62pp
- 8007250702 Forwards plant status re masonry wall problem & activities re Mount St Helens Meeting has been scheduled in Dethesda MD for 800666 to discuss NRC position re acceptability of plant startup NOVAK.T M Assistant Director for Operating Reactors 80/04/13
- 8007020021 Notification of 800619 meeting w/util in Bethesde, MD to discuss status of resolution of IE immediate action ltr redevolute heavy weight block walls & consideration of walls not covered by ltr TRANHELL.C Operating Reactors Branch 3 80/06/17 2pp
- 8007020288 Forwards safety evaluation re postulated fuel handling accident inside containment Specific equipment meds or revised refueling procedures are required to assure potential consequences are within guidelines CLARK.R A Operating Reactors Branch 3 80/06/17 3pp
- --8007020290 Safety evaluation re postulated fuel handling accident inside containment

 R Operating Reactors Branch 3 80/05/17 Spp
- --8007020294 Suitable Tech Space for installation of charcoal filters on purge exhaust sys
 # Operating Reactors Branch 3 80/06/17 Rep
- ECO7010418 Forwards list of design change requests for mod program described in PGE-1020. "Rept on Design Mods for Trojan Control Eldg " Piping support mods will not reduce shear capacity of major walls by more than 1% MCCARRELS F Portland Gameral Electric Co 80/06/23 App
- 8007160365 Forwards Amend 45 to License NPF-1. safety evaluation & notice of issuance & availability
 CLARK, R A Operating Reactors Branch 3 60/06/27 4pp.
- --B007160372 Amend 45 to License NPF-1, allowing insertion into reactor core of two fuel assemblies each containing may of three dummy stainless steel rods, for Cycle 3 operation . CLARK-R A Operating Reactors Branch 3 B0/06/27 Rpp
- --8007160376 Safety evaluation supporting Amend 48 to License NPF-1 * Operating Reacters Branch 3 80/06/27 7pp
- --BO07160379 Notice of issuance & availability of Amend 45 to License CLARK, R A Operating Reactors Branch 3 80/06/27, 2pp
- 8007170390 Summarizes Div of Power Supply & Reliability views re electric power sys reliability impacts in Pacific Northwest & northern CA should facility outage extend through Sept 1980, Cenpration imadequate for CA Recommends Jul raview MEINER, R & Energy, Dept. of 60/06/27 3pp
- 8007070273 Submits revised criteria to be used in analysis of out-of-plane behavior of heavyweight double wythe masonry walls Includes all masonry walls having safety significance All masonry walls will comply w/revised criteria by 801031, DROCHL.D J Portland General Electric Co 80/06/28 22pp
- BOO7070340 Responds to 800314 request for add1 info re adequacy of station electric distribution sys voltages Responses to specific questions & plant voltage profile tables encl ODODHIN.C Portland General Electric Co BO/06/30 7pp.
- B007170472 Forwards corrected Page 3/4 i-24 to Tech Spec submitted for Amend 44 to License NPF-1 CLARK.R A Operating Reactors Branch 3 80/06/30 3pp
- --8007170483 Tech Spst 3 | 3 5 for reactivity control sys * Portland General Electric Co 80/06/30 2pp

- BOO7090227 Forwards add1 info re auxiliary feedwater sys per 800514 request GOODHIN.C Portland General Electric Co 80/07/01 10pp
- GOODMIN'C LOLETBUG CAMBERS STAFFLIF CO. BOACALOT. 1966
- 8007210123 Forwards evaluation of control rod guide thimble wear in facilities designed by Westinghouse Based on review, issue is resolved CLARK, R. A. Operating Reactors Branch 3 80/07/01 5pp
- B007070300 Forwards License Change Application 62 requesting amend to License NPF-1 Class 111 Amend fee & Certificate of Svc encl QDODWIN, C Portland General Electric Co 60/07/02 2pp
- --8007070307 License Change Application 62 requesting amend to License NPF-I to incorporate mods in reactor coolant pump breaker position inputs to reactor trig logic Proposed revisions to Tech Spec Pages 3/4 3-2.-4 & -7 encl
 QDDDWIN.C Portland General Electric Co 80/07/02 6pp
- 8007230001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance £18ENHUT,D O Division of Licensing 80/07/02 69pp
- BOO7090360 Submits clarification of BOO616 add1 info re containment purge sys, submitted in response to BOO318 request High radiation signal can be overridden manually by rausing setpoint or holding reset on radiation monitors panel, GOODWIN.C Portland General Electric Co 80/07/03 2pp
- 8007160608 Submits clarifying info re License Change Application 62 re modifying logic to reactor coalant pump trip breaker position trip signal Upon approval, facility will no longer be vulnerable to reactor trips from loss of vital bus GDODHIN.C Portland General Electric Co BO/07/07 4pp
- 8007240304 Advises of NRC reorganization on 800420 which resulted in number of changes in ofe titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08 200
- 8007180441 Forwards Amend 46 to License NPF-1, safety evaluation & notice of issuance & availability Related correspondence CLARK.R A Degrating Reactors Branch 3 80/07/10 3pp
- --- 8007180448 Amend 46 to License NPF-1, changing Tech Specs by deleting from reactor protection sys, reactor trip derived from opening of any single reactor coolant pump circuit breaker above 36% power Related correspondence CLANK,R A Operating Reactors Branch 3 80/07/10 App
- --B0071B0453 Bafety evaluation supporting Amend 46 to License NPF-1 * Operating Reactors Branch 3 B0/07/10 3pp
- --BOO7180454 Notice of issuance & availability of Amond 46 to License NPF-1 CLARKAR A Operating Reactors Branch 3 BO/07/10 2pp
- B007170424 Forwards interim rept describing results of nondestructive examination of U-bends removed from steam generator D Axial cracks were detected in cold-leg transition.at or near extrados surface QDODNIN.C Portiand General Electric Co B0/07/11 8pp
- 8007300047 Forwards 800617-19 trip rept to Portland, OR & Mount St Halens re effect of volcanic activity & related phonomona FEMA bullatin re volcanic hazards encl LEFEVRE.H E. JUSTUG.P S Geosciences Branch 80/07/14 2ipp
- B007220570 Forwards list of requests for design changes associated w/ mod program described in PQE-1020 re design mods for control bldg Mods involve piping supports necessary to qualify pipe sys for response spectra. Certificate of Boy oncl
 BROCHL.D J Portland General Electric Co 80/07/17 4pp
- 8007250474 Forwards License Change Application 63 requesting amend to License NPF-1 Certificate of Svc enci CDCDMIN.C Portland General Electric Co 80/07/22 3pp
- ~~8007250481 License Change Application 63 requesting amend to License NPF-1, deleting portions of ETS revered by EPA controls, per ASLAB decision re jurisdictional control for establishing water quality layels & monitoring requirements * Portland General Electric Co 80/07/22 59pp

- BOO730038/ Forwards supplemental info re auxiliary foodwater sys.in response to Items B 2 % C & in enci to NRC 800914 ltr Bubmittal completes util responses CODDMIN.C Partland General Electric Co 80/07/25 8pp
- @ Inspection reports. IE Bulletins & correspondence
- BOO7030233 Bubmits addl response to 1E Bullbtin 79-066 Licensed operator assigned to control room is being replaced by Unlicensed operator trained in emergency pracedures until plant is returned to operation after Spring 1980 outlage BRDEHL.D J Portland General Flectric Co 80/04/16 2pp
- BOO7280199 Forwards response to IE Bulletin /9~018, "Chviron Qualification of Class IE Equipment" Includes revised master list of engineered safety feature systemidence of environ qualifications & list of outstanding items W/o enri GDODWIN.C Portland General Electric Co. 80/09/19 2pp
- 8007020234 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required ENGELMENR H Region 5, San Francisco, Office of the Director 80070728 Ip
- BD07310472 Forwards response to IF Bulletin BO~03 re loss of charconl from tray adsurber cells investigations conducted found no evidence of carbon cell fulluros GD0DHIN.C Portland despend Electric Co 80/06/04 App
- BOOTHS0190 Forwards response to II Bulletin BO-12, "Docay Heat Removal Bys Operability "Instauces of temporary detay heat removal degradation for short periods have been reported Procedure developed to provide backup tore heat removal WACS open GODDHIN, C Portland General Electric Co 80/06/09 4pp
- 8007300296 Responds to IE Bulletin 80-05 re vacuum damage to chemical vol control sys tanks All tanks w/active vacuum protection devices have backup Tunks w/passive vacuum protection viil be provided w/locking device & engraved wanning GDDBHIN.C Portland General Electric Co 80/06/09 6pp
- 8007220241 Forwards IV Info Natice 80-26. "Evaluation of Contractor GA Programs" No written response required ENGFLKEN.R H. Region 5. San Francisco. Office of the Director 90.004.00
- 80071805(8 Recommends that and 1 III Info Notice BO-21, "Anchorage & Support of Safety Related Flectrical Equipment," be distributed to appropriate Noords & parties EISLANUT, D O Division of Liconsing 80706/12 ,3pp
- --B00718053B Discusses IE into Notice 80-31. "Anchorage & Support of Support Party-Related Electrical Equipment " Written reopense is necessary since deficiencies found at other plants may have bearing on solomic qualification CLARK, R.A. Operating Reactors Branch J. 80/05/12. Ip
- 8007250360 Responds to IR Bulletin 79-18, "Audibility Problem Encountered on Evacuation of Personnel from High Notes Areas "Existing bys will be replaced w/Amproved in-plant communication network interim measures taken 9000MHM.C Portland General Electric Co 80/06/1/ 2pp
- 8007030018 forwards IE Bulletin 80-15, "Passible toss of Emergency Notification Sys (ENG) W/Loss of Offsits Power " Written response required ENGELKEN, R M. Region 5, Sen Francisco. Office of the Director 80/06/18 is
- 8007020470 Forwards IE Circular 40-13. "Luss of Reactor Contant Pump Couling & Natural Circulation Couldown "No written response required ENGELKEN, R. H. Region 5. Sun francisco. Office of the Director 80/06/20 ip
- 8007180270 Forwards IE Circular 80 14, "Radioartive Custamination of Plant Demineralized Water bys & Resultant Internal Contamination of Personaul " No written response required ENGFLKEN.R H Region 5, San francisco. Office of the f 80/06/24 1p
- BOO7290889 Follows up 7912'11 response Qualification of Class If Equipment Qualification of ASCO Solenoid Valvevalves are being replaced QOODWIN.C

- 8007240309 Forwards IE Insp Rept 50-344/80-08 on 800408-11,14-18 & OSO6-07 No noncompliance noted SPENCER G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/06/26 2pp
- --8007240314 IE Insp Rept 50-344/80-08 on 800408-11, 14-18 & 0504-09 No noncompliance noted Hajor areas inspected maint activities repressurizer code safety valves & preparations for control bldg wail mods HAIST.D P. ELIN.J O. Region 5, San Francisco, Office of the Director DODDS.R T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/06/26 11pp
- 8007010177 Ack receipt of 800604 ltr informing NRC of steps taken to correct violations noted in 800512 notice of violation NRBBERHAUS, L R Region 5. San Francisco, Safeguards Branch 80706277 to
- B007230390 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters WiEther A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required. ENGELKEN, R H Region 5. San Francisco, Office of the Director B0/06/27 ip
- 3007090327 Forwards response to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for uncontrolled releases Primary plant interfaces between radioactive & nonradioactive sys examined for cross-contamination GDODHIN, C fortland General Electric Co 80/07/01 5pp
- 1007150106 Ack receipt of 800612 ltr informing NRC of steps taken to correct violation noted in IE lnsp Rept 50-344/80-07 on 800414-18
 BOOK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 807/07/02 ip
- -8007150120 Responds to NRC 800523 ltr re violation noted in IE Insp Rept 90-344/80-07 on 800414-18 Corrective actions redwaste program will be closely monitored to insure compliance w/ regulations & procedures GDODWIN.C Portland General Electric Co 80/06/12 2pp
- -8007i50i24 Forwards IE Insp Rept 50-344/80-07 on 8004i4-i8 & notice of violation BDDM.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/05/23 2pp
- 8007190126 Notice of violation from insp on 800414-18 * Region 5, San Francisco, Office of the Director, 80/05/22 ip
- 8007150130 IE lnsp Rept 50-344/80-07 on 800414-19 Noncompliance noted radiation effluent exceeded Tech Spec limit & waste storage containers not labeled FiGH.R F. WENSLAWAKI.F A Region 5, San Francisco. Office of the Director BOOK.H E Region 5, San Francisco. Fuel Facility & Materials Safety Branch 80/05/82 ip
- 07180482 Requests written response to Items R b & 3 of IE Bulletin 80-11 within 70 days Design criteria for single wythe & composite walls for consideration of all in-plane/out-ofplane loads should be provided & fully justified ELARK/R A Operating Reactors Granch 3 80/07/03 3pp
- 07000293 Forwards IE Insp Rept 50-344/80-12 on 800514-14 No loncompliance noted REMS-J L. Region 5, San Francisco. Reactor Operations Nuclear upport Branch 80/07/08 2pp
- 1007300295 IE Insp Rept 50-344/80-12 on 600514-16 No noncompliance noted Major areas inspected response to IE bulletine & circulars & following on previous insp items
 JOHNSON,P H Region 5. San Francisco. Office of the Director STERNBERS,D M Region 5. San Francisco. Reactor Operations Nuclear Support Branch 60/07/02 4pp
- /160661 Forwards "Preliminry Rept op Trojan EDC-2 Fuel Examination "
 opt documents results of Fnd-nf Cycle 2 (EDC-2) fuel insp
 RDEHL,D J Portland General Electric Co 60/07/09 7pp.
- 7300518 Forwards IE Insp Rept 30-344/80-13 on 800610-11 No oncompliance noted REMS, J. L. Region B. Bab Francisco, Reactor Operations Nuclear ipport Branch 80/07/09 2pp

- --B007300525 JE Insp Rept 50-344/B0-i3 on 800610-i1 No noncompliance noted Major areas inspected apecial announced insp of circumstances surrounding & corrective actions taken re LERs 80-07 & 79-15 HORRILLP J. Region 5. San Francisco. Office of the Director STERNUERO. DM Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/07 App
- 8007250413 Responds to IE Bulletin 79-13 "insp of Feedwater Sys Plping " Exam of feedwater & surillary feedwater piping revealed no detrimental conditions Responses to remaining action items in IE bulletin submitted on 790719 CHRIBTENSEN 8 . LENTSCH, J W . BROEHL. D J Portland General Electric Co 80/07/18 1p
- R Periodic operating reports & related correspondence
- 8007140312 Forwards monthly operating rept for June 1980 YUNDT, C.P. Portland General Electric Co. 80/07/01 ip
- --8807140315 Monthly operating ropt for June 1980 BAIR.0 D Portland General Electric Co 80/07/01 5pp
- 8007170862 Forwards "Mount St Helens Brucekly Rept 800602-15 " LENTSCHJ N Portland Ogneral Electric Co 80/07/01 1p
- --8007170568 "Mount St Helens Diweekly Rept 800602-15 " One oversize drawing avertable in Central Files only # Foundation Sciences, Inc 80/07/01 24pp
- B Reportable occurrences, LERs & related correspondence
- 8007070070 PNO-V-BD-052 on 800619, 156 drums of low level radwaste received Examination of shipment determined that one drum was leaking No significant radioactive contamination found State of HA burial permit cancelled THOMAS, R D. Region 5. Ban Francisco, Office of the Director 80/06/19 ip
- GOO7080419 Forwards LER GO-010/03L-0
 YUNDT.C P Portland General Electric Co 80/05/27 2pp
- --B0070B0420 LER 80-010/03L-0 on 800929, foilowing refusiing.RCS boron concentration dropped below Tech Specs Caused by personnel error in calculation resulting in insufficient boric acid being added to RCS More boric acid added PERRY, J C Portland Goneral Electric Co 80/04/27 ip
- BOO7:30581 Followup rept re residual chlorine & pH reading out of spec for approx 11 minutes Highest value of residual chlorine measured was 4 ppm://owest.pH measurement was 4 5 Caused by Operator error YUNDT.C P Portland Genoral Electric Co 80/07/09 ip
- 8007150820 Forwards LER 80-011/03L-0 YUNDT, C P Portiand General Electric Co 80/07/09 2pp.
- --B007150826 LER B0-011/031-0 on B00611, during scheduled meint, both trains of emergency generators were out of svc at same time Caused by personnel error Equalizing charge terminated & battery returned to Svc PERRY.J C Portland General Electric Co 80/07/09 1p
- 8007230203 PNO-V-80-056 on 80070B offluent water whigh chloring & iow pH outside Tech Spec limits was released to Columbia River Caused by operational error in addition of chiorino to evo mator
 FISH-R Region 5, San Francisco, Office of the Director 80/07/09
 2pp
- 8007280648 RD on 800709, residual chlorine & pH readings were out of spoc for approx 11 minutes Highest residual chlorine measurement was 4ppm Lowest pH measurement was 4 5 Caused by operator error
 VUNDT.C P Portiand General Electric Co 80/07/09 1p
- 8007180347 Notifies that B00417 immediate action items to LER 79-15 have been completed Requests clearance to resume power operations
 BROEH..D J Portland General Clectric Co 60/07/12 ip

1

1

9907280545 Forwards LER 80-012/03L-0 YUNDT,C P Portland General Electric Co 80/07/16 2pp

- --B007280553 LER 80-012/03L-0 on B00701, during engineering walkdown of piping, three seismic restraints were found missing from steam drain line on steam turbine-driven auxiliary feedwater pump Caused by Dversight during const PERRY, J C Portland General Electric Co 80/07/16 ip
- 8007280563 Forwards RO re plant svc water effluent ph exceeding ETS lights on 800708 VUNDT,C P Portland General Electric Co 80/07/16 1p
- --B007280573 RO on B00708, during chlorination of svc water systmore chlorine added than required resulting in exceeding of ph & chlorine limits of ETS Caused by personnel error Chlorination stopped & dilution flow increased * Portland General Electric Co B0/07/16 ip
- 8007310403 Advises that all mods to masonry walls required prior to power operation resumption completed on 800712 NRC 800417 ltr approving licensee action encl Power operation resumed 800720 JORNSON, R W Portland General Electric Co 80/07/21 ip
- --8007310437 Advises that licensee action to assure acceptable structural properties of masonry walls has satisfied terms of NRC 800417 immediate action ltr Certificate of Svc encl ENDELMENR H Region 5. Ban Francisco, Office of the Director 80/07/12 3pp
- 8007290554 Advises that all actions committed to in util 800428 ltr re resumption of power operations now completed Summary of results for wall mode re heavyweight doubleweight wither std weight double withe & single withe walls entl BRDEHLD J Portland General Electric Co 80/07/25 2pp
- MCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007090254 Forwards info re fire protection sys mods scheduled for completion prior to entering Mode 4 after current outage, to aid in evaluation of request for revision to License Gondition 2t(3)h Lists commitments for interim surveillance CROMSER P Toledo Edison Co 80/07/01 5pp
- 80072300B3 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices. NRC wishes to interview security most personnel at facility EISENHUT, D G Division of Licensing 80/07/11 2pp
- 8007280107 Ack receipt of 800515 ltr submitting revision to fire hazards analysis rept Proposed alternative to install overhead Sprinkler sys is acceptable REID.R W Operating Reactors Branch 4 80/07/17 2pp.

9 Adjudicatory correspondence

- 8007020310 Discusses 800328 ltr proposal for meeting requirements of NRC 800305 order to modify license, Section VII 2. Commitments referenced in 791206 draft ANS 3 1 are acceptable, w/ exception of Section 5 2 1 8

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/31
- 8007310243 Forwards Commission 800527 mBmorandum & order containing decisions on UCS 780502 petataon for reconsideration of 780413 memorandum & order UCS 771104 petation sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/04/25 89pp

H Ceneral correspondence

- 8007290048 Responds to inquiry re flooding of site Natural phenomena considered in plant design & const Access to & from plant during flood considered in emergency plan In flood emergency rail boat or DKW transportation will be utilized KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/05/22 2pp
- M Antitrust correspondence
- 8007140231 Forwards Director of Nuclear Reactor Regulation order further modifying 800313 order w/respect to licenses & permits for facilities SALTZMAN,U Utility Finance Dranch 80/06/11 ip

- 8007)40256 Forwards Director of Nuclear Reactor Regulation order further modifying 800513 order w/respect to licenses & permits for facilities SALTZMAN.J Utility Finance Branch 80/06/11 ip
- --8007140265 Order granting extension until 800709, for Cleveland Electric Illuminating Co to file amend to tariff w/FERC as required by 800513 order DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/11 2pp
- 8007140B75 Conditional request for hearing re Commission 800513 order re mod of transmission tariff Urgus mod of order to bring consistency w/FERC tariffs in Opinion 84 or institution of hearing Util protest before FERC & Certificate of Svc encl QDLDBERG, R, WAGNER, T & Cleveland, DH GDLDBERG, R Goldberg, Fieldman & Hjelmfelt 80/07/07 14pp
- B007290533 Response in opposition to City of Cleveland, OH 800409 request for hearing re Director of Noclear Reactor Regulation 800513 order Filing, requesting tariff W/FERC, brings controversy to end w/o litigous course REYNOLDS, W B , ZAHLER, R E Cleveland Electric Illuminating Co
- P Operating license stage documents & correspondence
- B00724020B Forwards B&W licensees' responses to 790907 request for review of schadule for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115
 CAPRA.R A TMI-2 Bulletins & Orders 79/10/24 ip
- 8007230099 Requests submittal of proposed Tech Spot changes providing Por redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D Q Division of Licensing 80/04/11 62pp
- B007100006 Denies 790323 Proposed Change 2 to Tech Specs to alter safety features actuation sys containment radiation instrumentation requirement Forwards requests for addl infore bypass capabilities of engineered safety features NOVAX.T M Assistant Director for Operating Reactors 80/06/24
- B007010464 Forwards addl info re shift manning, licensing, testing of power operated relief valve isolation sys, automatic trip of reactor coalant pumps & small break LOCA methods, in response to NRC 800307 ltr
 CROUSE, R P Toledo Edison Co 80/06/26 4pp
- B007180227 Summary of B00610 meeting w/util % B&W in Bethesda.MD re fuel assembly holddown spring failures Viewgraphs encl QARNER,D Operating Reactors Branch 4 B0/06/30 33pp
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating whoken springs in core Requests response within 60 days
 NOVAK.T N Assistant Director for Operating Reactors 80/07/01
- B007210033 Forwards request for add1 info for review of plant operation in Cycle 2 Responses should be received by B00715 to permit complication of review by projected startup date NDVAK.T N Assistant Director for Operating Reactors 80/07/01
- BOO7210119 Requests response to encl questions re fuel assembly holddown spring failures. Initial holddown spring failure was identified during underwater insps of fuel in reactor vascel during current refueling outage NOVAK-T M Assistant Director for Operating Reactors BO/07/01 Sam
- 8007170457 Forwards Amend 26 to License NPF-3, E1A & notice of issuance & availability
 REID,R W Operating Reactors Branch 4 80/07/02 2pp
- --8007170461 Amend 24 to License NPF-3, deleting satisfied App 8 ETS restudies on fish, fish eggs & larvae REID, R W Operating Reactors Branch 4 80/07/02 App
- --8007170467 EIA supporting Amend R6 to License NPF-3 State of DH 800616 ltr re mod of NPDES Permit B211*AD encl * Operating Reactors Branch 4 80/07/02 38pp
- --8007170477 Notice of issuance & availability of Amend 26 to License NPF-3 & negative declaration REID,R W Operating Reactors Branch 4 80/07/02 2pp

- B007210329 Forwards Amend 25 to License APF-3, safety evaluation & notice of issuance & availability
 REID,R w Operating Reactors Branch 4 60/07/02 2pp
- --B0072103d3 Amend 25 to License NPF-3, modifying Tech Specs on surveillance frequency for venting ECCS pump casings & discharge piping high points Also corrects typographical error in Table 3 7-3 REID.R W Operating Reactors Dranch 4 80/07/02 7pp
- --8007210335 Safety evaluation supporting Amend 25 to License NPF-3

 * Office of Nuclear Reactor Regulation, Director 80/07/02 2pp
- --0007210340 Notice of issuance & availability of Amend 25 to License MPF-3 REID.R W Operating Reactors Branch 4 80/07/02 2pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Hodel Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT () Q Division of Licensing 80/07/02 65pp
- 8007180125 Forwards Amend 27 to License NPF-3, safety evaluation & notice of issuance & availability
 REID.R & Operating Reactors Branch 4 80/07/07 2pp
- --BD07180133 Amend 27 to License NPF-3.modifying Tech Specs to refloct changes in corporate structure of util REID.R W Operating Reactors Branch 4 60/07/07 14pp
- --8007180140 Safety evaluation supporting Amend 27 to License NPF-3 * Operating Reactors Branch 4 00/07/07 2pp
- --8007160149 Notice of issuance & availability of Amend 27 to License MPF-3 MEID.R W Operating Reactors Branch 4 20/07/0/ 2pp
- G007150670 Forwards suppl to G00211 reload rept describing info supporting repairs made to failed springs in fuel assemblies CRDUSE.R P Yoledo Edison Co 80/07/10 4pp
- B007280353 Advises of personnal changes resulting from reorganisation of Ofc of Nuclear Reactor Regulation NOVAN.TM Assistant Director for Licensing 80/07/10 2pp
- G007210454 Responds to 780120 request for overall asymmetric LOCA load evaluation BAK-1621, re Phase II analysis of LOCA loadings, provides acceptable demonstration of facility ability to maintain core coolability CR0USE.R P Toledo Edison Co 80/07/14 2pp
- 8007230581 Responds to NRL 800701 ltr requesting add1 info re Cycle 2 including design, transient analysis & startup testing Prior to fuel loading, insp is made to ensure assemblies are in proper storage location in spent fuel pool CRDUSE.R P Toledo Edison Co 80/07/16 4pp
- 8007250427 Responds to NRC 800701 ltr re fuel assembly holddown spring failure per 800710 meeting w/NRC & B&N re proposed repair process Cycle 2 Reload Rept suppl on 800710 noted replacement of broken springs Detailed responses encl CROUSE.R P Toledo Edison Co 80/07/18 9pp
- 8007250382 Informs that util modifying current RCS flow indication scheme in manner similar to NRC acceptable method Effort will be completed prior to startup following current refueling outage CROUSE.R P Toledo Edison Co 80/07/21 1p
- BOO7250434 Forwards Suppl 2 to "Davis-Besse Nuclear Power Station. Unit 1.5elsmic Re-evaluation." completing qualification summary of all aquipment listed in Attachment 1 to NRC 790130 ltr CROVSE.R P Toledo Edison Co 80/07/22 2pp
- --8007250438 Suppl 2 to "Davis-Besse Nuclear Power Station, Unit 1, Seismic Re-evaluation " * Tolego Edison Co 80/07/22 18pp
- 8007280485 Commits to suppl 780320 license amend request by changing Tech Specs to ensure RCS overpressure protection for periods of imperability of alternate relief valve in Modes 4 & 5 CROUSE,R P Toledo Edison Co 80/07/22 2pp

- 8007310380 Forwards response to NRC 800624 request for add1 info re bypass & reset of engineered safety features Design goal of safety features actuation sys is to automatically prevent or limit fission product & onerpy release from core CROUSE: R P Toledo Edison Co 80/07/23 Spp
- 8007310550 Forwards request for add1 info for review of 800211 proposed Tech Spec chango to support operation during Cycle 2 Requests response by 800729 NOVAK, T M Assistant Director for Operating Reactors 80/07/23
- Q Inspection reports, IE Bulletine & correspondence
- B007140548 Forwards IE Insp Rept 50-346/80-10 on 600415-17.29-0501. 06-08 & 12-13 No noncompliance noted HEISHMAN, R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch B0/05/27 2pp
- --B007140558 IE Insp Rept 50-346/B0-10 on 800415-17, 27, 30, 0501, 06-00 & 12 -13 No noncompliance noted Major areas inspected preparation for refueling outage, pre-fuel handling activities, fuel handling activities & maint during refueling outage JACKIW, I N . SHANSON, E R Region 3, Chicago, Office of the Director 80/05/23 5pp
- 8007020096 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/28
- 8007210344 Forwards IE Circular 80-13. "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required. KEPPLER, J O Region 3. Chicago, Office of the Director 80/05/28 to
- E007010116 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director B0/05/29 in
- B007210322 Forwards IE Insp Rept 50-346/80-14 on B00408-11.15-25.29-30, 0501.02 & 05-09 & notices of violation HEISHMAN,R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/09 2pp
- --8007210325 Notice of violation from insp on 800408-11,15-25,29-30,0501, 02 & 05-09 # Region 3, Chicago, Office of the Director, 80/06/03 1p
- --B007210327 IE Insp Rept 50-346/80-14 on B00408-11.15-25.29-30.0501.02 & 05-09 Moncompliance noted failure to establish fire watch patrol REYES.L A , MCGREGOR.L G , TAMBLING.T N Region 3, Chicago, Office of the Director B0/06/03 Bpp
- B007010254 Notifies that info requested by IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." is being compiled & evaluated Response will be available on 800627 CRGUSE, R P Toledo Edison Co 80/06/06 ip
- BOD722021B Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/06/10 ip
- 8007140191 Forwards IE 1nfo Notice 80-27, "Degradation of Rwactor Coolant Pumps Bluds " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11.
- 8007020040 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Re-review of all safety-related components affected by safety features actuation systhms that reset will not remove component from safe mode. CRUUSE, R P Toledo Edison Co 80/06/13 3pp
- 8007150824 Forwards results of follow-on analysis of identified discrepancies for hormally accessible safety-related piping in response to Item 48 of IE Dulletin 79-14, "Beismic Analysis for As-Duit Bafety-Related Piping Sys "CROUSE, R P Toledo Edison Co 80/06/14, 4pg
- 8007140464 Forwards IE Insp Rept 30-346/79-34 on 791218-19 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/17 2pp

- -800714047: IE Insp Rept 30-346/79-34 on 791218-19 No noncompliance noted Major areas inspected actions taken in response to IE Bulletin 79-19 re low level radwaste packaging for transport & burial GREOGRAL R Region 3, Chicago. Office of the Director FISHER, W.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/06/13 App
- 8007030046 Forwards IE Bulletin 80~15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Dffsite Power " Written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/1 Region 3. Chicago, Office of the Director 80/06/18
- 8007170064 Forwards description of results of followon analytical work to IE Bulletin 79-14 Effect of discrepancies discovered in IE Bulletin 79-14 insp evaluated Conclusions in 791019 ltr still valid CROUSE, R P Toledo Edison Co 80/06/18 App
- 8007180310 Respands to Items 1,2 & 3 in IE Bulletin 79-03, Revision A No applicable piping components w/design pressure stresses greater than 93% of allowable code values identified CROUSE, R P Toledo Edison Co 60/06/18, 2pp
- 8007140237 Forwards response to IE Bulletin 60-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ" Unprotected sys are regularly sampled & tested for tritium CRDUSE.R P Toledo Edison Co 80/06/19 2pp
- 8007230327 Forwards IE Insp Rept 50-346/80-11 on 8004i0-11,21-22, 0506-07 & 0604 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/19 2pp.
- --B007230333 IE Insp Rept 50-346/80-ii on B00410-ii.21-22.0506-07 & 0604
 No noncompliance noted Major areas inspected QA/QC program,
 nondestructive examination svaluations & work activities
 HARD,K D Region 3. Chicago, Office of the Director
 DANIELBON.D H. Region 3. Chicago, Reactor Construction &
 Engineering Support Branch B0/06/18 7pp
- 8007020571 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J O. Region S. Chicago, Office of the Director 80/06/20
- 8007090013 Forwards notice of violation & notice of proposed imposition of civil penalties re BO0430 radiation overexposure STELLO.V Office of Inspection & Enforcement, Dffice of the Director 80/04/20 3pp
- -8007090014 Notice of violation re radiation overexposure on 800430 Noncompliance noted, two persons received dose greater than 3 rems in querter & sposure rate evaluations were not adequate to ensure dose limits would not be exceeded Office of Inspection & Enforcement, Office of the Director BO/06/20 2pp
- ---B007070016 Notice of proposed imposition of civil penalties based on items of noncompliance re B00430 radiation overexposure # Office of Inspection & Enforcement, Office of the Director B0/06/20 ip.
- B007110214 Forwards notice of violation & notice of proposed imposition of civil penalities arrising from IE 800430 insp SYELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/20 3pp
- --B007110220 Notice of violation from insp on 800421-24.0502 & 06-08 Noncompliance noted them & rad tester received doses exceeding 3 rems & exposure rate evaluations made during sump tunnel entry were inadequete # 0#fice of Inspection & Enforcement, Office of the Director B0/06/20 2pp
- 8007170515 Forwards IE Circular 80-14, "Radioactive Contamination of Plent Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER. J Q Region 3, Chicago, Office of the Director 80/06/24
- 8007300601 Forwards lE Insp Rept 50-846/80-15 on 800512-16,19-23,28-30, 0602-06 & 09-10 & notice of violation. HEISHMAN, R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/25 2pp.

- -- 8007300604 Notice of violation from insp on 800512-16, 19-23, 28-3 06 & 09-10 * Region 3, Chicago, Office of the Director 80/06/24 ip
- --8007300606 16 Insp Rept 50-346/80-15 on 800512-16.19-23.28-30.06 20/300000 it insp kept 50-346/80-15 on 800512-16.19-23, 28-30.09-10 Noncompliance noted feature to notify NRC operations ctr within 1-h of accidental radioactive release or event requiring initiation of emergency plan TAMBLING.T H. REYES, L. A. Region 3, Chicago, Office of the Director 80/06/24 App
- B00723007& Responds to IE Bulletin 79-17. Revision I. "Pipe Cracks Biagnant Borated Water Sys at PWR Plants " All welds azamined & found to be clear of recordable indications CROUGE.R P Toledo Edison Co B0/06/27 ip
- 8007230141 Forwards response to IE Bulletin 80-05, "Vacuum Conditi Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Review shows correttive actions not required CROUSE.R P Toledo Edison Co 80/06/27 App
- 8007230340 Forwards IE Dulletin 80-16, "Potential Misapplication o Rosemount Inc Models ii31 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required, KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/
- B007170532 Responds to IE Bulletin 79-14. "Baismic Analysis for As Built Safety-Related Piping Sys " Insp of normally inaccessible piping completed B00522 Two deviations affecting sys operability will be corrected before startup CRDUSE, R P Toledo Edison Co 80/06/30 2pp
- BO07180271 Advises that response to Items 1.2a & 3 of IE Bulletin 80-11. "Masonry Wall Design." will be delayed 1 wk beyond date specified in bulletin CROUSE.R P Toledo Edison Co 80/06/30 1p
- 8007210216 Responds to IE Bulletin 79-02, "Pipe Support Same Plate Designs Using Concrete Expansion Anchor Holts " Dutstanding items have been completed except base plate accessibility which will be completed by 801101 CRDUSE, R P Toledo Edison Co 80/07/01 Spp
- 8007240024 Ack receipt of 800611 ltr informing NRC of steps taken correct violation noted in IC lasp Rept 80-346/80-13 Details withheld (ref 100782 790)
 HIND, J. A. Region B. Chicago, Safeguerds Branch 80/07/03 2pp.
- --8007240028 Responds to NRC 800521 ltr re violation noted in IE I Rept 50-346/80-13 Corrective actions withheld (ref 10CFR2 770) CROUSE:R P Toleda Edison Co BO/06/11 lp
- 8007230200 Forwards reply to IE Bulletin 80~08 re containment line penetration welds Repts results of const nondestructive examination of penetration welds CROUSE/R P Toledo Edison Co 80/07/10 App
- 8007230200 Forwards reply to 1E Bulletin 80-08 re containment line penetration welds Repts results of const nondestructive examination of penetration welds CROUSE:RP Taleda Edison Go 80/07/10 App
- 8007240307 Forwards corrected copy of notice of violation from ina 800312-16.19-23.20-30.0602-06 & 09-10 which was transmitted by NRC 800623 ltr HEISHMAN,R F Region O. Chicago. Reactor Operations Nuclear Sup HEISHMAN, R F Region G. Chicago, Reactor Operations Nuclear Sug Branch 80/07/10 1p
- --8007240313 Corrected natice of violation from imap on 800512-16, 28-30,0602-06 & 09-10 * Region 3, Chicago, Office of the Director 89/07/10 ip
- 8007250572 Forwards response to IE Bulletin GO-OB. "Eram of Contal Liner Penetration Welds " List of all penetrations w/ containment boundary butt walds hetween penetration sieeve & process piping as illustrated in ABME code encl CROUSE.R P Toledo Edison CO 80/07/10 App
- 8007270500 Forwards masonry wall design evaluation in response to 1.2a & 3 of 1E Dulletin 80-11 Stafety-related & nonsafety-related components identified on faces of walls Partial response to Items 2b & 3 will be filed by 801104 CROUSE.8 P Toledo Edison Co 90/07/14 Spp

```
8007310348 Forwards response to NRC 800620 ltr re 800430 personnel overexposure Corrective actions procedure now requires insport cavity area surrounding reactor vessel to identify water leakage Payment of civil penalty encl CROUSE, R P Toledo Edison Co 80/07/15 5pp
BOO7280429 Forwards IE Investigation Rept 50-346/80-14 on 800605-06 & notice of violation Notice of violation withheld (ref 10CFRZ 790)

MEPPLER.J 0 Region 3. Chicago. Office of the Oirector 80/07/17
---B0072B0435 IE Investigation Rept 50-346/80-18 on B00605-06
Noncompliance noted failure to assess adequacy of access
control & to meet security gian commitment App B rept
details withhold (ref 10CFR2 790)
WEIL-C H , MADEDA:T J , NORELIUS,C E Region 3, Chicago, Office of
the Director B0/07/11 13pp
8007310534 Ack receipt of 800627 ltr informing NRC of steps taken to correct violation noted in IE lnsp Rept 50-346/80-14
HEISHMAN, R F. Region 3, Chacago. Reactor Operations Nuclear Support
Branch 80/07/22 ip
    -8007310336 Responds to NRC 800605 ltr re violation noted in IE Insp
Rept 50-346/80-14 Corrective actions appropriate personnel
will ensure that fire watch is established as required by
           CROUSE, R P Toledo Edison Co 80/07/08 2pm
R Periodic operating reports & related correspondence
8007140318 Forwards monthly operating rept for June 1780 MURRAY.T D Toledo Edison Co 80/07/08 ip
--8007140322 Monthly operating rept for June 1980
SARSDUR, B Tolesp Edison Co 80/07/08 3pp
 & Reportable occurrences. LERs & related correspondence
EC07010434 Forwards LER 80-043/03L-0
MURRAY: T D Toledo Edison Co 80/06/26 1p
--8007010439 LER 80-043/03L-0 on 800528, while tosting safety features actuation sys, valve DH-11 closed & DH pump 1-1 was stopped Caused by procedural inadequacy Responsible personnel were made aware of problem ISLEY. Toledo Edison Co 80/06/26 3pp
BD07030260 Forwards LER 80-044/03L-0
MURRAY,T D Toledo Edison Co 80
                                                                                               80/06/27 1p
--B007030264 LER B0-044/03L-0 on B00331 decay heat flow indication FI-DH2B dropped low off scale Caused by technician performing surveillance test on inservice flow transmitter string w/o shift supervisor inowledge MAKATURA.L Toleda Edison Co 80/06/27 2pp
E007150607 RD on 800627, pipe support HCB-40-41 on component cooling water supply to control rod drive mechanism found not installed Also, lateral restraint CCA-B-HI5 on pressurizer relief inlet located 9 inches from analyzed focation MURRAY, T D Toledo Edison Co 80/06/27 ip
8007210573 Forwards questions we failure of holddown spring on fuel assembly Response should be submitted in time for NRC to include discussion in safety evaluation for reload NDVAK.T H Assistant Director for Operating Reactors 80/07/01
BO07110427 Forwards revised LER 77-2/2/01T-2
HURRAY, T D Toledo Edison Co BO/07/02 ip
     -8007110434 Revised LER 77-222/01T-2 on 770805, during hot functional testing, pressurizer power operated ralief valve was opened & severe movement of discharge piping was observed Caused by loop seals allowing water slug to cause pipe movement QUENNO2.5 M Taledo Edison Co 77/08/19 4pp
E007110391 Forwards revised LER 79-124/03L-1 MURRAY, T D Toledo Edison Co 80/07/03 1p
--8007110397 Revised LER 79-126/03L-1 on 791209, during diesel generator
test,generator 1-1 experienced load swings as load was
increased No apecific cause determined Gain & stability on
electric governor needed slight adjustments
HARTIGAN, J.P. Toledo Edison Co. 80/01/05. 2pp
```

```
B007110407 Forwards LER 80-045/03L-0
MURRAY, T D Toledo Edison Co B0/
                                                                                                 80/07/03 in
 --8007i10416 LER 80-045/03L-0 on 800609, while preparing to perform 8T 5091 01, N1-2 found partially disconnected from equipment in control room Apparently caused by personnel error Info tags hung on coax cables to insure proper connection WERNER, J Toledo Edison Co 80/07/03 2pp
 B007110418 Forwards LER 80-046/03L-0
MURRAY, T D Toledo Edison Co 80/07/03 1p
 ---8007110423 LER 80-046/03L-0 on 800606.during performance of 8T 5095 01, spent fuel pool level fell below Tech Spec requirement Caused by improper alarm setpoint Alarm setpoint adjusted to prevent recurrence CECH.L M Toledo Edison Co 80/07/03 2ep
 8007110440 Forwards LER 80-047/03L-0
MURRAY, T D Toledo Edison Co 80/07/03 1p
 --8007i10448 LER 80-047/03L-0 on 80060B shift supervisors discovered doors 306 & 40ia blocked open Apparently caused by lack of administrative controls when temporary signs on doors were prematurely removed before all permanent signs installed CECH.L Toledo Edison Co 80/07/03 2pp
E007150560 Forwards LER 80-048/01T-0
MURRAY, T D Toledo Edison Co B0/07/10 1p
--B007190566 LER 80-04B/01T-0 on B00627, during IE Bulletin 79-14 insp. pips support HCB-40-Bi found not installed & CCA-B-415 found mislocated Caused by initial const/installetion error Supports will be installed in proper locations, HEKBEL.C Toledo Edison Co 80/07/10 2pp
8007240126 Replacement transmittal ltr for LER 80-048/017-0
HURRAY,T D Toledo Edison Co 80/07/10 ip
8007170441 Forwards LER 80-049/03L-0
MURRAY, T D Tuledo Edison Co 80.
                                                                                                80/07/11 lp
--8007170450 LER 60-049/03L-0 on 800614, during restoration of containment pressure inputs to safety features actuation sys cabinets, actuation occurred Caused by deficient procedure ST 5061.01 App F not requiring trip bypass test ISLEY,T Toledo Edison Co 80/07/11 Spp
 8007220375 Forwards LER 80-050/03L-0
MURRAY, T D Taledo Edison Ca 80/07/17 1p
--B007220378 LER 60-050/03L-0 on B00623.while preparing to run 8T 5051 Oi, inboard & outboard bearing thermocouple wells found broken on HPI pump l-1, rendering motor imperable Probably caused by personnel stepping on line Hells replaced HARTIQAN, J P Toledo Edison Co 80/07/17 2pp
8007220458 Ferwards LER 80-051/03L-0
MURRAY, T D Toledo Edison Co 80/07/17 ip
    -8007220465 LER 80-051/03L-0 on 800619, while performing ST 5031 O7
Phase II, sequencer logic channels 2 & 4 did not operate as
designed Caused by component failure of relay SEGX & CR-3X
in C2618 Relay SEGX was replaced CR-3X was cleaned
ISLEY.T Toledo Edison Co 80/07/17 2pp
B007280596 Forwards updated LER 80-050/03L-i
MURRAY.T D Toledo Edison Co 80/07/21
---B00/280502 Updated LER B0-050/03L-1 on 800523, inboard & outboard bearing thermocoupie wells found broken on high pressure injection pump 1-1 Probably caused by someone accidentally stapping on line Wells replaced & vil reservoirs refilled HARTIGAN, J P Toledo Edison Co 80/07/17 lp.
8007280571 Forwards LER 80-053/01T-0
MURRAY, T D Toledo Edison Co 80/07/22 ip
      -B0072B057B LER 80-053/0iT-0 on G00709, meeting held to discuse results of integrated safety features actuation sys test Bome of logic modules on sequencer steps 2,3,4 & 5 tripped before being blocked Coused by design deficiency ISLEY,T Toledo Edison Co 80/07/22 3pp
8007280630 Forwards LER 80-052/01T-0
MURRAY: T D Toledo Edison Co 80.
                                                                                                80/07/22 1p
```

- --B007280643 LER 80-052/01T-0 on 800709, during review of seismic calculations, others ductwork of emergency diesel generators created overstressed conditions at exhaust notices Caused by design deficiency Supports will be added HARTIGAN, J.P. Toledo Edison Co. 80/07/22 2pp
- 8007280583 Forwards LER 80-034/03L-0 #URRAY, T D Toledo Edison Co 80/07/23 1p
- --B007280389 LER B0-054/03L-0 on 800627, NI-1 output failed to zero during fuel assembly movement Assembly removed & put in support rack Cause unknown but may be intermittent grounding problem or component failure Ground problems under investigation WERNER. B J Toledo Edison Co 80/07/23 2pp
- 800/280609 Forwards revised LER 79-084/01T-1 HURRAY.T.D Toledo Edison Co 80/07/23 ip
- --B007280622 Revised LER 79-D84/01T-1 on 790806, containment air coolers svc water outlet valves failed to meet response time Caused by undersized air opening on pnewmatic actuators Valves forced full open Actuating mechanisms redesigned RUDGLPH, J P Toledo Edison Co 79/0B/17 29p
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans
- E007280541 Responds to NRC 800702 ltr requesting info re evacuation times Util 800204 ltr w/State of AL & GA officials comments encl.

 CLAYTON.F L Alabama Power Co 80/07/21 lp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables EISEN#NT. D O Division of Licensing 80/06/25 89pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007100261 Forwards Amend 73 to FSAR for Unit 1 & OL application for Unit 2 CLAYTON,F L Alabama Power Co 80/07/08 lp
- --8007100267 Application for Amend 73 to FBAR for Unit 1 & OL application for Unit 2 Certificate of Svc encl
 * Alabama Power Co 80/07/08 App
- --8007100276 Amend 73 to FSAR for Unit 1 & OL application for Unit 2 Revises Unit 2 completion of const & commercial operating dates updating section re emergency lighting sys & info partaining to GA program * Alabama Power Co 80/07/08 400pp
- P Operating license stage documents & correspondence
- 8007230079 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D O Division of Licensing 80/06/11 62pp
- 8007150714 Responds to NRC 800507 ltr re add1 TMI-2 related requirements & submits response for Unit 1 Shift manning, revised scope & criteria for licensing exams & procedures for feedback of operating experience to plant staff encl CLAYTON, F L Alabama Fower Co 80/06/26 29pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Bpec changes & license conditions PWR Model Tech Bpecs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIBERNUT.D Q Division of Licensing 80/07/02 69pp
- 8007210499 Confirms 800711 agreements w/NRC re operability of auxiliary feedwater flow control valves at facility Commitments made re stroking listed valves as soon as possible & logging dc bus 14 & 18 voltages once per hr CLAYTON.F L Alabama Power Co 80/07/11 lp
- B007220510 Forwards process control program for radwaste solidification unitias discussed at 800709 meeting U/NRC CLAYTON,F L Alabama Power Co 80/07/14 1p

- --8007220515 Radiation Control & Protection Procedure FNP-D-RCP-474, Revision 1 "Mobile Salidification Unit Operation" MCCRACKEN.K W. Alguma Puwer Co. 80/01/10 59pp
- 8007220558 Forwards Revision I change pages to plant offsite desectable manual incorporates radiation monitor setpoint calculation methodology discussed during 800707 neeting W/NRC CLAYTON-F L Ajabama Power Co 80/07/14 App
- 8007220554 Forwards aux)liary feedwater endurance test data & test info requested in NRC 800408 ltr CLAYTUN.F L Alabama Power Co RO/07/16 20pp
- 8007/30400 Forwards addl info in degraded electrical power grid conditions in response to 800626 teleon Includes suppl to util 790115 ltr re assessmint of MRC Positions (.2 & 3 CLAYTON F L Alabama Power Co 80/07/17 13pp
- 8007230553 Forwards radiological Tech Spec info concerning hydrogenoxygen-nitrogen mixture curves & hydrogen recombiner instrumentation ialibr H/o encl CLAYTON.F I Alobama Power Co U0/07/17 lp
- BOO7300029 Forwards revised Pages 1 % 2 to NRC 800430 evaluation of util response to TMI Lessons Learned Category A items
 VARQA.S A Operating Reactors Dranch 1 80/0//23 4pp
- O Inspection reports, 1E Dulletins & correspondence
- 8007240108 Forwards lE Info Notice 80-20, "Loss of Decay Hoat Removal Capability at Dazis-Bosso Unit 1 While in Refueling Mode " No response required Q'REILLY,J P Rogion 2, Atlanta, Office of the Piroctor 80/05/08
- 8007020180 Forwards IF Info Nutice 80-22, "Breakdowns In Contamination Control Programs" No written response required O'RE[(LY, J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007210419 Forwards IE Circular GO-13. "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J.P. Region 2. Atlanta, Diffice of the Diructor 80/09/28 In
- 8007010253 Forwards IC Info Notice 80-23, "Lass of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- B007220040 Forwards IE Info Native 80-26, "Evaluation of Contractor OA Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/10
- B00/240369 Forwards IE Insp Rept 50-.146/80-11 on 800527 No noncompliance noted \$70/84.0 P Region 2. Atlanta, Fuel Facility & Haterials Bafety Branch B0/06/10 2pp
- --B007240976 IE Insp Rept 40-346/80 ii on 800527 No noncompliance noted Major areas inspected major radiation unurgency exercise TROJANDHENISR E. BRADFORDA H Region 2. Atlanta. Bffire of the Director JONATHS OR Region 2. Atlanta. Fuel facility & Materials Safety Branch 80/06/09 3pp
- 8007160218 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Funn Stude " No specific action or response required O'RFILLY, J.P. Region 2, Atlanta, Uffice of the Director 80/06/11
- 8007020751 Forwards IE Bulletin 80-15. "Possible Lass of Emergency Notification Sys (FAS) W/Loss of Officito Power" Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/18
- B007020385 Forwards 1E Circular EXP-15. "Loss of Reactor Coplant Pump Cooling & Natural Circulation Conident " No orition response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/06/20
- 8007070394 Forwards IE Insp Repts 50-548/80-10 t 50-364/80-11 on 800331-0448 No noncompliante noted LEMIS C Region & Atlanta Reactor Operations Nuclear Support Branch 80/06/21 2pp

- --B007070397 IE Insp Repts 50-348/B0-10 & 50-364/B0-11 on B00331-0425 No noncompliance noted Major areas inspected hot functional testing, IE bulletin follows & plant security MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch BRADFORD.H H Region 2. Atlanta, Office of the Director B0/05/21 App
- B00716079; Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralised Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/06/24
- BOO7230206 Forwards 1E Bulletin BO-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director BO/06/2 B0/06/27
- 8007210265 Forwards response to 1E Bulletin 80-08. "Examination of Containment Liner Penetration Welds" All containment butt welds between penetration sleeves & process piping in Unit 1 radiographed upon completion CLAYTON, F. L. Alabama Power Co. 80/07/01 5pp
- 8007i60547 Informs that requested actions re IE Bulletin 80-10 have been completed & are available for review at facility CLAYTON,F L Alabama Power Co 80/07/07 ip
- BOO7290859 Responds to 1E Bulletin BO-11. "Masonry Wall Design " All masonry walls, function of each wall & relation to safety-related equipment are listed & identified in encl walk-down summary sheets Sys supports sketch will be developed CLAYTON, F. L. Alabama Power Co. 80/07/07 9pp
- BO07250479 Responds to open items noted in BO0324 rept of insp on B00326-29 refire protection Obstructed sprintler sys heads will be relocated per nat! fire protection stds CLAYTON.F L. Alabama Power Co. 80/07/2! 5pp
- R Periodic operating reports & related correspondence
- 8007070168 Forwards revised monthly operating repts for Mar 1979-May 1980 CLAYTON, F.L. Alabama Power Co. 80/06/30 1p
- ~-BOD7070176 Revised monthly operating rept for Mar 1979 HAIRSTON.W G Alabama Power Co 79/04/01 1p
- ---BO070701B0 Revised monthly operating rept for Apr 1979 HAIRSTON.W G Alabama Power Co 79/05/01 lp
- --B007070190 Revised monthly operating rept for May 1979 HAIRSTON, W O Alabama Power Co 79/06/01 to
- --B007070194 Revised monthly operating rept for June 1979 HAIRSTON W G Alabama Power Co 79/07/01 ip
- --BO07070199 Revised monthly operating rept for July 1979 HAIRSTON.W G Alabama Power Co 79/08/01 ip
- --BO07070204 Revised monthly operating rept for Aug 1979 HAIRSTON W O Alabama Power Co 79/09/01 1p
- ---8007070208 Revited monthly operating rept for Sept 1979 HAIRSTON, W.G. Alabama Power Co. 79/10/01 lp
- --BOD7070214 Revised monthly operating rept for Oct 1979 HAIRSTON W G Alabama Power Co 79/11/01 lp
- --8007070217 Revised monthly operating rept for Nov 1979 HAIRSTON,U G Alabama Power Co 79/12/01 ip
- --8007070219 Revised monthly operating rept for Dec 1979 HAIRSTON, U.G. Alabama Power Co. 80/01/01 1p
- --8007070223 Revised monthly operating rapt for Jan 1980 HAIRSTON, N.G. Alabama Power Co. 80/02/01 1p
- -8007070226 Revised monthly operating rept for Feb 1980 HAIRSTON W G Alabama Power Co 80/03/01 ip
- -BOO707022B Revised monthly operating rept for Mar 1980 HAIRSTON,W G Alabama Power Co BO/04/01 1p

W. 7

- --B007070230 Revised monthly operating rapt for Apr 1980 HAIRSTON, W G Alabama Power Co 80/05/01 ip
- --B007070232 Revised monthly operating rept for May 1980 HAIRBTON:W G Alabama Power Co 80/04/01 1p
- 8007150662 Forwards monthly operating rept for June 1980 CLAYTON: F L Alabama Power Co 80/07/11 ip
- --8007150468 Monthly operating rept for June 1980. HAIRSTON,4 0 Alabama Power Co 80/07/01
- S Reportable occurrences, LERs & related correspondence
- B007160861 Part 21 rept re Westinghouse review of safety injection termination criteria following secondary side high energy line rupture w/potential for damage to centrifugal charging pumps Concerns are applicable to facility HAIRSTON.W 9 Alabama Power Co 80/06/13 2pp
- B007010444 Forwards LER 80-036/03L-0 CLAYTON: F L Alabama Power Co 80 80/06/25 1p
- ~-B007010446 LER 80-036/03L-0 on 80052B, during performance of RHR valves inservice test, iA RHR heat exchanger discharge valve failed to stroke close Caused by cap acrew connecting valve actuator to valve shaft coming out Cap screw replaced HAIRSTON, W G Alabama Power Co B0/06/25 2pp.
- 8007010404 Forwards LER 80-037/01T-0 CLAYTON.F L Alabama Power Co 80/06/27 1p
- -8007010412 LER 80-037/01T-0 on 800613. Hestinghouse notified util of potential for damage to centrifugal charging pumps due to Inadequate flow following secondary side high energy line rupture Caused by inadequate consideration during design. HAIRSTON. H O Alabama Power Co 80/06/27 3PP
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007020257 Forwards NRC Ofc of Nuclear Reactor Regulation B00428 reorganization chart Necessary period of transition made w/min disruption to angoing activities
 TEDESCO,R L Assistant Director for Licensing 80/06/13 2pp
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls I-3. "Technical Basis for Use of Equare-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj. to certain constraints MATTBON,R J Division of Safety Technology 80/06/25 Spp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0667 & Division of Licensing 80/06/26 2pp
- B007160451 Responds to ltr re facility Replacement power cost reported in NRC 800130 ltr is for fuel to operate plant Large part of replacement power would come from oil Intensity of recent earthquake was only fraction of DBE SCHMENCER. A Licensing Branch 2 80/06/27 11pp
- B007230621 Summary of B00612 meeting w/Mark II owners group in Bethesda, NO re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Visugraphs encl. ANDERSON, C.J. Generic Issues Brench 80/07/03 57pp
- B007180285 Notification of B00711 meeting w/util in Dethesda,MD to discuss certain problems w/facility review SELLS.D Licensing Branch 2 80/07/11, 3pp
- 800725047i Suggests 800704 meeting for presentation of info responding to NRC B00506 ltr re preliminary risk analysis Lists info to presented Philadelphia Electric Co 80/07/21 ip.
- B007230175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago. IL to discuss lead Mark II plants chugging & C/O load spucs aNDERSON. C Generic Issues Brench B0/07/23 2pp

@ Adjudicatory correspondence

9007310243 Forwards Commission 800327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 70413 memorandum & order UCS 771104 petition sought action refire protection for electrical cables
EISENHUT, D Q Division of Licensing 80/06/25 89pp

H Ganeral correspondence

- BOO7100272 Ack receipt of itr re const of facility Station is not presently under active review itr will be kept on file & returned when util application for OL review is initiated SCHMENCER.A Licensing Branch 2 80/06/23 lp
- --B0071002B9 Requests that NRC reconsider opening facility PA has not improved radiation monitoring or emergency response since TMI Berious nuclear accidents can & will happen Homeowner insurence does not cover loss of life or damages CLARK.C Affiliation Unknown 80/06/23 2pp
- BOO7110510 Responds to 800409 ltr re const of facility Environ & safety reviews will begin when util submits application for OL Ltr will be kept on file & referred to again when review initiated BCHMENCER. A Licensing Branch 2 80/06/23 2pp
- BO07140025 Ack receipt of B00610 ltr & resolution re const of facility Resolution will be considered along w/other correspondence in future reviews relative to facility licensing BCHMENCER, A Licensing Branch 2 80/06/26 lp
- 8007160644 Forwards 800628 correspondence to President Carter, Governor Thornburgh, Senators Schweiker & Heinz, Representative Lederer, State Senator Fumo, State Representative Rappaport & MRC re helbing facility const HAMKING, K L Pennsylvania, State of 80/06/28 7pp
- BOO7180345 Responds to 1tr re const of facility Ltr will be kept on file & referred to when NRC initiates DL review Facility will not be under active review until util submits DL application in late 1980 or warly 1981 SCH
- 8007250004 Ack receipt of itr re const of plant Plant not under active review Public comments will be considered during review SCHMENCER, A Licensing Branch 2 80/07/14 ip
- 8007250475 Responds to 800630 ltr to NRC re const & operation of facility NRC welcomes citizen ltrs & takes them into consideration during environ & safety reviews Facility will not be reviewed until OL application is received SCHMENGER.A Licensing Branch 1 80/07/i5 2pp

I. Financial information

- BOO701013B Responds to 800605 ltr to 0 Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, E Hearings Division 80/06/19 ip
- G Inspection reports. IE Bulletins & correspondence
- B007140469 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers" No written response required ORIER.8 H Region 1, Philadelphia, Office of the Director 80/05/12 ip
- 8007010238 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Fredwater Pumps." No written response required ORIER.8 H Region 1, Philadelphia. Office of the Director 80/05/29.
- 8007210604 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Frograms " No written response required GRIER, B. M. Region i. Philadelphia, Office of the Director 80/06/10 ip
- 8007140280 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Capability " No written response required ' GRIER, B H Region i, Philadelphia, Office of the Director 80/06/12 ip
- 8007280608 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance M/100FR50 55(e) " No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director 80/06/13 1p

- 8007020516 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, BH Region 1. Philadelphia, Office of the Director 80/06/20 1p
- 6007140728 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/06/24 ip
- 8007210225 Forwards IE Info Notice 80-24, "Low Lovel Radwaste Burial Criteria " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 (p
- 8007210312 Ack receipt of 800410 ltr informing NRC of staps taken to correct violations noted in IE insp Repts 50-352/79-12 & 50-353/79-11
 ORIGER, D.H. Region 1, Philadelphia, Office of the Director 80/06/26, 200
- --8007210321 Responds to NRC 800312 ltr re violations noted in IE Insp Repts 50-352/79-12 % 50-353/79-11 Corrective actions Uncontrolled copies of pipe support drawing removed from field KEMPER, J S Philadelphia Electric Co 80/04/10 Spp
- --8007210326 Forwards IE insp Repts 50-352/79-12 & 50-393/79-11 on 791120-30 & 1203-21 & notice of violation CARLSON:R T Region i. Philadelphia. Reactor Construction & Engineering Support Dranch 80/03/12 2pp
- --8007210330 Notice of violation from insp on 791120-30 & 1203-21 # Region 1, Philadelphia, Office of the Director #80/03/05 Zpp
- --8007210338 IE Insp Repts 50-352/79-12 & 50-353/79-11 on 791120-30 & 1203-21 Noncompliance noted failure to control design documents for masonry walls & failure to provide GA program for masonry wall subcontractors

 MATTIA.J C Region 1. Philadelphia. Office of the Director MCGAUOHY, R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/05 15pp
- B007230159 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ORIGA, BH. Region 1, Philadelphia, Uffice of the Director 80/06/27 2pp
- 8007210567 Responds to IE Bulletin 90-08 Flued heads which are butt welded to containment penetration sleaves used in both units ASME Code Section [11,1974 through Winter 1974 addends.applied KEMPER.J S Philadelphia Electric Co 80/07/02 7pp
- 8007210206 Ack receipt of 800623 ltr infurming NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-03 & 50-353/80-03 CARLSON T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/03 1p
- --8007210214 Responds to NRC 800526 ltr re violations noted in IE Insp Repts 50-352/80-03 & 50-393/80-03 Corrective actions GA issued stop work orders on pipe restraint PR-279 KEMPER. J B Philadelphia Electric Co 80/06/23 2pp
- ~-B007210221 Forwards 1E Insp Ropts 50-352/80-03 & 50-353/80-03 on B00225-0325 & notice of violation CARLBON.R T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch B0/05/26 2pp
- --8007210230 Notice of violation from insp on 800225-0325
 * Region 1, Philadelphia, Office of the Director 80/05/21 1p
- --B007210240 IE Insp Repts 50-352/80-03 & 50-35'J/80-03 on B00225-0325 Noncompliance noted feature to prehoat weld joint prior to welding MATTIA.J C., FINKEL, A. Region I. Philadelphia, Office of the Director MCGAUOHY, R. W. Region I. Philadelphia, Reactor Construction & Engineering Support Branch B0/05/21 15pp

- S Reportable occurrences LERs & related correspondence
- 8007020155 Forwards surpary or 800227 meeting wouth to discuss reporting requirements of significant design & const deficiencies for reply requested CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/27 Jp
- ---B007020164 Summary of B00227 meeting w/util in Region 1 ofc to discuss reporting requirements of significant design & const deficiencies a Region 1. Philadelphia, Office of the Director B0/02/27 2pp
- 8007210015 Ack receipt of 800606 final deficiency rept re heating, ventilation & air conditioning damper Rept will be reviewed & evaluated CARLEGON, P T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60,06/25 ip
- B007240226 Part II rept re defective Rosemount trip/calibr units & transmitters supplied by GE Caused by failure of essential switch that determines trip output logic Output of defective units will be corrected per GE instructions
 KEMPER.J 5 Philadelphia Electric Co 80/07/01 5pp
- 8007250152 Part 21 rept re defective GE crimp pins in electrica) connectors Cause not stated Encl GE rept states that GA procedures have been modified to preclude defective crimping in foure

 KEMPER J S Philadelphia Electric Co 80/07/01 7pp
- 8007090265 Deficiency rept re Colt Industries emergency diesel gamerator heat exchangers Deviation between configuration of high heat exchanger stack on generator skid & configuration analyzed in seismic rept detected KEMPER.J S Philadelphia Electric Co 80/07/02 2pp
- --8007090270 Part 21 rept he Colt emergency diesel generator heat exchangers Deviation between configuration of high heat exchangers stath on generator skid & configuration analyzed in Seissic reto the detected MORIARTY, J M Colt Industries, Inc. 80/01/16 ip
- --B007070275 Part 21 rept re Colt emergency diesel generator heat exchangers Units & & 7 have been corrected by fitting shims at bolted interface between generator skid & heat exchanger mounting feet
 MORIARTY, J M Colt Industries, Inc 80/06/13 1p
- 8007250287 Ack receipt of 800620 final deficiency rept re 4 kV switchgear circuit breaker auxiliary switch crank assembly defect defect CARLSON.R T Region 1. Philadelphia. Office of the Director 80/07/03 lp
- BOO7310281 Act receipt of 80070; final deficiency rept re defective crimps in electrical connectors CARLSON. T Region 1. Pulladelphia, Reactor Construction & Engineering Support Branch 80/07/11 1p
- --8007310286 Gignificant Deficiency Rept 14 te defective crimps in electrical connectors GE rept submitted per JOCFR21 provides detailed sits insp info Rept encl
 KEMPER.J S Philadelphia Electric Co 80/07/01 2pp
- U Congressional/Executive Correspondence
- 8004280239 Requests appearance on behalf of subcommittee to testify on issues re emergency planning procedures & preparedness along w/implications of lessons learned from accident at TMI Hearing scheduled for 800527 UDALLIN K House of Rep , Interior & Insular Affairs 80/04/16
- 8007110338 Responds to 800604 ltr expressing concerns about testimony of V Boyer util Senior Vice President HR Denton will meet w/ Boyer on 800630 to discuss matter in greater detail DIRCKS, W J Office of the Excustive Director for Operations 80/06/30 lp

- DOCKET 50-393 LIMERICK GENERATING STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8007020257 Forwards NRC Off of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEBERCO.R L Assistant Director for Licensing 80/06/13 2pp
- BOO721Q176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Gupple 1-3: "Technical Basis for Use of Square-Root-of-Bum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark Il Plants "Rept acceptable sub; to certain constraints MATTSDN.R J Division of Safety Technology 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUT, D 0 Division of Licensing 80/06/26 2pp
- 8007160491 Responds to ltr re facility Replacement power cost reported in NRC 800130 ltr is for funl to operato plant Large part of replacement power would come from oil Intensity of recent set thouse was only fraction of DBE BCHMENCER, A Licensing Branch 2 80/06/27 11pp
- 8007230621 Summary of 800612 meeting w/Mark II owners group in Bethesda, MD re lead plant closure & long-term program Hoda should be made to generic lead plant condensation oscillation & chugging pool boundary leads Viougraphs encl ANDERSON, C. J. Generic Issues Branch 80/07/03 57pp
- 8007180285 Notification of 800711 meeting w/util in Bathesda. Mp to discuss certain problems w/facility review SECLS. P Licensing Branch 2 80/07/ii Spp
- 8007250471 Suggests 800904 meeting for presentation of info responding to NRC 800506 ltr re preliminary risk snallysis Lists info to be presented. be presented BOYER, V B Philadelphia Electric Co 80/07/21 ip
- 8007290178 Notification of 800809 meeting w/representatives from Mark If owners group in Chicago. It to discuss lead Mark II plants chugging & C/O load spacs ANDERSON.C Generic Issues Branch 80/07/23 Spp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800027 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action reffire protection for electrical calles EISENHUT.D O Division of Licensing 80/06/25 EI9pp
- H General correspondence
- 8007100272 Ack receipt of itr re const of facility. Station is not grosently under active review Ltr will be kept on file & returned when util application for DL review is initiated. SCHWENCER, A Litensing Branch 2 80/06/23 ip
- --B007i002B9 Requests that NRC reconsider opening facility PA has not improved radiation monitoring or emergency response since TMI Berious nucleor accidents can & will happen Homeowner insurance does not cover loss of life or damages CLARK.C Affiliation Unknown 80/06/23 2pp
- 8007110510 Responds to 800409 ltr re const of facility Environ & safety reviews will begin when util submits application for OL. Ltr will be kept on file & referred to again when review initiated
 SCHWENCER, A Licensing Branch 2 80/04/23 2pp
- BO07140444 Forwards BO0428 torrespondence to President Carter, Onvernor Thomburgh, Benators Bihweiker & Heinz, Representative Laderer, Btate Senator Funo, State Representative Rappaport & NRC re halting Facility const HAMKINS, K L. Pennsylvania, State of 80/06/28 7pp
- 8007180345 Responds to itr re const of facility Ltr will be kept on file & referred to when NRC initiates OL review Facility will not be under active review until util submits DL application in late 1980 or early 1981 SCHMENCER.A Licensing Branch 2 80/07/01 ip
- 8007250004 Ack receipt of ltr re const of plant Plant not under active review Public comments will be considered during review SCHWENCER.A Licensing Branch 2 80/07/14 Ip

8007250475 Responds to 800630 ltr to NRC re const & operation of facility NRC welcomes citizen ltrs & takes them into consideration during environ & safety reviews Facility will not be reviewed until OL application is received BCHMENCER, A Licensing Branch i 80/07/15 2pp

I Financial information

- BOO701013B Responds to 800405 ltr to 0 Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial incom stancy identified CHRISTENBURY, E Hearings Division 80/06/19 ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7904120321 Rept on Zimmer Unit i Requests to be informed of NRC acceptance criteria & vaporization rate test results Considers NRC methodology of load combination acceptable CARBON.M W ACRS Advisory Committee on Reactor Safeguards 79/03/13 3pp
- Q Inspection reports. IE Bulletins & correspondence
- B007140469 Forwards IE Bulletin B0-13, "tracking in Core Spray Spargers " No written response required GRIER,B M Region 1, Philadelphia. Office of the Director B0/05/12 1p
- 8007010258 Forwards IE Info Notice 80-23, "Loss of Buction to Emergency Feedwater Pumps " No written response required GRIER, B M Region 1, Philadolphia, Office of the Director 80/05/29 1p
- 8007210604 Forwards IE Info Notice 80-24, "Evaluation of Contractor QA Programs " No written response required ORIER, 8 H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- BOO7140280 Forwards IE Bulletin 80-14, "Dagradation of BUR Scram Discharge Vol Capability " No written response required ORIER,B H Region 1, Philadelphia, Office of the Director BO/06/12 1
- 8007280608 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/06/13 1p
- BOO7020516 Forwards 1C Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response regulred. ORIER, B M Region 1, Philadelphia, Office of the Director BO/06/20 1p
- 8007160728 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER'S H Region 1, Philadelphia. Office of the Director 80/06/24 ip
- SOO7210225 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/06/25 ip
- E007210312 Ack receipt of 800410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-12 & 50-353/79-11 ORIER.B H Region 1, Philadelphia, Office of the Director 80/06/26 2pp
- --B007210321 Responds to NRC B00312 ltr re violations noted in IE Insp. Repts 50~352/79-12 & 50~353/79-11 Corrective actions uncontrolled copies of pipe support drawing removed from field KEMPER.J S Philadelphia Electric Co B0/04/10 3eo
- --B00721032& Forwards 1E Insp Repts 50-352/79-12 & 50-353/79-11 on 791120-30 & 1203-21 & notice of violation CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch B0/03/12 2pp
- --B007210330 Notice of violation from insp on 791120-30 & 1203-21 * Region 1. Philadelphia. Office of the Director 80/03/05 2pg

- ~~8007210338 IE Insp Repts 50~352/79~12 & 50~353/79~ii on 791120~30 & i203~2i Noncumpliance noted failure to rontrol design documents for misonry walls & failure to provide QA program for masonry wall subcontractors
 MATTIA-J C Region I. Philadelphia. Office of the Director MCGAUGHY.R W Region I. Philadelphia. Reactor Construction & Engineering Support Branch B0/03/05 15pp
- 8007230157 Forwards IC Bulletin 80-14. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Elther A or D Output Codes " Hritten response required IE Circular 80-16 also encl No written response required ORIER. B H. Reyjon 1 Philadelphia, Office of the Director 80/06/27 2pp
- 8007210567 Responds to IE Bulletin 80-08 Flued heads which are butt welded to containment penetration sleeves used in both units ASME Code, Section 111.1974 through Winter 1974 addends.applied
 KEMPER.J S Philadelphia Electric Co 80/07/02 7pp
- 6007210206 Ack receipt of 800623 ltr informing NRC of steps taken to refrect violations noted in IE Insp Repts 50-352/80-03 & 50-353/80-03 CARLEGOR T Region 1, Philadelphia, Reactor Construction & Engineering Support Br
- --8007210214 Responds to NRC 800526 ltr re violations noted in IE Insp Repts 90 382/80-03 & 50-351/80-03 Corrective actions 9A issued stop work orders on pipe restraint PR-239 KEMPER, J S Philadelphia Electric Co 80/04/83 2gp
- --800721022i Forwards 1E lnsp Repts 50-352/80-03 & 50-353/80-03 on 800225-0325 & notice of violation CARLSUN,R T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/26 2pp
- --8007210230 Notice of violation from insp on 800225-0325
 * Rogion 1, Philadelphia, Office of the Director 80/05/21 ip
- --8007210240 IE Insp Repts 50-332/80-03 & 50-35J/80-03 on 800225-0325 Noncompliance noted failure to preheat weld joint prior to welding HATTIA-J C , FINKEL,A Region 1, Philadelphia, Office of the Director MCGAUGHY.R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch BO/05/21 15pp
- 8 Reportable occurrences. LFRs & related correspondence
- B007020155 Forwards summary of B00227 meeting w/util to discuss reporting requirements of significant design & const deficiencies Nu reply requested CARLSON, R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch B0/05/2/ ip
- --8007020164 Summary of 800227 meeting w/util in Region 1 ofc to discuss reporting requirements of significant design & const deficiencies

 4 Region 1. Philadelphia. Office of the Director 80/02/27 2pp
- 8007210013 Ack receipt of 800606 final deficiency vept re heating, ventilation & air conditioning damper Rept will be reviewed & evaluated CARLEON, R.T. Region 1, Philodelphia, Reactor Operations Nuclear Support Branch 80/06/25 in
- 8007240226 Part 2) rept re defertive Hosemount trip/calibr units & transmitters supplied by GE Caused by failure of essential switch that determines trip output logic Output of defective units will be corrected per GE instructions

 KEMPER.J S Philadelphia Electric Co 80/07/03 Spp
- 8007250152 Part 21 rept re defective GF crimp pins in electrical connectors Cause not stated Enri GE rept states that GA pracedures have been modified to preclude defective crimping in futuru

 KEMPER J S Philadelphia Flectric Co 80/07/01 7pp
- 8007090265 Deficiency ropt is Colt Industries emergency diesel generator heat exchangers Deviation between configuration of high heat exchanger stack un generator skid & configuration analysed in seismic ropt detected KEMPER.J S Philadelphia Electric Co 80/07/02 2pp
- ---8007090270 Part 21 rept re Colt emergency diesel generator heat sichangers Deviation between configuration of high heat exchanger stack on generator skid & configuration analyzed in seismic rept debocted MORIARTY, J M Colt industries, inc 80/01/16 ip

- --BOO7090275 Part 21 rept re Colt emergency diesel generator heat exchangers Units & & 7 have been corrected by fitting shims at bolted interface between generator skid & heat exchanger mounting feet HORIARTY. J M (olt Industries, Inc. 80/06/13 ip
- 8007250287 Ack receipt of 800620 final deficiency rept re 4 kV switchgear circuit breaker ausiliary switch crank assembly defect CARLSON.R T Region i. Philadelphia. Dffice of the Director 80/07/03 ip
- 8007310281 Ack receipt of 800701 final deficiency rept re defective crimps in electrical connectors CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 ip
- --8007310286 Significant Deficiency Ropt 14 re defective crimps in electrical connectors 0E rept submitted per 10CFR21 provides detailed site insp info Rept enc) KEMPER,J S Philadelphia Electric Co 80/07/01 2pp

U Congressional/Executive Correspondence

- 8004280239 Requests appearance on behalf of subcommittee to testify on issues re emergency planning procedures & preparedness along wimplications of lessons learned from accident at IMI Hearing scheduled for 800527 UDALL.M K House of Rep . Interior & Insular Affairs 80/04/16
- 8007/10338 Responds to 800604 ltr expressing concerns about testimony of V Boyer, util Senior Vice President HR Denton will meet w/ Boyer on 800630 to discuss matter in greater detail DIRCKS, W J Deffice of the Esecutive Director for Operations 80/06/30 ip
- --BOD7110343 Requests that NRC seriously consider attitudes expressed by util during 800527 testamony & determine whether or not CP is consistent w/public health & safety KOSTMAYER.P H . MARKEY.E J House of Rep 80/06/04 3pp

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007010561 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation effective 800428 Considerations of activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications.as derived from NUREG-0660 & found in NUREG-0674 EISENHUT,D G Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-QS for Hope Creek & 33-54237-QS for River Bend reflecting documentation of electrical equipment qualification Repts withheld (ref 10CFR2 790)

 DUVALL.D D Gould-Brown Bevera 80/07/01 1p

G Adjudicatory correspondence

- B007080086 Proposed findings of fact & conclusions of law responding to ASLAE questions on Battelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges suspension of QLs Certificate of Sec enci
- 8007080046 Response to ASLAB request re Deficiency 1 Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- 800708004B Proposed findings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Perkins rationale & urges development of further evidence re failure mechanisms & human factors CAPLAN, R Ecology Action of Oswego 80/05/20 4pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Ø Division of Licensing 80/06/25 89pp

- B0070B0001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ASLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BDRDENICK. B M Hearing Branch 4 80/07/03 58pp
- --8007080003 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp
- --8007080006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order Inclusion is consistent w/ALAB-509.4LAD-340 & ALAB-362 Certificate of 8vc encl BORDENIC.X Hearing Branch 4 80/07/03 7pp
- 8007100258 Order granting Ecology Action of Oswego motion to file 800620 submission re generic radon issue BIEHOP,C J Atomic Safety and Licensing Appeal Panel 80/07/07 200
- 800731012B Response in opposition of NRC B00703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLAN.R Ecology Action of Oswaga 80/07/16 13pp
- 8007280353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fact submitted by other parties filed on 800718 Revised pages required to correct typographical errors Evc list encl TRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbriggs 80/07/21 10pp

H General correspondence

- 8007180060 Responds to 800311 request for info needed for fuel cost study Forwards excerpts of WASH-740.WASH-1226, HASH-1230, HASH-1400.NUREG-0020 (Vol 4, Number 1), NUREG-0480.NUREG-0512, NUREG-0517, NUREG/CR-1060 & FEB DENTON.HR Office of Nuclear Reactor Regulation, Director 80/05/14 153pp
- ---8007180063 Requests documents containing info needed for fuel cost study HILGER,W Affiliation Unknown 80/03/11 2pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I gumers group in Bethesda, MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-torm program GRIMES, CT Plant Systems Branch 80/02/21 3ipp
- Q Inspection reports. IE Bulletins & correspondence
- 8007140431 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers " No written response required ORIER.B H Region I. Philadelphia, Office of the Director 80/05/12 ig
- 8007010271 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps." No written response required GRIER, D. H. Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 800717026B Forwards IE Insp Ropts 50-354/80-03 & 50-355/60-03 on 800303-28 No noncompliance noted CARLBON.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007170274 IE Insp Repts 50-354/80-03 & 50-355/80-03 on 800303-28. No noncompliance noted Major areas inspected weld rod control, stored equipment maint, structural steel welding & electrical work status
 BATEMAN, W. H. , MCGAUGHY, R. W. Region 1, Philadelphia, Office of the Director 80/05/28 8pp
- 800721030B Forwards IE Insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 27 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/04 Epp
- --8007210309 IE Insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 29
 No noncompliance noted Major areas inspected noncompliance control trend analysis & control of field change request.
 CHAUDHARY, S K Region 1, Philadelphia, Office of the Director EDNETER, S.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/23 App

- BOO7210512 Forwards IE Info Notice 60-25, "Evaluation of Contractor GA Programs " No written response required GRIER.8 H. Region 1, Philadelphia, Office of the Director 80/05/10 1p
- BO07140284 Forwards IE Bulletin BO-14, "Degradation of BHR Stram Distharge Vol Capability " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director BO/06/12 1p
- BO07280614 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required ORIER.D H Region 1, Philadelphia, Office of the Director BO/06/13 ip
- 8007300317 Forwards 1E Insp Repts 50-354/80-08 & 50-355/80-08 on 800512-16 No noncompliance noted CARLBON R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/13 2pp
- -8007300321 IE Insp Repts 50-354/80-08 & 50-355/80-08 on 800512-16 No noncompliance noted Major areas inspected welding matl control. reactor vessel nozzle/safe-end field change welding & safety-related pipe welding REYNOLOB.S D Region i. Philadelphia, Office of the Director TRIPP LE Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 8pp
- 8007280242 Forwards IE Insp Repts 50-354/80-05 & 50-355/80-05 on 600421-25 No noncompliance noted CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/16 Zpp
- --8007280246 IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted Major areas inspected roactor vessel nostle safe and field changes & welding of safety-related piping REYNOLDES D Region i. Philadelphia, Office of the Director TRIPPL E Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 Spp
- B007170654 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-354/80-02 & 50-353/80-02 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/17 ip
- --8007170665 Forwards IE Insp Repts 50-354/80-02 & 50-355/80-02 on 800204-29 & notice of violation CARLEON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8007170670 Natice of violation from insp on 800204-29
 * Region i, Philadelphia, Office of the Director 80/03/19 2pp
- --8007170682 IE Insp Repts 50-354/80-02 & 50-355/80-02 on 800204-29 Noncompliance noted failure to establish measures to maintain cleanliness of relief valve piping stored in suppression chamber & to maintain weld rod control BATEMAN.H H. MCOAUCHY.R W Region I, Philadelphia, Office of the Director 80/03/19 9pp
- BO07020503 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/06/20 1p
- 8007160737 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- B00721027B Forwards IE Info Notice 80-24, "Low Level Radwaste Buriai Criteria." No written response required GRIER,B H Region I. Philadelphia. Office of the Director B0/06/25 lp
- 8007210276 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80~02 & 50-355/80-02 CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/27 ip
- --8007210282 Responds to NRC 800324 ltr re violations noted in 1E Insp Repts 50-354/80-02 & 50-355/80-02 Corrective actions documented interline cleanliness & hired GC inspector MARTIN.T.J Public Service Electric & Gas Co of New Jersey, 80/05/28 2pp

- 8007230170 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.D M Region i, Philadelphia, Office of the Director 80/06/27 2pp
- 8007250279 Submits reply to IE Builetin EO-OB re containment liner penetration welds No flued heads have been installed to date Joints are considered Class II & radiography will be performed MARTINIT J Public Service Electric & Gas Co of New Jersey BO/07/02 2pp
- B Reportable occurrences. LERs & related correspondence
- 8007310289 Ack receipt of 800625 interim deficiency rept re primary containment relief valves supplied by OPE Controls CARLSUNR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 ip
- --8007310293 Potential significant deficiency rept re primary containment relief valves supplied by GPE Controls Bechtel has completed review of revised stress analysis calculations Expected completion date of actions is 800815 MARTIN.T J Public Service Flectric & Oas Co of New Jersey 80/06/23 lp
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B00723002B Summary of 800207 meeting w/Mark 1 owners group in Dethesda. HD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007010561 Forwards NRC reorganization chart for DFc of Nuclear Reactor Regulation, effective 800428 Considerations of activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO, R L Assistant Director for Licensing 80/06/13 3pp
- 8007230001 Forwards statement of policy re requirements to be mot for current OL applications, as derived from NUREG-0660 & found in NUREG-0874 EIGENHUT, D 9 Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-08 for Hope Creek & 33-54237-08 for River Send reflecting documentation of electrical equipment qualification Repts withheld (ref 10CFR2 790)

 DUVALL, D D Gould-Brown Boveri 80/07/01 ip

Q Adjudicatory correspondence

- 8007080086 Proposed findings of fact & conclusions of law responding to ABLAB questions on Battelle rept Findings are adopted by TNI-2/Peachbottom Intervenore & Ecology Action Urges suspension of OLs Certificate of Boy encl
 KEPFOHD.C Environmental Coalition on Nuclear Power 80/06/18
- BO07080044 Response to ABLAB request re Deficiency i Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN.R Ecology Action of Oswegu 80/06/20 2pp
- 8007080048 Proposed Findings of fact endorsing Citizens for Bafe Environ filing to radiation source terms from V mining & milling Rejects Porkins rationale & urges development of further evidence re failure mechanisms & human factors CAPLAN.R Ecology Action of Oswego 80/06/20 4pp
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order ICES 771104 potition sought action re fire protection for electrical cables EISENRUT.D & Division of licensing 80/06/25 B3pp
- 8007080001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ABLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK, B M Hearing Branch 4 80/07/03 58pp
- --B0070B0003 Proposed corrections to 800226 transcript
 BORDENICK, B H Hearing Branch 4 80/07/03 2pp

- --8007080006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of isw presented in form of memorandum & order Inclusion is consistent u/ALA8~ 509. ALA8-50 & ALA8-56 Certificate of Svc enci BORDENIC, K Hearing Branch 4 80/07/03 7ap
- 8007100258 Order granting Ecology Action of Osbego motion to file 800820 submission re generic radon 16800 BISHOP, C.J. Atomic Rafety and Licensing Appeal Panel 80/07/07
- 8007310128 Response in opposition of NRC 800703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLANAR Ecology Action of Oswego 80/07/16 13pp
- 8007250353 Forwards revised Pages 7 & 16 to incenses reply to proposed findings of fact submitted by other parties filed on 800718 Revised pages required to correct typographical errors Svc list enci YRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge 80/07/21 10pp
- H General correspondence
- 8007180060 Responds to 800311 request for info needed for fuel cast study Forwards excerpts of WASH-740, WASH-1224, WASH-1250, WASH-1400, NUREG-0020 [Vol 4, Number 1); NUREG-0480, NUREG-0512, NUREG-0517, NUREG-
- --8007180063 Requests documents containing info needed for fuel cost study HILGER:W Affiliation Unknown 80/03/11 2pp
- O Inspection reports. IE Bulletins & correspondence
- 8007140431 Forwards IE Bulletin BO-13. "Cracking in Core Spray Spargers " No written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/05/12 ip
- 8007010271 Forwards IE Info Notice 80-23, "1.055 of Suction to Emergency Feedwater Pumps" No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/05/29 ip
- B007170269 Forwards IE Insp Repts 50~354/80-03 & 50-355/80-03 on 800303-28 No noncompliance noted CARLSON R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- ~-8007170274 IE Insp Repts 50-354/80-03 & 50-355/80-03 on 800303-28 No noncompliance noted Hajor areas inspected weld rod control, stored equipment maint, structural steel welding & electrical work status
 BATEMAN, W H . MCGAUGHY, R W Region J, Philadelphia, Office of the Director 80/05/28 8pp
- 800721030B Forwards 1E insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 29 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/04 2pp
- B007210612 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs "No written response required GRIER. BM Region I, Philadelphia, Office of the Director B0/06/10 Ip
- 3007140284 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required GRIER. B H Region 1. Philadelphia. Office of the Director BO/06/12 ip
- 07290614 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required SRIER.B H Region I. Philadelphia, Office of the Director. 30/06/13 1p

- 8007300317 Forwards IE Insp Repts 50-354/80-08 & 50-355/80-08 on 800512-16 No noncompliance noted CARLSON,R T Region i, Philadeiphia, Reactor Construction & Engineering Support Branch 80/06/13 2pp
- --8007300321 IE Insp Repts 30-354/80-08 & 50-355/80-08 on 800512-16 No noncompliance noted Major areas inspected welding matI control reactor vessel nozzle/safe-end field change welding & safety-related pipe welding REYNOLDS.S D Region 1. Philadelphia, Office of the Director TRIPF L E Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 8pp
- 8007280242 Forwards IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted CARLSON,R T Region I. Philadelphia, Reactor Construction & Engineering Support Dranch 80/06/16 2pp
- --8007280246 IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted Major areas inspected reactor vessel nozzle safe end field changes & welding of safety-related piping REYNOLDS.8 D Region i. Philadelphia. Office of the Director TRIPP.L E Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/12 5pp
- 8007170654 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-354/80-02 & GARLSON,R 7 Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/17 1p
- --8007170665 Forwards IE Insp Repts 50-354/80-02 & 50-355/80-02 on 800204-29 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8007170670 Notice of violation from insp on 800204-29
 * Region 1. Philadelphia, Office of the Director 80/03/19 #2pg.
- --B0071706B2 IE Insp Repts 50-354/B0-02 & 50-355/B0-02 on 800204-29 Noncompliance noted failure to establish measures to maintain cleanliness of relief valve piping stored in suppression chamber & to maintain weld rod control BATEMAN, W.H., MCGAUGHY, R.W. Region 1, Philadelphia, Office of the Director, B0/03/19 9pp
- 8007020503 Forwards IE Circular 80-13, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ORIER.1 H Region 1, Philadelphia, Office of the Director. 80/06/20 ip
- B007160737 Forwards IE Circular 80~14, "Radioactive Contamination of Plant Deminsralized Water Sys & Rasultant Internal Contamination of Personnel " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/06/24 ip
- 8007210278 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- B007210274 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 GARLSONR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/27 19
- --8007210282 Responds to NRC 800324 Itr re violations noted in IE Insp Repts 50-384/80-02 & 50-355/80-02 Corrective actions documented interline cleanliness & hired GC Inspector HARTINIT J Public Bervice Electric & Qas Co, of New Jersey 80/05/28 2pp
- B007230170 Forwards IE Bulletin B0-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ORIER,B H Region i, Philadelphia, Office of the Director G0/06/27 2pp
- 8007250299 Submits raply to IE Bullstin 80-08 re containment liner penetration wolds No Flued heads have been installed to date Joints are considered Class II & radiography will be parformed MARTIN, T J Public Service Electric & Gas Co of New Jersey 80/07/02. 2pp

- 8 Reportable occurrences, LERs & related correspondence
- 8007310289 Ack receipt of 800625 interim deficiency rept re primary containment relief valves supplied by GPE Controls CARLSON R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 ip
- --B007310293 Potential significant deficiency rept re primary containment relief valves supplied by OPE Controls Bechtel has completed review of revised stress analysis calculations Expected completion date of actions is B00815

 MRRTIN-T J Public Service Electric & Gas Co of New Jersey B0/06/25 ip
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- B007170644 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Ragion 3, Chicago, Office of the Director 80/06/24 in
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007020232 Forwards NRC Ofc of Nuclear Reactor Regulation 600428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- BO07030239 Notification of B00702 meeting w/BWR licensing review group in Bethesda.MD to discuss consensus position on reactor syc bldg open issue
 HILBON.J N Licensing Branch i B0/06/iB 9pp
- B007010297 Bummary of 800613 meeting w/utils, KMC, Inc. GE, Bechtel, S&W & Sargent & Lundy in Bethesda, MD re consensus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Balle docket Status repts enc!
 WILSON, J N Assistant Director for Licensing 80/06/19 46pp
- BOO7210176 Forwards NRC evaluation of GE rept,NEDE-24010-P & Suppls 1-3, "Technical Basis for Use of Square-Root-of-Sum-of-Equares (SRES) Kethod for Combining Dynamic Loads for Mark II Plants " Rept acceptable subj to certain constraints MATTSON,R J Division of Bafety Technology 80/06/25 Opp
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0644
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- BOO7170475 Summary of BOO613 meeting w/Mark II load plant applicants ps definition of T-quencher load spec following safety/relief valve actuation Virwgraphs encl BU.T H Containment Systems Branch 60/06/27 App
- 8007230252 Bummary of 800613 meeting w/Mark II lead plant applicants re methodology proposed by applicants to define T-quenther load spac following safety relief valve actuation New methodology will be applicable to all Mark II lead plants BU.T M Generic Issues Branch 80/06/27 3pp
- BOO7080317 Submits comments in response to NRC 800307 ltr & NUREG-0619, re mods to BWR control rod drive sys NRC position recutting, capping & rerouting control rod drive not applicable to facility Voices concern on insp time required BORGMANN, E A Cincinnati Gas & Electric Co 80/06/30 2pp
- S007170339 Notification of rescheduling of B00702 meeting w/BWR licensing review group in Bethesda, MD to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for B00709 HILSON, J N Assistant Director for Licensing 80/07/03 1p
- --8007170347 Notification of 800722 meeting w/BWR licensing review group in Bethesda, MD to discuss TMI issues required for OL issuance
 WILBON, J N Assistant Director for Licensing 80/07/03 ip
- --8007170351 Notification of 800724 meeting w/BHR licensing review group in Bethesda, MD to introduce BHR licensing review group & present consensus positions for Power Sys Branch, Containment Sys Branch & Equipment Qualification Branch & Equipment Qualification Branch & HILSON, J N Assistant Director for Licensing 80/07/03 9pp

- 8007230621 Summary of 800612 mouting w/Mark 11 owners group in Bothosds.MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON.C J. Generic Issues Branch 80/07/03 5/pp
- BO07280123 Summary of 800624 meeting w/util % Sargent & Lundy in Bethesda,MD re briefing on results of investigation & corrective actions on sv. water pump naise & vibration & silt & bildup in intake structure
 PELTIER,I A Licensing Branch 2 80/0//15 Sépp
- B007230133 Notification of B00775 meeting w/BUR Licensing Review Oroup in BethesdarMD to discuss curcensus posttions of BUR Licensing Review Group on ICSB open issues WILBON-J N Licensing Branch 1 80/07/16 10pp
- BD07220280 Forwards drawings re Category 1 masonry wails, per NRC request for add1 info Oversize drawings available in Central Files only FLYKN, J D Cincinnati Gas & Flectric Co 80/07/18 1p
- 8007290175 Notification of 800805 meeting w/iepresentatives from Mark II numers group in Chicago.IL to discuss lead Mark II plants chugging & C/D load spers ANDERSON.C Generic Issues Branch 80/07/23 2pp
- F Security, medical, emergency & fire protection plans
- B00707025B Forwards Amend 107, Revision 10 to sudustrial security plan Plan withheld (ref 10CFR2 790) B0RGMARN.E A Cincinnate Gas & Electric Co 80/07/03 2pp
- O Adjudicatory correspondence
- BOO7110094 Contentions per discussions w/HRC & applicant re GL application Alloges absence of adequate communication sys for coordination & direction of evacuation Certificate of Svc encl
 DENNISON.A B Zimmer Area Citizens Zimmer Area Citizens of KY DENNISON.A B Dennison.A B BO/O5/13 15pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENRUT.D G Division of Licensing 80/06/25 87pp
- 8007080209 Memorandum & order granting Zimmer Area Citizens petition to intervene & subjecting contentions to LNP-E0-14 discovery schedule Modifies LBP-80-14 re admittance BECHHOEFER, C Atomic Bafety and Licensing Board Panel 80/07/02 10pp
- 8007110330 Order granting extension until 800715 for Commission to elect whether to review ALAB-195
 HDYLE.J C Office of the Secretary of the Commission 80/07/09
- 8007220569 Motion & memorandum speking admission of add1 contentions Questions applicant financial capabilities & alleges errors in FES.NURE9-0629 Pricess used for cost/benefit analysis is contrary to NEPA Certificate of Suc encl MOLIVER, J Frankhauser, D D MOLIVER, J Woliver, J D BO/07/16
- K Utility Final Safety Analysis Report (FSAR) & amends
- B007140349 Forwards Revision 66 to F9AR submitted as Amend 108 to 01 application in response to NRC 791812 % 2/ & 900117 ltrs B0RGMANN E A Cincinnati Gas & Electric Co 90/07/11 2pp
- --8007110377 Revision 64 to FBAR, submitted as Amend 108 to DL application

 * Cincinnati Gar % Electric Cn 80/07/11 35pp
- BOO7210424 Furwards Certificate of Svt of Amend 108 to applications for OLs, in form of Revision 66 to FSAR BOROMANN, E A Cincinnati Gas & Electric Co 00/07/15 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007140554 Folwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required KEPPLER, J. 0 Region 3, (hicago, Office of the Director 80/05/12 to

- BOO7110477 Forwards lE Insp Rept 50-358/80-10 pn 80050in02 No moncompliance noted FIORELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/27 2pp
- 8007020034 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/28
- 800701007: Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps." No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/29
- 8007220176 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/10
- 8007240236 Forwards 1E Insp Rept 50-358/80-12 on 800501-02,05-09,12-16, 19-23 & 27-30 & notice of violation HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/10 2pp
- --- 8007240240 Natice of violation from insp on 800501-02,05-09,12-16, 7-23 & 27-30

 Region 3, Chicago, Office of the Director 80/05/06 Ip
- --8007240253 IR Insp Rept 30-258/80-12 on 800501-02,05-09,12-16,19-23 & 27-30 Noncompliance noted failure to control cleanliness of cable trays
 DANIELB,F T , TAMBLING, T N Region 3, Chicago, Office of the Director 80/06/06
- 8007010084 Forwards info to complete response to IE Bulletin 79-02.

 "Pipe Bupport Base Plate Designs Using Concrete Expansion
 Anchor Bolts " Encl lists supports for essential & seismic
 namessantial piping sys supported by expansion anchor bolts
 BOROMANN.E A Cincinnati Gas & Electric Co 80/06/11 2pp
- 80071404D: Forwards IE Sulletin BO-j4, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/12
- 8007230072 Forwards 1E Insp Rept 50-358/80-13 on 800513:14 & 23 & notice of violation FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- --- BD07230078 Notice of violation from insp on B00513,14 & 23 B Region 3, Chicago, Défite of the Director B0/06/11 B0/06/11 1p
- --B007230087 IE Insp Rept 50-358/80-13 on 800513.14 & 23 Noncompliance noted inadequate design consideration for pipe whip restraint connection bolts
 DANTELSON, DH. Region 3. Chicago, Reactor Construction & Engineering Support Branch YIN, 1 T Region 3. Chicago, Office of the Director 80/06/11 4pp
- BO07280657 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(g)" No written response required KEPPLER, J G Region G. Chicago, Office of the Director 80/06/13
- 8007020355 Forwards iE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown " No written response Faquired MEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/20
- 8007170459 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required REPPLER.J G Region 3, Chicago, Office of the Director 80/06/24

- 8007230307 Forwards IE Bulletin 80-14, "Potential Misapplication of Resembunt Inc Models 1151 & 1192 Pressure Transmitters Welther A or D Dutput Codes " Whitten response required IE Circular 80-16 also encl No written response required XEPPLER.J O Region S. Chicago, Office of the Director 80/06/27.
- 8007190102 Ark receipt of 800603 ltr informing NRC of stops taken to correct violations noted in IE Insp Rept 30-358/80-08 HEISHMAN:R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/20 2pp
- --B0D715010B Responds to NRC B00513 ltr re violations noted in IE Inep Rept 50-35B/80-0B Corrective actions nuclear engineering procedure revised requiring fuel assembly location verification & that insp & inventory records be microfilmed BORGMANN, E.A. Cincinnati Gas & Electric Co. B0/06/03. 4pp.
- 8007210313 Responds to NRC ltr re violation noted in IE Insp Rapt 50-358/80-12 Corrective actions debris & rubbish removed & cleaning crews assigned to reactor & auxiliary bidgs on westly schedule BOROMANNE A. Cincinnati Oas & Electric Co 80/06/30 2pp
- B007250616 Supple B00321 response to IE Bulletin R0-03 re loss of chercoal from std adsorber cells Perforated plates connected to both top & bottom plates w/continuous weld, precluding any possibility for charcoal leakage.
 BDROMANN,E A Cincinnati Gas & Electric Co. 80/06/30 2pp.
- BOO70B0374 Requests exception to requirement of ABME, Rection XI, 1974 edition re preservice insp program. Surface exam will be substituted for volumetric exam on piping support shear lugs welded by full penetration welding to Clase I piping.

 BOROMANN, E A Cincinnati Gas & Electric Co. BO/07/Oi, Spp.
- BOO7R50576 Responds to IE Bulletin 80-08 re exemination of containment liner genetration welds. Joint detail on Penetration Types 38.4A-C.E & 5 does not parmit meaningful radiographic insp. due to more complex geometry BOROMANN.E A Cincinnati Cas & Electric Co 80/07/07 41pp.
- B007280096 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ABME 8A-312. Type 304 Stainless Steel Fipe." 8A-312 or A-312. Type 300 series fusion welded tipe are not used at facility All BA-312 or A-312 piping used is seamless B0R0MANN.E A Cincinnati Gas & Electric Co 80/07/08, lp.
- 8007R10297 Ack receipt of 800430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-12. HEISHHAN, F. Region S. Chicego, Reactor Operations Nuclear Support Branch 80/07/11 lg
- -8007210302 Responds to NRC 800610 ltr re violations noted in IE Insp Rept 50-358/80-12 Corrective actions cleanup crews dispatched to remove cable pan debris BOROMANN, E A Cincinnati Gas & Electric Co 80/04/30. 2pp.
- BO07230437 Forwards response to IE Bulletin BO-11 re Category I contrets mesonry walls Hells are not subjected to wind, tornado, missile, pips whip restraint or impingement loads. Drewings forwarded under separate cover BOROMANN, E A Cincinnati Que & Electric Co 80/07/18 18pp.
- 8 Reportable occurrences, LERs & related correspondence
- 8007020324 Ack receipt of 800527 interim deficiency rept re walds rejected upon radiographic review. FiDRELLIG. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/04/17 ip
- 8007110238 Ack receipt of 800611 ltr par 10CFR50.58(e) re fire in Gould-Brown-Boveri motor control ctr Review will be completed during future insp FIDRELLI.9 Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/06/19 ip
- 8007150029 Ack receipt of 800611 interim deficiency rept re failure of power shield releas Will review finel rept upon receipt. FloRELLI.9 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/24 ip
- 8007180503 Ack receipt of 800527 final deficiency rept re design deficiencies Review will be completed during future inag FIGRELLI.G. Region 3, Chicago, Reactor Construction & Engineering Busport Branch 80/07/08 ip

- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B007010560 Forwards NRC reorganization chart for Dfc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representative Areas of disagreement may be discused through informal appeal TRDEBCO, R L Assistant Director for Licensing 80/06/13 2pp
- 8007070421 Bummary of 800528 meeting w/NRC consultant.Energy Technology Engineering Ctr.& applicant in Whittier.CA re Mechanical Engineering Branch open items re FSAR Draft safety evaluation.agenda & attendance list encl R000.#% Licensing Branch 3 80/06/16 24pp
- 8007020208 Nutification of 800702 meeting w/util in Bethesda.ND to discuss control room design review program RODD: H Licensing Branch 2 80/06/23 3pp
- GOO7020673 Requests addi info to define underclad cracking potential in reactor vessel norrles Ultrasonic exams did not indicate explicit correlation between observed cracking & pre/post-heat treatment Info required within two weeks GCHWENCER, A Licensing Branch 3 80/06/24 4pp
- BO07010479 Forwards affidavit of svc attesting to completion be distribution of responses to NRC financial analysis Guestions 1-9
 BASKIN, K P Southern California Edison Co BO/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D O Division of Licensing 80/06/26 2pp
- B00701035B Forwards "Preliminary Rept on Groingic Drilling & Investigation San Onofre Nuclear Cenerating Station Units 2 & 3 & 61 geophysical maps (interpretations) prepared by PJ Fischer of CA State Univ eni BASKIN.K P Southern California Edison Co 80/06/27 1p
- --B007010364 "Preliminary Rept on Geologic Drilling & Investigation San Gnofre Nuclear Generating Station Units 2 & 3 " BANNEICH. J A , BROGAN, Q E Woodward-Ciyde Consultants, Inc B0/06/27 47pp
- --8007010374 Sixty-one 3 5 kHz high respiction seismic lines List of # California State Univ. Northridge 80/06/09 62pp
- GOO7090234 Urgss extension of comment period for NUREC-0377 & 800319 amend until 800915 More stringent requirements, broader applicability & EPRI study results warrant addl time QILMAN, D W San Diego Gas & Electric Co 80/00/30 ip
- G007230635 Forwards std order for DDE work MATTEDN.R. J Division of Safety Technology FIN A-1121-0 U0/06/30 3pp
- --8007230652 Std order for DOF work "Review of Auxiliary Feedwater Sys Reliability Evaluation Studies for Diable Canyon I. McOuire I.Summer I & Ban Onofre 2 & ECCS Reliability Analysis of Manual vs Automatic "Issued to Sandia Labs ORENIER. B L Division of Safety Technology FIN A-1121-0 B0/06/27 9pp
- BOO7080081 Forwards response to NRC Question 361 65 in geoscience area Also forwards Woodward Clyde Consultants "Preliminary Rept on Geologic Drilling & Investigation Songs,Units 2 & 3, Ean Onofre,CA"

 BASKIN,K P Bouthern California Edison Co 80/07/01 18pp
- --8007080083 "Preliminary Rept on Spalagic Drilling & Investigation Songs, Units 2 & 3, San Onofre, CA " * Woodward-Clyde Consultants, In: 80/07/Q1 40pp
- BOO7170693 Advises of NRC acreptance of Amend 3 to Topical Rept. BCE-1-A, "GA Program " Topical rept must be referenced in Chapter 17 of SAR HAASS,W P Quality Assurance Branch 80/07/01 ip
- 8007210053 Natification of B00724 meeting w/util in Rosemead.CA to discuss results of Imperial Valley Oct 1979 earthquake analysis using Unit i analytical modeling technique RDOD. H. Licensing Dianch 3 80/07/11 70-

- 8007210463 Forwards supplemental calculations & Revision 1 pages to original calculations submitted to NRC on 800121 re design calculations of electrical tunnel BASKIN-K P Southern (alifornia Edison Co 80/07/16 39pp
- 8007280486 Ack receipt of NRC icoponace to Marine agreem Committee 791009 rept re facility radioingical monitoring program evaluation Detailed response will be submitted following mati review
 FISCHER, M L (allfornia, State of BO/07/18 ip
- B007290620 Forwards response to NRC B00624 request for info re potential for underclad crucking in reactor vessel noizles Noizle base mital math is SA-508 Class II Applicable math certification data sheets encl BASKIN K P Southern Cairbonna Edison Co 80/07/22 37pp
- BOO7310465 Forwards NRC review of Harine Review Committee rept to CA Coastal Commission on adequacy of plant radiological monitoring program M/b encl CHANDLER:L J Hearing Branch i 80/07/29 pp
- F Security, medical, emergency & fire protection plans
- 8007080271 Advises that revisions to safequards contingency plan will be submitted by 800718 BASKIN, K.P. Southern California Edison Co. 80/07/02 1p
- O Adjudicatory correspondence
- 8007030006 Responds to to 800519 itr % mailgram re NRC meeting practices on geology/seismology in Ol proceeding Future meetings will be held in convenient locations NRC unable to hunor request that meeting similar to 800520-21 be held CHANDLER.L. J. Hearing Branch 1 80/06/27 4pp
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fitre protection for electrical cobles E18ENHUT.D G Division of Licensing 80706/25 89pp
- B007090205 Proposes agenda for 800717 prehearing conference in response to ASLB 800624 order in OL proceeding CHANDLER.L.J. Hearing Branch 1 80/07/07 2pp
- 8007300359 Submits recommendations, on behalf of Southern CA Edison & San Diego Gas & Electric, for agenda items to be considered at prehearing conference to begin 800717 in San Diego, CA Related correspondence PIGVOYT, D R Chickering & Gregory 80/07/07 3pp
- B007140032 Forwards for consideration, applicant, NRC % Friends of the Earth et al 800627 precuted stipulation for extending response date to 800723 re applicants motion for summary disposition of Contentions to & 9 per M proceeding CHANDLER L J Hearing Branch 1 80/07/09 ip
- ---8007140034 Frecuted stipulation extending time to respond to applicant mutuum for summary disposition of dematering U feel cost contentions until 800727 U/proposed under PIODITO R Sauthern California Culson Co CHANDLER, L J Branch & WHARION R J Frend of the Earth 80/06/27 Hearing
- 8007210434 Forwards ruggrated new version of JA Patterson affidavit routin motion for summany displosition Return of affidavit w/signature & nutarisation requested if changes are suitable DAVISAL D. Hearing Branch 4 60/0//14 7pp
- 8007310470 Advises that NURLA-0694 transmitted to portion on 800716 Extra copies will be sent to partion when available M/n encl rept CHANDLER, L J Hearing Branch 1 80207, 78 1p
- H General correspondence
- 8007020181 Requests consideration of hasing Atomic Energy Council of Taiwan visit facility on biodera-09 council interested in observing wast may activity; to coperation will be major contribution to that exchange attendement LAFLEURIJ D. Assistant Director for international Cooperation Jpp B0/05/11

- Q Inspection reports. IE Bulletins * correspondence
- 9007230011 Notifies that 800110 response to IE Bulletin 79-13. Revision 2. Indicated util proposed utilizing ultrasonic examination techniques for importable indications as alternative to radiography Util withdraws proposed use of ultrasonics BASKEN, P. Southern California Edison Co. BU/03/04 ip
- 800725036: Responds to IE Builetin Su-OJ, "Loss of Charcoal from Std Type [1,2-lncm. Fray Adyurber (s]]s ' No charcoal adsorber cells he e hero received from manufarturer Charcoal adsorber fifters to be used are designed to prevent charcoal leakage BASKIN,K P Southern California Edison Co 80/03/31 1p
- 8007170530 Forwards iF Insp Repts 50-101/80-05 % 50-362/80-03 on 800324-27 No nanewelliance hoted SPENCER,0 S. Region 5 5% Fancisco. Reactor (onstruction & Engineering Support Branch 80/05/20 2pp
- ~~8007170539 [F lnsp Repts 50-361/80 05 % *0-362/80-03 on 800324-27 No noncompliance noted Major irvas in pected previous open items.cable installation & pipe supports & vestraints ECKHARPT J H. HERNANDFLO Region 5. San Francisco Office of the Director DDDDS:R T Region 5. San Francisco Reactor Construction & Engineering Support Branch 80/05/20 6pp
- 8007240088 Forwards response to NRC 870429 itr re violations & deviations noted during 800703-17 % 21-28 inspired constactivities Helding filler muth removed % dispositioned Bechtet work plan RC instructions revised PAPAV, L f Southern california Edison (o. 80/09/28 Spp.
- -8007240093 Ack recespt of 800528 itr informing NRC of steps taken to correct items in NRC 800428 ltr SPENCER.G S Region 5. Sun Francisco. Reactor Construction & Engineering Support Branch 80/07/11 to
- 8007300303 Responds to 1E Bulletin 80-05 re vacuum damage to chemical vol control syn tanks Table identifying syn 9 describing adequacy justification encl Tanks not currently protected with be provided widedquate protection prior to fuel load BASKIN.K P Southern California Edison Co 80/06/06 3pp
- B007220247 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required ENGELKEN,R H. Region 5. Sun Francisco, Office of the Director 80/06/10. Ip
- 8007160223 Forwards 1k Info Notice 80-27 "Degradation of Reactor Coolant Pump Studs No specific action or response required O'REILLY J.P. Region 2. Atlanta, Office of the Director 80/06/11
- 8007020131 Ack receipt of 800528 its informing NRC of steps taken to correct violations noted in IF lnsp Repts 50-361/80-06 & 50-362/80-04
 SPENCER, G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80-06/13 ip
- --8007020149 Respinds to NRC 800429 ltr re violations noted in IE Insp Repts 50-361/80-06 & 50-362/80-04 Corrective actions welding filler motil removed & dispositioned PAPAYAL T Southern California Edison Co 80/03/28 Spp
- --B007020158 Forwards IE 1map Repts 50-361/B0-06 & 50-362/B0-04 on B00301-31 & notices of collation & deviation SPENCER. 9 S. Region 5: Ban Franciscu. Reactor Construction & Engineering Support Branch 80'04/29 2pp
- ---B007020166 Notice of violation from insp on 800301-31 * Region 5 San Francisco, Office of the Director 80/04/24 ip
- --8007020174 Notice of deviation from insp on 800301-31

 * Region 5 San Francisco Office of the Director 80/04/24 1p
- --8007020191 IE insp Repts 50 301/80 06 % 50-362/89-04 on 800301-31
 Nonsampliance noted failure to store high strength balts
 in manner assisting correction % failure to control 87018
 welding electrones at 30 st elevation
 PATELR of Region 5, San francisco. Office of the Director
 DODDS RI Pagion 5, San francisco, Reactor Construction &
 Engineering Support Branch 804/04/24 5pp
- BOO727008H Forwards of Info Notice 80 all. Frompt Reporting of Info in Accordance Wilm 64'0 55(4) "No written response required ENGELHER. Fit Hamilton & Gamerico Office of the Director 80'06, 13 by

- 8007290489 Responds to IE Bulletin 80-09 re potential defects in ITT General control hydramotor actuators Supplied actuators were functionally tested & exhibited no adverse operating defects Valves will perform functions as designed BASKIN.K.P. Snuthern California Edison Co. 80/06/16. 1p
- 8007020478 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/16/20 1n
- 8007180292 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Hater Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKENIR H Region 5, San Francisco. Office of the Director 80/06/24 lp
- 8007230393 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes "Written response required IE Circular 80-16 also epcl No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/27 1p
- 8007310201 Responds to IE Bulletin 80-08 re containment line penetration welds examination Utils do not utilize flued head design for penetration connections Unacceptable welds repaired & radiographed until ASME code criteria met BASKIN.K P Southern California Edison Co 80/07/01 ip
- B007300313 Forwards 1E Insp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 Na noncompliance noted SPENCER.0 & Region B. San Francisco, Reactor Construction & Engineering Support Branch 80/07/03 2pp
- --8007300318 IE Insp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & Internals protection & piping storage PATE.R J Region 4. Dallas, Office of the Director DODDB.R T Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/02 App
- R Periodic operating reports & related correspondence
- 8007010216 Forwards "1979 Annual Dierating Rept, San Onofre Nuclear Generating Station," Vol 5.Biological & Oceanographic Data Analyses Includes ETS for Unit 1.const & preoperational monitoring programs for Units 2 & 3 BASKIN.K P Southern California Edison Co 80/06/25 lp
- ~-B007010226 "1979 Annual Operating Rept.San Unofra Nuclear Generating Station." Vol 5. Biological & Oceanographic Data Analysis "Includes ETS for Unit 1. const & preoperational monitoring grograms for Units 2 & 3 # Brown & Caldwell # Lockheed Environmental Sciences # Marino Biological Consultants, Inc . BO-RD-100 80/06/25
- 8007100262 Forwards "Biological & Oceanographic Data Analyses ETB for Unit I.Const Monitoring Program for Units 2 & 3, Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthyoplankton, "Vol 5 for 1979 OTTOSON, H L Southern California Edison Co 80/06/30 Zpp.
- --B007100268 "Biological & Oceanographic Data Analyses ETB for Unit 1, Const Moniforing Program for Units 2 & 3, Preoperational Moniforing Program for Units 2 & 3 & Special Study re Ichthoplankton," Vol 5 for 1979 AMBERGO, J. Brown & Caldwell ANDERSON, D. T. Lockheed Environmental Sciences ABGRABJK Marine Biological Consultants, Inc., 80-RD-100 80/06/30 800pp
- S Reportable accurrences. LERs & related correspondence
- 8007090330 Forwards final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing PAPAY.L T Southern California Edison Co 80/06/27 1p
- --800709033/ Final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Deformed joints will be removed & returned to manufacturer for analysis Data sheet review will be completed by 800780 # Southern California Edison Ca 80/06/27 2pp
- B0072B0143 Ack respipt of 8GOAll amended final deficiency rept re lack of qualification testing documentation for repaired power cable EMOELKENIR H Region 5, San Francisco, Office of the Director B0/07/92 lp

- B007210493 Confirms B00711 telcon re editorial error in B00527 final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Failed expansion joint was in component cooling water sys NUNN, D E Southern California Edison Co 80/07/11 ip
- 8007230579 Final deficiency rept re lack of nondestructive surface examination of weld repair excavation cavities prior to rewelding Code Cases N274 & 275 approved to provide alternate acceptance criteria to ASME. Section 3
 PAPAY, L T Southern California Edison Co 80/07/i5 4pp
- DOCKET 50-362 BAN ONOFRE NUCLEAR STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8007010560 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representative Areas of disagreement may be discused through informal appeal TEDESCO, R L Assistant Director for Licensing 80/04/12
- 8007070421 Summary of 800528 meeting w/NRC consultant,Energy Technology Engineering Ctr,& applicant in Whittier.CA re Mechanical Engineering Branch open items re FSAR Draft safety evaluation.agenda & attendance list encl RODD;H Licensing Branch 3 80/06/16 24pp
- 800702020B Notification of 800702 meeting w/util in Bethesda.MD to discuss control room design review program RODD.H Licensing Branch 2 80/06/23 3pp
- 8007020673 Requests add1 info to define underclad crecking potential in reactor vessel noizles Ultrasonic exams did not indicate asplicit correlation between observed cracking & pre/post-heat treatment info required within two weeks SCHWENCER, A Licensing Dranch 3 80/06/24 4pp
- B007010479 Forwards affidavit of svc attesting to completion & distribution of responses to NRC financial analysis Questions 1-9
 BABKIN.K P Southern California Edison Co 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EIBENHUT, D Q Division of Licensing 80/06/26 2pp
- BOO7010338 Forwards "Preliminary Rept on Geologic Drilling & Investigation, San Onofre Nuclear Generating Station Units 2 & 3 & 61 geophysical maps (interpretations) prepared by PJ Fischer of CA Stake Univ encl
 BASKIN, K P Southern California Edison Co 80/06/27 1p
- --8007010364 "Preliminary Rept on Geologic Drilling & Investigation San Onofre Nuclear Generating Station Units 2 & 3 " BARNEICH.JA, BROOAN.O E Woodward-Clyde Consultants, Inc 80/06/27 47pp
- ---B007010374 Sixty-one 3 5 kHz high resolution seismic lines List of drawings encl
 * California State Univ. Northridge B0/06/09 62pp
- 8007090234 Urges extension of comment period for NUREG-0577 & 800519 amend until 800915 More stringent requirements broader applicability & EPRI study results warrant addl time OllMAN, D H San Diego Gas & Electric Co 80/06/30 ip
- BOO70BD0B1 Forwards response to NRC Question 361 65 in geoscience area Also forwards Woodward Clyde Consultants "Preliminary Rept on Geologic Drilling & Investigation Songs, Units 2 & 3, San Onofrec CA"

 BASKIN.K P Southern California Edison Co BO/07/01 18pp
- --80070B0083 "Preliminary Rept on Groingic Drilling & Investigation Bongs, Units 2 & 3, Ban Onofre, CA" " Woodward-Clyde Consultants. Inc B0/07/0i 40pp
- 8007170693 Advises of NRC acceptance of Amend 3 to Topical Rept. SCE-1-A, "BA Program " Topical rept must be referenced in Chapter 17 of SAR Quality Assurance Branch 80/07/01 19
- 8007210093 Notification of 800724 meeting w/util in Rosemead.CA to discuss results of Imperial Valley Oct 1979 santhquake analysis, using Unit 1 analytical modeling technique ROOD, H Licensing Branch 3 80/07/11 2pp

- 6007210463 forwards supplemental calculations of Revision 1 pages to original ralculations submitted to NRc on 800121 for design calculations of electrical tunnel BASKIN.K.P. Southern California Edison Co. 80/47716 33pp
- 8007280486 Ack receipt of NRC responses to Marine Review Committee 791009 rept re facility radiological munitoring program evaluation Detailed response will be submitted fullowing matl review FISCHER,M L California, State of 80/07/18
- 8007290620 Forwards response to NRC 800624 request for info re potential for underclad crarking in reactor /essel noilles Noille base metal math is 4A 500 (lass II Applicable math certification data sheets incl BASKIN.K P Southern California Edison Co 60/07/22 37
- 8007310465 Forwards NRC review of Marine Review Committee rest to CA Coastal Commission on adequacy of plant radiological monitoring program W/o encl
 CHANDLERIL J. Hearing Branih 1 80/07/29 1p
- F Security, medical, emergency & fire protection plans
- 80070802/1 Advises that revision to safeguards contingency plan will be submitted by 800718 BABKIN, K.P. Southern California Edison Co. 80/07/02 ip
- Q Adjudicatory correspondence
- 8007030006 Responds to to 800519 lit & moligram re NRC meeting practices on gorlogy/seismology in Ol proceeding lature meetings will be held in convenient locations NRC unable to honor request that meeting similar to 800520 &i be held CHANDLER.L. J. Hearing Branch ! 80066.3.3 4pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 700502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re file grotection for oluctival cables EISENHUT, D 0 Division of ficensing 80/06/29 97pp
- 8007090205 Proposes agenda for 800717 prehearing conference in response to ASLB 800624 ander in OL proceeding CHANDLER, L.J. Hearing Branch 2 80°07/07 2pp
- 8007300359 Bubmits recommendations on behalf of Southern CA Edison & San Diego Gas & Electric, firm agenda i teme to be considered at prehearing confuience to hearn 600,17 in San Diego,CA Related correspondence PlovoTt,D R Chickering & Gregory 80,07/07 Jpp
- 8007140032 Forwards for consideration, applicantails & Friends of the CHANDLER L J Hearing Branch 1 80/07/09 1p
- --B007140074 Executed stipulation extending time to respond to applicant motion for runmary dispublition of dewalering U fuel cost contentions until 8007-7 W/proposed order PIGDIT.D R Southern Culterina Fdison to CHANDECR.L J He Branch 1 WHARTGO.R J Triends of the Earth 80/06/27 2pp Hearing
- B007210436 Forwards suggested new servion of JA Partorson affidavit re-util motion for summary disposition Returns of affidavit m/ signature & notarisation requested if changes are suitable DAVIS.L D Hearing Branch 4 80/07/14 7pp
- 8007310470 Advises that NUREG 0/194 transmitted to parties on 800716 Extra copies will be sent to parties when available M/o encl rept CHANDLER L J Hearing Branch 1 80/07/28 ip
- H General correspondence
- B007020iBl Requests consideration of having Atomic Energy Council of Tatuan visit facility on fill(804-05 founcil interested in observing wants ogt activities Cooperation will be major contribution to NRC exchange air-ingement

 LAFLEUR, J D Assistant Director for International (coperation B0/05/13) 3pp

- @ Inspection reports, JE Bulletins & correspondence
- BOD72300ii Notifies that BOOIIB response to IE Builetin 79-13.Revision 2.indicated util proposed utilizing ultrasonic examination techniques for reportable indications as alternative to radiography Util uithdraws proposed use of ultrasonics BASKIN, P Southern California Edison Co BO/03/04 ip
- 8007250361 Responds to IE Bulletin 80-03, "Loss of Charcoal From Std Type II:2-Inch, fray Adsorber Cells "No charcoal adsorber cells have been received from manufacturer Charcoal adsorber filters to be used are designed to prevent charcoal leakage BASKIN,K P Southern California Edison Co 80/03/31 ip
- BD07170530 Forwards JE Insp Repts 50-361/B0-05 & 50-362/B0-03 on BD0324-27 No nonrumpliance noted SPENCER.O B Region 5. Son Francisco. Reactor Construction & Engineering Support Branch #0/05/20 2pp
- --8007170939 (E Insp Repts 50-361/80-05 & 50-362/80-03 on 800324-27 No noncompliance noted Major areas inspected previous open items.cable installation & pipe supports & restraints ECKHARDT.J H. HERNANDEZ, G Region 5. San Francisco. Office of the Director DDDD5.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/20 dpp
- 8007240088 Forwards response to MRC 800429 ltm re violations & deviations noted during 800203-17 & 21-28 insp of const activities Welding filler matl removed & dispositioned Bechtel work plan QC instructions revised PAPAY, L T Southern California Edison Co 80/05/28 5pp
- ~-8007240093 Ack receipt of 800528 ltr informing NRC of steps taken to correct items in NRC 800428 ltr SPENCER.G S Region 5. Son Francisco, Reactor Construction & Engineering Support Branch 80/07/11 ip
- 8007300303 Responds to IE Bulletin 80°05 re vacuum damage to chemical vol control sys tanks Table identifying sys & describing adequacy justification and lanks not currently protected will be provided w/adequate protection pilor to fuel load BASKIN.K P Southern California Edison Co 80/06/06 3pp
- 8007220249 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/10 1p
- 8007020131 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in 1E losp Repts 50-361/80-06 & 50-362/80-04 SPENCER.0 S Region 5. San Francisco Reactor Construction & Engineering Support Branch 80/06/13 lp
- --BOO7020149 Responds to NRC BOD429 ltr re violations noted in IE Insp Repts 50-361/BO-06 % 50-362/BO-04 Corrective actions welding filler matl removed & dispositioned PAPAYLL T Southern California Edison Co 80/05/28 Spp
- --B007020158 Forwards IE Insp Repts 50-361/80-06 & 50-362/80-04 on B00301-31 & notices of violation & deviation GPENCER.0 S Region 5, Sun Francisco, Reactor Construction & Engineering Support Branch B0/04/29 2pp
- --8007020160 Notice of violation from insp on 800301-31 * Region 5. San Francisco. Office of the Director 80/04/24 1
- --B007020175 Notice of deviation from insp on 800301-31 * Region 5, San Francisco, Office of the Director 80/04/24 lp
- 8007290088 Forwards IE Info Notice 80~28, "Prompt Reporting of Info in Accordance WildCFP50 55(e) ' No willten response required ENGELKEN.R H Pegion 5. San Francisco, Office of the Director 80/08/13 lp
- 8007290489 Pesponds to 1E Bullobin NO-09 re potential defects in 1TT Oeneral control hydramotor actualors Supplied actuators were functionally tosted & exhibited no adverse operating defects Valver will perform functions as designed BASKIN.K P Southern California Edison Co 80/06/16 ip

- 8007020478 Forwards IE Circular 80-15, "Loss of Reactor Godlant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/06/20 1p
- 8007180392 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKENIR H Region 5, San Francisco, Office of the Director 80/06/24 ip
- 8007230393 Forwards IE Bullotin 80-16, "Potential Misapplication of Potenount Inc Models 1151 to 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/06/27 1p
- 8007310201 Responds to IE Bulletin 80-08 re containment line penetration welds examination Utils do not utilize flued head design for penetration connections Unacceptable welds repaired k radiographed until ABNE cide criteria met BASKIN.K P Bouthern California Edison Co 80/07/01 1p
- BOO7300313 Forwards IE Insp Repts 50-361/80-08 & 50-36R/80-05 on 800407-0502 No noncompliance noted SPENCER,G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/03 Rpp
- --B00730031B IE Insp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection & piping storage PATE,R J Region 4, Dallas, Office of the Director DODDB,R T Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/02 &pp
- R Periodic operating reports & related correspondence
- B007010216 Forwards "1979 Annual Operating Rept, San Gnofre Nuclear Generating Station," Vol 5. Biological & Oceanographic Data Analyses Includes ETS for Unit 1. const & preoperational monitoring programs for Units 2 & 3 BASKIN, K P Southern California Edison Co 80/06/25 1p
- --8007010226 "1979 Annual Operating Rept.San Onofre Nuclear Generating Station." Vol 5. Biological & Greanographic Data Analysis "Includes ETS for Unit i.const & preoperational monitoring programs for Units 2 & 3

 * Brown & Caldwell * Lockheed Environmental Sciences. * Marine Biological Consultants, Inc., 80-RD-100 BO/06/25
 BOOpp
- 8007100262 Forwards "Biological & Oceanographic Data Analyses ETS for Unit 1.Const Monitoring Program for Units 2 & 3. Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthypplankton, "Vol 5 for 1979 OTTOSON, H L Bouthern California Edison Co 80/06/30 2pp
- --8007100268 "Biological & Oceanographic Data Analyses: ETB for Unit 1, Const Monitoring Program for Units 2 & 3, Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthyoplankton," Vol 3 for 1979 AMBERG, P J Grown & Caldwell ANDERSON, D T Lockheed Environmental Sciences ABGRAB.K Merine Biological Consultants, Inc. 80-RD-100 80/06/30 800pp
- S Reportable occurrences, LERs & related correspondence
- B007090330 Forwards final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing PAPAY.L T Southern California Edison Co 80/04/27 1p
- ~-8007070337 Final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Deformed joints will be removed & returned to manufacturer for analysis Data sheet review will be completed by 800720.

 * Southern California Edison Co 80/06/27 2pp
- B0072B0143 Ack receipt of B0061) amended final deficiency rept re lack of qualification testing documentation for repaired power cable ENGELXEN, R H Region 5, San Francisco, Office of the Director B0/07/02 ip
- 8007210493 Confirms 800711 telean re-editorial error in 800627 final deficiency rept re-failure of expansion joints in safety-related piping sys during startup testing Failed oxpansion joint was in component cooling water sys. NUMN.D E Southern California Edison Co 80/07/11 ip.

BOO7230579 Final deficiency rept re lack of nondestructive surface examination of weld repair excavation cavities prior to rewelding Code Cases N274 & 275 approved to provide alternate acceptance criteria to ASME. Section 3
PAPAY, L T Southern California Edison Co 80/07/15 4pp

DOCKET 50-343 FORKED RIVER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8007020219 Forwards NAC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEOESCO.R L Assistant Director for Licensing BO/06/13 2pp

B007230001 Forwards statement of policy re requirements to be mot for current DL applications, as derived from NUREG-0660 & found in NUREG-0660. Division of Licensing 80/05/26 2pp

O Adjudicatory correspondence

BOO7310243 Forwards Commission BOO527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables
EISENHUT, D G Division of Licensing 80/06/25 89pp

H General correspondence

BOO7180060 Responds to BOO311 request for info needed for fuel cost study Forwards excerpts of MASH-740, WASH-1224, WASH-1250, WASH-1400, NUREO-0020 (Vol 4, Number 1), NUREO-0480, NUREO-0512, NUREO-0517, NUREO/CR-1060 & FE9 DENTON, H R Office of Nuclear Reactor Regulation, Director 80/03/14 153pp

--B0071B0063 Requests documents containing info needed for fuel cost #Fluey HILGER.W Affiliation Unknown 80/03/11 2pp

@ Inspection reports. IE Bulletins & correspondence

8007170593 Forwards IE Insp Rept 50-363/80-01 on 800506 No noncompliance noted
CARLBOOK T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 80/05/22 2pp

--B007170599 IE Insp Rept 50-363/B0-01 on B00504 No noncompliance noted Major areas inspected QA program for storage & maint of equipment metls & structures during suspension of const & status of outstanding items
NARROWLE Region 1. Philadelphia. Office of the Director HCOAUCHY.R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/05/20 Spp

B007010283 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Faadwater Pumps" No written response required GRIGR.B H Region 1, Philadelphia. Office of the Director 80/05/27 1p

8D07210568 Forwards IR Info Notice 80-26, "Evaluation of Contractor OA Programs "No written response required GRIER, B H Region 1, Philadelphia, Uffice of the Director 8D/06/10 1p

8007160346 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Stude No specific action or response ORIER, H Region 1, Philadelphia, Office of the Director

8007280587 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/13 ip

8007020507 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/20 ip

8007160701 Forwards IE Circular 80~14, "Radioactive Contomination of Plant Demineralized Water Sys & Resultant Internal Contomination of Personnel " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/24 1p

8007210192 Forwards IF Info Notice 80-24. 'Low level Radwaste Bortal friteria' No wilkton response required GRIER.O H. Region 1. Philidelphia. Office of the Director 80/06/25 1p

8007230121 Forwards IE Bulletin BO-16, 'Putential Hisapplication of Rosemount Inc Hodels 1151 % 1152 Prosure Transmitters W/Either A or D Dutput (ndes " Witten response required IE Circular 80 16 also encl No written response tequired ORIER.B H Region 1, Philadelphia, Office of the Director 80/86/27 2pp

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2 A Application/construction of age duruments & intrespondence

B007070575 Requests assignment of reviewer % extinated rompletion date for TMI-2 artium plan items listed in attached tubles. Bubmits licensing schedule Hoposted date for safety evaluation input is 800625. TEDESCORE Assistant Director for Licensing 80/06/09 9pp

8007020390 Advises of interim actions required for plant operation pending final resolution of ATMS concerns ATMS exergency operating procedure must be submitted by 800620 % approved prior to issuance of full power OL TEDESCO, R L Assistant Director for Licensing 80/06/13 3pp

8007020095 Requests addl into re-understad cracking in reactor vessel norites for determination of solv of heat treatments in cracks recently found by European substituting SCHWENCER, A linensing Branch 2 80/04/13 2pp

8007010287 Forwards request for add1 info needed for continuing review of OL application per 860523 telron Info must be submitted by 800627 or NRC informed of contrary in reven days SCHWERGER, A. Licensing Branch & 80706717 bpp

800/020473 Forwards request for addl info to continue review of OL application Info should be submitted by 800670 SCHWENCER.A Licensing Branch & 60/06/19 /pp

8007010424 Advises that annual usage factor for two unit processing using Unit 1 drumning station is necrosod to 504 using values for expected wasto volt in updated fSAR fields 11 5-1 Basis for determining usage factor encl CLAYTON F.L. Alabama Power to 80/08/23 3pp

B007070009 Notification of NOOAN 0709 meeting w/util to review applicant plans & personnel qualification for operation of Pacility

KINTNERAL Licensing Brainh & 80/06/23 2pp

8007100018 Notification of 800703 meeting wrutil in Bethesdo.MD to discuss util response to NRL 800221 request for review of qualification documentation for safety-related electrical equipment to district consumence to MURFO OTEN KINTER-L Licensing Branch 2 607047/23 App

8007010489 Forwards info in response to 800613 ftr is reactor lessel nozife underelad ciacking Ultrasonic cross not presently needed Cladding destructive cross recommended CLAYTON, F. L. Alahama Power (o. 80/06/25). dpp

BOO7230001 Forwards statement or pulting represents to be mot for current OL applications as durised from NUREG 0660 & found in NUREG 0694 EISENHUTLD G Division of Eisensing 80/06/26 2pp

B007070292 Forwards requested will into it strim generator tube integraty CLAYTON: F.L. Alabama Power to GGM 6777 App

BOO7210305 Notificiation of (BO707+11 meeting whit) to Dolthan,AL to inappet design reports of circled equipment forcew solvent qualification records RINTNER.L Licensing branch 2 (BO706/27) 5pp

8007080222 Forwards abnormal operating procedure. "Loss of Main Feedwaters" emergency operating procedures, "Steam Concrator Tube Repture & Independent one curing live to mall LOCA!" per NRC 800669 reque t CLAYTON:F L Alabama fower to 80706730 ip

--B00708022B Abnormal operating procedure "Cock of Main Feedwater," Vol 5.Revision 0 * Alabama Power Co. 10705 30 App.

- --8007080232 Fmerychcy operating procedure. 'Loss of Reactor Coolant." Vol 5.Revision O
 - * Alahama Power Co 80/05/14 42pp
- --80070802 & Emergency upwiating procedure, "Steam Generator Tube Rupture," Vul 5, Revision 0 • Alabama Fuwer Co 80/05/14 9pp
- --8007080243 Emergency operating procedure: "Anticapated Transients M/o Trip (ATMT): " Revision 0 * Alahama Power Co 80:06/04 4pp
- --8007090250 Emergency aperating procedure, "Inadequate Core Cooling Due to Small LDCA ' vol 5, Revision O • Alabam, Puwer to 80/05/12 App
- 8007070237 Forwards qualification summary info for non-NSSS mechanical & electrical equipment selected by seismic qualification review tram for evaluation CLAYTON,F L. Alabama Power Co. 80/06/30 114pp
- B007100(B5 Submits insponses to URC 800616 draft questions concerning containment purge valves Comparison of facility purge sys w/ Branch Technical Position (98 o-4 encl CLAYTON: F L Alabama Power Co 80/06/30 12pp
- 8007210306 Notification of 800709 meeting w/util in Bethesda,MD to discuse radiological fech Speck
 KINTNER,L Licensing Branch 2 89706/30 3pp
- BOO7210593 Notification of 800716 meeting w/etil in Bethesda, MD to discuss response to NRC position on degraded grid voltage protection & sys voltages KINTNER L. L. Licensing Branch 2 90/07/02 3pp
- 8007210598 Notification of 800719 meeting w/util in Bethesda, MD to discuss control room design KININGR.L i Licensing Branch 2 80/07/02 3pp
- 8007100177 Fermands addl into requested by NRC 800617 ltr re preservice insp program CLAYTEN,F L. Alabama Power Co. 80/07/03 25pp
- 8007140343 Forwards description of proposed modified startup physics test program Revived program resolves NRC conterns resolved back verification.review criteria & actions needed should review (riteria not be met CLAYTON, F.L. Alabama Power Co. 80/07/07. 13pp
- BOOT140579 Forwards response to (antainment Sys Branch Question 57 for facility Leak reduction program initiated to maintain leakage rates of sys outside containment to as low as practical CLAYTON.F.L. Alabama Fower Co. 80/07/07. 3pp
- B007100261 Forwards Amend 73 to FSAR for Unit 1 & OL application for Unit 2 CLAYTON F L Alabami Power to 80/07/08 ip
- --8007100267 Application for Amend 73 to FSAR for Unit 1 % OL application for Unit 2 Certificate of Syc Encl * Alabama Puwer Co 60/07/08 App
- --B007100276 Amend 71 to FSAR for Unit 1 & OL application for Unit 2 Review: Unit 2 completion of const & commercial operating dates updating section re emergency lighting sys & info pertaining to GA program * Alabama Power Co. 80/07/08 400pp
- 8007280121 Submith facility status rept as of 800704 Full power licensing schoolule advanced lemonth to most schoduled 801101 start of full power operation Applicant asked to formally request fuel loading * low power tenting license KINTNER.L. Licensing Branch 2 Sucul/ii 2pp
- 8007220510 Furwards process Control purgram for rodunste solidification unit, as discussed at 800709 mpeting w/NRC CLAYTON.F (Althuma Hower Co 80 07/14 lg
- --8007220519 Radiation (ontic) % Protection Procedure PNP-0-RCP-474, Revision 1. "Hobite Solidification Unit Operation " MCCRACKERIK W Alabama Power Pa 80/01/10 89pp
- 8007220558 Corounds Revision 1 change pages to plant offsite dose caller manual incorpolates radiation monitor setpoint calculation methodology discurred during 800709 meeting w/NRC CLAYTON F L. Alahama Power Co. 80/u7/14 hpp

- 8007250185 Advises that near-term DL applicants should perform augmented luw power startup tests similar to those proposed by TVA for Sequuyah, prior to exceeding 5% of rated thermal power EISERHUT.D 9 Division of Licensing 80/07/14 2pp
- 8007250320 Forwards info per NRC 800502 request ro THI-2 action plan Items I A 2 1.1 A 2 3 & I A 3 1 CLAYTON:F L Alabama Power Co 80/07/15 4pp
- 8007220486 Forwards add1 info re containment sump performance in response to NRC request CLAYTON,F L Alabama Power Co 80/07/16 4pp
- 8007220554 Forwards auxiliary feedwater endurance test data & test info requested in NRC 800408 ltr CLAYION,F L Alabama Power Cu 80/07/16 20pp
- 8007280399 Forwards request for add1 info re containment sump performance under post-LOCA conditions Response to Items 1:2 & 3 due by 800808 Item 4 info should be provided by Mar 1981 TEDESCO.R L Assistant Director for Liconsing 80/07/16 8pp
- 8007290202 Forwards request for addl info re 800620 response to TMI-2 action plan
 TEBESCO.R L Assistant Director for Licensing 80/07/16 9pp
- 8007220410 Forwards qualification repts & seismic specs for five pieces of equipment.per NRC request during 800707-10 plant site visit for seismic qualification review CLAYTUN.F L Alabama Power Ca 80/07/17 ip
- GOO72ROSBI Responds to GOO714 ltr re augmented low power startup test program Submits schedule & procedure for test performance Util In process of writing detailed procedures & reserves option of combining tests No knewn safety issue involved CLAYTON,F L Alabama Power Co GO/O7/17 1p
- 8007230403 Forwards addl info re degraded electrical power grid conditions.in response to 800626 telicon includes suppl to util 790115 ltr re assessment of NRC Positions 1.2 & 3, CLAYTON.F.L. Alabama Power Co. 80/07/17 13pp
- B0072304B5 Responds to Action Plan Item III D 3 4 re control room habitability Room meets SRP specs & guidance No mods required CLAYTON,F L Alabama Pawer Co 80/07/17 1p
- 8007230492 Forwards main control room design review commitments per NRC main control room review team 800715 discussions w/util CLAYTON,F L. Alabama Power Co. 80/07/17 9pp
- 8007230546 Informs that util will participate in EPRI/NSAC power safety & relief valve performance verification test program Licensee will submit evidence re operability of installed safety & relief valves Evidence expected by 820101 CLAYION,F L Alebama Power Co. 80/07/17 Ip
- B007230553 Forwards radiological Tech Spec info concerning hydrogenosygen-nitrogen mixture curves & hydrogen recombiner instrumentation calibr H/o encl CLAYTON.F L Alabama Power Co B0/07/17 ip
- 8007230967 Requests that OL w/limited authorization for facility be issued by 800901 per requirements in NRC 800626 itr Request includes fuel loading, low power testing & power operations up to 5% thermal power Full power OL requested by 801201 CLAYTUN, F L Alabama Power Co 80/07/17 ip
- 8007230992 Forwards info re sys description of core thermocouples in response to TMI-2 action plan Item II F 2 on inadequate core cooling instrumentation CLAYTON.F L Alabama Power Co 80/07/17 Spp
- 8007240071 Notifies that util in process of finalizing plans for instrumentation sys to relate reactor vessel water level to inadequate care Louling Provides list of commitments concerning instrumentation sys CLAYTON, F.L. Alabama Fower Co. 80/07/17 1p
- BOO7280357 Commits to guidance in Reg Guide 8 9 re establishment of bicassay program, w/exception of interpretation of atated in measurement results Problems of interpretation are atated in ICRP Publication i2, Paragraph 112
 CLAYTON F L Alabama Power Cp 80/07/18 1p

- BOO7280490 Suppls & supersedes util 8007)7 response to TMI-2 action plan items Util will participate in EPRI PWR safety & relief valve performance verification test program & will submit swidence of valve operability by BOO701 CLAYTON,F L Alabama Power Co 80/07/23 ip
- BOO7270637 Forwards requested info concerning TMI-2 action plan for facility Includes description of interim procedures & methods for qualifying high level accidential radioactivity releases for noble gas.particulates & radioactive effluents CLAYTON,F L. Alabama Power Co. 80/07/24. 5pp
- BO07270642 Forwards requested info re core subcooling instrumentation Includes description of incore thermocouple measurement means available at facility CLAYTON, F. L. Alabama Power Co. 80/07/24 7pp
- E NRC Bafety Evaluation Report (BER). supple & correspondence
- 8007270525 Forwards SER input re TMI Action Plan Task i A 3 addressing revised scape & criteria for licensing scams MDOREN A Division of human Factors Safety 80/07/18 2pp
- Q Afjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT. D O Division of Licensing 80/06/25 89pp
- J Insurance & indemnity information
- 8007080261 Forwards MAELU Excess Dinder XD-7.3 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/06/30 App
- Q Inspection reports. IE Bulletins & correspondence
- 600724010B Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Deste Unit 1 While in Refueling Mode " No response required D'REILLY, J P Region 2. Atlanta, Dffice of the Director 80/05/08
- 8007020180 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required C'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007210419 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written rosponse required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010233 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29 ip
- 8007220040 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/10 200
- B007160218 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required O'MEILLY, J P Region 2. Atlanta, Diffice of the Director B0/06/11 in
- 800723033B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020383 Forwards IE Carrular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No wratten response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/20
- 8007270385 Forwards lE Insp Rept 50-364/80-05 on 800604-06 No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/20 2pp

- --8007290393 IF insp Rept 50-364/80-05 on 800604-06 No noncompliance noted Major areas inspected matl runtiol & accounting GILLESPIE.F P. HODGES, J W. Region 2, Atlantic Safeguards Branch 80/06/20 Sou
- 8007070394 Forwards IE Insp Rept= 50-348/80-10 & 50-364/80-11 on 800331-0425 No noncompliance noted LEWIS.R C Region 2. Atlanta. Poactor Operations Nuclear Support Branch 80/04/21 2pp
- --B007070399 IE Insp Repts 50-348/80-10 t 50-364/80-11 on B00331-0425
 No noncompliance noted Najor Areat inspected hot functional testing. IE bulletin followup & plant security
 MARTIN.R D Region 2. Atlanta. Reactor Operations Nuclear Support Branch BRADFORD, WH Region 2. Atlanta. Office of the Director 80/05/21 6pp
- 8007160791 Forwards 1E Circular 80-14, "Radioactive (untumination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No writton response required O'REILLY, J. P. Region 2: Atlanta, Office of the Director 80/06/24 to
- 8007230206 Forwards IE Bulletin BO-16, "Potential Misapplication of Rosemount Inc Hodels 1151 % 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular BO-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27 ip
- B007210245 Forwards response to IL Bulletin 80-08, "fiamination of Containment Liner Penetration Welds" All containment butt welds between punctration sleeve, A process piping in Unit I radiographed Unit 2 to be radiographed upon completion CLAYTON, FL Alabama Power Cn 80/07/01 5pp
- 8007230510 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sy< Bus During Operation "Prior to initial fuel loading.procedures to be revised to reflect annunciation & authomatic control functions CLAYTON F L Alabama Power Co 80/07/17 ip
- B007310150 Submits add1 response to IF Gulletin 79-27 re loss of nonclass IE instrumentation & control power sys bus during operation Procedures will be revised to reflect affected annunciation & automatic control functions CLAYTON:F L. Alabama Power Co. 80707/17 ip
- 6007310330 Forwards "Inservice Insp Program for Class 1.2 & 3 Components " CLAYTON,F L Alabama Power (o 80/0//25 2pp
- ~~80073103/4 "Inspivice Insp Program for Class 1.2 & 3 Components "
 * Alabama Power Co 80/07/25 78pp
- S Reportable occurioners, LERs & related correspondence
- 8007160861 Part 21 rept re Westinghouse review of sofuty injection termination criteria following recondary side high energy line repture w/potential for dominge to confrifugil charging pumps Concerns are applicable to facility HAIRSTON:W G Alabama Power Co 80/06/11 2pp
- V Operator Examinations
- 8007290525 Folwards SER input r+ TM) Action Plan Task 1 A 3.addressing revised scope & crituria for licensing exams MOORE.V A Division of Human Factors Safety 80/0//18 app
- DOCKET 50-986 EDWIN 1 HATCH (NUCLEAR PLANT, UNIT 2
- 3007020488 Forwards request for aud) info in 8005/8 revised ou
- B007020488 Forwards request for add) info is 8005/8 revised goard training & qualification plan End withheld (ref 10EFR2 790)
 REID.R W Operating Reactors Branch 1 80/06/19 2pp
- 8007230104 Requests participation in study of people-related problems in nuclear satequards Study involves collection of data on licensee security forces & practices MRC wishes to interview security mgt personnel at facilities EISENHUT.D 0 Division of Licensing 80/07/11 2pp
- BOO7280514 Advisos that BOO718 imergency plan typereding per NUREG-0454 will be delayed until 801901 Requirts rept from BO0422-23 Emergency Preparedness Team roview HIDNER, W.A. Georgia Power (o. 80707/21 1p

- G Adjudicatory correspondence
- BOD7310243 Forwards Commission 800527 menorandum & order containing decisions on U.S 780502 petition for reconsideration of 780413 memorandum & order UCS 771101 petition sought action re fire protection for electrical cables EISENHULD G Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 neeting w/Mark I owners group in Bethesda, MO.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES C T Flant Systems Branch 80/02/21 31pp
- 8007140641 Advises that dates of responses to 79092/ generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Hatch 1 & 2 Rept on valve operability program required only for plants desiring to justify unlimited purging VERRELLI,D M Operating Reactors Branch 4 80/06/05 1p
- 0007010474 Advises that util will comply w/800507 ltr issuing five addl TMI-2 related requirements for operating reactors When implementation criteria is developed NRC will be notified of any variation from schedule Reserves three options WIDNER, W.A. Georgia Power Co. 80/06/20 lp
- 8007020628 Advises that review has been completed on 800513 rept of callbr results on seismic instrumentation Triaxial Time-History Accelerograph, 2Lbi-NO21 was returned to vendor for repair as recommended MANRY H Georgia Power Co 80/06/25 ip
- 8007090389 Notification of 800703 meeting u/util in Bethesda.ND to discuss util basis for delayed schedule for installing T-quenchers
 VERRELLI.D Operating Reactors Branch 4 80/06/26 2pp
- 8007080287 Discusses applicability of GE response to questions raised by C Michelson.in response to NRC 800507 request Automatic isolation may occur for breaks outside or inside containment depending on break size & location HIDNER.W A Georgia Power Co 80/06/30 2pp
- 8007180115 Forwards Amend 16 to License NPF-5, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/07/02 2pp
- --8007180134 Adend to to License NPF-05, temporarily revising Tech Specs for MPCI sys to permit startups w/inoperable MPCI, to conduct special test REID.R W Operating Reactors Branch 4 80/07/02 8pp
- ---B007180135 Sufety evaluation supporting Amend 16 to Licensa NPF-5 • Operating Reactors Branch 4 80/07/02 2pp
- ~-B0071B012B Notice of issuance & availability of Amend 14 to License NPF-5 REID.R W Operating Reactors Branch 4 80/07/02 2pp
- 8007180484 Confirms util commitments at 800703 meeting re schedule for completing muds for resolution of Mark I containment longterm program Meeting summary encl RESD.R W Operating Reactors Dranch 4 80/07/07 2pp
- --8007180487 Summary of 800703 meeting w/util re licensee schedule for completing mods for resolution of Mark I containment longterm program VERRELLI,D M Gperating Reactors Branch 4 80/07/07 6pp
- 8007230656 Provides info re new Dfc titles positions & assignments of personnel resulting from 800428 reorganization of Dfc of Nuclear Reactor Regulation NOVAK.T H Assistant Director for Operating Reactors 80/07/10
- 8007280634 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs re torus water temp If water temp cannot be restored within 24-h, reactor shall shutdown using normal shutdown procedures WIDNER:W A Georgia Power Co 80/07/17 3pp

- 8007310336 Requests written confirmation of 800718 telcon re critical situation concerning electrical power generation in region served by util NDVAK.T M Assistant Director for Operating Reactors 80/07/22
- @ Inspection reports, IE Bulletins & correspondence
- 8007240213 Forwards IE Info Natice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Made " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8007140490 Forwards IE Bullstin BD-13, "Cracking in Core Epray Epargers" Written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 90/05/12
- 8007020178 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28, to
- 8007010220 Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Foodwater Pumps" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/05/29 in
- 8007100064 Forwards IE Insp Repts 50-321/80-22 & 50-366/80-22 on 800412-0512 No nancompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 2pp
- B007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/10
- 8007140294 Forwards IE Bylletin 80-14, "Dagradation of RWA Beram Discharge Vol Capability " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12 to
- B007020736 Forwards IE Bulletin 80-i5, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/18
- 8007020298 Forwards notices of violation & proposed imposition of civil penalty re IE insp on 800319
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/19 2pp
- --800702030! Notice of violation from insp on 800319 Noncompliance noted packages of licensed maths shipped on 800318 w/radiation levels in truck cab exceeding regulatory limit # Office of Inspection & Enforcement, Office of the Director 80/06/19 | 1p
- ---8007020305 Notice of proposed imposition of civil ponsity in amount of \$4,000 re violation noted during 800319 insp

 ** Dffice of Inspection & Enforcement, Office of the Director 80/06/19 10
- 8007090074 Requests extension to 800718 to complete response to Itams 1 & 2 of IE Bulletin 80-10, "Contamination of Nonradioactive Bys & Resulting Potential for Unmonitored, Uncontrolled Release of Reducactivity to Environ"
 WIDNER, W.A. Georgia Power Co. 80/06/19 1p
- 8007140180 Piscusses 800319 incident which revealed radiation levels exceeding limits on truck cab arriving at Darnuell site Forwards notice of violation & notice of proposed imposition of civil penalty 8TELLO.V Diffice of Inspection & Enforcement, Office of the Director 80/06/19 2pp

- B007020450 Forwards IE Circular 80-15, "Loss of Reactor Coolent Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/20
- 8007i10250 Ack receipt of 800604 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-32i/80-i9 & 50-366/80-i9 STORR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/06/23 ip
- ---B007i1U259 Responds to NRC B005i2 ltr re violation noted in iE Insp Repts 50--321/80-19 & 50--366/B0-19 Corrective actions full awdit of emergency plan & implementing procedures completed HiDNER, W. A. Georgia Power Co
- --8007110262 Forwards IE Insp Repts 50-321/80-19 & 50-366/80-19 on 800421-25 & notice of violation STOHR, J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/05/12 2pp
- --8007110260 Notice of violation from insp on 800421-25
 * Region 2, Atlanta, Office of the Director 80/05/12 ip
- ---G007i10276 IE Insp Repts 50-32i/80-19 & 30-366/80-19 on 80042i-29 Noncompliance noted failure to audit emergency implementing procedures every 2 yrs under cognizance of sefety review foard.

 PERROTTI.D J. TROJANOWEKI.R Region 2. Atlanta, Office of the Director JENKINS, 0 R Region 7. Atlanta, Fuel Facility & Materials Bafaty Branch B0/05/12 9pp
- 8007390576 Forwards IE Insp Repts 50-321/80-14 & 50-366/80-14 on 800319,0429 & 30 Enforcement action disrussed in NRC 800619 ltr.
 0'REJLLY, J P Region 2. Atlanta, Office of the Director 80/06/23 2pp.
- ---8007300580 iE Insp Repts 50-321/80-14 & 50-366/80-14 on 800319,0429 & 30 Noncompliance noted radiation levels on vehicle cab in excess of regulatory limits BTOHR.JP, WOODRUFF.RL Region 2. Atlanta, Fuel Facility & Materiais Safety Branch LAGEY,LR Region 2. Atlanta, Opplice of the Director, 60/06/19 Spp
- 8007170115 Forwards IE Circular 80-14. "Radioactive Contamination of Piant Demineralized Water Sys & Resultant internal Contamination of Personnel" No written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/06/24 is.
- 8007230247 Forwards iE Bulletin BO-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required iE Circular BO-16 also encl No written response required O'RCILLY. J P Region 2, Atlanta, Office of the Director 80/06/2 ip.
- 8007220281 Submits final response to IE Bulletin 79-18 Noise evaluations performed for inaccessible areas following installation of evacuation signals Visual warning lights will be installed during Fall 1980 refueling outage WiDNER, W A Georgia Power Co 80/06/30 lp
- 8007090337 Forwards info in response to Items 1.2(a) & 3 required by IE Bulletin 80-15. "Masonry Wall Design " Item 2(b) to be addressed in final rept
 HiDNER, H. A Georgia Power Co 80/07/03 18pp
- 8007140384 Responds to IE Bulletin E0-08 re containment liner penetration weld exam Requests 30-day extension for info submittal due to large number of flued head containment liner penetrations & heavy high priority work load WIDMER. W A Georgia Power CO 80/07/07 Ip
- 8007280126 Ack receipt of 800623 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80-02 & 50-366/90-02 MURPHY.C. E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/09 ip
- --8007/280128 Responds to NRC 800208 & 0411 ltrs re deviations noted in IE Insp Repts 50-321/80-02 & 50-366/80-02 Corrective actions, submitted encl draft anguneering review of GA fire protection program at NRC 800602 meeting WIDNER, W A Georgia Power Co 80/06/23 42pp,

- 8007240252 Ack receipt of 800612 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-17 & 50-366/80-17 O'REILLY. J P Region 2 Atlanta, Office of the Director 80/07/11 is
- --8007240264 Responds to NRC MOUSI9 | tr re violations noted in IE Insp. Repts 50-321/80-17 & 50-366/80-17 Corrective actions new airlock scheme installed Actions to event & deviation reportability justified WIDNER, W.A. Georgia Power Co. 80/06/12 4pp
- --8007240277 Forwards IE Insp Repts 50-321/80-17 & 50-366/80-17 on 800308-0411 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/19 2pp
- --8007240285 Notice of violation from insp on 800308-0411
 * Region 2. Atlanta, Office of the Director 80/05/19 2pp
- --8007240292 IE Insp Repts 50-321/80-17 & 30-366/80-17 on 800308-0411 Noncompliance noted failure to maintain secondary containment door integrity & to meet NRC reporting requirements ROCERS, R F Region 2. Atlanta, Diffice of the Director DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/19 5pp
- 8007250292 Responds to IE Bulletin 80-17. "Failure of Cuntrol Rods to Fully Insert" Scram discharge vol (SDV) vent & drain operability verification test performed All drain & vent valves verified operable No residual water found in SDV WIONER, W A Georgia Power Co 80/07/11 1p
- 8007310275 Responds to HRC 800619 notice of violation re excessive radiation exposure rate inside cab of radwaste transport vehicle Radiation survey indicated radiation levels within code requirements Requests mitigation of violation severity WIDNER W.A. Georgia Power Co. 80/07/14 2pp
- --8007310287 Responds to NRC 800619 notice of proposed imposition of civil penalty Radiation survey of vehicle indicated levelt within code requirements Requests mitigation of severity of violation treduction of civil penalty WIDNER, W.A. Georgia Power Co. 80/07/14 2pp
- 8007280538 Advises of proposed compensatory measures re 2-wk extension for scram testing required for IE Bulletin 80-17 Util will perfurm tests as soon as possible should critical load situation ease WiDNER.W A Georgia Power Co 80/07/19 1p
- 8007280541 Advises of completion of Items 1 & 2 of iE Bulletin 80-10, "Contamination of Nonradioactive Sys " Complete dacumentation of affected sys % associated monitoring procedures available for review during Puture onsite insps WIDNER, W A Georgia Power Co 80/07/18 ip
- 8007290618 Requests delay in performing scram tests required by IE Bulletin 80-17 due to high temps in region Removing large units from svc would place severe strain on electric generating capacity of region WiDNER.W A Georgia Power to 80/07/18 2pp
- R Periodic operating reports & related correspondence
- 8007280678 Forwards monthly operating repts for June 1980 MANRY.M Georgia Pawer Co 80/07/10 1p
- ~~8007280686 Forwards monthly operating repts for June 1980 MANRY.M Georgia Power (o 80/07/10 1p
- --B007280892 Monthly operating repts for June 1780
 BLACKWELL:R M Georgia Power Co B0/07/10 7pp
- B Reportable occurrences, LLRs & related correspondence
- 8007010494 Ferwards LER 80-089/03L-0 MANRY.M Georgia Power Co 80/06/24 ip
- --8007010503 LER 80-089/03L-0 on 800530, while performing HNP-2-3315, torus suction valves 2E41-F041 & 2E41-F042 failed when given open signal Torus valves shorted out due to Londansation in HPC1 room Cause of condensation was strong leakage around soal NIX.8 T Georgia Power Co 80/06/24 2pp
- 8007010510 Forwards revised ICR 80-068/00X-i MANRY,M Georgia Power Cp 80/06/20 ip

--8007150685 LER 80-095/03L-0 on 800617, during HNP-2-3123, loop control sys blower operability, inhoard leadkage control sys flow indicator A peggod upscale & would not return to zero Caused by bent flow element float Float straightened & cleaned NIX.R T Georgia Power Co 80/07/07 2pp -8007010518 Re-used LER 80-068'031-t on 800422, while performing primary containment recombiner sys functional test recombiner sheath temp failed to remain within Terh Spec Caused by setpoint DAYLEY'S X Genequa Power on 80/06/24 2pp 8007170405 Forwards LER 80-100/01T-0 MANRY, M Georgia Power Co 80/07/08 Ip 8007030272 Forwards LER 80-090/03L-0 MANRY,M Georgia Power Co 80/98/24 1p --B007030274 LER B0-090703L-v on B00604.while starting up Unit 2 reactor. HPC1 auto isolation logic for channel B did not reset until reactor pressure was 15% paig (aused by callbr procedure w/overly conservative setpoint Setpoint changed NIX.R 1 Georgia Power En B0706/24 2pp --8007170410 LER 80-100/01T-0 on 800702, during performance of high drywell pressure surveillance procedures, found switches set above Tech Spec limit Apparently caused by setpoint drift Switches recalibr NIX.R T Georgia Puwer Co 80/07/08 2pp 8007170453 Forwards LER 80-096/03L-0 MANRY, M Georgia Power Co 80/07 8007030280 Ferwards LFR 80-092/03L-0 MANRY M Georgia Power Lo 80/06 20706724 1p 60/07/09 10 --B007030282 LER B0-092/09L-0 on B006il during surveillance checks at steady-state power operaturs found B rod block monitor bypassed while telecting rods Caused by component failure Power supply repaired t returned to svc NIX:R T Georgia Power Co B0/04/24 App --800717046B LER 80-096/03L-0 on 800627. w/reactor mode switch in run, reactor bidg to torus vacuum breaker isolation valve.
2748-F311.failed open Caused by failure of delta pressure switch. 2748-N211.reactor bidg to delta pressure switch
NIX.R T Georgia Power Ca 80/07/09 2pp B007030261 RG on B00523, licensee reviewed Kinemetrics; Inc B00513 calibr rept re seismic instrumentation Triarial Time-History Accelerograph 2L51-ND21 calibr indicates excessive change in longitudinal channel characteristics MANRY, M Georgia Power Co 80/06/25 ip 007210393 Forwards LER 80-093/03L-0
MARY,M Georgia Power Co 80/07. 80/07/11 1p --8007210397 LER HO-093/03L-O on BOO612.during steady state power. HNP-2-1050 rounds procedure readings showed drywell avarage temp high Caused by high ambient temp & inadequate cooling. Chilled water flow increased COG91N.C L Georgia Power Co GO/07/11 3pp 8007020520 Forwards 800627 NPDES rept made to State of GA re discharge of free available chloride in cooling tower blowdown MANRY, M Georgia Power Co. 80/06/26 lp B0072103B4 R0 on B00711.Unit 1 LPCI inverter tripped & Unit 2 4-kV bus 2F supply breaker & HPCI tripped Supply breaker trip caused by jumper missing from neutral leg Motor valve on HPCI replaced making it operable Events submitted per 1EB 80-17 MANRY.M Georgia Power Co 80/07/14 2pp --8007020523 NPDES nuncompliance notification on B00619, at full power operation, circulating water chlorination sequence was automatically activated, resulting in release of free available chloring in cooling water bloodown BYERLEY, T E Georgié Power Co B0/06/27 2pp 8007280505 Forwards LER 80-098/03L-0 MANRY.M Georgia Power Co 80/07. 8007030277 Forwards LER 80-094/03L-0 MANRY,M Georgia Power Co 80/06/26 (p 80/07/14 10 ---8007280512 LER 80-098/03L-0 on 800626.u/reactor at 99% steady state power, HPCI pump failed operability Caused by HPCI pump suction presoure transmitter 2E41-N019 drifting out of tolerance causing 2E41-H60A to indicate incorrectly NIX.R T Georgia Power Co 80/07/14 2pp --B007030277 LER B0-074/03L-0 on 800613, while performing routine surveillance on torus-drywell vacuum breaker valve-valve 2748-3238 failed to open Couse unknown Vacuum breaker valve will be repaired during nett reactor cold shutdown NIX.R T Georgia Power Co 80/06/26 2pp 8007240124 Forwards LER 80-097/03L-0 MANRY,M Georgia Power Co 80/07/15 1p BO07110429 Forwards LER 80-091/03L-0 MANRY, M Deorgia Power Co BO/06/ H0/04/30 1p --8007240128 LER 80-097/03L-0 on 800625, while performing surveillance procedure HNP-2-3307, HPC1 steam line flow FT&C, flowswitch 2E41-N004 setpoints exceeded Toch Spec limits Caused by setpoint drift Switch was recalibr & returned to svc NIX,R T Georgia Power Co 80/07/15 2pp --8007110437 LER 80-091/03L-0 on 800605, while pulling rods to increase Power Level are max fraction of limiting power density found higher than Fech Spec allowed Caused by combination of low feedwater & low zenon NRC reviewed problem CDGGIN, C.L. Georgia Power Co. 80/06/30 2pp 8007240165 Forwards LER 80-103/01T-0 MANRY, M Georgia Power Co 80/07/ B007110366 RD 50 366/1980-100 on 80070P, while performing surveillance procedures HNP-2-3002 & HNP-2-3172M, high drywoll pressure switches 2C71-N002A through D & ZEII-N011A through D found out of theirance faused by setpoint drift Switches recalibr MANRY, M Georgia Power Co 60/07/02 2pp B0/07/17 1p. --8007240167 LER 80-103/01T-0 on 800709, determined 2E11 NOIGA through D high drywall pressure switches outside Tech Spec limit Caused by setpoint drift Switches recalibr NIX:R T Georgia Power Co 80/07/17 2pp 8007150635 Forwards updated LER 80-064/03X-1 MANRY-M Georgia Power Co 80/07/03 1p 8007250411 Forwards LER 80-099/03L-0 MANRY,M Georgia Power Co 80/07 ~-B007150542 Updated LER B0-0:44/03X-1 on B00419, w/unit in cold shutdown, while performing MSIV leakago control sys LEFT; bleed valve EE3Z-F9018 indicating lights went out Caused by defective torque switch Torque switch has replaced COGGIN.C.L. Georgia Power Co. B0/07/03 2pp 80/07/17 1p --B007250412 LER 60-097/03L-0 on B00626, during instrument check, found B drywell analyzer giving false dioxygen reading Caused by personnel error Regulators marked for double check of reagent gas flow while changing reagent gas bottles NIX,R Y Georgia Power Co B0/07/17 2pp BO072B0450 Forwards updated LFR 80-045/01X-2 MANRY N Georgia Power Co 80/07/03 1p 8007280518 Forwards revised LER 80-096/03L-1 MANRY, M Georgia Power Co 80/07/17 tp --8007280455 Updated LER 80-045/01X-2 on 800404, leakage rates found unacceptable during leak rate test Coused by heat damage from installation welding Valvex will be replaced COGGIN.C.L. Georgia Power Co. 80/07/03 2pp --8007280526 Revised LER 80-096/03L-1 on 800619. w/reactor mode switch in 00/280325 Revised Lem 80-076/01.-- on Boweit w/reactor move run reactor bldg to torus vacuum oreaker isolation valve, 2748-F31: failed Caused by failure of delta pressure switch 2748-N21! Micro switch replaced NIX/R T Georgia Power Co 80/07/17 2pp 8007150578 Forwards LER 80-071/03L-0 MANRY,M 9807914 Power Co 80/07/07 1p

DOCKET 50-367 BAILLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 8007010479 Forwards well charts for 800611-18, Bailly wells w/o recorders.pond levels.pneumatic pressure transducers & water meter readings for 800618 & USGS wells for 800617 BOHN.R J Northern Indiana Public Service Co 80/06/24 34pp
- 8007210174 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj to certain constraints MATTSON.R J Division of Safety Technology 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0640 & found in NUREG-06494
 EISENHUT, D O Division of Licensing 80/06/26 2pp
- 8007230621 Summary of BOD612 meeting w/Mark 11 owners group in Bathesda, MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON, C J Generic Issues Branch 80/07/03 37pp
- E007.250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago, IL to discuss lead Mark II plants chugging & C/O lead specs
 ANDERSON.C Generic Issues Branch 80/07/23 2pp

O Adjudicatory correspondence

- BOO7140001 Response in opposition to ABLB provisional order in CP strension proceeding Urges immediate consideration of evacuation alternatives prior to const CRABOWSKI.A M . GRABOWSKI.O V Affiliation Unknown 80/06/24 4pp
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action as fire protection for electrical cables Division of Licensing 80/06/25 89nn FISENHUT. D O
- 8007020453 Response to opposition to ASLB 800530 provisional order ruling on interventions & scope of CP extension proceeding Urgos revision or clarification re issues & stds which cannot abide OL proceeding Certificate of Svc encl SHEA.X H . FRANTZ.S P . EICHHORN.W H Northern Indiana Public Service Co 80/06/30 44pp
- 6007080021 Submits statement of objections on behalf of util in response to ASLB special prehearing conference provisional under Urges ruling on contentions as previously filed due to unsuccessful negatiations Certificate of Svc encl
 SHEA,K H Lowenstein, Newman, Reis, Aselrad & Toll 80/06/30 1 80/06/30 4pp
- 8007080026 Response to ASLB 800530 special prehearing conference provisional order Urges issuance of revised order to answer whort pilings questions Adopts reworded Contentions R-1 1-15 Certificate of Byc encl
 BEKULER.B N Illinois, Stote of 80/06/30 12pp
- 8007080055 Response in opposition to ASLB 800530 special prehearing conference provisional order Requests revision of reworded contentions & urges that short pilings questions be answered within 10 days W/notice of appearance & Certificate of Svc VOLLEN,R J. OSANN,E W. Izaak Walton League of America. Porter County Chapter VOLLEN,R J. Vollen, R J. 80/06/30 21pp
- 8007150056 Notice of appearance in CP extension proceeding Certificate of Bvc sncl MURRAY, M J 11linois, State of 80/07/09 4pp

H, Qeneral correspondence

- B007140028 Forwards J Seed Itr directed to B Eizenstat w/RD Folsom B00620 response & White House tracking worksheet re plant site & design Urges return of documents to agency liaison after appropriate action after appropriate action SEAL,M.M. President of US & Executive Offices 80/06/24 App
- B007100235 Protests & appeals ruling that evacuation & other significant issues will not be admitted by NRC to facility CP hearings People must be allowed to speak at hearings Certificate of Syc encl SCHULTZ.Q Affiliation Unknown B0/06/25 3pp

- O Inspection reports IE Bulletins & correspondence
- 8007140509 Forwards IC Bulletin 80 13, "Cracking in Core Spray Spargers" No written recponse required KEPPLER, J. G. Region J. (hicago, Office of the Director 80/05/12
- B007010132 Forwards 1E Info Notice 80-P3 "Loss of Soction to Emergency Feedwater Pumps " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29
- 8007220206 Forwards (E Info Notice 80-76, 'E valuation of Contractor GA Programs " No written response or quired KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/iO
- B007140323 Forwards IE Dulletin 80-14. "Degradation of BMR Scram Discharge Vol Capobility ' No written response required KEPPLER, J G Region 3. Chicago, Office of the Director B0/06/12
- G007280635 Farwards 1E Info Notice 80-26, "Prompt Reporting of Info in Accordance W/10(FR50 55(e)" No written response required KEPPLER, J. G. Region 3, Chicago Office of the Director 60/06/13
- B007020587 Forwards IE (irrular H0-15, "Loss of Reactor Conlant Pump Cooling & Natural Circulation (coldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- B00717050) Forwards IE Circulai 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Persinnel" No written response required MEPPLER, J. G. Region 3. Chicago, Office of the Director B0/06/24
- 8007230332 Forwards IE Dulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-15 also encl No written response required KEPPLER.J G Region 3. Chirago, Office of the Director 80/06/2 80/06/27
- 8007250630 Informs that GE & Saryent & Lundy engineering has been stopped temporarily, due to project delays Util unable to obtain necessary info for response to IF Bulletin 80-09 Response will be submitted by 810601 SHORB, E M Northern Indiana Public Service Co 80,07/09 1p

R Periodic operating reports % related correspondence

- B007110438 Forwards well charts for 800418-25, Bailty Wells w/o recorders pond levels, pheumitic pressure transducers & water meter readings for 800428, USQS wells for 800424 80HN R J Northern Indiana Public Service Co 80/07/07
- 8007280141 Forwards "1979-1980 Annual Rept Dailly Nuclear ! Site. Encompassing Apr 1979-Mar 1980," sixth annual ecological monitoring program rept
 PURCELL J F Northern Indiana Public Service Co 80/07/07 ip
- --800728014/ "1979-On Annual Rept Bailly Nuclear i Site, Encompassing Apr 1979-Mar 1980," sixth annual ecological monitoring program rept # Texas Instruments, Inc. 80/06/30 425pp
- 8007210464 Forwards well charts for 800625-0702.Bailly wells w/o recorders, poid levels, pneumatic pressure transducers & water meter readings for 800702 & US65 wells for 800701 BDHN:R J Northern Indiana Public Service Co 80/07/16 39pp
- 8007280482 Forwards well charts for 800709 16. Bailly wells w/o recorders, pond levels, pneumatic picsture transducers & water meter reading for 800/16 % USG9 wells for 800715 BOHN, R. J. Northern Indiana Public Service Co. 80/07/

- DOCKET 50-368 ARKANISAS NUCLEAR ONE, UNIT 2

 F Security, and real emergency trice protection plans
- 800707014B Documents NRC tellon & approval of temporary exemption to existing emergency plan. Section 4 3 1 i-C requiring decontamination shower facilities in emergency control ctr TRIMBLE.D C Artainsas Power % Light Co 80/05/27 2pp
- B007230073 Notification of 8/107/22 meeting w/AR Pover & Light Co in Bethesda.MD to review proposed early warning sys VISSING S Operating Reactors Branch 4 80/07/16 2pp

G Adjudicatory correspondence

BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refine protection for electrical cables EISENHUT, D.G. Division of Licensing 80/06/25 89pp

H General correspondence

- 8007110449 Requests response to encl R Lacewell ltr re plans to increase facility spent fuel storage pond site BETHUNE.E House of Rep 80/04/30 2pp
- 8907010024 Submits updated info re admittance of NRC personnel to facility Requests that permanent nonemplayee picture badges & site prientation be provided W/u encl SEYFRIT. K V Region 4. Dailas. Office of the Director 80/06/16
- B007070020 Requests that util provide IE headquarters w/microfiche copy of listed P2IDs MADSEN.G L Region 4. Dallas. Office of the Director B0/06/16 2nn
- 8007250070 Responds to encl 800504 ltr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/27 22pp
- BOO7:00:148 Requests removal of TB Connet from list of correspondence recipients & addition of N Regnolds Licensee has changed legal representation TRIMBLE D C Artansas Power % Light Co 80/07/03 lp
- 8007310331 Responds to 800625 itr re 800510 event at Unit 1 Forwards
 LER 80-015/01-0 & 1E Insp Repts 50-313/80-07 & 50-368/80-07
 Discusses treatment of spilled water & radipactive content
 of water 4/o enci
 SEYFRIT.K V Region A. Dallas. Office of the Director 80/07/15
 20p

P Operating license stage documents 4 correspondence

- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D C Division of Liconsing 80/06/11 62pp
- 8007010538 Summary of 800519 meeting u/util & C-E in Bethesda,MD record protection calculation syn software Six issues identified for further consideration before implementation in plant software List of attenders & six issues and MARTIN,R Operating Reactors Branch 3 80/06/18 App
- B007080066 Responds to NRC B00515 request for info re GE turbine discs
 Unit 2 turbing is impolse reaction.1,800 rpm tandomcompound, four flow, two-stage reheat unit Hours of operation,
 number of turbine trips & uverspends encl
 CAVANAUOH, W. Arkansa» Power & Light Co. 80/06/26 Bpp
- 8007150489 Application to amend Licenses DPR-51 & NPF-6, deleting requirement for testing reactor bldg smake detectors while reactors remain critical Suggested changes to Tech Specpages & Class III fee enci
 CAVANAUGH. W Arkansas Power & Light Co 80/06/26 2pp
- --B007150494 Suggested changes to Tech Spec Pages 3/4 3-43 & 110p re fire detection instrumentation * Arkansac Proper & Light Co B0/06/24 Ppp

- B007070253 Responds to NRC 800410 ltr requesting that all licensess amend Tech Specs so that definition of term "operable" would be consistent w/NRC STB Revision will require at least 70 days TRIMBLE D C Arkensas Power & Light Co 80/07/01 2pp
- 8007180429 Informs that util is interested in participating in NRC research program for interim reliability evaluation program, discussed in 800612 meeting TRIMBLE, D C Arkansas Power & Light Co 80/07/01 3pp.
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- B00716034B Submits info re RCP oil collection sys per R Martin request Sys not required to be seismically qualified TRIMBLE, D C Arkansas Power & Light Co 80/07/08 ip
- 8007210023 Requests info re 800624 loss of offsite power transient at Unit 1 Info includes description of switchyard operation, process computer printouts of alumn during transient & strip charts for primary & secondary sys NDVAK,T M Assistant Director for Operating Reactors 80/07/08.
- 8007240311 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel. Also submits info for OETR NDVAK, T M Assistant Director for Operating Reactors 80/07/08
- 8007150394 Advises of continued compliants w/current regulations re hydrogen production from clad-water reaction after installation of RCB vents per NURED-0578 Procedural guidelines will be submitted 810101 TRIMBLE, D C Arkanses Power & Light Co 80/07/10 2pp
- 8007270040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement power on to ratepayers NRC would present any info at formal hearing No investigation plannad VOEGELI.R J Office of the Executive Legal Director 80/07/18, 200
- B007280222 Tech Bpec change request to allow continued operation of plant Qualified rediation monitors will not be available in time to meet existing Tech Specs effective B0080i Class IJ fee encl STEEL, C L Arkansas Power & Light Co B0/07/21 4pp
- --B0072B0226 Proposed revisions to Tech Bpecs,Pages 3/4 3-39 through 3/4 3-42, constituting Amend 7 to OL Change allows continued operation beyond 800731 end date for interim method of determining post-accident radiation levels + Arkansas Power & Light Co 80/07/21. 4pp
- Q Inspection reports. IE Bulletins & correspondence
- B007020194 Responds to IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break w/Continued Feedwater Addition " Sufficient time would exist for operator to isolate affected oncethrough steam generator in event of overpressurfization. TRIMBLE, D C Arkansas Power & Light Co 80/05/27 5pp.
- 8007020269 Forwards IE Info Notice 80-22: "Breakdowns In Contemination Control Programs" No written response required. BEYFRIT.K.V Region 4. Dallas. Office of the Director 80/05/28.
- 8007210342 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required. SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/05/28 in
- 8007010040 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/05/29, ip
- 8007220177 Forwards lE Insp Repts 50-313/80-07 & 50-368/80-07 on 800422-0521 & notice of violation. MADSEN,O L Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- --8007220185 Notice of violation from insp on 800422-0521, # Region 4, Dallas, Office of the Director 80/06/04 ip.

- 007220197 IE Insp Repts 50-313/80-07 % 50-368/80-07 on 800422-0521
 Noncompliance noted incomplete written procedures, insufficient adherence to procedures & poor housekerping assures
 WESTERMAN, T. F. JOHNSON, W.D., CALLAHAN, L.J., Region 4, Dallas, Office of the Director 80/06/04 18pp
- 7020201 Responds to 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chumical Vol Control Sys (CVCS) Holdup Tanks "
 nily Unit I reactor cuolant make-up tank & Unit 2 vol
 ontrol tank could contain appreciable amounts of hydrogen
 RIMBLE.D C Arkonsas Power & Light Co 80/06/10 Spp
- 7220074 Forwards IE Info Notice 80-26, "Evaluation of Contractor A Programs" No written response required SEVERIT, K V Region 4, Dallas, Office of the Director 60/06/10
- 77160321 Forwards IE Info Notice 80-27, "Degradation of Reactor coolant Pump Studs " No specific action or response squired EYFRIT.K V Region 4, Dallas, Office of the Director E0/06/11
- 07300349 Formards IE Insp Repts 50-313/80-09 & 50-368/00-09 on \$300527-30 & notice of violation pADSEN, Q L. Region 4. Dallas. Reactor Operations Nuclear Support granch 80/06/12 2pp
- __8007300333 Notice of violation from insp on E00527-30
 ** Region 4. Dollas. Reactor Operations Nuclear Support Branch
 80/06/11 ip
- B007300334 IE Insp Repts 50-313/80-09 & 50-368/80-09 on 800527-30 Nuncompliance noted failure to adhere to procedures for handling temporary mode to jumpers & bypasses YANDELLIA A. WESTERMAN.T F Region 4. Dallas, Office of the Director 80/06/11 3pp
- ESO7070172 Ack receipt of 800529 itr informing NRC of steps taken to correct viblations noted in IE Insp Repts 50-313/80-06 & 50-368/80-06 AMDERN 0 L Region 4, Dallas, Reactor Operations Nuclear Support Stanch 80/06/17 ip
- E3:007230244 Forwards IE Investigation Repts 50-313/80-08 to 50-348/80-08 on E00510-12 No noncompliance noted BRDHN, G D Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/06/20 2pp
- --8007230237 IE Investigation Repts 50-313/80-08 & 50-368/80-08 on 800510-12 No noncompliance noted Major areas inspected radiological conditions & environ impact associated w/main coolant pump seal failure BROWN.6 D Region 4. Dallas, Fuel Facility & Materials Safety Branch WILBORN.1. Region 4. Dallas, Office of the Director. 80/06/18 5pp
- HO07240031 Forwards IE Circular 80-19. "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/20
- GO07300320 Ack receipt of B00527 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-313/B0-07 & 50-368/B0-07
 HABBEN 0 L Region 4, Dallas, Reactor Degrations Nuclear Support Branch 60/07/22 ip
 - 8007300325 Responds to NRC 800A05 ltr re vaolation noted in 1E Insp Repts 50-313/80-07 & 50-368/80-07 Corrective actions Junction box cover replaced & door on end closed TRIMBLE.D C Arkansas Power & Light Co 80/06/27 2pp
- State of State to Science of Science of State to Science of State to Science of State to Science of Science of
- B007300333 Respends to NRC 800612 ltr re violation noted in IE Insp Repts 80-313/80-09 & 80-360/80-09 Corrective actions entries in jumper & bypass log were cleared Completed pages of log were forwarded to files TRIMBLE,D C Arkansas Power & Light Co 80/07/02 2pp

- R Periodic operating reports & related correspondence
- 8007210381 Forwards monthly operating tept for June 1980 TRIMBLE.D C Arkansas Power & Light Co 80/07/15 1p
- --8907210382 Monthly operating rept for June 1980
 PENDERGRAFT R Arkansas Power & Light (c. 80/07/15 5pp
- B. Reportable occurrencus, LERs & related currespondence
- 8007010527 Forwards LER 80-032/03L-0
 TRIMBLE.D C Arkansas Power & Light Co 80/06/24 1p
- --B007010535 LER 80-032/03L-0 or 800525 during Mode 1 aperation, plant computer failed on three occusions Couse undetermined Computer saftware diagnostic indutines or backup computer sas will be purchased to alliviate problems PENDERGRAFTER Arkunsas Power & Light Co 80/06/24 lp
- 800701D434 Forwards LER 80-071/U4L-0
 TRIMBLE, D C Arkansas Power % Light Co 80/06/25 1p
- --B007010441 LER 60-031/04L-0 on 800527, during Mode 1 operation, condenser gas sample munitur 2RITS 6443 was found inoperable Radiation levels were normal per Tech Specs Caused by bearing failure on sample motor Engineering evaluation underway PENDERGRAFT, R Arkansas Power & Light Co 60/06/25 1p
- 8007140621 PNO-IV-80-023 on 800624, all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of svc for maint HUNNICUIT, D Region 4. Dallas, Affice of the Director 80/06/25
- 8007010407 Forwards LER 80-034/03L-0
 TRINRLE.D C Arkansas Power & Light Co 80/06/25 ip
- --B007010414 LER 80-034/03L-0 on 800531 during Node 1 appration, leak developed on charging pump B suction pipe at coupling for capped test connection line Caused by vibration Defective pipe spool piece will be replaced SHIVELY.C N Artansas Power & Light to 80/06/26 ip
- 8007280546 RBs 50-313/80-22 & 50-368/80-042 on 808624 events occurred on 800 ky power lines which resulted in lose of all 800 ky power lines & reactor trips of bath units Cause not stated Both units stable Followup rept will be transmitted O'HANLON.J P Arkansas Power & Light Co 80/06/26 2pp
- B007010437 Forwards updated LFR B0~025/03X-1 TRINBLE.D C Artansas Power & Light Co 60/06/2/ 1p
- ---R007010440 Upsated LER 80-0-55/03X-1 nm 800307.during Nade i operation. valve 2CV-5657 was isolated to facilitate mpint whek & alarm indicated valve open when valve was closed Caused by backed out strew leaving switch micallyined Switch realigned PENDERGRAFT.R Ariansas Power & Light Co 80/05/27 lp
- 8007080160 Forwards 1&R 80-037/031-0 FRIMBLE,D C Arkansas Power & Light Co 80/06/27 1p
- --B0070B0166 LER BU-033/031-0 on B00530 during Made 1 operation plant protection sys C high 8/0 delta P trip was bypassed Caused by failed power supply on bistable card Distable card replaced & plant protection sys totted PENDERGRAFT.R Arkansas Power & Light Co 80/06/27 lp
- B0070B0171 Forwards LER 80-036/031-0
 TRIMBLE, D C Arkansas Power & Light Co 80/06/27 1p
- --B0070B017B LER H0-036/03L-0 or 800602 during Mode 3 operation, steam driven emergency feedwater pump 2P7A tripped on overspeed following manual start Cause and determined Pump will be tested frequently until trip problem resolved PENDERGRAFT, A Arkansas Power & Light Co 80/06/27 Sp
- B007280646 Forwards LER 80-009/001-0 TRIMBLE.D C Arkansas Power & Light Co 80/06/10 Ip
- --BD0728D695 LER BD-035/Oth O on BOW601, containment sump level indicator 2L1-5641 indicated approx 30%, after n)1 water had been drained from sump Caused by maynets being detached from float ball on level solitic NS-5661 Float ball replaced PENDERGRAFT. R Arkansas Power & Light Co. 80/06/30 ip

- BOO70B0144 Forwards LER BO-040/0 (L-)
 TRIMBLE D.C. Arkinisas Power & Light Cp. HO/0//02 in
- --B0070R0154 LFR B0-(40/Oct -d on B00bUs during normal shutdown operations in Mode Demorgancy fredwarts supply valve PCV-1075 failed to open on command Caused by loose connection on valve operator metal lead Cannection (leaned to 150 bened SHIVELY, C N Arkansas Power tright Co 80/07/02 ip
- 8007090328 forwards (ER BO-0 M/OJL) TRIMBLE: D C — Arkansas Power & Light Cn — 80/07/03 — 1p
- --B007090336 LER B0-038/0 R-0 on B00607, safety injection tank found to have boron concentration less than Tech Sper Probably caused by boron stratification adequacy of sampling method to be determined
 PENDERCRAFT. R Arkansas Power & Light Co. 80/07/03 ip
- 8007140394 Forwards LER 80-042/01F-0
 TAIMBLE-D C Arkansas Power & Light Co 80/07/07 ip
- --8007140405 LER 80 042/017-0 on 800707 w/Mayfinet 500 kV transmission line out of svc.Nabelvale 500 kV tripped on ground fault Caused by ground fault & resulting overload SHIVELY.C N Arkansas Fower & Light (o 80/07/07 5pp
- --8007190660 LER RD-041/O3L-O on 800610 during Mode I operation, plant computer was taken out of svi tendering CRLSB inoperable Computer was taken out of svi to broubleshoot problem re CRT displays Barkup plant computer will be instabled PENDERGRAFT.R Arkansax Power & Light Co. 80/07/09 ip
- 8007150483 Forwards LER 80-037/03L-0 TRIMBLE.D C Alkansas Pownt & Light Co 80/07/09 1p
- --B007150693 LER BG-039/03L-O on B00610 during Blode I operation, steam driven emergency feedwater pump 2P7A would not accelerate above 1.000 rpm after successful start Caused by incorrectly wired load frim ramp generator to EGM guvernor PENDERGRAFT.R Arkansas Pawer & Light Co 80/07/07 ip
- 6007150694 LER 79-100 has been cancelled COLLINS M Arkansas Power & Light Co 60/07/14 ip
- | B007210396 | Forwards updated | ER | B0-018/03X | TRIMBLE, D | C | Arkonsas | Powor & Light | Co | | B0/07/14 | | 1p
- --8007210400 (Ipdated LER B0-018/03X-1 on 800407, following loss of offsite power transfirst, emergency fredwater flow became erratic Prubably Lauved by heating of fredwater train w/o forced Plow allowing water to drain bark to rondensate pump CLOGOURN.T Arkansas Power & Light Co 80/07/14 2pp
- BO07310334 Discusses BO0706 routine surveillance test on emergency steam driven feedwater pump during which steam leak developed Requests that one of five failed study be delivered to Peramuters, Inc for analysis MADSEN.6 L. Region 4. Dallas, Ructor Operations Nuclear Support Branch 180/07/15 2pp
- DOCKET 50-349 WILLEAM B MCGUIRF NUCLEAR REATION, UNIT 1

 A Application/construction stage decements & correspondence
- 8007(105)9 Notification of 1000)4 meeting w/util in Bethesda.MD to discuss util design review of control room
 BIRKEL.R A ticensing Dranch 1 80/04/30 2pp
- 8007010571 Advise: that NRC 800409 request for independent plant-wide audit of installation of sufety-related equipment & cables need not be fulfibled based on addl info provided in util 800405 to youngstood and the fulfible based on addl info provided in util YOUNGSLOOP, B / Licensing Branch 1 80706770 3pp
- :007090091 Notsfication of 6006/5-27 meeting w/util to discuss TMI-2 action plan items Agunda encl BIRKFL:R A Licensing Branch 1 50.06/20 Spp
- B007230001 Forwards statement of policy to requirements to be met for current (M. applications, as derived from NURFG-0660 & found in NUREG-0694 E1SEMHULD C DEVISION of Licensing 80/06/26 2pp

- 8007110583 Forwards request for addl info re reactor sys as result of review of application for OLs
 YOUNGBLOOD, B J Licensing Branch 1 80/06/30 3pp
- 8007160486 Forwards TMJ review item schedule.designating principal branch review responsibilities
 BIRKEL.R A Licencing Branch 1 80/06/03 4pp
- 8007170696 Forwards schedule for review of TMI-2 task force items including designated principle branch review responsibilities
 BIRNEL:R A Licensing Branch 1 80/06/30 App
- 8007230635 Forwards std order for DDE work MATTSON:R J Division of Safety Technology FIN A-1121-0 80706/30 3pp
- --8007230652 Std order for DDE work "Review of Auxiliary Feedwater Bys Reliability Evaluation Studies for Diablo Camyon I, HeGuire 1.5ummer 1 & San Dnofre 2 & ECCS Reliability Analysis of Manual vs Automatic " Issued to Sandia Labs ORENIER.B L Division of Safety Technology FIN A-1121-0 80/06/27 7pp
- 8007080345 Forwards info & drawings re use of Category I masonry walls for supporting piping & components in response to NRC 800421 ltr Drawings available in Central Files only Fourteen illegible drawings encl PARKER.W O Duke Power Co 80/07/02 27pp
- 8007170685 Requests addl info re reactor sys YGUNGBLGGD,B J Licensing Branch 1 BO/07/02 Spp
- 8007110307 Forwards Chem-Nuclear "Process Control Program for CNSI Mobile Solidification Units Using Dow Process" Affidavit for withholding encl Program withheld (ref 10CFR2 790) PARKER.W D Duke Power Co 80/07/08 lp
- 8007180069 Requests that protection sys design be reviewed to determine degree of conformance to listed triteria Review results should be submitted by 800804
 YGUNGBLOOD, B J Licensing Branch 1 80/07/07 5pp
- 8007230127 Forwards summary of 800402-04 human factors engineering control room review Certain deficiencies must be corrected Requests meeting w/util to discuss matters before 800725 YOUNOBLOOD, B J licensing Branch 1 80/07/10 19pp
- B007230198 Discusses augmented low power startup test program for nearterm OL applicants Each applicant must perform tests similar to TVA proposed program for Sequeyah EISENHUT.D 0 Division of Licensing 80/07/10 3pp
- 8007210385 Forwards response to NRC 800625 request for add1 info re secondary water chemistry monitoring program Info provides administrative control rept parameters PARKER.W D Duke Power Co 80/07/14 2pp
- 8007220536 Forwards revised draft environ protection plan (nonradiological) Also requests that NRC not incorporate document as part of OL for facility PARKER, W D Duke Power Co 80/07/17 Bpp
- 8007280166 Advises that NRC has completed review of info in 800616 ltr re reactor vessel noizles Reactor vessel fabricated using procedure for welding & pre & post-clad heat treatments that increase potential underclad cracking YOUNGBLOOD. B J Licensing Branch 1 80/07/17 3pp
- 8007220365 Forwards updated pages to util 800323 response to TMI concerns Matl addresses NUREG-0694 requirements Another revision scheduled for 800801 & fuel loading for mid-Bept 1980
 PARKER, W D Duke Power Co 80/07/18 44pp
- 8007280011 Notification of 800730 meeting w/util in Bathesda.MD to discuss review of plant control room BIRKEL.R A Licensing Branch (80/07/18 4pp
- B007300459 Forwards addl info re justification for reducing steam generator low-low water level error allowance span, supplementing 791218 & B00507 ltms Proprietary page withheld (ref 100FRZ 790) Application for withholding enc? PARKER, W O Duke Power Co B0/07/21 13pp

- BOO7230181 Discusses unsite emergency diesel generator reliability per NUREO/CR-0660 Reliability is sufficiently assured for operation through first refueling, however, certain design & procedural modes are required YOUNOBLOOD, B. J. Licensing Branch 1 BO/07/22 4pp
- 8007310339 Forwards request for add) info re RCS vents for review of OL application
 TEDESCO.R L Assistant Director for Licensing 80/07/23 5pp
- F. Security, medical, emergency & fire protection plans
- B007010309 Forwards security plan for on site storage & in transit requirements for SNM Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/04/24 1p
- EGO7240060 Reviews state & local emergency preparedness measures for facility Revisions per NUREO-0654/FEMA REP-1 95% complete & compliance w/NRC stds established prior to EGO101 Completion scheduled for Aug 1980

 HCCONNELL, J W Federal Emergency Management Agency EGO/07/08 1p
- 8007300077 Forwards summary of recommendations from NRC review & 800617~18 meeting re facility emergency plan TEDESCO.R L Assistant Director for Licensing 80/07/23 16pp

Adjudicatory correspondence

- 6007140461 Statement of Board of Commissioners' position in apposition to radwaste transportation through Gaston County, NC Urges transportation via Interstates 77 & 65 Encourages expending energy & money for recycling W/correspondence County, NC 60/04/28 61pp
- --- GOO7140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON.H B Gaston County.NC BO/04/25 2pp
- --B0071404BB Forward's position of Gaston County Board of Commissioners, NG. apposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNE, C. A. Gaston County, NC 80/04/15 ip
- ECC7030036 Response in apposition to applicant 800820 motion to terminate stay of ASLB 790418 initial decision Suppl 3 to SER indicates that NRC review, re THI-related roquirements, is not complete Intervenor 800409 ltr to util enc!

 RILEY, J L Carolina Environmental Study Group 80/06/09 App
- --B007030040 Matian to admit TMI-related new contentions & to reopen OL hearing Consequences of significant hydrogen rolesse in Hestinghouse containment, were not subj of adversary proceedings Contentions & Certificate of Svc encl Riley, J. Caralina Environmental Study Group 80/06/09 6pp
- 8007010282 Forwards BER, Suppl 3, per ASLB 790418 initial decision. LBP-79-13, which stayed issuance of rept W/o encl METCHEN.E 0 Hearing Branch 4 80/06/19 ip
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D O Division of Licensing 80/06/25 89pp
- BOO7020620 Order granting extension until BO0707 for applicant to respond to intervenor BO0609 motion re admission of new contentions & reopening of OL hearings record LAZO,R H Atomac Bafety and Licensing Board Panel 80/06/27 1p
- BOO7090320 Forwards, in response to BOO630 request in OL proceeding, NVREQ-0660, "NRC Action Plan Developed as Result of TMI-2 Accident," & BOO602 "Further Commission Guidance for Power Reactor OLs, Statement of Policy " W/o Encls KETCHEN.C O Hearing Branch 4 BO/07/02 lp
- BO07:40004 Response in opposition to Carolina Environ Study Group motions to add new contentions & to reopen OL hearing Petitioner Pailed to comply w/new evidence criterion MCQARRY, J M Debevoise & Liberman, 80/07/09 13pp
- ---B007140007 Affidavit addressing issue of hydrogen generation & control following postulated TMI-type accident Action implemented effectively precludes excess hydrogen generation CANADV, K S Consumers Power Co 79/07/09 5pp

- --8007140010 Affidavit attesting that EC(2 moets acceptance criterie Mydrogen explosion will not present major damage to reactor vessel Charlotte Observer /91101 article & Certificate of Svc encl RABINW H Consumers Power to PO/0//09 5pp
- 8007140019 Response in apposition to util 800530 mation seeking termination of stay of ASLB 790418 initial decision Opposes Carolina Environ Study Group 800609 motion to reagen record for addicantentions Certificate of Svc encl KEYCHEN.E G Hearing Branch 4 80/07/10 12pp
- B007160613 Forwards re-executed Certificate of Svc correcting svc date to B00710 re NRC B00710 response to carolina Environ Study Group motion to reopen record & NRC B00710 response to util motion to terminate stay of initial decision DAVIS.L D Hearing Brench 4 B0/07/15 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta Office of the Director 80/05/08 2nd
- B007020204 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- B007210449 Forwards IE Circular B0-13, "Grid Strap Damage in Westinghouse Fuel Assemblies ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/05/28
- 8007010213 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/27
- 8007220048 Forwards IE Info Notice 80-25. "Evaluation of Contractor GA Programs" No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10 20p
- 8007160255 Forwards IE Info Nutice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/1k
- 8007250344 Forwards 1E Info Notice 80-2B, "Prompt Reporting of Info in Accordance W/10CFR50 55(c) " No written response required O'REILLY, J P Region 2. Atlanta, Diffice of the Director 80/06/13 2nn
- 8007020763 Forwards 1E Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REJLLY, J.P. Region 2. Atlanta. Office of the Director 80/06/18 in
- B007100036 Responds to 16 Bulletin 77~16 re vital area access control Controls will be addressed in NNSB review of facility security plan, therefore specific response is unnecessary PARKER. M O Duke Power Co 80/06/18 ip
- 8007020459 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007090165 Forwards 1E Insp Rept 30-369/RO 14 on 800602-04 No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/24 1p
- --B007090170 IE Insp Rept 50-369/80-14 on 800602-04 No noncompliance noted Major areas inspected prolicensing physical security survey, vital areas protected area & physical barriers Details withheld (ref 10CFR2 790)
 GILLESPIE, F. P. HDWELL, J. C. Region 3. Chicago, Office of the Director 80/06/23 ip
- B007170104 Forwards IE Circula: BU-14, 'Redicactive Contamination of Plant Demineralized Water Sus & Resultant Internal Contamination of Personnel' No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/24 ip

- 8007230235 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 115; & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/27
- 8007250598 Ack receipt of 15 ln*p Repts 50-369/80-10 & 50-370/80-06 No proprietary info PARKER.W O Duke Power Co 80/06/30 ip
- --8007250603 Forwards &E Insp Repts 50-369/80-10 & 50-370/80-06 on 800514-16 No concompliance noted HURPHY, C E Region 2. Atlanta. Practor Construction & Engineering Support Branch 80/06/10 2pp
- --8007250407 IE Insp Repts 50-369/80-10 & 50-370/80-06 on 800514-16 No noncompliance noted Major areas inspected unresolved items. IE builetins & Lirculars & Lirculars dentified items HUNTAM D. Region 2. Atlanta. Office of the Director RAUSCH. J K. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/10 5pp
- E007240357 Ack receipt of IE lnsp Rept 50-369/80-09 on 800506-09 No proprietary info PARKER, U O Duke Power Co 80/07/03 ip
- --800724036B Forwards IE Insp Rept %0-369/80-09 on 800506-09 No noncompliance Noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/13 2pp
- --B007240377 IE Insp Rept 50-369/80-09 on 800506-09 No noncompliance noted Major areas inspected preoperational test program, procedure reviews & rowlews of completed preoperational test packages

 DONAT.T J Region 2. Atlanta. Office of the Director GUICK, D Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/06/11 6pp
- BOO7210114 Responds to IE Bullstin BO-OB, "Framination of Containment Liner Penetration Welds " Welds in 22 penetrations repaired per nondestructive test performed during const Summary of types & sixes of penetrations en
- 8807240469 Ack receipt of 1E Insp Rept 50-369/80-09 No proprietary info PARKER, W D Duke Power Co 80/07/07 1p
- 9 Reportable occurrences. LERs & related correspondence
- 8006090319 Forwards Significant Deficiency Repts 369/80-06 & 370/80-05 re fire protection sys valve misapplication PARKER, # 0 Duke Power Co 80/05/16 ip
- B007160366 Pert 21 rept re Valcor Valve Model V32600-554-1 not designed for continuous oppration in energized mode Valves installed in diesel generator control air sys BDRGD.G J Valcor Engineering Corp 80/04/27 2pp
- BOO7140637 Forwards Significant Deficiency Repts 369/80-07 & 370/80-06 re centrifugal charging pump operation following secondary side high energy line rupture PARKER:W D Duke Power Co 80/07/07 ip
- --8007160663 Significant Deficiency Repts 369/80-07 & 370/80-06 recentrifugal charging pump operation following secondary side high energy line rupture Potential exists for inadequate min flow w/damage to pumps * Duke Power Co 80/07/07 1p
- 8007240333 Interim Part 21 rept to defective ITI actuators in dampers Customer notafication encl Jobs classified nonnuclear safety-related are not reportable Actuators supplied for other jobs are considered purchaser responsibility SLOAN.D.E American Warming & Ventilating. Inc 80/07/08 50pp
- 8007300330 Significant Deficiency Repts 50-369/80-09 & 50-370/80-08 re solenoid valves On 800627, diesel generator instrument air pressure observed lower than normal Caused by leaking vent Valve stroke to be modified or coils replaced DONAT.T J Duke Power Co 80/07/25 2pp
- 8007300339 Deficiency rept re improper weld configuration on steam generator encl stiffener ring connections Cause not stated Melds have been modified to meet design drawings Personnel rainstructed to assure compliance widesign drawings PARKER, W O Duke Power Co 90/07/25 2pp

- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B007110519 Notification of B00514 merting w/util in Bethesda.HD to discuss ptil design review of control room BIRKEL.R A Licensing Branch 1 80/04/30 2pp
- 800701057: Advises that NRC 800409 request for independent plant-wide audit of installation of safety-related equipment & cables heed not be fulfilled based on addl info provided in util 800605 ltr YOUNGBLOOD, B J Licensing Branch 1 80/06/20 3pp
- 8007090091 Notification of 800625-27 meeting w/util to discuss TMI-2 action plan items Agenda encl BIRKEL.RA Licensing Branch 1 80/06/20 5pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENNUT, D G Division of Licensing 80/06/26 2pp
- 8007110583 forwards request for add1 info re reactor sys as result of review of application for OLs' YOUNGBLOOD, B J Licensing Branch 1 80/06/30 5pp
- 8007160486 Forwards TMI roview item schedule designating principal branch review responsibilities
 BIRKEL.R A Licedsing Branch 1 80/06/03 4pp
- 8007170696 Forwards schedule for review of TMI-2 task force items including designated principle branch review responsibilities
 BIRKEL, R.A. Licensing Branch 1 80/06/30 4pp
- B007080345 Forwards info & drawings re use of Category I masonry walls for supporting piping & components in response to MRC B00421 ltp Drawings available in Central Files only Fourteen illegible drawings encl PARKER.W O Duke Power Co 80/07/02 27pp
- 8007170688 Requests add1 info re reactor sys YOUNGBLOOD: B J Licensing Branch 1 80/07/02 5pp
- 8007110309 Forwards Chem-Nuclear "Process Control Program for CNSI Mobile Solidification Units Using Dow Process " Affidavit for withholding encl Program withheld (ref 105782 790) PARKER.W O Duke Power Co 80/07/08 ip
- 8007180049 Requests that protection sys design be reviewed to determine degree of conformance to listed criteria Review results should be submitted by 800804
 YOUNDBLOOD, B J Licensing Branch 1 80/07/09 5pp
- 8007230127 Forwards summary of 800602-06 human factors engineering control room review Certain deficiencies must be corrected Requests meeting w/util to discuss matters before 800725 YOUNGBLOOD, B J Licensing Branch 1 80/07/10 19pp
- 800723019B Discusses augmented low power startup test program for nearterm OL applicants Each applicant must perform tests similar to TVA proposed program for Sequoyah EISENHUT, D.G. Division of Licensing 80/07/10 3pp
- 8007210383 Forwards response to NRC 800625 request for addl info re secondary water chamistry monitoring program Info provides administrative control rept parameters PARKER. H O Duke Power Co 80/07/14 2pp
- BOD7220534 Forwards revised draft environ protection plan (nonradiological) Also requests that NRC not incorporate document as part of OL for facility PARKER, W O Duke Power Co BO/07/17 Spp
- B007280166 Advises that NRC has completed review of info in B00616 ltr re reactor vessel nozzles Reactor vessel fabricated using procedure for weiding & pre & post-clad heat treatments that increase potential underclad cracking YOUNOBLOOD, B J Licensing Branch i B0/07/17 3pp
- B007220365 Forwards updated pages to util 800523 response to TMI concerns Mail addresses NUREO-0694 requirements Another revision scheduled for 800801 & fuel loading for mid-Sept 1980 PARKER, W. O. Duke Power Co. 80/07/18

- BOO7280011 Notification of BOO7JO meeting w/util in Bethesda, MD to discuss review of plant control room BIRKEL, R A Licensing Branch 1 BO/07/19 4pp
- B007300459 Forwards add1 info to justification for reducing steam generator low-low water level error allowance span.
 sypplementing 791418 & B00507 ltrs Proprietary page withheld fref 10CFR2 790) Application for withhelding encl
 PARKER, W O Duke Power Co 80/07/21 13pp
- 8007250181 Discusses onsite emergency dissel generator reliability per NUREO/CR-0660 Rallability is sufficiently assured for operation through first refueling, however certain design 5 procedural mode are required YDUNGBLOOD, B J Licensing Branch 1 80/07/22 4pp
- 8007310338 Forwards request for add1 info re RCS vents for review of OL application
 TEDESCO.R L Assistant Director for Licensing 80/07/23 5pp
- F Becurity, medical, emergency & fire protection plans
- 8007010307 Forwards security plan for on site storage % in transit requirements for SNM Plan withheld (ref 10CFR2 790) PARKER:W D Duke Power Co 80/06/24 lp
- 8007240060 Reviews state & local emergency proparedness measures for facility Revisions per NUREG-0654/FEMA REP-1 757 complete & compliance w/NRC stds established prior to 800101 Completion acheduled for Aug 1980 MCCONNELL, J W Federa) Emergency Management Agency 80/07/08 ip
- 8007300077 Forwards summary of recommendations from NRC review & 800617-18 meeting re facility emergency plan TEDESCO.R L. Assistant Director for Licensing 80/07/23 16pp
- 9 Adjudicatory correspondence
- 8007140461 Statement of Board of Commissioners' position in apposition to radwasto transportation through Coston County, NC Urges transportation via Interstates 77 & 85 Encourages expending energy & money for recycling Wicorrespondence # Gaston County, NC 80/04/28 61pp
- ---B007140473 Forwards add1 comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON: H B Gaston County. NC B0/04/25 2pp
- ~-B007140488 Forwards position of Gaston County Board of Commissioners, NC opposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNC C A Gaston County.NC B0/04/15 ip
- 8007030036 Response in opposition to applicant 800520 motion to terminate stay of ASLB 770418 initial decision Suppl 3 to SER indicates that NRC review, re TMI-related requirements is not complete Intervenor 800609 ltr to util encl RILEY.J L Carolina Environmental Study Group 80/64/09 6 B0/06/09 4pp
- ~-B007030040 Motion to admit (MI-related new contentions & to reopen CL hearing Consequences of significant hydrogen release in Hestinghouse containment, were not Subj of adversary proceedings Contentions & Certificate of Svc encl RILEY, J L Carolina Environmental Study Group 80/04/09 App
- 8007010282 Forwards SER, Suppl 3, per ASLB 790418 initial decision. LIB-79-13, which stayed issuance of rept W/b encl KETCHEN, E G Heating Branch 4 80/04/19 lp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petitinn for reconsideration of 780413 memorandum & order UCS 771104 petition snught action refire protection for electrical cables EISENHUI.D C Division of Licensing 80/06/25 87pp
- 8007020620 Order granting extension until 800707 for applicant to respond to intervenor 800609 motion re admission of new contentions & reopening of OL hearings record LAZO.R M Atomic Safety and licensing Board Panel 80/06/27
- 8007070320 Forwards.in response to 800630 request in OL proceeding, NUREG-0460. "NIRC Action Plan Developed as Result of THI-2 Accident," & 800602 "Further Commission Guidance for Power Reactor OLs. Statement of Policy " W/o encla KETCHEN,E O Hearing Branch 4 80/07/02 lp

- 8007140004 Response in apposition to intolina Environ Study Group motions to add new contentions to to reupth DL Araring Petitioner failed to comply when Evidence writerion MCGARRY. J M Consumers Down to MCGARRY. J M Deberoise & Liberman 80/01/09 13pp
- --800714000/ Affidavit addressing issue of hydrogen generation & control following postulated TMI-type accident Action implemented effectively precludes excess hydrogen generation: CANADY.K S Consumers Power Co. 79-07/09 Spp
- --B007140010 Affidavit attesting that L/(9 meets acceptance criteria Hydrogen explosion will not present major damage to reactor vessel Charlotte (Observe) 791101 article & Contificate of Svc encl RASIN.W H Consumers Power Ce 30/07/09 5pp
- E007140019 Response in apposition to util 800930 motion seeking termination of stuy of ASIN 790418 initial decision apposes Caroline Environ Study Group 800607 motion to reopen record for addicantesions Certific to 6 50c 201 KETCHEN, E.G. Hearing Branch 1 80/07/10 12pp
- 8007160613 Forwards re-executed Certificate of Syc correcting syc date NO/Abblid Forwards re-election Certificate of SAC correcting to BOOTO re NRC POOTIO response to Carolina Envison Study Group motion to reapon record % NRC 800710 response to util motion to terminate stay of Justial decision DAVIS.L D Hearing Branch 4 80/7/15 2pp
- Q Inspection reports. IE Bulletins % correspondence
- 8007240122 Forwards IE info Notice BU-PO. Loss of Decay Heat Removal Capability at Davis-Bosse Unit 1 While in Refueling Hode " No response required Region 2, Atlanta, Office of the Director 80/05/08 O'RETLLY, J.P.
- 8007210449 Forwards IE Circular 80-13, 'Grid Strap Damage in Westinghouse Forl Assembling 'No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director
- 8007010213 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2 Atlanta Office of the Director 80/05/29
- 8007220048 Forwards IE Info Notice 80-26 "Evaluation of Contractor GA Programs 'No written response required

 O'REILLY.J P Region 2, Atlanta Office of the Director 80/06/10
- 8007160255 Forwards IE Info Notice 80-2" "Degradation of Reactor Coolant Pump Stude "No specific action or response required
 O'REILLY J.P. Region 2. Atlanta Office of the Director BO/06/11 1 n
- 8007250344 Forwards It Info Notice 80-20, "Prompt Reporting of Info in Accordance W/(0CFRSO 55(e))" No written response required O'REILLY J.P. Region 2 Atlanta Office of the Director 80/06/13
- 8007020459 Forwards IE Circula: 80-15. "ps: or Peactor Coolant Pump Cooling & Natural Circulation Couldows " Ho written response required O'REILL'(J.P. Region P. Atlanta, uffice of the Director 80/06/20
- B007170104 Forward* IC Circular 40-14 "Radioartive Contamination of Plant Deministric Water bys & Position: Internal Contamination of Personnel "No circular response required O'REINLY, J.P. Region C. Atlanta, Office of the Director 80/06/24
- B007230235 Forwards IE Bolletin 80-16 (Pricential Misapplication of Rosemount Inc Models 1191 (1152 Presente Transmitters W/Either A or D Cutput Code (Written Jergonse required IE Circular 80-16 also and to written response required O'REILLY, J.P. Region 2, Atlantia, Orfice of the Director 80/06/3 80/05/27
- 8007250598 Ack receipt of tE stop Rept 50-669 80 to & 50-370/80-06 No proprietary info PARKER, W.O. Duke Power Co. Received 1p
- -8007250603 Formaide If Inip Repts 10-089 in 10 % 50-070780-06 on 800514-16 No noncompliance noted HURPHY.C F. Augion 2. Allanta, keaster construction & Engineering Support Branch 80/06/1) App

- --8007250607 IF Insp Repts 50 349/80-10 t 50-370/80-06 or 800514-16 No noncompliance noted Major areas inspected unresolved items.

 IE buildtins 'circular' licensee identified items.

 HUNT/M D Region 2 Atlanta Office of the Director RAUSCH, J K
 Region 2. Atlanta Reactor Construction 'Engineering Support

 Branch 80/06/10 5pp
- 8007210114 Responds to IE Bulletin 80-08. 'Examination of Containment Liner Penetration Welds ' Wild; in 72 penetrations repaired per nundestructi e test performed during const Summary of types % sizes of pinetrations end! PARKER.W O Dote Power Co 80'0''O' 9pp
- S Reportable occurrences, LFRs & related correspondence
- BOO6030319 Forwards Significant Deficiency Repts 369:80-06 & 370/80-05 refire protection systation PARKER.H O Duke Hower Co. 89/08/16 1p
- 8007160366 Part 21 tept re Valcor Valve Hodel V52600-554-1 not designed For continuous operation in energized mode Valves installed an diesel generator control air sys BORGO,G J. Valcor Engineering Corp. BO/O6/F7 2pp
- 8007160657 Forwards Significant Deficiency Repts 369/80-07 & 370/80-06 re centrifugal charging pump operation following secondary side figh energy line rupture PARKER.W O Duke Power Co 90/07/07 lp
- --8007160663 Significant Deficiency Repts 359/80-07 & 370/80-06 re centrifugal charding pump operation following secondary side high energy ling rupture Potential exists for inadequate min flow w/damage to pumps

 * Duke Power Co 80/07/07 1p
- BOO7240353 Interim Part 21 rept re despetive ITT actuators in dampers Customer notification encl Jobs classified monnuclear safety-related are not reportable Actuators supplied for other jobs are considered purchaser responsibility SLOAN.D & American Warming & Ventolating. Inc. 80/07/08 DOpp
- 8007300330 Significant Deficiency Repts 50-369/80-09 & 50-370/80-08 re solennid valves On 800627, dierel generator instrument air pressure observed Jower than normal Caused by Iraking yent Valve stroke to be modified or cult replaced DONAT.T J. Duke Power to 80/07/25 2pp

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- A Application/construction stage decuments & correspondence
- 8007030239 Notification of 800/02 meeting w/BWR licensing review group in Bethesda ND to dircuss consensus position on leactor SVE bldg open issue WILSON.J N Licensing Branch L 89/06/18 9pp
- 9007010297 Surmary of 800613 meeting w/utils.KMC.inc.GE.Bechtel.S&W & Sargent 's Lundy in Bethesda.MD re consensus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Salle doctet Statu- repts enci WILSON, J N Assistant Director for Licensing 80/06/19 46pp
- BD07210176 forwards NRC evaluation of GE rept, NEDE-24010-P % Supple 1-3. "Technical Bissis for the of Square-Ropt-of-Gum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept proceptable subj to certain constraints MATTSON.R J Division of Safrty Technology B0/06/25 3pp
- BOO723000: Forwards statement of policy or requirements to be met for current OL applications, as derived from NUREG-0660 % found to NUREG-0664 & Found to NUREG-0664 & Pavision of Licensing 80/06/26 2pp
- \$3007170475 Summary of P00614 morting w/Hark II lead plant applicants re definition of F-quencher load ages following safety/ relief val e actuation Visuyraphs encl di Containment Systems Branch 80/06/27 App

teting w/Hark II lead plant applicants re frants to define T-quencher load walve of teation New methodology rk II lead plants th NO/05/27 Jpp

hudoling of 800702 meeting w/BWR thesda MD to discuss consensus wh open issues Meeting

us for Licensing 80/07/03 in

- --8007170347 Not)+ication of 800722 meeting w/BNR licensing review group in Bethesda.HD to discuss THI issues required for OL
 - issuance
 WILSON, J N Assistant Director for Licensing 80/07/03 ip
- --8007170351 Notification of 800724 meeting w/BWR licensing review group in Bethesda, MD to introduce BWR licensing review group & present consensus positions for Power Sys Branch, Containment Sys Branch & Equipment Qualification Branch WILSON, J N Assistant Director for Licensing 80/07/03 9pp
- 8007230621 Summary of 800612 meeting w/Mark II owners group in Bethesda:MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON,C J. Generic Issues Branch 80/07/03 57pp
- 0007150529 Forwards response to NRC 800421 request for info re masonry wall design further review of masonry wall design is being conducted at LaSalle to complete response to 12 Bulletin 80-11 Package of 231 oversize drawings ncl PEOPLES.D L Commonwealth Edison Co. 80/07/08 23pp
- --8007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming * Sargent & Lundy, Inc. 80/07/08 231pp
- 8007160606 Forwards "Condensation Oscillation (CO) Load Data for Lasalle" & "Chugging Loads for Assessment of 4T CO Data " Repts withheld (ref 10CFR2 790) & available in Central Files DELGEORGE, L.O. Commonwealth Edison Co. BO/07/11 2pp
- 8007230133 Notification of 800725 meeting w/BMR Licensing Review Oroup in Bethesda-ND to discuss concensus positions of DMR Licensing Review Group on ICSB open issues WILSON.J N Licensing Branch 1 80/07/16 10pp
- 8007220518 Responds to 800922 & 0604 info requests Info re BHR jet pump holddown beam cracking will be submitted by 800815 & reactor vossel underclad cracking info by 800901 PEOPLES D L Commonwealth Edison Co 80707717 1p
- 8007250448 Forwards facility emergency procedures Table of contents included HOLYOAX, R H Commonwealth Edison Co 80/07/18 Ip
- --B007250455 Emergency procedures for facility including general abnormal procedures, general abnormal index & operating abnormal index * Commonwealth Edison Co. 79/05/22 82pp
- 8007250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago. It to discuss lead Mark II plants chugging % C/O load specs
 ANDERSON. C Generic Issues Branch 80/07/23 2pp
- B00729069B Forwards index for Facility general procedures Index will suppl general abnormal procedures & operating abnormal procedure index already forwarded H/o encl HOLYOAK,R H Commonwealth Editon Co 80/07/23 ip
- 8007300D33 Forwards request for addl info to complete review of FBAR TEDESCO.R L Assistant Director for Licensing 80/07/23 3pp
- F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld Fref 10CFR2 790)
 PEOPLES, D L Commonwealth Eduson Co 80/06/27 1p
- G Adjudicatory correspondence
- B007310243 Forwards Commission 800327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D. Q. Division of Licensing 80/06/23 87pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007070767 Forwards 800630 affidavat re 800613 distribution of Amend 49 DFLGEORGF.L D Communwealth Edison Co 80/06/27 2pp

- Q Inspection reports, IE Bulletins & correspondence
- 8007140837 Forwards IE Bulletin 80-13, "Cracking in Core Spray Bpargers " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/05/12 is
- \$007020065 Forwards 1E Info Notice 80~22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/29 to.
- D007170094 Forwards IE Insp Rept 50-373/80-24 on 800401-0509 & notice of violation
 KEPPLER, J 9 Region 3. Chicago, Office of the Director B0/05/29
 288
- ---B007170098 Notice of violation from insp on 800401-0509
 Region 3, Chicago, Office of the Director 80/05/26 1
- --8007170103 IE Insp Rept 50-373/80-24 on 800401-0507 Nontompliance nuted no procedure provided for removing control rous from reactor vessel on 800412 resulting in potential damage to two control rods & drive mechanisms MALKER, R D , EMEPLEY, S E , EPESSARD, R L Region 3, Chicago, Office of the Director 80/05/28 Bpp
- G007220136 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs " No written response required KEPPLER, J. O Region 3, Chicago, Office of the Director B0/06/10 to
- 8007140314 Forwards IE Bulletin 80-14, "Degradation of SHR Scram Discharge Vol Capability " No written response required REPPLER.J O Region 3, Chicago, Office of the Director 80/06/12 to
- BO07280709 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(s)" No written response required KEPPLER, J G Region 3, Chicago, Office of the Oirector 80/06/13 to
- 6007100004 Forwards response to IE Bulletin 80~09. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Drawden 2 & 3 uses AH-90 or NH-90 spries hydramotor actuators
 PEOFLES.D L. Commonwealth Edison Co 80/06/16 3pp
- 9007230693 Forwards IE Insp Repts 50-373/80-26 & 50-374/80-16 on 600528-29 No noncompliance noted FIORELLI.6. Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/06/19 2pp
- --B007230700 IE Insp Repts 50-373/80-26 & 30-374/80-16 on B00528-29 No noncompliance noted Major areas inspected mod in Unit 1 suppression pool, welding on dc power panels & calibr of 4160-volt & 480-volt switch gears
 NEIBLER, J H, WILLIAMS, C C Region 3, Chicago, Office of the Director 80/06/18 4pp
- B0070205B9 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/20 tp.
- ECO7230266 Forwards IE Insp Repts 50-373/80-28 & 50-374/80-17 on BOO610-11 No noncompliance noted FIORELLI-9 Region 3, Obicago, Reactor Construction & Engineering Support Branch BO/06/23 2pp
- --BO07230273 IE Insp Repts 50-373/80-28 & 50-374/80-17 on 800410-11 No noncompliance noted Major areas inspected preservice insp procedures, work activities & nondestructive examination test
 DANIELEGN.D.H , WARD.K D Region 3, Chicago, Office of the Director B0/06/20 Spp
- 9007170430 Forwards IE Circular 80~14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/24 to

- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemburt inc Models 1151 & 1152 Prossure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-16 also and No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 60/06/27 to
- 8007230275 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-373/80-15 HEISHMAN,R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/07/03 lp
- ~-800723028i Responds to NRC 800509 ltr re violations noted in IE Insp Ropt 50-373/80-15 Corrective actions battery chargers have been cleaned Units 1 & 2 steam dryers require extensive mod PEOPLES.D L. Commonwealth Edison Co. 80/06/06 App
- 8007250638 Forwards response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " Dresden Unit 1 designs will be reviewed & Feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D & Commonwealth Edison Co 80/07/09 7pp
- 8007210283 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/80-20 & 30-374/80-13 FIURELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/14 1p
- --8007210292 Responds to NRC 800426 ltr re violations noted in IE Insp. Repts 50-373/80-20 & 50-374/80-13 Corrective actions design control program deficiencies are subj of request for ASME use Urges reconsideration of Item 3 infraction PEOPLES,D L Communwealth Edison Co. 80/04/06 App
- 8007250467 Submits supplemental response to IE Bulletin 80-09, "Mydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES.D L Commonwealth Edison Co 80/07/15 ip
- B007280681 Ack receipt of 800625 Itr informing NRC of steps taken to correct violations noted in IF Insp Rept 50~373/80-24
 KEPPLER, J G Region 3. Chicago, Office of the Director B0/07/17
 Ib
- --8007280688 Responds to NRC 800529 ltm re violations noted in 1E Insp Rept 90-373/80-24 Corrective actions wrote formal equipment removal procedure PEOPLES.D L Commonwealth Edison Co 80/06/25 4pp
- 8007310530 Ack receipt of 800A0A & 0707 ltrs informing NRC of steps taken to correct violations noted in IF lnsp Rept 50-373/80-15 HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/22 2pp
- --8007310533 Forwards supplemental response to NRC B00509 ltr reviolations noted in IE Insp Rept 50-373/B0-15 Corrective actions util will perform visual insp of both dryer & separator prior to final installation in reactor tessel PEOPLES.D.L. Commonwealth Edison Co. B0/07/07 5pp
- B Reportable occurrences, LFRs & related correspondence
- B007170214 Part 2: report re installed Tech-Sil. Inc matls containing 5% Gel which cannot be traced in original formulation Cause not stated Unused matl has been returned to vendor Noncompliance Rept 9 encl ACERRAL S TECH-SIL. Inc 80/06/20 App
- DOCKET 50-374 LASALLE COUNTY STATION. UNIT 2

 A Application/construction stage documents & correspondence
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SR33) fished for Combining Dynamic Loads for Mark 11 Plants "Rept acceptable subj to certain constraints MATTSON.A J Division of Safety Technology 80/04/23 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0674
 EISENBUT, D G Division of Licensing 80/06/26 2pp

7170479 Summary of 800613 meeting w/Mark II lead plant applicants dofinition of T-quencher lead spec following safety/ elisef valve actuation Viewgraphs encl U,T M Containment Systems Branch 80/06/27 4pp

ì

7230252 Summary of 800613 meeting w/Mark Il lead plant applicants re ethodology proposed by applicants to define T-quencher load per following safety relief valve actuation New methodology ill be applicable to all Mark II lead plants J.T.M. Generic Issues Branch 80/06/27 3pp

7230621 Summary of 800612 meeting w/Mark II owners group in ethesda. ND re lead plant closure & long-term program Mods tould be made to generic lead plant condensation scillation & chugging pool boundary loads Viewgraphs encl NDERSON, C J Generic Issues Branch 80/07/03 57pp

'150527 Forwards response to ARC 800421 request for info re masonry vil design Further review of masonry wall design is being unducted at LaBalla to complete response to IE Bulletin J-II Package of 231 oversize drawings encl EDPLES, D.C. Commonwealth Edison Co. 80/07/08 23pp

007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
* Sargent & Lundy, Inc. 80/07/08 231pp

'160606 Forwards "Condensation Oscillation (CO) Load Data for isable" & "Chugging Loads for Assessment of 4T CO Data " ints withheld (ref BOCFR2 790) & available in Central Files ly

lg LGEORGE-L O Commonwealth Edison Co 80/07/11 2pp

220518 Rosponds to 800522 & 0604 info requests Info re BHR jet mp holddown beem crarking will be submitted by 800815 & actor vessel underclad cracking info by 800901
OPLES, D. L. Gammonwealth Edison Co. 80/07/17 lp

25044B Forwards facility emergency procedures Table of contents LYDAK, R H Commonwealth Edison Co 80/07/10 1p

07250455 Emergency procedures for facility,including general abnormal procedures, general abnormal index & operating abnormal index = Commonwealth Edison Co 79/05/22 B2pp

290698 Forwards index for Partitity general procedures Index will polygeneral abnormal procedures & operating abnormal occidure index already forwarded W/o encl
_YOAK, R H Commonwealth Edison Co 80/07/23 ip

300033 Forwards request for addl info to complete review of FSAR JESCO.R L. Assistant Director for Licensing 80/07/23 3pp

scurity, medical, emergency & fire protection plans

)10347 Forwards safeguards contingency plan amend Plan withheld of 10CFR2 790) PLES.D L Co Commonwealth Edison Co 80/05/27 1p

ljudicatory correspondence

110243 Forwards Commission 800327 momorandum & order containing islams on UCS 780502 patition for reconsideration of 413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables ENHUT, D G Division of Licensing 80/06/25 89pp

ility Final Safety Analysis Report (FBAR) & amends

170267 Forwards 800630 affidavit to 800613 distribution of Amend 49 1th Edison Co 80/06/27 208

rrespondence

king in Core Spray f the Director 80/05/12

> In Contamination tor 80/05/28

- B0070100B6 Forwards IE Info Notice 80-23, "Loss of Suction to Easignate Feeduater Pumps" No written response required KEPPLER, J & Region 3, Chicago, Office of the Director '600,003/47
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 90/06/10
- 8007140314 Forwards IE Bulletin 80-14, "Degradation of BHR Stram Discharge Vol Capability " No written response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/08/12
- 8007280709 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 55(e) " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/06/13
- 9007100004 Forwards response to IE Bulletin 80-07. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES.D L Commonwealth Edison Co 80/06/16 3pp
- 8007230693 Forwards IE Insp Repts 50-373/80-26 & 50-374/80-16 on 800328-29 No moncompliance noted FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230700 IE Insp Repts 50-373/80-26 & 50-374/80-16 on 800528-29 Renoncompliance noted Major areas inspected mod in Unit 1 suppression pool, welding on do power panels & calibr of 4160-volt & 480-volt swatch gears
 NEISLER, J H , HILLIAMS, C C Region 3, Chicago, Orfice of the Director 80/06/18 4pp
- 8007020389 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response MEPPLER, J G Region 3. Chicago, Office of the Director 80/06/20
- 8007230246 Forwards IE Insp Repts 50-373/80-28 & 50-374/80-17 on 800610-11 No noncompliance noted FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8007230273 IE Insp Repts 50-373/80-28 & 50-374/80-17 on 800610-11 No noncompliance noted Major areas inspected preservice insp procedures, work activities & nondestructive examination DANIELSON,D H , WARD,K D Region 3, Chicago, Office of the Director 80/06/20 5pp
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnal " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/24
- 8007230289 Forwards IE Bulletin 80-14, "Potential Misapplication of Rospmount Inc Models 1191 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-14 also encl No written response required KEPPLER. J G Region J. Chicago. Office of the Director 80/06/2 80/06/27
- 8007250638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresdon Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES,D L. Commentwealth Edison Co. 80/07/09 7pp
- 8007210283 Ack receipt of 800606 itr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-373/80-20 & FIGNELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/07/14 ip
- --B007210292 Responds to NRC 800426 ltr re violations noted in 1E Insy Repts 50-37.7/80-20 & 90-374/80-13 (orrective actions design control program deficiencies are subj of request for ASME use Unges reconsideration of Item 3 infraction PEOPLES.D.L. Communwealth Edison Co. 80/06/06 6pp

8007230467 Submits supplemental response to IE Bulletin 80-09, "Hydramotor Artuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES D. L. Commonwealth Edison Co. 80/07/15 1p

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

G Inspection reports. It Duilotins & Larrespondence

8007180281 Forwards IC Circular BO-14, "Radioactive Contamination of Plant Demineralized Water 1915 & Resultant Internal Contamination of Personnel" No written response required ENSELMEN.R H Region 9, Ban Francisco, Office of the Director 80/06/24 1p

DOCKET 50-376 NURTH COAST NUC PLANT

o Adjudicatory correspondence

BOO7010143 Homorandum in rusponse to ASLAN BOO604 order re absence of authority to involuntarily dismiss CP application due to abandonment of const Issue must be remanded to ASLO to inquire into facts W/appearance notice & Certificate of Svc REISL J. Healing Branch 3 LCSBY, R.P. Antitrust Division 80/06/27 19pp

B007020604 Memorandum in response to ASLAN 800604 order Interiocutory review of ASL3 order dension 9 formos potition to dismiss application and warrandod unicos legal boundaries are not explored M/Gertificato of Svc AXELRAD.M Pourto Nico Electric Power Authority AXELRAD.M Lowenstein.Newman.Roico.Aselrad & Toll 80/06/27 21pp

8007070224 Order granting option for applicant to respond to NRC 800627 memorandum in CP proceeding by 800718 TIBEOP.C J Atomic Safety and Licensing Appeal Panel 80/06/30 is

8007160981 Metion speking option to respond to applicant by 800808, if applicant responds to NRC 800627 memorandum by 800718, re ASLAD 800670 order Certificate of Svc encl FERROG C Citizens for the Conservation of Natural Resources, Inc 80/07/09 ip

8007230535 Response to NRC NO0627 memorandum, in reply to ASLAB 800630 order Interluciting review of ASLAB ander re diamissal of CP application w/o hearing on hoolth eafety & environ is not warranted Certificate of Bvc nncl AXELRAD, M. Puerta Rice Electric Power Authority, AXELRAD, M. Lowenstein, Newman, Rois, Axelrad & Toli 80/07/18 ilpp

8007230791 Memorandum in response to ABLAB B00604 order re-validity of ASLB B00929 order donying petition to intervene Urges reversal of ASLB order & institution of hearings Cartificate of Buc enci FERNDB 0 Citizens for the Conservation of Natural Resources, Inc 80/07/10 lipp

POCKET 50-378 CAORSO NUCLEAR STATION

A Application/construction stage documents & correspondence

B007430175 Notification of B00800 meeting w/representatives from Mark II owners group in Chicago IL to discuss load Mark II plants chugging & C/O load specs ANDERSON, C Ownerts Issues Branch 180/07/20 2pp

DOCKET 50 382 WATTR-ORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8007020318 Confirms discussions w/NRC re resumption of work by subcontractor, NISCB Work may resume in stop work area of A & Batope (page instants) installation, pending completion of remaining NRC 800909 prerequisites GEYRIT, K V Region 4, Dallos, Office of the Director 80/06/ii ip

8007230001 Forwards statement of policy re requirements to be met for current CL applications as derived from NUREG-O640 & found in NUREG-O644
EISERHAIT, D G Division of Licensing 800/06/26 2pp

8007080179 Responds to NRC requests for additinfo Licenses will provide amend to FSAR on 80073;
ASHELL,D.L. Louisiana Power & Light Co. 80/07/03 ip

F Security, medical, emergency & fire protection plans

8007010341 Forwards evacuation time estimate to state & lecal officials involved in emergency pianning for area around facility per NRC 791226 request "Evacuation Time Estimate" encl ASHELLID L Louisiana Power & Light Co 80706/23 10pp

---8007010343 "Evacuation Time Estimate " + Louisiana Power & Light Co 80/03/31 46pp

8007100163 Forwards Amend 10 to FSAR Radiological response plan has been revised & will be forwarded upon final approval ASWELL.D L. Louissana Power & Light Co. 80/06/27 1p

--8007100166 Amend 10 to application for OL re upgraded emergency plans.
ASHELL: D L Louisiana Power & Light Co 80/06/27 Rap.

--BOD7100168 Amend 10 to FSAR re upgraded emergency plans a Louisiana Power & Light Co 80/06/30 177pp

8007220373 Forwards response to NRC 800609 comments & revised pages to safeguards contingency pian Response & revised pages withhold (ref 100FR2 790)
ASMELL-D L Louisiana Power & Light Co 80/07/15 ip

B007250399 Forwards Aswell to Grimes B00625 ltr
ASWELL:D L. Louisiana Power & Light Co B0/07/21 1p

Adjudicatory correspondence

8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables.
EISENHUT, D 0 Division of Licensing 80/06/25 89pp

K Utility Final Safety Analysis Report (FSAR) & amends

8007100163 Forwards Amend 10 to FSAR Radiological response plan has been revised & will be forwarded upon final approval. ASWELL,D L Louisiana Power & Light Co 80/06/27 1p

--8007i00i66 Amend 10 to application for CL re upgraded emergency plans.
ABMELL, D.L. Louisiana Power & Light Co. 80/06/27 2pp.

--8007100168 Amend 10 to FBAR re upgraded emergency plans * Louisiana Power & Light Co 80/06/30 177pp

8007160386 Certifies svc of Amend 10 to FSAR on 800710.upon partiet in proceeding Related correspondence + Louisiana Power & Light Co 80/07/10 ip

8007160616 Certifies svc of Amend 10 to FSAR on 800710 .
KAVANAUGH, F M Louisiana Power & Light Co 80/07/10 1p

G Inspection reports, IE Bulletins & correspondence

B007250323 Forwards IE Info Notice 80-i2, "Instrument Failure Causes Opening of PDBV & Block Vaive " No specific action or response necessary BEYFRIY,K V Region 4, Dallas, Office of the Director B0/03/31.

8007240510 Forwards IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 60/05/16, in

8007110061 Forwards IE Insp Rept 50-392/80-09 on 800421-25 & notices of violation & deviation SEIDLE.W C Region 4. Dellas. Reactor Construction & Engineering Support Branch 80/05/21 2pp

--B007i10065 Notice of violation from insp on B00421-25 & Region 4, Dallas, Office of the Director B0/05/20 3pp

--B007i10070 Notice of deviation from insp on 800421-25
* Region 4, Dallas, Office of the Director. 80/05/20 ip

- 8007020261 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required BEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/28
- B007140436 Forwards IE Insp Rept 50-382/80-07 on 800402-04,09-11 & 0502 & natice of violation SEIDLE.W.C Region 4. Dallas, Reactor Construction & Engineering Support Branch. B0/05/28 2pp
- ---8007140441 Notice of violation from insp on 800402-04.09-11 & 0502 * Region 4, Dallas, Office of the Director 80/05/28 ip
- 8007210346 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director' 80 80/05/28
- 8007010020 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Faedwater Pumps." No written response required SEYFRIT.K, V Region 4. Dallas. Office of the Director 80/05/29
- 8007100429 Responds to IE Bulletin 80-05 as applicable to tanks that hold radidactive liquid or gases All low pressure tanks containing radioactive liquids or gases either designed for full vacuum or to prevent vacuum in tanks
 ASMELL.D L Louisiana Power & Light Co 80/06/09 3pp
- 8007220113 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required SEYFRIT.K.V Region 4, Dallas, Office of the Director 80/06/10
- 3007160327 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required SEVERIT.K V Region 4. Dallas, Office of the Director BO/06/11
- MO729006B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)," No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/13
- OC7150417 Bubmits interim reply to IE Bulletin 80-09 re hydramotor actuator deficiencies ITT General Controls AH-90 & NH-90 warles hydramotor actuators will be used in safety-related sys Text rept to be completed during who of 800627 ABHELL, D. L. Louisiana Power & Light Co. 80/06/17 lp
- DO724D045 Forwards IE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/20
- X07280144 Forwards IE Inop Rept 50-382/80-10 on 800602-05 % notice of violation

 BEIDLE: W C Region 4, Dallas, Reactor Construction & Engineering

 Bupport Branch BO/06/20 Rpp
- BOO7280148 Notice of violation from insp on 800602-05 a Region 4. Dalles. Office of the Director BO/06. 60/06/18 2pp
- B007280153 IE Insp Rept 50-382/80-10 on B00602-05 Noncompliance noted failure to follow procedures for control of design mods to failure to control use of calibr tool within necessary CROSHAN, W. A. Region 4, Dallas, Office of the Director TAPIA, J. I. TOMLINSON, D. P. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/18 5pp

- 8007170680 Forwards IE Circuls: 80-14, "Radibactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required SEYFRIT, N.V. Region 4, Dallas, Office of the Dijector 80/06/24
- BOO7230369 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes." Written response required IE Circular BO-16 also encl No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/27
- 8007290433 Ack receipt of 800620 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/80-09 SEIDLE:H C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --B007270439 Responds to NRC 800521 ltr re violations noted in IE Insp Rept 50-382/80-09 Corrective actions NISCO housekeeping & insp procedures revised for clarity ASHELL.D.L. Louisiana Power & Light Co. B0/06/20 5pp
- 8007300391 Ack receipt of 800630 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-362/80-07 SEIDLE/N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/08 1p
- --B007300395 Responds to NRC B00528 itr re violations noted in IE Insp Rept 50-382/80-07 Corrective actions D stop repairs to be accomplished by granding weld defects to sound motal & visually inspecting results ASHELLID L Louisiana Power & Light Co B0/06/30 2pp
- S Reportable occurrences. LERs & related correspondence
- B007290448 Part 21 rept re-potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Comechanical shock arrestor Customers will be notified of affected items & recommended solution
 BECKBTED. H F Bergen-Patterson Pipe Support Corp 80/06/20 Spp
- B007010319 Requests that completion date for submitting final deficiency rept re procedural & performance deficiencies in ultrasonic testing of structural welds performed by Industrial Englineering Morks be extended until 800731 ASWELL,D L Louisiana Power & Light Co. 80/04/27 ip
- 8007020397 Forwards Final Significant Cunst Deficiency Rept 16 re Control element drive mechanism guide cones off-set ASHELLID L Louisiana Power & Light Co 80/06/27 jp
- --- B007020405 Final Significant Canst Deficiency Rept 16 re control element drive mechanism guide Loner & penetration assemblies interface Offset Londition exists which could produce interference on control assembly chaft * Louisiana Power & Light Co 80/06/27 2pp
- 8007080234 Forwards interim rept of Significant Const Deficiency 17 re base metal defects in main steam & feedwater containment penetration anchors ASWELL,D.L. Louisiana Power & Light Co. 80/07/03. 1p
- --R0070B0239 Interim rept of Significant Const Definiency 17 re base metal defects in main steam & fredwater containment penetration anchors Evaluation underway to establish repair techniques Final rept will be forwarded by 810301 CRNICH.J. MILNISER.R.J. HART.J. Louisiana Power & Light Co B0/07/02 3pp
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1 A Application/construction stage documents & coursepondence
- 8007030239 Notification of 800/07,meeting w/BWR licensing review group in Dethesda, MD to discuss concensus position on reactor svr bidg open issue WILSON, J N Licensing Branch i 80/06/18 7pp
- 8007010297 Summary of EIRO613 meeting w/utils.KMC, Inc. GE. Bechtel. S&W & Sargent & Lundy in Dethesda, MD re consensus positions on reactor sve bldg & isolation cooling sys bldg open issues from La Salle docket Shatus repts encl
 WILSON, J N Assistant Director for Licensing 80/06/19 46pp

- BOO7210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Buppls 1-3. "Tychnical Basis for Use of Square-Root-of-Sum-of-Equares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj to certain constraints MATTBON,R J Division of Bafety Technology 80/06/25 3pp
- BOO7090391 Notification of B00714-17 meeting w/util,GE & Bechtol in Bethesda-MD to review open items for facility FSAR generated by NRC Mechanical Engineering Branch b BTARKER M Licensing Branch 1 G0/06/26 5pp
- BOO7230001 Forwards statement of policy re requirements to be mot for current OL applications as derayed from NUREG-0660 & found in NUREG-0694
 EISEMNIT D 0 Division of Licensing BO/06/26 2pp
- HOD7090378 Forwards request for add1 info re reactor sys YBUNGBLODD, B J Licensing Branch i 60/06/27 2pp
- GOO7170339 Notification of rescheduling of 800702 meeting w/BWR licensing review group in Bethesda, MD to discuss consensus positions on Reactor Sys Branch open issues Meeting reschaduled for 800709 HILBON, J.N. Assistant Director for Licensing 80/07/03 1p
- -8007170347 Notification of 800722 meeting w/BWR licensing review group in Bethesda, MD to discuss IMI issues required for OL WILSON, J N Assistant Director for Licensing 80/07/03 ip
- BOO7230621 Bummary of B00612 meeting w/Mark II owners group in Bathesda.MD re lead plant closure & long-term program Mods should be made to generic lead plant cundensation oscillation & chugging peol boundary inads Viewgraphs encl ANDERBON.C J Generic Issues Branch B0/07/03 57pp
- GPO7230133 Notification of 800725 meeting w/BWR Licensing Review Group in BothesdarMD to discuss concensus positions of BWR Licensing Review Group on ICSD open issues WILSON.J N Licensing Branch i 80/07/14 10pp
- BOO7250529 Comments on B00714-16 meeting w/NRC in Bethesds, MD to resolve issues & answer questions on FSAR Sections 3 6-10

 Deen issues were resolved & meeting was productive Licensing managers should have input in sulerting meeting jocation

 CURTIE: N W Pennsylvania Power & Light Co 80/07/18 2pp
- BOD7290019 Advisos that withholding affidavit per 100FR2 790 must be submitted to support 800609 request re Revision 2 to design assessment rept Affidavit must be transmitted within 30 days
 YOUNGBLOOD, B. J. Licensing Branch 1 80/07/21
- BOO7250175 Notification of BOO805 meeting w/representatives from Mark II dumers group in Chicago IL to discuss load Mark II plants Chugging k C/O load specs
 ANDEREON C Generic leaves Branch 90/07/23 2pp
- BOO7240006 Notification of 800821 meeting w/util in Bethesda.MD to discuss responses to Reactor Sys Branch questions BTARK.R.M Licensing Branch 1 80/07/23 3pp
- F. Security, medical, emergency & fire protection plans
- BOO7230325 Summary of 800616 meeting w/util in Bethesda.MD to receive applicant questions re technical support ctr & emergency operations facility Applicant wishes to clorify interpretation of certain NRC requirements

 BTARK.R M Licensing Branch 1 80/07/10 4pp
- BOD7220441 Forwards "Study Rept for Susquehanna Steam Electric Station Mass Notification & Evacuation." Part 1. prepared by AM Vorbees & Associates Rept in response to NRC 800702 request CURTIS.N W Pannayivania Power & Light Co 80/07/17 ip
- --B-007220448 "Bludy Rept for Susquehanna Stram Electric Station Mass Notification & Evacuation," Part 1 * PRC Planning & Economics, Alan M Voorhees & Associates Div B0/07/17 57pp

- O Adjudicatory correspondence
- 8007010276 Responds to 800607 ltr Transcripts of NRC technical meetings w/applicants are not available due to unofficial aspect Summaries of meetings available in LFDRs Future ltrs on behalf of intervenors should be sent to NRC counsel CUTCHIN.J M Hearing Branch 3 80/06/16 ip
- B007010273 Forwards Commission "Statement of Interim policy on Nuclear Power Plant Accident Considerations under NEPA of 1969." gublished in B00613 FR Commission decision.CLI-80-08 & ASLAB decision.ALAB-387 encl Wo attachments CUTCHIN.J M Hearing Branch 3 80/06/17 2pp
- 8007310243 Forwards Commission 800927 memorandum % order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum % order UCS 771104 petition sought action re file protection for electrical cables EISENHUT.0 0 Division of Licensing 80/06/25 89pp
- 8007190709 Advises that FES is scheduled to be issued in Dec 1980. safety evaluation in Feb 1981 & safety evaluation suppl in May 1981 Furcher significant changes will be provided per NRC 790129-31 prehearing commitmentif necessary CUTCHIN.J M Hearing Branch 3 80/07/10 Rep
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007080240 Forwards marked-up copy of PSAR, Subsection 3 92 & Table 3 9-33, corrected to agree w/preoperational & startup tests program Changes will be discussed at draft SER meeting during wt of 800714 CURTIS, N.W. Pennsylvenia Power & Light Co. 80/07/03 11pp
- 8007240131 Forwards Amend 22 to application for OL consisting of Revision 16 to FEAR CURTIS.N W Pennsylvania Power & Light Co 80/07/11 lp
- --8007240142 Amend 27 to application for OL consisting of Revision 16 to CURTIS.N W Pennsylvania Power & Light Co E0/07/14 19
- --8007240143 Revision 16 to FSAR + Pennsylvania Power & Light Co 80/07/14 &00pp
- O Inspection reports, 15 Bulletins & correspondence
- 8007140466 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers "No written responso required ORIER.B H Region 1. Philadelphia. Office of the Director BO/05/12 1p
- 8007170637 Forwards IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No noncompliance noted CARLSON.R T Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/05/28 2pp
- --8007170645 IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No DOTATIONS IE INSPIRENTS 30-35780-07 & 30-35780-03 on course moncompliance noted Major areas inspected site audit program & outstanding items DURR, J.P. Region I. Philadelphia, Office of the Director TRIPP, L.E. Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/23 3pp
- 8007010262 Forwards IE Info Natice 80-23, 'Loss of Suction to Emergency Paedwater Pumps " No written response required GRIER.II h Region 1, Philadelphia, Office of the Director 80/05/29 ip
- 8007170249 Forwards IE Insp Repts 50-387/80-11 & 50-388/80-07 on 800515-16 No noncompliance noted CARLEON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --B007170257 IE finsp Repts 50-387/80-11 & 50-388/80-07 on 800513-16 No noncompliance noted Major areas inspected site activities & review of NRC insp status

 DURR.J P Region i. Philadelphia. Office of the Director MCGAUSHY,R W Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/02 2pp
- R007210606 Forwards IE Info Notice R0-26, 'Evaluation of Contractor OA Programs " No written response required CRIER.B H Region J. Philadelphia. Office of the Director 80/06/10 Jp

- 8007140287 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/06/12 1p
- 8007280612 Forwards IE Info Notice 80-28 "Prompt Reporting of Info in Accordance WildCrR50 59(e)" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/13 1p
- 8007020513 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required CRIER B H Region 1, Philadelphia, Office of the Director 80/06/20 in
- 8007160733 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER B H Region I. Philadelphia. Office of the Director 80/06/24 1p
- 8007210271 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required ORIGE, B H Region 1 Philadelphia, Office of the Director 80/06/25 Ip
- 8007210334 Act receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 CARLSON.R T Region I, Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 lp
- --8007210341 Responds to NRC 800514 ltr re violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 Corrective actions all space heaters in motor control ctrs identified energized & checked periodically SABOL. A R Pennsylvania Power & Light Co 80/06/13 3pp
- --8007210345 Forwards IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & 0211-29 & notice of violation CARLSON,R Y Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8007210349 Natice of violation from insp on B00121-0201 & 0211-29 * Region 1. Philadelphia. Office of the Director 80/04/09 2pp
- ---B007210355 IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & C211-27 Moncompliance noted failure to follow approved procedures during preventive maint & to establish proper test program for performance of hydrostatic testing GALLOR H. RHOADS.C C Region 1. Philadelphia. Office of the Director MCCAUGHY.R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B0/04/07 18pp
- BOO7230166 Forwards 1E Dulletin 80-16, "Potential Misapplication of Rosemount Inc Hodels 1151 & 1152 Pressure Transmitters WEither A or D Output Codes" Written response required IE Circular 80-16 also encl No written response required CRIER.B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- BOO7180339 Advises that ASME Code Cases N-234 & N-235 have been approved for use in reactor pressure vessel preservice insperogram YOUNGELOOD, B J Licensing Branch 1 80/06/28 2pp
- BOO7180440 Requests add1 info to aid in facility licensing review re IE Bulletin 80-07 requirements & to provide commitment to adopt whatever long-term solution is approved Any short-term actions & supporting justification should be described YOUNGELOOD, B.J. Licensing Branch 1 80/06/30 2pp
- B Reportable occurrences, LERs & related correspondence
- 8007170671 Ack receipt of 800513 interim deficiency rept re pilot solenoid valve classification Resolution of deficiency panding receipt of final rept CARLEDN.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8007170610 Ack receipt of 800329 interim deficiency rept re pips supports wilded to containment liner plate Rept will be reviewed & evaluated CARLSON,R T Region 1, Philadelphia, Office of the Director 80/06/12 ip

- B007210049 Ack receipt of 800613 interim deficiency rept re unauthorized weld on reactor pressure vessel CARLEUN,R T Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 80706/26 ip
- 6007080213 Supplemental deficiency rept re Pacific theck valves Problems w/check valve operation in Unit 1 core spray pump discharge vertical pipe run will necessitate rework of bonnet stops Final rept will be provided by Sept 1980 CURTIG.N.W Pennsylvania Power & Light Co 60/07/03, 2pp
- 8007i40i97 Interim deficienty rept re Anchor-Darling Valve yotes. Cracks discovered in four radii at yoke mounting flange/yoke vertical section interface on Anchor-Darling valves in residual heat removal sys Final rept will be forwarded CURTIG:N W Pennsylvania Power & Light Co 80/07/07 Spp
- 8007140340 Interim deficiency rept re Anchor-Darling valve yokes. Cracks discovered in four radii at yoke mounting flange/yoke vertical section interface on Anchor-Darling valvee in residual beat removal sys Final rept will be forwarded, CURYIS,N W Pennsylvania Power & Light Co 80/07/07 3pp
- 8007140340 Interim deficiency rept per 10CFR50 55(e) & Part 21 recracks in four radii at yoke mounting flange/yoke vertical section interface on Anchor-Darling valves in RHR sys Final rept date will be provided after further review CURTIG,N W Pennsylvania Power & Light Co 80/07/07 3pp.
- 8007140170 Forwards final deficiency rapt re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors CURTIS N W Pennsylvania Power & Light Co. 80/07/08 2pp
- --B007140179 Final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors, Cause unidentified Visual insp & pull test initiated on Unit 1. • Pennsylvania Power & Light Co 80/07/08 2pp
- 8007180434 Interim rept.per lOCFR50 55(e) & Part 21, re premature time out & drifting set points for pneumatic time delay relays ossociated w/Apestat 7000 & GE CR 2820 relays Bechtel & util analyzing safety impact CURTIS.N W Pennsylvania Power & Light Co 60/07/11 2pp
- 8007290865 Ack receipt of 800616 final deficiency rept re Limitorque abtor operated valve stem nut staking CARLSONR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 ip
- B0071B02B2 Advises that 800122 ltr describing potential RO re copes structural floor beams determined not reportable under 10CFR90 55(e) CURTIB,N W Pennsylvania Power & Light Co 80/07/14. 2ps.
- S007180364 Potential deficiency rept re coped structural floor beams. Based on results of field insp & finite element analysis, conditions noted are nonconforming & are therefore not reportable per 10CFR55(e) Bechtel procedures revised CURTIS, N M Pennsylvania Power & Light Co 60/07/14 2pp.
- 8007230487 Interim deficiency rept re status of Anchor Darling valve yokes AE has advised final rept on cracked yokes on Anchor Darling valves will be available in Aug 1980 Final rept will be forwarded during Sept 1980
 CURTIS.N W Pennsylvania Power & Light Co 80/07/21 ip.
- 8007280215 Finel Deficiency MCAR 1-58, per 10CFR3D 35(e) & Part 21, rw QE equipment lacking proper slope Caused by Unclass design drawings & const failures All affected drawings will be revised & Unit 1 as-builts completed by 801230, CURTIS,N W Pennsylvania Power & Light Co. 80/07/21, 4pp
- S007280650 Final deficiency rapt re improper sloping of GE piping & tubing Bechtel Nonconformance Rept 5807 lists 41 small pipe installations to GE equipment that do not meet min glope requirement Revised acceptance criteria developed * Pennsylvania Power & Light Co 80/07/21 4pp.
- B007290455 Interim deficiency rept re pips support design drawings. Final rept will be provided in Apr 1781 CURTIS, N W Ponnsylvania Power & Light Co 80/07/22. 2pp
- 8007270623 Supplements & updates projected completion data of corrections re pipe support design drawings Bachtel Power Corp will provide final rept on defective condition by Mar 1981 Util final rept will be provided by Apr 1981 CURTIS, N W Pennsylvania Power & Light Co. 80/07/22, 2pp

- 779264 Interim deficiency rept re improper safety classification or splenoid valves Final rept will be provided in Nov 1980 (LRTIB,N W Pennsylvania Power & Light Co 80/07/23 ip
- MET 50-388 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2 APPlication/construction stage documents & correspondence
- T210176 Forwards NRC evaluation of GE rept. NEDE-24010-P & Suppls 3: "Technical Basis for Use of Square-Root-of-Sum-of-Quares (SRSB) Method for Combining Dynamic Loads for Mark I Plants "Rept acceptable subj. to certain constraints FTECN: R J. Division of Safety Technology 80/06/25 3pp
- '7090391 Notification of 800714-17 meeting w/vtil.GE & Bochtel in * thesda,MD to review open items for facility FSAR * Enerated by NRC Mechanical Engineering Branch TARK,R H Licensing Branch 1 80/06/26 3pp
- 7230001 Forwards statement of policy re requirements to be met for UFFent DL applications, as derived from NUREG-0660 k found PAREG-0694
 IBENAULD 0 Division of Licensing 80/06/26 2pp
- 7090378 Forwards request for addition or reactor sys
- 7230521 Bummary of 800612 meeting w/Mark II owners group in mthesda, MD re lead plant clasure & long-term program Mods hould be made to generic lead plant condensation ≈ £11245 on & chugging pool boundary loads Viewgraphs encl NIMERBON. € J Generic Issues Branch 80/07/03 57pp
- PRESS29 Comments on 800714-16 meeting w/NRC in Bethesds, MD to Pachys issues & answer questions on FSAR Sections 3 6-10 Pach issues were resolved & meeting was productive Licensing amagers should have input in selecting meeting location PRESS, N W Pennsylvania Power & Light Co 80/07/18 2pp.
- 7290019 Advises that withholding affidavit per 100fR2 790 must be ubmitted to support 800609 request re Revision 2 to design a seasont rept Affidavit must be transmitted within 30 Bus. DUNGBLOOD, 8 J Licensing Branch 1 80/07/21 2pp
- 7250175 Notification of B00805 meeting w/representatives from Mark E owners group in Chicago IL to discuss lead Hark II plants bugging & C/D load specs
 UDERSON.C Generic Issues Branch B0/07/23 2pp
- 7270005 Notification of 800821 meeting w/util in Bethesda,MD to Lacuss responses to Reactor Sys Branch questions FARK,R M Licensing Branch 1 80/07/23 3pp
- Becurity, medical, emergency & fire protection plans
- 7230325 Summary of B00616 meeting w/util in Bethesda, MD to receive >plicant questions re technical support ctr & emergency >erations facility Applicant wishes to clarify tterpretation of certain NRC requirements FARK, R M Licensing Branch 1 B0/07/10 4pp
- 7220441 Forwards "Btudy Rept for Busquehanna Steam Electric Station as & Notification & Evacuation." Part 1. prepared by AM 3 These & Associates Rept in response to NRC 800702 request. PRT18.N N Pennsylvania Power & Light Co 80/07/17 ip
- >07220448 "Study Rept for Susquehanna Steam Electric Station Mass Ptotification & Evacuation," Part i # PRC Planning & Economics, Alan M Voorhees & Associates Div #0/07/17. 59pp
- Ad Indicatory correspondence
- rO10276 Responds to 800607 ltr Transcripts of NRC technical meetings rapplicants are not available due to unofficial aspect.
 sammarkes of meetings available in LPDRs Future ltrs on shalf of intervenors should be sent to NRC counsel FTCHIN.J M Hearing Branch 3 80/06/16 1p

- 8007010273 Forwards Commission "Statement of Interim policy on Nuclear Power Plant Accident Considerations under NEPA of 1969," published in 800613 FR Commission decision.CLI-80-08 & ASLAB decision, ALAS-387 encl 4/o attachments CUTCHIN, J M Hearing Granch 3 80/06/17 2pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 87pp
- 8007150709 Advises that FES is scheduled to be issued in Dec 1980, mafety evaluation in Feb 1981 & safety evaluation suppl in May 1981 Further significant changes will be provided per NRC 790129-31 prehearing commitment if necessary CUTCHIN.J M Hearing Branch 3 80/07/10 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B007080240 Forwards marked-up copy of FSAR.Subsection 3 92 & Table 3 9-33.corrected to agree w/preoperational & startup tests program Changes will be discussed at draft SER meeting during wk of 800714 CURTIS.N W Pennsylvania Power & Light Co 80/07/03 lipp
- 8007240131 Forwards Amend 22 to application for DL consisting of Revision 16 to FSAR CURTIS:N N Pennsylvania Power & Light Co 60/07/11 ip
- --8007240142 Amend 22 to application for OL consisting of Revision 14 to CURTIS:N W Pennsylvania Power & Light Co 80/07/14 1p
- --8007240143 Revision 16 to FBAR

 * Pennsylvania Power & Light Co 80/07/14 600pp
- P Operating license stage documents & correspondence
- 8007100273 Submits add1 info re implementation of short-term Lessons Learned requirements Status of remaining Category A items, mid-up status of design & installation of Category B mods & schedule for implementation encl Forwards drawings BYLVIA.8 R Virginia Electric & Power Co 80/07/07 180pp
- G Inspectson reports. IE Gulletans & correspondence
- 8007140466 Forwards IE Bulletin 80-13. "Cracking in Core Spray Bpargers " No written response required GRIERIBH Region 1. Philadelphia Office of the Director BO/05/12 19
- 8007170637 Forwards IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No noncompliance noted CARLSON,R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/28 2pp
- ---8007170645 IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No noncompliance noted Major areas inspected site audit program & outstanding items
 DURR, J P Region 1, Philadelphia, Office of the Director
 TRIPPL E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/23 3pp
- 8007010262 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER.D H Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 8007170249 Forwards IE Josp Repts 50-387/80-11 & 50-388/80-07 on 800513-16 No noncompliance noted
 CARLBON,R T Region 1. Philadelphia, Reactor Construction &
 Engineering Support Branch 80/06/03 2pp
- --8007170257 |E Insp Repts 50-387/80-11 & 50-389/80-07 on 800513-14 No noncompliance noted Major areas inspected site activities & review of NRC insp status

 DURR, J P Region 1, Philadelphia, Effice of the Director

 MCGAUGHY, R W Region 1, Philadelphia, Heactor Construction & Engineering Support Branch 60/08/02 2pp
- 8007210406 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/06/10 ip

- 8007140287 Forcards IE Bulletin 80-14 'Degradation of BWR Scram Discharge Vol Cagability "No written response required GRIER. B M. Region 1, Philadelphia. Office of the Director BO/06/12 Ip
- 8007280612 Forwards IE Info Notice 80-28, 'Prompt Reporting of Info in Accordance W/10CFR50 55(e) 'No written response required GRIER.OH Region 1. Philadelphia, Office of the Director 80/06/13 ip
- 8007020513 Forwards IE Circular 80-15. "Loss of Reactor Goolant Pump Cooling 'Abdural Circulation Cooldown " No written response required GRIER: 0 H Region 1. Philadelphia, Office of the Director 80/06/20 1p
- 8007160733 Forwards 1E Circular 80-14, "Radioactive Contamination of Flant Demineralized Water Sys & Resultant Internal Contimination of Personnel "No written response required GRIER.B H Region 1 Philadelphia. Office of the Director 80706242 19
- 8007210271 Forwards IE Info Notice 80-24, "Low Level Radwaste Buriel Criteria" No written response required CRIER-8 H Region I, Philadelphia, Office of the Director 80/06/25 ip
- 8007210334 Ack receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 CARLBON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 ip
- ~-8007210341 Responds to NRC 800514 ltr re violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 Corrective actions all space heaters in motor control ctrs identified, enorgized & checked periodically SABOLIA R Pennsylvania fower & Light Co 80/06/13 3pp
- --8007210345 Forwards IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & 0211-29 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/14 2pp
- --8007210349 Notice of violation from insp on 800121-0201 & 0211-29
 * Region 1, Philadelphia, Office of the Director 80/04/09 2pp
- --B007210355 IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & 0211-29 Noncompliance noted failure to follow approved procedures during preventive maint & to establish proper test program for performance of hydrostatic testing OALLO,R H, RNDADS,G Q Region I, Philadelphia, Office of the Director MCGAUCHY,R W Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/04/09 18pp
- 8007230166 Forwards IE Bulletin BO-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular BO-16 also and No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/27 2pp
- 8007180939 Advises that ASME Code Cases N-234 & N-235 have been approved for use in reactor pressure vessel preservice insp program YOUNGBLOOD, B J Licensing Branch 1 80/06/28 2pp
- B007180440 Requests add1 info to aid in facility licensing review re IE Bulletin 80-07 requirement4 & to provide commitment to adopt whatever long-term solution is approved Any short-term actions & supporting justification should be described YOUNOBLOOD, B J Licensing Branch J 80/06/30 2pp
- B0072500BB Discusses actson taken re allegations made by former welder trainee R Milson Wilson has refused to provide specific info, therefore no further action is planned Ltr constitutes final followup to NRC B00123 ltr

 STELLD, V Office of Inspection & Enforcement, Office of the Director 80/07/10 2pp

- S Reportable occurrences, LERs & related correspondence
- 8007170671 Ack receipt of 800513 interim deficiency rept re pilot solenoid valve classification Resolution of deficiency pending receipt of final rept CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/11 ip
- 8007170610 Ack receipt of 800529 interim deficiency rept re pipe supports welded to containment liner plate Rept will be reviewed & ovaluated CARLEDN, T Region 1. Philadelphia. Office of the Director 80/06/12 ip
- 8007080213 Supplemental deficiency rept re Pacific check valves.
 Problems w/check valve operation in Unit 1 core spray pump
 discharge vertical pipe run will necessitate rework of
 bonnet stops Final rept will be provided by Sept 1980
 CURTIS:N W Pennsylvania Pawer & Light Co 80/07/03 2pp
- B007140170 Forwards final deficiency rept to insulation damage & deficient pan crimps in power goneration control complex/advanced control room panel connectors

 CURTIS,N W Pennsylvania Power & Light Co B0/07/08 Upp
- --8007140179 Final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors Cause unidentified Visual insp & pull test initiated on Unit 1 * Pennsylvania Power & Light Co 80/07/08 2pp
- 8007180434 Interim rept.per iOCFR50, 35(c) & Part 21, re premature time out & drifting set points for pneumatic time delay relays associated w/Agastat 7000 & OE CR 2820 relays Bechtel & util analyzing safety impact CURTIS:N W Pennsylvania Power & Light Co 80/07/11 2pp
- 8007270865 Ack receipt of 800616 final deficiency rept re Limitorque motor operated valve stem nut staking CARLSONR T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 1p
- 8007180364 Potential deficiency rept re coped structural floor beams Based on results of field insp & finite element analysis, conditions noted are nonconforming & are thorsefore not reportable per 10CFR5569 Bechtel procedures revised CURTIS.N W Pennsylvania Power & Light Co. 80/07/14 2pp
- B007290487 Interim deficiency rept re status of Anchor Darling valve unkes AE has advised final rept on cracked yokes on Anchor Darling valves will be available in Aug 1980 Final rept will be forwarded during Sept 1980 CURTIS, N W Pennsylvania Power & Light Co 80/07/21 1p
- B007280215 Final Deficiency MCAR 1-58, per 10CFR90 58(e) & Part 21, re QE equipment lacking proper slope Caused by unclear design drawings & const failures All affected drawings will be revised & Unit 1 as-builts completed by 801230 CURTIS, N W Pennsylvania Power & Light Co 80/07/21 Spp
- BOO7280450 Final deficiency rept re improper sloping of GE piping & tubing Beckbel Nonconformance Rept 5807 lists 41 small gipe installations to GE equipment that do not meet min slope requirement Revised acceptance criteria developed s Pennsylvania Power & Light Co 80/07/21 App
- 8007290455 Interim deficiency rept re pipe support design drawings. Final rept will be provided in Apr 1981 CURTIE,N W Pennsylvania Power & Light Co 80/07/22 App
- 9007290623 Supplements & updates projected completion date of corrections re pipe support design drawings Bachtel Power Corp will provide final rept on defective condition by Mari981 Util final rept will be provided by Apr 1981 CURTIS.N W Pennsylvania Power & Light Co 80/07/22 2pp
- 8007270264 Interim deficiency rept re improper safety classification for solenoid valves Final rept will be provided in Nov 1980. CURTIB, N W Pennsylvania Power & Light Co 80/07/23 ip
- 8007290716 Supplemental deficiency rept updating status of improper solenoid valve safety classification Bechtel Power Corp MCAR i-35 final rept will be available Oct 1980 & util final deficiency rept by Nov 1980 CURTIS, N W Pennsylvania Power & Light Co 80/07/23 1p

ı

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- BQ07030i75 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.R L Assistant Director for Licensing 80/06/i2 2pp
- UQ0722.3' '1 Forwards statement of policy re requirements to be met for curren. OL applications, as derived from NUREG-0660 & found in NUREG-0696 EISENHUT.D G Division of Licensing 80/06/26 2pp
- ₹ Security, medical, emergency & fire protection plans
- . B007010379 Forwards BN: fire protection review re upgrading existing fire pumps, cable spreading room fire barrier, smoke detectors, reactor coolant pump oil collection sys & automatic sprinkler sys for facility HALL.R E Brookhaven National Laboratory 80/06/24 6pp
 - B007280647 Advises that evacuation time estimates were submitted in 800717 ltr per 800702 request UHRIG.R E Florida Power & Light Cu 80/07/22 ip
 - O Adjudicatory correspondence
 - BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENMUT.D Q Division of Licensing 80706/25 87pp
 - H General correspondence
 - B007110306 Responds to B00512 ltr re encl L Starr ltr concerning plant problems Nuclear plant safety design approach involves use of multiple physical barriers to prevent release of radioactivity to environ DIRCKS, M J Office of the Executive Director for Operations 80/06/30 3pe
 - --E007110314 Requests response to L Starr 1tr concerning plant problems CHILES:L J Senate 80/05/12 1p
- BOO7240444 Responds to BOO521 ltr re S Corbin inquiry about plant safety aspects Safety design approach involves use of MUItiple physical barriers to prevent release of radioactivity to environ DIRCKS-W J Office of the Executive Director for Operations BO/07/15 3pp
- ---8007240468 Requests response to encl S Corbin inquiry about plant safety aspects STONE: R Senate 80/05/21 2pp

M Antitrust correspondence

- BOO7090051 Comments on Orlando Utils notice of withdrawal re-order madifying CPs Other intervening cities must be given similar nuclear access opportunities Urges establishment of procedures allowing author to be heard W/Certificate of Svc JABLON, R A Florida Cities JABLON, R A Spiegel & McDiarmid BO/07/07 4pp
- BO07150719 Response stating no objection to Orlando Utils Commission 800620 withdrawal of intervention FL Cities 800707 comments a equal treatment will be addressed in Unit 2 antitrust proceeding Certificate Syc encl DEMEY.L S Antitrust Division 80/07/11 4pp
- 8007230798 Advises of extension until 800916 for FL Cities & util to respond to interrogatories NRC & DDJ have no objection to extension ASLD approval requested Certificate of Svc encl ROTH.A J Florida Cities BOUKNIGHT.J A Florida Power & Light Co 80/07/18 3pp
- B007270004 Forwards notice of receipt of addl antitrust info which is to be published in FR YOUNGBLOOD, B J Licensing Branch 1 80/07/21 ip
- B007270753 Order granting extension until B00716 for FL Cities & util to respond to interrogatories
 SMITH: I W Atomic Safety and Licensing Board Panel 80/07/23 ip

- 8007250407 Discusses util % FL cities 800718 ltr to ASLB re completion of document production NRC will not agree on completion until documents are obtained & reviewed NRC is willing to postpose util answers to interrogatorios indefinitely DEMEY, L 8 Autitrust Division 80/07/21 2pp
- G Inspection reports. If Bulletins & Lairespondence
- 8007240206 Forwards IE Info Notice 80-20. "Loss of Decay Hoot Removal Capability at Davis-Besse Unit (White in Refering Mode " No response required D'REILLY.J P Region 2 Atlanta, Office of the Director 80/05/08 20n
- B007070165 Forwards IE Insp Rept 50-389/B0-06 on 800430-0502 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/17 2pg
- ---B007070169 IE insp Rept 50-189/80-06 on B00430-0302 No noncompliance nated Hajor areas inspected electrical & instrumentation GA implementing procedures review for Class IE components & sys & for Class IE cables & terminations

 MALTERS, D K Region 2. Atlanta, Office of the Director CONLOW, T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/19 Spp
- 8007020231 Forwards IE info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required O'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/05/20
- 8007210458 Forwards IE Circular 80-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies" No written response required D'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007010206 Forwards IR Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007220062 Forwards IG Info Notice 80-26 "Evaluation of Contractor GA Programs" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/10 2pp
- 8007160265 Forwards IE Info Nutice 80-27, Degradation of Reactor Coolant Pump Stude "No specific action or response required O'REILLY.JP Region 2, Atlanta, Office of the Director 80/06/II
- 8007250372 Forwards 16 Info Nutice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020454 Forwards IC Circular BO-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY.JP Region 2. Atlanta, Dffice of the Director 80/06/20 ip
- 8007170109 Forwards IC Circular 80-14, "Radinactive Cuntamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/24 in
- 8007230249 Forwards IE Bulletin 80-16. "Potential Hisapplication of Rosemount inc Models 119: & 1192 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No writton response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/27
- BOO7210060 Provides interim response to 1E Bulletin 80-0B, "Examination of Containment Liner Penetration Helds " Facility utilizes flued head design genetration connections Records under review Tables encl
 UHRIG.R E Florida Power & Light Co 80/07/07 i3pp
- 8007310212 Ack receipt of 800707 ltr informing NRC of steps taken to correct violation noted in IE investigation Rept 50~389/80-05 MURPHY,C C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 ip

- BOO7310220 Responds to NRC 800609 ltr re violation noted in IE Investigation Rept 50-389/BO-05 Corrective actions back of each individual ID badge will be stamped u/certification held UHRIG.R E Florida Power & Light Co BO/06/27 2pp
- 8007310223 Forwards 1E Investigation Rept 50-389/80-05 on 800408 & 21-24 & notice of violation O'REILLY J P Region 2. Atlanta, Office of the Director 80/06/09 Zpp
- 8007310228 Notice of violation from investigation on 800408 & 21-24 * Region 2. Atlanta. Office of the Director 80/05/09 ip
- 8007310235 IE Investigation Rept 50~389/80~05 on 800408 & 21~24
 Noncompliance noted failure to follow procedure requirement
 to use certified mondestructive examination personnel
 LONG.F W. MCGUIRE.D R. Region 2. Atlanta, Office of the Director
 VANDDORN.P K. Region 2. Atlanta, Reactor Construction &
 Engineering Support Branch. 80/06/09 App
- Reportable occurrences, LERs & related correspondence
- 07160599 Advises that final deficiency rept re diesel generator control panels will be delayed until 800731 JHRIG.R E Florida Power & Light Co 80/06/17 jp
- *KEY 50-390 HATTS BAR NUCLEAR PLANT, UNIT 1

 Application/construction stage documents & correspondence
- '701014B Requests add! info within two wks.needed to determine observed for underclad cracking in reactor vessel noisles librasonic exams did not indicate explicit correlation etween observed cracking & pre/post-clad heat treatment CHMENCER.A Licensing Branch 2 80/06/18 2pp
- 7020707 Forwards request for info re confirmatory piping analysis esponse should be submitted to ANL by B00703 Includes info siping layout & isometric drawings sufficient to model ys & support drawings wispport & hanger spring rates CHWENCER.A Licensing Branch 2 80/06/23 3pp
- 7010386 Advises that util has received no response to 790928 request or extensions until Nar & Dec 1981 for Hatts Bar I & 2 Addl ifety requirements may result in completion by Jan 1981 for Sequoyah 2.May 1981 for Hatts 1 & Feb 1982 for Hatts 2 ILLS.L M Tennessee Valley Authority 80/06/26 ip
- /230001 Forwards statement of policy re requirements to be met for JPFent DL applications, as derived from NVREG-0660 & found NVREG-0669 SENHUT. D © Division of Licensing 80/06/26 2pp
- '080253 Forwards add1 request re ultrasonic exam of welds LLS.L M Tennessee Valley Authority 80/07/01 3pp
- 3005B4 Notification of contract execution. Mod 2 to "Evaluation of ciling Stress Criteria for Steel Containment at Hatts r." Contractor Intl Structural Engineers
 AGESSER. C M Purchasing Section FIN 8-65B1 80/07/02 1p
- O7300587 Mod 2. changing completion date, to "Evaluation of Buckling Stress Criteria for Steel Containment at Watts Bar "
 International Structural Engineers, Inc PERLHAN, J
 Administrative Contracts Branch FIN B-6581 B0/07/02 ip
- djudicatory correspondence
- 310243 Forwards Commission 800527 memorandum & order containing Islons on UCB 780502 petition for reconsideration of 3413 memorandum & order UCB 771104 petition sought action fire protection for electrical cables SENHUT. D 0 Division of Litensing 80/06/25 89pp

- O Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit t While in Refueling Mode "No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007020192 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28, In
- 8007210488 Forwards IE Circular 80-13. "Orid Strap Damage in Hestinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/05/29 to
- B007220029 Forwards IE Info Notice 80~26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/10 Jpp
- 8007i60287 Forwards IE 1nfo Notice 80-27, "Degradation of Reactor Coplant Pump Btuds " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11 ip
- 8007250384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/13
- 8007270400 Forwards 1E Insp Rept 50-390/80-17 on 800527 & 30 No noncompliance noted STDHR, J P Region 2. Atlanta. Fuel Facility & Materials Bafety Branch 80/06/17 2pp
- ~~8007290404 IE Insp Rept 50-390/80-17 on 800529 & 30

 No noncompliance noted Major areas inspected environ monitoring programs & environ protection program JENKINS.0 R Region 2. Atlanta. Fuel Facility & Materials Bafety Branch CUNINGHAM.A L Region 2. Atlanta. Office of the Director 80/06/17 3pp
- 8007020391 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20,
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required, D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24, 1p
- 8007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Resenount Inc Models 1191 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment lincr penetration wolds Penetrations at Sequoyah. Watts Bar & Bellefonte contain flued head design Design for Yellow Creek not yet completed MILLS, L. M. Tennessee Valley Authority 80/07/08, 5pp.
- B007170272 Responds to NRC 800617 ltr re violations noted in IE Insp Repts 50-390/B0-14 & 50-391/B0-10 Corrective actions weld procedure changed to allow use of 1/B-inch filler metal for root pass & inspectors instructed to follow instructions MILL9.L M. Tennesse Valley Authority B0/07/10 3pp
- 8007230582 Responds to NRC ltr re violation noted in IE Insp Rapt 50-390/80-14 Corrective actions starting on 800418, items in room identified by engineering were cleaned & returned to warehouse per WBNF-0CP-1 & MILLS, L H Tennessee Valley Authority 80/07/15 4pp.

- Q007290813 Responds to 800626 request for add1 actions to avoid further nancompliance & date full compliance achieved re plant areas w/open pipe ends & manuays left unattended GA program initiated to check coverage Full compliance by 800714 MILLS.L M Tennessee Valley Authority 80/07/23 2pp
- & Reportable occurrences, LERs & related correspondence
- BOO7020619 Fifth interim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code Pittsburgh-Des Moines Steel Co & TVA discussing repairs Next rept will be provided by 800905 MILLS.L M Tennessee Valley Authority 80/06/18 ip
- 8007160571 Forwards final deficiency rept re chemical & vol control syscentrifugal charping pumps MILLS.L.M Tennesser Valley Authority 80/04/18 ip
- B007170664 Part 21 final rept re Westinghouse chemical & vol control sys centrifugal charging pumps Following secondary side high energy line rupture & associated reactor trip.min flow may not be met Emergency operating procedures modified HILLS.L N Tennessee Valley Authority 80/06/18 App
- 8007090222 Becond interim deficiency rept re radiation qualification of safety-related cables encl in conduit inside containment. Util continuing to investigate Rept detailing results of systemation & corrective actions expected by 800919 MILLS.L.M. Tennessee Valley Authority 80/07/01. ip
- 8007140422 Forwards first interim deficiency rept re insufficient analysis of 3-inch fire protection lines Will submit next rept by 800902 HILLS.L M Tennessee Valley Authority 80/07/03 1p
- --B007140427 First interim deficiency rept re insufficient analysis of 3-inch fire protection lines Layout drawings did not provide sufficient dimensions Three-inch fire protection lines will be rigorously analysed & supports will be added Tennessee Valley Authority 80/07/03 ip
- 8007170513 Forwards first interim deficiency rept re cutting of conduit supports w/o cutting release HILLS.L.M. Tennessee Valley Authority 80/07/11 ip
- --8007170525 First interim deficiency rept re cutting of conduit supports w/o cutting release Investigation underway Addl info expected by 800827

 * Tennesses Valley Authority. 80/07/11 ip.
- 8007170B91 Fourth interim deficiency rept re incorrect analysis of total temp range for essential raw cooling water piping Incorrect analysis confined to piping in auxiliary & reactor bldgs. New thermal analyses underway MILLB.L M Tennessee Valley Authority 80/07/11 2pp
- 8007230487 Second interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment Applicable GC procedures written or revised to include omitted equipment Available documentation to be revisued for further action MILLS,L,M. Tennessee Valley Authority 80/07/15 ip.
- 8007230505 First interim deficiency rept re inability of QE breakers to withstand design impulse levels. Caused by possible problem in assembly of breaker bushings, Circuit breakers will be returned to QE MILLS.L. M Tennessee Valley Authority 80/07/18 2pp
- 8007230587 Forwards revised fine) deficiency rept re potential to everlued containment cooling sys pump discharge nozzles MILLS.L M. Tennessee Valley Authority 80/07/18 ip.
- -B007230591 Revised final deficiency rept re potential to overload containment cooling sys pump discharge nozzles. Design modified by replacing some grid supports wanubbers Bupports will be properly installed as required by 801205 * Tennessee Valley Authority 80/07/18 ip
- B007290610 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins Westinghouse has not completed evaluation of pins taken from operating plant Next rept will be forwarded by 800911

 D'REILLY, J P Tennessee Valley Authority B0/07/24 ip

V Operator Examinations

8007080388 Notifies that response to NRC 800603 ltr re operator training was submitted in JR Calhoun 800416 ltr to P Collins MILLs, L. H. Tonnessee Valley Authority 80/07/01 ip

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B0070i0i4B Requests add1 info within two wks.needed to determine potential for underclad cracking in reactor vessel nuriles Ultrasonic exams did not indicate explicit correlation between observed cracking & pre/post-clad heat treatment BCHMENCER.A Licensing Branch 2 80/06/18 2pp
- B007020707 Forwards request for info re confirmatory piping analysis Response should be submitted to ANL by B00703 includes info re piping layout & isometric drawings sufficient to model sys & support frawings w/support & hanger spring rates SCHHENCER, A Litensing Branch 2 80/06/23 3pp
- 80070i0386 Advises that util has received no response to 290928 request for extensions until Mar & Dec 1981 for Watts Dar 1 & 2 Add1 safety requirements may result in completion by Jan 1901 for Bedgusyah 2.May 1981 for Watts 1 & Feb 1982 for Watts 2 MILLS.L M Tennessee Valley Authority 80/06/26 ip
- 8007230001 Forwards statement of policy is requirements to be not for current OL applications, as derived from NUREO-0640 & found in NUREO-0694 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007080253 Forwards addl request to ultrasonic exam of welds MILLS, L M Tennessee Valley Authority 80/07/01 3pp
- 80073005B4 Notification of contract execution, Mod 2 to "Evaluation of Buckling Stress Criteria for Steel Containment at Watts Bar " Contractor Intl Structural Engineers TRAGESSER, C M Purchasing Section FIN B-49B1 80/07/02 1p
- --8007300587 Mod 2.changing completion date, to "Evaluation of Buckling Stress Criteria for Steel Containment at Watts Bar " * International Structural Engineers, Inc PERLMAN.J Administrative Contrasts Branch FIN B-6881 80/07/02 ip
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 87pp
- H General correspondence
- 8007250081 Responds to 790425 request for info re nuclear energy Radiation doses from power plants is small fraction of dose from natural environ sources FEB excerpt & White House 800212 message to Congress encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/27 18pg
- Q Inspection reports. IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit | While in Refueling Mode" No response required 0'REILLY, J P Region 2, Atlanta, Diffice of the Director 80/09/08 3pp
- 8007210488 Forwards IE Circular 80-13. "Grid Strap Damage in Heatinghouse Fuel Assemblies " No written response requires O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28 ip
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/29
- 8007220029 Forwards IE Info Notice 80-24, "Evaluation of Contractor OA Programs " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/10 3pp

- 007160287 Forwards 1E Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required."
- required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
 ip
- 307250384 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/13 3pp
- 07020391 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY-J P Region 2. Atlanta, Office of the Director 60/06/20
- 07170070 Forwards IE Circular 80-14, "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required 1/REILLY.J P Region 2. Atlanta. Office of the Director 80/06/24
- 17230253 Forwards IE Builetin 80-16, "Potential Misapplication of Resemble to Models 1151 & 1152 Pressure Transmitters WEIther A or D Output Codes "Hritten response required (E Circular 80-16 also entl No written response required 148EILLY.J P Region 2. Atlanta. Office of the Director 80/06/27
- 7210036 Forwards response to IE Bulletin 80-08 re-examination of ontainment liner penetration welds Penetrations at equoyah. Watts Bar & Beilefonte contain flued head design esign for Yellow Creek not yet completed ILLS.L M Tennessee Valley Authorsty 80/07/08 Spp
- 7170272 Responds to NRC B00617 ltr re violations noted in IE Inspepts 50-390/B0-14 & 50-391/B0-10 Corrective actions weld vocadure changed to allow use of 1/B-inch filler metal for sot pass & inspectors instructed to follow instructions ILLS:L M Tennessee Valley Authority 80/07/10, 3pp
- leportable occurrences, LERs & related correspondence
- O20619 Fifth interim deficiency rept re refueling water storage ink overflow line not fabricated to ASME code Pittsburghs Mainus Steel Co & TVA discussing repairs Next rept will provided by 800905 LLS-L M Tennessee Valley Authority 80/06/18 ip
- 160971 Forwards final deficiency rept re chemical & vol control systems of the standard pumps and the systems of the systems o
-)716057B Final deficiency rept re potential for degradation of one or more chemical & vol control sys centrifugal charging pumps lesign & plant emergency operating procedures will be modified as recommended by Westinghouse
 Tennessee Valiny Authority 80/06/18 2pp
- 70664 Part 21 final rept re Westinghouse chemical & vol control centrifugal charging pumps Following secondary side high rgy line repture & associated reactor trip min flow may be met Emergency operating procedures modified LG.L M Tennesser Valley Authority 80/06/18 App
- 70222 Second interim deficiency rept re radiation qualification of ety-related cables encl in conduct inside containment 1 continuing to investigate Rept detailing results of luation & corrective actions expected by 800717

 -S.L M Tennessee Valley Authority 80/07/01 ip
- 10422 Forwards first interim deficiency rept re insufficient usis of 3-inch fire protection lines Wiil submit next by 800902 S.L.M. Tennessee Vallay Authority 80/07/03 ip
- 140427 First interim deficiency rept re insufficient analysis of inch fire protection lines Layout drawings did not provide fficient dimensions. Three-inch fire protection lines will rigorously analysed & supports will be added Tennessee Valley Authority 80/07/03 1p
-)313 Forwards first interim deficiency rept re cutting of conduit orts w/o cutting release
 .L M Tennessee Valley Authority 80/07/11 lp

- --8007170525 First interim deficiency rept re-cutting of conduit supports
 W/o cutting release Investigation underway Addl info
 sipected by 800829
 # Temnessee Valloy Authority 80/07/1: 1p
- B007170591 Fourth interim deficiency rept re incorrect analysis of total temp range for essential raw cooling water piping Incorrect analysis confined to piping in auxiliary & reactor bldgs New thermal analyses underway MILLS.L M Tennessee Valley Authority 80/07/11 2pp
- 8007230487 Second interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment Applicable QC procedures written or revised to include omitted equipment Available documentation to be reviewed for further action MILLS,L M Tennessen Valley Authority 80/07/15 ip
- 8007230505 First interim deficiency rept re inability of QE breakers to withstand design impulse levels Caused by possible problem in assembly of breaker bushings Circuit breakers will be returned to QE MILS.L M Tennessee Valing Authority 80/07/18, 2pp
- 8007230587 Forwards revised final deficiency rept re potential to overload containment cooling sys pump discharge nozzles MILLS.L M Tennossee Valley Authority 80/07/18 1p
- --800723059; Revised final deficiency rept re potential to overload containment cooling sys pump discharge nazzles. Design modified by replacing some grad supports w/snubbers Supports will be properly installed as required by 801205 * Tennesser Valiey Authority 80/07/18 1p
- 80072906:0 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins Hestinghouse has not completed evaluation of pins taken from operating plant Next rept will be forwarded by 80091;

 O'REILLY, J F Tennessee Valley Authority 80/07/24 1p
- V Operator Examinations
- BOO7080398 Notifies that response to NRC 800403 ltr re operator training was submitted in JR Calhoun 800416 ltr to P Collins MILLS.L M Tennessee Valley Authority 80/07/01 lp
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT &
- 8007020061 Summary of 800613 meeting w/util re structural & geotechnical engineering review w/emphasis on syc water intake structure
 HDUOHTGN.T C Licensing Branch 3 80/06/23 5pp
- B007140229 Notification of 800708-10 meeting w/util in Columbia, SC to review qualifications of util to operate plant List of agenda items encl
 KANE, W.F. Licensing Branch 2 80/06/26 Spp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D @ Division of Licensing 80/06/26 2pp
- B007180334 Forwards request for add1 info in connection w/NRC review of OL application Info covers areas of matls engineering, secondary water chemistry control & seismology Beismology questions replace those numbered 361 12 to 361 17 BCHWENGER.A Licensing Branch 3 B0/06/30, 14pp
- 8007230635 Forwards etd order for DOE work MATTEON.N J Division of Safety Technology FIN A-1121-0 BO/06/30 3pp
- --8007230452 Std order for DUE work "Review of Auxiliary Feedwater Sys Reliability Evaluation Studies for Diable Cangon 1, McQuire 1. Summer 1 & San Dnofre 2 & ECCS Reliability Analysis of Manual vs Autometic " Issued to Sandia Labs GRENIER.B L. Division of Safety Technology FIN A-1121-0 SO/06/27 900
- 8007070011 Notifies that two Hestinghouse plants w/reactor vessel internals similar to facility, have experienced fuel rod damage due to water jetting through reactor vessel lower internals baffle gaps Notes Westinghouse recommendation CREWB, E.H. South Carolina Electric & Oss Co. 80/07/01 2pp

- BOO7080393 Notifies of delay in response to NRC BOO618 ltr on underclad cracking in reactor vessel notiles Westinghouse info will not be available for approx 3 wks
 REMB-E H Bouth Carolina Electric & Gas Co BO/07/02 lp
- BO07160252 Forwards add1 info re svc water intake structure in response to NRC B00623 request All load combinations & loads specified for reinforced concrete strength design satisfied CREMS,F H Bouth Carolina Electric & Gas Co B0/07/03 6pp
- 8007170607 Forwards response to NRC 800630 1tr w/questions re secondary water chemistry control program FSAR amend will be filed in GREWS, E H South Carolina Electric & Gas Co 80/07/14 16pp
- --B007170612 "Chemistry Procedure CHP-612, Out-Df-Spec Handling & Reporting," Revision O LEACH.F J , CROLEY, B O Bouth Carolina Electric & Oas Co 80/03/27 17pp
- B007220428 Forwards May 1980 status rept re NUREG-0660 & NUREG-0694 CREMB.E H South Carolina Electric & Gas Co B0/07/18 70pp
- 800720030B Forwards "Environ Exposure of Low Voltage Power Cable," to suppl response to FSAR Guestions 31 71-73 Rept withheld (ref 10CFR2 790)
 CREMB.E H South Carolina Electric & Oas Co 80/07/21 1p
- 8007250491 Forwards Drawing R31E50290. Sheets 1-9, in response to FSAR electrical Question Si 67. Drawings withheld (ref 10CFR2 790)
 GREUBJE H South Carolina Electric & Gas Co 80/07/21 ip
- C Utility Environmental Report (ER), amends & correspondence
- 8007070269 Forwards Amend 5 to environ rept Certificate of Compliance CREWB, E H South Carolina Electric & Gas Co 80/07/03 4pp
- -8007070270 Amend 5 to environ rept
 # South Carplina Electric & Oas Co 80/06/30 2ipp
- F Security, medical, emergency & fire protection plans
- 6007090050 Notification of 800722 & 23 meetings w/util in Jenkinsville. BC to review facility emergency planning HOUGHTON, T.C. Licensing Branch 2 80/06/23 3pp
- B007220390 Forwards Revision 1 to facility radiation emergency plan CREMB, E H South Carolina Electric & Gas Co 80/07/18 1p
- ---B007220392 Radiation amorgancy plan. Revision 1 * South Carolina Electric & Oas Co 80/07/18 200pp
- 8007290626 Forwards "Evacuation Time Estimates," in response to NRC B00702 request CREMB.E H South Carolina Electric & Qas Co B0/07/24 lp
- --8007290627 "Evacuation Time Estimates " Lexington, Fairfield & Newberry Counties, BC comments encl * South Carolina Electric & Qas Co BO/02/26 10pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order. UCB 77104 petition sought action re fire protection for slectrical cables EISENHUT, D 0 Division of Licensing 80/06/25 89pp
- M Antitrust correspondence
- B007020597 Memorandum & order setting forth facts re General Electric Power Cooperative petition for significant changes determination under Atomic Energy Act.Requests Atty General assistance for final determination.

 CHILKS J Office of the Secretary of the Commission 80/06/30
- 8007090223 Requests info to be provided within 10 days in response to Commission 800630 order, CLI-80-28 Request does not relieve recipient from compliance wlorder, Response must include competitive status since Dec 1978 & latest annual rept CHANANIA, F. D Antitrust Division. 80/07/08 2pp

- 8007090248 Requests info to be provided within 10 days in response to Commission 800630 order, CLI-80-28 Request does not relieve recipients from compliance w/order Response must include competitive status since be/1738 & latest annual rept CHANANIA.F D Antitrust Division 80/07/08 Zpp
- B007090252 Requests life to be provided within 10 days, in response to Commission 8000630 order, CLI-80-28 Request does not relieve recipients from compliance w/order Response must include conjective status since Dec 1978 i latest annual rept CHANANIA, F D Antitrust Division 80/07/08 2pp
- B0072504B5 Motion for 20-day extension to file comments BEENY, S T Central Electric Fower Cooperative, Inc. BEENY, S T Brand & Hall 80/07/24 2pp
- --B00725050? Affidavit stating that Brand & Hall has received 100.000 documents from SC Electric & Gas Co Hany documents relate to NC & SC cases & may include inconsistent info Certificate of Svc and Brand & Hall 80/07/23 4pp
- 8007310424 Responds to 800708 request for info re 800630 memorandum & order Discusses St Electric & Gas Co competitive relationship w/Central Electric Power Cooperative, Inc Correspondence encl CONNER T D Conner, Moore & Corber 80/07/28 7pp
- Q Inspection reports. IE Bulletins & correspondence
- B007240220 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/05/00
- 8007240222 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required

 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- B007020170 Forwards IE Info Notice 80-22, "Breekdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007020171 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J F Region 2. Atlanta. Office of the Director 80/05/28
- 8007210471 Forwards IE Circular 80-13, "Grid Strep Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- B007210472 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010242 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/05/29
- 8007010248 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/29
- B007220017 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/10
- 8007220083 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10
- 8007160281 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/04/11

- B007250378 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR80 55(s) " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/13 200
- B0072303B0 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/13
- 8007020741 Forwards IE Builetin 80-15, "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Hritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007020748 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/18
- 800702038i Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/20
- 8007020384 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/06/20
- BOO7160781 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/2.
- 8007160784 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/24 ip
- 8007180256 Ack receipt of IE Insp Rept 50-395/80-14 No proprietary info JOHNSON, M C South Carolina Electric & Gas Co 80/06/24 ip
- --80D7180265 Forwards IE Insp Rept 50-395/80-14 on 800513-14 No noncompliance noted MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 8D/06/04 2pp
- --8007180275 IE Insp Rept 50-395/80-14 on 800513-16 No noncompliance noted Major areas inspected instrumentation cables termination work & work activities termination quality records. electrical components & sys quality records CONLON.TE Region 2. Atlanta. Reactor Construction & Engineering Support Oranch oldBBONS.TD. MERGIMEATHER, N. Region 2. Atlanta. Office of the Director 80/06/04 6pp
- 8007230213 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/27 in
- B007230217 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Qutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/27
 - nonse to IE Bulletin 80-05 Action Items 1 & p plant atmosphere or lines Size of Vent tup

ied on

- 8007010489 Supplement 3 to Part 21 rept re failed thrust bearing. Insp. complete Crankshoft thrust bearings on two diesel generators are free of reported potential defect MORIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div. 80706/26 ip
- 8007010357 Deficiency rept re possible improper rocker arm prelube pump operation Pump could fail to start as result of hydraulic lock in cylinder Instituting further review of other installation electrical schematics & instruction manuals MoriaRTY, J M Colf Industries, Inc., Fairbanks Morse Engine Div. 80/06/27 2pp
- 8007250457 Final deficiency rept re diesel generator prelube oil sump continuous operation Pump controls will be revised to operate for short period of time each day Length of time to be determined by mfg CREMB.E M South Carolina Electric & Oas Co 80/07/21 4pp
- DOCKET 50-374 UNIV OF VIROINIA CAVALIER REACTOR

 F Security, medical, emergency & fire protection plans
- 8007210429 Forwards physical security plan & proposed changes to Tech Specs Plan withheld (ref 10CFR2 790) SHRIVER, D L. Virginia, Univ of 80/07/15 2pp
- ---8007210433 Tech Specs 3 3.4 1.4 2.4 8.6.2 % 6 3 re safety limits, iimlting conditions for operation & surveillance requirements * Virginia, Univ of 80/07/15 9pp
- Q Inspection reports, IE Bulletins & correspondence
- B007:70:73 Forwards IE Circular B0-i4, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24.
- DOCKET 50-397 WPPSB NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- BO07030196 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO, R.L. Assistant Director for Licensing 80/06/12. 2pp
- 8007010002 Forwards drawings in response to Round One, Set Eight, Guestions 031 104 & 031 105 Control room panels revision status sheet encl RENBERGER, D.L. Washington Public Power Supply System 80/06/16.
- ---B007010004 "Radwaste & Control Bldg Elevations 501 Ft & 507 Ft.Lighting Plan " * Burns & Roc Co 79/12/11 1p
- --8007010007 "Radwaste & Control Bldg Elevations 501 Ft & 507 Ft/Pawar Conduit & Tray Plan " + Burns & Roe Co 80/04/16 1p
- --8007010018 "Radwaste & Control Bidg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan * Sheet 1 * Burns & Roe Co 80/06/11, ip
- --8007010021 "Radwaste & Control Bldg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan " Sheet 2, * Burns & Ros Co 80/06/12 Ip
- --B007010023 "Radwaste & Control Bidg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan " Sheet 3 * Burns & Ros Co B0/04/16 ip
- --8007010032 "Radwaste & Control Bldg Elevations 501 Ft & 507 Ft,
 Instrumentation & Control Conduit & Tray Plan " Bhest 4.

 * Burns & Roe Co 80/03/06 ip
- --8007010033 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Shest 1 # Burns & Roe Co 80/03/06 ip
- ---8007010038 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet 2 # Burns & Roe Co 79/12/06. 1p

5p

- --8007010041 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet 3 * Burns & Roo Co 80/03/24 ip

- ---BOO7010054 "Radwasta & Control Bidg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet 7

 * Burns & Ros Co 60/03/12 ip
- ---B00701005B "Radwaste & Control Bidg Cable Tables, Instrumentation & Control Conduit & Tray " Ehset B
 + Burns & Roe Co B0/03/11 1p
- --8007010059 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray." Sheet 9

 * Burns & Ree Co 80/03/11, 1p
- --B007010061 "Hadwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray." Sheet 10
 # Burns & Roe Co. 60/01/03 1p
- ---B007010064 "Radweste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet ii # Burns & Ros Co 80/03/24 ip
- --B007010069 "Radweste & Control Bldg Control Room & Remote Shutdown Room-Arrapsements," Sheet 1 * Burns & Roe Co. 80/01/14 ip
- --- BOO7010073 "Radwaste & Control Room Arrangements Elevation 467 Ft " Sheet 2. # Burns & Ros Co. 80/03/24
- --- 8007010076 "Salance of Plant Remote Shutdown Board (DD-RS) " Sheet RS1 of RS2 * Burns & Ros Co 75/08/08 1p
- --- 8007010083 "Balance of Plant Remote Shutdown Board (BD-RS) Lagend " Sheet RH2 of RH2 * Washington Public Power Bupply System 79/06/20 1p
- --8007010090 "Engraving Remote Shutdown VB " # General Electric Co 75/06/30 ip
- --8007010095 "Engraving Remote Shutdown VB "
 # General Electric Co 75/05/12 ip
- --8007010098 "Remote Shutdown VS "
 * Canarat Electric Co 75/12/15 ip General Electric Co
- B007030239 Notification of 800702 meeting w/BWR licensing review group in Bethesda.ND to discuss consensus position on reactor syc bldg open issue WILBON.J.N Licensing Branch 1 80/06/18 9pp
- 8007010277 Bummary of B00613 meeting w/utils.KMC. Inc. OE. Rechtel. S&W & Sargent & Lundy in Betheada. MD re consensus positions on reactor syc bidg & isolation cooling sys bidg open issues from La Balle docket. Batus repts enci HILSON, J N Assistant Director for Licensing 80/06/19 46pp
- B007230001 Forwards statement of policy ro requirements to be met for current OL applications, as derived from NUREG-0540 & found in NUREG-0594 Division of Licensing 60/06/26 2pp EIBENHUT, D Q
- BOO7140511 Forwards comments re adequacy of site archaeological investigations & Bonneville Power Administration survey & testing along Asche-Blatt transmission routs OCRODN.O J Interior, Dept of 80707/03 3pp

- 8007170339 Notification of B00702 meeting w/BWR licensing review group in Bethesda/ND to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for 800709
 HILBON.J N Assistant Director for Licensing H0/07/03 ip
- --8007170347 Notification of 800722 meeting w/BMR licensing review group in Bethesda.MD to discuss TMI issues required for OL issuance
 WILSDN.J N Assistant Director for Licensing 80/07/03 to
- --8007170331 Notification of 800724 meeting w/BHR licensing review group in Bethesda-MD to introduce BHR licensing review group & present consensus positions for Powbr Sys Branch. Containment Sys Branch & Equipment Qualification Branch 80/07/03 Spa WILSON J N Assistant Director for Licensing
- 8007230621 Summary of 800612 meeting w/Mark II owners group in Bethesda,MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs enci ANDERSON,C J Generic Issues Branch 80/07/03 57pp
- BOO71506BO Requests meeting w/NRC to discuss containment hydrodynamic loads & chugging data becoming available from 4YCO tests RENBERGER,D L Hashington Public Power Bupply System BO/07/10
- 8007290371 Forwards repts referenced in NRC 800602 Question 360 005 RENBERGER, D.L. Washington Public Power Supply System 80/07/11
- --B007230393 "Evaluation of Faulting in Warm Spring Canyon Area Southeast WA:" Dec 1979 Oversize drawings encl Prepared for WA Public Power Supply Sys FAROGOULS M Shannon & Wilson Inc 79/12/31 28pp
- --8007290396 "Geologic Reconnaissance of Wallula Gap,WA -- Blue Mountains -- LaGrande.OR Region," Dec 1979 Oversize drawings & map encl Prepared for WA Public Power Bupply Gys WIENLE-G F. HANILL.M L. CLAYTON,D N Shannon & Wilson,Inc 79/12/31 91pp
- --8007250398 "Osologic Evaluation of Selected Faults & Lineaments, Pasco & Walla Walla Basins, MA." May 1980 Oversize drawings encl Prepared for WA Public Power Supply Sys FAROGOUI, 6 M , THOMAS.R E Shannon & Wilson, Inc 80/05/31 45pp.
- --B007250400 "Seismological Roview of 360716 Milton-Freewater Earthquake Source Region:" Jan 1980 Prepared for MA Public Power Supply
 - Woodward-Clyde Consultants, Inc 80/01/31 64pp
- --8007250402 "Recent Seismicity of Hanford Region," Feb 1980 Prepared for WA Public Power Supply Sys

 * Woodward-Clyde Consultants, Inc. 80/02/29 98pp
- --8007250403 "Palsomagnetism & Age Dating." Jul 1978 Prepared for United Engineers & Constructors.Inc # Woodward-Clyde Consultants. Inc 78/07/31 53pp
- 8007310409 Responds to Round One Questions, Set 9, Questions 211 049 -311 106
 RENDERGER, D.L. Washington Public Power Supply System 80/07/11
- 8007210392 Ack receipt of NRC 800430 ltr approving request to discontinue certain aquatic monitoring & requesting copies of util submittals to State of MA re water quality NRC does not have authority to require water quality filings RENBERGER.D L Washington Public Power Supply System 80/07/14 Зрр
- 8007230133 Notification of 800725 meeting w/BWR Licensing Review Oracle in BetheedarMD to discuss concensus positions of BWR Licensing Review Oracle uniCSB open assues WILSON.J N Licensing Brench | 80/07/16 | 10pp
- 8007310447 Confirms 800718 telion re adequacy of work control & QA sys of mechanical contractor Wright Schuchart Harbor, Boecon GERT Litensee stop work directive will remain in effect until NRC has examined re-evaluation ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/07/18 10

Adjudicatory correspondence

1

17310243 Forwards Commission 800527 memorandum & order containing ecisions on UCS 780502 patition for reconsideration of 80413 memorandum & order UCS 771104 petition sought action e fire protection for electrical cables ISENHUT, D G Division of Licensing 80/06/25 87pp

Inspection reports, JE Bulletins & correspondence

17250394 Responds to IE Bulletin BO-D3, "Loss of Charcoal from Std ype II, 2-Inch Troy Adsorbor Cells " Visual insp of adsorber ells tube installed in control rnom purspency filter units of possible since delivery has not been made ENBERGER, D L Washington Public Power Supply System DO/03/18

7230003 Responds to 1E Bulletin 80-02 Marvin Engineering Co did not upply internal feedwater spangers or thermal sleeves for eactor pressure vessel at Unit 2 ENDERGER, D. L. Washington Public Power Supply System 80/04/28

7140097 Responds to S Meyers BOD314 ltr to Senator Magnuson re Drown allegations dealing w/80 Results of investigation eviewed w/Brown on BOD227 Since each inspector may look at arious code aspects, findings may differ TELLO.V Office of Inspection & Enforcement, Office of the irector 80/05/05 lp

007140098 Responds to DDE 800122 memo to NRC re R Brown 790821 & 0919 ltrs alleging faulty GC at sito Reply will be made directly to Brown upon completion of investigation STELLO, V Office of Inspection & Enforcement, Office of the Director 80/02/29 ip

JO7140102 Forwards response to R Brown 790919 ltr alleging faulty QC at site Investigation determined one allegation having no sefety significance was substantiated Other allegation, having safety significance partially substantated DIRCKB.W J Office of the Executive Director for Operations 80/04/25 Bpp

71409B7 Forwards IE Bulletin 80-13. "Cracking in Core Spray Jargers" No written response required (GELKEN,R E Region 5, San Francisco, Office of the Director >/05/12 ip

'220252 Forwards IC Info Notice 8D-26, "Evaluation of Contractor Programs" No written response required lockMEN.A H Region 5. Sen Francisco, DPFIce of the Director //06/10 lp

140414 Forwards IE Bullotin BO-14. "Degradation of BMR Scram scharge Vol Capability " No written response required GELMEN, R H Region 5. Ban Francisco, Office of the Director VO6/12 Ip

300544 Reponds to 1E Bulletin 80-07 re damage to Chemical volution systems. Bulletin inepplicable since facility is R not PMR. NSERGER, D.L. Washington Public Power Supply System 80/06/12

70070 Forwards 16 Info Notice 80-28, "Promot Reporting of Info

290070 Forwards Ik Info Notice 80-28, "Frampt Reporting of Info in cordance W/100FR50 \pm 51#) " No written response required GELKEN-R H Region 5, San Francisco. Office of the Director /06/13 ip

020466 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump 914ng & Natural Circulation Cooldown" No written response quared GELKEN, R H Region 5. San Francisco. Office of the Director 706/20 ip

180297 Forwards 1E Circular 80-14, "Redocative Contamination of ant Demineralized Water Sys ? Resultant Internal atomination of Personnel " No written response required BELKEN.R H Region 5. San Francisco, Office of the Director 06/24 1p

23040: Forwards IE Bulletin BO-16, "Potential Misapplication of smount Inc Models 1991 & 1992 Pressure Transmitters ither A or D Output Codes " Written response required Circular BO-16 also encl No written response required ELKENR H Region 5. San Francisco, Office of the Director, '06/27 1p

800723061B Ack receipt of 800305 & Q611 ltrs informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-397/79-10
SPENCER. 9 S Region 4, Dailas, Reactor Construction & Engineering Support Branch

--8007230623 Forwards revised response to violations noted in IE Investigation Rept 50-397/79-10 Transient analysis indicates matl adjacent to weld & under heating blanket were not excessively overheated RENBERGER.D L. Washington Public Power Bupply System 80/06/11 200

--8007230629 Forwards 1E investigation Rept 50-397/79-10 on 790517.0529-0601.11-14 & 0910-14 & notice of violation SPENCER.O S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/21 2pp

--8007230632 Notice of violation from insp on 790517.0529-0601,11-14 & 0910-14

A Region 5. San Francisco, Office of the Director 80/01/21

--B007230639 IE Investigation Rept 50-397/79-10 on 790517,0529-0601.11-14 & 0910-14 Noncompliance noted failure to qualify post-weld neat treatment procedure Procedures for equipment operations not provided BIGHUP,T W., HERNANDEZ. G. Region 5. Ban Francisco, Office of the Director DODDS,R T. Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/01/21 Spp

B007310171 Forwards status of flued head containment penetration welds in response to IE Bulletin 80-08 Work on flued heads covered by ASME code Completed welds examined radiographically Defects re incomplete fusion & surface porosity repaired RENBERGER.D L Washington Public Power Bupply System 80/07/10 3pp

800731049B Answers notice of proposed imposition of civil penalties dtd 800617 Majority of findings reflect deficiencies found by contractor, util & NRC Region 5 Encl Exhibit A details protests against imposition of certain proposed penalties STRAND, N D Washington Public Pawer Supply System 80/07/11 58pp

B007310502 Provides response to notice of violation & request for addl info Outlines short-term intermediate & continuing phases of evaluations Supporting documentation encl STRAND, N O Hashington Public Power Supply System B0/07/17 Japp

S Reportable occurrences, LERs & related correspondence

8007290704 Interim deficiency rept re gaps & voids in sacrificial shield wall Corrective action plan described in 800420 ltr Implementation as pending NRC concurrence RENBERGER, D L Washington Public Power Supply System 80/07/23 2pp

U Congressional/Executive Correspondence

8007210390 Discusses NRC B00617 issuance of Escalated Enforcement Act in form of penalty to util Interest expressed in correlation between schedule delays & cost overruns in rest of industry & financial arrangements similar to util WEAVER, J House of Pep 80/0//14 3pp

8007300367 Submits questions re unusual financing arrangement between util & Bonneville Power Administration Related correspondence WEAVER.J House of Rep. 80/07/14 2pp

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8007020427 Forwards computer magnetic tape of onsite meteorological data supporting FSAR Bubmitted in format described in DB Vassatlo 790810 itr Format description & tape dump of first 65 records encl Tape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/06/26 12pp

8007170628 Forwards FSAR, Vols i-20, amended OL application & environ rept for OL stage OL application only encl
JONES J A Carolina Power & Light Co 80/06/26 3pp

--B007170639 Application for CL Annual financial rept & prospectus encl * Carolina Power & Light Co B0/06/26 99pp

- B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0694.
 EISENAUT, D C Division of Licensing B0/06/26 2pp
- 8007150535 Requests ciarification of ANSI N45 2 10 as invoked by Reg QUIGE 174,as to whether or not certificates of conformance, certificates of compliance & certified test repts must contain longhand signature
 HCDUFFIE.M A Carolina Power & Light Co 80/07/09 1p
- BOO7220456 Forwards schedules of const milestones & activities as of 800630 Nilestone network schedule will be affected by 800618 revisions in schedule Fuel loading for Units 1 & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs (Carolina Power & Light Co 80/07/11 13pp
- C. Utility Environmental Report (ER), amends & correspondence
- 8007170652 Forwards FSAR.Vols 1-20.amended OL application & environ rept for OL stage Environ rept only encl JONES, J A Carolina Power & Light Co 80/06/26 3pp
- ---B007170663 Environ rept for facility.Voi 1 * Carolina Power & Light Co 80/06/26 350pp
- --- 8007170678 Environ rept for facility, Vol 2 * Caroline Power & Light Co 80/06/26 30000
- -8007170686 Environ rept for facility. Vol 3 8 Carolina Power & Light Co. 80/06/26 300рр
- f Becurity, medical, amergency & fire protection plans
- 8007010352 Forwards industrial security safeguards contingency & security personnel training & qualification plans for raview Plans withheld (ref 10CFR2 790)
 JONES J A. Carolina Power & Light Co 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D @ Division of Licensing 80/06/25 87pp.
- H General correspondence
- BOO7D2019B Responds to BOO516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Ehearon Herris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public DIRCKS, W J Office of the Executive Director for Operations BO/Q6/18 2pp
- power ANDREWS, I House of Rep 80/05/16 2pp
- K Utility Final Bafety Analysis Report (FBAR) & amonds
- B007170366 Forwards FSAR, Vols 1-20, amended OL application & environ rept for OL stage Only FSAR encl JONES, J. A. Carolina Power & Light Co 80/06/26 3pp
- 0007170372 Chapter 1 to Shearon Harris 1.2.3 & 4 FSAR. "Introduction & General Description of Plant" * Carolina Power & Light Co 80/06/26 500pp
- B007170377 Chapter 2 to Shearon Harris 1,2,3 & 4 FSAR, "Site Characteristics" # Carolina Power & Light Co 80/06/26 700pp
- BOO7170541 Chapter 3 to Bhearon Harris 1,2,3 & 4 FSAR, "Design of Structures, Components, Equipment & Sys " * Carolina Power & Light Co 80/06/26 700pp
- B087170572 Chapter 4 to Shearon Harris 1,2,3 & 4 FSAR, "Reactor "
 Carolina Power & Light Co 80/06/26 200pp

- 8007170578 Chapter 5 to Shearon Harris 1.2.3 & 4 FSAR, "RCS & Connected Sys " * Carolina Power & Light Co 80/06/26 175pp
- 8007170594 Chapter & to Shearon Harris 1,2,3 & 4 FSAR, "Engineered Safety Features " * Carolina Power & Light Co 80/06/26 650pp
- 8007170600 Chapter 7 to Shearon Harris i.2.3 & 4 FSAR, "Instrumentation & Controls" * Carolina Power & Light Co 80/06/26 500pp
- 8007170615 Chapter 8 to Shearon Harris 1.2.3 4 4 FSAR, "Electric
- Carolina Power & Light Co 80/06/26 125pp
- 8007170627 Chaptur 9 to Shealon Harris 1.2.3 & 4 FEAR. "Auxiliary Sys "
 * Carolina Power & Light Co 80/06/26 700pp
- 8007170643 Chapter 10 to Shearon Harris 1.2.3 % A FSAR, "Steam & Power Conversion Sys " * Carolina Power & Light Co. 80/06/26 150pp
- 8007170650 Chapter 11 to Shearon Harris 1.2.3 & 4 FSAR. "Radwaste Ngt " * Carolina Power & Light Co 80/06/26 175pp
- 8007170655 Chapter 12 to Shearon Harris 1,2,3 & 4 FSAR, "Radiation rotection " Carolina Power & Light Co 80/06/26 200pp
- 8007170661 Chapter 13 to Shearon Harris 1,2,3 & 4 FSAR, "Conduct of Operations "
 * Carolina Power & Light Co 80/06/26 250pp
- 8007170672 Chapter 14 to Shearon Harris 1.2.3 & 4 FSAR. "Initial Test * Carolina Power & Light Co 80/06/26 75pp
- 8007170677 Chaster 15 to Shearon Harris 1.2.3 & 4 FBAR. "Accident ılysis " Carolina Power & Light Co = 80/06/26 = 400pp
- 8007170684 Chapter 14 to Shearon Harris 1.2.3 & 4 FSAR, "Tech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Shearon Harris 1,2,3 & 4 F9AR, "QA" * Carolina Power & Light Co 80/06/26 37pp
- 8007170690 App i to Shearon Harris i.2.3 & 4 FSAR, "TM1 "

 * Carolina Power & Light Co 80/06/26 37pp
- G Inspection reports. IE Buileting & correspondence
- 8007240113 Forwards lE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/05/08
- 8007210422 Forwards IE Circular 80-i3. "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010179 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/29
- 8007220043 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10
- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Conlant Pump Stude " No specific action or response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/06/11
- 8007250339 Forwards IE Info Notice 80-28, "Prompt Reporting of Info In Accordance W/10CFR50 55(e) " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13

- 307100297 Ack receipt of IE Insp Repts 50-400/80-13, 30-401/80-11, 30-402/80-11 & 50-403/80-11 on 800513-16 No preprietary
- HOWE, P W Carolina Power & Light Co 80/05/15 1p
- H007100301 Forwards IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 & notice of violation MURPsy. C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/05 2pp
- 8007100305 Notice of violation from insp on 800513-i6 Region 3, Chicago, Office of the Director 80/06 80/04/05 10
- B007100313 IE insp Repts 50-400/80-13, 90-401/80-11,50-402/80-11 & 50-403/80-11 on 800513-16 Noncompliance noted tack welds deposited over fravy rust HERDY, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch MLETHEURGE, W.P. Region 2, Atlanta, Office of the Director B0/06/05 9pp
- 107020440 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 07100412 Ack receipt of 800609 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-01. S0-401/80-08. S0-401/80-08 S0-401/80-08 MININGERY C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/06/23 ip
- B007100416 Responds to NRC B00513 ltr re violation noted in IE Insp Repta NO-400/B0-11.50-401/B0-08.50-402/B0-08 & 30-403/B0-08 Corrective actions investigation held of collected test data re backfill math affecting Category I piping HOME,P W Carolina Power & Light Ca B0/06/05 3pp
- 1007100422 Ark receipt of 1E Insp Repts 50-400/80-ii,50-401/80-0B, 50-402/80-0B & 50-403/80-0B on B00422-24 No proprietary HONE,P W Carolina Power & Light Co 80/05/22 ip.
- 8007100428 Forwards IE Insp Repts 50-400/80-11,50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of Violation

 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering

 Busport Branch 80/05/13 2pp
- 3007100430 Notice of violation from insp on 800422-24 * Region 2, Atlanta, Dffice of the Director 80/0 80/05/12 1p
- 007100435 IE Insp Repts 50-400/80-11,50-401/80-08,50-402/80-08 & 50-403/80-08 on 800482-24 Noncompliance noted failure to consider effect of backfill settlement analysis of Category CONLON.T F Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J Region 2, Atlanta, Office of the Director 80/05/12 App
- 7160000 Forwards IE Circular 80-14. "Radioactive Contamination of lant Deminoralized Water Sys & Resultant Internal entamination of Personnel" No written response required "REILLY, J P Pegian 2, Atlanta, Office of the Director 80/06/20 80/06/24
- 7230220 Forwards IE Bulletin 80-16. "Potential Misapplication of Damaount Inc Hodols 1191 & 1192 Pressure Transmitters /Either A or D Output Codes " Written response required E Circular 80-16 also encl No written response required 'NEILLY.J P Region 2, Atlanta, Defice of the Director 80/04/2 80/04/27
- 7220210 Responds to IE Bulletin 80-08 Review of containment liner enetration wold designs verified by applicable drawings, alds not complete as plant is under const CDUFFIE.M A Carolina Power & Light CO 80/07/02 2pp
- Periodic operating reports & related correspondence
- 7280307 Forwards "Quarterly Data Rept, Shearon Harris Nuclear Power lant Monitoring Program, Api~June, 1980"
 CDUFFIE,M A Careline Power & Light Co 80/07/21 ip
- 007280513 "Quarterly Data Rept. Shearon Harris Nuclear Power Plant Monitoring Program, Apr-June 1980 * Caroline Power & Light Co 80 80/07/21 1p

- 8 Reportable occurrences, LERs & related correspondence
- 8007080249 Forwards final deficiency rept re omission of addl reinforcing steel in Unit i containment bldg exterior wall adjacent to const opening for equipment hatch CHIANGI.N J Caroline Power & Light Co. 80/06/30 ip
- --B0070B0257 Final deficienty rept re omission of add1 reinforcing steel in Unit 1 containment hldg exterior wall adjacent to const opening for equipment hatch Design review & mod to steel completed Craft work & insp procedures revised * Carolina Power & Light Co. 80/06/24 3pp
- 8007140377 Interim deficiency rept re significant failure of reactor protection sys following main feedline break Hestinghouse has indicated corrective action cannot be completed before Dec 1981 Final rept will be issued upon campletion CHIANGI.N J Carolina Power & Light Co 80/07/08, 1p
- 8007230247 Part 21 rept re lock of stud base qualification for angle arc shield Evaluation will be completed by 801001 CHIANGI.N J Carolina Power & Light Co 80/07/11 2pp
- V Operator Examinations
- 8007180428 Requests review & concurrence w/Senior Reactor Operator Certification program & retraining program per HR Denton B00328 Itr Certification program effective B00630 Retraining effective in 1981 Description of both programs encl COLLING.J M Carolina Power & Light Co 80/06/23 5pp
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020427 Forwards computer magnetic tape of onsite meteorological data supporting FSAR Submitted in format described in OB Vassatlo 790810 ltr.Format description & tape dump of first 65 records encl Tape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/06/26 12pp
- B007i70628 Forwards FSAR,Vols 1-20.amended OL application & environ rept for OL stage OL application only encl
 JONES,J A Carolina Power & Light Co 80/06/26 3pp
- -8007170639 Application for DL Annual financial rapt & prospectus encl, * Carolina Power & Light Co B0/06/26 99pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREQ-0660 & found in NUREQ-0694 EISENHUT, D O Division of Licensing 80/06/26 2pp
- B007150535 Requests clarification of ANSI N45 2 10 as invoked by Reg Quide 1 74.as to whether or not certificates of conformance, certificates of compliance & cortified test repts must contain longhand signature MCDUFFIE
- 8007220456 Forwards schedules of const milestones & activities as of E00630 Milestone network schedule will be affected by 800618 revisions in schedule Fuel loading for Units 1 & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs MCDUFFIE,M A Carolina Power & Light Co 80/07/11 13pp
- C Utility Environmental Report (ER), amends & correspondence
- B007170692 Forwards FSAR.Vols 1-20, amended OL application & environ rept for DL stage Environ rept only encl JONES.J A Carolina Power & Light Co B0/06/26 3pp
- ---8007170663 Environ rept for facility, Vol 1 * Carolina Power & Light Co 80/06/26 350pp
- --8007170678 Environ rept for facility, Vol 2 * Carolina Power & Light Co 80/06/26 30000
- --8007170686 Environ rept for facility, Vol 3 * Carolana Power & Light Co 60/06/26

- F. Becurity, medical, emergency & fire protection plans
- ©007010332 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withheld (ref 10CFR2 790) UNNEL J A Carolina Power & Light Co 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 memorandum & order UCB 771104 patition sought action re fire protection for electrical cables EIBENMANT, D O Division of Licensing 80/06/25 87pp
- H Qeneral correspondence
- 8007020198 Responds to 800516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Drunswick no threat to public DIRCKS W J Office of the Executive Director for Operations 80/06/18 2pp
- --- HOO7020217 Requests response to encl Mudio Alliance 800512 ltr commenting on ability of util to safely utilize nuclear power ANDREWS, I House of Rep 80/05/16 2pp
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8007170366 Forwards FSAR.Vols i~20.amended OL application & environ rept for OL stage Only FSAR encl JONES.J A Carolina Power & Light Cr 80/06/26 3pp
- G007170372 Chapter 1 to Bhoaron Harris 1,2,3 & 4 FSAR, "Introduction & Gameral Description of Plant" # Caroline Power & Light Co 80/06/26 500pp
- 8007170541 Chapter 3 to Shearnn Harris 1.2.3 & 4 FSAR, "Design of Structures, Components, Equipment & Sys "

 * Caroline Power & Light Co 80/06/26 700pp
- E007170378 Chapter 5 to Shearon Harris i.2.3 & 4 FSAR, "RCS & Connected Sys " " Carolina Power & Light Co 80/06/26 175pp
- 8007170394 Chapter 6 to Sheeron Harris 1.2.3 & 4 FSAR, "Engineered Macatu Features"
- Safety Features " # Carolina Power & Light Co 80/06/26 650pp
- 8007170600 Chapter 7 to Shearon Harris 1,2,3 & 4 FSAR, "Instrumentation & Controls " # Carolina Power & Light Co 80/06/26 500pp
- 8007170615 Chapter B to Shearon Harris i.2.3 & 4 FSAR, "Electric Power." * Carolina Power & Light Co BO/06/26 i25pp
- 8007170627 Chapter 9 to Shearon Harris 1,2.3 & 4 FBAR, "Auxiliary Sys" * Carolina Power & Light Co 80/06/26 700pp
- B007170643 Chapter 10 to Shearon Harris 1.2.3 & 4 FSAR, "Steam & Power Conversion Sys "
 # Carolina Power & Light Co 80/06/26 i5Opp
- 8007170650 Chapter 11 to Shearon Harris 1,2,3 & 4 FBAR, "Radwaste Mgt "
 4 Caroline Power & Light Co 80/06/26 175pp
- 8007170655 Chapter 12 to Shearon Harris 1,2,3 & 4 FSAR, "Radiation Protection." * Carolina Power & Light Co B0/06/26 200pp

- BOO7170661 Chapter 13 to Shearon Harris 1, 2, 3 & 4 FSAR, "Conduct of Operations" + Carolina Power & Light Co | BO/06/26 | 250ap
- 8007170672 Chapter 14 to Shearon Harris 1.2.3 & 4 FSAR, "Initial Test Program "
- Program " * Carolina Power & Light Co BO/06/26 75pp
- 8007170677 Chapter 15 to Shearon Harris 1,2,3 & 4 FSAR, "Accident Analysis "
 - # Carolina Power & Light Co 80/05/25 400pp
- 8007170684 Chapter 16 to Bhearon Harris 1.2.3 & 4 FSAR, "Yech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Shearon Harris 1.2,3 & 4 FSAR, "GA" * Carolina Power & Light Co 80/06/26 37pp
- 8007170690 App 1 to Shearon Harris 1,2,3 & 4 FSAR, "TMJ" * Carolina Power & Light Co 80/06/26 37pp
- O Inspection reports. IE Bulletins & correspondence
- B007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY. J P Region 2, Atlanta, Office of the Director B0/05/08
- 8007210422 Forwards IE Circular 80-13. "Orid Strap Damage in Heatinghouse Fuul Assemblios "No written response required, O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28 ip
- G007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergon Faedwater Pumps " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/03/29
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/06/10
- B007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Goolant Pump Stude," No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007250339 Forwards IE Info Notice 80-20, "Prompt Reporting of Info i Accordance W/10CFR50 35(e)" No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/13
- 8007100297 Ack receipt of IE Insp Repts 50-400/80-13, 30-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 No proprietary info HOME.P W Carolina Power & Light Co 80/06/16 ip
- ~-8007100301 Forwards 1E Insp Repts 50-400/80-13.50-401/80-11.
 50-402/80-11 & 50-403/80-11 on 600513-16 & notice of violation MRPHY.C E Region 2. Atlanta, Reactor Construction & Engineerin Bupport Branch 80/06/05 2pp
- --8007100305 Notice of violation from insp on 800513-16
 * Region 3, Chicago, Office of the Director 80/06/05 ip
- --B007100313 IE Insp Repts 50-400/80-17,50-401/80-11.30-402/80-11 & 50-403/80-11 on 800313-16 Noncompliance noted tack welds deposited over heavy rust HERDT. A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, N P Region 2, Atlanta, Office of th Director 80/06/03 9pp
- 8007020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump, Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20 10
- 8007100412 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-11. S0-401/80-08 to 50-402/80-08 to 50-403/80-08 MURPHYC E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/06/23 ip

- -8007100418 Responds to NRC 800513 ltr re violation moted in IE Insp Repts 50-400/80-11,50-401/80-08,50-402/80-08 & 50-403/80-08 Corrective actions investigation held of collected test data re backfill matl affecting Category I piping HDME,P W Carolina Power & Light Co 80/06/05 Spp
- -8007100422 Ack receipt of lE lnsp Repts 50-400/80-11,50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 No proprietary info HDME,P W Carolina Power & Light Co 80/05/22 lp
- -8007100428 Forwards IE Insp Repts 50-400/80-11,50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of violation MURPHY.C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/13 2pp
- -8007100430 Notice of violation from insp on 800422-24 * Region 2, Atlanta, Office of the Director 80/05/12 ip
- -8007100435 IE Insp Repts 50-400/80-11.50-401/80-08.50-402/80-08 & 50-402/80-08 on 800422-24 Noncompliance noted failure to consider effect of backfill settlement analysis of Category I piping CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAMAN.J J Region 2, Atlanta, Office of the Director 80/05/12 App
- 007160800 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " Nu written response required O'REILLY, J P Region 2. Atlants, Office of the Director 80/06/24 is
- J07230220 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 115; & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/5
- J07220210 Responds to IE Bulletin 80-08 Review of containment liner penetratiun weld designs verified by applicable drawings Helds not complete as plant is under const HCDUFFIE.H A Carolina Power & Light Co 80/07/02 2pp
- Periodic operating reports & related correspondence
- 107280507 Forwards "Quarterly Data Rept. Shearon Harris Nuclear Power Plant Monitoring Program. Apr-June. 1980" MCDUFFIE, M. A. Garelina Power & Light Co. 80/07/21 19
- 8007280513 "Quarterly Data Rept. Shearon Harris Nuclear Power Plant Honitoring Program. Apr-June 1980 " * Carolina Power & Light Cn 80/07/21 lp
- Reportable occurrences, LERs & related correspondence
- NOTIAO377 Interim deficiency rept re significant failure of reactor protection sys following main feedline break Westinghouse has indicated corrective action rannot be completed before Dec 1981 Final rept will be issued upon completion CHIANGI.N J Carolina Power & Light Co 80/07/08 ip
- 107230247 Part 21 rept re lack of stud base qualification for angle arc shield Evaluation will be completed by D01001 CHIANGIN J Carolina Power & Light Co 80/07/11 2pp
- Operator Examinations
- 07180428 Requests review & concurrence w/Senior Reactor Operator Cortification program & retraining program per HR Denton 800328 ltr Certification program effective 800630 Retraining effective in 1981 Description of both programs encl COLLINS.J M Carolina Power & Light Co 80/06/23 5pp
- CHET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

 Application/construction stage ducuments & correspondence
- O7020427 Forwards computer magnetic tape of onsite meteorological data supporting FSAR Submitted in format described in DB Vassatle 7908)0 ltr Format description & tape dump of first 55 records encl lape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/06/26 12pp

- 8007170628 Forwards FSAR,Vols 1-20,amended CL application & environ rept for CL stage CL application only encl JONES,J A Carolina Power & Light Co 80/06/26 3pp
- --8007170639 Application for OL Annual financial rept & prospectus encl.
 * Carolina Power & Light Co 80/06/26 99pp
- 8007230001 Forwards statement of policy re requirements to be ast for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D G Division of Licensing 80/06/26 2pp
- 8007150535 Requests clarification of ANSI N45 2 10 as invoked by Reg Ouide 1 74, as to whether or not certificates of conformance, certificates of compliance & certified test repts must contain longhand signature MCDUFFIE, K A Carolina Power & Light Co 80/07/09 1p
- 8007220456 Forwards schedules of const milestones & activities as of 800630 Milestone network schedule will be affected by 800648 revisions in schedule Fuel loading for Units 1 & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs MCDUFFIE,M A Carolina Power & Light Co 80/07/11 13pp
- C Utility Environmental Report (ER), amends & correspondence
- B007170652 Forwards FSAR, Vols 1-20, amended OL application & environ rept for OL stage Environ rept only encl
 JONES, J A Carolina Power & Light Co 80/06/26 3pp
- ---8007170663 Environ rept for facility.Vol 1 * Carolina Power & Light Co 80/06/26 350pp
- --8007170678 Environ rept for facility, Vol 2 * Carolina Power & Light Co 80/06/26 300pp
- --8007170686 Environ rept for facility:Vol 3 * Carolina Power & Light Co 80/06/26 300pp
- F Security, medical, emergency & fire protection plans
- 8007010332 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withhold (ref 10CFR2 790) JDNES, J A Carolins Power & Light Co 80/04/26 2pp
- Q Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 EPpp
- H General correspondence
- 8007020198 Responds to 800516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public. DIRCKS,W J Office of the Executive Director for Operations 80/06/18 2pp
- --8007020217 Requests response to encl Kudzu Alliance 800512 ltr commenting on ability of util to safely utilise nuclear power ANDREWS, I House of Rep 80/05/16 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007170366 Forwards FBAR.Vols 1~20.amended CL application & environ rept for OL stage Only FBAR encl
 JDNES.J A Carolina Power & Light Co 80/06/26 3pp
- --80071703A7 F8AR, Vols 1-20 * Carolina Power & Light Ca 80/06/26 7800pp
- 8007170372 Chapter 1 to Shearon Harris 1.2.3 & 4 FSAR. "Introduction & General Description of Plant"

 * Carolina Power & Light Co 80/05/26 500pp
- B007170377 Chapter 2 to Shearon Harris 1,2,3 & 4 FBAR, "Site Characteristics" * Capolina Pour & Light Co 80/05/26 700pp

- 6867170341 Chapter 3 to Shearon Harris 1,2,3 & 4 FSAR, "Design of Structures: Components: Equipment & Bys " & Carolina Power & Light Co 80/06/26 700pp
- 8007170572 Chapter 4 to Shearon Harris 1,2,3 & 4 FSAR, "Reactor " a Carolina Power & Light Co 80/06/26 200pp
- B007170578 Chapter 5 to Shearon Harris 1,2,3 & 4 FSAR, "RCS & Connected Sys "
 * Carolina Power & Light Co 80/05/26 175pp
- B007170594 Chapter 6 to Shearon Harris 1.2.3 & 4 FSAR. "Engineered Safety Features " # Caroline Power & Light Co 90/06/26 650pp
- 8007170600 Chapter 7 to Shearon Harris 1.2.3 & 4 FSAR.
 "Instrumentation & Controls"
 # Carolina Power & Light Co 80/06/26 500pp
- BO07170615 Chapter 8 to Shearon Harris 1,2,3 & 4 FSAR, "Electric Fower" Cerolina Power & Light Co 80/06/26 125pp
- 8007170627 Chapter 9 to Shearon Harris 1,2,3 & 4 FBAR, "Auxiliary Sys" * Carolina Fower & Light Co 80/06/26 700pp
- 9007170643 Chapter 10 to Shearon Harris 1,2,3 & 4 FSAR, "Steam & Power Conversion Sys " * Carolina Power & Light Co 80/06/26 150pp
- B007170650 Chapter 11 to Shearon Harris 1.2.3 & 4 FSAR. "Radwaste Mgt "
 * Carolina Power & Light Co B0/06/26 175pp
- 8007170661 Chapter 13 to Bhearon Harris 1,2,3 & 4 FSAR. "Conduct of Operations" Carolina Power & Light Co 80/04/26 250pp
- 8007170672 Chapter 14 to Shearon Herris 1, 2, 3 & 4 FSAR, "Initial Test Program"

 * Carolina Power & Light Co 80/06/26 75pp.
- 8007170677 Chapter 15 to Shearon Harris 1,2,3 & 4 FSAR. "Accident Analysis." * Carolina Power & Light Co 80/06/26 400pp
- 8007170684 Chapter 16 to Shearon Harris 1, 2, 3 & 4 FBAR. "Tech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Bhearon Harris 1, 2, 3 & 4 FSAR. "QA " * Carolina Power & Light Co 80/06/26 37pp

Q Inspection reports, IE Bulletine & correspondence

- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i Hhile in Refueling Mode "No response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/05/08 2pp.
- 8007210422 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/28 ip.
- 6007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required, O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/10

- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Rosetor Coolant Pump Study " No specific action or response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 60/06/11 in
- 8007250339 Forwards IE Info Hotice 80-20, "Prompt Reporting of Info in Accordance W/10CFR90 53(e)" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/33 2pp
- 8007100297 Ack receipt of IE Innp Repts 50 400/80-13.40-401/80-11. 50-402/80-11 & 50-403/80-11 on 800313-16 No proprietary info MOME.P W Caroline Power & Light Co 80/06/16 Lp
- --8007100301 Forwards IF Insp Repts 50-400/80-1.3, 50-401/80-11. 30-402/80-11 & 50-403/80-11 on 1000517-16 & notice of violation MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Dranch 80/06/07 Sup
- ---8007100305 Notice of violation from inop on 800513-14
 * Region 3, Chicago, Office of the Director 80/06/09 ip
- ---8007100313 IE Insp Repts 50-400/R0-13.50-401/R0-11.50-402/R0 11 & 50-403/R0-11 on 800513-16 Noncompliance noted took wolds deposited ever heavy rust HERDT.A R Region 2. Atlanta. Reactor Construction * Engineering Support Branch KLEINBORGE W P Region 2. Atlanta. Office of the Director 80706/05 9pp
- B007020440 Forwards lE Circular H0-15, "Loss of Reactor (volant Pump Cooling & Natural Circulation Cuoldows " No written responso required U-REILLY, J.P. Region 2, Atlanta, Office of the Director H0/06/20
- B007100412 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-11. 50-401/80-08, 50-402/80-08 & 50-403/80-08 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/23 ip
- ---BOD710041B Responds to NRC BOP513 lir re violation noted in It Insp Repts 50-4007B0-11; 50-4017G0-08; 50-4027B0-08; 50-4037B0-08 Corrective actions investigation held of collected test data re backfill math affecting Category I piping HOME, P.W. Carolina Power & Light Co. 80706705 Tap
- --8007100422 Ack receipt of IC Insp Repts 50-400/80 11.50-401/80 08. 50-402/80-08 & 50-403/80-08 on 800422-24 No proprietary info HOME.F W Carolina Power & Light Go 80/05/20 1p
- --8007100428 Forwards TE Insp Repts 50-400/80-11, %-401/80-08, 50-402/80-08 & 40-403/80-08 on 8004P2-24 & notice of violation MDBPHY.C E Region 2, Atlanta, Reactor Construction & ingineering Support Branch 80/05/13 Pp
- --8007100430 Notice of violation from insp on 600422 24
 * Region 2, Atlanta, Office of the Director (07097/2) in
- --8007100435 IE Insp Rupts 50-400/80-11:00 401/H0 (H, 90-402/80 00 & 50-403/80-00 on 800422-24 Noncompliance hated failure to consider effect of hackfill settlement analysis of (ategory I piping CONLONIT C Region 2. Atlanta, Reactor (antivetion & Engineering Support Branch LENAHAN, J.) Region 2. Atlanta, Office of the Director 80/05/12 App
- 8007160800 Forwards IE Circular 80-14 "Radium tive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REFLLY, J.P. Region 2, Atlanta, Office of the Director 80/0%/24
- 8007230220 Forwards 1E Bulletin 60-14. "Putintial disapplication of Resembling Models 1151 & 1152 Pressure Transmitters, W/Either A or D Butput Codes," Whitten response required IE Circular 80-16 also until No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 60/06/27
- 9007220210 Responds to IC Dullotin 80-00 Review of containment liner penetration weld designs verified by applicable drawings Welds not complete as plant is under const MCDUFFIC.H A Carolina Power & Light Co. 80/0//02 Ppp

eriodic operating reports % related correspondence

280907 Forwards "Quarterly Data Rupt.Shearon Harris Nuclear Power ant Monitoring Program.Apr-June.1980" DUFFIE.M A Carolina Power & Light Cu 80/07/21 ip

00/280513 "Guarterly Data Rept.Shearon Hairis Nuclear Power Plant Monitoring Program Apr-June 1980 " * Carolina Power & Light Co 80/07/21 ip

leportable accurrences. LERs & related correspondence

716037/ Interim duficiency rept re significant failure of reactor retection sys following main feedling break Westinghouse is indicated corrective action cannot be completed before to 1981 Final rept will be issued upon completion HANGI,N J. Carolina fower & Light Co. 80/07/08 ip

7230247 Part 21 rept re lack of stud base qualification for angle c shield Evaluation will be completed by 801001 HANGLAN J Carolina Power & Light Co 80707/11 2pp

lperator Examinations

/190428 Requests review & concurrence w/Senior Reactor Operator settification program % retraining program per HR Denton DOSED ltr Certification program effective BOOGSO Retraining Pective in 1981 Description of both programs encl DLLINS.J H Carolina Power & Light Co 80/04/23 5pp

ET 50-403 BHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 4 pplication/construction stage documents & correspondence

702042/ Forwards computer magnetic tape of onsite meteorological ta supporting FSAR Submitted in Format described in 4 Vasatin 790810 ltr Format description & tape dump of rat 65 records encl Tape available in Central Files only TDUFFIF.M A Carolina Power & Light Co 80/06/26 12pp

170A28 Forwards F8AR.Vols 1-20.amended OL application & onviron of for OL stage OL application only encl NES.J A Carolina Power & Light Co 80/06/26 3pp

107170639 Application for DL Annual Financial rept & prospectus encl * Carolina Power & Light Co = 80/05/26 = 99pp

23000) Forwards statement of policy re requirements to be met for rent OL applications as derived from NUREG-0660 & found NUREG-0674

ERNIUT, D O Division of Licensing BD/06/26 2pp

1905.39 Requests clarification of ANSI N45 2 10 as invoked by Reg vido 1 74,as to whether or not cortificates of conformance, prificates of compliance & certified test repts must suitain langhand signature PUFFIF.M A Coroline Power & Light Co 80/07/09 1p

/220456 Forwards schodules of const milestones & activities as of 10630 Milestone network schedule will be affected by 800618 sylvisions in schedule Foel loading for Units 1 & 2 will be slaged 1 yr & Units 3 & 4 delayed 3 yrs
DUFFIF.M A Carolina Power & Light Co 80/07/11 13pp

Itility Environmental Report (ER), amonds 4 correspondence

AR. Vols 1-20. amended GL application & environ viron rept only and er & Light Co 60/06/26 3pp

r facility, Vol 1

F Security, medical, emergency & fire protection plans

8007010352 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withhold (ref 10CFR2 790)

JGNES: J A Carolina Power & Light Co 80/06/26 2pp

9 Adjudicatory correspondence

8007310243 Forwards Commission 800327 memorandum & order centaining decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp

H General correspondence

B00702019B Responds to B00516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public DIRCKS.H J Office of the Executive Director for Operations B0/06/18 2pp

--8007020217 Requests response to encl Kudzu Alliance 800512 ltr communting on ability of util to safely utilize nuclear power ANDREWS, I House of Rep 80/09/16 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

B007170366 Forwards FSAR.Vols i-20.amended OL application & environ rept for OL stage Only FSAR encl
JONES, J.A. Carolina Power & Light Co. B0/06/26 3pp

---B007170367 FSAR.Vols 1-20 4 Carolina Power & Light Co 80/06/26 7800pp

B0071703/2 Chapter 1 to Shearon Harris 1,2,3 & 4 FSAR. "Interduction & General Description of Plant" + Carolina Power & Light Co B0/06/26 500pp

8007170377 Chapter 2 to Shearon Harris 1.2.3 & 4 FSAR. "Site Characteristics" * Carolina Power & Light Co BD/06/26 700pp

8007170541 Chapter 3 to Shearon Harris 1,2,3 & 4 FSAR. "Design of Structures. Components. Equipment & Sys " * Carolina Power & Light Co 80/06/26 700pp

8007170372 Chapter 4 to Shearon Harris 1.2.3 & 4 FSAR, "Reactor" + Carolina Power & Light Co 80/06/26 200pp

8007170578 Chapter 5 to Shearon Harris 1,2,3 & 4 FBAR, "RCS & Connected Sys " # Carolina Power & Light Co 80/06/26 175pp

BOO7170394 Chapter 6 to Shearon Harris 1.2.3 & 4 FSAR, "Engineered Bafety Features" * Carolina Power & Light Co BO/06/26 650pp

8007170600 Chapter 7 to Shearon Harris 1.2.3 & 4 FBAR, "Instrumentation & Controls "

* Carolina Power & Light Co 80/06/26 500pp

8007170615 Chapter 8 to Shearon Harris 1,2,3 & 4 FSAR. "Electric * Carolina Power & Light Co 80/04/24 125pp

B007170627 Chapter 9 to Shearon Harris 1.2.3 & 4 FSAR, "Auxiliary Sys" * Carolina Power & Light Co B0/06/26 700pp

8007170643 Chapter 10 to Shearon Harris 1.2.3 & 4 FSAR. "Steam & Power Conversion Sys " * Garolina Power & Light Co BO/06/26 150pp

8007170650 Chapter 11 to Shearon Harris 1,2,3 & 4 FSAR, "Radwaste Mgt " * Carolina Power & Light Co 80/06/26 175pp

8007170655 Chapter 12 to Shearon Harris 1,2,3 & 4 FSAR, "Radiation Protection "
* Carolina Power & Light Co 80/06/26 200pp

- 8007170661 Chapter 13 to Shearon Harris 1.2.3 & 4 FSAR: "Conduct of Operations" + Carplina Power & Light Co 80/06/26 230pp
- B007170672 Chapter 14 to Shearon Harris 1.2.3 & 4 FSAR, "Initial Test Program" # Carolina Power & Light Co B0/06/26 75pp
- 8007170677 Chapter 15 to Shearon Harris 1,2,3 & 4 FBAR, "Accident Analysis"

 Can Jina Power & Light Co 80/06/26 400pp
- 8007170694 Chapter 16 to Shearon Harris 1.2.3 & 4 FSAR: "Tech Specs " * Carolina Power & Light Co 80/06/26 500pp
- 8007170690 App 1 to Bhearon Harris 1.2,3 & 4 FBAR, "TM1 " # Carolina Power & Light Co 80/06/26 37pp
- Q Inspection reports: IE Bulletins & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode"
 No response required
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
 2pg
- 8007210422 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 lp.
- 8007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/05/29 is.
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/10.2nm.
- B007160223 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs." No specific action or response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/04/11
- B007250339 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required D'REILLY, y P Region 2, Atlanta, Diffice of the Director 80/06/13 2ab
- B007100297 Ack receipt of IE Insp Repts 50~400/80-13,50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 No proprietary info. HOME, P.W. Carolina Power & Light Co 80/06/16 ip
- --8007100301 Forwards IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 & notice of violation MARPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Rupport Branch 80/06/05 2pp
- ---8007100313 IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 Noncompliance noted tack welds deposited over heavy rust HERDTA R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/06/05 9pp.
- 8007020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- B007100412 Ack receipt of B00605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-11, 50-401/80-09, 50-402/80-09 & 50-403/80-09 MRRPHY, C.E. Region 2, Allanta, Reactor Construction & Engineering Bupport Branch 80/06/23 ip

- --B007100418 Responds to NRC B00513 ltr re violations noted in 1E Repts 50-400/B0-11.50-401/B0-08.50-402/B0-08 & 50-403/B0-08 Corrective actions investigation held of collected test data re backfill math affecting Category I piping HOWE,P W Carolina Power & Light Co B0/06/05 3pp
- ---8007100422 Ack receipt of 1E Imag Repts 50-400/80-11,50-401/80-00 50-402/80-00 % 50-403/80-00 on 800422-24 No proprietary info HOWE,P W Corolina Power & Light Co 80/05/22 ip
- --8007100428 Forwards IE Inap Repts 50-400/80-11.50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of violation HURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineer Support Branch 80/05/13 2pp
- --8007100430 Notice of violation from insp on 800422-24
 * Region 2. Atlanta, Office of the Director 80/05/12 ip
- --8007100435 IE Insp Repts 50-400/80-51.50-401/80-08.50-402/80-08 on 800422-24 Nancompliance moted failure to consider offect of backfill settlement analysis of Category I piping COMLON: TE Region 2, Atlanta, Reactor Construction & Engineer Support Branch 80/05/12 Spp
- 8007160800 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/06, to
- 8007230220 Forwards IE Bulletin 80-16. "Potential Misapplication o Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta. Défice of the Director 80/06, 1p
- 8007220210 Responds to IE Bulletin 60-08 Review of containment lin penetration weld designs verified by applicable drawings Walds not complete as plant is under const MCDUFFIE.H A Carolina Power & 1.19ht Co 80/07/02 2pp
- R Periodic operating reports & related correspondence
- 8007280507 Forwards "Guarterly Data Rept,Shearon Harris Nuclear Pol Plant Monitoring Program,Apr-June,1780 " MCDUFFIE.M A Carolina Power & Light Co 80/07/21 ip
- --B007280513 "Quarterly Data Rept. Shearon Harris Nuclear Power Plan Monitoring Program. Apr-June 1980 " * Caroline Power & Light Co 80/07/21 1p
- S Reportable occurrences, LERs & related correspondence
- 8007160377 Interim deficiency rept re significant failure of reacti protection sys following main feedline break Westinghouse has indicated corrective action cannot be completed before Dec 1981 Final rept will be issued upon completion GNIANGIN J Carolina Power & Light Co 80/07/08 1p
- B007230247 Part 21 rept re lack of stud base qualification for anglers shield Evaluation will be completed by B01001 CHIANGLN J Carolina Power & Light Co B0/07/11 2pp
- V Operator Examinations
- 8007180428 Requests review & concurrence w/Benior Reactor Operator Certification program & retraining program per HR Denton 800328 itr Certification program effective 800430 Retraining effective in 1981 Description of both programs encl COLLING.J M Carolina Puwer & Light Co 80/06/23 5pp
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/curstruction stage documents & correspondence
- BOD7230001 Forwards statement of policy re requirements to be a current DL applications, as derived from NUREQ-0560 & found in NUREQ-0594 EISENHUTED 0 Division of Licensing 80/06/26 2pp

8007010363 Responds to NRC 800421 request for info on Category 1 masonry walls Design criteria will be developed utilizing acceptable methodology No masonry walls installed at present BROWN & C Virginia Electric & Power Co 80/06/27 1p

H General correspondence

8007150047 Responds to 800327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants operating & under const & relative costs of coal vs nuclear energy YDUNOBLOGO.B J. Operating Reactors Dranch ! 80/05/13 Spp

J Insurance & indomnity information

8007150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE,D A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/07/10 3pp

@ Inspection reports, IE Bulletins & correspondence

8007240230 Forwards IE Info Nutice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/08

8007210477 Forwards IE Circular 80-13. "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28

8007010239 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 in

8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/06/10 2an

8007160307 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required D'AEILLY, J P Region 2, Atlanta, Office of the Director 80/06/11

80072503B1 Forwards IE Info Notice 80-2B, "Prompt Reporting of Info in Accordance M/10CFR50 55(e) " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/13 208

8007020434 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director GO/04/RO.

8007170119 Forwards IE Circular 80-14, "Redioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 ip

8007230270 Forwards IE Bulletin 80-14. "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director BO/06/27

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0894
 EJERNIUT, D G Division of Licensing 80/06/26 2pp

8007010363 Responds to NRC 800421 request for info on Category 1 masonry walls Design criteria will be developed utilizing acceptable methodology No masonry walls installed at gresent BRCHN, B C Virginia Electric & Power Co 80/06/27 1p

H General correspondence

BOO7150047 Responds to BOO327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants.operating & under const & relative costs of coal vs nuclear energy VOUNCBLOOD.B J Departing Reactors Branch 1 80/05/13 5pp

J Insurance & indemnity information

BOO7150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE,D A Marsh & McLennan,Inc., M & M Nuclear Consultants.Inc. Div BO/07/10 3pp

G Inspection reports, IE Bulletins & correspondence

BOO7240230 Forwards IE info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "
No response required
O'REILLY, J P Region 2, Atlanta, Office of the Director BO/05/08

8007210477 Forwards 1E Circular 80-13, "Grid Strap Damage in Hastinghouse Fuel Assemblies" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 is

8007010237 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/05/29 ip

8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10.

8007160307 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/11

800725038i Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/13

8007020434 Forwards JE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/06/20

8007170119 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director. 80/06/24 10

GOO7230270 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Dutput Codes " Hritten response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/27.

DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

Q Inspection reports. IE Bulletins & correspondence

8007170188 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P. Region 2. Atlanta, Office of the Director 80/06/24

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8007020402 Forwards revised Pages 5-11,-12,-17 & -31 to FES including corrections re occupational radiation exposure CRUTCHFIELD, D Operating Reactors Branch 5 80/06/11 2pp

- ---BO07020411 Revised Pages 5-11,-12,-17 & -31 to FES, including corrections re occupational radiation exposure

 # Operating Reactors Branch 5 80/06/11 5pp
- 8007230574 Requests that addl info on concerns re excessive radioactive releases & inadequacy of dose assessment analysis expressed in DES be included in final ETS info should be available to all participants in review process for project TAYLOR, B J Environmental Protection Agency 80/07/03 2pp
- 8007180337 Submits State of WI Dept of Administration comments on final EI8 for facility Increase in spent fuel assemblies should have received explanation & documentation in final EI8 Description re age of fuel assemblies is unclear NIELSEN, Q.A. Wisconsin, State of 80/07/08 2pp
- F. Security, medical, emergency & fire protection plans
- BOO7170240 Notifies that FEMA/NRC steering committee reconsidered size of emergency planning zone for water cooled reactors of less than 250 fW thermal & adopted encl position Proposed rule & NURED/0654/FEMA-REP-i will be modified in conformance GRUTCHFIELD, D M Operating Reactors Branch 5 BO/06/13 3pp
- BOO7180079 Requests add1 info re fire protection mods, Status of avaluation encl. Response requested within 30 days of receipt of 1tr
 LAINAB.O C Assistant Director for Safety Assessment 80/06/16
- 8007290634 Forwards results of fire protection review re Items 3.1.27 & 3 2 2 on water demand analysis Licenses should be requested to modify high pressure svc water/fire protection water sys to provide protection for turbine lube oil tank HALL: R E Brockhaven Netional Laboratory 80/07/23 3pp

Q Adjudicatory correspondence

- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT. D D Division of Licensing 80/06/25 89pp
- 8007140012 Second prehearing conference order outlining matters discussed re new policy for procedural assistance to intervenors, special circumstances in severe accidents & Goulse Region Energy Coalition presentation on full-term OL BECHROEFER, C Atomic Safety and Licensing Board Panel 60/07/08 App.
- 8007130503 Order granting extension until 800616 for Coulee Region Energy Coalition to respond to interrogatories Supplemental responses must be filed by 800716 & applicant/NRC aummany disposition motions by 800804 Anticipates 800708 prehearing BECH+NDEFER.C. Atomic Safety and Licensing Board Panel 80/07/10 280.
- BOO717036B Response to questions of ASLB 800521 memorandum & order re prohearing conference in full term OL proceeding Addresses offgas emissions discrepancies in FEB, workers' exposure & environ monitoring Affidavit & Certificate of Svc encl BTEELE, T A . HIEBTAND. D. S. Dairyland Power Cooperative 80/07/11
- 8007280656 Forwards supplemental response to NRC interrogatories Related correspondence and HORSE: A Affiliation Unknown 80/07/17 26pp
- ---8007280672 Transcript of D Raphael before Senate Subcommittee on Rural Development RAPHAEL, D Rural America. 79/11/30 11pp.
- ---8007289677 Transcript of DL Ostendorf before House Subcommittee on Conservation & Credit
 OSTENDORF, D. L. Rural America 80/03/19 9pp
- ---B007280694 "Nuclear Waste Time Bomb in Our Bones"
 DIXON. Q A Affiliation Unknown B0/03/25 23ep

- --8007280696 Rept before 39th annual meeting of util LINDER.F Dairyland Power Cooperative 80/06/18 14pg
- 8007310101 Supplemental response to NRC interrogatories Identifies individuals to be called in support of contentions Submits elaborate discussion of radiation effects & energy conservation Affiliation & Centificate of Suc encl MORSE, A.K., NYGAARD, O.R. Affiliation Unknown 80/07/17 19pp
- 8007300428 Motion to file second round of interrogatories directed to Coulee Region Energy Coalition Intervenor lengthy supplemental response to MRC discovery requests will not be adequately addressed unless clarified W/Certificate of Svc WOODHEAD, C.P. Hearing Branch 3 80/07/28 App
- 800731046P Order designating ASLB to consider & rule upon requests for hearing re Dfc of Nuclear Reactor Regulation 800225 order to show cause re dewatering sys Adjudicatory hearing, if determined should be limited to two issues stated in order CHILK-S J Office of the Secretary of the Commission 80/07/29 350

H General correspondence

- 8007140221 Responds to 800320 ltr re licensee withholding of info fram public on reactur operation decisions Licensee not required to provide documents to concerned party since issue is not under litigation
 EISCNHUT.0 G Division of Licensing 80/04/24 5pp
- --8007140227 Expresses displeasure w/licensed withholding of info from public re reactor operation decisions Repeated requests to be included on svc list for correspondence to NRC have been ignored FANTLE.W Couloe Region Energy Coalition 80/03/20 2pp

l Financial information

- 8007310434 Forwards Annual Financial Rept 1979 & certified financial statements for 1978 & 1979
 LINDER:F Dairyland Fower Cooperative 80/07/24 1p
- --8007310443 Annual Financial Rept 1979 Certified financial statements for 1978 & 1979 encl * Dairyland Fower Cooperative 80/05/15 47pp
- P Operating license stage documents & correspondence
- 8007010120 Forwards final rule published in 800309 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUICHFIELD, D Operating Reactors Branch 5 80/06/10 5pp
- 8007100399 Responds to 800229 ltr which expressed opposition to ACR8 recommendation to restructure BEP Role of licensess in program will expand Ltr forwarded to Commissioners DENTUN.HR Defice of Nuclear Reactor Regulation, Director 80/06/18 4pg
- --B007100420 Expresses opposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined. cost in dollars & manpower would increase dramatically SOUAFFSTALL, SEP Owners Group 80/02/29 2pp
- 8007010070 Responds to FOIA request for 57 documents referenced in M Toker memo to ACRS concerning pollot-cladding interaction Forwards documents Missing records are duplicative, superseded or available alsowhere FELTON, J M Division of Rules and Records 80/06/20 2pp
- --80070i0080 Discusses similarities in fuel fod failures for INRs resulting from control blade movements Foilure pattern w/bresden & LACOURF fuel rade was associated w/location of fuel rads relative to control rads
 SIEOGLE L. Atomic Energy Commission, Directorate of Licensing 73/09/20 2pp
- 8007240079 Requests add1 info to continue review of adequacy of station electric distribution sys voltages Response requested within 45 days of receipt of ltr CHUTCHFIELD.D H Operating Reactors Branch 5 80/06/27 4pp
- 8007210638 Forwards "SEP Technical Evaluation Topic VIII-4, Electrical Penetrations of Reactor Containment LACGUR "
 CRUTCHFIELD,D M Operating Reactors Branch 5 80/07/01 2pp

- --B007210640 "SEP Trebbical Evaluation Topic VIII-4, Electrical Penetrations of Reactor Containment LACDHR" Operating Reactors Branch 5 80/07/01 App
- 8007080300 Forwards drawings providing additinfolie safe shutdown, requested by NRC 800610 telecopy
 SHIMSHAK.R Dairyland Power Cooperative 80/07/02 3pp
- --8007080305 Requests drawings or diagrams re-safe shutdown by 800707 NAYS, 9 Commission 80/06/10 2pp
- 8007140305 Notifies that Item i of TMI Lessons Learned requirements was not forwarded w/NRC 800507 Itr t has not yet been received LINDER.F Dairyland Power Cooperative 80/07/07 ip
- 8007210447 Forwards review of RCS pressure boundary stainless steel piping & fitting matl LINDER.F Dairyland Power Cooperative 80/07/10 18pp
- BOO72B0190 Forwards NRC evaluation of SEP Topics Ill-10 A.V-11 A.VI-7 C 1 & III-3 D Evaluations will be basic inputs to integrated wherety assessments unless changes are needed to reflect as-built conditions CRUTCHFIELD.D Operating Reactors Branch 5 BO/07/10 iSpp
- 8007220525 Forwards "Response to NRC Review Questions" re util answer to BOO325 order to show cause LINDER,F Doiryland Power Cooperative BO/07/14 Ppp
- --BO07220526 "Response to NRC Review Questions." prepared for util SINGH-H Dames & Moore BO/07/11 74pp
- BOO72BOO76 Responds to BOO318 ltr to J Ahearne objecting on behalf of numers of plants under EEP review, to current plans for expensited review of environ qualification of electrical equipment Forwards applicable memorandum to order DENTON, N R Office of Nuclear Reactor Regulation, Director 4рр 80/07/16
- ← Inspection reports, iL Bulletins & correspondence
- B007140523 Forwards IE Builetin B0-13, "Cracking in Core Spray Spargers " Hritten response required KEPPLER,J & Region 3, Chicago, Office of the Director 80/05/12
- B007020058 Forwards IE Info Notice 80-22, "Bleakdowns In Contemination Control Programs" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/28
- 8007010112 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J C Region 3. Chicago, Diffice of the Director 80/05/29
- BOO7020679 Submits further response to IF Builetin 80-07, "BHR Jet Pump Assembly Failure" LINDER:F Dairyland Power Cooperative 80/06/02 ip
- 007100085 Forwards IE Insp Rept 50-409/79-24 on /91227-28 No noncompliance noted

 DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/06/05 2pp
- --8007100087 IE insp Rept 50-409/79-24 on 791227-28 No noncompliance noted Major areas inspected licensee actions per IE Bulletin 77-19 re packaging of low lovei radwoste for transport & ourial
 FIEHER.W L Region 3. Chicago, Fuei Facility & Materials Safety
 Branch OREGER.L R Region 3. Chicago, Dffice of the Director
 80/06/03 4pp
- 9007220195 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/10
- 0007140571 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 8A-312.Type 394 Stainless Steel Pipe " Np A-312 stainless steel fusion walded piping is in use in safety-related piping at facility LINDER.F Dairyland Power Copperative 80/06/13 2pp

- 8007i80355 Responds to IE Bulletin 80-08, "Examination of Containment Linur Penetration Welds "Facility has no containment penetrations utilizing flued hood design Three penetrations w/containment boundary but welds used LINDER.F Dairyland Power Compensative 80/06/13 3pp
- 8007030032 Forwards IE Bulletin 80-15. "Possible Loss of Emerypncy Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/ Region 3, Chicago, Office of the Director 80/06/18
- 8007020378 Forwards IE Circular 80-i5. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLERN J G Region 3, Chicago, Office of the Director 80/06/20
- 8007180362 Responds to IE Bulletin 80-06, "Engineered Safety Frature (ESF) Reset Controls " Safety-related functions noted to reset upon removal of actuating signal listed in encl App A, w/proposed mods defined LINDER, F Dairyland Power Cooperative 80/06/20 5pp
- 8007170479 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/24
- 8007180072 Responds to IE Dulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Emergency notification sys is powered offsite from reliable power supply bocked by batteries & diesel generator LINDER.F Dairyland Power Cooperative 80/06/25 2pp
- 8007230320 Forwards 1E Dulletin 80-16, "Potential Misapplication of Rosemount Int Models ii5i & ii52 Pressure Transmitters W/Elther A or D Output Codes " Hritten response required IE Circular 80-16 also enel No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/27
- B007220096 Submits reply to IE Bulletin B0-16 re misappiication of certain Rosemount pressure transmitters Transmitters are not used in safety-related or other circuits
 LINDER:F Dairyland Power Cooperative 80/07/09 ip
- 8007280050 Responds to IE Bulletin 80-10 re contamination of nonradicactive sys & resulting potential for unmonitored, uncontrolled release of radicactivity to environ Instrument air used in containment bidg is protected by check valves LINDER:F Dairyland Power Cooperative 80/07/ii App
- 8007270480 Responds to IE Bulletin 80-ii LACBUR containment bldg has no masonry walls Four identified in turbine bldg No 89E established No separate masonry walls re-evaluation planned at present Evaluation will be part of SEP LINDER.F Dairyland Power Cooperative 80/07/i6 3pp
- 8007300244 Verifies that action specified in util 800711 ltr rm item 2 of IE Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored.Uncontrolled Release of Radioactivity to Environ." completed on 800714
 LINDER.F Dairyland Power Cooperative 80/07/18 ip
- R Periodic operating reports & related correspondence
- B007i60677 Forwards monthly operating rept for June 1980 LINDER.F Dairyland Power Cooperative 80/07/08 ip
- --8007i60681 Monthly operating rept for June 1980 GDDDMAN, L B Dairyland Power Cooperative 8 80/07/07
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT R A Application/construction stage documents & correspondence
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls I-3. "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj. to certain constraints MATYSON.R J Division of Safety Technology 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0860 & found in NUREG-0874 EISENHUT, D.G. Division of Licensing 80/06/26 2pp

- EOO7080337 Responds to SA Varga 800421 request for info on Category 1 mssonry walls Concrete masonry walls will not be used in Category I structures
 RHODE, Q K Nlagara Mohawk Power Corp 80/07/02 ip
- 8007230521 Summary of 800512 meeting w/Mark II owners group in Bethesda, MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON, C. J. Generic Issues Branch 80/07/03 57pp
- 6007180520 Forwards request for addl info re geologic investigation of site
 YDUNGBLOOD, B J Licensing Branch 1 80/07/09 500
- GOO7210624 Bummary of 800610 meeting w/util in Bethesda,MD re welding defects in biological shield wall RIPER.K L Licensing Branch I 80/07/09 5pp
- 8007250472 Informs of util schedule for setting biological shield wall & reactor pressure vessel Biological shield wall setting mcheduled for 800728-0829 & reactor pressure vessel for LEMPGES, T E Niagara Mohawk Power Corp 60/07/18 1p
- GOO7250175 Notification of GOOBO5 meeting w/representatives from Mark II owners group in Chicago, IL to discuss lead Mark II plants chungging & C/O load specs ANDERBON. C Generic Issues Branch 80/07/23 Zpp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEN#UT, D Q Division of Licensing 80/06/25 89pp
- I. Financial information
 - BOO7280275 Forwards util Annual Financial Rept for 1979. LEMPGEB.T E Niagara Mohawk Power Corp BO/07/22
 - H Antitrust correspondence
- BOO7290533 Response in opposition to City of Cleveland, DH 800609 request for hearing re Director of Nuclear Reactor Regulation 800513 order Filing, requesting tariff w/FERC, brings controversy to end w/o litigous course REYNOLDS, W B , ZAHLER, R.E. Cleveland Electric Illuminating Co REYNOLDS, W B Shaw, Pittman, Potts & Trowbridge 80/07/25 9pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007140459 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required ORIER.B H. Region i. Philadelphia. Office of the Director. BO/03/12 ip
- 8007210201 Forwards IE Insp Rept 50-410/80-02 on 800319-21 & 0410-11, No noncompliance noted GARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/03 2pp
- ---B007210209 IE Insp Rept 50-410/80-02 on 800319-21 & 0410-i1 No noncompliance noted. Major areas inspected reactor pressure vessel internals storage, biological shield wall status & plant insp tours

 CERNE, A. C. MCBREARTY, R. A. Region I, Philadelphia, Office of the

 Director MCGAUGHY, R. W. Region I, Philadelphia, Reactor

 Construction & Engineering Support Branch 80/05/07 9pp
- 8007020302 Requests add1 info re actions taken to preclude occurrence of cracking described in IB Bulletin 80-07 Also requests commitment to adopt whatever long-term solution is approved TEDESGO.R L Assistant Director for Licensing. 80/06/10. 2pp
- BOO7210590 Forwards IE Info Notice 80-26: "Evaluation of Contractor GA Programs " No written response required QRIER.B H Region i, Philadelphia, Office of the Director. BO/66/10 ip
- B007i40264 Forwards IE Bulletin 80-14, "Dagradation of BWR Stram Discharge Vol Capability " No written response required. GRIER,B H Region i, Philadelphia, Office of the Director 80/06/12. 1p

- 8007180552 Forwards IE Insp Rept 50-410/80-03 on 800424 No CARLSON,R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- --B007180561 IE Insp Rept 50-410/80-03 on 800424 No moncompliance noted Major areas inspected reactor bldg.primary containment turbine bldg.water intake structure area & area of ground fault Fault CERNE,A C . FEIL,R A Region i. Philadelphia. Office of the Director MCGAUGHY,R W Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/09 2pp
- B007280603 Forwards 1E Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/06/13 ip
- 800702051i Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1, Philadelphia, Uffice of the Director 80/04/20 ip
- 8007160717 Forwards IE Circular 80-14, "Redicactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- 8007210210 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/06/25 ip
- 8007230151 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- B Reportable occurrences, LERs & related correspondence
- B007020111 Ack receipt of B00512 ltr forwarding interim deficiency rept re environ & seismic qualification of electrical aquipment Rept will be reviewed & evaluated CARLSON: R T Region 1. Philadulphia. Office of the Director B0/05/30 ip
- B007020004 Forwards summary of 800507 meeting re biological shield wall weld defect problem Util was informed that NRC would conduct insp on B00512 to review work in progress CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/03 3pp
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREQ-0660 % found in NUREQ-0694
 EISENHUT, D @ Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT.D O Division of Licensing 80/06/25 87pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007010294 Forwards IE Info Notice 80-23, "Loss of Suttion to Emergency Feedwater Pumps " No written response required GRIER,B H Region i, Philadelphia, Office of the Director 80/08/29 ip
- 8007210563 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required GRIER.B.H Region 1. Philadelphia, Office of the Director 80/06/10 | 1p

- 8007160345 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/13
- 8007280581 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accurdance WiCCTR50 55(e) " No written tesponse required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/19 1p
- GUO71BOO39 Responds to 1E Bulletin HO-09 "Hydramotor Actuator Deficiencies " Dumpers w/ITT General Controls NH-90 actuators purchased but not shipped Vendors re-evaluating selections & will restify that steel is Type 1060-1070 WOGLEVER.C J Duquesne Light to BO/06/17 2pp
- 8007020504 Forwards IE Circular 80-15, "Loss of Reactor Coplant Pump Cooling & Natural Circulation Conldown" No written response required ORIER, B H Region 1, Philodelphia, Office of the Director 80/06/20 to
- 8007160673 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER. II H Region L. Philadelphia. Office of the Director 80/06/24 | 1p
- BOO701034B Responds to NRC 000327 ltr re violation noted in IE Insp Rept 50-412/80 04 Corrective actions nine welds were reradingraphed & manually processed Machine will not be utilized on film applicable to ASME Section III welds MOOLEVER.E J Duquesne Light Co 80/06/25 6pp
- 8007210178 Ferwards IE 1nfo Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required ORIER, D II Region i. Philadelphia, Office of the Director 80/06/25 1p
- 8007230115 Forwards 16 Dullotin 80-15, "Potential Misapplication of Rosemount Inc Models 151 & 1152 Pressure Transmitters H/Cither A or D Uutput Codes " Written response required 16 Circular 80-16 alon oncl No written response required ORIER, B | Region 1, Philadelphia, Dffice of the Director 80/06/2/ 2pp
- BOO/210016 Responds to IF Sulictin 79-03A re iongitudinal weld defects in ASME SA-312 type stainless steel Pipe 304 Piping sys is subj to design stresses greater than 85% of allowance No action required MODLEVER, E. J. Duqueene Light Co. 80/07/07 ip
- A Periodic operating reports & related correspondence
- 8007290840 Enrwards magnetic tape containing mateorological data for 1979 Tape available at hydrology-Metorology Branch only StEBFR. J D Duquesne Light (o 80/07/21 Spp
- B Reportable occurrences, LERs & related correspondence
- 0007010459 Supplement 3 to Part PI rept re failed thrust bearing Insp complete Crankshaft thrust bearings on two diesel generators are free of reported potential defect MGRIARTY, J II Colt Industries, Inc., Fairbonks Horse Engine Div. 80/06/26 Ip
- BOO7180534 Ack receipt of BO0521 final deficiency rept re crane wall reinforcing steel NRC has no further questions CARLBON,R T Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch BO/06/27 ip
- B007270050 Ack receipt of B00616 final deficiency rept re weld discrepancies in reactor vessel support structure CARLSON, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/07/07 ip
- BOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- NOO7010186 Advises of reorganization of Ofc of Nuclear Reactor Regulation effective 800428 Mpt of all licensing matters for facility has been assigned to J Matore Organizational description and TEOESGQ,R L. Assistant Director for Licensing 60/06/13 1ipp

- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D 0 Division of Licensing 80/06/26 2pp
- BOO7030185 Forwards application for amend to CPPR-116 consisting of addition of to-owners & co-applicants
 PORTER.W L Duke Power Co 80/07/01 3pp
- ~~8007030189 Application for amend to CPPR-116 re sale of 56.25% undivided ownership in Unit i & 28 15% interest of support facilities to NC Electric Membership Corp & 18 75% undivided ownership to Baluda River Electric Cooperative DAILLE C Dute Power Co HUBDARD, J M North Carolina Muncipally Owned Electric Systems Association 80/07/01 45pp
- 6007210476 Forwards revised application for amend to CPPR-116 adding co-numbers & co-applicants PORTER.W L Duke Power Go 80/07/14 ip
- --8007210486 Rovised application for amend to CPPR-116 adding NC Electric
 Membership Corp & Saluda River Electric Cooperative, Inc. as
 co-coupers & co-applicants
 DAIL, L C Duke Power Co HUBBARD, J M North Carolina Electric
 Membership Corp FARIS, H M Saluda River Electric
 Cooperative, Inc 80/07/01 ,17pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorendum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorendum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/25 87pp
- M Antitrust correspondence
- BOO7160607 Forwards info requested by Atty General re util BOO701 application for CP amend adding co-owners & co-applicants Antitruot advice per Atomic Energy Act requested Wo soci BHAPAR.H & Office of the Executive Logal Director GO/07/11 1
- O Inspection reports, IE Bulletins & correspondence
- 8007240122 forwards 1E 1nfo Notice 80-20, "Loss of Decay Heat Removal Capability at Dovis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J P Region 2, Atianta, Office of the Director 80/05/08
- 0007020204 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007210449 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 is.
- 8007010213 Forwards 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/05/29 ip
- 000722004B Forwards IE Info Notice 80~26. "Evaluation of Contractor OA Programs" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director BO/06/10 2pp
- B007160255 Forwards IE Info Notice 80-27, "Degradation of Heactor Coolant Pump Stude " No specific action or response required G'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/11.
- 8007230344 Forwards IE Info Notice 80-28, "Frompt Reporting of Info in Accordance W/10CFR30 55(e)" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- 8007020459 Forwards IE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/20

- 9007100417 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-05 & 50-414/80-05 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering
- Bupport Branch 80/06/23
- -BOO7100419 Responds to NRC 800505 ltr re violations noted in IE Insp. Repts 50-413/80-05 & 50-414/80-05 Corrective actions individual cited in insp. rept has met all requirements for Level 2 & has been so certified PARKER. W. D. Duke Power Co. 80/05/28 3pp
- -8007100423 Forwards IE Insp Repts 50-413/80-05 & 50-414/80-05 on 800305-31 & notice of violation MRRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/05 2pp
- ***B007100426 Notice of violation from insp on 800309-31 * Region 2, Atlanta, Office of the Director B0/0 BO/04/05 2pp
- -B007100432 IE Insp Repts 50-413/B0-05 & 50-414/B0-05 on B00305-31
 Roncompliance noted failure to provide adequate procedure
 for rigging near Class IE equipment & failure to follow
 drawing requirements
 MAXNELL-0 F Region 2. Atlanta, Office of the Director
 RAUSCH, J K Region 2. Atlanta, Reactor Construction & Engineering
 Bupport Branch B0/05/05 1ipp
- BO07170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY,J.P Region 2, Atlanta, Office of the Director 80/06/2-80/05/24
- 9007230235 Forwards IE Bulletin 80-16, "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/2 80/06/27
- B007210261 Responds to IE Bullotin 80-08, "Examination of Containment Liner Penetration Welds " Welds in 13 penetrations repaired as result of nondestructive examination Summary of typos & sizes of penetrations encl PARKER, W.O. Duke Power Co. 80/07/07 7pp
- 9. Reportable occurrences. LERs & related correspondence
- BOO7020537 Deficiency rept re faulty connections in electrical equipment As described in BOO201 Deficiency Rept BD 413-414/80-01,all Unit i safety-related motor control ctrequipment has been inspected & necessary mods completed PARKER, W O Duke Power Co BO/06/18 1p
- 8007160514 Forwards deficiency rept re rejectable indications in welding of containment vessel equipment hatch PARKER, N. O Duke Power Co 80/07/11, 1p
- -BOO7160518 Deficiency rept re rejectable indications in welding of containment vessel equipment hatch Rejectable weld areas ground out & weld repaired per approved procedures Repaired areas examined & found acceptable on 800611 m Duke Power Co 80/07/11 p
- 9007280501 Significant deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture, initially reported 800617 Inadequate min flow may result in degraded pump performance Hestinghouse reviewing problem PARKER, H O. Duke Power Co 80/07/17 2pp.
- DOCKET 50-414 GATAWBA NUCLEAR STATION: UNIT 2
- A. Application/construction stage documents & correspondence
- 8007010186 Advises of reorganization of Off of Nuclear Reactor Regulation effective 800428 Mgt of all licensing matters for facility has been assigned to J Matore Organizational description encl. TEOESCO,R L. Assistant Director for Licensing. 80/06/13 11pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694 EIBENHAUT, D. O. Division of Licensing 80/06/26 2pp.
- 8007030185 Forwards application for amend to CPPR-il6 consisting of addition of co-owners & co-applicants PDRTER.M.L. Duke Power Co 80/07/01 3pp

- -8007030189 Application for amend to CPPR-116 re sale of 56 25% undivided ownership in Unit 1 & 28 15% interest of support facilities to NC Electric Membership Corp & 18 75% undivided ownership to Saluda River Electric Cooperative DAILLC Duke Power Co HUBBARD.J M North Carolina Muncipally Duned Electric Systems Association 80/07/01 45pp
- B007210474 Forwards revised application for amend to CPPR-114 adding co-owners & co-applicants
 PORTER.W L Duke Power Co B0/07/14 ip
- ~~8007210486 Revised application for amend to CPPR-116 adding NC Electric Membership Corp & Saluda River Electric Cooperative, Inc. as co-country & co-applicants
 DAILL C Duke Power Co HUBBARD. J M North Carolina Electric Membership Corp FARIS.H H Saluda River Electric Cooperative, Inc. 80/07/01 17pp

Q Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 Memorandum % Order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/04/25 87pp
- M Antitrust carrespondence
- BOO7140607 Forwards info requested by Atty General re util BOO701 application for CP amend adding co-owners & co-applicants Antitrust advice per Atomic Energy Act requested W/o encl BHAPAR: H K Office of the Executive Legal Director BO/07/11 80/07/11 1p
- O Inspection reports, 1E Bulletins & carrespondence
- 8007240122 Forwards IE lnfo Notice 80-20, "Lnss of Docay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required C'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- B007210449 Forwards IE Circular 80~13, "Grid Strop Damage in Wastinghouse Fuel Assemblies " No written response required O'REILLY, J P Ragion 2, Atlanta, Office of the Director E BO/05/20
- 8007010213 Forwards 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220048 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/10
- G007140255 Forwards IE Info Notice G0~27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- B007250344 Forwards 1E Info Notice B0-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/13
- 8007020459 forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007100417 Ack receipt of 800528 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-05 & 50-414/80-05 MURPHY.C E Region 2. Atlanta, Reartor Construction & Engineering Support Branch 80/06/23 ip
- ---8007100419 Responds to NRC 800505 ltr re violations noted in IE Insp Rapts 50-413/80-05 & 50-414/80-05 Corrective actions individual cited in insp rept has met all requirements for Level 2 & has been so cortified PARKER, W O Duke Power Co 80/05/28 3pp
- --8007100423 Forwards IE Insp Repts 50-413/80-05 & 50-414/80-05 on 800303-31 & notice of violation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/05 2pp

- --8007100426 Notice of violation from insp on 800305-31
 * Region 2: Atlanta: Office of the Director 80/04/05 2pp
- --B007100432 IE Insp Repts 50-413/B0-05 & 50-414/B0-05 on B00305-31 Noncompliance noted failure to provide adequate procedure for rigging near Class IE equipment & failure to follow drawing requirements MAXWELL.G F Region 2. Atlanta, Office of the Director RAUSCH.J K Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/07 lipp
- 8007170104 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Deminoralised Water Sys & Resultant Internal Contamination of Personnel 'No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 to
- B007230235 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Sutput Codes " Written response required IE Circular 80-16 also ent! No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- E007210261 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds " Welds in 13 penetrations repaired as result of hondestructive examination Summary of types & sizes of penetrations encl PARKER, W O Dute Power Co 80/07/07 7pp
- S Reportable occurrences. LERs & related correspondence
- E007020537 Deficiency rept re faulty connections in electrical equipment As described in 800201 Deficiency Rept ED 413-414/BO-01.all Unit i safety-related mater control ctracquipment has been inspected & necessary mode completed PARKER. W O Duke Pauer Co 80/06/18 ip
- 8007280801 Signsficant deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture, instially reported 800617 Inadequate min flow may result in degraded pump performance Westinghouse reviewing problem PARKER, N O Duke Power Co 80/07/17 2pp
- DUCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

 A Application/construction stage decuments & correspondence
- 8007160810 Forwards correction to fuel load date in 800514 ltr Correct date for Unit 1 is 810831 DALE,L F Mississippi Power & Light Co 80/06/11 lp
- --B0071606i7 Corrects 800514 ltr requesting updated & complete schedule of safety review Correct fuel load date is 810831 DALE, L. F. Mississippi Power & Light Co. 80/05/14 ip
- BOO7010237 Forwards NRC reorganization chart of DPc of Nuclear Reactor Regulation, effective BOO428 Facility activities should be made through assigned mgt representative Areas of disagraement may be discussed through informal appeal TEDESCO.R L. Assistant Director for Licensing 80/06/13 2pp
- EOO7010087 Notification of 800708 meeting w/util, BNML, GE & Bechtel Power Corp in Gaithersburg, ND to review Mechanical Engineering Branch dreft SER HOUGHTON, T C Licensing Branch 3 80/06/16 3pp
- BOO7010100 Notification of 800625 meeting w/util,GE,Bechtel Power Corp & Savannah River Lab in Gaithersburg,MD to discuss FSAR Baction 7. "Instrumentation & Control" HDUGHTDN:T C Licensing Branch 3 80/06/16 2pp
- BOD7230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D G Division of Licensing 80/06/26 2pp
- 8007030245 Forwards structural drawings supplementing technical info submitted on 800329 & 0606 DALE, L. F. Mississippi Power & Light Co. 80/06/30 2pp
- --8007030248 Package of 72 structural drawings to be recalled at later date for micrafilming * Bechtel Corp 80/06/30 72pp

- 8007240287 Summary of B00625 meeting w/applicant in Gaithersburg, HD re instrumentation & control sys questions & response & discussion of review schedule HDUQHTON, T C Licensing Branch 3 80/07/03 7pp
- 8007280494 Forwards response to 10 remaining open issues in diaft SER Info covers seismic subsystem analysis, acceptance criteria for steady state piping vibration & preservice & inservice pump & valve testing
 DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- BD07220569 Forwards "Cultural Resources Survey of Ray Braswell Transmission Line Route Harren & Claiberne Counties, MS," per NRC 80011B request DALE, LF Mississippi Power & Light Co 80/07/17 1p
- --8007220573 "Cultural Resources Survey of Ray Braswell Transmission Line Routs Warren & Clasborne Counties.MS " D'HEAR.V W. ATKINSON.J P Mississippi Power & Light Co 80/06/09 22pp
- 8007290322 Forwards comments to amplify previous questions rainstrumentation & controls raised at 800625 meeting SCHWENCER.A Licensing Branch 3 80/07/21 3pp
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8007070245 Forwards response to open issues for use at 800708 meeting w/Mechanical Engineering Branch re draft SER for FBAR Sections 3 6-3 10 Responses to remaining ten issues will be provided on 800707 DALE.L. F. Mississippi Power & Light Co. 80/07/02 26pp
- 8007140388 Forwards partial transmittal of responses to draft SER for FSAR Sections 3 6-3 10

 DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- F Security, medical, emergency & fire protection plans
- 8006300379 Forwards Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FBAR, App 98 8TAMPLEY, N.L. Mississippi Power & Light Co 80/06/27 1p
- ---BOO4300382 Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FBAR App 98 Certificate of Svc encl
 STAMPLEY, N L Mississippi Power & Light Co 80/04/27 2nd
- --B004300384 Amend 40 to FSAR, providing revisions to fire protection plan & emergency plan * Mississipi Power & Light Co 80/06/27 85pp
- 8007010361 Forwards omergency & radiological response plans for State of MS.Port Oibson/Claiborne County.MS. & State of LA, in support of util revised emergency plan submitted on 800627 as part of Amond 40 to FGAR DALE.L F Mississippi Power & Light Co 80/06/27 2pp
- 8007180293 Forwards response to NRC 800702 itr re estimated evacuation times Estimated evacuation times for 10-mile emergency planning zone prepared by Clairborne County, MS & Tanses Parrish, LA, encl
 DALC, L F Mississippi Power & Light Co 80/07/11 33pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 mamorandum & order UCB 771104 patition sought action re fire protection for electrical c
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007110412 Forwards affidavit of svc for Amend 40 to FBAR.per NRC 780627 ltr DALEL F Mississippi Power & Light Co 80/07/07 2pp
- G Inspection reports. IE Bulletins & correspondence
- 800724021B Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Resse Unit i While in Refueling Mode" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08.

- B007140484 Forwards IE Bulletin 80-13. "Cracking in Core Spray
 Spargers " No written response required
 O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/12
- B007020173 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/28
- 8007010250 Forwards IE Info Notice 80-23, "Loss of Buction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007100119 Forwards IE Insp Rept 50-416/80-11 on 800512-15 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/30 2pp
- ---B007100124 IE Insp Rept 50-416/80-11 on 800512-15 No noncompliance noted. Hajor areas inspected preoperational test program & testing & previous insp findings
 KELLOG, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch WAONER, A Q Region 2, Atlanta, Office of the Director 80/05/30. 4pp
- 8007220078 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 2cs.
- 8007160278 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- BOO7140299 Forwards IE Bulletin 80-14, "Degradation of BMR Scram Discharge Vol Capability," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/06/12 is.
- BOO7250377 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50.55(e)" No written response required U/REILLY.J P Region 2. Atlanta, Office of the Director 60/06/13 2pp
- 8007020374 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/20
- 8007310240 Forwards IE Insp Repts 50-416/80-13 & 50-417/80-09 on 800603-06 No noncompliance noted MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 80/06/23 2pp
- 8007160789 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Recultant Internal Contamination of Personnel" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/24 is
- B007230R13 Forwards IE Bulletin 80-16, "Potential Misapplication of Roseacunt Inc Models 1151 & 1152 Prossure Transmitters WEither A or D Output Codes " Hritten response required IE Circular 80-16 also encl No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director ip.
- BOO7140B&O Ack receipt of 800&17 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-416/80-08 MURPHY.C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. BO/07/01 ip.
- ---BOO7160B62 Revised response to NRC BOD401 ltr re violation noted in IE
 Insp Rept 50-416/BG-08 Corrective actions.insp program
 instituted by constructor & all nonconformances will be
 documented.
 HCGAUGHY.J.P Mississippi Power & Light Co BO/06/17 7pp

- --8007160866 Responds to NRC 800401 ltr re violation noted in IE Insp Rept 50-416/80-08 Corrective actions all personnel have been reinstructed in installation & insp procedures MCGAUGHY. J. P. Mississippi Power & Light Co. 80/05/19 2pp
- --8007160869 Forwards IE Insp Rept 50-416/80-09 on 800303-06 & notice of violation
 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --8007160870 Notice of violation from insp on 800303-06 * Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/03/31 2pp
- --8007i60872 IE Insp Rept 50-416/80-08 on 800303-06 Nancompliance noted failure to follow pape support anstallation & insp procedures ANG.W P., WILCOX, J.D. Region 2. Atlanta. Office of the Director HERDIAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/31 App
- 8007210270 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " Evaluation not complete Requests extension to 800813 DALE.L.F. Mississippi Power & Light Co. 80/07/03 ip
- B007290432 Forwards response to NRC B00624 ltr ro violations noted in IE Insp 50-416/80-12 on B00527-30 Corrective actions responsible field engineers have been instructed to obtain sequential number from respective discipline cut rebar log MCGAUGHV.J P Mississippi Power & Light Co 80/07/21 3pp
- 8 Reportable occurrences, LERs & related correspondence
- B007020619 Status deficiency rept re effects of loss of site power on rod position indication & neutron munitaring Deficiency still under investigation Final rept will be forwarded on 800723

 DALE, L. F. Mississippi Power & Light Co. 80/05/21 2pp
- 8007170392 Part 21 rept re potentially defective diesel generator control panels mfg by Intl Control & Switchgear Co Insp underway to determine applicability of deficiency Final rept will be submitted by 800625 MCGAUGHY.J P Mississippi Fower & Light Co 80/05/22 2pp
- 8007160395 Interim deficiency rept re incorrect pipe supplied by TX Pipe Bending Heavier wall would not cause overstressed condition Generic implications in other applications under invostigation Final rept will be submitted by 800829 MCGAUGHY. J P Kississippi Power & Light Co 80/05/23 2pp
- B007160642 Second interim deficiency rept (PRD-80/07) re inadequate Fisher Controls QA program re safety-related controls for nenpressure retaining parts & components QA program ovaluation continues Final rept will be submitted by B00626 MCGAUGHY.J P Mississippi fower & Eight Co 80/05/23 [p
- BOO7020379 Status Deficiency Rept 4 re GE failure to implement proper GA program for electrical work Util is reviewing reinsp of GA program Final rept will be submitted by BOO714 MCGAUGHY, J P Mississippi Power & Light Co BO/03/30 2pp
- 8007020640 Status Deficiency Rept 2 re mud to dragon valve manifolds Review of application of valve manifolds & safety-related impact still under investigation Final rept will be forwarded by 800702 MCGAUHY, J P Mississipp Power & Light Co 80/06/02 2pp
- 8007160611 Interim deficiency rept re mods to Dragon valve manifolds Review of MCAR-GONS 26 in M Couge 800306 site insp concluded that deficiency was improperly evaluated Final rept will be submitted by 800702 MCGAUGHY.J P Nicsissippi Power & Light Co 80/06/02 2pp
- 800hi90577 Deficiency rept (PRD-80/24) re GE Type SB-12 switches Questions rationals that safety function of breaker was to trip on signal from reactor protection sys Re-avaluation will be conducted & final rept filed by 800710 MCGAUGHY.J P Mississippi Power & Light Co 80/06/12 2pp
- B0070R0601 Forwards interim deficiency rept re GE failure to provide qualified instrumentation in safety-related sys MCGAUGHY, J P Mississippi Power & Light Co 80/06/13 2pp
- --8007020603 Interim deficiency rept re &E failure to provide spismically & environmentally qualified instruments for use in nuclear safety-related says in balance-of-plant power generation control complex Corrective action plan expected by 800711 * Mississippi Power & Light Co 80/06/13 4pp

- 8007020538 Forwards interim deficiency ropt (PRD-80/ii) re Rosemount Model 510 DU trip unit & Final deficiency rept (PRD-80/ii) re Model 1152 pressure transmitters MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/24 2pp
- --8007020539 Final deficiency rept (PRD-80/ii) re Model 1152 pressure transmitter u/common mode failure of capacitor at greater than 175 F or when damping potentiometer is lotated clockwise 6E issued field disposition instructions # Mississippi Power & Light Co 80/06/24 ip
- --8007020541 Interim rept (PRD-80/11) re Rosemount Model 5i0 DU trip/calibr unit w/common mode failure of essential switch that determines trip output logic GE has issued field disposition instructions for onsite repair * Mississippi Power & Light Co 80/06/24 ip
- B007020630 Forwards final deficiency rept re defects in diesel generator control panels MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/25 ip
- --8007020432 Final deficiency rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Co Equipment being repaired by Morrison-Knudsen GA activity will be increased Applicability of 10CFR21 under evaluation # Mississippi Power & Light Co 80/06/25 ip
- BOO7070298 Status Deficiency Rept 3 re inadequate GA program for nonpressure retaining parts & components Detail of AE investigation under evaluation Final rept will be forwarded by BOO728
 - MCGAUGHY.JP Mississippi Power & Light Co 80/05/27 2pp
- 8007:10413 Forwards final deficiency rept re mod to Dragon Valves, Inc. valve manifolds MCGAUSHY...P Hississippi Power & Light Co 80/07/02 2pp
- --B007i10417 Final deficiency rept re mod to Dragon Volves, Inc. valve manifolds Failure of valve would not rause malfunction during emergency operation of standay liquid control sys & not considered reportable per 100FRSO 53(s)

 * Hississipp: Power & Light Co 80/07/02 2pp
- 8007ii043D Status Rept 1 re procedural violation in cutting rebar Stop work order issued on 80053O to stop hole drilling operations for electrical support Craft & field engineering personnel trained Final rept will be submitted by 800117 MCCAUGHY.JP Mississippi Fower & Light Co 80/07/02 2pp
- 8007190093 Part 21 rept. supplementing info previously filed under 10CFR50 55(e), re Rosemount, Inc Model 510DU master & slave trip units Info should have been included in review of deficiency repts filed since 1977 MCGAUGHY, J P Mississippi Power & Light Co 20/07/02 9pp
- BOO7150099 Part 21 rept.supplementing info previously filed under IOCFR5D 55(e).re Gould-Brown Boveri solid-state trip dayies Rept should have been included in review of deficiencies filed since 1977 MCGAUGHY, J. P. Mississippi Power & Light Co. BO/07/02 4pp
- 8007130103 Part 21 rept, supplementing info previously filed under iOCFR50 35(e).re Westinghouse electrical penetration assemblies Ropt should have been included in review of deficiencies filed since 1977 MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 4pp
- G007170396 Forwards Final Deficiency Rept PRD-B0/26 re defective GE SB-12 switches, orginally reported 800512 Rept on applicability of 10CFR21 will be submitted upon completion of evaluation MCGAUGHY, J P Mississippi Power & Light Co 80/07/10 1p
- ---BC07170400 Final Deficiency Rept PRD-80-26 re defective GE SD-12 switches identified in IE Circular 79-17 Switches found to be installed in switchesar supplied by vendor Vendor will furnish new switches to correct condition

 # Mississippi Fower & Light Co 80/07/10 lp
- B007170290 Forwards first Interim Deficiency Rept PRD-80/32 re standby svc water sys design deficiency Final rept will be submitted by E01020 MCGAUGHY, J P Mississippi Power & Light Co 80/07/11 ip
- --B007170294 First Interim Deficiency Rept PRD-80/32 re standby svc water sys design deficiency Debris picked up by standby svc water & HPCS svc water pumps transferred into sys No provision axists for filtering Sys design will be analyzed & Mississippi Power & Light Co. 80/07/11 1p

- B007170435 First interim deficiency rept (PRD-80/3i) re failure of PPCB switchgoar to comply w/seismic requirements NSSS vendor evaluation of effects on safety has not been completed Final rept will be submitted by B00923 MCGAUGHY, J P Mississippi Power & Light Co 80/07/11 ip
- 800722038B Status Deficiency Rept 6 re failure to establish GA program OE has not completed review of insp results & evaluation of safety implications Final rept to be provided by 80090B MCGAUGHY, J P Mississippi Power & Light Co 80/07/14 2pp
- BOO72203B9 Status Deficiency Ropt 2 re damage to intermediate metallic conduit Extent & safety implications remain under investigation Final rept to be provided no later than BO1006 MCGAUGHY, J P Mississippi Power & Light Co BO/07/15 3pp
- 8007250510 Status Rept 2 to deficiency rept re design nomographs related to ITT General Controls hydramotor electrohydraulic actuators Evaluation by NSSS vondor incomplete Final rept should be forwarded by 800915 MCGAUGHY, J P Mississippi Power & Light Co 80/07/21 2pp
- --8007250520 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Two NH90 series hydramotor actuators in use, Evaluation indicates that no mode required DALE.L F Mississippi Power & Light Co. 80/06/16 2pp
- 8007280566 Potential deficiency rept re nonconformances associated w/calibr svcs provided by Computer Sciences Corp Nonconformances noted during util Apr 1980 audit of calibr facility Final rept will be submitted by 800822 MCGAUGHY, J. P. Hississippi Power & Light Co 80/07/22 Ip
- 8007290655 Provides status of potentially reportable deficiency re fractured valve body on jacketwater thermostatic valve of standby diesel generator Magnetic particle examination performed Reportability will be determined by 601010 MCGAUGHY, J F Mississippi Power & Light Co 80/07/23 2pp
- 8007270666 Forwards Status Rept 2 of potentially reportable deficiency re malfunctions of Limitorque valve apprature Caused by excessive threading of stom protectors final rept by 801103 MCGAUGHY. P Mississippi Power & Light Co 80/07/23 Zpp
- 8007270671 Forwards status of potentially reportable deficiency re incorrect translation of weld requirements from design drawings to field sketches Investigation continuing Final rept will be submitted by 800917 MCGAUGHY.J P Mississippi Power & Light Co 60/07/23 2pp
- 8007290714 Provides status of potentially reportable deficiency re loss of offsite power accident & offects on rod position sys & neutron monitoring sys Deficiency still under investigation Final rept will be provided by 801230 MCGAUGHY. J P Mississippi Power & Light Co 80/07/23 2pp
- B007290791 Deficiency Status Rept 1 re damaged stator coil for standby diesel generator Deficiency investigation incomplete Reportability determination & final ropt will be submitted by 801217 MCGAUGHY.J P Hississippi Power & Light Co 80/07/23 1p
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007160610 Forwards correction to fuel load date in 800514 ltr Correct date for Unit 1 is 810831 DALE,L F Mississippi Power & Light Co 80/06/11 1p
- --8007160617 Corrects 800514 ltr requesting updated & complete schedule of safety review Correct fuel load date is 810831 DALErL F Mississipp: Power & Light Co 80/05/14 ip
- B007010237 Forwards NRC reorganization chart of Ofc of Nuclear Reactor Regulation, effective 800428 Facility activities should be made through assigned mgt representative Areas of disagreement may be discussed through informal appeal TEDESCO, R L Assistant Director for Licensing 80/06/13 2pp
- B007010D87 Notification of 800708 meeting w/vtil,BNML,QE & Bechtel Power Corp in Gaithersburg.MD to review Mechanical Engineering Branch draft SER HDUOHTON.T C Liconsing Branch 3 80/06/16 3pp

- BOO7010100 Notification of 800623 maeting w/util.GE.Bechtel Power Corp & Savannah River Leb in Gaithersburg.HD to discuss FSAR Bection 7, "Instrumentation & Control" HOUGHICM.T C Licensing Branch 3 80/06/14 2pp Licensing Branch 3 80/06/16 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREO-0660 & found in NUREO-0674 EIGENMUT.D O Division of Licensing 80/06/26 2pp

- B007030245 Forwards structural drawings supplementing technical info submitted on B00827 & 0606 DALE.L F Mississippi Power & Light Ca B0/06/30 2pp
- --8007030248 Package of 72 structural drawings to be recalled at later date for microfilming # Bechtel Corp 80/06/30 72pp
- 8007240287 Summary of 800625 meeting w/applicant in Gaithersburg.MD re instrumentation & control sys questions & response & distustion of review schedule HCKONTONIT C Licensing Branch 3 80/07/03 7pp
- 0007280494 Forwards response to 10 remaining open Issues in draft SER Info covers seismic subsystem analysis, acceptance criteria for steady state piping vibration & preservice & inservice pump & valve testing
 DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- B007270567 Forwards "Cultural Resources Survey of Ray Braswell Transmission Line Route, Marren & Claiborne Counties, MS." per NRC B00118 request DALE, L F Mississippi Power & Light Co 80/07/17 ip
- ---B007220373 "Cultural Resources Survey of Ray Braşwell Transmission Line Route Harren & Clasborne Counties.MS " D'HEAR.J W., ATKINSON.J P Mississippi Power & Light Co B0/06/09 22pp
- 8007270322 Forwards comments to amplify previous questions re instrumentation & controls raised at 800625 meeting ECHMENCER.A Licensing Branch 3 80/07/21 3pp
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- BOO7070245 Forwards response to open Issues for use at 800708 meeting w/Mechanical Engineering Branch re draft SER for FSAR Sections 3 &-3 io Responses to remaining ten issues will be provided on 800707 DALE, L.F. Mississippi Power & Light Co. 80/07/02 24pp
- 8007140368 Forwards partial transmittal of responses to draft SER for FSAR Sections 3 6-3 10
 DALE-L F Mississippi Power & Light Co 80/07/00 13pp
- F Security, medical, emergency & fire protection plans
- 8007010361 Forwards emergency & radiological response plans for State of MS.Port Oibson/Claiborne County.MS. & Stats of LA.in support of util revised emergency plan submitted on 800627 as part of Amend 40 to FSAR DALE.L F Mississippi Power & Light Co 80/06/27 2pp
- 8007180273 Forwards response to NRC 800702 ltr re estimated evacuation times Estimated evacuation times for 10-mile emergency planning zone prepared by Clairborne County. MS & Tensas Parrish.LA. encl
 DALE.L.F Mississippi Power & Light Co 80/07/11 33pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission R00927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D © Division of Licensing 80/04/25 89pp
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8006300379 Forwards Amend 40 to application for OLs for Licenses CPPR-11B & CPPR-119, consisting of revisions to FSAR.App 9D 9TAMPLEY.N L Mississippi Power & Light Co 80/06/27 lp
- --8006300382 Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR App 98 Certificate of Syc encl. BTAMPLEY,N L Mississippi Power & Light Co 80/06/27 2pp

- --8006300384 Amend 40 to FSAR, providing revisions to fire protection plan
 - & emergency plan
 # Mississippi Power & Light Co 80/06/27 B5pp
- 8007110412 Forwards affidavit of syc for Amend 40 to FSAR.com NAC 780627 ltr DALE, L F Mississippi Power & Light Cu 80/07/07 2pp
- Q Inspection reports: JE Bulletins & correspondence
- 8007240218 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007140484 Forwards IE Bulletin 80-13, "Crarking in Core Spray Spargers" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director BO/05/12
- 8007010250 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feadwater Pumps " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29
- 8007220078 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/06/10
- B00716027B Forwards IE Info Notice 80-27, "Degradation of Reactar Coplant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/11
- 8007140299 Forwards IE Bulletin GO-14, "Degradation of BHR Scram Discharge Vol Capability " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/12
- 8007250377 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10(FR30 55(v) " No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/13
- 8007020374 Forwards IE Circular 80-15. "Loss of Reactor Conlant Pump Cooling & Natural Circulation Cooldown" No writton response required D'RETLLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 8007310240 Forwards IE lnsp Nepts 50-416/80-13 & 50-417/80-09 on B00603-06 No moncompliance noted MURPHY, C C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --B007310245 IE Insp Repts 50-416/B0-13 & 50-417/B0-09 on B00503-06
 No noncompliance noted Major areas inspected radiography,
 welding, pitrasonic examination & previous insp findings
 HERDT, A R Region P. Atlanta, Reactor Construction & Engineering
 Support Branch VANDDDRN.P K. ZAJACL D Region P. Atlanta,
 Office of the Director B0/06/20 App
- B007160789 Forwards IE Circuler 80-14, "Hadioactive Contamination of Plant Deminoralized Water Bys & Resultant Internal Contamination of Personnol " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/06/24
- 8007230213 Forwards IE Bulletin 80-16, "Potential Misapplication of Resembunt Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Dutput Codes " Written response required IE Circular 80-16 also ent No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/6
- 8007210270 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Wolds " Evaluation but complete Requests extension to 800815 DALE, L.F. Mississippi Power & Light Co. 80/07/03 lp

- 8 Reportable occurrences, LERs & related correspondence
- 8007020615 Status deficiency rept re effects of loss of site power on rod position indication & neutron monitoring Deficiency still under investigation Final rept will be forwarded on 800723 DALE-L F Mississippi Power v. Light Co 80/05/21 2pp
- G007170592 Part 21 rept re potentially defective diesel generator control panels mfg by Intl Control & Switchgear Co-Insp underway to determine applicability of deficiency Final rept will be submitted by B00625 KCGAUGHY. J. P. Mississippi Power & Light Co. 80/05/22 2pp
- 8007160585 Interim deficiency rept re incorrect pipe supplied by TX Pipe Donding Hoavier wall would not cause overstressed condition Genetic implications in other applications under investigation Final rept will be outmitted by 800827 MCGAUGHY, J P Mississippi Power & Light Co 80/05/23 2pp
- B007160642 Serond interim deficiency rept (PRD-B0/07) re inadequate Fisher Controls GA program in safety-related controls for nonpressure retaining parts & components GA program evaluation continues Final rept will be submitted by 800626 MCGAUGHY.JP Mississippi Power & Light Co 80/05/23 Ip
- BOO70205/9 Status Deficiency Rept 4 re GE failure to implement proper GA program for electrical work Util is reviewing reinsp of GA program Final rept will be submitted by BOO714 MCGAUGHY, J P # 11ssissippl Power & Light Co 80/05/30 2pp
- R007020640 Status Deficiency Rept 2 re med to dragon valve manifolds Review of application of valve manifolds & safety-related impact still under investigation Final rept will be forwarded by 800702 MCGAUHY, J P Mississippi Power & Light Co 80/06/02 2pp
- BOO7160611 Interim deficiency tept re mods to Dragon valve manifolds Review of MCAR-GONS 26 in M Gouge BOO306 site insp. concluded that deficiency was improperly evaluated Final rept will be submitted by 800702
 MCGAUGHY.J P Mississippi Power & Light Co 80/06/02 2pp
- 0007020601 Forwards interim deficiency rept re GE foilure to provide qualified instrumentation in safety-related sys HCGAUGHY,J P Mississippi Power & Light Co 80/06/13 2pp
- --8007020603 Interim deficiency rept to GE failure to provide seismically & environmentally qualified instruments for use In nuclear safety-related sys in balance-of-plant power generation control complex formertive action plan expected by 800711 # Mississippi Power & Light Co 80/06/13 4pp
- B00702053B Forwards interim deficiency rept (PRD-B0/11) re Rosemount Modol 310 DU trip unit & final deficiency rept (PRD-B0/11) re Modol 1132 pressure transmitters MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/24 2pp
- ~-8007020539 Final definiency rept (PRD-89/11) re Model 1152 pressure transmitter w/common made failure of capacitor at greater than 1/5 F or when damping patentiometer is rotated clockwise 0E issued field disposition instructions * Misslesippi Pawer & Light Co 80/06/24 ip
- --8007020541 (nterim rept (PRD-80/11) to Rosemount Model 310 DU trip/ collibr unit w/common mode failure of essential switch that determines trip output logic GE has issued field disposition instructions for onsite repair # Hississippi Power & Light Co. 80/06/24 lp
- 8007020630 Forwards final deficiency rept re defects in dissel generator control panels MCGAUGHT, J P Mississippi Power & Light Co 80/06/25 ip
- --8007020632 Final deficiency rept re defects in diesol generator control panels mfg by Intl Control & Switchgear Co Equipment being repaired by Marrison-Knudson (A) activity will be increased Applicability of 100FRJ under evaluation # Mississippi Power & Light Co 80/06/29 ip
- 8007070298 Status Deficiency Rept 3 re inadequate GA program for nonpressure retaining parts & components Detail of AE investigation under evaluation Final rupt will be forwarded by 800728 MCGAUGHY.JP Mississippi Power & Light Co. 80/06/27 2pp
- 8007110413 Forwards final deficiency rept re mod to Dragon Valves, Inc. valve manifolds
 MCGAUGHY. J P Mississippi Power & Light Co 80/07/02 2pp

- --8007110417 Final deficiency rept re mod to Dragon Valves, Inc. valve manifolds Failure of valve would not cause malfunction during emergency operation of standby liquid control sys & not considered reportable per 10CFR50 59(e) * Hississippi Powor & Light Co 80/07/02 2pp
- 8007110430 Status Rept i re procedural violation in cutting rebar Stop work order issued on 800530 to stop hole drilling operations for electrical support Craft & Field engineering personnel trained Final rept will be submitted by 800117 MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 2pp
- B007150093 Part 21 rept, supplementing info previously filed under IQCFR50 95(e), re Rusemount, Inc Model 510DU master & slave trip units Info should have been included in review of deficiency repts filed since 1977
 MCGAUOHY, J P Mississippi Power & Light Co \$00/07/02 9pp
- B007150099 Part 21 rept, supplementing info previously filed under iOCFR50 55(e), re Gould-Brown Bovori solid-state trip devices Rept should have been included in review of deficientios filed since 1977

 MCGAUGHY, J P Mississippi Power & Light Co 80/07/02 4pp
- 8007190109 Part 21 rept, supplementing info previously filed under 10CFR30 59(e), re Westinghouse electrical penetration assemblies Rept should have been included in review of deficiencies filed since 1977
 MCGAUGHY, J P MIssissippi Power & Light Co 80/07/02 4pp
- 8007170376 Forwards Final Deficiency Rept PRD-80/26 re defective QE 88-12 switches, orginally reported 800312 Rept on applicability of lOCFR21 will be submitted upon completion of evaluation MCGAUGHY, J P Misslaslppi Pownr & Light Co 100/07/10 ip
- --B007170400 Final Deficiency Rept PRD-80-26 rs defective GE SB-12 switches identified in IE Circular 79-17 Switches found to be installed in sultchgear supplied by vendor Vendor will furnish new switches to correct condition # Mississippi Power & Light Co 80/07/10 ip
- 8007170270 Forwards first Interim Deficiency Rept PRD-80/32 re standby svc water syn design deficiency Final rept will be submitted by 801020 MCOAUGHY.J P Miselssippi Power & Light Co 80/07/11 ip
- --- 8007170294 First Interim Deficiency Rept PRD-80/32 re standby syc water sys design deficiency Debris picked up by standby syc water & HPCS syc water pumps transforred into sys No provision exists for filtering Sys design will be analyzed # Mississipp: Pawer & Light Co 80/07/11 ip
- B007170435 First Interim deficiency rept (PRD-80/31) re failure of HPCB switchgear to comply w/solsmic requirements NBSS vendor evaluation of effects on safety has not been completed Final rept will be submitted by 800923
 MCGAUGHY, J P Hississippi Power & Light Ca 80/07/11 ip
- 8007220388 Status Deficiency Rept & ro failure to establish QA program QE has not completed review of lase results & evaluation of safety implications Final rept to be provided by 800908.

 MCGAUGHY, J P Mississippl Power & Light Co 80/07/14 2pp
- 8007220389 Status Deficiency Rept 2 re damage to intermediate metallic conduit Extent & safety implications remain under investigation Final rept to be provided no later than 801006 MCGAUGHY.J P Mississippi Power & Light Co 80/07/19 3pp
- H007230510 Status Rept 2 to deficiency rept re design nomographs related to ITT General Controls hydramotor electrohydraulic actuators Evaluation by NSS9 vendor incomplete, Final rept should be forwarded by 800915
 MCGAUGHY, J P Mississippi Power & Light Co 80/07/21 2pp
- --B007250520 Responds to 1E Bulletin 80-09. "Hydramotor Actuator Deficiencies " Two NH90 sories hydramotor actuators in usa Evaluation indicates that no mods required DALE, L F Hississippi Power & Light Co B0/06/16 2pp
- B007280566 Potential deficiency rept re nonconformances associated w/calibr svcs provided by Computer Sciences Corp Nanconformances noted during util Apr 1980 audit of calibr facility Final rept will be submitted by 800822, MCGAUGHY.J P Mississippi Power & Light Co 80/07/22 lp

- PO7290655 Provides status of potentially reportable deficiency refractured valve body on jacketwater thermostatic valve of tendby diesel generator Hagnetic particle examination performed. Reportability will be determined by 801010 PC GAUGHY. J P Mississippi Power & Light Co 80/07/23 2pp
- >O7290666 Forwards Status Rept 2 of potentially reportable deficiency for malfunctions of Limitorque valve operators Caused by excessive threading of stem protectors Final rept by B01103 PG GAUGHY, J P Hississippi Power & Light Co 80/07/23 20p
- PO7290671 Forwards status of potentially reportable deficiency re incorrect translation of weld requirements from design drawings to field sketches Investigation continuing Final rept will be submitted by 800917 POWER & Light Co 80/07/23 2pp
- PO72907i4 Provides status of potentially reportable deficiency re loss of offsite power accident & affects on red position mus & neutron monitoring sys Deficiency still under invastigation Final rept will be provided by 801230 PCGAUGHY, J.P. Mississippi Power & Light Co. 80/07/23 2pp
- O7290791 Deficiency Status Rept 1 re damaged stator coil for standby dissel generator Deficiency investigation incomplete Reportability determination & final rept will be submitted by 801217
 PCOAUGHY.J P Mississippi Power & Light Co 80/07/23 1p
- DCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
 - Application/construction stage documents & correspondence
- DOT230001 Forwards statement of policy re requirements to be met for Current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EXSENTUTION Division of Licensing 80/06/26 2pp
- Adjudicatory correspondence
- OO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memoransum & order UCS 771104 petition sought action the fire protection for electrical cables EISENHUT.D 0. Division of Licensing 80/06/25 99pp
- . Financial information
- O-07150622 Forwards 1980 cash flow estimates for CT Light & Power Co. Startford Electric Light Co & Western HA Electric Co Gash flows are adequate to meet potential premium requirements for ice-Anderson Act D-1608NOR, L A Northeast Utilities 80/07/03, 2pp
- . Imapection reports, IE Bulletina & correspondence
- OO7010312 Forwards IE Info Notice BD-23, "Loss of Suttion to Emergency Feedwater Pumps" No written response required ORIER, B H Region i. Philadelphia, Office of the Director BO/05/29 ip
- ICO7170519 Forwards response to IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) H-Oldup Tanks " Provides list of sys in facility containing tanks that can be valved to contain primary sys water COUNDIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) GO/06/09 7pp
- O7210880 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs." No written response required ORIER,B H. Region 1, Philadelphia, Office of the Director BO/Q6/10 1p
- NOO7160397 Forwards IE Info Notice 80-27, "Degradation of Reactor Coplant Pump Studs " No specific action or response required QRIER,B H. Region 1. Philadelphia, Office of the Director 80/06/11 ip
- ### O 7280600 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR80 55(e)" No written response required.

 ORIER, B H Region i, Philadelphia, Office of the Director, 80/06/13 19

- 8007010354 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" No ITT General Controls Model AM-90 % NM-90 hydramotor actuators have been purchased for use at util COUNSTL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/16 2pp
- BO07020494 Forwards IE Circular BO-15, "Loss of Reactor Coclant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, D. H. Region 1, Philadelphia, Office of the Director BO/06/20 ip
- B007160734 Forwards IE Circulat B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER B H Region 1. Philadelphia. Office of the Director B0/06/24 1m
- B007210207 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER, B H Region I, Philadelphia, Office of the Director B0/06/25 1p
- B007230146 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.I H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- 8007210533 Forwards IE lnsp Rept 50-423/80-03 on 900423 No noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/12 2pp
- --B007210545 1E Insp Rept 50-423/80-03 on 800423 No noncompliance noted Major areas insported containment & reactor area, control bldg, turbine bldg & other svc areas Newly assigned inspector introduced CERNE, A C , FEIL, R Region I, Philadelphia, Office of the Director MCGAUGHY, R W Region I, Philadelphia, Reactor Construction & Engineering Support Beanch 80/06/10 3pp
- S Reportable occurrences, LERs & related correspondence
- BOO7210457 Ack receipt of BOO014 deficiency rept to possible inadequacy of charging pumps following secondary sys high energy line rupture CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Dranch 80/07/01 1p
- --B007210320 Interim deficiency rept confirming 800515 telcon
 Westinghouse centrifugal changing pumps may not deliver min
 flow at valve set point pressure Action will be delayed
 until Westinghouse analysis completed
 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast
 Utilities) B0/06/14 lp
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT (
 A Application/cunstruction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D @ Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- B007290774 Forwards evacuation time estimates per NRC 791226 & 800702 requests EHREN9PEROER, W. Georgia Power Co. 80/07/23 ip
- --B007290777 Evacuation time estimates for factilities Maps encl * Georgia Power Co = 80/07/23 - 89p
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D Q Division of Licensing 80704/28 89pp

H General correspondence

- 9007080344 Requests that NRC levise correspondence distribution. changing addressee to HE Ehrensperger EHRENSPERGER, W. Georgia Power Co. 80/06/30 tp
- Q Inspection reports. IE Bulletins & correspondence
- 8007240213 Forwards IE lofo Notice 60-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY,J P Region 2, Atlanta, Office of the Director 60/05/08
- 8007210466 Forwards IE Circular 80-13, "Crid Strap Damage in Wastinghouse Fuel Assemblies" No written response required 3'REILLY, J P Region 2. Atlanta, Office of the Director (80/05/28
- 8007010220 Forwards 1E Info Notice 80-23, "Loss of Surtion to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/29
- 8007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY-U P Region 2, Atlanta, Office of the Director 80/06/10
- 8007160274 Forwards JE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- B007250375 Forwards Ik Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 95(e) " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/13
- 8007020218 Responds to IE Bulletin 80-09. "Hydromotor Actuator Deficiencies " Util does not use 177 General Controls AH90 series hydromotor actuators for any safety-related sys or DUTTON,D Georgia Power Co 80/06/16 2pp
- B007290409 Forwards IE Insp Hepts 50-424/H0-09 & 50-425/B0-09 on 800522 & 23 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --8007290414 IE Insp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted Major area inspected licensee identified item re erosion of Category I backfill CONLON. F. Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARRIS. J. R. Region 2. Atlanta Control Research Page 18 (1988) 18 Director 80/06/13
- B007020450 Forwards IE "ircular 80-15. "loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required D'REILLY. J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 8007110315 Ack receipt of 800605 ltr informing NRC of steps taken to correct /julation noted in 1E Inap Repts 50-424/80-07 & 50-425/80-07
- , Region 2, Atlanta, Reactor Construction & Engineering ncb BG/06/24 lp MURPHY. C E Support Branch
- ~-8007110521 Responds to NRC 800501 ltr re violation noted in IE Insp Repts 90-424/80 07 % 50-425/80-07 Corrective actions records from Sept 17*2-Apr 1980 were reviewed & correlation curves were generated & evaluated DUTION.D Georgia Power Co 80/06/05 2pp
- --8007i10527 Forward: IE Insp Repts 50-424/80-07 & 50-425/80-07 on 800414-16 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch S0/05/01 2pp
- --8007110531 Notice of violation from insp on 800414-16
 * Region 2. Atlanta. Office of the Director 80/0 80/05/01 1p

- -BOO/110536 IE Insp Repts 50-424/80-07 & 90-429/80-07 on BOO414-16 Noncompliance noted failure to evaluate mainture check test LENAHAN, J. J. Region 2. Atlanta, Office of the Director CANLON, L. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 5pp
- 80071/0115 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Musuitant Internal Contamination of Personnel "No written response required O'REILLY, J P. Rogion 2, Atlanta, Office of the Director 80/06/2 80/06/24
- 8007220275 Responds to IE Builetin 80-08 Flued head penetration welds installed & examined according to ASME requirements DUTTON, D. Georgia Power Co. 60/06/26. 2pp
- 8007230247 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1991 & 1992 Prossure Transmitters W/Either A or D Output Codes " Writton response required IE Greular 80-16 also wil No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/2 80/04/27
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to becurrent OL applications as derived from NUREO-0660 & found in NUREO-0694 to be met for EIBENHUT, D (Division of Licensing 80/06/26 Ppp
- F Security, medical, emergency & fire protection plans
- 8007290774 Forwards evacuation time estimates per NRC 791226 & 800702 requests
 EHRENSPERGER.W Georgia Power Co 110/07/25 ip
- --8007290777 Evacuation time estimates for furlities Maps encl * Georgia Power Co 80/0//23 Bpp tinp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 8005:// monor and under containing decisions on UCS /80502 patition for reconsideration of 780413 memorandum & order US //1104 patition sought action to fire protection for electrical cobies EISENHUT, D G Division of Licensing 80/06/25 G9pp
- It General correspondence
- 8007080344 Requests that NRC revise correspondence distribution, changing addresses to WE Chrenspergor EHRENDPERGER.W. Georgia Power to 807467,80 ip
- Q Inspection reports. It Bulletins & currespondence
- 800/240213 Forwards IL Info Notice 80 PG, "Loss of Derny Heat Removal Capability at Davis-Besse Unit I While in Refueling Mide "No response required D'REILLY, J.P. Region P, Atlanta Office of the Director 180/05/00 Region P. Atlanta Office of the Director 10/05/00
- BOO/210468 Forwards It Circular 80 19, "Grid Strap Damage in Wastinghouse Fuel Assemblies " No written insputes required O'REILLY, J.P. Region 2, Atlanta, Hefice of the Director (60/05/28
- 8007010220 Forwards IE Info Motice 40-23. "Inst of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J.P. Ragion 2, Atlanta, Office of the Director 60/03/29
- 8007220072 Forwards LE lafe Notice 60-26, "Evaluation of Contractor OA Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director HO/06/10
- 8007160274 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response O'REILLY, J.P. Rugson P. Atlanta, Office of the Director 80/06/11

- 8007250375 Forwards IE Info Notice 80.28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- 8007020218 Responds to IE Bulletin 80-09. "Mydromotor Actuator Deficiencies " Util does not use ITT General Controls AM90 series hydramotor actuators for any safety-related sys or . Georgia Power Co GD/06/16 2pp
- 8007270407 Forwards IE lnsp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted MRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/14 2pp
- --8007290414 IE Insp Repts 50-424/60-09 & 50-425/60-09 on 800522 & 23 No noncompliance noted Major area inspected licenses identified item re-crosion of Category I backfill COMLONITE Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARRIELJ R Region 2. Atlanta, Office of the Ninetan 8006/13 200 B0/06/13
- 8007020450 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown" No written response required 0'REILLV, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007110515 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-424/80-07 & 50-425/80-07 MRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/24 lp
- --E007110521 Responds to NRC 800501 ltr re violation nated in IE lnap Repts 50-424/80-07 & 50-425/80-07 corrective actions records from Bapt 1979-Apr 1980 were reviewed & correlation curves were generated & evaluated DUTTON: D Georgia Power Co 80/06/05 2pp
- --8007110527 Forwards IE Insp Repts 90-424/80-07 & 50-425/80-07 on 800414-16 & notice of violation MRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- 31-014008 on qual merd trialation from inco on 800414-16 O/GB Tractor Director BD/G 80/05/01 Ip
- --8007110536 IE Insp Repts 50-424/80-07 & 50-425/80-07 on B00414-16 Noncompliance noted failure to evaluate moisture check test results TENAHAN. J Region 2. Atlanta. Office of the Director CANLON. L E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/01 5pp
- 8007170115 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Diminavalized Water Sys & Resultant Internal Contamination of Personnel" No written response required UREILLY. J P Region 2. Atlanta. Office of the Director 80/06/24
- 800/220279 Responds to IE Bulletin 60-08 Flued hoad panetration welds installed & examined according to ASME requirements DUTTON.D Georgia Power Co 80/06/26 2pp
- 8007230249 Forwards IE Bulletin 80-16. "Potential Misapplication of Reservoint Inc Models 1191 & 1192 Pressure Transmitters Whither A or D Output Codes " Unitten response required IE Circular 80-16 also encl No unitten response required O'REILLY-J P Reglon 2. Atlants. Office of the Director 80/06/2 80/06/27
- DOCKET 50-433 UC-BANTA BARBARA RESEARCH REACTOR G Inspection reports, IE Bulletins & correspondence
- 8007180243 Forwards IE Circular 60-14. "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internet Contamination of Personnel" No written response required ENGELKENR II Region 5, San Francisco. Office of the Director 80/06/24 lp

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- 8007020566 Submits summary of 800613 meeting for W Butler briefis Commissioner Gilinsky on alternate methods for controlling hydrogen in ice condenser containment Serves as notification for parties to floating nuclear plant proceeding AUSTIN, J H Property & Supply Branch 80/06/26 19
- 8007230001 Forwards statement of policy re requirements to be met current DL applicitions, as derived from NURES-0540 & found in NURES-0594 EISENHUT, D.G. Division of Licensing 80/06/24 2pp
- 8007210345 Forwards 36A93, "OPS Responses to Post-TNI NRC Requirements," Revision i Rept replesents vast anjority of new info required to support issuance of mgt license Requests meeting w/NRC at earliest possible convenience HAGGAP B Offshore Power Systems (subs of Westinghouse Electr Corp.) 80/07/15 3pp
- ---8007210404 "QPS Responses to Post-TMI NRC Requirements " Revisi
 * Offshore Pauer Systems (subs of Hestinghouse Electric Cor; 36/93 R1 80/07/31 122pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 630027 momorandum & order containly decisions on UCS 780502 petition for reconsideration of 760413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUI.D O Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007150013 Ack receipt of encl 800407 ltr to President Carter re omployment opportunities offered by affshore floating nuclear plant project Decisions on commercial projects are made by private sector.e/MRC approval
 HATSON, J. H. President of US & Executive Offices 60/05/16
- 8007140106 Ack recript of 800407 ltm to White House Final decision license floating nuclear plants will not be made until roview is complete. ACRS makes finding re safety & ASLB authorises issuance of license DENTON, H R Office of Nuclear Reactor Regulation, Director BO/86/19 Spp
- ---8007140108 Requests reply to CT Brown 800407 ltr expressing supp fluating nuclear power plant project SEAL,M M Prosident of US & Executive Offices 80/05/21 3p
- O Inspection reports. IE Bulletins & correspondence
- 8007240084 Forwards IC Info Notice 80-20. "Loss of Decay Heat Remo Capability at Davis Desse Unit i While in Refueling Mode "
 No response required
 O'REILLY.J P Region P, Atlanta, Office of the Director 80/05
- B007210414 Forwards IF Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies "No written response required O'REILLY-J P Region P. Atlanta, Office of the Director
- 8007010179 Forwards IE Info Notice 80-23. "Loss of Surtion to Emer Fooduater Pumps" No written response required D'REJELY, J.P. Region 2, Atlanta, Office of the Director 80/03
- 8007220026 Forwards IE Info Natice 80-26, "Typloation of Contracto GA Programs " No written response required G'REILLY J P Region 2, Atlanta, Office of the Director 80/06,
- 9007160315 Forwards IE Info Nutire 80-27, 'Degradation of Reactor Goolant Pump Studs ' No specific action or response O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04
- 8007250389 Forwards IE Info Nuture 80-28, "Prompt Reporting of Info Accordance W/10CFR90 58(s)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/

- 8007020380 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'RERLLY, J P Rogion 2, Atlanta. Office of the Director 80/06/20
- 8007170134 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P. Region 2. Atlanta. Office of the Director 80/06/24
- 8007230199 Forwards IE Bulletin 80-16. "Potential Misapplication of Rusemount Inc Models 1153 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 60/04/27 in

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007010426 Submits info re INRYCO, Inc tendon installation operations & related GA/QC activities, in response to NRC BC0424 Itr Training activities satisfactorily completed as confirmed in 800417 telcon Work will be resumed on buttonheading NILLS,L M Tennessee Valley Authority 80/06/23 1p
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NURE9-0660 % found in NUME9-0674
 EISENHUT.D 9 Division of Licensing 80/06/26 2pp
- BOO7180276 Notification of BO0723-24 meeting w/util & ANL in Dethesda, MD to review electrical, instrumentation & control drawings for conformence w/separation, redundancy & single failure criteria
 BOURNIA.A Licensing Branch 1 80/07/07 4pp
- 8007150546 Advises that facility diesel drawings have been transmitted under separate cover to A Bournia, per NRC 800701 request MILLS.L M Tennessee Valley Authority 80/07/08 ip
- 8007150551 Advises that facility diesel generator frawings are being transmitted under separate cover to 8 Halverson.per NRC request HILLS,L M Fennessee Valley Authority 80/07/08 ip
- 6007300080 Forwards request for additinfore QA program
 TEDESCO.R L Assistant Director for Licensing 80/07/23 3pp

Q Adjudicatory correspondence

- BOO7310243 Forwards Commission BOG527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 760413 memorandum & order UCS 77104 petition sought action re fire protection for electrical cables EISEMHUT, D O Division of Licensing 80/06/25 89pp
- g, Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE info Notice 80-20, "Loss of Detay Heat Removal Capability at Davis-Bosse Unit : While in Refueling Mode "
 No response required
 O'REILLY, J.P Region 2. Atlanta, Office of the Director 80/05/08
 See
- 8007020192 Forwards IE Info Notice 80-22, "Oreskdowns In Contamination Control Programs " No written response required O'REILLY, J.P., Region 2, Atlanta, Office of the Director 80/05/28 to
- 8007210488 Forwards IE Circular 80-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies" No written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007010225 Forwards 1E Info Notice 80-23, "Lose of Buction to Emergency Feedwater Pumps" No written rasponse required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 60/05/29 ip
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs," No written response required CYREILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/10

- 8007160287 Forwards IE Info Notice 80-27, "Degradation of Reactor Conlent Pump Studs " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director \$0/06/11 ip
- E0072303B4 Forwards IE Info Notice E0-28, "Prompt Reporting of Info in Accordance W/10CFRSD 55(e)" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director. 90/06/13. 3pp
- 8007270344 Forwards IE Insp Repts 50-438/80-08 & 50-439/80-08 on 800327-30 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/16 2pp
- --8007270361 IE Insp Repts 50-438/80-08 & 50-439/80-08 on 800527-30. No noncompliance noted Major areas inspected containment prestressing, receiving & atorage insp & IE Bullatins 79-28 & 60-03 CANTRELL, F & Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIGHT, R W Region 2, Atlanta, Office of the Director 60/06/16 Spp
- B007020391 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director, 80/06/20,
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Daminoralized Water 8gs & Resultant Internal Contamination of Personnel." No written response required. O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/06/24, to
- 8007230233 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters Hiether A or D Output Codes " Hritten response required. IE Circular 80-16 also encl. No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007100205 Responds to NRC 600606 ltr re violations noted in IE Insp Repts 50-438/60-07-02,50-439/60-07-02,50-438/60-07-01 & 50-439/80-07-01 Corrective actions welder & rod room attendants retrained to Welding matl control requirements MILLS,L M. Tennesses Valley Authority 60/06/30, 4pp.
- 8007100169 Forwards revision to 800602 response to infraction noted in IE Insp Rept 50-438/80-06 QC Investigation Rept 3619 was written to disposition improperly routed cables. Hork release was written to aliminate conduit misrouting HILLS: L M Tennessee Valley Authority 80/07/01. 3pp.
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment liner penetration walds Penetrations at Sequoyah, Watts Bar & Bellafonte contain flued head design. Dasign for Yellow Creek not yet completed MILLS, L. N. Tennesses Valley Authority 80/07/08 5pp.
- 8 Reportable occurrences, LERs & related correspondence
- 8007300167 Fourth interim deficiency rept re upper stressing head for rock anchor Util & post-tensioning contractor metallurgical investigations are incomplete Record of math furnished by contractor will appear in final rept OILLELAND, J E Tennesse Valley Authority 76/04/12, 2pp.
- 8007100233 Forwards interim deficiency rept re const GA audit. HILLS.L M Tennessee Valley Authority 80/06/30 ip
- --8007100236 Interim deficiency rept re failure to document required insps of all permanent mechanical equipment since Jul 1979 Util reviewing available insp records & reinspecting equipment to determine possible damage # Tennassee Valloy Authority BO/06/30 ip
- B007100209 Forwards second interim deficiency rept re const QA audit deficiency MILLB.L M Tennessee Valley Authority B0/07/02, ip,
- --B007100213 Second interim deficiency rept re const (A audit deficiency. Welders & foremen retrained on 800522 Plan is being developed to ensure training for every certified welder & foreman * Tennessee Valley Authority 80/07/02. Ip

1

- 6007160650 Forwards final deficiency rept re violation of Inryco field installation procedures
 MILLS.L H Tennessee Valley Authority 80/07/07 ip
- --8007160656 Final deficiency rept re violation of Inryco field installation procedures Inryco GC documentation was signed by individuals other than those performing work Util issued stop work order for all quality related work on 800423 * Tennessee Valley Authority 80/07/07 2pp
- 8007160424 Eighth interim deficiency rapt re failure of expansion anchors to pass qualification tests Final resolution to NCR 871 was provided in 790720 rept NCR 898 will be resolved w/final resolution to IE Bulletin 79-02 Next rept by 810114 MILLS.L.M Tennessee Valley Authority 80/07/08 ip
- 9007280&60 Suppls 800630 response to deficiency noted in IE Insp Repts 50-438/80-07 & 50-439/80-07 Util is investigating time between discovery of potential concern & issuance MILLS, L M Tennessee Valley Authority 80/07/22 2pp
- 8007290725 Fourth interim deficiency rept re seismic response for primary branch lines Found not conservative for all pipe sizes under 1/2 of BBE loadings per Revisions i & 2 of B&H Spec 1391 Revision 3 to verify response spectra HILLS.L H Tennessee Valley Authority 80/07/23 2pp
- BOOT/290749 Third interim deficiency rept re two welds found lacking sufficient internal purge; during rework operations of chemical addition & boron recovery sys Caused by inadequate maint. Program being developed to check purging process MILLB.L.M Tennessee Valley Authority 80/07/23 2pp
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8007230001.Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREC-0660 & found in MREC-0694
 EISEN#KMT, D Q Division of Licensing 80/06/26 2pp
- 8007180276 Notification of 800723-24 meeting w/util & ANL in Bethesda. MD to review electrical, instrumentation & control frawings for conformance w/separation, redundancy & single failure ECURNIA, A. Licensing Branch 1 80/07/07 4pp
- 8007130546 Advises that facility diesel drawings have been transmitted Under separate cover to A Bournia, per NRC 800701 request MILLS, L M Tannessee Valley Authority 80/07/08 ip
- 8007130551 Advises that facility diesel generator drawings are being transmitted under separate cover to S Halverson.per NRC request MILLS.L.M. Tennessee Valley Authority 80/07/08 ip
- 8007300080 Forwards request for add1 info re GA program
 TEDESCO.R.L Assistant Director for Licensing 80/07/23 3pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UGB 771104 petition sought action re first protection for electrical cables EISENHAT; D. Q. Division of Licensing. 80/06/25 89pp.
- D. Advisory Committee on Reactor Bafeguards reports & correspondence
- 7705140021 Forwards portion of Bellefonte Subcommitte meeting transcript questioning whether operator could diagnose accident & assess core status.
 BENDER, M ACS Advisory Committee on Reactor Safeguards 79/04/05.
- G. Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/05/08

- 8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/05/29
- 8007220029 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/10
- 8007160287 Forwards 1E Info Notice 80-27. "Degradation of Reactor Coplant Pump Stude " No specific action or response O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/11
- 8007250384 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/13
- 8007270344 Forwards IE Insp Repts 50-438/80-08 % 50-439/80-08 on 800527-30 No noncompliance noted MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --8007290361 JE Insp Repts 50-438/80-08 & 50-439/80-08 on 800527-30 No noncompliance noted Major areas inspected containment prestressing receiving & storage insp & IE Bulletins 79-28 & 80-03 CANTRELL, F 8 Region 2. Atlanta, Reactor Construction & Engineering Support Branch WRIGHT, R & Region 2, Atlanta, Office of the Director 80/04/14 8pp
- 800702039: Forwards IE Circular 80-:5, "Loss of Reactor Coclant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007170070 Forwards IE Circular 80-14, "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/24
- 8007230253 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/2 80/04/27
- 8007100203 Responds to NRC 800606 ltr re violations noted in IE Insp Repts 50-438/80-07-02,50-439/80-07-02,50-438/80-07-01 & 50-439/80-07-01 Corrective actions welder & rad radm attendants retrained to welding malt control requirements MILLS,L M Tennessee Valley Authority 80/06/30 4pp
- S Reportable accurrences. LERs & related correspondence
- 8007300167 Fourth interim deficiency rept re upper stressing head for rock anchor Util & post-tensioning contractor metallurgical investigations are incomplete Record of matl furnished by contractor will appear in final rept OILLELAND, J E Tennessee Valley Authority 76/04/12 2pp
- 8007100233 Forwards interim deficiency rept re const GA audit MILLS:L N Tennessee Valley Authority 80/06/30 ip
- --8007100236 Interim deficiency rept re failure to document required insps of all permanent mechanical equipment since Jul 1979 Util reviewing available insp records & reinspecting equipment to determine possible damage # Tennessee Valley Authority 80/06/30 lp
- 8007100209 Forwards second interim deficiency rept re const QA audit deficiency MILLS:L M Tennessee Valley Authority 80/07/02 ip
- ~-8007100213 Second interim deficiency rept re const GA audit deficiency Welders & foremen retrained on 800522 Plan is being developed to ensure training for every certified welder &
 - Tennessee Valley Authority B0/07/02 ip

- 8007140650 Forwards final deficiency rept re violation of Inryco field installation procedures
 MILLS:L M Tennessee Valley Authority 60/07/07 1p
- --8007160656 Final deficiency rept re violation of Inryco field installation procedures Inryco QC documentation was signed by individuals other than those performing work Util issued stop work order for all quality related work on 800423 * Tennessee Valley Authority 80/07/07 2pp
- B007160424 Eighth interim deficiency rept re failure of expansion anchors to pass qualification tests final resulution to NCR B71 was provided in 790720 rept NCR B98 will be resulved w/final resulution to IE Bulletin 79-02 Next iept by 810114 MILLS.L M Tunnessee Valley Authority 80/07/08 ip
- 8007280660 Supple 800630 response to deficiency noted in IE Insp Repts 50-438/80-07 & 50-439/80-07 Util is investigating time between discovery of putential concern & issuance MILLE, L M Tennessee Valley Authority BO/07/22 2pp
- B007290725 Fourth interim deficiency rept re seismic response for primary branch lines Found not conservative for all pipe sizes under 1/2 of SBE loadings per Revisions 1 & 2 of B&H Spec 1391 Revision 3 to verify response spectra MILLS.L M Tonnessee Valley Authority B0/07/23 2pp
- 8007290749 Third interim deficiency rept re two welds found lacking sufficient internal purge, during rework operations of chemical addition & boron recovery sys Caused by inadequate maint Prngram being developed to check purging process MILLG.L M Tennessee Valley Authority 80/07/23 2pp
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- BOO7020214 Forwards NRC Ofc of Nucleor Reactor Regulation BOO428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCORL Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D Q Division of Licensing 80/06/26 2pp
- 8007130540 Submits list of changes util plans to make re environ monitoring program during const Rationale for changes oncl DAVIDSON.D R Cleveland Electric Illuminating Co 80/07/07 Spp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EXSENHUT.D G Division of Licensing 80/06/25 89pp
- # General correspondence
- 8007230542 Forwards NRC 1979 Annual Rept in response to 800621 request re progress of nuclear power & regulations on power plants Unit I will start operation in 1984 & Unit 2 in 1988 Cover sheet only encl DENTON.HR Office of Nuclear Reactor Regulation, Director BO/Od/27 2pp
- 8007230109 Forwards, under separate cover, acceptance review copy of OL application, consisting of application & environ rept for placement in Perry, OH Public Library Util will submit FBAR on 800904 for review BOUDER. J L Division of Rules and Records 80/07/07 ip
- M Antitrust correspondence
- 8007140231 Forwards Director of Nuclear Reactor Regulation order further modifying 800513 order w/respect to licenses & parmits for facilities BALTZMAN,J Utality finance Branch 80/06/11 1p
- 8007140256 Forwards Director of Nuclear Reactor Reculation order further modifying 800913 order w/respect to licenses & permits for facilities SALTZMAN.J Utility Finance Branch 80/06/11 ip

- --8007140265 Order granting extension until 800709.for Claveland Floctric Illuminating to to file amend to tariff w/FERC as required by 800513 order DENTON,H R Office of Nuclear Reactor Regulation, Director by 800513 or a DENTON, H R O
- 80071408/9 Conditional request for hearing re Commission G00513 order re mod of transmission tariff Urges mod of order to bring consistency w/FERC tariffs in Opinion 84 or institution of hoaring Util protest before FERC & Certificate of Svc encl GOLDBERG, R, WAONER, T & Cleveland, CH GOLDBERG, R Goldberg, Fieldman & Hjelmfelt 80/07/09 14pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007140551 Forwards IE Bullotin 80-13. "Cracking in Core Spray Spargers" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/12
- 8007090194 Forwards IE Insp Repts 50-440/80-07 & 30-441/80-07 on 800905-07 & notice of violation FIDRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/21 2pp
- --8007090156 Notice of violation from insp on 800505-07 * Region 3. Chicago, Office of the Director 80/0
- --BOD7090139 IE Insp Repts 50-440/BO-07 & 30-441/BO-07 on BOD303-07
 Noncompliance noted inadequate issuance of documents,
 inadequate quality records, inadequate instructions & failure
 to follow procedures for soil placement
 HAYES, D W Region 3, Chicago, Reactor Construction & Engineering
 Support Branch GALLAGHER, E J. LANDSMAN, R L Region 3, Chicago,
 Office of the Director BO/05/19 App
- 8007090176 Forwards IE Insp Repts 50-440/80-06 & 50-441/80-06 on 800421-24 & notice of violation FIDRELLI.9 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/21 2pp
- ---B007090176 Notice of violation from insp on 800421-24 * Region 3, Chicago, Office of the Director 80/0
- --8007070179 IE insp Repts 50-440/80-06 & 30-441/80-06 on 800421-24
 Noncompliance noted failure to identify component to be
 covered by 9A program & inadequate indectrination &
 training of personnel
 HAYES.D W Region 3, Chicago, Reactor Construction & Engineering
 Support Branch HUGHEB.J, LANSMAN,R B Region 3, Chicago,
 Office of the Director 80/05/16 App
- 8007010137 Forwards IE Info Notice 80-23, "Loos of Buction to Emergancy Feedwater Pumps " No written response required KEPPLER, J G Region 3, Chicage, Office of the Director 80/05/27
- 8007160725 Forwards IE lnsp Repts 50~440/80-08 & 50~441/80-08 on 800906-09 & notice of violation FIGRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/06/04 2pp
- --B007160734 Notice of violation from insp on 800506-09 * Region 3, Chicago. Office of the Director B0/0
- --B007160741 IE Insp Repts 50-440/B0-08 & 30-441/B0-08 on B00506-09
 Noncompliance noted failure to sperify appropriate codes or
 stds in purchase order
 LEE.E W Region 3, Chicago, Office of the Director
 DANIELBON, D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch B0/06/0R App
- 8007220178 Forwards IC Info Notice 80-26. "Evaluation of Contractor QA Programs" No written response required KEPPLER, J. G. Region 3, (hicago, Office of the Director 80/06/10
- 8007140360 Forwards IE Bulletin 80-14. "Degradation of BWR Beram Discharge Vol Capability " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/12
- 8007280653 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 95(e) " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/06/13

- 8007020363 Forwards IE Circular 80-15, "Loss of Reactor Loclant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/20 10
- B007170465 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KFPPLFR.J Q Region 3. Chicago. Office of the Director 80/06/24 is
- 8007230310 Forwards IE Bulletin 80-16, "Potential Misappiication of Rosempunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 aiso enci No written response required KEPPLER, J © Region 3, Chicago, Office of the Director 80/04/27 is
- 0007180353 Submits add1 info re response to IE Bulletin 60-09 Litton Industrial Products. Inc & Fisher Co. Inc supplying Model NH-90 series hydramotor actuators Deficiencies described in IE Bulletin 80-09 will not affect performance of valves DAVIDSON, D R Cleveland Electric Illuminating Co 80/07/03 2pp
- 8007230101 Forwards suppl info to 800618 response to IE Bulletin 80-09 re hydramotor actuator deficiencies Litton Industrial Products, Inc. actuators use Number 2 springs & have no possibility of being fabricated from incorrect matl DAVIDSON, D R Cleveland Electric Illuminating Co 80/07/03 2pp
- 8007180588 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 FIORELI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --BOO71BO591 Responds to NRC.BO0521 ltr re violations noted in IE Insp. Repts 50-440/BO-06 & 50-441/BO-06 Training program cumplies w/NRC requirements Drawing D-220-002 to be revised to show seismically adequate lighting supports DAVIDBON.D.R Cleveland Electric Illuminating Co BO/06/23 4pp
- BO07180406 Forwards response to IE Bulletin 80-08 re examination of containment liner penetration welds Lists penetrations w/ flued head design DAVIDSON, D R Cleyeland Electric Illuminating Co 80/07/10 5pp
- 8007180582 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07 FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- BOO72303i3 Ack receipt of BO0703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/B0-08 & 50-441/B0-0B FIDRELLI,0. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/15 ip
- --B007230321 Responds to NRC 800604 ltr re violations noted in IE Insp Repts 50-440/80-08 & 50-441/80-08 Corrective actions obtained codes & stds for Pullman Power Products welding matl. DAVIDBON.D R Cleveland Electric Illuminating Co 80/07/03 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007180495 Ack receipt of 800630 final deficiency rept re Rosemount Model 510 DU trip calibr units/ii52 pressure transmitters Review will be completed during future insp. FIDRELLI, 9 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/14 lp
- 8007140534 Part 21 rept re deficiencies of Cutler-Hammer motor control ctrs Cause undetermined Proposes that starter units u/improper wire be returned to manufacturer for rewiring & that splice plate carriage bolts be replaced DAVIDSON, D. R. Cleveland Electric Illuminating Co. 80/06/25, 2pp
- B007080294 Final deficiency rept re Rosemount Models 310 DU trip/calibr units & 1152 pressure transmitters Originally reported by GE per Part 21 in May 1980 Amplifier boards & trip units will be replaced beginning Sept 1980 w/completion by 810101 DAVIDSON: D R Cleveland Electric Illuminating Co 80/06/30 2pp

- B00716059B Interim deficienty tept re use of None-bol 7-0015-7 CWS polyvinyl alchohol film, water soluble purge dam mat1 Util is in process of identifying deficient matl & having chemical analysis performed Final rept provided by B01215 DAVIDSON, D R Clevoland Electric Illuminating Co 80/07/11 3pp
- 8007180545 Ack receipt of 800625 interim deficiency rept re Gutler-Hammer mater control etrs Final rept will be reviewed upon receipt FIDRELLI, G. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/14 ip
- DOCKET 50-441 PERRY NUCLEAR PUWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8007020214 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition mede w/min disruption to engoing activities TEDEBCO, R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy to requirements to be met for current OL applications as derived from NURCG-0660 & found in NURCG-0674
 EISENHUT, D 0 Division of Licensing 80/06/26 2pp
- B007150940 Submits list of changes util plans to make re environ monitoring program during count Rationale for changes encl DAVIDBOND R Cleveland Electric Illuminating Co 80/07/07 5pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCG 780902 potition for reconsideration of 780413 memorandum & order UCB 771104 potition sought action re fire protection for electrical cables EISCNHUT,D 0 Division of Licensing 80/06/25 87pp
- H Conoral correspondence
- B007230542 Forwards NRC 1979 Annual Rept in response to B00621 request reprogress of nuclear power & regulations on power plants Unit i will start operation in 1984 & Unit 2 in 1988 Cover sheet only encl
 DENTON.H R Dffice of Nuclear Reactor Regulation, Director B0/06/27 2pp
- 8007230i09 Forwards, under separate cover, acceptance review copy of OL application, ronsisting of application & environ rept for placement in Perry, OH Public Library Util will submit FSAR on 800904 for review SOUDER, J. L. Division of Rules and Recurds 80/07/07 ip
- M Antitrust correspondence
- B007140251 Forwards Director of Nuclear Reactor Regulation order further modifying B00913 order w/respect to licenses & permits for facilities BALTZMAN, J Utility Finance Branch 60/06/11 1p
- 8007140256 Forwards Director of Nuclear Reactor Regulation order further modifying 800513 order w/respect to licenses & permits for facilities BALTZMAN.J Utility Finance Branch 80/06/11 ip
- --8007140265 Order granting extension until B00709, for Cleveland Electric Illuminating Co to file amend to tariff w/FERC as required by B00913 order DENTON, HR Office of Nuclear Reactor Regulation. Director 80/06/ii 2pp
- 8007140B75 Conditional request for hearing re Commission 8005f() order re mod of transmission tariff Urgos mod of order to bring consistency w/FCRC tariffs in Opinion 84 or institution of hearing Util protost before FFRC & Certificate of Svc oncl GDLDBERG,R, WAONER,T C. Cleveland, ON GULDBERG,R Goldberg, Fieldmen & Hjelmfelt 80/07/09 14pp
- 8007270533 Response in opposition to City of Cleveland, Dit 800409 request for hearing re Director of Nuclear Reactor Regulation 800513 order filing, requesting tariff w/FERC, brings contraversy to end w/o littgous course REYNOLDS, W D , IAMLER, R E Cleveland Electric lituminating Co REYNOLDS, W B Shaw, Pittman, Potts & Trewbridge 60/07/25 9pp

- @ Inspection reports. IE Bulletins & correspondence
- 8007140551 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director #80/05/12
- 8007090154 Forwards IE Insp Repts 50-440/80-07 & 50-441/80-07 on 800505-07 & notice of violation FIORELLIAG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8007070156 Notice of violation from insp on 800505-07 * Region 3. Chicago, Office of the Director 80/05/19 2pp
- --8007090159 IE Insp Repts 50-440/80-07 & 50-441/80-07 on 800505-07
 Noncompliance noted inadequate issuance of documents,
 inadequate quality records, inadequate instructions & failure
 to follow procedures for soil placement
 HAYES,D W Region 3, Chicago, Reactor Construction & Engineering
 Support Branch GALLAGHER,E J , LANDSMAN,R L Region 3, Chicago,
 Office of the Director 80/05/19 6pp
- 8007090176 Forwards IE Insy Repts 50-440/80-06 & 50-441/80-06 on 800421-24 & notice of violation FiORELLI, O Region G. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- ~~8007090178 Notice of violation from insp on 800421-24 • Region 3, Chicago, Office of the Director 80/05/16 Ip
- --8007090179 IE Insp Repts 50-440/80-06 & 50-441/80-06 on 800421-24
 Noncompliance noted failure to identify component to be
 covered by 6A program & inadequate Indoctrination &
 training of personnel
 HAYES,D W Region 3. Chicago, Reactor Construction & Engineering
 Support Branch HUGRES, J. LANDEMAN.R B Region 3. Chicago,
 Office of the Director 80/05/16 App
- B007010137 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/05/29
- 8007160725 Forwards 1E Insp Repts 50-440/80-08 & 50-441/80-08 on 800506-09 & notice of violation FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007160734 Notice of violation from INSP on 800306-09
 # Region 3, Chicago, Office of the Director 80/06/02, ip
- --8007160741 IE Insp Repts 50-440/80-08 & 50-441/80-08 on 800506-09.
 Noncompliance noted failure to specify appropriate codes or stds in purchase order
 LEE,E W Region 3, Chicago. Office of the Director
 DANIELSON,D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch 80/06/02 4pp
- B007220178 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/06/10
- 8007140360 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director BO/06/12
- 8007280653 Forwards IE info Notice 80-28. "Prempt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required XEPPLER, J G Region 3, Chicago. Office of the Director BQ/06/13 ip
- 8007020365 Forwards IE Circular 80-15. "Loss of Reactor Goolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/06/20.
- 8007170465 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/06/24

- 8007230310 Forwards IE Sulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Mritten response required IE Circular 80-16 also encl No written response required KEPPLER.J G. Region 3. Chicago, Office of the Director 80/06/27.
- 8007150553 Submits add1 info re response to IE Bulletin 80-09.Litton Industrial Products Inc & Fisher Co.Inc supplying Model NH-90 series hydramotor actuators Deficiencies described in IE Bulletin 80-09 will not affect performance of valves DAVIDEON, D R Cleveland Electric Illuminating Co 80/07/03 2pp
- BOO7230101 Forwards suppl info to BOO618 response to 1E Bulletin 80-09 re hydramotor actuator deficiencies Litton Industrial Products, Inc. actuators use Number 2 springs & have no possibility of being fabricated from incorrect mat 1 DAVIDSON, D R Cleveland Electric Illuminating Co 80/07/03. 2pp
- 8007180588 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 FIRRELIA Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --8007180591 Responds to NRC 800521 ltr re violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 Training program complies W/NRC requirements Brawing 0-220-002 to be revised to show seismically adequate lighting supports DAVIDSON, D R Cleveland Electric Illuminating Co. 80/06/29 4pp.
- BOO7:80406 Forwards response to 1E Bulletin 80-08 re examination of containment liner penetration welds Lists penetrations w/ flued head design DAVIDSON.D R Cleveland Electric Illuminating Co. 80/07/10. Spp.
- 8007:80582 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07 FIORELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/10 lp
- --8007180585 Forwards response to NRC 800521 ltr re violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07. Corrective actions GC Procedure 8 revised analyzed compaction equipment & GC procedure for soil insp being revised.

 DAVIDSON, D. R. Cleveland Electric Illuminating Co. 80/06/23. App.
- BOO7230313 Ack receipt of BOO703 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-440/BO-08 t 50-441/BO-0B FIDRELLIO Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/07/15 ip.
- --800723032i Responds to NRC 800404 ltr re violations noted in IE insp. Repts 50-440/80-08 & 50-441/80-08 Corrective actions: obtained codes & stds for Pullman Power Products welding matl DAVIDBON, D. R. Cleveland Electric Illuminating Co. 80/07/03. 3pp.
- B Reportable occurrences, LERs & related correspondence
- 8007180475 Ack receipt of 800630 final deficiency rept re Rosemount Model 510 DU trip calibr units/1152 pressure transmitters. Review will be completed during future insp FIORELLI, O Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/14 ip
- B0070B0294 Final deficiency rept re Rosemount Models 510 DU trip/calibrunits & 1152 pressure transmitters Originally reported by 9E per Part 21 in May 1980 Amplifier boards & trip units will be replaced beginning Best 1980 w/completion by 810101.
 DAYID80N.D R Cleveland Electric Illuminating Go. B0/06/30. 2pp.
- 8007i60598 Interim deficiency rept re use of Mono-Bol 7-0015-3 CMB polyvingl alchohol film,water soluble purge dam matl. Util is in process of identifying deficient matl & having chemical analysis performed final rept provided by 801215. DAYIDBON.D R Cleveland Electric Illumineting Co. 80/07/11. 3pp.
- 8007180545 Ack receipt of 800625 interim deficiency Pept re Cutler-Hammer motor control ctrs. Final rept will be reviewed upon receipt.
 FIGRELLI.O Reginn 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/07/14 ip

į

DOCKET 30-443 BEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

- B007210013 Confirms request for B00703 meeting w/util in Seabrook.NH to introduce NRC senior resident inspector & discuss quality matters re const CARLBON.R T Region i. Philadelphia, Reactor Operations Nuclear Bupport Branch B0/06/25 ip
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0664 EISENHUT, D Q Division of Licensing 80/06/26
- 8007180062 Notifies that ABME Code Case N-103-1 (17:5-1) is acceptable & may be used in const of components for facilities Use of code case should be documented in FBAR YOUNGBLOOD, B J Licensing Branch 1 B0/07/09 2pp
- BO072B0439 Bubmits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH.D Yankes Atomic Electric Co 80/07/24 7pp

9 Adjudicatory correspondence

- B007020402 Order granting extension until 800711 for Commission to elect whether to review ALAB-422 & ALAB-561
 CHILK.8 J Diffice of the Secretary of the Commission 80/06/27
- 8007140409 Submits Town of Balisbury, NA Article 13, approved at 800513 town meeting, re F Kramer petition opposing OL for Public Svc Commission of NH Area surrounding facility cannot be safely syacouted & no town funds will be spent MCRSE, W T Salisbury, NA 80/06/30 lp
- 8007140497 Order granting extension until 800801 for Commission to review ALAB-422 & ALAB-561 HOYLE, J C Office of the Secretary of the Commission 80/07/10

H General correspondence

- B007020090 Responds to 791011 ltr requesting const of plant be halted until safe evacuation plan can be achieved. Licensee must submit evacuation study for NRC review & approval before OL DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/11 2pp
- --8007020096 Requests that NRC reply to SC Dunfmy 791011 ltr opposing plant const until adequate evacuation plan is achieved Supporting documentation encl SEAL.H M President of UB & Executive Offices 79/10/19 App
- BO07100421 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within next yr DENTON.HR Office of Nuclear Reactor Regulation, Director 80/06/11 2pp
- 8007100424 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within nest yr DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp
- 8007250519 Forwards IE Insp Repts 50-443/80-01 & 50-443/80-04 citing violations re Cadwell spliting & weld rod control in containment bldg W/o encl CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/30 lp
- 8007230622 Responds to 800508 ltr to President Carter re facility licensing NRC reviewed environ impacts of project prior to making decision on CP issuance. Facility poses no threat to environ or public health & safety YOUNGBLOOD, BJ Licensing Branch 1 80/07/15 2pp
- B007240474 Partial response to FDIA request for five categories of documents re facility licensing proceeding Forwards NUREO-0348 & 800311 & 0702 ltrs Request has been circulated for addit mat that may be available. Ltrs only encl FELTON.J M Division of Rules and Records 80/07/21 ip

I Financial information

- 80070800i0 Forwards Annual Financial Rept 1979 for each owner of facility RITSHER.J A Ropes & Gray 80/07/03 2pp
- --800708001i Annual Financial Rept 1979

 * Public Service Cu of New Hampshire 80/07/03 25pp
- --8007080012 Annual Financial Rept 1979 * United Illuminating 80/01/04 30pp
- --8007080014 Annual Financial Rept 1979 * New England Power Co 80/01/25 2000
- ~~8007080016 Annual Financial Rept 1979 * Central Maine Power Co 80/02/14 34pp
- --8007080018 Annual Financial Rept 1979 * Central Vermont Public Service Corp 80/02/i5 33pp
- --8007080019 Annual Financial Rept 1979
 * Fitchburg Gas & Electric Light Co 80/02/07 2500
- --8007080020 Annual Financial Rept 1979
 * Eastern Utilities Associates 80/03/06 3300
- -- 8007080022 Annual Financial Rest 1979 New Bedford Gas & Edison Light Co 80/03/28
- --8007080025 Annual Financial Rept 1979 * Hudson Light & Power Dept 80/07/03 14pp
- --8007080028 Annual Financial Rept 1979
 * Vormont Electric Cooperative, Inc 80/03/07 24op
- --8007080031 Annual Financial Rept 1979 * Bangor Hydro-Electric Co 80/0∂ 80/02/26 25pp
- --B007080033 Annual Financial Rept 1979
 * Taunton Municipal Lighting Plant 80/02/22 190 o
- --B0070B0037 Annual Financial Rept 1979
 * Massachusetts Municipal Wholesale Co

80/03/03 14gs

- -8007080038 Annual Financial Rept 1979 * Maine Public Service Co 80/03/ B0/03/15 21pp
- --8007080040 Annual Financial Rept 1979
 * Connecticut Light & Power Co 8 80/03/14 21pp
- G Inspection reports, IE Bulletine & correspondence
- 8007010265 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/05/29 ip
- 8007010219 Ack receipt of 800505 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-443/80-03 & 50-444/80-03 Region i, Philadelphia, Office of the Director CARLSON R T
- --8007010223 Responds to NRC 800401 ltr re violations noted in lE Insp Repts 50-443/80-03 & 50-444/80-03 Corrective actions procedures re atud welding insp instituted DEVINCENTIS.J Public Service Co of New Hampshire 80/05/05
- --8007010229 Forwards IE Insp Repts 50-443/80-03 & 50-444/80-03 on 800226-28 & notice of violation CARLSON,R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --8007010232 Notice of violation from insp on 800226-28 * Region 1, Philadelphia, Defice of the Director B0/03/31 1a

- --8007010235 IE Insp Repts 50-443/80-03 % 50-444/80-03 on 800226-2B Noncompliance noted util failed to conduct stud welding insp as required & failed to rontrol changes to assure affected contractor procedures CERNE, A C , MCGAUGHY, R W Region 1, Philadelphia. Office of the Director 80/03/31 7pp
- 8007210613 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Frograms " No written response required GRIER:8 H Region 1, Philadolphia, Office of the Director 80/06/10 1p
- 8007140363 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs 'No specific action or response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/06/11 In
- BO07280616 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director BO/06/13 ip
- 8007020524 Forwards 1E Circular 80~15, "Loss of Reactor Copiant Pump Gooling & Natural Circulation Cooldown" No written response required GRIER: II H Region 1, Philadelphia, Office of the Director 80/06/20 ip
- 8007160740 Forwards IE Circular BO-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIERS H Region i, Philadelphia, Office of the Director BO/06/24 lp
- 8007210281 Forwards IE Info Notice 80-24. "Low Level Radwaste Durisl Criteria " No written response required GRIER.B H Region I. Philadolphia. Office of the Director 80/06/25 lp
- 8007250623 Responds to IE Bulletin 80-06, "Examination of Containment Liner Penetration Welds " Each unit has 19 penetrations of flued head design All flued bead penetrations to be butt welded to sleeves using consumable inserts DEVINCENTIS.J Public Service Co of New Hampshire 80/06/25 2pp
- 800723017B Forwards IE Builetin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ORIER.B H Region i. Philadelphia. Office of the Director BO/06/27 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007010182 Ack receipt of 800315 final deficiency rept re undetected failure in engineered safety features actuation sys CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 1p
- 8007170389 Ack receipt of 800530 interim deficiency rept on use of invalid seismic amplified response spectra Rept will be reviewed & evaluated CARLSON,R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/12 ip
- ---BO07170596 Advises that final deficiency rept re use of invalid seismic amplified response spectra originally promised for 800601 will be delayed until 800901 Ongoing corrective action not sufficiently complete to render final rept DEVINCENTIS, J Public Service CO of New Hampshire 80/05/30 200
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007210013 Confirms request for 800703 meeting w/util in Seabrook,NH to introduce NRC senjor resident inspector & discuss quality matters re const CARLSON.R T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/25 1p
- B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0670 & Burnd of NUREG-0670 & Division of Licensing B0/06/26 2pp

- 8007180062 Notifies that ASME Code Case N-103-1 (1715-1) is acceptable & may be used in const of components for facilities Use of rode case should be documented in FSAR YOUNGBLOOD. II J Licensing Branch I 80/07/09 2pp
- B007280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH D Yantee Atomic Electric Co 80/07/24 7pp
- @ Adjudicatory correspondence
- B007020602 Order granting extension until 600711 for Commission to elect whether to review ALAB-422 & ALAB-561 CHILK, S. J. Office of the Secretary of the Commission 60/06/27
- B007140409 Submits Town of Balisbury.MA Article 13, approvad at 800313 town mosting, re F Kramer petition opposing OL for Public Elvc Commission of NH Area surrounding facility cannot be eafely evacuated & no town funds will be spent MORSE.W T Salisbury.MA 80/06/30 ip
- 8007140457 Order granting extension until 800801 for Commission to review ALAD-422 & ALAB-561 HDYLE,J C Office of the Secretary of the Commission 80/07/10
- H General correspondence
- B007020070 Responds to 79101J ltr requesting const of plant be halted until safe evacuation plan can be achieved Licensee must submit evacuation study for NRC review & approval before OL. 15 issued
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80706/11 2pp
- --B007020076 Requests that NRC reply to SC Dunfey 791011 ltr opposing plant const until adequate evacuation plan is achieved Supporting documentation onci SEAL.M M President of UB & Executive Offices 79/10/19 App
- 8007100421 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within next yr DENTON. HR Office of Nuclear Reactor Regulation, Director 80/06/11 2pp
- B007100424 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning roviews of plants under const will start within nest yr DENTON.HR Office of Nuclear Reactor Regulation. Director 80/06/11 2pp
- 8007230622 Responds to 800508 ltr to President Carter re facility licensing NRC reviewed environ impacts of project prior to making decision on CP issuance Facility poses no threat to environ or public health & safety YOUNOBLOOD, N J Licensing Branch 1 60/07/15 2pp
- 8007240474 Partial response to FDIA request for five categories of documents re facility licensing proceeding Forwards NUREO-0348 & 800311 & 0702 ltrs Request has boen circulated for addl matl that may be available Ltrs only encl FELTON.J M Division of Rules and Records 80/07/21 ip
- I Financial information
- 8007080010 Forwards Annual Financial Rept 1979 for each owner of facility RITEMER, J A Ropes & Gray 80/07/03 2pp
- --8007080011 Annual Financial Rept 1979 * Public Service Co. of New Hampshire 80/07/03 25pp
- --B0070B0012 Annual Financial Rept 1979 * United Illuminating 80/01/04 30pp
- --8007080014 Annual Financial Rept 1979 * New England Power Co 80/01/25 20pp
- ---B007080016 Annual Financial Rept 1979 * Central Maine Power Co 80/02/14 34pp

- --B007080019 Annual Financial Rept 1979
 * Fitchburg Gas & Electric Light Co 80/02/07 25pp
- --8007080020 Annual Financial Rept 1979
 * Eastern Utilities Associates 80/03/06 33pp
- ---8007080022 Annual Financial Rept 1979 * New Bedford Gas & Edison Light Co 80/03/28 44pp
- --8007080028 Annual Financial Rept 1979
 * Vermont Electric Cooperative, Inc. 80/03/07 24pp

- --8007080037 Annual Financial Rept 1979

 * Massachusetts Municipal Wholesale Co 80/03/03 15pp
- --8007080040 Annual Financial Rept 1979 * Connecticut Light & Power Co 80/03/14 21pp
- G Inspection reports, 1E Bulletins & correspondence
- 8007010265 Forwards 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/05/29 ip
- 8007010219 Ack receipt of 800905 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/80-03 & 50-444/80-03 CARLSON.R T Region 1, Philadelphia, Office of the Director 80/05/30 1p
- --B007010223 Responds to NRC B00401 ltr re violations noted in IE Insp Repts 50-443/80-03 & 50-444/80-03 Corrective actions procedures re stud welding insp instituted DEVINCENTIS,J Public Bervice Co of New Hampshire B0/05/05
- --8007010227 Forwards IE Insp Repts 50-443/80-03 & 50-444/80-03 on B00226-28 & notice of violation GARLEON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --8007010232 Notice of violation from insp on 800226-28 * Region 1. Philadelphia, Office of the Director 80/03/31 1p
- --8007010235 IE Insp Repts 50-443/80-03 & 50-444/80-03 on 800226-28 Noncompliance noted util failed to conduct stud welding insp as required & failed to control changes to assure affected contractor procedures CERNE.A C . MCGAUGHY,R W Region i, Philadelphia, Office of the Director 80/03/31 7pp
- B007210613 Forwards 1E Info Notice B0-26, "Evaluation of Contractor GA Programs " No written response required ORIEG, B H Region 1. Philadelphia, Office of the Director B0/06/10 ip
- B007160363 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRICE, B H Region 1, Philadelphia, Office of the Director 80/06/11 1p
- 8007280616 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required CRIER, B.H Region 1, Philadelphia, Office of the Director 80/06/13 1p

- 8007020524 Forwards IE Circulai 80-i5, "Loss of Reactor Goolant Pump Cooling & Natural Circulation Cooldown " No written response required GRICR.B H Region i, Philadelphia, Office of the Director 80/06/20 1p
- 8007160740 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/06/24 1p
- B007210281 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/06/25 lp
- B007250623 Responds to IE Builetin 80-08. "Examination of Containment Liner Penetration Welds " Each unit has 19 penetrations w/ flued head design All flued head penetrations to be butt welded to sleeves using consumable inserts DEVINCENTIS.J Public Service Co. of New Hampshire 80/06/25 2pp
- 8007230178 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl Na written response required ORICR, 8 H. Region I. Philadelphia. Office of the Director 80/66/27 2pp
- S Reportable occurrences, LERs & related correspondence
- 8007010182 Ack receipt of 800515 final deficiency rept re undetected failure in engineored safety features actuation sys CARLBON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 lp
- B007170889 Ack receipt of 800530 interim deficiency rept on use of invalid seismic amplified response spectra Rept will be reviewed & evaluated CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 1p
- --B007170596 Advisos that final deficiency rept re use of invalid seismic amplified response spectra originally promised for 800601 will be delayed until 800901 Ongoing corrective action not sufficiently complete to render final rept DEVINCENTIS. J. Public Service Co. of New Hampshire 80/05/30 2pp
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1
- A Application/construction stage documents & correspondence
- B007020224 Advises of filing of detailed electrical, instrumentation & control drawings submitted by TX Utils Generating Co Action taken in conformance w/NRC PM Operating Procedure 200, Revision I Drawings in Central Files only BURWELL.S Licensing Branch P 80/06/06 ip
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREQ-0660 & found in NUREQ-0694 EISENHUT.D g Division of Licensing 80/06/26 2pp
- B007180366 Forwards Freese & Nichols.Inc B00620 ltr in response to NRC B00415 request for addi info re floodplain mgt Response will be incorporated into util environ rept GARY.R J Teras Utilities Generating Co B0/07/10 3pp
- 8007240066 Summary of 800625 meeting brtween Assistant Director for Environ Technology & Assistant Director for Liconsing rempt, technical oversight & mechanics of environ review performance MULLER, DR Assistant Director for Environmental Technology TEDESCO, R L Assistant Director for Licensing 80/07/14 App
- 8007210478 Forwards electrical, instrumentation & control drawings to assist in plant review OARY, R J Texas Utilities Generating Co 80/07/15 2pp
- --8007210485 "Control Panel Schematic" Sheet 1 of 8 * De Laval Turbine Inc 76/07/16 ip
- ---8007210490 "Control Panel Schematic " Sheet 2 of 8 * De Laval Furbine Inc 76/07/16 ip

- --8007210496 "Control Panel Schematic " Sheet 3 of 8 4 Do Laval Turbine Inc 76/07/16 1p
- --8007210500 "Control Panel Schematic " Sheet 4 of 8 # De Laval Turbine Inc 76/07/16 ip
- --8007210504 "Control Panel Schematic" Sheet 5 of 8 * De Laval Turbine Inc 76/07/16 lp
- --8007210508 "Control Panel Schematic" Sheet 6 of 8 * De Laval Turbine Inc 76/07/16 lp
- --8007210510 "Control Panel Schematic" Sheet 7 of 8 * De Laval Turbine Inc 76/07/16 lp
- --8007210914 "Control Panel Schematic" Sheet 8 of 8 * De Laval Turbine Inc 76/07/16 tp
- --8007210517 "Interconnection Diagram" Sheet 1 of 2 * De Laval Turbine Inc 77/04/06 ip
- --B007210519 "Interconnection Diagram" Sheet 2 of 2 * De Laval Turbine Inc 77/04/06 ip
- --8007210927 "Schematics Diesel Generator Local Panel," as-built * Do Laval Turbing Inc * Delta Switchboard Co * Gibbs & Hill. Inc (subs of Dravo Corp) 76/07/16 lp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8007140053 Provides background info on schedule, content & form of facilities OL stage environ review for initiation of appropriate MEPA review & technical oversight functions list of reviewers; review schedule & DES outline encl SCHMENCER, A Licensing Dranch 2 80/06/26 8pp
- F Security, medical, emergency & fire protection plans
- BOO7110376 Requests rovisions & add1 info to safeguards contingency plan re evaluation of util application for DL Forwards statement of MRC positions Response should be submitted within 60 days Statement withheld (ref 10CFR2 790) BCHWENCER.A Licensing Branch 2 80/06/23 2pp
- 8007080282 Advises that upgraded emorgency plan for facility will be submitted by 800930 GARY.R J Texas Utilities Generating Co B0/06/30 ip

G Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D C Division of Licensing 80/06/25 87pp
- 8007090327 Exceptions to ASLB 800616 order re 800430 prehearing conference Order errod in rejecting intervenor Contentions 1.3.6(b)(e).8 & 10 & conditioning acceptance of Contentions 5 & 23 Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 80/06/30 4pp
- BOO7030246 Response in opposition to ASLB BOO616 order re BOO430 prehearing conference-ruling on admissibility of contentions Urges mad of order to delete Contentions 3, 4, 9, 11 & 17 & to reword Contention 23 Certificate of Syc enci REYNDLDS.N S. HORIN.W A. Texas Utilities Congrating Co. REYNDLDS.N S. Debevoise & Liberman SO/07/01 17pp
- 8007100255 Nemorandum & order dismissing fitizene Association for Sound Energy appeal from unpublished ASLB 800616 prehearing conference order rejecting contentions Interlocutory appeal is not permitted unless petition is denied in entirety BISHOP.C J Atomic Safety and Licensing Appeal Panel, 80/07/03 2pp
- 8007300366 Requests that missing pages from FSAR Amends 1-10, listed in encl. be forwarded along w/any addl amends Also requests that name be added to mailing list Certificate of Svc encl Related correspondence
 ELLIS.J Citizens Association for Yound Energy 80/07/07 5pp
- 8007310123 First set of interrogatories directed to applicant Requests details of signed sale negotiations Certificate of 8vc encl Related correspondence ELLIS. J Citirens Association for Bound Energy 80/07/07 App

- BOO7310167 Order affirming grant of add1 time for Citizens Association for Bound Energy to respond to applicant BOO701 motion & to file position to ASLB BOO616 order Five-day extension for Citizens for Fair Util Regulation re NUREO-0694 granted BOMERS. S Atomic Safety and Licensing Board Panel BO/07/10
- 8007170261 Forwards NUREG-0694, "TMI-Related Requirements for New OLs."
 per 800710 telcon Copies forwarded to Citizens for Fair
 Util Regulation & Association of Community Organizations for
 Reform Now W/o encl
 TURN, 6 E Hearing Branch 1 80/07/11 ip
- 8007220946 Motion for reconsideration of ASLB 800430 order for certification of denied contentions Maintains validity of contentions, especially Class 9 accident scenario Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 80/07/14 20pp
- 8007220559 Suppl to intervenor 800714 motion for reconsideration or certification of denied contentions re ASLB 800430 order Submits new info in support of Contention 1 re State of TX vs TX Utils companies Certificate of Svc enci ELIS.J Citizens Association for Sound Energy 80/07/14. 7pp.
- 8007180437 Response in opposition to TX Association of Community Organizations for Reform Now 800701 motion seaking reconsideration of 800616 order denying cetain proposed contentions Rewording must be denied W/Certificate of 8vc. REYNDLDS; N S . HORIN; M A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liborman 80/07/16 12pp
- B007230741 Response in opposition to TX Association of Community Organizations for Reform Now B00701 motion for reconsideration of ASLB B00616 order Orges denial of alternative motion for certification W/Gertificate of BVC TURK, B E Hearing Branch i B0/07/21 24pp
- 8007230748 Responso to applicants' 600701 objections re prehearing conference order & to applicants' motion for mod Urges deniai of requests re Contentions 3,4,9,17 & 23 Motion to delete Contention ii must be granted W/Certificate of 8vc TURK,6 E Hearing Branch I 80/07/21 18pp
- 8007290759 Order extending time until 800808 for Commission to review ALAD-599 CHILK, B. J. Office of the Bacratary of the Commission, 80/07/24 is
- G007310328 Response to Citizens Associatina for Sound Energy 900707 first set of interrogatories & requests for clarification. Explains communication w/public re electric util matters. W/affidavit.Certificate of Svc & supporting documentation REYNOLDS.N S . HORIN.H A Texas Utilities Generating Co REYNOLDS.N S . Debevoise & Liberman 60/07/28 36pp

M Antitrust correspondence

- B007010247 Forwards work order extending Hartley contract to B00531 W/o sncl BLUME.M B Antitrust Division B0/04/14 in
- 8007010264 Forwards signed stipulation abiding by ASLB 800331 protective order re Houston Lighting & Power corporate study W/o oncl BLUME, M B Antitrust Division 80/04/14 ip
- G007010298 Forwards documents mistakenly omitted from Hartlay documents W/o encl HDD0DDNA P. Antitrust Division B0/05/07 ip
- 8007210388 Reviews 800702 draft transmission svc settlement agræmment.
 Document found to be unacceptable due to provisions making
 Austin jurisdictional as practical matter for wheeling
 "Postage stamp" wheeling rate is not proper in TX
 BALOUGH, R. C. Austin, TX 80/07/10 2pp
- B007190425 Status rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept. Differences w/NRC re license conditions not yet resolved. Certificate of Svc encl GREEN, D Q Houston Lighting & Power Co * Baker & Botts. * Lowenstein, Newman, Reis, Axelrad & Toll 60/07/11 7pp
- 8007150431 Btatus rept on settlement negotiations Urges 60-day suspension of proceedings, including hearing date, due to continued negotiations w/Public Utils Board of City of Brownsyllbe TX. H/Certificate of Svc & pleading before FERC. BTAHL, D M. Centrel & Bouth West Corp BTAHL, D M. Isham, Lincoln & Beals. 80/07/11 26pp

- 8007150449 Status rept by Public Utils Board of City of Brownsville, TX re settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc encl PDIRIER.M R Brownsville, TX POIRIER.M R Spiegel & McDiarmid 80/07/11 dpp
- 8007i50500 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc encil CHANANIA.F D Antitrust Division 80/07/11 8pp
- 8007160625 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DDJ but agreement w/NRC may be reached re license conditions dealing w/bulk power wheeling rates. Certificate of Svc encl
 BAMPLESIM D , KNDITS, J B Texas Utilities Generating Co
 SAMPLESIM D Worsham, Forsythe & Sampels 80/07/11 6pp
- 8007170364 Status rapt re development of settlement discussions Urges denial of addl extension of time due to belief that no sattlement will be reached between DOJ & applicants Certificate of Svc encl
 CYPHERT.B S Justice.Dept of 80/07/11 App
- BD071703BB Second status rept re settlement negotiations progress Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc and JUHN,D F Affiliation Unknown JOHN,D F Medinaelectric Cooperative.Inc JOHN,D F McDermott,Will & Emery 60/07/11 App
- 8007210455 Bubmits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Cartificate of Bvc enci BURCHETTE, W H , RITTB, F H Northcutt Ely B0/07/11 App
- 8007160547 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests 800708 for briefs & 801006 for commencement of evidentiary hoaring Settlement does not appear to be possible Certificate of Svc encl
- B007220500 Buggests reconsideration of 800307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 MILLER, M E Atomic Safety and Licensing Board Panel B0/07/16. ip
- 8007220556 Order denying petitions for directed certification w/p prejudice to resubmission following ASLB determination BISHOP.C J Atomic Safety and Licensing Appeal Panel BO/07/18 2pp
- BOO7300418 Withdrawal of 770511 notice of appearance R Fabrikant responsible for all communications until further notice Centificate of Byc sncl GYPHERT.8 B Justice, Dept of BO/O7/R3 4pp
- 8007280620 Draws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DUJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 ip
- G007280527 Motion for extension until B00731 to file objections w/ proposed revision to ASLB B00717 prehearing conference order & notice of final prehearing conference Discussions w/ parties have commenced & must proceed LEHIS: G H Hearing Branch 2 B0/07/25 2pp
- --B007280636 Joint motion for clarification of ABLB 800716 memorandum containing decision to reconsider ABLB 800307 order resettlement documents Moyes for order establishing schedule for production of settlement documents M/Certificate of Syc FABRIKANT.R Justice.Dept of CHANANIA.F D . BLUME.H B Antitrust Division 80/07/25 8pp
- 8007300356 Order granting extonsion until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order MOLFE, BJ Atomic Safety and Licensing Board Panel 80/07/25. 1p.

N. Antitrust hearing transcripts

8007180008 Transcript of 800714 prehearing conference in Bethesda, MD re-settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel, 80/07/14 78pp

- B007250441 Proposed correction to 800409 prehearing transcript Certificate of Svc encl
 CRCEN, D G Houston Lighting & Power Co * Bater & Botts *
 Lowenstein, Newman, Reis, Axelrad & Toll B0/07/22 Spp
- **0** Inspection reports, IE Bulletins & correspondence
- 8007290328 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/31
- 8007180490 Discusses IE Insp Repts 50-445/80-il & 80-446/80-il on B00404 & forwards notice of violation 9EIDLE.W C Region 4. Dalias, Reactor Construction & Engineering Support Branch 80/04/09 2pp
- --B007iB0499 Notice of violation from insp on 800404 Noncompliance noted failure to follow piping installation procedures * Region 4, Dallas, Office of the Director 80/04/09 lp
- 8007240509 Ferwards IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRITIK V Region 4, Dallas, Office of the Director 80/05/16
- 8007110227 Forwards IE lnsp Repts 30-445/80-14 & 50-446/80-14 on B00313-16 No noncompliance noted SEIDLE:N C Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/05/23 Zpp
- --B007110234 IE Insp Repts 50-445/80-14 t. 50-446/80-14 on B00312-16 No nancompliance noted Major areas inspected Const activities. RCPB piping work & other safety-related piping work GILBERT.L D . HALL, R E Region 4. Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W A Region 4. Dallas, Office of the Director B0/05/23 4pp
- 8007020255 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28 in
- 8007210351 Forwards IE Circular 80-13, "Grad Strap Damage in Westinghouse Fuel Assemblies " No written reaponso required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/28
- B007010026 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required SEYRIT.K V Region 4, Dallas, Office of the Director B0/03/29 in
- B007170196 Responds to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies" Six vendors identified as potential suppliers of equipment containing ITT Owners hydramotor actuators Vendors confirmed no actuators supplied to facilities OARY.R J Texas Utilities Generating Co B0/06/10 ip
- B00722012B Forwards IE Info Nutice B0-26, "Evaluation of Contractor GA Programs" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director B0/06/10 in
- 8007110592 Ack receipt of IC losp Repts 50-445/80-13 & 50-446/80-13 No proprietary info GARY:R U Texas Utilities Generating Co 80/06/11 ip
- 8007160334 Forwards 1E info Notice 80-27, "Degradation of Reactor Coolant PUmp Studs " No specific action or response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/11
- 8007290077 Forwards IE Info Notice 80~20, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required SEYFRIT.K V Region 4, Dallas. Office of the Director 80/06/13
- 8007180567 Forwards JE Insp Repts 50-445/80-11 & 50-446/80-11 in Apr-May 1780 No noncomptionce noted BEIDLE:W C Region 4, Dallas, Reactur Construction & Engineering Support Branch 80/06/17 2pp

- --BOO7180574 IE Insp Repts 50-445/BO-il % 50-446/BO-il in Apr-May 1980 No noncompliance noted Major areas inspected safety-related page & equipment installation.cencrete repair activities, electrical installation & protection of major components TAYLOR, R G. CRUSSMAN, W A. Region 4. Dallas, Office of the Director BO/06/14 1Opp
- H007140455 Ack receipt of IE Insp Repts 50-445/80-14 % 50-446/80-14 on 800523 No propriotary info OARY,R J. Telas Utilities Generating Co. 80/06/18 Ip
- 8007140497 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-445/80-13 & 50-446/80-13 SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/19 ip
- --8007140502 Responds to NRC ltr to violations noted in IE lnsp Repts 50-445/80-13 % 50-446/80-13 Corrective actions mgt met w/welders to reaffirm importance of strict adherence to specified weld procedures GARY.R J Toras Utilities Generating Co 80/06/06 App
- 8007240057 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/20
- 8007170683 Forwards IE Circular 80-14, "Radigactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required SEYFRI7.K V Region 4, Dallas, Office of the Director 80/04/24
- 9007230370 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters W/Elther A or D Output Codes" Written response required IE Circular 80-16 also enci No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/27
- B Reportable occurrences, LERs & related correspondence
- 6007210162 PNS-IV-BO-010 group of approx tucive people harassing security force over period of five days State & local law enforcement authorities have been actively supporting security force KELLY.J Region 4. Dallas. Office of the Director 80/07/09 ip
- 8007210352 Updates 800421 deficiency rept re discrepancies involving installation & insp requirements for Class 5 non-nuclear safety-related piping supports FEAR is being revised Final rept will be forwarded by 800582 GARY.R J Teios Utilities Generating Co 80/07/14 ip
- DDCKET 50-446 COMANCHE PEAK STEAM ELECTRIC 5TA . UNIT 2

 A Applacation/construction stage documents & correspondence
- S007020224 Advises of filing of detailed electrical, instrumentation & control drawings submitted by TX Utils Oenerating Co Action taken in conformance w/RMC PM Depositing Procedure 208. Revision I Drawings in Central Files only DURWELL, S Licensing Branch 2 80/06/06 ip
- BO07230D01 Forwards statement of policy re requirements to be mot for current OL applications. As derived from NURFG-0660 & found in NURFG-0694
 EISENHUT.D @ Division of Licensing 80/06/26 2pp
- 8007180366 Forwards freese & Nichols.inc 800620 ltr in response to NRC 800419 request for add1 info re floodplain mgt Response will be incorporated into util environ rept GARY.R J Texas Utilities Generating Co 80/0//10 3pp
- 8007240066 Summary of 800625 meeting between Assistant Director for Environ Technology & Assistant Director for Licensing rempt technical overeight & mechanics of environ review performance
 MULLER-D R Assistant Director for Environmental Technology
 TEDESCORE Assistant Director for Licensing 80/07/14 4pp
- 8007210478 Forwards electrical instrumentation & control drawings to assist in plant review GARY. R J Texas Ubilities Menerating Co 80/07/15 2pp
- --8007210485 "Control Panel Schematic " Sheet 1 of 8 * De Laval Turbine Inc 76/07/16 ip

- --8007210490 "Control Panel Schematic " Sheet 2 of 8 * De Laval Turbine Inc 76/07/16 ip
- --8007210496 "Control Panel Schematic" Sheet 3 of 8 # De Laval Turbine Inc 76/07/16 ip
- --8007210500 "Control Panel Schematic" Sheet 4 of 8 * De Laval Turbine Int 76/07/16 ip
- ---8007210504 "Control Panel Schematic" Sheet 5 of B * De Laval Turbine Inc 76/07/16 1p
- --8007210508 "Control Panel Schematic" Sheet 6 of 8 * De Laval Turbine Inc 76/07/16 1p
- --8007210510 "Control Panel Schematic " Sheet 7 of 8 * De Laval Turbine Inc 76/07/16 ip
- --8007210514 "Control Panel Schematic " Sheet 8 of 8 * Do Laval Turbino Inc 76/07/16 ip
- --8007210517 "Interconnection Diagram" Sheet 1 of 2 * De Laval furbing Inc 77/04/06 ip
- ~~8007210519 "Interconnection Diagram " Sheet 2 of 2 * De Laval Turbine Inc 77/04/06 ip
- --8007210527 "Schematics Diesel Generator Local Panel," as-built * De Laval Turbine Inc * Delta Switchboard Co * Gibbs & Hill, Inc (subs of Dravo Corp) 76/07/16 ip
- D NRC Draft/Final Environmental Statements, supple & correspondence
- B007140053 Provides background info on schedule, content & form of facilities OL stage environ review for initiation of appropriate NEPA review & technical oversight functions List of revieuers, review schedula & DES outline encl
 SCHWENCER, A Licensing Branch 2 80/06/26 Opp
- F Security, medical, emergency & fire protection plans
- 8007110576 Requests rovisions & add1 info to safeguards contingency plan re evaluation of util application for GL Forwards statement of NRC positions Response should be submitted within 60 days Statement withheld (ref 10CFR2 770) SCHWENCER.A Licensing Branch 2 80/06/23 2pp
- 8007080282 Advises that upgraded emergency plan for facility will be submitted by 800930 GARY,R J Trans Utilities Generating Co 80/06/30 1p
- 9 Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition aought action re fire protection for eflectrical cables EISENHUT, D G Division of Licensing B0/06/25 B7pp
- 8007090327 Exceptions to ASLB 800616 order re 800430 prehearing conference Order erred in rojecting intervenor Contentions 1.3.6(b)(e).8 & 10 & conditioning acceptance of Contentions 5 & 27 Certificate of Svc encl ELLIS.
- 8007030246 Response in apposition to ASLB 800616 order re 800430 prehearing conference, ruling on admissibility of contentions Urges mod of order to delete Contentions 3, 4, 9, ii & 17 & to reword Contention 23 Certificate of Svc encl REYNOLDS, N S. HORIN, W A. Texas Utilities Generating Co
- 8007100255 Hemorandum & order dismissing Citizens Association for Bound Energy appeal from unpublished ABLB 800616 prehearing conference order rejecting contentions Interlocutory appeal is not permitted unless petition is defined in antirety BISMOP.C J Atomic Safety and Licensing Appeal Panel 80/07/03, 2pp
- B007300366 Requests that missing pages from FBAR Amends 1-10, listed in ruch, be forwarded along w/any add1 amends Also requests that name be added to mailing list Certificate of Svc encl Related correspondence,
 ELL18,J Citizens Association for Spund Energy 80/07/07 5pp

- B0073(0123 First set of interrogatories directed to applicant Requests details of signed sale negotiations Certificate of 3vc uncl Related correspondence
 - Citizens Association for Sound Energy 80,07/07 5pp
- 8007310167 Order affirming grant of addl time for Citizens Association for Sound Energy to respond to applicant 800701 motion & to file position re ABLB 800616 order Five-day extension for Citizens for Fair Util Regulation re NUREO-0694 granted BOWERS.E S Atomic Safety and Licensing Board Panel 80/07/10
- BOO7170261 Forwards NUREG-0694. "THI-Related Requirements for New Ols," per BOO710 telcon Copies forwarded to Citizens for Fair Util Regulation & Association of Community Organizations for Reform Now W/o encl
 TURK,S E Hearing Branch 1 90/07/11 1p
- B007220546 Motion for reconsideration of ASLB 800430 order for cortification of denied contentions Maintains validity of contentions, especially Class 9 accident scenario Certificate of Svc encl ELLIB, J Citizens Association for Sound Energy 80/07/14 20pp
- 8007220559 Suppl to intervenor 600714 motion for reconsideration or certification of denied contentions re ASLB 600430 order Submits new info in support of Contention i re State of TX ye TX Utils companies Certificate of Syc encl ELLIS.J Citizens Association for Sound Energy 80/07/14 7pp
- 8007180437 Response in opposition to TX Association of Community Organizations for Reform Now 800701 motion seeking reconsideration of 800616 order denying cetain proposed contentions Rewording must be denied W/Certificate of Svc REYNOLDS, N B, HORIN, W A Fexas Utilities Generating Co REYNOLDS, N B Deservice & Liberman 80/07/16 12pp
- B007230741 Response in opposition to TX Association of Community Organizations for Reform Now B00701 motion for reconsideration of ASLD B00616 order Urges denial of alternative motion for certification W/Certificate of Svi TURK B E Hearing Branch 1 B0/07/21 24pp
- G007230748 Response to applicants' 800701 objections re prehearing conference order & to applicants' motion for mod Urges denial of requests re Contentions 3.4.9:17 & 23 Notion to delete Contention 11 must be granted W/Certificate of Svc TURK 6 E Hearing Branch 1 80/07/21 18pp
- 8007290758 Order extending time until 800808 for Commission to review ALAB-599
 CHILK,S J Office of the Secretary of the Commission 80/07/24
- 8007310328 Response to Citizens Association for Sound Energy 800707 first set of interrogatories & requests for clarification Explains communication w/public re electric util matters W/affidavit.Certificate of Svc & supporting durumentation REYNOLDS,N S , HORIN,N A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 80/07/28 36pp

M. Antitrust correspondence

- \$007010247 Forwards work order extending Hartley contract to 800531 W/o BLUME, M B Antitrust Division 80/04/14 ip
- 8007010264 Forwards signed stipulation abiding by ASLB 800331 protective order re Houston Lighting & Power corporate study H/o encl BLUME.M B Antitrust Division 80/04/14 lp
- 8007010298 Forwards documents mistakenly omitted from Hartley documents W/o encl HODGDDN.A P Antitrust Division 80/05/07
- BOO7210388 Reviews BOO702 draft transmission svc settlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for wheeling "Postage stemp" wheeling rate is not proper in TX BALOUGH.R C Austin, TX BO/07/10 2pp
- BOO7130425 Btatus rept advising that absent change in DDJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Byc encl QREEN, D. Q. Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll BO/07/11 7pp

- 9007150431 Status rept on settlement negotiations Urges 60-day NOTIONAL STATUS rept on settlement negotiations urges ou-day suspension of proceedings including hearing date due to continued negotiations w/Public Utils Board of City of Brownsville TX W/Certificate of Svc & pleading before FERC STAHL.D M Central & South West Corp STAHL.D M Isham, Lincoln & Beale 80/07/11 24pp
- 8007150449 Status rept by Public Utils Board of City of Brownsville,TX re settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc entl POIRIER.M R Drownsville,TY POIRIER.M R Spiegel & McDiarmid 80/07/11 брр
- B007150500 Third status rupt on settlement progress Suggests 30-day min extension to pursue negatiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc oncl (HANANIA,F D Antitrust Division 80/07/11 Gpp
- 8007160629 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DOJ but agreement u/NRC may be reached re incense conditions dealing w/bulk power whosling rates Cortificate of Sive encl SAMPLES.M D. XMOTTS.J B. Toxas Utilities Generating Co SAMPLES.M D. Worsham, Forsythe & Sampels 80/07/11 6pp
- 800/170344 Status rept re development of mettiement discussions Urges denial of addl extension of time due to belief that no settlement will be reached between DOJ & applicants Certificate of Sov encl CYPKERT.9 B Justice.Dept of 80/07/11 App
- 8007170388 Second status rept re settlement negotiations progress Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc Affiliation Unknown JOHN, D.F. Medinael e, Inc. JOHN, D.F. McDeimott, Will & Emery JOHN, D F Medinaelectric Cooperative, Inc. 80/07/11 6pp
- 8007210455 Submits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Certificate of Sive encl BURCHETTE, W. H. . RITIS, F. H. Northoutt Ely 90/07/11 4pp
- G007160547 Hotton seeking reneval of BOJ G00521 motion to establish trial & other procedural dates Suggests 900908 for briefs & G01006 for commencement of evidentiary hearing Settlement does not appear to be pussible Certificate of Skc encl CYPHERT, S B , PARMENTER, F Justice, Dopt of 80/07/14 App
- 8007220500 Suggests reconsideration of 800307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 NILLER,M E Atomic Safety and Licensing Board Panel 80/07/16 ip
- 8007220556 Order denying petitions for directed certification w/o projudice to resubmission following ASLB determination BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/07/18
- B00730041B Withdrawal of 790511 notice of appearance R Fabilikant responsible for all communications until further notice Cortificate of Svc ancl CYPHERTS 8 Justice.Dapt of 80/07/23 App
- 0007280620 Draws attention to two pleadings that should be treated separately although stapled toyether NRC motion for extension of time & NRC/BDJ joint motion for clarification & for establishment of production schedule Antitrust Division 80/07/25 in
- B007280627 Motion for extension until 800731 to file objections w/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions w/ parties have commenced & must proceed LENIS.9 H Hearing Branch 2 80/07/25 2pp
- --B007280636 Joint motion for clarification of ASLB 800714 memorandum containing decision to reconsider ASLD 800307 order resettlement documents Moves for order establishing schedule for production of settlement documents W/Certificate of Svc FABRIKANT, R Justice Dept of CHANANIA, F D, BLUME, H B Antitrust Division 80/07/25 8pp
- 8007300354 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800/17 final prehearing conference order Atomic Safety and Licensing Board Panel 80/07/25 ip

N Antitrust hearing transcripts

- 8007180009 Transcript of B00714 prehearing Conference in Bethesda, MD re-settlement negotiations Pp 891-946

 * Atomic Safety and Licensing Doard Panel B0/07/14 78pp
- BOO7250441 Proposed correction to BOO409 prehearing transcript Cartificate of Svc encl
 OREEN, D G Houston Lighting & Power Co & Baker & Botts
 Lowenstein, Newman-Reis, Azelrad & Toll BO/07/22 Spp
- @ Inspection reports, IE Bulletins & correspondence
- 800725032B Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PCRV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4. Dalias. Office of the Director 80/03/31
- BOO7180490 Discusses IE Insp Repts 50-445/80-11 & 50-446/80-11 on BOO404 & forwards notice of violation SEIDLE.H C Region 4. Dallas, Reactor Construction & Engineering Support Branch BO/04/09 2pp
- --8007180499 Notice of violation from insp on B00404 Noncompliance noted Failure to follow piping installation procedures # Region 4. Dallas, Office of the Director 80/04/09 ip
- BOO7240309 Forwards IE Info Notice BO-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRIT, X V Region 4. Dallas, Office of the Director 80/05/16
- B007110229 Forwards IE Insp Repts 50-445/80-14 & 50-446/80-14 on 800913-14 No noncompliance noted SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8007110234 IE Insp Repts 50-445/80-14 & 50-446/80-14 on 800513-16 No noncompliance noted Major areas inspected const activities, RCPB piping work & other safety-related piping work. GILBERT.4. D . HALL, R E Region 4. Dallas, Reactor Construction & Engineering Support Branch CROSSMAN.W A Region 4. Dallas, Office of the Director 80/05/23 4pp
- 8007020233 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/05/28
- B007210351 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required SEYFRIY.K V Region 4, Dallas, Office of the Director 60 80/05/28
- 8007010026 Forwards IE Info Notice 80-20, "Loss of Buction to Emergency Feedwater Pumps" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director. 80/05/29
- 8007170196 Responds to IE Bulletin BO-09. "Hydramotor Actuator Deficiencies " Six vendors identified as potential suppliers of equipment containing ITT General hydramotor actuators Vendors confirmed no actuators supplied to facilities GARY,R J Texas Utilities Generating Co BO/06/10 ip
- 8007220128 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/06/10,
 - -- n Repts 50-445/80-13 & 50-446/80-13 ~ ~ 'ii. ip

, of Reactor

tor. 80/06/11

Accordance W/10CFR50 55(e) " No written response required BEYFRIT, X V Region 4. Dellas. Office of the Director 80/06/13

- 8007180567 Forwards IE Insp Repts 50-445/80-11 & 50-446/80-11 in Apr-May 1980 No noncompliance noted SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Bupport Branch 80/06/17 200
- ~=8007i80574 IE Insp Repts 50-445/80-ii & 50-446/80-ii in Apr-Maw 1980, Wa noncompliance noted Major areas inspected safety-related pipe & equipment installation, concrete repair activities, electrical installation & protection of major components TAYLOR,R 0 . CROSSMAN,W A Region 4. Dallas, Office of the Director 80/06/i6 iOpp
- 8007140455 Ack receipt of IE Insp Repts 50-445/80-14 & 50-446/80-14 em 800523 No proprietary info QARY,R J Texas Utilities Generating Co 80/06/18 ip.
- 8007140497 Ack receipt of 800606 its informing NRC of steps taken to correct violations nated in IE Insp Repts 50-445/80-13 to Correct Violations named on 500-446/B0-13
 SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Bussort Branch 80/06/19 ip
- --8007140502 Responds to NRC ltr re violations noted in IE Insp Repts 50-445/80-13 & 50-446/80-13 Corrective actions, agt met w/welders to reaffire importance of strict adherence to specified weld procedures, GARY.R J Texas Utilities Generating Co 60/06/04 App
- 8007240057 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/20.
- 8007170683 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required SEYFRIY.K.V Region 4, Dallas, Office of the Director \$0/06/24
- 8007230370 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required, IE Circular 80-16 also enci No written response required, SEYFRIT, K V Region 4, Dailas, Office of the Director. 80/06/27
- S Reportable occurrences, LERs & related correspondence
- 8007080062 Final deficiency rept re Unit 2 reactor vessel outlet nozzles w/short safe-ends Invastigation determined that matter not reportable per 10CFR50 55(e) Supporting records available at site OARY, R. J. Texas Utilities Generating Co. 80/06/26 1p.
- 8007210162 PNS-IV-80-010 group of approx twelve people harassing security force over period of five days. State & local law enforcement authorities have been actively supporting security force.

 KELLY, J Region 4. Dellas, Office of the Director 80/07/09, 1p
- B007210352 Updates B00421 deficiency rept re discrepancies involving installation & insp requirements for Class 5 non-nuclear safety-related piping supports FBAR is being revised Final rept will be forwarded by 800922 GARY.R.J Texas Utilities Generating Co 80/07/14 1p
- DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be mot for current OL applications, as derived from NUREO-0660 & found in NUREO-0674
 EISENHUT, D O Division of Licensing 80/06/26 2pp
- DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EIBENHUT, D Q Division of Licensing 80/06/26 2pp.

ļ

1 1

1

BOCKET 50-452 GREENHOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISEMBUT, D G. Division of Licensing 8D/06/26 2pp

_

Q. Adjudicatory correspondence

BOO7080008 Motion to compel withdrawal of application due to unwarranted delays Requests rules & regulations that will govern proceeding & necessary funds to retain legal counsel Cartificats of Svc encl AGPERGER, R Q Citizens for Energy & Employment, 80/06/02 App.

B007090297 Forwards Concerned Citizens for Employment & Energy B00402 motion to compel withdrawal of application & NRC response, to ARL9 for appropriate action CHILK, E J. Office of the Secretary of the Commission B0/07/03

B007140370 Forwards request for withdrawal of application urging termination of proceeding w/o prejudice & extension of time to respond to Citizens for Employment & Energy motion, VOIGT.H H Lebourf, Lamb, Leiby & MacRee 80/07/09 2pp

--8007140378 Request for withdrawal of 730404 application w/o prejudice to future rights. Urges continuation of withholding confidential documents from public disclosure or to be notified of contrary determination. Certificate of Svc encl VOIOT.H H Detroit Edison Co VOIOT.H H LeBoeuf, Lamb, Leiby & HacRae. 80/07/09 App.

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A. Application/construction stage documents & correspondence

B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NURE0-0660 & found in NURE0-0694.
EISENBUT, D 0. Division of Licensing. 80/06/26 2pp.

9, Adjudicatory correspondence

8007080008 Motion to compel withdrawal of application due to Unwarranted delays Requests rules & regulations that will govern proceeding & necessary funds to retain legal coursel Certificate of Svc ancl.

ABPERGER, R O Citizens for Energy & Employment 80/06/02 4pp

B007090297 Forwards Concerned Citizens for Employment & Energy B00602 motion to compel withdrawal of application & NRC responses to ASLB for appropriate action CHLK.S J Office of the Secretary of the Commission B0/07/03 in.

9007140370 Forwards request for withdrawal of application Urging termination of proceeding w/o prejudice & extension of time to respond to Citizens for Employment & Energy motion VOIOT, H H Leboeuf, Lamb, Leiby & MacRae 80/07/09 2pp

--B007140378 Request for withdrawal of 730404 application w/o prejudice to future rights Urges continuation of withholding confidential documents from public disclosure or to be notified of contrary determination Certificate of Bvc encl VDIOT.H H. Detroit Edison Co VDIOT.H H. LeBoeuf, Lamb, Leiby & MacRam. 80/07/09, App.

DOCKET 50-454 BYRON STATION: UNIT 1

A. Application/construction stage documents & correspondence

BOG7010411 Forwards documentation of safety-related electrical aquipment qualification Addresses NRC Questions 40 01 & 40,77. Requests NRC approval of response format prior to incorporation into FBAR NAUGHTON, W.F. Commonwealth Edison Co. 80/06/25. 2ipp

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
EIBERMUT, D 9 Division of Licensing 80/06/26 2pp.

8007190529 Forwards response to NRC 800421 request for info re masonry wall design Further review of masonry wall design is being conducted at LaBalle to complete response to IE Bulletin 80-ii Package of 201 oversize drawings enci PEOPLES, D L Commonwealth Edison Co 80/07/08 23pp

~-8007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming * Sargent & Lundy. Inc 80/07/08 231pp

F Becurity, medical, emergency & fire protection plans

8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
PEOPLES D L Commonwealth Edison Co 80/06/27 Ip

O Adjudicatory correspondence

8007310243 Forwards Commission 800527 Memorandum & order containing decisions on UCS 780502 petition for reconsideration of 7804i3 memorandum & order UCS 77104 petition sought action re fire protection for electrical cables EIBENHUT, D @ Divasion of Licensing 80/06/25 89op

K Utility Final Safety Analysis Report (FSAR) & amends

B00702040B Forwards Amend 26 to FSAR
NAUGHTON, W F Commonwealth Edison Co 80/04/27 5pp

--B007020420 Amend 26 to FBAR, containing portion of responses to GA Branch & Reactor Sys Branch addl first round questions * Commonwealth Edison Co 80/06/30 200pp

8007080299 Forwards 800630 affidavit certifying distribution of FSAR Amend 26 NAUGHTON, W F Commonwealth Edison Co 80/06/30 2pp

8007160339 Forwards addl FSAR drawings & info for auxiliary & containment bldg structures & components in response to NRC 800616 ltr NAUGHTON, W F Commonwealth Edison Co 80/07/03 107pp

--8007160566 "Transient Thermal Analysis of Reactor Bldg Dome Ring Section "

* Sargent & Lundy, Inc 75/09/22 74pp

--B007160369 "Thermal Transient Analysis of Reactor Bldg Structural Sections "
WHITES J C. MHARANA, S B Sargent & Lundy, Inc 79/05/05 77pp

--8007160574 Pockage of 182 structural drawings to be recalled at later date for microfilming
* Sargent & Lundy, Inc. 80/03/31 IB2

8007270678 Forwards drawings listed in FSAR, Subsection I 7, per NRC request NAUGHTON W F Commonwealth Edison Co 80/07/07 1p

--8007290607 Package of 63 drawings to be recalled at later date for filming
* Westinghouse Electric Corp 72/08/04 63pp

B007140320 Forwards Amend 27 to FBAR, amending application for CPs & DLs
NAUGHTON, H F Commonwealth Edison Co 80/07/11 2pp

--8007i4032B Amend 27 to FSAR, amending application for CPs & OLs Consists of responses to add1 first round Questions 42i 6-421 iB, inadvertently omitted from Amend 26 * Commonwealth Edison Co 80/07/31 14pp

8007220540 Forwards affidavit stating that distribution of facility FSAR, Amend 27 has been made per Encl 1 to R8 Boud 791029 itr to C Reed NAUGHTON, H F. Commonwealth Edison Co BO/07/16. 2pp

Q Inspection reports. IE Bulletins & correspondence

B007210356 Forwards IE Circular B0-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/05/28

- 8007010086 Forwards 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29 to
- 8007020030 Forwards response to 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES, O L. Commonwealth Edison Co 80/06/04 3pp
- 8007150113 Forwards IE Imsp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 Wo noncompilance noted FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --8007150118 IE Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No noncompliance noted Major areas inspected incense action on previous insp findings re employee qualification & concrete coating thickness HILLIAMS C C . JONES C E Region 3. Chicago, Office of the Director 80/06/05 3pp
- 8007220194 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/10 ip
- 8007160165 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- 8007280709 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 35(e) " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/13 ip
- 8007100004 Forwards response to IE Bulletin 80-09, "Hydremotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEOPLEG.D L Commonwealth Edison Co 80/06/16 3pp
- 8007020599 Forwards IE Circular 90-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLERIJ G Region 3, Chicago, Office of the Director 80/06/20
- BOD7170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required KEPPLER.J O Region 3. Chicago. Office of the Director BO/06/24 in
- 8007300138 Forwards IE Insp Repts 50-454/80-11 & 50-455/80-10 on 800613 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/25 2pp
- --B007300143 IE Insp Repts 50-454/80-11 & 50-455/80-10 on B00613 No noncompliance noted Major areas inspected results of investigation into cause of math failure of containment post-tension sys anchor heads & corrective actions planned OALEAGHEN,E J. KANKLIN.J E Region 3. Chicago. Office of the Director HAVEG,D W Region 3. Chicago. Reactor Construction & Engineering Support Branch B0/06/23 3pp
- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER. J G Region 3, Chicago, Office of the Director 80/06/27 1p
- 8007250638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Waids" Dresden Unit i designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co 80/07/09 7pp
- 8007280467 Submits supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Util roview remains incomplete due to necessity of consulting equipment suppliors Response will be submitted by 800829 FEUPLES.D L Commonwealth Edison Co 80/07/15 1p

- 8 Reportable occurrences. LERs & related correspondence
- 8007020431 Interim deficiency rept re failure of post-tonsioning anchorheads Generally concurs w/INHYCO 800530 rept All Category B heat treet lots will be tested Replacement anchorheads from accepted heat treat lots will be installed NAVGHTON, W F Commonwealth Edison Co 80/06/27 2pp
- 8007270041 Concurs w/anchorhead evaluation & acceptence plan propded in 800627 final deficiency rept Implementation will be examined during future insps
 KEPPLER, J O Region 3, Chicago, Office of the Director. 80/07/18
 20
- 8007280670 Deficioncy rept re intermittent contact operation of W-# switch Util will not implement interim fix unless no permanent solution is available prior to fuel load Util will monitor Westinghouse recommendations.

 NAUGHTON, W F Commenwealth Edison Co 80/07/23, 2pp

DOCKET 50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Guestions 40 O1 & 40 77 Requests NRC approval of response formet prior to incorporation into FBAR NAUGHTON, H F Communwealth Edison Co 80/06/25 21pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-06494
 EISENHUT, D Q Division of Licensing. 80/06/26. 2pp.
- 8007190529 Forwards response to NRC 800421 request for info re masoning wall design further review of masoning wall design is being conducted at LaBalle to complete response to IE Bulletin 80-ii Package of 231 oversize drawings enti PEOPLES, D. L. Commonwealth Edison Co. 80/07/08 23pp.
- --B007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
 # Sargent & Lundy. Inc 80/07/08, 231pp
- F Security, medical, emergency & fire protection plans
- B007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790).
 PEOPLES, 0, L Commonwealth Edison Co 80/06/27 ip.
- O Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for slectrical cables.
 EISENHUT,D 0 Division of Licensing 80/06/25 87pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B007020408 Forwards Amend 26 to FRAR
 NAUGHTON, W F Commonwealth Edison Co 80/06/27 5pp
- --8007020420 Amend R6 to FSAR, containing portion of responses to 0A Branch & Reactor Sys Branch addl first round questions, 5 Commonwealth Edison Co 80/06/30 200pp
- B0070B0299 Forwards B00630 affidavit certifying distribution of FBAR Amend 26 NAUGHTQN, W F Commonwealth Edison Co 80/06/30 2pp.
- 8007160359 Forwards addl FBAR drawings & info for auxiliary & containment bldg structures & components in response to NMC 800616 ltr NAUGHTON, W F Commonwealth Edison Co 80/07/03, 107pp
- ---B007160366 "Transient Thermal Analysis of Reactor Oldg Dome Ring Bection" * Bargent & Lundy, Inc 75/09/22, 74pp.
- --8007160569 "Thermal Transient Analysis of Reactor Bldg Structural Bections " WillE.J G , KHARANA, S S Sargent & Lundy, Inc 79/03/03. 77pp

- --8007;60574 Package of 182 structural drawings to be recalled at later date for microfilming * Sargent & Lundy, Inc. 80/03/31 182
- 6007290678 Forwards drawings listed in FSAR, Subsection 1 7, per NRC
- NAUGHTON, W F Commonwealth Edison Co 80/07/07 1p
- -8007290687 Package of 63 drawings to be recalled at later date for filming # Westinghouse Electric Corp 72/08/04 63pp
- 8007140320 Forwards Amend 27 to FSAR amending application for CPs & NAUGHTON.W F Commonwealth Edison Co 80/07/11 2pp
- --8007140328 Amend 27 to FBAR.amending application for CPs & OLs Consists of responses to addl first round Questions 421 6-421 18, inadvertantly omitted from Amend 26 Commonwealth Edison Co 80/07/31 14pp
- B007220540 Forwards affidavit stating that distribution of facility FBAR, Amend 27 has been made per Encl 1 to RS Doyd 791029 ltr NAUGHTON, W F Commonwealth Edison Co 80/07/16 2pp
- Q. Inspection reports, IE Bulletins & correspondence
- 8007210336 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B 80/05/28
- 8007010086 Forwards IE info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPL68.J & Region 3, Chicago. Office of the Director 80/05/29
- BOO7020050 Forwards response to IE Bullotin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys weter Possitive pressure is maintained PEOPLES.D L Commonwealth Edison Co 80/06/04 3pp
- 8007150113 Forwards IE Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No nencompliance noted FIGRELLI, Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --8007150118 IC Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No noncompliance noted Major areas inspected licensee action on previous imap findings re employee qualification & certification & concrete coating thickness WILLIAMS C C , JONES, C E Region 3, Chicago, Office of the Director 80/06/05 3pp
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required KEPPLER.J 9 Region 3. Chicago, Office of the Director 80/06/i0
- 8007160145 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No appositic action or response KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/11
- B007280709 Forwards IE Info Natice B0-28, "Prompt Reporting of Info in Accordance W/10CFR90 55(e) " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/13
- 8007100004 Forwards response to 1E Bulletin 80-09. "Hydramotor Actuator Deficiencies." No %aPoty-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES, D. L. Commonwealth Edison Co. 80/06/16 3pp
- 8007020589 Forwards IE Circulor 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER. J O Region 3. Chicago, Office of the Director 80/06/20
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnol " No written response required KEPFLER, J G Region 3, Chicago, Office of the Director 80/06/24

- 800730013B Forwards IE Insp Repts 50-454/80-11 & 50-455/80-10 on 800413 No noncompliance noted FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/25 2pp
- --8007300143 IE Inso Repts 50-454/80-11 & 50-455/80-10 on 800613 No ngmcompliance noted Major areas inspected results of investigation into cause of matl failure of contains post-tension sys anchor heads % corrective actions planned GALLACHER: C J . KANKLIN, J E Region 3. Chicago. Defice of the Diroctor HAYES, D W Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/23 3pp
- 8007230289 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27
- 8007250638 Forwards response to IC Bulletin 80-08. "Examination of Containment Liner Penetration Welds" Dresdom Unit 1 designs will be reviewed & feasibility of performing radiographic axaminations will be assessed before unit returned to svc PEOPLES, D L Commonwealth Edison Co 80/07/09 7pp
- 8007250467 Submits supplemental response to IC Bulletin 80~09, "Hydramotur Actuator Duficiencies" Util review remains incomplate due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES.D L Commonwealth Edison Co 80/07/15 tp
- B Reportable occurrences, LERs & related correspondence
- 8007020631 Interim deficiency rept re failure of post-tensioning anchorheads Generally concurs w/INRYCO 800530 rept All Category B heat treat lots will be tested Replacement anchorheads from accepted hoat treat lots will be installed NAUGHTON.W F Commonwealth Edison Co 80/06/27 2pp
- 8007270061 Concurs w/anchorhead evaluation & acceptance plan proposed in 800627 final defictioncy rept implementation will be examined during future insps KEPPLER.J O Region 3. Chicago, Office of the Director 80/07/18
- B007280670 Deficiency rept re intermittent contact operation of W-2 switch Util will not implement intorim fix unless no permanent solution is available prior to fuel load Util will monitor Mustinghouse recommendations
 NAUGHTON, W F Commonwealth Edison Co B0/07/23 2pp
- DOCKET 50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 80070104li Forwards documentation of safety-related electrical equipment qualification Addresses NRC Questions 40 01 & 40 77 Requests NRC approval of response format prior to incorporation into FSAR NAUGHTON.W F Commonwealth Edison Co 80/06/25 2ipp
- BOO7R30001 Forwards statement of pullcy re requirements to be mot for current OL applications as derived from NUREO-0660 & found in NUREO-0694 EIBENHUTID G Division of Licensing 80/06/26 2pp
- B007150529 Forwards response to NRC 800421 request for info re masonry wall design lis being conducted at LaSalle to complete response to IE Bulletin 80-1; Package of 231 oversize drawings encl PEOPLES.D L Commonwealth Fdison Co 80/07/08 23pp
- --8007150537 Pockage of 231 concrete masonry wall drawings to be recalled at later date for microfilming * Sargent & Lundy, Inc 80/07/08 231pp
- F Becurity, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES, D L. Commonwealth Fdison Co. 80/06/27 Ip

- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorendum % order containing decisions on UC9 780502 petition for reconsideration of 780413 memorandum % order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT. D G Division of Licensing 80/06/25 89pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007020408 Forwards Amend 26 to FSAR NAUGHTON,W F Commonwealth Edison Co 80/06/27 5pp
- --8007020420 Amend 26 to FSAR, containing portion of responses to GA Branch & Reactor Sys Branch addi first round questions * Commonwealth Edison Co 80/06/30 200pp
- BOO70B0299 Forwards BOO630 affidavit certifying distribution of FSAR Amena 25 NAUGHTON.W F Commonwealth Edison Co 80/06/30 2pp
- BOO7160559 Forwards add1 FSAR drawings & info for auxiliary & containment bldg structures & components in response to NRC BOO616 1TF NAUGHTON W F Commonwealth Edison Co BO/07/03 107pp
- --8007160565 "Transient Thermal Analysis of Reactor Bldg Dome Ring Section "
 - * Sargent & Lundy, Inc 75/09/22 74pp
- ---8007160569 "Thermal Transjent Analysis of Reactor Bldg Structural Sections" WHITC, J G . KHARANA, S B Sargent & Lundy, Inc 79/05/03 77pp
- ---8007:60974 Package of 182 structura) drawings to be recalled at later date for microfilming * Sargent & Lundy. Inc 80/03/31 182
- 8007290678 Forwards drawings listed in FSAR. Subsection 1 7. per NRC request
 NAVOHTON. W F Commonwealth Edison Co 80/07/07 1p
- --8007290687 Package of 63 drawings to be received at later date for filming
 * Westinghouse Electric Corp 72/08/04 63pp
- 8007140320 Forwards Amend 27 to FSAR, amending application for CPs &
- DLs NAUGHTON, W.F. Commonwealth Edison Co. 80/07/11 2pp
- --B007140328 Amend 27 to FSAR, amending application for CPs & OLs Consists of responses to addl first round Questions 421 6-421 18, inadvertently omitted from Amend 26 a Commonwealth Edison Co B0/07/31 14pp
- BOO7220340 Forwards affidavit stating that distribution of facility FSAR.Amend 27 has been made per Encl 1 to RB Boyd 791029 ltr to C Reed NAUGHTON, W F Commonwealth Fdison Co BO/07/16 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007210336 Forwards TE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28, in
- B007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required XEPPLER.J G Region 3, Chicago, Office of the Director 80/05/29 in
- B007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES O L Commonwealth Edison Co 80/06/04 3pp
- 8007180508 Forwards IE Insp Repts 50:456/80-05 & 50-457/80-05 on 800429 & 0520 & natice of violation FIORELLI.G Region 3, Chicago. Reactor Construction & Engineering Bupport Branch 80/06/05 2pp
- --B0071B0513 Notice of violation from insp on B00429 & 0520
 * Region 3. Chicago, Office of the Director 80/06/03. 2pp

- ---8007180519 IE Insp Repts 50-456/80-05 & 50-457/80-05 on 800429 & 0520, Noncompliance noted failure to perform survoillance on valves in storage & failure to meet wolding or storage procedure requirements

 LEE.E W Region 3, Chicago, Office of the Director

 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/03 Spp
- B007220196 Forwards IE Info Notice 80~26, "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3, Chicago, Office of the Director B0/06/10, in
- 8007230002 Forwards IE Insp Repts 50-456/80-04 & 50-457/80-04 on 800514-15 & notice of violation FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- --B007230006 Notice of violation from insp on 800514-15
 4 Region 3, Chicago, Office of the Director 80/06/09 19
- --B007230019 IE Insp Repts 50-456/B0-04 & 50-497/B0-04 on G00514-13.
 Noncompliance noted failure to assure design basis
 correctly translated into specs
 SCHMEIDINZ,E R. GALLACHER,E J., WILLIAMS,C C. Region 3. Chicago,
 Office of the Director SO/06/09 9pp
- 8007160165 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J. Q. Rogion 3, Chicago, Office of the Director 60/06/11
- 8007280709 Forwards IC Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 95(e)" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/13 is
- 8007100004 Forwards response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEDPLES.D L Commonwealth Edison Co 80/06/16 3pp
- 8007020589 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown "No writton response required KEPPLER-J O Region 3, Chicago, Office of the Director 80/06/20.
- 8007170430 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel" No weitton response required KEPPLER, J C Region 3, Chicago, Office of the Director 80/06/24
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Resembunt Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes "Mritten response required IE Circular 80-16 also enci No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27.
- 6007290638 Forwards response to IE Bulletin 80-08. "Examination of Containment Linur Penetration Wolds " Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co 60/07/09 7pp.
- GOO7250467 Submits supplemental response to IE Bulletin 80-07, "Hydrameter Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by BOO229 PEOPLES.D L Commenwealth Edison Co GO/07/15 1p
- 8007240340 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-436/80-05 & 50-457/80-05 FIGRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/16 ip
- ---B007240351 Responds to NRC 800605 ltr re violations noted in IE Insp Repts 50-456/80-05 & 50-457/80-05 Corrective actions.weave weld procedures reviewed & rod oven calibr checked PEOPLES,D L Commonwealth Edison Co 80/07/09 4pp

- 8 Reportable occurrences. LERs & related correspondence
- GOO72B0570 Deficiency rept re intermittent contact operation of W-2 multch Util will not implement interim fix unless no permanent solution is available prior to fuel load Util will monitor Hestinghouse recommendations NAUGHTON.W F Commonwealth Edison Co BO/07/23 2pp
- DOCKET 50-497 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Questions 40 01 & 40 77 Requests NRC approval of response format prior to incorporation into FBAR NAUGHTON, H F Commonwealth Edison Co 80/06/25 21pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-06474
 EIBEN#UT.D 0 Division of Licensing 80/06/26 2pp
- 8007150529 Forwards response to NRC B00421 request for info re masonry wall design Further roview of masonry wall design is being conducted at LaBalla to complete response to IE Bulletin 60-ii Package of 231 oversize drawings encl PEOFLES, D L Commonwealth Edison Co 80/07/08 23pp
- ---B007150537 Package of 23i concrete masonry wall drawings to be recalled at later date for microfilming # Bargent & Lundy, Inc B0/07/OB 23ipp
- F. Security, medical, emergency & fire protection plans
- BO07010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES D L: Commonwealth Edison Co 80/06/27 1p
- Q. Adjudicatory correspondence
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENMAUT.D © Division of Licensing 80/04/25 89pp
- M. Utility Final Safety Analysis Report (FSAR) & amends
- BO0702040B Forwards Amend 26 to FSAR NAUGHTON, W. F. Commonwealth Edison Co 80/06/27 5pp
- 8007080299 Forwards 800630 affidavit certifying distribution of FBAR NAUGHTON, W F Commonwealth Edison Co 80/06/30 2pp
- 8007140559 Forwards add1 FBAR drawings & info for auxiliary & containment bldg structures & components in response to NRC 800616 ltr NAUCHTON, W F Commonwealth Edison Co 80/07/03 107pg
- --8007160566 "Transient Thermal Analysis of Reactor Bldg Dome Ring * Sargent & Lundy, Inc 75/09/22 74pp
- --B007160569 "Thermal Transient Analysis of Reactor Bldg Structural WHITE: J G Sargent & Lundy, Inc 77/05/05 77pp
- --B007i60574 Package of 182 structural drawings to be recalled at later date for microfilming * Sargent & Lundy, Inc 80/03/31 182,
- 8007290678 Forwards drawings listed in FBAR, Subsection i. 7, per NRC request. NAUCHTON, W F Commonwealth Edison Co 80/07/07, ip
- --8007290687 Package of 63 drawings to be recalled at later date for Westinghouse Electric Corp 72/08/04 63pp

- 8007140320 Forwards Amend 27 to FSAR.amending application for CPs & NAUGHTON, W F Commonwealth Edison Co 80/07/11 2pp
- --8007140328 Amend 27 to FSAR.amonding application for CPs & OLs Consists of responses to add1 first round Questions 421 6-421 iG, inadvertently omitted from Amend 26
 * Commonwealth Edison Co 80/07/31 14pp
- 8007220540 Forwards affidavit stating that distribution of facility FSAR, Amend 27 has been made per Encl 1 to RS Boyd 791029 ltr to C Read NAUGHTON.W F Commonwealth Edison Co 80/07/16 2pp
- O Inspection reports, IE Bulletins & correspondence
- B007210356 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director E 80/05/28
- B0070100B6 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/05/29
- 8007020050 Forwards response to IE Bulletin 80-05, "Yacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS)
 Holdup Tanks "Three Zion holdup tanks can be valved to
 contain primary sys water Positive pressure is maintained
 PEOPLES D L Communwealth Edison Co 80/06/04 3pp
- 8007180508 Forwards 1E Insp Repts 50-456/80-05 & 50-457/80-05 on 800427 & 0520 & notice of violation FIORELLIA Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- --B007180513 Notice of violation from insp on 800429 & 0520 * Region 3. Chicago. Office of the Director B0/04/03
- --8007i805i9 IE Insp Repts 50-456/80-05 & 50-457/80-05 on 800429 & 0520 Noncompliance noted failure to perform surveillance on valves in storage & failure to meet welding or storage procedure requirements
 LCE.E W Region 3, Chicago, Office of the Director
 DANIELSON.D H Region 3. Chicago, Reactor Construction &
 Engineering Support Branch BO/06/03 5pp
- 8007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required REPPLER, J G Region 3, Chicago, Dffice of the Director 80/06/10
- 8007230002 Forwards IE Insp Repts 50-456/80-04 & 50-457/80-04 on 800514-15 & notice of violation FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/10 2pp
- --8007230006 Notice of violation from insp on 800514-13
 * Region 3. Chicago, Office of the Director 20/0 80/06/09 in
- --B007230019 IE Insp Repts 50-496/B0-04 & 50-497/B0-04 on B00514-15
 Noncompliance noted failure to assure design basis
 correctly translated into specs
 SCHWEIBINZ R . OALLAGHER.E J . WILLIAMS.C C Region 3. Chicago.
 Office of the Director B0/04/09 9pp
- 8007160165 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/11
- 8007280709 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/100FR50 95(e) " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/13
- 8007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Daficiencies," No safety-related sys or component at Dreeden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES, D. L. Commonwealth Edison Co. 80/04/14 3pp
- 8007020589 Forwards IE Circular 80-15, "Loss of Reactor Codiant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/20

- 8007170430 Forwards 1E Corcular 80-14. 'Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel 'No written response required KEPPLER. J. G. Region 3. Chicago. Office of the Director 80/06/24 to
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Whither response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/27 in
- 800725063B Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresder Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES, D. L. Cammonwealth Edison Co. 60/07/09 7pp
- 8007250467 Submits supplemental response to IE Bulletin 80~09, "Hydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800827 PEOPLES,D L Commonwealth Edison Co 80/07/15 ip
- 8007240340 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/80-05 & 50-457/80-05
 FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/16 lp
- ---800724035; Responds to NRC 800605 itr re violations noted in IE Insp. Repts 50-456/80-05 & 50-457/80-05 Corrective actions weave weld procedures reviewed & rod oven calibr checked PEOPLES, D. L. Commonwealth Edison Co.
- 5 Reportable accurrences. LERs & related correspondence
- 8007280670 Deficiency rept re intermittent contact operation of W-2 switch Util will not implement interim fix unless no permanent solution its available prior to fuel load Util will monitor Bestinghouse recommendations NAUGHTON, R F Commonwealth Edison Cp 80/07/23 2pp

DOCKET 50-459 RIVER BEND STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007010558 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation effective 800428 Considerations re activities should be made through assigned mpt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- .0007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 % found in NUREG-0674 EISENMUT.D O Division of Licensing 80/06/26 2pp
- 6007080191 Forwards Qualification Summary Repts 33-52260-09 for Hope Creek & 33-54237-05 for River Bend reflecting documentation of electrical equipment qualification Repts withheld (ref. 10CFR 2790)

 DUVALL.D D Gould-Brown Bovers 80/07/01 ip
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp
- H General correspondence
- B007140638 F01A request for documents re three Har 1980 violations occurring at facility
 KRAUSE.L. Affiliation Unknown B0/06/15 1p
- 8007020684 Responds to 800611 request for clarification re alteration of property mentioned on Page 14 of prelimary case rept on Port Hudson Battlefield Landmart in LA Alteration referred to is widening of electrical transmission line corridor REGAN, W H Siting Analysis Branch 80/06/18 1p
- 8007140635 Responds to FOIA request for documents re three Mar 1980 violations occurring at facility Forwards listed documents FELTON, J.M. Division of Rules and Records 80/07/07 ip

- Q Inspection reports. IE Bulletins & correspondence
- B007250316 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/31
- 8007210137 Ack receipt of 800305 ltr informing NRC of steps telen to correct items of noncompliance noted in IE Insp Rept 50-458/79-06 on 791118-21 & 1204-07 Requests addl info re Items A-1 & B-2 EIDLE.H C Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --800721014B Responds to violations noted in IE Insp Rept 50-450/79-06 en 791118-21 & 1204-07 Mortar bar tests are being conducted to determine if high alkalai cement may be used w/util source aggregate in future
 WEIGAND.J O Gulf States Utilities Co 80/03/05 4pp.
- 8007140568 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/12,
- 8007240511 Forwards IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/16
- 8007020249 Forwards 1E Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required BEYFRIT, K V Region 4. Dallas. Office of the Director 80/05/28
- 8007010028 Forwards IE Info Natice 80-23, "Losp of Suction to Emergancy Feedwater Pumps" No writton response required SEYFRIT, N. V. Region 4, Dallas, Office of the Director 80/05/29,
- 8007220104 Forwards IE Info Notice 80-Ré. "Evaluation of Contractor GA Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/10
- 8007140404 Forwards IE Bulletin 80-14, "Degradation of BUR Scram Discharge Vol Capability " No written response required SEFFRIT.K V Region 4, Dallas, Office of the Director 80/06/13
- 8007270057 Forwards 1E info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 60/06/12
- 8007240035 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/20
- 8007170669 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required. SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/24 in
- 8007230376 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Butput Codes "Written response required IE Circular 80-16 also encl No written response required 8EYFRIT, K V Region 4, Dallas, Office of the Director 90/06/27.
- 8007220394 Submits response to 1E Bulletin 80-11 re Category 1 masonry walls employed by plants under CP & CL review Station engineering design criteria indicate that no piping or equipment will be supported from masonry walls.

 DRAPER.E L Gulf States Utilities Co 80/07/15, ip

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

- 9007010558 Forwards NRC reorganization chart for Ofc of Nuclear Reactor 20/010338 rotwards Nut reorganization thank for out or white Regulation effective BOD428 Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCORL Assistant Director for Licensing BO/06/13 RO/06/13 2pm
- B007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0650 & found in NUREG-0674 EISENHUT. D G Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-QS for Hope Creek & 33-54237-QS for River Bend reflecting documentation of elactrical equipment qualification Repts withheld (ref 10CFR2 770) DUVALL, D D Gould-Brown Doveri 80/07/01 1p

O Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing NO/310243 From the Commission boose memoration a broad decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 89pp
- Q Inspection reports. IE Bulletins & correspondence
- BOO7250316 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Region 4. Delles, Office of the Director 80/03/31
- 8007140568 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/12
- 8007240511 Forwards IE Info Notice 80-21. "Anchorage & Support of Bafaty-Related Electrical Equipment" No written response SEYFRIT.K V Region 4. Dellas. Office of the Director BO/05/16
- 8007020249 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 6007010028 Forwards IE Info Notice 80-23. "Lass of Suction to Emergency Feedwater Pumps " No written response required BEYFRIT, K V Region 4, Dallas. Defice of the Director 80/05/29
- 8007220104 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required SEYFRIT, K V Region 4, Dollas, Office of the Director 80/06/10
- 8007140404 Forwards IE Bulletin 80~14. "Degradation of BWR Stram Discharge Vol Capability " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/12
- 8007270057 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(a) " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director, 80/06/13
- B007240035 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No writton response required BEYFRIT, K V Region 4, Dallos, Office of the Director 80/04/20
- B007170669 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bus & Resultant Internal Contamination of Personnel " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/24

- 8007230376 Forwards IE Bulletin 80-16, "Potential Misapplication of Messmount Inc Models (15) & 1322 Pressure Transmitters
 W/Either A or D Output Codes " Written response required
 IE Circular 80-16 also enti No written response required
 SEYFRIT.K V Region 4. Dalias. Office of the Director 80/06/27
- DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007030197 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.R L Assistant Director for Licensing GO/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current CL applications as derived from NUREG-0660 & found in NUREG-0694
- EISENKUT.DG Division of Licensing 80/06/26 2pp
- 8007210392 Ack receipt of NRC 800430 ltr approving request to discontinue certain aquatic munitoring & requesting copies of util submittals to State of HA re water quality NRC does not have authority to require water quality filings RENBERGER, D. L. Washington Public Power Supply System 80/0
- BOO7250544 Forwards "Reliability Evaluation of WPPSS Nuclear Projects Numbers 1 & 4." in response to NRC 800124 request for evaluation of loss of main feedwarter event RENDERGER.D L Washington Public Power Supply System 80/07/22
- --BOO7250552 "Reliability Evaluation of WPPS9 Nuclear Projects Numbers 1 & 4." Vol 1.main rept MCBRIDE, A.F., MINARICK, J.W., BOZARTH, D.P. Science Applications. 60/07/16 214pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & urder UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.0 G Division of Licensing 80/06/25 89pp
- G Inspection reports, IE Bulletins & correspondence
- 8007270444 Responds to IE Bulletin 80-03, "Loss of Charconl from 8td Type II.Two-Inch.Tray Adsorber Colls " Standardized 31 5 X 23 inch.flat bed.Type II charconl adsorber cell units used in all cleanup sys RENBERGER,D L Washington Public Power Supply System 80/03/19
- 8007220252 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENGELKEN, R H. Region 5: San Francisco. Office of the Director 80/04/10
- B007300299 Forwards response to 1E Dulletin 80-05 re vacuum demage to chemical control sys tenks Design changes to low pressure process tanks not required Table describing subj tanks & protection provided enci RENBERGER, D.L. Washington Public Power Supply System 80/06/12
- B007290090 Forwards IE Info Nutice 80-28, "Prompt Reporting of Info in Accordance W/IOCFR50 55(e)" No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/86/13 ip
- 8007020466 Forwards IE Circular 80-ib. "Loss of Reactor Coolant Pump Cooling & Natural Circulation (Cooldown " No written response required ENGELKEN, R H Region 5, San Francisco. Office of the Director
- B007180299 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5, San Fiantisco, Office of the Director B0/06/24 lp

- 8007230401 Forwards IE Bulletin BO-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Dutput Codes " Hritten response required IE Circular BO-16 also encl No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/06/27 ip
- 8007290518 Responds to IE Bulletin 80-08 Problems re containment liner pentration weld do not exist at facility Design for primary piping typical of ASME code configurations Process pipe/fived bead assemblies not installed RENBERGER.D L Washington Public Power Supply System 80/07/10
- S Reportable occurrences, LERs & related correspondence
- 6007170577 Forwards interim deficiency rept re defective condition in design of floor supporting component cooling & makeup pump area heating, ventilation & air conditioning sys Train B equipment

 BENBERGER, D. L. Washington Public Power Supply System 80/07/ii
- --8007170585 Interim deficiency rept re defective condition in floor supporting component cooling & makeup pump area Caused by usage of incorrect vertical amplified rosponse spectra Structural frame designed for installation # Washington Public Power Supply System 80/07/11 2pp
- U Congressional/Executive Correspondence
- B007300367 Bubmits questions re unusual financing arrangement between util & Bonneville Power Administration Related correspondence WEAVER.J House of Rep 80/07/14 2pp
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007010243 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activites should be made through assigned mpt representative Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- B007020433 Notification of cancelled 800624-26 site visit w/util to determine status of completion of const BUCKLEY.B Licensing Branch 3 B0/06/17 3pp
- B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREO-0660 & found in NUREO-0694
 E16ENHU7.D 0 Division of Licensing 80/06/26 2pp
- GOO7250557 Advises NRC that util is planning repairs to reactor pressure vessel GE has been authorized to perform work, which has been subcontracted to Reactor Controls, inc Defective elbow on reactor drain line will be replaced KDCH.L J illinois Power Co BO/07/02 ip
- Q. Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENSUT.D C Division of Licensing 80/06/25 87pp
- O Inspection reports, IE Bulletins & correspondence
- 8007140495 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required 3. Chicago. Office of the Director 80/05/12

900414-18 & 21-22 & tion & Engineering

4-18 & 21-22 80/05/14 2pp

- --B00711016B IE Insp Rept 50-461/B0-06 on 800414-18 & 21-22 Moncompliance noted measures not established for control of purchased matl or for 8C of identified structrues HESCOTT, H H. GALLAOHER, E.J. KNOP, R.C. Region 3, Chicago, Office of the Director 80/05/16 14pp
- G007010104 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 90/05/29.
- 6007220204 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 90/06/10
- 8007160751 Forwards 1E lnsp Rept 50-461/80-09 on 600520-23 & notice of violation FigRelia Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/06/11 2pp
- --8007160756 Notice of violation from insp on 800520-23
 * Region 3, Chicago. Office of the Director 80/06/09 ip
- --8007160764 IE Insp Rept 50-461/80-09 on 800520-23 Noncompliance noted: inadequate insp during concrete work activities HEBOIT; H M, GALLAOHER, E J. KNOP, R C. Region 3. Chicago, Office of the Director 80/06/09 7pp
- BOO7140325 Forwards IE Builetin 80-14. "Degradation of DWR Scram Discharge Voi Capability " No written response required REPPLER.J C Region 3. Chicago, Office of the Director 10
- 8007030215 Responds to IE Bulietin 80-09, "Hydramotor Actuator D#ficioncies " Licensee dees not utilize actuator modols in s#fety-related applications, WULLER.0 E lliinois Power Co 80/06/13 1p
- 8007280638 Forwards iE info Notice 80-28, "Prompt Reporting of Info in Accordance W/iOCFR90 55(e)" No written response required REPPLER, J O Region 3, Chicago, Office of the Director 60/06/13, in
- 8007110228 Ack receipt of 800609 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-461/80-07. FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/19 lp
- --8007i10233 Rosponds to NRC 800509 itr re violations noted in IE Insp Rept 50-461/80-07 Corrective actions removed sandwich & all weld rods stored in oven & destroyed flux coated rod to prevent possible uss GERSTNER.W C Illinois Power Co 80/06/09 2pp
- 8007020584 Forwards IE Circular 80-15, "Loss of Roactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/06/20 ip
- 8007310363 Forwards IE lnsp Rept 50-46i/80-10 on 80050i-30 & notice of vigiation F10RELLI, Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8007310364 Notice of violation from insp on 800301-30
 * Region 3, Chicago, Reactor Construction & Engineering Support
 Branch 80/06/19 lp
- ---B007310367 IE Insp Rept 50-461/80-10 on 800501-30 Noncompliance noted; control rod drive ponetration rework activity performed w/o written approved instructions or approved design change. LIVEMORE, H H, KNOP.R C Region 3, Chicago, Office of the Director 80/06/19 4pp
- 8007170495 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnal" No written response roquired KEPLER, J. 0 Region 3, Chicago, Office of the Director 80/06/24 ip
- 8007210516 Ack receipt of 800617 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-06 FIGRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip

- --8007210521 Responds to NRC 800520 ltr re violations noted in 1E Insp Rept 50-461/80-06 Corrective actions inspectors reinstructed on visual insp & bend test requirements OERSTNER.W C Illinois Power Co 80/06/17 4pp
- 9007230330 Forwards IE Bulletin 80-i6. "Potential Misapplication of Rosemount Inc Models i151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Gircular 80-16 also encl No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27 to
- 8 Reportable occurrences, LERs & related correspondence
- 8007140202 Ack receipt of 800613 interim deficiency rept re concrete embeds that failed to meet designer specs FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip
- 8007180511 Ack receipt of 800624 interim deficiency rept re control rod drive penetrations through drywall FIORELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80707/07 lp
- 8007160626 Forwards deficiency repts inadvertently sent to Region 3 instead of IE headquarters
 WRLER, G E Illinois Power Co 80/07/08 2pp
- ---B007160638 Interim deficiency rept re use of incorrect soil characteristic value as design input to computer model for developing bldg response spectra Insufficient info is available to determine reportability of possible deficiency KOCH, L J Illinois Power Co 80/03/31 ip
- --B007i60651 Deficiency rept re breakdown in GE C&ID quality sys Improper or inadequate GA documentation was provided for antety-related equipment (local panels) delivared to site Product quality certifications revised accordingly KOCH,L J Illinois Power Co 80/04/30 2pp
- ---B007160665 Potential deficiency rept re concrete imbeds providing lateral support for RHR heat exchangers which do not meet designer specs Util will make reportability determination within 2 wks

 KDCH,L J Illinois Power Co B0/04/13 1p
- ---8007i&0&79 Potential deficiency rept re control rod drive penetrations through drywell wall Util requires approx 3 wks to make reportability determination ROCHL J lilinois Power Co 80/0&/24 ip
- 800723051B Interim deficiency rept re nonconforming elbow in two-inch drain line from reactor pressure vessel Foreign matl found in albow Removal of elbow scheduled for wk of 800714 Final rept will be submitted late Aug 1980 KOCH.L J Illinois Power Co 80/07/14 2pp
- B007300429 Supplemental deficiency rept re Sargent & Lundy soil characteristics error in facility design Investigations revealed use of incorrect value of soil modules for compacted backfull Reportability determination not complete. KDCH.L J Illinois Power Co B0/07/15 2pp
- 8007280506 Final deficiency rept re control rod drive (CRD) penetrations through drywell wall Control drive tubes which have been adversely affected by welding are being replaced KOCH.L J Illinois Fowar Co 80/07/18 5pp
- DOCKET 50-462 CLINTON POWER BYATION, UNIT 2
- A. Application/construction stage documents & correspondence
- BOO7010243 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activites should be made through assigned mgt representative Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0674
 EISENHUT, D Q Division of Licensing BO/06/26 2pp

G Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007140495 Forwards IE Bulletin 80-13, "Cracking in Core Spray Bpargers " No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/05/12
- B007010104 Forwards IE Info Notice B0-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29 to
- 8007220204 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/10 to
- 8007140325 Forwards IE Bulletin 80-i4, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/12 io
- 8007030215 Responds to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies" Licensee does not utilize actuator models in safety-related applications WULLER:0 E Illinois Power Co 80/06/13 ip
- BOO728043B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required EPPLER, J G Region 3, Chicago, Office of the Director BO/04/13, lp
- B007020584 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/06/20
- 8007170495 Forwards IE Circular 80-14, "Redicactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/24 in
- 8007230300 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27 lp
- 8 Reportable occurrences. LERs & related correspondence
- 8007180511 Ack receipt of 800624 interim deficiency rept re control rod drive penetrations through drywall FIORELLI,Q Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/07/07 ip
- 8007160626 Forwards deficiency ropts inadvertently sent to Region 3 instead of 1E headquarters WULLER, 0 E 1311nois Power Co 80/07/08 2pp
- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007110274 Forwards add1 questions re alternative sites If util intends to pursue CP application.NRC should be advised of schedule for submitting required info MILLER, J R Standardization & Special Projects Branch 80/04/25
- I Financial information
- BOO7010138 Responds to 800605 ltr to 0 Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, E Hearings Division 80/06/19 ip

DOCKET 50-444 FULTON GENERATING STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007110274 Forwards addl questions re alternative sites If util intends to pursue CP application, NRC should be advised of schedule for submitting required info MILLER, J.R. Standardization & Special Projects Branch 80/06/25

I Financial information

- B007010138 Responds to 800605 ltr to G Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTERMENTY. E Hearings Division 80/06/19 lp
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 800703039 Comments on proposed rules 10CFR50 & 51 requirement that Class 9 accidents be considered in E18 should be applied retroactively to plant since site has not been fully determined DOHERTY-JF Doherty, JF 80/05/04 1p
- B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0650 & found in NUREG-0654
 EISENHUT.D G Division of Licensing 80/06/26 2pp

Q Adjudicatory correspondence

- B007030029 Response in opposition to applicant notice of deposition Urgas that applicant by ordered to informally contact D Marrack for deposition arrangements after answering encl interrogatories & request for production of documents MARRACK, D Marrack, D 80/06/11 ip
- -8007030029 Interrogatories & requests for production of documents re intervenor Contention 2E that EIS do not address power line impacts on migratory waterfowl Certificate of Syc and MARRACK.D Harrack.D 80/06/11 5pp
- 8007110080 Motion to compel applicant answers to intervenors' 800908 interrogatories & request for production of documents Certificate of Svc encl Related correspondence MARRACK, D. Marrack, D. RENFRD, W. Affiliation Unknown 80/06/16
- 8007100174 Concurs w/800611 proposel to consolidate interrogatories Dakor 1, Cumings 1, TX PIRO Addl 32, Doggett 4 & Perronod 1 w/ Bakor as representative Confirms that Doggett will lead party on consolidated contentions Bishop 14 & Doggett 1(h) DDGGETT, B A Doggett, B A 80/06/20 2pp
- 8007020471 Response to JF Doherty fourteenth set of interrogatories Includes info ro anticipatd enrichment of spent fuel stored in pool racks self-sufficiency of fuel pool cooling sys & applicant position on Reg Ouide 1 13 W/Gertificate of Svc BIDDLE, C F. NEWMAN. J. R. Houston Lighting & Power Co. BIDDLE, C T Baker & Botts BO/04/24 37pp
- 8007020636 Order denying B Daker 800411 motion to compel discovery from applicant, consolidating certain of Baker, Cumings, Tx PIRG, Doggett & Perrenod contentions & granting partial relief to Rentfro & Morrack re motion to compel applicant answers HDLFE.S J Atomic Safety and Licensing Board Panel 80/06/27 Spp
- 80070300&; Protective order allowing JF Doherty to inspect specific safety-related items from vendor OE "Reed Rept." in possession of util Insp is conditioned on confidential treatment per enci agreement WOLFE.S J Atomic Safety and Licensing Board Panel 80/06/27 App
- BDD723024& FOIA request for 20 documents for use as intervenor in facility proceeding DOHERTY.J F Doherty.J (* 80/06/27 4pp
 - orwards Page 12 to be inserted in applicant response to JF th set of interrogatories Related correspondence Baker & Botto 80/06/20 ip

- --B007080019 Page 12 of applicant response to JF Doherty 14th set of interrogatories Includes info re rod drop analysis & performance BIDDLE,C T Houston Lighting & Power Co 80/06/30 ip
- --B0070B0017 Response to UF Doherty 15th set of interrogatories. Contains statements re neutron data.clad swelling calculation.control pod drop accident & reactor pressure vessel pedestal Affidavit & Certificate of Svc enci BIDDLE.C T, NEHMAN.J R Howston Lighting & Power Co BIDDLE.C.T. Baker & Botts B0/06/20 21pp
- 8007090290 Request to withdraw portion of intervenor 800611 motion to compel discovery from applicant due to availability of certain documents for insp.re most recent rate case H/Ceptificate of Svc encl Related correspondence BAKER, B Affiliation Unknown 80/06/30 2pp
- ~-8007090298 Accepts suggested financial qualification contentions Saler
 1. Cumins 1. Doggett 4. Perrenod 1 & TX PRIO Addi 31 Agraes to
 be lead party provided that applicant answers Doggett first
 set of interoggatories W/Certificate of Svc
 BAKER, B Affiliation Unknown 80/06/30 2pp
- 800708005B Motion for issuance of subpoens directed to D Marrack for 800708 deposition, por ASLB 800623 Momorandum & order Certificate of Svc & draft subpoens w/deposition schedule encl Related correspondence CULP, R H, CUPELAND, J G Houston Lighting & Power Co CULP, R H Lowenstein, Newman, Reis, Axelred & Toll 80/07/01 9pp
- BOO7090189 Answers to BA Doggett & WM Perrenod interrogetories Identifies H Dean as witness anticipated to testify re financial qualifications includes info re cost of delays & GA funding W/affidavit & Certificate of Bvc GOPELAND, J O , NEWHAN, J R Houston Lighting & Power Co GDPELAND, J O Baker & Botts BO/07/01 21pp
- 8007080030 Confirms 800702-03 teleons & advises of 800710 meeting at Travolodge Astrodome to discuss contentions motions for summary disposition & proposals for hearing schedule Input & suggestions are beneficial BLACK, R L Hearing Branch ! 80/07/03 2pp
- 8007080044 Confirms teleon agreement NRC responses to 13th set of interrogatories will be filed by 800721 & to 14th set of interrogatories by 800728
 SDMINKI'S M Hearing Branch 3 80/07/03 ip
- BOO7310116 Interrogatories & requests for production of documents directed to util Requests identification of witnesses & expert testimony-related documents w/factual basis for expert optnion
 BISHOP J M , BISHOP, M Affiliation Unknown 80/07/05 ip
- 8007310108 Interrogatories & request for documents directed to util Requests most recent population projection data & methodology used for updating projection Related correspondence BISHOP,J N , DISHOP,M Affiliation Unknown 80/07/06 8pp
- B007140540 Response to applicant first set of interrogatories & request for production of documents re impact of transmission lines & FEB MARRACK D Marrack, D B0/07/08 ip
- --8007160565 Response to applicant second set of interrogatories & request for production of documents re intervenor pleadings before ASLB & ASLAB Certificate of Evc encl MARRACK, D Marrack, D 80/07/08 3pp
- 8007160570 Response to D Harrock first set of interrogatories. Includes statements re transmission lines & alternative transmission sites & routes Prospective witness FJ Schlight prof qualifications, affidavit & Certificate of Svc encl HANCOCK, D. NEMMAN, J. R. Houston Lighting & Power Co HANCOCK, D. Baker & Botts 80/07/08 iipp
- BOO7170159 Fourth set of interrogatories directed to util re financial qualifications includes questions on disciplinary actions & role of Houston Industries Related correspondence BAKER,B L. Affiliation Unknown BO/07/08 9pp.
- --B007170171 First set of interrogatories directed to NRC re financial qualifications, hearing expectation & witnesses intended to be called BMER, B L Affiliation Unknown B0/07/08 4pp

.

i

- 6007160645 Response to intervenor D Marrack 800508 interrogatories Identifies expert witnesses expected to be called in support of consolidated Rentfro Contention 2 Affidavit & Certificate of Svc encl
 HANCOCK, D , NEWMAN, J R Houston Lighting & Power Co HANCOCK, D Bater & Botts 80/07/09 13pp
- BOO7170374 Interrogatories & request for production of documents directed to NRC Requests factual basis of anticipated testimony re natural gas use as fuel & subsequent costs of electricity W/Certification of Svc Related correspondence SCOTT.J M Texas Public Interest Research Group BO/07/09 4pp
- B007140015 Advises of Chairman of ASLB suggestion that parties meet on B00710 to present schedule agreement to Board E0H1NKI.8 M Hearing Branch 3 80/07/10 2pp
- B007160639 Response in opposition to intervenor JF Doherty B00627 motion for financial assistance ASLB authority does not extend to appropriation of funds Certificate of Svc encl COPELAND. J O . NEMMAN. J R Houston Lighting & Power Co COPELAND. J O Baker & Botts B0/07/11 Spp
- 8007220552 Response in apposition to applicant 800626 request for denial of intervenor 800611 motion to compel Applicant & NRC did not roise timely objections to intervenor due right to discovery W/supporting documents & Certificate of Svc HARRACK,D Harrack,D RENTERO,W Affiliation Unknown 80/07/12
- 8007180432 Response to JF Deberty 19th request for documents Literature on applicant turbine, NEDD 21, 617 re analog transmitter trip unit sys, Figures 15 1-38 2 % 7 7-2 of FSAR & other documents are available for insp & copying Certificate of Svc encl BIDDLE.C T, NEWMAN.J R Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/07/15 4pp
- 8007180240 Forwards FH Potthoff 800709 hand-serviced first set of interrogatories directed to Houston Lighting & Hower BLACK:R L Hearing Branch 1 80/07/16 1p
- --8007180276 First set of interrogatories directed to Houston Lighting & Power Requests factual info re U fuel sources, costs, method of wining & stripping, site & extent of mining & feasibility of manne biofarm for synthetic natural gas supply POTTHOFF,F H Affiliation Unknown 80/07/09 2pp
- 8007220004 Order advising that ASLB will dismiss R Framson Contention i & will permit litigation of JF Doherty Contention il Directs FH Potthoff to respond to applicant first interrogatories by 800727 Marrack motion to quash subpoema denied as most WOLFE,S J Atomic Safety and Licensing Doard Panel 80/07/16 2pp
- 8007230240 Partial response to FOIA request for 20 documents for use as intervenor in facility proceeding Forwards documents listed in App A No documents have been located suby to Items 1 & 2 Bearch is continuing W/o encls
 FELTON.J M Division of Rules and Records 80/07/14 3pp
- 8007230603 Objections to applicant & NRC schedule proposal given at 800710 meeting Dates of responses re summary disposition & grehearing conference re financial qualifications, unreasonably early Questions rewriting of contentions BAKER, D Affiliation Unknown 80/07/16 2pp
- BOO7180426 Forwards notice of RL Black appearance & CP Woodhead withdrawal in proceeding BLACK R L Hearing Branch 1 80/07/17 4pp
- 8007220021 Response in opposition to JF Deherty 800427 motion for financial assistance from funds appropriated by Congress Forthcoming change in rules will provide relief per Gommission 791210 approval Certificate of Svc encl BOHINKI. 8 M Hearing Branch 3 80/07/17 4pp
- 8007220159 Forwards NRC proposed schodule & NRC proposed revised schedule suggesting 800808 prehearing conference Tentative contentions encl for prehearing framework re summary disposition & simplification of text SOHINKI,8 M Hearing Branch 3 60/07/18 113pp
- BOO7240010 Partial response to JF Doberty 13th set of interrogatories Includes statements & discussions re transport theory, rod drop accident & spent feel pool loss of water Explains feel rod ballooning & swelling Widffidavit & Certificate of Svc MOON, C W Assistant Director for Licensing 80/07/21 38pp

- 8007250424 Response to Potthoff 900716 motion for extension of discovery Applicant will respond to untimely interrogatories & other discovery requests by 800731 Certificate of Svc encl
 COPELAND, J G , NEWNAN, J R Houston Lighting & Power Co COPELAND, J O Baker & Botto 80/07/21 4pp
- 8007300116 Motion for preparation of suppl to FFS adequately assessing Class 9 accident impact Alleges that FES will violate NEPA if Class 9 is not addressed Urges review of environ contentions W/Certificate of Svc 900TT.J M Texas Public Interest Research Oroup 80/07/21 8pp
- B007230703 Order scheduling B00B13-14 prehearing conference in Houston,
 Ti Schedule for responses to motions for summary disposition
 & for testimony & commencement of evidentially hearing with
 be set during conference Contentions will be simplified
 WOLFE,S J Atomic Safety and Licensing Board Fanel 80/07/22 2pp
- BOO7270082 Response to Potthoff first set of interrogatories Objects to majority of inturrogatories on basis of irrelevancy Applicant has not commissioned study on marine bio farm feasibility to provide synthetic gas W/Certificate of Svc COPELAND. J G , NEWMAN, J R Houston Lighting & Power Co BO/07/23 7pp
- 8007290746 Order admitting deferred contentions re adequacy of emergency evacuation plans Directs consolidation of contentions & initiation of discovery by 800905 Schoussler admitted as intervening party Defines actions re final rule LINENBERGER.G A. WOLF.S J. Atomic Safety and Licensing Board Panel 80/07/24 2pp
- 8007300413 Response to Daker request for documents Most recent rate filing before TX Public Util Commission available for insp & copying Certificate of Svc encl Related correspondence COPELAND. J G . NEWMAN. J R . Houston Lighting & Power Co COPELAND. J G . Baker & Botts 80/07/24 3pp
- BOO7300449 Response to Doherty requests for admissions Admits presence of small blowdown load due to BMR pipe rupture Admits lack of automatic mouns to place RHR sys in cooling mode W/ Certificate of Svc & affidavit Relatid correspondence COPELAND, J G Metropolitan Edison Cu NEMMAN, J R Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/07/24 14pp
- BD07300402 Response to B00709 interrogatories & request for production of documents includes info re natural gas alternative, conservation & interconnuct.orror in computer program & technical qualifications Cortificate of Svc enc. COPELAND, J. G. Houston Lighting & Power Co. CUPELAND, J. G. Baker & B070725 3ipp
- B007300435 Response to B00706 interrogatories & requests for production of documents includes into re movement of Braios River toward proposed pipeline route & max peak overpressure for each critical structure Certificate of Svc encl COPELAND, J 0 Houston Lighting & Power Co COPELAND, J 0 Daker & Botts 80/07/25 17pp
- B007310094 Response to JM & M Bishop B00705 interrogatories & requests for production of documents Identifies witnesses & summarizes substance of testimony Certificate of Svc & profiqualifications encl Related correspondence COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co COPELAND, J G , Baker & Botts 80/07/25 17pp
- BOO731030B Response to JF Doherty 14th set of interrogatories Submits info re qualification of welder & procedures for cadwelding Describes scram reactivity function & coefficient Affidavit & Certificate of Svc encl Related correspondence COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co COPELAND, J G , Daker & Botts & BU/07/25 25pp
- 8007300397 Partial response to fourteenth set of interrogatories Includes info re application of North Anna criterial pressure vessel integrity & fracture toughness surveillance program CW Moon affidavit & Cortificate of Svc encl SOMINKI, 8 M Hearing Branch 3 MOGN, C W Assistant Director for Licensing 80/07/28 13pp
- 8007300404 Partial response to fifteenth set of interrogetories
 Includes info re control rad drift outresonance parameters
 & gadalinia distribution in furl pellets CW Haon affidavit
 & Certificate of Svc encl
 80HINKIS M Hearing Branch 3 MODN.C W Assistant Director for
 Licensing 80/07/28 15pp

100423 Response to intervenors' first set of interrogatories re mancial qualifications SER Suppl 2 contains out-of-date fo NTC will present analysis when will updates filings wf qualifications.offidavit & Centificate of Svc encl JN.C H Assistant Director for Licensing SCHINKI.S H Hearing anch 3 80/07/28 13pp

300424 Response to JF Doherty 800708 second request for admissions mits that NRC misstated info provided in Amend 2 to ilication Discusses failure to scram on routine shutdown Jul 1900 Affidavit & Certificate of Svc encl NKING N Hearing anch 3 B0/07/28 5pp

310312 Partial responses to TX PIRC interrogatories & production of cuments includes statements re FES.PSAR & QA program scusses reduction of occupational radiation exposures sinst Reg Guide 8 08 W/affidavit & Certificate of Svc N.C W Assistant Director for Litensing 80/07/29 27pp

310473 Forwards NUREC-0594. "Occupational Radiation Exposure at mmercial Nuclear Power Reactors 1978." re NRC 800729 sponse to TX PIRC interrogatories & production of cuments H/o encl ACK.R L Hearing Branch 1 80/07/30 ip

meral correspondence

300348 Requests change of addressee on NRC correspondence from Turner to GH Oprea.Jr Address is unchanged IEA.G H Houston Lighting & Power Co 80/07/23 1p

T 50-457 ALLENS CREEK NUCLEAR STATION, UNIT 2

110243 Forwards Commission 800527 memorandum & order containing cassons on UCS 780502 petition for reconsideration of 1413 memorandum & order UCB 771104 petition sought action fire protection for electrical cables 18NHUT, D G Division of Licensing 80/06/25 89pp

230246 FDIA request for 20 documents for use as intervenor in ilisty proceeding HERTY.JF Doherty.JF BD/06/27 4pp

30240 Partial response to FOIA request for 20 documents for use as ervenor in facility proceeding Forwards documents listed App A No documents have been located subj to Itoms 1 & 2 rich is continuing M/o encls.
TON.J M Division of Rules and Records 8D/07/16 3pp

neral correspondence

19034B Requests change of addressee on NRC correspondence from Turner to GH Oprea, Jr Address is unchanged EA.O H Houston Lighting & Power Co 80/07/23 1p

T 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2
plication/construction stage documents & correspondence

30001 Forwards statement of policy re requirements to be met for rent OL applications, as derived from NUREG-0560 & found NUREG-0594

ENHUT. D G Division of Licensing 80/06/26 2pp

judicatory correspondence

10243 Forwards Commission B00327 memorandum & order containing isions on UCS 780502 petition for reconsideration of 413 memorandum & order UCS 77104 petition sought action fire protection for electrical cables ENHUT.D G Division of Licensing 80/06/25 87pp

ion reports, IE Bulletins & correspondence

Reporting of Info in required e Director DOCKET SYN-50-482 HOLF CREEK GENERATING STATION

A Application/construction stage ducuments & correspondence

8007250046 Summary of 800401 meeting w/util in Bethesda.MD re review plans for utils DL applications
LICITRA.E A Licensing Branch 3 80/04/29 5pp

G007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694 EISENHUT, D Q Division of Licensing 80/06/26 2pp

BD07170313 Discusses Dames & Moore & KS Geological Survey evaluations of possible pop-up in floor of ultimate heat sink Pop-ups mapped in floor are nontectonic & pose no hazard to integrity of safety-related structures LEFEVAE: H Geosciences Branch 80/07/02 3pp

--B007170317 Forwards photographs of two minor pop-up features in upper part of Plattsmouth Limestone in ultimate heat sink escavation at facility Concurs w/D Fenster & site geologists that pop-ups were caused by differential thermal espansion. WILSON, F W Kensas, Univ of 80/06/02 7pp

8007300337 Forwards Union Electric & KS Cas & Electric responses to NRC questions re facility design & const GA programs Revised GA program.incorporating util commitments & agreements, will be available within YO days
SEIKEN'S J Nuclear Power Plant Standards Committee 80/07/28
24pp

80073005ii Forwards info & drawings re Category i masonry walls, in response to 80072i itr Calculations and PETRICK.N A Standardized Nuclear Unit Power Plant System 80/07/29 79pp

---B007300514 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 1,974 Ft " * Bechtel Corp 10466 79/04/04 1p

--B007300317 "Architectural Ausiliary & Reactor Bldg Floor Plan, Elevation 2.000 Ft " * Bechtel Corp 10466 79/04/04 19

--8007300520 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2.026 Ft " * Bechtel Corp 10466 79/11/05 ip

--B007300521 "Architectural CMU Wall Penetrations, Auxilary Bldg "
4 Bechtei Corp 10466 79/04/14 ip

--B007300522 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466 79/04/04 ip

--9007300524 "Architectural CMU Wall Penetrations, Control Bldg " # Bechtel Corp 10466 79/08/19 ip

--B007300526 "Architectural Auxiliary & Reactor Bldg Floor Plans, Elevations 1,988 ft,1,989 ft & 2,013 ft,6 Inches " * Bechtel Corp 10466 79/04/04 1p

--8007300528 "Architectural CMU Wall Penetrations, Control Bidg & Communication Corridor" "Bachtel Corp 10466 80/01/23 ip.

--B007300533 "Architectural.CMU Wall Penetrations.Control Bldg & Communication Corridor" * Bechtel Corp 10464 79/03/29 1p.

---8007300534 "Architectural, Auxiliary Bldg, Btair A-2, Plans & Sections "
* Bechtel Corp 10466 78/10/04 ip

--8007300535 "Architectural CMU Wall Fenetrations, Control Bldg & Communication Corridor" * Bechtel Corp 10466 80/03/13, 1p

---8007300536 "Architectural. Auxiliary Bldg, Elsvator2, Plans & Sactions."

* Dechtel Corp 10466 78/10/04 ip

- ---BO07300538 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor"

 Bechtel Corp 10466 79/03/29 ip
- --B007300539 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor " * Sechtel Corp 10466 80/03/05 1p
- - Bachtel Corp 10466 78/09/11 1p
- --B007300542 "Architectural Control & Diesel Generator Bldgs & Gommunication Corridor Floor Plans Elevations 2,000 & 2,016 Ft."
 - Bechtel Corp 10466 79/04/04 ip
- --B007300546 "Architectural Control & Diesel Generator Bldgs & Communication Corridor Floor Plans, Elevations 2,032 & 2,047
 - Bechtel Corp 10466 79/04/04 1p
- ---B007300547 "Architectural General Masonry Details "
 * Bechtel Corp 10466 80/01/28 ip
- ---B007300549 "Architectural Lontral Bldg & Communication Corridor Floor Plan.Elevations 2,073 Ft.6 Inches & Roof Plan.Elevation 2,087 Ft.2 Inches " * Bechtel Corp 10466 79/04/04 ip
- --- 8007300554 "Architectural Access Control Floor Plan. Elevation 1,784
 - Ft " * Egchtel Corp 10466 78/08/29 1p
- -- 8007300556 "Architectural Access Control & Control Room Areas, Interior Bechtel Corp 10466, 79/04/19 1p

- -8007300564 "Architectural Computer Room & Control Room Detailed Floor Plans,Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466 80/01/28 ip
- --- B007300568 "Architectural Communication Corridor, Stair CC-1, Plans & * Bechtel Corp. 10466 B0/01/07 1p
- --8007300570 "Architectural Elevator 1 Communication Corridor Plans. Sections & Details " * Bechtel Corp 10466 80/02/26 1p
- F Security, medical, emergency & fire protection plans
- 8007110137 Informs that responses have not been received to Encl i of 800320 request for add1 info on 0A program for fire protection YOUNGELOOD, B. J. Licensing Branch i 80/06/30 2pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D G Division of Licensing 80/06/25 89pp

- 8007220140 Forwards final response to 791102 ltr re concerns on NAZ20140 Forwards Final response to Allog its re concerns of facility Areas of response include extended time for Commission decision, location & condition of PDR in Burlington-KS & corruption allegations
 ETELLO. V Dffice of Inspection & Enforcement, Office of the Director 80/07/03 3pp
- --8007220146 Advises that Commissioners Kennedy & Hendrie & Chairman Ahearne agree that Director's decision re const activities need not be reviewed Commissioner Bradford preferred Commission to make review Problems w/contractor sited CHILK, 8 J Office of the Secretary of the Commission B0/03/3i
- --8007220154 Requests reason forr time extension for investigation into revoking CP for proposed facility Suggests transfer of LPDR to more accessible librery NRC should not depend on util to rept internal personnel corruption
 WHITE,T Affiliation Unknown 79/11/02 2pp
- H General correspondence
- 8007250633 Responds to 770904 ltr to DOE re const problems at facility NRC 770718 ltr to Christy attempted to dispel concern re adequacy of concret an base mat Ltr from KS Btate Bldg Trades Council encl in support of NRC position STELLO.V Office of Inspection & Enforcement, Diffice of the Director 80/07/07 App
- --8007250647 Responds to KS State Bldg & Const Trades Council 790808 ltr NO ARC base mat acceptance decisions were based on concrete samples made from base mat tust mix Structure will meet intended safety function Related documentation enci STELLO, V Office of Inspection & Enforcement, Office of the Director 79/10/02 14pp
- M Antitrust correspondence
- 8007250698 Requests util suppl antitrust info submitted w/800506 ltr Requests response within 30 days NASH,D Utility Finance Branch 80/07/08 3pp
- 8007230547 Forwards FR notice of receipt of info for antitrust review of DL application Notice will be published simultaneously in listed newspapers & trade Journals
 YOUNGBLOOD, B J Licensing Branch 1 80/07/10 2pp
- --8007230552 Notice of receipt of info for antitrust review of DL application
 YOUNGBLODD, B J Licensing Branch 1 80/07/10 2pp
- 8007280013 Forwards FR notice re receipt of info for antitrust review of DL application, YOUNGBLOOD,B J Licensing Branch 1 80/07/10 ip
- 8007280015 Forwards FR notice of receipt of info for antitrust review YOUNGBLOOD, B J Licensing Branch 1 80/07/10 Jp
- G. Inspection reports, 1E Bulletins & correspondence
- BOO7250321 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary BEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/31
- BO07240513 Forwards IE info Notice 80-21. "Anchorage & Support of Bafety-Related Electrical Equipment " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director BO/05/16
- 8007070083 Forwards 1E Insp Rept 50-482/80-08 on 800407-11 & 28-29 & notice of deviation

 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering

 Support Branch 80/05/23 2pp
- ---B0070700B7 Notice of deviation from insp on 800407-i1 & 28-27 * Region 4, Dallas, Office of the Director 80/05/22 ip
- --8007070091 IE Insp Rept 50-482/80-08 on 800407-ii & 28-29
 Noncompliance noted failure to designate cable tray for use in Class IE & 11/1 as wafety-related CROSSHAN, W.A., OBERG, C.R., MARTIN, L.E. Region 4, Dallas, Office of the Director 80/05/22 iipp

- 8007110187 Forwards IE Insp Rept 50-482/80-09 on 800429-0502 & notice
 - of violation

 SEIDLE:W C Region 4, Dailas, Reactor Construction & Engineering
 Support Branch 80/05/23 2pp Support Branch
- ***B007110192 Notice of violation from insp on 800429-0502
 * Region 4. Dallas. Office of the Director 80/05/2 80/05/22 3pp
- --6007110198 IE Insp Rept 50-482/80-09 on 800429-0502 Noncompliance NOVILOYME IE Insp Rept 50-482/480-09 on 890489-0902 Noncompliance noted improper storage of safety-related items, failure to identify nonconforming conditions & failure to provide adequate test procedures
 CROSSHANA A . DEERG. C R . TAPIA. J I Region 4. Dallas, Office of the Director 60/05/22 9pp
- 8007020259 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 8007210348 Forwards 1E Carcular 80-13, "Grad Strap Damage in Heatinghouse Fuel Assemblies " No wratten response required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/05/28
- B007010025 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps" No written response required SEYFRIT.K V Region 4. Dellas. Office of the Director 80/05/29
- B007010162 Responds to 1E Bulletim 79-2B. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Top cover gaskets on switches e/applicable date codes will be replaced on valves listed in encl
 PETRICK.N A Standardized Nuclear Unit Power Plant System B0/06/02 2pp
- 8007100441 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "SNUPPB recycle holdup tanks do not depend on pressure regulators to compensate for Ievel variations
 PETRICKAN A Standardized Nuclear Unit Power Plant System 2pp 80/06/05
- B007220109 Forwards 16 Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/10
- 8007160324 Forwards IE Info Notice 90-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required
 EEYFRIT, K V Region 4. Dallas. Office of the Director 60/05/11
- B007290066 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 95(el " No written response required SEYFAIT.K V Region 4. Dallas, Office of the Director 80/06/13
- BOO7020378 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Two safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICKIN A Standardized Nuclear Unit Power Plant Gystem 80/06/16 lp
- 8007280724 Forwards It Insp Rept 50-482/60-11 on 800527-30 & notice of violation
 SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 90/06/17 2pp
- --8007280728 Natice of violation from insp on 800527-30 * Region 4. Dallas, Office of the Director 80/04.

50-482/80-11 on 800527-30 Noncompliance noted ation welds in accordance w/NE-4000

ruction &

Pump

720

- 8007170673 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/24
- 8007230373 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular 80-16 also encl No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/27
- 8007290013 Act receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-492/80-09 SEIDLE,W C Region 4. Dellas. Reactor Construction & Engineering Support Branch 80/07/09 ip
- --B007290017 Responds to NRC B00523 ltr re violations noted in IE Insp Rept 50-482/80-09 Corrective actions Daniel mechanical supervision instructed by const manager re UP-I-01 procedures KDESTER. C L Kansas Gas & Electric Co BO/06/24 4pp
- B Reportable occurrences, LERs & related correspondence
- 8005090053 Interim defictioncy rept re Ruskin vertical fire dampers. Due to problems identified after 800215 rept. addl design mode are required for dampers & will be described by 800515 PETRICK.N A Standardized Nuclear Unit Power Plant System. 80/04/03 2pp
- 8007020068 PNO-IV-80-022 on 800610, five craftsmen were terminated as result of investigation by site mgt & Level 1 GC civil inspector terminated for entry of false test info OBERG.C R. CROSMAN.W A Region 4, Dailas, Office of the Director 80/06/11 2pp
- 800721004B Ack receipt of B00612 final deficiency rept re Bunker Remo Corp electrical penetration assemblies. Rept will be reviewed & evaluated CARLSON R T Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/25 ip
- 8007210231 Ack receipt of 800606 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON R T Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/26 ip
- 8007070325 Discusses 800620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficiency per 10CFR50 33e PETRICK,N A Standardized Nuclear Unit Power Plant System 80/26/20 1p
- B007290245 Ack receipt of B00612 ltr re pipe support sway strut defictioncy Rept expected by B00731 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/03 ip
- --8007290254 Confirms 800611 telcon requesting extension until 800731 to submit rept of significant deficiency re pipe support sway struts Add1 time required for further engineering examination & study SEIKEN, S J Standardized Nuclear Unit Power Plant System 1 p
- 8007310297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping break CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 1p
- --8007310302 Deficiency ropt to postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design ovolution Does not consider matter reportable per 10CFRSO 55(e)
 PETRICK,N A Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8007290590 Final deficiency rapt re generic deficiencies in Corner & Lada. Inc pipe support sway struts funite insp &/or tests will assure that assemblies are acceptable for use Corner & Lada generic rept encl PETRICK, N A Standardized Nuclear Unit Power Plant System 80/07/24 9pp

U Congressional/Executive Correspondence

- 9007110546 Responds to 800516 ltr re delays in DL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE J F Commission 80/06/23 lp
- --8007i10552 Responds to 8005i6 itr re delays in DL application reviews Full review schedules are being developed for licensing of docksted applications Delays resulted from TMI-2 accident AMEANING, J F Commission 80/06/23 lp
- --B007i10566 Responds to B00516 ltr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AMEARNE.J F Commission B0/06/23 ip
- --8007i10568 Responds to 800516 ltr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNEI, F. Commission 80/06/23 lp
- ---B007110371 Discusses concerns about delays in NRC review of OL applications NRC failure to carry-out review in timely manner increases cost of electricity supplied to constituents

 EAOLETON, T. F. DANFORTH, J. C., KASSEBAUM, N. L. Senate 80/05/16

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 6007250046 Summary of 600401 meeting w/otil in Sethesda.MD re review plans for utils OL applications
 LICITRA.E A. Licensing Branch 3 60/04/25 5pp
- B007100379 Forwards Eachtel rept BLUE-700 & Daniel Intl Corp 800529 telcon record sheet & GC Procedure GCP-507.Revision 5.per NRC 800527 request for addl info on cabed rept Number of sabeds involved to be determined by Jul 1980 BCHNELL.D P Union Electric Co B0/06/19 40pp
- B007140574 Confirms 800626 meeting w/util in Glen Ellyn, IL to discuss proposed reorganization of Daniels Intl GA/GC function KEPPLER, J. G Region 3. Chicago, Office of the Director 80/06/24
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREQ-0660 & found in NUREQ-0694
 EIBENHUT, D Q Division of Licensing 80/06/26 2pp
- 8007270034 Declines 800618 invitation to attend State of MD Dept of Natural Resources 800716 public hearing re NPDES application due to prior commitments Requests copy of hearing testimony DENTON.H.R Office of Nuclear Reactor Regulation. Director 80/07/21 2pp
- 8007300337 Forwards Union Electric & KS Oas & Electric responses to NRC questions re facility design & const QA programs Revised QA programs incorporating util commitments & agreements.will be available within 90 days

 BEIKEN.8 J Nuclear Power Plant Standards Committee 80/07/28
- R007300511 Forwards info & drawings re Category 1 masonry walls, in response to 800721 ltr Calculations encl PETRICK.N A Standardized Nuclear Unit Fower Plant System 80/07/29. 79pp
- --B007300514 "Architectural Auxiliary & Reactor Dldg Floor Plan, Elevation 1,974 Ft " * Bachtel Corp 10466 79/04/04 ip
- ---B0073D0517 "Architectural Auxiliary & Reactor Bldg Floor Plan. Flevation 2,000 Ft " # Bechtel Corp 10466 79/04/04 1p
- --8007300520 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2,026 Ft " * Bechtel Corp. 10466 79/11/05 lp

- ~~8007300521 "Architectural CMU Wall Penetrations.Auxilary Bldg " * Bechtel Corp 10466 79/04/14 lp
- ~-8007300522 "Architectural Autiliary & Reartor Bldg Floor Plan, Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466 79/04/04 lp
- --8007300524 "Architectural CMV Wall Penetrations, Control Bldg "
 # Bechtel Corp 10466 79/08/19 ip
- ~-8007300526 "Architectural Auxiliary & Reactor Bldg Floor Plans, Elevations 1,988 ft,1,989 ft & 2,013 ft,6 inches " * Bechtel Corp 10466 79/04/04 1p
- --B007300528 "Architectural CMU Wall Penetrations.Control Bldg & Communication Corridor" * Bechtel Corp 10466 80/01/23 1p
- --B007300529 "Architectural Auxiliary Bldg, Stairs A-1 & A-1A, Plans & Bechtel Corp 10466 78/10/04 1p
- --B007300533 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor "

 * Bechtel Corp 10466 79/03/29 lp
- ~-8007300534 "Architectural Auslivary Bldg. Stair A-2, Plans & Sections "
 # Bechtel Corp 10466 78/10/04 ip
- --B007300535 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor "
 # Bechtel Corp 10466 80/03/13 tp
- --8007300536 "Architectural Auxiliary Bldg. Elevator2, Plans & Sections "
 # Bechtel Corp 10466 78/10/04 ip
- --8007300538 "Architectural CMU Wall Penetrations.Control Bldg & Communication Corridor "

 * Bechtel Corp 10466 79/03/29 1p
- --8007300539 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor" * Bachtel Corp. 10466 80/03/05 lp
- --8007300540 "Architectural Control & Diosel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 1,974 & 1,984 Ft " * Bechtel Corp 10466 78/09/11 1p
- ---B007300542 "Architectural Control & Diesel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 2,000 & 2,016 Ft "
 - * Dechtel Corp 10466 79/04/04 ip
- --8007300543 "Architectural CMU Wall Penetrations, Control Bldg. Communication Corridor & Radwaste Bldg * Bechtel Corp 10466 B0/03/12 1
- --8007300546 "Architectural Control & Diesol Generator Didgs & Communication Corridor, Floor Plans, Elevations 2, 032 & 2, 047 Ft "
- Bechtel Corp 10466 79/04/04 1p
- --8007300547 "Architectural General Mgsonry Details " * Bechtel Corp 10466 00/01/28 ip
- --8007300549 "Architectural Control Bldg & Communication Corridor Floor Plan Elevations 2,073 ft. & Inches & Roof Plan Elevation 2,087 ft. 2 Inches " # Bechtel Corp 10464 79/04/04 lp
- --8007300551 "Architectural General Masonry Details " * Bechtel Corp 10466 79/10/22 1p
- --8007300554 "Architectural Access Control Floor Plan, Elevation 1,984 * Bechtel Corp 10466 78/08/29 1p
- --- 8007300536 "Architectural Access Control & Control Room Areas, Interior Elevations " * Bechte) Corp 10466 79/04/19 1p
- ---B007300559 "Architectural Control Bldg & Communication Corridor, Miscollaneous Details & Stairt C-2, CC-2 & CC-3 " * Bechtel Corp 10466 79/03/07 1p

- --8007300562 "Architectural Hot Lab Equipment & Furniture Layout, Elevations & Details, Elevation 1.984 Ft " * Bechtel Corp 10466 78/09/15 1p
- --8007300564 "Architectural Computer Room & Control Room Detailed Floor Plans, Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466 80/01/28 ip
- --8007300566 "Architectural Control Bldg. Stair C-1, Plans & Section " * Bechtel Corp 10466 78/08/24 ip
- --- 8007300568 "Architectural Communication Corridor, Stair CC-i, Plans &
 - Bechtel Corp 10466 80/01/07 1p
- --8007300570 "Architectural Elevator i Communication Corridor Plans, Sections & Details " * Bechtel Corp 10466 80/02/26 ip
- F Security, medical, emergency & fire protection plans
- B007110154 Informs that responses have not been received to Encl 1 of B00320 request for addl info on QA program for fire protection YOUNGELOOD. B J. Licensing Branch 1 B0/06/30 2pp
- 8007(50534 Informs that guard training plan required by 10CFR73, App B. will be submitted by 80(10)(BRYAN, J K Union Electric Co 80/07/08 2pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007270085 Responds to 800328 ltr from Lawson.MO school students to Fresident Carter re adequacy of qualifications of personnel designing plant Centain design activities failed to meet NRC requirements Util corrective actions under review DIRCKS.W J Office of the Executive Director for Operations 80/05/30 lp
- 8007250070 Responds to encl 800504 ltr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- O Inspection reports. IE Bulletins & correspondence
- 8007140522 Forwards IE Insp Rept 50-483/80-12 on 800407-25 & notice 107/140522 Furwards 1- 2007 ... of violation FloRELLI, G. Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/05/19 2pp
- --8007140526 Notice of violation from insp on 800407-25 * Region 3, Chicago, Office of the Director 80/0 80/05/16 16
- ~-B007140541 IE Insp Rept 50~483/80~12 on 800407~25 Noncompliance noted failure to assure that applicable regulatory requirements are correctly translated into drawings procedures & instructions NNOP.R C . HANSEN.W A Region 3. Chacago, Office of the Director 80/05/16 Epp
- 8007210401 Forwards le Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No writton response required KEPPLER. J O Region 3. Chicago, Office of the Director B 80/05/28
- 8007010123 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director, 80/05/29
- BOO7010162 Responds to IE Bulletin 79-28, "Possible Matfunction of NAMCO Model EA180 Limit Buitches at Elevated Temps " Top cover gaskets on swatches w/applicable date codes will be replaced on valves listed in encl PETRICK: N A Standardized Nuclear Unit Power Plant System. 80/04/02 2pp

- 8007150017 Forwards IE Insp Rept 50-483/80-13 on 800506-09, No northwares is insp Rept 70-489/80-13 on 800506-09, No noncompliance noted FIDIRELLI,0. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/04 2pp
- --8007150023 IE Insp Rept 50-483/80-13 on 800306-09 No noncompliance noted Major areat inspected followup of 10CFR30 53e repts & procedures & work on seal welds for control rod drive machanisms

 ERH,C A , VARDEL,T E , KNOP,R C Region 3, Chicago, Office of the Director BD/06/04 Epp
- BOO7100441 Responds to IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 SNUPPS recycle holdup tanks do not depend on pressure regulators to compensate for level variations
 PETRICK:N A Standardized Nuclear Unit Power Plant System.
 BO/06/06 2pp
- 8007210116 Forwards IE Insp Rept 50-483/80-10 on 800326-27 & 0502, No noncompliance noted

 KEPPLER, J Q Region 3, Chicago, Office of the Director 90/06/10,
- --8007210125 IE Insp Rept 50-483/80-10 on 800326-27 & 0502 No NOVED LE INSPIRED SUMBSIDE OF ON BUOSED AND NO NORMALISMED OF A GOOD NO NO NORMALISMED OF A GOOD NORMALISMED OF A GOOD NORMALISMED OF A GOOD NORMALISMED OF A GOOD OF A CHICAGO, Office Of the Director 80/06/09 7pp
- 8007220222 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required REPPLER.J G Region 3. Chicago. Office of the Director 80/06/10
- 8007160200 Forwards IE Info Notice 80 27, "Degradation of Reactor Capiant Pump Studs " No specific action or response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/06/11
- 8007280628 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER,J G Region 3, Chicago, Office of the Director 60/06/13
- 8007020378 Responds to IE Bullatin 80-09, "Hydramotor Actuator Deficiencies " Tuo safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor Actuate Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICKN A Standardized Nuclear Unit Power Plant System 80/06/16 lp
- 9007100436 Forwards exhibits which were omitted from IE Insp Rept 50-483/80-10
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/17 13ap
- 8007020570 Forwards IE Circular 80-15, "Loss of Reactor Coolant Puap Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/20
- 8007:709:8 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel "No written response required. KEPPLER:J G Region 3, Chicago: Office of the Director 80/06/24. 80/06/24.
- B007300151 Forwards IE Insp Rept 50-483/80-16 on 800610-12 No noncompliance noted FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/06/24 2pp
- --8007300157 IC Insp Rept 50-483/80-16 on 800610-12 No noncompliance noted Major areas inspected followup of 10CFRSO 55(e) repts & unresolved item WEBCOTT, H M , GALLAGHER, E J , KNOP, R C Region 3, Chicago, Office of the Director 80/04/24 3pp
- 8007300160 Forwards 1E Insp Rept 50-483/80-15 on 800501-30 & notice of violation FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 2pp
- --- 8007300164 Notice of violation from insp on 800501-30, Region 3. Chicago, Office of the Director 80/0 80/06/23 1p

- --B007300169 IE Insp Rept 50-483/B0-15 on B00501-30 Noncompliance noted failure to assure that electrical components stored in place were properly protected from damage or deterioration HAMSEN, H A. KNOP, R C Region 3, Chicago, Office of the Director B0/06/23 iipp
- BOO7230343 Forwards IE Bulletin 80~16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80~16 also encl No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/06/27
- 9007150002 Ack receipt of B00606 & i3 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-463/80-09 on B00423-24 FIORELLI, O Region 3. Chicago. Reactor Construction & Engineering Support Branch
- --B007150006 Responds to NRC B00314 1tr re violations noted in IE Insp Rept 30-4B3/B0-09 Corrective actions civil & mechanical GC conducted training review sessions w/insp personnel BRYAN.J.K Union Electric Co B0/06/06 4pp
- ---B007150010 Supplements B00606 response to NRC B00514 ltr re violations noted in IE Insp Rept 50-483/B0-09 Corrective actions all safety-related surface-mounted plates installed prior to B00501 will be reinspected.

 BRYAN.J.K. Union Electric Co B0/06/13 3pp
- BOO7210198 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Forwards Apps D & E of Bechtel Power Garp Epsc 10466-M-203 providing details re weld joints, page ast & size for flued head penetration essemblies.
 BRYAN, J K. Union Electric Co 80/07/01 5pp
- 8007130456 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-483/80-12 FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/07/07 ip
- B. Reportable occurrences. LERs & related correspondence
- BOO714019B Ack receipt of 800616 interim deficiency rept re surface mounted plates Final rept will be reviewed upon receipt FIDRELLI.0 Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/24 ip
- BOO721004B Ack receipt of BOO612 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies Rept will be reviewed & svaluated. CARLEON,R T Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/06/25 ip
- 8007210231 Ark receipt of 800505 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON.R.T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/26 1p
- BOO7070325 Discusses BOO620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficiency per 10CFR50 55e PETRICK, N. A Btandardized Nuclear Unit Power Plant System BO/06/30 1p
- BOO7270245 Ack receipt of BOO612 ltr re pipe support sway strut deficiency, Rept expected by BOO731. CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch BO/07/03 ip
- --B007290254 Confirms B00611 teleon requesting extension until 800731 to submit rept of significant deficiency re-pipe support sway struts. Addl time required for further engineering examination be study SEIKEN, B. J. Standardized Nuclear Unit Power Plant System B0/06/12, 1p
- 8007310297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping break
 CARLSON, R. T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 ip
- ---BOO7310302 Deficiency rept re postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design evolution Does not consider matter reportable per iOCFR50 55(e) PETRICK,N A Standardized Nuclear Unit Power Plant System. BO/06/30. ip.

- 8007250336 Interim deficiency rept re out-of-tolerance conditions on major bolt & minor nut diameters for maths supplied by Industrial Mechanics. Inc Insp program ostablished & equipment on order final rept expected by Bol201 BRYAN, J K Union Electric Co 80/07/18 1p
- B007290590 Final deficiency rept re generic deficiencies in Corner & Lada. Inc pipe support sway struts Onsite insp &/or tests will assure that acsemblies are acceptable for uso Corner & Lada generic rept encl
 PETRICK.N A Standardized Nuclear Unit Power Plant System
 B0/07/24 9pp
- U Congressional/Executive Correspondence
- B007ii0546 Responds to B005i6 itr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission B0/06/23 ip
- --8007110552 Responds to 800516 itr re delays in OL application reviews Full review schedules are being devoloped for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission 80/06/23 lp
- --B007i10566 Responds to 800516 ltr re delays in OL application reviews Full review schedules are being devaloped for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE. J F Commission 80/06/23 ip
- --B007i10568 Responds to B008i6 ltr re delays in OL application reviews Full review schedules are buing developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission 80/06/23 ip
- ---BOO7i10571 Discusses concerns about delays in NRC review of OL applications NRC failure to carry-out review in timely manner increases cost of electricity supplied to constituents

 EAGLETON, T F , DANFORTH, J C , KASSEDAUM, N L Senate 80/05/16
- BOO7280509 Responds to BOO530 itr re assignment of NRC project manager for facility & delay in NRC review of OL applications for plants under const in MO Project manager has been assigned to facility Licensing delays resulted from THI-2 DIRCKS, W J Office of the Executive Director for Operations BO/07/07 ip
- DOCKET STN-90-484 TYRONE ENERGY PARK, UNIT 1
- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUT.D 0 Division of Licensing 80/06/26 2pp
- Q. Adjudicatory correspondence
- B007010256 Forwards NRC 800616 order requiring licenses to show cause why CP should not be revoked since util intends to cancel project
 project
 DENTON H R Office of Nuclear Reactor Regulation, Director
 80/06/16 2pp
- --8007010263 Order to show cause why CP should not be revoked since licensee intends to cancel project DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/16 Jpp
- BOO7010272 Grants 790815 request that CF be revoked because of licensee decision to cancel project Forwards NRC BOOA16 order that licensees how cause why license should not be revoked DENTON.HR Office of Nuclear Reactor Regulation, Director BO/OA/14 in
- B007080086 Proposed findings of fact & conclusions of law responding to ABLAB questions on Battelle rept Findings are adopted by TM1-2/Peachbottom Intervenors & Ecology Action Urges suspension of Ots Pertificate of Svc encl MEPFORD. C Environmental Coalition on Nuclear Power 80/06/18
- 8007070310 Forwards response to NRC 800616 ltr & order to show cause why License CPPR-157 should not be revoked No objection raised BAXER,T A Shaw, Pittman, Potts & Trowbridge 80/07/01 ip

- --8007070313 Response stating no objection to 800616 to order to show cause why License CPPR-137 should not be revoked BAXTER, T A Northern States Power Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 80/07/01 ip
- E007150475 Ack receipt of NRC 800616 ltr w/encl show cause order issued to applicants Phone number & new address submitted for further correspondence likBlG.R Badger Safe Energy Alliance, Inc. 80/07/07 ip
- BOO7150458 Petition for late intervention & motion to defer revocation of CP Cancellation of unit will have substantial & negative impact on present & fluture electric interstate market due to being integral part of development Certificate of Svc encl FRANCIS.F E South Dakota. State of FRANCIS.F E North Dakota. State of FRANCIS.F E North Dakota. State of FRANCIS.F E Spiegel & McDiarmid 80/07/11 9pp
- B00725040B Response in opposition to Dakota Commissions' 8007il motion to defer action on petition to intervene re 800616 order to show cause Commissions did not actually request hearing & do not have requisite interest Cortificate of Svc encl BAXTER.T A Northern States Power Co BAXTER.T A Shew, Pittmen, Potts & Trowbridge 80/07/22 Bpp
- BOO7290703 Comments in opposition to Dakota Commissions' 800711 untimely motion to intervene Petitioners failed to assert interest NRC has no jurisdiction CP should be revoked W/certification of svc GALAZEN. 7 Northern Thunder 80/07/23 2pp
- I Financial information
- 8007010421 Annual Rept 1979
 # Cooperative Power Association 79/12/31 29pp
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT I
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be mat for current OL applications. as derived from NUREO-0660 & found in NUREO-0674
 EISENHUT, D & Division of Licensing 80/06/26 2pp
- G Adjudicatory correspondence
- 8007080086 Proposed findings of fact & conclusions of law responding to ASLAB questions on Battelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges suspension of GLs Certificate of Svc encl
 KEPFORD, C Environmental Coalition on Nuclear Power 80/06/18
 12pp
- 80070B0046 Response to AGLAB request re Deficiency i Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN, R Ecology Action of Oswego 80/06/20 2pp
- BOO7080048 Proposed fundings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Perkins rationals & urges development of further evidence re failure mechanisms & human factors CAPLAN,R Ecology Action of Oswego 80/06/20 4pp
- Q Inspection reports. IE Builetins & correspondence
- 8007010288 Forwards 1E Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " Na written response required ORIER.B M Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 8007010162 Responds to IE Bulletin 79~28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Top cover gaskets on switches w/applicable date codes will be replaced on valves listed in enc!
 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/02 2pp
- 8007100441 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 SNUPPS recycle holdup tanks do not depend on pressure regulators to compensate for level variations PETRICK.N A Stendardised Nuclear Unit Power Plant System 80/06/06 2pp

- 8007210615 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIER.8 H Region 1, Philadolphia. Office of the Director 80/06/10 ip
- 8007160367 Forwards iE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/06/11 10.
- 8007280619 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55to) " No written response required GRIER.B H Region 1, Philadeiphia, Office of the Director 80/86/13 ip
- 6007020378 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Two safety-related uses of ITT General Controls Hodels AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 80/06/16 1p
- 8007020508 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.D H Region 1, Philadelphia, Office of the Director 80/06/20 10
- 8007i60744 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/06/24 ip
- B007210284 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required ORIER,B H Region 1, Philadelphia. Office of the Director, B0/06/25 ip
- 8007230180 Forwards 1E Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1191 & 1192 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also enci No written response required GRIER, B H Rogion i, Philadelphia, Office of the Director, 80/06/27 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007210231 Ack receipt of 800606 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/26 ip
- 8007070325 Discusses 800620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficiency per 10CFRSO 55e
 PETRICK-N A Standardized Nuclear Unit Power Plant System 80/06/30 to
- 8007310297 Ack recoipt of B00630 final deficiency rept re postulated feedwater line piping break CARLSON.R T Region 1. Philadeiphia. Reactor Construction & Engineering Support Branch 80/07/11 ip
- --8007310302 Deficioncy rept re postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design evolution Does not consider matter reportable per iOCFRSO 55(e) PETRICK.N A Standardized Nucloar Unit Power Plant Bystem. 80/04/30 ip
- DOCKET BTN-50-486 CALLOWAY PLANT, UNIT 2
- A Application/construction stage decuments & correspondence
- 8007250046 Summary of 800401 meeting w/util in Bethesda.MD ra raview plans for utils OL applications LICITRA.E A Licensing Branch 3 80/04/20 5pp
- 8007100379 Forwards Bechtel rept RLVE-700 & Daniel Intl Corp 800529 telcon record sheet & QC Procedure GCP-507, Revision 5, par NRC 800529 request for addl info on ambed rept Number of smbeds involved to be determined by Jul 1980 8CHNELL D F Union Electric Co. 80/06/19 40pp

- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0560 & found in NUREG-0574
 EIBENHUT, D 0 Division of Licensing 80/05/25 2pp
- 8007300337 Forwards Union Electric & KS Gas & Electric responses to NRC questions re facility design & const GA programs Revised GA program, incorporating util commitments & agreements, will be available within 90 days
 ESIKEN, 8 J Nuclear Power Plant Standards Committee 80/07/28
- B007300511 Forwards info & drawings re Category i masonry walls, in response to B00721 ltr Calculations encl PETRICK, N. A Standardized Nuclear Unit Power Plant System B0/07/29 778pp
- -6007300514 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 1,974 Ft " * Bechtel Corp. 10466. 79/04/04 1p
- ---B007300517 "Architectural Auxiliary & Reactor Bldg Ficor Plan, Elevation 2,000 Ft " # Bechtel Corp 10466 79/04/04 ip
- -8007300520 "Architectural Auxiliary & Reactor Dldg Floor Plan, Elevation 2,026 Ft " Bechtel Corp 10466. 79/11/05 1p
- -8007300522 "Architectural: Auxiliary & Reactor Bldg Floor Plan, Elevation 2.047 Ft.& Inches " # Bechtel Corp 10466. 79/04/04 1p
- --8007300324 "Architectural CMU Wall Penetrations, Control Bldg." * Bechtel Corp 10466 79/08/19 ip
- -B007300526 "Architectural Ausiliary & Reactor Bldg Fioor Plans, Elevations 1,988 Ft, 1,989 Ft & 2,013 Ft, 4 Inches " # Bechtel Corp. 10466 77/04/04 lp.
- -8007300529 "Architectural Auxiliary Bldg. Stairs A-1 & A-1A, Plans & Eachtel Corp 10466 78/10/04 ip

- ---B007300334 "Architectural Auxiliary Bldg. Btair A-2. Plans & Bections " Eschtel Corp 10466 78/10/04 ip

- ---B00730033B "Architectural CMV Wall Penetrations.Control Bidg & Communication Corridor."

 * Bechtel Corp. 10466 79/03/29 ip
- -8007300539 "Architectural CMU Wall Penetrations, Control 81dg & Communication Corridor." * Eachtel Corp. 10466 80/03/05 1p
- --8007300540 "Architectural Control & Dissel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 1:974 & 1:984 Ft."
 - Bechtel Corp. 10466 78/09/11 ip
- --- B007300342 "Architectural Control & Diesel Generator Bldgs & Communication Corridor Floor Plans Elevations 2:000 & 2:016 Ft."
 - Bechtsi Corp. 10466 79/04/04 ip
- --8007300543 "Architectural CMU Wall Penetrations, Control Bldg. Communication Corridor & Radwaste Bldg " * Bechtel Corp 10466 80/03/12 ip

- --B007300546 "Architectural Control & Diesol Generator Bldgs & Communication Corridor, Floor Plans, Elevations 2, 032 & 2, 047 Ft " Bechtel Corp 10466 79/04/04 1p
- --8007300547 "Architectural General Masonry Details " * Bechtel Corp 10466 80/01/28 lp
- --8007300549 "Architectural Control Bidg & Communication Corridor Flo Plan Elevations 2.073 Ft.6 Inches & Roof Plan Elevation 2.087 Ft.2 Inches " * Bechtel Corp 10466 79/04/04 lp
- --8007300551 "Architectural General Masonry Details "
 * Bechtel Corp 10466 79/10/22 Up
- --8007300554 "Architectural Access Control Floor Plan. Elevation 1, 984 Bechtel Corp 10466 78/08/29 1p
- --8007300556 "Architectural Access Control & Control Room Areas, Interi Elevations " * Bechtel Corp 10466 79/04/19 1p
- --8007300559 "Architectural Control Bldg & Communication Corridor, Miscellaneous Details & Stairs C-2.00-2 & CC-3 " * Bechtel Corp 10466 77/03/07 1p
- --8007300562 "Architectural Hot Lab Equipment & Forniture Layout, Elevations & Details, Elevation 1,984 Ft " * Bechtei Corp 10466 78/09/15 ip
- --B007300364 "Architectural Computer Room & Control Room Detailed Flor Plans, Elevation 2.047 Ft. 6 Inches " * Bechtel Corp 10466 80/01/29 ip
- --8007300366 "Architectural Control Bldg. Stair C-1, Plans & Section "
 * Bechtel Corp 10466 78/08/24 ip
- --8007300568 "Architectural Communication Corridor, Stair CC-1, Plans & Bection " * Bechtel Corp 10466 BO/01/07 ip
- --B007300570 "Architectural Elevator | Communication Corridor Plans. Sections & Details " * Bechtel Corp 10466 B0/02/26 1p
- F Security, medical, emergency & fire protection plans
- 8007150534 Informs that guard training plan required by iOCFR73, App D, will be submitted by 801101
 BRYAN.J K Union Electric Co 80/07/08 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing fecisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical co
- H General correspondence
- BOO7270085 Responds to BOO328 ltr from Lawson, MD school students to President Carter re adequacy of qualifications of personnel designing plant Certain design activities failed to meet NRC requirements Util corrective actions under review DIRCKS WJ Defice of the Executive Director for Operations BO/05/30 lp
- B007250070 Responds to encl 800504 itr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENION.H R Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8007210401 Forwards 1E Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/05/28.

- 8007010123 Forwards IE info Notice 80-23, "Loss of Suction to Emergency Fuedwater Pumps" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director BO/05/29 10
- 8007010162 Responds to IE Builetin 79-28, "Possible Halfunction of NAMCO Model PAI80 Limit Suitches at Elevated Temps" Top cover gaskets on suitches w/applicable date codes will be replaced on valves listed in encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/02 2pp
- 8007100441 Responds to iE Builetin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks "SRUPPS recycle holdup tanks do not depend on pressure regulators to compensate for level variations PETRICKIN A Standardized Nuclear Unit Power Plant System 80/08/06 2pp
- 8007220222 Forwards 1E Info Notice 80-26. "Evaluation of Contractor QA Programs " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/10 in
- 8007160200 Forwards IE Info Notice 80 27. "Degradation of Reactor Coulant Pump Studs " No specific action or response required MEPPLER. J 0 Regson 3. Chicago. Office of the Director 60/06/11
- 8007280628 Forwards iE lnfo Notice 80-28, "Frompt Reporting of Info in Accordance W/iOCFR50 55(e)" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/13
- 8007020378 Responds to IE Bulletin 80-09. "Hydremotor Actuator Deficiencies " Two safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK, N A Standardized Nuclear Unit Power Plant System 80/06/16 19
- 8007020570 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J O Region 3. Chicago, Diffice of the Director 80/06/20
- 8007170518 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/06/24 ip
- 8007230343 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required XEPPLER.J 9 Region 3, Chicago. Office of the Director 80/06/27.
- B0072:0198 Responds to IE Bulietin 80-08, "Exam of Containment Liner Penstration Walds "Forwards Apps D & E of Bechtel Power Corp Spec 10466-H-200 providing details re weld joints, pipe math & size for flued head penetration assembliss BRYAN.J K Union Electric Co 80/07/01 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007140198 Ack receipt of 800616 interim deficiency rept re surface mounted plates Final rept will be reviewed upon receipt FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip
- 800721004B Ack receipt of 800512 final deficiency rept re Bunker Ramp Corp plettrical penetration assemblies Rept will be reviewed & evaluated CARLSONAR T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/25 ip
- 8007210231 Ack receipt of 800404 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON R T Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/24 ig

- B007070325 Discusses 800620 rept of potential deficiency re-excessive pressure in fredwater lines following postulated high energy line break Excessive pressure does not constitute deficienty per 10CFR50 55e
 PETRICKN A Standardized Nuclear Unit Power Plant System B0/06/30 1p
- 8007270245 Ack receipt of 800612 ltr ro pipe support sway strut deficiency Rept expected by 800731 GARLESDN.R T Region 1. Philadeiphia. Reactor Construction & Engineering Bupport Branch 80/07/03 1p
- --B007290284 Confirms 800611 telcon requesting extension until 800731 to submit rept of significant deficiency re pipe support sway struts. Addl time required for further engineering examination & study SEIKEN, S. J. Standardized Nuclear Unit Power Plant System 8026412 1884
- 80073i0297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping break
 CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 ip
- --B0073i0302 Deficiency rept re postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design evolution Does not consider matter reportable per 10CFR50 55(e) PCTRICK,N A Standardized Nuclear Unit Power Plant System, 80/06/30 ip
- 8007250336 Interim deficiency rept re out-of-tolerance conditions on major holt & minor nut diameters for metis supplied by Industrial Mechanics, Inc. Insp program established & equipment on order Final rept expected by 80i201
 BRYAN.J K Union Eiectric Co. 80/07/18 lp
- 800729090 Final deficiency rept re generic deficiencies in Corner & Lada. Inc pipe support sway struts Onsite insp &/or tests wiii assure that assemblies are acceptable for use Corner & Lada generic rept encl.
 PETRICK.N A Standardized Nuclear Unit Power Plant Bystem BC/07/24 9pp
- U Congressional/Executive Correspondence
- B007ii0546 Responds to B005i6 ltr re delays in OL application reviews. Full review schedules are being developed for licensing of docksted applications Delays resulted from TMI-2 accident AHEARNE, J. T. Commission B0/06/23 lp
- --8007i10552 Responds to 8005i6 ltr re delays in OL application reviews. Full review schedules are being developed for licsnsing of docketed applications Delays resulted from TMI-2 accident. AHEARNE.J F. Commission 80/06/23 lp
- --B007110566 Responds to 800516 ltr re delays in CL application reviews.
 Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE.JF. Commission B0/06/23
- --B007110568 Responds to 800516 ltr re delays in OL application reviews.
 Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AMEARNE, J F Commission 80/06/23 ip
- --BO07110371 Discusses concerns about delays in NRC review of OL applications NRC failure to carry-out raview in timely manner increases cost of electricity supplied to constituents

 EAQLETON, T. F., DDLE, R. Benate BO/05/16. 4pp
- BOO7280509 Responds to BO0520 ltr re assignment of NRC project menager for facility & delay in NRC review of DL applications for plants under const in MD Project manager has been assigned to facility Licensing delays resulted from TMT-2. DIRCKB.H J Office of the Executive Director for Operations BO/07/07 ip
- DDCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D O Division of Licensing 80/06/26 2pp

18 - - ---

Q Adjudicatory correspondence

- BOO6200066 Forwards Pages 4.5 & 6 which were inadvertently omitted from Ethible A of High Rock Lake Association BOO521 affidavit

 BPRINGER.D High Rock Lake Association BO/05/23 ip
- B007310243 Forwards Commission 800927 memorandum & order cuntaining decisions on UCS 780902 patition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D Q Division of Licensing 80/04/25 B9pp
- BO07020475 Request for 30-day extension to file brief in support of D Bpringer B00415 petition to intervene & request for hearing Certificate of Bvc encl BPRINGER, D Affiliation Unknown 80/06/27 2pp
- 8007030243 Buppl withdrawing argument presented in NRC B00626 response in opposition to intervenors' motion to reconsider or reopen record Untimely filing is no longer asserted per ALAB-597 but motion still fails to meet stds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 4pp
- BOO7090311 Comments on D Springer 800321 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC 800505 response to D Springer 800415 petition Certificate of Syc encl BARTH.C A Hearing Branch 3 80/07/08 4pp
- BOO711034B Order granting 20-day extension for Opringer to file brief in support of 800415 petition Extension begins upon receipt of NRC 800708 response to Opringer affidavit filed in CP proceeding BOMERS E 8 Atomic Safety and Licensing Board Panel 80/07/09 is

Q Inspection reports, IE Bulletins & correspondence

- 8007240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- 0007210439 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 ip,
- B00701018B Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Factor Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 1p
- 8007220054 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 2pp
- 8007160230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coplant Pumps Studs " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/11 ip.
- 8007250368 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFRSO 55(e)" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007170096 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/06/24 to

- 600723022B Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Dutput Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 10
- B007250532 Forwards response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & Pabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code, including Summer 1977 addenda DAIL, L. C. Duke Power Co. 80/07/07 6pp

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

- A Application/construction stage documents % correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREO-0560 & found in NUREO-0594
 EISENHUT, D O Division of Licensing 80/05/26 2pp

O Adjudicatory correspondence

- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D G Division of Licensing 80/06/25 89pp
- B007020475 Request for 30-day extension to file brief in support of D Springer 800415 petition to intervene & request for hearing Certificate of Svc encl
 SPRINGER, D Affiliation Unknown B0/06/27 2pp
- 8007030243 Suppl withdrawing argument presented in NRC 800626 response in opposition to interveners' motion to reconsider or reopen record Untimply filing is no innger asserted per ALAB-597 but motion still fails to meet stds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 4pp
- B0070903il Comments on D Springer B00521 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC B00505 response to D Springer B00415 petition Certificate of Byc encl BARTH:C A Hearing Branch 3 B0/07/08 App
- B00711034B Order granting 20-day extension for Springer to file brief in support of 800415 petition Extension bogins upon receipt of NRC 80070B response to Springer affidavit filed in CP procoeding BOWERS, E 8 Atomic Safety and Licensing Board Panel 80/07/09 ip

@ Inspection reports, IE Bulletins & correspondence

- 8007240129 Forwards IE info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Desse Unit i While in Refueling Mode "
 No response required
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
 Zpp
- 8007210439 Forwards IE Circular BO-13, "Orld Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/29 ip
- B0070101BB Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29 ip
- B007220054 Forwards IE Info Notice B0-26, "Evaluation of Contractor QA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/10
- 8007160230 Forwards 1E Info Notice 80-27, "Degradation of Reactor Goolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 800725036B Forwards lE Info Notice 80-28, "Prompt Reporting of Info in Accordance M/10CFR50 55(e)" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/13 200

- 8007020445 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cuoling & Natural Circulation Cooldnum " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007170096 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required CREILLY, J P. Region 2, Atlanta, Office of the Director 80/06/24
- 80072J0228 Forwards IE Bulletin 90-16. "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- BOO/250532 Forwards response to 1E Bulletin BO-00. "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code: including Summer 1977 addenda DAILL C Dute Power Co 80/07/07 App
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EJSENIUT, D C Division of Liconsing 80/06/26 2pp
- G Adjudicatory correspondence
- 8007020475 Request for 30-day extension to file brief in support of D Springer 800415 petition to intervene & request for hearing Certificate of Svc ancl Springer, D Affiliation Unknown 80/06/27 2pp
- 8007030243 Supp) withdrawing argument presented in NRC 800626 response in opposition to intervenors' motion to reconsider or reopen record Untimely filling as no longer asserted per ALAD-597 but motion still Fails to meet stds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 App
- 8007090311 Comments on D Springer 800521 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC 800505 response to D Springer 800415 petition Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/08 4pp
- 8007110348 Order granting 20-day extension for Springer to file brief in support of 800415 petition Extension begins upon receipt of NRC 800709 response to Springer affidavit filed in CP proceeding 80WERS, E S Atomic Sefety and Licensing Board Panel 80/07/09 1p
- @ Inspection reports. IE Bulletins & correspondence
- 8007240139 Forwards JE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp
- 8007210439 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Surtion to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007220054 Forwards 1E Info Notice 80-26, "Evaluation of Contractor OA Programs" No whitten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 200
- 8007160230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'REJLLY. J P Region 2: Atlanta, Office of the Director 80/06/11,

- 8007250368 Forwards IE Info Notice 80-28. "Frompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/06/13
- BOO7020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20.
- 8007170096 Forwards IE Circular 80-i4. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/04/24 to
- 8007230229 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required. O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/27.
- 8007250532 Forwards response to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code.including Summer 1977 addenda DAIL.L C Buke Power Co 80/07/07 App
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective B0042B States means of appeal of staff position TEDCBCO,R L Assistant Director for Licensing B0/06/12 2pp
- B00723000i Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREC-0660 & found in NUREC-0694 EISENHUT, D Q Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 87pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8007240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- 8007210439 Forwards lE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuol Assemblies " No written response required, D'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/05/29, in
- 800701010B Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director, 80/05/29 in
- 8007220034 Forwards 16 Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 2pp
- B007i60230 Forwards IE Info Notice 80-27, "Degradation of Reactor Content Pump Studs " No specific action or response required TREILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/11 in
- B00725036B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W10CFR50 55(e) " No written response required.
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13 200

- 8007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required
 - O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007170076 Forwards IE Circular 80-14, "Radioactive Contamination of Piant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24
- 8007230228 Forwards IE Bulletin 80-15, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 60-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/2
- 8007250532 Forwards response to IE Bulletin BO-08, "Exam of Containment Liner Penetration Heids " Piping penetrations are designed & fabricated in accordance w/1977 edition of ABME Boiler & Pressure Vessel Code, including Summer 1977 addenda DAIL-L C Duke Power Co 80/07/07 6pp

DOCKET STN-30-492 CHEROKEE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position
 TEDEBCG, R L Assistant Director for Licensing 80/06/12 2pp
- 800723000i Forwards statement of policy re requirements to be met for current OL applications.as derived from NUREG-0660 % found in NUREG-0694 EIGENHUT.D O' Division of Licensing 80/06/26 2pp
- O. Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D.Q Division of Licensing 80/06/25 89pp
- Q Inspection reports, IE Bulletins & correspondence
- B007240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode"
 No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
 208.
- 8007210437 Forwards IE Circular 80-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- B007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/05/29
- 8007220054 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required D'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/10 20s
- 8007160230 Forwards IE Info Notice BO-27, "Degradation of Reactor Coolent Pumps Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- 8007250348 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/13 2bp
- B007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/20

- B007170096 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Persunnel" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/24 to
- 800723022B Forwards IE Sylletin GO-16, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/27 in
- B007230532 Forwards response to JE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Piping genetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code.including Summer 1977 addenda DAIL.L C Duke Power Co 80/07/07 6pp
- DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.R L Assistant Director for Licensing 80/06/12 2pp
- BO07230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0674
 EISENHUT, D 0 Division of Licensing 80/06/26 2pp
- G Adjudicatory correspondence
- 80073i0243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 77i104 petition sought action re fire protection for electrical cables EIBENHUT, D O Division of Liconsing 80/06/25 87pp
- O Inspection reports. IE Bulletins & correspondence
- BOO7240139 Forwards IE Info Notice BO-ZO, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/08
 200
- 8007210439 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28 io
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29 ip
- B007220054 Forwards 1E Info Notice 80-26. "Evaluation of Contractor OA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director G0/06/10 2pp
- B007i60230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pumps Studs" No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/06/11 ip
- 8007250368 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CF650 55(e) " No written response required. D'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/13 2pp
- 8007020445 Forwards JE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Looidown " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007170096 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/24 in

- 8007230228 Forwards IE Bulletsn 80-16, "Potential Misapplication of Resemburt Inc Models 1151 & 1192 Pressure Transmitters WEIther A or D Output Codes 'Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007250532 Forwards response to IE Bulletin BO-OB. "Fiam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edution of ASME Boiler & Pressure Vessel Code.including Summer 1977 addenda DAIL.1 C Duke Power Co 80/07/07 App
- DOCKEY 50-496 MONTAGUE NUCLEAR POWER STATION. UNIT 1

 Application/cunstruction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0699
 EISENHUF, D G Division of Licensing 80/06/26 2pp
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be mot for current DL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D Q Division of Licensing 80/06/26 2pp
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007020673 Responds to 800314 request for revision of items contained in NRC 800417 immediate action 1tr lnacturacies in preliminary info initially provided to Region 4 were included in immediate action 1tr SEYFRIT, K V Region 4. Dailas. Office of the Director 80/06/10 2nn
- --8007020678 Requests revision of items contained in NRC 800417 immediate action ltr to ensure that correct info is transmitted & misinterpretations are minimized Inaccurate info provided to NRC included in immediato action itr TURNER, E A Houston Lighting & Power Co 80/05/14 2pp
- B007020227 Forwards NRC Oft of Nuclear Reactor Regulation B00428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current GL applications as derived from NUREG-0669 & found in NUREG-0694
 EISENHUT, D G Division of Licensing BO/06/26 2pp
- BOO7300375 Requests specific direction & instructions for qualification of stress analysis computer cade Code is planned to be released from AD Little-Inc & will be used in calculations for piping sys (ARME II & Ara NABI 831 1) BARKER.D & Houston Lighting & Power Co BO/07/23 ip
- Adjudicatory correspondence
- 8007020609 Confirms understandings re withdrawals of Brown & Root brochure on implementation of GA program at job site & associated videotape Copies will be available as evidence in order to show cause & pending DL application CUMAN, F E Baker & Botts 80/06/io 3pp.
- EQ07:10001 Answers to NRC interrogatories & request for documents
 Identifies DE Swage as witness intended to be called re
 nonconformance repts of Contention 1 DG Bridenbaugh & R
 Hybbard will be called re Contention 3 W/Certificate of Svc
 SINKIN, L A Committee for Application of Nuremberg Principles to US
 Nuclear Power Production 80/06/13 9pp
- B007310243 Forwards Commission B00327 memorandum & order containing decisions on UCB 780302 petition for reconsideration of 780413 memorandum & order UCB 771104 patition sought action fe fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/25 89pp

- BD07300415 Discusses B0061B deposition & request for documents Requests reasons for document request within 14 days & change in date of deposition to last wk in Jul in San Antonio TX Related correspondence SINKIN, L. Citizens Concerned About Nuclear Power, Inc. B0/07/02
- 8007300406 Requests confirmation that meeting notes, members names, documents & records, position papers, taped convorsations, consent of interviewes, by-laws & notes will be provided as agreed in deposition Related correspondence COMAN,F Baker & Botts 80/07/07 App
- E007160553 Identifies documents to be produced within 30 days per P Buchorn deposition testimony re application for OL Related correspondence MUDSON,T B Baker & Botts 60/07/08 4pp
- B007310145 Motion for discovery schedule extension until B01201 MRC B00430 order to show cause wording parallels Contention I 7 which may be resolved by util corrective actions in answer to order W/Certificate of Svc Rolated correspondence SINNIN.L A Citizens Concerned About Nucloar Power. Inc B1NKIN.L A Citizens for Equitable Utilities B0/07/09 4pp.
- 8007180246 Forwards notice of appearance in proceeding BLACK, R L. Hearing Branch i 80/07/16 2pp
- G007220013 Submits rept re status of onforcement action Early hearing schedule discussions re GA/GC issues should abide enforcement action resolution Day City TX BOOB17 public hearing will be held per ASLB 800430 order BLACK.R L Hearing Branch i 80/07/18 2pp
- B007240485 Advises of status of enforcement action per NRC commitment Houston Lighting & Power responded to 1E 800430 notice of violation & civil penalty by paying amount imposed Affirms postion re discussions of AA/ACC corly hearing schedule BLACK,R L Hearing Branch 1 80/07/18 2pp
- B007300417 Discovery rept for June-Jul 1980 Received B00616 Rentfro & Marrack interrogatorios & replied on 800709 Received B00706 Marrack motion to quash subpoena for deposition. Deposition taken by agreement on 800716 Rolated correspondenco COPELAND; J G Baker & Botts 80/07/18 1p
- 8007300090 Response stating no opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utils motion for discovery extension until 801201 Certificate of Svc encl HUDSON, T B Baker & Botts * Lowenstein Newman, Reis, Azelrad & Toli 80/07/23 2pp
- 8007290748 Response stating no objection to issuance of order extending discovery period until 801201 upon roquest of Citizens Concerned About Nuclear Power No hearings re IE enforcement action are imminent Certificato of Syc encl BLACK.R L. Hearing Branch i 80/07/28 2pp
- H General correspondence
- 8007300348 Requests change of addressee on NRC correspondence from EA Turner to GW Oprea. Jr Address is unchanged OPREA. 0 W Houston Lighting & Power Co 80/07/23 1p
- M Antitrust correspondence
- 8007010247 Forwards work order extending Hartley contract to 800531 W/o encl BLUME, M B Antitrust Division 80/04/14 1p
- 8007010264 Forwards signed stipulation abiding by ABLB 800331 protective order re Howston Lighting & Power corporate study W/o encl BLUME, M II Antitrust Division 80/04/14 1p
- 8007010298 Forwards documents mintakenly omitted from Hartley documents W/o enci HDDGDDN.A P Antitrust Division 80/05/07 lp
- 8007020577 Ack receipt of 800530 ltr to TX Parks & Hildlife Dept advising that TX Utils Generating Co is not propered to anter into lease agreement w/Dapt covering Squaw Cresk Reservior, Requests info re util intentions PREISTER, D J Texas, State of 80/06/10 2pp.

- B007210388 Reviews B00702 draft transmission svc settlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for wheeling "Postage stamp" wheeling rate is not proper in TX BALOUGH R C Austin, TX B0/07/10 2pp
- 8007150425 Btatus rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Svc encl CREEN.D O Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/ii 7pp
- 8007130431 Status rept on settlement negotiations Urges 40-day suspension of proceedings, including hearing date, due to continued negotiations w/Public Utils Doard of City of Brownsville, TX W/Certificate of Svc & pleading before FERC STAHL, D M Central & South West Corp STAHL, D M Isham, Lincoln & Beale 80/07/11 26pp
- 8007150449 Status rept by Public Utlls Board of City of Brownsville, TX re settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc encl PDIRIER.M R Brownsville, TX POIRIER, M R Spiegel & McDlarmid 80/07/11 App
- 8007150500 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc encl
 CHANANIA.F D Antitrust Division 80/07/11 Bpp
- B007160625 Status rept re-settlement negotiation progress Expresses no optimism for agreement w/DDJ but agreement w/NRC may be reached re-license conditions dealing w/buik power wheeling rates Certificate of Svc encl
 SAMPLES,M D KNOTTS,J B Texas Utilitles Generating Co
 SAMPLES,M D Worsham, Forsythe & Sampels 80/07/11 &pp
- B007170364 Status rept re development of settlement discussions Urgss deniel of addl extension of time due to belief that no settlement will be reached between DOJ & applicants Certificate of Svc encl
 CYPHERT. S B Justice, Dept of 80/07/11 6pp
- 80071703BB Second status rapt re settlement negotiations progress Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of 8vc encl
 JOHN.D F Affiliation Unknown JOHN.D F Medinaslectric Copperative, Inc. JOHN.D F McDermott, Mill & Emery BO/07/11 App
- 8007210495 Submits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Hod of joint ownership agreement drafts exchanged Certificate of Sec enci BURCHETTE.W H , RITTS.F H Northcutt Ely 80/07/11 4pp
- B007140347 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests 800708 for briefs & 801006 for commencement of evidentiary hearing Settlement does not appear to be possible Certificate of Syc encl CYPHERT.8 B , PARMENTER,F Justice, Dept of 80/07/14 6pp
- 8007220500 Buggests reconsideration of 800307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402
 MILLER.M.E Atomic Safety and Licensing Board Panel 80/07/16 ip
- BOO7220536 Order denying petitions for directed certification w/o prejudice to resubmission following ABLB determination BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/18
- 8007300418 Withdrawal of 7705i1 notice of appearance R Fabrikant responsible for all communications until further notice Certificate of Svc encl CYPHERT.S D Justice. Dept of 80/07/23 App
- 8007280620 Draws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DOJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 ip
- \$007280627 Motion for extension until 800731 to file objections w/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions w/ parties have commenced & must proceed LEWIS.S H Hearing Branch 2 80/07/25 2pp

- --B007280636 Joint motion for clarification of ASLB 800716 memorandum containing decision to reconsider ASLB 800307 order resettlement documents Mover for order establishing schedule for production of settlement documents W/Certificate of Svc FADRIKANTIR Justice, Dept of CHANANIA, FD, BLUME, MB Antitrust Division 80/07/25 Spp
- B007300354 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order WOLFE,S J. Abomic Safety and Licensing Board Panel 80/07/23 1p

N Antitrust hearing transcripts

- B007180008 Transcript of 800714 arehearing conforence in Dethesda, MD re settlement negatiations Pp 891-946 * Atomic Safety and Licensing Board Panel 80/07/14 78pp
- B00725044i Proposed correction to B00409 prehearing transcript Certificate of Syc encl GREEN.D G Houston Lighting & Power Co * Baker & Botts * Lowenstein.Neuman.Reis.Axelrad & Toll 80/07/22 Spp '
- ⊕ Inspection reports: IE Bulletins & correspondence
- 8007250319 Forwards IE lnfo Notice 80-i2, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4, Dallas. Office of the Director 80/03/31 lo
- 8007150064 Ack receipt of 800109 & 0308 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 SEIDLE: W C Region 4. Bailas. Reactor Construction & Engineering Support Branch 80/04/04 ip
- --8007150075 Responds to NRC 791212 & 800220 ltrs re violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 Corrective actions const procedure CCP-4 revised on 800317 to incorporate baffie board use TURNER.E A Hoveton Lighting & Power Co 80/03/18 2pp
- B007010072 Updates B00331 response to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" No addl info has been received from vendors TURNER.E A Houston Lighting & Power Co 90/04/30 2pp
- 8007230718 Ack receipt of 800430 ltr from NRC Responses to notice of violation, notice of proposed imposition of civil penalties & Section 6 of order to show cause will be submitted within periods specified in NRC notice & orders OPREA, G W Houston Lighting & Power Co 80/05/14 lp
- 8007240505 Forwerds IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRIT.K V Region 4, Dalles, Office of the Director 60/05/16
- 8007010203 Forwards IE Insp Repts 50-498/80-06 & 50-499/80-06 during Apr 1980 No noncompliance noted BEIDEL, W C Region 4. Dalias, Reactor Construction & Engineering Bupport Branch 80/05/19 3pp
- --B007010212 IE lnsp Repts 50-498/80-06 & 50-497/80-06 during Apr 1980
 No noncompliance noted Major areas inspected previous items
 of noncompliance, site tour, safety-related piping, containment
 structural steel & foilowup on const deficiency
 PHILLIPB.H B , CROSSHAN.W A Region 4. Dallas, Office of the
 Director B0/05/13 App
- B007100342 Forwards IE Insp Repts 50~498/80~11 & 50~499/80~11 on 800505-08 No noncompliance noted BEIDLE: W C Region 4. Dallos, Reactor Construction & Engineering Bupport Branch B0/05/23 2pp
- --B007100346 IE Insp Repts 50-498/B0-11 t 50-499/B0-11 on B00505-08 No noncompliance noted Major areas inspected const activities, stop work order for RCPB welding & reactor containment liner dome welding CROBEMAN WA Region 4. Dallas, Reactor Construction & Engineering Support Branch GLBERT, L. D. MARTIN L. E. Region 4. Dallas, Office of the Director B0/05/22 App
- 8007020253 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/28 is

- 8007010037 Forwards 1E Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/27 in
- B007240333 Forwards IE Insp Repts 50-498/80-12 & 50-499/80-12 on 800512-15 No noncompliance noted SEIDLE:N C Region 4, Dollas. Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --8007240337 IE Insp Repts 50-498/80-12 & 50-499/80-12 on B00512-15 No moncompliance noted Major areas inspected observation of work & review of records re earthwork & concrete TAPIA.J I. CROSSMAN.W A Region 4. Dallas. Office of the Director HALL.R E Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/03 6pp
- 6007100433 Updates response to 1E Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches No corrective action required for majority of vendors the vendor still conducting review & other implemented corrective action recommended TURNER, E A Houston Lighting & Power Co 60/05/04 2pp
- 800722009B Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/10 to
- B007020104 Ack receipt of 800523 itr informing NRC of steps taken to correct violations noted in 800430 notice of violation & order to show cause Implementation of existing GA/GC procedures will be focus of followup insp STELLD,V Office of Inspection & Enforcement, Office of the Director 80/06/11 2pp
- 8007170203 Responds to IC Bulletin 80-09 "Aydramator Actuator Deficiencies" No safety-related sys or component in South TX Project uses subj actuators OPREA.0 W Houston Lighting & Power Co 80/06/13 1p
- 8007270059 Forwards IE Info Natice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 95(e) " No written response required SEYFRIT.K V Region 4, Dalias, Office of the Director 80/06/i3
- 8007230278 Forwards 1E Insp Repts 50-498/80-10 & 50-499/80-i0 during May 1980 No noncompliance noted SEIDLE.W C Reginn 4. Dalias. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230292 IE Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted Major areas inspected structural backfill, structural concrete, containment tendons, component storage & followup on const deficiencies CROSSHAN, H A. PHILLIPS, H S. Rogion 4. Daltas, Office of the Director 80/06/17 App
- B007240039 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director B0/06/20
- 8007280132 Forwards IE Investigation Repts 50~498/80-09 & 50~499/80-09 on 800415-18 No noncompliance noted SEYFRIT, K V Region 4, Dailas, Office of the Director 80/06/23 200
- --B0072B0137 IE investigation Repts 50-498/B0-09 & 50-499/B0-09 on B00415-18 No noncompliance noted Major area investigated allogation that Brown & Ruot Inc attempted to intimidate GC inspectors & employees into covering up const defects ERYERIT.K V. DRISKILL.D D. BACI, P E Region 4, Dallas, Office of the Director B0/06/19 10pp

lication of

ed red r 80/05/27

- 8007150007 Forwards IE Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-06 No noncumpliance noted SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/30.
- --8007150009 IC Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-06 No noncompliance noted Major areas inspected allegations that consultant firm had recommended const be discontinued at site for one yr HERR, R K , DRISKILL, D D., SEYFRIT, K V Region 4, Dalias, Office of the Director 80/06/30 App
- 8007090246 Revises IE Bullatin 80-08 review submittal date from 800707 to 0804 OPRCA.0 W Houston Lighting & Power Co 80/07/03 2pp
- 8007220578 Responds to IE Bulletin 79-28 re use of NAMCO Hodel EA 180 stem-mounted limit switches. Review of all vendors indicates only one affected Recommended corrective action implemented OPREA. O W Houston Lighting & Power Co 80/07/14 2pp
- 9 Reportable occurrences. LERs & related correspondence
- 8007100443 Second interim deficiency rept re damage to Unit 2 reactor containment bldg steel liner plate Plate removal & mapping completed Next interim rept to be submitted by 800711 TURNER, E A Houston Lighting & Power Co 80706/06 4pp
- 8007160219 Second interim Part 21 rept re steel liner plate in reactor containment bldg. Progress on repair includes completed removal of deformed liner plate & detailed mapping of removed plate submitted to contractor TURNER, E A Houston Lighting & Power Co 80/06/06 6pp
- 8007070304 Second interim deficiency rept re polar crane rail tie-down studs investigation by vendor concludes that acceptability of polar crane hold-down studs are questionable Brown & Root will further evaluate sys Next report to be sent 800801 TURNER, E A Houston Lighting & Power Co 80/06/23 5pp
- 8007020618 RO on 800529, during design review, seismic qualification of easentiel cooling water intake structure gentry crane & diesel generator fuel storage tank found w/deficient response spectra values New seismic evaluation in progress.

 DPREA, Q W Houston Lighting & Power Co 80/06/26 4pp
- 8007090365 Interim deficiency rept re breakdown in quality program for concrete placement CII-W90 Brown & Root continuing investigation of conditions & examining documentation & physical quality of placement OPREA.O W Houston Lighting & Power Co 80/07/03 2pp
- B007ii0337 Advises that 800605 potentially reportable deficiency reconcrete placement in diesel generator bidg is not reportable under iOCFR50 55(e)

 OPREA.O W Houston Lighting & Power Ca 80/07/03 3pp
- 8007130645 Final deficiency rept re reactor vessel outlet nozzie safeends Evaluation shows that condition would not adversely affect safety of plant operation Matter considered not reportable under 10CFR 80, 35(s) DPREA
- B007160604 Forwards interim deficiency rept re linear plate buige repair Next rept will be submitted B01001 OPREA, G W Houston Lighting & Power Co B0/07/11 3pp
- --8007160609 Interim deficiency rept re linear plate bulge consisting of logic for linear plate bulge repair * Houston Lighting & Power Co 80/07/11 ip
- B0072105ii Third interim deficiency rept re damage to steel liner in reactor containment bldg Logic for liner bulge repair encl Next rept will be forwarded by B0100! OPREA.O W Houston Lighting & Power Co B0/07/11 4pp
- 8007290441 Part 21 rept re latent math noncompliances in ASME Section III pipe supports supplied by NPS Industries Initial review indicates no deficiency since supports are used in nonwelding applications RICE.H M Brown & Root Corp (subs of Halliburton Corp) BO/07/11 Spp
- 8007230512 First interim deficiency rept re breakdown in Brown & Root QA program re procurement cycle of purchased matls at facility Procedures for procurement cycle control & all vendor-related activities & records under review OPREA.G W Houston Lighting & Power Co 80/07/14 5pp

- 8007230525 Interim deficiency rept re diesel generator Fuel oil tank room exhaust fans Per commitments in PSAR & FSAR, fans must be connected to Class IE power Fans not supplied from Class IE source Corrective actions being evaluated OPREA.O W Houston Lighting & Power Co 80/07/16 3pp
- 8007230476 Interim deficiency rept re min/max soil density test on essential cooling water backfill Detailed info re deficiency will be provided to NRC a part of response to Item 2.App A. of 800430 order to show cause OPREA.G W Houston Lighting & Power Co 80/07/17 3pp
- BOO7230540 Interim deficiency rept re matl control of ASTM A-325 structural steel bolts improper segregation of Category I & non-Category I structural steel bolts in field resulted in bolts procured under non-Category I specs OPREA, G W Houston Lighting & Power Co BO/07/i7 4pp
- 8007300382 Interim deficiency rept re re-evaluation of piping welds previously found acceptable Liquid penetrant retest by Bouthwest Research determined that eight welds exhibited lines! indications in excess of code limitations OPREA.O H Houston Lighting & Power Co 80/07/24 3pp

U Congressional/Executive Correspondence

8007300365 Requests testimony presented at 800627 committee hearing re issues relating to const of nuclear power plants ECKHARDT,B House of Rep , Interst & Foreign Commerce 80/07/il

DOCKET STN-50-499 BOUTH TEXAS PROJECT. UNIT 2

A. Application/construction stage documents & correspondence

- 8007020675 Responds to 800514 request for revision of items contained in NRC 800417 immediate action ltm Inaccuracies in preliminary info initially provided to Region 4 were included in immediate action ltm SCYFRIT.K'V Region 4. Dallas. Office of the Director 80/06/10 ZDD.
- --B00702067B Requests revision of items contained in NRC B004i7 immediate action ltr to ensure that correct info is transmitted & misinterpretations are minimized Inaccurate info provided to NRC included in immediate action ltr TURNER.E A Houston Lighting & Power Co B0/05/14 2pp.
- BO07020227 Forwards NRC Dfc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to engoing activities
 TEDESCO:R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0694
 EIBENHUT, D © Division of Licensing 80/06/26 2pp
- BOO7300375 Requests specific direction & instructions for qualification of stress analysis computer code Code is planned to be released from AD Little. Inc & will be used in calculations for pipting sys (ABME II) &/or ANSI B31 1)
 BARKER, D 0 Houston Lighting & Power Co BO/07/23 ip

O Adjudicatory correspondence

- 8007020605 Confirms understandings re withdrawals of Brown & Root brochure on implementation of QA program at job situ & associated videotape. Copies will be available as evidence in order to show cause & pending QL application COHAN. F E Baker & Botts 80/06/10 3pp
- 8007110001 Answers to NRC interropatories & request for documents Identifies DE Swayre as witness intended to be calied re nonconformance repts of Contention 1 DO Bridenburgh & R Hubbard will be called re Contention 3 W/Certificate of Svc. 81NKIN,L A Committee for Application of Nuremberg Principles to US Nuclear Power Production 80/06/19 9pp
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on VCB 780502 petition for reconsideration of 780413 memorandum & order VCB 771104 petition sought action re fire protection for electrical cables.

 EISENHUTID © Division of Licensing 80/06/25 89pp.

- B007300415 Discusses B00618 deposition & request for documents Requests reasons for document request within 14 days & change in date of deposition to last wk in Jul in San Antonio, TX Related correspondence
 SINKIN,L Citizens Conceined About Nuclear Power, Inc. 80/07/02
- 6007300406 Requests confirmation that meeting notes, members names, documents & records, position papers, taped conversations, consent of interviouses, by-laws & notes will be provided as agreed in deposition Related correspondence CDWAN,F Baker & Botts 80/07/07 4pp
- 8007160553 ldentifies documents to be produced within 30 days per P Bucharn deposition testimony re-application for OL Related correspondence HUDSON,T II Baker & Botts 80/07/08 4pp
- 8007310145 Motion for discovery schedule extension until 801201 NRC 800430 order to show cause wording parallels Contention 1 7 which may be resolved by util corrective actions in answer to order M/Certificate of Svc Related correspondence BINKIN.L A Citizens Concerned About Nuclear Power. Inc SINKIN.L A Citizens for Equitable Utilities 80/07/08 App
- 8007180245 Forwards notice of appearance in priceeding BLACK:R L. Hearing Branch i 80/07/16 2pp
- 8007220013 Submits rept re status of enforcement action Early hearing schedule discussions re GA/AC issues should abide enforcement action resolution Day City TX 800817 public hearing will be held per ASLB 800420 order BLACK.R L. Hearing Branch i 80/07/18 2pp
- 8007240485 Advises of status of enforcement action per NRC commitment Houston Lighting & Power responded to 16 800430 notice of violation & civil penalty by paying amount imposed Affirms position re discussions of GA/GC early hearing schodule BLACK:R L Hearing Branch i 80/07/19 2pp
- 8007300417 Discovery rept for June-Jui 1980 Received 800416 Rentfro & Marrack interrogatories & replied on 800709 Received 800706 Marrack motion to quash subponna for deposition Deposition taken by agreement on 800716 Related correspondence COPELAND. J O Baker & Botts 80/07/18 ip
- 8007300090 Response stating no opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utils motion for discovery extension until 801201 Cortificate of Svc encl HUDSON, T B Houston Lighting & Power Co HUDSON, T B Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/23 2pp
- 8007290748 Response stating no objection to issuance of order extending discovery period until 801201 upon request of Citizens Concerned About Nuclear Power No hearings re IE enforcement action are imminent Certificate of Svc encl BLACK.R L Hearing Branch i 80/07/28 2pp

H General correspondence

- 8007300348 Requests change of addressee on NRC correspondence from EA Turner to GW Oprea. Ir Address is unchanged OPREA.O W Houston Lighting & Power Co 80/07/23 ip
- M Antitrust carrespondence
- 8007010247 Forwards work order extending Hartley contract to 600531 W/o encl
 BLUMB, M B Antitrust Division 80/04/14 ip
- 8007010264 Forwards signed stipulation abiding by ASLG 800331 protective order re Houston Lighting & Power corporate study H/o enci BLUME, H D Antitrust Division 80/04/14 (p
- BO0701029B Forwards documents mintakenly omitted from Hartley documents M/a oncl HDD002N.A P Antitrust Division HO/05/07 Ip
- BOO7020977 Ack receipt of BOO990 itr to TX Farks & Hildlife Dept advising that TX Utils Generating Co is not prepared to enter into lease agreement w/Dept covering Squew Greek Reservior Requests info re util intentions PREISTER, D J Texas, State of 80/06/10 2pp

- B007210388 Reviews 600702 draft transmission avoisettlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for unselling "Postage stamp" wheeling rate is not proper in TX BALDUOH.R C Austin, TX 80/07/10 2pp
- B007150425 Status rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Syc encl GREEN,D Q Houston Lighting & Power Co BO/07/11 7pp
- 8007150431 Status rept on settlement negotiations Urges 40-day suspension of proceedings.including hearing date.due to continued negotiations w/Public Utils Board of City of Brownsville.TX W/Certificate of Svc & pleading before FERC. STAHL.D M Central & South West Corp 80/07/11 26pp
- 6007150449 Status rept by Public Utils Board of City of Brownsville,TX re settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc encl
 PDIRIER,M R Brownsville-TX 80/07/11 opp
- B007150500 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission sycs & other areas Certificate of Syc encl CHANANIA.F D Antitrust Division B0/07/11 Bpp
- 8007160625 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DOJ but agreement w/MRC may be reached re license conditions dealing w/bulk power wheeling rates Certificate of Svc encl
 SAMPLES.M D Texas Utilities Generating Co KNOTYS.J B Debevoise & Liberman 80/07/11 App
- 8007170344 Status rept re development of settlement discussions Urges denial of addl extension of time due to belief that no settlement will be reached between DDJ & applicants Certificate of Syc encl
 CYPHERT, 8 B Justice, Dept of 80/07/11 6pp
- 8007170388 Second status rept re settlement negotiations progress. Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc encl
 JOHN, D F Affiliation Unknown 80/07/11 App
- 8007210455 Submits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Certificate of Syc encil BURCHETTE, W. H. Northcutt Ely 80/07/11 4pp
- 8007160547 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests B00708 for briefs & 801006 for commencement of evidentiary hearing Settlement does not appear to be possible Certificate of Svc encl CYPHERT,S B Justice, Dept of 80/07/14 App.
- 80072R0500 Buggests reconsideration of B00307 discovery order in light of extensive settlement negotiations Subsequently conducted by all parties & counsel on 800402 MILLER, ME Atomic Safety and Licensing Board Panel 80/07/16 ip
- 8007220556 Order denying petitions for directed certification w/o prejudice to resubmission following ASLB determination BIBHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/16
- 8007300418 Withdrawal of 790511 notice of appearance & Fabrikant responsible for all communications until further notice Certificate of Svc encl CYPMERT-S B Justice.Dept of BO/07/23 App
- 8007280620 Draws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DDJ joint motion for clarification & for establishment of production schedule CHANANIA:F D Antitrust Division BD/07/25 1p
- B007280627 Motion for extension until B00731 to file objections w/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions w/ parties haye commenced & must proceed LEWIS, S H Rearing Branch 2 80/07/25 2pp

- ~-8007280636 Joint motion for clarification of ASLB 800716 memorandum containing decision to reconsider ASLB 800307 order to settlement documents flows for order establishing schedule for production of settlement documents MyCertificate of Byc FABRIKANT, R Justice, Dept of 80/07/25 8pp
- 8007300356 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order order the MDLFE, S. J. Atomic Safety and Licensing Board Panel, 80/07/25 ip
- N Antitrust hearing transcripts
- 800718000B Transcript of 800714 prehearing conference in Bethesda. MD re settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel 80/07/14 78pp
- B007250441 Proposed correction to B00409 prehearing transcript Certificate of Svc encl OREEN, D O Houston Lighting & Power Co 80/07/22. 5pp
- Q Inspection reports, IE Bulletins & correspondence
- B007250319 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve." No specific action or response necessary SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/31.
- B007150064 Ack receipt of B00109 & 0308 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-498/79-20 & 50-499/79-20 EEIDLE: U C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/04 ip
- --B007150075 Responds to NRC 791212 & B00220 ltrs re violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 Corrective actions const procedure CCP-4 revised on B00317 to incorporate baffle board use TURNER, E A Houston Lighting & Power Co 80/03/18 2pp
- 8007010072 Updates 800331 response to 1E Bulletin 79-20, "Possible Malfunction of NAMCO Model EA180 Limit Buitches at Elevated Temps " No addl info has been received from vendors TURNER, E A Houston Lighting & Power Co 80/04/30 2pp
- B00723071B Ack receipt of 800430 ltr from NRC Responses to notice of violation notice of proposed imposition of civil penalties & Section A of order to show cause will be submitted within periods specified in NRC notice & orders OPREA.0 W Houston Lighting & Power Co 80/00/14 lp
- 8007240505 Forwards IE Info Notice 80-21, "Anchorage & Bupport of Safety-Related Electrical Equipment" No written response required. SEYFRIT, K V Region 4, Dallas. Office of the Director 80/05/16
- 8007010203 Forwards IE Insp Repts 50-498/80-06 & 50-499/80-06 during Apr 1980 No noncompliance noted SEIDEL,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/17 3pp
- B007100342 Forwards IE Insp Repts 50-498/80-11 & 50-497/80-11 on B00505-08 No noncompliance noted BEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch B0/05/23 2pp
- --8007100346 IE Insp Repts 50-498/80-11 & 50-499/80-11 on 800505-08.No noncompliance noted Major areas inspected const activities, stop work order for RCPB welding & reactor containment liner dome welding cRUSSMANN A Region 4, Dallas, Reactor Construction & Engineering Support Branch OILBERT, L.D., MARTIN, L.E. Region 4, Dallas, Office of the Director 80/05/22 Spp
- B007020259 Forwards IE Info Notice B0~22, "Breakdowns In Contamination Control Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director. 80/05/28. ip
- 8007010037 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Freedwater Pumps" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/29.

- 8007240333 Forwards IE Insp Repts 50-498/80-12 & 50-499/80-12 on BOO\$12-15 No noncompliance noted BEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Bupgort Branch 80/06/03 2pp
- --8007240337 IE Insp Repts 50-498/80-12 & 50-499/80-12 on 800512-15 No noncompliance noted Hajor areas inspected observation of work & review of records re earthwork & concrete.

 TAPIA, J I . CROSSMAN, W A Region 4, Dallas, Diffice of the Director HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/03 6pp
- BOO7100433 Updates response to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches No corrective action required for majority of vendors One vendor still conducting review & other implemented corrective action recommended TURNER, E A Houston Lighting & Power Co 80/06/04 2pp
- BOO722009B Forwards IE Info Notice BO~24, "Evaluation of Contractor GA Programs" No written response required BEYFRITK V Region 4, Dallas, Office of the Director 80/06/10 to
- BOQ7020104 Ack receipt of BO0523 ltr informing NRC of steps taken to correct violations noted in BO0430 notice of violation & order to show cause. Implementation of existing GA/GC procedures will be focus of followup insp STELLO,V Office of Inspection & Enforcement, Office of the Director BO/06/ii 2pp
- BOO7170203 Responds to IE Bulletin BO-09 "Hydramotor Actuator Deficiencies " No safety-related sys or component in South TX Project uses subjactuators DRREA. O W Houston Lighting & Power Co BO/06/13 1p
- BO07290059 Forwards IE Info Notice BO-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required. SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/13 in
- BOO723027B Forwards IE Insp Repts 50-498/B0-10 & 50-499/B0-10 during May 1980 No noncompliance noted BEIDLE.N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --B007230292 IE Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted Major areas inspected structural backfill:structural concrete, containment tendons, component storage & followup on const deficiencies
 CROSSMAN; M. A., PHILLIPS; H. S. Region 4, Dallas, Office of the Director 80/06/17 6pp.
- BOO7240039 Forwards IE Circular BO-15, "Loss of Reactor Comlant Pump Gmoling & Natural Circulation Comidown " No written response required BEYFRIT,K V Region 4, Dallas, Office of the Director BO/06/20
- BOO7280132 Forwards IE Investigation Repts 50-498/80-09 & 50-497/80-09 on 800415-18 No noncompliance noted SEYFRIT,K V Region 4, Dallas, Office of the Director 80/06/23.
- --8007280137 IE Investigation Repts 50-498/80-09 & 50-499/80-09 en 800415-18 No noncompliance noted Major area investigated allegation that Brown & Root Inc attempted to intimidate GC inspectors & amployees into covering up const defects SEVFRIT, K V, DRIGKILL, D D., BACT, P E Region 4. Dallas, Office of the Director 80/06/19 10pp
- BOO7170676 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/06/24 is.
- B007230364 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Cutput Codes." Whitten response required IE Circular 80-16 also encl No written response required BEYFRIT.K V. Region 4, Dallas, Diffice of the Director 80/06/27
- BO07130007 Forwards lE Investigation Repts 50-478/80-15 & 50-499/80-15 on 800605-06, No noncompliance noted.

 BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/06/30 is

- --8007150009 fE Investigation Repts 50-498/80-15 & 50-499/80-15 on 800405-06 No noncompliance noted Major areas inspected allegations that consultant firm had recommended const be discontinued at site for one yr HERR.R K. DRISKILL D. SEYFRIT.K V. Region 4. Dailas, Office of the Director 80/06/30 6pp
- B007090246 Revises IE Bulletin B()-0B review submittal date from B00707 to 0804 OPREA, 6 W Houston Lighting & Power Co 80/07/03 2pp
- 8007220978 Responds to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches Review of all vendors indicates only one affected Recommended corrective action implemented OPREA.C W Houston Lighting to Power Co 80/07/14 2pp
- S Reportable occurrences, LERs & related correspondence
- BOO7100443 Second interim deficiency rept to damage to Unit 2 reactor containment bldg steel liner plate Plate removal & mapping completed Next interim rept to be submitted by BOO711 TURNER,E A Houston Lighting & Power Co 80/06/06 App
- 8007160217 Second interim Part 21 rept re steel liner plate in reactor containment bidg Progress on repair includes completed removel of deformed liner plate & detailed mapping of removed plate submitted to contractor TURNER, E A Houston Lighting & Power Co 80/06/06 App
- 8007070306 Second interim deficiency rept re polar crane rail tie-down studs Investigation by vendor concludes that acceptability of polar crane hold-down studs are questionable Brown & Root will further evaluate sys Next report to be sent 800801 TURNER, E A Houston Lighting & Power Co 80/06/23 5pp
- 80D702061B RG on 800527, during design review, seismic qualification of essential cooling water intoke structure gantry crane & diesel generator fuel storage tank found w/deficient response spectra values New seismic evaluation in prograss OPREA, G W Houston Lighting & Power Co 80/06/26 4pp
- BOD7090365 Interim deficiency rept re breakdown in quality program for concrete placement CI1-M90 Brown & Root continuing investigation of conditions & examining documentation & physical quality of placement OPREA, G H Houston Lighting & Pownr Co BO/07/03 2pp
- B007110337 Advises that 800605 potentially reportable deficiency reconcrete placement in diesol generator bldg is not reportable under 10CFR50 55(e)

 DREA, 0 W Houston Lighting & Power Co 80/07/03 3pp
- 8007190645 Final deficiency rept re reactor vessel outlet nozzle safeends Evaluation shows that condition would not adversely affect safety of plant operation Natter considered not reportable under 107FR50 55(e) OPREA
- 8007160604 Forwards interim deficienty rept re linear plate bulge repair Next rept will be submitted 801001 OPREA.G W Houston Lighting & Power Ca 80/07/11 3pp
- --8007160609 Interim deficiency rept re linear plate bulge consisting of logic for linear plate bulge repair

 # Houston Lighting & Power Co 80/07/11 ip
- BO072105il Third interim deficiency rupt re damage to steel liner in reactor containment bldg Logic for liner bulge repair encl Next rept will be forwarded by 801001 OPREA, 0 W Houston Lighting & Power Co 80/07/11 4pp
- BOO7290441 Part 21 ropt re latent math noncompliances in ASME Section III pipe supports supplied by NPS Industries Initial review indicates no deficiency since supports are used in nonwelding applications RICE.W M Brown & Root Corp (subs of Halliburton Corp) BO/07/11 3pp
- 8007230512 First interim deficiency rept re breakdown in Brown & Root GA program re procurement cycle of purchased matis at facility. Procedures for procurement cycle control & all vendor-replated activities & records under review OPREA.O W Houston Lighting & Power Co 80/07/14 5pp
- B007230525 Interim deficiency rept re diesel generator fuel oil tank room exhaust fans Per commitments in PSAR & FBAR.fans must be connected to Class IE power Fans not supplied from Class IE source Corrective actions being evaluated OPREA.Q W Houston Lighting & Power Co B0/07/16 3pp

- 8007230476 Interim deficiency rept re min/max soil density test on essential cooling water backfill Detailed info re deficiency will be provided to NRC as part of response to Item 2.App A. of 800430 order to show cause OPREA.Q W Houston Lighting & Power Co 80/07/17 3pp
- 8007230540 Interim deficiency rept re mati control of ASTM A-325 structural steel bolts Improper segregation of Category I & non-Category I structural steel bolts in field resulted in bolts procured under non-Category I specs
 OPREA, G W Houston Lighting & Power Co 60/07/17 4pp
- 8007300382 Interim deficiency rept re re-evaluation of piping welds previously found acceptable Liquid penutrant retest by Sauthwest Research determined that eight welds exhibited lineal indications in excess of code limitations OPREA.G W Houston Lighting & Power Co 80/07/24 3pp

U Congressional/Executive Correspondence

8007300365 Requests testimony presented at 800629 committee hearing re issues relating to const of nuclear power plants ECKHARDT.B House of Rep , Interst & Foreign Commerce 80/07/11

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D & Division of Licensing 80/04/26 2pp

@ Adjudicatory correspondence

- 8005200066 Forwards Pages 4.5 % 6 which were inadvertuntly omitted from Exhibit A of High Rock Lake Association 800521 affidavit 5PRINGER.D High Rock Lake Association 80/05/23 1p
- --8006200071 Pages 4.9 % 6 for Exhibit A of High Rock Lake Association 800521 affidavit 8PRINGER.D High Rock Lake Association 78/11/16 App

H General correspondence

- 600727004B Responds to inquiry re flooding of site Natural phenomena considered in plant design & const Access to & from plant during flood considered in emergency plan in flood emergency rail, boat or DKW transportation will be utilized KEPFLER, J O Region 3, Chicago, Office of the Director 60/05/22
- 8007020053 Responds to 800520 ltr re J Branum inquiry about facility expansion Counsel for applicants requested that ASLAB terminate proceedings on CP applications due to reduced growth projections & financial constraints No action taken DIRCKS, W J Defice of the Executive Director for Operations 80/04/20 ip

DOCKET 50-501 DAVIS-DESSE NUCLEAR POWER STATION, UNIT 3

- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREO-0660 & found in NUREO-0694
 EIBENHUT, D G Division of Licensing BO/06/26 2pp

H General correspondence

- E007290048 Responds to inquiry re flooding of site Natural phenomenal considered in plant design & const Access to & from plant during flood considered in emergency plan In flood emergency rails boat or DAV transportation will be utilized KEPPLER.J 9 Region 3. Chicago, Office of the Director 80/05/22
- 8007020053 Responds to 800520 itr re J Dranum inquiry about facility expansion Counsel for applicants requested that ASLAD terminate proceedings on CP applications due to reduced growth projections & financial constraints No action taken DIRCKS,W J Diffice of the Executive Director for Operations

- DOCKET BIN-50-502 HAVEN NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current GL applications as derived from NUREO-0660 & found in NUREO-0694 Division of Licensing 80/06/26 2pp EISENHUT. D C

@ Adjudicatory correspondence

- 8007230802 Motion for termination of proceeding Director of Ofc of Nuclear Reactor Regulation notified on 800517 re withdrawal of application Certificate of Evc encl CHURCHILL, B W. Hisconsin Electric Power Co. CHURCHILL, B H. Shaw, Pittman, Potts & Trowbridge 80/07/17 4pp
- 8007310314 Responds to applicants' 800717 motion to terminate protecting No objection to termination or to applicants 800317 withdrawal of application Certificate of Gvc Encl CDLOBERG, 8 C Hearing Branch 2 80/07/29 3pp
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0694 EISENHUT, D 9 Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- 8007300344 Forwards map, overlay, table & methodology basis rd emergency evacuation time estimates por NRC 800702 request RENBERGER.D L Washington Public Power Supply System 80/07/24
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBEANUT.D 0 Division of Licensing 80/06/25 89pp
- G Inspection reports, IE Bulletins & correspondence
- 8007230007 Forwards suppl info to 790525 response to IE Bulletin 78-12 Record search in response to C-E rept. "Atypical Meld Matl in Reactor Vessel Welds." produced no evidence of use of atypical weld matl in reactor prossure vessels RENBERGER.D L Washington Public Power Supply System 80/03/17.
- 8007270405 Forwards insp program committed to in 770710 response to IE Bulletin 77-03 re longitudinal weld defects in stainless steel pips spools No evidence of longitudinal weld defects RENBERGER.D L Washington Public Power Supply System 80/04/15
- B007180023 Forwards IE Insp Repts 50-508/80-05 & 50-509/80-05 on B00513-15 No noncompliance noted B008, HE Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch B0/05/23 2pp
- --8007180025 IE Insp Repts 50-509/80-05 & 50-509/80-05 on 800513-15 No noncompliance noted Major areas inspected organization & administration.procedures.audits & CP requirements YUHAS, O P. HENSLAWSKI, F.A. Region 5, San Francisco, Office of the Director. 800N.H E. Region 5, Ban Francisco, Fuel Facility & Haterials Safety Branch 80/05/28 9pp
- 8007220232 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENCELKEN.R H Region 3, Sen Francisco, Office of the Director 80/05/10
- 8007300306 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks Tanks adoquately protected against Vacuum damage Holdup tanks equipped w/vacuum breakers Equipment drain tank designed for full vacuum w/ntrogen cover gas.
 RENDERGER, D L Washington Public Power Supply System 80/06/12

- B007270070 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 85(e) " No written response required ENOELKEN,R H Region 5, San Francisco, Office of the Director B0/06/13 1p
- 8007020466 Forwards IE Circular 80-15, "Loss of Reactor Coolant Fump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/20 ip
- BOG7180299 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN.R H. Region 5. San Francisco, Office of the Director 80/06/24 ip
- 8007230401 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl. No written response required ENGELKEN, R. H. Region 5, Ban Francisco, Office of the Director 80/06/27, 1p
- BOO7180329 Responds to NRC 800609 ltr re violations noted in IE insp on 800520-23 Corrective actions util has established hold goint to visually inspect all accessible interior/exterior ASME Secton III spool welds RENBERGER, D L Washington Public Power Supply System 80/07/11
- U Congressional/Executive Correspondence
- 9007300367 Submits questions re unusual financing arrangement between util & Bonneville Fower Administration Related correspondence
 MCAVER.J House of Rep 80/07/14 2pp
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0694
 EIBENKUT.D Q. Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- BOO7300344 Forwards map.overlay, table & methodology basis re emergency evacuation time estimates per NRC 800702 request RENBERGER.D L Washington Public Power Bupply System 80/07/24 ilpp.
- Q. Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25. 89pp
- G Inspection reports, IE Bulletins & correspondence
- BOO7230007 Forwards suppl info to 790525 response to IE Bullstin 78-12
 Record search in response to C-E rept, "Atypical Weld Hat!
 in Reactor Vessel Welds," produced no evidence of use of
 atypical weld matl in reactor pressure vessels
 RENBERGER, D. L. Washington Public Power Bupply Bystem 80/03/17
 19.
- 8007290405 Forwards insp program committed to in 790710 response to IE Bulletin 79-03 re longitudinal weld defects in stainless steel pipe spools No evidence of longitudinal weld defects was found RENBERGER, D. L. Washington Public Power Bupply Bystem 80/04/15 330p
- 8007180023 Forwards JE Insp Repts 50-508/80-05 & 50-509/80-05 on 800513-15 No noncompliance noted BOOK.H E. Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch 80/05/23 2pp

- --8007i80025 IE Insp Repts 50-508/80-05 % 50-509/80-05 on 8005i3-i5 No noncompliance noted Major areas inspected organization & administration, procedures, audits & CP requirements YUHAS, 8 P. WENSLAMSKI, F. A. Region S. Ban Francisco, Office of the Director BOK. H E. Region S. San Francisco, Fuel Facility & Materials Safety Branch 80/05/28 9pp
- 8007220252 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required ENGLKEN,R H Region 5, San Francisco, Office of the Director 80/06/10 ip
- 8007300306 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks Tanks adequately protected against vacuum damage Holdup tanks equipped w/vacuum bleakors Equipment drain tank designed for Full vacuum w/nitrogen cover gas RENBERGER, D L. Washington Public Power Supply System 80/06/12
- 8007290090 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/IOCFR50 95(e) " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/13 lp
- 8007020466 Forwards IE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/20 ip
- 8007180299 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel "No written response required ENGELKENIR H Region 5. San Francisco, Office of the Director 80/04/24 lp
- B007230401 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1551 & 1552 Pressure Transmitters W/Elther A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ENDELKEN.R H Region 5. San Francisco, Office of the Director 80/06/27 ip
- 8007180329 Responds to NRC 800609 ltr re violations noted in IE insp on 800520-22 Corrective actions util has established hold point to visually inspect all accessible interior/exterior ASME Secton 111 spoot welds. RENBERGER,D L Hashington Public Power Supply System 80/07/11 4pp
- DOCKET 50-513 WPPSS NUCLEAR PROJECT: UNIT 4
- A Application/construction stage documents & correspondence
- 8007030197 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.R L. Assistant Director for Licensing 80/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0440 & found in NUREG-0474 ElseNHUT.D @ Division of Licensing 80/04/24 2pp
- 8007210392 Ack receipt of NRC 800430 ltr approving request to discontinue certain aquatic monitoring & requesting copies of util submittals to State of WA re water quality NRC does not have authority to require water quality filings RENNERGER, D.L. Washington Public Power Supply Bystem 80/07/14
- B007250544 Forwards "Reliability Evaluation of HPPSS Nuclear Projects Numbers 1 & 4." in response to NRC B00124 request for evaluation of loss of main feedwater event RENBERGER, D L Washington Public Power Supply System B0/07/22 200
- ---BOO7250592 "Reliability Evaluation of MPPSS Nuclear Projects Numbers 1 & 4." Vol 1, main rept MCBRIDE, A F , MINARICK, J W , BOZARTH, D F Science Applications, Inc 80/07/16 214pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D @ Division of Licensing B0/06/25 B9pp

@ Inspection reports. IE Bulletins & correspondence

- 8007290444 Responds to IE Bulletin 80~03, "Loss of Charcoal from Std Type II.Two-Inch,Tray Adsorber Cells " Standardized 31 5 X 23 inch.flat bed.Type II charcoal adsorber cell units used in all cleanup sys RENBERGER,D L Washington Public Power Supply System 80/03/19 2pp
- 8007220252 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs " No written response required ENOELKEN, R H Region 5, San Francisco. Office of the Director 80/06/10 1p
- 800/300299 Forwards response to IE Bulletin 80-05 re vacuum damage to chemical control sys tamks Design changes to low pressure process tanks not required Table describing subj tanks & protection provided enci
 RENBERGER.D 1. Washington Public Power Supply System 80/06/12
 10pp
- 8007270070 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance M/IOCFRSD 55(e) " No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/06/13 1p
- 8007020466 Forwards JE Circular 80-i5, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELMEN, R H Region 5, San Francisco, Office of the Director 80/06/20 ip
- 8007180299 Forwards 1E Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required. EMPELKENSE H. Region 5, San Francisco, Office of the Director 80/06/24 1p
- B007230401 Forwards IE Bulletin B0-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular B0-16 also entl No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/27 ip
- 80072705iB Responds to IE Bulletin BO-08 Problems re containment iiner pentration weld do not exist at facility Design for primary piping typical of ASME code configurations Process pipe/fived head assemblies not installed RENHERGER.D L. Washington Public Power Supply System 80/07/10
- S Reportable occurrences, LERs & related correspondence
- BOO7170577 Forwards interim deficiency rept re defective condition in design of Floor supporting component cooling & makeup pump aree heating ventilation & air conditioning sys Train B equipment
 BENBERGER, D. L. Washington Public Power Supply Gystem BO/07/11
- --B0071703B3 Interim deficienty rept re defective condition in floor supporting component cooling & makeup pump area Gaused by usage of incorrect vertical amplified response spectre. Structural frame designed for installation * Washington Public Power Supply System 80/07/11. 2pp
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8007020265 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TRDESCO, R L Assistant Director for Licensing 80/06/13, 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0460 & found in NUREG-0594 EISENHUT, D G Division of Licensing BO/06/26 2pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- BOO7070028 FOIA request from Atty General, State of IL for documents re NRC decision to issue suppl to final EIB for facility HANSELL, D Illinois, State of 80/05/28 2pp

- 8007070026 Responds to Atty General, State of IL request for documents re NRC decision to issue suppl to final EIS for facilities. Forwards documents listed in App A FELTON, J. H. Division of Rules and Records 80/06/19 2pp
- ---8007070031 Discusses alternate site reviews on pending cases reessessment of effort & impacts involved in upgrading
 alternative site analysis section of FEB Provides detailed
 description of active cases
 REGAN.W H Assistant Director for Environmental Projects
 78/04/08 4pp
- --B007070033 Discusses facilities alternative site reviews.Requests review of alternative site issues including comments as to deficiencies in light of Board decisions BALLARD,R L. Environmental Projects Branch 1. 78/07/19. ig.
- ---B007070034 Discusses facilities' alternative site analysis.
 FEB is insufficient Lists deficiencies under Filgrim &
 Saabrook Applicant has not made explicit environ comparison
 of alternative sites investigeted
 LAWRENCE
- ---B007070040 Discusses fecilities' alternete site reanalysis.Ligts deficiencies in FEG needing correction.Forwards appropriate methodology for conducting witernetive site analysis in light of recent adjudicatory decisions.

 LAWRENCE, J.F. Hearing Branch 4. 78/08/01 2pp
- --B007070044 Discusses review of alternative site record in light of Board decisions Recommends need to supplement precent record, indicating further syplication of processes used the bases for view of relative destrability of available sites LAHRENCE, J.F. Hearing Branch 4 78/08/02 2pp.
- ---B007070044 Motion for leave to supplement record re alternative sites, based on guidance found in Pilgrim decision BORDENICK, B.M., LAHRENCE, J.F. Hearing Branch 4, 78/08/02 2pp.
- --8007070049 Forwards schedule for alternative site review for facilities. Verbal assessment of deficiencies have been provided Ltr of authorization is being drafted WATKING.D Building & Operations Branch 78/08/11 2pp.
- --8007070050 Order approving 780802 motion for leave to supplement record es to alternative sites for facilities, YORE, J. R. Atomic Sefety and Licensing Board Panel 78/08/17 Rpp
- --B007070053 Forwards tentative schedule for conduct of addl alternative site essessment & NRC technical & legal questions as result of preliminary review of FEB:CP & environ rept on alternative sites Provides authorization to pruceed w/work. MODRE, V A Assistent Director for Environmental Projects 78/09/25, 5pp
- --8007070055 Responds to 780928 request Forwards info re cases consisting of or having potential of addl alternative site studies.

 NORELY A Assistant Director for Environmental Projects 78/09/28 4pp
- F Becurity, medical, emergency & fire protection plans
- 8007270825 Forwards "Evacuation Time Estimates For Qilliam & Morrow Counties. OR & Klickitet County, WA in response to 800702 request. Advises that NRC responded to 791226 request on 800404 Study found no unusual evacuation problem. LINDBLAD, W J Pacific Gas & Electric Co. 80/07/25 1p.
- --8007270832 Forwards "Evacuation Time Estimates for Gilliam & Morrow Gounties.OR & Klickttat County.WA per 791226 request. Preliminary study revealed no unusuel evacuation problems. LINDBLAD.W J Pacific Oas & Electric Co 80/04/04 lp.
- --8007290835 "Evacuation Time Estimates For Gilliam & Morrow Counties, OK & Klickitat County, MA"

 * Parific Gas & Electric Co 80/03/31, 21pp.
- @ Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables.
 E18ENHUT, D 0 Division of Licensing, 80/06/25 89pp.

- 8007170201 Motion for postponement of B00723 pretrial conference re early site suitability hearing issues Suggests conference call to hear applicant objections State of OR & LK Marbet have no objection to postponement Certificate of Svc encl BDRDENICK.B M Hearing Branch 4 80/07/15 6pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007220239 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENGELKEN R H Region 5. San Francisco, Office of the Director 80/06/10 ip
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020265 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCOLR L. Assistant Director for Licensing 80/06/13 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications.as derived from NUREG-0660 & found in NUREG-0674
 EIBENHUT, D Q Division of Licensing 80/06/26 2pp
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- B007070028 FDIA request from Atty General, State of IL for documents to NRC decision to issue suppl to Final EIS for facility.

 HANSELL,D Illinois, State of 80/05/28. 2pp.
- BOO7070026 Responds to Atty General State of IL request for documents re NRC decision to issue suppl to final EIS for facilities Forwards documents listed in App A FELTON, J M Division of Rules and Records BO/06/19 2pp
- --B007070031 Discusses alternate site reviews on pending cases re assessment of effort & impacts involved in upgrading alternative site analysis section of FEB Provides detailed description of active cases REGAN.H H. Assistant Director for Environmental Projects 78/06/08 App
- ---B007070033 Discusses facilities alternative site reviews Requests review of alternative site issues including comments as to deficiencies in light of Board decisions.

 BALLARDIR L Environmental Projects Branch 1 78/07/18 lg.
- --8007070036 Discusses facilities' alternative site analysis FEB is insufficient.Lists deficiencies under Pilgrim & Seabrook Applicant has not made explicit environ comparison of alternative sites investigated LANKENCE; J F Hearing Branch 4 78/07/24 2pp
- --8007070040 Discusses facilities' alternate site reanalysis Lists deficiencies in FEB needing correction. Forwards appropriate methodology for conducting alternative site enalysis in light of recent adjudicatory decisions LAMRENCE, J.F. Hearing Branch 4 78/08/01 2pp
- --BOO7070044 Discusses review of alternative site record in light of Board decisions Recommends need to supplement present record, indicating further explication of processes used & bases for view of relative desirability of available sites LAHRENCE, J.F. Hearing Branch 4 78/08/02 2pp
- --BOO7070046 Motion for leave to supplement record re alternative sites, based on guidance found in Pilgrim decision
 BORDENICK, B M. LAMMENCE, J F Hearing Branch 4 78/08/02 2pp
- --8007070049 Forwards schedule for alternative site review for facilities Verbal assessment of deficiencies have been provided Ltr of authorization is being drafted HATKINB, D. Building & Operations Branch 78/08/11 2pp
- --B007070050 Order approving 780802 motion for leave to supplement record as to alternative sites for facilities
 YORE, J.R. Atomic Safety and Licensing Board Panel 78/08/17
 20a
- --BOO7070053 Forwards tentative schedule for conduct of add1 alternative site assessment & NRC technical & legal questions as result of preliminary review of PES, CP & environ rept on alternative sites Provides authorization to proceed w/work MORE, V A Assistant Director for Environmental Projects 78/09/25. Spp

- ----B007070055 Responds to 78092B request Forwards info re cases consisting of or having potential of addl alternative site studies MODRE, V A Assistant Director for Environmental Projects 78/09/2B 49p
- F Security, medical, emergency & fire protection plans
- 9007290B25 Forwards "Evacuation Time Estimates For Gilliam & Morrow Counties.OR & Klick that County.WA in response to 800702 request Advises that NRC responded to 791226 request on 800404 Study found no unusual evacuation problem LINDBLAD.W J Pacific Gas & Electric Co 80/07/25 1p
- --8007290832 Forwards "Evacuation Time Estimates for Gilliam & Morrow Countres. DR & Mischitat County. WA per 791224 request Preliminary study revealed no unusual evacuation problems LINSBLAD. W. Pacific Gas & Electric Co 80/04/04 1p
- --8007290835 "Evacuation Time Estimates For Gilliam & Morrow Counties.OR & Klickitat County, NA"

 * Pacific Gas & Electric Co 80/03/31 21pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/06/25 87pp
- 8007170201 Motion for postponement of 800723 pretrial conference re early site suitability hearing issues Suggests conference call to hear applicant objections State of OR & LK Marbet have no objection to postponement Certificate of Svc encl BORDENICK. B M Hearing Branch 4 80/07/15 6pp
- G Inspection reports. IE Bulletins & correspondence
- BOO7220239 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs "No written response required ENGELKEN.R H Region 5. San Francisco, Diffice of the Director 80/06/10 ip
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 E19ENHUT.D 0 Division of Licensing 80/06/26 2pp
- H General correspondence
- 8007180042 Responds to 800123 ltr re NRC approach to emergency planning around nuclear plants Commission endorsed NUREG-0376 for development of state t local radiological plans Exact configuration of zones will be decided during plant review DENTON, HR Office of Nuclear Reactor Regulation, Director 80/04/03 2pp
- --B007:B0047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed 10-mile radius is unworkable for people of Long Island Responsible plan should be developed BEHAN, J L New York, State of 60/01/23 ip
- Q Inspection reports, 1E Bulletins & correspondence
- 8007010280 Forwards IE Info Natice 80-23, "Loss of Suction to Emergency , Feedwater Pumps" No written response required ORIER.B H Region i. Philadelphia. Office of the Director 80/05/29 ip
- 8007010066 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Engineering activities have been curtailed to point where detail design data requested as unavailable PLABKON, R E Long Island Lighting Co 80/06/05 ip
- 8007210571 Forwards IS Info Notice 80-26, "Evaluation of Contractor OA Programs "No written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/06/10 lp

- 800716040: Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant fump Stude " No specific action or response requires CRIER.B H Region i, Philadelphia, Office of the Director 80/06/11 ip 80/06/11
- 8007280594 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/IOCFR50 55(e) " No written response required ORIER, 8 H Region i. Philadelphia. Office of the Director 80/06/13 ip
- 8007020509 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required
 GRIER, D.H. Region 1. Philadelphia, Office of the Director
 80/06/20 ip
- B007i60704 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B. H. Region I. Philadelphia, Office of the Director
- 8007210199 Forwards JE Info Notice 80-24. "Low Levei Radwaste Burial Criteria " No written response required GRIER.8 H Region 1. Phyladelphia. Office of the Director. 80/06/23 1p
- 8007230128 Forwards IE Bulletin HO-ić, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IC Circular 80-16 also encl No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/06/27 2pp
- 8007210515 Responds to IE Bulletin 80-08 re containment liner penetration weld examinations Penetrations will be fabricated per Reg Guide i 19 Butt welds will be radiographed PLASKUN-R E Long Island Lighting Co 80/07/01 2pp
- DOCKET STN-50-517 JAMESPORF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0694 ETSENHUT, D G Division of Licensing 80/06/26 2pp
- H General correspondence
- 8007180042 Responds to 800123 ltr re NRC approach to emergency planning around nuclear plants Commission endorsed MUREO-0376 for development of state & local radiological plans Exact configuration of zones will be decided during plant review DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/03 2pp
- --BO071B0047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed IO-mile radius is unworkable for people of Long Island Responsible plan should be developed BEHAN, J.L. New York, State of BO/01/23 lp
- G Inspection reports, IE Bulletins & correspondence
- 8007010280 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/05/29 1p
- G007010066 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 Engineering activities have been curtailed to joint where detail design data requested is unavailable PLASKON.R E Long Island Lighting Co 80/06/05 ip
- 8007210571 Forwards TE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required GRIER.D H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- 8007160401 Forwards IE Info Notice 80-27, "Degradation of Reactor Conlant Pump Stude " No specific action or response required
 GRIER, B H Region i, Philadelphia, Dffice of the Director
 80/06/11 ip

- 8007280594 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance M/10CFR50 35(e)" No written response required GRIER. II H Region 1. Philadelphia. Office of the Director 80/06/13 1p
- 8007020509 Forwards IE Carcular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/06/20 ip
- 6007160704 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel "No written response required GRIER, II H Region I, Philadelphia, Office of the Director 80/06/24 ip
- 8007210199 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER, B # Region 1, Philadolphia, Office of the Director. 80708/23 1p
- 8007230128 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007210515 Responds to IE Bulletin 80-08 re containment liner penetration weld examinations Penetrations will be fabricated per Reg Oulde 1 19 Butt welds will be radiographed PLASKON,R E Long Island Lighting Co 80/07/01 2pp
- DUCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage decuments & correspondence
- 8007020232 Forwards NRC OFC of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to angoing activities
 TEDESCOR L Assistant Director for Licensing 80/06/13 2pp
- 8007010338 Forwards "Socioeconomic Monitoring & Mitigation Rept." Continuing info will be provided on semiannual basis MILLS.L M Tennéssee Valley Authority 80/06/29 lp.
- --8007010350 "Socipeconomic Monitoring & Mitigation Rept," data as of Tennessee Valley Authority 80/05/31 52pp.
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694 Division of Licensing 80/06/26 200
- O Adjudicatory correspondence

EIRENHUT. D G

- 8007310243 Forwards Commission 800527 memorandum & order containing DV/310243 regulares commission Educa/ memoranoum a grear cont decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENNUT.D 9 Division of Licensing 80/06/25 87pp
- H Ceneral correspondence
- 8007i10570 Responds to encl 800506 ltr addressed to President Carter 14 safety measures being taken to protect citizens of IN Facility is subj to stringent const controls Radiation exposure will be kept to as low as reasonably achievable TEDESCO,R L Assistant Director for Licensing 80/06/26 2pp
- Q. Inspection reports. JE Dulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removel Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- 8007140479 Forwards 1E Bulletin 80-13, "Gracking in Core Spray Spargers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/12

- 8007010225 Forwards IE Info Notice 80-29, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/29 is.
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'RETELLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 3bo
- 8007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/12 1p.
- 8007280384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)," No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/13 dag.
- 8007020499 Forwards response to IE Bulletin 80-09 transmitted by JP Q'Reilly 800417 1tm Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 HILLS.L M Tennessee Valley Authority 80/06/16 2pp
- 8007300589 Forwards IE Insp Repts 50-518/80-10.50-519/80-10. 50-520/80-10 & 50-521/80-10 on B00428-0530 No noncompliance noted MXRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/06/17 2pp
- ---BO07300594 IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted Major areas inspected earth compaction structural concrete & previous insp findings GANTRELL.F.8 Region 2. Atlanta. Reactor Construction & Engineering Support Branch SUANN B Region 2. Atlanta, Office of the Director 80/06/17 6pp
- 8007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- BOO7170070 Forwards IE Cir-ular 80-14, "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnol " No written response required O'REILLY: J P. Region 2. Atlanta. Office of the Director BO/06/24 in.
- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Reseasount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or b Dutput Codes " Written response required IE Circular 80-16 also enci No written response required D'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/06/27 in.
- BOO7R20236 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Hodel EA180 Limit Switches at Elevated Temps "
 Investigations show no NAMCO EA180 switches are installed or planned for installation.
 MILLB.L M Tennessee Valley Authority BO/07/Oi ip
- 8007280616 Responds to IE Bulletin 80-98. "Examination of Containment Penetration Welds "Results of investigation encl MILLB.L M Tennessee Valley Authority 80/07/97 5pp
- 8007240265 Ack receipt of B00624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/B0-08, 50-519/B0-08, 50-519/B0-08, 50-521/B0-0B MNRPHY,C.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/08 lp
- ~~8007240279 Responds to NRC 800530 ltr re violations noted in 1E Insp Repts 50-818/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment unsite & ready for installation on next vessel MILLS.L M Tennessee Valley Authority 80/06/24 4pp
- --8007240273 Forwards 1E Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 50-521/80-08 on 800331-0425 & notice of Violation HURPHY,C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --B007240305 Notice of violation from insp on 800331-0425
 * Region 2, Atlanta, Office of the Director 80/05/30 is

- ~~8007240329 IE insp Repts 50-518/80-06.50-519/80-08,50-520/80-08 & 50-521/80-08 on 800331-0425 Noncompliance noted reactor pressure vessel scored in dusty area CONTRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch SWAN.W B Region 2. Atlanta, Office of the Director 80/05/30 App
- S Reportable occurrences. LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities Detailed info will be provided to assist determination of significant safety hexard OIROUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17 3bo
- 8006250275 Forwards final deficiency rept re incorrect root face on skewed cadweld sleeves
 MILLS.L.M Tennessee Valley Authority 80/06/19 1p
- 8007170247 Part 21 rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is provided to absist in determination of significance as safety hazard OIROUX.E.J. Carrior Corp. Carrier Air Conditioning Div. 80/06/20
- B007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917 MILLS.1. M Tennessee Valley Authority 80/07/02 ip
- --8007110328 First interim deficiency rept on Resembunt Model 1152 pressure transmitter defects During testing. GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/0≥ ip
- 8007140349 Forwards second interim deficiency rept re cracks in reactor pressure vessel shield wall Final rept to be submitted before 801003 Will provide addl info re repair of shield wall & corrective actions MILLS, L M Tennessee Valley Authority 800/07/03 ip
- --8007140353 Second interim deficiency rept re cracks in reactor gressure vessel shield wall Discovered base metal cracks in shield wall inner shell plates Evaluation revealed crack initiated at toe of tack well bead of backing strip
 * Tennessee Valley Authority 80/07/03 2pp
- 8007230528 Final deficiency rept re omitted heaters from Reliance Electric Co motor operator Deficient motor will be replaced by B01130 GE will review yendor QA program to assure proper implementation MILLS, L M Tennessee Valley Authority 80/07/18 2pp
- B007290734 Final Deficiency Rept 4 re deficient welds found on anchor bolt chair & containment shell & base plate Caused by QA/QC imapectors not allowing welds to pass inso Task force & retraining & recertification program initiated # Tennessee Valley Authority B0/07/24 3pp
- DOCKET STN-50-519 HARTSVILLE NUCLEAR FLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B007020252 Forwards NRC Ofc of Nuclear Heactor Regulation B00428 reorganization chort Necessary period of transition made w/min disruption to ongoing activities
 TEDEBCO.R L. Assistant Director For Licensing B0/06/13 2pp
- B007010338 Forwards "Socioeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS.L M Tennessee Valley Authority 80/06/25 ip
- --8007010350 "Secioeconumic Monitoring & Mitigation Rept." data as of 790930

 * Tennessee Valley Authority 60/05/31 52pg
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D 0 Division of Licensing BO/06/26 2pp

O Adjudicatory_correspondence

BOD7310243 Forwards Commission BOO527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT,D G Division of Licensing BO/04/25 69pp

H General correspondence

- B007i10970 Responds to encl 800306 ltr addressed to President Carter re safety measures bring taken to protoct citizens of TN Facility is subj to stringent const controls Radiation exposure uill be kept to as low as reasonably achievable TEDESCO.R L Assistant Director for Licensing 80/06/26 2pp
- O Inspection reports. 1E Bulletins & correspondence
- BOD7240009 Forwards IE info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/05/08
- B007140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Bpargers" No written response required D'REILLY, J P Region 2. Atlanta. Dffice of the Director 80/05/12 io
- 8007010225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/29 is
- 8007220027 Forwards IE Info Notice 80-26, "Evaluation of Contractor A Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 3pp
- B007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/12 Ip
- B007250384 Forwards IE Info Notice B0~28, "Prompt Reporting of Info in Accordance W/100FR50 55(e)" No written response required O'REILLY.J P Region 2. Atlanta, Defice of the Director 80/06/13
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP D'Reilly B00417 ltr Final rept for Hartsville & Phipps Bend glants will be sent on or before B01017 HILLS:L M Tennessee Valley Authority B0/06/16 2pp
- B007300589 Forwards IE Insp Repts 50-518/80-10,50-819/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --8007300594 1E Insp Repts 50-518/80-10,50-519/80-10,50-520/80-10 & 50-521/80-10 on 800428-0530 Ne nencompliance noted Major areas inspected earth compaction, structural concrete & previous insp findings
 CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Dranch SWAN, W B Region 2, Atlanta, Office of the Director 80/06/17 6pp
- of the Director 80/04/1/ 6pp

 B00702039i Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump
 Gooling & Natural Circulation Cooldgen " No written resonse
- 8007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/20, lp
- B007170070 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnal "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/06/24.
- 8007230250 Forwards IE Bulletin BO-16. "Potential Misapplication of Rosemount Int Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J F Region 2, Atlanto, Office of the Director 80/06/27.

- B007220236 Responds to IE Bulletin 79-28, "Possible Halfunction of NANCO Model EAIBO Limit Buitches at Elevated Temps "
 Investigations show no NAMCO EAIBO switches are installed or, planned for installation
 MILLS:L M Tennessee Vailey Authority B0/07/01 ip
- 8007280613 Responds to IE Bulletin 80-08, "Examination of Containment Penetration Wolds " Results of investigation encl MILLS.L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-518/80-08, 50-519/80-08, 50-521/80-08 & 50-521/80-08 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --B007240279 Responds to NRC 800330 ltr re violations noted in IE Insp Repts 50-518/80-08,50-519/80-08,50-320/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment onsite & ready for installation on next vessel MILLB.L M Tennessee Valley Authority 80/06/24 App
- --8007240293 Forwards IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 50-521/80-08 on 600331-0425 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007240305 Notice of violation from insp on 800331-0425 * Region 2. Atlanta, Office of the Director 80/05/30 1p
- --B007240329 IE Insp Repts 50-518/80-0B, 50-519/80-0B, 50-520/80-0B & 50-521/B0-0B on 800331-0425 Noncompliance noted reactor pressure vessel stored in dusty area CONTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SMAN.H B Region 2, Atlanta, Office of the Director 80/05/30 6pp
- S Reportable occurrences, LCRs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities Dotailed info will be provided to assist determination of significant safety hazard OIROUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17 3pp
- 8007170247 Part 21 rept of potentially defective Rosemount.Inc transmitter in control sys of air conditioning units.Info is provided to assist in determination of significance as safety hazard 9IROUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/20
- B007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before B00917 MILLS.L H Tennessee Valley Authority 80/07/02 ip
- --8007110328 First interim deficiency rept on Rosemount Hodel 1:52 pressure transmitter defects During testing, GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/02 1p
- 8007290734 Final Deficiency Rept 4 re deficient welds found on anchor bolt chair & containment shell & base plate Caused by GA/GC inspectors not allowing welds to pass insp Task force & retraining & receptification program initiated # Tennessee Valley Authority 80/07/24 3pp
- DOCKET STN-50-920 HARTBVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8007020252 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO:R L Assistant Director for Licensing 80/06/13 2pp
- 8007010338 Forwards "Socioeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS.L M. Tennessee Valley Authority 80/06/25 ip
- --8007010350 "Socioeconomic Monitoring & Mitigation Rept." data as of
 - * Tennessee Valley Authority 80/05/31, 52pp

BOO7230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
EISEMBUT, D O Division of Licensing 80/06/26 2pp

DISCLARATION OF DISCRETE CO. GOVED

@ Asjudicatory correspondence

B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENMUT, D 0 Division of Licensing 80/06/25 89pp

H General correspondence

BOO7110570 Responds to enci 800506 itr addressed to President Carter re safety measures being taken to protect citizens of TN Facility is subj to stringent const controls Radiation exposure will be kept to as low as reasonably achievable TEDESCO.R L Assistant Director for Licensing 80/06/26 2pp

Q Inspection reports, IE Bullstins & correspondence

- BOO7240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- BOO7140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Beargers" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12 is
- G007010225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Fordwater Pumps" No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director B0/05/29 ip.
- 8007220027 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director. 80/06/10 Tan.
- 900714030; Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/12 is.
- 8007250384 Forwards IE Info Notice 80-28. "Frompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/13
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP O'fkeilly 800417 itr Final rept for Hartsville & Phipps Hend plants will be sent on or before 801017 MILLS-L M Tennessee Valley Authority 80/06/16 2pp
- 8007300589 Forwards IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted.

 MCRPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch \$00/06/17 2pp
- --B007300394 1E Insp Repts 50-518/B0-10, 50-519/B0-10, 50-520/B0-10 & 50-521/B0-10 on 800428-0530 No noncompliance noted Major areas inspected earth compaction, structural concrete & previous insp findings
 CANTRELL.F B Region 2, Atlanta, Reactor Construction & Engineering Support Branch SMAN, W B Region 2, Atlanta, Office of the Director 80/06/17 6pp
- BOO7020391 Forwards IE Circular 80-i5, 4"Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response regulated O'REILLY, J.P. Region R. Atlanta, Office of the Director BO/06/20 in.
- BO07170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required OfREILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 ip.

- 8007230253 Forwards IC Bulletin 80-16, "Potential Misapplication of Rosemount Inr Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27 in
- 8007220236 Responds to JE Bulletin 79-26. "Possible Maifunction of NAMCO Model EAIBO Limit Switches at Elevated Temps " Investigations show no NAMCO EAIBO switches are installed or planned for installetion MILLS, L M Tennessee Valley Authority 80/07/01 lp
- 8007280615 Responds to 1E Bulletin 80-08, "Examination of Containment Panetration Welds " Rusuits of investigation encl MILLS.L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-918/60-08, 50-519/80-08, 50-521/80-08 \$ 50-521/80-08 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/07/08 1p
- --B007240279 Responds to NRC B00530 ltr re violations noted in IE Insp Repts 50-518/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment ansite & ready for installation on next vossel MILLS.L M Tonnessee Valley Authority B0/06/24 App
- --B007240293 Forwards IE Insp Repts 50-519/80-08,50-519/80-08 & 50-521/80-09 on 800331-0425 & notice of violation MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007240305 Notice of violation from insp on 800331-0425 * Region 2. Atlanta. Office of the Director 80/05/30 ip
- --8007240329 It Insp Repts 50-519/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 on 800331-0425 Noncompliance nated reactor pressure vossel stored in dusty area CONTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SHAN.H B Region 2. Atlanta, Office of the Director 80/05/30 App
- 8 Reportable occurrences, LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities Detailed anfo will be provided to assist determination of significant safety hazard OIRDUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/17 3pp.
- 8007170247 Part 21 rept of potentially defective Resembnt. Inc transmitter in control sys of air conditioning units Info is provided to assist in determination of significance as safety hazard QIROUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/20 29pp
- 8007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917 MILLS,L M Tennessee Valley Authority 80/07/02 ip
- ~-B007i1032B First interim deficiency rept on Rosemount Model 1152 pressure transmitter defects During testing GE found ambiguous output to over & underpressure conditions Review to determine number of transmittens on location underway * Tennessee Valley Authority 80/07/02 ip
- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8007020252 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCORL Assistant Director for Licensing 80/06/13 2pp
- 8007010338 Forwards "Secioeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS, L. M. Tennessee Valley Authority 80/06/25 ip
- --8007010350 "Socioeconomic Monitoring & Nitigation Rept." data as of 790930
 - * Tennessee Valley Authoraty 80/05/31 52pp

B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D O Division of Licensing 80/06/26 2pp

Q Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp

H General correspondence

B007110570 Responds to encl B00506 itr addressed to President Carter re safety measures being taken to protect citizens of TN Facility is subj to stringent const controls fladiation exposure will be kept to as low as reasonably achievable YEDESCO.R L Assistant Director for Licensing B0/06/26 2pp

@ Inspection reports, IE Bulletins & correspondence

- B0072400B9 Forwards IE Info Notice B0-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode"
 No response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
 300
- 8007140479 Forwards IE Butletin 80-13, "Crocking in Core Spray Spargers " No written rosponse required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12 ig
- 8007010225 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/29 to
- B007220029 Forwards 1E Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/1 Jon
- 6007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Gapability " No written response required D'REXLLY, J.P. Region 2, Atlanta, Office of the Director to
- 8007250384 Forwards IC Info Notice 80~28, "Prompt Reporting of Info in Accordance W/IOCFR50 55(e)" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/13 3pp
- 8007020499 Forwards response to 1E Bulistin 80-09 transmitted by JP O'Reilly 800417 1tr Final rept for Hartsville & Phipps Bend pinets will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp
- 80073005B9 Forwards IE Insp Repts 50-51B/80-10,50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted MVRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --B007300594 IE Insp Repts 50-518/80-10,50-519/80-10,50-520/80-10 & 50-521/80-10 on 800428-0330 No noncompliance noted Major areas inspected earth compaction, structural concrete & previous insp findings GANTRELL, F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/17 App
- B00702039: Forwards IE Circular 80-18, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director B0/06/20
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Demineralized Mater Sys & Resultant Internal Contemination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 50/06/24 Ip

- B007230253 Forwards IE Bulletin B0-16. "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular B0-16 also enci No written response required G'REILLY, J P Region 2. Atlanta, Office of the Director B0/06/27
- 8007220234 Responds to IE Bulletim 79-28, "Passible Halfunction of NAMCO Hodel EA180 Limit Switches at Elevated Temps" Investigations show no NAMCO EA180 switches are installed or planned for installation MILLS.L M Tennessee Valley Authority 80/07/01 ip
- B007280615 Responds to IE Bulletin 80-08, "Examination of Containment Penatration Welds " Results of investigation encl HILLS-L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing MRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-80 & 50-521/80-08 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/08 ip
- ~-8007240279 Responds to NRC 800530 ltr re violations noted in IE Insp Repts 50-518/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment onsite & ready for installation on next vessel MILLS,L M Tennessee Valley Authority 80/06/24 App
- --8007240273 Forwards IE Insp Repts 50-518/80-08, 50-517/80-08, 50-520/80-08 & 50-521/80-08 on 800331-0425 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007240305 Notice of violation from insp on 800331-0425, * Region 2, Atlanta, Office of the Director 80/05/30. 1p
- --B007240329 IE Insp Repts 50-518/B0-08, 50-519/B0-08, 50-520/80-08 & 50-521/B0-08 on B00331-0425 Noncompliance noted reactor pressure vessel stored in dusty area CANTRELL, F & Region 2, Atlanta, Reactor Construction & Engineering Support Branch G0/05/30 App
- S Reportable occurrences. LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities Detailed info will be provided to assist determination of significant safety hozard OIRDUX, E.J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17 3pp
- G007170247 Part 2: rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is provided to assist in determination of significance as safety hazard OIROUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/20. 27pp
- 8007i10320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603. Final rept will be submitted on or before 800917 HILLS.L. M Tannessee Valley Authority 80/07/02 ip
- ---B007110328 First interim deficiency rept on Rosemount Model 1152 pressure transmitter defects During testing, GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway # Tennessee Valley Authority B0/07/02 ip
- DOCKET BIN-50-522 SKAQIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- E007030305 Comments on proposed rules 10CFR30 & 51 w/Swinomish Tribal Community endorses position for Full consideration of Class 9 accidents Urges consideration of Class 9 accident in Skagit proceedings W/Certificate of Svc OENDLER.H W Skagitonians Concerned About Nuclear Power MEANS, D, 8 Affiliation Unknown 80/06/17 App
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0699
 EISENMUT.D Q Division of Licensing BO/06/26 2pp

- \$007150737 Informs NRC that four private utils have formed wholly-owned engineering & const company to perform engineering licensing & const eves for major generating projects Company will be activated on 800715 Press release encl
 FERCUSON, W. J. Affiliation Unknown 80/07/08 4pp
- Q. Adjudicatory correspondence
- 9007010257 Forwards ABLB 800306 memorandum summarizing hearing status & FT Thomson 800414 1tr to ASLB indicating site change possibility W/o encl BHXX8DN.D T Hearing Branch 1 80/04/16 ip
- BOO7310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISCHAUT.D O Division of Licensing B0/06/25 89pp
- BOO7100171 Bubmits third status rept concerning progress made in remolving USGS/NRC BOO306 requests for add1 info re geology/ seismology of plant site Requests for add1 info remain unchanged due to incomplete rept THOMSEN, F T. Perkins, Coie, Stone, Olsen & Williams BO/06/2:
- B007010330 Advises of no development re NRC or USOS review of application. NRC is unable to predict date for rescheduling hearings BLACK, R. L. Hearing Branch 1 80/06/30. 1p
- 8007300372 Forwards notice of withdrawal of counsel RM Sandvik & appearance of FW Ostrander as counsel for State of GR SAMOVIK.R.M Oregon, State of 80/07/03 ip.
- --B007300377 Notice of withdrawal of counsel RM Sandvik & appearance of FN Ostrander as counsel for State of OR Certificate of Evc enci.
 OSTRANDER, F W Oregon, State of 80/07/03 Spp
- 8007110042 Schedule setting 800731 for applicants & NRC to submit repts in response to ASLB 800306 order, Paragraph 14 C Applicants must indicate intention to change site & NRC must explain status of response to applicants' 800215 submittal DEALE, V. B. Atomic Safety and Licensing Board Panel 80/07/08 ip
- 9007230797 Motion for order evidencing current status & setting schedule for further proceeding Amend to application will be filed by 900930 Anticipated schedule for environ rept & PBAR amends may be filed on same date W/draft order & release.
 THOMSEN.F.T. Portland General Electric Co THOMSEN.F.T Parkins. Gale. Stone. Claes & Williams 80/07/16 7pp.
- B007250351 Forwards 800216 certificate of svc inadvertently omitted from 800716 correspondence THOMSEN, F. T. Perkins, Cole, Stone, Olsen & Williams 80/07/17
- Q Inspection reports, IE Bulletins & correspondence
- 8007220244 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/10, 1p.
- 8007140418 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability," No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/66/12 ip.
- DOCKET BIN-50-529 SKAGIT NUCLEAR POWER PROJECT: UNIT 2
- A Application/construction stage documents & correspondence
- B007030305 Comments on proposed rules 10CFR50 & 51 w/Swinomish Tribal Community endorses position for full consideration of Class 9 accidents Unges consideration of Class 9 accident in Skapit proceedings. W/Certificate of Buc CENDLER, M. W Skapitonians Concerned About Nuclear Power. B0/06/17
- 9007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EISENAUT, DO Division of Licensing 80/06/26 2pp

- 8007i50737 Informs NRC that four private utils have formed wholly-owned engineering & const company to perform engineering. licensing & const sycs for major generating projects Company will be activated on 8007i5 Press release encl
 FERGUSON, W U Affiliation Unknown 80/07/08 4pp
- Q Adjudicatory correspondence
- 8007010257 Forwards ASLB 800306 memorandum summarizing hearing status & FT Thomsen 800414 ltr to ASLB indicating site change possibility M/o encl SWANSON.D T Hearing Branch 1 80/04/16 lp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables

 EISENHUT, D O Division of Licensing 80/06/25 89pp
- 8007100171 Submits third status rept concerning progress made in resolving USOS/NRC 800306 requests for addl info re geology/ seismology of plant site Requests for addl info remain unchanged due to incomplete rept
 THOMSEN.F T Pertins, Cole. Stong, Glsen & Williams 80/06/27
- 8007010330 Advises of no development re NRC or USGS review of application NRC is unable to predict date for rescheduling hearings BLACK, R t. Hearing Branch 1 80/06/30 ip
- 8007300372 Forwards notice of withdrawal of counsel RM Sandvik & appearance of FW Ostrander as counsel for State of CR SANDVIX.R M Gregon, State of 80/07/03 ip
- --8007300377 Notice of withdrawal of counsel RM Sandvik & appearance of FW Distrander as counsel for State of ER Certificate of Syc encl OSTRANDER, F W Oregon, State of 80/07/03 3pp
- 8007110042 Schedule setting 800731 for applicants & NRC to submit repts in response to ASLB 800306 order.Paragraph 14 C Applicants must indicate intention to change site & NRC must explain status of response to applicants' 800215 submittal DEALE.V.B Atomic Safety and Licensing Board Panel 80/07/08 is
- 8007230797 Motion for order evidencing current status & setting schedule for further proceeding Amend to application will be filed by 800930 Anticipated schedule for environ rept & PBAR amends may be filed on same date W/draft order & release THOMSEN.F T Portland Openeral Electric Co THOMSEN.F T Porting. Goie. Stone. Olsen & Williams 80/07/16 7pp
- 8007250351 Forwards 800216 certificate of svc inadvertently omitted from 800716 correspondence THOMSEN,F T Perkins, Coie, Stone, Olsen & Hilliams 80/07/17
- G Inspection reports, 18 Bulletins & correspondence
- B007220244 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs" No written response required ENGELMEN.R H Region 5, San Francisco. Office of the Director B0/06/10 ip
- 8007140418 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required EMGELMEN.R H Region 5, San Francisco, Office of the Director BO/06/12 ip
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION: UNIT 1 A Application/construction stage documents & correspondence
- 8007210237 Bummary of 800311 meeting w/utfl in Bethesda.MD re review plans for OL applications LICITRA.E.A Light Water Reactors Branch 3 80/04/25 4pp
- 8007010330 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mpt representatives Areas of disagreement may be discussed through informal appeal TEDESCO, R. L. Assistant Director for Licensing 80/06/13 2pp

- 8007020209 Ack receipt & docketing of 791001 joint application for DLs Forwards list of incomplete sections following preliminary review of FBAR & environ rept Discusses licensing procedures & importance of timely communication EISENHUT. D G Division of Licensing 80/06/16 7pp
- B00702019A Notification of B00709-10 meeting c/util in Bethesda, MD to dlscuss ac power sys KERRIGAN, J Licensing Branch 2 80/06/23 2pp
- BOD7230001 Forwards statement of policy re requirements to be mot for current OL applications, as derived from NUREO-0660 & found in NUREO-0679
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007080227 Requests authorization under CPPR-141, CPPR-142 & CPPR-143 to use ASME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds VAN BRUNTLE E Arizona Public Service Co 80/06/27 ip
- B007090285 Forwards Bechtel Power Corp & util responses to open items of Class IE dc power sys review Responses have been submitted to review board & final resolution will be submitted to NRC when completed VAN IRUNI.E E Arizona Public Service Co 80/06/30 lopp
- 8007110398 Forwards proofs of svc for applicant FSAR.OL application, general info & environ rept, required by MRC 800618 ltr VAN BRUNT, E E Arizona Public Service Co 80/07/01 8pp

O Adjudicatory correspondence

- 8007020680 Forwards 800519 ltr.FR notice & Director's decision under 10CFR2 206 denying Frlends of the Earth 791024 petition to require supplemental environ statements on Class 9 accidents at facilities
 DENTON.H R Office of Nuclear Heactor Regulation. Director 80/06/17 2pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- 8007170539 Forwards 800702 FR notice re opportunity for hearing on application for OLs SCHMENCER.A Operating Reactors Branch 3 80/07/02 3pp
- --B007170542 Notice of receipt of application for facility Obstrotice of availability of applicant environ reptinotice of consideration of issuance of facility Obs & notice of opportunity for hearing Newspaper notice encl
 SCHMENCER.A Licensing Branch 3 B0/07/02 10pp
- 8007110002 Order granting extension until 800722 for Commission to elect to review decision on enforcement action request. DD-80-22 HOYLE.J C Office of the Secretary of the Commission 80/07/08 in
- 8007300106 Notices of appearance in proceeding Certificate of Bvc encl GEHR.A C . BISCHOFF.C A Arizona Public Service Ca 80/07/23 3pp

H General correspondence

- S007110526 Responds to 800407 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR, Section ? 1 SCHWENCER, A Licensing Branch 2 80/06/26 App
- 8007210018 Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded SOUDER, J L Division of Rules and Records. 80/07/07 ip
- K Utility Final Bafety Analysis Report (FBAR) & amends
- BOO7280585 Notifies that FBAR & environ rept complete & no further action required Forwards revised & now pages to be incorporated in next FBAR amend & environ rept suppl VAN BRUNT.E E Arlzona Public Bervice Co BO/07/23 ip.
- --- 8007280590 "Addi Info for Amend 2 to FBAR," re geology, seismology & geotechnical engineering of structural design, & integrity of reactor coolant pressure boundary Preliminary version "

 * Arlzona Public Service Co 80/07/23 19pp

- ~-B007ZB0598 "Addl Info for Suppl 1 to Environ Rept," re need for power, geography & demography. & applicant preoperational environ programs Prellminary version

 * Arizona Public Service Co 80/07/23 29pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007280063 Suppls 800208 response to 1E Bulletin 79-28. "Possible Malfunction of NAMCO EA180 Limit Switches at Elevated Temps" Bub; switch is supplied on 1 5-inch pneumatic operated gate valve. Gaskets replaced prior to shipment VAN BRUNT, E E Arizona Public Service Co 80/03/11 ip
- 8007250357 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type II.2-inch Tray Adsorber Cells " Type II tray adsorber cells are not used at facility Filtration units used are rechargeable, permanent, single-unit adsorbers, VAN BRUNT, E E Arizona Public Service Co 80/03/18 lp
- BO07170265 Forwards IE Insp Repts 30-528/80-05,50-529/80-05 & 50-530/80-05 on 800303-14 No noncompliance noted SPENCER,0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/05/20 2pp.
- --B007170270 1E Insp Repts 50-528/80-05,50-529/80-05 & 50-530/80-05 en 800303-14 No noncompliance noted Major areas Inspected:Unit i control bldg cable tray,concrete records & Unit 3 containment basemat concrete placement VORDERBRUGGEN Region 5, San Francisco, Office of the Director DODDS:R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/20 App
- 8007010016 Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Feedwater Pumps" No written response required ENGELKEN.R H Region 5. San Francisco, Défice of the Director 80/05/29 ip
- 8007220235 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required ENGELMEN.R H Region 5, San Frencisco, Office of the Director 80/04/10 1p
- 8007300516 Responds to 1E Bulletin 80-05 re damage to chemical vol control sys tanks Thirty addl days needed to obtain info requested in Item 2 VAN BRUNT, E.E. Arizona Public Servica Co. 80/06/10 ip
- B007290000 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required ENGELKEN.R.H Region D, San Francisco, Office of the Director. B0/06/13 1p.
- 8007270523 Responds to IE Builetin 80-09 Two suppliers make use of hydramotor actuators. Thirty-day extension necessary to determine if actuators are used in safety-related sys & if corrective actions required.

 VAN BRUNT, E E Arizona Public Service Co 80/06/17 ip
- 8007020477 Forwards IE Circular 80-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown " No written response required. ENGELMEN.R H Region 5, San Francisco, Diffice of the Director, 80/06/20 10.
- 8007180286 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel, "No written response required ENGELKENR H Reglon 5, San Francisco, Office of the Director 80/06/24 10
- 8007230381 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl. No written response required. ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/27 ip
- 8007300530 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks No addl vacuum features needed for justification LRS holdup tanks cannot collapse due to vacuum VAN BRUNT, E E Arlzona Public Service Co
- 8007290516 Responds to IE Bulletin 80-09 re hydromotor actuator deficiencies Flald adjustment of present units necessary Springs used have stroke length precluding permanent set problem VAN BRUNT, E.E. Arizona Public Service Co. 80/07/03 2pp

- 8007210543 Act receipt of 800624 ltr informing of steps taken to correct item of noncompliance noted in IE Insp Repts 50-528/80-06.50-529/80-06 Corrective actions will be varifized during future insp BPENCER.Q 8 Region 5. Ben Francisco. Reactor Construction & Engineering Support Branch 80/07/08 ip
- ~-8007210546 Forwards response to item of noncompliance noted in IE Insp Rapts 50-528/80-06,50-529/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than omission to rept.as situation was potentially reportable deficiency VAN DRUNT,E E Arizona Public Service Co 80/06/24 3pp

- 8007310505 Forwards IE Insp Repts 50~528/80~09.50-529/80~09 & 50~530/80-09 on 800801-23.No noncompliance noted BPENCER.0 8 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/07/11. 2pp
- --B007310516 IE Insp Repts 80-528/80-09, 50-529/80-09 & 50-530/80-09 on B00501-23 No noncompliance noted Major areas inspected Unit i cadwelder qualification.containment bldg closure.pipe hangers & supports & electrical cable installation program VORDERBRUEGOEN Region 5, San Francisco, Office of the Director. DODDB, R T Region 5, San Francisco, Reactor Operations Nuclear Support Branch. B0/07/10 Spp
- B Reportable occurrences, LERs & related correspondence
- 8007020531 Forwards final deficiency rept re inadequate size of Figure 211 sway strut assemblies
 VAN BRUNT, E E Arizona Public Service Co 80/06/25 2pp
- B007020525 Forwards interim deficiency rept re undersized fillet welds for structural steel.

 VAN BRUNT.E.E Arizona Public Service Co 60/06/26 2pp
- --8007020527 Interim deficiency rept re undersized fillet welds for structural steel Caused by personnel error Welding procedures & qualification repts of five suppliers being reviewed & evaluated # Arizona Public Bervice Co 80/06/26 2pp
- 8007140207 Forwards final deficiency rept re NAMCO controls Beries EA 180 limit switches VAN BRUNT,E E Arizona Public Bervice Co 80/07/03 2pp
- --B007140217 Final deficiency rept re NAMCO controls Series EA 180 limit switches Top cover gasket matl emits resin vapor which forms deposit on internal components of switch Caused by improper curing of gasket matl Gaskets will be replaced # Arizona Public Service Co 80/07/03 ip
- 8007140339 Forwards interim deficiency rept re operability failure of vertical fire dampers VAN BRUNT, E E Arizona Public Service Co 80/07/03 2pp
- ---8007140341 Interim deficiency rept re operability failure of vertical fire dampers Caused by lack of design tolerance on sheet matal sides preventing full closure of damper door Tests & design changes are being implemented Final rept by 800915 & Arizona Public Service Co 80/07/03 1p
- BO07160652 Forwards final deficiency rept re closure of Comsip. Inc containment gas analysis pump valve VAN BRUNT, E E Arizona Public Service Co 80/07/09 2pp

- --8007160658 Final deficiency rept re Comsip.lnc containment gas analysis sys pump Protection for pump is inadequate in case of inadvertent closure of outlet valve w/pump running Units will be modified per Comsip.lnc instructions * Arizona Public Service Co 80/07/09 3pp
- B007170470 Forwards final deficiency rept re visual insp rather than insp by liquid penetrant of circumferential wold joints on ASME Section 11% Class 3 piping sys VAN BRUNTLE E Arizona Public Service Co B0/07/09 2pp
- --B007170493 Final deficiency rept re visual insp rather than insp by liquid penetrant of circumferential weld joints on ASME Section III.Class 3 piping sys Welds reinspected by liquid penetrant Three deficient welds discovered & repaired # Arizona Public Service Cn 80/07/09 2pp
- B007290722 Final deficiency rept re inadequate embedment of anchor bolts for seal tables Caused by umission of anchor bolt extension in design drawings Design change will be implemented to reflect proper anchoring in concrete VAN BRUNTLE E Arizona Public Servica Co 80/07/21 App
- 8007290773 Final deficiency rept re inadequately designed reinforcing step1 in walls of main steam support structure Caused by failure to use dynamic load factor of 2 0 in design Design change package will be implemented VAN DRUNT, E E Arizona Public Service Co 80/07/21 4pp
- DOCKET STN-30-529 PALO VERDE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8007210237 Bummary of 800311 meeting w/util in Bethesda, MD re review plans for OL applications
 LICITRA.E A Light Water Reactors Branch 3 80/04/25 4pp
- B007010550 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective B0042B Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007020209 Ack receipt & docketing of 791001 joint application for OLs Forwards list of incomplete sections following preliminary review of FSAR & environ rept Discusses licensing procedures & importance of timely communication EISENHUT.D G Division of Licensing 80/06/14 7pp
- 8007020194 Notification of 800709-10 meeting w/otil in Bethesda.MD to discuss ac power sys KERRIGAN.J Licensing Branch 2 80/06/23 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUT, D O Division of Licensing 80/06/26 2pp
- B007080227 Requests authorization under CPPR-141.CPPR-142 & CPPR-143 to use ASME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds VAN BRUNT, E E Arizona Public Service Co 80/06/27 1p
- B007090285 Forwards Eschtei Power Corp & util responses to open items of Class IE dr power sys review Responses have been submitted to review board & final resolution will be submitted to NRC when completed VAN BRUNT, E E Arizona Public Service Co 80/06/30 10pp
- 8007:10398 Forwards proofs of svc for applicant FBAR.OL application, general info & environ rept.required by NRC 800618 ltr VAN BRUNT.E E Arizona Public Service Co 80/07/01 8pp
- G Adjudicatory correspondence
- 8007020680 Forwards 800519 ltm.FR notice & Director's decision under 10CFR2 ROA denying Friends of the Earth 791024 petition to require supplemental environ statements on Class 9 accidents at facilities
 DENTON:H R OFFice of Nuclear Reactor Regulation. Director 80/06/19 2pp
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protection for electrical cables

- 800717053B Forwards 800702 FR notice re opportunity for hearing on application for DLs SCHMENCER, A Opporating Reactors Branch 3 80/07/02 3pp
- --B007170542 Notice of receipt of application for facility (Ls;notice of availability of applicant environ reptinotice of consideration of issuance of facility CLs & notice of apportunity for hearing Newspaper notice encl
 SCHWENCER, A Liconsing Branch 3 80/07/02 10pp
- BOO7110002 Order granting extension until BO0722 for Commission to elect to review decision on enforcement action request, DD-BO-22
 HOYLE, J C Office of the Secretary of the Commission 80/07/08
- 8007300106 Notices of appearance in proceeding Certificate of Svc encl QENR.A C . BISCHOFF.C A Arizona Public Service Co 80/07/23 3pp

H General correspondence

- 8007110526 Responds to 800407 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR. Section 9 1 BCHWENCER. A Licensing Branch 2 80/06/26 4pp
- 8007210018 Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded SOUDER. J. L. Davision of Rules and Records 80/07/07 lp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B0072B0589 Notifies that FSAR & environ rept complete & no further action required Forwards revised & new pages to be incorporated in next FSAR amend & environ rept suppl VAN BRUNT,E E Arixona Public Service Co 80/07/23 ip
- --B0072B0990 "Add1 lnfo for Amend 2 to FSAR," re gmology, seismology & guotechnical empineering of structural design. & integrity of reactor coulant pressure boundary Preliminary version " w Arisona Public Service Co B0/07/23 19pp
- --B0072B0598 "Add1 Info for Suppl 1 to Environ Rept," re need for power, geography & Hemography, & applicant preoperational environ progrems Preliminary version # Arirona Public Service Co B0/07/23 29pp
- A Inspection reports: IE Bulletins & correspondence
- 8007280063 Suppls H00208 response to IE Bulletin 79-28, "Possible Malfunction of NAMCO EAIBO Limit Switches at Elevated Temps" Subj switch is supplied on 1 5-inch pneumatic operated gate valve Gaskets replaced prior to shipment VAN BRUNTEE Arizona Public Service Co 80/03/11 ip
- 8007250357 Responds to IE Bulietin 80-03, "Loss of Charcoal from 8td Type II,2-Inch Tray Adsorber Cells " Type II tray adsorber cells are not used at facility filtration units used are rechargeable.permanents.single-unit adsorbers VAN DRUNT,E E Arizona Public Service Co 80/03/18 ip
- 0007170265 Forwards IE Insp Repts 50-528/80-05,50-529/80-05 k 50-530/80-05 on 800303-14 No moncompilance noted SPENCER.O 9 Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/05/20 2pp
- ---B007170270 IE Insp Repts 50-528/80-05, 50-529/80-05 & 50-530/80-05 on B00303-14 No moncompliance noted Major areas inspected Unit i control bidg cable tray, concrete records & Unit 3 containment basemat concrete placement VORDERBRUGGEON Region 5, San Francisco, Office of the Director DDDDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/05/20 App
- 8007010016 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Foodwater Pumps " No written response required. ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/09/27 ip
- 8007220235 Forwards IE Info Notice 80-25. "Evaluation of Contractor GA Programs " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/06/10 ip

- 8007300516 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks Thirty add1 days needed to obtain info requested in Item 2 VAN BRUNT,E E Arizone Public Service Co 00/06/10 1p
- 8007270080 Forwards lE Info Notice 80-28, "Prompt Reporting of Info in Accordance M/ICCFRSO 95(e)" No written response required ENDELKEN,R H Region 5, San Francisco, Office of the Director 80/06/13 ip
- 8007290523 Responds to IE Bulletin 80-07 Two suppliers make use of hydramotor actuators Thirty-day extension necessary to determine if actuators are used in safety-related sys & if corrective actions required VAN BRUNTLE E Arizona Public Service Co 80/06/17 ip
- BOO7020477 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/20 in
- 8007180286 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/24 1p
- BOO72303Bi Forwards lE Bulletin BO-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Prossure Transmitters W/Either A or D Output Codes "Written response required IE Circular BO-16 also encl No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director BO/06/27 19
- B007300530 Responds to IE Bulletin B0-05 re damage to chesical vol control sys tanks No addl vacuum features needed for justification LRS holdup tanks cannot collapse due to vacuum VAN BRUNT, E E Arizona Public Service Co
- B007270516 Responds to IE Bulletin 80-09 re hydromotor actuator deficiencies Field adjustment of present units necessary Springs used have stroke length precluding permanent set problem VAN BRUNT, E E Arizone Public Service Co 80/07/03 2pp
- B007210543 Ack receipt of B00624 ltr informing of steps taken to correct item of noncompilance noted in IE Insp Repts 50-528/ B0-06, 90-527/80-06 & 80-9530/80-06, Corrective actions will be varified during future insp SPENCER, 0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/07/08 Ip
- --8007210346 Forwards response to item of noncompliance noted in IE Insp Repts 50-528/80-06,50-527/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than omission to rept.as situation was potentially reportable deficiency VAN BRUNT,E E Arizona Public Bervice Co 80/06/24 3pp
- --8007210556 Forwards IE Insp Repts 50-528/80-06,50-529/80-06 & 50-530/80-06 on 800415-18 & notice of violation 8PENCER,0 8 Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8007210565 Notice of violation from insp on 800415-18
 * Region 5. Sen Francisco. Office of the Director 80/05/23 1p
- --B007210578 IE Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Noncompliance noted failure to rept deficiency within required reporting period ECKHARDT.J H. HERNANDEZ.G Region 5, San Francisco, Office of the Director DODDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 App.
- 8007310505 Forwards iE Insp Repts 50-528/80-07.50-529/80-07 & 50-530/80-07 on 800501-23 No noncompliance noted 8PENCER.O B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --B007310514 IE Insp Repts 50-528/80-07, 50-529/80-07 & 50-530/80-09 on B00501-23 No noncompliance noted Major areas inspected Unit 1 cadwelder qualification, containment bldg closure, pipe hangers & supports & electrical cable installation program. VORDERBURGGEN Region 5, Ban Francisco, Office of the Director DODDE, R T Region 5, Ban Francisco, Roactor Operations Nuclear Support Branch 80/07/10 Spp

occurrences, LERs & related correspondence
orwards interim deficiency rept re undersized fillet welds
for al steel
for E Arizona Public Service Co 80/06/26 2pp

Interim deficiency rept re undersized fillet welds for all steel Caused by personnel error Helding is a qualification repts of five suppliers being a evaluated and Public Bervice Co. 80/06/26 2pp.

prwards final deficiency rept re NAMCO controls Series it switches

E E Arizona Public Service Co 80/07/03 2pp

Final deficiency rept re NAMCO controls Series EA 180 limit Top cover gasket matl emits resin vapor which sosit on internal components of switch Caused by curing of gasket matl Caskets will be replaced and Public Service Co 80/07/03 ip

porwards interim deficiency rept re operability failure of fire dampers

E E Arizone Public Bervice Co 80/07/03 2pp

#3 Interim deficiency rept re operability failure of vertical appears Caused by lack of design tolerance on sheet addes preventing full closure of damper door Tests & Changes are being implemented Final rept by 800715 con

Forwards final deficiency rept re closure of Comsip, Inc. ant gas analysis pump valve.
The E Arizona Public Service Co. 80/07/09 2pp.

so Final deficiency rept re Comsip, Inc containment gas analysis ap Protection for pump is inadequate in case of reant closure of outlet valve w/pump running Units and additional service of outlety of the contains of the service of the contains of the co

Forwards final deficiency rept re visual insp rather than a squid penetrant of circumferential weld joints on tion III.Class 3 piping sys.
T.EE Arizona Public Service Co 80/07/09 2pp

93 Final deficiency rept re visual into rather than into by penetrant of circumferential weld joints on ASME in III. Class 3 piping sys Welds reinspected by liquid ment Three deficient welds discovered & repaired wona Public Service Co 80/07/09 2pp

Final deficiency rept re inadequate embedment of anchor re seal tables Coused by omission of anchor bolt in dealgn drawings Design change will be ted to reflect proper anchoring in concrete

T-E E Arizons Public Bervice Co. 80/07/21 App

-30-330 PALD VERDE NUCLEAR STATION, UNIT 3
tion/construction stage documents & correspondence

Summary of 800311 meeting w/util in Bethesda,MD re review r OL applications ₹ A Light Water Reactors Branch 3 80/04/25 4pp

Forwards NRC reorganization chart for Ofc of Nuclear Reactor Oh, effective 800428 Considerations re activities made through assigned mgt representatives Areas of ment may be discussed through informal appeal R. L. Assistant Director for Licensing 80/06/13 2pp.

Ack receipt & docketing of 791001 joint application for rds list of incomplete sections following by review of FBAR & environ rept Discusses procedures & importance of timely communication 0 0 Division of Licensing 80/06/16 799

Notification of 800709-10 meeting w/otil in Betheada, MD to to power sys Unicensing Branch 2 80/06/23 2pp.

Parwards statement of policy re requirements to be met for applications, as derived from NUREO-0660 & found 0.0474

B0070B0227 Requests authorization under CPPR-141, CPPR-142 & CPPR-143 to use ABME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds

VAN BRUNT,E E Arizona Public Service Co 80/05/27 ip

8007090285 Forwards Bechtel Power Corp & util responses to open items of Class IE dc power sys review Responses have been submitted to review board & Final resolution will be submitted to NRC when completed VAN BRUNT.E E Arizona Public Service Co 80/06/30 10pp

8007110398 Forwards proofs of svc for applicant FSAR.OL application, general info & environ rept, required by NRC 800618 ltr VAN BRUNT,E E Arizona Public Service Co 80/07/01 8pp

♥ Adjudicatory correspondence

8007020680 Forwards 800519 ltr.FR nutice & Director's decision under 10CFR2 206 denying Friends of the Earth 791024 petition to require supplemental environ statements on Class 9 accidents at facilities DENION,H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp

8007310243 Forwards Commission 800527 momorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables
EISENHUT.D G Division of Licensing 80/04/25 87pp

8007170538 Forwards 800702 FR notice re opportunity for hearing on application for OLs
SCHWENCER, A Operating Reactors Branch 3 80/07/02 3pp

--B007170942 Notice of receipt of application for facility OLs; notice of availability of applicant environ rept; notice of consideration of issuance of facility OLs & notice of opportunity for hearing Newspaper notice encl
BCHWENGER, A Licensing Branch 3 80/07/02 10pp

8007110002 Order granting extension until 800722 for Commission to elect to review decision on enforcement action request, DD-80-22 HOYLE, J C Office of the Secretary of the Commission 80/07/08 to

8007300104 Notices of appearance in proceeding Certificate of Svc encl QEHR: A C : BISCHOFF: C A Arizona Public Service Co 80/07/23 3pp

H General correspondence

8007110526 Responds to 800409 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area spent fuel pool shipping cask area & Ruel pool cooling & cleanup sys Detailed description may be found in FSRR, Section 9 1 SCHWENCER. A Licensing Branch 2 90/06/26 4pp

80072i001B Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded SDUDER, J L Division of Rules and Records 80/07/07 ip

K Utility Final Safety Analysis Report (FBAR) & amends

B007280385 Notifies that FSAR & environ rept complete & no further action required Forwards revised & new pages to be incorporated in next FSAR amend & environ rept suppl VAN DRUNTIE E Arizona Public Service Co 80/07/23 lp

--8007280590 "Add1 Info for Amend 2 to FSAR," re geology, seismology & geotochnical engineering of structural design, & integrity of reactor coolant pressure boundary Preliminary version "
* Arizona Public Service Co 80/07/23 17pp

--8007280598 "Addl Info for Suppl 1 to Environ Rept." re need for power, geography & demography. & applicant preoperational environ programs Preliminary version

* Arizona Public Service Co 80/07/23 29pp

G Inspection reports, IE Bulletins & correspondence

8007280043 Suppls 800208 response to 1E Builetin 79-28, "Possible Malfunction of NAMCO EAISO Limit Switches at Elevated Temps" Subj switch is supplied on 1 5-inch pneumatic operated gate vulve Castets replaced prior to shipment VAN IRUNT, EE Arizona Public Service Co 80/03/11 ip

- 07250357 Responds to IE Bulletin BO-O3, "Loss of Charcoal from Std ype 11.2-Inch Tray Adsorber Cells " Type II tray adsorber ells are not used at facility Filtration units used are echargeable, permanent, single-unit adsorbers VAN BRUNT.E E Arisona Public Service Co BO/O3/1B lp
- 07170265 Forwards IE Insp Repts 50-528/80-05.50-529/80-05 & 80-530/80-05 on 800303-14 No noncompliance noted PRENCER O S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/20 2pp
- 007170270 IE 3nsp Repts 50-528/80-05.50-529/80-05 & 50-530/80-05 on 800303-14 No noncompliance noted Major areas inspected Unit 1 control bldg cable tray concrete records & Unit 3 containment basemat concrete placement VORDERIBRUEGGEN Region 5. San Francisco. Office of the Director DODDS R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/20 App
- 07010Di6 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency redwater Pumps " No written response required NOVELECTION OF THE REGION 5. San Francisco, Office of the Director NOVO5/29 ip
- 07220235 Forwards IE Info Notice 80-26. "Evaluation of Contractor A Programs " No written response required KNGELMEN.R H Region 5. San Francisco, Office of the Director 10/06/10 ip
- 17300516 Responds to IE Bulletin 80-05 re damage to chomical vol control sys tanks Thirty addl days needed to obtain info requested in Item 2 'AN BRUNT, E.E. Arizona Public Service Co. 80/06/10 lp
- 72900BD Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in ACCORDANCE W/10CFR50 55(e)" No written response required NOCELKEN,R H Region 5, San Francisco. Office of the Director NO/06/13 1p
- 7290523 Responds to JE Bulletin 80-09 Two suppliers make use of gdramotor actuators Thirty-day extension necessary to etermine if actuators are used in safety-related sys & if corrective actions required AN BRUNT, E Arisona Public Service Co BO/06/17 ip
- 7020477 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump coling & Natural Circulation Cooldown " No written response equired NGELKEN,R H Region 5. San Francisco, Office of the Director
- 0/05/20
- 07180286 Forwards IE Circular BO-14, "Radioactive Contamination of lant Demineralized Water Sys & Resultant Internal ontamination of Personnel " No written response required NOCELKEN R H Region 5, San Francisco, Office of the Director 10/04/24 1p
- 7230381 Forwards IC Bulletin 80-16. "Potential Misapplication of osemount Inc Models 1151 & 1152 Pressure Transmitters (Veither A or D Output Codes " Heitten response required E Circular 80-16 also encl No written response required NOELKEN,R H Region 5, San Francisco. Office of the Director 0/06/27 Ip
- 7300530 Responds to IE Bulletin 80~05 re damage to chemical volontrol sys tanks No addl vacuum foatures needed for ustification LRS holdup tanks cannot collapse due to acuum
- AN DRUNT, E E Arizona Public Service Co 80/04/27 2pp
- 7270516 Responds to IE Bulletin 80-09 re hydromotor actuator eficiencies Field adjustment of present units necessary prings used have stroke length precluding permanant set roblem
- AN DRUNT, E E Artiona Public Service Co 80/07/03 200
- 7210543 Ack receipt of 800624 ltr informing of steps taken to orrect item of noncompliance noted in IE Insp Repts 50-528/0-06,50-529/80-06 & 50-530/80-06 Corrective actions will be earlied during future insp FENCER,0 8 Region 5, 8an Francisco, Reactor Construction & ngineering Support Branch 80/07/09 ip
- 007210546 Forwards response to item of noncompliance noted in 1E Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than omission to rept. as situation was potentially reportable deficiency VAN BRUNT, E.E. Arizona Public Service Co. 80/06/24 3pp

- --8007210536 Forwards 1E Insp Repts 50-528/80-06,50-529/80-06 & 50-530/80-06 on 800415-18 & notice of violation SPENCER.0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 2pp
- ~~8007210565 Notice of violation from insp on 800415-18 * Region 5, San Francisco, Office of the Director 80/05/23 1p
- --8007210378 IE Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Noncompliance noted failure to rept deficiency within required reporting period ECKHARDT, J. H. HERNANDEZ. O Region 5. Ban Francisco. Office of the Director DODDS, R. T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/23 6pp
- B007310505 Forwards IE Insp Repts 50-528/80-07, 50-529/80-07 & 50-530/80-09 on 800501-23 No noncompliance noted SPENCER.0 S Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --B007310516 IE Insp Repts 50-528/80-09, 30-529/80-09 & 50-530/80-09 on B00501-23 No noncompliance noted Major areas inspected Unit 1 cadwelder qualification, containment bldg closure, pipe hangers & supports & electrical cable installation program VORDERADRUEGOEN Region 5. San Francisco. Office of the Director DDDDB.RT T Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/10 Spp
- B Reportable occurrences, LERs & related correspondence
- B007020525 Forwards interim deficiency rept re undersized fillet welds for structural steel VAN BRUNT,E E Arizona Public Bervice Co 80/06/26 2pp
- --8007020527 Interim deficiency rept re undersized fillet welds for structural steel Caused by personnel error Welding procedures & qualification repts of five suppliers being reviewed & evaluated e Arizona Public Service Co 80/06/26 2pp
- 8007160546 Forwards final deficiency rept re dowel omission during concrete placement

 VAN BRUNT, E E Arizona Public Service Co 80/07/08 2pp
- B007160652 Forwards final deficiency rept re closure of Commission Commission
- ---8007160658 Final deficiency rept re Comsip. Inc containment gas analysis sys pump Protection for pump is inadequate in case of inadvertent closure of outlet valve w/pump running Units will be modified per Comsip. Inc instructions # Arizona Public Service Co 80/07/09 3pp
- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR
- B. Utility Preliminary Safety Analysis Roport, amends
- 8007080264 Forwards affidevit confirming distribution of PSAR Amend 55 to local public officials & EPA representatives COPELAND,R L Energy, Dept of, Clinch River Breader Reactor Plant BO/07703 2pp

i

- F Security, medical, omergency & fire protection plans
- EOO7010366 Forwards physical security plan Plan withheld (ref iOCFR2 790)
 COPELAND,R L Energy, Dept of, Clinch River Breeder Reactor Plant. BO/06/27 App
- 8007100194 Forwards revised responses to Questions 421 3 & 421.10 re physical security plan Responses withheld (ref 10CFR2 790) Related correspondence COPELANDLR L Chargy, Dept of, Clinch River Breeder Reactor Plant, 80/06/27 App

- DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8007280286 Forwards physical security plan for SNM of low strategic significance Plan withheld (ref 10CFR2 790) JONES,D W. Memphis State Univ 80/07/23 ip
- Q. Inspection reports: IE Bulletins & correspondence
- BOO7170177 Forwards IE Circular 80-14, "Redicactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required D'RETLLY, J P Region 2, Atlanta, Office of the Director BO/06/24 to
- DOCKET BIN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- | 8007010096 Forwards util revised project GA manual Contains resolution of IE comments from review of previous manual Project mgt procedures & ASME GA manual will be reviewed for consistency w/project GA manual. H/O enci
 - 8007210058 Advises of readiness for NRC review & evaluation of Items A 1.c.,d. & B 1 of app to V Stello 800515 ltr re graduated revision of order dated 790815 BHIELDS/B W Public Service Co of Indiana, Inc. 80/06/19 ip
 - BOO7140581 Confirms 800627 meeting w/MD Menscer & HA Darker at site to discuss const related activities KEPPLER.J.O Region 3, Chicago, Office of the Director 80/06/24
 - 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0460 & found in NUREO-0494
 EIBENHUT, D. O Division of Licensing 80/06/26 2pp
 - BOO7250142 Notifies that licensee revised GA program & prerequisites necessary for receipt insp.under restart program ltems A 2 & B, 3, have been satisfactorily completed Util is authorized to begin receipt insps for Item B, 4, STELLO, V. Office of Inspection & Enforcement. Office of the Director. 80/07/07 Spp.
 - F Security, medical, emergency & fire protection plans
 - BOO7280571 Requests confirmation that divisional personnel located onsite would not be covered by NOREC-0554 & FEMA REP-1 unless specific oneite emergency assignments were involved BHIELDS, S. W Public Service Co. of Indiana, Inc. 86/07/18 2pp
 - 9. Adjudicatory correspondence
 - 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENNUT.D.O. Division of Licensing. 80/06/25 899p
 - B007100295 Discusses Save the Valley addl comments to Commissioner re resumption of work at facility, docketed on 800514 NRC will review document to determine whether addl enforcement measures are appropriate STELLD, V Office of Inspection & Enforcement, Office of the Director. 80/06/24 2pp
 - --8007100308 Notice that Save the Valley addl comments to Commissioner re resumption of work at facility, docketed on 800514.will be treated under 100FR2 206 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/06/26 lp
 - H General correspondence

1

8007110588 Forwards response to questions & comments presented at 800325 public meeting. Util required to adhere to ASME code for safety-related piping sys Revised GA program description encl. H/o description of the BTELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 Spp.

- B007010031 Submits addl info arrising from Sassafras Audubon Society 790701 request for hearing re heavy faults & forwards B00610 ltr to D0 Fry STELLO,V Office of Inspection & Enforcement, Dffice of the Director B0/06/16 2pp
- ---B007010046 Ack receipt of B00515 roply to request for background info on statement re heavy foults made in 790901 request for hearing Term was inappropriate Concrete structures will exhibit cracks which do not affect integrity SHEWHAKER,R E Office of Inspection & Enforcement, Office of the Director 80/06/10 2pp
- --8007010055 Responds to 800508 inquiry re statement in 790901 request for hearing on confirming suspension of const re heavy faults Forwards 790ill Indianapolis Star news article in which statement appeared Requests any info on subj FREY.D G Sassafras Audubon Society 80/05/15 2pp
- 8007110544 Notifies that action per 10CFR2 296 is being taken to consider comments docketed on 800507 & 14 re resumption of const at plant Notice of request for action will be published in FR STELLO,V Office of Inspection & Enforcement, Office of the Director 80/06/26 4pp
- 8007220549 Forwards summary of latest (June 1980) organizational change Info includes revised organization charts & provides overview identifying individual changes which affect overall QA program
 SHIELDS, S W Public Service Co of Indiana, Inc 80/07/09 Spp
- G Inspection reports, IE Bulletins & correspondence
- 8007210363 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007010074 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/29 to
- 8007100096 Forwards IE Insp Repts 50-546/80-19 & 50-547/80-19 on 800913 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/04/03 2pp
- --B007100099 IE lmsp Repts 50-546/80-19 & 50-547/80-19 on 800513 No noncompliance noted Major areas inspected environ monitoring program & environ protection program E8810.T H , GREER.R H Region 3. Chicago, Office of the Director 80/06/02 3pp
- 8007160469 Forwards IE insp Repts 50-546/80-17 & 50-547/80-17 on 800422-29, 30 & O513 No noncompliance noted FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/10 2pp
- --B007160479 IE Insp Repts 50-546/80-17 & 50-547/80-17 on 800422-25.30 O513 No noncompliance noted Major areas inspected project QA manual, personnel qualifications & physical verification of structural steel activities SCHMEIBNINZ.E. HARRISON.J., WILLIAMS.C.C. Region 3, Chicago, Office of the Director 80/06/06 7pp
- 8007220215 Forwards IE Info Nutrice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/06/10
- 8007160187 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolants Pump Studs " No specific action or response required MEPPLER, J Q Region D. Chicago, Office of the Director 80/06/11
- 8007020027 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02, 50-546/79-03 & 50-547/79-03, 50-546/79-04 & 59-547/79-04 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/13 ip
- --8007020031 Responds to NRC ltr re violations 50-546/79-02.50-547/79-02.50-546/79-03.50-50-546/79-04 & 50-547/70-04 Corrective ac re GC insp have been rewritten to clarift SHIELDS, S W Public Service Co of India

- 007280631 Forwards IE Info Notice 80~28. "Prompt Reporting of Info in Accordance W/100FR50 55(e)" No written response required MEPPLER, J. G. Region J. Chicago, Office of the Director 80/06/19 1p
- B007140506 Responds to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies " Vendor will not utilize incorrect spring math in facility actuators having greater than 3-inch stroke No mad heeded for equipment qualification or test programs BHIELDS, BW Public Service Co of Indiana, Inc 80/06/18 ip
- 3007230704 Forwards IE Insp Repts 50~546/80~22 & 50~547/80~22 on 800501~31 No noncompijance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/19 2pp
- -8007230710 IE Insp Repts 50-546/80-22 % 50-547/80-22 on 800501-31 No nuncompliance noted Major areas inspected auxiliary & fuel handling blogs & containment HARRISON, J , WILLIAMS, C C Region 3, Chicago, Office of the Director 80/06/18 4pp
- 8007020548 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Matural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20, ip
- 3007170510 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys % Resultant Internal Contamination of Personnel " No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/06/24 ip
- 3007230308 Forwards IE Bulletin 80-16, "Potential Misappiication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also oncl No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/2
- 1007730238 Responds to 12 Bulletin 80~08, "Exam of Containment Liner Penetration Welds " Penetrations will be installed per ASME code Radiographic examinations of Types 1 & 2 flued head penetrations will be performed SHIELDS, S W Public Service Co of Indiana, Inc. 80/07/03 2pp
- 3007230093 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Cuntrol Syn (CVCS) Holdup Tanks "Design features & proper operating procedures ensure adequate protection against vacuum damage SHIELDS.B W Public Service Co of Indians, Inc. 80/07/07 2pp.
- 3007280083 Forwards restart program w/NRC hold points Based on insp findings,which confirm info reported in 800627 ltr.concludes ltems A 2 & B 3 uf restart program meet OA requirements Program acceptable STELLG/V Office of Inspection & Enforcement, Office of the Director B0/07/07 App
- . Reportable occurrences. LERs & related correspondence
- 3007100229 Interim deficiency rept re certified matl test repts for weld filler matl ASMC has not provided code interpretation of requirements re repts to date, but util expects to file final rept on or before 801001
 SHELDS, S W Public Service Cn of Indiana, Inc. 80/06/27 ip
- 2007210012 Ack receipt of 800430 final deficienty rept re damage to containment liner on Unit ! FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- NOO7210021 Ack rerespt of 800602 interim deficiency rept re problem in operation of centrifugal charging pumps at min allowable flow ratu FIDRCLLI-6 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/03 ip
- 1007210025 Ack receipt of 800425 interim deficiency rept re certified matl test repts for weld filter matl FIGRCLLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- OOTELOOB: Act recipt of BOD428 final deficiency meet re concrete auxiliary bldg slab FIORCLLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/07/03 lp

- 8007210054 Ack receipt of 800425 final deficiency rept re joints in safety-related structural steel FIORELLI, 9 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007230615 Ack receipt of 800425 final deficiency rept re use of noncode matl in certain code, Category I component supports F10RELL1.6 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007180536 Ack receipt of 800513 final deficiency rept re failure to meet PSAR basis secondary cooling flow rate due to main feedwater line rupture w/concurrent failure of steam generator blowdown isolation valve on another loop FIGRELLI, 0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/07 lp
- B007240319 Ack recoipt of B00627 interim deficiency rept re incorrect weld filler used in welding of safety-related pipe spool pieces FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- 8007250397 Interim deficiency rept re automatic actuation function of Mestinghouse Type N-2 switch Util will consider vendor findings & determine any corrective actions Final rept will be forwarded by 801121 SHIELDS, S W Public Service Co of Indiana, Inc. 80/07/21 2pp
- 8007280667 Interim deficiency rept re reinforcing steel installations not meeting spec requirements Cause not stated Engineering evaluation will be performed on pertinent reinforced concrete elements
 SHIELDG.S W Public Service Co of Indiana, Inc. 80/07/24 2pp
- U Congressional/Executive Correspondence
- 800711031B Discusses concerns re DDJ investigation of alleged coverup of const flaws Stop work order should not be lifted w/o release of final FDI rept Independent engineer should be allowed continued access to site if const resumes FORD.W H Senate 80/05/08 ip
- 8007080159 Responds to 800313,0417 & 0508 ltrs re facility const resumption Use of consultant to perform regular insp functions would not provide addl safety assurance AHEARNE.JF Commission 80/06/16 3pp
- **B007R502R5 Provides five main topics of considerations re resumption of safety-related const work, in response to 800515 request Includes verification of adequacy of previously placed concrete & ratios & numbers of QA/GC personnel DIRCKB.H J. Office of the Executive Director for Operations 80/07/02 5pp
- --B007250246 Requests info re IE recommendation to allow gradual resumption of const & issues discussed in related Commission briefing DECKARD, J House of Rep , Government Operations BO/05/15 Spp
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B007010094 Forwards util revised project QA manual Contains resolution of 1E comments from review of previous manual Project mgt procedures & ASME QA manual will be reviewed for consistency w/project QA manual W/o encl SHIELDB.8 W Public Service Co of Indiana, Inc 80/06/04 ip.
- BOD721005B Advises of readiness for NRC review & evaluation of Itams A 1 c .d. & B 1 of app to V Stello BO0515 ltr re graduated revision of order dated 790815 SHIELDS.S W Public Service Co of Indiana, Inc 80/06/19 ip.
- BOO71405B1 Confirms 800627 meeting w/MD Menscer & HA Barker at site to discuss const related activities KEPPLER, J 0 Region 3. Chicago, Office of the Director. BO/06/24 to
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D © Division of Licensing 80/06/26 2pp

- 8007250142 Notifies that licensee revised GA program & prerequisites nacessary for receipt insp.under restart program Items A 2 & B 3, have been satisfactorily completed Util is authorized to begin receipt insps for Item B 4 BTELLO.V Office of Inspection & Enforcement. Office of the Director 80/07/07 5pp
- F Security, medical, emergency & fire protection plans
- BO07280591 Requests confirmation that divisional personnel located onsite would not be covered by NUREG-0554 & FEMA REP-1 unless specific onsite emergency assignments were involved SHIELDS.S W. Public Service Co of Indiana, Inc 80/07/18 2pp

@ Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp
- 8007100275 Discusses Save the Valley add! comments to Commissioner re resumption of work at facility, docketed on 800514 NRC will review document to determine whether add! enforcement measures are appropriate BTELLD, V Office of Inspection & Enforcement, Office of the Director 80/06/26 2pp
- ---B00710030B Notice that Save the Valley addl comments to Commissioner re resumption of work at facility, docketed on B00514, will be treated under 100FR2 206 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/06/26 ip

H. General correspondence

- 8007110588 Forwards response to questions & comments presented at 800325 public meeting Util required to adhere to ABME code for safety-related piping sys Revised QA program description encl W/o description.

 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/23 Spp
- B007010031 Submits add1 info arising from Sassafras Audubon Society 790901 request for hearing re heavy faults & forwards 800610 ltr to D0 Fry STELLO, V Office of Inspection & Enforcement, Office of the Director. B0/06/16. 2pp
- ---B007010046 Ack receipt of 800313 reply to request for background info on statement re heavy faults made in 790701 request for hearing. Term was inappropriate Concrete structures will exhibit cracks which do not affect integrity SHEMMAKER, R E Office of Inspection & Enforcement, Office of the Director 80/06/10 2pp.
- --BOO7010033 Responds to BOO30B inquiry re statement in 790901 requost for hearing on confirming suspension of const re heavy faults Forwards 790111 Indianapolls Star news article in which statement appeared Requests any info on subj FREY, D G Sassafras Audubon Society BO/05/13 2pp
- 8007110544 Notifies that action per iOCFR2 206 is being taken to consider comments docketed on 800507 & 14 re resumption of const at plant Notice of request for action will be published in FR STELLO, V Office of Inspection & Enforcement, Office of the Director 80706/26 App
- 8007220549 Forwards summary of latest (June 1980) organizational change. Info includes revised organization charts & provides overview identifying individual changes which affect overall GA program SHIELDS.S W Public Service Co of Indiana. Inc 80/07/09 Bpp
- O Inspection reports, IE Bulletins & correspondence
- BOO7210363 Forwards IE Circular BO-13, "Orid Strep Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director BO/05/28
- BOO7010074 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Foodwater Pumps" No written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director SO/05/29 to.

- 8007100094 Forwards IE Insp Repts 50-446/80-19 & 50-347/80-19 on BO0513 No noncompliance moked DAVIS,A B Region 3. Chicago Fuel Facility & Materials Safety Branch 80/06/03 2pp
- --8007100099 lE Insp Repts 50-546/80-19 & 50-547/80-19 on 800513 No noncompliance noted Major areas inspected environ monitoring program & environ prutoction program &SSIG.T H. GREER.R H. Region 3. Chicago, Diffice of the Director 80/06/02 3pp
- 8007160469 Forwards IE Insp Repts 50-546/80 17 & 90-547/80-17 on 800422-29,30 & 0513 No noncompliance noted FIGRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- ~~80071&0479 IE Insp Repts 50~546/80~1/ & 90~547/80~1/ on 800422-25.30 OSI3 No honcompliance noted Major areas inspected project 8A manual, personnel qualifications & physical verification of structural steel activities SCHEIDNINZ,C, HARRISON,J, J, WILLIAMS,C, Region 3, Chicago, Office of the Director 80/06/06. 9pp
- 8007220215 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written responso required KEPPLER.J G Rugion 3, Chicago, Office of the Director 80/06/10 lp
- B007160187 Forwards IE Info Notice 80-27, "Dogradation of Reactor Companies Pump Study" No specific action or response required MEPPLER. J G Region 3. Chicago, Office of the Director 80/05/il. to
- B007020027 Ack receipt of 800328 ltr informing NRC of steps taken to correct violations noted in IE Imp Repts 50-546/79-02 & 50-547/79-02, 50-546/79-03 & 50-547/79-03, 50-546/79-04 & 59-547/79-04 B CORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/06/13 ip
- --H007020031 Responds to NRC ltr re violations noted in IE Insp Repts 50-546/79-02, 50-547/79-02, 50-546/79-03, 50-547/79-03, 50-546/79-04 & 50-547/70-04 Corrective actions procedures re GC insp have been rewritten to claifly process SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/05/28 Spp
- 8007280631 Forwards 1E Info Nutice 80-28. "Prompt Reporting of Info in Accordance W/10CFR90 99(e)" No written response required KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/06/13
- G007i40506 Responds to 1E Bulletin (10-09, "Hydramotor Actuator Deficiencies" Vendor will not utilize incorrect apring mati in facility actuators having greater than 3-inch strake No mod needed for equipment qualification or test programs SHIELDS, B W Public Service Co. of Indiana, Inc. 80/06/10 ip
- 8007230704 Forwards 1E Insp Repts %0-546/80-22 & 90-547/80-22 on 800501-31 No noncompliance hoted FIORELLI & Region 3. Chicago: Reartor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230710 IC Insp Repts 50-546/80-22 & 50-547/80-22 on 800501-31 No noncompliance noted Major areas inspected auxiliary & fuel handling bligs & containment HARKEDN.J J. WILL IAMS.C C. Region D. Chicago, Office of the Director 80/06/18 App
- 9007020548 Forwards JE Circular 80-15, "Loss of Apactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chirago, Office of the Director 80/06/20
- 8007170510 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24 tp
- 8007230338 Forwards IE Bulletin 80-fc. "Potential Rosemount Inc Models 1151 & 1152 Prossure Trans W/Either A or D Output Codes " Writton respons IE Circular 80-16 also encl No written response KEPPLER, J O Hegian 3, Chicago, Office of the D ip

- 800723023B Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Penetrations will be installed per ASME code Radiographic examinations of Types 1 & 2 flued head penetrations will be performed SHIELDS,S W Public Service Co of Indiana, Inc. 80/07/03 2pp
- 8007230093 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 Design features & proper operating procedures ensure adequate protection against vacuum damage SHIELDS,8 W Public Service Co of Indiana, Inc 80/07/07 2pp
- BOO72BOOBS Forwards restart program w/NRC hold points Based on insp findings,which confirm info reported in BOO627 ltm.concludes Items A 2 & B 3 of restart program meet GA requirements Program acceptable STELLO.V Office of Inspection & Enforcement, Office of the Director BO/07/07 App
- S Reportable occurrences. LERs & related correspondence
- 8007100229 Interim deficiency rept re certified matl test repts for welf filler matl ASME has not provided code interpretation of requirements re repts to date, but util expects to file final rept on or before 801001
 SHIELDS, S W Public Service Co of Indiana, Inc 80/06/27 ip
- 8007210021 Ack receipt of 800602 interim deficiency rept re problem in operation of centrifugal charging pumps at min allowable flow rate FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 lp
- BOO7210025 Ack receipt of BOO425 interim deficiency rept re certified matl test repts for weld filter matl FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/03 lp
- 0007210031 Ack recippt of B00428 final deficiency rept re concrete auxiliary blog stab FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/07/03 ip
- BOO7210054 Ack receipt of BOO425 final deficiency rept re joints in safety-related structural steel FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007230615 Ack receipt of 800425 final deficiency rept re use of noncode math in certain code.Category I component supports FIDRELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/03 ip
- BOD7180536 Ack receipt of 800513 final deficiency rept re failure to meet PSAR besis secondary cooling flow rate due to main feedwater line rupture w/concurrent failure of steam generator blowdown isolation valve on another loop. FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Eugpart Branch 80/07/07 ip
- 8007240317 Ack recelpt of 800627 interim deficiency rept re incorrect weld filler used in welding of safety-related plps spool
- process. FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- 8007250397 Interim deficiency rept re automatic actuation function of Hestinghouse Type W-2 switch Util will consider vendor findings & determine any corrective actions Final rept will be forwarded by 801121 BHIELDS.S W Public Service Co of Indiana, Inc. 80/07/21 2pp
- 9007280647 Interim deficiency rept re reinforcing steel installations not meeting spec requirements Cause not stated Engineering evaluation will be performed on pertinent reinforced concrete elements
 SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/07/24, 2pp.
- ▶ Congressional/Executive Correspondence
- 8007110318 Discusses concerns re DDJ investigation of alleged coverup of const flaws Stop work order should not be lifted w/o release of final FBI rept Independent engineer should be allowed continued access to site if const resumes FDRD,W H Senate 80/05/08 lp
- B0070B0159 Responds to B0D313,0417 & 0508 ltrs re facility const resumption Use of consultant to parform regular insp functions would not growide addl aafety assurance AHEARNE, J F Commission B0/06/16 3pp.

- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT
- A Application/construction stage documents & correspondence
- BD0723000\$ Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-06494
 EISEM-UT, D G Division of Licensing 80/06/26 2pp
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B007010228 Advises of reorganization of Ofc of Nuclear Reactor Regulation: effective B00428 Mgt of all licensing matters for facilities has been assigned to D Scaletti Organizational description encl TEDESCO.R L Assistant Director for Licensing 80/06/13 Assistant Director for Licensing 80/06/13 10pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674
 EIBENHUT, D G Division of Licensing 80/06/26 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- BOO7180481 Responds to encl 800228 ltr to President Carter re nuclear power plants Radiation exposure considered as part of EIB before CP issued Every effort made to protect public health & safety at all nuclear plants DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/05 2pp
- A Inspection reports, IE Bulletins & correspondence
- B007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" No response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/05/08
- 8007140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spangers " No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29.
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- 8007140301 Forwards IE Bulletin 80-14. "Degradation of BHR Scram Discharge Vol Capability " No written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/6
- 8007250394 Forwards IE Info Notice 90-28, "Prompt Reporting of Info in Accordance W/100FR50 55(e) " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13.
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP O'Reilly 8004i7 ltr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS.L M Tennessee Valley Authority 80/06/16 2pp
- BOO7170559 Responds to TV Abbatiello 800606 telcon re IE Investigation Repts 50-553/80-05 & 50-554/80-04 Error in Peragraphs 2 & 3 of Attachment A of subj repts has been corrected changing assistant const engineer to assistant const superintendent. ALDERSON.C E Region 2, Atlanta, Office of the Director. 80/06/19 in.

- BOO7020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response raquired O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Hater 84s & Resultant Internal Contamination of Personnel " No written response required. O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/24
- 8007230233 Forwards IE Bulletin 80-16, "Potential Misapplication of Museacount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes "Written response required IE Gircular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27 is.
- B007220236 Responds to IE Bulletin 79-28, "Possible Malfunction of MAMCO Model EA180 Limit Switches at Elevated Temps "
 Investigations show no NAMCO EA180 switches are installed or glanned for installation.
 MILLS.L.M. Tennessee Valley Authority. 80/07/01, 1p.
- 2007180189 Ack receipt of 800619 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-553/80-08 & 50-554/80-07.

 MMRHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/02. ip.
- --- 8007180220 Notice of violation from insp on 800507-09
 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/21. 1p
- 8007280615 Responds to IE Bulletin 80-08, "Examination of Containment Fenetration Welds," Results of investigation encl MILLS, L. M Tennessee Valley Authority 80/07/07. Spp
- B. Reportable occurrences: LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities. Detailed info will be provided to assist determination of significant safety hazard GIROUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17 3pp.
- B007170247 Part Ri rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is growided to assist in determination of significance as safety hazard OIRDUX, E. J. Carrier Corp. Carrier Air Conditioning Div. B0/06/20 29pp.
- 8007100252 Fifth interim deficiency rept re high pressure core spray diesel generator switchgear wiring discrepancies 9E has not provided to util revised/corrected drawings or replacement parts to complete actions Final rept to be filed by 801001 MILLS, L M Tennessee Valley Authority 80/06/27 ip
- 8007110320 Forwards first interim deficiency rept on Resembnt Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917. HILLS, L. H. Tennessee Valley Authority 80/07/02. ip

- --B007ii0328 First interim deficiency rept on Rusemount Model 1152 pressure transmitter defects During testing GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/02 ip
- B007220490 First interim deficiency rept re reactor pressure vessel shroud head & moisture separator assembly fire Reactor pressure vessel assembly was initially hydroblasted w/demineralized water Assembly will be cleaned thoroughly Tennessee Valley Authority 80/07/14 3pp
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8007010228 Advises of reorganization of Ofc of Nuclear Reactor Regulation, effective 800428 Mgt of all licensing matters for facilities has been assigned to D Scaletti Organizational description encl TEDESCO,R L Assistant Director for Licensing 80/06/13 10pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 E1SENHUT, D G Division of Licensing 80/06/26 2pp
- **Q** Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 77104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 87sp
- H General correspondence
- 8007180481 Responds to entl 800228 ltr to President Carter re nuclear power plants Radiation exposure considered as part of E18 before CP issued Every effort made to protect public health & safety at all nuclear plants DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/05 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/08 3so
- 8007140479 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/12 in
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/29 lp
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/10 Gpp
- 8007i40301 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/12 19
- 8007290384 Forwards JE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10GFR50 95(s)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- 8007020497 Forwards response to IE Bulletin 80-09 transmitted by JP B'Reilly 800417 itr Final rept for Martsville & Phipps Bend plants will be sent on or before 801017 MILLS, L M Tennessee Valley Authority 80/06/16 2pp
- 8007170559 Responds to TV Abbaticilo 800606 teleon re lE Investigation Repts 50-553/80-05 & 50-554/80-04 Error in Paragraphs 2 & 3 of Attachment A of subj repts has been corrected, changing assistant const engineer to assistant const superintendent ALDERSON, C E Region 2, Atlanta, Office of the Director. 80/06/19.

- 007170557 Forwards IE Investigation Repts 50-553/60-05 & 50-554/80-04 on 800220-22 No noncompliance noted LONG.F J Region 2. Atlanta, Office of the Director 80/05/29
- 007170584 JE Investigation Repts 50-553/80-05 & 50-584/80-04 from insp 10/1/0584 IE Investigation Repts 50-553/80-05 & 30-554/80-04 from on 80020-22 Major areas inspected allegation that welding GC inspector was instructed by supervisor to exceed permissible weld bead widths LONG, F. J. HARSK.R J. Region 2. Atlanta, Office of the Director BO/05/28 10pp
- 7020391 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Juling & Natural Circulation Cooldown " No written response equired 'REILLY.J P Rogion 2. Atlanta, Office of the Director 80/06/20
- 7170070 Forwards If Carcular 80-14, "Radioactive Contamination of lant Demineralized Water Sys & Resultant Internal intomination of Personnel" No written response required 'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/2. 80/05/24
- 7230203 Forwards IE Bulletin 80-16, "Potential Misapplication of isemount Inc Models 1151 & 1152 Pressure Transmitters (Either A or D Dutput Codes " Written response required. Circular 80-16 also encl No written response required REILLY.) P Region 2. Atlanta. Office of the Director 80/06/2 80/06/27
- '220236 Responds to IE Bulletin 79-28. "Possible Malfunction of MCO Model EAIBO Limit Switches at Elevated Temps " vestigations show no NAMCO EAIBO switches are installed or anned for installation Tennessee Valley Authority 80/07/01
- 180187 Ack receipt of 800619 ltr informing NRC of steps taken to rrect violation noted in IE Insp Repts 50-553/HO-08 & -554/HO-07 RPHY.C E Region 2. Atlanta, Reactor Construction & Engineering
- 60/07/02
- 07180199 Forwards IE lnsp Repts 50-553/80-08 & 50-554/80-07 on 300507-09 & notice of violation URPHY,C E Region 2. Atlanta. Reactor Constitution & Engineering Support Diamch BO/05/28 2pp
- 97180220 Notice of violation from insp on 800507-09 Region 2: Atlanta, Reactor Construction & Engineering Support Tranch 80/05/21 lp.
- 17180234 IE Insp Repts 50-553/80-08 & 50-554/80-07 on 800507-09.
 Repts for a concrete batch plant insp ENAHAN, J. J. Region 2. Atlanta, Diffice of the Director Instruction & Engineering Upport Branch 80/05/21 5pp
- '80615 Responds to LE Bulletin 80-08, "Examination of Containment stration Wolds" Regults of investigation encl LS.L M Tennessee Valley Authority 80/07/07 3pp
- portable occurrences, LERs & related correspondence
- 70236 Part 21 rept re potential defect in air conditioning units facilities Detailed info will be provided to assist ermination of significant safety hazard OUX,E J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17
- 50275 Forwards final deficiency rept re incorrect root face on wed cadweld sleeves LS.L M Tennessee Valley Authority 80/06/19 ip
- 70247 Part 21 rept of potentially defective Rosemount. Inc namitter in control sys of air conditioning units Info is vided to assist in determination of significance as etu hazard
- Carrier Corp Carrier Air Conditioning Div 80/06/20
- 00252 Fifth interim deficiency rept re high pressure core spray sel generator switchgear wiring discrepancies OE has not vided to util revised/corrected drawings or replacement to to complete actions Final rept to be filed by B01001 LS.L M Tennessee Valley Authority B0/06/27 1p

- 8007:10320 Forwards first interim deficiency rept on Roseneunt Kodel 1:52 pressure transmitter defects initially reported 800603 Finel rept will be submitted on or before 8009:17 HILLS,L M Tennessee Valley Authority 80/07/02 ip,
- --- 8007110328 First interim deficiency rept on Rosempunt Model 1152 pressure transmitter defects During testing, QE found ambiguous autput to over & underpressure conditions Roview to determine number of transmitters on location underway to Tennessee Valley Authority 80/07/02 lp
- 8007220450 First interim deficiency rept re reactor pressure vessel shroud head & moisture seperator assembly fire Roactor pressure vessel assembly was initially hydroblested w/ deminoralized water Assembly wall be cleaned thoroughly promoses Valley Authority 80/07/14 Spp
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- EOO630036B Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retordancy will be provided i yr subsequent to receipt of CP MMENCH. 8 W Public Bervice Co of Oklahoma 80/06/20 2pp.
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0670 EISENHUT, D O Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- BOO7020613 Motion to intervene as interested state in Case 80-1566 before US Court of Appeals for DC Circuit NRC regulations grant states legal right to intervene at appeal stage Certificate of Svc enci Related correspondence BERGER, R F, CARTWRIGHT, J E Oklahoma, State of BO/06/24 10pp
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/04/25 89pp
- 8007310153 Notices of JO Thomas & CS Rogers withdrawal & RF Berger appearance in proceeding. Certificate of Svc encl THOMAS.J G , ROGERS.C S , BERGER,R F Oklahoma. State of 80/06/30
- 8007170367 Forwards SH Hanauer of Accident Task force 711005 memodesignated Number 22, re telcon w/P Bray of OE, in response to 800707 ltr PATON. W D Hearing Branch 4 80/07/15 1p
- ---B007170371 Advises of teicon w/R Selvatori of Westinghouse re Classes 2-8 accidents & probable causes Official use only, HANAUER, S.H. Atomic Energy Commission 71/10/05 1p
- H General correspondence
- 8007030013 Responds to 800905 ltr re emergency planning for fecilities Requirements for emergency planning are being revised in response to recommendations of NRC/EPA Joint Task Force on Emergency Planning & TML Lessons Learned Task Forces.

 ORIMES, B K Emergency Preparedness Program Office. 80/06/23. Rep
- --B007030019 Opposes const of facilities until adequate emergency response plan can be developed Recommends responsibility for emergency response plan be placed w/independent consulting svc.not State of OK MALONE, K Affiliation Unknown 80/05/05 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007220118 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/10
- 8007290075 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/13

DOCKET STN-50-997 BLACK FOX STATION, UNIT 2

- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENAUT, D 0 Division of Licensing 80/06/26 2pp
- F. Becurity, medical, emergency & fire protection plans
- 8006300368 Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retordancy will be provided i yr subsequent to receipt of CP MUENCH. 9 W Public Service Co of Oklahoma 80/06/20 2pp
- O Adjudicatory correspondence
- B007020613 Motion to Intervene as interested state in Case 80-1566 bafore US Court of Appeals for DC Circuit NRC regulations grant states legal right to intervene at appeal stage Certificate of Svc encl. Related correspondence

 BERGER, R.F., CARTHRIGHT, J.E. Oklahoma, State of 80/06/24 10p
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCB 780302 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables EISENKUT.D © Division of Licensing 80/06/25 89pp
- BOO7310133 Notices of JO Thomas & CS Rogers withdrawal & RF Berger appearance in proceeding Certificate of Svc encl THOMAS J O., ROGERS, C.S., BERGER, R.F. Oklahoma, State of 80/06/30 78p.
- 9007170369 Forwards 8H Hanauer of Accident Task Force 711005 memodesignated Number 22.re telcon w/P Bray of 0E.in response to 800709 ltr.
 PATON.H.D Hearing Branch 4 80/07/15 ip
- --B007170371 Advises of telcon w/R Salvatori of Hestinghouse re Classes 2-B accidents & probable causes Official use only HANAUER, B, H. Atomic Energy Commission 71/10/05 ip

H General correspondence

- 8007030013 Responds to 800505 ltr re emergency planning for facilities Requirements for emergency planning are being revised in response to recommendations of NRC/EPA Joint Task Force on Emergency Planning & TMI Lessons Learned fask Forces GRIMES, D. K. Emergency Preparedness Program Office 80/06/23 Rpp
- O Inspection reports, IE Bulletins & correspondence
- 800722011B Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director BO/06/10 lp
- 8007270075 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required BEYFRIT, K. V. Region 4, Dailas, Office of the Director 80/06/13

DOCKET STN-50-541 B-BAR-205

- H General correspondence
- 8007280149 Ack recaipt of wasay on "Excellence in Operations " Commends attitude toward work on nuclear power DENTON.H R Office of Nuclear Reactor Regulation, Director BQ/07/14 1p.

- DUCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT UNIT 1
- A Application/construction stage decuments & correspondence
- 8007310537 Confirms 800701 telcon is placement of earthfill in ERCW spray pand Concurs in resumption of earthfill placement, based on final rept in util 800711 ttr O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/16 lp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENAUT.D G Division of Licensing 80/04/26 2pp
- Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007300013 Responds to 790405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kempny Commission Rept encl DENTON. HR Office of Nuclear Reactor Regulation, Director 80/06/26 28pp
- 8007220027 Responds to DO Jourdan B0032B ltr to J Schlesinger Regulations require that extensive studies be performed to show that proposed plants will not endanger health & safety DENTON, HR Dffice of Nuclear Reactor Regulation, Director B0/07/01 2pp
- --8007220030 Forwards DO Jourdan 800328 ltr for consideration KENDRICK, H Energy, Dept of 80/06/03 Jpp
- @ Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/08
 3pp
- 8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required U'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007150447 Forwards IE Insp Repts 50-566/80-08 & 50-567/80-08 on 800513-16 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- --8007150452 IE Insp Repts 50-566/80-08 & 50-567/80-08 on 800513-16 No noncompliance noted Major areas inspected licenses identified items, insp followers litem warehouse storage & observation of safety-related concrete activities THOMASIM Region 2. Atlanta, Office of the Director CANTRELLIF B Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/04 4pp
- B007220029 Forwards IE Info Nutice 80-24, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 300
- 8007140287 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/ in
- B007250384 Forwards 1E 1nfo Notice B0-28, "Prompt Report Accordance W/JOCFR50 55(e) " No written response requi O'REILLY, J P Region 2, Atlanta, Office of the Direct

- 8007020391 Forwards IE Circular 80-15. Loss of Reactor Coolant Pump Conling & Natural Carculation Cooldown " No wratten response required
 O'REILLY, J P Region & Atlanta, Office of the Director 80/06/20
- B007290422 Forwards IE Insp Repts 50-564/80-09 \$ 50-567/80-09 on B00602-06 No noncempliance noted MURPHY.C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0706/23 2pp
- --8007290432 IE Insp Repts 50-566/80-09 % 50-567/80-09 on 800602-06 No noncompliance noted Major areas inspected steel structures & supports in containment welding, welding matl control.welder qualification & procedures HERDIA R Region 2. Atlanta. Reactor Construction & Engineering Support Branch CROWLEY, B.R. Region 2. Atlanta, Office of the Director 80/06/20 App
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLYJP Region 2, Atlanta, Office of the Director 80/06/2/ 80/06/24
- 8007230253 Forwards IE Bulletin 80-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also enci No written response required O'REILLY.J P Region 2, Atlanta. Diffice of the Director 80/06/2 80/06/27
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment liner ponetration welds Penetrations at Sequoyah. Watts Dar & Bellefonte contain flued heaf design Design for Yellow Creek not yet completed MILLS.L M Tennessee Valley Authority B0/07/08 5pp
- 9 Reportable occurrences. LERs & related correspondence
- 8007160473 Forwards second interim deficiency rept re const QA audit Next rept will be submitted by 800820 W/o encl MILLS.L M Tennessee Valley Authority 80/07/09 lp
- 8007230255 Part 21 rept re Bristol structural steel framing for control bldg flework of fillet welds is being performed Next rept will be submitted by 800815
 NILLS.L M Tennessee Valley Authority 80/07/09 3pp
- 8007170342 Forwards final deficiency rept re placement of earthfill in ERCW apray pond MILLS.L M Tennessee Valley Authority 80/07/10
- ---8007170344 Final deficiency rept re placement of earthfill in ERCW spray pond GA audit revealed eight items of noncompliance re placement & insp of earthfill Laborers will be assigned to remove all visible unsuitable math during fill placement # Tennessee Valley Authority 80/07/10 4pp
- 8007170356 Forwards final deficiency rept re const QA audit MILLS.L M Tennesses Valley Authority 80/07/10 ip
- ~8007170358 Final deficiency rept re const OA audit Concrete piacement evaluated & found acceptable Inspectors instructed in requirements of general const spec # Tennessee Valloy Authority 80/07/10 ip
- 8007180659 Forwards revised final deficiency rept re placement of earthfill in essential raw cooling water spray pond MILLS.L M Tennessee Valley Authority 80/07/11 1p
- --8007150663 Revised final deficiency rept re placement of earthfill in essential raw cooling water spray pond Insufficiently compacted math was removed & replacement fill recompacted Util will use penetrometer tests for fill operations # Tennessee Valley Authority 80/07/14, App
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007310537 Confirms 800701 telcon re placement of earthfill in ERCW spray pond Concurs in resumption of earthfill placement, based on final rept in util 800711 ltr O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/1 80/06/14

- 8007230001 Forwards -tatement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & Found in NUREG-0694
 - EISENHUT. D C Division of Licensing 80/06/26 2pp

& Adjudicatory correspondence

- BD07310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for olectrical cables EISENHUT, D C Division of Licensing 80/06/25 89pp
- H General correspondence
- B007300013 Responds to 770405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kemeny Commission Rept encl DENTON: HR Office of Nuclear Reactor Regulation, Director E0/04/26 28pp
- 8007220027 Responds to DO Jourdan 800028 ltr to J Schlesinger. Regulations require that extensive studies be performed to show that proposed plants will not undanger health & safety DENTON:H R Office of Nuclear Reactor Regulation, Director 2pp 80/07/01
- --8007220030 Forwards DQ Jourdan 800328 ltr for consideration. KENDRICK: H Energy, Dept of 80/06/03 3pp
- Q Inspection reports. IE Builetins & correspondence
- BOO7240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueiing Mode " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. BQ/05/08. Зрр
- 8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director, B B0/05/28
- B007010225 Forwards IE Info Notico 80~23, "Loss of Buction to Emergency Faedwater Pumps " No written response required D'REILLY. J P Region 2. Atlanta. Office of the Director B0/05/29
- BOO7150447 Forwards IE lnsp Repts 50-546/80-08 & 50-367/80-08 on BOO513-16 No noncompliance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch BO/06/05 2pp
- --8007150452 IE Insp Repts 50-566/80-08 & 50-567/80-08 on 800513-16.No noncompliance noted Major areas inspected licenses identified items, insp foilowup item, warshouse storage & abservation of safety-related concrete activities THOMASH M Region 2, Atlanta, Office of the Director CANTRELL, F B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/04 App
- 8007220029 Forwards 1E Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/06/10
- 8007160287 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007280384 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 55(e) " No written response required, G'REILLY. J P Region 2, Atlanta, Office of the Director. 80/06/13.
- 8007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20,
- 8007290422 Forwards IE Insp Repts 50-566/80-09 % 50-567/80-09 on 800602-06 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp

- --B007290432 IE Insp Repts 30-356/B0-09 & 50-367/B0-09 on B00602-06
 No noncompliance noted Major areas inspected steel
 structures & supports in containment welding, welding matl
 cuntrol, welder qualification & procedures
 HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch CROWLEY, B R Region 2, Atlanta, Office of the
 Director 80/06/20 App
- 6007170070 Forwards IE Circular 80-14, "Redipactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24
- B007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters Whitten response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlenta, Office of the Director B0/06/27 is.
- 8007210036 Forwards response to IE Builetin 80-08 re-examination of containment liner penetration weids Penetrations at Bequoyah. Watts Bar & Bellefonte contain fixed head design Design for Yeilow Creek not yet completed MILLS.L M Tennessee Valley Authority 80/07/08 Spp
- 8 Reportable occurrences, LERs & related correspondence
- B007160473 Forwards second interim deficiency rept re const GA audit. Next rept will be submitted by 600820 M/o encl MILLS.L.M. Tennessee Vailey Authority 60/07/09 ip
- B007230255 Part 2: rept to Bristoi structural steel framing for control bldg Rework of fillet welds is being performed Next rept will be submitted by B00815 MILLS.L M Tennessee Valley Authority B0/07/09 3pp
- B007170342 Forwards final deficioncy rept re placement of earthfill in ERCW spray pond
 MILLS,L.M Tennesses Valley Authority 80/07/10 ip
- --B007170344 Final deficiency rept re placement of earthfili in ERCW spray pond GA audit revealed eight items of noncompliance re placement & insp of earthfill.Leborers will be assigned to remove all visible unsuitable mati during fili placement a Tennessee Valley Authority 80/07/10. 4pp
- 8007170356 Forwards final deficiency rept re const QA audit MILLS.L.M Tennessee Valley Authority 80/07/10 ip
- --9007i70358 Final deficiency rept re const QA audit Concrete placement evaluated & found acceptable Inspectors instructed in requirements of general const spec.

 # Tennessee Valley Authority 80/07/10 1p

DOCKET STN-50-568 NEP NUCLEAR, UNIT 1

- A. Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0550 & found in NARGO-0574 EISENHUT, D Q Division of Licensing 60/05/25 2pp

DOCKET BTN-50-569 NEP NUCLEAR, UNIT 2

- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NURES-0660 & found in NARES-0694 EIBENNUT.D.Q Division of Licensing 80/06/26 2pp

DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674
 EISENBUT, D 0. Division of Licensing BO/06/26 2pp

- DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of palicy me requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-06694
 EISENHUT, D C Division of Licensing BD/06/26 2pp

DOCKET 50-582 SUNDESERT. UNIT 1

- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of pulicy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-06694
 EISENHUI, D. Q. Division of Licensing 80/06/26 2pp

DOCKET 50-583 SUNDESERT, UNIT 2

- A Application/construction stage decuments & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 E18ENHUT.D 9 Division of Licensing 80/06/26 2pp

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications.as derived from NUREQ-0650 & found in NUREQ-06594
 E1BENHUT.D Q Division of Licensing 80/06/26 2pp
- H General correspondence
- 8007i10526 Responds to 800409 itr to R Ryan Each unit will include separate fuel bidg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR, Section 9 i BCHWENCER, A Licensing Branch 2 80/06/26 App
- DOCKET BIN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5
- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D 9 Division of Licensing BO/06/26 2pp
- H General correspondence
- BOO7110526 Responds to BOO409 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR, Section 9 1 SCHMENCER, A Licensing Oranch 2 BO/06/26 App

DOCKET 50-594 KO-R1. UNITS 3 & 4

- A Application/construction stage documents & correspondence
- 8007280479 Requests license to export steam generator components to Bouth Korea HESS-R J Wastinghouse Electric Corp 80/07/15 2pp
- --8007280487 Advises that amend request should remain active Vandor is applying for separate components license rather than waiting for amend approval HEMBY.E Q DFFice of international Programs. Director 80/07/15 in.
- --8007280495 Submits application to amend license to add intermediate contigned
 HESS,R J Westinghouse Cleatric Corp 80/04/10 ip

DOCKET STN-50-596 NEW HAVEN, UNIT 1

A Application/construction stage documents & correspondence

B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0460 & found in NUREG-04694
EISENHUT, D G Division of Licensing 80/06/26 2pp

DOCKET STN-50-597 NEW HAVEN, UNIT 2

A Application/construction stage documents & correspondence

B007230001 Forwards statement of policy re requirements to be met for turrent OL applications, as derived from NUREG-0660 & found in NUREG-0574

EISENHUT, D G Division of Licensing B0/06/26 2p

DOCKET 90-999 CARROLL FACILITY I

C Utility Environmental Report (ER), amends & correspondence

B007140627 Forwards affidavit of svc for distribution of site suitability environ rept. Revision 3. Buppl 2. in response to NRC 790404 request NAUONTON. W F Commonwealth Edison Co B0/05/23 2pp

G Adjudicatory correspondence

8007010131 Request for extension until 800710 to file brief in opposition to Catizens Against Nuclear Power & E Gogol 800812 notice of appeal from ASLB 800802 memorandum & order NRC was involved in other adjudication W/Certificate of Svc. GOLDBERG.S C Hearing Branch 2 80/06/27 4pp

B007020462 Brief in opposition to Citizens Against Nuclear Power et al appeal from ASLO 800330 order re denial of Contentions 1.2.
4-11 & 13 Early site review need not include full review required under NEPA H/contentions & Certificate of Svc HILLER,M I . BIELAMSKI,A P Commonwealth Edison Co HILLER,M I Isham. Lincoln & Deale 80/06/27 26pp

8007100244 Request for extension until 800718 to file brief in opposition to Citizens Against Nuclear Power, J Runyon & E Ougol 800617 appeal from ASLB 800830 memorandum & order recontentions Winotice of appearance & Certificate of Syc JONES, B W Hearing Branch 2 80/07/09 5pp

BO07220110 Brief in opposition to Citizens Against Nuclear Power, J Bunyon & E Gogol BO0612 notice of appeal from ASLB B00530 memorandum & order denying intervention Argument re EIS constitutes impermissible challenge to NRC regulations GOLDBERG.S C . JONES.B W Hearing Branch & B0/07/18 27pp

--8007220121 Summarizes veius on early site reviou proposed regulations Supports idea in general but opposes application to reprocessing facilities & expresses concerns re certain technical issues Certificate of Svc encl SPETH.0 Council on Environmental Quality 77/04/27 Spp

DDCKET 50~600 CARROLL FACILITY II

C Utility Environmental Report (ER), amends & correspondence

B007160627 Forwards affidavit of svc for distribution of site suitability environ rapt, Revision 3, Suppl 2, in response to NRC 790404 request NAUCHTON, W F Commonwealth Edison Co 80/05/23 2pp

G Adjudicatory correspondence

8007010131 Request for extension until B00710 to file brief in apposition to Citizens Against Nuclear Power & E Gogol B00612 notice of appoal from ASLB 800530 memorandum & order NRC was involved in other adjudication W/Certificate of Svc GOLDBERG, S C Hearing Branch 2 80/06/27 App

8007020462 Brief in opposition to Citizens Against Nuclear Power et al appeal from ASLB 800530 profer re denial of Contentions 1.2.
4-11 & 13 Early site review need not include full review required under NEPA W/contentions & Certificate of Svc MILLER.M I . DIELAWSKI, A P Commonwealth Edison Co MILLER.M 1 isham. Lincoln & Beale 80/06/27 26pp

8007100244 Request for extension until 800718 to file brief in opposition to Citizens Ageinst Nuclear Power, J Runyon & E Ougol 800612 appeal from ASLB 800930 memorandum & order recontentions W/notice of appearance & Certificate of Svc JONES.B W Hearing Branch 2 80/07/09 5pp

BOO7220110 Brisf in opposition to Citizens Against Nuclear Power, J Runyon & E Oogol BOO612 notice of appeal from ASLB BO0530 memorandum & order denying intervention Argument to EIS constitutes impermissible challenge to NRC regulations QDLDBERO, & C. JONES, B. H. Hearing Branch 2 80/07/18 27pp

---8007220121 Summarizes veiws on early site review proposed regulations
Supports idea in general but opposes application to
reprocessing facilities & expresses concerns re certain
tachnical issues Cortificate of Svc enc!

SPETH. © Council on Environmental Quality 77/04/27 5pp

DUCKET 50-754 GENERAL ELECTRIC TEST REACTOR

Q Adjudicatory correspondence

BOD7020468 Forwards May 1780 safety evaluation re GETR SWANSON, D T Hearing Branch 1 80/06/27 1p

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

BO07140035 Forwards IE Insp Repts 70-0008/80-01 & 30-05728/80-01 on 800422-24 No noncompliance noted DAVIB, A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/03 2pp

--8007140041 IE Insp Repts 70-0008/80-01 & 30-05728/80-01 on 800422-24. No noncompliance noted Major areas inspected organization, operations review. Facility changes & mods, safety committees & internal & external exposure control FISHER.W L. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/02 6pp

BOO7170609 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required MEPPLER, J G Region 3, Chicago, Défice of the Director, 80/06/24 to.

8007180502 Notifies of fee required for review of 791218 request for route approval for shipment of Monticello spent fuel MILLER.W D License Fee Management Branch 80/07/02 tp

8007250049 Forwards 800402 for request for NRC review of physical protection plan for SNM of moderate & low strategic significance Fayment is requested within 15 days M/o encl. WEISS, D License Fee Management Branch 80/07/16 1p

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

8007030005 Forwards 1E Bulletin 80-15, "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power." Written response required. ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/18 ip

80073i0342 Forwards revised pages to 800507 increment of analysis of effects of natural phenomena & environmental character surrounding plant Revisions include significant changes in demography & minor changes in dispersion meteorology ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/06/18

8007180281 Forwards IE Circular 80~14, "Radioactive Contamination of Plant Demineralized Water Sqs & Resultant Internal Contamination of Personnel " No written response required ENDELMEN.R H Region 5, San Francisco, Office of the Director 80/06/24 1p

8007240475 Forwards IE Insp Rept 70-0025/80-07 on 800630-0702 of activities under License SNM-21 No noncompliance noted Heyor areas inspected physical protection against industrial sabotage Encl withheld (ref 10CfR2 790) NDRDERHAUD, R Region 5, San Francisco, Safeguards Branch, 80/07/10 1p

- B007250580 Responds to B00612 request for reconsideration of amend fee submitted for NRC review of B00519 physical security plan Plan will require major amend to License 5NM-21 Therefore, NRC fee assessment is justified MILLER.W O License Fee Management Branch B0/07/11 2pp
- --8007250988 Forwards safeguards amend fee for NRC review of physical security plan Requests reconsideration of fee Licensee submitted plan in response to regulatory requirement & was not applying to amend License SNM-21 REMLEY. M. E. Rockwell International Corp., Energy Systems Div 80/06/12 in
- 8007310452 Amends License SNH-21. Section 9 0 by correcting administrative errors in License Condition 9 A 1 A & adding B00314 page change to security plan Approves 800314 request to use specific type of shotgun at facility MCCORKLE. 0 W Physical Security Licensing Branch 80/07/16 1p
- BOO7310475 Forwards request for addl info & revisions to E90-80-17, "Physical Security Plan for Protection of Moderate Strategic Quantities 'of SNM at Hot Labs of Energy Sys Group of Rockwell Intl " Encl withheld (ref 10CFR2,790) MCGORKLE, O W Physical Security Licensing Branch 80/07/16 ip

DOCKET 70-0027 BABCOCK & WILCOX CO

- 8007020337 Forwards revised application for amend to License SNM-42, replacing 790831 application All refs to alloy shop pickle operations have been deleted.

 CDRDANIR A Babcock & Hilcox Co . Naval Nuclear Fuel Div 80/05/30 ip
- --B007020358 Replaces 790B31 ltr by forwarding Revision 4 to License SNM-42 Revision deletes night shift mgt audit incorporates conditions during power outage & changes emergency pian Fea encl.

 CORDANI, R A Babcock & Wilcox Co , Naval Nuclear Fuel Div B0/09/30 4on
- --B007020365 Application for amend to License SNM-42, deleting night shift mgt audit incorporating conditions during power outage & changing emergency plan as noted * Babcock & Wilcox Co., Naval Nuclear Fuel Div 80/05/30 App
- B007280220 Discusses IE insp of License SNM-42 on 800513-16 & forwards IE Insp Rept 70-0027/80-07 KENNA-W B Region 2, Atlanta, Safeguards Branch 80/06/03 2pp
- --B007280223 IE Insp Rept 70-0027/80-07 on B00313-16 No noncompliance noted Major areas inspected operations, organization, facility changes & mods, internal audits & followup of previously identified items
 CONYELL, 0 P Region 2, Atlanta, Office of the Director KAHLE, J B Region 2, Atlanta, Bafeguards Branch 80/06/03 5pp
- 8007020721 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Ragion 2. Atlanta, Office of the Director 80/06/18
- 8007170149 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 ip.
- 8007240119 Amend 11 to License SNM-42, authorizing deletion of night shift manager audit, Audible alarm requirement exemption request denied FAGE, R. Q. Uranium Fuel Licensing Branch 80/07/01 ip
- --8007240125 Discusses review of 800530 license emend application.
 Recommends deletion of night shift mgt audit requirement
 Denies exemption from audible alarm requirements under
 postulated conditions.
 KETZLACH,N , CROW,H T Uranium Fuel Licensing Branch 80/07/01
- 8007210097 Notifies that 791109 request for route approval involving spent fuel shipment to Nuclear Engineering Co in Hanford Works, MA is subj to license fee schedule Review completed on 800326 MILLERIN D License Fee Management Branch 80/07/03 ip

- 8007250648 Forwards revised NUREG-0561 amending interim rule for physical protection of spent fuel in transit Addl areas have been designated as heavily populated Routes approved for BM encl New requirements apply 800703 W/o encl NCCORKLE.G W Physical Security Liconsing Branch 80/07/03 ip
- 8007250053 Requests notification of approx meeting date to discuss status of possible scrap recovery contract between NRC & facilities NRC has proposed Aug or Sept 1980 meeting date in Silver Spring, MD PARTLOW, J O Material Control Licensing Branch 80/07/15 ip

DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

- 800707004B Forwards page changes to fundamental nuclear mati control plan Changes include organizational revisions, NRC review recommendations & current operational procedures Changes withheld (ref 10CFR2 790)

 BCHWENSFEIR,R Toxas Instruments, Inc 80/05/27 2pp
- 8007030389 Recommends approval of page changes to fundamental nuclear matl control plan submitted 79:126,800227 & 0527 License Conditions 1 i.2 3,3 1,3 1 i.3 2,6 3 & 8 1 should be deleted Ltr to vendor & amend enci HUFF,D Material Control Licensing Branch 80/04/13 ip
- --8007030395 Amend MPP-1 to License SNM-23 permitting use of shipper values for U-308 receipts Licensee shall report all intentional distards & matl unaccounted for on monthly basis

 * Material Control Licensing Branch 80/04/16 3pp
- 8007020625 Forwards IE Bulletin BO-15. "Possible Loss of Emergency Notification Sys (ENS) W/Lows of Offsite Power " Written response required ORIER, B H Region 1. Philadelphia, Office of the Director BO/06/18 ip
- 8007160842 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER.8 H Region 1. Philadelphia. Office of the Director 80/06/24 ip
- 8007210167 Ack receipt of 800612 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 70-0033/80-06 BMITH, Q H Region i, Philadelphia Fuel Facility & Materials Safety Branch 80/06/24 lp
- --8007210175 Responds to NRC 800522 itr re violations noted in IE Insp Rept 70-0033/80-04 Corrective actions route card for metal drums revised to show drums are approved only for contaminated metal waste SCHMENSFEIR, R Texas Instruments, Inc. 80/06/12 2pp
- --8007210180 Forwards IE Insp Rept 70-0033/80-06 on 800421-25 & notice of violation SMITH.0 H Region 1. Philadelphia, Fue) Facility & Materials Safety Branch 80/05/22 2pp
- --80072j0i84 Notice of violation from insp on 800421-25 * Region 1. Philadelphia, Office of the Director 80/05/22 1p
- --8007210195 IE insp Rept 70-0033/80-06 on 800491-25 Noncompliance noted failure to foilow posted max safe quality at work station KINNEY, W H Region i, Philadelphia, Office of the Director CROCKER, H H Region I, Philadelphia, Fuel Facility & Materials Bafety Branch 80/05/22 9pp
- 8007210098 Requests payment of administrative amond fee in connection W/800618 request for delay in submitting safeguards plan WEISS, J D License Fee Management Branch 80/07/09 ip
- 8007220527 Advises that requirements for IE Bulletin 80-i5, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power" have been completed SHERMAN.F L. Tecns Instruments, Inc. B0/07/16 Spp
- 8007250445 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power" Bulletin requirements have been completed Phone operating on emergency power was successfully tested w/NRC on 800716 SHERMAN, F L lexas Instruments, Inc. 80/07/21 3pp

- DOCKET 70-0036 COMBUSTION ENGINEERING, INC.
- 8007170519 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Damineralized Hater Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/06/24

DOCKET 70-0135 BARCOCK & WILCOX CO

- B007140644 Forwards IE Insp Rept 70-0135/80-08 & 70-364/80-07 on B00303-28 No noncompliance noted MARTIN, N C Region i, Philadelphia, Safeguards Branch 80/05/21 2an
- -8007140448 IE Insp Repts 70-0135/80-08 & 70-0364/80-07 on 800303-28 No noncompliance noted Major areas inspected mot! control & accounting, physical security, health & industrial safety Info withheld (ref 10CFR2 790) JOYNER, J. H., KUSHNER, N. L. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/08 9pp
- B007020002 Ack receipt of B00512 ltr informing NRC of steps taten to satisfy commitment made per IE lnsp Rapts 70-0135/80-09 & 70-0346/80-08 MARTIN.W. & Region 1. Philadelphie, Safeguards Branch B0/05/28
- --8007020005 Confirms action taken to implement commitment made per IE Insp Repts 70-0135/80-09 & 70-0364/80-08 Corrective actions revised low entitled U physical Inventory to incorporate commitment to remeasure each uranyl nitrate tank AUSTIN.M A. Babcock & Wilcox Co., Nuclear Material Div. 80/05/12

- 8007170522 Forwards IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on 800505-09.No noncompliance noted MARTIN.N.O Region i. Philadelphia, Safeguards Branch 80/05/28 Zpp.
- --B007170630 IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on 800505-09
 No noncompliance noted Hajor areas inspected physical
 inventory & internal controls Details withheld
 (ref 10CFR2.790)
 BISSETT.P H. JGYNER, J H. Region i. Philadelphia. Office of the
 Director 80/05/27 ip.
- 8007140398 Responds to 800116 ltr requesting exemption from 10CFR73 requirements Applicability of regulation should be determined for various types of BNN waste & appropriate application should be made MCCORKLE.G W. Physical Security Licensing Branch 80/06/12 2pp
- BO07220211 Forwards Amend 8 to License SNM-145, revising Spec 1-4 (organization) & Spec 1-5 (Tech Specs & contro) sys) of conditions section of application FAOE, R. O Uranium Fuel Licensing Branch 80/06/23 2pp

- BOO7:70632 Responds to 800625 ltr to request for extension to complete requirements of 10CFR/0 51 for low entriched U mail balance period ending 800611 Licensee shall complete mail balance by BOO725
 PARTLOH J 0 Material Control Licensing Granch 80/07/03 ip
- BOO71BO372 Ack receipt of BOO625 itr requesting amend to License SNM-145 Approval was granted on BOO703 Amend requires administrative fee WEISS.D. License Fee Management Branch 80/07/08 ip
- DOCKET 70-0143 NUCLEAR FUEL SIRVICES, INC.
- 8007170620 Appoints WJ Direks to coordinate personnel to evaluate MUF discrepancy at facility R Burnett will supervise NRC personnel at site Requests advisement of any resource problems to administrative k/or personnel support QUSSICKLE V Office of the Executive Director for Operations 79/09/18 10
- 8003250864 Discusses 800205-07 site visit to assess effectiveness of new process monitoring requirements Due to incomplete feedstack dissolution, ii of 15 dissolution batches alarmed Further review will be made duiling 800225 site visit JOY.D R ?taterial Control Licensing Bianch 80/03/03 ip
- BOO7110006 FOIA request for 11 documents concerning facility
 COCHRAN.T B Natural Resources Defense Council 80/04/10 2pp
- 8007140513 Forwards 1E Insp Rept 70-0143/80-12 on 800317-0424 KENNA.W 8 Region 2 Atlanta, Safeguards Branch 80/05/16 2pp
- --8007140527 IE Insp Rept 70-0143/80-12 on 800317-0424 No noncompliance noted Major areas inspected physical inventory observations & verification Dotails withheld (rof 10CTR2 790) CLAY.E.L., GILLESPIE:FP Region 2, Atlanta, Safeguards Branch HODGES, J.W. Region 2, Atlanta, Office of the Director 80/05/15
- BOD7280179 Safety evaluation re NFS proposed remedial actions & other alternatives re soil cantamination Recommends contaminated Danner Bpring Branch stream bed be fenced until final action at decommissioning CROW.W T . SHUM, E V Uranium Fuel Licensing Branch BO/06/06 13po
- ---8007280184 Forwards "Investigation Progress Rept of Soil Contamination (Former Creek Bod) at NFS-Erwin " HICHEL.C J Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/02/04 ip
- --8007280187 "Investigation Progress Rept of Soil Contamination (Former Creek Bed) at NFS-Erwin " * Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/01/31
- BOO7250376 Disapproves of ducision reached by NRC re continued operations of NFB facility Due to labor conflict & licensing violations, facility operated less than six months during 1979 Quality production important in such facility SHERBONDY, B.N. Affiliation Unknown 80/06/10 3pp
- B007010105 Ack receipt of 800514 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0140/80-08 KENNA.W B Region 2, Atlanta, Safeguards Branch 80/06/11 ip
- --8007010109 Responds to NRC 800428 ltr re violations noted in 1E Insp. Rept 70-0143/80-08 Corrective actions withhold (ref. 10CFR2 790)

 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Gotty 011 Co. 1. 80/05/14 1p
- --B007010117 Forwards IE Insp Rept 70-0143/80-08 on B00311-14 & notice of Violation Notice of Violation withheld (ref 10CFR2 790)
 KENNA.W II Region 2, Atlanta, Safeguards Dranch 80/04/28 2pp
- ~=8007010125 IE Insp Rept 70-0113/R0-08 on 800311-14 Noncompliance noted failure to follow procedures Details withheld (ref 10CFR2 790)
 PERNY, C D , QILLESPIE.F P Region 2. Atlanta, Safeguards Dranch 80/04/28 in
- 8007010221 Responds to 800603 request for change in mot1 balance area structure re Plant 11 Change is acceptable Lirense Condition 2.6 is added to Amend MPP-1 of License SNM-124 PARTLOW, JO Material Control Licensing Branch 80/06/17 ip

- B007030292 Act receipt of IE Insp Rept 70-0143/80-15 No proprietary info MANSER, N C Nuclear Fuel Bervices, Inc (subs of Getty Dil Co) B0/06/17 ip
- --8007030293 Forwards IE Insp Rept 70-0143/80-15 on 800513-16 No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguerds Branch 80/06/03 2pp
- BOO7020729 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power "Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007180555 Forwards Revision 14 to fundamental nuclear mati control plan.Ltr & revision withheld (ref 10CFR2 790)
 HENSLEY.K D Nuclear Fuel Services. Inc (subs of Getty Dil Co > 80/06/18 2pp.
- 8007020258 Reports manhours used in reviewing 790828 application for amend of License BNY-124
 DELANEY.J.C. Uranium Fuel Licensing Branch 80/06/19 ip
- 8007020304 Reports manhours used in reviewing 790330 application for each of License SMN-124
 DELANEY.J.C Uranium Fuel Licensing Branch 80/06/19 1p
- 8007070010 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 70-0143/80-04 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/19 is.
- --8007070014 Responds to NRC 600416 Itr re violations noted in IE Insp Rept 70-0143/80-04. Corrective actions shipments discontinued until program has been established to prevent recurrence of infraction MANSER, N C Nuclear Fuel Services, Inc (subs of Getty Oil Co.) BO/05/09, dpp
- ---B007070015 Forwards IE Insp Rept 70-0143/80-04 on B0022i & notice of violation STOMRJ P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/04/16 2pp
- --8007070017 Notice of violation from insp on 800221 * Region 2, Atlanta, Office of the Director 80/04/16 2pp
- ---B007070019 IE Insp Rept 70-0143/B0-04 on 800221 Noncompliance noted failure to transfer BNM in accordance w/terms & conditions of recipient radioactive mat1 license & to adequately survey package prior to shipment & transfer.

 DAVIS.J H Region 2. Atlanta, Office of the Director GIBGON, A FREGION 2. Atlanta, Fuel Facility & Haterials Bafety Branch B0/04/14 Spp.
- 8007140078 Forwards 1E Insp Rept 70-0143/80-17 on 800424-0523 No noncompliance noted KENNA, N.B. Region 2, Atlanta, Safeguards Branch 80/04/24, ip.
- --B007i40086 IE Insp Rept 70-0143/80-17 on 800424-0523 No noncompliance noted Major areas inspected contributors to cumulative inventory differences & worker concerns Details withheld (ref 10CFR2.790).

 LEE.T.D., JONES.D.W. Region 2, Atlanta, Office of the Director. OILLEBPIE.F.P. Region 2, Atlanta, Safeguards Branch 80/06/24.
- BOO7150552 Discusses Commission order allowing resumption of operation w/relexed conditions & granting post-hearing alternative for which NRDC responded w/o Commission subsequent action Urges that willtany function exception not be invoked WEISS,E R Sheldon, Harmon & Weiss 80/06/24 2pp
- 8007170134 Forwards IE Circular 80-14, "Radioective Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/24 1p.
- 8007140038 Ack receipt of 800603 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-14 , KENNA:H.B Region 2, Atlanta. Bafeguards Branch 80/06/23 ip

- ---B007140064 Responds to NRC B00514 ltr reviolations noted in 1E Insp. Rept 70-0143/80-14 Corrective actions withheld (ref. 10CFR2 790)

 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). B0/06/03 1p
- --B007140047 Forwards IE Insp Rept 70-0143/B0-14 on B00422-23 & notice of violation Notice of violation withheld (ref 10CFR2 790)

 KENNA.W B Region 2. Atlanta, Safeguards Branch B0/05/14 2pp
- --B007i40073 IE Insp Rept 70-0143/80-14 on 800422-25 Noncompliance noted failure to notify NRC of change made to matl control & accounting program within 2 months of change Details withheld (ref joCRE 770)

 BATES.J W Region 2, Atlanta. Office of the Director OILLESPIE,F P Region 2, Atlanta, Safeguards Branch 80/05/14 io
- 8007110584 Grants 800613 request, w/NRC mods, for delay in determining U inventory difference value re 800527 highly enriched U physical inventory of Plant 1 Conditions added to Amend MPP-1 of License SNM-124
 BURNETT/R F Division of Safeguards 80/06/26 2pp
- 8007020637 Forwards process monitoring charts which provide summary required by NRC 800626 Itr Enci withheld (ref 10CFR2 790) MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/06/27 ip
- B007020445 Note forwarding corrected version of Commission 800626 memorandum & order, CLI-80-27 & Commission 800627 notice of hearing in License SNM-124 proceeding # Docketing & Services Branch B0/06/27 ip
- ~-8007020547 Corrected memorandum & order.CLI-80-27, granting NRDC 800205 request for hearing ro whother License SNM-124 should be revoked Contemplates informal procedural framework due to sensitive military issues re weapons enriched w/U CHILK.8 J Office of the Socretary of the Commission 80/05/25
- --8007020556 Corrected notice of legislative hearing in response to NRDC 800206 requestive revocation of License SNM-124 Written factual 4 legal testimony due by 800701 suggestions by 800715 Oral argument scheduled for 801015-1101 CHILK S J Office of the Secretary of the Commission 80/06/27 408
- --8007020660 "Amend to Rules of General Applicability Providing Exception from Protedues for Adjudications re Conduct of Military or Foreign Affairs Functions." IOCFR2 immediately offertive final rule Permits more flexible due process limits CHILK.8 J Office of the Secretary of the Commission 80/06/26
- 8007070333 Forwards NFS QA program re shipping packages for radioactive matl per 800424 request MICHEL.C J Nuclear Fuel Services. Inc (subs of Getty Qil Co) 80/06/27 ip
- --8007070335 GA program for shipping packages for redicective matl

 * Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/06/13.
 21nc
- 8007100008 Add1 response to FOIA request for documents re licensing of facility & transcripts of closed Commission meetings App A documents available in FDR Document 1 of App B & portions of Documents 2-21 withheld (ref FOIA Exemptions 3.4 & 5) FELTON.J M Division of Rules and Records 80/06/27 5pp
- --B007100015 Discusses application of inventory difference regression equation to Aug inventory Info withheld procedures for safeguarding nuclear matl & NRC prodectional advice, opinions & recommendations (ref FOIA Exemptions 4 & 5) MESSINGER, M Haterial Control & Accountability Development Branch 79/09/26
- ---B007100020 Summary of B00102-03 meeting between util & NRC in Silver Spring,MD to MCA license conditions applicable for resumed highly enriched U operations info partially withheld (ref FOIA Exemptions 4 & 5) Charts encl JQY,D Material Control Licensing Branch B0/01/10 1p
- ---B007100023 Forwards matl balances opvering inventory for 790Bi4-1004
 Info withheld safeguards & security measures (ref FdIA
 Exemptions 3 & 4)
 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Gil Co)
 79/12/05 5pp

- --8007100028 Forwards debailed rept on current t planned projects designed to improve facility accountability sys & associated inventory difference results Rept withheld (ref FOIA Exemptions 3 & 4)
 TAYLOR C W Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.)
 7971023 | p
- --B007100032 Discusses SECY-77-650A. "NRC Regulation of Highly Enriched U Operations at Facility " Lists add1 requirements needed if position taken by JF Ahearne in B00109 memo is adopted Info partially withheld (ref FDIA Exomption 3)
 HANRAHAN.E J Material Control Licensing Branch 60/01/11 2pp
- --B007100038 Sunmary of Commission 800114 meeting re SECY-79-650 & SECY-79-650A concerning facility Scope & quality of matl control & accounting elements would be improved Summarizes proposed actions Info partially withheld (ref FOIA Exemption 3) HANRAHAN.E J Material Control Licensing Branch 80/01/15 2pp
- --8007100044 Discusses 791004 inventory difference of high enriched U exceeding limit of error constraint Forwards rept detailing causes contributing to inventory differences & corrective actions taken Rept withheld (ref FOIA Exemption 3) TAYLOR.C W Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 79/11/02 2pp
- --B007100052 Forwards comments on J9 Partlow 790525 ltr to KD Hensley Info withheld safeguards & security measures (ref FDIA Exemption 3) HENSLEY,K D Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 79/07/06 3pp
- --8007100057 Submits list of recont mods at facility which upgraded matl accountability & control program Info withheld procedures for safeguarding licensed SNM (ref FOLA Exemption 4)

 JOY.D R Material Control Licensing Branch 79/09/ii 2pp
- --B007100069 Forwards and status rept re 790B14 Inventory differences of highly enriched U exceeding limit of error constraint Info withheld procedures for safeguarding nuclear matl (ref FDIA Exemption 4)
 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Gil Co) 79710/02 3pp
- --B00710007& Notifies of 790816 meeting w/util to discuss highly enriched U inventory difference past, present & Future Forwards listing of topics re inventory differences which will be included in discussions W/o encl

 ENITHEON Hearing Branch 2 79/08/01 to
- --BOD7100072 Summary of 790B16 meeting between util & NRC in Bethesda.MD re concerns of highly enriched U inventory difference behavior inventory difference is licensee problem info partially withheld (ref FOIA Exemption 5)
 UOY.D Material Control Licensing Branch 79/0B/21 2pp
- --8007100081 Summary of 790816 meeting w/util Lists major util concerns including amproving of accounting sys Majority of meeting spent on reporting status of NRC questions info partially withhold (ref FGIA Exemption 5)
 PARTLOW.J G Material Control Licensing Branch 79/08/17 2pp
- 8007110004 Responds to FOIA request for 11 documents concerning facility Items 2.3 & 5-10 have been addressed in earlier NRC responses Attachment II of Document 11 withheld (ref FOIA Exemption 4 & 10CFR2 790)
 FELTON.J M Division of Rulos and Records 80/06/27 2pp
- ---8007110007 New & revised conditions to Amend MPP-1 to License SNM-124 * Commission 80/01/21 11pp
- BO07160B3B Ack receipt of B00603 % ii ltrs informing NRC of steps taken in response to concerns noted in 1E Insp Repts 70-0143/79-49 & 70-0143/B0-12 KENNA. H D Region 2, Atlanta. Safeguards Branch 80/06/27 ip
- ~-8007160843 Requests 60-day extension to respond to concerns identified in IE Insp Rept 70-0143/79-49
 MANSER,W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 80/04/08 | Ip
- B007070191 Requests that Attachment A of Insp Rept 70-0149/B0-01 be withheld (ref 10LFR2 790) MANIER W C Nuclear Fuel Services. Inc (subs of Getty Oil Co) B0/06/30 2pp
- 8007070350 Responds to request for info me contamination control program in SNM-0124, Amend 5 Provides revised personnel exit procedures & personnel surveys
 MANSER, W C Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)
 80/06/30 2pp

111

- BOO7150963 Forwards site security training plan, Revision 1 Changes make corrections on site-specific implementation & do not lessen effectiveness of site security training or physical protection plan Revision I withheld (ref 10CFR2 790) MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Dil Co) BO/07/01 ip
- BOO7210039 Notifies that fee submitted w/790330 application for Amend 5 to License SNM-124 will be partially refunded in accordance w/manpower expenditures review MILLER.W D License Fee Hanagement Branch 80/07/01 lp
- BOO71BO30B Ferwards 1E lnsp Rept 70-0143/80-19 on BOO616-19 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA,H B Region 2, Atlanta, Sefeguerds Branch BO/07/07 2pp
- --B007180316 IE lnsp Rept 70-0143/80-19 on 800616-19 Noncompliance noted failure to annually recertify one new std in each NDA series & failure to make process & engineering studies Details withheld (ref 10CFR2 790)

 DATES, J W Region 2, Atlanta, Office of the Director GILLESPIE, F P Region 2, Atlanta, Safeguards Dranch 80/07/03 ln
- BOO7150518 Forwards rovised Page 137 to Amend Request 78-5 submitted 780827 & resubmitted as Amend Request 80-1 on 800124 Amend can be issued welexamption from License SNM-124 Condition 29 requested on 791107 MICHEL.C.J Nuclear Fuel Sorvices, Inc (subs of Getty Gil Co) 80/07/09 2pp
- --8007150520 Requests License SNM-124 be amended to allow transport of enriched V outside confines of plant Shipments will be limited to 5 kg V-235 MICHEL, C F Nuclear Fuel Services, Inc. (subs. of Getty Cil Co.) 78/06/27
- 8007220003 Answer to Commission notice of hearing stating NRC willingness to participate as party Svc may be made on QH Cunningham & RL Fonner on behalf of NRC Certificate of Svc encl
 CUNNINGHAM, G H Regulations Division 80/07/14 2pp
- 8007220243 Add1 response to FOIA request for info concerning facility Nonexempt portions of documents listed in app are located in DC PDR Documents i.2 & 3 partially withheld (ref FOIA Elemptions 4 & 5) Documents 5 & 6 are undergoing review FELTON, J H Division of Rules and Records 80/07/16 3pp
- --800722024B Revised conditions to Amend MPP-1 to License SNM-124 BURNETT.R F Division of Safeguards 80/02/01 3pp
- --8007220251 Discusses 800227-29 site visit to further evaluate effectiveness of new process monitoring license conditions. Info partially withheld (ref FOIA Exemptions 4 & 5) Responses to M Udall questions dtd 800306 encl
 JOY.D R Material Control Licensing Branch 80/03/11 4pp
- 8007290072 Notifies of issuance of Amend 7 to License SNM-124, providing exemption from roquingment that emergency evacuation drill be conducted at least annually for each shift PAGE.R G Uranium Recovery Licensing Branch 80/07/16 ip
- --8007290083 Safety evaluation supporting Amend 7 to License SNM-124 DELANEY.J C Uranium Recovery Licensing Branch CROW.W T Uranium Fuel Licensing Branch 80/07/16 1p
- BOO7300092 Addl response to FOIA request for matl received, considered or approved by Commission during consideration of facility inventory info partially withheld security measures & restricted data (ref FOIA Exemptions 3 & 4)
 FELTON, J M Division of Rules and Records BO/07/16 3p
- --B007300094 Discusses reporting of facility 790818-1004 inventory difference Draft physical protection license conditions and License condition partially withheld safeguarding procedures (rof FOIA Exemption 4) DIRCKS.W J Office of Nuclear Material Safety & Safeguards 79/10/22 2pp
- ---8007300103 Discusses facility inventory difference for 790618-0818 NFB is ceasing all production operations & preparing for plant inventory in accordance w/NNSS orders Info partially withheld restricted data (ref FGIA Exemption 3) DIRCKS, W J Office of Nuclear Material Safety & Safeguards 79/09/17 1p

- 8007280352 Forwards response to NRC 800624 ltr re violations noted in IE Insp Rept 70-0143/80-20 Response withheld (ref locre2 790)
 MANSER, H C Nuclear Fuel Services. Inc (subs of Getty Oil Co) 80/07/18 1p
- BOO7230464 Forwards response to IE Insp Rept 70-0143/80-19 Response withheld (ref 10CFR2 790) MANBER, M C Nuclear Fuel Services, Inc (subs of Oetty Dil Co) 80/07/21 1p
- BO07270713 Responds to NRC 800626 ltr re lE Insp Rept 70-0143/80-13 Attachment states corrective action taken W/o encl MANSER.W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 80/07/21 ip
- 8007290547 Forwards general soil decontamination plan.per 800715 request
 MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Dil Co)
 90/07/25, 4pp

DOCKET 70-0157 TEXAS, UNIV. OF

- 8007210320 Responds to IE Bulletin 79-i9, "Packaging of Low Level Radwaste for Transport & Burial " Wastes are deposited in plastic bag in lined steel containers Waste collection contractor is responsible for ultimate disposal EURACK, J A Texas, Univ of. 79/09/04 2pp
- --B007210324 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial." & list of bulletins issued in last 6 months Requests response to IE Bulletin 79-19 SEYFRIT, K. V Region 4, Dallas, Office of the Director 79/08/10 App.

DOCKET 70-0184 WESTINGHOUSE ELECTRIC CORP

- B007230014 Advises of correct address for future correspondence in response to 800602 ltr Revised radiation safety manual has been forwarded to Matla Licensing Branch KINNEMAN, J D Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/07/02. 1p
- ---8007230015 Forwards revised radiation procedure & safety manual W/q encl SPANGENDERO, C. Westinghouse Electric Corp 80/06/02 1p

DOCKET 70-0203 NOTRE DAME, UNIV OF

- 9007010047 Ack receipt of 800528 ltr informing NRC of steps taken to correct noncompliance identified in 800513 ltr.Discusses licensee Jenial of noncompliance Item 10.81x-month leak test is required Supporting documentation encl KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/09
- ---8007010060 Requests that provision for possession of Pu-baryllium ba removed from License SNM-198 Also requests designation of TJ Hirons as course instructor & only person responsible for handling leak testing, GAY, N. R. Notre Dame. Univ. of 61/12/21 ip

DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO

- 8007150809 Forwards application for amend to License SNM-414, consisting of revised pages to Chapter 3 of license re site & facilities description
 AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/05/09
 20s
- 8007140644 Forwards IE Insp Rept 70-0135/80-0B & 70-364/80-07 on 800303-28, No noncompliance noted MARTIN, W G Region 1, Philadelphia, Safeguards Branch 80/05/2i 2pp.

- --B007140648 IE Insp Repts 70-0135/80-08 % 70-0364/80-07 on 800303-28
 No moncompliance noted Major areas inspected matl control & accounting, physical security, health % industrial safety Info withhold (ref 10CFR2 790)
 JONNER, J. H., KUBHNER, W. L., Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/08 9pp
- B007020002 Ack receipt of 8005i2 ltr informing NRC of steps taken to satisfy commitment made per IE Insp Repts 70-0139/80-09 & 70-0364/80-08 MARTIN,W G Region i, Philadelphia, Safeguards Branch 80/05/28
- --8007020005 Confirms action taken to implement commitment made per IE
 Insp Repts 70-0135/80-09 & 70-0364/80-08 Corrective actions
 revised low enriched U physical inventory to incorporate
 commitment to remeasure each uranyl nitrate tank
 AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 80/05/12
- --8007020008 Forwards 1E Insp Repts 70-0135/80-09 & 70-0344/80-08 on 800317-20 & 24-26 No noncompliance noted MARTIN W 0 Region 1, Philadelphia, Safeguards Branch 80/04/22 200
- --B007020012 IE Insp Repts 70-0139/B0-09 & 70-0364/B0-08 on 800317-20 & 24-26 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10GFR2 790)

 JOYNER, J H Region i, Philadolphia, Safeguards Branch
 HDL0DY, D J Region i, Philadelphia, Office of the Director B0/04/17 ip
- 8007170622 Forwards IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on B00505-09 No noncompliance noted MARTIN.W G Region I, Philadelphia, Safeguards Branch B0/05/20 200
- --B007170430 IE Insp Repts 70-0135/B0-13 & 70-0364/B0-12 on 800505-09 No noncompliance noted Major areas inspected physical inventory & internal controls Details withheld (ref IOCFR2 790) BISSETT, P H , JUNNER, J H Region 1, Philadelphia, Office of the Director 80/05/27 ip
- 800714059B Responds to 800116 ltr requesting exemption from 10CFR73 requirements Applicability of regulation should be determined for various types of SNM waste & appropriate application should be made MCCGRKLE. O W Physical Security Licensing Branch 80/06/12 2pp
- 8007020612 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (CNS) W/Loss of Offsite Power " Written response required GRIERB H Region I, Philadelphia, Diffice of the Director 80/06/18 Ip
- 8007150128 Ack receipt of 800611 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-24 GRIER, B H Region 1, Philadelphia, Office of the Director 800/86/19 lp
- --8007150135 Responds to NRC 800115 ltr re viblations noted in 1E Insp. Rept 70-0364/79-24 Corrective actions justification submitted re noncompliance AUSTIN,M A Babcock & Hilcox Co , Nuclear Material Div 80/06/ii
- --B007150141 Ack receipt of 791203 ltr informing of corrective actions taken re IE Insp Rept 70-0364/79-24 Requests written statement re Item B including corrective stops taken & date when full compliance will be achieved GRIER, B. H. Region 1. Philadelphia, Office of the Director B0/01/15 2pp
- --B007150148 Provides specific responses & corrective actions redisclosed items resulting from IE Insp 70-0364/79-24 on 790924-28 Routine surveys of Nuclear Matls & Mfg Div vault area being performed & cited organizational changes begun AUSTIN, M A Babcock & Hilcox Co , Nuclear Material Div 79/12/03 400
- --B007150100 Forwards IE Insp Rept 70-0364/79-24 on 790924-28 & netice violation
 ShiTh,O H Region 1, Philadelphia, Fuel Facility & Materials |
 Bafety Branch 79/11/08 2pp
- --8007150154 Notice of violation from insp on 790924-28
 * Region i, Philadelphia, Office of the Director 79/11/06 2pp

- 8007160780 Forwards IE Circular BO-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/24 ip
- E007210107 Responds to E0061B moeting re decommissioning & decomtamination of Facility NRC will not proceed w/reviews of E00229 fundamental nuclear math control plan for License SMM-414 Rovised plan expected by E00721 PARTLOW, J Q Material Control Licensing Dranch E0/07/03 lp
- B007210094 Advises licensee that NRC will refund portion of fee paid for review & approval of B00212.0318 & 0415 applications for license amend License Condition 2 i 2 was added to Amend MPP-1 to License SNM-414 on B00604
 MILLER,W D License Fee Management Branch B0/07/10 ip
- 8007230712 Responds to 800626 request for reduction in number of nondestructive assay stds to be maintained during decommissioning Three stds are sufficient for calibr & control of nondestructive measurement sys
 PARTLOW.J & Material Control Licensing Branch 80/07/16 ip

DOCKET 70-0371 UNITED NUCLEAR CORP

- 8007230119 Forwards IE Insp Rept 70-0371/80-08 on 800512-15 No noncompliance noted MARTIN.W G Region i, Philadelphia, Safeguards Branch 80/06/11 2pp
- --8007230124 IE Insp Rept 70-0371/80-08 on 800512-15 Ne noncompliance noted Major areas inspected licensee action on previous insp findings & records & repts MOLTNER.E. JOYNER.J H Region i. Philadelphia, Safeguards Branch 80/06/09 ip
- 8007020617 Forwards TE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Hritten response required ORIER, B H Region i, Philadelphia, Office of the Director 80/06/18 1p
- 8007160846 Forwards IE Circular 80-14. "Redioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required CAIER, B H Region 1. Philadelphia. Office of the Director 80706/24 1p
- B007180058 Ack receipt of 800610 itr informing NRC of steps taken to mest commitment per IE lasp Rept 70-0371/80-06 MARTIN W G Region 1. Philadelphia. Safeguards Branch 80/06/27
- --8007180066 Responds to NRC 800520 ltr re-commitment made in response to IE insp Rept 70-0371/80-06 Corrective actions attached form used to record receipt of bottles of sludge W/o form QANLEY.D C United Nuclear Corp .Neval Products Div 80/06/10, lo
- --8007180071 Disrusses IE insp of Liconse SNM-368 & forwards IE Insp Rept 70-0371/80-06 on 800407-11 & 14-18 No noncompliance noted MARTIN.W O Region 1, Philadelphia, Bafeguards Branch 80/05/20 2pp
- --8007;80082 IE Insp Rept 70-0371/80-06 on 800407-11 & 14-18 No noncompliance noted Major areas inspected inventory verification.reconcilitation.mensurement & statistical control Details withheld (ref 10CFR2 790)

 UDYNER, H . BISHETT.P Region 1. Philadelphia. Safeguarda Branch HOLODY.O Region 1. Philadelphia, Office of the Director 80/05/12 19
- B007280090 Notifies that 800616 request for amend to License SNM-348 requires fee WEISS.D License Fee Management Branch 80/07/03 ip
- BOO7250363 Notifies that BO0626 request re shutdown & scrap processing has been classified as minor amend to License ENM-368 Minor amend fee is required
 WEISB.D License Fee Management Branch 80/07/08 ip

attricks \

- BD07230053 Requests notification of approx meeting date to discuss status of possible scrap recovery contract between NRC & facilities NRC has proposed Aug or Sept 1780 meeting date in Silver Spring.MD PARTCON.J 0 Haterial Control Licensing Branch 80/07/15 1p
- DOCKET 70-0398 COMMERCE, DEPT OF
- BO07iA0B3i Forwards IR Circular BO-i4, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel " No written response required, GRIER, B H Region i, Philadelphia. Office of the Director BO/06/24 ip

DOCKET 70-0474 UPBALA COLLEGE

- BOO7310291 Notifies of expired License SNM-450 & discusses actions to be taken by licenses CROCKER.H W Region 1. Philodelphia. Fuel Facility & Materials Safety Branch 80/05/07 2pp
- DOCKET 70-0572 MONSANTO RESEARCH CORP
- 8007020476 Advises that request for exemption to reduce allowable isotopic concentration of Pu-238 from 80% to 78% has been granted BURNETT.R F Division of Safeguards 80/06/17 ip

DOCKET 70-0625 HOWARD UNIV

- BOO70101BO Ack receipt of BO0425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-11063/80-01.
 30-01321/80-01.40-6789/80-01 & 70-0625/80-01
 BMTR, 0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch BO/09/28 ip
- ---B007010185 Responds to NRC 800328 ltr re violations noted in 1E lnsp Repts 30-11063/80-01.30-01321/80-01.40-6789/80-01 & 70-0625/80-01 Corrective actions offluent concentrations evaluated & Cf-25% source tested ALEXIS.C P Howard Univ 80/04/25 2pp
- --8007010197 Discusses IE insp Repts 30-11043/80-01,30-01321/80-01, 40-6789/80-01 & 70-0625/80-01 on 800320-21 & forwards notice of violation Shith, 0 H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/28 2pp
- --8007010209 Notice of violation from insp on 800320-21 Noncompliance noted failure to conduct required surveys, Cf-232 source stored in unlocked room & food stored in refrigerator w/radioisotopes
 * Region i, Philadelphia, Office of the Director 80/03/28 2pp

DOCKET 70-0697 UNION CARBIDE CORP

- 8007020341 Reports completion of criticality review of 800802 application Recommends that nuclear criticality safety aspects of application be approved PAGE, R & Uranium Fuel Licensing Branch 80/06/19 2pp
- GOO7140849 Forwards IE Circular 80-14, "Radiooctive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel" No written response required GRIER, B H Region I, Philadelphia, Office of the Director, 80/06/24 ip
- B007210289 Ack receipt of B00520 itr informing NRC of steps taken to correct violations noted in IE Inep Rept 70-0687/80-03 ORIGR, B Region i, Philadelphia, Office of the Director, 80/06/30
- --8007210293 Responds to NRC 800423 itr re violations noted in IE Insp Rept 70-0687/80-03 Corrective actions will maintain air sampling records MCGOVERN.J J Union Carbide Corp 80/05/20 ip
- ---8007210295 Forwards IE Insp Rept 70-0687/80-03 on 800227-29 & notice of violation SNITHA 9 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/23 2pp.

- \$307210074 Notifies that 791129 request for routs approval involving spent fuel shipment from Tuxedo,NY to Bavannah River reprocessing site in BC is subj to license fee schedule Review completed on B00303 MILLER,W 0 License Fee Menagement Branch 80/07/03 ip
- 2007230148 EN-BO-012A on B00711.order imposing civil penalty of \$1,000 mas issued. After consideration of licensee response. IE concluded that one item of noncompliance did occur IRCOCRETT.T W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/07/11 ip
- BOO7300038 Ack receipt of BO0428 ltr in response to NRC BO0407 notice of violation & notice of proposed imposition of civil penalties Also forwards order imposing civil monetary penalty.

 BTELLO, V. MRC Regional Offices BO/07/11 Zpp
- -8007300040 Order imposing civil monetary penalty re noncompliance noted in IE insp of facility on 800102-27 App A, evaluation & conclusion encl 8TELLO, V. NRC Regional Offices 80/07/11 5pp
- 8007280101 Returns check which accompanied 800707 ltr Fee for same request was received on 800419 WEISB,D License Fee Management Branch. 80/07/17 lp.

DOCKET 70-0734 GENERAL ATOMIC CO.

- 9007030009 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Netification Sys (ENS) M/Loss of Offsite Power " Written response required.
 ENGELKEN R. H. Region 5, San Francisco, Office of the Director 80/04/18 19
- MO7240076 Responds to NRC B00424 site-specific questions re details of paysical protection sys Response withheld (ref 100FR2 770) NCCORKLE, 9 W Physical Security Licensing Branch B0/06/20 ip
- 8007180274 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater 8ys & Resultant Internal Contamination of Paraonnel." No written response required EMPELKENIR H. Ragion 5. Ban Francisco. Office of the Director Me204/24. 1p.
- 8007230081 Requests resolution of outstanding fee issues for certain shysical security-related documents & emergency plans Hemo dtd 790910 re 790220 quest training plan submitted by GA Co never answered MILLER, M. O. License Fee Management Branch 80/07/16 2pp
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.
- BO07240072 Responds to BO0421 ltr requesting change to spent fuel routs approved by NRC B00417 ltr Proposed change has been reviewed & approved Attachment to B00421 withheld (ref 100FR2 790)
 MCCORKLE.O W. Physical Security Licensing Branch B0/04/30 ip
- 8007180305 Forwards IE Circular 80-14, "Radicattive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required EMGELKEN,R H. Region 5, Ban Francisco, Office of the Director. 80/06/24, 19
- \$007170621 Notifies that 791228 request for route approval involving apent fuel shipment from Waterford.CT to Pleasanton.CA is subj to Commission license fee schedule Review completed on 800417.

 MILLER, W. Q. License Fee Management Branch 80/07/03 ip.
- 8007280027 Notifies that amend fee is required for 800620 request reuse of SNM outside secured areas MEISS,D. License Fee Management Branch 80/07/08, 1p

8007250161 Forwards NRC 800522 fee request for review of physical protection plan for SNM of moderate strategic significance Requests payment within 19 days
WEISS.D License Fee Management Branch 80/07/16 ip

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8007250486 Forwards IE Insp Rept 70-0820/80-06 on 800513-15 No noncompliance noted Cover sheet only encl (ref 100FR2 790) MARTIN.W O Region i, Philadelphia, Safeguards Branch 80/06/17 2pp
- --8007250494 IE Insp Rept 70-0820/80-06 on 8003i3-15 No noncompliance noted Major areas inspected organization, shipping & receiving, measurements & stetistical controls Details withheld (ref LOCF82 790) COHEN, I., ZIBULSKY, H., JOYNER, J. H. Region 1. Philadelphia, Office of the Director 80/06/13 ip
- 8007020622 Forwards IE Builetin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director SO/06/18 1p
- 8007160845 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 in
- 8007210106 Requests payment of minor safeguards amend fee in connection w/800626 request for exemption from requirements of 10CFR73 20.73 45 & 73 46 Request has been classified as requiring minor amend to License SMM-777 HFISS, D License Fee Management Branch 80/07/08 ip

DOCKET 70-0824 BABCOCK & WILCOX CO

- BOO7010006 Forwards replacement pages to BAM-381 for License GNM-77B Enci responds to NRC questions arising from 800218 request to amend license to allow const & use of temporary waste storage facility DUSEN.A F Babcock & Wilcox Co 80/03/25 ip
- ---BD07010010 Replacement pages for BAW-381, "Demonstration & Conditions for License SNM-778," May 1970 * Babcock & Wilcox Co BAW-318 A12 R10 70/03/31 7pp
- --B007020350 Replacement page for BAW-381, "Demonstration & Conditions for License SNM-778," Dec 1978 + Babcock & Wilcox Co BAW-381 78/12/31 9pp
- B007150839 Lists costs incurred & manhours expended in review of 800218 application & 800325 & 0408 suppls for amend to License SNM-778 KETZLACH.N Uranium Fuel Licensing Branch 80/05/30 ip
- 8007020337 Forwards proposed license conditions & comments on license renewal application W/o encl CRDW,W T Uranium Fuel Licensing Branch 80/06/10 3pp
- B007010293 Requests extension until 800701 to satisfy Item 3 of Insp Rept 70-0824/80-01 Required forms, re hazardous math, not yet received from printer DLSEN, A F. Babcock & Wilcox Co 80/06/13 lp
- --8007010295 Forwards IE Insp Rept 70-0824/80-01 No noncompliance noted KENNA,W B Region 2. Atlanta, Safeguards Branch 80/05/21, 2pp
- --8007010301 [E Insp Rept 70-0824/80-01 on BO0429-0502 No noncompliance noted Major areas inspected facility changes & mods, operations review, followup on unresolved items & followup on items of noncompliance KAMLE. J B Region 2. Atlanta, Office of the Director KENNA, # B Region 2. Atlanta, Bafeguards Branch 80/05/19 7pp
- 8007020723 Forwards IE Dulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power" Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/06/18

- 8007170148 Forwards IE Circular 80-14. "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/06/24 lp
- B00721003B Notifies of fee required for review of 791205 request for route approval for shipment of spent fuel assemblies from Lynchburg Rosearch Ctr to Oconbe Nuclear Power Station HILLER: W O License Fee Hanagement Branch B0/07702 ip
- 8007230648 Forwards revised NUREC-0361 amending interim rule for physical protection of spent fuel in transit Addl areas have been designated as heavily populated Routes approved for 8&W encl New requirements apply 800703 W/o encl MCCORKLE.G W Physical Security Licensing Branch 80/07/03 1p
- DOCKET 70-0925 CIMMARON FACILITY, MERR-MCGEE CORP
- 8007170300 Forwards IE Insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08 & notice of violation DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/06/16 2pp
- --8007170305 Notice of violation from insp on 800407-08
 * Region 3, Chicago, Office of the Director 80/06/12 ip
 - 9007170310 IE Insp Repts 70-0729/80-02 & 70-1173/80-02 on 800407-08 Noncompliance noted empty.open 55-gallon drums were found in waste shipment storage Room 121 DURRY.N E Region 3, Chicago. Dffice of the Director FIBHER,W L Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/06/12 10pp
- G007030023 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Natification Sys (EMS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/18
- E007110513 Forwards IE Insp Rept 70-0925/80-04 on B00610-12 No noncompliance noted MIND, A Region 3, Chicago, Safeguards Branch 80/06/23 ip
- --8007110518 IE Insp Rept 70-0925/80-04 on 800610-12 No noncompliance noted Major areas inspected facility organization & operation, measurement & statistical details & physical inventory Details withheld (ref 10CFR2 790)
 HIND. J. A. Region 3. Chicago, Safeguards Branch PATTERBON, J. P. Region 3. Chicago, Diffice of the Director 80/06/20 Ip
- 8007170800 Forwards IE Circular 80-14, "Radiooctive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/24 ip
- 8007250626 Forwards survey map inadvertently omitted from IE Insp Repts 70-0925/80-02 & 70-1193/80-02 W/o encl DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/07/08 Ip
- 8007280710 Forwards survey map inadvertently omitted from IE Insp Repts 70-0725/80-02 & 70-1193/80-02 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- 8007230549 Ack receipt of 800627 Itr informing NRC of steps taken to correct violations noted in IE insp repts
 BAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/07/15 ip
- --8007230564 Responds to NRC 800616 ltr re violation noted in IE insp repts Corrective action empty drums removed from Room 121 r-NcOse Nuclear Corp 80/06/27 ip.

DOCKET 70-0984 PACIFIC NORTHWEST LAB

B007180283 Forwards IE Circular 80~14. "Radioactive Contamination set Plant Demineralised Mater Bys & Resultant Internal Contamination of Porsonnel " No written response required, ENGELKEN,R H Region 5. Ban Francisco, Office of the Director 80/06/24 ip

DOCKET 70-0997 HESTINGHOUSE ELECTRIC CORP

8007180338 Discusses IE Insp. Rept 70-0997/80-01 conducted on 800606 No noncompliance noted Major areas inspected, selective examinations of procedures & representative records, interviews w/personnel & measurements by inspector KINNEMAN. J D. Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/06/30 ip

DOCKET 70-1062 TODD SHIPYARDS CORP.

- 8007240228 Responds to 15 Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial." No radwaste has been generated over past 5 yrs under License BNM-1015. Radwaste generated under State of TX Licenses B-871231. WINTERB.C E Todd Shipyards. 79/09/04 1p
- --8007240348 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Bulletin requires action of licenses SEYFRIT,K V Region 4, Dailas, Office of the Director, 79/08/10 Ip
- 8007010056 Responds to 800422 memo by forwarding 800609 ltr to Todd Bhipyards w/guideline describing decontamination requirement to be met prior to termination of License BMT-1015, State of TX responsible for decontamination re raduate storage PAGE/R G Uranium Fuel Licensing Branch. 80/06/09 1p
- --8007010281 Forwards "Ouidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct Source or SMM."
 Requirements do not apply to activities under TX license, PAGE,R 0 Uranium Fuel Licensing Branch. 80/06/09 ip

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

- 8007020097 Ack receipt of 800305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1100/80-02 k 30-03754/80-01 GRICR, B H Region 1, Philadelphia, Office of the Director 80/09/30 2pp
- --B007020103 Responds to NRC 800417 ltr re violations noted in IE Insp Repts 70-1100/60-02 & 30-03754/80-01 Facility does not concur w/inspector opinion requiring response to IE Bulletin 77-19 LICHTENBERGER Combustion Engineering, Inc 80/05/05, ip.
- --8007020106 Forwards IE Insp Repts 70-1100/80-02 & 30-03754/80-01 on 800310-12 No noncompliance found Certain aspects of operation not conducted per IE Bulletin 79-17 requirements. SHITH, 0 H Region I. Philadelphia. Fuel Facility & Materials 8efety Branch 80/04/17 2pp
- --B007020121 IE Insp Repts 70-1100/80-02 & 30-03754/80-Di on B00310-12 No noncompliance noted Major areas inspected licensee response to IE Bulletin 79-19 ROTH.J Region 1, Philadelphia, Office of the Director, CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/04/14 9pp
- B007020107 Forwards add1 info supporting 800111 renswal application for Certificate of Compliance 9022, per NRC 800501 request Revised pages and1.

 LICHTENBERGER, H C-E Power Systems 80/06/06 6pp

1

1 .

- --8007020114 "Shipping Container "
 * C-E Power Bystems 7499-774030. 79/06/13. ip
- B007160840 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/06/24 Ip

- BOO7200733 Ack receipt of BOO606 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70~1100/BO-03 MARTIN, M. O Region i. Philadelphia. Safeguards Branch BO/07/09. to
- --8007280737 Responds to NRC 800522 ltr re violation noted in IE Insp. Rept 70-1100/80-03 Corrective actions new stds will be developed for assay machine so range of values will be massured within calibr limits

 LICHTEMBERGER Combustion Engineering, Inc. 80/06/06 ip
- --B007280743 Forwards IE Insp Rept 70-1100/80-03 on 800428-0501 & natice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN, N G. Region 1, Philadelphia, Safeguards Branch 80/05/22 20c.
- --B007280746 IE Insp Rept 70-1100/80-03 on 800428-0501 Noncompliance noted failure to reject results outside calibr range of measurement sys Betails withheld (ref 10CFR2 790) COMEN. I DELLA RATTA, A Region 1, Philadelphia, Office of the Director JOYNER, J. H. Region 1, Philadelphia, Bereguards Branch 80/05/19 1p.
- B007220423 Advises that quarterly reporting level of 18 uCi of airborne particulates was exceeded During period 800330-0628 total quantity discharged was 22 23 uCi low enriched U Problem attributed to undersized absolute filters Filters replaced LICHTENBERGER. C-E Power Systems 80/07/10 2pp
- 8007290001 Forwards summary of 800617 meeting relactions to dispose of redwaste found in remote location on Windsor site SHITH, O. H. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 80/07/11. 1p.
- -8007270003 Summary of 800617 meeting w/C-E in King of Prussia, PA reactions to dispose of radwaste matl found in remote location on Windsor site.

 RDTH.J Region 1. Philadelphia, Office of the Director 80/07/11

DOCKET 70-1113 GENERAL ELECTRIC CO.

- 8007150027 Ack receipt of 800409 k 0613 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/80-03 KENNA, M. B. Region 2, Atlanta, Bafeguards Branch 80/06/17 ip
- --8007150033 Responds to NRC B00304 ltr re violations noted in IE Insp Rept 70-1113/80-03 Corrective actions trailer returned to Wilmington afg dept correctly placarded & labels affixed to overpack surface. KAPLANIA L. General Electric Co. 80/04/07. Bpp
- ---8007150038 Forwards IE Insp Rept 70-1113/80-03 on 800129-30 & 0211-12 & notice of violation D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/04 Spp.
- --8007150043 Notice of violation form insp on 800127-30 & 0211-12 # Region 2, Atlenta. Office of the Director 80/03/03 2pp
- --B007150049 IE Insp Rept 70-1113/80-03 on 800129-30 & 0211-12
 Noncompliance noted failure to properly label, provide
 placerde & describe in shipping documents shipment of SNM
 STEELE,P W , CLAY,F L Region 2, Atlanta, Office of the Director
 KAHLE,J B Region 2, Atlanta, Safeguards Branch 80/03/03 24pp
- 9007020732 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/18
- 8007030228 Responds to 800329 itr concerning NRC request for amend fee for review of physical security plan for SNM, Amend fee is due Upon completion of review.cost will be reviewed & any overpayment refunded.

 MILLER, W. D. License Fee Management Branch 80/06/19 2pp.

- 8007070187 Approves Amend 13 to License SNM-1097, revising completic date for add1 details of decommissioning plan Details must be provided within 90 days after publication of Battelle model decommissioning plan PAGE,R G Uranium Fuel Licensing Branch 80/06/24 tp
- --8007070195 Safety evaluation supporting Amend 13 to License SNM-revising completion date for addl details of decommissioning piam STEVENSON, R. L., CROW, W. T. Uranium Fuel Licensing Branch 80/06/24 2pp
- 8007170152 Forwerds IE Circular 80-14, "Radioactive Contamination Plant Demineralised Water Sys & Resultant Internal Contamination of Personnel " No westten response required O'REILLY, J.P. Region 2, Atlanta, Dffice of the Director 80/06, in
- 8007160718 Forwards IE Insp Rept 70-1113/80-08 on 800617 No noncompliance noted Dotails withheld (ref 10CFR2 790) XENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/27 2p
- --B007160727 IE Insp Rept 70-1113/B0-08 on 800617 No noncompliance Major areas inspected facility organization & mgt of matl control sys Details withheld (ref jocfR2 790) HODGES,J W., GILLESPIE,F P. Region 2, Atlanta, Safeguards Brai B0/06/25 ip
- 8007080212 Responds to IE Bullotin 80-15, "Possible boss of Emerger Notification 8ys (EMB) w/Loss of Offsite Power " No emergency notification sys exists at facility KAPLAN, A L. General Electric Co. 80/06/30 lp
- 8007250673 Responds to requests for changes to License SNM-1097.Am MPP-2.Condition 2 1 re fundamental nuclear math control plan Corrections & revised amends encl Encls withhold (ref iOCFRZ 790)
 PARTLOW, J 0 Material Control Licensing Branch 80/07/03 2pp

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 8007020221 Forwards moderate socurity plan suppl Suppl withheld (ref 10CFR2 770)
 PIPIAZZA.R P Westinghouse Electric Corp 80/05/20 ip
- 8007020015 Ack receipt of 800428 ltr informing NRC of steps taken correct violations noted in IE. Insp Rept 70-1149/80-05 Ltr to be withheld (ref 100FR2 790) MARTIN, W G Region 1. Philadelphia. Safeguards Branch 80/05/2
- --8007020017 Forwards 1E Insp Rept 70-1143/80-05 on 800226-28 & no of violation Notice of violation withheld (ref 10CFR2 790) MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch 80/04 200.
- --B007020022 IE Insp Rept 70-1143/80-05 on B00226-28 No noncomplia noted fatiure to document testing & maint of securityrelated equipment Details withheld (ref 10CF82 770) MADDEN, H. Region i. Philadelphia, Safeguards Branch 80/04/C lo
- 8007210185 Forwards JE Insp Rept 70-1143 on 70-1143/80-09 on 60051 No noncompliance noted BMITH.0 H Region 1. Philadelphia. Fuel Facility & Materials 9. Branch 80/06/09 2pp
- --8007210190 IE Insp Rept 70-114.3/80-09 on 800513-16 No nencomplia moted Major areas inspected licensee action on previous insp findings, organization, nuclear safety & instrument calibr & safety committee activities KINNEY, W W Region i. Philadelphia. Office of the Director CROCKER, H W Region i. Philadelphia. Foel Facility & Materia Safety Branch 80/06/06 12pp
- 800702068) Forwards IE Bulletin 80-15, "Possible Loss of Emergent Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director, | BO/06/18 | 19
- B00716078B Forwards IE Circular B0-14, "Radioactive Contamination Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required GRIER, DH Region 1, Philadelphia, Office of the Director | B0/06/24 | 19

-)7210287 Requests elemption to requirements of IE Bulletin 80-15 rp lessible loss of emergency notification sys w/loss of lessive power Facilities being decontamintated No motification sys will underway or planned Decommissioning set for 1982 (DDRE.J S Westinghouse Electric Corp 80/06/27 lp
- 07230288 Amend 19 to License SNM-1120 authorizing decontamination decommissioning of glove bases
 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 80/07/03
- 07280282 Informs of partial refund of fee accompanying 800612 application for Amend 19 to License SNM-1120 MILLER.W O License Fee Management Branth 80/07/14 1p
- CKET 70-1151 WESTINGHOUSE ELECTRIC CORP
- 07100362 Ack receipt of 800401 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1151/80-05 KENNA, W.B. Region 2, Atlanta, Safeguards Branch E0/04/30 ip
- 8007100370 Responds to NRC 800313 itr re violations noted in IE inap Rept 70-1151/80-05 Corrective artions withheld (ref MCFR2 790) QUODWIN, W L Westinghouse Electric Corp 80/04/01
- B007100374 Forwards IE insp Rept 70-1151/80-05 on 800211-15 & notice of violation Notice of violation withheld (ref locFR2 790)
 KENNA-W D Region 2. Atlanta. Safeguards Branch 80/03/13 2pp.
- 80071003B1 IE insp Rept 70-3151/80-05 on 800211-15 Noncompliance noted NDA measurement control procedures failed to describe requirements for reporting program data Details withheld requirements for reporting yourself of the Director GillESPIE.F P Region 2. Atlanta, Office of the Director GillESPIE.F P Region 2. Atlanta, Safeguards Branch 80/03/04
- 06300292 Forwards revised manual, "Fundamental Nuclear Mati Control Plan Columbia Plant " Requests approval Manual withheld (ref 10CFR2 790) P Westinghouse Electric Corp , PWR Systems Div DIPIAZZA. R P
- 07020213 Forwards IE Insp Rept 70-1151/80-12 on 800415-18 No nuncompliance noted
 KENNA.W D Region 2. Atlanta. Safeguards Branch 80/05/00 2pp
- 8007020220 IE Insp Rept 70-1151/80-12 on 800415-18 No noncompliance noted Major areas inspected operations nuclear criticality safety, internal review & audit.facility mode & LOCFR21 programs CORYELL.O P ? Region 2. Atlanta. Office of the Director Region 2. Atlanta. Gafeguards Branch 80/05/00 4pp
- 006300017 Forwards site physical Security plan for approval Fee encl Plan withheld (ref 10CFR2 770) DIPIAZA.R P Westinghouse Electric Corp. PWR Systems Div BO/05/15 ip
- DOTORO735 Forwards 1E Dulletin B0~15, "Possible loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta: Office of the Director 50/04
- Region 2. Atlanta: Office of the Director 80/04/10
- 007030022 Advises of issuance of Amend 5 to SNM-1107, deleting requirement for gross beta analyses of Divisor air particulates Table for Condition 39 replaced w/encl tables PAGE; R Q Uranium Fuel Licensing Branch 80/06/19 3pp
- -8007030028 Safety evaluation supporting amend to License SMM-1107. deleting requirement for gross beta analyses for air particulates SHUM-E Y , CROW, W T Uranium Fuel Licensing Branch 80/06/19
- 00717014; Forwards IE Circular 80-14, "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24,
- OO7180355 Forwards addl info supporting request for amend to License SNM-1107 to authorize use of SNM in advanced waste treatment process Lor & addl info withheld (ref 10CFR2 790)
 DIPIAZZA.R P Westinghouse Electric Corp BO/06/24 2pp

- BOO71BOO7B Ack receipt of BOO329 ltr re survey & release of 1,200 lb of molybdenum scrap Release should not be made until JE has had opportunity to make independent evaluation CROM. If Uranium Fuel Licensing Branch BO/06/25 lp
- 8007150818 Lists costs incurred & manhours expended in review of 800514 application for amend to License SNM-1107 SHUM,E Y Uranium Fuel Licensing Branch 80/06/26 1p
- 8007210062 Ack receipt of 800605 itr informing NRC of atera taken to correct violation noted in IE Insp Rept 70-1151/80-14 9TOHR, J P Region 2. Atlanto, Fuel Facility & Materials Safety Branch 80/07/08 lp
- ---B007210077 Responds to NRC B00606 ltm re violation noted in IE Insp Rmpt 70-i151/B0-14 Corrective actions first aid training program schedulad & attended by shift supervisors & health physics technicians G000WIN.W L . D'AMORE.M Westinghouse Electric Corp B0/06/25
- --8007210082 Forwards IE insp Rept 70-1151/80-14 on 800519-23 & notice of violation BTOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety 80/06/06 2pp
- --8007210086 Notice of violation from insp on 800517-23
 * Region 2, Atlanta, Office of the Director 80/0. 80/06/06
- --B007210093 IE Insp Rept 70-1151/80-14 on 800519-23 Noncompliance noted failure to complete first gid training for all shift sugervisors & health physics technicians PERROTTI.D J Hegion 2. Atlanta, Office of the Director JUNKINS.G R Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/06 9pp

DOCKET 70-1177 DAVIS & ELKINS COLLEGE

- 8007280298 IE Insp Findings & Licensee Ack dtd 800611 of License SNH-1119 Insp findings no noncompliance noted, DROWN,R A Region 2, Atlanta, Office of the Director 80/06/11
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.
- 8007020244 Responds to 800509 itr to LC Rouse re changes to Cimarron standby physical ascurity pian Changes do not decrease effectiveness of plan, & are therefore being inserted into plan Encls to 800509 itr withheld (ref 100FR2 790) MCCORKLE, G W Physical Security Licensing Branch 80/06/02 1p.
- 8007170300 Forwards it insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08 Entite of violation DAVIGAD Region 3, Chicago, Fuel Pacility & Materials Safety Branch 80/06/16 2pp
- --8007170305 Notice of violation from insp on 800407-08
 * Region 3, Chicago, Office of the Director 80/0 80/06/12
- --B00/170310 IC Insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08. NOTIONAL IT INSPECTS TO CARDINAL & TO TIME WERE ROUND IN ACCOUNT IN A COUNTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE DIRECTOR FISH BROYOGALL REGION J. Chicago. Office of the Director FISH BROYOGALL REGION J. Chicago. Fuel Facility & Materials Safety Branch BOYOGALL 10pp FIBHER, W L
- B007030023 Forwards IF Bulletin B0-15. "Possible Loss of Emergency Natification Bys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3. Chicago, Offsics of the Director 80/06/1 80/06/18
- BOO7170500 Forwards IC Circular BO-14, "Radidactive Contamination of Plant Demineralized Water Sus & Resultant Internal Contamination of Personnel "No written response required KEPPLER.J.O Region 3, Chicago, Office of the Director. 80/06/24.
- 8007140673 Forwards IC Insp Rept 70-1193/80-03 on 800612-13 compliance noted

 A Region 3. Chicago, Safeguards Branch, 80/07/02 ip.
- --8007140482 IE Insp Rept 70-1193/80-03 on 800412-13 No noncompliance noted Major areas inspected nuclear mail control & accounting Details withheld (ref 10CFR2 790) HIMD. J A Region 3. Chicago, Bafeguards Branch PATTERSON, J P. Region 3. Chicago, Offico of the Director 80/07/01 ip.

- 8007250626 Forwards survey map inadvertently omitted from IE Insp. Regts 70-0925/80-02 & 70-1173/80-02 W/o encl DAVIS.A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/08 ip
- 2007280710 Forwards survey map inadvertently omitted from IE Insp Repts 70-0925/80-02 & 70-1193/80-02 DAVIB,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/14 Zpp
- 8007230549 Ack receipt of 800627 ltr informing NRC of steps taken to correct violations noted in IE insp repts DAVIS.A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/07/15 ip.
- DOCKET 70-1201 UF A CONVERSION FACILITY, BABCOCK & WILCOX CO.
- 8007100390 Ack receipt of 800421 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1201/80-04
 KENNA, M. B. Region 2, Atlanta, Befaguards Branch 80/04/30 ip.
- -8007100397 Responds to NRC B00401 ltr re violation noted in IE Insp Rept 70-1201/B0-04, Corrective actions withheld (ref 10CFR2 790) Babcock & Wilcox Go , Nuclear Material Dlv. 80/04/21
- -8007100404 Forwards IE Insp Rept 70-1201/80-04 on 800304-07 & notice of violation. Notice of violation withheld (ref 100FR2.790).
 KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/04/01 2pp
- BATEB, J. W., Olllespie, F.P., Region 2, Atlanta, Safeguards Branch BO/04/01 2pp
- B007030368 Forwards IE Insp Rept 70-1201/80-06 on 800330-0404 No BTOWN, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/05/07 2pp
- -8007030370 IE Insp Rept 70-1201/80-06 on 800330-0404 No noncompliance noted, Major areas inspected, followup on previous insp findings, internal & external exposure control, respiratory protection & instrument calibr.

 MILLSAP, W.J. Region 2. Atlanta, Office of the Director.

 GIBSON.A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/03/07 9pp
- BOO7020080 Revises License Conditions 1 1,2 1,3 1,5 2 & 8 1 of License BWH-1168. Adds License Conditions 3 1 & 4 10 to License Amand HPP-2; authorizing changes to pages of nuclear matl control plan & exemptions from 10CFR70 BURNETT, R. F. Physical Becurity Licensing Branch. 80/05/29. 1p
- 8007020725 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/06 Region 2, Atlanta, Office of the Director, 80/06/18
- 8007170144 Forwards IE Circular 80-14, "Radioactive Contamination of Flant Demineralized Mater Sus & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/24
- 8007240106 Amends License SNM-1168 authorizing revision of action level for airborne concentration of radioactivity in fuel-rod-end welding area & liquid affluent release Also adds dates of BOO109 & O612 to Item 9. PAGE,R. 9 Urenium Fuel Licensing Branch BO/07/01 ip
- --8007240110 Discusses review of 800109 license amend application & 800612 suppl. Recommends issuance of license amend KETZLACH.N., GROW.W.T. Uranium Fuel Licensing Branch 80/07/01
- 9007310493 Adds license conditions to License SNM-1168. Amend MPP-2 re use of stds for measurement calibr & storage of certain matts, in response to 800626 request for exemptions from code requirements.

 BURNETT, R. F. Division of Safeguards 80/07/18 1p

DOCKET 70-1220 GENERAL ELECTRIC on

- 8007170422 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal
 Contamination of Personnel " No written response required
 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24
- DOCKET 70-1252 EDLOW INTERNATIONAL CO
- 8007240080 Advises that request for 30-day extension for submittal of security plan has been granted Submission date is changed to 800617 MCCORKLE.O W Physical Security Licensing Branch 80/05/29 1p
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO / INC
- 8007240322 Forwards IE Insp Rept 70-1257/80-04 on 800331.0401 & 22-23 No noncompliance noted

 No noncompliance noted

 BODK.H E Region 5. San Francisco, Fuel Facility & Materials Safety

 Branch 80/06/11 2pp
- --8007240331 IE Insp Rept 70-1257/60-04 on 800331,0401 & 22-23 No noncompliance noted Major areas inspected facility mods, radwaste mgt & internal review & audit COOLEY,N J. THOMAS,R D. BOOK,N E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/06/10 7pp
- 8007030008 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required ENGELKEN R H Region 5, San Francisco, Office of the Director. H Region 5, San Francisco, Office of the Director, 80/04/18
- 8007090183 Recommends endorsement of encl review of estimate of release of Pu from Exxon nuclear mixed oxide fuel plant at Richland. HA as staff position & basis for succepting increments of analysis of effects of natural phenomena on Pu fabrication AYER, J. E. BURKHARDT. W. Advanced Fuel & Spent Fuel Licensing Branch 80/06/24 1p
- ~~8007090186 "Increment of Analysis Estimated Airborno Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland, WA as Result of Postulated Damago from Severe Wind & Earthquake Hazard "
 MISHIMA, J. SCHWENDIMAN, L. C., AYER, J. E. Battélle Nemorial Institute, Pacific Northwest Laboratory PNL-3340 80/02/29
- 8007180304 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminsralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director, 80/06/24 ip
- B007210310 Forwards BNWL rept, "Increment of Analysis.Estimated Airbourne Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland.MA as Result of Postulated Damage from Severe Wind & Earthquake Hazard" ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 80/06/24
- --8007210315 "Increment of Analysis, Estimated Airbourne Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland.WA as Result of Postulated Damage From Severe Wind & Earthquake MISHIMA, J. SCHWENDIMAN, L.C. Battelle Memorial Institute. Pacific Northwest Laboratory AYER, J.E. Advanced Fuel & Spent Fuel Licensing Branch PNL-3340 80/02/29 45pp
- 8007240032 Discussed IE insp of License SNM-1227 on 800512-16 No noncompliance noted Hajor areas inspected selective exam of procedures & records, interviews w/personnel & observations by Inspector Details withheld (ref 10CFR2 790) NORDERHAUGLE R Region 5, San Francisco, Safeguards Branch 80/07/07 2pp
- 8007210089 Advises licensee that NRC will refund portion of fee paid for review & approval of 800123 application for license amend License Condition 2 i of MPP-2 to License SMM-1227 was revised on 800530 in response to application MILLER.W O License Fee Management Branch 80/07/10 ip
- BOO7250044 Returns payment which accompanied BOO519 request to amend renewal application for Licensu SNN-1227 Request has been combined w/790531 renewal application
 WEISS,D License Fee Management Branch BO/07/16 ip

DOCKET 70-1278 PUBLIC SERVICE OF COLORADO

- B007290629 Forwards Endorsement 52 to ANI Policy NF-192 & Endorsement 45 to MAELU Policy NF-69
 OASCHLER, J A Public Service Co of Colorado B0/07/22 3pp
- DOCKET 70-1308 MURRIS OPERATIONS. GENERAL ELECTRIC CD
- B007150057 Forwards calculations of temp change estimates from max heat discharge at nearost ground level location to coolers. In support of statements in EIA CLARK.A T Advanced Fuel & Spent Fuel Licensing Branch B0/05/27
- 8007020608 Forwards GE 800606 ltr to NMSS re proposed addition to pump room at facility RQDHEY,M A Mayer, Brown & Platt 80/06/12 ip
- --80D7020611 Forwards add1 info re proposed addition to pump room, per NRC 791004 request After completion of project, appropriate revision of NEDO-21326C, "Consolidated SAR" will be submitted DAMSON.D M General Electric Co 80/06/06 7pp
- B007010573 Forwards JE Insp Rept 70-1308/80-03 on 800520-22 t notice of violation Motice of violation withheld (ref 10CFR2 790) HIND. J A Region 3. Chicago. Safeguards Branch B0/06/16 2pp
- --8007010578 IE Insp Rept 70-1308/80-03 on 800570-22 Noncompliance noted some vital barriers not properly maintained Details withheld (ref 10CFR2 790) CREED, J R. PIRTLE, G L. Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Safeguards Branch 80/06/13 2pp
- 8007:70422 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel" No written response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director 80/06/24 in
- G007140038 Memorandum in opposition to State of IL B00620 motion for reconsideration of ASLB G00604 order ruling on IL B00320 contentions NRC B00609 interim policy does not grant ASLB jurisdiction to review Class 9 accident W/Certificate of Svc SZWAJKOWSKI.R. RODNEY.M A General Electric Co SZWAJKOWSKI.R Hayer, Brown & Platt B0/07/07 9pp
- B007280035 Summary of 800610 meeting w/GE in Silver Spring.HD re 000123 request for license amend CLARK.A T Core Performance Dranch 80/07/09 2pp
- B007140023 Response in opposition to State of IL 800620 motion for reconsideration re Contentions 9 & 11 & in support of motion re Contention i(a) & request for illarification Requests add1 discovery Mynotice of appearance & Certificate of Svc CRAY. J R Hearing Branch i B0/07/i0 17pp
- BOO7160587 Notice of GE AcGrath of GE 800725 deposition in Chicago, IL Requests production of documents & tangible evidence readopted contentions
 SEKULER/S N . SCOTT, W J lilinois, Etate of 80/07/11 ip
- 80071803B7 First set of interregatories directed to applicant Requests Identification of comployees & representatives wiknowledge about operation of spent fuel federal repository Certificate of Svc enck
 9COTT.W J. SEKULER.S N. Illinois, State of 80/07/14 7pb
- B007170215 Interrogatories & request for production of documents directed to intervenor Rorem et al Requests identification of witnesses & documents re Contentions 1(b), 2 & 6, definition of terms & description of basis for allegations CRAY. J R Hearing Branch 1 B0/07/15 15pp
- --8007170220 Interrugatories & request for production of documents directed to State of IL Requests views, positions on proposed testamony on Contentions in 7 w/witnesses intended to be called Certificate of Sv. encl GRAY, J R Hearing Branch i 80/07/15 28pp
- 800722013B Request for production of documents in form of natice directed to State of 1L Relates to GE interrogatories. State of 1L Contentions 1-7, expert untrasses' opinions & State of IL 800320 second amended contentions W/Certificate of Svc IL 800320 second amended contentions W/Certificate of Svc SZMAJKONSKI.R. ROOPHEY, M A General Electric Co SZMAJKONSKI.R Mayer, Orown & Platt BO/07/15 3pp

- 9007220147 Interrogatories directed to intervenor Rorem et al.Requests identification of independent & employed expert witnesses intended to be called in license renewal proceeding Certificate of Svc oncl ROONEY, M A . SZWAJKOWSKI R General Electric Co ROONEY, M A Mayer. Brown & Platt GO/07/15 App
- B007220168 Interrogatories directed to State of IL Requests identification of all independent & employed expert witnesses intended to be called during hearing. Demands basis upon which contentions were formed Certificate of Svc encl RDONEY, M A . 92WAJKONSKI.R W General Electric Co ROONEY, M A Mayer. Brown & Platt 80/07/15 10ps
- 8007220170 Request for production of documents in form of notice directed to intervenor Rorem et al Relates to intervenor answers to GE interrogatories, basis of Contentions 1(b), 2 & 6 & intervenor intended testimony W/Certificate of Byc ROONEY, H A . SZWAJKOWSKIJR General Electric Co ROONEY, H A Mayer. Brown & Platt 80/07/15 3pp
- 8007220015 Corrects 800715 svc list re NRC interrogatories directed to intervenor Rorem et al & NRC interrogatories & request for production of documents directed to State of IL Documents served 800715, sent via certified mail. receipt requested ROTHSCHILD.M U Hearing Branch | 80/07/17 ip
- 8007220009 Forwards NRC objections to State of IL 800711 notices of depositions & request for production of documents NRC will not object to untimely motions if filed during discovery phase ROTHSCHILD; M U Hearing Branch 1 80/07/18 ip
- --8007220011 Response in opposition to State of IL 800711 notices of depositions & request for production of documents MRC willing to discuss reasonable arrangements w/IL members w/specializes knowledge ROTHSCHILD.M U Hearing Branch 1 80/07/18 App
- 6007230519 Advises Assistant Atty General that CE will respond to all interrogatories & document production requests on 800804 QE reserves right to object to deposition of any individual who is not proper deponent Certificate of Svc encl 8ZWAJKDWSKI,R Mayer, Brown & Platt 80/07/18 2pp
- DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 8007170422 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Dumineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 90/06/24 to

DDCKET 70-1319 U B NUCLEAR, INC

- B007020733 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys (EMB) W/Loss of Offsite Power " Written response required O'REJLLY, J P Region 2, Atlanta, Offlice of the Director B0/06/18 to
- 8007280320 Advises that License SNM-1315 is terminated & facilities & equipment released for unrestricted use PAGE:R 0 Uranium Fuel Licensing Branch 80/06/19 ip
- --8007280327 Discusses review of US Nuclear, Inc request for termination of License SNM-1315 & release of facility for restricted use Recommends that license be terminated SOONO.A L . CROW.W T Uranium Fuel Licensing Branch 80/06/19 3pp
- 8007170131 Forwards 1E Circular 80-14. "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel "No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/24

DOCKET 70-1333 METROPOLITAN EDISON CO

- 8007ii0007 Responds to FDIA request for all indemnity agreements, insurance policies & associated info between util,NRC &/or AEC re facility forwards documents listed in App A FELTON,J M Division of Rules and Records 80/06/23 7pp
- --B007110015 Forwards Amend 1 to Indomnity Agreement B-64 W/o encl MILLER,J G Metropolitan Edison Co 74/04/03 ip

í

- --B007110022 Forwards amend to indemnity agreement effoctive 740301 reflecting amend to 10CFR140, "Financial Protection Requirements & Indemnity Agreements " Amend increases nuclear energy liability insurance to \$110 million SALTZHAN.U Atomic Energy Commission. Directorate of Licensing 74/03/08 1p

DOCKET 70-1359 IRT CORP

- 8007240098 Amend 14 to License SNM-1405; changing expiration data to 811031. PAGE.R O. Urenium Fuel Licensing Branch 80/06/26 ip

DOCKET 70-1489 QDGOYEAR AEROSPACE CORP

8007170623 Forwards IE Circular 80-i4, "Radioactive Contamination of Plant Demineralized Mater 80s & Resultant Internal Contamination of Personnel "No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/06/24 is.

DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO

- 9007240282 Issues Amend 8 to License SNM-1503, authorizing use of neutron sources & specifying expiration data of 801231 or data of conversion of CPPR-30 to OL or whichever comes earlier
 PAGE, R O Uranium Fuel Licensing Branch 80/06/30 2pp
- --B007240270 Discusses B0010B & 0404 iicense amend applications requesting authorization to store neutron sources & extension of license expiration date Amend requests should be approved DELAMEY, J. C., CROW, W T Uranium Fuel Licensing Branch 80/06/30

DOCKET 70-1739 TRI-BTATE MOTOR TRANSIT CO

8007020305 Advises of approval of 800530 request for temporary amend to BNM Security Transportation Plan II Vendor itr to be withheld (ref iOCFR2 790)
MCCORKLE, Q W Physical Security Licensing Branch 80/06/09 ip

DOCKET 70-1869 RADIATION MANAGEMENT CORP

- 8007170264 Add1 response to FOIA request for records concerning Hittman Nuclear & Development Corp.RAD Svcs.Inc & Radiation Mgt Corp Forwards balance of documents (142 pages) listed in app FELTON.J.M Division of Rules and Records 80/06/02 2pp
- —B007170322 Discusses IE Insp 75-01 of activities under Licenses 37-13129-01 & BNM-1324 on 751009 & forwards notice of violation NELSON,P R Atomic Energy Commission, Directorate of Regulatory Operations 75/10/20 2pp
- --B007170324 Natice of violation from insp on 751009 Noncompliance notedlicenses possessed excessive amount of Co-60 in unscaled spurces # Atomic Energy Commission, Directorate of Regulatory Operations 75/10/20 ip

- --8007170337 IE Insp Rept 75-01 on 690916 of activities under Licenses 37-13129-01 & SNM-1524 Noncompliance noted licensee eiceeded license authorization of 10 mCi of Co-60 in unsealed sources SLUBODIEN-M J. MCCLINTO(K.R O Atomic Energy Commission. Directorate of Regulatory Operations 69/09/16 6pp
- ~~800717034i Discusses IE Insp 77-0; of Licenses 37-i3129-0; & SNM-i524 on 771129 No noncompliance noted Major areas inspected procedures & representative records; interviews w/personnel, measurements made by inspector & observations MCCLINTOCK:R D Region i. Philadelphia, Fuel Facility & Materials Safuty Branch 78/01/03 2pp
- --8007170345 IE Insp Rept 77-01 on 771127 No noncompliance noted Major areas inspected organization, internal audits, training & employee instructions, radiation protection procedures, matls, facilities & instruments & receipt & transfer of matls HCCLINTOCK, R O Region i, Philadeiphia, Office of the Director 77/12/23 12pp
- --8007170349 IE Insp Rept 78-01 on 780228 No noncompliance noted Major areas inspected circumstances re loss & recovery of contaminated resin drum including examination of procedures & representative records
 COBTELLO,F, MCCLINTOCK,R O Region i, Philadelphia, Office of the Director 78/03/06 ilpp
- --8007170407 Discusses Insp Rept 78-01 of Licenses 37-13129-01 & 8NM-1524 on 780228 No noncompliants noted Major areas inspected loss & recovery of contaminated resin drum including examination of procedures & representative records MCCLINTOCK.R O Region i, Philadeiphia, Office of the Oirector 78/03/13 2pp

DOCKET 70-2000 MT SINAI HOSP HARTFORD, CT

- 8007230597 Ack receipt of 8006ii itr informing NRC of ateps taken to correct violations noted in IE insp of Licenses 06-14734-01 & ENM-1559 on 800424 KINNEMN.J D Region i. Philadelphia. Fuel Facility & Materiais Safety Branch 80/06/25 ip
- --8007230501 Responds to NRC 800527 itr re violations noted in IE insp of Licensus 06-14737-01 & SNM-1559 on 800424 Corrective actions will perform routine hand & radiopharmaceutical preparation area surveys
 BRUNER, R B Mount Sinal Hartford, CT 80/06/11 2pp
- --B007230608 Discusses iE insp of Licenses 06-14734-01 & SNM-1559 on B00424 & forwards notice of violation CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch B0/05/27 2pp
- --B0072306ii Natice of violation from insp on B00424 Noncompliance noted failure to conduct routing radiopharmaceutical & hand surveys
 - * Region 1. Philadolphia, Office of the Director 80/05/27 ip

DOCKET 70-2153 UNITED NUCLEAR CORP

- 8007240383 Responds to 800623 request for meeting w/NRC to discuss decommissioning of United Nuclear Corp Wood River Junction, RI operation NMSB personner will meet w/Governor's ofc on 800708 & attend public meeting later in Charlestown, RI AMEARNE, J F Commission 80/07/02 ip
- --B0072403B9 Requests meeting w/NRC to discuss concerns re developments affecting operations at & decommissioning of United Nuclear Corp Wood River Junction, RI operation List of questions to be discussed encl OARRAHY. J J Rhode Island, State of B0/05/23 ip

DOCKET 70-2175 UNITED NUCLEAR CORP

- BO07240383 Responds to B00623 request for meeting w/NRC to discuss decommissioning of United Nuclear Corp Wood River Junction. RI operation NMS8 personnel will meet w/Governor's ofc on B00708 & attend public meeting later in Charlestown.RI AHEARNE.J F Commission B0/07/02 1p
- --B0072403B9 Requests meeting w/NRC to discuss concerns re developments affecting operations at & decommissioning of United Nuclear Corp Mode River Junction, RI operation List of questions to be discussed encl
 GARRHY, J J Rhode Island, State of B0/05/23 ip

DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO

B007230056 Natifies util that License SNM-1667 is amended in accordance w/800625 application.extending expiration date until 801231 or upon conversion of CPPR-69 to OL-whichever is earlier PAGE.R O Uranium Fuel Licensing Branch 80/06/30 ip

--B007230062 Safety evaluation re 600625 application to amend license.
extending exprastion date until B01231 Extension is needed
to complete remainder of NRC faculity licensing process
Recommends approval of application
DELANEY.J.C. CROH.W.T. Uranium Fuel Licensing Branch B0/06/30
ip

DOCKET 70-2478 TRANSNUCLEAR, INC.

B007070003 Forwards IE Insp Rept 70-2478/80-03 on 800417-18 & 22-23 No noncompliance noted KENNA.W B Region 2. Atlanta, Safeguards Branch 80/05/09 2pp

--8007070005 IE Insp Rept 70-2478/80-03 on 800417-18 & 22-23 No noncompliance noted Major areas inspected physical protection of irradiated fuel in transit Details withheld (ref 10CFR2 790)
MDORE, D E Region 2, Atlanta, Office of the Director OlllESPIE, F P Region 2, Atlanta, Safeguards Branch 80/05/09 to

8007030004 Partial response to FBIA request for documents re transportation of spent nuclear fuel from Portsmouth.VA to Alken.8C Forwards listed documents Other documents available in PBR NRC review of request is continuing FELTON.J M Division of Rules and Records 80/06/23 ip

--8007030011 Confirms 800318 teleon re notification of NRC required by Condition 5 of License 15NM-01498 STONEBURNER.W Transporter, inc 80/03/18 1p

--B007030014 Confirms B00318 teleon re notification of NRC required by Condition 5 of License ISNM-01498 Pegase Cask 2 contains 35 irradiated fuel elements & is scheduled to arrive at Portsmuth, VA on B00416 BTONEBURNER, W Transnuclear, Inc 80/03/18 ip

--8007030020 Confirms on 800416 telcon re notification of NRC required by Condition 5 of License ISNM-01698 Essor flask contains 16 irradiated furl elements & is scheduled to arrive at Portsmouth, VA on 800309 BTONEBURNER. W Transpucieer, Inc. 80/04/16 is

8007310481 Response to FDIA request for documents re transportation of spent fuel from Portsmouth, VA to Savannah River Plant In Aikan, SC Encl info partially withheld safeguarding procedures & security sheasures (ref FDIA Examption 4) FELTON, J M Division of Rutes and Records 80/07/22 3pp

--8007310485 Confirms 800320 teicon notifying NRC that Pegase Cask 1 contains 36 fradiated fuel elements & will arrive in Portsmouth. VA Info partially withheld date of arrival (reffold Exemption 4) NRC fee determination enci 8TONEBURNER. W Transnuclear, Inc. 80/05/20 2pp

--8007310496 Confirms 800521 telcon notifying NRC that Pegase Cask 4 contains one irradiated fuel plement & will arrive in Portamouth.VA info partially withhold date of arrivalirsf FOIA Examption 4) NRC fee determination encl STONEOURNER, W. Transnuclear, Inc. 80/05/21 2pp

DOCKET 70-2574 CARLIBLE HOSP CARLIBLE, PA

8007010597 Discusses IE Insp Repts 30-00472/80-01, 30-03018/80-01 & 70-2374/80-01 on 800522 of activities under Licenaes 37-02385-01, 37-02385-02 & SNM-1762 No noncompitance noted Hajor areas inspected air supply & exhaust sys CROCKER.H W Region i. Philodelphia, Office of the Director 80/04/02 2pt

DUCKET 70-2609 COMMONWEALTH EDISON CO

8007020429 Amends License GNM-1802, extending expiration date until 810630 in response to util 800403 request PAGE.R G Uranium Fuel Licensing Branch 60/06/13 ip. --8007020431 Discusses 800403 amend application for License 2004-1802 requesting extension of expiration date until 810630 Recommends license extension DELANEY, J. C. Uranium Fuel Licensing Branch 80/04/13 Xp

8007150092 Forwards IE Insp Rept 70-2609/60-01 on 800624 No noncompliance noted HIND.J A Region J. Chicago. Baieguards Branch 80/07/02 2pp

--BOO7150094 IE Insp Rept 70-2409/80-01 on BOO424 No noncompliance noted Major areas inspected security procedures & organization, previous items of nuncompliance & communication Details withheld (ref 10CFR2 790)
PIRTLE, Q L , KNICELEY, J R Region 3, Chicago, Office of the Director HNDD, J A Region 3, Chicago, Bafeguards Branch 80/07/01

DOCKET 70-2423 HODUINE SPENT FUEL POOL, DUKE POWER CO

8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Quiton County,NC Urges transportation via Interstates 77 & 85 Encourages expending energy & money for retycling Mcorrespondence & Caston County,NC 80/04/28 61pp

--8007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided OASTON, H B Gaston County, NC 80/04/23 2pp

--B007140488 Forwards position of Caston County Board of Commissioners. NC.opposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNE.C A Caston County.NC 80/04/15 ip

8007180510 Forwards responses to Pages 4-6 of Oaston County Board of Commissioners 800428 questions addressed to ARLB re util appilication to transfer & store spent fuel from Oconee Nuclear Station ROBERTS.JP Advanced Fuel & Spent Fuel Licensing Branch. 80/06/25 1300

B007230706 Forwards response to questions contained in B00428 position document Responses concern safe transport & storage of spent fuel RDBERTB.J P Advanced Fuel & Spent Fuel Licensing Branch 60/06/25. 12pp

8007280045 Ack receipt of 800702 ltr forwarding spent fuel transportation security glan. Revision 3 Request for proposed primary route is subj to fee Will notify of amount WE186.D License Fee Management Branch 80/07/17 lp

DOCKET 70-2651 MANCHESTER MEMORIAL HOSP MANCHESTER, CT

8007150314 Act receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE Rept 70-2651/80-01 CROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/04/10 lp

--8007150318 Responds to NRC 800220 ltr re violation noted in IE Insp Rept 70-2651/80-01 W/g encl corrective actions ABBOTT, W S Manchester Memorial Hosp Manchester, CT. 80/02/27

--B007150325 Forwards notice of violation from IE Insp Rept 70-2651/80-01 on B00207 MCCLINYOCK:R O Region i, Philadelphia, Fuel Facility & Materiais Bafety Branch 80/02/20 2pp

--BD07150302 Notice of violation from insp on 800207 Noncompliance notedfailure to continue followup on patient in whom pacemaker was implanted during Jul 1977 * Region J. Philadelphia. Office of the Director 80/02/20

.

DOCKET 70-2838 CINCINNATI CAS & ELECTRIC CO

BOO7010189 Notifies util that Item 4 of License SNM-1823 is amended in accordance w/600410 request Expiration date for license is extended until 811130, PAGE.R. 9 Uranium Fuel Licensing Branch 80/06/13 ip

-B007010195 Bafety evaluation recommending approval of 800410 ficense amend application Application requests that expiration date for License BNN-1823 be extended until 811102

DELANEY, J C . PAGE, R G Uranium Fuel Licensing Branch 80/06/13 is

DOCKET 70-2860 BOUTH CAROLINA ELECTRIC & GAS CO

BOO731042B Application for renewal of License SNM-1834 NICHOLS.T C South Carolina Electric & Gas Co 80/07/28 1p

DOCKET 70-2005 COMMONWEALTH EDISON

8007010094 Advises of Amend 2 to License SNM-1833, extending expiration date to 820331 or conversion of CPPR-100 to OL, whichever is earlier PAGE.R. Q Uranium Fuel Licensing Branch 80/06/13 ip

--B007010184 Bafety evaluation supporting approval of util 800403 request to extend License BNM-1833 to 820331 due to const & licensing delays
DELANEY, J C , CROW, W T Uranium Fuel Licensing Branch 80/06/13

DOCKET 70-2902 NORTH MEMORIAL MEDICAL CENTER MINNEAPOLIS, MN

B007270024 IE Insp Findings & Licensee Ack dtd B00609 of License BNH-1834 Insp findings no noncompliance noted BLRGIN,R E. Region 3, Chicago, Office of the Director B0/06/09

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

8007020038 Responds to 800409 request for list of threatened & endangered species in vicinity of proposed plant Endangered species most likely to accur is American alligator (mississippiemsis)
HICKMAN, O. L. Interior, Dept of, Fish & Wildlife Service 80/05/22

9007020514 Forwards comments & questions re environ rept per 600521 discussion in Bilver Spring, MD Requests that responses be submitted by 800710 to maintain review schedule SHUMLE, Y Uranium Fuel Licensing Branch 80/06/03 lipp

BOO7010027 Responds to BO042: Itr requesting scoping meeting to accept add1 public comments on DEB re proposed const & operation of Mestinghouse plant Another meeting is not warranted. Required expense & effort would not outweigh any benefits CROW.W T Uranium Fuel Licensing Branch BO/06/06 2pp

BOO7110003 Amended petition to intervene & request for hearing re AL nuclear fuel fabrication plant application Certificate of Svc.designation-authorizations in lieu of notice of appearance & board of directors resolution and CAMPRELL, R. H. Bafe Energy Alliance HCPHILLIPS, J. McPhillips, J. BO/06/11 9pp

BO07110055 Motion for order relieving petitioner from 20-copy requirement in AL nuclear fuel fabrication plant application proceeding due to limited resources Certificate of Svc encl
MCPHILLIPS, J. L. Safe Energy Alliance MCPHILLIPS, J. L. HCPhillips, J.L. 80/06/12 2pp

8007030291 Response in support of Safety Energy Alliance of Central AL. Inc 800612 petition to intervene re SNM license application for AL plant near Prattyille. AL Intervention must be conditioned upon showing of common interests TURK. B. E. Hearing Branch 1 80/07/02 13pp

---B007030294 Response in support of Safety Energy Alliance of Central AL, Inc B00612 motion requesting relief from 20 conformed copies filing requirement. Recommends order containing spec of those to be serviced W/Certificate of Svc TURK B E Hearing Branch 1 B0/07/02 4pp

8007250456 Forwards State of OR 770311 petition to intervens.NRC 770801 stipulation w/Portland general Electric & State of OR & ASLB 770920 order ruling on contentions Documents intended to serve as examples for drafting contentions W/o encis TURK, S.E. Hearing Branch 1 80/07/23 2pp

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

8007020230 Notifies of issuance of Amend 1 to License SNM-1861, increasing possession limit, authorizing use of high density fuel storage racks & incorporating specified organizational changes
PAGE.R G Uranium Fuel Licensing Branch 80/04/17 1p

--8007020233 Safety evaluation supporting Amend i to License SNM-18ái Increases possession limit authorizes use of high density fuel storage racks & incorporates specified organizational changes DELANEY, J.C., CROW, W.T. Uranium Fuel Licensing Branch 80/06/17 in

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 CHEM-NUCLEAR SYSTEMS, INC

800717047i Requests add1 info re GA program per 790427 Itr Requests reply within 30 days
MACDDNALD.C E Transportation Branch 80/07/03 ip

DOCKET 71-0005 MAGNAFLUX CORP

B007020044 Forwards GA program revised in accordance w/NRC B00509 ltr for Model MX-IC-100 exposure device Response to NRC NRC B00509 questions re GA program encl RDSAUER.P J Magnaflux Corp (subs of Peabody Galion Corp) B0/04/12 Ann

--8007020047 QA program for Model MX-1C-100 exposure device

Magnaflux Corp (subs of Peabody Galion Corp) 80/04/12
iloo

8007140706 Forwards GA program approval for radioactive matl package MACDONALD, C C Transportation Branch 80/07/01 ip

--8007140709 GA program approval for radioactive mati package QQQ5, Revision O MACDONALD,C E Transportation Branch 80/07/01 ip

DOCKET 71-0017 RHODE ISLAND ATOMIC ENERGY COMMISSION

B00721011B Responds to B00430 request for add1 info re GA program for BMI-1 shipping package & forwards QA manual DIMEGL10.A F Rhode Island, State of 80/07/01 ip

--B007210130 GA manual for BMI-i shipping package
* Rhode Island. State of B0/07/01 'sipp

DOCKET 71-0082 KERR-MOGRE NULLEAR CORP

8007170476 Requests addl info re QA program per 800131 ltr Requests reply within 30 days
MACDDNALD.C E Transportation Branch 80/07/03 ip

DOCKET 71-0109 UNION CARBIDE CORP

B007170480 Requests addl info re QA program per 790926 ltr Requests reply within 30 days
MACDDNALD, C E Transportation Branch 80/07/03 ip

DOCKET 71-0121 NEUTRON PRODUCTS, INC.

8007230349 Forwards Revision 3 to GA program SMEDIRA, G Neutron Products, Inc. 80/06/24 3pp

--B007230354 QA program,Revision 3 SHEDIRA.C , RANGOMOFF, J A Nautron Products, Inc BO/OA/24, 100pp

8007220099 Forwards QA program approval for radinactive mati package MACDONALD,C E Transportation Branch 80/07/10 ip

--8007220106 GA program approval for rodicactive matt package Ol21. Revision O MACDONALD.C & Transportation Branch BO/07/10 1p DOCKET 71-0139 TULSA GAMMA RAY, INC

8007210200 Forwards revised GA program
STEWART, N. L. Tulsa Comma Hay, Inc. 80/06/27 ip

--8007210205 GA program for radwaste packaging
* Tulsa Gamma Ray, Inc 80/06/27 3pp

8007240186 Forwards 8A program approval for radioactive matl package MACDONALD.C E (rensportation Branch 80/07/15 1p

--8007240193 (A program approval for radioactive matt package 0139, Revision O MACDUNALD,C E Transportation Branch 80/07/15 ip

DECKET 71-0143 RANCHERS EXPLORATION & DEV CD

B007170485 Requests addl into re GA program per 790427 1tr Requests reply within 30 days MACDDNALD, C.E. Transportation Branch GD/07/03 1p

DOCKET 71-0170 GENERAL ELECTRIC CO

8007280058 Requests extension until 801001 for implementation of QAP-1.Revision i Significant reduction in engineering & operating personnel procludes generation of program procedures
CUNNINGHAM.G F General Flectric Co 80/07/08 lp

DOCKET 71-0173 DATTELLE-PACIFIC NORTHWEST LADS

8007310013 Forwards QA program approval for radipactive mati package MACDONALD.C E Transportation Branch 80/07/31 ip

--8007310015 (A program approva) for radioactive mati package 0173. Revision 0 MACDONALD,G E Transportation Branch 80/07/11 ip

DOCKET 71-0179 NUCLEAR CONTAINERS, INC

80071704B7 Requests add1 info re OA program per 791009 ltr Requests reply within 30 days
MACDONALD.C € Transportation Branch 80/07/03 1p

DOCKET 71-0189 TODD SHIPYARDS CORP

BD07020026 Confirms that NRC considers 780626 application for GA program withdrawn Facility may not conduct transportation activities in Non-Agraement State per 10CFR190 20 MACDUNALD, C E Transportation Branch 80/06/17 lp

DOCKET 71-0192 NUCLEAR PACKAGING, INC.

B007280125 Advises that revised GA program description will be resubmitted by 800801 per 800701 telcon OLIVADDTI.J R Nuclear Packaging, Inc 80/07/01 ip

DOCKET 71-0221 ALLIS CHALMERS CORP

8007110014 Fprwards GA program für industrial radiography licensees OILL,S A Allis-Chalmers Corp 80/06/13 ip

--8007(100)6 QA program for industrial radiography dicensess * Allis-Chalmers Corp 60/06/13 3pp

NC

ing packages for radioactive c (subs of Getty Dil Co) ---B0071B04B3 GA program for shipping packages for radioactive Matl.
Revision 3
** Ruclear Fuel Services. Inc (subs of Getty Oll Co) 80/05/13

8007220055 Forwards GA program approval for radioactive matl package. MACDDNALD.C E Transportation Branch 80/07/10 1p

---8007220067 GA program approval for radioactive mat1 package 0249, Revision 0 MACDONALD,C E Transportation Branch 80/07/10 ip

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

8007240450 Forwards QA program approval for radioactive matl package MACDDNALD,C E Transportation Branch 80/07/09 1p

--8007240457 GA program approval for radioactive matl package 0251, Revision O MACDONALD,C E Transportation Branch 80/07/09 ip

DOCKET 71-0252 DAYTON X-RAY CO

8007010576 Forwards QA program approval for redirective matl package MACDONALD,C E Transportation Branch 80/06/12 1p

--8007010579 GA program approval for radioactive matl package 0252, Revision O MACDDNALD, C E Transportation Branch 60/06/12 1p

DOCKET 71-0271 RIDIHALOH, EGGERS & ASSOCIATES

B007170492 Requests addl info re QA program per 791019 ltr Requests reply within 30 days MACDDNALD.C E Transportation Branch 80/07/03 ip

DOCKET 71-0346 PUBLIC SERVICE CO OF COLORADO

E007140698 Forwards GA program approval for radioactive matl package MACDDNALD,C E Transportation Branch 80/07/01 ip

--B007140702 QA program approval for radioactive matl package 0346. Revision 1 HACDENALD.C E Transportation Branch 80/07/01 1p

DOCKET 71-0348 BRANCH RADIOGRAPHIC LABORATORIES

ED07290929 Forwards Revision 1 to GA program for industrial radiography
BRANCH.W H Branch Radiographic Laboratories. Inc. 80/07/11 ip

DOCKET 71-0370 AMEREHAM CORP

BOD7290932 Forwards GA program for packaging radioactive matls, BELGRAIR.D P Amersham Corp 80/07/14 1p

DOCKET 71-0371 MODEL NNFD-10, UNIFIED NUCLEAR CORP

8007230053 Forwards request for add1 info to complete review of GA program MACDOMALD, C.E. Transportation Branch 80/07/10 3pp

DOCKET 71-0381 E L CONWELL & CO

E007020650 Forwards GA program for transportation of licensed matls, in response to NRC 800416 ltr CAPPER.W E E L Conwell & Co 80/06/04 lp

- -- B007020552 GA program for transportation of licensed matls
 Organizational chart for industrial radiography encl

 * E L Conwell & Co 80/05/04 3pp
- 9007020518 Forwards 0A program approval for radioactive mat1 package MACDONALD, C E Transportation Branch 80/06/17 1p

DOCKET 71-0383 MODEL NLT 1/2 LWT CASK, NL INDUSTRIES, INC

- BOO7230025 Responds to NRC 800418 & 0508 ltrs re QA program Radioactive matts shipped pursuant to 10CFR50.App B GA program satisfies provisions of 10CFR7; 5: Date of approval concurrent \(\times \) approval date of license LUADVALL.A E. Baltimore Gas & Electric Co 80/06/19 1p
- 8007240175 Forwards GA program approval for radioactive matl package MACDONALD, C E Transportation Branch 80/07/15 1p
- --8007240179 GA program approval for radioactive matl package 0383. Revision 0 McCDONALD, C E Transportation Branch. 80/07/15 1p

DOCKET 71-0384 NEW ENGLAND NUCLEAR CORP

- 8007010370 Forwards GA Program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/06/13 1p
- ---9007010974 GA program approval for radioactive matl package 0384, Revision O MACDONALU, C.E. Transportation Branch 80/06/13 1p

DOCKET 71-0387 MASSACHUSETTS MATERIALS RESEARCH, INC

- B007070061 Forwards GA program approval for radioactive matl package MACDONALD.C.E. Transportation Branch 80/06/12 1p

DOCKET 71-0389 GEORGIA, UNIV OF

- BOO7100349 Forwards GA program for handling, storage & transportation of shipping containers MUBC.L A Georgia, Univ of, BO/O6/17 1p
- 9007160322 Forwards GA program approval for radioactive mat1 peckage MACDONALD.C E Transportation Branch. 80/07/01 ip
- --8007160335 GA program approval for radioactive matl package 0387, Revision 0, HACDOMALD: C E Transportation Branch 60/07/01 ip

DOCKET 71-0391 NAVY, DEPT OF

- 8007160310 Forwards GA program approval for radioactive mat1 package. MACDONALD, C E Transportation Branch 80/07/01 lp
- ---B007160317 GA program approval for radioactive matl package 0391, Revision O, MACDONALD, C E. Transportation Branch 80/07/01 1p

DOCKET 71-0392 BAKER TESTING SERVICES, INC

8007070128 Forwards GA program & shipping papers to accompany transported packages of radioactive matls
KENNETH, B F Baker Testing Bervices, Inc. 80/06/13 1p

- --8007070133 QA program for facility * Baker Testing Services, Inc. 80/06/13 4pp
- BO07160767 Forwards CA program approval for radioactive matl pack MACDONALD:C E *ransportation Branch BO/07/07 1p
- --8007160772 GA program approval for radioactive matl package 039 Revision 0 MACDDMALD.C E Transportation Branch 80/07/07 ip

DOCKET 71-0393 ALLIS-CHALMERS CORP

- 8007160343 Forwards GA program approval for radioactive matt pack MACDONALD.C E Transportation Branch 80/07/01 ip
- --8007160347 GA program approval for radioactive matl package 039 Revision O MACDUNALD.C E Transportation Branch 80/07/01 ip

DOCKET 71~4824 MODEL HA-10. BABCOCK & WILCOX CO

- BOO7230047 Notifies of expiration of Certificate of Compliance 48 for Model HA-10 To continue using package, should submit consolidated application & drawings MACDONALD.C E Transportation Branch 80/07/10 ip
- DOCKET 71-4888 MODEL SENTINEL-25A. B. C. CO. D. E. F. TELEDYNE
- 8007010240 Forwards fee for renewal of three certificates of compliance Requests renewal of current revision of Certificate of Compliance 4888 for 5-yr period ending 850731

 MCGREW J W Teledyne Energy Systems 80/06/13 ip
- 8007160381 Ferwards Revision 4 to Certificate of Compliance 4888 Model's Sentinel 29A, 25B, 25C, 25C3, 25D, 25E, 25F & LCG-25A, 25B & 25C MACDDNALD, C E Transportation Branch 80/07/07 2pp
- ~=8007160387 Cortificate of Compliance 4888. Revision 4. for Model Sentinel 25A, 25B, 25C, 25C3, 25D, 25E, 25F & LCG-25A, 25B & 25C MACDONALD, C E Transportation Granch 80/07/97 3pp

DOCKET 71-4986 MODEL RA-2, EXXDN NUCLEAR CO . INC

- 8007280077 Requests extension of expiration date to 801031 for Certificate of Compliance 4985 due to add1 time required for NRC approval of renewal application KAPLAN.A L. General Electric Co., Nuclear Energy Products Div 80/07/01 1p
- 8007160409 Forwards Revision 6 to Certificate of Compliance 4986 Models RA-1,RA-2,RA-3 & RA-J MACDONALD,C E Transportation Branch 80/07/07 2pp
- --8007160412 Certificate of Compliance 4986 Revision 6 for Model RA-2 RA-3 & RA-J MACDONALD.C E Transportation Branch 80/07/07 6pp
- B0072B071B Forwards Revision 7 to Certificate of Compliance 498/ Models RA-1.RA-2.RA-3 & RA-J shipping containers MACDDNALD.C E Transportation Branch B0/07/R1 2pp
- --B007280720 Certificate of Compliance 4986, Revision 7. for Mode RA-2, RA-3 & RA-J shipping containers MACDONALD, C.E. Transportation Branch 80/07/21 6pp

ł

DOCKET 71-5088 MODEL D34710-1, U S NUCLEAR, INC

- 8007100080 Advises that Certificate of Compliance 3088 for Mode D34710-1 expires on 800930 in order to continue using package, should submit renewal application & Fee MACDONALD, C E Transportation Branch 80/06/16 2pp
- 8007240157 Requests withdrawal of Certificate of Compliance 508 no longer has use for Model D24710-1 VOIGHT.AF Ames Laboratory, Energy & Mineral Resources Res Institute 80/06/24 ip ;

DOCKET 71-5341 MODEL NEP-55, BABCOCK & WILCOX CO

- BOO7G10533 Application to amend (ertificate of Compliance 334i.Revision 3, revising Itom 5 (a){2} re exceptions to DOT Spec 6M & deleting Item 6 Results of add1 testing including 30-ft drop test enci CORDANI, R A B R0/05/14 10pp Babcock & Wilson Cp . Naval Nuclear Fuel Div
- BOD7170093 Forwards Revision 4 to Certificate of Compliance 5341 for Model NFP-55 MACDONALD, C E Transportation Branch 80/07/07 Ip
- --B007170097 Certificate of Compliance 5341. Revision 4, for Model NFP-55 MACDONALD, C E Transportation Branch B0/07/07 2pp
- DOCKET 71-5480 MODEL RCC-1,-2,-3, WESTINGHOUSE ELECTRIC CORP
- B00711028i Forwards Revision 7 to Certificate of Compliance 5450 for Models RCC,RCC-1.RCC-2.RCC-3 & RCC-4 MACDDNALD.C E Transportation Branch B0/06/27 2pp
- --8007110290 Certificate of Compliance 5450 Revision 9, for Models RCC, RCC-1.RCC-2.RCC-3 & RCC-4 MACDONALD.C E Transportation Branch 80/06/27 5pp
- 8007240094 Application for amend to Certificate of Compliance 5450 extending expiration to 801031 Request necessary to assure shipments requiring IAEA authorization after 600731 D191AZZA.R P Westinghouse Electric Corp 60/06/27 Jp
- 8007180084 Notification of registration as user of Model RCC in response to request HACDONALD.C E Transportation Branch B0/07/09 ip
- DOCKET 71-5607 MODEL OF Y-2, GENERAL ELECTRIC CO
- 8007240090 Forwards Revision I to Certificate of Compliance 56077, suppl ADVANCED TO PROPERTY REPORTS IN THE CENTER OF COMMITTAINESS OF CHANGES TO PACKAGE

 ROSS.D & Energy.Dept of BO/06/20 App
- DOCKET 71-5748 MODEL DB-250-2, COMBUSTION ENGINEERING CO . INC
- 8007010101 Application for renewal of Certificates of Compliance 5768, 6387 & 658) for Models 88-230-2.60 & 51032-1, respectively Fee encl
 HICHEL. C Nuclear Fuel Services: Inc (subs of Getty Oil Co)
 80/05/22 ip
- --B007010106 Requests addl fees to 800022 application for renewal of Cortificates of Compliance 5768,6387 & 6581 MCISS,J D Litense Fee Management Branch 80/06/02 ip
- --8007010121 Forwards odd1 fees no 800522 application for renewal of Centificates of Compliance 5768,6387 & 6581 in response to NRC 800602 request MICHEL.C J. Nuclear Fuel Services, Inc. (subs. of Cetty Oil Co.) 80/06/13
- 8007220131 Forwards Revision 4 to Certificate of Compliance 5768 for Model BB-250-2 MACDONALD,C E Transportation Branch 80/07/10 2pp
- --8007220135 Certificate of Compliance 5768, Revision 4 for Model BB-250-MACBONALD, C E Transportation Branch B0/07/10 4pp

DOCKET 71-5926 MODEL 100. GENERAL ELECTRIC CO

- 8007110473 Forwards Revision 5 to Certificate of Compliance 5926 for MACDONALD, C E Transportation Branch 80/06/23 2pp
- --8007110476 Certificate of Compliance 5926 Revision 5, for Model 9E-100 MACDDNALD, C E Transportation Branch 80/06/23 2pp
- DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO
- 8007020500 Forwards Revision 4 to Certificate of Compliance 5942 for Model CE-700 MACDDNALD.C E Transportation Branch 80/06/18 2pp
- -8007020506 Certificate of Compliance 5942, Ravision 4. for Model **9E-70**0 MAGDDNALD, C E Transportation Branch 80/06/18 3pp.

POCKET 71-5957 MODEL BMI-1, ENERGY, DEPT OF

- 8007290iiO Application for renewal of Certificate of Compliance 5957 for Model BMI-1 shipping cask BAN encl BURIAN:R J Battelle Memorial Institute, Columbus Leboratories BO/06/11 5pp
- --8007250115 "SAR for Model BMI-1 Shipping Cask," Revision A Oversize drawings encl

 # Hattelle Memorial Institute, Columbus Laboratories, 80/03/28
- 8007020003 Requests registration as user of Model SN-1 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/06 ip
- 8007020001 Requests registration as user of Model BMI-1 SYLVIA:B R Virginia Electric & Power Co 80/04/10 1p
- DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO
- 8007220113 Forwards Revision 2 to Certificate of Compliance 5971 for Model QE-200
 MACBONALD, C E Transportation Branch 80/07/09 2pp
- --8007220125 Certificate of Compliance 5971, Revision 2, for Model GE-200. MACDONALD, C E Transportation Branch 80/07/09 3pp
- DOCKET 71-5979 MODEL 5979, ALPHA-OMEGA SERVICES, INC
- BOO7280151 Forwards application for Revision 2 to Certificate of Compliance 3977 consolidating original application & subsequent supplix referenced in certificate BECK,E J Alpha-Dmega Services, Inc. 80/06/30 2pp
- --80072B0195 Application for Revision 2 to Certificate of Compliance 9979; consolidating original application & subsequent suppls referenced in certificate * Alpha-Omega Services, Inc 80/06/30 150pp
- ---B0072B0160 "General Arrangement -- Contain * Alpha-Dmega Bervices Inc 60/05/16 Container
- --8007280165 "Container/Transfer Cask"

 * Alpha-Omega Services.Inc 80/05/18 ip
- --- B007280173 "Details Inserts (Turret) & End Caps Container/Transfer Alpha-Dmega Barvices, Inc 80/04/30 1p.
- ---B007280177 "Details Overpack & Pallet Ship/Transfør Cask." * Alpha-Omega Bervices,Inc. B0/05/21 ip.
- 8007230038 Forwards Revision 3 to Certificate of Compliance 5979 for Model 5979
 MACDONALD, C E Transportation Branch 80/07/09, 1p.
- --8007230040 Certificate of Compliance 5979, Revision 3, for Model 5979 MACDONALD.C.E Transportation Branch 80/07/09 2pp.

- DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO
- 9007010395 Requests issuance of Certificate of Competent Authority 5980 per 1973 IAEA regulations for Model 600 shipping container Issuance will restrict foreign shipments to special form matis & limit fissile contont of Pu & U-235 GUNNINOHAM,O E General Electric Co 80/05/14 58pp
- -8007010600 "Model 600 Shipping Cask "
 * General Electric Co 79/08/23 ip
- ---8007010602 "Special Control Drawing Model 600 Cask Seal " Sheet 1 " Owneral Electric Co 79/09/28 ip
- --B007010403 "Base Model 400 Cask "
 # Owneral Electric Co 79/08/24 ip
- --8007010605 "Jacket Hodel 600 Cask "
 * Qeneral Electric Co 79/09/28 ip
- 9007210041 Notifies that fee submitted w/791008 application for Revision 4 to Certificate of Compliance 5780 will be partially refunded in accordance w/manpower expenditures review MILLER, W.O. License Fee Management Branch 80/07/01 ip
- DOCKET 71-5998 MODEL GE-400, GENERAL ELECTRIC CO
- 8007210583 Forwards Revision 2 to Certificate of Compliance 5998 for MACDONALD, C E Transportation Branch 80/07/09 19
- DOCKET 71-6078 MODEL 927 At & C1. COMBUSTION ENGINEERING, INC.
- BO07020102 Forwards info & ravised drawings re C-E Model 927A1 & 927C1 containers in support of application for renewal of 791210 Cartificate of Compliance 6078 LICHTENBERGER.H C-E Power Systems BO/05/30 App
- --8007020109 *Bhipping Container " Sheet 1 or 4 * C-E Power Systems 80/05/27 ip

- -9007020115 "Strongback Assembly " Sheet 4 of * C-E Power Systems 776060 80/05/29
- BOO7110452 Forwards Revision 7 to Certificate of Compliance 6078 for Models 92761 & 92761 MACDONALD,C E Transportation Branch 80/06/23 ip
- -BO07110461 Certificate of Compliance 6079, Revision 7, for Models 927A1 ₺ 92701 MACDONALD, C E Transportation Branch, 80/06/23 2pp
- DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO
- 8007020495 Notification of registration as user of Model 8-2 in response to request MACDONALD,C E Transportation Branch 80/06/17 ip
- DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC
- BOO7140413 Forwards application for renewal of Certificate of Compliance 6294 for Model UNC-2901 shipping package ESKRIDGE.H E C-E Power Bystems 80/06/20 ip

- --8007140620 Application for renewal of Certificate of Compliance 6294 for Model UNC-2901 shipping package Three oversize drawings enc 1 C-E Power Systems 80/05/20 51pp
- B007240201 Forwards Revision 4 to Certificate of Compliance 6294 for MACDUNALD,C E Transportation Branch 80/07/15 2pp
- --B007240207 Certificate of Compliance 6294. Revision 4. for Model UNC-2201 MACDONALD, C E Transportation Branch 80/07/15 2pp
- DOCKET 71-4375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC
- 8007110245 Forwards Revision 8 to Certificate of Compliance 6375 for Model CNS 4-45 MACDONALD,C E Transportation Branch 80/06/23 3pp
- --8007110270 Certificate of Compliance 4375. Revisson 8. for Model CNS MACDONALD, C E Transportation Branch 80/06/23 3pp
- DOCKET 71-6387 MODEL 60. BATTELLE MEMORIAL INSTITUTE
- 8007010101 Application for renewal of Certificates of Compliance 5768. 6387 & 6581 for Models BB-250-2.60 & 51032-1.respectively Fee enc1 MICHEL,C J Nuclear Fuel Services, Inc (subs of Getty Gil Co) 80/05/22 ip
- --8007010106 Requests add1 fees re 800922 application for renewal of Certificates of Compliance 9768.6387 & 6981 WEISS,J D License Fee Management Branch 80/06/02 ip
- ---800701012! Forwards add1 fees to 800322 application for renewal of Certificates of Compliance 3760,6387 & 6581 in response to NRC 800602 request MICHEL, C J 80/06/13 Nuclear Fuel Services, Inc (subs of Octty Oil Co)
- 8007140646 Forwards drawings in support of recertification of Model 60 shipping container SMITH F M Hanfor ntainer Hanford Engineering Development Laboratory — 00/07/02
- --8007140649 "Shipping Container Fuel Pin Model 60 Assay & Details " Sheet 1 of 7 * Hanford Engineering Development Laboratory 78/09/31
- --8007140654 "Bhipping Container Fuel Pin Model 60 Assay & Details " Bheet 2 of 7 * Hanford Engineering Development Laboratory 78/05/31 ip
- --B00714065B "Shipping Container Fuel Pin Model 60 Assay & Details "
- Bheet 3 of 7 * Hanford Engineering Development Laboratory 78/02/23 lp
- --8007140662 "Shipping Container Fuel Pin Model 60 Assay & Details " Hanford Engineering Development Laboratory 78/07/18
- --8007140666 "Shipping Container Fuel Pin Model 60 Assay & Details " Hanford Engineering Development Laboratory /8/07/18 ip
- --8007140668 "Shipping Container Fuel Pin Model &D Assay & Details " Sheet 6 of 7 * Hanford Engineering Development Laboratory 78/02/23 ip
- --8007140673 "Shipping Container Fuel Pin Model 60 Assay & Details " Hanford Engineering Development Laboratory 78/02/23. 1p
- --8007140678 "Pin Holder Assembly " Sheet 1 of 1 # Hanford Engineering Development Laboratory 78/09/29

1 p

- --8007140687 "Liner Shipping Container Fuel Pin Model 120 A Details " Sheet 1 of 2 * Hanford Engineering Development Luboratory 76/0
- --8007140690 "Liner Shipping Container Fuel Pin Model 120 p Sheet 2 of 2 * Hanford Engineering Development Laboratory 76/04/1.

- 8007220143 Forwards Revision 6 to Certificate of Compliance 6387 for Model 60
 MACDONALD, C.E. Transportation Branch 80/07/10 2pp
- --8007220152 Certificate of Compliance ASH7. Revision 6. for Model 60 MACDONALD. C E Fransportation Branch 80/07/10 5pp
- 8007280776 Forwards Revision 7 to Certificate of Compilance 6387 for Model 60 shipping package MACDONALD.C E Transportation Branch 80/07/23 2pp
- --8007280779 Certificate of Compliance A3B7.Revision 7.for Model 60 shipping package MACDONALD.C E Transportation Branch 80/07/23 Bpp
- DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8007100100 Responds to B00603 ltr re proposed QC Bpec 85-21 69 for insp of Model 6400 peckage Spec does not assure compliance QA program must be submitted re procurement maint ropair & use Acceptance criteria encl MACDONALD.C E Transportation Branch 80/06/17 12pp
- BDCKET 71-6568 MODEL LL-60-150, TVA
- 8007270008 Forwards Revision 1 to Certificate of Compliance 6568 for Model LL~60~150 shipping container MACDONALD,C C Transportation Branch 80/07/21 2pp
- ---8007290011 Certificate of Compliance 6568.Revision 1, for Model LL-60-150 shipping container, superceding Cortificate of Compliance 9033 entirely MACDONALD, C E Transportation Brench 80/07/21 3pp
- DOCKET 71-6581 MODEL 51032-1 & 1A. EXXON NUCLEAR CO. INC
- BOO7010101 Application for renewal of Certificates of Compliance 5768; 6387 & 6581 for Models BB-250-2,60 & 51032-1, respectively Fee and MICHEL,C J Nuclear Fuel Services, Inc. (subs. of Cetty Oil Co.) BO/05/22 is
- --B007010106 Requests add1 fees re B00522 application for renewal of Certificates of Compliance 5768,6307 & 6581 WEISS.J D License Fee Monagoment Dranch 80/06/02 ip
- --B007010121 Forwards add1 fees re B00522 application for renewal of Certificates of Compliance 5768,6387 & 6381 in response to NRC 800602 request MICHEL.C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) B0/06/13 ip
- B007100040 Forwards Revision 12 to Certificate of Compliance 6581 for Models 51032-1 & 51032-1a MACDDNALD,C E Transportation Branch 80/06/24 1p
- ---B007100041 Certificate of Compilance 6581. Revision 12. for Models B1032-1 & B1032-1 MACDONALD.C E Transportation Branch 80/06/24 App
- 8007160386 Requests Cartificate of Compliance 658) be extended for 3-month period until 801031
 HANSEN,L E Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 80706724 | 1p
- B007220046 Forwards request for add1 info re 790613 application requesting amend for Model 51032-1 & 51032-1a packages Info should be incorporated as revised pages into application MACDONALD.C E Transportation Branch 80/07/07 2pp
- DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLFAR ENGINEERING CO
- BOD7240155 Application to renew Certificate of Compliance 6679 BACR, T S Nuclear Engineering Co , Inc., (subs of Teledyne, Inc) BO/60/27 ip
- DOCKET 71-6597 MODEL 8500 PKG, GENERAL ELECTRIC CO
- 8007220039 Notification of registration as user of Model OE 8500 MACDONALD.C E Transportation Branch 80/07/10 ip

- DOCKET 71~6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 8007300001 "Safety Analysis of Modified NAC-1 Spent Fuel Shipping Cast" * Nuclear Assurance Corp NAC-E-801 R1 80/07/15 500pp
- BOO7020422 Forwards Revision 10 to Certificate of Compliance 665B for Model NFB-4
 MACDONALD.C E Transportation Branch 80/06/19 3pp
- --800702042B Certificate of Compliance 6698, Revision 10, for Model NFS-4 MACDONALD, C E Transportation Branch 80/06/19 6pp
- 8007180469 Application for revision of Certificate of Compliance 6698 to provide schedular flexibility in performance of inner shell measurements to include prenotification requirement to NRC of time & location of measurement operations

 JDHNSON.C R Nuclear Assurance Corp 80/07/03 2pp
- 8007280532 Forwards Revision 11 to Certificate of Compilence 6698 for Madel NFS-4 MACDONALD, C E Transportation Branch 80/07/14 3pp
- --B007280343 Certificate of Compliance 6698, Revision 11. for Model NF6-4 MACDUNALD C E Transportation Branch B0/07/14 6pp
- DOCKET 71-6717 MODEL 6717 D
- BOO7270277 Advises of name & address change from Contra Costa Industrial X-Ray Co in Martines, CA to Contra Costa Insp Go in Concord, CA DAMSDN:R S Contra Costa Inspection Co 80/03/01 1p
- ---B007290282 Requests registration as user of Model 533 DAWSON, R Contra Costa Inspection Co 80/07/01 ip
- BOO7220086 Notification of registration as user of Model 6717-B MACDONALD, C E Transportation Branch 80/07/10 1p
- DOCKET 71-9007 MODEL FL 10-1. GENERAL ELECTRIC CO
- BOO7110161 Forwards Revision 8 to Certificate of Compliance 9009 for Model FL 10-1 MACDONALD.C E Transportation Branch BO/O6/13 2pp
- --B007110166 Certificate of Compliance 9009. Revision 8, for Model FL 10-1 MACDONALD, C E Transportation Branch 80/06/13 4pp
- DOCKET 71-9010 MODEL NLI-1/2. NL INDUSTRIES. INC
- B0072B03i5 Requests Revision A to Certificate of Compliance 9010 to authorize shipment of PHR U oxide fuel assemblies HILLIAMS.C E NL Industries, NL Nuclear Div 80/06/23 3pp
- BOO7270016 Forwards Revision 7 to Certificate of Compliance 9010 for Model NLI-1/2 shipping package MACDONALD.C E Transportation Branch BO/07/16 2pp
- --B00729001B Cortificate of Compliance 9010, Revision 7, for Model NLI-1/2 shipping package, superceding Certificate of Compliance 9010 Revision 6 entirely MACDQMALD: C E Transportation Branch B0/07/16 5pp
- DOCKET 71-9015 MODEL TN-B, TRANSNUCLEAR, INC
- 8007020527 Forwards Revision 2 to Certificate of Compliance 9015 for Model TN-8 MACBONALD, C E Transportation Branch 80/06/18 1p
- --B007020532 Certificate of Compliance 9015, Revision 2, for Model TN-8, MACDONALD, C E Transportation Brench B0/06/18 3pp
- DOCKET 71-9016 MODEL, TN-9 , TRANSNUCLEAR, INC
- 8007020512 Forwards Revision 2 to Certificate of Compliance 9016 for Model TN-9 MACDONALD, C E Transportation Branch 80/05/18 ip

- --8007020517 Certificate of Compliance 9016 Revision 2 for Model TN-9 MACDONALD, C E Transportation Branch 80/06/18 4op
- POCKET 71-9019 MODEL BU-6, GENERAL ELECTRIC CO
- 9007290056 Advises of intention to ship radioactive mat1s from listed facilities using Package Model CNSI AL-33-90 MAYER.L C Northern States Power Co 80/07/03 lp
- DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO
- BOO7210043 Advises that fee submitted w/BOO314 application for Revisions 3 & 4 to Certificate of Compliance 9019 will be partially refunded in accordance w/manpower expenditures raview MILLER.W O License Fee Management Branch BO/07/01 ip
- DOCKET 71-9022 MODEL CE-250-2, COMBUSTION ENGINEERING CD . INC
- BOO7020107 Forwards add1 info supporting BO0111 renowal application for Certificate of Compliance 9022,prr NRC B00501 request Revised pages encl
 LICHTENDERGER.H C-E Power Systems 80/06/06 6pp
- ---8007020114 "Shipping Container" & C-E Power Bystems 7499-7/6030 79/06/13 ip
- 8007020484 Forwards Revision 4 to Certificate of Compilance 7022 for Model CE-250-2 MacDONALD, C. E. Transportation Branch 80/06/19 2pp
- --- 8007020583 Certificate of Compliance 9022, Revision 4. for Model CE-280-2 MACDONALD. C E Transportation Branch 80/06/19 2pp
- R007280211 Notifies that company no longer requires registration as user of Model CE-250-2 AUBTIN.M A Babcock & Wilcox Co , Nuclear Material Div 80/07/08
- DOCKET 71-9027 MODEL: 741, TECHNICAL OPERATIONS, INC.
- 8007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 1p
- DOCKET 71-9030 MODEL SENTINAL-8, 3, & MW-3000, TELEDYNE, INC
- 8007010245 Forwards fee for renewal of three certificates of compliance. Requests renewal of current revision of Certificate of Compliance 9030 for 5-yr period ending 850731.

 MCGREW, J. W Teledyne Energy Bystems 80/06/13 1p
- BOO7280561 Forwards Revision 2 to Certificate of Compilance 9030 for Models FM-3000. Sentinel-3 & Bentinel-8 MACDONALD, C E Transportation Branch 80/07/14 ip
- ---B007280565 Certificate of Compliance 9030.Revision 2.for Models MM-3000.Bentinel-3 & Bentinel-8 MACDONALD.C E Transportation Branch 80/07/14 2pp
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC
- 9007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 ip
- POCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC.
- BOO7030367 Requests registration as usor of Models 650,660,680 & 741 JOHNBON, M Navy, Dept of 80/05/27 ip
- DOCKET 71-9035 MODEL 680, TECHNICAL OPERATIONS, INC
- 8007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 ip

- DOCKEY 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC
- B007030375 Forwards consolidated drawings re 800520 ltr conterning application for renewal of Certificate of Compliance 7037 MUNRO.J J Tech/Ops (Technica) Operations. (nc.) 80/06/13 [p
- --8007030376 "Model 933 Projectol Descriptive Assembly " Sheet t of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/06 ip
- --8007030378 "Model 533 Projector Descriptive Assembly " Sheet 2 of 2 * Toch/Ops (Technica) Operations, Inc.) 80/06/06 1p
- ~-B007030379 "Model 713 Projector Discriptive Assembly " Sheet i of 2 * Tech/Ops (Technical Operations, Inc.) B0/06/09 ip
- --B007030381 "Model 713 Projector Descriptive Assembly " Sheet 2 of 2 * Tech/Obs (Technical Operations, Inc.) 80/06/09 in
- --B007030384 "Model 616 Gamma Ray Projector Descriptive Assembly " Sheet
 - i of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/03 ip
- ---8007030385 "Model 616 Gamma Ray Projector Descriptive Assembly " Sheet 2 of 2 * Tech/Ops (Technical Operations, Inc) 80/06/03 lp
- --8007030384 "Model 644 Iridium Pipe Crawier Descriptive Assembly " Sheet l of 2 * Tech/Ops (Technical Operations, Inc) 80/06/10 ip
- ---B007030387 "Mode) 644 Iridium Pipe Crawler Descriptive Assembly " Sheet 2 of 2 * Tock/Ops (Technical Operations, Inc.) 80/06/11 ip
- B007220279 Advises that registration as user of Model 715.as indicated in NRC B00520 ltr.is not necessary No radioactive matl shipped DAWSDN.R 8 Contra Costa Industrial X-Ray Co B0/06/16 lp
- 8007170178 Notification of registration as user of Model 713 in response to request MACDDNALD.C E Transportation Branch 80/07/09 1p
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- BOO7240200 Forwards Revision 5 to Certificate of Compliance 9044 for Model 0E-1600 MACDDNALD.C E Transportation Branch BO/07/15 3pp
- --8007240215 Certificate of Compliance 9044 Revision 5, for Model 9E-1600 MACDONALD, C E Transportation Branch 80/07/15 5pp
- DOCKET 71-9049 MODEL GE-500: GENERAL ELECTRIC CD
- 8007280575 Forwards Revision 2 to Certificates of Compliance 9049 for Madel GE-500 MACDINALD,C E Transportation Branch 80/07/14 tp
- --8007280580 Certificate of Compliance 9049. Revision 2, for Model GE-500 MACDONALD, C E Transportation Branch 80/07/14 2pp
- DOCKET 71-9053 MODEL 683, TECHNICAL OPERATIONS, INC.
- B007100373 Forwards application for renewal of Certificate of Compliance 9053 for Model 683 Type B MUNRO.J J Tech/Ops (Technical Operations, Inc.) B0/06/16 3pp
- --B007100376 Application for renewal of Certificate of Compliance 9033 for Model AGB Type B * Tech/Ops (Technical Operations, Inc.) 80/06/13 52pp
- 8007280698 Forwards Revision 2 to Certificate of Compliance (Model 683 MACDONALD, C.E. Transportation Branch 60/07/14 2pp
- --80072B0703 Certificate of Compliance 9053 Revision 2. for M MACDUNALD, C.E. Transportation Branch 80/07/14

- 8007290i16 Advises that Model 683 package.Certificate of Compliance 9053, meets IACA requirements
 MACDONALD,C C Transportation Branch 80/07/14 ip
- DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF
- BOO7160417 Requests registration as user of Model N-55 CORDETT, J S Chem-Nuclear Bystems, Inc. 80/06/26 1
- B00722007i Notification of registration as user of Model N-55 MACDDNALD, C E Transportation Branch 80/07/10 ip
- DOCKET 71-9000 MODEL HN-600, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8007180088 Notification of registration as user of Model HN-400 in response to request
 MACEDANALD, C E Transportation Branch 80/07/09 ip
- 8007280762 Forwards Revision 4 to Certificate of Compliance 9080 for Model NN-600 shipping package MACDONALD, C E Transportation Branch 80/07/21 3pp
- 8007030222 Natifies NRC of intention to ship radioactive matl from facilities using Model IN-Mon MAYER, C. O. Northern States Power Co. 80/06/13 ip
- DOCKET 71-7081 MODEL CNSI-1600, CHEM-NUCLEAR SYSTEMS, INC
- 800722049B Requests registration as user of Model CNBI 1-13C HERBEIN, J O Metropolitan Edison Co 80/07/ii 2pp
- DOCKET 71-9094 MODEL CNSI-14-195-H. CHEM-NUCLEAR SYSTEMS, INC.
- 8007100461 Submits payment for extensions of Certificates of Compliance 9094. Revision 5 & 9096. Revision 2 providing for required transition of gasket seal changes. CORRETT. J S Chem-Nuclear Systems. Inc 80/06/16 1p
- --8007100462 Requests payment for extensions of Cort)ficates of Compliance 9094. Revision 5 & 9096. Revision 2. providing for required transition of gasket seal changes WEIBS.D License Fee Management Branch 80/06/11 ip
- BOO7140242 Requests that all future correspondence be addressed to author CRANE.P A Pacific Oas & Electric Co BD/Oh/19 ip
- DOCKET 71-9094 MODEL CNS1-21-300: CHEM-NUCLEAR SYSTEMS: INC
- B0071004&1 Submits payment for extensions of Certificates of Compliance 9094. Revision 5 & 9096. Revision 2 providing for required transition of gasket seal changes CORDETT. J B Chem-Nuclean Bystems. Inc 80/06/16 ip
- --B007100462 Requests payment for extensions of Cortificates of Compliance 9094 Revision 5 & 9096. Revision 2. providing for required transition of gasket seal changes WEIBB.D. License Fee Management Branch B0/06/11 ip
- --- -- -9108 HODEL AL-33-90, ATCOR, INC
 - Requests registration as User of Model CNS 6-75 C Artanese Power & Light Co 80/06/27 ip
 - radinactive matls from listed -33-90 BO/07/03 to
 - PACKAGING, INC
 - for certificate of compliance 30/06/06 ip

- --B0070206B5 Revision 3 amends to Model NP-50xxL application, deleting stainless steel liner & including full-scale drop test rept * Nuclear Packaging, Inc B0/06/06 13pp
- 8007070177 Forwards Revision 3 pages to SAR (application) for Model NP-50xxL casks
 HANSEN,L J Nuclear Packaging, Inc 80/06/06 ip
- --B007070179 Revision 3 to pages BAR (application) for Model NP-50seL casks

 Nuclear Packaging, Inc. 80/06/06 9pp
- --B007070182 "Transportation Shield.Type A.Models 50-1 5L.50-2 5L. 50-3 OL & 50-4 OL " Sheet 1 of 2 * Nuclear Packaging, Inc 79/01/16 ip
- --8007070185 "Transportation Ghield Type A, Models 50-1 51.50-2 5L, 50-3 OL & 50-4 DL " Sheet 2 of 2 * Nuclear Packaging, Inc 80/04/06 1p
- 8007110464 Forwards Revision O to Certificate of Compilance 9130 for Model NP-50-2 SL MACDONALD.C E Transportation Branch 80/06/23 1p
- --8007110468 Certificate of Compliance 9130.Revision O.for Model NR-50-2 L HACDONALD, C E Transportation Branch 80/06/23 7pp
- DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC
- 8007240154 Requests registration as user of Model T-3 FITZSIMMONS, T Energy, Dept of 80/06/19 1p
- 8007220184 Requests registration as user of Hodel T-3 KEENEY, W P Argonne National Laboratory - Argonne West 80/06/27
- B007240212 Forwards Revision 1 to Cortificate of Compliance 9132 for Model 7-3 MACDDNALD.C E Transportation Branch 80/07/15 2pp
- ---B007240217 Certificate of Compliance 9132 Revision 1, for Model T-3 MACDONALD C E Transportation Branch 80/07/15 4pp
- DOCKET 71-9136 GENERAL ELECTRIC
- BOO7180460 Notified of minor corrections & clarifying changes to Drawing 908645. "OF Packaging Model 9136." originally submitted w/800331 approval request CUNNINGHAM.0 E General Electric Co BO/05/11 2pp.
- ---8007180470 "GE Packaging Model 9136" MUNIS General Electric Co 80/01/30 1p
- 8007220089 Authorizes delivery to carrier for transport of up to 30 hoods & giove boxes containing low level solid radwaste in accordance w/skatements & representations made in 800331 ltm. Safety systuation enci MACDONALD.C E Transportation Branch 80/07/02 lp
- --B007220097 Safety evaluation re delivery of up to 30 hoods & glove boses containing low level solid radioactive matl to carrier for transport in Model GE-9136 packaging MACDOANLD C E Transportation Branch B0/07/02 4pp
- DOCKET 71-9139 MODEL GE-589, GENERAL ELECTRIC CO
- BOO6190913 Forwards add1 info on Model 589 re application (NEDU-24613) for NRC certification for inclusion in BOO324 submittal Oversize drawings available in Central Files only CUNNINGMAM.O E Coneral Electric Co 80/05/29 44pp
- B006190921 "Lead Shielded Shipping Casks " # PX Engineering Co , Inc 80/05/07 ip
- 8006190923 "Lead Shielded Shipping Casks " # PX Engineering Co. Inc. 80/05/07 ip
- BOO6190925 "Lead Shielded Shipping Casks "
 # PX Engineering Co , Inc 80/05/05 ip

80072B0771 Forwards Revision O to Certificate of Compliance 9139 for Model 5B9 shipping package MACDONALD,C E Transportation Branch 80/07/22 ip

--B007280773 Certificate of Compliance 9139, Ravision O. for Model 589 shipping package MACDONALD, C E Transportation Branch 80/07/22 Spp

		1
		;
		1

```
COMMISSION MEETING RECORDS
 LOCFR
B007010022 Marked up transcript of 770331 Commission policy session in
Hashington, DC re NRC & intl physical protection stds
    Pp 1-28
# Commission 77/03/31 28pp
B007010589 Transcript of 800624 public meeting in Washington.DC to discuss ASLB rept on clearance rule Pp 1-49 L Dickwit 791109 memo to Commissioners and
                                         BO/06/24
                                                                    67pp
8007020150 Transcript of 800619 public meeting re briefing on rept on potential threat to nuclear activities from insiders & DOE study on effectiveness of security clearances Pp 1-50 Q Weisz statement & viewgraphs encl # Commission 80/06/19 89pp
8007030347 Transcript of 800626 public meeting w/representatives of Conference of Radiation Control Program Directors re Agraement States program in Washington, DC Pp 1-38 Morning sassion, Related correspondence encl
* Commission 80/06/26 40pp
8007070011 Transcript of 800625 public briefing for Commissioner
Gliinsky by AIF on Pinancial status of utils, in Washington,
BC Pp 1-67 Morning session Viewgraphs encl
* Commission 80/06/25 78pp
8007070013 Transcript of Affirmation Session 80~30 on 800626 in Washington, DC Pp i~4 Morning session * Commission 80/06/26 6pp
8007070016 Transcript of 800625 public meeting w/industry, state & local & special interest group panels on emergency planning & preparadness rulemaking & NRC response Pp i=131 Afternoon session Related statements & correspondence encl * Commission 80/06/25 600pp
8007090028 Transcript of 800516 open Affirmation Session 80-23 in Washington, DC re-order in Tarapur export Pp i-3 * Commission 80/05/16 4pp
--B007090030 Informs of correction to SECY-B0-238 re proposed exports of
fuel & components to Tarapur Commission SECY papers cited
are incorrectly referenced Draft memorandum & order enci
BHEA.J R Office of International Programs, Director 80/05/13
--8007090033 BECY-80-238A
Forwards NM98 technical review for Commission's consideration in conjunction w/review of pending Tarapur fuel & component exports
SMEA.J R Office of International Programs, Director 80/05/13
--8007090038 Forwards proposed NM9S technical review for Commission consideration re-proposed exports of fuel & components to
          Tarapur
BURNETT,R F Division of Bafeguards 80/05/12 App
8007090406 Transcript of 800421 closed meeting in Washington, DC re
US-Canada agreement Pp 1-4
* Commission 80/06/20 5pp
8007110142 Transcript of 800513 closed meeting in Washington, DC rediscussion of Tarapur export license Pp i-14 * Commission 80/06/19 14pp
8007110485 Transcript of 800710 briefing by Executive Branch on Intl Bafeguards in Washington, DC Pp 1-62 * Commission. 80/07/10 64pp
```

```
8007ii0494 Transcript of 79062! closed discussion re intl safeguerds matters in Washington DC Pp 1-47

* Commission 79/06/21 51pp
8007140065 Transcript of 800626 discussion of SECY-80-107 re proposed interim hydrogen control requirements for small containments in Washington, DC Pp 1-56 * Commission 80/06/26 58pp
 --B007140068 Requests participation in 800626 Commission meeting re
hydrogen control Substantial hydrogen generation is
effectively prevented in BWR due to unique inherent design
           Features
SHERWOOD, G G General Electric Co 80/06/23 1p
B007i40074 Transcript of B006iB staff presentation on final rulemaking on emergency preparedness in Washington, DC Pp i-90 Viewgraphs & FEMA B00602 ltr encl * Commission B0706/18 7lpp
--8007140079 Supports final rule on emergency preparodness Rule is consistent w/FEMA proposed procedures for review of state plans & preparedness NRC will be furnished copies of FEMA approval of state & local plans as appropriate

JETT, O Federal Emergency Management Agency 80/06/02 lp
B007140250 Transcript of 800626 Affirmation Session E0-31 in
Washington DC Pp i-9 Certification & disclaimer encl
* Commission B0/06/26 ilpp
8007140277 Responds to FOIA request for all info which directed or discussed any changes of proposed fire protection rule in SECY-80-088 App documents have been forwarded J Guibert 800311 memo withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records 80/06/26 2pp
 --8007140291 Staff requirement memo re 800423 open Affirmation Bassian
80-18 in Washington.DC Includes overall records of
Commission votes re SCCY 80-166.SECY 80-177 & SECY-80-088
CHILKIS J Office of the Secretary of the Commission 80/05/01
8007140491 Responds to FOIA request for rept on potential threat to nuclear activities from insiders, DOE study on effectiveness of security clearances & supporting documents used at 800619 briefing re repts Documents available at PDR, DOE & CIA FELTON. J Division of Rules and Records 80/07/10 kp
    -- BD07140504 Aunshine FR Notice of Commission meetings during wk of
           800616
            MAGEE.W Office of the Secretary of the Commission 80/06/16
8007140498 FOIA request for ropt on potential threat to nuclear activities from insiders, DOE study on effectiveness of security cloarances & supporting documents used at 800619 briefing re repts

COCHRAN. T. D. Natural Resources Defense Council 80/06/24
8007140389 Transcript of 790531 clused meeting re Task Force on NRC
Safeguards Policy Pp 1-40
* Commission 80/07/03 42pp
8007170282 Commission determination statement Submits list of portions of transcript of 790308 discussions to be withheld from public disclosure (ref 100FR9 104) CHILK.S J Office of the Secretary of the Commission 80/07/03
 ---8007170296 Transcript of Commission 790308 discussion re export matter in Washington, DC Pp 1-49 Portions withheld (ref LOCFR9 104) * Commission 79/03/08 49pp
```

- BOO7170315 Transcript of Commission BO0608 closed discussion retestamony to be given BO0611 in Washington, DC Pp 1-53
 * Commission BO706/CB 55pp
- 8007170527 Advises that Commission determined that transcript of 771019 briefing on special safeguards implementation repts should be withheld (ref 10CFR9 104) BIDYLE.J C Office of the Secretary of the Commission 80/07/08

- 8007170554 Advises that Commission determined that transcript of 770921 briefing on special safeguards implementation repts should be withheld per 10CFR9 104(a)(1) HOYLE.J C Office of the Secretary of the Commission 80/07/0
- 8007170587 Commission determination statement releasing portions of Transcript of Commission 771215 briefing by C Bennett in Washington.DC Pp 1-41 8 Commission 80706/30 43pp
- 8007170590 Unofficial transcript of Affirmation Bession 80-32 on 800703 in Washington, DC Pp 1-3 # Commission 60/07/03 5pp
- 8007i70597 Unoffical transcript of 800703 public meeting re NRC response to panel presentations on emergency planning in Washington, DC Pp 1-50

 w Commission 80/07/03 60pp
- --B007170604 SECY-B0-275B

 Proposes mods to FR & final rule changes on emergency
 preparedness submitted for Commission approval in
 SECY-B0-275 Changes do not effect cost estimates Replacement pages entl MINOGUE, R B Office of Standards Development, Director 80/07/02
- B007180027 Commission determination statement releasing portions of transcript of 770908 legislative testimony in Washington, DC Pp 1-113
 - Commission B0/07/02 114pp
- 8007180091 Transcript of 800131 Affirmation Session in Washington, DC
 - Pp 1-11 * Commission B0/01/31 12pp
- 8007240384 Unofficial transcript of 800715 briefing in Washington, DC re analysis of alternatives for conducting independent verification testing on environmentally qualified equipment
 - Pp 1-71 * Commission 80/07/15 74pp
- 8007240425 Transcript of Commissioners/ACRS joint meeting on 800711 in Washington, DC Pp 1-28 * ACRS Advisory Committee on Reactor Safeguards 80/07/11 30pp
- B007240439 Unofficial transcript of 800717 public meeting re safety issues in Washington.DC Pp 1-60 Handout encl * Commission 80/07/17 66pp
- BOO7240449 Unofficial transcript of BOO711 public meeting in Washington,DC to nuclear data link Pp 1-74 * Commission 80/07/11 77pp
- 8007230014 Transcript of 800711 Affirmation Session 80-33 re SECY-80-274 in Washington DC Pp 1-2 # Commission 80/07/11 3pp
- --8007250019 SECY-80-274 207230019 SECY-80-874
 Recommends approval of publication of regulations re
 implementation of IAEA requirements for licensees Draft FR
 notice & press release & summany of comments encl
 MINOQUE, R B Deffice of Standards Development, Director SHEA, J R
 Defice of International Programs, Director DIRCKS, W J Defice
 of Nuclear Material Safety & Safeguards 80/06/02 127pp

- B007300020 Transcript of B00527 public meeting on personnel dosimetry performance testing in Washington.DC Pp 176-275 * Commission B0/05/27 100pp
- 8007300024 Transcript of 800723 meeting in Washington DC re discussion & vote on emergency preparedness rule Pp 1-135 Supporting documentation entl
- 80/07/23 280pp
- B007300537 Bunshine FR notice of Commission 800721-23 open meetings in Washington DC for budget presentations THEED,R M Office of the Sacretary of the Commission 80/07/16
- B007300545 Sunshine FR hotice of Commission 800718 & 18 open meetings in Weshington, DC to discuss matters outlines, including identification of new & unresolved safety issues
 TWEED.R M Dffice of the Secretary of the Commission 80/07/10
- 8007300352 Sunshine FR notice of Commission 800715,21 & 22 meetings in Washington DC to discuss outlined matters including Browns Ferry problem, budget & export issue (closed session)
 TWEED.R M Office of the Secretary of the Commission 80/07/15
- ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- 8005150676 NRC is examining action plan items & judging applicability & scheduling which leave some sites w/o applicable criteria. PLESSET, M S ACRS Advisory Committee on Reactor Safeguards B0/05/04 2pp
- 8006160057 Discusses draft final rules 10CFR50 & 70 on emergency planning NRC-FEMA approach should be developed & implemented to encourage state & local agencies to incorporate federal efforts into their emergency planning PLESSET, M B ACRB Advisory Committee on Reactor Sefeguards 80706/11 2pp
- 8006300097 Responds to ACRS 800418 memo forwarding BL Cohen 800324 ltr re loss of water supply from refueling water storage tank Describes design provisions & operational security measures making total loss of water during LOCA unlikely DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/23 3pp
- --B006300112 Forwards draft of study, "Physics of Reactor Meltdown Accident " Requests review COHEN.B L. Pittsburgh, Univ of 80/03/24, 1p
- 8007010359 Summary of 242nd ACRS meeting on 800603-07 in Washington, DC Lists items scheduled for consideration at 243rd ACRS meeting on 800710-12 PLEBERTH H AGRS - Advisory Committee on Reactor Sefeguards SL-0251 80/06/19 3pp
- B007020215 Notice of change of date of ACRS Subcommittee on Concrete & Concrete Structures 800325-26 meeting New date is 800422-23 HOYLE, J.C. Office of the Secretary of the Commission 80/03/14
- 8007030340 Transcript of ACRS Subcommittee on Bafeguards & Security 800626 public meeting in Washington, DC Pp 1-129 Morning session Sandia Labs viewgraphs entitled. "Nuclear Power Plant Design Concepts for Babotage Protection," encl ACRS Advisory Committee on Reactor Safeguards. 80/06/26 175pp
- 8007030361 Transcript of ACRS Subcommittees on Waste Mgt & Fuel Cycle 800626 joint meeting in Washington, DC Pp i-32 Afternoon session ACRB - Advisory Committee on Reactor Safeguards 80/06/26, 33pp.
- 8007100149 Forwards meeting agenda for 242nd ACRS meeting on 800605-07 in Washington, DC ZECH, G G Technical Support Branch 80/05/19 5pp
- 8007110431 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 800701 meeting in Inglewood CA Pp 1-286 Slide presentation by Nuclear Safety Analysis Ctr encl - Advisory Committee on Reactor Bafeguards 80/07/01
- B007110435 Transcript of ACRS 800702 meeting in Inglewood,CA re Class 9 accidents Pp 1-329 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 80/07/02

i

NONDOCKETED ITEMS

- 8007140928 Summary of ACRS Subcommittee on ECCS 800325 meeting in Washington.DC re Westinghouse upper head injection adequacy ra ECCS model or small break LOCA's Supporting documentation
- ACRE Advisory Committee on Reactor Safequards 80/04/06
- 8007140531 Summary of ACRS Power & Electrical Sys Subcommittee 800407 meeting in Washington. DC re possible response to Gilinsky 800307 ltr re nuclear data lank in emergencies * ACRB Advisory Committee on Reactor Safeguards 80/06/06 10p
- --8007140540 Comments on nuclear data link sys between NRC & operating nuclear power plants Supports NUREG-0460 objective but does not agree w/utilization of data for issuance of NRC orders Industry input & need basis should be considered ANDERSON, T M Westinghouse Electric Corp NS-TMA-2228 80/04/09
- BO07140547 Bummary of ACRS Ad Hnc Subcommittee on NRC Action Plans
 Developed as Result of TMI-2 Accident B00401-02 meeting in
 Bethesda, HD re Draft 3 of NUREO-0660

 * ACRS Advisory Committee on Reactor Safeguards B0/06/07
- 8007150005 Transcript ACRB Subcommittee of Reactor Safety Research 800708 morning meeting in Washington.DC Pp 1-293 Supporting enc l ACRB - Advisory Committee on Reactor Bafeguards 80/07/08
- 8007190026 Transcript ACRS Subcommittee on Fire Protection 800709 afternoon meeting in Washington DC Pp 1-122 * ACRS Advisory Committee on Reactor Bafeguards 80/07/09
- BOO7150439 Summary of ACRB ATMB Subcommittee BOO326 meeting in Washington, DC w/NRC & industry representatives re resolution OP ATWÉ
- ACRB Advisory Committee on Reactor Safeguards 80/05/16 25pp
- 8007150443 Summary of ACRS Ad Hoc Subcommittee on NRC Action Plans Developed as Result of TMI-2 Accident 800305 meeting in Hashington, DC re near-term CL items identified in plan ACRB - Advisory Committee on Reactor Safeguards 80/04/05
- 8007170301 Transcript of ACRE Subcommittee on Advanced Reactors 800630 meeting in Los Angeles, CA Pp 1-262 Slide presentation encl ACRS - Advisory Committee on Reactor Bafeguards 80/06/30
- B007180002 Transcript of ACRB 243rd meeting in Washington, DC rs FY82 safety research budget & venting of TMI-2 containment Pp 1-246 Supporting mat1 enc1 * ACRB Advisory Committee on Reactor Bafeguards 80/07/10
- 8007180024 Summary of 235th ACRS mesting on 791108-10 in Washington, DC List of attenders, agenda & Apps 1 through 34 encl * ACR8 - Advisory Committee on Reactor Bafeguards 80709794
- 8007180028 Summary of 237th ACRS meeting on 800i10-i2 in Washington, BC List of attendess, agenda & Apps 1 through 24 encl * ACRB - Advisory Committee on Reactor Bafuguards 80/04/28
- 8007180603 Comments on revised draft emorgoncy plans proposed by NRC Offsite plan would be improved if coordinated through FEMA, w/other types of emergencies that occur more frequently HEALY, J W Los Alamos Scientific Laboratory 80/05/28 3pp
- B007210027 Comments on proposed rule, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule should be supplemented by reg guides to reduce range of interpretations Rule should not be condensed LIPINSKI,W C Argonne National Laboratory 80/06/19 3pp
- G007210029 Comments on ACRS Subcommittee on Concrete & Contrate Structures G00422-23 meeting Industry should be responsible for certain kinds of research NRC should suppl that effort by research related to own mission WHITE, M White, M P Consulting Engineer CCS-1 G0/05/25
- B007210050 Notice that closed sessions will not be necessary for previously announced ACRS subcommittee meetings listed Affected meetings include Safeguards & Becurity on B00426 & Waste Mpt & Fuel Cycle on B00428-27 HOYLE, J C Diffice of the Bacretary of the Commission B0/04/23

- 8007210139 Discouses development of valve blocks using zinc axide instead of vilien carbide Zinc oxide valve columns can be readily connected in parallel for increased thermal capacity Paper ie zinc oxide varistor protoctive sys encl JOHNSON: I S Affiliation Unknown 80/06/09 lipp
- 800/210332 Summary of ACRS BAW Whiter Reactors Subcommittee 800429 meeting in Washington DC re NUREG-0867. "Transient Response of B&W Designed Reactors"
 - ACRS Advisory Committee on Reactor Safeguards 80/06/05
- 8007210354 Responds to Commission 800401 ltr requesting clarification of ACRS concerns w/present reactor coolant pump trip & fift termination criterion Emphasis on immediacy of pump trip & on eventual automatic may not be desirable PLESSET.M S ACRS Advisory Committee on Reactor Safeguards 80/07/16 App
- 8007210523 Responds to Commission 800604 request for views on use of In-core thermocouples as aid in detection of off-normal conditions & in-accident enalysis Instruments displaying readings should be readily available in control rooms PLESBET, M S ACRS - Advisory Committee on Reactor Safeguards 80/07/16 2pp
- 8007210524 Bummary of ACRS Subcommittee on Regulatory Activities 800430 eting in Washington, DC

 ACRS - Advisory Committee on Reactor Safeguards 80/06/05 23pp
- B007210534 Summary of ACRS Subcommittee on Extreme External Phenomena 791115-16 meeting in Los Angeles,CA je metters concerning NAC research on external phenomena * ACRS Advisory Committen on Realthr Safeguards B0/03/25 36pp
- 8007210588 Summary of ACRS Subcommittee on Concrete & Concrete
 Structures 800422-23 meeting in Mashington DC re research,
 technical assistance & seismic safety programs
 * ACRS Advisory Committee on Reactor Safeguards 80/06/0
- 8007220057 Transcript of ACRS Subcommittee on Advanced Reactors 800709 meeting in Mashington.DC Pp 1-149

 * ACRB Advisory Committee on Reactor Sufeguards 80/07/09
- 0007230012 Natice of ACRS subcommittees & working groups' preliminary schedule of Jul-Bept 1980 proposed meetings HDYLE.J C Office of the Secretary of the Commission 00/06/17
- B007P30023 Notice of ACRS Subrummittee on Advanced Reactors E00709 meeting in Washington DC to discuss continued review of NRC funding b direction for annual ACRS repts 10YLE.J C Office of the Secretary of the Commission B0/06/19
- B00/230026 Notice of ACRB Subcommittee on Fire Protection 800709 meeting in Washington DC to discuss proposed fire protection rule for facilities operating prior to 790101 per SECY-80-80 HOYLE, J C Office of the Gerrotary of the Commission
- B007230070 Notice of ACRS Subcommittee on Class 9 Accidents B00702 meeting in Inglewood.CA to discurb Class 9 role in licensing processinged for degraded Love mitigation features & FYB1-82 NRC research budget for severe accident phenomena HDYLE.J C Office of the Berretary of the Commission 80/06/ii
- 8007230112 Notice of ACRS Subcommittue on Reactor Safety Research 800708 meeting in Washington, DC to discuss continued review of NRC research program MOYLE, J C Defice of the Sucretary of the Commission 80/06/18
- 8007230120 Notice of indefinite postponement of ACRS Subcommittee on ECCS 800624-25 meeting noted in 800607 FR HOYLE, J.C. Office of the Secretary of the Commission 80/06/11
- 8007230125 Notice of ACRS Bubcommittee on Reliability & Prubabilistic Assessment 800701 meeting to discuss continued evaluation of quantitative safety goals CHILK.6 J. Office of the Secretary of the Commission 80/06/10
- 8007230134 Notice of ACRS Bublimmitter on Advanced Reactors 800630 meeting in Inglewood. GA ro NRC funding & program direction CHILK. 8 J Office of the Secretary of the Commission 80

- 8007230729 Notification of ACRS 800710 meeting in Washington,DC to discuss proposed rept re NRC safety research budget for FY82
- HOYLE, J C Office of the Secretary of the Commission 80/06/19
- 8007240425 Transcript of Commissioners/ACRS joint meeting on 800711 in Washington DC Pp 1-28 * ACRS - Advisory Committee on Reactor Safeguards 80/07/11 30pp
- 6007240475 Comments on fire protection Reg Guide i 120 excess automation may present hazards greater than fire Flooding & coilepse of trays may be serious Water resistance of aged dry cables unknown EBERSDLE.J C ACRS Advisory Committee on Reactor Safeguards 76/08/16 2pp
- 8007250521 Franscript of 243rd ACRS meeting on 800711 in Hashington, DC Pp 460~586, Part 2

 * ACRS Advisory Committee on Reactor Bafeguards 80/07/11
- 8007300002 Transcript of ACRS 243rd meeting on 800711 in Washington, DC Pp 323-459 * ACRS Advisory Committee on Reactor Safeguards 80/07/11
- 8007300026 Transcript of ACRS 243rd meeting on 800710 in Washington DC Pp 247-322 Viewgraphs encl # ACRB Advisory Committee on Reactor Bafeguards 80/07/10 95pp

COMMISSION NRC COMMISSIONERS

1.1

- 7909110639 Responds to 790703 itr re approval of NRC actions HENDRIE. J M Commission 79/07/16 ip
- 7909260597 Responds to 790921 ltr re transport of raduaste from TMI & air shipment of nerve gas bombs from Co to UT States are not routinely notified of raduaste shipments DDD has jurisdiction over transport of nerve gas espiosive weapons HENDRIE. J M Commission 79/09/ii 12pp
- 800701027B Responds to 790306 memo re revised civil penalties proposal Suggests Section 234(c) be worded "Commission shall afford to person notified per subsection (b) apportunity for hearing " STGIDER: C R Office of the Coneral Counsal 79/03/08 5pp
- 8007010552 Responds to 791113 ltr requesting assessment of Washington Post 791111 article re "Radiological Assessment of WhYL Ruchear Power Plant " Dfc of Nuclear Reactor Regulation completing detailed review of rept AHEARNE, J F Commission 80702/20 4pp
- B007010354 Advises that Commissioner Bradford will assume speaking responsibility at B00924 ALl-ABA course on atomic energy licensing & regulation
 HENDRIE, J N Commission B0/06/ii ip
- 8007020023 Weekly info rept for wk ending 800613 REHM.T A Office of the Executive Director for Operations 80/06/18 28pp
- G007020129 Forwards response to questions in 800812 ltr re NRC resource allocations for FY81 & 82 Includes post-TMI licensing requirements, resource allocations for CP reviews vs OL reviews & number of OL reviews Processed AHEARNE, J F Commission 80/06/05 4pp
- BOO7020168 Requests response to J Hendries concerns expressed in 790226 memo re revised civil penalties legislative proposal KENNEDY, R f Commission 79/03/06 2pp

- 8007020325 Responds to Commission 800512 request for estimate of NRC & applicant resources needed to identify extent to which IL applications comply wicerrent NRC regulations Two addi mangres per application would be required by NRC & applicant DENION. H R Office of Nuclear Reactor Regulation, Director 80/06/13 dep
- --B007020331 Forwards procedure for documentation of deviations from SRP SERs issued after 770101 for plants under OL review & issued after 770801 for CP applications under review are to document deviations from BRP RUSCHE, B C Office of Nuclear Reactor Regulation. Director 76/09/20 | ilpp
- --B007020334 Forwards revised procedure for documentation of deviations from SRP, supersoding 760920 memo Procedure remains unchanged for CP reviews, but requires only limited licensee participation in OL reviews RUSCHE, B C Office of Nuclear Reactor Regulation, Director 77701/31 19pp
- B007020672 Ack receipt of invitation to participate in round table at concluding plenary session of inti conference on current nuclear plant safety issues in Oct 1980 Round table discussion is excellent idea HENDRIE.J M Commission 80/06/11 1p
- --B007020674 Notifies of B01020-24 inti conference on current nuclear plant safety issues in Stockholm, Sweden Conference will include round table discussion to identify current views & issues related to conference EKLUND, S International Atomic Energy Agency (Austria) 80/03/29 200
- 8007030355 Draft NRC reorganization plan. Number 1 of 1980 * Commission 80/05/01 App
- BOO70BO076 Comments on S 1860, Small Business Innovation Act of 1979, requiring Federal agencies w/research & doveloment budget in ercess of \$100,000,000 to establish small business innovation research program Discussion of problems onel AHEARNE, J F Commission 80/06/12 5pp
- 60070800B2 Requests comments on encl S 1840, Email Business Innovation Act of 1979, requiring federal agencies w/research & development budget in excess of \$100,000,000 to establish small business innovation research program NELSON, 6 Senate, Small Business 80/03/11 68pp
- 8007070104 Responds to Subcommittee on Nuclear Regulation 800901 ltr posing questions re Commission approach to foreign health & safety issues Commission issued decision on reactor export to Philippines on 800506 W/response to specific questions AHEARNE, J. F. Commission 80/06/06 lipp
- --8007090114 Order granting issuance of licenses to Westinghouse for export of reactor to Philippines Separate Commissioner opinions enci CHILK.S J. Office of the Secretary of the Commission 80/05/06
- 0007090122 Weekly info rept for Wk ending 800627 REHM.T A Office of the Czecutive Director for Operations 80/07/02 34pp
- 600711001B Weekly info rept for wk ending 800620 REHH.T A Diffice of the Executive Director for Operations 80/06/15 28pp
- 8007110266 Provides Subcommittee on Oversight & Investigations of detailed responses to questions re role & impact of GMB in administration of laws & NRC operation AHEARNEL F Commission 80/06/12 iOpp
- --8007110278 Requests response to questions or role & impact of DMB in administration of laws & NRC operation ECKHARDT,B House of Rep., Interst & Foreign Commerce B0/03/21 788
- --8007ii0282 Discusses legal basis for NRC budget referral to DMB W/ supporting documentation STDIBER.C R Office of the General Counsel 78/07/28 20pp
- --8007110296 Discusses interagency comments on NRC Mill Tailings Bill Includes matters raised by EPA: DOE & DOI 8TDIBER, C R Dffice of the General Counsel 78/06/22 14pp
- --B007110297 Statement of JF Ahoarns on President's Reorganization Plan 1 of 1980
 AHEARNE, J F Commission 80/07/08 8pp

- 8007ii0298 Responds to request for info re impact of Nuclear Nonproliferation Act institutional arrangements on decision about proposed U exports to India KENNEDY.R T Commission B0/06/13 ip
- 8007110377 Informs Subcommittee on Nuclear Regulation of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA &FL AMEARNE, J F Commission 80/06/24 2pp
- --8007110382 Informs Subcommittee on Environ Energy & Natural Resources of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AHEARNE, J F Commission 80/06/24 2pp
- --8007110387 Informs Subcommittee on Energy & Environ of status of Agreement State regulatory programs Programs in all 28 states determined adequate for CY77 Significant program deficiencies found in CA & FL AHEARNE, J F Commission 80/06/P4 2pp
- --B007i10392 Informs Subcommittee on Energy & Power of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AMEARNE. J F Commission 80/06/24 2pp
- --8007110393 Discusses status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY77 Bignificant program deficiencies found in CA & FL RYAN, R O Office of Management and Program Analysis 80/06/19 200
- B007110399 Provides Bubcommittee on Nuclear Regulation w/responses to B00620 questions re licensing & const of new onsite spent fuel storage pools
 KAMMERER, C Office of Congressional Affairs B0/06/24 11pp
- 8007110538 Provides Bubcommittee on Nuclear Regulation w/comments on actions taken in amending \$ 2358 Requested funds for casework personnel loan assistance program & TMI-related work are much needed Add comments forthcoming AHEARNE, J F Commission 80/06/25 2pp
- 8007140120 Responds to 800620 ltr re Commission 800616 statement of policy on TMI-related OL requirements Commission has no intention of restricting litigation of TMI-related issues Change would permit parties to raise more not fewer, issues AHEARNE, J F Commission 80/06/30 2pp
- 8007130829 Submits contribution to Commission decision process re access clearance rule for SNM by reviewing setting for decision, presenting abservations on state of record & legal issues & outlining principle aptions available BICKWIT, L Office of the General Counsel 79/09/11 17pp
- 8007160516 Weekly info rept for wk ending 800620 REHM.T A Office of the Executive Director for Operations 80/06/25 36pp
- 8007160716 Responds to request for NRC views on DDE legislative proposals re extension of NRC licensing authority over certain DDE facilities for radwaste mgt NRC does not support DDE proposals due to inconsistency w/NRC recommendations AMEARNE, J F Commission 80/06/16 7pp
- E007140B48 Expresses appreciation for 800522 ltr to NRC re future role of Ofc of State Programs Views expressed will be carefully considered in any reorganization which may affect Ofc of State Programs
 DIRCKS.U J Office of the Executive Director for Operations 80/06/04 lp
- --B007160B51 Expresses concern re future role of Ofc of Btate Programs
 Ofc is vital source of current info & regulations on nuclear
 power facilities in Northeast Urges continued operation of
 Ofc of State Programs
 LADD.E Massachusetts, State of B0/05/22 ip
- 8007140854 Expresses appreciation for 800523 ltr to NRC re future role of Ofc of State Programs Views expressed will be carefully considered in any reorganization which may affect Ofc of State Programs
 DIRCKS, V J Office of the Executive Director for Operations
 80/06/04 ip

- --8007160858 Explesses concern le future role of Ofc of State Programs Ofc has been of great assistance to State of CT in addressing several pressing nuclear-related issues Urges continuation of Ofc of State Programs FIT2PATRICK.T Connecticut, State of BO/05/23 Ip
- B007170415 Responds to request for views & recommendations re enrolled bill to authorize appropriations to NRC for FYBO Commission has reviewed & found bill acceptable Two notes technical corrections should be made AHEARNE.JF Commission 80/06/20 lp
- --8007170418 Requests views & recommendations re encl enrolled bill to authorize NRC appropriations for FY80 FREY, J M Office of Management & Budget 80/06/17 14pp
- 8007180029 Forwards comments made during South American Conference on Small & Medium Size Reactors in Montevideo, Uraguay refuture of nuclear power in US.in response to 800602 ltr MENNEDY; R T Commission 80706/12 lp
- ---B007180034 Comments on B00417 testimony before Subcommittee on Energy & Mater Development Majority of US utils employ good people, but attentions are diverted & diluted in responding to regulatory details

 LEE,8 Commonwealth Edison Co 80/05/02 Ip
- B007180036 Forwards Representative Udali 781128 itr re nuclear accident review board proposal ACRS should be asked to sot up suitable subgroup to make trial review of incidents & occurrences per H Lewis recommendation HENDRIE.J M Commission 78/12/05 2pp
- --8007180427 Comments on H Lewis suggestion for creation of nuclear accident review board adequate consideration has not been given to benefits that might result from analysis of AOs or other accidents by independent review group UDALL.M K House of Rep 78/11/28 4pp
- --B007iB0431 Requests views on encl H Lewis suggestion for improved nuclear accident analysis & prevention by creation of statutorily independent quasi-judicial board UDALL, M K House of Rep , Interior & Insular Affairs 78/01/27
- 8007180164 Declines invitation to participate in World Congress of Metallurgy in Lima, Peru Invitation passed to other members of Commission & NRC staff for anyone interested in attending Congress

 KENNEDY, R T Commission 80/05/08 ip
- --B007180169 Extends invitation to participate in World Congress of Matallurgy in Lima, Peru. 800616-21 DETETA, P.M., NAVARRO, C.C. Peru. 80/04/08 1p
- 8007180216 Ack receipt of 800303 itr commenting on talk given at Brown Univ on 800327 re energy & providing info on cancer risks KENNEDY.R T Commission 80/05/12 ip
- --8007180221 Commends 600327 speech at Brown Univ re energy Realisms are being instanuated into US energy considerations Provides info re UT cancer claims H/a encl LAPP.R E Lapp.Inc 80/05/03 lp
- BOO7/BOABB Ack receipt of BOO404 ltr providing brief description of proposed instrumentation sys for moasuring water level in core of PMR Addl exchange of info necessary to compare proposal w/others
 KENNEDY,R T Commission BO/03/28 App
- 8007180494 Ack receipt of 800623 ltr Nuclear power can achieve full potential & help to meet nath energy needs only of continuing dialogue between regulators & plant operators exists
 KENNEDY.R T Commission 80/06/30 ip
- --8007180579 Ack receipt of addl info on civilian nuclear power industry Nuclear power is vital to US & world energy needs Well-regulated & operated nuclear plant presents very low level risk LEE. B. Commonwealth Edison Co. 80/06/23 2pp
- E007180501 Expresses gratitude for valuable contributions to nuclear research over last 5 yrs KENNEDY,R T Commission 80/05/06 ip
- B007180544 Weekly info rept for wk ending 800703 REHM.T A Office of the Executive Director for Operations B0/07/10 20pp

- B0071B0550 Responds to B004iB telegram Gross arror in telegram should be corrected Reason for postponement of NRC B00421 meeting on Philippine export applications was that some Commissioners were not ready to release opinion on issues KENNEDY.R T Commission 80/05/22 lp
- 8007230224 Responds to FOIA request for H Denton 800613 memb to Commissioners entitled, "Compilance of CL Applications W/ Current NRC Regulations.Reg Guides & Branch Technical Positions 'Forwards memb FELTON.J M Division of Rules and Records 80/07/16 1p
- 8007230229 FOIA request for H Denton 800613 memo to Commissioners entitled. "Compliance of OL Applications W/Current NRC Regulations.Reg Ouides & Brench Technical Positions" WEISS.E R Sheldon, Harmon & Weiss 80/07/11 lp
- 8007230735 Ack receipt of 800512 itr re progress in cooperative efforts to reduce packaging & transport problems Full time inspicoverage at Beatty should be discontinued Contract retransportation surveillance will be forwarded shortly AHEARNE.JF Commission 80/06/12 1p
- --8007230739 Advises that full-time NRC inspector will no longer be needed at Beatty,NV waste disposal site State will provide appropriate insp surveillance as of 800401 LIST.R Nevada, State of 80/05/12 ip
- 8007230749 Responds to 800222 ltr re strengthening & clarifying federal laws related to physical security at nuclear facilities Comments on specific areas in ltr re sabotage guards, personnel selection & protection of safeguards info AHEARNE. J F Commission 80/06/12 12pp
- --B007230751 Expresses concern re physical security of nuclear facilities Neod to strengthen & clarify federal law exists in areas of sabotage guards personnel selection & screening & protection of safeguards info WALSKE, C Atomic Industrial Forum 60/02/82 4pp
- 8007240027 Ack receipt of 800609 ltr commenting on policy statement for TMI-related OL requirements Statement does not diminish intervenors present rights to litigate TMI-related (saues before ASL9 & ASLAB AHEARNE.J F Commission 80/06/30 2pp
- --8007240034 Ack receipt of 800607 ltr commenting on policy statement for TMI-related OL requirements Statement does not diminish intervenors present rights to litigate TMI-related issues before ASLU & ASLAB AHEARNE.J.F. Commission 80/06/30 2pp
- --8007240044 Comments on policy statement for TMI-related IIL requirements intervenors should be allowed to litigate TMIrelated issues HEIS3.E R Sheldon, Harmon & Weiss 80/06/09 3pp
- --B007240050 Comments on policy statement for THI-related OL requirements NRC fails to understand requirements of administrative due process JORDAN, W.S. Sheldon, Harmon & Weiss B0/06/13 4pp
- 8007240209 Heetly info rept for wk ending 800711 REHM.T A Office of the Executive Director for Operations 80/07/17 28pp
- 8007240480 Forwards description of actions re use of existing nuclear sites for new power plants & for radwaste storage, per OAO BOO401 rept recommendations W/o encl AHEARNE, J F Commission BO/07/10 1p
- --BOO7240481 Providet Bubcommittee on Energy & Environ w/description of actions re use of existing nuclear sites for new power plants & for radwaste storage, per GAO BOO401 rept recommendations W/O encl
 AHEARNE, J.F. Commission BO/07/10 pp
- --B0072404B3 Provides Subcommittee on Nuclear Regulation w/description of actions re use of printing nuclear sites for new power plants & for radwaste storage per GAD 800401 rept recommendations W/o enc?

 AMEAGNE-JF Commission 80/07/10 1p
- --B0072404B7 Provides Subcommittee on Energy & Power w/description of actions se use of existing nuclear sites for new power plants & for radwaste atorage, per GAD B0040) rept recommendations W/o encl AHEARNE.JF Commission B0/07/10 ip

1

- --B007240491 Provides Bubcommittee on Environ Energy & Natural Resources widescription of actions re use of dissting nuclear sites for new power plants & for reduceste storage, per GAD B00401 rept recommendations M/o encl.

 AMEARNELJ F. Commission 80/07/10 lp
- --B007240493 forwards description of actions reluse of existing nuclear sites for new power plants & for radwaste storage.per GAO B00401 rept recommendations W/o net AHEARNELJ F Commission B0/07/10 ip
- --8007/40476 Forwards description of actions re use of existing nuclear sites for new power plants & for indwaste storage,per GAD BOO401 rept recommendations M/o enci AHEARNE,J F Commission BO/07/10 ip
- --8007240497 Forwards description of actions re use of existing nuclear sites for new power plants & for radwaste storage.per GAD 800401 rept recummendations AHEARNE, J F Commission 80/07/10 Spp
- B007250007 Ack receipt of fl00523 ltr re new IAEA training program course Schodule commitments would limit availability to give requested informal lecture HENDRII. J N Commission 80/07/02 lp
- --B007250010 Extends invitation to give informal lecture on 800924 for new LACA nuclear power training program Course calendars & outline enci RBCRB.1 Argonne National Laboratory B0/06/23 ip
- 8007290029 Forwards Commissioner Konnedy lecture given at Brown Univ Ctr for Energy Studies. In response to request Mitre Corp study referenced in Konnedy lecture is C Zraket & M Scholl Oct 1779 "Solar Energy Bys & Resources" W/o encl SCIFERT. C & Commission 80/05/20 lp
- --1007250028 Requests written copy of 800'327 lecture presented before Brown Univ Ctr for Energy 'Studies Also requests identification of Mitre Corp study referenced in lecture CORTIOAN.J J Indiana State Univ 80'05'14 lp
- BOD7290079 Forwards "NRC Geminimus) Ropt to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "Congress should relieve NRC of responsibility for further repts due to other resource priorities W/o encl AHCARNC. J. F. Commission 80/07/09 [p.
- ---BOO72500DE Forwards "NRC Comiannual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "
 Gongress should relieve NRC of responsibility for further repts due to other resource priorities H/o encl AMEARNE.J F Commission 89/07/09 ip
- ---B0072500B5 Provides Bubcommittee on Energy Nuclear Proliferation & Federal Svcs w/ "NRC Beminimual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Evel Cycle Bys "
 H/o encl
 AHFARNE, J P Commission 80/07/09 ip
- --8007230089 Provides Subrommittee on Arms Control Oceans & Intl Environ of "NRC Seminnum! Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "NRC should be relieved of lesponsibility for further repts W/o encl AMFARNE.J F Commission 80/07/09 ip
- --8007250098 Forwards "NRC Beminimumal Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Bys "Congress should relieve NRC of responsibility for further repts due to other resource priorities We encl AMEARNE.J! Commission 89/0//09 by
- --8007230101 Provides Bubcommittee on Environ Energy & Natural Resources

 W/ "NRC Semiannual Rept to Congress on Status of Domestic &
 Intl Evaluations of Nuclear Fuel Cycle Sys "NRC should be
 relieved of responsibility for further repts W/o encl
 AMEARNE.J F Commission 80/07/09 ip
- --G007250105 Provides Bubcommittee on Energy & Power w/"NRC Semiannual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "NRC should be relieved of responsibility for further repts W/o encl AMFARNE.J C Commission 09/07/09 ip.
- --B007290114 Provides Subcommittee on Energy & Environ

 w/ "NRC Semiannum! Rept to Congress on Status of Domestic &
 Intl Evaluations of Nuclear Fuel Cycle Sys " NRC should be
 relieved of responsibility for further repts W/o gnc!
 AMEARNE, J Commission 60/07/09 ip

- --8007290137 "NRC Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys " # Commission 80/04/30 3pp
- 8007250111 Responds to Samford Univ 800627 invitation to speak on Cordell Hull Speakers Forum program Requests to be listed as possible speaker approx 801113 due to schedule commitments
 HENDRIE.J M Commission 80/07/07 ip
- --8007250117 Extends Invitation to speak on Cordell Hull Speakers Forum at Samford Univ during Sept-Nov 1980 WILLIAMS, J E , MILLER, J G Affiliation Unknown 80/06/27 1p
- --8007250215 Requests views on encl H R 6745, Radiation Control Act of 1977 BTA00ERS, H O House of Rep 80/03/21 12pp
- 8007250611 Discusses 800402 ltr to NRC stating that Figure 4 of SECY-80-107 is erronoous Thermodynamics of zirconlum-steam reaction were in fact considered in NRC calculations Discussion paper re thermodynamic considerations encl DENTON.HR Office of Nuclear Reactor Regulation, Director 80/05/29 12pp
- --8007250621 Expresses opinion that that Figure 4 of SECY-80-107 is erronoous because thermodynamics of zirconlum-steam reaction were not considered Supporting documentation encl LEYSE.R H Affiliation Unknown B0/04/02 20pp
- 8007290721 Response to Inquiry re BWR rollef valve discharge piping Requirements for fabrication & Inservice imap of containment components are being developed by ASME Code Containment Working Groups
 DENTON.M R Office of Nuclear Reactor Regulation. Director 80/07/07 3pp
- 8007280157 Rosponds to 800820 & 0513 ltrs expressing concern re procedures in proposed rulemaking on storage & disposal of nuclear waste Forwards 800528 order re working group to monitor development of record AHEARNE. J F Commission 80/06/12 lp
- B0072B0162 Ack receipt of Q00522 ltr expressing concern re future role of Ofc of State Programs NRC romains committed to preserving class working relations w/states & Conference AHEARNE, J. F. Commission 60/06/19 lp
- --8007280170 Forwards resolution requesting Commission proceed w/caution in deliberation & actions re reorganization of NRC Ofc of State Programs has provided agreement states w/info vital to programs & improved NRC/state relations PARROTT, M W Conference of Radiation Control Program Directors, Inc. 80/05/22 Zpp
- B007280722 Responds to B00121 request for rept on plans for full-time monitoring of vital nuclear power plant operations Presently planned resident inspector program in conjunction ω/nuclear data link will provide sound program Related data ancl ΑΗΕΑRΝΕ. J F Commission B0/06/12 Spp
- --8007280725 Requests views re desirability of installing nuclear data link & characteristics if installed GILINSKY,V Commission 80/03/07 ip
- --8007280729 Requests rept on full-time monitoring of vital nuclear power plant operations Resource requirements of plan should be specified Range of alternatives for insuring continued federal presence in control room should be provided * Office of Management & Budget 80/01/21 Jp
- 9007290347 Discusses NRC concerns re State of NM program for regulating U mills & mill tailings Lists provisions not approved by Environ Improvement Board which should be included in program to comply w/UMTRCA by 811111

 AMEARNE, J F Commission 90/05/12 3pp

- --B007290359 Discusses 4 mill regulations that should be adopted to enable State of NM to meet requirements of UMTRCA State should take action on differences between RTAX & Environ Improvement Div recommendations as discussed in encl KERR, G W Office of State Programs, Director 80/03/20 4pp
- B00730006B Ack receipt of 1tr expressing appreciation for NRC assistance in healing last fall Advises of Commissioner inability to attend SSEB meeting KENNEDY.R T Commission B0/05/06 ip
- --B00730074 Expresses appreciation for Commission assistance on emergency radiological planning environ monitoring & transportation hearings Final rept available from hearings CARYER, A R South (aroling, State of 60/04/24 lp
- 800730008B Weekly info rept for wk ending 800717 REHN.T A Office of the Czecutive Director for Operations 80/07/23 30pp
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 8007010380 Notification of contract execution.Mod 2 to "Sys Analysis of Shallow Land Burial" Contractor Science Applications.
 Inc
 SMITH.P A Technical Assistance Contracts Branch FIN 8-6428-9
 80/06/08 ip
- --8007010582 Mod 2.duleting ref to VP Dura in Article 8 & substituting JA Stoddard: to "Sys Analysis of Shallow Land Burlal" TREVINO.T Science Applications. Inc DOUGHERTY.D J Division of Contracts FIN B-6428-9 NRC-02-79-032 80/06/08 1
- 8007010413 Notification of contract execution.Mod 6 to "Commercial LMFBR Safety Study " Contractor Univ of CA at Los Angeles JACOBS, A Research Contracts Branch FIN 0-3019 80/06/16 lp
- --8007010619 Mod 6.revising scape of work for Tasks 1 & 2 extending period of performance until 800930 & providing add1 funding. to "Commercial LMFOR Safety Study"

 DHILLON.H California Univ of, Los Angeles MORTON, X V
 Research Contracts Branch FIN B-3019 NRC-04-76-246 80/06/16
 20p
- 8007010624 Notification of contract execution Mod 3 to "Evaluation of Retention & Migration Data from Natural & Inadvertent Reposituries " Contractor Stanford Univ JACOUS: A Research Contractor Branch FIN D-6341 80/04/16 1p
- --8007010827 Mod 3. extending persod of performance to 800630 to
 "Evaluation of Retention & Migration Data from Natural &
 Inadvertent Repositories"
 GUSTAFEON, F. A. Stanford Univ. MDRTON, K. V. Research Contracts
 Branch FIN D-6341 NR(-04-78-266 80/04/16 2pp
- B007020007 Notification of contract execution Mod 2 to "Historical Belsmicity & Late Cenozoic Faulting in AZ,Part I," Contractor AZ Board of Regents HAGEY,H A Research Contracts Branch FIN D-679B NRC-04-79-212 B0/05/15 ip
- --8007020009 Mod 2.extending period of performance to 801231.to
 "Historical Seismicity & Late Comeiotic Faulting in AZ.Pert
 I "
 CARR.S E Arizona, State of MORTON,K V Research Contracts
 Branch FIN 8-6798 NRC-04-79-212 80/05/15 1p
- 8007020024 Notification of contract execution, Mod 3 to "Guantification Classification of Two-Phase Flow Regimes Using Olobal & Local Neutronic Perturbations " Contractor Univ of WA JACOBS, A Research Contracts Branch FIN 0-6324 NRC-04-78-245 80/05/28 p
- ---8007020025 Mod 3, extending period of performance to 800930, to "Quantification Classification of Two-Phase Flaw Regimes Using Olobal & Local Neutronic Perturbations " TREIBEL, M C Mashington, Univ of MORTON, K V Research Contracts Branch FIN B-6324 NRC-04-78-245 80/05/28 2pp
- BOO7020386 Notification of contract procution, Mod 3 to "Source Document Microfiche & Duplicates " Contractor Microtech Industries Inc HAGAN, T F Administrative Contracts Branch FIN B-6357 NRC-10-79-651 80/06/10 tp
- --B007020398 Mod 3 revising billing procedures for pickups & delivery,to
 "Source Document Mirrofiche & Duplicates "
 * Microtech Industries, Inc. MATTIA.M J Administrative
 Contracts Branch FIN 8-6.57 NRC-10-79-651 80/06/03 2pp

- B007020542 Notification of contract precution Hod 3 to "Measurement & Stds Development for Nuclear Matl Safguards " Contractor NBS
 - NBS GUSTAVE.R P Research Contracts Branch FIN B-60169 NRC-01-79-011 B0/06/10 Ip
- ~-8007020553 Mod 3, revising stope of work to include changes proposed in NBS 790103 ltr, to "Measurement % Stds Development for Nuclear Matl Safeguards" SHREVE, D B Commerce. Dept of MDRTON, K V Research Contracts Branch FIN D-60169 NR(-01-79-011 80/06/10 lp
- 8007020572 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Weste Mgt " Contractor BDM Corp SMITH-P A Office of Nuclear Material Safety & Safeguards NRC-02-77-201-17 80/06/18 ip
- B007020730 Notification of contract execution, Mod 2 to "Subscriptions to Inside NRC " Contractor McGraw Hill Publishing Co. Inc. FLYNN, M. J. Administrative Contracts Branch NRC-10-79-663 80/06/06 ip
- --B007020731 Mod 2, increasing total number of subscriptions from 45 to new total of 49 to "Subscriptions to Inside NRC" COLLING, P. McGraw-Hill Publications Co. MATTIA.M J. Administrative Contracts Branch. NRC-10-79-463
- 800703006B Notification of contract execution.Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Southwest Research Inc BM174,P A Technical Assistance Contracts Branch NRC-02-77-201-46 80/06/13 1p
- --8007030071 Mod 2, extending period of performance through 800631, to "Technical Assistance in Development of Regulator Framework for Nuclear Waste Mgt "
 BIROEL, 5 H Southwost Research Institute DDUGHERTY, D J
 Technical Assistance Contracts Branch NRC-02-77-201-44
 BB0/06/13 Soc
- 8007030336 Notification of contract execution "Statistical Analysis Study to Assist NRC Senior Personnel Hearing Counsel in Preparing for Pending Equal Employment Opportunity Class Litigation " Contractor SL Wolfbein PLYNN, M J Administrative Contracts Branch NRC-10-80-694 80/06/12 bp
- --B00703D346 Contract "Statistical Analysis Study to Assist NRC Senior Personnel Hearing Counsel in Proparing for Pending Equal Employment Opportunity Class Action Litigation," awarded to SL Wolfbein, S L NRC-10-80-694 80/06/12 55pp
- BOO703D337 Notification of contract execution "Licensing Technical Assistance," awarded to Botence Applications.Inc ED0EWORTH,P J Technical Assistance Contracts Branch FIN B-A955-0 NRC-02-80-03505 B0/06/05 Ip
- 8007030353 Notification of contract execution, Mod 3 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor WAPDRA Inc SMITH, P.A. Technical Assistance Contracts Branch NRC-02-77-201 80/04/13 1p
- --8007030357 Mod 3, estending period of performance for one addl yr to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt "
 KING, W A WAPORA. Inc DDUGHERTY, D J Technical Assistance
 Contracts Branch NRC-02 77-201-36 80/06/13 5pp
- BOO7030369 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework Por Nuclear Waste Mgt " Contractor Teknekron, Inc BMITH, P A Technical Assistance Contracts Granch NRC-02-77-201-18 80/06/18 p
- B007070021 Nolification of contract execution.Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Wasto Mgt " Contractor SCS Engineers SMITH.P A Technical Assistance Contracts Dranch NRC-02-77-201-21 80/06/10 19
- BOO7070032 Notification of contract execution "Licensing Technical Assistance," awarded to Science Applications, Inc EDGEWORTH, P J Technical Assistance Contracts Branch NRC-02-80-03306 B0/06/03 ip

- BOO7070037 Notification of contract execution "Licensing Technical Assistance" awarded to Science Applicating, Inc EDGEMORTH:P J Technical Assistance Contracts Branch FIN-8-6954-0 NRC-02-80-03504 B0/06/05 ip
- BOO7070052 Mod 5, extending period of performance until 810630 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " PICKARD, C Synergy, Inc DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-77-201-23 80/06/18 1p
- --B007070034 Mod 4.extending period of performance until 810630 to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Myt"
 HELWIG,R A Donovan, Hamester & Rattion, Inc. DOUGHERTY,D J
 Technical Assistance Contracts Branch NRC-02-77-201-34
 80/06/18 2pp
- --8007070057 Mod 5, extending poriod of performance until 810430 to "Technical Assistance in Development of Regulatory Framework for Nuclear Wate Mgt " COHEN, S Teknekron, Inc DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-77-201-18 80/06/18 ip
- --8007070058 Mod 5, extending period of performance until 810430, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " CONRAD,E T 808 Engineers, Inc DOUGHERTY,D J Technical Assistance Contracts Branch NRC-02-77-201-21 80/04/18 lp
- --B007070060 Mod 5.extending period of performance until 810630.to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt"
 WALSH.B G RDM Corp DOUGHERTY, D J Technical Assistance
 Contracts Branch NRC-02-77-201-17 80/06/18 ip
- --B007070062 Mod 4, extending pariod of parformance until 810630, to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Wasta Mgt "
 STOLLER, S.M. 9 M Stoller Corp. (subs. of Arthur D. Little, lnc.)
 DUUMHERTY, D.J. Technical Assistance Contracts Branch
 NRC-02-77-201-27 80/06/18 ip
- BOO7070065 Natification of contract execution, Mod 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Donovan, Hammester & Rattien, Inc BNITH,P A Technical Assistance Contracts Branch NRC-02-77-201-34 80/06/18 lp
- 8007070129 Notification of contract execution, Mod i to "Computer Output Microfilming & Production of 35 mm, Aperture Cards " Contractor Microtech Industries, Inc HAGAN, T E Administrative Contracts Branch NRC-10-80-361 80/06/10 ip
- --8007070134 Mod i revising billing procedures for pictups & delivery to "Computer Output Microfilming & Production of 35 mm Aperture Cards" RUCCHIGO J P Microtech Industrius, Inc. MATTIA, M J Division of Contracts NRC-10-80-361 80/06/10 2pp
- GOO7070414 Notification of contract execution, Mod 2 to "Implementation of Executive Development " Contractor Projects Associates, Inc HOYLE, A Administrative Contracts Branch NRC-10~79-368. BO/06/18
- ---B007070418 Mod 2, extending expiration date to 800930 to "Implementation of Executive Development"

 CDNVERBAND, E Project Associates PERLMAN, J Division of Contracts NRC-10-79-368 B0/06/18 ip
- BD07090084 Notification of contract execution "Licensing Technical Assistance." awarded to Bcience Applications, Inc ED0EWORTH.P J Technical Assistance Contracts Branch FIN B-6982-0 NRG-02-80-035 80/06/05 lp
- 8007100010 Notification of contract execution Mod 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mpt " Contractor EM Stoller Corp SMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-27 80/04/18 lp
- 8007100011 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Synorgy, Inc BMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-23 90/06/18 ip

- 8007100109 Natification of contract execution, Mod 2 to "Review of San Unefre Units 2 & 3 Size Rate vs Magnitude Study "Contractor DB Slemmons TRAOCESER.C M Purchasing Section FIN 8-6870 NRC-03-79-146 80/06/18 1p
- --B007100112 Mod 2, increasing funds, extending expiration date to 800730 & increasing manday seffort from 40 to 59 mandays to "Review of San Onofre Units 2 & 3 Blsp Rate vs Magnitude Study "SLEMMONS, D B Slemmons, D B PERLMAN, J Division of Contracts FIN B-6870 NRC-03-79-146 80/06/18 1p
- 8007100304 Notification of contract execution.Mod i to "Purchase & Maint of Multichannei Analytical Equipment for NRC Regions "
 Contractor Nuclear Data.Inc.
 HAGAN, T T Administrative Contracts Branch FIN 3-1005
 NRC-05-80-254 80/06/10 lp
- --8007i00312 Mod i.revising acceptance & billing provisions & correcting administrative error, to "Purchase & Maint of Multichannel Analytical Equipment for NRC Regions"
 RIZZQ.R R Nuclear Data, Inc MATTIA.H J Administrative Contracts Branch FIN 8-1005 NRC-05-80-254 80/06/10 2pp
- 8007100361 Notification of contract execution "Nondestructive Examination (NDE) Nobile Van.Region i." awarded to Mobile Bys WIGGINS.E J Administrative Contracts Branch NRC-05-80-259 BD/06/18 ip
- --8007100368 Contract "Nondestructive Examination (NDE) Mobile Van. Region i." awarded to Mobile Sys KIMMEL, J J Mobile Systems MATTIA.M J Administrative Contracts Branch NRC-05-80-259 BD/06/18 A3pp
- 8007110535 Notification of contract execution, Hod & to "Coordination of Federal/State Radiation Control Activities & Assistance in Bolving Radiation Control Problems " Contractor FDA FLYNN, H J Administrative Contracts Branch FIN B-1620 NRC-04-76-247 80/06/20 1p
- --8007110539 Mod 6, setting forth effort for 1980, extending period of performance & providing addl funds, to "Coordination of Federal/State Radiation Control Activities & Assistance in Solving Radiation Control Problems"

 CROWN, H M HEW, Dept of, Food & Drug Administration MATTIA, M J Administrative Contracts Brench FIN 8-1620 NRC-06-76-247
- 8007110559 Notification of contract execution, Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Kaman Sciences Corp SMITH, P A Technical Assistance Contracts Branch NRC-02-77-201-43 80/06/19 ip
- 8007i10572 Notification of contract execution, Mod 2 to "Consuiting 8vcs in Connection W/NRC Antitrust Hearings " Contractor Miner & Miner FOSTER, J Technical Assistance Contracts Branch FIN 8-1119 NRC-03-76-273 80/06/13 1p
- --8007110979 Med 2.deobligating funds & closing out contract to "Consulting Svcs in Connection W/NRC Antitrust Hearings" MEYERS.C W Miner & Miner, Inc DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-i117 NRC-03-76-273 B9/06/13 10
- 8007140200 Notification of contract execution "ADP Sys Support." awarded to Technosociates. Inc FLYNN, M J Administrative Contracts Branch NRC-10-80-473 80/04/30 ip
- --8007140203 Contract "ADP Sys Support," awarded to Technassociates, Inc ZENTMER: M A Technassociates, Inc CDLLINS, F M Division of Contracts NRC-10-80-673 80/06/30 79pp
- G0071402iO Open Solicitation RS-ADM-BO-669 for contractor to piace new & renewal subscriptions for domestic & foreign periodicals, serials & other related sycs at agency price & guarantee delivery of all issues on each subscription MATTIA.M J Administrative Contracts Branch 80/06/16 69pp
- B007140512 Notification of contract execution, Mod 3 to "Loan Agreement Between State of IL, DDT & NRC to Conduct Joint Study on Transportation of Radioactive Matl in IL " Contractor IL Dept of Public Health FLYNN, H J Administrative Contracts Branch NRC-06-78-358 SO/07/03 ip

- --B00714052i Mod 3.extending person of performance & adding additeporting requirements to "Loan Agreement Between State of IL.DUT & NRC to Conduct Joint Study on Transportation of Radioactive Hatl in il."

 KEMPINERS,W L IIIInois, State of MATTIA.N J Administrative Contracts Branch SANTMAN.L D Transportation. Dept of NRC-06-78-358 B0/07/03 2pp
- B007140590 Notification of contract execution Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor IRT Corp SMITH.P A Administrative Contracts Branch NRC-02-77-201-40 B0/06/19 ip
- 8007140626 Notification of contract execution "Licensing Technical Assistance," awarded to Science Applications.inc EDGEHORTH.P L Technical Assistance Contracts Branch FIN B-6953-0 NRC-02-B0-035 80/06/05 ip
- --8007140633 Contract "Licensing Technical Assistance," awarded to Science Applications.inc

 * Science Applications Inc DDUGHERTY, D J Technical Assistance Contracts Branch FIN 9-4953-0 NRC-02-80-035 80/06/05 3pp
- B007150048 Notification of contract execution. Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Hgt " Contractor Social Research Application Corp
 BMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-42
 B07/A/19 1a
- 8007150055 Notification of contract execution Med 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor GEO-Ctrs. Inc SMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-35 BO/06/19 p
- 8007150040 Notification of contract elecution, Mod 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor R Stone & Co BMITH P A Tochnical Assistance Contracts Branch NRC-02-77-201-28 80/06/19 ip
- 8007160208 Notification of contract execution.Mod 2 to "Consulting Svcs in Connection W/NRC Antitrust Hearings" Contractor Barbay Engineers SHEW.D Technical Assistance Contracts Branch FIN B-1117 NRC-03-76-272 80/07/02 lp
- --8007160229 Mod 2, closing out contract, to "Consulting Svcs in Connection W/NRC Antitrust Hearings" BROOMS, F M Barbay Engineers, Inc FlN 8-1119 NRC-03-76-272 BD/07/02 ip
- B007150490 Mod 2.extending period of performance until 810630, to "Technical Assistance in Bevelopment of Regulatory Framework for Nuclear Waste Mgt "BOWNE, W D IRT Corp DDUGHERTY.D J Tochnical Assistance Contracts Branch NRC-02-77-201-40 80/04/19 ip
- --8007160476 Mod 2.extending period of performance until Bi0630, to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt"
 LEMIS.C Social Research Applications Corp NOUGHERTY, D J
 Technical Assistance Contracts Branch NRC-02-77-201-42
 B0/06/19 ip
- --8007160498 Mod 2.extending period of performance until 810630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Mgt"
 MARRAM.E P Geo-Centers, Inc DOUGHERTY, D J Tochnical Assistance Contracts Branch NRC-02-77-201-35 80/06/19 lp
- --8007160504 Hod 4, extending period of performance until 810630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt"
 KAHLE:R Ralph Stone & Co DOMOHERTY:D J Technical Assistance Contracts Branch NRC-02-77-201-28 80/06/19 lp
- --8007160513 Med 2.extending period of performance until 810630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt" BRIDGES: A P Kaman Sciences Corp DOUGHERTY: D J Technical Assistance Contracts Branch NRC-02-77-20: -43 80/06/19 ip
- 8007170122 Notification of contract execution.Mod 5 to "Survey Instruments " Contractor Eberling Instrument Corp MEDROM.L A K. Administrative Contracts Branch fin B-1215 NRC-05-77-242 80/07/08 ip

- 1129 Mod 2, decreasing funds to "Survey Instruments"

 R Eberline Instrument Corp. HAITIA.H J. Administrative racts Branch. FIN B-1215. NRC-05-79-242. 80/07/08. lp.
- 15 Notification of contract esecution, Mod 1 to "Development of Regulatory Program in Support of UMIRCA" Contractor of CA Administrative Contracts Branch FIN B-1653 -80-308 80/07/10 1p
-)145 Mod 1, increasing funds to "Development of State Regulatory ram in Support of UNTRCA

 alifornia. State of MATTIA.M J Administrative Contracts
 h FIN B-1653 MRC-06-80-308 60/07/09 5pp
- of Notification of contract execution. Mod 5 to "Mobile Lab " ter Mobile Sys

 E Administrative Contracts Brunch FIN B-1014
 79-257 80/07/08 1p
- J14i Mod 5. decreasing funds to "Mobile Lab"
 L.J J Hobile Systems MATTIA.N J Administrative Contracts
 th FIN 8-1014 NRC-05-79-257 80/07/08 ip
- 7 Notification of contract execution.Mod 1 to "Cost of ound Tests" Contractor American Mine Svcs.Inc
 '.R Administrative Contracts Branch NRC-02-80-055
 7 jp
-)172 Mad i,adding J Germundson to key personnel under "Cost of 'ground Tests" "
 JGALL.A J American Mine Services, Inc MATTIA, H J
 188trative Contracts Branch NRC-02-80-055 80/06/09 ip
- 2 Notification of contract execution, Had 1 to "Development of legulatory Programs in Support of U Hill Tailings on Control Act " Contractor State of TX . J Administrative Contracts Branch FIN B-1652 80-307 B0/06/30 1p
- 1216 Mod 1.extending period of performance & increasing funding, evelopment of State Regulatory Programs in Support of 1 Tailings Radiation Control Act " xas. State of MATIJA.M J Administrative Contracts Branch -1652 NRC-06-80-307 80/06/30 1p
- / Notification of contract elecution Mod 4 to "Word Processing Contractor Automated Correspondence Sys. Inc. R Administrative Contracts Branch NRC-10-78-598
- 222 Mod 4, providing add1 funds, to "Word Processing Svcs "standard Correspondence Systems, Inc. MATTIA: M $_{\rm J}$ istrative Contracts Branch NRC-10-78-598 80/06/30 1p
- 6 Notification of contract election "Development of Automated Selection Sys." awarded to Gasser Associates, P. A. Administrative Contracts Branch FIN B-1214 B0-253 B0706/27 ip
- i93 Contract "Development of Automated Vendor Selection Bys." ed to Gasser Associates, P A. R.E.R. Gasser Associates, P A. MATTIA, M J. Administrative acts Branch FIN B-1214 NRC-05-80-253 80/06/27 224pp,
- i Notification of cuntract esecution. Mod 1 to "Development of egulatory Programs in Support of U Mill Tailings on Control Act " Contractor State of DR J Administrative Contracts Branch, FIN B-1652 80-309 80/06/30 lp
- 524 Mod 1, extending period of performance & increasing funding. evelopment of State Regulatory Programs in Support ::11 Tailings Radiation Control Act "egon. State of MATTIA, H J Administrative Contracts Branch R-1652 NRC-04-80 309 80/06/30 5pp
- 3 Natification of contract execution, Mod I to "Development of equiatory Programs in Support of U Mill Tailings on Control Act " Contractor State of WA J Administrative Contracts Branch FIN 0-1652 30-306 B0/06/30 ip
- ild Mod i, increasing Funds, to "Development of State Regulatory oms in Support of U Mill Tailings Radiation Control
- shington, State of MATTIA, M J Administrative Contracts , FIN B-1652 NRC-06-80-306 80/06/30 8pp

- B007210122 Notification of contract specution, Mod 1 to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control Act " Contractor State of NM FLYNN, M J Administrative Contracts Branch FIN B-1452 NRC-06-80-676 80/06/30 1p
- --B007210135 Mod 1, adding funds, to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control
 - New Merico, State of MATTIA,M J Administrative Contracts
- 8007210154 Notification of contract elecution, Mod 1 to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control Act " Contractor State of CO FLYNN, M J Administrative Contracts Branch FIN 9-1652 NRC-06-80-311 80/06/30 1p
- --8007210160 Had 1:adding funds to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control
 - Act "
 Colorado. State of MATTIA.M J Administrative Contracts
 Branch FIN 8-1652 NRC-06-80-311 80/06/30 3pp
- 8007210253 Notification of contract execution "Btwam Generator Modeling During Reflood Stage of LOCA:" awarded to MIT BROMBERG.B Research Contracts Branch FIN B-7229 NRC-04-6 80/06/26 ip NRC-04-80-219
- --B00721025B Contract "Steam Generator Modeling During Reflood Stage of LOCA:" awarded to MIT DUMHER: 0 H Massachusetts Institute of Technology MORTON, K V. Research Contracts Branch FIN D-7229 NRC-04-80-219 80/06/26
- B007210263 Notification of contract execution "Environ Monitoring Program w/State of NY," awarded to State of NY BAISDEN,L Research Contracts Branch FIN B-5109 NRC-05-80-271 80/01/01 1p
- --8007210267 Contract "Environ Monitoring Program w/State of NY," awarded to State of NY LANAHAN, M P New York, State of MORTON, K V Research Contracts Branch FIN B-5109 NRC-05-80-271 BD/01/01 16pp
- 8007210317 Notification of contract execution "ADP Bys Support," awarded to Small Business Administration Subcontractor Technossociates Inc FLYNN.M J Administrative Contracts Branch NRC-10-80-673 80/06/24 jp
- --8007210331 Contract "ADP Sys Support," awarded to Small Business Administration Subcontractor Technassociates, Inc COLLINS, F M Small Business Administration CHILK, S J Office of the Secretary of the Commission ZENTNER, M A Technassociates, Inc 80/06/24 77pp
- B00724016B Notification of contract execution.Mod 2 to "Cost of Underground Tests" Contractor American Mine Sycs.inc CQLEMAN.R Administrative Contracts Branch NRC-02-80-055 B0/06/09 ip
- --8007240170 Mad 2.extending contract term by i wk.to "Cost of Underground Tests" * American Mine Services.Inc MATTIA.H J Administrative Contracts Branch NRC-02-80-055 80/06/09 ip
- --8007240173 Confirms agreement w/proposed extension until 800728 for contract completion MCDOUGALL.J American Mine Services. Inc. NRC-02-80-055 J American Mine Services, Inc NRC-02-80-055 80/07/11
- 8007250556 Notification of contract execution, Mod 1 to "Site Characterisation Test Programs " Contractor.Golder Associates
 COLEMAN, R Administrative Contracts Branch NRC-02-80-256.
 B0/06/09 19
- ---B007230562 Mod i.extending period of performance, to "Site Characteristion Test Programs " * Oolder Associates MATTIA, M J Administrative Contracts Branch NRC-02-80-236 B0/06/07 2pp
- B007250569 Notification of contract execution, Mod 7 to "Steam-Water Interfactal Transport " Contractor Northwestern Univ MAGEY,H Research Contracts Branch FIN B-6188 NRC-04-77-052 80/07/02 ip

- --8007250578 Mod 7.providing funds for add1 work scope,to "Steam-Water Interfacial Transport" MINTZER.D Northwestern Univ MORTON.K V Research Contracts Branch FIN 0-6188 NRC-04-77-052 80/07/02 4pp
- B007280234 Notification of contract execution "Characterization of Existing Burface Conditions at Sheffield Low Level Waste Bite Disposal Facility," awarded to Harding-Lawson Associates
 LITLE: M Administrative Contracts Branch FIN B-6970-0
 NRC-02-B0-057 B0/07/09 1p
- --B0072B0236 Contract "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Site Disposal Facility,"
 awarded to Harding-Lawson Associates
 HEIM.0 E Harding-Lawson Associates PERLMAN, J Administrative
 Contracts Branch FIN B-6970-0 NRC-02-80-057 80/07/09 10pp
- B007280338 Bubmits Progress Rept 30 for June 1980 Site visit task underway Itinerary encl PLATO.P Michigan, Univ of NRC-01-77-180 80/04/27 App
- 8007280320 Notification of contract execution.Mod 4 to "Effluent Inventory Bys on Sheffield Low Level Waste Disposal Site "
 Contractor NUS Corp
 SNITH.P A Technical Assistance Contracts Branch NRC-02-78-035
 80/07/03 ip
- --8007280527 Mod 4.adding addressee to "Effluent Inventory Sys on Sheffield Low Level Haste Disposal Site " EDMONDBON L R NUB Corp DDUGHERTY.D J Technical Assistance Contracts Brench NRC-02-78-035 80/07/03 2pp
- 8007280712 Notification of contract execution, Mod 1 to "Site Characterization Test Programs " Contractor Goler Associates COLEMAN, R Administrative Contracts Branch NRC-02-80-056 80/06/09 1p
- --8007280717 Requests 1 wk extension to "Site Characterization Test Programs" PENTZ:D L Golder Associates NRC-02-80-056 80/06/07 ip
- B007300577 Notification of contract execution "Development of Communications Console Design." awarded to Bendix Field Engineering Corp HOYLE, A Administrative Contracts Branch FIN B-1259 NRC-05-80-290 80/07/10 ip
- ---8007300590 Contract "Development of Communications Console Design," awarded to Bendix Field Engineering Corp ENGLE, N J Bendix Corp PERLMAN, J Administrative Contracts Branch FIN B-1259 80/07/10 5pp
- B007300579 Notification of contract execution.Mod 6 to "Electrostatic Copying Svcs " Contractor Potomac Research Inc FLYNN,M J Administrative Contracts Branch NRC-17-77-152 B0/07/11 ip
- --B0073005B1 Mod 6, extending period of performance to "Electrostatic Copying Svcs " BAUMANN,R Q Potomac Research, Inc MATTIA.M J Administrative Contracts Branch NRC-17-77-152 80/07/11 ip
- B007300595 Notification of contract execution, Mod 3 to "Personnel Neutron Dosimetry for Nuclear Power Plants" Contractor Rennselaer Polytechnic Inst JACOBA, A Research Contracts Branch FIN B-6651 NRC-04-78-263 B0/06/27 ip
- --8007300598 Mod 3, extending period of performance for seven months, to
 "Personnel Neutron Dosimetry for Nuclear Power Plants "
 LOGIUDICE, J H. Rensselaer Polytechnic Inst. MORTON, K. V. Research
 Contracts Branch FIN B-6651 NRC-04-78-263 80/06/27 Rpp.
- B007310006 Notification of contract execution, Mod 2 to "Presentation of General & Refresher Courses in Concrate Technology & Codes " Contractor Portland Cement Association BAISBUNL Research Contracts Branch FIN X-1175 NRC-05-79-261 G0/07/01 ip
- --8007310010 Mod 2, changing personnel, to "Presentation of General & Refresher Course in Concrete Technology & Codes"

 ** Portland Cement Association MORTON, K V Research Contracts
 Branch FIN X-1175, NRC-05-79-261 80/07/01 ip

- FINANCIAL DISCLOSURE INFORMATION
- 8007020737 informs that confidential statement of employment & financial interests has been reviewed Exemption from provisions of IOCFRO 735-21 must be granted in order to allow work on licensing matters involving GE VOLLMER.R H Division of Engineering 80/06/11 ip
- 800715006) Forwards list of DIV of Safety Technology employees in grades GSI3-15 & employees below GS-13 in occupational codes of interest for whom submission of confidential financial statements are required MATTSON, R J Division of Safety Technology 80/07/01 4pp
- 8007300030 Advises that request for exemption from 10CFRO 735-21 is granted & participation in matters before NRC affecting Westinghouse permitted Interest in pension fund not so substantial as to affect impartiality VOLLMER.R H Division of Engineering 80/07/16 1p
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7812210553 Forwards IE Insp Rept 30-12052/78-01 on 781011 No items of noncompliance noted insp included exam of activities at Pittsburgh office re radiation safety & compliance w/rules & regulations W/out rept MCCLINTOCK,R O Region 1. Philadelphia. Fuel Facility & Materials Safety Dranch 78/10/31 ip
- 7906200225 Requests Executive Branch position re GC application for license to export six detector assemblies to India Forwards 790507 application Wσ encl OPLINGER, 0 @ Assistant Director for Export/Import & International Safeguards 79/05/15 ip
- 7909110639 Responds to 790703 ltr re approval of NRC actions HENDRIE, J M Commission 79/07/16 ip
- 8005090523 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE lnsp 79-01 on 791212 MCCLINTOCK,R O Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/24 ip
- --8003090524 Responds to NRC 800107 ltr re violations nated in lE insp on 791212 Correctivo actions discussed infractions \(\text{w} \) technicians involved Classes planned \(\text{w/all} \) technicians on requirements \(\text{restrictions} \) CARMEL, \(\text{P} \) Rad Services, Inc 80/01/30 ip
- --B005090527 Discusses IE Insp 79-01 on 791212 & forwards notice of violation MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch B0/01/09 2pp
- --8005070527 Notice of violation from insp on 791212 Noncompliance noted required radiation surveys not performed on packages received
 * Region 1. Philadelphia, Office of the Director 80/01/09 200
- 8005200366 Ack receipt of 800312 resolution in support of nuclear energy adopted by Northumberland County Board of Supervisors Certain short-term tasks, identified in TMI Action Flammust he completed prior to OL Issuance KAMMERER. C Office of Congressional Affeirs 80/04/28 2pp
- 8005270154 Bubmits legal opinion on two questions re operation of U Mill Tailings Radiation Control Act of 1978 NRC has legal authority to impose groundwater protection conditions & concurrent jurisdiction over nonrodiological hazards BHAPAR.H K Diffice of the Executive Legal Director 80/04/28 57pp
- 8003290403 Ack receipt of 800421 ltr informing NRC of steps taken to correct violations noted in IE insp of License 37-13129-01 on 800228
 CROCKER,H H Region 1, Philadelphia, Office of the Director 80705/07 ip
- --B005290407 Responds to NRC 800328 ltr re violations noted in IE insp of License 37-13128-01 on 800228 Corrective actions new procedures will be developed to improve coordination in receipt of incoming radioactive samples KIM.S M Reduation Management Corp 80/04/21 2pp
- --8005290612 Discusses IE insp of License 37-13129-01 on 800228 & forwards notice of violation CROCKER.H W Region I, Philadelphia, Office of the Director 80703/28 2pp

- --B005290616 Notice of violation from insp on 800228 Noncompliance noted failure to keep records showing receipt of radioactive samples
 - * Region 1. Philadelphia, Office of the Director 80/03/28 1p
- BOO6:20402 Discusses reasons for delays in licensing new nuclear plants.in response to 800424 requests re HA Cosgrove comments Delays caused by post-TMI efforts to improve safety at operating plants KAMMERER.C Office of Congressional Affairs 80/05/20 2pp
- BOO6120419 Responds to BOO423 re L Nutter concerns about nuclear plant siting & evacuation plans NRC not responsible for decision re wheather on not nuclear power should exist in US Proposals to stop nuclear power development not snacted KAMMERER.C Defice of Congressional Affairs BO/05/07 2pp
- 8007010082 "AECL/RNML Cooperative Pellet/Cladding Interaction Program "
 PANKASKIE.P J Brookhaven National Laboratory MEYER.R 0 Core
 Performance Branch 77/11/30 18pp
- ~~B007010093 Summary of 740116 meeting w/GE re furl performance Onsite into techniques reactor history & failure mechanisms were discussed Lists GE conclusions. AEC impressions & recommended actions Lists of attendees encl COFFMAN.F D Atomic Energy Commission. Directorate of Licensing 74/01/21 400
- --8007010108 Forwards summary of NRC 750305 meeting w/GE in San Jose to discuss GE fuel failure experience & preconditioning interim operating mgt recommendations Discussion outline & list of meeting attendees enci W/o encls
 CQFFMAN.F D Core Performance Branch 75/03/19 ip
- ---BOO7010114 Forwards summary of NRC 750417 meeting w/B&W in Bethesda.MD to discuss pellet-cladding mechanical interaction Discussion outline & list of meeting encl W/o encls COFFMAN.F D Core Performance Branch 75/04/23 lp
- --8007010124 Summary of 750805 meeting w/GE.Comm Ed.BNML.Northern States Power Co & Boston Edison Co re preconditioning interim operating mgt recommendations Known patterns of reactor operations have caused fuel failures Agenda encl COFFMAN.F D Core Performance Branch 75/08/15 Spp
- --BOO7010145 Discusses need for prompt NRC action re pellet-clad interaction Recommends that encl ltr be sent to each listansee Lists other factors to be considered M/o encl ROSS.D F Assistant Director for Reactor Safety 75/08/25 2pp
- ---8007010149 Summary of 760309 meeting w/Hestinghouse & BNML in Bethesdo. MD re pellet-clodding interaction Meeting agenda & attendees list oncl SIEOELIBL Core Performance Branch 76/04/01 7pp
- --B007010152 Expresses thanks for info & cooperation afforded B Siegel & F Coffman during recent trip to labs Pellet-cladding interaction model discussions & data analysis provided clearer understanding of Canadian results
 ROSS.D F Assistant Director for Reactor Safety 76/04/14 ip
- --8007010138 Forwards summary of NRC 740318 meeting w/AECL in Ontario. Canada re pellet-cladding interaction Intent of meeting was to discuss current Canadian fuel operating recommendations for CANDU-DHW reactors & basis for recommendations COFFMAN.F D Reactor Safety Branch 76/06/01 7pp
- --6007010161 Summary of 760408 meeting w/GE & BNML in Bethesda.MD to review pellet-cladding interaction failures & effects on reactor design & operation List of attendees encl GIEGEL.D L Care Performance Branch 76/04/26 Spp
- --8007010165 Summary of 760421 meeting w/Exxon Nuclear Co in Sethesda, MD to discuss pellet-cladding interactions Exxon Nuclear has had no fuel failures on bundles being irradiated Meeting agenda & list of attendees uncl
 BIEGEL.B L Core Performance Branch 76/04/30 4pp
- --B00701016B Summarizes NRC 760519 meeting w/B&W in Dethesda. HD to discuss pellet-cladding interactions B&W has experienced flow primary coolant activity levels indicative of faw failures Neeting agenda & attendes list encl BIEGEL. B L Core Performance Branch 76/05/24 App
- ---8007010173 Summarizes NRC 760521 meeting w/C-E in Dethesda, MD to discuss pellet-cladding interactions Lists data presented from overpower ramp tests Meeting agenda & list of attendees encl SIECEL: B L Core Performance Branch 76/07/09 4pp

- --8007010176 Submits description of data for proposed joint pelletcladding interaction program Lists items for review.prior to signing program agroement w/BNML CHECK.P S Core Performance Dranch 77/02/08 2pp
- --8007010181 Summary of 770615 mooting w/LWR fuel vendors in Bethesda, MD re LWR fuel damage criteria, mechanisms & limits List of attendess, agenda & excerpts from SPPs encl TOKAR, M Core Performance Branch 77/06/23 14pp
- --B007010187 Forwards brief summary of pellet-cladding info reviewed at Chalk River Nuclear Labs Lists questions which arose from efforts to establish fuel rod failure probabilities from Pickering-B bundle shift data PANKASKIE,P J Battelle Memorial Instituto, Pacific Northwest Laboratory 77/12/09 2pp
- --8007010191 Updates evaluation of applicability of FUELDGRAM to LWR pellet-cladding failures Model will generate failure probabilities for CANDU data subset which will provide reasonable feel bundle to fuel rod failure correlation PANKASKIE, P J Battelle Memorial Institute, Pacific Northwest Laboratory 78/01/23 10pp
- --8007010194 Forwards examples of correspondence w/US fusi vendors concerning contributions to AECL program w/FUELOGRAM8

 Description of contract, "LNR Fuel Pellet-Cladding Interaction & Failure Limits," encl

 MEYER,R Q Core Performance Branch FIN 8-1195 78/02/14 3pp
- ---B007010178 Requests data presented at 760517 pellet/cladding interaction meeting between NRC & B&W. Data needed for assessment of applicability of AECL pellet/cladding interaction model to LWR fuels ROSS, D F Assistant Director for Reactor Safety 77/1i/30 ip
- --8007010204 Confirms telcons identifying addl GE info needed for use in joint BANL/AECL program to assess applicability of FUELDGRAMS to LMRs
 ROSS,D F Assistant Director for Reactor Safety 77/03/01 1p
- --80070i0207 Forwards agenda for 780302 pellet/cladding interactions meeting in Richland Requests notification if changes needed CHECK.P S Core Performance Branch 78/02/15 2pp
- ---8007010210 Recommends final meeting & rept re cooperative pellet/ cladding interactions effort w/Canadians Rept should be nonproprietary & contain descriptions of relevant FUELOGRAMS & predictive models MEYER, R O Core Performance Branch 78/07/12 ip
- --B007010215 Requests add1 fuel behavior data re peliet/cladding interaction Data will be used for developing improved fuel damage limits for licensing of PMRS & BMRs Lists current meeds for program, present status & licensing impact DENTON, H R Defice of Nuclear Reactor Regulation, Director 79/08/07 7pp
- --8007010218 Speech entitled "Development of Improved LWR Fuel Damage Limits for Reactor Licensing," presented at ANS 781114 meeting in Mashington. Or TOKAR. M Core Performance Branch 78/11/14 37pp
- --B007010222 Summary of 781212 meeting w/AECL & BNML in Ontario Canada re draft rept on BNHL/AECL cooperative technical assistance program on pellat/cladding interaction FUELDORAM Lists meeting objectives Meeting agenda encl TOKAR. M Core Performance Branch 78/12/15 3pp
- --- SD0701C227 Notifies of 790503 meeting in Portland.OR to discuss utilization of data re fuel failure caused by pellat/cladding interactions Forwards draft rept for review W/o enci
 TEDESCO.R L Assistant Director for Reactor Safety 79/03/27
- --8007010230 Provides procedure for transmittal of data requested for ENML consultant use in PROFIT pellet/cladding interaction model KNIEL.K Core Performance Branch 79/08/02 ip
- --8007010233 Comments on "Draft Rept on Joint Program by BNML & AECL, Mar 1977 " PROFIT data base is strongly biased toward high failure rate Independent variables are ambiguously defined OLDBERG, T Electric Power Research Institute 79/05/07 App

- --8007010238 Submits tabulation of estimates of fuel failure probability for control rod withdrawal ATWS in PMR Hot standby to 20% rated power & full (100%) to overpower (110%) were considered in estimates PANKASKIE, P J Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/08 2pp
- --8007010241 Requests proposel from BNWL to provide technical assistance re fuel failurs to Div of Sys Safety Forwards statement of work Authorization to commence work becomes effective upon acceptance of executed NRC Form 173
 SHRDEDER, F Division of Systems Safety 79/08/07 7pp
- --8007010244 "Pellet/Cladding Analysis of Turbine Trip W/o Bypass," final rept, Jan 1979, prepared for BNWL POMERDY, D L . SAUAR, T O . WARING, J P Scanpower, Inc 79/01/31 85os
- --8007010249 Requests proposals from INEL to provide technical assistance re fuel performance to Div of Bys BaPety Forwards estatement of work Authorization to commence work becomes effective when NRC Form 173 accepted BCHROEDER, F Division of Systems Safety FIN A-4268 79/08/24 688
- 8007010079 FDIA request for 57 documents referenced in M Toker memo to ACRB re pellet-cladding interaction KIQOINS, S R Hestinghouse Electric Corp 80/05/06 7pp
- 6007020122 Responds to FOIA request for documents re US radiation monitoring or related activities of French nuclear weapons testing since 1966 Documents are being referred to ClA for disclosure determination & direct response FELTON, J M Division of Rules and Records 80/06/25 ip
- 8007020127 FOIA request for documents re US radiation monitoring or related activities of French nuclear weapons testing since 1946 by Wheeling T AGM US Instruments ship or other vessel TREAKLE, K Greenpeacs Foundation 80/05/29 lp
- 8007020132 Responds to FOIA request for all memos, ltrs & records conterning organization, People Generating Energy NRC has no files indexed or maintained under organization Other relevant info may be available in LPPRs FELTON, J M Division of Rules and Records 80/06/25 1p
- 8007020136 FOIA request for all memos.ltrs & retords concerning organization.People Generating Energy Affidavit encl BELIN.A Center for Law in the Public Interest 80/06/11 2pp
- 8007020284 Add1 response to FOIA request for info re award of contract NRC-10-77-140 issued to Damans & Associates Forwards documents listed in encl Info partially & completely withheld NRC advice & opinions free FOIA Exemption 5) FELTON, J M Division of Rules and Records 80/02/12 3pp
- --8007020287 Proposal evaluation rept. Solicitation RS-77-98, "Audit of Supergrade Positions." Info partially withheld NRC advice & opinions (ref FOIA Exemption 5)
 JONESC C Commission MATTIA, M J Administrative Contracts
 Branch 77/06/23 App
- --8007020292 Final proposal evaluation rept & recommendation. Bolicitation RB-77-38, "Audit of Bupergrade Positions" Info partially withhold NRC advice & opinions (ref FDIA Exemption 5) JONES C C Commission MATTIA, M J Administrative Contracts Branch 77/06/23 14pp
- 8007020450 Responds to FDIA request for info re dates for scheduled & unscheduled outages for plants located in continental US & info related to maint operations being performed on plants Forwards NUREO-0020, Vol. 4 W/o encl
 FELTON, J M Division of Rules and Records 80/06/25 ip
- 8007020463 FDIA request for info re dates for scheduled & unscheduled outages for plants located in continental US & info related to maint operations being performed on plants SKORDHOD, P M Briggs Engineering & Testing 80/06/04 ip
- 8007030007 FOIA request for documents or transportation of spent fuel from Fortsmouth, VA to Savannah River plant in Aiken, SC MEYER, K. A. Affiliation Unknown 80/06/03 2pp
- 8007030033 Add1 response to FDIA request for documents listing nuclear plant locations, accidents occurring at each location, environ impact results, radiation leaks, to huclear waste depots around US, Forwards J Braun 800612 memo FELTON, J M. Division of Rules and Records 80/06/23 ip

- --8007030038 Provides response to FOIA Request 80-278 for list of nuclear waste depots around US locations & cost Request is interpreted to reference commercial high & low level & U mill tailings BRAUN.J Licensing Process & Integration Branch BO/04/12 App
- BOO7030064 Responds to FOIA request fin summaries of all radiation exposure data & NRC or ACRS position papers leading to NRC adoption of 0 i as max radiation permissible Forwards documents listed in App A No position papers exist W/o encl FCLTON, J M Division of Rules and Rocords 80/06/25 3pp
- 8007030066 FDIA request for summaries of all radiation exposure data & NRC or ACRB position papers loading to NRC adoption of O i as max radiation permissible dose ICE,R D Driahoma: Univ of 80/05/27 2pp
- 8007030331 Responds to FOIA request for NRC telephone directory Forwards directory W/o encl FELTON,J M Division of Rules and Rocords 80/06/26 App
- BOO7030332 FOIA request for NRC telephone directory
 ODNCALVES, A National Employee Benefit Associates 80/06/20 lp
- 8007080036 BECY-75-429
 Discusses procedure by which NRC can determine whether matters of alleged or suspected criminal violations of law should be referred to DOJ Recommends that Inspector & Auditor Off accept full responsibility
 BHAPAR,H K Office of the Executive Legal Director 75/08/11 3pp
- BOO7090377 FOIA request for winning proposal in response to RFP RB-NRR-BO-102, "Energetic Thermal Interactions Recriticality & HTOR Accident & Transient Coolant Flow "RAUNER, L M Advanced Technology, Inc. 80/02/27 1p
- 8007090380 Response to RFP R8-NRR-80-102, "Energetic Thermal Interactions, Recriticality & HTGR Accident & Transient Coolant Flow " Describes proposed technical approach, research plans, schedules & milestonsc THCOFANU8, T G Purdue Univ R8-NR-80-102 79/12/15 54pp
- BOO71000DB Add1 response to FDIA request for decuments to licensing of facility & transcripts of closed Commission meetings App A documents available in PDR Document 1 of App B & purtions of Documents 2-21 withheld free FDIA Exemptions 1.4 & 5) FELTON, J M Division of Rules and Records 80/06/27 5pp
- --8007100015 Discusses application of inventory difference regression equation to Aug inventory info withheld procedures for safeguarding nuclear meth & NRC predecisional advice, opinions & recommendations (ref fOIA Exemptions 4 & 5) MCBSINGER, M. Material Control & Accountability Development Branch 79/09/24 30s
- --8007100020 Summary of 800102-03 meeting between util & NRC in 811ver Spring.MD re MCA license conditions applicable for resumed highly enriched U operations Info partially withhold (ref FDIA Exemptions 4 & 5) Charles encl JOY.D Material Control Licensing Branch 80/01/10 [p
- --8007100023 Forwards mat) balances covering inventory for 790814-1004 Info withheld safeguards & security measures (ref FGIA Exemptions 3 & 4) HENSLEY.K D Nuclear Fuel Services, Inc. (subs. of Gatty Oil Co.) NFE 79-1385 79/12/05 Spp
- --8007100028 Forwards detailed rept on current & planned projects designed to improve facility accountability sys & associated inventory difference results Rept withheld (ref FOIA Exemptions 3 & 4)
 TAYLOR.C W Nuclear Fuel Services. Inc (subs of Gatty Oil Co)
 NFE 79-081 79/10/23 tp
- --8007100032 Discusses BECY-79-650A. "NRC Regulation of Highly Enriched U Operations at Facility " Lists addl requirements needed if position taken by JF Absorne in 800107 memo is adopted Info partially withheld (ref FOIA Exemption 3) HANRAHAN, E.J. Haterial Control Licensing Branch 80/01/11 2pp
- --8007100038 Summary of Commission R00116 meeting re SECY-77-680 & SECY-79-650A concerning facility Scape & quality of matl control & accounting eloments would be improved Summarizes proposed actions info partially withheld fref FDIA Exemption 3).

 HANRAHAN.E J Material Control Licensing Branch 80/01/15 Rpp

- --B007100044 Discusses 791004 inventory difference of high enriched U exceeding limit of error constraint Forwards rept detailing causes contributing to inventory differences & corrective actions taken Rept withheld (ref FDIA Exemption 3) TAYLOR,C W Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) NFE-79-083 79/11/02 2pp
- --8007100052 Forwards comments on JO Partiow 790525 ltr to KD Hensley Info withheld safeguards & security measures (ref FOIA Exemption 33 HENGLEY, K D No. 79/07/04 3pp Nuclear Fuel Services, Inc (subs of Getty Oil Co)
- --B007100057 Submits list of recent mods at facility which upgraded matl accountability & control program Info withheld procedures for safeguarding licensed SNM (ref FOIA Exemption 4)
 JOY-D R Material Control Licensing Oranch 79/09/11 2pp
- --B007100069 Forwards info status rept to 790814 inventory differences of highly enriched V exceeding limit of error constraint Info withheld procedures for safeguarding nuclear mat) (ref FOIA Exemption 4)
 HENSLEY.K D Nuclear Fuel Services, Inc. (subs. of Catty Dil Co.) 79/10/02 3pp
- --E007100072 Summary of 790816 meeting between util & NRC in Bethesda. HD re concerns of highly enriched U inventory difference behavior Inventory difference is licensee problem Info partially withheld (ref FDIA Exemption)

 JOY. D Material Control Licensing Branch 79/08/21 2pp
- --B0071000B1 Summary of 770B16 meeting w/util Lists major util concerns including improving of accounting sys Majority of meeting spent on reporting status of MRC questions Info pertially withheld (ref FOIA Exemption 5)
 PARTLOW, J O Material Control Licensing Branch 79/08/17 2pp
- BOD7100327 Notifies that JF Ahearns concurs in wording of fire protection rule.SECY-80-088.as revised by J Parry 800317 memo subj to listed changes BAUTER.O Commission 80/04/16 ip
- --8007100334 Forwards draft memo summarizing individual Commissioner comments on SECY-80-088, fire protection actions Requests comments or concurrence in time to affirm paper on 800319 Draft memo-moutisied pages & draft FR notice encil PARRY, 8 J 8 Office of the Recretary of the Commission 80/03/17
- 8007110004 Responds to FOIA request for 11 documents concerning facility Items 2.3 & 5-10 have been addressed in earlier NRC responses Attachment D of Document 11 withheld (ref FOIA Exemption 4 & 10CFR2 770)
 FELTON, J M Division of Rules and Records 80/06/27 2ep
- G007110149 Responds to FDIA request for 1979 quarterly repts for 3M Co Po-ZIO static elimination devices Info withheld (ref FOIA Exemption 4) FELTON.J M Division of Rules and Records 90/07/09 ip
 - Division of Rules and Records 80/07/09 ip
- BOO7110159 FOIA request for 1979 quarterly repts for 3M Co Po-210 static elimination devices
 MILEHAM.J Hark IV Industries, NRD Div 89/06/20 1p
- 8007110242 Advises that RT Kennedy concurs in changes to SECY-BO-OBB, fire protection rule proposed in 0 Souter 800416 memo, subject attached revisions 0UILDERT, J Commission 80/04/17 App
- --8007110246 Notifies that JM Hendria concurs w/800416 version of fire protection rule circulated by G Sauter as modified by RT Kennedy FONTECILLA, H Commission 80/04/18 ip
- BOO7110496 Requests Commission approval to publish for comment, amend to iOCFRB0 in form of App R. w/fire protection requirements for plants in operation prior to 790i0i Amené would facilitate implementing BTP 9 5-1 FQNTECILLA, H M Commission 00/03/14 2pp
- 8007110504 Discusses status of App R to 10CFR50 re impact of requiring all fire protection features installed by 801101 Eleven plants will not complete Section 3 i mods & Section 3 2 open items by 801101

 LAINAS.O Plant Bystems Dranch 80/04/11 3pp
- 8007110547 Describes status of alternate/dedicated shutdown mys as of BOODER CASE E Office of Nuclear Reactor Regulation, Director BO/07/10

- 8007110585 Forwards info requested by JF Ahearne re status of fire protection review programmalternate/dedicated shutdown mys status as of 800331 & other outstanding lasues LAINAS. G Assistant Director for Safety Assessment 80/04/02 7pp
- 8007140212 Responds to FQIA request for page from MASH-740 update 650413.consisting of IN Sunderman memo to 82 Stawlewicz, Document 136 Forwards memo FELTON.J M Division of Rules and Records 80/06/26 1p
- --8007140220 Discusses revision to HASH-740 Comparison of ground rules in two analyses & effects is instructive in pointing out real differences Forwards table consisting of comparison of selected input & output items in HASH-740 & revision SUNDERMAN.D N Battalle Memorial Institute, Columbus Laboratories 65/04/13 3pp
- 8007140214 FOIA request for page from WASH-740 update, 650413, consisting of DN Sunderman memo to BZ Szawlewicz, Document 136 GROSSHAN, K Island Cluseup News Service 80/06/18 ip
- 8007140226 Responds to FDIA request for documents re M Balisle Forwards documents listed in App A M/o encls FELTON.J M Division of Rules and Records 80/07/01 2pp
- 8007140228 FOIA request for documents re M Belisle M Belisle affidavit BELIN.A Center for Law in the Public Interest 80/06/11 3pp
- 8007140239 Responds to FOIA request for records re five categories of info concerning proposed fire protection rule All documents relative to request ere available in Washington, DC PDR FELTON.J M Division of Rules and Records 80/06/27 2pp
- 6007140243 FOIA request for records re five categories of info concerning proposed fire protection rule MCGARRY.J M Debevoise & Liberman 80/06/16 Zpp
- 8007140245 Responds to FOIA request for Contract NRC-08-80-338, "Study of US Nuclear Health & Bafety Info Dissenination," awarded to Franklin Inst Contract is available in Washington, DC PDR FELTON, J M Division of Rules and Records 60/07/08 ip
- 8007140248 FOIA request for Contract NRC-08-80-338, "Study of US Nuclear Health & Safety Info Dissemination," awarded to Franklin Inst NDCELLA.8 J Advance& Technology, Inc 80/07/01 ip
- 8007140277 Responds to FOIA request for all info which directed or discussed any changes of proposed fire protection rule in 8ECY-BO-OBB App documents have been forwarded J Guibert 800311 meno withheld (ref FOIA Exemption 3) FELTON-J M Division of Rules and Records 80/06/26 2pp.
- --8007140271 Staff requirement memo re 800423 open Affirmation Session 80-18 in Mashington: DC. Includes overall records of Commission votes re SECY 80-166, SECY 80-17 & SECY-80-088 CHILMS J Office of the Secretary of the Commission. 80/05/01
- --8007140297 Discusses fire protection rule proposed in SECY-80-088, Lists JF Ahearne recommandations re provisions which should be incorporated in rule Includes info re public comment period & implementation of nonshutdown sys mods.

 SAUTER, O Commission 80/04/10 ip
- --8007140302 Discusses fire protection rule proposed in SECY-80-088 Commission affirmed. W/comments, proposed fire protection rule delineating certain min fire protection requirements at 800423 Affirmation Session 60-18, Lists recommended changes NOTLEY.D P Engineering Metholology Standards Branch 60/06/03
- 8007140286 FOIA request for all info which directed or discussed any changes to proposed fire protection rule in SECY-80-088 & record of Commission's vote re changes KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp). 80/05/30 ip
- B007140491 Responds to FOIA request for rept on potential threat to nuclear activities from insiders, DOE study on effectiveness of security clearances & supporting documents used at B00619 briefing re repts Documents available at PDR, DDE & CIA FELTON, J Division of Rules and Records 80/07/10 ip.
- ~~8007140504 Bunshine FR Notice of Commission meetings during wk of 800616 MAGEE. W Office of the Secretary of the Commission 80/06/16.

- 8007140498 FOIA request for rept on potential threat to nuclear activities from insiders.DOE study on effectiveness of sacurity clearances & Supporting documents used at 800619 briefing re repts
 COCHRANIT B Natural Resources Defense Council 80/06/24 ip
- 8007140645 Responds to FQIA request for winning technical proposal in response to RFP RB-NNS-80-024, "Development of Advanced Matl Accounting Sys Simulation (AMASS) Model "Forwards proposal FELTON.J M Division of Rules and Records B0/07/09 ip
- --8007140656 Response to RFP RS-NMS-80-024. "Development of Advanced Matl Accounting Sys Simulation (AMASS) Model "Objective is mod of MCLAMS simulation model for broad application to wide variety of licensoe facilities * NUBAC.Inc RS-NMS-80-024 80/01/04 70pp
- 8007140650 FOIA request for winning technical proposal in response to RFP RS-NMS-80-024, "Development of Advanced Mati Accounting Bys Bimulation (AMA88) Model "TREVINOLT Science Applications, Inc TT-860 80/06/27 ip
- B007140664 Responds to FOIA request for 5 documents re state U mill incidents Forwards documents
 FELTON, J M Division of Rules ond Records 60/07/07 ip
- 8007140674 FOIA request for 5 documents re state U miil incidents BURKS.N Black Hiiis Ailiance 80/06/16 2pp
- 8007150743 Responds to appeal re denial of FOIA request for records re Abalone Alliance & info concerning FBI Director 770804 memo to Deputy Atty General NRC has no further documents subj to request DIRCKS.W J Office of the Executive Director for Operations
- 8007150749 Appeals denial of FUIA request for all records re Abalone Alliance & info concerning FBI Director 770804 memo to Deputy Atty General FBI 770804 memo encl VARON, C Affiliation Unknown 80706703 7pp
- 8007150796 Responds to FDIA request for records re Abalone Alliance & info concerning FBI director 770804 memo to Deputy Atty General Forwards document ro Abalone Alliance Other documents may be available in CA PDRs W/A encls FELTON, J M Division of Ruies and Rocords 80/05/05 ip
- 8007150786 Submits additesponse to FOIA request for five categories of info concerning proposed fire protection rule Documents listed in app are available in Washington.DC PDR Five documents re request are still under review FELTON.J M Division of Rules and Records 80/07/09 2pp
- BOO7170197 Responds to FOIA request for Region 2 list used for distributing bulletins info notices & circulars & Region 4 list for distributing quarterly publication re centractor/ vandor insp info Forwards lists W/o encls FELTON, J M Division of Rules and Records BO/07/14 ip
- 8007170202 FGIA request for Region 2 list for distributing bulistins, info notices & circulars & Region 4 list for distributing quarterly publication re contractor/vendor insp info KEEMAN.T Inside D O E , McGraw-Hiil Publication 80/06/13 ip
- 8007170292 Discusses IE Insp Rept 30-13219/78-01 of License 19-17039-01 on 780425 No noncompliance noted Hajor areas inspected procedures & representative records, personnel interviews & observations by inspector MCCLINTOCK, R O Rogion 1. Philadelphia, Fuel Facility & Haterials Safety Branch 78/05/18 2pp
- --8007170278 IE Insp Ropt 30-13219/78-01 of License 19-17039-01 on 780425 No noncompliance noted Major areas inspected procedures & representative records, personnel interviews & observations by inspector * Region I, Philadelphia, Office of the Director 78/05/10 3pp
- --B007170304 IE Insp Rept 77-01 of License 19-17039-01 on 790111 No noncompliance noted Major areas inspected procedures & representative records, personnel interviews & observations by inspector MCCLINTOCK, R O Region i, Philadelphia, Office of the Director 79/01/11 App
- --B007170306 IE Insp Rept 78-01 conducted on 781011 No noncompliance noted Major areas inspected procedues & representative records, personnel interviews & observations by inspector CAMPELLLM, MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 78/10/17 13pp

- --B007i703i4 lE Insp Rept 79-01 of RAD Svcs.lnc on 79i2i2 Noncompliance noted failure to keep records of receipt transfer storage. survey & monitoring of mails CAMPEELL.M. NCCLINTOCK,R O Region 1. Philadelphia. Office of the Director 80/01/02 12pp
- --8007170318 IE Insp Findings & Licensee Ack dtd 690916 of License 37-13129-01 Insp findings no noncompliance noted STEARNS.C F Atomic Energy Commission 69/09/16 9pp
- --B007170326 Ack receipt of 751109 itr informing NRC of steps taken to correct violation noted in IE insp on 751009 Actions will be examined during subsequent insp of licensed program NRLSON.P R Atomic Energy Commission, Directorate of Regulatory Operations 75/11/12 lp
- --8007:70328 Informs NRC of steps taken to correct violation noted in IE insp on 751009 Corrective action complete inventory of Co-60 has been taken & new procedure is under preparation to avoid future problems

 LINNEMAN.R E Radiation Management Corp 75/11/05 ip
- --8007i70399 Discusses IE insp Repts 30-06309/79-01 & 30-14546/79-01 of Licenses 37-13i29-01 & 37-i3i29-02 on 790201 & forwards notice of violation MCCLINTOCK.R O Region i, Philadelphia, Office of the Director 79/02/12 2pp
- --8007170402 Notice of violation from insp on 790201 Noncompliance noted failure to instruct all individuals working in restricted area of precautions & procedures to minimize exposure to radiation & radioactive matis

 * Region i. Philadelphia, Office of the Director 79/02/12 2pp
- --8007170411 Ack receipt of 790305 ltr informing NRC of steps taken to correct violations noted in IE they of Licenses 37-13129-01 & 37-13129-02 on 790201 MCCLINTOCK, R O Region i, Philadelphia, Fuel Facility & Materiels Safety Branch 79/03/23 ip
- ---8007170416 Responds to NRC 790201 ltr re violations noted in IE insp of Licenses 37-13129-01 & 37-13129-02 on 790201 Corrective actions addi instructions given now employees & surveys made & records mathetined KIM.S M Radiation Management Corp 79/03/05 4pp
- --8007170432 IE insp Rept 79-01 on 790201 Noncompliance noted failure to instruct all individuals working in restricted area of precautions & procedures to minimize exposure to radiation & radioactive matls

 MCCLINTOCK, RO Region i, Philadelphia, Office of the Director 79/02/05 9pp
- ---800717043B IE Insp Rept 80-01 on 80022B Noncompliance noted no records found showing receipt of samples from customers COSTELLO.F. CAMPIELL.M Region I. Philadelphia. Office of the Director 80/03/19 lipp
- B007220207 Addi response to FOIA request for documents re proposed nuclear reactors located near Gyaema,Korea Forwards JR Shea draft memo to Commissioners SECY-80-239 is located in DC PDR Info partially withheld (rof FOIA Exemption 5) FELTON,J M Division of Roles and Records 80/07/15 2pp
- --B007220214 Draft Commission paper re licensee for GE to export two reactors. KNU 7 & 8 to Korea Reactors would be located on Oyasme Forwards final Executive Branch views Info partially withheld (ref FOIA Exemption 5) SMEALJR Office of international Programs, Director B0/07/15 Spo
- 8007220243 Add1 response to FDIA request for info concerning facility Nonexempt portions of documents listed in app are located in DC PDR Documents 1.2 & 3 partially withheld tref FDIA Examptions 4 & 5) Documents 5 & 6 are underpoing review FELTDN.J M Division of Rules and Records 80/07/14 3pp
- --8007220281 Discusses 800227-29 site visit to further evaluate effectiveness of new process monitoring license conditions. Info partially withheld (ref FOIA Exemptions 4 & 5). Responses to M Udall questions dtd 800306 encl. JOY, D R. Material Control Licensing Branch 80/03/11 4pp
- 8007220326 FOIA request for "Submerged Domineralizer Bys Tachnical Evaluation Rept"

 MONTAGUE, P National Campaign for Radioactive Waste Safety.

 BO/06/23 lp

- 8007230224 Responds to FDIA request for H Denton 800613 memo to Commissioners entitled, "Compliance of DL Applications H/Current NRC Regulations.Reg Outdes & Branch Technical Positions "Forwards memo FELTON.J M Division of Rules and Records 80/07/14 1p
- --8007230234 Requests astimate of NRC & licenses resources involved in implementing proposed requirements of anci draft mema renew OLS compliance w/current NRC rules, reg guides & branch tachnical positions Response expected by 800523 CHILMS J Dffice of the Secretary of the Commission COMPS-80-13 BO/05/12 2pp
- 8007230229 FOIA request for H Denton 800613 memo to Commissioners antiklod. "Compilance of Di. Applications W/Gurrent NRC Regulations. Reg Guides & Branch Technical Positions "WEISS.E R Sheldon. Harmon & Weiss 80/07/11 ip
- 8007230250 Add1 response to FOIA request for all info re changes to proposed fire protection rule in SECY-80-088 & record of Commission's voto Commissioner Bradford concurrence encl.

 Six documents withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 80/07/16 2pp
- --8007230256 Notifies that Commissioner Bradford concurs w/revisions in 800416 memo re fire protection rule (SECY-80-088) Excerpt of rule encl THONPSON.H L Commission 80/04/21 3pp
- BOO7230635 Requests comments on encl memo describing results of corresion tests for commercial grade mild steel partially embedded in DDN vinyl ester-styrene waste form containing NS-i decontamination waste concentrate
 NEILEON,R M Brookheven National Laboratory 79/12/04 7pp
- 8007240183 Add1 response to FOIA request for five catagories of info re proposed fire protection rule Consultant rept.CT-1256 & ACR8 member rept are available in PDR Forwards R Ferguson 791026 memo & 60 A Filotto 800516 memo FELTON.J M Division of Rules and Records 80/07/18 1p
- --8007240188 Forwards brisf description of evaluation program & guideline documents for proposed fire protection rule Draft proposed rule entl
 FEROUSEN, R Plant Systems Branch (Pre 791030) 79/10/26 49pp
- E007240195 Add1 response to FGIA request for three categories of documents re Union Carbide U mill facility in Gas Hills, HY Forwards documents listed in App A H/o encis
 FELTON, J H Division of Rules and Records BO/07/17 3pp
- 8007240431 Responds to FD1A request for records developed in course of NRC investigations of 12 corporations & seven individuals NRC has no documents subj to request FELTON.J H Division of Rules and Records 80/07/17 1p
- 8007240437 FBIA request for records developed in course of NRC investigations of 12 corporations & seven individuals.

 BCMMER. J. C. Stroock, Stroock & Lavan. 80/07/03 ip
- BOO7240433 Responds to FOIA request for any add1 insp documents re US Radium Corp No further documents are available FELTON. J M Division of Rules and Records 80/07/22 ip
- 8007240462 FDIA request for any add1 insp documents re US Radium Corp HEGARTY, W Self-Powered Lighting, Ltd 80/07/01 ip
- 9007240479 Ltr to all applicants for CPs & OLs requesting info re evacuation time estimates around proposed nuclear plants Requested info should be submitted by 800801 EIERNHUT.D G Division of Licensing 80/07/02 ip
- 80072B0022 Responds to FDIA request for R Burnett speech delivered at Inst of Nuclear Matls Mgt annual meeting Forwards three speeches presented by R Burnett at annual meeting FELTON.J M Division of Rules and Records 80/07/22 ip
- --8007280055 "Physical Protection Roles & Requirements What Drives Them "ERICKSON, R A , BURNETT, R Physical Security Development Branch 80/07/22 Spp
- --BOO7250058 "NRC Response to Bignificant Inventory Differences "
 BURNETT,R Physical Security Development Branch 80/07/22 45p
- --8007250961 "Future Outlook for US Nuclear Safeguards " DIRCKS:N J Office of Nuclear Material Safety & Bafeguards 80/07/22 Spp

- 8007250043 FOIA request for R Burnett speech delivered at Inst of Nuclear Hatls Mgt annual meeting WEISS.E R Sheldon. Harmon & Weiss 80/07/08 ip
- 8007230069 Responds to FOIA request for info re availability of NRC mostang records Provides list of available NRC meeting records All documents are available in PDR FELTON, J M Division of Rules and Records 80/07/22 2pp
- 8007250072 FOIA request for info re availability of NRC meeting records ETHEREDGE, California, Univ of, Berkeley 80/06/20 Ip
- B0072500B3 Add1 response to FDIA request for all documents involved in preparation of NUREG-0459 & upgraded physical protection regulations in iOCFR73 Provides list of 55 unclassified NRC documents & 236 unclassified open source documents FELTON.J H Division of Rules and Records 80/07/16 8pp
- 8007280197 Add1 response to FOIA request for certain proposals submitted under RFP-R8-NKS-024 Forwards nonpreprietary versions of proposals submitted by NUSAC, Inc. BNHL. Los Alamos Technical Associates, Inc & Science Applications, Inc FELTON, J M Division of Rules and Records 80/07/21 lp
- --8007280202 Nonproprietary response to RFP-RS-NMS-024, "Development of Advanced Mati Accounting Sys Simulation Model "Proposal develops simulation model for evaluating current accounting practices & to study data analysis Battelle Hemorial Institute, Pacific Northwest Laboratory RS-NMS-80-024 79/12/28 27pp
- --8007280209 Nonproprietary response to RFP-RS-NMS-024, "Development of Advanced Matl Accounting Sys Simulation Model " Describes technical approach.related experience & capabilities, organization & mgt & personnel * Los Alamos Technical Associates, Inc. RS-NMS-80-024 80/01/04 32pp
- --B0072B02i3 Nonproprietary revised response to RFF-RB-NMB-024,
 "Development of Advanced Matl Accounting Sys Bimulation
 Model " Develops computer program for use in analysis of
 matl balance period inventory results,
 * Science Applications, Inc. RB-NMS-80-024 80/04/16 19pp
- 8007280267 Responds to FOIA request for 1tr identifying individual who informed Region 3 of possible radioactive matl deposited in disposal dump in Newburgh Heights,OH NRC was informed by telcon No documents are available FELTON,J M Division of Rules and Records 80/07/22 1p
- 8007280270 FOIA request for ltr identifying individual who informed Region 3 of possible radioactive matl deposited in disposal dump in Newburgh Heights, DH ZELLNER, R J McGean Chemical Co , Inc 80/07/03 ip
- B007280272 Responds to FOIA request for NRC contracts awarded for FYB0 Forwards list of contracts executed in FY78,FY79 & FYB0 All contracts are available in PDR FELTON, J H Division of Rules and Records 80/07/16 ip
- --8007280279 Lists all contracts executed in FY78,77 & 80 FELTON,J M Division of Rules and Records 80/06/19 24pp
- 8007280274 FOIA request for NRC contracts awarded for FY80, VERRECCHIA.F Critical Mass Energy Project 80/07/07 1
- 8007280283 Responds to FOIA request for records re Scott Luminous, Inc Forwards documents listed in App A Deletions of info partaining to other companies have been made in Documents 1,2,10 & 18 H/o encis FELTON, J M Division of Rules and Records 80/07/17 3pp
- B007280285 F01A request for records re Scott Luminous. Inc TAYLOR. J 8 Affiliation Unknown 80/06/25 2pp
- B0072B0270 Responds to FOIA request for Commissioner Gilinsky 1979 telephone logs & related documents Requested info is available in PDR FELTON.J H Division of Rules and Records 80/07/17 ip
- 8007R80294 FOIA request for all Commissioner Gilinsky telephone lags, calendars & memos IRVINE,R J Accuracy in Media 80/07/10 1p,

- SOC73000B2 Add1 response to FOIA request for mat1 received considered or approved by Commission during consideration of facility inventory info partially withheld security measures & restricted data free FOIA Exemptions 3 & 4)
 FELTON, J M Division of Rules and Records 80/07/16 3p
- BOO7310232 Responds to FOIA request for documents re export of SNM & replacement parts to India Forwards documents listed in App A Documents will be placed in PDR FELTON J B Division of Rules and Records BO/07/24 3pp
- --8007310247 Updates BCO403 analysis of fuel requirements for Tarapur I & Il Analysis is based on more detailed & current info Provides discussion.conclusions.refueling schedule & projected operating schedule for reactor GB Bedi ltr encl PEDERSEN.K Office of Policy Evaluations 79/01/16 9pp
- --8007310290 Provides supplementary info re Tarapur reactor fuel requirements, in response to Commissioner Abberne question re basis for fuel fabrication time DOS provided 9-month fabrication period Inadequete data available for analysis PEDERSEN.K Office of Policy Evaluations 79/01/18 2pp
- --8007310260 Lists questions re review of License XSNM-1379 concerning proposed export of low enriched fuel to India Requests Executive Branch response SHEA, J R Office of International Programs, Director 79/05/25
- --B007310266 Forwards updated analysis of estimated fuel requirements for Tanapur reactors, reflecting fuel covered by application XSNN-1379 M/o encl DEVINE.J Office of Policy Evaluations 79/06/07 ip
- --B007310270 Application by OE for license to export six traversing incore probe detector assemblies to India WILSON, B D General Electric Co DDW-79122 79/05/07 ip
- 8007310237 FOIA request for documents re export of SNM & replacement parts to India BARNES, J N Center for Law & Social Policy 80/06/30 4pp
- B007310258 Responds to appeal re FDIA request for list of snvironmentally qualified equipment Forwards nonproprietary portions of Franklin Research Ctr rept & complete Wyle Labs rept & NUREO-0390 NUREO-0390 not encl DIRCKS W J Office of the Executive Director for Operations GD/07/24 1p
- --B007310265 "Equipment Qualification Test Bummary of Bome Equipment Tested at Franklin Research Ctr." nonproprietary version * Franklin Institute/Franklin Research Center 80/07/24 57pp
- B007310262 Appeals denial of FOIA request for list of environmentally qualified equipment NRC failure to adhere to procedural requirements of FOIA constitutes illegal denial of request KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/06/18 2pp
- 8007310276 Responds to FOIA request for info re industrial use of radioactive magnesium-thorium alloy & any work-related problems associated w/use No records available subj to request Forwards documents listed in App A W/o encl FELTON, J M Division of Rules and Records 80/07/24 2pp
- BOD7310280 FOIA request for info re industrial use of radioactive magnesium-thorium alloy & any work-related problems associated w/use FARNAN. J Affiliation Unknown BO/07/07 ip
- 8007310481 Response to FOIA request for documents re transportation of spent fuel from Portsmouth, VA to Bavannah River Plant in Aiken, 8C Encl info partially withheld sefeguarding procedures & security measures (ref FOIA Exemption 4) PELTON, J M Division of Rules and Records 80/07/22 3pp
- ---B0073104B3 Confirms B00920 telcom notifying NRC that Pegase Cask i contains 36 irradiated fuel elements & will arrive in Portsmouth, VA Info partially withheld date of arrival (ref FOIA Exemption 4) NRC fee determination enci STONEBURNER, W Transmutiser, Inc. 164B7. B0/05/20 2pp

- --BOO731049& Confirms 800921 toleon notifying NRC that Pegase Cask 4 contains one irradiated fuel element & will arrive in Portsmouth, VA Info partially withheld date of arrivalitef FOIA Exemption 4) NRC fee determination encl STONEBURNER, W Transnucleur. Inc. 14486 80/05/21 Zpp
- --B007310503 Requests extension until B00530 re route approval Two casks, Model 8B/23 are expected to arrive & no elternative southern ports are available to spont fuel shipments w/svc from Sweden info partsally withheld (ref FOIA Exemption 4) HARMON D & Edinw International Co 80/02/22 1p
- --B0073i0506 Confirms 800421 notification of spent fuel shipment from Bweden arriving in Fortsmouth,VA Info partially withheld dates & times (rof FOIA Exemption 4) RAVENDEROFI,N Edipw International Co AB 24 2 80/04/21 2pp
- GOO73104B3 Responds to FOIA request for proposal RS-NRR-80-111.
 "Charactorization of Nuclear Power Plant Protective Coating
 Gys Under DBA Conditions "Forwards proposal
 FELTON, J M Division of Rules and Records 00/07/24 ip
- --B007310492 Solicitation for RS-NRR-80-111. "Characterization of Nuclear Power Plant Protective Coating Sys Under DBA Conditions " Proposals should be submitted to NRC Div of Contracts DDUOMERTY, D J Technical Assistance Contracts Branch RS-NRR-80-111 80/01/18 94pp
- 8007310488 FOIA request for proposal RS-NRR-80-111, "Characterization of Nuclear Power Plant Protective Coating Sys under DDA Conditions"
 PUSCIELL A A Consumers Power Co PUSC 25-80 80/07/07 1p
- 8007310544 Add1 response to FOIA request for 57 decuments referenced in M Toker memo to ACRS re pellet-cladding interaction GE preparation of nonpreprietory version of Decument 3 delayed. Request for Document 17 withdraum Forwards Document 52 FELTON.J M Division of Rules and Records 80/07/22 ip
- ---BOD73:0549 Draft request for add1 data re reactivity initiated accident fuel behavior Data will be used in developing improved fuel damage limits & acceptance criteria for licensing PHRs & BHRs DENTON.41 R Office of Nuclear Reactor Regulation, Director
- GEN TEC 19 GENERIC TECHNICAL ISSUES
- BOO6120859 Forwards NUREO/CR-1321 GE Cummings will be added to svc list for future repts emanating from genetic task to sys interaction W/o enci CDFFMAN.F D Systems Interaction Branch 80/05/28 is
- B007030015 "Code Assessment & Applications Program Piping Bys Stress Dependent Damping Study " GRUBBIR L 6080 Idaho.Inc FIN A-6156 79/10/31 20pp
- BOO7070249 Forwards comments on NUREG-0619 Bys changes such as low flow feedwater control & rerouting of reactor water cleanup sysshould only be implemented hased on plant unique evaluations demonstrating performance improvement ORIDLEY.R L General Electric Co MFN-111-080 80/06/19 11pp
- BOO7210423 Summary of third technical BOO315-16 meeting in Nethesda.MD re task action plan A-11 progress & future plans JOHNSON.R E Generic Isques Branch BO/06/13 App
- --8007210430 Notification of thisd technical 900513-16 meeting in Betheads, MD to discuss task action plan A-11 progress & future plans JDINSQN,R C Generic Issues Branch 80/05/06 4pp
- BOO7D10256 Notification of BOO7D0-31 meetings w/vendors & consultants in San Jose, CA to discuss Mark III LOCA-related pool dynamic load critoria FIELDS.M Containment Systems Branch BO/07/2: 4pp
- 18E INSPECTION AND ENFURCEMENT
- 7710250495 IC Circular BO-13, "Grid Strap Damage in Westinghouse Fuel Assemblies"

 **Office of Inspection & Enforcement. Office of the Director BO/05/28 2pp
- BOOR280661 IE Builetin 80-13, "Cracking in Care Egray Spargers" * Office of Inspection & Enforcement, Office of the Director 80/05/12 3pp

- B004240210 PND-B0-Ol on B00313. Westinghouse notified IE of pending 10CFR21 Ltr re-potential cracking of control rod guide tube support pins in foreign FMR Vendor proposes pin insp-program involving two domestic plants currently down MDDDS. R. Office of Inspection & Enforcement. Defice of the Director NGONAN.V Engineering Branch 80/03/13 2pp
- B00424025B PNO-III-B0-43 on B00306.licensee 22-00057-06 received Po-210 static eliminator bar from SD Warren Co.West Brook.HE, that was leaking Delivery truck found contaminated DDT, state; Region 1 & carrier notified PAPERIELLO.C J. DAVIS.A B Region 3. Chicago. Office of the Director 00/03/07 ip
- 8004240278 PNO-11I-BO-46 Licenser 4B-00537-06 reported employee working in radiation therapy dept w/Co-60 unit had whole body badge rept of 5 2 rems for period BO0110-0210 Licensee will conduct formal review & submit 30 day rept PAFERJELLO. C. DAVIS.A B Region 3. Chicago. Office of the Director BO/03/33 10
- 8004240316 EN-80-COIA on 800310 order imposing civil penalties issued for License 29-09914-01 Action based on six items of noncompliance re loss of 55 C: Ir-192 source, exposure to individual & failure to rept loss BROCKETT, T Office of Inspection & Enforcement. Office of the Director THOMPSON. D Executive Officer for Operations Support 80/03/10 ip
- 8005020572 PND-1-80-052 on 800331.Region I was notified by Info Technology.Int of receipt of vial labeled Xe-133 Vial had been included in shipment from licensee Vial was shielded Only background levels of radiation measured at surface OLENN.J E , SMITH.G H Region I. Philadelphia, Office of the Director 80/04/01 ip
- 8005050047 IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" * Office of Inspection & Enforcement, Office of the Director 80/05/30 5pp
- 8005050056 IE Bullstin BO-14. "Degradation of BWR Stram Discharge Vol Capability " * Office of Inspection & Enforcement, Office of the Director BO/06/12 2pp
- 8005050059 lE Info Notice 80-22, "Breakdowns in Contamination Control Programs" * Office of Inspection & Enforcement, Office of the Director 80/05/28 2pp
- 8005050061 IE Info Notice 80-23. "Loss of Suction to Emergency Femouster Pumps " * Office of Inspection & Enforcement, Office of the Director 80/05/29 ip
- BOOS050063 IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/IGCRSO 55(e)" * Office of the Director 80/06/13 ip
- 8005050064 IE Info Notice 80~26. "Evaluation of Contractor GA Programs " * Office of Inspection & Enforcement, Office of the Director 80/06/10 2pp
- 8005050066 IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc. Models 1151 & 1152 Pressure Transmitters" * Office of Inspection & Enforcement, Office of the Director 80/06/27 6pp
- 8005050067 IE Circular BO-16. "Operational Deficiencies in Rosempunt Model 510DU Trip Units & Nodel 1532 Pressure Transmitters " * Office of Inspection & Enforcement, Office of the Director \$\text{control_{127}} 2p\$
 - e 80-27, "Degradation of Reactor Coolant Pump

 1 & Enforcement, Office of the Director
 - iss of Emergency Notification fice of the Director
 - >r Coolant Pump Cooling &

- 8003050074 IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel"

 # Office of Inspection & Enforcement, Office of the Director 80/06/24 2pp
- BO07140621 FNO-IV-BO-023 on BO0624, all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of svc for maint HUNNICUTT, D Region 4, Dallas, Office of the Director BO/06/25 Zbo
- BO07230143 EN-BO-02B on BO0703, order issued requiring prompt repactaging of waste byproduct mat1 & prompt transfer to authorized land burial facility Action based upon licensee agreements in BO0701 meeting w/Region 1 ofc BROCKETT.T. T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director BO/07/03 ip
- 8007230216 PNO-1-80-099 on 800710,50 Bluestein reported that package containing 4 4 mCi I-131 had been stolen from private automobile KINNEMAN,J D. SMITH.C H Region i. Philadelphia. Office of the Director 80/07/10 ip
- 800724013B PNO-V-BO-059 on 800717, Region 5 ofc notified that two shipments of 14 mCl 1-125 had been damaged in shipment Inspectors dispatched to inspect shipment Radiological survey detected no contamination THOMAS.R D Region 5. Ban Francisco, Office of the Director 80/07/18 ip
- 8007250197 PND-I-80~102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level scram Cold shutdown underway for further analysis of incident KEIMIO.R R Region 1. Philadelphia. Office of the Director. 80/07/18 2pp
- BO07290058 PNO-I-80-i01 on 800715, plant tripped from i00% power due to water leakage on coolant pump penetrations Possible damage to coolant pumps & penetrations is being investigated REBELOWBKI,T Region i, Philadelphia, Office of the Director 80/07/16 ip
- 8007290331 PNO-IV-80-024 on 800716 plant was shut down due to primary to secondary leak Max radioactivity detected was below Tech Spec limit
 JOHNSDN.W D Region 4. Dallas, Office of the Director 80/07/17 ip

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8004010434 Buggests that rushes toward opening existing power plants or starting const on new plants should be weighed w/precautions for safety & safe disposal of nuclear wasts NEILSDNLL E Affiliation Unknown 80/03/31 ip
- 8003200366 Act receipt of 800312 resolution in support of nuclear energy adopted by Northumberland County Board of Supervisors Certain short-term tasks identified in TMI Action Plan, must be completed prior to UL issuance KAMMERER.C Office of Congressional Affairs 80/04/20 2pp
- BO06:20402 Discusses reasons for delays in licensing new nuclear plants, in response to B00424 requests re HA Cosgrave comments Delays caused by post-TMS efforts to improve safety at operating plants
 KAMMERER, C Office of Congressional Affairs 80/05/20 2pp
- 8006/20419 Responds to 800423 re L Nutter concerns about nuclear plant siting & evacuation plans NRC not responsible for decision re wheather on not nuclear power should exist in UB Proposals to stop nuclear power development not enacted.

 KAMMCRER.C Office of Congressional Affairs 80/05/07 2pp
- 8006170304 Informs that Ofc of Technology Assessment has been assigned to review & evaluate current status of nuclear power plant standardization NRC assistance is requested to ensure that views of all parties of interest are represented.

 JOHNS, L. B. Congress (Joint & Rotating Committees, etc.) 80/06/11
- B007020069 Responds to uncl MW Will B00430 inquiry re safety aspects of military nuclear plants vs commercial nuclear plants NRC not responsible for licensing military plants DDE, Div of Naval Reactors, should be contacted DIRCKS, M J Office of the Executive Director for Operations B0/06/24 2pp

--B007290036 Informs that farm has been selectd by major power company to design new nuclear power plant operator training facility Requests meeting to discuss how firm may be of assistance to NRC O'NEILL, 7 V Lester B Knight & Associates, Inc B0/06/24 ip B007290089 Responds to B00324 ltr re nuclear power Forwards Chapter 5 of of President Carter's Second Natl Energy Plan DENTON, H R Office of Nuclear Reactor Regulation, Director B0/05/14 13pp

NUREO NUREG REPORTS AND HELATED CORRESPONDENCE

B007010498 Forwards comments of Interorganizational Advisory Committee on Radiological Emergency Planning & Preparedness on NUREO-

8007010498 Forwards comments of literorganizational Advisory Committee on Radiological Emergency Planning & Preparedness on NUREG0659 & NRC statement of interim NRC policy on stockpiling potassium iodide, in response to 800505 & 09 ltrs
MANCUSD.F Connecticut, State of 80/06/25 Spp

8007020396 Advises that ltrs to OL applicants, CP holders & licensees, which contain NUREG-0660 requirements are being prepared for OL applicants & CP holders. NRC will use requirements presented in Encl 1 of SECY 80-230

EISENHUT, D G Division of Licensing 80/06/02 2pp

BOO7030350 NUREQ/CR-1316
"Solubility Classification of Airborne U Products Collocted at Perneter of Allied Chemical Plant Hetropolis, IL "
KALHARF.D R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-21239 PNL-3288 80/05/31 34pp Available at MITS

8007030339 Advises that C Michelson concerns, originally addressed to C-E Sys 80 designs, should be forwarded to R&M Responses necessary by 791011 for NUREG-0565 witteup ROSZTGCZY, Z R TMI-2 Bulketins & Orders 79/09/06 2pp

8007030373 NUREQ-0597
"User's Guide to GASPAR Code"
ECKERMAN.K F , CONGEL.F J Assistant Director for Environmental
Technology RECECKLEIN,A K Occupational Health Standards Branch
80/06/30 88pp Available at 0PO \$3 78

BOO7030374 NURREG-0561 RI
"Physical Protection of Shipments of Irradiated Reactor
Fuel, Interim Guidance"
"Office of Nuclear Haterial Safety & Safeguards 80/06/30 74pp
Available at 060 \$3.75

BOO7070249 Forwards comments on NUREG-0619 Bys changes such as low flow feedwater control & rerouting of reactor water cleanup sys should only be implemented based on plant-unique evaluations demonstrating performance improvement GRIDLEY.R L. General Electric Co. MFN-111-080 80/06/19 11pp

BOO7070351 Comments on NUREG-0388 "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "
Generic requirement for typo testing may restrict available means for qualification w/o positive validity of results SCHERER.A F C-E Power Systems LO-BO-038 80/06/27 3pp

B007090015 BECY-80-275
Discusses finalization of emergency planning rule changes, including consideration of public comments Recommends FR publication re final rulemaking Related documentation encl MINDOUE, R D Office of Standards Development, Director B0/06/03

--B007090017 NUREO-0685

Draft "Environ Assessment for Effective Changes to 10CFR50 & App E of 10CFR90.Emorgency Planning Requirements for Nuclear Power Plants " Related documentation encl DTI.N R Division of Siting, Health & Bafoguards Standards 80/06/30 54pp

BOO7090163 Forwards "Human Engineering Quide to Control Room Evaluation," Pinal rept.Vols 1 & 2 re control room evaluation process & human engineering guidelines, respectively MALONE, T B Essex Corp 80/06/30 1p

--8007090144 NUREO/CR-1580 VI
"Human Engineering Guide to Control Room Evaluation,"
Vol 1 re control room evaluation process
MALLORY.X - FLEGER.S - JOHNSON-J Essex Corp NRC-04-79-209
80/08/31 100pp

--B007090167 NUREG/CR-15B0 V2

"Human Engineering Guide to Control Room Evaluation." Vol 2
re human engineering guidelines
HALLDRY.K , FLEGER.S , JOHNSON.J Essex Corp NRC-04-79-209
B0/08/31 140pp

BOO7090214 Requests extension of comment period until at least 800915 re NUREG-0577 & amends covered in 800519 ltr Significance & possible impact of both documents may not presently be recognized & justified CLAYTON.F L Alabama Power Co 80/07/02 ip

8007090331 Comments on NRC 800520 ltr re addl guidance on NUREO-0577 Proposed revised procedure should be revised to reflect applicants of plants w/o CP who have fabricated RCS component supports
LENTSCH, J W Portland General Electric Co JWL-269-80 80/07/02

BOO7090362 Summary of BOO612 meeting w/BHR owners group re plans for satisfying safety & relief valve test requirements per NURGE-0378 Section 2 1 2 HEMMINGER E G Mechanical Engineering Branch BO/06/26 6pp

BOO7090371 NUREO/CR-1523

"EFACTOR Computer Code for Calculating Dose Equivalent to
Target Organ per uCi-Day Residence of Radionuclide in Source
Organ Supplementary Rept "
DUNNING, D E , PLEASANT, J C , KILLDUOH, G Q Oak Ridge National
Laboratory FIN B-0188 DRNL/NUREG/IM/- 80/05/31 130pp
Available at NTIS

B007100363 NUREG/CR-020B R1
"Pulsed Noutron Activation Measurement of Emergency Core
Coolant Bypass Flow on LOFT Reactor "
KEMLEB:P Argonne National Laboratory BDLBRID; C W E0&O, Inc
ANL-CT-78-37-2 B0/06/30 94pp Available at NTIS

B007110195 Ack receipt of 800915 ltr expressing concern w/proposed approach to ATMS in NUREO-O460.Vol 4
DENTON-H R Office of Nuclear Reactor Regulation, Director B0706/04 Ip

--8007ii0203 Expresses concern on behalf of owners of C-E designed & operating NSSS plants re approach to ATW9 in NUREG-0460, Vol 4 NRC on course that will prescribe resolution to ATW9 issue w/o due regard to industry comments
LUNDVALL.A E Daltimore Gas & Electric Co 80/08/15 2pp

--BD07110207 Forwards comments on NUREQ-0460.Vol 4 re ATMH on behalf of owners of C-E NBSB power plants issue about to be resolved by NRC w/o consideration of many relevant views More detailed comments will be submitted in Jul 1980 LUNDVALL.A E Baitimpre Gas & Electric Co 80/05/15 4pp

B007110439 Responds to B00118 ltr transmitting resolution re public health implications of nuclear power plants NUREG-0654 requires that public info program be developed jointly by util. state & local officials

ORIMEBIBK Emorgency Preparedness Task Force 80/06/R3 2pp

--8007110443 Forwards resolution re public health implications of nuclear power plants NRC should support future legislation dealing wisafety & guidelines for safe handling of nuclear matts & wastes Requests that response be sent to H Whitman BAKCR.T Student Nurses Association of Pennsylvania 80/Q1/18

B007110453 Bubmits comments on NUREC-0577, addl guidance re major component support low-alloy bolting NRC should consider reduction in max postulated flaw depth & include acceptable conversion table between yield strength & motl hardness COOPER, W E Teledyne Engineering Services 809-042 80/07/03

8007110560 NUREO-0480
"TM1-1 Restart,Evaluation of Licensee Compliance W/
Short- & Long-Term Items of Section II of NRC Order
Dtd 790809,Met Ed. at al"
Office of Nuclear Reactor Regulation, Director * Division of
Licensing 80/06/30 230pp Available at NTIS

8007140083 Forwards comments on NUREG/CR-1280 Rept shows that writer is not aware of many positive espects of civilian protram Differences between Navy & civilian programs were not discussed PARKER.W D Duke Power Co 80/06/11 bpp

BO07140092 NUREG/CR-1459
"Experiment Data Rept for Bemiscale Mod-3 Small Break Test Geries (Tests S-SB-2 & B-SB-2A) "
MYABAKI,D H E000 IdahorInc E00-2038 B0/06/J0 221pp

8007140396 Forwards "Emergency Procedure Guidelines" for BHR owners group, per NUREO-0578, Requirement 2 i 9 Description of how analyses of NEDO-24708 & emergency procedure guidelines apply to all FSAR Chapter 15 events forthcoming BUCHHOLZ, R H General Electric Co MFN-117-BO 80/06/30 40pp

B007140357 Requests extension of completion date, until B00915, for comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports"
HIDNER, W A Georgia Power Co 80/07/07 ip

BO07140375 Forwards comments on NNREG-0577 Sandia rept considers only matls used in component supports at responding nuclear plants & classifies plants according to susceptibility to brittle fracture w/o considering all factors ZARAKAS, P Consolidated Edison Co of New York B0/07/07 2pp

8007140610 NUREG/CR-1464
"Review of Nuclear Power Plant Offsite Power Source
Reliability & Related Recommended Changes to NRC Rules &
Regulations "
BATTLE.R E . CLARK, F H . REDDOCH, T W Dak Ridge National Laboratory
FIN 8-0235 ORNL/NUREO/TM-3 80/05/31 113pp Available at NTIS

8007140617 NUREC/CR-1258 V2
"Insp Methods for Physical Protection Project Annual Rept.
Mar 1979 through feb 1980"
BRADLEY,R T. BOMDEN. D D. OLBON. A W. Lawrence Livermore Laboratory
FIN A-0143 UCID-18123-79-A 80/06/30 58pp Available at NTIS

BD07140701 Comments on NUREO-0654 smergency response plans must be simple to use & understand Nuclear mystique must be considered in how & when to notify public to prevent counterproductive reactions
VANDENBURGH, D E Yankee Atomic Electric Co WYC 80-15 B0/05/30 iing

B007i504B6 Forwards comments on NUREO-0577 Main yield strength used to determine susceptibility of mati to stress corrosion cracking should be iBO ksi.for consistency w/Sandia rept (Page C-23) recommendations
L00MIS.J B Sargent & Lundy, Inc 80/07/07 2pp

B007160457 Comments on NUREO-75/087 NRC personnel drafting BRPs are confusing responsibilities NRC is incorrectly providing design details & design philosophy HALTER, J F Energy Products Group B0/06/06 3pp

BO07140489 Responds to NRC B00520 request for comments on NUREG-0577 Request requires significant engineering effort due to util five plants w/three different designs Add) three months (until Oct 1980) required to develop thorough comments RENNERGER, D. Washington Public Power Supply Bystem 002-80-143 80/07/09 1p

8007160491 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports " Every path to integrity demonstration should be left open to licenses SCHERER.A E C-E Power Systems LD-80-041 80/07/09 2pp

BOO7160495 Requests extension of comment period until BOO915 for reviewing "For Comment" edition of NUREG-0977 & providing significant comments DRAPER, E L Gulf States Utilities Co RBG-7964 BO/07/07 1

E007170311 NUREQ/CR-1253
"Methods for Assessing Background Leveis of Rediation & Rediative Meths in Environ Around U Mills "
WACHAN.N A., BILKER.H B., GLIBBMEYER.J A. Battelie Memoriai
Institute, Pacific Northwest Laboratory FIN B-2121-8 PNL-3256
E0/04/30 98pp Available at NTIS

8007170618 NUREG/CR-1512

"Evaluation of Matls Interactions for Advanced Reactor Sys," annual progress rept

8MANSON.D 0 . VAN PAABSEN.H L Aerospace Corp FJN 8-1130

ATR-8017814)-1 80/06/30 73pp Aveitable at NTIS

8007180031 NUREO/CR-1460
"LWR Safety Resparch Program Quarterly Progress Rept Oct-Dec 1979"
MASSEY, W. E., KYGER, J. A. Arguinne National Laboratory FIN A-2014
ANL-80-43 80/05/31 37pp Available at NTIS

BOO7180049 NUREG-1385
"Development of 'Good' Physical Protection Plan Capability
73 45(b)"
BENNETT.H A. GLASCOAGA.H T Sandia Laboratories BLOEDEL.S A
Allied General Nuclear Services FIN A-1153 SANDSO-7027
80/03/31 150pp Available at NTIS

8007180065 NUREG/CR-1413
"Radionuclide Dotay Data Dase Index & Summary Table "
KOCHER.D C Oak Ridge National Laboratory FIN 8-0198
DRML/NUREO-70 80/05/31 29pp Available at GPO

8007180072 NUREG/CR-1169 V3
"Safeguards Vulnerability Analysis Program (SVAP) User's
Manual"
ORVIS.N J Lawrence Livermore Laboratory FIN A-0115 UCRL-52730
80/05/31 97pp Available at NTIS

8007210391 Discusses 800713 & 17 telcon re definition & implementation of NUREO-0660 requirements for modifying HPCI/RCIC setpoints BHR owners group recommendations probably not to include mods to setpoints, due to negligible reduction BUCHHOL2,R H General Electric Co., Nuclear Energy Products Div RHB-057-80 90/07/11 2pp

BOO7210491 NUREG/CR-1500
"Selsmicity & Tectonic Relationships of Nemaha Upilift in OK Part III"
UK Part III"
LUZA:K V. LAMSON, J.E. Okiahoma, Univ. of FIN 8-5767 80/06/30 79pp Available at QPO 3.75

8007220019 NUREG/CR-0830
"Monitoring Random Errors of Nuclear Math Measurements"
BROUNS,R J. RODERTS,F P. MERRILL.J A Battelie Memorial Institute.
Pacific Northwest Laboratory FIN 8-20149 PNL-3022 80/06/30
39pp Avaiable at NTIS

B007220024 NUREQ/CR-1234

"Insider Threat to Secure Facilities Data Analysis "
HEINEKE, J. M. Lawrence Livermore Laboratory FIN A-0132
UCRL-52744 80/06/39 74pp

8007220034 NUREO/CR-111B
"Distribution of Illegal Incident Characteristics Cases of Bank Fraud & Embezilement Computer-Related Crime & Insider Theft from Drug Manufacturers & Distributors "
HEINEKE.J M Laurence Livermore Laboratory FIN A-0132 UCRL-52742 80/06/30 126pp

BO0722034B NUREG-0494
"TMI-Related Requirements for New Ols"
* Commission 80/04/30 43pp

8007230201 NUREO/CR-1555
"Critical Experiments Measurements & Analyses to Establish
Crack-Arrest Methodology for Nuclear Pressure Vessel
Steels," progress rept June-Doc 1979
ROSENTIELD,A R., ADOU-804FD, L., GILLOT,R. Dattelle Memorial
institute, Columbus Laboraturies FIN A-4046 DMI-2064 80/06/30
48pp Available at NTIS

B007230205 NUREG/CR-1440
"LMR Status Monitoring During Accident Conditions "
VONHERMANN, J. BROWN, R. TOMF, A EG&G Idaho, Inc FIN A-6294
EGG-CA-5153 B0/06/30 205pp Available at NTIS

BOO7230625 NUREG/CR-1361
"Drag Devices for Two-Phase Mass Fipw Measurements "
ANDERBON.J L CGRG Idaho.Inc FIN A-6038 EGG-2025 80/05/31
56pp

B007240132 Ack receipt of B00612 ltr to Chairman Hendrie expressing concern re NRC approach to AfGb (NUREO-0640) & requesting to address Commission on same day as NRC presentation First session will be devoted to NRC personnel only DIRCRB, M. J. Office of the Executive Director for Operations 80/07/01 lp

--B007240135 Expresses concern re NRC approach to ATWS issues Requests response to encl comment. & opportunity to make presentation on day that NRC presents issue for consideration LEE.O Atomic Industrial Forum B0/06/12 ip

--8007240137 Forwards paragraph to be included in response to Alf request to address NRC on ATMS issue
TRUBATCH.5 Office of the General Counsel 80/06/24 2pp

8007240262 NUREG-0030 V3 ND2 Vellow Book "Const Status Rept Nuclear Power Plants," data

Vallow Book "Const Status Rept Nuclear Power Plants," data as of 800430 ** Defice of Management and Program Analysis 80/04/30 50pp Available at NTIS

8007240283 NUREG/CR-0570 V2 APP

ADVANCED ROMEOVAR-020 V2 APP
"Technology, Safety & Costs of Decommissioning Ref Low Level
Waste Burial Ground," App. Vol 2
MURRHY, E 5, HOLTER, G M. Rattelle Nemorial Institute, Pacific
Northwest Laboratory FIN A-2(36 80/06/30 167pp

8007240394 NUREG/CR-1357

NOZEACGYA NUREC/CR-1557
"Steam-Haber Miring & Sys Hydrodynamics Program, Task 4."
Quarterly progress rept Apr-June 1979
COLLIER.R P. BISHCP.T A. DWORAK.J A Battelie Memorial Institute,
Columbus Laboratories FIN A-4048 BMI-2038 80/07/31 11App
Available at NTIS 34 25

BOO7240409 NUREG/CR-1486
"Seasonal Variation of 10 Square Mile Probable Max
Precipitation Estimates - US East of 105th Meridian,"
Hydrometeorological Rept 53
HD.F P , RIEDEL, J T Commerce, Dept of, National Decanographic &
Atmospheric Administration 80/06/30 98pp Available at NTIS

B007240439 NUREG/CR-1504

"User Guade to EPIC.Compute: Program to Calculate Motion of Fuel & Coolant Subsequent to Pan Fallure in LMFBR" PIZZIGA: PA . GARNER.P L . ABRAMSON.P B Argonne National Laboratory FIN A-2015 ANL-80-47 77/10/31 123pp Available

8007240478 NUREQ/CR-1489

007240478 NUREG/CR-1489
"Best Extimate Method vs Evaluation Method Comparison of Two
Techniques in Evaluating Selsmic Analysis & Design " Selsmic
safety mangins research program
BUMPUS-S E , JOHNSON, J J , SMITH, P D Lawrence Livermore Laboratory
FIN A-0130 UCRL-52746 60/07/31 116pp Available at NTIS
44 25

BD072B050B NUREO/CR-1440
"LWR Status Monitoring During Accident Conditions"
UDNHERRMANN, J. BRDWN, R. TOME, A. EG&O, Inc. FIN A-6294
ECG-EA-5133 B0/C6/30 209pp Available at NTIB \$6.00

G0072B0567 Submits comments on NUREG-C619 Bys changes for both fordwater & control and drive sys cannot be implemented by proposed dates June 1983 Forecast as earliest completion

JANECEX.R F Commanwealth Edison Co 80/07/23 2pp

8007280683 NUREC/CR-1520
"Experiment Data Rept for LOFT Anticipated Transient
Experiment id-3" GRAP forwarding itr encl
STITT, B D. CARPENTER, J M. Idaho National Engineering Laboratory
FIN A-6048 EGG-2045 86/07/31 135pp

8007270145 NUREG/CR-0508

"Security Communication Bys for Nuclear Fixed Site Facilities"

Facilities " HOWINGTON,L C Union Carbide Corp TAYLOR,L L Bernard Johnson,Inc FIN B-0218-7 Y/DW-128 80/07/31 192pp

8007290152 NUREG/CR-1395

Prompt Burst Energetics Experiments Fresh U Carbide/Sodium Series " REIL.K G . YOUNO.M F Sandia Laboratories FIN A-1016 SANDBO-0820 E0/08/31 (36pp /

B007290251 NUREG/CR-0743

OFFICE NUMBER NOT AS THE PROPERTY OF PARTY OF THE PROPERTY OF PARTY OF PART

8007270689 Comments on NUREO-0377 Large weld repairs made under restraint & possibly poor access could crack Structure could possibly become unsafe & fail KASCSAK.R X Long Island Lighting Co 80/07/23 2pp

8007290781 Request for stay of effectiveness of Commission 800616 statement of policy ro guidance for power reactor OLs. pending judicial review Commission action endorsing NUREG-0694 may be unlawful Certificate of Svc enc. HEISSIER Union of Concerned Scientists LATHAM, S B Shoreham Opponents Coalition WEISSIER Bheldon, Harmon & Weiss 80/07

--B007270B03 Affidavit stating that current NRC regulations re hydrogen control measures are not adequate to insure health & safety NUREG-0694 does not correct hydrogen control deficiencies Prof qualifications encl POLLARD, R D Union of Concerned Scientists 80/07/18 12pp

--8007290809 Affidavit re need to analyze sys interaction due to insufficient info for unresolved Safety Issue A-17 MINOR.G C Shoreham Opponents Coalition 80/07/11 9pp

8007300041 NUREG/CR-1260
"Evaluation of Docket Files for Terminated SNM Licenses"
HOLOHAY, C F, LANTZIP M, DICKSON, H W Oak Ridge National
Laboratory FIN A-9085-7 DRNL/NUREG/TM-3 80/06/30 5
Available at NTIS

8007300152 Forwards comments on proposed SRP 3 9 6. Revision 2 increased costs appear to be greater than those described in impact assessment Paragraph 1 i a re valve & pump testing should be VAN BRUNT, E E Arizona Public Service Co 45FR3425 002 80/04/27

8007300575 NUREO/CR-1483

"Blowdown Heat Transfer Separate Effects Program for Jan-Mar 1980." quarterly progress rept CRADDICK.W O , ANKLAM.T M , BOHANAN.R F Oak Ridge National Laboratory FIN B-0125 ORNL/NUREO/TM-3 80/06/30 18pp Available at NTIS

Available at

B007310004 NUREG-0304 V4

"Regulatory & Technical Repts." compilation for 1979

OLIU.H E . MCKENZIE.L , ARAGON,R Systematic Evaluation Program
Branch (Pre 791030) 79/12/31 300pp

BO07310007 NUREG/CR-1184

"Evaluation of Simulator Adequacy for Radiation
Qualification of Safety-Related Equipment"
BONZON.L . BUCKALEN.W H Sandia Laboratories FIN A-1031-0
BAN079-1787 B0/05/31 201pp

8007310009 NUREO/CR-1520
"Experiment Data Rept for LOFT Anticipated Transient
Experiment L6-5"
STITT, B D, CARPENTER. J M EQ&Q Idaho, Inc FIN A-6048 EQG-2045
80/07/31 151pp

8007310113 Natice of extension of public comment period for NUREG-0577, re potential for low fracture toughness & lamellar tearing on PHR steam generator & reactor coolant pump supports, from 800721 to 0808 ERNST, ML Assistant Director for Environmental Technology 80/07/18 2pp

8007310210 NURE9/CR-1301

"Analysis of Organohalogen Products from Chlorination of Natural Waters Under Simulated Biofouling Control Conditions"

Conditions

BEAN, R M . MANN, D C . RILEY, R G Battelle Memorial Institute Pacific Northwest Laboratory FIN 8-R098 PNL-3275 80/06/ 50pp Available at NTIS \$4 25

8007310216 NUREG/CR-1289

NOVINCES NOREYCK-1289
"Evaluation of Isotope Migration - Land Buriel, Water
Chemistry at Commercially Operated Low Level Radwaste
Disposal Sites." status rept through Sept 1979
WEISB. A J. COLCHBO.P Brookhaven National Laboratory FIN A-3042
BNL-NUREG-51143 80/03/31 294pp

B007310217 NUREG/CR-1439
"One Dimensional Neutron Kinetics Model for THOR Code,"
final rept

final rept LAMRENCE,R D , CHIANG,R T Brookhaven National Laboratory A-3014 BNL-NUREG-51187 80/04/30 36pp

8007310225 NUREO/CR-1119
"Piping Inelestic Fracture Mechanics Analysis "
CHAND. C I . NAMAOAKI M . GRIFFIS.C A Navy, Dept. of, Navel Research
Laboratory FIN B-6587 4259 80/06/30 91pp Available at NTIS

8007310R31 NURE9/CH-0742

"Review & Integration of Existing Literature Concerning Potential Social Impacts of Transportation of Radioactive Matis in Urban Areas "
QCRDDN,C, GEBSELL:T F Sandia Laboratories ANDERSON,C Wm Marsh Rice Univ FIN A-1077 SAND78-7017 80/07/31 180pp

BOO7310R34 NUREG/CR-1337
"Heat Removal Characteristics of Vol Heated Boiling Pools
#/Inclined Boundaries "
GREENS, G A , JONES, D C , BCHWARZ, C E Brookhaven National
Laboratory FIN A-3024 BNL-NUREG-51137 80/04/30 179pp

8007310241 NUREO/CR-1178 V1
"Design Quidance & Evaluation Methodology for Fired Site
Physical Protection Bys"
BENNETT, H A , OLASCOAQA, M T Gandia Laboratories FIN A-1153-9
GAND79-2378/1 80/07/31 100pp Available at NTIS #7 50

8007310R46 NUREO/CR-1295
"ORN. State Level Electricity Demand Forecasting Model"
CHERN.N B , DICK.J W , OALLGHER,C A Dak Ridge National Laboratory
FIN 8-0190-8 GRNL/NUREG-63 80/07/31 100pp Available at NTIB

8007310255 NUREO/CR-1425
"Cracking & Relocation of U Dioxide Fuel During Initial Nuclear Operation "
APPELHANS: A D . MILLER, R H EG&O Idaho, Inc DAGBJARTSSON, B Oarmany, Federal Republic of FIN A-6041 E00-2032 E0/05/3 SBbo

8007310471 NUREO/CR-1513

"Evaluation of Isotope Migration - Lend Burial Water
Chemistry at Commercially Operated Low Level Radwaste
Disposal Sites," quarterly progress rept, Jan-Mar 1980
CYYSCINSKI, K S. WEISS, A. J. Brookhaven National Laboratory FIN
A-3042 BNL-NUREG-51219 80/05/31 30pp Available at NTIS

BOO7310554 NUREO/CR-1477
"Heavy-Bection Steel Technology Program," quarterly progress
rapt for Jan-Mar 1980
WHITMAN.O D . BRYAN.R H Oak Ridge National Laboratory FIN B-0119
DRNL/NUREG/TM-3 BO/07/31 53pp Available at NT18

ORO CORRESPONDENCE WITH OTHER URGANIZATIONS

GOOA120770 Clarifies comments made at ANSI-N551 Steering Committee on Pumps 800421 meeting in Pittsburgh, PA re qualification issue Functional qualification by experience has merit but practical verification aspects pose problems Minutes encl BROWN, E J Director's Office 80/05/30 4pp

8007010013 Forwards fully executed std order for DOE work "ARAC Site Installations at Nuclear Power Plants," issued to LLL DICKINSON, P Energy, Dept of FIN A-0351-0 80/06/10 1p

--8007010017 Executed std order for DDE work "ARAC Site Installations at Nuclear Power Plants." issued to LLL
KERR.O W Assistant Director for State Agreements Programs *
Energy, Dept of FIN A-0351-0 80-80-006 80/06/10 ip

8007010157 Advises that IC Infa Notice 80-23, "Lose of Buction to Emergency Feedwater Pumps," was sent to listed utile on 800528 PAPPAB,H Region 3, Chicago, Office of the Director 80/05/30

8007010284 "Looking But Not Seeing Federal Nuclear Power Plant Insp Program" TYEL B Union of Concerned Scientists 80/06/30 163pp

8007010607 Advises that IE Circular 00-03. "Protection From Toxic Gas Hazards." was inadventently sont w/o encl NUREO-75/087, Sections 2 2 1,2 2 8,2 2,3 & 6 4 encl CARROLL, D E Region 3, Chicago. Office of the Director 80/04/03

8007020130 Forwards and order for DOE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Power Plants," for acceptance RYAN,R C Office of State Programs, Director 80-80-011 60/06/12

--B007020443 Std order for DOE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Power Plants." issued to 1D Natl Engineering Lab RYAN,R C Defice of State Programs, Director FIN B-1604-0 80-17-08-02 80/06/12 ip 8007030054 Advises that IE Bulletin 80-15, "Possible Loss of Emergency Notification Syn (ENS) W/Loss of Offsite Power," was sent to listed utils on 800618 PAPPAS.H Region 3, Chicago Office of the Director 80/Q6/19 20p

B007070132 Forwards std order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Pawer Plants." for acceptance RYAN R G Office of State Programs, Director 80/06/12 to

8007110543 Discusses choice of NBS x-ray techniques & choice of Cr values L-G should be included as one of five x-ray techniques Cx values published in final version of law should be defensible in court PLATD.P Michigan, Univ of 80/06/10 2pp

8007140421 Advises that IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability," was sent to listed utils on 800612 PAPPAS:H Region 3, Chicago, Office of the Director 80/06/13

B007140597 Advises that IE Bulletin 80-13, "Cracking in Core Spray Spargers," was sent to listed utils on 800512 PAPPAS,H Region 3, Chicago, Office of the Director 80/05/13

8007150770 Advises that iE Info Notice 80-27, "Degradation of Reactor Comiant Pump Studs," was sent to listed utils on 800611 PAPPAS:H Region 3, Chicago, Office of the Director 80/Q6/12 2ns

--B007150778 Advises that IE info Notice 80-27, "Degradation of Reactor Coolant Pump Studs." was transmitted for issuance on 800611 Notice should be issued to all PHR Pacilities holding OLS or CPs Draft itr encl MOSELEY, N C Division of Reactor Operations Inspections 80/06/10 200

B007170343 Advises that IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel." was sent to listed utils on 800624 PAPPAS.H Region 3. Chicago. Office of the Director 80/06/25

GOO7210334 Advises that IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies," was sent to listed utils on 800528 FAPPAS.H Region 3, Chicago, Office of the Director 80/05/30

8007220261 Advises that 1E Info Notice 80-26, "Evaluation of Contactor GA Programs," was sent to listed licensees on 800610 PAPPAS.H Region 3, Chicago, Office of the Director 80/06/12

8007240065 Advises that IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown," was sent to listed licensees on 900600 PAPPAB.H Region 3. Chicago, Office of the Director BO/06/24

B007280079 Ltr to all power reactor applicants & licensues re Commission memorandum & order on UCB 780302 petition for reconsideration of previous memorandum & order dto 780413 EISENHUT.D @ Division of Licensing 80/06/25 ip

--8007280084 Hemorendum & order affirming prior decision to deny UCS requested relief in view of add) improvement of fire safety CHILKS J Office of the Secretary of the Commission CLI-80-21 80/05/23 25pp

8007290104 Advises that IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)," was sent to listed utils on 800613 PAPPA9.H Region 3, Chicago, Office of the Director 80/06/16 20s

8007290771 Forwards summary of 800619 meeting w/AIF Subcommittee on Safety Parameter Integration in Rethesda.MD re draft emergency facilities functional requirements HINNERB.W Division of Systems Safety RO/07/09 ip

--8007290782 Summary of 800519 meeting w/AIF Bubcommittee on Safety Parameter Integration in NethesdarMD re draft emergency facilities functional requirements * Division of Systems Safety 80/07/09 7pp

- B007290781 Request for stay of effectiveness of Commission 800016 statement of policy reguldance for power reactor OLs. pending judicial review Commission action endorsing NUREO-0694 may be unlawful Certificate of Sic encl WEISS, E. R. Union of Contoined Bijentists. LATHAM, S. B. Shoreha Opponents Coalition. WEISS, F. R. Sheldon, Harmon & Weiss. 80/0 LATHAM, S B Shorehan
- --8007290803 Affodavit stating that current NRC regulations re hydrogen control measures are not adequate to insure health & safety NUREO-0894 does not correct hydrogen control deficiencies Prof qualifications enci
 PCLLARD.R D Union of Concerned Brientists 80/07/10 i2pp
- --8007290B09 Affidavit re need to analyze sys interaction due to insufficient info for unresolved Safety lssus A-17 MINDR, C.C. Shoreham Opponents Coelition 80/07/11 9pp
- 8007300005 Requests review of entl safety guide re maint of nuclear power plants by 800811 MDRRISDN.W H Assistant Director for General Engineering Standards 80/07/10 2pp
- --R007300007 SG-07 "Maint of Nuclear Power Plants." Revision 7

 International Atomic Energy Agency (Austria) 50-50-07 79/12/11 52pp

PROPOSED RULE

- 8004110923 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60, & 70 rules are inadequate repaiticipation of Indian Tribal goves Failure to involve tribes in initial process will result in later practical & political difficulties STONE.R J Energy,Dept of 80/03/24 2pp
- B0042B021B Preliminary statement in response to Chairman Ahearne B00312 itr re proposed rulemaking on radwaste storage & disposal Solid radwaste may be disposed of w/o risk based on fundamental earth science processes # Interior.Dept of. Geological Survey B0/04/15 14pp
- BOOSGODERS Comments on proposed rules 100FR20 & 50 100FR50 72(a b) should be clarified to permit plant operation pursuant to Tech Specs w/o requiring that repts be sent to NRC COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/05/02 2pp
- BOO6110406 Hemarandum in support of State of MN motion for 60-day extension of schedule dates be proposed rulemaking on radwaste storage % disposal NRC dalay of core bibliography filing was not anticipated W/Certificate of Svc MUCHNICKI.E D Dhio. State of 800/05/i4 10pp
- 8006270352 Requests ACRS comments on SECY-80-088 re proposed fire protection rule for nuclear power facilities operating prior to 790301 ARLOTTO G A Division of Engineering Standards 80/05/16 lp
- B007010005 Comments on proposed rule ICCFR51 agrees w/AIF position that inclusion of safety matters in comparision & ranking of alternate sites in NEPA review process is not appropriate
 ANDERSON.T M Westinghouse Electric Corp NS-TMA-2256 B0/06/09
- B007010403 Comments on proposed rule 10CFR51 utils should be allowed to include existing sites on slates of candidate sites. Application of proposed changes to existing inventoried or banked sites is unclear VANDENBURGH, D Yankee Atomic Electric Co WYC 80-17 80/06/10
- 8007020030 Notice to recipients of PR-20 advises that Comment δ was miscoded δ will not be used again Correction notice replaces comment
- Docketing & Services Branch 80/03/20
- B00702004A Notice to recipients of PR-20 45FR18023 advises that Comment 4 was miscoded & will not be used again Correction should replace comment

 Be Docketing & Services Branch 80/05/30 19
- B007020100 Memo to recipients of comments re proposed rules 10CFR30, 44FR75167 & 45FR3913 Lists comments previously filed in 10CFR30, 44FR75167, now cross-filed w/10CFR50, 45FR3913, * Docketing & Services Branch B0/06/05 1p

- 8007020203 Comments on proposed rule 10CFR51 should be amended to state reactor type & thermal power capacity to which regulation applies & specifically exclude others
 FISHERIC R General Atomic Co (subs of Gulf Dil Co) 80/06/05
- BOO7020212 Comments on proposed rule 10CFR51 definition of term "Physiographic Unit" should be included Penalty for failure to provide notice of intent 3 months in advance should only be 3-month delay in commencement of review + LeBoeuf, Lamb, Leiby & MacRae 80/06/09 4pp
- 8007020224 Comments on proposed rule 10CFR31 proposed penalties for failure to provide notice of intent within time specified are inappropriate Penalties are irrelevant to objectives stated in introduction & scope COGK.J W Consumers Power Co 80/06/09 App
- 8007020296 Forwards comments on proposed rule 10CFR51 environ density should be explicitly defined & included in Section 2 NRC has no logal requirement to expand alternate sites review to include safety as NCPA issue

 UHRIQ.R E Florida Power & Light Co L-80-185 80/06/13 13pp
- B007020300 Comments on proposed rule 10CFR20 certification of personnel dostmetry processors is major step forward in radiation protection programs Commends NRC actions STOCKS-H B Indiana, State of B0/06/03 ip
- B007020307 Forwards comments on proposed rule 10CFR20 Choice of measurement quantities must be made by considering practical limitations & biological parameters Processor should be required to test only for type of radiation produced DARIOS.E L. Yankee Atomic Electric Co. 80/04/22 3pp
- 800702030B Correction notice for recipients of proposed rule 10CFR20 re performance testing for personnel dosimetry Comment 4 miscoded & will not be used again Correction notice should replace Comment 4 # Docketing & Services Branch 80/05/30 lp
- 8007020312 Comments on proposed rule 100FR20 processor must be given ample time & trial desimeter exposures to permit calibr of processing equipment Expressos gratitude for apportunity to discuss proposed std w/ather in-house desimetry processors JAHORSKI.R L Omaha Fublic Power District BO/04/30 2pp
- 8007020315 Forwards comments on proposed rule iOCFR20 Item 8 re eye protection makes compliance difficult & should be deleted Neutron source should be standardized Photon component should be well defined CAULDHELL.F S Yankse Atomic Electric CD RDS 34/80 80/04/18
- 8007020327 Comments on proposed rule 10CFR20 rule must apply to all thermoluminescent dosimetry if user is to be effective Certification should be matched to monitoring purpose QIBSONJ D Stone & Webster Engineering Corp 80/05/27 2pp
- B007020329 Comments on proposed rules IOCFR20 discrepancy stemming from tissue depth at which dosos are recommended to be measured prohibit fair & meaningful dusimetry std Advises of plans to attend 800423 meeting DARDIS
- 8007020332 Comments on proposed rule 10CFR20 voluntary program not effective Dept of Health & Environ Science supports mandatory testing & certification program Health economic & legal considerations demand dose assessments be accurate LLDYD.L L Montana. State of 80/06/02 2pp
- 8007020340 Comments on proposed rule 10CFR20 certification of processors is not appropriate way of improving quality of personnel dosimotry Arguments suggest need for more uniform application of std methodology FAY.C W Wisconsin Electric Power Co 80/06/03 2pp
- 8007020342 Comments on proposed rule 10CFR51 NRC should carefully consider AIF commonts, representing consensus among utils & BYERLEY, T.E. Georgia Power Co. 80/06/06 ip
- BOO7020345 Comments on proposed rule 10CFR20 unjustifiable expense to regulate radiation exposures when 95% are below 1 25 rem/yr Voluntary commitments working GERBI.B J. Affiliation Unknown 80/06/16 2pp

!

- BOO7020352 Comments on proposed rule 10CFR50, submitted by Logistics Enterprises Corp NPRDS does not have substantial incentives for useful involvement by utils Sys should be streamlined & LERs & NPRD-46 combined & Affiliation Unknown P-0152 B0/06/05 13pp
- 8007020368 Comments on proposed rule 10CFR51 Requests 30~day extension of comment period Extension would not significantly impact implementation of regulation since new applications for early review are not likely to be filed GRAY, FS Lowenstein, Newman, Reis, Axelrad & Toll 80/06/03 1p
- B00702038B Comments on proposed rule 10CFR51 safety & emergency planning should not be admitted as issues in NEPA alternative site review Recommends continued use of Reg Quide 4 7 PEOPLES,D L. Commonwealth Edison Co. B0/06/09 4pp
- BOD7020400 Comments on proposed rule 10CFR5i explicit statements about critical nature of reactor siting to public safety & pravision for acoping should be included HEDEMAN.W N Environmental Protection Agency BO/06/09 2pp
- 8007020406 Forwards corrected 800606 ltr commenting on proposed rule 10CFR51 Original was mailed w/important sentence inadvertently deleted PATTERBON.J D Middle South Services, Inc 80/06/10 lp
- --8007020413 Corrects 800606 comments on proposed rule 10CFR51 application to existing inventoried or banked sites is not clear Status of sites which are part of ongoing review are not reviewed Endorses AIF comments
 PATTERSON.J D Middle South Bervices, Inc. 80/06/10 3co

ì

- 8007020407 Comments on proposed rule iOCFR51 proposed rule should be clarified re procedures & substantive requirements for alternative site decisions in pending cases
 METTERHANN, M J Conner, Moore & Corber 80/06/05 2pp
- 8007020412 Comments on proposed rule 10CFR51 min requirements for alternative site analysis on proposed rule will greatly assist applicants in siting nuclear facilities Variety of methodologies should be taken into account REEVES,R W American Electric Power Co , Inc 80/06/06 Spp
- 8007020416 Forwards comments on proposed rule 10CFR51 regulations concerning alternative site review should be coordinated w/ 800303 proposed regulations concerning EIS LODNIB.J B Sargent & Lundy, Inc. 80706703 2pp
- BOO7020421 Comments on proposed rules 10CFR2 & 50 regulations in Part 2 should be revised to incorporate proposed requirement Option B w/mods Part 50 10 should be replaced w/encl proposed regulation
 WILSON.J N Licensing Branch 1 80/06/12 4pp
- 8007020424 Comments on petition for rulemaking 2-10 proposed rule could require Commission to hold unnecessary hearings & cause delays in approval of proposed licensing action which does not present significant hazands

 ORAY,F S Lowenstein, Newman, Reis, Axelrad & Toll 80/06/16 3pp
- 800702043B Comments on proposed rule 10CFR20 on behalf of Zimmer Area Citizens any meti which exceeds level of radiation found normally in that meti in netural environ should be considered as radwaste & disposed of accordingly FIBSE, R Affiliation Unknown 80/06/13 lipp
- BD07Q20439 Comments on proposed rule 10CFR20 NRC whould sponsor mandatory dosimetry test program for all civilian personnel dosimetry processors Advises of inability to attend 800423 meeting of in-house dosimetry processors KLOTZ.A 8 Northeast Utilities NEE-80-RA-236 80/04/16 3pp
- BOO7020441 Comments on proposed rule IOCFR20 NRC should set performance std such that any processor not meeting std is prohibited from performing personnel dosimetry
 KLOTZ,A S Northeast Utilities NEE-80-RA-296 80/04/16 2pp
- 8007020444 Forwards comments on proposed rule 10CFR20 should include explanation why linear no-threshold assumption of effects selected Consideration should be given to retaining current limits for concentrations in air & water CULVER.J P Air Force, Dept of 80/06/10 App
- 8007020447 Comments on proposed rules 10CFR50 & 51 issues in NRC 800312 request for comments are outside DOT field of expertise Bupports President Center 800212 program on raduaste mpt Hhite House press release & raduaste mpt program encl GOLDSCHMIDT, N Transportation, Dapt of 80/04/07 29pp

- B007020449 Comments on proposed rule 10CFR20 guidelines should be included to be used in training sessions for radiation workers, informing of clinical 'cytological indicators of higher than normal risk of serious health damage BERTELL, R Ministry of Concern for Public Health 80/05/21 3pp
- 8007020452 Comments on proposed rule 10CFR20 use of robots to carry out routine work at nuclear power plant would free human employees to concentrate attention on tasks that can not be carried out by machine ABLER, W.L. Affiliation Unknown 80/06/08 2pp
- 8007020457 Comments on proposed rule 10CFR20 exposure stds should be made as low as possible PECK.H Affiliation Unknown 80/06/09 lp
- 8007020461 Comments on proposed rule 10CFR20 special consideration should be given to exposure of embigo. Fetus & minors Implementation should be sufficiently flexible to allow radiation protection programs to be adapted to situations STEBBING.0 E Army.Dept of Diffice of Surgeon General DASO-PSP-E 80706/09 2pp
- B007020464 Comments on proposed rule iOCFR20 emphasis should be put on mgt commitment to radiation safety program & expert qualifications of radiation safety mgt & personnel HALEMAN.G R Yale Univ 80/06/11 2pp
- B007020465 Comments on proposed rule (OCFRS) approves of advertising in local newspapers, if all local newspapers are included Emergency planning in early site review should include planning for future appulation LEWIS,M I Affiliation Unknown 80/06/09 2pp
- B007020472 Comments on proposed rule 10CFR91 practical implementation appears to fall short of stated objectives Lycensee believes implementation will impact adversely on siting process CDUNBIL.W 9 Connecticut Yankee Atomic Power Co CCUNBIL.W 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/09 3pp
- BOO7020556 Comments on proposed rule 10CFR51 second alternative of exclusionary safety stds.w/.nclusion of safety issues in alternative site ronsideration.is preferable 5tds will permit flexibility in candidate site proposal POND, G D Connecticut, State of BO/O6/11 2pp
- 8007020585 Comments on proposed rule 10CFR90 & provides status of fire protection mode Requests reconfirmation of commitment datas outlined in safety evaluation:
 BYLVIA.B R Virginia Electric & Power Co 3541/061478 80/06/30 Bpp
- 8007020635 Notifies of issuance of FE5 re proposed rulemaking on storage & disposal of nuclear waste FES transmitted to persons on encl svc list

 BROWN 0 F Energy Dept of 80/06/10 /pp
- 8007020659 Submits Progress Rept 29 for Mag 1980 re performance testing for personnel dosimetry "PLATO.P Michigan, Univ of NRC-01-77-180 NRC-01-77-180 80/06/02 6pp
- 8007020661 Responds to 800418 ltr requesting apportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future w/state officials & public CHILK.B J Office of the Secretary of the Commission 80/06/11
- B007020663 Responds to 800403 ltr requesting apportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future w/state officials & public CHILK.8 J Office of the Secretary of the Commission B0/06/11
- 8007020664 Responds to 800409 lts requesting opportunity to assemble group from sucless industry or utils to brief Commission on proposed emergency planning seguiations Meeting will be scheduled in near future wishate officials & public CHILK, S. J. Office of the Secretary of the Commission BO/O6/ii in
- 8007020665 Responds to 800424 ltm requesting opposituality to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations fleeting will be scheduled in near future wistate officials & public CHILK.S J Office of the Secretary of the Commission 80/06/11 in

- BO07020667 Requests opportunity to assemble group from nuclear industry or utils to bruse Commission on proposed emergency planning regulations
 KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp.)
 80/04/24 ip
- 800702066B Requests apportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations
 OMEN.19 H Dute Power Cn 80/04/09 2pp
- BOO702067! Requests opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations
 KEARNEY, J J Edison Electric Institute BO/04/18 lp
- 8007020682 Comments on proposed rule (OCFR20 neutron testing w/Puberyllium source should be reinstated for use w/Cf-252 source distinctly test Unable to attend Apr meeting of commencial processors
 HOLDEN.R H Radiation Detection Co 80/04/25 App
- 8007020689 Comments on proposed rules IOCFR2,19,20,21,30,40,51,40 & 70 on behalf of Radwaste Mgt Group.consisting of listed utils NRC underestimates cost of site characterization Perfection being established as std for siting decisions SILBERG, F E Shaw, Pittman, Potts & Trowbridge 80/03/04 Bpp
- 8007020695 Forwards comments on proposed rule 10CFR20 neutron source should be standardized at facility to eliminate problems w/ dose determination Advises of plans to attend 800423 meeting CAULDHELL, F S Yankee Atomic Electric Co RDS-34/80 80/04/18
- 8007020701 Comments on proposed rules iOCFR2, 19, 20, 21, 30, 40, 51, 60 & 70 unnacessary to address policy-related issue as to number of fully characterized high level redwaste sites Addl comments encl ROBINSON, R X Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/02/29 3pp
- 8007020728 Forwards comments on proposed rule 10CFR51 single delay period of 3 months should be applied, regardless of whether detailed studies have been performed Section 8 2 should be deleted VAN ERUNT, E.E. Arizona Public Service Co. ANPP-15636 80/06/12 Ann
- 8007020742 Comments on proposed rule IOCFR20 sys failing to provide satisfactory measurement could still provide satisfactory control Timelinoss vital to support requirements of control 5td does not give due credit to personnel dosimetry # Tennessee Valley Authority 80/04/23 4pp
- 8007020746 Comments on proposed rule 10CFR20 processor certification is step in right direction & formation of testing & certification lab is needed Processors need access to specialized celibr sources Leb must be highly autonomous DARTLETT, W T Affiliation Unknown 80/06/06 3pp
- GOD7030001 Comments on proposed rule 10CFR20 Univ of HI testing program results demonstrate operational difficulties in passing personnel desimetry performance test Passing of std does not ensure good personnel desimetry

 JONES, W C Omaha Public Power District 60/06/13 2pp
- EQ07030003 Comments on proposed rules iOCFR2, 19, 20, 21, 30, 40, 51, 60 & 70 weaknesses are further testimony to NRC unwillingness to cast aside past prejudices & demonstrate political courage requisits to successful geologic disposal program DIEHL, D S Sierra Club 80/03/03 Sap
- BOO7030012 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 40 & 70 licensing philosophy based on best site, best waste form or best waste package should be avoided Overall sys approach should be adopted instead Detailed comments encl
 JOHNSON, N T Westinghouse Electric Corp 80/02/25 3pp
- G007030024 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70, submitted by AR Archeological Burvey statement re timing of state historic preservation officer review should be made in final procedures for radwaste disposal DAVIB, H A Arkansus, State of 80/02/26 lp
- 8007030045 Requests listing of NM Environ Evaluation Group as interested party to NRC generic waste disposal rulemaking proceeding Requests receipt of past repts & future meeting natices & repts MEILL.R H New Moxico. State of 80/05/13 ip

- --8007030050 Requests placement on svc list for generic proceeding on confidence in storage & disposal of nuclear wastes DAVIS.J P Consolidated Edison Co of New York 80/05/06 ip
- --B007030059 Requests transcript of 800i29 first general meeting of participants in proceeding & that Sensible ME Power co-counsel be placed on distribution list for transcript & all future distributions
 MILLER.D S Miller.D S 80/05/06 ip
- EOO70300B2 Comments on proposed rule 10CFR51 should not apply to CP applications docketed before effective date or to related OL applications Safety issues should not be considered in alternative site analysis GRAY.FS Lowenstein, Newman. Reis. Azelrad & Toli EO/06/19 3pp
- ED070300B4 Comments on proposed rule iOCFR50 NRC should support further testing re use of water extinguishing sys over energized electrical equipment OSA 1979 limited test rept encl HUTTON, J R Energy, Dept of E0/06/ii 19pp
- BOO70300B7 Comments on proposed rule iOCFR20 mandatory program not justified implementation should be delayed until problems are resolved Btd ANSI NI3 is should be used for test LEHIB.L Duke Power CO BO/O6/11 2pp
- 80077030095 Comments on proposed rulos 10CFR50 & 51 applications not yet reviewed by Licensing Board should include Class 9 accidents in EIB JOHNSON, C Texas Public Interest Research Group 80/04/30 3pp
- BOO7030104 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60 & 70 submitted by CA Energy Resources Conservation & Development Commission Proposed procedures are significant improvement over NRC Nov 1978 proposed general statement of policy VARANINI.E E . GREW.P C California. State of 80/03/03 5pp
- BOO7030107 Comments on proposed rules iOCFR2, 19, 20, 21, 30, 40, 51, 60 & 70 rules are deficient in several key aspects & continue to reflect passive approach of Commission in dealing w/DOE program in 1972 general statement of policy
 BERICK, D Environmental Policy Institute BO/03/03 3pp
- 8007030113 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 aubmitted by CT Dept of Environ Protection Provisions should be made for federal funding to support monitoring program administered by state after decommissioning HEUDNER.A T Connecticut, State of 80/02/28 1p
- BOO7D30119 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60 & 70 on behalf of Util Waste Mgt Group & EEI Endorses change in Commission approach which would eliminate formal step of provisional const authorization AXELRAD.M Lowenstein.Newman.Reis.Axelrad & Toll 80/03/03 9pp
- 8007030127 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 major concerns are in areas of site characterisation, consultation & concurrence w/states & public participation Reserves final comments
 HANCOCK,D Southwest Research and Information Center 80/02/28 2pp
- GOOTOGOIDE Forwards comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 Site characterization rept should be made on site by site basis NRC should not be involved in screening of sites for site characterization MCCRAY, J O Arizona, Univ of GO/02/20 2pp
- E007030158 Comments on proposed rules 10CFR2,19,20,21,30,40,51,40 & 70 Indian trabal govts should be provided adequate opportunity to participate in licensing process GABRIEL, E Council of Energy Resource Tribes B0/03/03 App
- BOO703017i Forwards comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70. submitted by League of Women Voters of US Mandatory hearings should be required before repository is authorized for const POWERS, D Affiliation Unknown BO/02/28 2pp
- BOO7030179 Comments on proposed rule IOCFR20 derived limits for concentration in air & water should be retained & updated to reflect most current technical data Use of limits for intakes would provide addl problem solving flexibility COPELAND.R L Energy, Dept of Clinch River Breeder Reactor Plant BO/06/17 Spp

- 8007030190 Comments on proposed rule iOCFR20 care should be exercised in adopting statements of scientific advisory bodies directly into regulatory framework Adoption of Sys Intiunits will not make contribution to laymen understanding RDGERS.W L. Gulf Oil Corp., Gulf Mineral Resources Co. 80/06/10 550
- B007030193 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 supports requirements re characterizing number of sites in appropriate media by in situ tests at depth before selection of repository site & issuance of license to construct MENARD. H W Interior, Dept of, Geological Burvey 80/02/29 2pp
- B007030200 Comments on proposed rules iOCFR2.19.20.21.30.40.51.60 & 70 unclear whether two or more repository sites must be rejected for each site accepted All US waste generated to gr 2000 could be accomposed in two nat
- BOO7030204 Comments on proposed rule locared natural radiation is only one component of environ radiation that also includes manenhanced & manemade radiation Only measurement of particular area must be done in field w/addl doses based on findings HASBERBACH.A E New York Federation for Safe Energy BO-57 BO/06/17. 10pp
- --E007030209 Comments on EPA DRP-S1D 72-1. "Natural Radiation Exposure in UB," by DT Oakley no such thing as true measurement of background radiation, average permissible dose or population dose Requests that NRC review rept HABBERBACH.A E New York Federation for Safe Energy EPA DRP-BID-72 80/04/25 App
- 8007030341 Comments on proposed rule 10CFR73; reiterates 790817 request that spent fuel or irradiated reactor fuel be carried on special trains NRC & DOT opinions influenced ICC denial of restrictions on transport of raduaste BMITH:R L Consolidated Rail Corp 80/04/14 3pp
- 8007030343 Comments on proposed rule iOCFR20 assumptions should be clearly identified & be accompanied, where appropriate, by full explanation of attendant applications. Full definition of ALARA should be retained in any revision SCHERER, A E C-E Power Bystems LD-80-033 80/06/18 5pp
- 8007030348 Comments on proposed rule 10CFR20 Sys Intl units should not be used in regulatory program unless used as secondary units & appear in parentheses NRC should provide detailed procedures for dose determination when required LARSON.H J Atomic Industrial Forum 80/06/18 10pp
- 8007030349 Comments on proposed rule 10CFRBO experience at fire five yrs ago demonstrates that R-h supply of water is inadequate Special protective features should include properly designed & separated trays w/cabling suspended above floor at tray LEWIS.M I Affiliation Unknown 80/05/31 2pp
- B007030351 Forwards comments on proposed rule 10CFR20 atds should be consistent w/applicable federal protection guidance & should include consideration of work of recugnized nati & inti advisory organizations.

 EATES.A Affiliation Unknown B0/06/16 24pp
- BOD7030394 Comments on proposed rule 10CFR20 social & economic factors must be considered Balance must be maintained between social benefits & associated risks Recommends that ALARA not be used as numerical guides ALLHENDINGER, P. Affiliation Unknown 80/06/18 3pp
- 8007030365 Comments on proposed rules iOCFR50 & 51 Class 9 events should be considered in NEPA reviews for ail reactors SECY-80-131 concluded that NEPA snylron reviews should include analysis of all possible radicipal accidents WRIOHT.F 8 Massachusetts, State of 80/04/22 opp
- B007030366 Comments on proposed rule 10CFR20 recognition of differences in susceptibility to radiation is virtually absent NRC should halt sidvancement of nuclear technology until scientists have better understanding of long-term effects DRAKE, O A Affiliation Unknown B0/06/16 2pp
- 8007070043 Comments on proposed rule 100FR73 2-day notice to delay scheduled shipment is not adequate to allow shipmen to modify plans NRC should notify shipper within 24-h of receiving 7-day notice from shipper MANOUSI,J Transnuclear, Inc. 80/02/28 ip.
- 6007070063 Comments on proposed rule 10CFR20 licensee has no concerns w/required reporting of doses to public from fuel cycle.

 Implementation of discharge limits for Kr-85 k I-129 in 1983 should be clarified LEHIS.L. Duke Power Co 80/06/12 lp.

- B00707006/ Comments on proposed rule [OCFR73 restrictions on shipment of moderate strategic significance SNM will significantly impede commence Factors influencing delay of conflicting shipments should be given FLOWERS, F. D. Goneral Electric Co. FDE. 80-56 80/04/01 2pp
- B007070084 Comments on proposed rvies 1007R2,19,20,21,30,40,51,60 & 70 supports proposed step-by-step process for reviewing DDE development of geologic repositories binal regulations require discussion of presence & potential of resources LASH, T.R., YUAN, G. Natural Resources Defense Council B0/02/29 13pp
- 8007070085 Comments on proposed rules 10CFR30 & 33 suggests rewording to clarify that Mo-99 breakthrough tests would be required only for elutions from Mo '99/Tc-99m generator BRODKS:TR Maryland, State of 79/08/31 1p
- BOD7070092 Comments on proposed rule 10CFR20, on behalf of Comm Ed major changes in sys of radiotion protection stds should only be made if & when warranted by new info from responsible scientific bodies

 BTRELON, R., ELLIOTT, E.D. Levy, Gotman, Coldberg & Kaplan BO/06/18
- B007070112 Comments on proposed rule IOCFR20 assumption of linear dose response near zero effect-zero dose intercept is scientifically unsupportable More practical limitations are ambient radiation & natural incidence of biological effect HODSQN.W L Vet Admin Hopp Northport.NY 80/06/16 2pp
- 8007070i18 Comments on proposed jule 10CFR20 numerical exposure guidelines should be consistent w/ICRP Publication 26, w/ dose guidelines of 5 rem/yr from external & internal sources combined DALE.L F Mississippi Power & Light Co AECM-80/130 80/06/16
- B00707012) Comments on proposed rule 10CFR20 important to emphasize need to make use of newly available capabilities represented by Radiation Policy Council
 NEY. HR National Council on Radiation Protection & Measurements
 B0/06/12 2pp
- B007070174 Comments on proposed rule IOCFR20 technical bases for numerical limits should be readily identifiable & primary consideration in proposed stds Highly controversial results should not be basis for imposing more restrictive limits CADENA, D O Bouthwest Research Institute 80/06/16 3pp
- 8007070178 Comments on proposed rule 10CFR20 Commission should limit responsibility to specific & substantive regulations & refrain from issuing ambiguous & highly interpretative policy statements which may paralyze advancements in field MURPHY,R Medi-Physics, Inc. 80/06/17 3pp
- B007070402 Comments on proposed rule 10CFR20 placing guidance into regulations that should be placed in reg guides to referencing reg guides in regulations can short circuit intended review & approval process
 NILBON.R Exron Nuclear Co. inc. (subs. of Exron Corp.) 80/06/10-200
- B007070406 Comments on proposed rule iOCFR20 recognition should be given to alternative threshold nonlinear effect point of view Assumption of linear dose-effect relationship is not universally accepted, except as conservative upper limit SANDERS, C I Armstrong Cork Co 80/06/16 lp
- 8007070407 Comments on proposed rule 1007820 proposed personnel review of numerical dose limits for internal & external exposures in combination appears to be unnocessary Use of engineering controls has resulted in no significant detectable burdens VANDENBUROH, D.E. Yankee Atomic Electric Co. MYC 80-18 80/06/13 2nd
- 8007080009 Statement of position on proposed rulemaking re storage & disposal of radwaste Urges serious study of nontechnical criteria & requirement that consultation & concurrence procedure be consolidated in 50 states H/Curlificate of Svc ANDALMAN,E Mississippians Against Disposal 80/06/25 6pp
- 8007080249 Forwards Scientists & Engineers for Secure Energy statement of position re storage & disposal of nuclear waste To ensure waste disposal facilities will exist when needed, demonstration projects should be begun immediately RICHARDS. J R Capital Legal Foundation 80/07/01 28pp

- 80070B0347 Comments on proposed rule 10CFR20 on behalf of util Occupational Radiation Stds Group licenser should establish specific procedures to implement emergency occupational exposures w/expusure limited to one time only Repts encl GALLO.J Isham. Lincoln & Beale 80/06/18 13pp
- --BOO70BO353 'Radiation Camer Risks & Linear Hypothesis " Brief author biography encl GGLDMAN, M. California, Univ. of, Davis BO/06/18 17pp
- --B007080357 "Practical Threshold for Radiation " WHIPPLE.G H Michigan. Viniv of 80/06/10 12pp
- --8007080360 Memorandum of discrimination issues raised by special accupational radiation exposure stds for women HOLZWEIG.5 F Isham Lincoln & Beale 80/06/18 19pp
- 800709004B Comments on proposed rule 10CFR20 requests that name be added to mailing list in connection w/rulemaking procedure STENSVANG.J M Vanderbill Univ 80/06/JB 1p
- 8007090098 Forwards 800314 errata to 800415 statement of position re proposed rules 100FR30 & 51 Svc list encl BROWN, O F Energy, Dept of 80/05/19 App
- --8007090103 Errata to 800415 statement of position reproposed rules 1005R30 & 51
 4 Energy, Dept of DDE/NE-0007 80/05/14 App
- 8007090i13 Forwards corrected Pages 3.7 % 10 to 800229 comments on proposed rules 100FR2.19.20.21.30.40.51.60 % 70 JONES, A Natural Resources Defense Council US SD 901-1 80/03/03 4pp
- 8007090145 Comments on proposed rules 10CFR50 & 51 although decision to defer commercial reprocessing in US was based primarily on economic considerations delay was also intended to encourage other countries to consider deferral KEENY. B H Unknown Affiliation 80/04/11 4pp
- --B00709014B Comments on proposed rules 10CFR50 & 51 supports conclusions of Interagency Review Group on Nuclear Waste Mgt in Mar 1979 rept to President
 SPEIM.6 Council on Environmental Quality B0/04/15 5pp
- B007090399 Comments on proposed rule iOCFR20 orges that NRC view low level isotopes used in medicine with context & not delay promutgation of appropriate requirements for disposal until problems of reactor waste disposal can be solved LINTON.O W Affiliation Unknown 80/06/iB 2pp
- B007090402 Comments on proposed rule 10CFR19 success of conferences is largely due to informal nature which allows candid discussion between NRC & licenses mgt Proposed rule is unnecessary & would intrude on mgt responsibility PARKER. W D Duke Power Co 80/06/04 2pp
- 8007100001 Comments on proposed rule 100FR20 changes ought to be made only when overwhelmingly required Major rewrite, as proposed, would be counterproductive to purpose of radiation protection
 BRITIS-JS Health Physics Society 80/06/12 3pp
- 8007100003 Forwards comments on proposed rule 10CFR30 rule is very vagua & does not fully identify specific fire protection as intended implementation deadlines are unrealistic & should be re-evaluated Proposed rule encl
 GIBBS, D C Middle South Services, Inc 80/06/10 13pp
- B007100007 Comments on proposed rule 100FR20 anything beyond performance std based on objectives of acquiring info through measurement would be unduly restrictive Regulations should be written in terms meaningful for implementation ZELAC, R E Temple Univ 60/06/11 2pp
- 8D07100D13 Comments on proposed rules 10CFR2.19,20.21,30.40,51.60 & 70 technical crituria should be established to limit releases to biosphere to less than is now legally acceptable MABON, D.C. Rockwell International Corp., Atomics International Div BOEBQ-1978 60/02/28 3pp
- 8007100017 Comments on proposed rule 10CFR20 any changes from concentrations to annual intake limits must be carefully worsed to ensure age & sex differences are well understood by public Clear anstrument calib: info should be included WINANG.L F Oregon, State of 80/06/10 App

- B007i00024 Camments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 proposed prelicensing process introduces unnecessary & redundant slements into otherwise sound program for geologic investigations & determinations of site suitability MEYERS,8 Energy,Dept of 80/03/03 10pp
- 8007100030 Comments on proposed rule iOCFR20 provision should be made for rational disposal of small activities of radionuclides used in diagnostic nuclear medicine procedures Situation is prosently chaotic EVANS.R D Massachusetts Institute of Technology 80/06/16 App
- 8007100035 Comments on proposed rule 10CFR20 suggests extending 30-day reporting requirements to 60 days following month during which radiation levels or radioactive matt releases were in excess of limits COUNSIL.H G . LEE.H F Connecticut Yankee Atomic Pawer Co COUNSIL.H G . Ortheast Nuclear Energy Co (subs of Northeast Utilities) 810006 80/05/29 3pp
- 8007100046 Comments on proposed rule 10CFR73 regulation should indicate how NRC will obtain relevant info & what factors will influence decision on which shippers & consignees will be delayed HIGAN, J.P. General Atomic Co. (subs. of Gulf Cii Co.) 80/03/04 20p
- 8007100047 Forwards util statement of position re proposed relemaking on storage & disposal of radeaste SANGER.H S Tennescee Valley Authority 80/07/07 1p
- --B007100050 Statement of position re proposed rulemaking on storage & disposal of radwaste Spent fuel may be stored safely onsite & offsite based on available & emerging suitable technology SANCER; H S , BURGER; J F , BUBTION, R R Tennessee Valley Authority 80/07/07 13pp
- --8007100054 "Spent Fuel Mgt Program Study Summary Rept." Sept 1979 Certificate of Svc encl * Tennessee Valley Authority 79/09/30 35pp.
- 8007i00079 Comments on proposed rules 10 CFR 2,30,40,50,51,70 & 110 rules do not indicate procedures for identification, evaluation & protection of historical &/or archaeological properties which may be affected by NRC licensing DINCAUZE,D F Massachusetts, Univ of 80/04/07 ip
- 80071000B3 Comments on proposed rule 10CFR20 terminology used to express amount of radiation & degree of exposure should be uniform & made clear for lay people Specific means for obtaining other exposure info should be provided PRITCHARD. C C Interior. Dept of Bureau of Mines 80/06/13 App
- 8007100086 Comments on proposed rule iOCFR20 San Diggo County concurs w/reporting requirements Reporting process should be linked to local govt which would respond to emergency situation HONDERGER.R F Galifornia, State of 80/06/17 1p
- B007100070 Comments on proposed rule 10CFR140 discusses effects of TMI-2 accident on physical & mental health of family & local citizens Disagrees w/Galtzman statement that determination of damages would be difficult under present regulations MOSES.V R Affiliation Unknown 80/01/18 5pp
- 8007100092 Comments on proposed rule 10CFR20 requests combination of code requirements for dose & radioactive release to eliminate duplicate regulations & redundant reporting Literal enforcement of code would be costly & redundant HOFFMAN, D.P. Consumers Power Co. 80/06/12 2pp
- 8007100094 Comments on proposed rule 100FR73 clarifies 800212 ltr re DOE license-exempt shipments for matl of low strategic significance Rewording was not intended to suggest NRC has authority to order DOE shipper actions WEI82.0 Energy, Dept of 80/03/05 2pp
- B007100104 Comments on proposed rule iOCFR70 clarification of intentions re (a)(1) is essential w/respect to carrier obligations & growing number of states speking to regulate transportation of radioactive matls
 JORDANIA 6 Affiliation Unknown 5048611 80/06/12 3pp
- 8007100160 Forwards summary statement of position of Util Nuclear Waste Mgt Oroup & EEI. "Capability for Disposing of High-Level Wastes Safely." "Long-Term Safety of Nuclear Waste Disposal" & "Capability for Bafe Interim Storage of Fuel" AXELROD.M Lowenstein, Newman, Reis, Azelrad & Toll 60/07/07 7pp

-

- --8007100180 Summary statement of position of Util Nuclear Waste Mgt Group & EEI Spent nuclear fuel from licensed facilities can be disposed of in safe & environmentally acceptable manner a Edison Electric Institute * Lowenstein Newman, Reis, Azelrad & Toll 80/07/07 32pp
- --B007100184 "Capability for Disposing of High Level Wastes Safely "
 # Nuclear Safety Associates 80/07/07 140pp
- --6007100188 TR-3195-1 "Long Term Bafety of Nuclear Waste Disposal Basls for Confidence"
 BARTLETT. J W. OBTON, S G , GIUFFRE, M S Affiliation Unknown BO/07/07 100pp
- --B007100191 "Capability for Bafe Interim Storage of Spent Fuel "
 LAMBERT, R General Electric Co HALEY, J Westinghouse Electric
 Carp SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/07/07
- 8007100246 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges that reliable date be set by which repository sys will be in operation Adequate storage guarantee must be commensurate willfe of plant BROWN, W J , MUCHNICKI, E D Dhio, State of BO/07/07 26pp
- 8007100248 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges exclusion of consideration of offsite disposal & extended onsite storage from individual licensing proceedings
 * Atomic Industrial Forum 80/07/07 59pp
- BOO7100254 Forwards ANS statement of position re proposed rulemaking on nuclear waste storage & disposal MONBDISSE,R M American Nuclear Society MONBOISSE,R M Pacific Legal Foundation BO/07/03 ip
- ~~8007100257 Statement of position of ANS proposing that NRC reach finding of confidence re safe nuclear waste storage & disposal w/o danger to man or environ HONBOISSE.R M ZUMPRUN.R A American Nuclear Society MONBOISSE.R M Pacific Legal Foundation 80/07/03 38pp
- 8007100327 Notifies that JF Ahearne concurs in wording of fire protection rule. SECY-80-088. as revised by J Parry 800317 memo subj to listed changes SAVIER. O Commission 80/04/16 lp
- --8007100334 Forwards draft memo summarizing individual Commissioner comments on SECY-80-088 fire protection actions Requests comments or concurrence in time to affirm paper on 800319 Draft memo, modified pages & draft FR notice encl PARRY. 8 J S Office of the Secretary of the Commission 60/03/17
- 8007100328 "Spent Fuel Mgt Program Study Summary Rept " DAVIDSDN,R H , MOEGLING, J B Tennessee Valley Authority 79/09/30
- 8007100348 Comments on proposed rule 10CFR20 items should be added to provide for involvement of workers & representatives in auditing & controlling exposures & to provide for worker access to medical & exposure records

 HICKS:M M Utility Workers Union of America 80/06/16 4pp
- 8007100352 Comments on proposed rule 10CFRAO comparative evaluations of alternate waste forms for every repository are not justified DOE should specify allowable waste forms or set MCELMURRY, B R Affiliation Unknown BO/06/13 2pp
- B007i10005 Forwards RR Lund 800024 ltr re Commission proposed rule on emergency planning Requests comments on concerns that rule is overbroad for medical licensees
 BIMPBON, A K Senate, Judiciary Committee 80/05/08 5pp
- 8007110019 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 40 & 70 site characterization rept should include discussion of mineral resource confilicts, geologic conditions below repository level & regional geologic conditions HANCOCK, D , MECTOR, A 0 Goothwest Research and Information Center 80/03/03 '4pp
- 8007110026 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 site acceptability criteria should be defined to avoid ambiguity & to assure proper attention & informed decisions at each critical step of investigation HEDEMAN, W N Environmental Protection Agency, 80/03/07 2pp

- 8007110031 forwards comments on proposed rules 10(FR2, 19.20, 21, 30, 40, 51, 60 % 70 NRC responsibility in determining licensembility should be based solely on whether particular site meets certain predetermined criteria W100IN.E A Atomic Industrial Forum 80/03/06 4pp
- 8007110048 Statement of position re proposed rulemaking on storage &
- B007i10096 Comments on proposed rule 10CFR50 requests that ltr & attachments be read into record as testimony when Commission considers proposed rule on emergency planning Regulations for planning should only address needed capabilities COX.F T Texas. State of B0/04/28 7pp
- B007110067 Statement of position re proposed rulemaking on storage & disposal of radwasts Any alternative for radwasts disposal in geologic disposal site will be unacceptable due to unpredictable consequences Certificate of Svc encl LOCHSTET, W A Affiliation Unknown 80/07/03 App
- 8007110087 Statement of position re proposed rulemaking on storage & disposal of radwaste Doclines to state present comments but reserves right to offer cross-statements when appropriate HILSDN.R P South Carolina. State of 80/07/03 ip
- BOO7110101 Statement of position re proposed rulemaking on storage & disposal of radwaste Deep goologic disposal uncertaintles require forther evaluation Disagreements between levels of govt must be solved DOE must provide assurance re schedule GRIFFIN.W., DIAMOND, M.J. Vermant, State of BO/07/O1 3pp
- B007i10121 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges imposition of moratorium on new nuclear plants until technical & institutional problems are resolved factual gaps & known problems still present ABRAMS,R., CORMIN.J.W., BIALIK,E 1 New York, State of 80/07/07
- 8007110225 Comments on proposed rules 10CFR70 & 73 application of rule to nonpower reactors will have devastating effect on research reactors & associated education & research activities carried on at univ research reactors WILSON.W E Washington State Univ 79/10/08 13pp
- --8007110231 Forwards comments on proposed rules 10CFR70 & 73 facility
 will be shut down rather than incur costs for upgrade
 Faculty/staff positions will be eliminated
 MILSON.W E Washington State Univ 79/08/20 3pp
- --B007i10239 Forwards comments on proposed rules 100FR70 & 73 no detailed impact statement or cost-benefit analysis is available to predict effects of proposed rulemaking on US educational sys WILSON,WE Washington State Univ 79/08/30 3pp
- B007110242 Advises that RT Kennedy concurs in changes to BECY-B0-08B, fire protection rule, proposed in 0 Bouter 800416 memo. subj to attached revisions

 GUILBERT: J Commission 80/04/17 4pp
- --BOO7:10246 Notifies that JM Hondrie concurs w/BO0416 version of fire protection rule circulated by G Sauter as modified by RT Kennedy FONTECILLA.H Commission 80/04/1B 1p
- 8007110257 Forwards Wi Ad Hor Radioactive Waste Disposal Committee comments on proposed rules 10(FR2.19.20.21.30.40.51.60 & 70 application.environ rept & amonds shall be filed w/ufficials designated by governor State of HI 790727 ltr to DOE encl HALSTEAD.R J Wisconsin. Statu of 80/06/04 19pp
- 8007110345 Statement of position re proposed relemaking on storage & disposal of radwaste Joins in New England Coalition on Nuclear Pollution to NBDC statements of position H/certification of svc MILLER.D S Sensible Maine Power MILLER.D S Hiller.D S 80/07/07 lp
- 8007110492 Comments on proposed rule 10CFR20 NRC should draft NUREG rept to accompany regulation which details technical basis for numerical limits & quantitative requirements in revised rule
 TAYLOR.J J Westinghouse Electric Corp WRD-1097 BO/06/18 22pp

- BOO7110496 Requests Commission approval to publish for comment amend to 10CFR50 in form of App R.w/fire protection requirements for plants in operation prior to 790101 Amend would facilitate implementing BF 9 5-1
 FONTECILLAR M Commission 80/03/14 2pp
- BOO7110497 Comments On proposed rule IOCFR2O party other than operating util should be responsible for monitoring all radioactive releases from nuclear plants
 STAMIRIGOU Affiliation Unknown BO/06/17 Ip
- 80071i0504 Discusses status of App R to iOCFR50 re impact of requiring all fire protection features installed by 80i101 Eleven plants will not complete Section 3 1 mods & Section 3 2 open items by 80i101

 LAINAS.0 Plant Systems Branch 80/04/1i 3pp
- B007110507 Forwards comments on proposed rule 10CFR51 from RC Peydar of MH State Legislature DURKIN, J A Senate 80/06/19 ip
- 8007110534 Comments on proposed rule IOCFR20 addi reporting requirements should be initiated only if well defined benefit is to be derived GERTH, 0 E Mallinckrodt, Inc. 80/06/18 Jpp
- 8007110547 Describes status of alternate/dedicated shutdown sys as of 800328 CABE, E Office of Nuclear Reactor Regulation. Director 80/07/10
- GOO7110553 Hotion to produce documents forthwith & extend date for submitting comments on proposed rule 10CFR50 until at least 30 days following date info requested in KHC Inc 1980 FOIA request is made available CONNER.T B KHC. Inc 80/06/24 9pp
- 80071i0386 Forwards info requested by JF Ahearns re status of fire protection review program alternate/dedicated shutdown systatus as of 8003fi & other outstanding issues
 LAINAS.6 Assistant Director for Safety Assessment 80/04/02 7pp
- B007140002 Statement of position re proposed rulemaking on storage & disposal of radwaste Complete set of acceptablifty criteria may not be possible due to lack of successful site studies Detailed tests needed for actual site risk assessment Interior,Dept of: Geological Survey 80/07/07 38pp
- BOO71400ii Statement of position re proposed rulemaking on storage & disposal of radwaste NRC should find that no contiusions can be drawn as to whether or not spent fuel can be safely stored until permanent disposal sites are available SENCEHAL.M E . OLSON.J F , SPANNAUS, W Minnesota, State of 80/07/03 9pp
- --BOO7i400i4 Comments re proposed ruiemaking on storage & disposal of radwaste No scientific basis may be advanced for safe 40-yr spent fuel storage ADRAHAMSON.D Hinnesuta, Univ of, Hinneapolis 80/07/02 40pp
- 8007140036 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges establishment of positive finding of confidence Notes evidence of demonstrated waste agt technology re potential toxicity & full-core discharge GRAMER, EN Neighbors for the Environment 80/07/04 3pp
- --B007140040 "Demonstrated Technology Three Examples From History & Analysis of Nuciear Waste Mgt," by JD Rae, of Maryey Mudd College of Engineering & Technology in Ciaremont, CA RAE, J B Affiliation Unknown 77/07/08 23pp
- ---B007i40046 ISBN 0-89448-i06-1
 Evaluating Hazards of Disposing of Wastes from Energy
 Production," Bureau of Radiation Protection, Harrisburg, PA
 Presented as part of ANS B00227-29 topical meeting re
 technical assessment of nuclear power & alternative
 DDRNSIFE, W P
 P#NNsylvania. State of 80/02/29 19pp
- --800714005i I D 77-11-07
 "Relative Spent Fuel Storage Hazard," prepared for ANS
 winter meeting in 9an Francisco.CA
 STRANL.J F NUS Corp EROSNAN.D F Los Angeles. CA CRAMER.E N
 Southern California Edison Co 77/11/30 28pp
- BOO7140043 Statement of position re proposed rulemaking on storage & dispusal of radwaste Urges determination re recycling technique & location interim away-from-reactor sites should be avoided Geological survey list of publications enci MACARIOR, J D Delaware, State of 80/07/03 20pp

- 8007140045 Forwards statement of position re proposed rulemaking on storage & disposal of radwaste O'DONNELL,A J Bechtel Corp 80/07/03 1p
- --B007140049 Statement of position re proposed rulemaking on storage & disposal of radwaste Radioactive waste can be safely disposed of in mined geologic repository, in basalt & granite chambers & in different host media & Bechtel Corp 80/07/03 6pp
- B007i40096 Comments on proposed rule tOCTR20 single agency should have responsibility for radiation related matters Recordseoping requirements should be streamlined COLLIER,R E Affiliation Unknown B0/06/18 2pp
- 8007140277 Responds to FOIA request for all info which directed or discussed any changes of proposed fire protection rule in SECY-BO-OBB App documents have been forwarded J Outhert BOO311 meno withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records BO/O6/26 2pp
- --B007140291 Staff requirement memo re 800423 ppon Affirmation Session 80-18 in Mashington,DC Includes overall records of Commission votes re SECY 80-166,SECY 80-177 & BECY-80-088 CHILK,9 J Office of the Socretary of the Commission 80/05/01 130s
- --8007140297 Discusses fire protoction rule proposed in SECY-80-08Q Lists
 JF Aboarne recommendations re provisions which should be
 incorporated in rule includes info re public comment
 period templemontation of nonshutdown sys mods
 SAUTER.G Commission 80/04/10 ip
- --B007i40302 Discusses fire protection rule proposed in BECY-80-088 Commission affirmed, w/commonts, proposed fire protection rule delineating certain min fire protection requirements at B00423 Affirmation Session B0-18 Lists recommended changes &OTLEY, D P Engineering Metholology Standards Branch B0/06/03, 200
- 8007140286 FOIA request for all info which directed or discussed any changes to proposed fire protection rule in SECY-80-088 & record of Commission's vote re changes KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/05/30 ip
- 8007:40387 Statement of position on proposed radwaste storage & disposal rulemaking No aspect of DDE program provides reasonable assurance reliable offsite waste disposal sysuill be avaitable before current nuclear licenses expire SHELDON, K.P. Natural Resources Defense Council SHELDON, K.P. Sheldon, Harmon & Weiss 80/07/07 95pp
- 8007140402 Comments on DOE position re proposed radwaste disposel & storago rulemaking Technicai facts inadequately addressed or improperty interpreted DOE defense in depth approach not as strong as position paper purpon
- --B007i40408 Comments on DDE B004i5 statement of position re proposed radwaste disposal & storage rulemaking Transportation impacts through reliance on reliroads could significantly add to consumer cost
 LEVERANCE.J Wisconsin. State of B0/07/07 3pp
- --8007140417 Testimony re DDE statement of position re proposed radwaste storage & disposal rulemaking DDE position does not deal adequately w/social.political & institutional aspects of radwaste mpt ML Symon 800805 ltr to RW Riley encl KELLY, J E Wisconsin, State of 80/07/io 3ipp
- B007140432 Forwards statement of position re proposed rulemaking on storage & disposal of radwaste Requests addition of MJ Murray & removal of D Hansell & S Bekuler from svc list MURRAY.M J Illinois, State of 80/07/07 ip
- --8007140439 Statement of position re proposed rulemaking on storage & disposal of radwaste DOE conclusions that waste packaging methods will be developed when need arises are meaningless due to insufficient data & technical uncertainties HURRAY, M J , SCOTT, W J . VRANKEN, J V Illinois, State of 80/07/07 Spp
- --8007140449 Affidavit stating that DDE position re waste packaging matls is masleading DDE statements re interim spent fuel storage inadequate W/bibliography & proof of svc. RDV.R Illinois, State of RDY.R Pennsylvania State Univ 80/07/03 8pp

- BO07140454 Comments on proposed rules 10CFR2 & 50 prefers current regulations rather than proposed options A-D which would prolong licensing schedule w/o assuring timely decisions ROBINSON.H J Black & Veatch 80/06/16 2pp
- 8007i4046B Forwards comments on proposed rule 10CFR50 rule is vague & unenforceable Updating existing reg guides rather than implementation of App B would better serve safety, fire protection & financial interest of consumer DUNGAN, K W Affiliation Unknown 80/06/i9 App
- 8007140538 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 State of WI Ad Hoc Radioactive Waste Disposal Committee agrees w/rulemaking rationals Supports decision to withdraw proposed Nov 1978 general statement of policy HALSTAD, R J Wisconsin, State of 80/05/27 2pp
- 8007140343 Comments on proposed rules 10CFR20 & 50 disagrees w/immediate effectiveness requirement for significant & nonsignificant events
 HDFFMAN.D P Consumers Power Co 80/05/29 5pp
- 8007i40849 Comments on proposed rule 10CFR19 10CFR19 14(h), as proposed, not necessary & language used does not explicitly define public access or individuals w/legitimate interests Informal conferences w/licensee mgt would be beneficial RAGDEN, O Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/04/28 2pp
- B007140357 Comments on proposed rules 10CFR20 & 50 consolidated reporting requirement list should be developed & obsolete & repetitious requirements should be cancelled Addl burden could distract plant operators
 FAY.C W Wisconsin Electric Power Co 80/06/04 3pp
- 8007140564 Comments on proposed rule 10CFR20 commends NRC action to have NRC certified lab w/continual monitoring by NBS BTEIN,E L Delaware, State of 80/05/29 ip
- BOO7140575 Comments on proposed rules 10CFR2 & 50 favors proposed rule change to 10CFR2 105,10CFR50 5B & 10CFR50 91 NRC capable of determining significant hazard considerations & 30-day wait before amend issuance unnecessary DALE, t. F. Mississippi Power & Light Co. BO/05/28 1p
- BO07140382 Comments on proposed rule 10CFR20 proposes that manufacturer be tested & certified before TLD clips are allowed on market.eliminating film processing problems HALEK,F A Gulf Nuclear, Inc. BO/05/29 lp
- BO0714059i Comments on proposed rule lOCFR20 personnel dosimetry problem might be helped by periodic insp of personnel & facilities & personnel monitoring establishments Standardization lab could result in greater errors NURNBERGER, C E Affiliation Unknown BO/05/19 2pp
- BO07140599 Comments on proposed rule iOCFR20 supports NRC position that certification lab be self-supporting or operated under contract to govt agencies
 LANDBUER,R B., WHEELER,R V Affiliation Unknown 80/05/30 ip
- 8007140611 Forwards final rept of technical review of draft 10CFR60, Bubpart E technical criteria DAVI9.5 Arizona, Univ of NRC∽04~80~217 80/02/20 135pp
- B007140640 Comments on proposed rule 10CFR20 NRC efforts to revise rule must proceed in concert w/studies performed by other govt agencies VILLFORTH, J C HEW, Dept of, US Public Health Service 80/06/23
- 8007140691 Comments on proposed rule 10CFR20 NRC radiation protection stds should be consistent w/applicable federal guidance & include consideration of work of recognized natl & intl organizations
 8ATES:A Farm Legal TN 80/06/20 16pp
- 8007140695 Comments on proposed rule 10CFR60 radwaste should be catagorized by thermal characteristic, as well as radioactive characteristic w/distinction of time period during which medda temp increases

 BYER. G H Affiliation Unknown 80/06/26 4pp
- 8007150004 Comments on proposed rule 10CFR20 NRC has not adequately demonstrated need for personnel dosimetry testing & certification program Citing improper use of dosimetry data in apidemiological studies as argument is invalid MOFFITT.A E Bethimhem Steel Corp 80/06/24 10pp

- 8007130046 Corrects Comment 3 which was miscoded in rulemaking Requests placement of corrected notice in file * Docketing & Services Branch 80/06/30 1p
- 8007150051 Corrects Comment 19 which was miscoded in rulemaking Requests placement of corrected notice in file + Docketing & Services Branch 80/06/30 lp
- 8007190067 Comments on proposed rule 10CFR20 Items B (4) & C (3) should contain ref to soil concentration stds & Item D (7) should also include effluent monitoring DEBOERITK New York. State of 80/06/18 ip
- 800715006B Comments on proposed rule IOCFR51 Dept of Natural Resources supports requirement that applicants provide notice of intent to tender application for CP J months prior to submittal Reduces duplication & insures coordination # Georgia, State of 80/06/27 2pp
- 8007150070 Comments on proposed rule 10CFR20 cost/benefit equation of added certification regulation should be considered Certification does not guarantee Improvement Testing labs should be established by processors & not under NRC control LINTON.O W Affiliation Unknown 80/06/26 jp
- 8007180072 Comments on proposed rule (OCFR20 program will be large expense for limited benefit Testing is overemphasized Requirements for processors should begin w/committee of experienced experts

 JONES:D E Affiliation Unknown 80/06/24 App
- BOO7150077 Comments on proposed rule 10CFR20 supports mandatory processor cortification process.certification by category, establishment of cortification board & change in beta exposure testing process
 DEHART.R M Air Force, Dept of 80/06/24 3pp
- 8007150080 Comments on proposed rule iOCFRRO testing program may cause processors to design dosimeter merely to pask test Program must evaluate processor in intangible areas Accuracy requirements are everly restrictive JACKSON.P G Army.Dept of 80/06/23 3pp
- BOO71900B4 Comments on proposed rule 10CFR20 NRC program should permit integration w/similar federal & state programs All elements of certification program should be available to all processors & implementing agencies
 VILLFORTH, J C HEW, Dept of, US Public Health Service 80/06/27
- BOO71500B9 Comments on proposed rule loceR50 objects to requirements of Bubpart P to proposed App R No reasonable basis exists for requiring either reactor coolant pump fire suppression system or lube oil components to utilistand SSE VAN BRUNT.E E Arizona Public Service Co 80/06/30 ip
- 8007150095 Comments on proposed rule 10CFR50 concurs w/need for fire safety rules & to upgrade existing facilities Program should not rely on existing NFPA stds NRC should develop new fire codes. Respectally new fire sprinkler codes. Respectally new fire sprinkler codes. Respectation with the sprinkler codes. Repetation Unknown 80/06/16 9pp
- 8007150103 Comments on proposed rule 10CFR50 supports proposed regulations Existing fire extinguishers are inferior fire fighting tools Fixed suppression sys for cables should be automatic & primary reliance should be water spray PATTON.R M Affiliation Unknown 80/06/17 2pp
- 8007150104 Comments on proposéd rule 10CFR20 should incorporate ECRP-26 W/o exception, provided incorporation would be compatible W/federal acceptable radiation risk policy BUCHHOLZ:R M General Electric Co ANT-14-80 80/06/16 3pp
- 8007150110 Comments on proposed rule 10CFR20 present radiation stds unsafe Federal govt should initiate energy program to promote conservation & renewable energy sources ROHIC. B Affiliation Unknown 80/06/16 lp
- BOO7150112 Comments on proposed rule (OCFR30 opposes adoption in present form Deadline of BOI101 for implementation is unreasonable Preparation of ETS needed since shutdown would cause adverse consequences to snytron by yollution CONNER.T B Affiliation Unknown BO/Q6/3Q App
- 8007150116 Comments on proposed rule IOCFR20 specific elements of radiation protection program should be developed in reg guides or other suitable documents Requirements for transportation of radioactive matis already covered by DOT BERNSEN.8 A Dechtel Power Corp (subs of Bechtel Corp) BO/06/17 20s

- B007150it9 Comments on proposed rule IDCFR50 impact of rule on plants w/acceptable fire protection plan should be invostigated Section II.Part A.Paragraph 2f will allow inadequate protection against expusure fires COHN.B M Gage-Babcock Associates, Inc. B0/06/26 2pp
- B007180182 Comments on proposed rule 10CFR20 for vast majority of individuals, no significant internal exposure is accumulated Reporting of internal exposure should only be required for situations exceeding 40-h control measure DISE, D P Niagara Mohawk Power Corp 80/06/17 4pp
- 8007150133 Comments on proposed rule 100FR50 strongly disagrees w/need for proposed rule Alternative designs should remain acceptable Proposed rule is overly specific implementation date of 601101 cannot be met VAMN.A D Georgia Power Co 80/06/27 3pp
- 8007150134 Comments on proposed rules IOCFR2 & 50 suggests rewording of Paragraph 30 91(b) to reflect const & operation considerations SP & power level increase not relevant to significant helards finding HOFFMAN.D P Consumers Power Co 80/06/23 lp
- B007:50140 Comments on proposed rule lOCFR&O geologic setting requirement should indicate detailed investigation necessary to define actual & potential impacts Gradients vary due to thermal conductivisty & boundary condition changes MCGRAY.J G Arizona, Univ of 80/06/26 2pp
- 8007150143 Comments on proposed rule 10CFR50 concerns anclude applicability, schedule & overall effect on fire protection Rule should not apply to mode resolved in SER issued prior to effective date Implementation schedule unreasonable HEIDER, I. H. Yankee Atomic Electric Co. HYC 80-22 80/06/25 33;
- 8007150152 Comments on proposed rule 10CFR50 30-day review period inadequate in light of excessively specific & restrictive requirements Outage time required for meds systemate Cost outwepghs benefits Alternate methods not permitted HOWARD.J E Boston Edison Co VP-N 80-69 80/06/27 App
- B00719015B Comments on proposed rule 10CFR90 stds should result in high level of fire safety Quidelines slanted toward use of water for all tire protection problems Fire brigade training ravision suggested BUNSTROM,R F Affiliation Unknown B0/06/24 2pp
- 8007150166 Comments on proposed rule 10CFR50 manually actuated fire suppression sys should not be specified fire barriers & suppression sys must be inspected to maintain integrity Min fire brigade size questionable MELOTT,R X Affiliation Uninown 80/06/23 3pp
- B007160196 Forwards comments on proposed rule 10CFR50 wording is vague & unenforceable Fire protection terms mentioned in app are improperly used & inadequately explained Comment period of 30 days is insufficient DUNGAN.K # Affiliation Unknown B0/06/19 App
- 8007160402 Comments on proposed rule 10CFR70 requests NRC simplify licensing of nuclear pacemakers SMYTH,N P D Affalantion Unknown 80/04/29 2pp
- 9007160405 Comments on proposed rule 10CFR61,approach to regulation by performance objectives is highly commendable RODGERS-J, WHEELER.M., DEPUORTER.J Los Alamos Scientific Laboratory 80/05/14 Gpp
- 8007160415 Comments on proposed rule 10CFR50 concerned w/subjective nature of many requirements HATHAWAY.L R Marsh & McLennan.inc , M & M Nuclear Consultants.inc Div 80/06/23 App
- 8007160420 Comments on proposed rule iOCFR50 in general too vague for effective implementation Significant lack of definitions & usage of many terms

 ODOUNING Portland General Electric Co 80/06/27 10pp
- 8007160593 Advises of CPC adoption of EEJ 800707 statement of position re-proposed rulemaking on storage & disposal of radwaste QALLO.J Isham, Lincoln & Beale 80/07/11 1p
- BD07160619 Comments on proposed rules 10CFR2 & SO concurs w/proposed rule change NRC can make significant hazards determination No public interest is served by requiring 70-day wait before issuing amends of DLS & CPs DALE, L F Mississippi Power & Light Co AECH-80/106 80/05/28 in

- 8007160779 Comments an proposed rule (OUFRAO objects to storing high level nuclear waste in rock formations Hastes should be stored in retrieval storage facilities until genuine disposal mothod is found MASSERBACH.A & Affiliation Unknown 80/06/li ip
- 6007170105 Comments on proposed rule 10CFR20 promulgation of major change would be disruptive & not advance cause of occupational radiation safety Licensees should not be required to defend NRC does 6565 LEHIS:L Duke Power Co 80/06/17 11pp
- B007170179 Forwards 1 Remson 800518 comments on proposed rule 10CFR60 to BMI Hydrology can porform containment function for period as short as 1,000 yrs Geochemistry provides backup solution to transport problem
 NICHOLSON,T J Site Safety Standards Branch 80/06/26 5pp
- 8007170491 Comments on proposed rule 10CFR50 on behalf of utils listed in Attachment A Expresses concern that most utils will be unable to meet implementation date being mandated by Commission Pages missing from Commont 8 docketed 800630 KNUTH.D F Kerr-McGee Corp 80/06/27 41pp
- B007210i68 Comments on proposed rule 10CFR50 objects of proposed stds on procedural & substantive grounds General objections concern imadequacy of technical data & justification supporting proposed rules KEARNEY. J Edison Electric Institute 80/06/30 28pp
- 8007210259 Comments on proposed rule 10CFR20 pilot study conducted by Univ of MI does not accurately reflect capabilities of all processors Clerical errors which occurred during study do not reflect performance of commercial processors TDDD.W E Affiliation Unknown 80/06/12 5pp
- BOOTR20093 Comments on proposed rule 10CFR50 fixed supression sys for cables should be automatic not manual & primary Reliance should be placed on water spray Conventional fire sprinkler sys should not be used PATTON.R M. Affiliation Unknown BO/06/17 2pp
- --8007220102 Comments on proposed rule lOCFR50 should not rely overly on existing NFPA stds NRC should establish program to ascertain viability of existing codes & begin to develop new fire rules Vendor fire protection repts encl PATYON,R M Affiliation Unknown 80/06/16 9pp
- 8007220439 Comments on proposed rule 10CFR50 to require same spacing of clear air space horizontally & vertically is inconsistent Horizontal spacing of 50 ft is considered very extreme FULLER. J K Public Service Co of Colorado P-80200 80/07/03 4pg
- 8007220539 Notice of appearance in proposed rulemaking proceeding re storage & disposal of radwaste Certificate of Svc encl BERGER.R F Oklahoma, Btate of 80/07/09 5pp
- B007230042 Comments on proposed rule 10CFR50 high priority status for adol changes to fire protection programs & design features of existing operating plants uncertain CAHNA AL Bochtel Power Corp (subs of Bechtel Corp) B0/06/27 200
- B007230044 Comments on proposed rule 1907R50 overly specific & in present form could force changes reducing safety of plants ZARAKAB.P Consolidated Edison Co of New York 80/06/30 3pp
- B007230147 Comments on proposed rule iOCFR50 proposed rule would not allow for Flexibility or alternatives Regulation should specify requirement & intent of fire protection program CURTIGN W Pennsylvania Power & Light Co 80/06/27 2pp
- 8007230175 Comments on proposed rule 10CFR50 implementation dates unreasonable & impracticable Fire protection requirements impose financial burden on customers & subvert util earlier compliance efforts
 POINDEXTER.C H Daltimore Gas & Electric Co 80/06/30 16pp
- 8007230181 Comments on proposed rule 10CFR50 insufficient comment period, conflicts could exist re previously approved requirements & value/impact assessment Proposed rule overprestriptive & inadequate UHRIO, R E Florida Power & Light Co L~80-207 80/06/30 6pp
- 8007230187 Comments on proposed rule 10CFR50 SER documented agreements should not be subj to snother review or mod Implementation schedule unreasonable Previously approved agreements should not be rescinded PECPLES,D t. Commonwealth Edison Co. 80/06/27 7pp

- B007230193 Comments on proposed rule 10CFR50 requirements impractical & excessive Implementation costs & schedule unrealistic BAYNARD.P Y Florida Power Corp 3-F-2 80/06/27 5pp
- 8007230250 Add1 response to FOIA request for all info re changes to proposed fire protection rule in SECY-80-088 & record of Commission's voto Commissioner Bradford concurrence encl 3ix documents withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 80/07/16 2pp
- --8007230296 Notifies that Commissioner Bradford concurs w/revisions in BOO416 memo re fire protection rule (SECY-BO-098) Excerpt of rule enci THOMPSON.H L. Commission BO/04/21 3pp
- E007230262 Comments on proposed rule iOCFR50 specific fire protection sys imposition will have severe impact on licensees complying w/previously approved programs & will retard implementation PRATT.C M Power Authority of the State of New York 80/06/30
- B007230583 Forwards affidavit of svc omitted from statement of position of State of MN submitted 800703 CLEON, J F Minnesota. State of 80/07/07 2pp
- BOO7240003 Comments on proposed rule 10CFR80 concurs in comments filed by licensees implementation time insufficient Addl critoria should be identified for redundant sys separation DALTROFF, B L Philadelphia Electric Co 80/06/30 épp
- E007240136 Comments on proposed rule 10CFR30 min fire protoction issue should be roopened Arbitrary implementation date unfair
 HOFFHAN, D.P. Consumers Power Co. 80/06/27 Bpp
- 8007240i40 Comments on proposed rule 10CFR50 comment period & implementation schedule should be extended Comprohensive value/impact & environ analyses re fire protoction should be conducted MCGARRY, J M Debevoise & Liberman 80/06/30 55pp
- B007240145 Comments on proposed rule 10CFR50 rule substantial & unjustified deviation from past rulemaking practices Bpecific App R requiroments revoke approved altornate approaches Implementation dates arbitrary WHITE,L D Rochester Gas & Electric Corp 80/06/27 9pp
- 8007240147 Comments on proposed rulo 10CFR61 foderal & state govts should stimulate addl low levol radwaste disposal site devolopment Supports establishing min radioactivity level New & efficient sites should be developed JENNINGS, J Affiliation Unknown 80/07/02 3pp
- BO07240151 Comments on proposed rule 10CFR50 statement that prior agreements w/NRC re fire protection are invalid not reasonable Power plants have expended significant time & money for mods to improve fire protection

 UTLEY.E E. Carolina Power & Light Co NO-80-1001 80/06/30 8p
- 8007240359 Comments on proposed rule 19CFR30 30-day comment period not adequate opportunity nor proper mechanism for setting forth fire protection provisions Adjudacatory hearing would be preferable PORTER. H L Duke Power Co 80/06/30 App
- 8007240367 Comments on proposed rule lOCFR50 previously accepted fire protection altenatives should continue to be accepted Atternate shutdown capability implementation negates positive mod aspects THORPEJ R Oeneral Public Utilities QPU Bervice Corp E&L-2534 80/06/27 9pp
- 8007240375 Comments on proposed rule 10CFR50 opposes proposed rule ra fire protection because it circumvents reiterated peer review comments & is not directed toward power plant safety anhancement Rule should be withdrawn
 PIELAGE.H W Affiliation Unknown 80/06/28 5pp
- 80072403Bi Commonts on proposed rule iOCFR20 Dept of Commerce Natl Voluntary Accreditation Program is possible alternative for identifying competent testing labs Forwards 800123 FR notice defining personnel dosimetry criteria for accredited labs LOCKE, J W Commerce. Dept of 80/06/27 45pp
- BO07250524 Comments on proposed rule 10CFR&O quoting annual rate quantitatively apprear premature Concept of relative risk should be addressed

 JOHNSON:R E Affiliation Unknown 45FR31373 024 80/07/11 1p

- 8007250703 Comments on proposed rule 19CFR20 urges NRC to identify scientific & technical info used as basis for rewriting 10CFR20 or terminate agency action re proposed rulemaking LANDMER.R R Dow Chemical Co. Dow Chemical U S A Div 45FR18023 035 80/06/06 2pp
- B007250710 Comments on proposed rule 10CFR20 Financial cost of mandatory dosimetry testing program should be kept as low as possible w/o jeopardizing volidity of program HQLDEN-R H Affiliation Unknown 45FR20493 032 80/04/25 5pp
- 8007280009 Comments on proposed rule 10CFR60 NRC should establish criteria & stds for overall aus of high level radwaste disposal ather than defining specific performance values for individual components
 ROBINSONG V Exon Nuclear Co , Inc (subs of Exxon Corp)
 45FR31393 015 80/07/11 Jpp
- 8007280016 Forwards comments on proposed rule 10CFR60 NRC should establish criteria & stds for overall sys of high level radwaste disposal rather than defining specific performance values for individual components
 WALSKE.C Atomic Industrial Forum 45FR31393 014 80/07/11 5pp
- 8007280024 Comments on proposed rule 10CFR60 rule represents significant progress toward defining technical criteria for high level wasto repositories Performance of required barriers constitutes sound approach to licensing MENARD.N W Interior.Dept of Geological Survey 45FR31393 012 80/07/10 6pp
- 8007280032 Comments on proposed rules 10CFR2 & 10 requests petition be denied Requirement to conduct informal public hearing in overy instance would inhibit improvements in facility design &/or operation by diverting important resources

 OIBBB, D C Atomic industrial Forum 45FR26071 011 80/07/01 2pp
- 8007280037 Comments on proposed rule iOCFR60 draft technical criteria will provide regulatory means to implement requirements of environ stds EPA will propose in near future HEDEMAN.W N Environmental Protection Agency 45FR31393 023 80/07/18 3pp
- 8007280044 Comments on proposed rule iOCFR&O submitted by CA Enorgy Commission draft technical critoria demonstrate that NRC is aware of issues rejevant to repository licensing VARANINI.E E California, State of 45FR31393
- BOO7280052 Comments on proposed rule iOCFRBO rule roflects NRC vacillation After establishing specific fire protection programs. NRC is proposing whift in groundrules Resulting safety benofits are few MCDDNALD.R P Alabama Power Cn 45FR36082 041 BO/06/27 lipp
- 8007280099 Comments on proposed rule 10CFR50 NRC is hampered because original rule did not concentrate on dodicated remote shutdown capability as solution to fire risk Schodule for completion may be unroalistic CARNEY, J J American Nuclear Insurers 45FR36082 040 80/06/30 200
- --8007280057 Comments on draft reg guido. "Qualification Test for Cable Penetration Fire Stops for Use in Nuclear Power Plants "
 Worst case for gonoric acceptance is valid method
 BANYER, 8 0 , BORNHOEFT, W fi American Nuclear Insurors 79/08/30
 200
- 8007280713 Ack receipt of 800214 ltr & petition on behalf of vendor & 17 utils re NRC proposal for interim emergency planning upgrade regulation Ltr & petition treated as comments on proposed rule Comments will be considered DIRCKS.W J Office of the Executive Director for Operations 80/07/14 lp
- BOO7290002 SECY-BO-291
 Recommends that Commission approve notice of denial of Petition for Rulemaking 2-9 filed by Union of Concerned Scientists & Natural Resources Defense Council Draft documentation encl
 SHAPARI K Office of the Executive Legal Director 43FR48621 SO/06/17 15pp

- --3007290005 Forwards petition for rulemaking 2-8 & comments on proposed rule IGCFR21 RDISMAN, A 2 Natural Resources Defense Council 43FR48621 21 79/03/02 1a
- --B007290012 Petition for rulemaking on amend to 10CFR21, re exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past ARC activities
 POLLARD, R Union of Concerned Scientists RDISMAN, A Z Natural Resources Defense Council 43FR40621 21 79/03/02 14pp
- 8007270235 Forwards quarterly rept on proposed rules for period ending 800430 Rept provides public w/info re NRC rulemaking activaties Related FR notice forthcoming FELTON. J H Division of Rules and Records 80/06/24 26pp
- 8007290286 "Security Facility Approval & Sefeguarding of Natl Security Info & Restricted Data: " & "Financial Protection Requirements & Indemnity Agreements: " 10CFR95 & 140 final rule Reflects revised Canal Zone status DIRCKS.H J Office of the Executive Director for Operations 80/05/23 4pp
- 8007270424 Comments on proposed rule 10CFR30 proposed App R re fire protection specific for regulation Regulations should provide policy or statement of position implementation schedule is unrealistic DRAPER.E L. Oulf States Utilities Co. 45FR36082-045 80/06/26 2pp
- 8007370852 Comments on proposed rule 10CFR20 recommendations of natl & inth bodies must be followed Revisions must not be issued until EPA guidance is established Suggests costbenefit study
 COUNSIL. W G Connecticut Yenkee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities).
 45FR18023 71 80/06/26 3pp
- B00729085B Comments on proposed rule 100FR34 fully supports proposed change KOVACS.B Foster Wheeler Corp 45FR39856 003 B0/07/10 1p
- 8007270887 Comments on proposed rule 10CFR50 Nisgare Hohewk Power Corp indorses comments re fire protection filed on 800630 on of various utils MCGARAY.J M Debevoise & Liberman 45FR36082 052 80/07/14 1p
- 8007270927 Requests that util 790725 comments on "Study of Nuclear Power Plant Const During Adjudication" be considered as comments on proposed rules 10CFR2 & 50 MILLS.L M Tennessee Valley Authority 45FR34279 003 B0/07/02
- 8007300007 Forwards comments on proposed rule 10CFR20 hasty rulemaking may result in adoption of rule before sound certification program has been established Suggestions on establishment of test & certification program included EDMARDS D W Yankee Atomic Electric Co 45FR20493 020 80/06/26 10pp
- B007300014 Comments on proposed rule 10CFR20 supports certification of dosimetry processors Several facets of Health Physics Society Stds Committee/ANSI stds will restrict influence on determination of individual doses YDDER.R C Battella Hemorial Institute, Pacific Northwest Laboratory 45FR20493 049 60/06/25 19pp
- G007300018 Comments on proposed rule 10CFR2D strongly supports requiring litensess to use tested & certified personnel dosimetry svc Tweting lab should be monitored by NBB PARROTTH W Conference of Radiation Control Program Directors, Inc 45FR20493 048 80/07/03 2pp
- B007300027 Comments on proposed rules ICCFR2 & 50 on behalf of Boston Edison Co. Houston Lighting & Power Co & Puget Sound Power & Light Section 2 754 should be reinstated Immediate effectiveness rule should not be amended QARY.F B Lowerstein, Newman, Rais, Axelrad & Toll 45FR34279 008 B0/07/03 3pp
- 8007300032 Comments on proposed rules IOCFR2 & 30 on behalf of utils re immediate effectiveness rule Fifth option, retention of present syst should be adopted w/mod * LeBgeuf, Lemb, Leiby & MacRae 45FR34279 006 60/07/07
- B007300039 Forwards comments on proposed rules 100FR2 & 50 on behalf of UCS re immediate effectiveness rule Option C.repeal of rule, 1s most appropriate action Gross unPairness of rule examplified by Seabroak proceeding

 WEIGH, Bheidon, Harmon & Weiss 45FR34279 007 B0/07/07 App

- 8007300043 Comments on proposed rules 10CFR2 & 50 on behalf of New England Coalistion on Nuclear Pollution re immediate effectiveness rule Urges implementation of Option C. total repeal Const should cease during ASLAG proceedings MEISS, E. R. Sheldon, Harmon & Weiss 45 FR34279 004 80/07/07 7pp
- G007300049 Comments on proposed rule 10CFR30 endorses EEI comments
 Improvement of previously approved schedules is
 unreasonable Short implementation schedule may limit careful
 consideration of fire sefety provisions
 DISE.D P Niagara Mohawk Power Corp 45FR36082 039 80/06/30
- B007300055 Comments on proposed rule 10CFR50 fire protection rule imposes backfitting requirements w/o affording licenses opportunity to legally protect interests Requests withdrawal of App R regulations requiring specific factual bases IRIMBLE.D C Arkansas Fower & Light Co 45FR36082 037 80/06/30
- B007300064 Comments on proposed rule 10CFR30 case-by-case review preferable to litgation which would result from proposed rule Addi manpower requirements for fire brigade definitions & potential litigation costs excessive JACDB. B B Stone & Hebster Engineering Corp 45FR36082 038 B0/07/07 4pp
- B007300066 Forwards comments on proposed rule iOCFR20 formalizing test procedure may result in processors designing dosimeter to pass test instead of providing best possible dosimeter TARAB.D N Army.Dept of, Headquarters Material Development & Readiness Command 45FR20493 047 80/06/24 3pp
- 8007300072 Comments on proposed rule iOCFR50 modifies & voids existing agreements between util & NRC Rule includes new requirements not within scope of original fire hazard analysis & sefety evaluation
 MATTIMOE, J J Sacramento Municipal Utility District 45FR36082 044
 80706730 Jpp
- B0073000Bi Forwards comments on proposed rule iOCFR50 requests change not be adopted as written Required completion date is unreasonable Deadline does not consider overall fire protection in existence at facility

 MATTINGE, J S Sacramonto Nunicipal Utility District 45FR360B2 048 B0/07/03 10pp
- 8007300085 Comments on proposed rule 10CFR50 proposed rule on fire protection too ambiguous to provide desired results implementation date for new mods & restinding of previously agreed upon completion dates are unacceptable FAY.C W Wisconsin Electric Power Co. 45FR36082 049 80/06/30 6pp
- 8007300113 PNL-2882
 "Disruptive Event Analysis Volcanism & Igneous Intrusion "CROHE, B M Battelle Memorial Institute, Pacific Northwest Laboratory II-182 79/10/31 47p
- B007300141 Comments on proposed rule 10CFR50 App R should be abandoned Overspecification of detailed design & procedural requirements are inappropriate Overspecification voids efforts to upgrade fire protection capability CROUSE.R P Toledo Edison Co 45FR36082 05: 80/06/30 2pp
- 8007300234 Comments on proposed rule iOCFR50 sound technical bases may not exist to support emergency planning iones noted in rule Fifteen-minute notification requirement is unrealistic Specific comments encl
 CLUSEN.R C Energy.Dept of 45FR75167 203 80/07/09 9pp
- 8007300249 DNHI-18
 "Summary Characterization & Recommendation of Study Areas
 for Gulf Interior Region"
 # Dattelle Hemorial Institute III-016 79/05/31. 70pp
- 8007300411 Comments on proposed rule 10CFR73 re physical protection of irradiated spent fuel in transit unneccesarily duplicative routing requirements may confuse carriers & interfere w/ private competition in shipping industry CUNNINGHAM, G W Energy, Dept of 45FR37397 CO2 80/07/11 2pp
- B007300449 Comments on proposed rules 10GFR2 & 30 only acceptable option is Option E which would retain present sys unchanged. Present sys impacts on decisionmaking felt only w/respect to environ.not safety-related concerns PEOPLES.D L Commonwealth Edison Co 45FR34279 010 B0/07/07 opp

- BOO7300475 Comments on proposed rules 10(FR2.19.20,21.30,40,51,40 & 70 on behalf of Americans for Indian Opportunity Part of rules entitled. "Participation by State Govts." should mention Indian tribes
 HARRIBL Affiliation Unknown 44FR70408 033 B0/06/27 ip
- 8007300865 Comments on proposed rule 10CFR34 submitted by Hughes Airwest Supports limiting requirements for retention of records of daily readings of pocket dusimeters No need for retention of records for more than 1 yr.

 MEIER.N 0 Affiliation Unknown 49FR39886 002 80/07/10 1p
- B007300569 Comments on proposed rules 10CFR2 & 90 Commission adds for granting stays should be related Basic procedures of licensing process, including immediate effectivenes rule, are sound CALLO, J. WILLIAMS, F. C. Public Bervice Co. of Oklahoma 45FR34279 009 80/07/07 10pp
- 800/300571 Comments on proposed rules iOCFR50 & 51 strongest regulations possible should be applied to development of any EIS required by NEPA Supports Commissioners Gilmsky & Bradford position
 CURRY.J B Affiliation Unknown 45FR40101 005 B0/07/03 ip
- 8007300573 Comments on proposed rules 10CFR50 & 51 all nuclear projects where CP has not been issued, should be required to undergo investigation of full range of consequences possible from Class 9 accident
 KEESE, B Texas, State of 45FR40101 006 80/07/18 1p
- SD07310277 Comments on proposed rule 10CFR30 implementation schedule for fire protection unreasonable App R should reflect intent of reg guide while allowing flexibility re compliance methods Proposed revisions onc?

 BYLVIA.B R Virginia Electric & Power Co 45FR36082 043 80/06/30 32em
- BOO7310444 Comments on proposed rules locfR2 & 50 present immediate affectiveness rule re const during adjudication should be retained Recommends adoption of Option E re retaining present sys

 WALEKE.C Atomic Industrial Forum 45FR342/9 OIL 80/07/0/ ip
- --B007310445 Comments on "Study of Nuclear Power Plant Const During Adjudication" Immediate effectiveness rule should be retained as it is currently being interpreted & implemented Rule balances reactor const needs & public sofety WALEKE.C Atomic Industrial Forum 79/01/30 2pp
- 8007310456 Comments on proposed rules 10CFR2 & 50 Findings 2.5.6.10 & 13 do not present convincing case for change in immediate effectiveness of rule re const during adjudication VAN GRUNT.E E Arizona Public Service Co 45PR34279 012 80/07/10 5pp
- 8007310464 Forwards comments on proposed rules 10CFR2 & 50 Seabrook case is no reason to change sym of immediate effectiveness. More delay in nuclear licensing process is intolerable Delay is chief weapon of antinucleal movement.

 VANDENBURGH.D Yankse Atomic Electric Co 49FR34279 013 80/07/16 31pp.

PRM PETITION FOR RULEMAKING

- 8007030078 Comments on petition for rulemaking 51-6 Part 51 already contains provision requiring E18 in appropriate cases Guigg petition should be denied because no NRC proposal for major federal action is identified THOMAS.W N Virginia Electric & Power Co 534 80/06/16 App
- 8007030184 Comments on petition for rulemaking 51-6 ElS of use of high burnup nuclear fuel would not be significant NRC review of generic environ analysis should not delay issuance of amends which are conditioned to times when fuel undergoes exposure PARKER.W O Duke Power Co 80/06/13 9pp
- 8007090294 Comments on Citizens Advisory Board of Metropolitan Area Planning Agency petition for rulemaking 2-10 Opposes request due to addl burden on licensing process w/o benefit of procedure effectiveness Present regulations fulfil request CDUNBILLW O Northeast Utilities 810023 80/04/14 3pp
- 8007100077 Comments on petition for rulemaking 2-10 requirement for informal hearing would apply License amend involves no significant safety issue
 VAN BRUNT, C. E. Artiona Public Service Co ANPF-15662 80/06/16

- B007100120 Comments on petition for relemaking 140-2 by Washington Legal Foundation Proposed rule would substantially increase costs to industry 's consumers Price-Anderson approach is best for situation involving alight chance of diaster POPEO.D J . BENSING.D Affiliation Unknown B0/06/18 App
- 8007100129 Comments on petition for rulemaking 140-2 supports petition Liability insurance should be paid for by Stockholders not rate payers EDDLEMAN Affiliation Unknown 80/06/08 1p
- 8007100176 Comments on potation for relemaking 140-2 by Association of Bar of City of NY Providing only liability inserionce would not be in public interest "leveld jeopardize nuclear power LEDERER,P D Affiliation Unknown 80/06/18 Spp
- 8007100130 Comments on petition for rulemaking 140-2 enderses axisting rule Petition does not raise policy issues requiring additions ideration Price-Anderson Act & Amends inflect Congressional Intent
 NEXON-8 H Commonwealth Edison Co 80/06/13 2pp
- 8007:00:134 Commonts on petition for rulomaking 140-2 defends Price-Anderson Insurance & Indemnity Program by describing backgrounds of program & history of nuclear insurance pools PROOM B C American Nuclear Insurers KELLY. A Mutual Atomic Energy Liability Underwriters 80/06/13 9pp
- BOD7100290 Comments on potition for rulemaking 2-10 proposed mods to regulations are unneeded detrimental to officiency & contrary to requirements of law Petition should be denied KNOTFS.J B Dobevoise & Liberman BD/06/16 Epp
- BOO7100343 Comments on petation for rulemaking 2-10 frequent public hearings of trivial matters would divert mgt attention & engineering resources away from plant operations & would be significant drain on liconsee & NRC resources
 PEOPLES,D. L. Commenwealth Edison Co. 80/06/16 25p
- BOO7100345 Comments on petition for rulemaking 2-10 disting rules for formal intervention are sufficient to ensure that persons w/bona fide interests get full apportunity to partiripate in proceedings cost-benefit aspects compel denial BROCHL,D J Portland General Electric Lo 80/06/11 2pp
- 8007100355 Comments on patition for rulemaking 2-10 budgetary & personnel impact on NRC would be significant & would abstruct & delay licensing Proposed changes would not raise quality of public participation or regulatory process PATTERSON, J D Middle South Services, Inc. 60/06/12 2pp
- 8007100357 Comments on petation for relemaking 51-6 test programs should be developed in reactors at remote sites to evaluate cladding & fuel damage & emission of airborne & liquid affiliants before increasing nuclear fuel assembly burnup GULBRANSEN.E A Pittsburgh. Univ of 80/06/04 2pp
- 8007100359 Commonts on petition for rulemaking 2-10 hearings should be nocessary only in cases where literaing or regulatory action requires EIA Petitioners' concerns are adequately addressed by current regulatory plans
 DIPIAZZA:R P Hestinghouse Electric Corp 80/06/16 2pp
- 8007100366 Comments on petation for rulemaking 51-6 better U utilization (less mining & milling) will have positive effect on environ improved assumbly designs will result from current submided burnup programs

 CAVANAUGH, W. Arkansas Power & Light Co. 1-160-10 80/06/13 App
- 8007100378 Comments on petition for rolemaking 51-6 plans underway to subject high-bornup assemblies from inventory to periodic surveillance to characterize behavior during water pool storage Proposes combination reactor % pool surveillance JOHNSON A B Battello Momorial Institute, Parific Northwest Laboratory 80/04/12 3pp
- 8007100385 Comments on petition for rulemaking 51-6 high burnup fuel might produce more radioactive gas from reactors & spent fuel pools & produce deteriorated Liadding on spent fuel rods NRC should support petition to require full FIS KRICHIVER.R Affiliation Unknown 80/06/16 1p
- BOD7100437 Comments on petition for rulemaking 2-10.an behalf of Dotroit Edison.Niagera Mohawk PG of IN Rochester Gas & Electric current NRC practice re public hearings is adequate No amend to regulations is necessary LEDGEUF, R J , LAMB.H R , LETTY.A C LeBoruf. Lamb, Letty & MacRae BO/06/14 4pp

- 8007110451 Comments on petition for rulensking 51-6 petition takes statements out of conteit to leaves incorrect implication that greater fission gas releases are projected to occur to environ w/use of high burnup fuel LANG.P M Energy, Dept of SU/06/10 Epp
- 8007;10502 Comments on petition for rulemaking 140-2 since liability insurance provided by nuclear insurance pools is max amount available no change in regulations re financial protection warranted 8000EN.T J Alabama Power to 80/05/23 1p
- 8007110509 Comments on patition for rulemaking 140-2 requests initiation of rulemaking proceeding to investigate possibility of amending regulations or financial protection requirements for nuclear facilities

 UDALL.M K House of Rep , Interior 's Insular Affairs 80/06/20
- 8007110522 Comments on petition for rulemaking 51-6 since high burnup nuclear fuel program is currently under development & not fully implemented, petition is premature DIPFAZZA.R P Westinghouse Electric Corp WRD-LA-151 80/06/16
- 8007i10529 Connents on petition for rulemaking 51-6 preparation of generic EIS for high burnup nuclear fuel unwarranted Petition should be denied EDMARDS, D W Yonkee Atomic Electric Co WYC 80-21 80/06/20 2pp
- B007140030 Comments on petition for rulemaking 2-10 requiring formal public hearings for every amend and & susponsion of CL would place immense burden on util & NRC MODN.J H Yankee Atomic Electric Co MYC 80-19 80/06/19 2pp
- 8007140047 Comments on petition for rulemaking 140-2 results sought by petitioners are beyond NRC authority. Unworkable & unwise To advocate mandatory conversion of property insurance to liability insurance is irresponsible NALSKE.C Atomic Industrial Forum 80/06/23 3pp
- 8007i40052 Comments on patition for rulemaking 140-2 NRC should increase amount of primary layer financial protection licenses are required to maintain CHARBERLAIN W M California, State of 80/06/20 lopp
- B007140235 Comments on petition for rulemaking 51-6 petition should be denied High burnup fuel should not increase impact on environ since fuel & cladding in pool environ are relatively stable & conditions in fuel storage pool less severe PEOPLES, D. L. Commonwealth Edison Co. B0/06/19 6pp
- 8007140240 Comments on petition for rulemaking 51-6 petition should be denied Developmental program for high burnup fuel not intended to change existing regulatory limits of radioactive release
 NILLS,L M Tennessee Valley Authority 80/06/19 2pp
- B007140448 Comments on petition for rulemaking 140-2 opposes proposed change Nuclear liability insurance available from American Nuclear Insurers is max available from private sources at cost & on reasonable terms

 MB0DS,T G Arizona Public Service Co 80/06/20 3pp
- B007140410 Comments on petition for rulemaking 20-6 requests 5 minutes during 800if5 meeting to present view on occupational radiation exposure stds

 FLEISCMAKER.D S Natural Resources Defense Council B0/01/11 5pp
- B007170275 Comments on petition for rulemaking 51-6 much of petition is based on misinterpretation of technical terminology & apparent lack of knowledge of contemporary, worldwide nuclear fuel cycle research
 SHIELDS, R O Affiliation Unknown B0/06/13 App
- 80072102/3 Comments on petition for rulemaking 2-10 change could prove counterproductive to public health & safety Establishment of min criteria on intervention should be designed to encourage groups wilegituate interest in proceedings to participate UTLEY.E E Consumers Power Co 80/06/16 2pp
- 8007230048 Comments on petition for rulemaking 140-2 rationale for petitioners conclusion that present liability insurance not max insurance available premised on faulty analysis of insurance market GOUNSIL. N 3 Northeast Utilities MGC-80-0-413 80/06/23 2pp
- 8007280189 Comments on petition for rulemaking 140~2 strongly urges rulemaking to reform Price-Anderson Act BINGHAH.J House of Rep. 45FR26973 012 80/07/03 (p.

- 8007290002 SECY-80-291
 Recommends that Commission approve notice of denial of Petition for Rulemaking 2-9 filed by Union of Concerned Scientists & Natural Resources Dofense Council Draft documentation encl
 SHAPAR.H K Defice of the Executive Legal Director 43FR48621
 80/06/17 15pp
- --8g07290005 Forwards petition for rulemaking 2-8 & comments on proposed rule 10CFR21 RDISMAN, A Z Natural Resources Defense Council 43FR48621 31 79/03/02 1p
- --B007290012 Petition for rulemaking on amend to IOCFR21, re exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past NRC activities PDLLARD.R Union of Concerned Scientists ROIBMAN.A Z Natural Resources Defense Council 43FR48621 21 79/03/02 14pp
- B007300003 Comments on proposed rule 10CFR51 proposed amends should clarify treatment of existing reactor sites as candidates for additionable whether product or process-oriented review is required
 MILLS.L M Tennessee Valley Authority 45FR24168 027 80/07/09 20p
- 8007300294 Comments on petition for rulemaking 91-6 generic EIS not appropriate re use of high burnup nuclear fuel in commercial nuclear reactors since overall environ impact will be positive Discusses misconceptions in petition TAYLOR, J H Babcock & Wilcox Co 45FR25557 014 80/07/02 4pp
- PROJ PROJECTS PREDOCKET LICENSING
- 8007100152 Forwards corrected version of Exhibit 1 to answers to CA Dept of Water Resources fourth set of interrogatories MEISS,R L Pacific Ons & Electric Co 80/06/16 ip
- --8007100154 Corrected Exhibit 1 to answers to fourth set of interrogatories re reliability calculations * Pacific Gas & Electric Co B0/06/16 23pp
- 8007)60491 Advises NRC that proposal to extend LWBR operation was discussed at 241st ACRS meeting ACRS believes it is acceptable to operate reactor core to 24,000 EFPH as proposed PLESSET. M S ACRS Advisory Committee on Reactor Safeguards 80/05/04 2pp
- B007230075 Requests review of encl final GEIS on U milling Also requests statement of concurrence in those sections contributed by respective ofts Final GEIS has been prepared in response to public comments re draft GEIS W/o encl MARTIN.J B Division of Waste Management 80/07/03 2pp
- B007250440 Forwards Amend 43 to FSAR SCHAPE, A R Hanford Engineering Development Laboratory 80/06/04
- --8007250444 Amend 43 to FSAR

 * Hanford Engineering Development Laboratory 00278 80/06/04 128pp
- 8007290039 Ack receipt of 800512 ltr forwarding essay, "Fxcellence in Operations" NRC shares hope that attitude will become general in nuclear field W/o encl NRC to C Eberle ltr DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/14 ip
- --B007290042 Forwards essay, "Excellence of Operations" from contest inspired by quote in recent inside NRC newsletter Hopefully philosophy can eventually be general attitude of nuclear field SUMMERS. J. Affiliation Unknown B0/05/12 2pp
- E007290463 Suggests that ANL subcontract w/RAE Corp for Jul-Sept 1980 to finalize App P (ladon attenuation models) & App U (radon control cost-benefit analysis) for GEIS
 MARTIN.D E Uranium Recovery Licensing Branch 80/06/18 2pp
- --B007290470 Advises that NRC has no need for further assistance from Stanley Consultants, Inc at present Requests extension of contract until 800930 in case assistance is required for review of finalized matl .

 MARTIN.D E Uranium Recovery Licensing Branch 80/06/18 ip

- PT21 NDNCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- B0072i0079 Part 21 rept re recall of welding fittings containing J55 grade drill casing matl Armco Steel Co has completed testing of all raw matls in plantiall in-process matl & in-process of checking field complaints & matl returned to Tube Turns HAYDEN, L E Chemtron Corp., Tube Turns Div B0/07/03 3pp
- B00724037i Part 2i rept re defective Atomic Energy of Canada Limited commercial products Models Theratron 40 & 80 & Eldorado 6 & 8 to the Eldorado 6 & 8 t
- BOO7250297 Forwards Part 21 rept re Valcor valve Part V52600-554-1, which failed to cycle immediately following sustained period of continuous energization Caused by use of valves not designed for operating condition
 BORGO G U Valcor Engineering Corp 80/07/03 4pp
- PT9 10CFR, PART 9 -
- 7812210353 Forwards IE Insp Rept 30-12052/78-01 on 781011 No items of noncompliance noted Insp included exam of activities at Pittsburgh office re radiation safety & compliance w/rules & regulations W/out rept MCCLINTOCK, R O Region i, Philadelphia, Fuel Facility & Materials Barety Branch 78/10/31 ip
- 8005070523 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE Insp 79-01 on 791212 MCCLINTOCK,R O Region i. Philadelphia. Fuel Facility & Materials Bafety Branch 80/02/26 ip
- --B005090524 Responds to NRC 800109 ltr re violations noted in IE insp on 791212 Corrective actions discussed infractions w/ technicians involved Classes planned w/all technicians on requirements & restrictions CARMEL, P Rad Services. Inc 80/01/30 ip
- --8005090527 Discusses 1E Insp 79-01 om 791212 & forwards notice of violation
 HCCLINTOCK, RO Region 1, Philadeiphia, Fuel Facility & Materials Safety Branch 80/01/09 2pp
- --B005090529 Notice of violation from insp on 791212 Noncompliance noted required radiation surveys not performed on packages received
 - Region 1. Philadelphia. Office of the Director 80/01/09 2pp
- BOO5290403 Ack receipt of BO0421 ltr informing NRC of steps taken to correct violations noted in IE insp of License 37-13129-01 on BO0228 CROCKER.H W Region 1: Philadelphia, Office of the Director BO/05/07 ip
- ---8005290607 Responds to NRC 800328 ltr re violations noted in IE insp of License 37-13128-01 on 800228 Corrective actions new procedures will be developed to improve coordination in receipt of incoming radioactive samples KIM, S M Radiation Management Corp 80/04/21 2pp
- --H005270412 Discusses IE insp of License 37-13127-01 on BOOP2B & forwards notice of violation CROCKER, H W Region 1, Philadelphia, Office of the Director 60/03/28 2pp
- ---8005270616 Notice of violation from insp on 800228 Noncompliance noted failure to keep records showing receipt of radioactive samples # Region i, Philadelphia, Office of the Director 80/03/28 ip
- QA999 QUALITY ABSURANCE INSPECTIONS
- B007010015 Ack receipt of B00523 ltr re discrepancy between notice of deviation contained in GA Program Insp Rept 97900340/80-01 & Procedure GAI-O21-002 Notice of deviation should have been discussed during exit meeting P07APGVS, U Region 4, Dallas, Vendor Inspection Branch B0/06/17
- --8007010029 Discusses discrepancy between notice of deviation & item noted & discussed by WK Melley during 800422-24 audit & exit interview Procedure @AI-021-002 referenced in notice contains six deficiences Procedures uncl MYERS.F 8 Yerway Corp 80/05/23 12pp

- --8007010034 Forwards GA Pingram Insp Rept 99900340/80-01 on 800422-24 & notice of deviation POTAPOVS, U. Region 4, Dallas, Vendor Inspection Granch 80/05/08 Den
- --8007010039 Notice of deviation from insp on 800422-24
 * Region 4, Dallas, Office of the Director 80/05/06 ip
- --8007010051 GA Program Insp Rept 99900340/80-01 on 800422-24
 Noncompliance noted GA instructions for control of magnetic
 particle examb did not contain all info specified by ASME
 Codes
 KELLEY,W D , WHITESELL,D E Region 4, Dallas, Vendor Inspection
 Branch 80/05/06 9pp
- 8007010135 Ack receipt of 800422 & 0515 ltrs informing NRC of steps taken to correct violation noted in GA Program Insp Rept 979700384/80-01
 PDTAPOVS.U Region 4, Dallos, Vendor Inspection Branch 80/06/04
- --8007010142 Responds to NRC 800502 ltr requesting add1 info re previous response to Insp Rept 99700384/80-01 Apologizes for error in response due to typing mistake Product audit does exist in GA sys manual HUPPERT, WW Guif & Western Industries. Inc 80/05/15 2pp
- ---8007010147 Ack receipt of 800422 ltm informing NRC of steps taken to correct violation & deviation noted in GA Program Insp Rept 99900384/80-01 Requests add1 info POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/05/02 in
- --8007010151 Responds to NRC 800328 ltr re violation & deviation noted in GA Program Insp Rept 97900384/80-01 Corrective actions bulietin re 1005R21 to employees & dealers has been distributed Marking procedures will be updated by 800401 HUPPERT.W W Oulf & Western Industries, Inc 80/04/22 12pp
- --8007010154 Forwards QA Program Insp Rept 99900384/80-01 on 800303-07 & Motices of violation & deviation POTAPDVS U Region 4, Dallas, Vendor inspection Granch BO/03/28
- --8007010163 Notice of violation from losp on B00303-07
 * Region 4. Dallas. Office of the Director 80/03/26 ip
- --8007010167 Notice of deviation from insp on 800303-07
 * Region 4. Dallas, Office of the Director 80/03/26 App
- --B007010171 GA Program Insp Rept 999003B4/80-01 on 800303-07 Noncompliance noted failure to follow 10CFR21 procedures Receiving insp had not been done using sample tables of insp manual FOSTER.W E . HUNNICUTT.D M Region 4. Dalias. Vendor Inspection Phasek R0/03/26 10pp
- 8007100326 Ack receipt of 800530 Ir informing NRC of steps taken to correct deviation noted in GA Program lasp Rept 99900046/80-01 FOTAFGVS, U Region 4. Dallas, Vendor Inspection Branch 80/06/05
- --8007100330 Responds to NRC 800519 ltr re deviation noteed in QA Program
 Insp Rept 99900048/80-01 Corrective actions will make every
 effort to ensure that audits are conducted on time
 8HAYNE:R W Anchor/Darling Valve (subs Anchor/Darling
 Industries) 80/05/30 in
- --B007100333 Forwards QA Program Insp Rept 99900049/80-01 on 800421-25 & notice of deviation POTAPDVB.U Region 4, Dallas, Vendor Inspection Branch 80/05/19
- --8007100336 Notice of deviation from this on 800421-25
 * Region 4, Dallas, Vendor Inspection Branch 80/05/13 19
- --8007100339 QA Program Insp Rept 99900048/B0-01 on 800421-25
 Noncompliance noted followup corrective actions for audits
 not taken within specified timeFrame
 WHITESELL, D E , HUNTER, V H Region 4, Dallas, Vendor Inspection
 8 ranch 80/05/13 5pp
- H007140033 Ack receipt of 800530 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900401/80-01
 PDTAFBUS, U Region 4, Dallas, Vendor Inspection Branch 80/06/12 to

- --8007140037 Responds to NRC 800502 ltr re deviation noted in QA Program Insp Rept 99900401/80-01 Corrective actions all 1980 internal audits have been reviewed & published within 30 days of post-audit conferences FTHERIDGE, N.R. Combustion Engineering, Inc. 80/05/30 3pp
- --B007140039 Forwards OA Program Insp Rept 99900401/80-01 on 800408-10 & notice of deviation PDTAPOVS.V Region 4. Dallas, Vendor Inspection Branch 80/05/02
- --B007140042 Notice of deviation from insp on B00408-10 # Region 4, Dallas, Vendor Inspection Branch B0/05/01 2pp
- --BO07140048 GA Program Insp Rept 99900401/80-01 on 800408-10 Nuncompliance noted audit repts not issued within required time & corrective action on previous insp not taken as committed HALE.C J. BRICKLEY,R H. AGEE, J.R. Region 4, Dallas, Vendor Inspection Branch 80/05/01 17pp
- BOO7140057 Ack receipt of BOOAOU itr informing NRC of steps taken to correct violation noted in GA Program Insp Rept 9700521/180-01 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch BO/O6/11
- --B007140063 Forwards Bechtel response to item of noncompliance noted in GA Program Insp Rept 99900521/80-01 Corrective action initiated however Part 21 evaluation not conducted Requests comments PGTAPDV9.U Region 4. Dailas. Vendor Inspection Brench 80/04/30
- --8007140075 Responds to NRC BODD11 ltr re violation noted in GA Program
 Insp Rept 99900521/80-01 Corrective actions amended
 iOCFR55(e) rept includes corrective actions & provisions for
 closed loop actions will be incorporated into procedures
 CARACU-I R Bechtel Power Corp (subs of Bechtel Corp.)
 80/04/08 4pp
- --B007i400B2 Forwards GA Program Insp Rept 99900521/80-01 on B00i07-10 & notice of violation PUTAPOVS.V Region 4. Dalies. Vendor inspection Brench 80/02/11
- --8007140087 Notice of violation from insp on 800107-10.
 * Region 4. Dallas. Vendor Inspection Branch 80/02/08 2pp
- --BO071400BB GA Program Insp Rept 97900521/80-D1 on B00107-10
 Noncompliance noted design of safety-related components not
 evaluated
 HALE.C. J. BRICKLEY.R H., DREAUX.D G. Region 4. Dallas. Vendor
 Inspection Branch 80/02/08 12pp
- BOO7160076 Ack receipt of BOO605 ltr informing NRC of steps taken to correct deviation noted in QA Program Imap Rept 99900503/ BO-01 POTAPOVB.U Region 4. Dallas, Vendor Inspection Branch BO/06/17
- --B007160109 Responds to NRC B00507 ltr re deviation noted in GA Program
 Insp Rept 99900303/80-01 Corrective actions mod of drawing
 & spec modified for clarification of design review & check
 process
 HENDRICKSON.T A Burns & Ree Co B0/06/05 7pp
- --8007160115 Forwards GA Program Insp Rept 99900503/80-01 on 800414-18 & notice of deviation POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch 80/05/07 2pp
- ~-6007160121 Notice of deviation from insp on 600414-18
 * Region 4. Dallas, Office of the Director 60/05/06 2pp
- --B007140126 GA Program Insp Rept 99900503/80-0t on 800414-18
 Nuncompliance noted certain safety-related calculations
 lacked verification statement & some audits improperly done
 FOX.D f . BREAUX.D C . J Region 4, Dallas, Vendor
 Inspection Branch B0/05/06 9pp
- 9007160133 Forwards GA Program Insp Rept 99900021/80-01 on 900421-24 No noncompliance noted POTAPOVE,U Region 4. Dallas, Vendor Inspection Branch 80/05/01 200

- --B007160146 QA Program Insp Rept 99900021/B0-01 on 800421-24 No noncompliance noted Major areas inspected heat treatment, noncomformances & corrective action & implementation of IOCFRSO.App B criteria BARNES, I, HUNNICUTT.D M Region 4. Dallas. Office of the Director B0/04/30 App
- 8007160150 Forwards QA Program Insp Rept 79700026/80-01 on 800414-18 No noncompliance noted POTAPGVS.U Region 4, Dallas, Vendor Inspection Branch 80/05/14
- --8007160157 GA Program Insp Rept 99900026/80-01 on 800414-18 No noncompliance noted Major areas inspected implementation of 10CFR50.App B criteria OLLER E . HUNNICUTT.D M. Region 4, Dallas, Vendor Inspection Branch 80/04/28 Bpp
- B007160161 Forwards GA Program Insp Rept 99900521/80-02 on 800428-0501 No noncompliance noted POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch 80/05/19 280
- --8007160171 GA Program Insp Rept 99700521/80-02 on 800428-0501 No noncompliance noted Major areas inspected implementation of requirements of 10CFR30. App '0. in area of design inputs & design insp BRICKLEY.R H , ACCE.J R , HALE.C J Region 4. Dallas, Vendor Inspection Branch 807/05/15 9pp
- 8007160177 Ack receipt of 800606 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900104/80-01 POTAPUVS.U Region 4. Dailas, Vendor Inspection Branch 80/06/17 in
- --800716018B Responds to NRC 800507 ltr re deviation noted in GA Program
 Insp Rept 99900104/B0-01 Corrective actions welders
 reinstructed re bardfacing
 HYLAND.F B Westinghouse Electric Corp 80/06/06 5pp
- ---B007160193 Forwards QA Program Insp Rept 99900104/80-01 on B00421-25 & notice of deviation PDTAPDVS.U Region 4, Dalles, Vender Inspection Branch 80/05/07
- ~~8007160202 Notice of deviation from insp on 800421-25 * Region 4. Dallas. Office of the Director 80/05/05 2pp
- ---B007160207 0A Program Insp Rept 99900104/B0-01 on B00421-25
 Noncompliance noted welding performed outside parameters of
 essential variables
 ELLERBHAUL E, HUNNICUTT,D M Region 4, Dallas, Vendor Inspection
 Branch 80/05/05 opp
- B007160393 Ack receipt of B00613 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900001/ B0-01 P0TAPEUVS.U Region 4. Dallas. Vendor Inspection Branch B0/06/18 is
- --8007160397 Responds to NRC 800513 ltr re deviation noted in QA Program Insp Rept 99900001/80-01 Corrective actions deviated fuel rods in tray tagged as to nonconforming condition BARDGH-C J Babtock & Wilcox Co , Nuclear Material Div 80/06/13
- --8007160404 Forwards GA Program Insp Rept 99900001/80-01 on 800429-0502 & notice of deviation POTAFOVS,U Region 4, Dalias, Vendor Inspection Branch 80/05/13 2pp
- --B007160408 Notice of deviation from insp on B00429-0502
 Region 4, Dallas, Vendor Inspection Branch 80/05/09 2pp
- --8007160411 (A Program Insp Rept 9990001/80-01 on 800429-0502 Noncompliance noted 15 fuel rods not properly tagged MCNEILL, M M , WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/05/09 7pp
- 8007210257 Forwards GA Program Insp Rept 99900390/80-01 on 800513-16 No honcompliance noted POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 60/05/27 20p

- --B007210264 QA Program Insp Rept 99900390/80-01 on B00513-16 No noncompliance noted Major aleas inspected implementation of 10CFR50.App D.including control of noncomformances & corrective actions, weld control & audits BROWN, R L , WHITESELL, D E Region 4, Dalles, Vendor Inspection Branch 80/05/23 App
- 8007210269 Forwards QA Program Insp Rept 99900289/80-02 on 800505-09 No noncompliance noted PDTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/05/28
- --8007210275 GA Program Insp Rept 99900289/80-02 on 800505-09 No moncompliance noted Major areas inspected implementation of iOCFR50.App B & applicable codes % stds & action on previous insp findings
 SUTTON, J W. WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/05/21 App
- B007210536 Forwards GA Program Insp Rept 99700716/80-01 on 800513 No noncompliance noted POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/05/29 2pp
- 8007220136 Ack receipt of BD0623 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990089780-01
 PDTAPOVS.U Region 4. Dalias, Vendor Inspection Brench B0/07/07
- --8007220142 Responds to NRC 800528 lr re deviation noted in GA Program Insp Rept 99900089/80-01 Corrective actions personnel from other depts will be trained to perform internal audits HAN,K Huico, Inc 80/06/23 2pp
- ---B007220145 Forwards GA Program Insp Rept 99900089/80-01 on 800505-08 & notice of deviation FORAPOVS.V Region 4. Dallas. Vendor Inspection Branch 80/05/28
- --8007220150 Notice of deviation from insp on 800505-08 * Region 4, Dallas, Office of the Director 80/05/27 ip.
- --8007220155 OA Program Insp Rept 97900089/80-01 on 800905-0B
 Noncompliance noted dept heads did not include probable
 cause or effective date of corrective action in response to
 adverse findings
 HUNTER,V H, WHITEBELL,D E Region 4, Dallas, Vendor Inspection
 Branch 80/05/27 App
- 8007220182 Ack receipt of 800627 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900325/80-01 POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/07/07
- 1p
- --B0072201B9 Responds to NRC 800604 ltr re deviation noted in QA Program Insp Rept 99700325/80-01 Corrective actions initialed book for new extruder for all active orders run on that machine Procedures for scheduling shop orders are being written AIROLA.E Q Brand-Rex Co 80/06/27 3pp
- --B007220196 Forwards QA Program Insp Rept 99900325/80-01 on 800520-22 & notice of deviation POTAPDV8.V Region 4, Dallas, Vendor Inspection Branch 90/06/04 200
- --8007220202 Notice of deviation from insp on 800520-22 * Region 4, Dallam Vendor Inspertion Branch 80/06/04 Jpp
- --B007220208 QA Program Insp Rept 99700325/B0-01 on B00520-22
 Noncompliance noted no clear & complete documented instructions for shop orders initiated & no extruding guidelines generated for several tasks in progress HUNDICUTT, D M . FOSTER, W E Region 4, Dailas, Vendor Inspection Branch 80/06/04 9pp
- 800723013B Forwards comments to be incorporated in D&H procedures implementing 10CFR21 Remaining actions stated in 800520 ltr re safety matters appear to be adequate Add1 verfication of proper implementation will be undertaken BTELLO.V Office of Inspection & Enforcement, Office of the Director 80707/09 3pp

- 8007230155 Ack receipt of 800619 ltr informing NRC of steps taken to turrect deviation noted in GA Program Insp Rept 99900507/00-01 POTAPOVS.V. Region 4. Dallus Vendor Inspection Branch 80/07/02
- --B007230160 Responds to NRC 800522 ltr re deviation noted in GA Program Insp Rept 9790050780-01 Corrective actions due to other commitments.carrective action will be delaged until 800701 MCFARLAND.J C Sargent & Lundy, Inc 80/06/19 19
- 8007250052 Ack receipt of 800522 itr informing NRC of steps taken to correct deviation noted in 9A Program Insp Rept 99900036/80-01
 POTAPOVS.V Region 4, Dallas, Vendor Inspection Branch 80/06/10 to
- --8007250097 Responds to NRC 800424 itr re deviation noted in GA Program Insp Rept 99900036/80-01 Corrective actions personne: & supervisors have been reinstructed re importance of weld math segregation BATES. 0 J. MILLER. L. C. STONE. W. A. Combustion Engineering, Inc. 80/05/22 Spp
- ~-B007250095 Forwards GA Program Insp Rept 99900036/B0-01 on B00407-i1 & notice of deviation POTAPOVS, V Region 4, Dallas, Vendor Inspection Branch B0/04/24 200
- --8007250100 Notice of deviation from insp on 800407-11 * Region 4. Dallas, Office of the Director 80/04/23 3p;
- --8007250109 GA Frogram Insp Rept 99900036/80-01 on E00407-11
 Noncompliance noted signoff on certain shop traveler was not
 in accordance w/Criterion 5 of 10CFR50
 BARNES,I. ELLERSHAW.L C., HUNNICUTT.D M Region 4, Dallas, Vendor
 Inspection Branch 80/04/23 15pp
- 8007250184 Forwards QA Program lnsp Rept 99900713/80-01 on 800429-30 No noncompliance noted POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch BO/05/14 2pp
- --B007250189 GA Program Insp Rept 99900713/80-01 on 800429-30 No noncompliance noted Major areas inspected GA program & possible handling damage to instrumentation OLLER, R E. HUNNICUTIO M. Region 4. Dallas. Vendor Inspection Branch 80/05/13 9pp
- B007290582 Ack receipt of 800620 ltr informing NRC of staps taken to correct deviation noted in QA Program Insp Rept 99700398/80-01 POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch B0/06/26
- --B007290587 Responds to NRC 800522 ltr re deviation noted in QA Program Insp Rept 99900398/80-01 Corrective actions reviewd Section 1 4.1save A of product design engineering manual to conform w/current practices CONNELLY,D 0 General Electric Co 80/06/20 App
- --8007250589 Forwards GA Program Insp Rept 99900398/80-01 on 800505-09 & notice of deviation PUTAPOVS.V Region 4, Dailas, Vendor Inspection Branch 80/05/22
- --B007250592 Notice of deviation from insp on B00505-09
 * Region 4. Dallas, Office of the Director 80/05/20 2pp
- ~-8007250594 On Program Insp Rept 9990039B/80-01 on B00505-07
 Nancompliance noted practices not consistent w/Criterion 5,
 App II to 10CFR50 & Section 1 4 Issue A of product design
 engineering manual
 HUNNICUTI.D M , FOBTER.W E Region 4, Dailas, Vendor Inspection
 Branch BENNETT.A II Region 4, Dallas. Office of the Director
 B0/05/20 9pp
- 8007280085 Forwards QA Program Insp Rept 97900519/80-01 on 800324-28 No noncompliance noted POTAPOVS, V Region 4, Dallas, Vendor Inspection Branch 80/04/29 2pp
- --B007280086 GA Program Insp Rept 99900519/60-01 on 800324-28 No noncompliance noted Major aleas inspected design insp, potential 10CFR21 items & action on previous insp findings BRICKLEY,R H. AQEE, JR. HALE.C J. Region 4, Dallas. Vendor Inspection Grench 80/04/24 21pp

- G007290030 Forwards Volgenau 780428 itr to Gore & SECY-79-4489.om;tted from V Steilo 800709 itr M/o encl PERANICH.H W Division of Reactor Construction Inspection 8040747 to
- 8007270307 Forwards OA Program insp Rept 99900404/80-01 on 800121-24 No monocompliance noted POTAPOVS.V Region 4. Dallas Vendor Inspection Branch 80/06/06
- --B007290321 GA Program Insp Rept 99900404/E0-01 on B00121-24 No noncompliance noted Major areas inspected review of procedures & controls adopted to implement requirements of 10trR21 ANDERSON.D G . BRICKLEY.R H . HALE.C J Region 4. Dallas, Vendor Inspection Branch 80/06/06 17pp
- 8007290327 Forwards GA Program Insp Rept 99700404/E0-02 on 800512-16 No noncompliance noted POTAPOVS V Region 4. Dallas, Vendor Inspection Branch 80/06/03 2pp
- --B007290337 GA Fragram Insp Rept 79900404/80-02 on 800312-16 No noncompliance noted Major areas inspected design corrective action: interfaces & inputs BRICKLEV,R H. AGEE. J. R. HALE, C. J. Region 4, Dallas, Vendor Inspection Branch B6/06/04 [opp
- B007290338 Ack receipt of B00508 & 0707 itrs informing NRC of steps taken to correct deviation noted in GA Program insp Rept 9990216/80-01 FGTAPQVS.U Region 4. Dallus, Vendor Inspection Branch 80/07/21
- ~-B007290368 Responds to NRC 800617 ltr re deviation noted in GA Program Insp Rept 99900216/80-01 Corrective actions Procedure N-306, available in draft form during insp.was completed & distributed to personnel involved KATZ.L Tubeco, Inc 80/07/07 2pp
- --8007290378 Ack receipt of 800508 itr informing NRC of steps taken to correct deviation noted in OA Program Insp Rept 97900216/80-01 Addl info requested re Item H POTAPOVS, U Region 4. Daljas, Vendor Inspection Branch 80/06/17 lp
- ~-BD07290392 Respands to NRC 800414 itr re deviation noted in GA Program Insp Rept 99900216/80-01 Corrective actions area of pipe attachment was ground to depth sufficient to remove possible contamination & examined by liquid pentiral GOLDSHITH.W Tubeco, Inc 80/05/08 15pp
- 8007290474 Ack receipt of 800415 & 0515 ltrs informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 97970035760-01 PCTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 80/06/06
- --B007290477 Responds to NRC 800429 itr re deviations noted in QA Program
 Insp Rept 99900355/80-01 Corrective actions QA manager
 assigned responsibility for effectiveness of personnel
 training & inductrination re callibr program requirements
 HIRATA.Y Hirata Valve Industry Co. Ltd., Kawashi Div SH-360
 80/05/15 ip
- --8007290481 Ack receipt of 800415 ltr in response to NRC 800222 ltr Requests addition reactions taken to assure effectiveness of personnel training & indoctrination re continued compliance w/calibr program POTAPOVS.U Region 4. Dallas. Vendor Inspection Dranch 80/04/29 lp
- --B007290487 Forwards response to NRC 800222 Itr re deviations noted in GA Program Into Rept 99900395/80-01 Corrective actions GA program for collect control procedure for targue wrenches has been revised HIRATA.* Hirata Valve Industry Co . Ltd . Kawaski Div SK-359 80/04/15 10pp
- --8007270492 Forwards GA Program Insp Rept 99900355/80-0! on 800121-25 & notice of deviation SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/22 2pp
- ----8007290497 Notice of deviation from insp on 800121-25 * Region 4. Dallas, Office of the Director 80/02/21 3pp

- --8007290504 GA Program Insp Rept 99900355/BO-01 on 800121-25
 Noncompliance nated revised welding procedure spec not
 submitted to customer for approval GA program not in
 accordance w/code requirements
 BARNES: I . HUNIZCUTT. D M Region 4. Dallas, Vendor Inspection
 Branch 80/02/21 13pp
- 8007270836 Forwards OA Program Insp Rept 99900316/80-01 on 800528-30 No noncompliance noted POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 80/06/11 2ap
- --8007270862 GA Program Insp Rept 99900316/80-01 on 800528-30 Major areas inspected action on previous findings, nonconformances & corrective action, training, records & procurement controls GLERR E. POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch 80/06/12 7pp
- B007300173 Ack receipt of 800516 & 0709 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900712/80-01 P0TAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/07/17 lb
- -- 8007300178 Responds to NRC 800611 ltr re deviation noted in QA Program Insp Rept 99900712/80-01 Corrective actions internal audit forms revised to include all depts Certified matl test repts obtained for 10 spools of wold wire in question CAPRA.L A Systems Control, Inc. 80/07/09 6pp
- -- Goorgooid2 Ack receipt of Goosia ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 9900712/EO-OI Requests addl info re actions taken to prevent exclusion of any dept from twice yearly audits, POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch Go/O6/11
- --80073001BB Responds to NRC 800414 ltr re deviations noted in QA Program Insp Rept 99900712/80-01 Corrective actions all certification on welding matis shall be obtained prior to releasing to shop Current drawing policy is being revised CAPRAL A Systems Control, Inc 80/05/16 2pp
- --8007300192 Forwards GA Program Insp Rept 99700712/80-01 on 600325-26 th notice of deviation FOTAPOVS.U Region 4, Dallas. Vendor Inspection Branch 60/04/14 2pp
- --8007300194 Notice of deviation from insp on 800025-26 Region 4. Dallas. Office of the Director 80/04/11 4pp
- --8007300198 QA Program Insp Rept 99900712/80-01 on 800325-26
 Noncompliance noted failure to conduct internal audits of
 all dests & to have available certifications for weld wire
 issued to shop
 ELLERSHAW.L E . HUNNICUTT.D M Region 4, Dallas, Vendor Inspection
 Branch 80/04/11 ijpp
- 6007300308 Ack receipt of 800709 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900214/80-01 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 60/07/21
- --8007300315 Provides followup to 800509 itr re deviation noted in GA Program Insp Rept 99900214/80-01 Forwards quality procedure directives re training program for nuclear product quality & visual insp of welds
 DONEOAN, G C Anderson-Greenwood & Co 80/07/09 13pp
- B007300310 Forwards GA Program Insp Rept 99900209/80-01 on B00506-09 No noncompliance noted POTAPOVS, U Region 4, Dallas. Vendor Inspection Branch 80/06/04 2pp
- --8007300314 QA Program Insp Rept 99900209/80-01 on 800806-09 Major areas inspected previous insp findings & identified problem areas ELLERSHAHLE : POTAPOVB. U Region 4, Dallas, Vendor Inspection Branch 80/06/04 App
- 8007310174 Ack receipt of 800219 & 0425 itrs informing NRC of steps taken to correct deviation noted in GA Program Inep Rept 99700039/79-02 FOTAPDVS.U Region 4. Dallas, Vendor Inspection Branch. 80/06/10

1

- --8007310179 Responds to NRC BOU324 ltr re deviation noted in QA Program
 Insp Rept 99900039779-02 Corrective actions error in sketch
 requirement was result of human croor, corrective actions not
 possible QA manual modified
 GLUIS, B. J. VAN DE POLL H N. Rhine-Scholde-Verolmo Zware
 Apparetenbouw KD 80019 80/04/25 2pp
- --B007310176 Ack receipt of B00219 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900039/79-02 Requests addl info PUTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/03/24
- --B007310182 Responds to NRC 800114 ltr re deviation noted in GA Program Insp Rept 99900039/79-02 Corrective actions missing revision numbers on master travelers folled in & design review of stress repts will be conducted 1.0DDER, M Rhine-Schelde-Verolme Zware Apparatenbouw KD 80013 80/02/19 App
- --B007310188 Forwards GA Program lnsp Rept 99900039/79-02 on 791105-08 & notice of deviation POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/01/14
- ---B007310189 Notice of deviation from inap on 791105-08 * Region 4, Dallas, Office of the Director 80/01/11 2pp
- --B007310195 GA Program Insp Rept 99900039/79-02 on 791105-08
 Noncompliance noted failure to include process spec revision
 number on master traveler & incorrect definition of test
 specimen depth from forging surface recorded
 BARNES, I . POTAPOVS, U . HUNNICUTT, D M Region 4, Dallas, Vendor
 Inspection Branch 80/01/11 10pp

RECOD REGULATORY GUIDES

r

- 7909210176 Comments on proposed revision to Reg Quides 5 7,5 14,5 44 & 5 37 one person adequate as observer of officialing & opening of matis & packages as long as second employee present Specified calibr stds should be permitted NILSON,R Exton Nuclear Co , Inc (subs of Exxon Corp) 79/08/02 200
- 800701030B Forwards FR notice of issuance & availability of draft reg guide. "Instruction Concerning Risk From Occupational Radiation Exposure " Requests publication at earliest passible date CHILK, S J Diffice of the Secretary of the Commission 80/05/22
- B007020i18 Comments on Reg Guide i 125, "Physical Models for Design & Operation of Hydraulic Structures & Sys for Nuclear Power Plants" portions exist which applicants may not be able to follow LEX.B L Bechtel Power Corp (subs of Bechtel Corp) 77/09/30 in
- BOO7090375 Comments on proposed Reg Guide B XX guide would be valuable assist to operating personnel Minor reorganization would improve usefulness Presentation as currently organized may scare potential worker off before understanding situation MAMPBON.D C Oak Ridge National Laboratory 807/06/11 1p
- 8007090398 Comments on proposed Reg Guide 8 XX dissemination of info should be considered prior to employment, to minimize difficulties of Question 31 Same program to inform local citizens would be appropriate for guide NELSON, R R Firex Corp 80/06/11 ip
- 9007090400 Comments on proposed Reg Guide B XX statement that estimates of radiation risks are as rellable as estimates from any other important hazard is patently false People should be made aware of different views of highly qualified experts CHILDERS, B Affiliation Unknown 80/05/29 lp
- B007090408 Forwards rept commenting on proposed Reg Quide i 97 Comments by students do not represent opinion of faculty Increasing amount of info reactor operator must know during accident is not beneficial Computers should be considered SAVAGE,M R , MILLER,D W Ohio State Univ 80/03/09 159pp
- 8007090413 Comments on proposed Reg Guide 8 14 response of Trac? Etch devices should be determined in environ where used Power reactor health personnel should be required to make spectra measurements & calculate response of survey meter RYAN.R M Rensselaer Polytechnic Inst 80/06/02 2pp

- 9007090416 Comments on proportd Ring Guide 8 XX NRC has obligation to present confroversy on both sides relies estimates Info is presently stated in one-sided manner Guide is necessary step in right direction EVDOXIMOFF, V N Boston Univ Medical Center Boston, MA 80/06/10 ip
- 800709041B Comments on proposed Reg Guide B XX mention of genetic effects should be deleted since data shows no effect & Fear serves no useful purpose Risk instructions seem unnecessary when patients are not advised during i-ray procedures CORNELL.D A Principla College 80/06/03 ip
- 8007100053 Comments on proposed Reg Guide 8 XX NRC regulation of 40 mps-hr/wk is legal requirement that bears no relationship to dose received for most radionuclides HEALY, J W. Los Alamos Scientific Laboratory HH-32 80/06/04 2pp
- 8007100101 Comments on proposed Reg Guide 8 XX sufficient emphasis should be put on fact that levels of exposure resulting in detectable effects are higher by orders of magnitude, than doses allowed by current regulation or actually received BAYNARD FY Florida Power Corp 80/06/i1 2pp
- 8007100113 Comments on proposed Reg Guide 8 XX some discussion on public perception of risk should be incorporated People need to be shown that perception of nuclear risk is greater than threat
 FORD.C H Reuter-Stokes. Inc 80/06/10 2pp
- 8007100116 Comments on proposed Reg Guide 8 XX cigarette smoke & natural radiation are lumped together as cancer causes, implying relatively equal magnitude Such statements are misleading & detract from realistic evaluation of risk TUMA:A T Popular Bluff Hosp Popular Bluff:MD 80/06/03 2pp
- 8007100122 Comments on proposed Reg Guide 8 XX word "generally" should be added to Question 14 Evidence exists to support hady repair especially at low levels of exposure & for large numbers of people exposed DRASTER.J J Affiliation Unknown 80/06/03 10pp
- 8007100127 Comments on proposed Reg Guide B XX guide fills vital need of supplying sober-accurate % Comparative data re misks of life work Reasonable charge to users would not be out of line Highly recommends policy LUND,R R Memorial Hosp of Natrona County Casper,WY B0/05/10
- BOD7100133 Comments on proposed Reg Guide B XX prudence of zero threshold should be presented auoner w/some explanation of controversy about assumption Argument presented on medical vs occupational exposure dilemma is weak FRIES.B A Chovron Research Cu 80/06/17 ip
- 8007100135 Comments on proposed Reg Guide 8 XX Question 24, Answer(C), should be eliminated entirely Effect of paragraph will be to touch off another series of attempts to force woman out of nuclear industry
 WEGNER, M 8 General Electric Co 80/06/03 3pp
- B007100137 Comments on proposed Reg Guide 8 XX extending analysis to future generations may result in substantial long-range damage Question 4 should draw distinction between procreating & nonprocreating workers

 MRAMER.P 8 Hilliams College, Massachusetts 80/06/11 2pp
- 8007100170 Forwards comments on proposed Reg Guide 8 XX clearly written & superior to instruction classes on radiation effects Bibliographic data should be given for "independent study " BOELDT,E J Affiliation Unknown 80/06/17 App
- 8007100181 Comments on proposed Reg Guide 8 XX total body radiation should never occur other than for that done by chiropracters, etc Presentation should be reversed to prevent individuals becoming overly frightened HENRY.G W Affiliation Unknown 80/05/79 2pp
- B007100196 Comments on proposed Reg Guide B XX instructional sharts will be very helpful in trying to explain risks of radiation to personnel Table 2 is especially valuable in relating risks to other necessary things in 16°e BERKEBILE.R D Elyria Memorial Hosp Elyria.OH 80/06/12 ip
- 8007100386 Comments on proposed Revision i to Reg Guide i 13i in implementation of ongoing qualification programs environ conditions of cables that will be used for subsequent tests should be monitored & documented BASKIN, K P Southern California Edison Co 80/05/30 2pp

- EDO7100416 Comments on proposed Reg Guide B XX good attempt to instruct occupational radiation workers, but entire field of medical occupational radiation exposure has not been addressed properly RANDALL H G of Elizabeth Hosp Appleton. WI NRC 80/05/27 1p
- 8007100425 Comments on proposed Reg Guide 8 XX guide should mention that NRC licensees presently are not required to provide neutron dosimeters for workers 5 that mai dose does not reflect exposure which worker may also experience DREV.L A Affiliation Unknown 80/05/30 lp
- BOO7100427 Comments by Rio Algom Corp.Lisbon Mine.on proposed Reg Guide B XX info is greatly needed not only for workmen but general public Supports NRC in introducing info in form of reg guide LAHTON.M D Affiliation Unknown 80/06/02 2pp
- BOO7100434 Comments on proposed Reg Guide B XX draft is well written, concise & comprehensive enough for general instruction of radiation workers Should include difference in effects of whole-body or critical origin dose & partial body dose GRANLUND, R W Pennsylvanio State Univ BO/06/04 ip
- 8007140475 Comments on proposed Reg Guide 8 XX to eliminate wide-spread irrational fear on part of public:info re nuclear sys & policies should be disseminated CHAPIN.D Saithsunian Institute 80/06/12 2pp
- BOO7140483 Comments on proposed reg guide, "Instruction Concerning Risk from Occupational Radiation Exposure " Population base in Tables 2 & 3 does not include estimated number of days of lost life expectance."

 CEMBER, H Northwestern Univ 80/06/26 ip
- BOO7140572 Comments on possible use of util load dispatch microwave links to insure communication between NRC & plant & role of Reg Guide i 97 in determining safety vector IE developing list of util load dispatcher telephone numbers DENTONIA R Défice of Nuclear Reactor Regulation. Director BQ/07/01 2pp
- --B007i40578 Draft specs. "Functional Requirement for Safety Parameter Display Technical Support Ctr Emergency Offsite Facility Kuclear Data Line " • Commission 80/06/09 30pp
- 8007j40586 Comments on proposed Reg Guide 4 14.Revision 1 introduction needs clarification Respondent does not understand what kind of environ impact NRC expects after decommissioning at U mills HASHIMOTO, K Affiliation Unknown 80/06/07 ip
- 8007150085 Comments on Reg Guide 1 97.Revision 2 original choice of fission chamber was prodent 8F3 & 810 detectors inadequate for measuring neutron sensitivity LINGREN.C L Affiliation Voknown 80/06/21 2pp
- BOO7150153 Comments on proposed Reg Quide 4 14.Revision i NRC a priori assumptions that radiation protection programs designed for man are adequate for wildlife are unfounded Proposes measures to monitor wildlife DANIELSON, L. J. National Wildlife Federation 80/06/18 5pp
- BOO7150159 Comments on proposed Reg Quide 4 14,Revision 1 environ data units should be appropriate for control level ref, efficient & environ monitoring data should be appraised & drinking water monitoring requirements are unresonable MOONEY.R R. PETERSON,D S Washington, State of 80/06/24 2pp
- 8007150342 Comments on draft reg guide, "Instructions Concerning Risk from Occupational Radiation Exposure" Question & answer format unsatisfactory More complete presentation could be made in shorter test by avoiding leading questions

 BLA88CK:L A Defense, Dept of. Defense Nuclear Agency 80/06/17
 5pp.
- 8007160446 Comments on proposed Reg Guide 7 XX. "Measurement of Radiation Levels on Surfaces of Packages of Radioactive Hatis." Surface dose rate should be redefined as that when griger tube of survey meter touches package surface FRIES B A Catalytic, Inc. (subs. of Air Products & Chemicals, Inc.) 80/06/13 2pp
- 8007160778 Comment» on proposed Reg Guide 1 08 re selection & training of nuclear plant personnel qualifications needed in plant personnel underestimated Operators should meet airline pilot level requirements

 WILLIS.C A Philippines 79/06/11 1p

- B007160805 Offers no comments on Reg Guide 4 16. "Effluent Monstoring at Nuclear Fuel Processing & Fabrication Plants." in response to 800522 meno KNIGHTON Q W Research & Standards Coordination Branch #0/06/19
- --8007160814 Summary of 800528 meeting w/C~E owners group in Dethesda.KD re tradequate core cooling List of attendees & viewgraphs encl PHILL2PB.L E Core Performance Branch 80/06/23 31pp
- 8007180174 Responds to request for concurrence re Reg Ouide 1 141, Revision 1. "Containment Isolation Provisions for Fluid Sys " Regulatory position section of guide satisfactory Should not designate implementation on case-by-case basis DENTON.HR OFfice of Nuclear Reactor Regulation, Director 80/07/03 4pp
- --B007180179 Responds to WM Morrison 800417 memo re Reg Guide 1 141.
 "Containment Isolation Provisions for Fluid Bys " Approval
 w/comments recommended Guide should be updated to reflect
 latest version of AN917ANS 56 2 when available
 BUTLER.W R Containment Systems Branch 60/05/08 2pp
- 8007180175 Comments on proposed Revision 1 to Reg Quide 8 12 concurs w/ guide position that dosimetry requirements can generally be met by quick screening techniques SHITH.DR Los Alamos Scientific Laboratory Q-14-18-CB-76, 80/06/19 2pp
- 8007180230 Comments on proposed Reg Quide B XX, "Instructions re Risk from Occupational Radiation Exposure" Approach to risk snalysis & training fails in its mission to educate Identifies style, content, emphasis & syntax problems ANDREMS. J P. Catalytic, Inc. (subs of Air Products & Chemicals, Inc.) 80/06/19 4pp
- 8007240475 Comments on fire protection Reg Guide 1 120 excess automation may present haiards greater than fire Flooding & collapse of trays may be serious. Mater resistance of aged dry cables unknown EBERBULE. J C ACRS Advisory Committee on Reactor Bafeguards 74/08/16 2pp
- 8007250060 Responds to B00701 request for clarification re use of Level I personnel to perform direct inspa Level I personnel may perform tests using approved procedures Level II personnel can evaluate & rept test results NAASS.W P Guality Assurance Branch B0/07/16 ip
- B007280039 Comments on proposed rul# iOCFR30 NRC is hampered because original rule did not concentrate on dedicated remote shutdown copability as solution to fire risk Schedule for completion may be unrealistic CARKEY...) J. American Nuclear Insurers 45FR36082 040 80/06/30
- --B007280067 Comments on draft reg guide, "Qualification Test for Gable Penetration Fire Stops for Use in Nuclear Power Plants " Worst case for generic acceptance is valid method BANYER,R G . BDRNHOEFT,W H American Nuclear Insurers 79/08/30
- B007310120 Notice of issuance & availability of Revision 1 to Reg Ouide 5 57. "Shipping & Receiving Control of Strategic BNM." incorporating recent changes to Commission physical protection regulations
 SMITH.R 0 Office of Standards Development, Director, 80/07/08
- RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- BD05130445 "LWR Thermal Hydraulic Development Program." munthly highlight ltr for Feb 1980 JONES, D C Brookhaven National Laboratory FIN A-3045 B0/02/29 6pp
- 80070200ii "Nuclear Power Plant Design Concepts for Babotage Protection," fifth quarterly progress rept.Apr-June 1979 ERICSON:D M Sandia Laboratories FIN A-1210 79/08/20 11pp
- 8007020016 "Experimental Criticality Data for Code Validation." informal monthly progress rept for May 1980 BIERNANS R Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2094 80/06/02 3pp

- B0070200B5 "Vapor Source Distribution Electrically Heated Vol-Boiling Bys." to be presented at B00813-15 ASME Century 2 meeting sympoxium on polyphase flow & transport technology OlMSBERG. T Brookhaven National Laboratory BNL-NUREG-27461 B0/05/15 12pp
- 8007020356 "Safeguards Analysis for Byproduct Maths & Small Quantities of SNN," monthly progress rept Mar 1980 CHESTER,R D , KANAK,K K , RANDLPH.M L Dak Ridge National Laboratory FIN B-6108 DRNL/HASRD-75 80/04/14 6pp
- 8307020364 "Shutdown Heat Removal Sys Reliability in Thermal Reactors " SUN,Y H. BARI.R A Strockhaven National Laboratory BNL-NURE0-27595 80/06/30 8pp
- BQ07030015 "Code Assessment & Applications Program Piping Sys Stress Dependent Damping Study " ORUBB.R L EG&G idaho.lnc FIN A-6156 79/10/31 20pp
- BCO7110148 "Physical Protection of Nuclear Facilities," monthly progress rept for May 1980 CHAPMAN.L D Sandia Laboratories FIN A-1060 80/06/18 6pp
- B007:10551 "Sandia Core Melt & Separate Effects Program," monthly ltr for May 1980 BERMAN,M Sandia Laboratories B0/06/23 Bpp
- BO07140031 "Evaluation of Docket Films of Terminated Licenses," monthly progress rept for May 1980 HDLGMAY.C F. DICKSON.H W Oak Ridge National Laboratory FIN A-9085-7 CRNL/HASRD-81 BO/05/31 18pp
- BO07140044 "Safeguards Analysis for Byproduct Matls & Small Quantities of BNN," monthly progress rept for May 1980 CHESTER:R O , KANAK, K & RANDOLPH.M L Oak Ridge National Laboratory FIN B-6108 ORNL/HASRD-82 B0/06/11 App
- BO07140503 "Environ Statements Project," monthly progress rept for May 1980 ZITTEL.H E Oak Ridge National Laboratory FIN 8-0001 ORNL/ED/E15-131 80/05/31 5pp
- B007140507 "Div of Reactor Safety Research ORNL Programs." May 1980 wonthly highlights
 MYNATT.FR Oak Ridge National Laboratory 80/06/10 36pp
- B007140634 "Technology & Costs of Termination Surveys Associated W/Decommissioning Nuclear Facilities," monthly progress rept for May 1980
 DICKBON.H W , HOLDHAY.C F Dak Ridge National Laboratory FIN A-9042 ORNL/HASRD-83 80/05/31 5pp
- 8007140642 "Investigation of Post-CHF Heat Transfer for Water-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation." monthly progress rept for May 1780 CHEN.J C., SUNDARM, R. K., NIJHAWAN, S. Lehigh Univ. FIN A-4055 NRC-04-74-180 80706/17 App
- B007190016 "Advanced Instrumentation for Reflood Studies," foreign trip rept HERSKOUITZ,M B , MCCOLLOUGH,N D , ROBERTS,M J Oak Ridge National Laboratory FIN 8-0413 ORNL/FTR-850 80/06/05 7pp
- 8007190059 "Licensing Audit Calculation (LACE) Models in FRAP-T4 Code Description & Developmental Assessment," interim rept for Apr 1980 BOHN, M P , BIEFKEN, L J , LOATS, E T EG&O Idaho, Inc FIN A-6050 EGG-CDAP-5144 80/04/30 202pp
- 8007150066 89007150066
 "Effect of Dispersed Condensed Phase on Rayleigh-Taylor
 Instability of Gas-Liquid Interface." informal rept,
 Har 1980
 HGSZYNSKI,J R. GINSBERG,T Brookhaven National Laboratory FIN
 A-3024 80/03/31 41pp
- BOO7150407 "BHR Blowdown/ECC Program Fifty-Fifth Monthly Progress
 Repts" May 1980
 BURNETTE, 0 W General Electric Co NRC-04-76-215 80/05/31 92pp
- 8007160280 Progress Rept 28 for Apr 1980 re value/impact statement for dosimetry testing program PLATO,P Michigan, Univ of NRC-01-77-180 80/04/30 8pp

- 8007170460 "Investigation of Post-CHF Heat Transfer for Water-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation." monthly progress cepts for Mar-Apr 1980 CHEN.) C. SUNDARAM. R. y. NIJHAWAN, S. Lehigh Univ. FIN A-4055 NRC-04-74-180 80/04/22 /pp
- 800717064B "Environ Assessments of Fuel Cycle Facilities," monthly progress rept
 ZITTEL.H E Oak Ridge National Laboratory FIN B-0279
 ORNL/ED/E18-130 80/05/31 App
- 8007180233 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for May 1980 BULISCHECK.T. VAN RODYEN.D Brookhaven National Laboratory FIN A-3208 80/06/17 6pp
- 8007180240 "HTGR Safety Program." monthly highlights for Hay 1980 BASTRE, C Brookhaven National Laboratory FIN A-3016 80/06/07
- 8007180245 "TRAC Assessment & Model Development," monthly highlights for May 1980 8AHA,P Brookhaven National Laboratury FIN A-3215 80/05/31
- 8007180253 "Thermal Reactor Safety Code Development," monthly highlights for May 1980 LEVINE,M.M. Brookhaven National Leboratory FfN A-3014 80/05/31
- 8007180330 "Mathematical Simulation of Sediment & Contaminant Transport in Surface Woters," quarterly rept for Oct-Dec 1979 * Battelle Memorial Institute, Pacific Northwest Laboratory P3N B-8271 79/12/31 26pp
- 8007180352 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Apr 1980 HDLDMAY,C F. DICKSON,H W. Oak Ridge National Laboratory FIN A-9085-7 ORNL/HASRD-77 80/04/30 15pp
- 8007180354 "Forerasting Electricity Domand by State & by Util Svc Area." progress rept for May 1980 CHERN.W S Gak Ridge National Laboratory FIN B-0190-8 DRNL/ED/EAS-807 80/06/11 7pp
- 8007180351 "LWR Thermal Hydraulir Development Program." monthly highlight ltr for May 1980 ABUAF.N Brookhaven Nationel Laboratory FIN A-3045 80/05/31 7pp
- 8007210001 "Mathematical Simulation Sediment & Containment Transport in Surface Waters." quarterly rept for Jan-Mer 1980 # Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2271 80/03/31 34pp
- B007210003 "SEC Code Development & Validation." monthly highlight ltr for June 1980 AGRAMALA K. GUPPY.J P Bronkhaven National Laboratory F1N A-3015 80/06/13 7pp
- BOO7210005 "NRC Nuclear Waste Mgt Technical Support in Development of Nuclear Waste Form Criteria," interim rept for May 1980 CZYBCINSKI,K S , SHYLER,K J , K.AMUT,C J Brookhaven National Laboratory FIN A-3158 BD/05/31 95pp
- 8007210007 "NRC Nuclear Waste Mpt Technical Support in Development of Nuclear Waste Form Criteria." Interim rept for Apr 1980 BIDA: 0. DAVIS: R F. MACKENZIF, D R. Brockhaven National Laboratory FIN A-3158 80/04/30 9App
- 8007210010 "Evaluation of LVR Residual Heat Removal Under Accident Conditions," monthly highlights for May 1980 BARI,R A Broukhaven National Laboratory FIN A-3315 80/06/03
- 8007210014 "Thermal Hydraulic LMFBR Bafety Experiments," monthly highlight itr for May 1980 GINBBERG, T Brookhaven National Leboratory FIN A-3024 80/05/31
- 8007210017 "LOFT Program Division: " pretest prediction rept for June 1980 KESE J., TAYLUR,O A. CONDIE.K G. FOSG. Inc. FIN A-6048 EGG-LOFT-5172 80/06/30 Bipp
- 8007210602 "LHR In-Plant Measurement Program." informal monthly progress rept for May 1980 MANDLER, J H EGEQ. Inc FIN A-60/5 80/06/24 4pp

- 8007210607 "Investigation of Ventilation Component Response to Large Pressure Pulsee." informal monthly progress rept for May 1980
 - 1980 GREOORY, W.S. Los Alamos Scientific Laboratory FIN A-7028 80/06/27 3pp
- 8007220045 "LOFT Program Div." quick-look rept on LOFT Nuclear Experiment L2-7 MCCREENY.8 E EG&G idaho, Inc FIN A-5048 EGG-LGFT-5192 80/06/20 Adm
- 8007220047 "Methods for Determination of Inorganic Constituents in Yrench Leachates from Shallow Land Radwaste Disposal Sites," informal rept GARSER, St. Brookhaven National Laboratory FIN 3042 BNL-NUREO-27591 80/03/31 55pp
- BOO7220053 "Stress Corrosion Cracking of Alloy 600 Using Constant Strain Rate Test." informal rept for Mar 1980 BULISCHECK.TS., VAN ROOYEN, D. Brookhaven National Laboratory BNL-NUREG-27759 60/03/31 24pp
- 8007220058 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels." monthly progress rept for May-June 1980 HUJTON/PH Battelle Nemorial Institute, Pacific Northwest Laboratory FIN 8-2088 80/07/07 35pp
- 8007220065 "FRIDA Computer Code for Dynamic Longitudinal Response of Fuel Rods Subjected to Thermal Translants," interim rept 81NCH.J N : BOHN,M P , ENGELMAN,O P EG&O Idaho,Inc FIN A-6050 EGG-CDAP-3173 BO/06/20 66pp
- 8007230177 "LOFT Monthly Progress Rept for Apr 1980 "
 KAUFHAN, N C FOLG Idaho, Inc &D-MR-006 80/05/31 116pp
- 8007230185 "LOFT Small Break Test Thermocouple Installation "FORS.R M EGEO Idaho, Inc RE-A-80-044 80/05/28 12pp
- 8007230194 "Stress Analysis of Modified Pulsed Neutron Activation Sys Downstream Shield Support Structure " MUSBY,W R E060 Idaho,Inc RE-A-80-047 80/05/28 48pp
- 8007230223 "Site Visits to Eight Major Dosimetry Processors " PLATO,P . HUDSON.G Michigan. Univ of 79/05/31 App
- B007230231 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incapient Cracking of Bypass Lines & Pipes in BMR Piping Bys," Progress Rept & for B00524-0420 * Daedalean Associates, Inc. NRC-04-78-242 80/07/31 Bpp
- 8007240257 "Water Reactor Research Directorate Monthly Rept for May 1980 "
- * Idaho National Engineering Laboratory 60/06/30 187pp
- 8007240294 "Advanced Reactor Bafety Analysis Technical Assistance, Reactor Projects," monthly highlights for May 1980 BARI,R A Brothaven National Laboratory FIN A-2000 80/06/05 4pp
- 8007280002 "Accident Aeroso) Characterization." Informal monthly progress report for June 1980 ONZARSKI P C Battelle Nemorial Institute, Pacific Northwest Laboratory FIN 8-2287 BD/07/15 4pp
- 8007280004 "Shipping Cask Sabotage Bource Term Investigation," informal monthly progress rept for Juno 1980 SCHMIDI, E W Dattelle Memorial Institute, Columbus Laboratories FIN B-6012 80/07/07 10pp
- 8007280081 "Sandia Core Melt & Beparate Effects Program," monthly progress ltr for June 1980 BERMAN.H Sandia Laboratories 4441/HL~13 80/07/10 7ap
- 8007280092 "Operational Aids for Reactor Operators." foreign trip rept K16NEA.R A Dak Radge National Laboratory FIN B-0436-9 ORNL/FTR-859 80/06/16 17pp
- 8007280095 "Dusimetry & Biotransport Models to Implement ALARA." quarterly progress rept Apr-June 1980 KOCHER, D C , KODMELL-BOYER, RYAN.M T Dak Ridys National Laboratory FIN 8-0168 ORNL/HASRD-84 80/06/(10 5pp
- 8007280144 "PBF LOC-58 Test Experiment Safety Analysis "
 00SSMANN.6 R EGRG Idaho, Inc FIN A-6041 EGG-TFCP-5043
 79/11/30 40pp

- 8007280171 "LOFT Monthly Progress Rept for May 1980 "
 KAUFMAN, N C EG&O Idaho, Inc LO-MR-007 80/06/30 114pp
- BOO72B0174 "Modular Drag Dist Turbine Qualification Tests " FLITTON, V E EG&O Idaho, Inc LTR 141-109 BO/06/06 14pp
- B00728017B "TRAC-PIA Calculations for 2007 Hot Leg Break & 200% Hot Leg Break Simultaneous W/Rupture of 14 Steam Generator Tubes in PWR "
- IN TWA "
 SQLANDER, M A EG&G Idaho, Int FIN A-6047 EGG-CAAP-5191
 80/06/30 74pm
- B007280186 "TRAC-PIA Calculations for 200% O 25 Meter Diameter & O 10 Meter Diameter Cold Leg Break in PWR "
 HHCATLEY,P D . BDLANDER,M A EG&G Idaho,Inc FIN A-6047
 EGG-CAAP-5190 B0706/30 90pp
- BOO7290174 "PBF TC-1 Test Experiment Safety Analysis" GOSSMANN:S R Energy Dept of, Idaho Operations Office FIN A-6041 EGG-TFBP-TR-502 79/10/31 35pp
- 6007290180 "Experimental Data Rept for Transient Flow Calibr Facility Tests 11B101, 11B102, & 11B201 " WAMBACH, J. L. E0&G ldaho, Inc. USNRC-P394 80/06/17 97pp
- 8007270191 "Measurement of Velocity Vectors in Two-Phase Flows Using Five Hole Stagnation Probe " DEASON.V A . FINCKE, J R EG&G Idaho, Inc USNRC-P394 80/06/06 340*
- 8007270201 "PBF PR-1 Test Experiment Safety Analysis " GGSSHANN.8 R EG&G Idaho.Inc FIN A-6041 EGG-7FBP-5080, 80/01/31 22pp
- 6007290226 "Calculations of Large Cold Leg Break W/Steam Generator Tube Ruptures in PMR using TRAC-PIA Computer Program," preliminary assessment rept LARSON.J R E08:0 Idaho.lnc FIN A-6047 E00-CAAP-5189 80/06/30, 930p
- 8007290233 "Physical Protection of Nuclear Facilities," monthly progress rept for June 1980 CHAPMAN.L D. Bandia Laboratories FIN A-1060 80/07/09 App
- 8007270241 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities," monthly progress rept for June 1980 FREDERICK, E.J. Oak Ridge National Laboratory FIN B-0425 80/07/14 App
- 8007290246 "Decontamination as Presursor to Decommissioning," monthly progress rept for June 1980
 PERRIGD,L D Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN B-2303 80/07/07 3pp
- H007310181 "Shipping Cask Sabotage Spurce Term Investigation," informal monthly progress rept for Hay 1980 BCHMIDT.E W Battelle Memorial Institute, Columbus Laboratories FIN B-6012 80/06/10 17pp
- 8007310183 "Shipping Cask Sebotage Source Term Investigation," informal monthly progress rapt for Apr 1980 SCHNIDT.E H Battelle Memorial Institute, Columbus Laboratories FIN N-6012 80/05/13 4pp
- S007310187 "Experimental Criticality Data for Code Validation," informal monthly progress rept for June 1980 BIERNAN, S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN G-2074 80/07/03 3pp
- 8007310R51 "Technology & Costs of Termination Surveys Associated W/ Decommissioning Nuclear Facilities." monthly progress rept for June 1980 DICKSON,H W. HOLOWAY,C F. Dak Ridge National Laboratory FIN A-7042 ORNL/MASRD-86

REVIEW ORP NRC RESEARCH REVIEW GROUPS

8007220041 Forwards graphs & executive summary from five recent fire suppression tests discussed within review group Objectave was to obtain fully developed cable tray fire in donor cable tray Add tests under consideration w/Halon FEIT,R Division of Reactor Safety Research 80/07/07 7pp

POSITION PAPERS BEFORE THE COMMISSION SECY

8007010589 Transcript of 800624 public meeting in Washington, DC to discuss ABLB rept on clearance rule Pp 1-49 L Bickwit 791109 memo to Commissioners encl

* Commission 80/06/24 67pp

BOO702024B SECY-79-371A
Informs Commission of current status of activities in Ofc
for Analysis & Evaluation of Operational Data Mission
statement.personnel assignments.task action plan description
& status of selected activities encl
HELTEMES.C J Director's Office 79/11/21 8pp

B007020262 SECY-R-74-132

00702022 SECY-R-74-132
Discusses formation of regulatory requirements review committee Program for controlling ratcheting, charter for regulatory requirements review committee & press announcement encl
MUNTZING, L M Atomic Energy Commission 74/03/05 19pp

B007020270 SECY-R-74-095

NO/20270 SECY-R-74-095
Discusses regulatory program for minimizing & controlling ratcheting Ratcheting can be minimized & controlled but no completely eliminated Program will make ratcheting part of licensing process Program encl
MUNTZING.L M Atomic Energy Commission 73/12/19 12pp

8007070598 SECY-80-153

DOVO/1076 BELY-EU-153 Forwards traft FR notice of proposed rulemaking re revision of reactor siting criteria & draft itrs to PIRG & Congress Recommends approval MINDOUE.R B Office of Standards Development, Director 80/03/19 3600

8007080036 SECY-75-429

DIVIDUOID DECY-79-429
Discusses procedure by which NRC can determine whether matters of alleged or suspected criminal violations of law should be referred to DOJ Recommends that Inspector & Auditor Ofc accept full responsibility SHAPAR.H K. Office of the Executive Legal Director 75/08/11 3pp

B007090015 SECY-B0-275
Discusses finalization of emergency planning rule changes, including consideration of public comments Recommends FR publication re final rulemaking Related documentation encl MINGGUE, R B Office of Standards Development, Director

--8007090017 NUREG-0685

DOFOTOUR NAMES—Good Draft Environ Assessment for Effective Changes to 10CFR30 & App E of 10CFR30; Emergency Planning Requirements for Nuclear Power Plants "Related documentation enci OTT-WR Division of Biting, Health & Bafoguards Standards 80/06/30 54pp

--8007090019 Concurs in proposed final rule on emergency planning, pending resolution of IE comments Resource impact on NRC for full implementation of rule must be addressed in Commission Paper STELLO.V Office of Inspection & Enforcement, Office of the Director BO/05/14 1p

--B007090021 Concurs in sending revised emergency preparedness rule to Commissioners Bupplementary Info section should contain add1 info on technical justification for i5-minute notification requirement DENTON.H R Office of Nuclear Reactor Regulation, Director H0/05/16 1p

--8007090023 Concurs in final rulemaking on emergency preparedness
Sequirements for implementation of federal state & local
govt exercises apply to nuclear reactors & not to operations
licensed by NMSS
DIRCKS-N J Office of Nuclear Material Safety & Safeguards
B0/05/19 19

--8007090025 Supports final rule on emergency planning NRC final rule is consistent w/proposed FEMA procedures for review of state emergency plans JETT-0 Federal Emergency Management Agency 80/06/02 ip

8007090028 Transcript of 800516 open Affirmation Session 80-23 in Washington, DC re order in Tarapur export Pp 1-3 + Commission 80/05/16 4pp

--- 8007090030 Informs of correction to SECY-80-208 re proposed exports of fuel & components to Tarapur Commission SECY papers cited are incorrectly referenced Inset memor andom & order encl BHEAJR Office of International Programs, Director 80/05/13

--8007090033 SECV-80-238A 00/094031 St.Creuradem Forwards NNSS technical review for Commission's consideration in conjunction w/review of pending Tarapur fuel & component ejports SHEA.J R Office of International Programs, Director 80/05/13

--800709003B Forwards proposed NMSS technical review for Commission consideration re-proposed exports of fuel & companents to BURNETT, R F Division of Safeguards 80/05/12

8007100098 SECY-79-299
Informs Commission of results of NRC study of generic financial qualifications issue & requests decision on encl proposed rulemaking Recommends approval of Alternative i c & publication of proposed rulemaking in FR DENTONIH R Office of Nuclear Reactor Regulation, Director DENTON, H R 79/04/27 84pp

8007100264 SECY-80-171
Requests Commission comments on proposed legislation to establish state planning council on radwaste mgt Major changes proposed by DOE would give council budgetary & spending authority Recommends sending encl ltr to DOE STAIBER.C R Dffice of the General Counsel 80/03/31

8007110484 SECY-80-1078

Provides balance of addl info requested re proposed interim hydrogen control requirements for small containments Advisable to require inerting of all Mark I & Mark II containments pending rulemaking proceeding DENTON.HR Office of Nuclear Reactor Regulation, Director 80/04/20 7pp

--B007110487 Forwards summary of Probabilistic Analysis Staff views on value of inerting to overall risk reduction based on 791003 presentation before ACRS Subcommittee on TMI-2 Inerting has small value in terms of overall risk reduction BERNERO,R M Probabilistic Analysis Branch (Pre 791030) 10pp 80/06/10

--8007110495 Discusses Reliability & Risk Assessment Branch evaluation of relative impact of inerting Mark I containments from overall risk standpoint Inerting containment would not appear to have significant effect on reducing overall risk MATISON,R J Division of Safety Technology 80/05/27 lipp

--B007110498 Forwards "BWR Perspective on Interim Hydrogen Control Measures," as addi info on accident prevention for IMRs Substantial hydrogen generation is effectively prevented in BWR due to unique inhorent design features SHERWOOD, Q G General Electric Co MFN-048-80 80/04/21 1

8007110532 SECY-80-220

BICKWIT. Office of the General Coursel BO/04/27 19pp

B00711054B SECY-79-106
Provides Commission w/results of further loview of extent that intensing or other regulatory actions relied on WASH-1400 No reason exists to alter previous recommendations Symposes of items identified in NRC survey encl DENTON; R Office of Nuclear Reactor Regulation, Director 79/02/09 114pp

8007140055 SECV-RO-275A

NOT 40000 SECT-BU-2734
Provides proposed changes to FR notice re final rule on emergency proporediess in response to Commission directives from 800618 meeting Forwards replacement pages to SECY-80-MINDOUE, R B Office of Standards Development, Director 80/06/23

--8007140059 SELY-80-275
Replacement Pages 31, 25, 25a, 50, 51, 71a & 47 modifying FR notice & final rule changes to emergency preparedness
* Office of Standards Development, Director BD/06/25

8007140121 SECY-79-424

novibular operators approval of FR notice inviting public comment on NRC value-impact guidelines Recommends approval Draft FR notice, draft its to Congress & draft public announcement end HALLER, N M Office of Management and Program Analysis 79/07/02

```
-0007140122 Adviser that Cornit ioners have agreed to adopt guidelines contained in EPCr.-77-3684 for use in value-impact analysis CMLM.9 J Office of the recretary of the Compission 78/01/23
               -- 9207140130 Requests NAC to rendort review of Barem study, "Cost-Benefit
Analysis in Energy Decision-Making of NAC" Also requests
preparation of draft FR instite which would solicit public
comment on value-impact by Judelines
CHRLM S. J. Office of the Secretary of the Compission 79/01/18
            m-8007140135 by:Lusses importance of Value/inpact assessments in meeting fundamental safety & other statutory mandates Recent value/ impact assessments are well prepared although there is room
                        for improvement ANDERS U.A. Commission 76/04/15 1p
           --8007140139 'value-impact Guadelines' Contoans numerous NRC memos commenting on guadelines related cornents h several brief NRC repts re guadelines (1916) (1916) (1916)
          8007140539 SECY-90-101
               007140039 Sett-10-301
Requests review of proposed issuance of litense for GE to export components to Finland Equipment destined for country not previously authorized to export per Nuclear Nonproliferation Act of 1978 Recommends issuance SHEALUR Office of International Programs. Oirector 80/06/20
         8007140552 SECY-80-294
Informs of Frecutive Branch response on pending license for
Union Carbide Corp to export U-235 to France
SHEA.J R Office of International Programs Director 80/06/18
       --BOO7140560 Frecutive Branch position re application by Union Carbide Corp to export 9 85 kg U-235, enriched to 93% U to France Litense should be issued tir of assurance encl MOSENZO, L V State. Dept of. Bureau of Oceans & Internat! Environ & Scientific Affairs BO/06/11 2pp
      B007140576 SECY-80-153A

Forwards revised schedule for proposed rulemaking on reactor siting Distusses need for greater deliberation MINDOUE.R B Office of Standards Development, Director 80/06/17
    8007150050 SECY-HD-198
Recommends return of Rockwell Intl application for license
to export specially-designed valve to india w/o action
Executive Branch prefers returning w/o action as opposed to
denisi due to political differences involved Draft licenci
SHEA. J R Office of International Programs. Director BD/06/19
      B007150054 SECY-B0-307
         OO/15054 SECY-BO-307
Advises of intention to forward nuclear safety cooperation arrangement w/Argentina to Argentine Natl Energy Commission (EMEA) in response to CNEA request for cooperation proposal Cooperation arrangement enci
SHEA, J. R. Diffice of International Programs, Director BD/06/24
  BOO7150069 SECY-BO-306
Informs of proposed retransfer of 5.126 kg U.in form of apent fuel from Spain to United Kingdom Staff analysis currently being prepared 4 will be forwarded DOF BOOS17 retransfer analysis encl
SHEA.J R Office of International Programs. Director GO/06/23 in
 --8007150074 Forwards DDE analysis of proposed retransfer of 5.126 kg
U.in form of spent fuel from Spain to United Kingdom
Recommends approval
MCCDLDRICK F Energy, Dept of 80/06/17 22pp
BOO7160796 SECY-BO-107A

Provides addi info per Commission request re proposed interia hydrogen control requirements Forwards eight listed stowards.

DENION.H R

Office of Nuclear Reactor Regulation, Dir BO/04/22 Opp
```

Office of Nuclear Reactor Regulation, Director

```
B007170244 SECY-B0-117
Forwards Executive Branch responses re two pending export
license applications for Taiwan
SHEA, J.R. Office of International Programs, Director B0/07/01
       --8007170251 Forwards Executive Branch analysis re Hestinghouse
application for license to export 8,845 kg U~2,15, contained
in 325,822 kg U. to Taiwan
NDSENZO.L V State.Dept of Bureau of Oceans & Internatl Environ
& Scientific Affairs 80/06/12 13pp
      --B00717028B Application by Westinghouse for license to export U dioxide sintered pellets, encapsulated in scaled fuel rods & assembled into fuel assemblies, to Tajuan & Westinghouse Electric Corp | ICB-7823 | 78/11/17 | 1p
      8007170523 SECY-80-318
          NOTIFIED 318 Approval of proposed license to allow Nigsho-lwai American Corp to export 47 162 kg U & 44 003 kg U-235 to
           Mapan
GHEA,JR Office of International Programs, Director 80/07/01
     --B007170534 License for Nissho-Iwai American Corp to export 44 003 kg
U-235, contained in 47 162 kg U, to Japan
PETERSON M R Office of International Programs, Director
80/07/01 2pp
    8007170597 Unoffical transcript of 800703 public meeting re NRC response to panel presentations on emergency planning in Washington, SC Pp 1-50 * Commission 80/07/03 60pp
   --8007170604 SECY-80-2758
Proposes mode to FR & final rule changes on emergency
preparedness submitted for Commission approval in
SECY-80-275 Changes do not offect cost estimates Replacement
names encl
             pages ant l
HINOQUER B Office of Standards Development, Director 80/07/02
  8007180004 SECY-80-102E
Discusses approval of release of Kr-85 from reactor bidg atmosphere by controlled purging Recommends authorization for controlled purging Draft negative declaration re purging & prest release and DENTON.H R Office of Nuclear Reactor Regulation, Director COLUMNICO 1100
  B007210009 BECY-B0-316
Recommends issuance of proposed license for Transnuclear, Inc to export 39 077 kg U.enriched to 93 3% to Japan Forwards Executive Branch views re proposed export SHEA, J. R. Office of International Programs. Director 80/07/01
     -8007210076 Forwards Executive Branch position re Transnuclear, Inc & Nissho-twoi American Corp applications for licenses to export U-235 to Japan Licenses should be conditioned as
            noted
NOSENZO,L V State:Dept of Dureau of Oceans & Internat! Environ
& Scientific Affairs 80/01/29 App
 --B0072100B3 License for Transnuclear, Inc to espurt 39 077 kg U. enriched
to 93 3% to Japan
PETERSON, M R Assistant Director for Export/Import & International
Safeguards NUK-231 78-169 B0/07/01 2pp
  8007230026 Notice of ACRS Subcommittee on Fire Protection 800707 meeting in Washington DC to discuss proposed fire protection rule for facilities operating prior to 770101 per SECY-80-
      HOYLE, J C Office of the Secretary of the Commission 80/06/19
8007230179 SECY-BQ-242
Responds to RT Hennedy B00213 request for info re independent safety engineering group Existence of industry-wide groups does not alleviate need for independent safety engineering group or other util review groups
DENTON, HR Office of Nuclear Reactor Regulation, Director B0/05/13 6pp
8007250014 Transcript of 800711 Affirmation Session 80-33 re

SECY-80-274 in Washington DC Pp 1-2

# Commission 80/07/11 3pp
```

!

```
---BO07250019 SECY-BO-274
Recommends approval of publication of regulations reimplementation of IAEA requirements for licensees Draft FR notice & press release & summary of comments encl HIMDOUE.R B Office of Standards Development. Director SHEA, J.R. OFfice of International Programs, Director DIRCKS.W J Office of Nuclear Material Safety & Safeguards BO/OA/O2 127pp
```

B007230174 SECY-B0-278
Informs Commission of current status of resources & projected end-d-gr position No financial plan changes being recommended, pending several decisions, most significantly. Congressional action on NRC FYBO supplemental DARRY, L W Office of the Controller 80/06/04 2pp

--8007250180 "FY80 Mid-Yr Resource Review"

* Division of Budget 80/05/30 45pp

8007280062 SECY-80-308
Advises of near-signature status of NRC info exchange arrangement w/Japan Nuclear Safety Bureau & Agenty of Natural Resources & Energy Arrangement will be signed in Japanese & English Textural authenticity verified 800613 SHEAJR Office of International Programs, Director 80/06/24

BOO72800B6 SECY-80-313
Informs of Executive Branch position re application by DDE to export mixed oxide fuel pins to United Kingdom Recommends license be granted
SHEA. J R Dffice of International Programs, Director BO/06/30

BOO7290002 SECY-80-291
Recommends that Commission approve notice of denial of Petition for Rulemaking 2-9 filed by Union of Concerned Scientists & Naturel Resources Defense Council Draft documentation encl
BHAPARII K Office of the Executive Legal Director 43FR4862;
HNAPARII K 1500

--B007290005 Forwards patition for rulemaking 2-8 & Comments on proposed rule 10cFR21
ROISHANLA 2 Natural Resources Defense Council 43FR48621 21
79703702 ip

~=8007290012 Petition for rulemaking on amend to iOCFR21,rs exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past NRC activities
POLLARD,R Union of Concerned Scientists ROISMAN.A Z Natural Resources Defense Council 42FR48621 21 79/03/02 14pp

8007290023 SECY-80-299
Recommends that Commission approve mod to portion of security clearance processing solicy to permit certification of other federal agency security clearances to serve as basis for NRC certifications Security agreements w/DDE encl DDNOGHUE.D J Office of Administration 80/06/19 13pc

800729028 Draft Commission paper re approval of FR publication of "Quide for Evaluation of Agraement State Radiation Control Programs." as proposed policy statement w/request for comments Draft notice & guide enci
KERRIO W Office of State Programs. Director DIRCKS,W J Office of the Executive Director for Operations 80/06/02 38pp

~~8007270029 Discusses proposed criteria revisions for evaluation of agreement states Fundamental issues requiring resolution include ability of agreement states to bring proper technical skills to bear on radiological issues DIRCKS,W J Division of Safeguards 80/05/23 2pp

STATE PROG STATE PROGRAMS

8007010039 Forwards specific comments & recommendations re program for control of agreement matls Program adequate to protect health & safety w/some improvement suggested Requests review & comments on recommendations KERR.O W Office of State Programs. Director 80/06/11 App

8007010128 Ack receipt of 800602 itr to JM Hendrie, praising Ofc of State Programs past efforts & expressing concerns re future role Close working relations w/states will be preserved DIRCKS.W J Office of the Executive Director for Operations BO/06/17 1p

--8007010133 Praises Ofc of State Programs past efforts & expresses concerns re future role
MMELLER, E W. Alasta, State of 80/06/02 ip

8007010159 Commends organization of unnual meeting of Conference of Radiation Control Program Disortors held May 1980 in Louisville, KY JANINEK, M. Office of State Programs Director 80/06/10 lp

8007020099 Ack receipt of 80(1450 lin requesting NRC assistance at MD Commission on Intergovernmental Cooperation 800603 meeting Witness who will be prepared to answer questions re spent fuel will be privided J Elsaszer will accompany witness RYAN.R G Defice of State Programs. Director 80/05/21 ip

--8007020338 Requests that NRC testify before MD Commission on Intergovernmental Cooperation 8006/3 % 17 hearing in Annapolis, MD on nuclear waste mgt problems Specific questions encl EASTER, J.H. Maryland, State of 80/04/28 2pp

B007020113 Act receipt of 800521 itr expressing concern re future role of Ofc of State Programs NRL temains committed to preserving close working relations wistates DIRCKS, W.J. Office of the Executive Director for Operations B0/06/12 ip

B007020156 Forwards info requested re 1900 Houston Gamma Ray Co incident Release limit for contamination at that time was 0 5 millirems/h & instruments were less sensitive than those used today MERR.Q W Office of State Programs. Director SA/ECA 80/06/11

B007020316 Discusses Div of Mincs & Geology fault evaluation program for Livermore Volley Preliminary special study zone maps will be prepared by B10701 & fault evaluation repts will be issued Supporting documentation encl
HARTIE W California. State of 16526 80/06/04 12pp

8007020690 Confirms Schneider discussion w/GA Christianson of ND Dept of Health to NRC veriew of radiation control program & notes adequacy of program to protect health & safety Improvements to written enforcement procedures recommended RYAN.R G Office of State Programs, Director 80/06/11 13pp

B007020699 Responds to 800529 ltr requesting info re U milling operations & NRC Agreement State program Provides address for obtaining draft GEIS Forwards NURES-0511 & brochure re Agreement State program W/o encls

WERR, O W Office of State Programs, Director SA/CG 80/06/11

8007020766 Informs that under Scatton 274 of Atomic Energy Act.NRC is authorized to transfer to states, through agreement, some regulatory authority over byproduct source & SNM Twenty-Four states have compatible programs

RYAN, R Q Office of State Programs, Director 80/06/19 2pp

8007030347 Transcript of 800626 public meeting w/representatives of Conference of Radiation Control Program Directors re Agreement States program in Washington.DC Pp 1-38 Morning session Related correspondence ent.1 * Commission 80/06/P6 40pp

8007070016 Transcript of 800625 public meeting w/industry.state & local & special interest group panels on emergency planning & preparedness rulemaking & MRL response Pp L-131 Afternoon session Related statements & correspondence encl # Commission 80/06/25 600pp

B007110165 Forwards list of state bills not received Requests that copies be forwarded ORAMBAUG Office of State Programs. Director 60/06/25 1p

BOO7110377 Informs Subcommittee on Nociear Regulation of status of Agreement State requiatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL.

AHEARNE, J F Commission 80/06/24 2pp

--8007110382 Informs Subcommittee on Environ Energy & Natural Resources of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CYJ9 Significant program defiriencies found in CA & FL AHEARNE, J F Commission 80/06/24 2pp

--8007110387 Informs Subcommittee on Fivergy & Environ of Status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AHEARNE, J F Commission 80/96/74 29p

- ~-8007110392 inform. Subcommittee on Energy & Power of status of Agreement State regulatory programs Programs in all 25 states determined adequate for 6779 Significant program deficiencies found in CA : FL AHEARNE. J F Commission. 80/05/24 2pp
- --8007110395 Discusses status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL RYAN,R G Office of Management and Program Analysis 60/06/19 20s
- BOD7140569 Forwards comments & recommendations on State of NC radiation control program
 KERR, C W Office of State Programs, Director BO/06/27 3pp
- B007150044 Respinds to B00325 ltr by forwarding marked-up rept on state transportation surveillance program & updated versions of Apps I & II Suggests B00708-11 meeting to discuss approach & plan of action
 RYAN.R G Office of State Programs. Director B0/06/24 24pp
- 8007170234 Discusses results of NRC review of state radiation control program Program for regulation of agreement matl adequate to protect public health & safety & compatible w/Commission program Full-time prof should be hired RYAN,R G Office of State Programs. Director 80/06/27 2pp
- 8007170254 Confirms info provided in 800617 telron in response to 800611 ltr Responsibility for mgt of training programs for state & local smergency plunning & response personnel transferred from NRC to FEMA RYAN,R G Office of State Programs. Director 80/07/02 2pp
- --B007170277 Requests assistance in training local law enforcement, maergency response & health personnel Cortland County Resolution IBO enci FEUSB.J V New York, State of 80/06/11 Spp
- 8007180017 Expresses appreciation for 800526 ltr to NRC refuture role of Ofc of State Programs Views expressed in ltr will be carefully considered in any reorganization which may affect Ofc of State Programs
 DIRCKS.W.J. Office of the Executive Director for Operations
 80/06/04 lp
- --8007/80022 Expresses concern re future role of Ofc of State Programs Single point of contact which can work effectively w/all levels of NRC is vital Contact should have sufficient status to deal directly w/Commissioners & Executive Director MYERS, I L. Alabama, State of 80/05/26 19
- 8007180021 Forwards Nuclear Engineering Co. Inc 800404 application for ranewal of State of NV radioactive matl license at Beatty low level waste disposal site State of NV has requested NRC comment.

 MERR, G. H. Assistant Director for State Agreements Programs SA/RJD 80/06/03 350pp
- 8007180214 Ack receipt of 800624 ltr expressing concern about future role of Ofc of State Programs Views expressed will be carefully considered in any future reorganisation DIRCKS.H J. Office of the Executive Director for Operations 80/07/03 ip
- ---B0071B0217 Supports continuation of Ufc of State Programs as viable unit in NRC organizational structure Ufc of State Programs has consistently provided readily accessible source of technical-legal & policy advice COHEN.J C New York State of B0/06/24 App
- BOO7180558 Act receipt of 800321 ltr w/schedule .ions for radiological emergency response operations collifor FY81 NRC chooses Option liregardless of who has runding & responsibility RYAN R Q Office of State Programs. Director 80/07/01 1
- BOO721006B Advises that actions to adopt 10CFR71 revisions, re packaging a transportation of radioactive matls, should be initiated as soon as possible due to high degree of public focus on issue Requests plans

 KERR. Q W Office of State Programs Director BO/07/07 ip
- BOO7210263 Notification of cuntract execution "Environ Monitoring Program w/State of NY." awarded to State of NY BAISDENL Recearch Contracts Branch FIN B-5109 NRC-03-80-271

- --8007210267 Contract "Environ Monitoring Program w/State of Ny,"
 awarded to State of NY
 LANAHAN,H P New York, State of MORTON,K V Rosearch Contracts
 Branch FIN B-5109 NRC-05-80-271 80/01/01 14pp
- 8007230735 Ack receipt of 800512 ltm re progress in conperative efforts to reduce packaging & transport problems Full time insportered as Beatty should be discontinued Contract retransportation surveillance will be forwarded shortly AMEARNE, J.F. Commission 80/06/12 ip
- --8007230739 Advises that full-time NRC inspector will no longer be needed at Beatty, NV waste dispusal site State will provide appropriate insp surveillance as of 800601 LIST.R Nevada: State of 80/05/12 lp
- 8007250301 Advises that F Young will be NRC representative to State Planning Council meetings beginning w/800721 meeting RYAN,R 0 Office of State Programs, Director 80/07/09 ip
- 8007250026 Recommends that written procedures be developed for escalated enforcement action Written procedures are necessary so that state can respond adoquotely & in timely manner to incidents involving agreement matls RYAN.R O Diffice of State Programs, Director 80/07/02 2pp
- B007250639 Confirms comments made at B00603-06 regulatory program review Submits addl comments & recommendations designed to improve % strengthen radioactive matls program KERR.G W Office of State Programs, Director SA/JOL 80/07/02 5pp
- 8007280162 Ack receipt of 800522 ltr expressing concern re future role of Dfc of State Programs NRC remains committed to preserving cluse working relations w/states & Conference AHEARNE, J F Commission 80/06/19 ip
- ~~8007280170 Forwards resolution requesting Commission proceed w/caution in deliberation & actions re reorganization of NRC Ofc of State Programs has provided agreement states w/info vital to programs & amproved NRC/state relations PARROTT.M W Conference of Radiation Control Program Directors, Inc. 80/05/22 200
- 8007270028 Draft Commission paper re approval of FR publication of "Guide for Evaluation of Agreement State Radiation Control Programs," as proposed policy statement w/request for comments Draft notice & guide encl KERR, G H Office of State Programs, Director DIRCKS, H J Office of the Elecutive Director for Operations 80/06/02 38pp
- --6007270027 Discusses proposed criteria revisions for evaluation of agreement states Fundamental issues requiring resolution include ability of agreement states to bring proper technical skills to bear on radiological issues DIRCKB, W J Division of Bafeguards 80/05/23 2pp
- 8007290041 Forwards third quarterly transportation surveillance progress rept. first yr. submitted by State of WA under contract w/DOT & NRC JANINEK.M Diffice of State Programs, Director 80/07/16 15pp
- --B007290050 Forwards third quarter, first yr, transportation contract progress rept for B00310-0609 W/o encl GRONEKYER, E L Washington, State of B0/07/09 ip
- 8007290060 Forwards third quarterly transportation surveillance progress rapt, third yr, submitted by State of MI under contract w/NRC & DDT covering 800301-0531

 JANINEK.M Office of State Programs, Director 80/07/16 19pp
- --B007290065 Forwards third quarter, third yr transportation surveillance progress rept for 800301-0531 M/o encl REIZEN, M S Michigan, State of NRC-06-77-051 80/06/30 lp
- 8007290347 Discusses NRC concerns re State of NM program for regulating U mills & mill tailings Lists provisions not approved by Environ improvement Board which should be included in program to comply w/UMTRCA by 8111111

 AHEARNE, J F Commission 80/06/12 3pp

- ---8007290339 Discusses U mill regulations that should be adopted to enable State of NM to meet requirements of UMTRCA State should take action on differences between RTAX & Environ Improvement Div recommendations as discussed in encl KERR, 0 W Office of State Programs, Director 80/03/20 App
- BOO7300068 Ack receipt of 1tr expressing appreciation for NRC assistance in hearing last fall Advises of Commissioner inability to attend SSEB meeting KENNEDY:R T Commission 80/05/06 lp
- --BOO7300074 Expresses appreciation for Commission assistance on pmergency radiological planning shviron monitoring & transportation hearings Final rept available from hearings CANTERA R Bouth Carolina. State of BO/04/24 lp
- BD07010295 Updated list of state liaison officers
 # Office of State Programs, Director B0/07/31 lipp
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- BC07010234 Requests reply to 800221 inquiry re-status of technical review of topical rept on Fox Howlett rebar coupler, submitted 780322 Coupler approved by every major code writing agency FOX.C J. Fox Industries 80/06/25 1p
- 8007010349 Notifies that info requested in NRC 800610 ltr will be forwarded on 800718 Affirmation encl DARMITZEL, R W General Electric Co 80/06/23 2pp
- B007010507 Requests participation at Commission B00626 meeting on hydrogen control Gubstantial hydrogen generation effectively prevented in BHR due to dusign features SHERHOOD, 0 G Ogneral Electric Co 80/07/01 Ip
- 83077020089 Forwards status of TMI Bullstins & Orders Task Force work
 Discusses BEM operating plant response to IE Bullstins
 79-03.79-058 79-058 & 79-050
 HELTEMES C J TMI-2 Bulletins & Orders IEB-79-05 79/09/13 8pp
- --8007020095 Forwards summary of 790910 meeting re status of \$E Bullstins 79-06B & 79-06C & generic issues pertaining to C-E designed reactors VILLALVA, 1. TMI-2 Bullstins & Orders IEB-79-06B 79/09/12
- B007G20322 Requests add1 info to complete review of CE-1-A. "Comm Ed QA Program." Revision 11 Response requested by B00627 HAASE,W P Quality Assurance Branch CE-1-A.R 11 80/06/11 2pp
- 8007020570 Forwards WCAP-9748 & WCAP-9749, "Westinghouse Owners Group Asymaetric LOCA Load Evaluation, Phase C " Proprietary version withheld (Ref 10CFR2 770) Application for witholding proprietary into encl ANDERBON-T M Westinghouse Electric Corp , Nuclear Energy Bystems NS-TMA-2266 80/06/30 lipp
- --B007020596 WCAP-9749
 "Westinghouse Duners Group Asymmetric LOCA Load Evaluation,
 Phase C:" non-proprietary version
 CAMPRELL T E Westinghouse Electric Corp , Nuclear Energy Systems
 B0/06/30 220pp
- BOO7020641 Forwards MCAP 9558. Revision 1 & MCAP 9570. Revision 1.

 "Mechanistic Fracture Evaluation of Reactor Coolant Pips
 Containing Postulated Circumforential Through-Mall Crack "
 Affidavit encl Proprietary rept withheld (ref 10CFR2 790)
 ANDERSON.T M Hestinghause Clectric Corp N9-TMA-2265 BO/06/30
- --8007020544 HCAP-9570 R1

 "Michanistic Fracture Evaluation of Reactor Coolant Pipe Containing Postulated Circumferential Through-Wall Crack." Revision in monproprietary version FALUSAMY, S S, HARTMANN, A J, ANDERSON, T M Wastinghouse Electric Corp 80/06/30 200pp
- 8007020724 Notification of 800527 meeting w/Westinghouse & NAI in Bethesda, MD to discuss WCAP-9500 review Westinghouse will present Section 4.4 design of 17 x 17 optimized fuel as described in rept
 PHILLIPS, L.E. Core Performance Branch 80/05/23 2pp
- 8007030211 Discusses concerns re requirement for immediate trip of reactor toolant pumps in event of reactor trip & safety injection initiation caused by low pressure condition. WILSON B A TMI-2 Bulletina & Orders IEB-79-05C 79/10/07 5pp

- 8007030220 Provides status rept/schedule for issuance of NRC evaluations of B&W licensee responses to IE Bulletins 79-05. 79-05% & 79-05% & 79-05C CAPRAIR A TMI-2 Bulletins & Orders IEC-79-05 79/08/31 2pp
- B007030359 Advises that C Hichelson concerns, originally addressed to C-E Sys B0 designs, should be furwarded to B&W Responses nacessary by 791011 for NUREO-0365 writeup R0STY0CZY: Z R TM1-2 Bulletins & Grders 79/09/06 2pp
- B007070106 CAI-TR-106 R2A
 Corrections to Feb 1980 GAI-TR-106 Revision 2A. "QA Program
 for Nuclear Power Plants"
 # Gilbert/Commonwealth Cos 80/06/23 ip
- E007070290 Ack receipt of NRC 800630 ltr re corporate organization WP Rausch has been named director of project support & QA diva & DJ McCormick is manager of corporate QA Corporate operations manual,Part 11 Organization encl HENDRICKSON,T Burns & Roe Co 80/06/30 9pp
- 8007080248 Notifies that Hestinghouse study re inadequate core conling conditions will be submitted by mid-Jul 1980 REED, C Commonwealth Edison Co DG-35 80/07/01 ip
- 8007080274 Forwards input for 1979 fuel performance annual rept including table summary of C-E fuel stradiated &/or discharged in 1979 & "Performance of C-E fuel in Operating FWRS"

 SCHERER, A E C-E Power Bystems LD-80-039 80/07/01 3pp
- 8007080312 Responds to NRC request for info re "Fuel Performance Annual Rept " Includes info re current B&W design fuel performance programs underway in 1979 & summary of B&W fuel performance for 1979
 TAYLOR, J H Babcock & Wilcox Co 60/07/03 15pp
- GOO7090198 Forwards "Effects of Asymmetric LOCA Loadings. Phase 11 Analysis "Rept updates "Effects of Asymmetric LOCA Loadings. Phase 11 Status." submitted Feb 1980 TAYLOR, J H Babcotk & Milcor Co ESC-186 80/07/01 1p
- --E0070902D1 BAM-1621 "Effects of Asymmetric LOCA Loadings, Phase II Analysis " ALLEN, R B , ANTOWN, R L , AU-YANG, M K Babcock & Wilcor Co BO/07/31 BOOpp
- 8007090310 Forwards OR rept, NEDE-24757-P. "Caorso Safety Relief Valve Discharge Tosts Phase 2 Test Rept "Test rept withhe" (ref 10CFR2 790) BUCHHOLZ.R H General Electric Co RHB-051-80 8L /03 5pp
- 8807100075 Notification of 800528 meeting w/C-E others group in Bethesda.MD to discuss group obligations for instrumentation re core cooling PHILLIPS: L. Core Performance Branch 80/05/23 1p
- BOO7100210 Forwards Amend 1 to CENPD-183, "C-E Methods for Loss of Flow Analysis " SCHERER.A E Combustion Engineering, Inc. LD-80-035 80/06/24
- --8007100212 CENPO-183 R1
 "C-E Methods for Loss of Flow Analysis." Amend 1
 # Combustion Engineering. Inc LD-80-035 80/06/30 12pp
- 8007100219 Forwards "Class IE Qualification Qualification of Class IE Instrumentation," Revision 1.Jul 1980 SCHERER.A E C-E Power Systems LD-80-040 80/07/03 1#
- --8007100220 CENPD-255 Ri "Class IE Qualification - Qualification of Class IE Instrumentation." Revision 1.Jul 1980 W C-E Power Systems 80/07/21 87pp
- 8007100253 Forwards Revision 9 to MCAP-B183, "Operational Experience w/Hestinghouse Cores (up to 791231)"
 ANDERSON-T # Westinghouse Electric Corp ELM-B0-006 80/04/21
 2pp.

- --B007100295 WCAP-B1UJ RP
 Revision 9 to "Operational Experience w/Hestinghouse Cores
 (up to 791231)"
 SKARITKA, J. JORIJ. J. A. Westinghouse Electric Corp. 80/04/30
- B007110215 Forwards "Oadolinia Fuel Properties for LHR Fuel Safety Evaluation " Rept withheld (ref 10CFR2 790) Affidavit uncl UHSLEY.O F Erron Nuclear Co. Inc (aubs of Erron Corp.) 0FO 099 B0 80/06/09 4pp
- 8007110243 Forwards Revisions 1-P & 1-NP to CEMPD-153-P & NP,
 "Evaluation of Uncertainty in Nuclear Power Peaking
 Measured by Self Powered, Fixed In-Core Detection Sys "
 Revision 1-P withheld (ref 10CFR2 790), Afficiarylt enci
 BCMERER, A C Combustion Engineering, Inc LD-80-024 80/05/16
- --BOO711024B CENPD-153-NP RI

 "Evaluation of Uncertainty in Nuclear Power Peaking
 Heasured by Self Fowered Fired In-Core Detection Sys,"
 Revision 1-NP nonproprietary version
 JUNSEDN.A. TERNEY, U.B. CAUMP, M.H. Combustion Engineering, Inc.
 BO/05/31 250pp
- 8007110341 Forwards XN-NF-80-17(P), Vols 1, 2, 2A, 20, & 3, XN-NF-79-59(P), XN-NF-524(P) & XN-NF-79-71(P), Revision 1 Repts withheld (ref 10CFR2 770) ONSLEY, 0 F Exson Nuclear Co , Inc (subs of Exxon Corp) OFO 096 80 80/05/30 3pp
- 8007110499 Requests response to encl NRC position re CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations " Yrs of experience required for position of manager of QA not described HAASS.N P Quality Assurance Branch 80/08/08 2pp
- 8007110330 Notification of 800612 meeting w/GE BWR owners group to discuss current plans of group to satisfy L2 requirements for relief valve testing TELFORD.J T Operating Reactors Assessment Branch. 80/06/03 2pp
- 8007110578 Notifies of NRC approval of XN-NF-1A, Revision 3, "QA Program Topical Rept for Nuclear Fuel Design & Fabrication " Program may be implemented upon issuance of revision HAA85, N P Quality Assurance Branch 80/06/27 ip
- 8007140356 Forwards "Emergency Procedure Guidelines" for BMR owners group, per NUREC-0576. Requirement 2 1 9 Description of how analyses of NEDD-24708 & emergency procedure guidelines apply to all FSAR Chaptor 15 events forthcoming BUCHMOLZ.R II General Electric Co MFN-117-80 80/05/50 40pp
- 8007140367 Forwards supply to equipment qualification test repts, revised equipment qualification data package, application for withholding & affidavit re commitments made in MCAP-0567
 ANDERSON, T.M. Westinghouse Electric Corp. NS-TMA-2260 80/06/16
- ---8007440373 EQDP-EBE-15 R2

 "Recorders Post-Accident Monitoring Equipment Qualification
 Data Package: Revision 2 Submitted as part of Suppl 1 to
 MCAP-8587

 ANDERSON T M Mestinghouse Electric Corp. Nuclear Energy Systems
 80/05/31 17pp
- --8007140379 WCAP-8587 S2

 "HCID OFTIMAC 100 Recorders Equipment Qualification Test
 Rept." Suppl 2 Nunproprietary version of HCAP-8587

 HCELIHANEY, D. 1. MILLER, D. 8. ANDERSON, T. M., Westinghouse Electric
 Corp. E19A 80/05/31 42pp
- OO7140407 Porwards "Equipment Qualification Test Rept Barton Pressure Transmitters-Qualification Group D " Application for withholding proprietary info & affidavit encl Proprietary varsion withheld (ref 100FR2 790) ANDERSON.T M Westinghouse Clectric Corp NS-TMA-2258 80/06/16 1000
- -8007140416 MCAP-8587 B2-E02A

 "Equipment qualification fest Rept Barton Pressure
 Transmitters Qualification Group B "Nonproprietary
 version
 MCELMANEY, D L . MILLER, R B . ANDERSON, T M Westinghouse Electric
 Corp 80/05/J1 30pp
- 8007140420 HCAP-8587 81 "Equipment Quelification Pata Package," Suppl 1. Revision 2. " Mostinghouse Flectric Corp. EQUP-ESE-2 80/05/91 15pp

- B007140426 Forwards uddl capies of NEDO-25224, "GESSAR Assessment Rept, Review of BHR/6 Protection In-Depth for Transient & Accident Eyents" BUCHHOLZ,R H General Electric Co RHB-049-B0 B0/06/30 lp
- 8007140630 Forwards topical rept evaluation of BAW-10123, "Nuclear Applications Software Package," re nuclear analysis for reactor cores
 MILLER, J. R. Standardization & Special Projects Branch B0/06/19
- --8007140637 Topical rept evaluation of BAM-10123, "Nuclear Applications Boftware Package" Rept acceptable BROOKS,W Core Performance Branch 80/06/19 5pp
- 8007140639 Forwards tupical report evaluation for NEDE-24010-P re use of square root of sum of squares method for combining dynamic loads for Mark II plants
 MILLER, J. R. Standardisation & Special Projects Branch 80/06/19
- --8007140643 Topical rept evaluation of NEDE-24010-P, "Technical Sasis for Use of Square Root of Sum of Squares Method for Combining Dynamic Loads for Mark II Plants " Rept acceptable & Mechanical Engineering Branch 80/06/19 Spp
- 8007190526 Requests NRC attention to PPI-TR-7701.Revision I Sys described in topical rept sold to applicant Review of submittal requested as soon as possible HALL.H C Teledyne Energy Systems PPD-WCH-263 80/07/10 ip
- 8007150646 Forwards proprietary version of WCAP-8687, Suppl 2, nonproprietary version of WCAP-8587, Suppl 2 & Equipment Qualification Data Package EBE-10, Revision 2, which is part of nonproprietary WCAP-8587, Suppl 1 ANDERSON, T M Hestinghouse Electric Corp N9-TMA-2237 80/06/16
- --8007150652 WCAP-8587 S2-E10A Nonproprietary version "Equipment Qualification Test Rept, Nuclear Instrumentation Sys (Normal & Abnormal Temp & Humidity Testing) " VQOEDING,E L Westinghouse Electric Corp 80/05/31 24pp
- ~~8007150656 WCAP-B587 R1
 Revision 2 of "Equipment Qualification Data Program Nuclear Instrumentation Bys (NIS) Consols (Power Range Channel) "
 nonpropristary version
 ANDERSON, T M Westinghouse Electric Corp EGDP-ESE-10 80/05/31.
- GOO7150724 Summarizes BOO619 NRC/GE meeting re ECCS licensing issues concerning LDCA analysis model & amends. GESTR model. ECCS input reverification program & core spray program BUCHHOLZ, R H General Electric Co LFR-030-80 80/07/08 4pp
- BOO7i60743 Forwards proprietary HCAP-8687, Suppl 2-E04A, nonproprietary MCAP-8587, Suppl 2-E04A & Revision 2 to Equipment Qualification Data Package EBE-4, part of nonproprietary HCAP-8587, Buppl 1 Info withheld (ref 10CFR2 790) ANDERSON, T M Hestinghouse Electric Corp NS-TMA-2259 80/06/16 10pp
- --B007160755 WCAP-8587 B2-E04A

 "Equipment Qualification Test Rept, Barton Differential
 Pressure Transmitters Qualification Group B (Seismic
 Design Verification Testing)," nonproprietary version
 MCELHANEY, D L , MILLER, R D Westinghouse Electric Corp
 200-2
- --B007160765 WCAP-8587 R2 81
 Revision 2 Suppl 1 to, "Equipment Qualification Data Package ESE-4," nonpropietary version
 ANDERSON: T M Westinghouse Electric Corp EGDP-ESE-4 B0/05/31
 17pp
- 8007160805 Offers no comments on Reg Guide 4 16, "Effluent Monitoring at Nuclear Fuel Processing & Fabrication Plants," in response to 800522 memo KNIGHTON, G W Research & Standards Coordination Branch 80/06/19, 200
- --8007160814 Summary of 800528 meeting w/C-E owners group in Sethesda, MD re inadequate core cooling List of attendees & viewgraphs enct PHILLIPS, L.E. Core Performance Branch 80/06/23 31pp

1

- 8007170417 Forwards "BWKIN Nuclear Reactor Core Minotics Code B&W version of MEKIN" & affidavit re request for proprietary classification TAYLOR, J H Babcock & Wilcox Co 80/07/07 ip
- --BOC7170421 Affidavit re proprietary classification of "BWKIN Nuclear Core Kinetics Code, B&W Version of MCKIN" TAYLOR, J H Babcock & Wilcox Co 80/07/09 7pp
- BOO7180471 Forwards generic ltr to all operating PWRs requesting amend to Tach Specs for each three PWR types and EIBENHUT.D O Division of Licensing 10/06/11 in
- --BOO7180479 Ltr to all operating PWRs requesting amend to Tech Specs redecay heat removal capability Amend is necessary to provide permanent long-term assurance that redundanty will be maintained EIBENHUT.D O Division of Licensing 80/06/11 ip
- --8007180486 STS for RCS:providing for redundancy in decay heat removal capability in all modes of operation * Babcock & Wilcox Co 80/06/11 8pp
- --8007180496 STB for RCB.providing for rodundancy in decay heat removal capacity in all modes of operation a Combustion Engineering, Inc. 80/06/11 9pp
- --8007180504 STS for RCS, providing for rodundancy in decay heat removal capability in all modes of operation a Hestinghouse Electric Corp 80/06/11 Spp
- BOO7210051 Advises that Dfc of Controller will be billing OE for review of NEDO-11207-040. "Nuclear Energy Business Group DWR QA Program Description," Revision 1
 HILLER W D License Fee Management Branth 80/07/01 1#
- 8007210229 Forwards Amend Sa to 21A, "Nuclear GA Manual," consisting of revised Page 5
 HAABS, W P Quality Assurance Branch 80/07/17 2pp
- --8007210233 21A A05A Amend 5a to 21A: "Nuclear QA Manual," consisting of revised Page 5 w C F Braun & Co 80/07/17 ip
- 8007210366 Forwards Acurex Corp 800531 response to NRC questions on NEDE-24778-P. "Vent Bys Compressibility Effects on Mark I Pool Buell"

 BUCHHOLZ,R H General Electric Co RHB-058-80 80/07/14 47pp
- 8007210410 Forwards written notification supplied to customers on 800708 re-potential for inadvertent boron dilution event while shutdown & operating on RHR sys Modifies previously reported interim actions
 ANDERSON, T.M. Westinghouse Electric Corp., PMR Systems Div NB-TMA-2272 80/07/08 7pp
- 8007220134 Forwards review of CENPO-133-P & revision describing method used to establish overall measurement uncertainty of core power distribution components Rept is acceptable for reference in license applications
 MILLER, J.R. Standardization & Special Projects Dranch 80/07/02
- 80072203R? Forwards nonproprietary version of NEDD-R4781-1, "Comparison of Single & Hultivent Chugging at Two Scales." submitted on behalf of Mark II owners group BUCHHCR.2, R H General Cisctric Co MFN-122-80 80/07/08 lp
- --8007220334 NEDO-24781-1
 "Comparison of Bingle & Multivent Chugging at Two Bceles."
 nonproprietary version
 PATEL.B.R. DOLAN.F X . BLQCK.J A. Creare. Inc CREARE-TN-307
 80701/31 84pp
- 8007220052 Forwards procedure guidelines for plants w/high & low heaf high pressure safety injection sys.emergency procedures & interim adequate core cooling instructions for refinations for post-LOCA cooldown & depressurization REED. C Commonwealth Edison Co DO-07 80/07/15 2pp
- ---8007220354 "Interface Quidelines Between Emergency Procedures & Inadequate Core Cooling Instructions,"

 * Commonwealth Edison Co 80/07/15 1p.
- --8007220357 "Ref Instructions for Post-LOCA Cooldown & Depressurization," Revision 0 # Commonwealth Edison Co #80/04/30 13pp.

- --8007220359 "Ref Emergency Operating Instructions (HP), 'Revision 2 8 Commonwealth Edison Co. 1538h B0/04/30 B9pp
- --8007220361 "Ref Emergency Operating Instructions (LP)," Revision 2 # Commonwealth Edison Co +80/04/30 /2pp
- 8007220482 Forwards WCAP-9753 % WCAP-9754 re inadequate core cooling studies & vendor 600711 application for withholding info w/ supporting affidavit Repts will provide analytical basis for guidelines re inadequate core cooling detection & remedy REED. C Westinghouse Operating Plants Owners Group 100-36 80/07/17 3pe
- --8007920494 Affidavit justifying withholding of proprietary info in vendor ECCS repts from public disclosure (ref 10CFR2 790) WEISEMANN.R A Westinghouse Electric Corp AW-77-18 77/04/20 App
- --8007820499 HCAP-9744
 "Loss of Feedwater Induced LGCA Analysis Rept "
 TAUCHE, W Mestinghouse Electric Corp , Nuclear Energy Systems 80/09/31 182pp
- --B007220903 WCAP-9754

 "Inadequate Core Cooling Studies of Scenarios w/Feedwater
 Available,Using NOTRUMP Computer Code "
 THOMPSON.C M , MARK.R H , HILL, G C Wostinghouse Electric Corp ,
 Nuclear Energy Systems 80/06/30 410pp
- B007240001 Forwards BAW-1623, "Control Rod Guide Tube Wear Measurement Program " Rept documents wear measurements in response to NRC 791123 ltr to owners of BSW designed reactors TAYLORJ H Babcock & Wilcor Co 80/07/18 lp
- ~~B00724000D BAW~1623
 "Control Rod Oulde Tube Wear Measurement Program"
 " Babcock & Wilco Co 80/06/30 25pp
- B007250476 Advises that NRC had accepted DNS-RSS-001F, "Dow Sys for Solidification of Low Level Radwastr from Nuclear Power Plants" Final rept to be submitted pending incorporation of amends per ent) NRC guidelines

 DDNQVAN.L J Dow Chemical Co 80/07/21 1p
- --8007250483 Informs of NRC acceptance of DNS-RSS-001P re radwaste sqlidification Fire protection & interfaces w/plant systemould be considered interface requirements that will be addressed by applicants referencing rept
 MILLER.J R Standardization & Special Projects Branch 80/06/19
- 800725051B Requests approval of proposed change in fuel design analysis described in NEDE-24011-P-A-I. "Generic Reload Fuel Application." Aug 1979 Change would allow OE to respond to BMR util requests in high capacity 18-month operating cycle ENGCL.R E General Electric Co MFM-127-80 80/07/21 2pp
- 8007280899 Forwards errata sheet to EDAC-117-253 O1. "Evaluations for O & g Ground Acceleration Case Suppl 2 to Addl Investigations to Determine Effects of Combined Vibratory Varona Fault," Revision 1. Suppl 2
 GILLIAND.D L General Electric Co 80/07/25 2pp
- --8007280606 EDAC-117-293 Of Ri
 Errata sheet to "Evaluation for O 6 g Ground Acceleration
 Case Suppl 2 to Add1 Invectigations to Detarmine Effects
 of Combined Vibrotory Veroma Fault." Revision 1. Suppl 2
 H Engineering Decision Analysis Company, Inc. 80/07/28 2pp
- BOO73000B6 Notification of BOO80B meeting w/Human Performance Tachnologies & Sandia Lab in bilver Spring. MD to develop checklist for emergency procedures BTONE.J C Office of Inspection & Enforcement, Office of the Director 80/07/2d 2pp

- 8007300399 Further discusses specific info in WCAP-8480 re upper head injection Guantitative info needed to high resistance of flow path in transferring steam to upper head when pressure is lower than RCS

 MALLES.G B Dartmouth College 80/07/24 2pp
- 8007300452 Forwards "NRC Benchmark ME101 Verification Rept.Apr 1980 "
 ME101 calculations agree within 2% of answers provided
 w/benchmark problems except for answers to Problem 3
 Rept available in Central Files only
 CAHN.A L Bechtel Power Corp (subs of Bechtel Corp) 80/07/23
 in
- 8007310256 Notification of 800730-31 meetings w/vendors & consultants in San Jose,CA to discuss Mark 111 LOCA-related pool dynamic load criteria FIELDS,H Containment Systems Granch 80/07/21 4pp

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8007010270 Responds to 800513 request for separate MILBOS computer output for San Niguel ore buying station Tailings mgt program & radiological impact assessment underway Preliminary results & dose estimates encl SCARANO,R A Uranium Recovery Licensing Branch 80/06/16 5pp
- --8007010274 Requests offsite dose commitment output from HILDDS for ore stockpiles, receiving hopper, belt conveyor & sampling plant Comparison of ore buying station to offsite dose estimates for complete milt will be useful to vendor & NRC HAZLE-A J Colorado, State of 80/05/13 2pp
- 6007020092 Advises that NRC is unable to participate in Homestake Mining Co Pitch groject on continuing basis requested in 800219 ltr due to limited resources for technical assistance to Agreement States Suggests review on state level 8CARANDIR A Uranium Recovery Licensing Branch 80/06/09 ip
- S007020128 Forwards "Simulation Study of Evaporation Pond Seepage at Mount Taylor U hill Project." in partial response to State of NM Environ Improvement Div. 800609 request for addl info re proposed groundwater discharge plan RDGERS, W L Gulf Oil Corp. Gulf Mineral Resources Co 14569. 30/06/10 ip
- --8007020135 44iTL337
 "Bimulation Bludy of Evaporation Pond Seepage at Mount
 Taylor U Mill Project"
 MUNHERVEE, H Gulf Science & Technology Co 16569 80/05/30
- B00702014B Biscusses review of proposed Nose Rock U Mill Mill was proposed for const in State of NM & anviron & tailings mgt review was conducted in response to technical assistance request Case considered complete as of Mar 1980
 MILLER, H.J. Uranium Recovery Licensing Branch B0/03/21 2pp
- 8007020264 Provides in Fo in response to J Helie inquiry re United Nuclear Corp. Church Rock U Hill tailings 790716 dam failure Faiture caused some radioactive tailings solution to be released into Rio Puerco Released FR excerpts ent DIRCKS.H J Office of the Executive Director for Operations 80/06/09 2690
- --B007020277 Testimony of WJ Direks before Subcommittee on Energy & Environ re Church Rock U mill tailings dam failure
 DIRCKS,H J Office of the Executive Director for Operations
 House of Rep , Interior & Insular Affairs 79/10/22 14pp
- B007020281 Forwards response to Item 1 discussed at 800417 meeting, completing responses to 17 items identified during 800512 moeting Requests meeting during wk of 800609 Eversized drawings ent 1
 THOMPSON, M.A. Cypros Mines Corp. 16568 80/06/02 10pp
- 8007020359 Requests that Union Carbide & Acres American consider encl items in submitting tailings pond stability analysis to Blate of CD Dept of Health Includes careful presentation of all assumptions made during modeling JUNOE, W.R. Colorado. State of 16582 80/03/21 25pp.
- 8007020709 Corrects typographical errors in 800602 response to 1tem 1 Replacement Page 3 enc1 THOMPSON.M A Cyprus Mines Corp 16566 80/06/09 2pp
- --8007020712 Corrected Page 3 in 800602 response to Item 1
 * Cyprus Mines Corp. 16566 80706709 lp

- B007070195 Lists prioritized directives in order to expedite contract completion Further statistical analysis need not be undertaken EADIE.8 Uranium Recovery Licensing Branch FIN B-2214 80/06/02
- 8007100431 Responds to 800226 request for review of Cotter Core proposal re disposal of contaminated trash in U mill tailings impoundment Disposal will have no adverse effect on function of impoundment W/o encl consultant comments BCARANO, R A Uranium Recovery Licensing Branch 80/05/19 200
- 8007110454 Forwards 800613 testimony presented at Railroad Commission of TX hearing on application for surface mining & reclamation permit for project Requests issuance of permit as soon as possible DAVIS.0 R Anaconda Co
- ~-B0071:0457 Testimony of Anaconda Copper Co by GR Davis on 800613,before Railroad Commission of TX Pp 1-11 Draft affidavit & resume encl DAVIS.O R Anaconda Co , Anaconda Copper Co Div 16616 80/06/16 14pp
- --8007110459 Testimony of Camp Dresser & McKee by ED Sethness on 800413, before Railroad Commission of TX Pp 1-5 Resume encl SETHMESG.E D Camp Dresser & McKee.Inc , Environmental Sciences, Drv 16616 80/06/13 7pp
- --8007il0462 Testimony of EL Reed & Associates by EL Reed on 800613, before Railroad Commission of TX Pp 1-7 Resume encl REED.E L Ed L Reed & Associates, Inc 14616 80/06/13 7pp
- 8007150045 "Principle Parameters for Radiological Assessment "

 Dawn Mining Co 16708 80/05/31 22pp
- 8007170660 Forwards "Low Level Waste Licensing Branch Review of Nuclear Engancering Co. Inc Application for Renswal of Beatty, NV License." in response to request SMITH, R D Low Level Waste Licensing Branch 80/07/03 lp
- --8007170668 "Low Level Waste Licensing Branch Review of Nuclear Engineering Co.Inc Application for Renewal of Beatty.NV License " * Low Level Waste Licensing Branch 80/07/03 40pp
- 8007180021 Forwards Nuclear Engineering Co, Inc 800404 application for renewal of State of NV radioactive matl license at Beatty low level waste disposal site State of NV has requested NRC comment KERR, G W Assistant Director for State Agreements Programs SA/RJD 807/06/03 330pp
- B0071B052B Requests establishment of waste mpt docket file WM-13 at fl Street PDR Docket file concerns technical assistance to State of NV for state renewal of Beatty, NV low level waste facility license HEDDINGS, TP Low Level Waste Licensing Branch B0/07/09 2pp
- 8007210104 Forwards completed Page 4 of Operational Monitoring Rept 3-80. CAIN.J Cotter Corp 14748 80/04/30 2pp
- BO07210138 Ack receipt of B00619 ltr re proposed study of potential U development in CO Total impact study should be conducted rather than case by case evaluation Requests moral & financial support for study REMPLE.L Citizens for Safe Environment 16797 80/06/22 1p
- BOO7220025 Forwards long range plan for processing of Uravan mineral belt ores & supporting documentation submitted to Radiation & Halardous Maste Control Div of CO Dept of Health REXEMEYER. C Union Carbide Corp 16693, 80/06/19 4pp
- --8007220032 NUS-3574 "Facilities Stack Audit, Uravan U Mill " * NUS Corp 16693 80/05/23 84pp
- ---8007220036 NUB-3582
 "40CFR190 Related Radiological Doses Due to Operation of Uravan U N111 "
 BARTAM, B W. ENOLEHART, R W. CONWAY, T W NUB Corp 16693 80/08/30 84pp
- --B007220042 "Cost Rept Tailings Storage & Evaporation Pond Evaluation, Long Park & Paradox Valley Sites Urayan U Mill.Montrose County.CO." for Union Carbide Corp B0DDY,J R Dames & Moore 16693 80/05/23 65pp

- --8007220049 "Tailings Storage / Evaporation Pond Evaluation.Long Park & Paradox Valley Sites.Dravan U Mill.Montrose County.CO." for Union Carbide Corp BDDDY.J R Dames & Moore 16693 80/05/23 200pp
- --8007220056 "Uravan Tallings Piles Prior to Reclamation " BROWN.R Union Carbide Corp 16693 80/06/09 lp
- ---8007220044 "Proposed Reclamation Plan for Unavan Tailings Piles "
 BROWN,R Union Carbide Corp 16593 80/06/09 ip
- --B007220074 "Proposed Plans & Estimated Costs for Tailings & Reclamation.Mill Decommissioning & Pond Reclamation at Uravan Hill for Surety Purposes " Hemo dt B00530 re requirements for sub-surface disposal permit encl # Union Carbide Corp 16693 80/05/30 19pp
- ~-8007220081 "First Quarter, 1980 Summary, Environ & Health Physics Monitoring, Uravan, CO " JONES, R K Union Carbide Corp 16693 80/03/31 63pp
- --B007220087 "1979 Annual Summary, Environ & Health Physics Monitoring, Uravan, CO " * Union Carbide Corp 14693 79/12/31 200pp
- --8007220101 NUB-3595
 "Review of Available Meteorological Data Representative of Uravan V Hill Bite Vicinity "
 COFFCY, H E , MAXWELL, D R , CONWAY, T W NUS Corp 16693
 80/05/07 2ipp
- --B007220111 NUB-3544

 "Correlation Analysis of Variables Affecting Airborne
 Radioactive Particulate Concentration Near Uravan U Hill "
 Intl Engineering Co. Inc. itr forwarding preliminary const
 estimates of proposed disposal sites encl
 BARTRAM, B W. DOUGHERTY, D X., ENGLEHART, R W. NUS Corp. 16493
 B0/03/13 200pp
- --B007220119 "Preliminary Geotechnical investigation of Proposed Spring Creek Mesa Toilings & Effluent Disposal Site Near Uravan, CO " KINO.K B Morrison Knudsen Co , inc 16693 B0/05/3i 150pp
- 8007230i45 Responds to B00623-24 memos transmitting State of NM response to Church Rock tailings dam stability issues raised in NRC 791810 ith NRC geotechnical consultant is reviewing response to determine if issues are addressed properly SCARANO.R A Uranium Hecovery Licensing Branch B0/06/30 ip
- B007230720 Forwards R Kinneson review of NM Environ Improvement Div proposed verification sampling scheme W/o encl EADIE.0 Uranium Necovery Licensing Dranch 80/07/09 ip
- B007250150 Requests confirmation of 800418 telcon re application for source matts license NRC will not require revised amended application under new guidelines since environ work was based on ald guidelines
 SHERMAN, II D Arnaid & Porter 14779 80/06/25 2pp
- B007280194 Forwards as-built plans for breach repair & tailings dam expansion W/o encl MILL-TM United Nuclear Corp 16817 80/06/27 ip
- BOO72902PB Confirms that BOO42b ltr accurately describes NRC oplnion re filing of amended application w/Btate of CO Radiation & Hazardous Waste Control Div for matls license BCARAND.R A. Uranlum Recovery Licensing Branch
- 8007310497 Forwards "Bolid Wasto Disposal Rept." for June 1980 to Dept of Health Radiological & Nazardous Waste Div JONES, R. K. Union Carbide Corp. 14854 80/07/15 ip
- --8007310300 "Roiid Woste Disposal Rept," for June 1980 * Union Carbide Corp 60/07/15 67pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 7906200223 Requests Executive Brench position re GE application for license to export six detector assemblies to India Forwards 790507 application M/o encl IPLINDER, 0 Q Assistant Director for Export/import & international Bafeguards 79/05/10 ip

- B007010009 Executive Branch position re DDE application for license to export 32 & kg U.containing & 45 U-235, to France Ltr of assurance encil License should be granted NOSENZO, L V State, Dept of, Dureau of Oceans & Internat) Environ & Scientific Affairs 80/06/10 3pp
- 8007010012 Executive Branch position re Dept of Havy application for incense to export 3.019 kg depleted U to Australia License should be granted NDSENZOL V State. Dept of Bureau of Oceans & Internat! Environ & Scientific Affairs 80/06/11 1p
- Scientific Affairs B0/06/11 1p
- 8007010014 License for Marubeni America Corp to eiport & g Pu.l g Pu-242.10 g U-233 & 100 g U oxide to Japan PETERSON,M R Assistant Director for Ciport/Import & International Bafeguards 210126-0W 80/06.19 2pp
- 8007010019 Esecutive Branch position re application for licenses to export highly enriched U to Japan Since no intermediate consignee is used.license condition requiring specific modes of transport is no longer necessary NDSCNIOL V State, Dept of. Bureau of Doceans & Internati Environ & Scientific Affairs 80/06/10 ip
- B007010102 Application by Westinghouse for license to export one BF3 proportional counter to West Cermany POCHAL, W F Westinghouse Electric Corp ZE-10302 80/06/09 lp
- B007010170 License for Borg-Harner Corp to export carbon & stainless steel globe & check gate valves to Belgium PETERSON, M.R. Assistant Director for Export/Import & International Bafeguards 60/06/18 lp
- 8007010572 Requests extension of expiration date of license to BiO630, because of delay on some items due to inability to acquire raw mat!

 ROGERS.W F Metai Belicus Corp 80/06/19 ip
- BOO7010577 Application by Aldrich Chemical Co for license to export 5 kg deuterium in 20 kg deuterium axiderto Belgium EDELSTEIN.B Aldrich Chemical Ca. inc (subs of Sigma-Aldrich Corp.) 12/80 BO/04/12 lp
- B007020014 Application by Aldrich Chemical Co.Jnc for license to export i kg deuterium.in 5 kg deuterium oxide to New Zealand EDELBTEIN.B Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 10/80 B0/06/12 lp
- B007020020 License for Panalpina Airfreight, Inc to export 7 g U. containing 1 &i g U-225, to finiand
 PETERSON, M R Assistant Director for Export/Import & International Safeguards B0/06/iB 2pp
- B007020057 Requests assistance in obtaining necessary ltr of assurance for application for export license PETERSON, M.R. Assistant Director for Export/Import & International Bafeguards B0706/18 ip
- 8007020084 Application by GA Co to amend license to extend explication date until Jul 1982
 MDHRY,W R General Atomic Co (subs of Gulf Oil Corp) IEL-1185-B0/06/05 ip
- B007020093 Advises that NRC B00516 formal vote determined that applications to export SNM to India did not meet criteria for issuance Applications were referred to President for further consideration
 SHEA, J R Office of International Programs, Director 80/04/12 in
- 8007020123 Advises that application to export specially designed parts & components to India was referred to President for add1 consideration NRC unable to determine that application meets criteria of Atomic Energy Act SHEA, J.R. Diffice of International Programs, Director 80/06/16 ig
- 8007020153 Application by Kawecki Berylco Industries.Inc for license to export 414 4 ft Zirconium II seamless tubing to West Germany TRIOLO.K Kawecki Berylco industries. Inc 78408 80/06/03 1p
- 8007020238 Forwards DRG Intl.Inc 1tr re export license W/o encl PETERSON.N R Assistant Director for Export/Import & international Safeguards 80/06/18 lp

- 7020260 Fierutive Branch position re DOS application for license to aport 610 mired oxide fuel pins to United Kingdom Ltrs of ssurance enci License should be granted DSENZOL V State, Dept of, Bureau of Oceans & Internat
- 7020274 License for Transnuclear.Inc to export 30.746 kg U. ontaining 1.274 kg U-235.& 129.224 kg natural U to Germany ETERSON.M R Assistant Director for Export/Import & International afeguards NUM-319 80-059/ 80/06/19 2pp
- 7020277 Forwards B00326 license application & favorable recutive Branch views for review Under 10CFR110.Commission eview no longer required W/o encls ETERSON.M R Office of International Programs, Director 80/06/23
- 7020283 Amend 4 to license for GA Co extending expiration date rom 800701 to 820701 ETERSON.M R Assistant Director for Export/Import & International afeguards IEL-740 80706/19 ip
- 7020289 Amend 3 to Livense 3 for Eastman Kodak Co extending spiration date from 800701 to 820701 ETERSON M R Assistant Director for Export/Import & International afeguards 80/06/20 ip
- 7020344 Requests assistance in obtaining necessary ltr of assurance or application for export license ETERSUN-H R Assistant Director for Export/Import & International afeguards 80/06/18 lp
- 7020346 Submits application to amend license to extend expiration ate until 800630.to transfer 0 231 mC: tritium to United ingdom
 UTTME.O KMS Fusion. Inc. (subs. of KMS Industries, Inc.)
- 10/06/05
- 17020349 Requests assistance in obtaining necessary ltr of assurance or application for export license EYERSON.MR Assistant Director for Export/Import & International afeguards 80/06/18 lp
- 17020351 License for Marubeni America Curp to export 27,155 kg U.
- roads) Citemes for marboant America comp to esport 27,255 kg 0, ontaining 800 kg U-235, to Japan 'ETERSON'H R Assistant Director for Export/Import & International afeguards AHO121AH 80/06/18 2pp
- 7020373 License for Ediow Intl Co as agent for Heridian Enterprises a export 508 kg U.contained in 600 kg depleted U oxide lowder, to Talwan "ETERSON.N R Assistant Director for Export/Import & International lafeguards IM-1 80/06/24 2pp
- 17020379 Application by CERAC, inc for license to export 43 94 Eg horium.contained in 50 kg thorium oxide to West Germany, OLTON,E Cerac, Inc. 80/06/20 1p
- 17020383 Application by Isotope Products Labs for license to export g solid curium metal oxide as source w/beryllium holder, o France
- ELM.K Isotope Products Laboratories W/O 7853 80/06/19 1p
- 07020425 Forwards license application, favorable Elecutive Dranch views & proposed license for diport of 27 l kg U to West Jarmany for fuel element fabrication License will be issued
- 1/40 encils

 ATTERBON. H Assistant Director for Export/Import & International Bafeguards B0/06/19 ip
- 07020658 Forwards China Natl Instruments 800606 ltr re use of self-nowered detectors Westinghouse 800611 memo encl PDCHAL, W. F. Westinghouse Electric Corp. 80/06/16 3pp.
-)7020734 Forwards Executive Branch response re encl pending export license application for advance info Requests initiation of final review to facilitate early response to forthcoming action paper Wo encis
 HEA.J R Office of International Programs, Director 80/06/18
- Office of International Programs, Director 80/06/18
- D7030063 Application by Aldrich Chemical Co.Inc for license to export 1 kg deuterium in 5 kg deuterium pride to South (orea
- (orea EDELSTEIN, B Aldrich Chemical Co . Inc (subs of Bigma-Aldrich Sorp > 14/80 80/06/12 1p

- B007030276 Requests assistance in obtaining necessary ltr of assurance for entl B00606 export license application W/o entl PETERSUN,M R Assistant Director for Export/Import & International Bafaguards B0/06/18 ip
- 8007030360 License for Netal Bellows Corp is amended to extend exprastion date until 810730 All other conditions remain unchanged PETERSON M R Assistant Director for Export/Import & International Safeguards A 14471-2 80/04/24 ip
- B007070004 Forwards applications for license to export fuel rod nuclear assay sys & CF-252 source to West Ormany HANSEN.L E Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/06/16 lp
- --8007070006 Application by Exxon Nuclear Corp for license to export 1 09 mg Cf-252 neutron source to West Germany HANSEN.L E Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/06/16 1p
- -- B007070008 Application by Exxon Nuclear Co.Inc for license to export fuel rod nuclear assay sys to West Germany HANSEN,L E Exxon Nuclear Co , inc (subs of Exxon Corp) 80706/14 Jpp
- 8007070007 License for Wastinghouse to export 180 oc: Np-237,contained in 12 radiation surveillance capsules to Taiwan PETERBON, M R Assistant Director for Export/Import & International Safeguards 80/06/24 2pp
- 8007070018 Application by Transnuclear. Inc. to amend license to extend expiration date to 811101
 MATSON, V Transnuclear, Inc. 80/06/18 ip
- B007070023 Forwards application for license export source matt to Italy REENAN.R P Westinghouse Electric Corp ICS-0417 80/06/12 1p
- --8007070024 Application by Westinghouse for license to export 3 7 kg U-235, contained in 617 kg depleted U.to Italy HERSCH.M M Westinghouse Electric Corp ICS-0417 80/06/12 ip
- B007070025 License for GA Co to export 1 035 kg U-235, contained in 5 2 kg U as TRIGA World fuel cluster elements, to Taiwan PETERSON, N R Assistant Director for Export/Import & International Bafeguards 80/06/24 2pp
- 8007070029 Application by Bigma Chemical Co for license to export iO kg deutersum to New Zealand * Bigma Chemical Co (subs of Bigma-Aldrich Corp) D-46 HO/06/13 Ip
- 8007070034 Application by Borg-Warner Corp. Nuclear Valve Div to smand license to extend expiration date to 810701 HAN.S Y Borg-Warner Corp. Nuclear Valve Div CSM/80/256, 80/06/19 19
- 8007070038 ticense for Mitsubishi Intl Corp to export 450 mCi Cf-252. to Japan PETERBON, M R Assistant Director for Export/Import & International Safeguards 60/06/23 2pp
- B007070041 Application by Westinghouse for license to export three WL-6377 compensated ionization chambers to France POCHAL, W.F. Westinghouse Electric Corp. ZE-20359A 80/06/16 ip
- 8007070047 License for Chem-Nucloar Sys, Inc to export auxiliary
- 8007070111 license for GE to export 0 25 kg U-235, contained in 2 5 kg U-85 pellets in zirconjum rode, to Taiwan PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/06/24 2pp
- 8007070125 Submits breakdown for Taiwan fuel designed loading for Mannshann 1 & 2 Total equals 162,911 kg.containing 4,474 kg V-235
 HESS.R J Westinghouse Electric Corp 80/06/19 lp
- 8007070140 Forwards Nukem Ombh of Hest Germany telex re export & storage of 129,200 kg natural U.containing 919 kg U-239, MATSON,V Transnuclear, Inc. 80/06/02 2pp

- B007070145 Forwards Nukem Gmbh telex re delay in export of highly
- Transnuclear, Inc 80/05/09 3pp
- 8007070425 License for Halprin Supply Co to export 125 mCi tritium, contained in foils in Model 1127-E static electricity detection meter, to Singapore PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/06/24 2pp
- 8007090028 Transcript of 800516 open Affirmation Session 80-23 in Washington DC re order in Tarapur export Pp i-3 * Commission 80/05/16 4pp
- ~-8007090030 Informs of correction to SECY-80-238 re proposed exports of fuel & components to Tarapur Commission SECY papers cited are incorrectly referenced Draft memorandum & order encl BHEA.J R Office of International Programs, Director 80/05/13
- ~-8007090033 SECY-80-238A ANAYOUGH SECY-BO-2304 Forwards NMSS technical review for Commission's consideration in conjunction w/review of pending Tarapur fuel & component exports SHEA.J R Office of International Programs, Director 80/05/13
- ~-800707003B Forwards proposed NMSS technical review for Commission consideration re proposed exports of fuel & components to Tarapur BURNETT,R F Division of Safeguards 80/05/12 4pp
- 8007090104 Responds to Subcommittee on Nuclear Regulation 800501 ltr posing questions re Commission approach to foreign health & safety issues Commission issued decision on reactor export to Philippines on 800506 W/response to specific questions AHEARNE, J F Commission 80/06/06 11pp
- --8007070114 Order granting issuance of licenses to Westinghouse for export of reactor to Philippines Separate Commissioner opinions encl
 CHILK:S J Office of the Secretary of the Commission 80/05/06
- 8007090109 License for QA Co to export fuel cluster assembly tools, fuel cluster handling tools, fuel rod insp device & fuel rod storage rack, to Talwan PETERBONN N R Assistant Director for Export/Import & International Bafeguards 80/06/24 1p
- 8007100027 License for Byron Jackson Pump Div.Borg Warner Corp. to export specially designed or prepared parts & components for use in primary coolant pumps & other pumps to Taiwah PETERBONNA R Assistant Director for Export/Import & International Bafeguards 80/06/24 lp
- B007100146 Executive Branch position re Radium Chemical Co.Inc application for amend to license to export tritium to Buitzerland, Belgium & Wost Germany License amend should be granted NGBENZO,L V Stato Dapt of Bureau of Oceans & Internati Environ & Scientific Affairs 80/06/24 2pp
- B007100263 Forwards application by Westinghouse for license to export 6.0 kg U oxide pellets, containing max of 4 5% U-235, to Belgium
 - REENAN.R P Westinghouse Electric Corp IC9-0412 80/06/12 ip
- --8007100271 Application by Wastinghouse for license to export 6 0 kg U axide pellets, containing max of 4 5% U-235, to Belgium KEENAN, R P Westinghouse Electric Corp 108-0412 90/06/12 ip
- B007100281 Forwards application by Mitsui & Co,inc for license to export 99 kg U-235, contained in 3,640 kg UF-6, to Japan BAIRI, T Mitsui & Co , Ltd 80/06/03 ip
- --8007100287 Application by Mitsui & Co. Inc for license to export 99 kg U-235, contained in 3.640 kg UF-6, to Japan TAHA, K Mitsui & Co., Ltd MBK-TR-12 80/06/09 ip
- 8007100341 Requests assistance in obtaining ltr of assurance for encl 800609 application for Export License XSNM-1694 W/o application PETERBON,M R Assistant Director for Export/Import & International Assistant Director for Export/Import & International 80/06/27 ip Bafequards
- 8007110010 Forwards application by Canadian Embassy for license to export 4 x 0 5 g Pu Metal #949 e to Canada HARRISON, J E Laos 80/06/09 lp

- --8007110012 Application by Canadian Embassy for license to export 4 x 0 5 g Pu Metal #949 e.to Canada HARRISON J E Canada 80/06/09 2pp
- 8007110021 Forwards application for license to export U oxide pellets to Belgium KEENAN.R P Westinghouse Electric Corp. ICS-0412 80/06/12 1p
- 8007110029 License for Metal Bellows Corp to export spare nuclear parts to Spain is amended to add another authorized ultimate consignee
 PETERSON.M R Assistant Director for Esport/Import & International
 Safeguards 14845 80/06/27 ip
- 8007110142 Transcript of 800513 closed meeting in Washington.DC re disrussion of Tarapur export license Pp 1-14 * Commission 80/06/19 16pp
- B007110213 ticense for US Dept of Navy to export 3.019 kg depleted U.as component of 20mm ammunition, to Australia PETERSON H R Assistant Director for Export/Import & International Safeguards SER 63/779042 B0/06/27 2pp
- 8007i10218 License for Westinghouse to export three compensated ionization chambers Model WL 6377 to France PETERSON N R Assistant Director for Export/Import & International Bafeguards ZE-20359 80/07/01 1p
- 8007110226 License for Westinghouse to export one proportional counter, Model 4X33785, to France PETERSON.M R Assistant Director for Export/Import & International Safeguards ZE-20356 80/07/01 1p
- 8007110237 Application by Reuter-Stakes, Inc for license to export two fission counters, compensated contration chamber & neutron ionization chamber to Mexico SKARUPA, J D Reuter-Stokes, Inc. 80/06/25 ip
- B007110241 License for Aldrich Chemical Co. Inc to export 1 kg deuterium, contained in 5 kg deuterium oxide to Israel PETERSON M R Assistant Director for Export/Import & International Safeguards 13/80 80/07/02 2pp
- 8007i10252 Requests assistance in obtaining 1tr of assurance for encl BOQ612 application for Export License XSNM-1695 W/o application PETERSONIM R Office of International Programs, Director BO/06/27
- B007:10271 Amend 1 to license for Transnuclear, Inc. adding Allied Chemical Corp as supplier of natural U only PEYERSDN,N R Assistant Director for Export/Import & International Safeguards NUX-319 80-059 80/07/01 1pp
- 8007110275 Forwards application by Mitsul & Co.Inc for license to export 5.429 kg enriched U hexafluoride, enriched to max 3 95%, to Japan SAINI,T Mitsul & Co., Ltd 80/06/12 ip
- --800/110283 Application by Mitsui & Co.Inc for license to export 5,429 kg enriched U hexafluoride,enriched to max 3 95%,to Japan # Mitsui & Co., Ltd MBK-F3-R6 (A) 80/06/12 19
- B007110469 Forwards NUKEM B00611 itr correcting typing error in supplemental info accompanying 800430 export license application & NUKEM 800611 itr to ANL containing addi supplemental data MATSON.V Transnuclear, Inc 80/06/18 7pp
- 8007110480 Requests amend to license to import addl 200 g Pu MAT50N,V Transmuclear, Inc. 80/06/18 1p
- BOO7:10491 License for Edlow Intl Co to Export 0 50 g Pu, as Pu sulfate tetrahydrate: to Japan PETERSON, M R Assistant Director for Export/Import & International Bafeguards 8-89-79 BO/06/27 2pp
- BOO7i10528 Submits application to amend license to export adding Fuerios Electricas de Cataluna as ultimate consignee ROGERS.W F Metal Bellows Corp BO/06/26 1p
- 8007140253 Forwards Transputlear, Inc 800418 ' resease expert license application W/o PETERBON, M R Assistant Director for Exp Safeguards 80/06/30 ip

- 8007140258 Advises that SNM shall be exported under general incense regulations effective 800421 Application is being processed as component license URIGHT, B L Office of International Programs: Director 80/04/18
- 8007140266 Advises that 15-day waiting period requirement was waived for incense applications to export byproduct matl & components to Euron West Ourman facility PETERSONIM R Assistant Director for Export/Import & International Bafeguards 80/06/30 Ip
- --8007140274 License for Exxon Nuclear Co.lnc to export one fuel rod nuclear assay sys to Hest Germany PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/06/30 lp
- 8007140203 Advises that 15-day waiting period requirement was walved for license application to export hyproduct matl & components to Exian West German facility PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/06/27 ip
- --8007140288 License for Exxon Nuclear Co. Inc to export 1 09 mg Cf-252 neutron source to West Germany PETERSON M R Assistant Director for Export/Import & International Safeguards 80/06/27 2pp
- 8007140293 Amend) to license extending expiration data from 801101 to 811101 & adding two suppliers All other export conditions remain unchanged
- PETERSON M R Assistant Director for Export/Import & International Bafeguards 80/06/30 pp
- 8007140539 SECY-80-301 907140539 SECY-80-301
 Requests review of proposed issuance of iscense for GE to export components to Finland Equipment destined for country not previousty authorized to export per Nuclear Nonproliferation Act of 1978 Recommends issuance SHEA.J R Office of International Programs, Director 80/06/20
- --8007140546 Forwards application for license to export components to Finland Ltr of assurance & draft license encl HILSON, B D General Electric Co BDW-80013 B0/01/30 3pp
- 8007140552 SECY-BO-294 OFFICE OF Executive Branch response on pending license for Union Carbide Corp to export U-235 to France SHEA.J R Office of International Programs, Director 80/06/18
- --8007140360 Executive Branch position re application by Union Carbide Corp to export 9 85 kg U-235 enriched to 93% U to France License should be issued Ltr of assurance encl NOSENZOL V State. Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/11 2pp
- B007140367 Forwards application for export license for minor nuclear supert Ltr of assurance required PETERSON.M R Assistant Director for Export/Import & International Safeguards B0/06/27 ip
- 8007140577 Amend 1 to license for Radium Chemical Co Inc. extending expiration date from 800601 to 810701 & permitting change in intended distribution of tritium gas PETERSON, HR Assistant Director for Export/Import & International Safeguards 80/07/03 1p
- 8007140579 License for Westinghouse to export proportional counter to be used as neutron detector for neutron source strength determination in GKSB research reactor, to West Germany PETERSONN NR Assistant Director for Export/Import & International Safeguards 80/07/03 ip
- 8007140583 Forwards Executive Branch responses on pending applications for Export Licenses XSNM-1431 & XSNM-1564 which require Commission review Final review should begin as soon as possible W/o encls
 SMEA-J R Office of International Programs, Director 80/07/01
- 8007140586 License for DDE to Export U-235, contained in 27 1 kg U, to West Germany PETERSON. M R Assistant Director for Export/Import & International Safeguards 80/07/03 2pp
- 8007140588 License for Isotope Products Lab to export ig Cm-244, solid NOTABLE DESIGNATION OF THE STATE OF THE STAT

- 8007140596 License for Teledyne Wah Change Albany to export 400 lbs Zircaloy-2 tube shells to Norway PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/30 2pp
- 8007140603 License for Cerac, Inc to export 43 94 kg thorium, contained in 50 kg thorium oxide, to West Germany PETERSON, H R Assistant Director for Export/Import & International Safeguards 80/06/30 2pp
- 8007i40696 Discusses IE insp of License XSNM-i426 on 800610 No noncompliance noted Major areas inspected compliance w/requirements of 10CFR70 & 71 re packaging of radioactive satl for transport NORDERHAUD, L R Region 5, San Francisco, Safeguards Branch
- B007140711 License for Aldrich Chemical Co to export i kg deuterium, contained in 9 kg deuterium oxide, to Bouth Korea PETERBON, M R Assistant Director for Export/Import & International Bafeguards 14/80 80/07/02 2pp
- 8007130001 Forwards application for export license for minor nuclear export Ltr of assurance required W/o enci PETERSON,N R Assistant Director for Export/Import & International Bafaguards 80/07/02 ip
- 800715D003 License for Sigma Chemicai Co to export 10 kg deuterium Oride to Franco

 Stide to Franco

 PETERSON. H R Assistant Director for Export/Import & International

 Safeguards D-45 80/07/02 2pp
- 8007150008 License for Aldrich Chemical Co to export 1 kg deuterium Oxide to New Zealand
 PETERBON.H R Assistant Director for Export/Import & International
 Reference 10-60 60/07/02 2pp
- 8007150012 License for Aldrich Chemicol Co to export 1 kg deuterium, contained in 5 kg deuterium oxide, to Venezuela PETERSON, M R Assistant Director for Export/Import & International Safeguards 11/80 80/07/02 2pp
- 8007150030 Cancels Export License Application X8NM-1486 since matl cen be exported under licensee general license HRIGHT.B L Office of International Programs, Director 80/06/30
- 8007150034 Cancels Export License Application XRNM-1631 sincs matl can be exported under licensee general license WRIOHT.B L Office of International Programs, Director 80/06/30
- B007130036 Discusses Transnuclear 800314 application to export 103 258 kg U.enriched to 93 3% U-235, to Hest Germany for conversion by NUMEN & fabrication at Hobeg into THTM fuel Forwards 1tr justifying need for highly enriched U MENNICKEN, J B Euratom Supply Agency (Belgium) 80/06/23, 4pp
- --B007150040 Provides technical background info necessary for US evaluation of technical & economic justification for Transnuclear export of highly enriched U to Hest Germany to fuel THTR reactor MATZ, Q . MULLER, H Nukom OmbH 80/05/21 6pp
- BOO7150039 Cancels Export License Application XSNM-1487 since metl can be exported under licensee general license WRIGHT.D L Office of International Programs, Director 60/06/30
- BOO7150050 BECY-BO-29B
 Recommends return of Rockwell Intl application for license to maport specially-designed valve to India w/o action Executive Branch prefers returning w/o action as opposed to denial due to political differences involved Draft ltr snct. SHEA, J R Dffice of International Programs. Director 80/4
- 8007150062 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl. PETERSON M R Assistont Director for Export/Import & International Safeguards 80/07/02 1p
- 8007190063 License for Aldrich Chemical Co to export 5 kg dautarium, contained in 20 kg dautarium oxide to Balgium PETERSON,M R Assistant Director for Export/Import & International Bafaguards (2/80 80/07/02 2pp

- B007i50073 License for Transhuclear, Inc to export 32 737 kg U-235, contained in 35 088 kg U to Sweden PETERBON.M R Assistant Director for Export/Import & International Bafeguards B0/06/30 2pp
- 800715007B License for Transhuclear, Inc to export 67 736 kg U-235, contained in 72 6 kg U. to France PETERSON.M R Assistant Director for Export/Import & International Bafeguards 80/06/30 2pp
- BOO713033 Forwards supplemental info on inventory forwarded directly to US Dept of State by Euraton Supply Co
 MATSON, V Transnuclear, Inc. 80/06/18 3pp
- 8007150836 Forwards Executive Branch response on pending application to export Po & U to United Kingdom Application will require Commission review Application & amend encl W/o encls SHEALJR Office of International Programs. Director BO/06/27 ip
- GOO7160394 Forwards application by Monsanto Research Corp for license to export one neutron source Model 2765 containing approx 1 mg Cf-252, to India HOADLEY.S D Monsanto Research Corp 191-9AO(I) 80/07/01 ip
- ~-8007160399 Application by Monsanto Research Corp for license to export one neutron source Model 2765.containing approx 1 mg Cf~252. to India HOADLEY.S D Monsanto Research Corp L91-9AU(I) 80/07/01 in
- 8007i40403 Application by Aldrich Chemical Co.Inc For license to export 1 kg deuterium.contained in 5 kg deuterium oxide.to Jamaica EDELSTEIN.8 Aldrich Chemical Co., Inc. (subs of Bigma-Aldrich Corp.) 15/80 B0/06/27 ip
- 8007i40824 Cancels Export License Application XSNM-1549 since matl can be exported under general component license WRIGHT, B L Office of International Programs, Director 80/06/30
- 8007170003 Executive Branch position re Tech/Ops application for license to export 5.000 kg depleted U.in form of metal shielding to Albanla, Bulgarla, Czechoslovakla, West Germany, Hungary, Mongolia, Poland & Soviet Union NOSENZO, L. V. State, Dept of, Bureau of Oceans & Internatl Environ & Bcientific Affairs 80/07/07 2pp
- B007170072 Executive Branch position re Edlow Intl Co application for license to export 10.000 Ci tritium in bulk gaseous form to Canada License should be granted MOSEMZOL V States Dept of, Bureau of Oceans & Internatl Environ & Sciuntific Affairs 80/07/03 2pp
- BOO7170077 License for Sigma Chemical Co to export 10 kg deuterium oxide to New Zealand PETERSON.M R Assistant birector for Export/Import & International Bafeguards BO/07/08 2pp
- BOO7170080 License for Westinghouse to export three compensated ionization chambers to France PETERSON.M R Assistant Director for Export/Import & International Bafeguards BO/07/QB lp
- 8007170176 Response in apposition to Ctr for Development Policy 800613 petition to intervene re nuclear reactor export to South Korea If petition granted.public hearing must be rejected per applicable statute & regulations W/Certificate of Syc BECKER.J M Office of the Executive Logal Director 80/07/14 24pp
- 8007170191 Response in opposition to Ctr for Development Policy 800613 petition to intervene re nuclear reactor export to South Korea Public participation will adversely affect public interest Certificate of Svc encl
 BETTAUER.R J State. Dept of 80/07/14 30pp
- B007170204 Executive Branch position re Halprin Supply Co application for license to export approx 125 mCi tritium to Singapore License should be granted MOSENZOL V State, Dept of. Bureau of Oceans & Internatl Environ & Bcientific Affairs B0/06/12 2pp

- 8007170223 Executive Oranch position re OA Co application for liconse to export 1 035 kg U-235 contained in 5 2 kg U to Taiwan Ltrs of assurance encl License should be granted NDERXOL V State Oept of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 5pp
- 8007170229 Ltr of assurance re Transpuclear. Inc 800523 application for license to export 704 997 kg U-235, contained in 21,044 7 kg total U & 0 034 kg U-235, contained in 1 kg total U, to Switzerland MARCHALAD European Communities. Commission of 80/06/13 1p
- 8007i70235 Executive Branch position re Gladi: Corp application for license to export 40:000 lb Zircaloy-4 trex tubes to Taiwan Ltr of assurance encl License should be granted NOSENZOL V State, Dept of. Bureau of Dicens & Internati Environ & Scientific Affairs 80/06/12 4pp
- 8007170244 SECY-80-317
 Forwards Esecutive Branch responses re two pending export
 license applications for Taiwan
 SREA, J.R. Office of International Programs, Director 80/07/01
- --B007:70251 Forwards Executive Branch analysis re Westinghouso application for license to export 8.845 kg U-235.contained in 325.822 kg U.to faiwan NDSENZOL V State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 13pp
- --8007170258 Application by Westinghouse for license to export V dioxide sintered pellets encapsulated in smaled fuel rods & assembled into fuel assemblies to Tojuan * Westinghouse Electric Corp 109-7823 78/11/17 lp.
- 8007170235 Executive Branch pusition re Tech Aid, Inc application for license to export 8,613 343 Kg heavy water to Taiwan End use statement encl HELFRICH, G.F. State, Dept of, Gureau of Oceans & Internat! Environ & Scientific Affairs 80706/26 2pp
- --8007i70262 Forwards supplementary and use statement to application for license to export 4 tons heavy water to Taiwan WU.X. Coordination Council for North American Affairs 80/05/14 280
- 8007170523 SECY-80-318
 Recommends approval of proposed license to allow Nissho-Iwai
 American Corp to export 47 162 kg U & 44 003 kg U-235 to
 Japan
 SHEA, J R Office of International Programs, Director 80/07/01
 Spp
- --8007170534 License for Nissho-Iwas American Corp to esport 44 003 kg U-235.contained in 47 162 kg U.to Japan PETERSON.M R Office of International Progrems. Director 80/07/01 2pp
- 8007180449 Forwards application for license to export 40 g U-235, contained in 1 226 g U. to France
 KEENAN.R P Westinghouse Electric Corp ICS-0456 80/06/17 1p
- --8007180453 Application by Westinghouse for license to export 40 g U-235 contained in 1.226 g U to France KEENAN.R F Westinghouse Electric Corp ICS-0456 80/06/19 ip
- 8007210009 SECY-BO-316
 Recommends 125uance of propused license for Transnuclear: Inc
 to export 39 O77 kg U, enriched to 93 3%, to Japan Forwards
 Executive Branch views re proposed export
 SHEALJ R Office of International Programs, Director 80/07/01
 5pp
- --8007210076 Forwards Executive Branch position to Transmuclear. Inc & Nissho-Iwai American Corp applications for licenses to export U-235 to Japan Licenses should be conditioned at noted NOSENZO, L V State, Dept of, Nosenzo, L V State, Dept of, Scientific Affairs 80/01/29 6pp
- --8007210083 License for Transnuclear, Inc to export 39 077 kg V.enriched to 93 3%, to Japan PETERSON M R Assistant Director for Export/Import & International Safeguards NUK-231 78-169 80/07/01 2pp
- B007210073 Executive Branch position re DOE application for license to export 5 37 kg U-P35, contained in 27 i kg U-to West Germany Ltr of assurance encl License should be granted, NOSENOL V State Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/06/11 3pp

- 8007210096 Executive Branch position re Westinghouse application for license to export 8.045 kg U-235, contained in 325.022 kg U, to Taiwan Ltr of assurance encl License should be granted NOSENZO, L V State.Dept of, Dureau of Oceans & Internati Environ & Scientific Affairs 80/06/12 13pp
- 8007210124 Amend i to license for Borg-Warner Corp increasing value of squipment & extending expiration date PETERSON.M R Assistant Director for Export/Import & International Safeguards A493531 80/06/27 ip
- 8007210129 Application by Sigma Chemical Co for license to export compounds containing deuterium to Australia STERN.H C Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-47 80/06/23 ip
- 8007210316 Application by Reuter-Stokes Inc for license to export radiation detectors Model RS-(L-0201-231, to Spain End use statement encl * Reuter-Stokes Inc 80/06/30 2pp
- --8007210318 Advises of desire not to apply for extension of License XSNM-1397, due to deletion of requirement for SNM license for detectors EECKHOUT.A Router-Btokes. Inc. 80/06/30 ip
- B007220107 Amends License ISNM-1699 authorizing import of 243 31 kg of U.containing 182 72 kg U-239 & 349 3 g of produced Pu Proposed amend represents no substantial change to circumstances involved in issuance of basic license MDDRE-N Office of International Programs. Director 80/07/03 Zpp
- ---B007220il4 Amends Transnuclear Inc License ISNM-1699 Increasing quantity of Pv authorized for export to 545 G g FETERSUM N R Assistant Director for Export/Import & International Safeguards B0707703 ip
- 8007220207 Add1 response to FOIA request for documents re proposed nuclear reactors located near Gyaema. Korea Forwards JR Shea draft memo to Commissioners SECY-50-229 is located in DC PDR Info partially withheld (ref FOIA Exemption 5) FELTON J M Davision of Rules and Records 80/07/15 2pp
- --8007220214 Braft Commission paper re licenses for GE to export two reactors XNU 7 & 8 to Korea Reactors would be located on Gyaems Forwards final Executive Branch views Info partially withheld (ref FOIA Exemption 8) SMCA.J.R Office of International Programs, Director E0/07/15 Sno
- 1007220540 Response in opposition to Ctr for Law & Development Policy 800413 petition to intervene re licenso for reactor export to South Korea lasues raised re environ impacts in foreign countries are beyond NRC jurisdiction W/Certificate of Svc. CDMAN, B Z . KCRRICK, J R Westinghouse Electric Corp CDMAN, B Z Eckert, Seamans, Cherin & Mellott 80/07/14 15pp
- 1007230557 Forwards FR notice of applications for export licenses received SHEA, J.R. Office of International Programs, Director 80/07/03 ip
- -8007230546 Notice of applications for export licenses received BHEALJ R Office of International Programs, Director 80/07/03 2pp
- OO7230502 Response in opposition to Ctr for Development Policy 800520 petitions to intervene re standing as matter of right NRC will submit upinion re possibility of discretionary hearing after Executive Branch views Cortificate of Bvc encl BECXER.J M Office of the Executive Legal Director 800707/18.
- 007230719 Discusses application for license to export waste gas mgt treatment sys to South Africa Application has been forwarded to US Dapt of Commerce which assumed licensing authority over such items on 800628 PETERSON
- 107230723 Discusses application for license to export two personnel air locks to Bouth Africa Application has been forwarded to US Dept of Commerce, which assumed licensing authority over such items on 800625
 PETERSON M R Assistant Director for Export/Import & International Safeguards 80/07/16 ip

- 8007240030 Forwards application for license to export 41 59 g U. containing 0 47 g U-235, & 41 59 g U.containing 0 34 g U-235 to Japan SHIMAS Hitsubishi International Corp (subs of Hitsubishi Corp.) ED/06/20 1p
- --B007240036 Application by Mitsubish; Intl Corp for license to export
 41 59 g U.containing O 47 g U-235 to 41 59 g U.containing
 O 34 g U-235, to Japan End use statement encl
 SHIMA.S Mitsubishi International Corp (subs of Mitsubishi
 Corp) 80/06/20 3pp
- 8007240042 Requests Executive Branch position re Reuter-Stokes Inc application for license to export components for research reactor to Mexico PEYERSON, M & Assistant Director for Export/Import & International Safeguards 80/07/07 ip
- 8007240046 Informs that license application for export of 8 5 metric tons of heavy water to Taiwan is being returned NRC has received info that mot 1 is no longer required by contamer since project has been cancelled PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/07/07 ip
- 8007240052 Notifies that figurer-Stokes Inc has requested withdrawal of syport license application PETERSON, MR Assistant Director for Export/Import & International Bafeguards 80/07/10 ip
- BOO7240053 Discusses IE insp of Import License ISNM-77009 on BOO4ii No noncompliance noted Major areas inspected selected exam of procedures & records, intervieus w/portonnel & observations by inspector Portions withhold (ref iOCFR2 770)
 MARTIN, W 0 Region i. Philadelphia, Bafeguards Branch BO/05/20, 10
- --B007240089 IE Insp Rept ii-695/80-02 on B004ii No noncompliance noted, Major areas inspected irradiated fuel shipment general requirements for transportation Portions withheld (ref 10GFR2 790)
 EMITH 0 C Region i. Philadelphia, Office of the Director DEVLIN, J W Region 1, Philadelphia, Safeguards Branch 80/05/13 ip
- 8007240224 Forwards application for license to import 80,000 kg U, enriched to less than 3 5% U-235 from USBR HANSEN,L E Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/06/23 ip
- --8007240247 Application by Exxon Nuclear Co.Inc for license to import 80.000 kg U.containing up to 2.800 kg U-235, from UBSR HANSEN,L E Exxon Nuclear Co. Inc (subs of Exxon Corp) 80706/23 ip
- B007240362 License for Edlow Intl Co to export 10,000 Ci tritium gas to Canada PETERSON, M R Assistant Director for Export/Import & International Bafeguards B0/07/15 ip
- 8007240370 Amend i to license for Nissho-Iwai Ambrican Corp extending expiration date from 800801 to 810801 PETERSON, H R Assistant Director for Export/Import & International Bafeguards MACPJ 2473KY 80/07/15 1p
- GOO7240370 License for DQE to expart 6 45 kg U-235 contained in 32 6 kg U metal; to France PETER50N, H R Assistant Director for Export/Import & International Safeguards 80/07/11 2pp
- BOO7240377 License for GE to export 34 neutron detectors, Model NA-200to Finland PETERSON, MR Assistant Director for Export/Import & International Bafeguards BDW 80012 80/07/15 ip
- E007240405 License for Nistho-Iwai American Corp to export 44 003 kg U-235.contained in 47 162 kg U metal to Japan PETERSON, M R Assistant Director for Export/Import & International Bafeguards NIAC-78-1103 E0/07/14 2pp
- 8007240410 License for Westinghouse to export 40 g U-235, contained in 1,226 g U in 30-A cyclinder to France PETERSON, MR Assistant Director for Export/Import & International Bafeguards 108-0456 60/07/15 2pp
- 8007240418 License for Transnuclear, Inc to export 704 997 kg U-235, contained in 21,044 7 kg U. & 0,034 kg U-235, contained in 1 kg U. to Buitrerland PETERSON, H R Assistant Director for Export/Import & International Safeguards RBU 331 80-1201, 80/07/14 2pp

- 8007240421 License for Canadian Embassy to export 2 g Pv to Canada PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/07/14 2pp
- B007240434 Application by Ediow Intl Corp for license to export 20 micrograms PU-242 in tracer solution to Japan HARMON, D W Ediow International Co SHIB-4 80/06/30 ip
- 8007240440 Executive Branch position re GE application for license to export neutron detectors to Finland License should be granted NOSENZO.L V State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/07/07 3pp
- B007240447 Ltr of assurance re Westinghouse license to export 10 g U-235.contained in 1.226 g U. to France MARCHAL, J European Communities, Commission of 80/07/09 lp
- B007240472 Forwards B00702 ltr of assurance re application for license to export 40.000 lb Zircaloy-4 trex tubes to Taiwan DEAN.D Taiwan (Republic of China) 80/07/07 2pp
- B007230030 Discusses application for license to export inservice insp sys to South Africa NRC forwarded application to US Dept of Commerce, which assumed export licensing authority over such items on B00625 PETERSON, H R Assistant Director for Export/Import & International Safeguards 80/07/17 lp
- B007250033 Discusses application for license to export four sets of personnel air locks to South Africa NRC has forwarded application to US Dept of Commerce, which assumed export licensing authority over such items on 800625 PETERSON, HR Assistant Director for Export/Import & International Bafeguards 80/07/17 1p
- 8007250041 Discusses application for license to export ultrasonic insp sys to Argentina NRC has forwarded application to US Dept of Commerce, which assumed export licensing authority over such items on 800625
 PETERBON, M R Assistant Director for Export/Import & International Safeguards 80/07/16 1p
- 8007250555 Ltr of assurance re export of 213 kg U-235.contained in 6,155 kg U.to Japan NIYABAYASH1.M Japan 80/03/27 ip
- 8007250563 Forwards GE 800617 ltr re license application W/o encl PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/07/15 ip
- 8007250656 Forwards draft Commission Action Papers re applications for exports to Taiwan Requests comments as soon as possible BHEALJ R Office of International Programs. Director 80/07/18 1p
- B007250685 Response in opposition to Ctr for Law & Development Policy B00620 petition to intervene Legislative history of Nuclear Non-Proliferation Act provides guidance re public participation W/Certificate of Svc COWAN, B Z, XENNICK, J R Westinghouse Electric Corp COWAN, B Z Eckert, Beamans, Cherin & Mellott B0/07/21 13pp
- BOO7250714 License for Sigma Chemical Co to export 10 kg deuterium cride to Australia PETERSON'N R Assistant Director for Export/Import & International Safeguards D-47 80/07/14 2pp
- 8007280078 Returns 800314 application for license to export valve to India due to Executive Branch position that proposed export does not meet Atomic Energy Act criteria W/o encl SHEALJR Defice of International Programs, Director 80/06/14
- BOO728D1i7 Amend 1 to license for OE changing name of ultimate consignee to Studsvik Energiteknik AB.in Sweden PETERBON,M R Assistant Director for Export/Import & International Bafaguards BDW 79202 80/07/17 ip
- BOO7280131 Confirms telcon that qualification program for subj license will require 46 BWR fuel segments of which 20 will be unirrediated MILBON.B D General Electric Co BDW-B0067 80/06/17 ip
- 8007280223 Application by Reuter-Stokes, Inc. for license to export one fixsion counter, Model RS-PA-1408-110, to Uraguay SKARUPA, J D Reuter-Stokes, Inc. 80/07/22 lpp

- 8007280289 Forwards 800707 application % proposed license for export of 90,800 kg depleted U to Canada Executive Branch position not required License will be issued W/o enc? PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/07/15 ip
- 8007280293 Returns 780918 application for license to eigert 40.000 lb Zircaloy-4 trex tubes to Taiwan due to American Inst 800702 cancellation of order PETERSON-M R Assistant Director for Export/Import & International Safeguards 80/07/15 1p
- 8007280360 Forwards application for license to export spare parts used in refueling sys that loads or unloads fuel elements into reactor to Cananda SCHAUB, J B General Motors Corp. 80/07/07 ip
- --8007280366 Application by General Motors Corp for license to export spare parts in refueling sys that loads or unloads fuel elements into reactor to Canada SOKOLOWSKI.O General Motors Corp 83344 80/07/01 ip
- B0072B0372 Application by Westinghouse for license to export one compensated innization chamber. Model ML-230B4.to Japan PACHAL.W F Westinghouse Electric Corp ZE-60185 80/07/OB 3pp
- 8007280383 Application by Air Products & Chemicals, Inc for license to export 54 3 g deuterium to United Kingdom NGVAKGVICH.D Air Products & Chemicals, Inc 80/07/09 2pp
- B007280393 Application by Sigma Chemical Co for license to export compounds containing deuterium to France STERN, W C Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-48 80/07/10 Ipp
- 8007280397 Forwards application to export 198,900 lb depleted U, contained in 200,000 lb depleted U (0 75% titanium alloyed), to Canada SCHAEFER.M R RM1 Co , RM1 (stanium 80/07/07 io
- --8007280403 Application by RMI Co Extrusion Plant for license to export 198.500 lb depleted U.contained in 200.000 lb depleted U (0 75% titanium alloyed), to Canada SCHAEFFER, M R RMI Co , RMI Titanium 80/07/07 2pp
- 8007280407 Requests amend to export license to reflect new ultimate consignee
 HILSON, B D General Electric Co R0/06/17 ip
- 8007280464 Requests amend extending export license YAMANA, K. Nissho-lwai American Corp. MACPJ 2473KY 80/07/03 ip
- 8007280473 Requests import license to reimport 10 kg highly enriched U-235, contained in 55 fuel elements, along w/recovered scrap math. From France
 BALALIS.C 0 Union Carbide Corp 80/07/02 ip
- B007280517 Requests Executive Branch position re Nonsanto Research Corp application for license to export Cf-252 neutron source to India PETERSON.N R Assistant Director for Export/Import & International Safeguards 80/07/10 ip
- 8007280525 Requests Executive Branch position re Transnuclear, Inc application for license to export SNM to The Netherlands PETERSDN.M R Assistant Director for Export/Import & International Bafeguards 80/07/14 ip
- B0072B0535 Requests Executive Branch position re Mitsubishi Intl Corp application for license to export SNM, in form of Make tubes, to Japan PETERSON, M R Assistant Director for Export/Import & International Safeguards B0/07/14 ip
- B007280547 Executive Branch position re Westinghouse application for amend to export license extending expiration date to Bit23i MOSENZOLL V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/07/08 2pp
- 8007280559 Executive Branch position re Eddew Intl Co application license to export 3 3 mg CF-252 to East Germany License should be granted NOSENZOL V State.Dept of, Bureau of Oceans & Internation Scientific Affairs GO/07/ji 2pp

- BOO7280569 Amend I to license for Integrated Photomatria Inc changing quantity from 528 micrograms U-235 to 528 mg U-235 (99 9% enrichment)
 PETERSON, M.R. Assistant Director for Export/import & International Safeguards 80/07/14 1pp
- B007290025 Submits application for license to import 15,000 kg U, containing 225 kg U-235, from France MATSON, V Transnuclear, Inc 80-152/02 80/07/03 3pp
- 8007290027 Submits application for license to import 14,000 kg U. containing 140 kg U-235. from France
 MATSON, V Transnuclear, Inc 80-151/01 80/07/07 3pp
- 8007290044 Ack receipt of 800906 itr forwarding Executive Branch position re Westinghouse application to export two power reactors to South Korea Questions impact of recent political developments on export' SHEA.J R Office of International Programs, Director 80/06/26
- 8007290212 Responds to 780929 request for Executive Branch position re Oladix Corp application to export 40.000 to of Zircaiou-4 tubing Applicant abandoned request on 800708 HELFRICH.G F State, Dept of Bureau of Oceans & Internati Environ & Belentific Affairs 80/07/11 ip
- 8007290390 Submits application for license to import 40,000 kg U. containing 140 kg U-235.from France
 MATSON.V Transnuclear, Inc 80-150/02 80/07/07 3pp
- 8007290446 Forwards application by Transnuclear, Inc for license to export 20 050 kg U.containing 18 707 kg U-235 to The Netherlands MATSUN.V Transnuclear, Inc 80/07/03 lp
- --8007290452 Application by Transnuclear Inc for license to export 20 050 kg U.containing 18 707 kg U-235, to The Netherlands
 Transnuclear, Inc. (NUK-333)80-149 80/07/03 4pp
- 8007290460 Forwards application by Marubeni America Corp for Ilcense to export 156.333 kg U.containing 3.486 kg U-235 to Japan NAKAI, T Marubeni America Corp (subs of Harubeni Corp) MAS-7408 80/07/11 1p
- --8007290467 Application by Marubeni America Corp for license to export 156.333 kg U.containing 3.486 kg U-235.to Japan NAKAI.T Marubeni America Corp (subs of Marubeni Corp) SK-1169/2K0170 S0/07/11 1p
- 8007270857 Application by Reactor Experiments, Inc for license to export 62 4 mg U-235, contained in 62 5 mg U, to Japan Ltr of assurance encl * Reactor Experiments, Inc. 080 80/07/15 2pp
- 8007290882 Forwards 600529 telet to Soviet Union re request for U-308 stds. to be forwarded to State Dept Further communications or developments per application will be forwarded MULLER. L DRG International Inc 80/06/04 2pp
- 8007300037 License for Reuter-Stakes to export one radiation detector, Nodel RS-C3-2510-14, to Canada DEVINE, J B Assistant Director for Export/Import & International Safeguards V-8517 80/07/23 2pp
- 8007300301 Forwards Dfc of Nurlear Reactor Regulation assessment of potential radiological effects of Korean Nuclear Power Station on global commons Assessment represents reasonable upperbound appraisal of potential plant releases DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/01 Spp
- 8007310018 Requests that application to export tritium to Yugosiavia be withdrawn, on behalf of Radiochemical Ctr MARKON, D W Edlow International Cc 80/07/18 ip
- B00731002B Ltr of assurance re Mitshubishi Nuclear Fueld Co application for license to export 377 kg U-235 contained in 14.000 kg U.to Japan HIYADAYABHI.M Gambia 80/07/14 lp
- 8007310039 Forwards application for export license for minor nuclear export Ltr of assurance required W/o enci DEVINE.J B Assistant Director for Export/Import & International Bafeguards 80/07/22 ip
- B007310042 Submits application to amend license to extend expiration date to B51001
 WILSON, B D General Circtric Co BDW-80074 80/07/07 lp

- 8007310044 Submits application to amend license to extend expiration General Electric Co RDW-80073 80/07/07 1p
- 8007310066 Submits application to amend ilcense to export 28 elements consisting of seven strings of four detectors each, to West Commany
 WILSON B D Deneral Electric Co , Nuclear Energy Products Div
 BDW-BOOBO BO/07/15 1p
- 8007310069 Forwards application for license to export 12 samples of U dioxide pellets earh yr for five yrs.each shipment containing 7 g U-235, to Switzerland
 KEENAN.R P Westinghouse Electric Corp ICS-0512 80/07/01 ip
- --B007310073 Application by Westinghouse for license to export 12 samples of Y dioxide pellets each ur for five yrs.each shipment containing 7 g U-235, to Switzerland KEERANN R P Westinghouse Electric Corp FE-20162 80/07/01 lp
- B007310082 Application by Matheson Gas Products for license to export Bize 3 cylinder containing 500 liters deuterium to Brazil F18HER. H F Matheson Gas Products 3532 X 60/07/11 2pp
- 8007310087 Application by Reuter-Btokes for license to export 1 4 g U dioxide on internal surface of Model RS-C3-2510-114 radiation detector, to Canada Ltr of assurance enci SKARUPA, J D Reuter-Stokes, Inc V-8317 80/04/17 2pp
- 8007310194 Requests Executive Branch position re Marubeni America Corp application for license to export SNN to Japan DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/07/22 ip
- 8007310197 License for QE to export miscellaneous replacement or spare parts & components to Finland PETERSON, M R Assistant Director for Export/Import & International Bafeguards BDW-80013 80/07/10 ip
- BOO7310232 Responds to FOIA request for documents re export of SNK & replacement parts to India Forwards documents listed in App A. Documents will be placed in PDR FELTON.J M Division of Rules and Records BO/07/24 3pp
- ---8007310247 Updates 800403 analysis of fuel requirements for Tarapur l & II Analysis is based on more detailed & current info Provides discussion, conclusions, refueling schedule & projected operating schedule for reactor GS Bedi tr encl PCDERSEN. M. Office of Policy Evaluations 79701/16 9pp
- --8007310280 Provides supplementary info re Tarapur reactor fuel requirements, in response to Commissioner Ahearns question re basis for fuel fabrication time DDB provided 9-month fabrication period inadequate data available for analysis PEDERSEN.K Office of Policy Evaluations 79/01/18 2pp
- --8007310260 Lists questions re review of License X8NM-1379 concerning proposed export of low enriched fuel to India Requests Executive Branch response SHEALJ R Office of International Programs, Director 79/05/25
- --8007310266 Forwards updated analysis of estimated fuel requirements for Tamapur reactors, reflecting fuel covered by application XBNM-1379 W/o encl BEVINE.U Defice of Policy Evaluations 79/06/07 ip
- --8007310270 Application by GE for license to export six traversing incore probe detector assemblies to India WILSON B D General Electric Co BDM-79122 79/05/07 ip
- 8007310492 Application by Mitaubishl Intl Corp for license to export 450 nCi Cf-252 cormet wire to Japan KUGE,T Hitaubishi International Corp (subs of Mitaubishi Corp). PIT-L-1812 80/07/22 ip
- BOO7310484 Application by Sigma Chemical Co for license to export compounds containing deuterlum to Canada STERN, M C. Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-49, BO/07/23 ip
- 8007310489 Forwards application for license to export reactor vessel gaskets, retaining clips & retaining clip screws to South Korea MUIR.H B Babcock & Wilcox Co 80/07/18 ip

--8007310490 Application by B&W for license to export reactor vessel gaskets, retaining clips & retaining clip screws to South Korea MUIR, HS Babcock & Wilcox Co 788-998052-51 80/07/17 ip

8007310511 Advises that NBS confirmed that matl requested for siport on application is in sensing components installed in instruments Enriched U could be exported under general license Byproduct license required to export instruments WRIGHT, B L Office of International Programs, Director 80/07/24 ip

8007310520 Application by Agip USA Inc for license to export radioactive ref sources to Italy End use statement entl * AGIP USA. Inc 80-64203-2 80/07/07 Spp

8007310522 Amend I to license for QE extending expiration date to B31001 & clarifying categories of parts & components authorized for export to West Germany DEVINE, I Assistant Director for Export/Import & International Bafeguards 80/07/23 ip

i I		
•		

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this indefindicates that the document is an enclosure to anoth document. To obtain the accession number of the princip document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Princip, Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUT i con	ACCEBBION NUMBER	SUBJECT CATEQUAY
ABBOTT, W S	8007150318*	70-2651	AHEARNE, J F	8007230108	50-320 H	ALDERSON, C. E	0007170550	44
ABERCROMBIE, H	8007220342	50-259 R	AHEARNE, J. F	8007020303	50-320 U	ALEXIS, C. P	8007170559	50~550
ABERCROMBIE, H	8007220481	50-259 R	AHEARNE, J F	8007020129	COMMISSION		8007010185*	40~6789
ABERCROMBIE, H	8007110271	50-260 8	AHEARNE, J. F	8007070104		ALGER, D. M	8007140351	50~186
ABERCROMBIE, H	8007110425	50-296 B	AHEARNE, J F	8007010547	50-350 b	ALLAN, J ALLEN, J	8007280408* 8007070079*	50~280 50~293
ABERCROMBIE, N	8007290864	50-259 g	AHEARNE, J. F	E007110346	50-320 н	ALLEN, J	B007070075*	50~280
ABERCROMBIE, H	8007140552	50-259 R	AHEARME, J. F	8007080076	COMMISSION	ALLEN, J	8007300412	50~280
ABGRAB, K	8007100268*	50-206 R	AHEARNE, J F	8007110266	COMMISSION	ALLEN, B D	8007270647	50~275
ABLER, W L	8007020452	PR	AKEARNE, J F	8007230735	COMMISSION	ALLEN, R B	8007070201*	TOPREP
ABOU-SAYED, 1	8007230201	NUREQ	AKEARNE, J F	8007230745	COMMIESION	ALLMENOINGER, P	8007030354	PR
ABRAHAMSON, D ABRAKSON, P B	8007140014*	PR	AHEARNE, J F	8007280157	COMMISSION	L 4.ORBENA	8007100248*	80~206
ABRAMS, R	8007240459	NURED	AHEARNE, J F	80072B0722	COMMISSION	ANDALMAN, E	8007080009	PR
ABT, S R	8007110121	PR	AHEARNE, J F	8007290347	COMMISSION	ANDERS, W A	8007140135*	BECY
ABT. 8 R	8007170331* 8007180491	40-8681	AHEARNE, J F	8007080159	50-546 U	ANDERSON, T M	8007140540*	ACRE
		40-8691	AHEARNE, J. F	8007160716	COMMISSION	ANDERSON, T M	B007100253	TOPREP
AUT.8 R AUT.8 R	8007170302*	40-8402	AHEARNE, J F	8007280142	COMMISSION	ANDERSON, J L	8007230425	RUREO
ADT, S R	8007180288	40~8602	AHEARNE, J F	8007170415	COMMISSION	ANDERSON, T M	8007140379*	TOPREP
ADT. B R	6007280070	40-B6B1	AHEARNE, J F	8007110546	50~482 U	ANDERSON, T M	B007140416*	TOPREP
ADT, B R	8007170332* 8007170335*	40-8681	AHEARNE, J F	9007110552#	50~492 U	ANDERSON, T M	8007150656*	TOPREP
		40-B481	AHEARNE, J F	8007110566*	50-482 U	ANDERSON, T M	B007160765*	TOPREP
ABT,S R ABT,B R	8007170308*	40-8602	AHEARNE, J. F	800711054B*	50-482 U	ANDERSON, T M	6007140373×	TOPREP
ADT, S R	8007280066	40-8402	AHEARNE, J F	8007110377	NO 1881 MNO 2	ANDERSON, D Q	8007270321*	0A797
ADT, B R	8007180279	40-8481	AHEARNE, J F	8007110382*	COMMISSION	ANDERSON, T H	8007010005	PR
ABT. S R	8007180480	40-8698	AMEARNE, J F	8007110397*	COMMISSION	ANDERSON, T M	6007140367	TOPAEP
	8007170297*	40-8602	AHEARNE, J F	8007110392*	COMMISSION	ANDERBON, T M	8007140407	TOPREP
ABT.S R ABUAF.N	ED07170329*	40-8661	AHEARNE, J F	8007110538	COMMISSION	ANDERSON, T M	8007190646	TOPREP
ACERRA, L S	6007180361	RES	AHEARNE, J F	8007140050	50-320 U	ANDERSON, T M	8007160743	TOPREP
ACKERMAN, W C	6007170214 8007020694	50-373 8	AHEARNE, J F	8007140062*	90-320 U	ANDERBON, T. K	8007170230	50-275
ACOSTA, A P	8007020028	40-8502	AHEARNE, J F	6007140120	COMMISSION	ANDERSON, T M	8007080371	50-339
		40-8584	AHEARNE, J F	8007240027	CONMIBBIOM	ANDERSON, D T	8007100268*	50-206
ACOSTA, A P ACOSTA, A P	8007010305	40-8594	AHEARNE, J F	8007240034*	COMMISSION	ANDERSON, T (4	8007020441	TOPREP
ACOSTA, A P	8007210560 8007270619	40-8584	AHEARNE, J F	6007240383	70-2153	ANDERSON, T 41	9007020644×	TOPREP
AOAM, L. D	8007210393	40-0584	AHEARNE, J F	8007250202	COMMISSION	ANDERSON, T M	8007020590	TOPREP
ADLER, T A	8007310393	50~289 H	AHEARNE, J F	8007110297*	COMMISSION	ANDERSON, C. J	8007230621	50-397
		90-287 G	AHEARNE, J F	8007250079	COMMISSION	ANDERGON, T M	8007210410	TOPREP
ADLER T A ADLER, T A	8007140009* 8007140008	90-289 Q 50-289 Q	AHEARNE, J F	8007250082*	COMMISSION	ANDERSON, N R	8007300099	50-339
ADLER, T A	8007140009*	50-289 Q	AHEARNE, J F	8007250085*	COMMISSION	Anderson, C	8007250175	50-322
ADLER, T A	8007250680	50-287 Q	AHEARNE, J F	8007250089*	COMMISSION	ANDERSON, C.	8007310231	NUREO
ADLER, T A	8007250689	50-2B7 C	AHEARNE, J F	800725009B*	COMMISSION	ANDUGNINI.Q C	#4710E2700B	50-293
			AHEARNE, J F	8007250101*	COMMISSION	ANDOGNINI, O. C.	8007280252*	50~293
AOLER, T A	8007250680 8007250689	50-287 C	AHEARNE, J F	8007250105*	COMMISSION	ANDOONINI, O C.	8007140415	50-293
ADLER, T A	8007220001	50~289 O	AHCARNE, J F	8007250114×	CORMISSION	ANDOGNINI, O C	8007210006	50-293
ADLER, T A	8007220001	50-289 Q	AHEARNE, J F	80072501184	COMMISSION	ANDOGNINI. G C	8007210301	50-293
ADLER, T A	8007220002	50-287 Q	AHEARNE, J F	8007240480	COMMISSION	ANDOGNINI, O C	8007030142	50-293
			AHEARNE, J F	8007240481#	COMMISSION	ANDOCHINI.C O	8007150557	50-293
ADLERIT A ADLERIT A	8007220002 8007220585	50-287 C 50-287 C	AHEARNE, J F	8007240483*	COMMISSION	ANDOGNINI, O C	8007250309	50-293
AGEE, J R	8007280088*	QA999	AHEARNE, J F	8007240487*	COMMISSION	ANDOONINI.O C.	8007290594	50-293
AGEE, J R	800714004B*	QA999	AHEARNE, J F	8007240491*	COMMISSION	ANDREWB. H O	8007080285*	TOPREP
AGEE, J R.	8007160171*	QA999	AHEARNE, J F	8007240493*	CORHIGBION	ANDREWS, I	0007020217*	50-324
			AHEARNE, J F	E007240496*	COMMISSION	ANDREWS. J. P	8007180230	REOOD
AGEE, J R AGRAWAL, A K	8007290337* 8007210003	QA999 REB	AHEARNE, J. F	8007240497*	COMMISSION	ANG, W P.	8007160872*	50-416
AHEARNE, J F	8007010552*	COMMISSION	AIROLA, E D	#907220189	QA999	ANKLAM, T H	8007300575	NUREO
AHEARNE, J F	8007220273*	40-299	AKERS, D W	8007270217	50-284 P	ANTOUN R L	8007090201*	TOPREP
AHEARNE, J F	8007100211*	50-302 P	ALBOSTA, D ALBEN, N M	8007160634	50-329 H	APPELHANS, A D.	90073i0255	NUREO
	., -	'	WHITE IN THE	8007180433*	90-277 R	APPLEYARD, M H	8005190626	50-320

AUTHOR	ACCESS I DN	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGORY
ARAGON, R	8007310004	NUREO	BARDES.C R	8007110147*	50-320 J	BAXLEY,8 X	8007030278*	50-321 8
ARAUZ, O A	8007220385*	50-302 P	BARDES.C R	8007110151*	50-320 J	BAXLEY,8 X	8007110442*	50-321 8
ARCHITZEL, R	8007210247*	50-317 Q	BARDES.C R	8007110156*	50-320 J	BAXLEY,8 X	8007210492*	50-321 9
ARLOTTO, O A	8006270352	PR	BARDES.C R	8007110160*	50-320 J	BAXTER,T A	8007070310	50-484 0
ARNOLD, R C	8007110030*	50-289 J	BARDES.C R	8007110167*	50-320 J	BAXTER,T A	8007070315*	50-484 0
ARNOLD: R. C	8007070287	50-320 P	BARDES, CR	8007110176*	50-320 J	BAXTER, T A	8007070315*	50-484 G
ARNOLD: R. C	8007170456	50-320 P	BARDES, CR	8007110178*	50-320 J		8007150527	50-312 0
ARNOLD: R. C	8007220485	50-320 0	BARDES, CR	8007110201*	50-320 J		8007150556*	50-312 0
ARNOLD: R. C	8007310439	50-320 P	BARDES, CR	8007110208*	50-320 J		8007150556*	50-312 0
ARSENAULT: F J	8007220018	MISC	BARDES, CR	8007110212*	50-320 J		8007250345	50-312 P
ASH, R F	8007090359#	50-317 G	BARDESIC R	8007110217+	50-320 J	BAXTER, T A BAXTER, T A BAYNARD, P Y BAYNARD, P Y BAYNARD, P Y	8007250408	50-484 0
ABHENDEN, M C	8007180011#	50-327 G	BARIAR A	8007210010	RES		8007250408	50-484 0
ASPEROER, R O	8007080008	50-452 G	BARIAR A	8007240294	RES		8007100101	REGGD
ASWELL, D L	8007100429	50-382 G	BARIAR A	8007020364	RES		8007020387	50-302 P
ASWELL, D L	8007150417	50-382 G	BARKER, J L	8007070080+	50-10 G		8007230173	PR
ABHELL, D. L.	8007290439*	50-382 Q	BARKER, J L	8007230388*	50-10 G	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8007110122	50-302 P
ABHELL, D. L.	8007010341	50-382 F	BARKER, D Q	8007300375	50-498 A		8007150708	50-302 R
ABHELL, D. L.	8007010319	50-382 8	BARLEY, S R	8007180110*	50-320 H		8007210203	50-302 P
ABHELL, D. L.	8007020397	50-382 8	BARNES, I	8007310195*	GA979		8007180294	50-302 P
ABHELL, D. L.	8007100163	50-382 K	BARNES, I	8007270504*	GA999		8007180313	50-302 P
ABWELL, D L ASWELL, D. L ASWELL, D. L ASWELL, D L ASWELL, D L	8007100166* 8007300395* 8007080179 8007080234 8007220373	50-382 K 50-382 Q 50-382 A 50-382 S 50-382 F	BARNES, I BARNES, I BARNEICH, J BARNES, J BARNTHOUSE, L W	8007250109* 8007160146* 8007010364* 8007310237 8007210498	0A999 0A999 50-361 A FOIA 50-247 P	PYNARD, PY. BAYNARD, PY BAYNARD, PY PYNARD, PY PYNARD, PY PYNARD, PY PYNARD, PY	8007180384 8007230542 8007220383 8007240074 8007250326	50-302 P 50-302 Q 50-302 P 50-302 P 50-302 P
ASHELLID L ATKINGONJJP AU-YANO,M K AUGTIK,M A AUGTIK,M,A	8007250399 8007220573* 8007090201* 8007150148* 8007150809	50-382 F 50-414 A TOPREP 70-344 70-344	BAROCH.C J BARRETT.P A BARRY.L W BARTH.C A BARTH.C A	8007140397* 8007230064* 8007250176 8007030243 8007090311	GA999 50-341	P V GANANYAB P V GANYAB P V GANYAB P V GANYAB P V GANYAB	8007280127 8007280373 8007170316 8007030254 8007070212	50-302 P 50-302 F 50-286 Q 50-286 F 50-333 F
AUBTIN, M. A AUBTIN, M. A AUBTIN, J. H AUBTIN, M. A AUTIO, M. A	8007020005# 8007150135# 8007020566 8007280211 8007070284	70-135 70-364 50-437 A 71-9022 50-29 S	BARTH, C.A. BARTLETT, N.T. BARTLETT, J. U. BARTLETT, J. BARTHAN, V.	8007250688 8007020746 8007100188* 8007280540 8007240378*	50-282	G C 'SNAVE G C 'SNAVE G C 'SNAVE G C'SNAVE	8007180597 8007140347 8007280471 8007080303 8007080332	50-286 0 50-286 0 50-220 0 50-286 V 50-333 P
AUTIG:H A	8007210002	50-27 0	BARTNOFF, S	8007070113	50-219 P	BAYNE, J P	8007080347	50-286 P
AVIS:A B.	8007280271	27-48	BARTRAM, B W	8007220111*	WABTE MOT	BAYNE, J P	8007290728	50-286 P
AXELRAD:H	8007030119	PR	BARTRAM, B W	8007220036*	HABTE MOT	BAYNE, J P	8007280461	50-286 I
AXELRAD:H	8007020604	50-376 0	BABKIN, K P	8007230011	50-361 G	BAYNE, J P	8007290580	50-286 P
AXELRAD:H	8007020604	50-376 0	BABKIN, K P	8007250361	50-361 G	BAYNE, J P	8007290585	50-286 F
AXELRAD, M	8007100160	PR	Babkin, k p	8007110401	50-206 P	BAYNE, J P	8007290692	50-333 P
AXELRAD, M	8007230535	50-376 0	Babkin, k p	8007100386	REGOD	BEACH, A B	8007110076*	50-382 G
AXELRAD, W	8007230535	50-376 0	Babkin, k p	8007300303	50-361 Q	BEAN, R M	8007310210	NUREG
AXELBON, W L	8007250406	50-155 F	Babkin, k p	8007250355	50-206 Q	BECHHOEFER, C	8007080209	50-358 Q
AYER, J E	8007090186*	70-1257	Babkin, k p	8007310162	50-206 Q	BECHHOEFER, C	8007140012	50-409 G
AYER, J. E	8007210315#	70-1257	Babkin, k p	8007290489	50-361 G	BECHHOEFER, C	8007150505	50-409 Q
AYER, J. E	8007090183	70-1257	Babkin, k p	8007010465	50-206 P	BECK, M K	8007220073*	40-8771
AYERS, P. J	8007230532	50-10 D	Babkin, k p	8007010216	50-206 R	BECK, E J	8007280151	71-5979
AYRES, S. T	8007100175	50-272 Q	Babkin, k p	8007010479	50-361 A	BECKER, J M	8007170176	XPORTLIC
BAGI, P. E	8007280137*	50-49B Q	Bagkin, k p	8007010358	50-361 A	BECKER, J M	8007230602	XPORTLIC
Badran, 8 Baer, T 8 Baer, T 8 Bagaglio, M Bagden, G.	8007010551* 8007240155 8007220508 8007310327* 8007140549	50-237 S 71-6679 27-48 50-275 G PR	Baskin, k p Baskin, k p. Baskin, k p Baskin, k p Baskin, k p	8007080081 8007310201 8007080271 8007150579 8007210463	50-341 A 50-341 G 50-206 F 50-206 P 50-341 A	BECKMAN, D A DECKBTED, W F BEDNAR, L F BEENY, S T BEENY, S T	8007230174* 8007270448 8007080368* 8007250485 8007250485	50-334 0 50-322 8 50-298 6 50-395 M
BAODEN, Q	8006240081	40-1162	BABKIN,K P	8007270620	50-361 A	BEERS, F C	8007180400*	50-271 R
BAILEY, R.	8007230158	50-320 8	BATEMAN, W H	8007170682*	50-354 G	BEHAN, J L	8007180047*	50-322 H
BAIR, Q Q,	8007140315*	50-344 R	BATEM, W H	8007170274*	50-354 G	BELANGER, J L	8007310267*	50-305 Q
BAISDEN, L.	8007210263	CONTRACT	BATEM, J W	8007100381*	70-1151	BELCHER, R L	8007230495	50-166 R
BAISDEN, L	8007310006	CONTRACT	BATEM, J, W	8007100410*	70-1201	BELGRAIR, D P	8007270732	71-370
BAKER, T. BAKER, K. R BAKER, K. R. BAKER, B. BAKER, B.	8007110443* 8007010393* 8007140493* 8007090290 8007090298*	NUREO 50-255 Q 50-155 Q 50-466 Q	BATES, J W BATES, B J BATES, A BATES, A BATES, E F	8007140073* B007250057* B007030351 B007140691 B007290475*	70-143 QA999 PR PR 50-128 R	Belgrair, D P Belin, A Belin, A Belinle, O A Belke, W L	8007270734* 8007020136 8007140228 8007220088* 8007070101	71-370 FOIA FOIA 50-335 Q 50-286 P
BAKER: B. L BAKER: B. L BAKER: B BALALIB: C. O BALLARD: R. L	8007170159 8007170171* 8007230603 8007280473 8007070033*	50-466 0 50-466 0 50-466 0 XPORTLIC 50-514 D	BATES, A K BATES, J. O BATTLE, R E BAUGUS, M	8007090347 8007180316# 8007230507 8007140610 8007230067#	50-327 P 70-143 50-329 A NUREO 50-320 H	BELL.J J BELMORE.C I BENBERGER.D L BENDER.M	8007280265 8007220033* 8007150712* 8007170577 7905140021	50-287 G 50-287 H 50-217 R 50-460 8 50-437 D
BALLARD,R L	8007300035	50-289 0	BAUER, R H	8007240094*	71-5607	BENNETT, H A	8007180049	NUREO
BALLENTINE,J M.	8007220358	50-327 R	BAUER, E R	8007280453*	50-317 8	BENNETT, A B	8007250594*	GA979
BALLINGER.P L	8007080375*	50-298 R	BAUM, E A	8007030184	50-280 F	BENNETT, H A	8007310241	NUREO
BALLINGER.P L	8007250425*	50-298 R	BAUM, E A	8007070201	50-339 P	BENSINO, D	8007100120	PRM
BALOUGH,R C	8007210388	50-445 M	BAUM, E A	8007150569	50-338 P	BERGER, R F	8007020613	SO-556 O
Banasiak, L. J	8007160540	50-10 D	BAUM, E. A	8007220579	50-338 F	BERGER, R F	8007310153	SO-556 0
Banabzak, L. J	8007180368	50-10 D	BAUM, E. A	8007240049	50-339 A	BERGER, R F	8007220539	PR
Banab, E. M	8007090131	40-5021	BAUM, E. A	8007280432	50-338 F	BERICK, D.	8007030107	PR
Bardes, C. R	8007110107*	50-320 J	BAUM, E. A	8007250383	50-338 F	BERKEBILE, R D	8007100194	REOOD
Bardes, C. R	8007110125*	50-320 J	BAUMANN, R. O	8007300581*	CONTRACT	BERMAN, M	8007110551	RES
Bardes, C R	8007110128*	50-320 J	BAUN, PH	8007150573*	50-133 R	BERMAN, M	8007280081	RES
Bardes, C. R	8007110132*	50-320 J	BAUNACK, W	8007250263*	50-220 Q	BERNERO, R M	8007110487*	SECY
Bardes, C. R	8007110135*	50-320 J	BAUNACK, W	8007210255*	50-333 Q	BERNSEN, B A	8007150116	PR
Bardes, C. R	8007110140*	50-320 J	BAUNACK, W	8007290010	50-220 8	BERTELL, R,	8007020449	PR
Bardes, C R	8007110143*	50-320 J	BAXLEY, SX	8007010518*	50-366 S	BETANCOURT, B	8007020693*	50-281 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY
BETETA, P M BETHUNE, E BETTAUER, R J BETTENHAUSEN, L BEYEA, J	8007180169* 8007110449 8007170191 8007230221* 8007170089	COMMISSION 50-313 H XPORTLIC 50-293 9 50-320 P	80HN, M P 80HN, M P 80HN, M P 80HN, R J	8007150059 8007010478 8007220065 8007210464 8007280482	RES 50-367 A RES 50-367 R 50-367 R	BRADFORD.W H BRADFORD.P A BRADFORD.W H BRADFORD.G P BRADFORD.O P	8007070399* 8007300291* 8007240376* 8007220203 8007220209*	50-348 4 50-257 4 50-348 4 50-287 4
BIALIK, E I BICKWIT, L BICKWIT, L BICKWIT, L BIDA, O	8007110121 8007150927 8007110532 8007140182 8007210007	PR COMMISSION SECY 50-247 P RES	BOHN R J BOLANDER, M A BOLANDER, M A BOLES, G S BOLES, G S	8007110438 8007280178 8007280186 8007290656* 8007290681*	50-367 R RES RES 50-327 B 50-327 B	BRADFORD.0 P BRADLEY.R T BRADLEY.E J BRADLEY.E J BRADLEY.E J	8007220217* 8007140617 8007180443 8007220551 8007280384	50-289 / NUREQ 50-277 / 50-277 /
BIDDLE.C T BIDDLE.C T BIDDLE.C T BIDDLE.C T BIDDLE.C T	8007020471 8007020471 8007080013 8007080017# 8007080015*	50-466	BOOK'H E BOOK'H E BOOK'H E BOOK'H E	8007310007 8007140609* 8007300585* 8006110739* 8007310339*	NUREC 27-48 50-254 G 27-10 50-295 G	BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8	8007010480* 8007150603* 8007150538* 8007210432* 8007210413*	50-313 50-313 50-313 50-313 50-313
BIDDLE.C T BIDDLE.C T BIELAWSKI.A P BIELAWSKI.A P	8007080017* 8007180432 8007180432 8007020462 8007020462	50-466 G 50-466 G 50-466 G 50-599 G 50-599 G	800K, H E 800K, H E 800K, H E 800K, H E 800K, H E	B007140657* B007140663* B007170556* B007140670* B007150130*	40-2940 40-2940 50-315 @ 40-2940 50-344 @	BRAMLETT, L S BRAMLETT, L B BRAMAOAN, E F BRANCH, W H BRANDENBURG, B	8007180318* 8007280511* 8007100369 8007270729 8007220160	50-313 50-313 NUREO 71-368 50-247
BIELAWSKI.A P BIERMAN.S R BIERMAN.S R BIOIARELLI.H J BINOHAM.J	8007230810 8007020014 8007310187 8007100172* 8007280187	50-255 0 RES RES 50-245 S PRM	800K, H E 800K, H E 800K, H E 800K, H E	8007110174 8007110184* 8007150124* 8007180023 8007180025*	50-206 Q 50-206 Q 50-344 Q 50-508 Q	BRAND, WE BRANDENBURO, B BRAND, J BREAUX, D BREAUX, D O	8007250502* 8007290522 8007030038* 8007140088* 8007140126*	50-395 ; 50-247 ! FOIA GAPPP GAPPP
BIRCHELL,R C BIRCHELL,R C BIRGEL.B H BIRKEL,R A BIRKEL,R A	8007290639* 8007290818* 8007030071* 8007110519 8007140486	90-327 8 50-327 8 CONTRACT 50-369 A 50-369 A	800K, H E 800K, H E 800K, H E 800K, H E	8007230355* 8007230350 8007160721* 8007230297* 8007240331*	50-224	BRICKLEY,R H BRICKLEY,R,H BRICKLEY,R H BRICKLEY,R M BRICKLEY,R,H	8007140088* 8007280088* 8007140048* 8007160171* 8007290337*	0A777 0A777 0A777 0A777 0A777
BIRXEL.R A BIRXEL.R A BIRXEL.R A BIBCHOFF.C A BISHOP.T W	8007090091 8007170696 8007280011 8007300106 8007230639*	50-369 A 50-369 A 50-369 A 50-528 G 50-397 Q	BOOK, H E BOOK, H E BOOK, H E BOOK, H E	8007230291* 8007240322 8007310163 8007310168* 8007150106	50-204 Q 70-1257 50-288 Q 50-288 Q 50-344 Q	BRICKLEY, R H BRICKLEY, R H BRIDGES, A P BRIGGS, L BRIGGS, L	8007290321* 8007310316* 8007160513* 8004240215 8004240221	94999 50-266 0 CONTRACT 50-318 50-219
BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.J M BISHOP.J M	8007090224 8007100022 8007100255 8007310116 8007310108	50-376 G 50-295 G 50-445 G 50-466 G	BOOK, H E BOOKE, B L BOOKE, B L BORDENICK, B M	8007230282 8007100003* 8007220520 8007220520 8007070044*	50-206 Q 50-320 Q 40-1162 40-1162 50-514 D	BRIOHT,R M BRIOHT,R M BRIOHT,R M BRIOHT,R M BRIOHT,R M	8007030242 8007180540 8007010355 8007070329 8007080257	50-302 P 50-302 P 50-302 P 50-302 A
BISHOP.L L BISHOP.C J BISHOP.C J BISHOP.C J	8007110048 8007110048 8007100258 8007220092 8007220103*	PR PR 50-320 G 50-275 G 50-275 G	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8007080001 8007080003* 8007080005* 8007080059 8007160601	50-320 Q 50-320 Q 50-320 Q 50-322 Q	N A,THOIRE R MATHOIRE B L,ABJANIRE B L,ABJANIRE B L,EITIRE	8007100153 8007150598 8007080417* 8007210431* 8007100001	50-302 , 50-302 & 50-309 50-309 PR
BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.T A BISSETT.P	8007220556 6007310160 8007310463 8007240394 8007180082*	50-445 If 50-344 & 50-309 & NUREO 70-371	BORDENICK, 8 M BORDENICK, 8 M BORDENICK, 8 M BORER, P. J BORGMANN, E A	8007140583 8007170201 8007240008 8007280572* 8007150108*	50-322 Q 50-514 Q 50-322 H 50-298 S 50-358 Q	BROCKETT, T BROCKETT, T BROCKETT, T BROCKETT, T W BRODERICK,N E	8004240316 8007140350 8007230143 8007230148 8007030208*	ILE 50-219 ILE 50-54 50-285 ;
BISSETT.P H BIVING.W S BLACK.R L BLACK.R L BLACK.R L	8007170630* 8007230721* 8007010330 8007080030 8007190043	70-135 40-8452 50-522 0 50-466 0 50-341 0	BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A	8007010084 8007080317 8007210302* 8007210313 8007250616	50-358 Q 50-358 A 50-358 Q 50-358 Q 50-358 Q	BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J	8007030233 8007100345 8007100058* 8007020594 8007070273	50-344 û PRH 50-344 û 50-344 û
BLACKWELL,R H BLACKWELL,R H BLACK,R L BLACK,R L BLACK,R L	8007280680* 8007280692* 8007180246 8007180260 8007180426	50-321 R 50-321 R 50-498 0 50-466 0 50-466 0	BORGMANN, É A BORGMANN, É A BORGMANN, É A BORGMANN, É A BORGMANN, É A	8007080374 8007070258 8007250576 8007280096 8007140369	50-358 G 50-358 F 50-358 G 50-358 G 50-358 K	DROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J BROEHL, D J	8007160661 8007180347 8007220570 8007250413 8007290554	50-344 f 50-344 50-344 f 50-344 f
BLACK, R L BLACK, R L BLACK, R L BLACK, R L BLAKE, E L	8007220013 8007240485 8007270748 8007310473 8007180394	50-498 0 50-498 0 50-498 0 50-466 0 50-289 0	BORGMANN, E A BORGMANN, E A BORGO, O J BORGO, O J BORNHOEFT, W H	8007210424 8007230437 8007160366 8007250297 8007280067*	50-358 K 50-358 Q 50-369 S PT21 PR	Broan, Q E Brombero, B Brooks, T Brooks, H Brooks, F K	8007010364* 8007210253 8007070085 8007140637* 8007160229*	50-361 ; CONTRACT PR TOPREP CONTRACT
BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L	8007180394 8007230521 8007230521 8007300437 8007300437	50-287 Q 50-287 Q 50-287 Q 50-287 Q 50-289 Q	BOSCHWITZ,R BOUKNICHT,JA BOURNIA,A BONDEN,TJ BOWDEN,DD	8007310528* 8007230798 8007180294 8007110502 8007140617	50-282 H 50-389 M 50-438 A PRM NUREG	BROBNAN, D.F., BROUNG: R.J. BROUNC: W.G. BROUN: R.A. BROWN: G.F.	8007140051* 8007220019 8006110739* 8007150471* 8007090098	PR HUREO 27-10 50-280 (PR
Bland. J 8 Block. J A Bloedel. G A Blough. A R Blume. M 9	8007010289 8007220334* 8007180049 8007230736* 8007010247	50~255 P TOPREP NUREQ 50~277 Q 50~445 M	BOWERB, E 8 BOWERB, E 9 BOWERB, E 9 BOWERB, E 9 BOWERB, E 9	8007020586 8007020606 8007080204 8007110348 8007310167	50-322 0 50-322 0 50-322 0 50-488 0 50-445 0	BROWN,R L BROWN,E BROWN,E J BROWN,O D, BROWN,O D	9907210264* 8007140494* 8006120770 8007170297* 8007170329*	0A999 50-283 (080 40-8602 40-8681
BLUME.M B BLUMMBERG.N BODDY.J R BODDY.J R	8007010264 8007280636# 8007020070* 8007220042* 8007220047*	50-445 M 50-445 M 50-277 Q Waste Mgt Waste Mgt	BOWERS, E S BOWD, D C BOYD, D C BOYD, D C	8007250708 8007140490 8007070061* 8007010393* 8007240210*	50-142 Q GGNTRAGT 50-282 Q 50-255 Q 50-282 Q	BROWN, R. BROWN, O. F BROWN, O. D. BROWN, H. H	9007220056* 8007220064* 9007020635 9007170271 8007030048	HASTE HOT HASTE HOT FR 40-8602 50-275
BODTKE, P J BOELDT, E J. BOODEN, O BOODEN, O BOHANAN, R F	8007110414* 8007100170 8007100071* 8007220314 8007300575	50-255 R REGOD 40-1162 40-1162 NUREO	BOYER, V 8 BOZARTHID P BOZICHIT A BOZICHIT A BRADFORD, P A	8007250471 8007250552* 7910150157 8007030099 8007030213*	50-352 A 50-460 A 40-4669 40-4669 50-273 P	BROWN, H H BROWN, R A BROWN, O D. BROWN, O D BROWN, C H	8007030048 8007280278 8007170327 8007230257* 8007300309*	50-275 (70-1177 40-8681 50-313 (50-263 (

4

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
erchio d erchio d erchio d erchio c erchio c erchio c	8007230244 8007290231 8007290244* 8007010363 8007010413	50-313 0 40-8102 40-8102 50-404 A 50-339 0	BURCHETTE, W H BURGESS, B L BURGER, J F BURGER, F J BURGER, F J	B007210455 B007240210* B007100050* B0071B0400* B007290024	50-445 M 50-262 G PR 50-271 R 70-2902	CALHOUN, J R	8007290646 8007290657 8007290790 8007290820 8007290822	50-327 8 50-259 \$ 50-327 9 50-294 9 50-327 \$
eromir. Broinir Brohnio d Brohnil J Bronnim s	8007280508 9007230205 8007180112 8007300340 8007070272*	NUREG NUREG 50-285 G 50-193 G 50-316 S	BURIAN.R J BURKE.T J BURKHARDT.W BURKS.N BURNETT.R F	8007250110 8007020073* 8007090183 8007140674 8007220248*	71-9957 50-922 8 70-1257 FOIA 70-143	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007250414 8007270636 8007270665 8007270720 8007270810	50-327 S 50-327 B 50-327 B 50-260 S 50-327 S
BROWN, H J BROWN, H S BROWN, B C BROWN, B C BROWN, B C	8007100246 8007150703* 8007180371 8007250365 8007310421	PR 50-315 8 50-281 0 50-281 0 50-280 P	BURNETT, R F BURNETT, R F BURNETTE, G N BURNETT, R F BURNETT, R F	8007070038* 8007020080 8007150407 8007020476 8007110584	10CFR 70-1201 RES 70-572 70-143	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007290762 8007290685 8007290695 8007290578 8007290649	90-327 \$ 50-327 \$ 50-327 \$ 50-327 \$ 50-327 \$
BROWN, H BRUGGER, R BRUGGER, R BRUNER, R BRUNNER, E J	8007250429 8007080266 8007080260 8007230601* 8004240212	50-275	BURNETT, R F BURNETT, R BURNETT, R BURNE, B G BURNE, B Q	B007310453 8007250055* 8007250058* B007070126 B007310319	70-1201 FOIA FOIA 50-255 Q 50-255 Q	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALLAHAN, L J	8007290662 8007290475 8007290708 8007290737 8007220197*	50-327 6 50-327 8 50-327 8 50-259 8 50-313 0
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8004240215 8004240221 8004240228 8007020049* 8007230730*	50-318 \$ 50-219 \$ 50-293 \$ 50-277 Q 50-277 Q	BURTON, R M BURWELL, B BUSTION, R R BUTLER, W R BUTLER, & D.	8007210125* 8007020224 8007100050* 8007180177* 8007180011*	50~483 Q 50~445 A PR REOOD 50~327 Q	CAMPBELL.M CAMPBELL.M CAMPBELL.R CAMPBELL.R H CAMPBELL.T E	8007170306* 8007170314* 8007170438* 8007110003 8007020596*	FOIA FOIA FOIA 70-2909 Toprep
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8007220050 8007230202* 8007230157* 8007180077 8007280254*	50-219	BYERLEY, T E CADENA, D Q CAHILL, W J CAHILL, W J	8007020342 8007020523# 8007070174 8007010081 8007020077	PR 50~366 B PR 50~3 Q 50~3 Q	CANADY, K 8 CANLON, L E CANNON, R H CANTER, H L CANTRELL, F B	8007140007* 8007110536* 8007150522* 8007240420* 8007240327*	50-369 0 50-424 0 50-327 F 50-312 0 50-518 0
BRUNNER, E J BRUNNER, E J BRUNNER, E J. BRUNNER, E J. BRUNNER, E J	9007310118* 9007020035 8007170688 8007210157 8007210241	50-272	CAHILL, H J CAHILL, H J CAHILL, H J CAHILL, H J CAHILL, H J	8007170287 8007180540 8007180592 8007090228 8007090251	50-3 Q 50-3 Q 50-3 Q 50-247 P 50-247 P	CANTRELL, F S CANTRELL, F S CANTRELL, F S CAPHTON, D L CAPHTON, D L	8007150452* 8007290361* 8007300594* 8007220060* 9007230221*	50~566 G 50~438 G 50~518 G 50~219 G
BRUNNER, E J. BRUNNER, E J BRUNNER, E J. BRUNNER, E J BRUNNER, E J	8007250258* 8007210251 8007230387 8007230130 8007230377	50-220	CAHILL, H J. Cahn, A L Cahn, A L Cain, C L Cain, C L	8007170349 8007230042 8007300452 8007300585* 8007290244*	50-3 R PR TOPREP 50-254 Q 40-8102	CAPHTON, D L CAPLAN, R CAPLAN, R CAPLAN, R CAPPER, W E	8007310131* 8007080046 8007080048 8007310128 8007020650	50-272 Q 50-320 Q 50-320 G 50-277 Q 71-381
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J.	8007020540 8007020536 8007020145 8007310499 8007310361	50-271 8 50-213 8 50-247 9 50-247 0 50-245 0	CAIN; J CALDHELL; R A CALDHELL; R A CALDHELL; E CALHOUN; J R	8007210104 8007100225* 8007070161* 8007080255 8007010382	WASTE MOT 50-267	CAPRA,R A CAPRA,R A CAPRA,L A CAPRA,L A CARACO,I R	8007030220 8007240208 8007300168* 8007300178* 8007140075*	TOPREP 50-269 P GA999 GA999 GA999
ERUNNER, E J. BRUNNER, E J. BRUNNER, E J. BRUNNER, E J. BRUNNER, E J	8007180445 8007140615 8007230005 8007310052 8007230162	50-219	R C ALHOUN, J R CALHOUN, J, R CALHOUN, J, R CALHOUN, J, R	B007010435 B007010528 B007010370 B007010417 B007010479	50-327	CARBAUGH, E H CARBON, M W CARDILE, F P CAREY, N, W CARFAGNO, S P	8007240009* 7904120321 8007100369 8007010397 8007070368	50-155 Q 50-353 Q NUREO 50-271 I 50-338 P
Bruthter, E. J. Bruthner, E. J. Bruthner, E. J. Bruthner, E. J. Bruthner, E. J.	8007230140 8007230171 8007250241 8007310104 8007280248	50-334	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R	8007010525 8007010534 8007010490 8007010512 8007080283	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007020066 8007210326* 8007170665* 8007010227* 8007020216	50-322 8 50-352 0 50-354 0 50-443 0 50-334 0
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, J E BRYAN, J X	8007270010 8007270058 8007250197 8007270701 8007150004*	50-220 \$ 50-286 8 50-219 8 50-329 A 50-483 G	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R	8007080293 8007080301 8007080334 8007080394 8007080405	50-259 8 50-259 8 50-327 6 50-260 8 50-260 8	CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R.T CARLSON.R.T	8007210345* 8007170606 8007170593 8007210221* 8007020155	50-387 0 50-286 0 50-363 0 50-352 0 50-352 8
BRYAN, J K BRYAN, J K BRYAN, J K BRYAN, J K BRYAN, R H	8007150010* 8007210198 8007150534 8007250336 8007310554	50-483 Q 50-483 Q 50-483 F 50-483 S NUREO	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R	8007110372 8007080281 8007080370 8007080419 8007080313	50-327 8 50-327 8 50-260 8 50-276 8 50-257 9	CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8007170437 8007010219 8007020111 8007170268 8007170283	50-387 Q 50-443 G 50-410 S 50-354 Q 50-322 G
BUCHHOLZ, R H	8007150104 9007140356 9007140426 9007090310 9007150724	PR TOPREP TOPREP TOPREP TOPREP	R L.NUCHJAD R L.NUCHJAD R L.NUCHJAD R L.NUCHJAD R L.NUCHJAD	8007080400 8007070003 8007110378 8007110388 8007150495	50-327 & 50-259 & 50-294 & 550-294 & 550-327 & 8	CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8007020004 8007170249 8007210201 8007210308 8007220278	50-410 S 50-387 Q 50-410 Q 50-354 Q 50-317 Q
BUCHHOLZ, R. H BUCHHOLZ, R. H BUCKALEH, H. H BUCKALEH, H. H BUCKLEY, B.	8007220329 8007210391 8007210366 8007310007 8007020433	TOPREP NUREO TOPREP NUREO 50-461 A	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007150504 8007150470 8007150580 8007150491 8007150570	50-327 8 50-327 8 50-327 8 50-327 8 50-239 8	CARLBON.R T CARLBON.J D CARLBON.R T CARLBON.R T CARLBON.R T	8007010182 8007170080* 8007170671 8007170610 8007170587	50-443 8 50-133 9 50-387 8 50-387 8 50-443 6
BUCKLEY, B. C BUCKLEY, B. C BUCKLEY, B. C. BUDNITZ, R. J BULIBCHECK, T. S	8007080343 8007230029 8007250550 8007230727 8007220053	50-275 A 50-275 A 50-275 A 50-320 H RES	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007160519 8007210461 8007180301 8007220469 8007230470	50-327 8 50-327 9 50-296 8 50-327 9 50-259 8	CARLSON:R T CARLSON:R T CARLSON:R T CARLSON:R.T CARLSON:R.T	8007180592 8007300317 8007300326 8007250267 8007280242	50-410 q 50-354 Q 50-219 Q 50-273 Q 50-354 Q
BULISCHECK, T, BUMFUB: B E BUNKER: P. L. BUNTINO, J O BURACK, J. A	8007180233 8007240476 8007220385* 8007170681* 8007210320	RES NUREO 50-302 P MISC 70-157	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007250436 8007220568 8007230490 8007230523 8007250418	50-327 \$ 50-327 \$ 50-257 \$ 50-259 \$ 50-327 \$	CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8007170454 8007280071 8007140843 8007210013 8007210015	50-354 0 50-333 0 50-322 0 50-443 A 50-352 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R T	8007210048 8007310061 8007210045 8007210231 8007210276	50~462 S 50~277 Q 50~367 S 50~482 S 50~354 Q	CASHWELL,R J CATTON,1 CATTON,I CAULDHELL,F B CAULDWELL,F S	8007310405* 8007220308 8007160240 8007020315 8007020695	50-156 R 50-3 O 50-142 F PR PR	CHILK, 8 J CHILK, 8 J CHILK, 8 J CHILK, 8 J	8007230134 8007020461 8007020663 8007020664 8007020665	ACRS PR PR PR PR
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007210334 8007180534 8007250519 8007210033 8007210457	50-387 Q 50-412 S 50-443 H 50-322 Q 50-423 S	CAVANAUGH, W CAVANAUGH, W CECH, L GECH, L	8007100366 8007080066 8007150489 8007110423* 8007110448*	PRM 50-348 P 50-313 P 50-344 8 50-346 S	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8007210331# 8007020647# 8007020660# 8007020602 8007020629	CONTRACT 70-143 70-143 50-443 0 50-271 0
CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8007210528 8007250287 8007210206 8007290249 8007290860	50-311 0 50-352 8 50-352 0 50-482 8 50-412 S	CEMBER, H GERNE, A C CERNE, A C CERNE, A C CERNE, A C	8007140483 8007010235* 8007210209* 8007180561* 8007210345*	REGGD 50-443 0 50-410 0 50-410 0 50-423 0	CHILK, S J CHILK, S J CHILK, S J CHILK, S J	8007020656* 8007020597 8007100026* 8007090297 8007170282	70-143 50-395 M 50-295 O 50-452 O 10CFR
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007290845 8007310281 8007310289 8007310297 8007210533	50-387 \$ 50-352 5 50-354 \$ 50-482 8 50-423 0	CHAFFEE.A CHAMBERLAIN W M CHANANIA.F D CHANANIA.F D CHANANIA.F D	8007210107* 8007140052 8007090223 8007090248 8007090252	50-224 Q PRK 50-375 M 50-395 M 50-395 M	CHILK:8 J CHILK:8 J CHILK:8 J CHILK:8 J CHILK:8 J	8007290758 8007300369 8007300394 8007300358 8007310462	50-445 Q 50-320 H 50-271 H 40-1162 50-409 Q
CARMEL, P CARMEAN, B D CARNEY, J J CARPENTER, J M CARPENTER, J M	8005090524* 8007080230 8007280059 8007310009 8007280683	PT9 MISC PR Nureo Nureo	CHANANIA,F D CHANANIA,F D CHANANIA,F D CHANDLER,L J CHANDLER,L J	9007150500 8007280620 8007280636* 8007030372 8007020094	50-445 M 50-445 M 50-320 H 50-320 Q	CHOW, E T CHOW, E T CHOW, E T	8007240177* 8007100140 8007210481 8007230328* 8007110047*	50-250 R 50-337 P 50-320 H 50-305 G 50-263 G
CARR, S E CARROLL, D E CARROLL, D E CARROLL, J T CARTER. A R	8007020009* 8007010606 8007010607 8007230570 8007300074*	CONTRACT 50-10 0 ORQ 50-219 8 COMM16510N	CHANDLER, L J	8007010304 8007030006 8007140034* 8007140006 8007070104	50-320 H 50-361 0 50-361 0 50-320 T 50-320 0	CHON, E T CHRISTIANSON, W CHRISTENBURY, E CHRISTOFFER, Q CHRISTENBURY, E	8007240018* 8007100291* 8006120011 8007020211* 8007010138	50-301 G 50-331 G 50-261 T 50-275 G 50-277 I
CARTER,K W CARTWRIGHT,J E CARTWRIGHT,W R CARTWRIGHT,W R	8007070278 8007020613 8007010353 8007010375* 8007010378	50-287	CHANDLER,L J CHANDLER,L J CHANDLER,L J CHANDLER,L J CHANDLER,L J	3007080061 8007070205 8007170357 8007140032 8007300271	50-320 0 50-361 0 50-320 0 50-361 0 50-320 P	CHRIBTOFFER, O CHRIBTENSEN, B CHURCH, J W CHURCHILL, B W CHURCHILL, B W	8007240107* 8007250413 8007150582* 8007230802 8007230802	50-263 0 50-344 0 50-327 P 50-502 0 50-502 0
CARTWRIGHT, W R	8007030262 8007030265 8007030270 8007030271* 8007030273	50-339 & 50-338 & 50-338 & 50-338 & 50-338 & 50-339 & 50-320 & 50-320 & 50-320 & 50-320 & 50-320 & 50-	CHANDLER, L J CHANDLER, L J CHANDLER, L J CHAND, C 1 CHAPIN, D	8007310467 8007310470 8007310465 8007310225 8007140475	50-320 0 50-361 0 50-361 A NUREQ REGOD	CIESZIEHICZ: S CIPOLLA:R C CLARDY:L CLARITY:H M CLARK:A T	8007180336* 8007280404* 8007100291* 8007280489 8007020417	50-10 R 50-206 8 50-331 Q 50-263 P 50-268 P
CARTWRIGHT, UR CARTWRIGHT, UR CARTWRIGHT, UR CARTWRIGHT, UR CARTWRIGHT, UR CARTWRIGHT, UR	8007030275* 8007030281 9007030283* 8007030285 8007030288*	50-339 S 50-339 S 50-339 S 50-339 B 50-339 B	CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D	8007010458* 8007160525* 8007150519* 8007150514* 8007290817*	50-320 8 50-320 8 50-320 8 50-320 8 80-320 8	CLARK, A T CLARK, F H GLARK, R A GLARK, R A GLARK, R A	8007150057 8007140610 8007030194 8007020235 8007180538*	70-1308 NUREG 50-285 P 50-282 F 50-344 G
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8007070358 8007070343* 8007070374 8007070379* 8007090296	50-339 8 50-339 8 50-339 6 50-339 6 50-339 8	CHAPMAN, L D CHARMAN, L D CHARNDFF, Q CHARNDFF, Q CHASE, J W	8007110148 8007290233 8007300381 8007300381 8007280484*	RES RES 50-244 Q 50-244 Q 50-259 Q	CLARK,R A CLARK,R A CLARK,R A CLARK,R A CLARK,R A	8007100132 8007100136* 8007100141* 8007020288 8007030362	50-335 P 50-335 P 50-335 P 50-344 P 50-336 P
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8007090304* 8007090308 8007090312* 8007090317 8007090323*	50-339	CHATTERTON, M CHATTERTON, M CHAUDHARY, S K CHECK, P S CHECK, P, B	8007210102 8007240204 8007210309* 8007010176* 8007010207*	50-338 P 50-338 P 50-354 Q FOIA FOIA	CLARK, C CLARK, R CLARK, R CLARK, R CLARK, R CLARK, R	8007100289* 8007100078 8007140345 8007140372* 8007140379*	50-352 H 50-338 P 50-344 P 50-344 P 50-344 P
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8007090335 8007090342* 8007090345 8007090353* 8007070373	50-339 8 50-339 8 50-338 5 50-338 8 50-338 8	CHECK, P B CHEN, J C CHEN, J C CHERN, W S CHERN, W S	8007170654* 8007170460 8007140642 8007180354 8007310246	50-270 P RES RES RES RUREO	GLARK, R A GLARK, R A GLARK, R A GLARK, R A GLARK, R A	8007170472 8007170588 8007210123 8007100034* 8007180482	50-344 P 50-266 P 50-344 P 50-344 O 50-344 Q
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, N R CARTWRIGHT, W R CARTWRIGHT, W R	8007070381* 8007140209 8007140225* 8007150686 8007150701*	50~338 \$ 50~339 8 50~339 8 50~338 8 50~338 8	CHESTER,R O CHESTER,R O CHIANO,R T CHIANOI,N J CHIANOI,N J	8007020356 8007140044 8007310217 8007080249 8007160377	RES RES NUREO 50-400 S 50-400 B	CLARK, A T CLARK, R A CLARK, R, A CLARK, R A CLAY, F, L	8007280035 8007180441 8007180448* 8007180454* 8007150047*	70-1908 50-344 P 50-344 P 50-344 P 70-1113
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8007150808 8007150810 8007150815* 8007150817* 8007150767	50-339 8 50-339 8 50-339 8 50-339 8 50-338 8	CHILDB.W V CHILDERS,B CHILDB.W V	8007230247 8007090400 8007010495* 8007010519* 8007140374*	50-400 S REGOD 50-333 S 50-333 S 50-333 B	CLAY.E L CLAYTON.D N. CLAYTON.F L CLAYTON.F L CLAYTON.F L	8007140527* 8007250396* 8007010424 8007010444 8007010489	70-143 50-397 A 50-344 A 50-348 B 50-344 A
CARTWRIGHT, W R	8007150777* 8007220575 8007220580* 8007220507 8007220512*	50-338 8 50-338 8 50-338 9 50-338 8 50-338 8	CHILDS'N A CHILDS'N A CHILDS'N A CHILDS'N A	8007140394* 8007150715* 8007280524* 8007280617* 8007280669*	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8	CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F. L	8007150714 8007010404 8007070292 8007070169 8007080222	50-348 P 50-348 B 50-364 A 50-348 R 50-364 A
CARTWRIGHT, W R	8007220601 8007220611* 8007230493 8007230497* 8007290838	50-339 S 50-339 S 50-338 S 50-338 8 50-338 8	CHILES, L J CHILK, B J CHILK, B J CHILK, B J	8007110314* 8007140122* 8007140130* 8007220144* 8007140291*	50-335 H SECY SECY 50-482 G FOIA	CLAYTON, F. L.	8007090237 8007100185 8007210265 8007090214 8007100177	50-364 A 50-364 A 50-348 Q NUREO 50-364 A
CARTWRIGHT, W R CASE, E Q CASE, E Q CASE, E CASHHELL, R J	8007270843* 8007140066* 8007140071* 8007110547 8007310403	50-338 8 50-320 9 50-320 9 FOIA 50-156 R	CHILK'S A CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8007090114* 8007230234* 8007010308 8007280084* 8007230125	COMMISSION FOIA REGOD ORG ACRS	CLAYTON, F, L CLAYTON, F, L CLAYTON, F, L, CLAYTON, F, L CLAYTON, F, L	8007140343 8007160549 8007160579 8007290859 8007100261	50-364 A 50-348 Q 50-364 A 50-348 Q

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007150662 8007210499 8007220510 8007220558 8007250320	50~348 R 50~348 P 50~348 P 50~348 P 50~364 A	COLLINS.J T COLLINS.J T COLLINS.J T COLLINS.J T	8007250237 8007170547 8007170462 8007170540 8007180539	50-320 8 50-320 8 50-320 R 50-320 E 50-320 R	CONTE.R J CONTE.R J CONTI.P L CONTRELL.F 8 CONVERSANO.E	8007240118 8007230218 8007010001 8007240329* 8007070418*	50-320 8 50-320 8 50-201 1 50-518 0 CONTRACT
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007220486 8007220554 8007220410 8007220591 8007230403	50~364 A 50~348 P 50~364 A 50~364 A 50~348 P	COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	8007230643 8007170553 8007170564 8007170557 8007240203	50-320 P 50-320 8 50-320 S 50-320 S 50-320 S	CONWAY, T W CONWAY, J CONWAY, W F CONWAY, T W CONWAY, J T	8007220101* 8007170692* 8007230695 8007220036* 8007010075	WASTE MOT 50-217 0 50-271 0 Waste mot 50-247 P
CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L	8007230495 8007230492 8007230510 8007230546 8007230553	50-364 A 50-364 A 50-364 G 50-364 A 50-348 P	COLLINS, M COLLINS, M COLLINS, J COLLINS, J T COLLINS, J T	8007150694 8007150702 8007150690 8007250719 8007250713	50-368 B 50-298 8 50-267 S 50-320 R 50-320 F	CONWAY, W F CONWAY, W F COOK, R J COOK, R J	8007180549 8007180594 8007180398 8006300138* 8007230412*	50-271 Q 50-271 Q 50-271 R 50-327 Q 50-327 Q
CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L	8007230567 8007230592 8007240071 8007310150 8007280557	50-364 A 50-364 A 50-364 A 50-364 Q 50-364 A	COLLINS, J T COLLINS, J T COLLINS, R C COLLINS, P F COLLINS, J T	8007240118 8007230218 8007280023 8007290055 8007310337	50-320 8 50-320 8 50-320 P HISC 50-320 P	CODY'A M CODY'A M CODY'A M CODY'A M	8007020226 8007020649 8007020306 8007300304* 8007070119	PR 50-327
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007250479 8007280641 8007280490 8007290637 8007290642	50-348 0 50-348 F 50-364 A 50-364 A 50-364 A	COLLINS, M COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007220399 8007220400 8007220401 8007220402 8007220404	50-295 8 50-295 8 50-295 8 50-295 8 50-295 8	CODK'A M CODK'A M CODK'A M CODK'A M CODK'A M	8007280060 8007310329* 8007140331* 8007150497 8007160612	50-327 A 50-327 G 50-275 R 50-327 A 50-327 G
CLAYTON, F L CLEMENT, C CLEMENT, C CLEMONS, P CLEVELAND, C J	8007310330 8007010450* 8007070372* 8007210304* 8007220038	50-364 G 50-336 S 50-336 S 70-687 50-263 P	COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007220405 8007220404 8007220408 8007220409 8007220411	50-295 S 50-304 S 50-304 B 50-304 S 50-304 S	COONEA'N T COOK'T M COOK'T M COOK'T M	8007210483 8007290206 8007280124 8007240331* 8007070352	50-329 A 50-329 8 50-329 R 70-1257 50-276 8
CLOGBURN, T CLUCAS, J A CLUSEN, R C COCHRAN, T B COCHRAN, T B	8007210400* 8007010457 8007300234 8007110004 8007140498	50-368 8 50-275 H FR 70-143 FOIA	COLLINS, M COLLINS, M COLLINS, M COLLINS, J T GOLLINS, M	8007220412 8007220413 8007220414 8007310136 8007230339	50-304 8 50-304 8 50-304 6 50-289 R 50-237 8	COONEY, M J COONEY, M J COOPER, W E COOPER, W E	8007080214 8007180419 8007210378 8007310386 8007110453	50-277 8 50-277 R 50-278 9 50-329 A NUREG
COCHRAN, R G COCHRAN, R G COCHRAN, R G COFFEY, M E COFFMAN, F D	8007210502 8007210512* 800724003B 8007220101* 8007010093*	50-59 R 50-59 R 50-59 R Waste Hot Fola	COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007230345 8007230347 8007230351 8007230352 8007230357	50-295 8 50-295 8 50-295 8 50-295 8 50-295 8	COOPER.L J COPELAND.R L COPELAND.R L COPELAND.R L COPELAND.J 0	8007250501 8007030179 8007010366 8007100174 8007080058	50-298 8 PR 50-537 F 50-537 F 50-466 Q
COFFMAN, F D COFFMAN, F D COFFMAN, F D COFFMAN, F D	8007010108* 8007010114* 8007010126* 8007010158* 9006120855	FOIA FOIA FOIA FOIA OEN TEC IB	COLLINS.M COLLINS.M COLLINS.J T COLLINS.J T COLLIER.R P	8007230359 8007230397 8007310356 8007310458 8007240394	50-249 8 50-245 8 50-320 P 50-320 P NUREO	COPELAND, J 0. COPELAND, J 0 COPELAND, J 0 COPELAND, R L COPELAND, J 0	8007090189 8007080058 8007090189 8007080264 8007160639	50-446 Q 50-466 Q 50-466 Q 50-537 B 50-466 Q
CDG01N, C L CDG01N, C L CDG01N, C L CDG01N, C L CDG01N, C L	8007030286* 8007020642* 8007110437* 8007110313* 8007150642*	50-321	COLOMBO, P COLOMBO, R W COLOMBO, R W COLOMBO, R W COLT, B	8007310214 8007080277* 8007150592* 8007310418* 8007230630*	NUREO 50-312 8 50-312 R 50-312 8 50-320 H	COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	8007160639 8007300417 8007250424 8007250424 8007270082	50-466 0 50-478 0 50-466 0 50-466 0
C0991N, C L C0991N, C L C0991N, C L C0991N, C L	8007280455# 8007170419# 8007210397# 8007210371# 8007220519#	50-386 8 50-321 8 50-386 8 50-321 8 50-321 8	CDLTON, E COMPTON, R M CONDIE, K Q CONGEL, F J CONGEL, F J	8007020379 8007160742* 8007210017 8007030373 8007100369	XPORTLIC 50-338 O REB NUREO NUREO NUREO	COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	8007300413 8007300447 8007300413 8007300447 8007300402	50-466 Q 50-466 Q 50-466 Q 50-466 Q
COHEN, B COHEN, B COHEN, I COHEN, I COHEN, B	8007300513* 8006300112* 8007280746* 8007250494* 8007070057*	50-321 8 ACRB 70-1100 70-820 CONTRACT	CONCEL.F J CONLON.T E CONLON.T E CONLON.T.E CONLON.T E	8007170359* 8007100413* 8007100435* 8007070169* 8007180234*	50-320 0 50-324 0 50-400 0 50-387 0 50-553 0	COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	8007300435 8007310074 8007310308 8007300402 8007300435	50-466 Q 50-466 Q 50-466 Q 50-466 Q
COHEN, J C COHN, B M COLBERT, W F COLEMAN, R COLEMAN, R	6007180217* 8007150119 8007160667 8007170167 8007240168	State Prog FR 50-341 A CONTRACT CONTRACT	CONLON: T E CONLON: T E CONLON: T E CONLON: T E CONNERS: E L	8007100151* 8007150021* 8007180275* 8007290414* 8007140027	50-269 0 50-269 0 50-395 0 50-424 0 50-336 P	COPELAND, J O COPELAND, J G CORBETT, J S CORDETT, J S CORCORAN, T	8007310074 8007310308 8007100461 8007160417 8007270221	50-466 Q 50-466 Q 71-9094 71-9070 40-299
COLEMAN, R COLEMAN, R COLEMAN, R COLLINS, P COLLINS, R	6007250554 8007280712 8007170217 8007020731* 8007150071*	CONTRACT CONTRACT CONTRACT CONTRACT 50-267 G	CONNELLY, D O CONNER, T B CONNER, T B CONNELL, C CONNER, T B	8007250587* 8007110553 8007150112 8007210377* 8007150059	GA999 PR PR 50~284 R 27~39	CORCORAN, T CORDANI.R A CORDANI.R A CORDANI.R A CORE.M	8007020088* 8007010553 8007020339 8007020358* 8007070385*	50-10 U 71-5341 70-27 70-27 50-285 8
COLLIER, R E COLLINS, P F COLLINS, J N COLLINS, J T COLLINS, F N	8007140074 8007020317 8007180428 8007020182 8007210331*	PR 30-254 V 30-400 V 50-320 R CONTRACT	CONNER, T B CONNOLLEY, J L CONRAD, E T CONRAD, R E CONTE, R J	8007310424 8007070385* 8007070058* 8007010334 8007250207	90-395 M 50-285 8 CONTRACT 50-334 P 80-320 8	CORNELL, D A CORREA, M A CORREA, M. A CORREA, M A CORRIGAN, J J	8007090418 8007010523 8007310342 8007310376 8007250028*	REGOD 50-272 J 50-272 J 50-272 J COMMIBBION
T L.ENILLOS T L.ENILLOS T L.ENILLOS T L.ENILLOS T L.ENILLOS	8007100183 8007110293 8007250207 8007250223 8007250201	50-320 P 50-320 F 50-320 B 50-320 B 50-320 S	CONTE,R J CONTE,R J CONTE,R,J CONTE,R J, CONTE,R J	8007250201 8007250214 8007250231 8007250237 8007170547	50-320 8 50-320 8 50-320 8 50-320 8 50-320 6	CORWIN.J W CORYELL.G P CORYELL.G P COSTELLO.F COSTELLO.F	8007110121 8007020220* 8007280225* 8007170349* 8007170438*	PR 70-1151 70-27 70-1869 FOIA
COLLINS, F M COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	8007140203* 8007150053 8007180102 8007250214 8007250231	CONTRACT 50-320 R 50-320 R 50-320 S 50-320 S	CONTE.R J CONTE.R J CONTE.R J CONTE.R J CONTE.R J	8007170540 8007170553 8007170564 8007170557 8007240203	50-320 8 50-320 8 50-320 8 50-320 8 50-320 8	COSTELLO, F COTTLE, W T COUNBIL, W G COUNBIL, W G COUNBIL, W G	8007140631* 8007170224* 8007300338* 8005300283 8007100035	40-8702 50-327 G 50-213 P PR PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COUNSIL. W O COUNSIL. W O COUNSIL. W O COUNSIL. W O	8007100035 8007020039 8007020472 8007170494 8007020472	PR 50-336 Q PR 50-213 Q PR	CREWS,E H CREWS,E H CREWS,E H CREWS,E H CREWS,E J	8007090011 8007170561 8007080393 8007220219 8007310294	50-395 A 50-204 G 50-395 A 50-395 Q 50-312 G	CROW, W T CROW, W T CROW, W T	6007010184* 9007020233* 9007030028* 9007280327* 8007220220*	70-2885 70-2910 70-1151 70-1319 70-135
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007170519 8007010328 8007170320 8007170320 8007210520*	50-423 Q 50-245 P 50-213 Q 50-213 D 50-423 S	CREWS.E H CREWS.E H CREWS.J L CREWS.J L CREWS.J L	8007070269 8007160252 8007300273 8007300339 8007300518	50-395 C 50-395 A 50-344 G 50-206 G 50-344 G	CROW, U T	8007070175* 8007180078 8007230062* 8007240270* 8007240110*	70-1113 70-1151 70-2379 70-1739 70-1201
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007010337 8007030356 8007010337 8007010354 8007030356	50-213 F 50-245 F 50-213 F 50-423 Q 50-245 F	CREWS, J L CREWS, E H CREWS, E H GREWS, E H CREWS, E H	8007310321 8007170607 8007220390 8007220428 8007250308	50-275 Q 50-375 A 50-375 F 50-375 A 50-375 A	CROWELY, D R	8007240125* 8007270083* 8007300113 8007070107* 8007100060*	70-27 70-143 PR 50-335 <u>0</u> 50-251 0
COUNSIL.W O COUNSIL.W O COUNSIL.W O COUNSIL.W O	8007010337 8007090294 8007180137 8007020569 8007180578	50-213 F PRM 50-213 D 50-213 P 50-213 Q	H B.RWBRD H B.RWBRD H S.RWBRD H SANGLOBIRD H B.RWBRD H B.RWBR H B.RWBR	8007250459 8007250491 8007250426 8007250410# 8007080239#	50-395 S 50-395 A 50-395 F 50-336 S 50-382 S	CROWLEY, B R CROWLEY, B R CROWN, H M CRUMP, M W CRUTCHFIELD, B	8007270432* 8007310501* 8007110537* 8007110248* 8007100077	50-366 G 50-270 G CONTRACT TOPREP 50-206 P
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007020569 8007230048 8007290852 8007080164 8007290852	50-213 P PRM PR 50-334 P PR	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8007150163* 8007090373* 8005290612* 8007150314 8007020121*	70-364 50-271	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007100102* 8007100107* 8007030335 8007100394 8007100401*	50-206 P 50-206 P 50-155 P 50-217 P
COUNSIL, W C COUNSIL, W C COUNSIL, W C	8007080135 8007090231 8007070251 8007090231 8007170425	50-245 P 50-213 F 50-245 P 50-213 F 50-213 F	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8005290603 8007310291 8007140631* 8007140627 8007210195*	PT9 70-474 40-8702 40-8702 70-33	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007100408* 8007160421 8007160425* 8007160427* 8007250541	50-219 P 50-29 P 50-29 P 50-29 P 50-155 P
COUNSIL, W C COUNSIL, W C COUNSIL, W C COUNSIL, W C	8007170425 8007100200 8007210387 8007140344 8007210237	50-213 F 50-245 P 50-245 P 50-334 P 50-213 P	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKET, L	9007230608* 8007010597 8007210170* 8007230212 8007310019	70-2000 70-2574 70-1143 50-245 8 50-219 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007250546 0007250594 8007250558 8007010003 8007100276	50-249 P 50-219 P 50-10 P 50-237 P 50-255 P
COUNSIL.W C COUNSIL.W C COUNSIL.W C COUNSIL.W C	8007160369 8007210238 8007300324 8007220457 8007250300	50-213 G 50-336 P 50-213 P 50-245 P 50-245 P	CROLEY, B O CROBBY, P J CROBBMAN, W A CROBBMAN, W A CROBBMAN, W A	8007170612* 8007230574* 8007010212* 8007110076* 8007070091*	50-395 A 50-219 8 50-498 Q 50-382 Q 50-482 Q	CRUTCHF (ELD, D CRUTCHF (ELD, D CRUTCHF (ELD, D CRUTCHF (ELD, D CRUTCHF (ELD, D	8007100299* 6007110247 600710254* 6007010111 6007010113	50-255 P 50-255 P 50-255 P 50-155 P 50-219 P
COUNBIL, W O COUNBIL, W O COUNBIL, W O COUNBIL, W O COWAN, F E	8007240053 8007240067 8007280574 8007280673 8007020605	50-213 P 50-213 P 50-245 P 50-213 P 50-478 0	Crossman, W A	8007110178* 8007100346* 8007110234* 8007240337* 8007020068	50-482 Q 50-495 Q 50-445 Q 50-496 Q 50-482 S	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007010118 8007010120 8007010122 8007010124 8007010130	50-29 P 50-409 P 50-213 P 50-244 P 50-245 P
COWAN, F COWAN, B Z COWAN, B Z COWAN, B Z COWAN, B Z	8007300406 8007220560 8007220560 8007250685 8007250685	50-498 Q XPORTLIC XPORTLIC XPORTLIC XPORTLIC	CROSS, J L CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, J L	8007020740 8007180574* 8007230292* 8007280153* 8007210103	50-327 G 50-445 G 50-478 G 50-382 G 50-259 G	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007010137 8007010146 8007020186 8007020170 8007020173	50-206 P 50-10 P 50-10 P 50-206 P 50-217 F
COX.F T COX.B CRABTREE,R A CRADDICK,W O CRAMER,E N	8007110056 8007020455* 8007080217 8007300575 8007140051*	PR 50-271 H 50-309 I NUREO PR	CROSS, J L CROSS, J L CROSS, J L CROUSE, R P CROUSE, R P	8007250596 8007310067 8007300374 8007010254 8007240028*	50-259 0 50-259 0 50-327 K 50-346 0 50-346 0	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D	8007020402 8007020662 8007020666 8007020669 8007020676	50-409 D 50-10 Q 50-219 Q 50-245 Q 50-155 Q
CRAMER, E N CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8007140036 8007250668 8007230662 8007280697 8007230016	PR 50-193	CROUSE, R P	8007020040 8007150824 8007170064 8007180310 8007140237	50-346 Q 50-346 Q 50-346 Q 50-346 Q	GRUTCHFIELD.D GRUTCHFIELD.D GRUTCHFIELD.D GRUTCHFIELD.D GRUTCHFIELD.D	9007010042 9007010217 9007010272 9007140623 9007140628#	50-10 P 50-10 P 50-10 P 50-244 P 50-244 P
CRANE.P A CRANE.P A CRANE.P A CRANE.P A CRANE.P A	8007240187 8007250658 8007140242 8007020394 8007010469	50-275 0 50-275 0 71-9094 50-275 A 50-133 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8007010464 8007230076 8007230141 8007170532 8007180271	50-346 P 50-346 Q 50-346 Q 50-346 Q	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	800/140636* 80071/0042 80071/0240 8007020479 8007160459	50-244 P 50-155 F 50-409 I 50-10 P
CRANE, PA CRANE, PA CRANE, PA CRANE, PA CRANE, PA	8007070153 8007300280 8007160520 8007310468 8007150377	50-275 A 50-275 0 50-275 A 50-133 Q 50-275 F	CROUSE, R P	8007300141 8007070254 8007210216 8007310536# 8007150670	PR 50-346 F 50-346 Q 50-346 Q	CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	6007180289 0007250666 0007280107 8007180180 8007220158	50-255 P 50-255 P 50-244 P 50-155 H 50-206 P
CRANE, P A CRANE, P A CRANE, P A CREED, J R CREED, J R	8007180405 8007180340 8007180358 8007010578* 8007310267*	50-275 0 50-275 A 50-133 0 70-1308 50-305 0	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8007230200 8007230200 8007250572 8007210454 8007270500	50-346 Q 50-346 Q 50-346 Q 50-346 P 50-346 Q	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007220162* 8007220165* 8007240069 8007140236 8007240073	50-206 P 50-206 P 50-244 P 50-155 H 50-248 P
CREIGHTON, T CREMAR, D A CREWAS, J L CREWAS, E H CREWAS, J L	8007220224* 8007070269 8007170569* 8007110489 8007220330	M190 50-10 D 50-206 G 50-395 B 50-73 Q	CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P	8007310348 8007230581 8007250427 8007250382 8007250434	50-346 P 50-346 P 50-346 P 50-346 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	800/240079 800/180436 800/180438 800/180466 800/210638	50-409 P 50-10 P 50-10 P 50-27 P 50-409 P
CREWS.J L CREWS.J L CREWS.J L CREWS.J L	8007210099 8007170084 8007240385 8007240407 8007240267	50-224	CROUSE, R. P CROUSE, R. P CROW, W. T. CROW, W. T CROW, W. T	B007280485 8007310380 8007010027 8007280177 8007020337	90-346 P 90-346 P 70-2909 70-143 70-824	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	800/230111 8007240275 800/250673 800/250674 800/280103	50-245 P 50-10 P 50-255 P 50-213 P 50-213 P
								'

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCEGSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CRUTCHFIELD, D	8007290373	50-155 P	DALE, L F	8007160619	PR	DAVIS, A B	8007230549	70-925
CRUTCHFIELD, D	8007170049	50-206 H	DALE, L F	8007160610	50-416 A	DAVIS, S M	8007230153*	50-318 6
CRUTCHFIELD, D	8007280150	50-213 P	DALE, L F	8007070118	PR	DAVIS, S M	8007280453*	50-317 8
CRUTCHFIELD, D	8007250716	50-219 P	DALE, L F	8007250520*	50-416 S	DAVIS, S M	8007280676*	50-317 8
CRUTCHFIELD, D	8007280172	50-206 P	DALE, L F	8007010361	50-416 F	DAWSON, R S	8007290277	71-6717
CRUTCHFIELD, D	8007290364	50-155 P	DALE.L F	8007030245	50-416 A	DAWSON, D H	8007020611*	70-1308
CRUTCHFIELD, D	8007180196	50-213 F	DALE.L F	8007070245	50-416 E	DAWSON, R S	8007220279	71-9039
CRUTCHFIELD, D	8007240144	50-244 P	DALE.L F	8007210270	50-416 Q	DAWSON, R	8007290282*	71-6717
CRUTCHFIELD, D	8007280180	50-213 P	DALE.L F	6007110412	50-416 K	DEALE, V B	8007110042	50-522 0
CRUTCHFIELD, D	8007250032	50-10 P	DALE.L F	8007140388	50-416 E	DEAN, D	8007240472	XPORTLIC
CRUTCHFIELD, D	8007280142	50-244 G	DALE.L F	8007280494	50-416 A	DEASON, V A	8007270171	RES
CRUTCHFIELD, D	8007280161	50-255 P	DALE.L F	6007180293	50-416 F	DEBDER, T K	8007150067	PR
CRUTCHFIELD, D	8007280206	50-213 P	DALE.L F	8007220569	50-416 A	DECKARD, J	8007250246*	50-546 V
CRUTCHFIELD, D	8007240250	50-10 F	DALTROFF.S L	8007210215*	50-277 Q	DECKER, T	8007170556*	50-315 G
CRUTCHFIELD, D	8007250691	50-217 P	DALTROFF.S L	6007010378	50-277 O	DEHART, R M	8007150077	PR
CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8007250672 8007250720 8007289098 6007280†35 8007280†35	50-213 P 50-219 P 50-206 P 50-244 P 50-409 P	DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L	8007020072 8007180104 8007180117 8007170507 8007240003	50-277 Q 50-277 Q 50-277 Q 50-277 Q PR	DELANEY.J C DELANEY.J C DELANEY.J C DELANEY.J C	8007010184* 8007010195* 8007020431* 8007020233* 8007020258	70-2685 70-2638 70-2609 70-2710 70-143
GRUTCHFIELD.D	8007300050	50-244 F	DALTROFF, S L DALTROFF, S L DANCE, H C DANGE, H C	8007250631	50-277 Q	DELANEY.J C	8007020304	70-143
CULP.R H	8007080058	50-466 Q		8007210547	50-277 Q	DELANEY.J C	8007240102*	70-1359
CULP.R H	8007080058	50-466 Q		8007250511	50-277 Q	DELANEY.J C	8007230062*	70-2375
CULVER.J F	8007020444	FR		8007010089	50-327 B	DELANEY.J.C	8007240270*	70-1738
CULVER.M N	8007150713*	50-302 R		8007240272*	50-321 Q	DELANEY.J.C	8007270083*	70-143
CUNNINGHAM, O E CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, R E	8007010595 8006170915 8007020078 8007140580 8007180460	71-5980 71-9137 50-201 P 50-201 P 71-9136	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANFORTH, J C	8007280484 8007100066* 8007170224* 8007310351* 8007110571*	50-259	DELOEDROE,L O DELOEDROE,L O DELLA RATTA,A DELDRO,S D	8007020074 8007070267 8007160606 8007280746* 8007150623*	50-295 G 50-373 K 50-373 A 70-1100 50-315 S
Cunningham, a l Cunningham, a l Cuniingham, o e Cuniingham, o u Cunningham, o h	8007290404* 8007290853* 8007280058 8007300411 8007220003	50-390 9 50-328 9 71-170 PR 70-143	DANIELGON, D H DANIELGON, D H DANIELG, F T DANIELGON, D H DANIELGON, L J	8007160741* 8007180519* 8007240253* 8007230087* 8007150153	50-440 Q 50-456 Q 50-358 Q 50-358 Q 8EQQD	DENNISON, A B DENNISON, A B DENTON, H R DENTON, H R	8007110094 8007110094 8007210109 8007110549 8007100099	50-358 0 50-358 0 40-2061 BECY BECY
RANDONIMOUS REPORTED TO THE STAND TH	8007310383 8007010537* 8007080410* 8007150599 8007280394*	50-5 F 50-206 S 50-206 S 50-206 R 50-206 S	DANIELSON, D H	8007230333* 8007230375* 9007230758* 8007230273* 8007310316*	50-346 Q 50-304 Q 50-295 Q 50-373 Q 50-266 Q	DENTON, H R	8007010215# 8007170083 8004240480 8007160786 8007180481	FOIA ' 50-320 P 50-284 P 8ECY 50-553 H
CURRY, J B CURTIB, J R CURTIB, J R CURTIB, J R CURTIB, N H	8007300571 8007230297* 8007030021 8007310168* 8007230147	PR 50-206 G 50-206 B 50-289 G PR	DANIEL, 8 L DARIOS, E L DARMITZEL, R U DARMITZEL, R U DARMITZEL, R U	8007290251 8007020307 8007010349 8007160360 8007220349	NUREG PR TOPREP 50-70 P 50-70 P	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007110593 8007180463 8007180468 8007180067 8007180474	50-295 H 50-320 H 50-320 H 50-320 H
U C.GITRUD	8007110376*	50-327 S	DAROIG, E L	8007020329	PR	DENTON: H R DENTON: H, R DENTON: H R DENTON: H R DENTON: H R	8007180492	50-320 H
U C.GITRUD	8007290659*	50-327 S	DAUCE, H	8004240250	50-327 5		8007230179	BECY
U N.GITRUD	8007080213	50-387 S	DAVIDEON, R H	8007100328	PR		8007180040	50-217 H
U N.GITRUD	8007080240	50-387 K	DAVIDEON, D R	8007180585*	50-440 G		8007180182	50-320 H
U N.GITRUD	8007140197	50-387 S	DAVIDEON, D R	8007180591*	50-440 G		8007180459	90-339 H
CURTIB,N W CURTIB,N W CURTIB,N W CURTIB,N W	8007140340 8007140170 8907180434 8007240131 8007180282	50-387 8 50-387 6 50-387 6 50-387 K 50-387 8	DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R	8007140534 8007080294 8007150553 8007230101 8007230321#	50-440 8 50-440 8 50-440 Q 50-440 Q	DENTON, H R	8007290089 8007160731 8007210046 8007090021* 8007180546	50-320 H 50-320 H 50-320 H
CURTIB.N W CURTIB.N W CURTIB.N W CURTIB.N W CURTIB.N W	8007180364 8007240142* 8007220441 8007250529 8007250487	50-387 S 50-387 K 50-387 F 50-387 A 50-387 S	DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIG, 8 DAVIG, 8 DAVIG, H A	8007150540 8007180406 8007140598 8007140611 8007030024	50-440 A 50-440 G 50-440 E PR PR	DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R	8007180553 8007210208 8006300097 8007020055 8007100207	50-320 H 50-320 H ACR8 50-320 H 50-302 P
CURTIS, N H CURTIS, N H CURTIS, N, H CURTIS, N, H	8007280215 8007270455 8007270423 8007270264 8007270716	50-387 B 50-387 B 50-387 S 50-387 B 50-387 B	B A.SIVAD B A.SIVAD H L.SIVAD B A.GIVAD P L.SIVAD	8004240258 8004240276 8007070019* 8007210007 8007030050*	1&E 1&E 70-143 RES PR	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8007250611 8007180004 8007180042 8007110195 8007010246	COMMISSION 50-320 P 50-322 H NUREG 50-320 H
Curther, A P	8007230498	50-124 P	DAVIG.A B	8007100094	50-546 Q	DENTON, H R	8007020677	50-320 H
Cutchin, J M	8007010274	50-387 Q	DAVIS.A B	8007140035	70-8		8007100392	MISC
Cutchin, J M	8007010273	50-387 Q	DAVIS.A B	8007100085	50-409 Q		8007110483	30-320 H
Cutchin, J M	8007150709	50-387 Q	DAVIS.A B	8007170545	50-315 Q		8007170548	50-320 H
Cyphert, S B.	8007170364	50-445 M	DAVIS.Q.R	8007110454	NASTE HOT		8007180224	MISC
CYPHERT.S B	8007160547	50-445 H	DAVIS, O R	8007110457*	HASTE MOT	DENTON, H R	8007210530	50-320 H
CYPHERT.S B	8007300418	50-445 M	DAVIS, A B	8007170300	70-925	DENTON, H R	8007170551	50-320 H
CYR.K	8007300370*	50-266 0	DAVIS, A B	8007140464	50-346 Q	DENTON, H R	8007210645*	50-301 0
CYR.K D	8007100241	50-266 0	DAVIS, A B	8007110200	50-10 Q	DENTON, H R	8007210647*	50-301 0
CYR.K D	8007290070	50-266 0	DAVIS, A B	8007280454	50-87 Q	DENTON, H R	8007020090	50-443 H
C2Y8CIN8KI.K 8	8007210005	RES	DAVIS, A B	8007210501	50-263 Q	DENTON, H R	E007020432	50-271 0
C2Y8CIN9KI.K 8	8007210471	NUREQ	DAVIS, A B	8007230268	50-275 Q	DENTON, H R	B007020437*	50-271 0
D'AMORE.M	8007210077*	70-1151	DAVIS, A B	8007160700	40-7982	DENTON, H R	B007100421	50-443 H
DAODJART88DN.8	8007310255	NUREO	DAVIS, A B	8007310335	50-295 Q	DENTON, H, R	B007100424	50-443 H
DAIL.L C.	8007030189*	50-413 A	DAVIS, A B	8007250626	70-925	DENTON, H R	B007140265*	50-346 M
DAIL.L C	8007210486*	50-413 A	DAVIS, J F	8007290622	50-312 P	DENTON, H R	8007180462	MISC
DAIL.L C	8007250532	50-488 G	DAVIS, J P	8007210473	50-3 R	DENTON, H R	8007020325	COMMISSION
DALE.L F.	8007160617*	50-416 A	DAVIS, L D	8007210436	50-361 0	DENTON, H R	8007140040	50-320 0
DALE.L F	8007020615	50-416 B	DAVIS, A B	8007280710	70-925	DENTON, H R	8007280593*	50-320 0
DALE.L F	8007140575	PR	DAVIS, L D	8007160613	50-367 0	DENTON, H R	8007010254	50-484 0

AUTHOR	AGCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DENTON, H R	8007010263* 8007010272 8007030210 8007290047 8007100145	50-484 Q 50-484 Q 50-273 P 50-320 H	Dickinson, P Oickeon, H W Dickeon, H W Dickeon, H W Dickson, F S	8007010013 8007180352 8007140031 8007140634 8007280333	ORO RES RES RES 40-8745	DODDS, R T DODDS, R T DODDS, R T DODDS, R T DODOS, R T	8007170537# 8007180018# 8007210578# 8007240326# 8007240314#	50-361 0 50-206 0 50-528 0 50-206 0 50-344 0
DENTON, H R	8007100377 8007270064 8007020243 8007020481 8007020485*	80-10 P 50-320 H 50-312 G 50-3 G	OICKSON, H W DICKSON, H W OIEHL, D S DICTCH, R DIETCH, R	8007300041 8007310251 8007030003 8007020362 8007020366*	NUREO RES PR 90-206 P 50-206 P	DODDS,R T DODDS,R T DOGGETT,S A DOHERTY,J F DOHERTY,J F	8007300318* 8007310516* 8007100174 8007030339 8007230246	50-361 0 50-528 0 50-466 0 50-466 A 50-466 0
DENTON, H R OENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007020690 8007140106 8007070059 8007070064* 8007070069*	50-528 G 50-437 H 50-280 H 50-280 H 50-280 H	DIGGS.R H DIGGS.R M DIMEGLIO.A F DIMEGLIO.A F OINCAUZE.D F	8007020510 8007210156 8007090272 8007210118 8007100079	50-277 P 50-331 P 50-193 P 71-17 PR	DOLAN, F X DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E	8007220334* 8007310284* 8007110465 8007030206 8007020245	TOPREP 50-315 Q 50-315 Q 50-315 Q 50-315 Q
DENTON, H R	8007110484 8007140021 8007020399 8007290275 8007290287*	SECY 50-323 H 50-320 P 50-327 G 50-327 G	DIPIAZZA,R P OJPIAZZA,R P DIPIAZZA,R P OJPIAZZA,R P DIPIAZZA,R P	8006300292 8006300017 8007020221 8007100358 8007110522	70-1151 70-1151 70-1143 PRM PRM	DOLAN, J E DOLE, R DONAT, T J DONAT, T J DONEGAN, G C	8007020591 8007110571* 8007240377* 8007300330 8007300315*	50-315 P 50-486 U 50-369 G 50-369 B QA999
DENTON, H R	8007110082 8007110554 8007110563* 8007170330* 8007170333*	50-271 H 50-155 G 50-155 G 50-10 G 50-10 G	DIPIAZIA,R P DIPIAZZA,R P DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007180545 8007240094 8007300103* 8007020279* 8007300094*	70-1151 71-5450 70-143 UASTE MGT 70-143	DONOGHUE, D J DONOVAN, L J DORFMAN, L O DORNSIFE, N P DORNSIFE, N P	8007270023 8007250476 8007110327* 8007140946* 8007140046*	SECY TOPREP UIGC PR PR
DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007170336* 8007230225 8007230626 8007280122 8007290054	50-10 G 50-320 H 50-320 H 50-320 H 50-320 H	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007140102* 8005200252 8007090023*, 8007290286 8007290029*	50-397 Q 50-320 U SECY PR SECY	DOTILER, T DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8007290296* 8007310492* 8007220111* 8007140633* 8007010582*	50-327 G FOIA HASTE MOT CONTRACT CONTRACT
DENTON, H R	8007300013 8007230542 8007230070 8007230081 8007290234	50-320 H 50-440 H 50-320 H 50-320 H 50-312 H	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007290085 8007140118* 8007290028 8007250019* 8007140848	50-341 K 50-277 H SECY 10CFR COMMISSION	DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DDUGHERTY, D J DOUGHERTY, D J	8007030071* 8007030357* 8007110575* 8007070052 9007070094*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R	8007140572 8007220027 8007220129 8007300301 8007170439	REGOD 50-5&6 H 50-320 P XPORTLIC 50-337 P	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007140854 8007180017 8006270181 8007020229 8007020264	COMMISSION State Prog 50-155 H 50-320 H WASTE MOT	Daugherty, D J	8007070057# 8007070058* 8007070060* 8007070062* 8007160490	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R	8007170443* 8007180174 8007280182 8007220031 8007230286	50-339 P RECOD 50-320 H 50-289 H 50-320 H	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8007020113 8007010128 8007020117 8007020198 8007020053	State Prog State Prog 50-271 H 50-324 H 50-500 H	DOUGHERTY, D U O, YETSHOUDG U O, YETSHOUDG U O, YETSHOUDG U O, YETSHOUDG	8007160496* 8007160478* 8007160504* 8007160513* 8007280527*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007250721 8007210643 8007230569 8007240297 8007240302*	COMMISSION 50-301 Q 50-320 H 50-327 P 50-327 P	DIRCKS, W J DIRCKS, W J OIRCKS, W J OIRCKS, W J	8007020091 8007020069 8007020082 8007230117 8007110321	50-320 H MISC 50-10 U 50-201 P MISC	DRACOMETTE,K B DRAKE,O A DRAFER,E L DRAFER,E L DRAPER,E L	8007020760 8007020366 8007290424 8007160495 8007220574	27-47 PR PR HUREO 50-459 Q
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007250624 8007280149 8007290039 8007250699 8007280076	50-289 H 50-561 H PROJ MIBC 50-10 P	OIRCKS, W J OIRCKS, W J OIRCKS, W J	8007140230 8007110304 8007110335 8007110338 8007240132	50-10 H 50-335 H MISC 50-352 U NUREQ	DRASTER, J J DREY, L A DREY, K DREY, K DREY, K	8007100122 8007100425 8007080926 8007210145 8007220386	REGOD REGOD 50-320 H 40-8502 50-10 D
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007290031 8007280106 8007290034 8007310549* 8007300284	50-289 H 50-320 H 50-483 A FDIA 50-259 P	Dircks, W J Dircks, W J Dircks, W J Dircks, W J	8007250225 8007250277 8007260823 8007280549 8007180214	50-546 U 50-275 H 50-329 H 30-171 H State Prog	ORIGHILL.D D DRIGHILL.D D DROMERICK.A N DROMERICK.A N DUDRY.N E	B007280137# B007150007* B00707053 G007280006 G007170310*	50-478 Q 50-478 Q 50-337 P 50-311 P 70-925
DEPOORTER. J DEVELIN. J. H DEVINE. J DEVINCENTIS, J DEVINCENTIS, J	8007140405 8007140615 8007310266* 8007010223* 8007170576*	PR 50-334 8 F01A 50-443 Q 50-443 B	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007250251 8007280509 8007150743 8007250167 8007280713	50-317 H 50-483 U FOIA 50-320 H PR	DUCE, 8 W OUCKWORTH, J P DUCKWORTH, J P OUTMER, G H	8007270217 8007210029 8007080246 8007230441	50-254 P 50-201 Q 50-201 Q 50-201 Q CONTRACT
DEVINCENTIS, J B L, JOHNS DEVINE, J B L, JOHNS DEVINE, J B L, JOHNS DEVINE, J B L, JOHNS DEVINE, J	8007250623 8007310039 8007310194 8007300037 8007310522	50-443 G XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J OIRCKS, W J	8007280714 8007240444 8007250062 8007250061* 8007310258	PR 50~335 H 50~320 H F01A F01A	DUNBAR, J DUNGAN, K W DUNGAN, C N DUNN, C N	8007100192* 8007140448 8007160176 8006230660 8007230150*	50-237 G PR PR 50-334 G 50-334 G
DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W	8007100074# 8005230131 8007240059# 8007230308# 8007290199#	50-293 Q 50-245 B XPORTLIC 50-289 Q 50-244 Q	DIRCKS, W J OTRCKS, W J DIRK, H OIGE, D P OIGE, D P	8007310526 8007310532 8007240413* 8007150122 8007070761	50-282 H 50-150 H 50-287 H PR 50-220 P	DUMN. C N DUMN. C N. DUMN. C N DUMN. C N DUMN. C N	8007230130# 8007210011 8007210011 8007080276 8007080080	50-334 P 50-334 G 50-334 G 50-334 P 50-334 P
DEVLIN, J W DEWEASE, J O DEWEY, L S. DEWITT, R & DEWITT, R &	8007230366* 8007220443 8007150719 8007250407 8007100201*	50-213 0 50-259 R 50-250 14 50-389 M 50-255 P	OISE, D P OISE, D P OISE, D P DIXON, O A OIXON, B	8007070089 8007300049 8007170394* 8007280684* 8007280503	50-220 0 PR 50-220 P 50-409 0 50-344 Q	DUNIH, C, N DUNIH, C N DUNIH, C N DUNIH, C, N DUNIH, B D	8007080424 8007150643 8007160564× 8007160654× 8007170371×	50-334 0 50-334 P 50-334 P 50-334 Q 50-330 R
DEWITT,R 8 DHILLON.H DIAMOND.M J DICK.J W DICKAJ W DICKASHON.M W	8007110209# 8007010419# 8007110101 8007310244 8007130091#	50-155 P CONTRACT PR NUREO 50-267 Q	DOAN, P F DORSON, W G DODDS, R T DODDS, R T ODDOS, R T	8007090007# 8007310386 8007230639# 8007020191# 8007170270#	50-298 8 50-329 A 50-397 Q 50-361 Q 50-528 Q	DUNIA, C N DUNIA, C N DUNIA, C N DUNIA, C N, DUNIA, C N, DUNIA, C N	8007140480 8007140595 8007140595 8007140647 8007150483	50-334 P 50-334 P 50-334 0 50-334 C
							,	33 831

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY
DUNN. C N DUNN. C N DUNN. C N DUNN. C N	8007150567 8007180418 8007220506 8007150480 8007220588	50-334 R 50-334 S 50-334 S 50-334 P 50-334 Q	EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0	8007170555 8007180150 8007280185 8007230198 8007310022	50-324 F 50-267 F 50-10 D 50-369 A 50-10 H	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007180295 8007180299 8007180304 8007180305 8007230381	50-312 0 50-397 0 70-1257 50-70 0 50-528 0
DUNN.C N DUNN.C N DUNN.C N DUNN.C N DUNNIC N	8007170545 8007250294 8007270543 8007270580 8007070371	50-334 0 50-334 0 50-334 P 50-334 G NUREG	EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0	8007310025* 8007230083 8007230090 8007230095 8007230104	50-10 H 50-346 F 50-269 F 50-312 F 50-321 F	ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8007230385 8007230387 8007230370 8007230393 8007230394	50-275 Q 50-133 Q 50-344 Q 50-361 Q 50-206 Q
DURKIN, J A DURR. J P DURR. J P DURR. J P DURR. J P	B007110507 B007020225* B007170645* B007220285* B007170257*	PR 50-334 Q 50-387 Q 50-317 Q 50-387 Q	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8007230126 8007230184 8007230208 8007230616 8007250185	50-277 F 50-302 F 50-275 A 50-311 P 50-364 A	ENGELKEN,R H ENGELHAN,G P ENGEL,R E ENGELKEN,R H	8007230399 8007230401 8007220065 8007170574* 8007280143	50-312 G 50-397 G RES 50-260 P 50-361 B
DUTTON, D DUTTON, D DUTTON, D DUVALL, D D DWDRAK, J A	8007110521* 8007020218 8007220275 8007080191 8007240394	50-424 G 50-424 O 50-424 G 50-354 A NUREG	EISENHUT, D G EISENHUT, D G EISENHUT, D G EKLUND, B	8007300061 8007310358 8007290357 8007300275 8007020674*	50-259 F 50-295 H 50-259 Q 50-277 B COMM169ION	ENGELKEN,R H ENGELKEN,R H ENGEL,R E ENGLEHART,R W ENGLEHART,R W	8007310437* 8007310447 8007250515 8007220111* 8007220036*	50-344 B 50-397 A TOPREP WASTE MOT WASTE MOT
DYER.O H EADIE.G EADIE.G O EADIE.G O EADIE.G G	8007140495 8007070155 8007100082 8007230141 8007230279	PR WABTE HOT 40-8200 40-8714 40~8200	ELIN, J O ELLERSHAW, L E ELLERSHAW, L E ELLERSHAW, L E ELLERSHAW, L E	8007240314* 8007300198* 8007250109* 8007160207* 8007300314*	50-344 Q GA797 GA797 GA797 GA797	ENOLE:N J ERB.C M ERH.C A ERICKBON:R A ERICBON:D M	8007300590* 8007170635* 8007150023* 8007250055* 8007020011	CONTRACT 50-329 0 50-483 0 FOIA RES
EADIE.G O EADIE.G EAGLETON.T F EARLEY.A F EARLY.P J	8007250054 8007230720 8007110571* 8007090306 8007180111	40-1341 HASTE HOT 50-482 U 50-322 G 50-286 G	ELLIS,J ELLIS,J ELLIS,J ELLIS,J ELLIS,J	8007070092 8007090327 8007300344 8007310123 8007220546	PR 50-445	ERNST, M L ESKRIDGE, H E ESSIO, T H ESSIO, T H ESSIO, T H	8007310113 8007140613 8007100079* 8007280457* 8007230276*	NUREO 71-4294 50-546 G 50-87 G 50-295 G
EAST. D EASTER, J. H EBERSOLE, J C EBNETER, S D EDNETER, S. D	8007170106 8007020338* 8007240475 8007170611* 8007210309*	40-8745 State Prog ACRS 50-286 G 50-354 G	ELLIS, J EMRATH, R M ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007220559 8007220574* 8007140584 8007140587 8007020234	50-445 0 50-327 8 50-133 0 50-397 0 50-344 0	ETHERIDGE,M R ETHEREDGE,L EURY,L W EVANS,R D EVANS,V R	8007140037* 8007250072 8007210022 8007100030 8007160245	GA999 FGIA 50-261 G PR 50-317 F
EDNETER, S D EDNETER, S D EDNETER, S D ECKERMAN, K F ECKHARDT. B	8007250270* 8007280080* 8007310063* 8007030373 8007110278*	50-293 0 50-333 0 50-277 0 NUREO COMMISSION	ENGELKEN'S H ENGELKEN'S H ENGELKEN'S H ENGELKEN'S H	8007020240 8007020242 8007020246 8007010016 8007220235	50-312	EVANB, V R EVDOKIMOFF, V N FABRIKANT, R FAHRNER, W J FAHRNER, W J	8007280481 8007090416 8007280636* 8007070078* 8007210136*	50-317 F REQOD 50-445 M 50-341 B 50-341 B
ECKHARDT, J H ECKHARDT, J H ECKHARDT, B EDDLEMAN EDELSTEIN, B	8007170539* 8007210578* 8007300365 8007100125 8007010577	50-361 0 50-528 0 50-498 U PRM XFORTL1C	ENGETKEN'E H ENGETKEN'E H ENGETKEN'E H ENGETKEN'E H	8007220237 8007220239 8007220241 8007220244 8007220249	50-133 Q 50-514 Q 50-344 Q 50-522 Q 50-206 Q	FAHRNER,W J FAHRNER,W J FAHRNER,W J FAIRHURBT,C FAIROBENT,J E	8007140326 8007170406 8007220545 8007030200 8007170342	50-341 8 50-341 8 50-341 8 PR 50-320 H
EDELSTEIN, B EDELSTEIN, B EDELSTEIN, B EDOENDRTH, P EDGENORTH, P EDGENORTH, P	8007020014 8007030063 8007160403 8007030337 8007070032	XPDRTLIC XPORTLIC XPORTLIC CONTRACT CONTRACT	ENGETKEN' & H ENGETKEN' & H ENGETKEN' & H ENGETKEN' & H	8007220250 8007220252 8007140412 8007140414 8007140418	50-312	FAIRTILE,M B FALK,K M FALK,K M FALK,K M FANTLE,H	8007240037 8007280477 8007230607 8007310373 8007140227#	50-302 P 50-301 G 50-266 G 50-266 H 50-409 H
EDGEWORTH, P J EDGEWORTH, P J EDGEWORTH, P J EDMONDSON L R EDWARDS, D W	8007070037 8007090084 8007140626 8007280527* 8007110529	CONTRACT CONTRACT CONTRACT CONTRACT PRM	ENGETKEN' U H ENGETKEN' U H ENGETKEN' U H ENGETKEN' U H	80072900B0 80072900B6 80072900BB 8007290090 8007030005	50-528	FARIB,H M FARLCY,A F FARLEY,A F FARNAN,J , FARNELL,A 8	8007210486* 8007030053 8007030053 8007310280 8007090045	50-413 A 50-322 Q 50-322 Q FBIA 50-327 Q
EDHARDE, D W EECKHOUT, A EGAN, O R EHRENGPERGER, W EHRENGPERGER, W	8007300009 B007210318* B007280404* B007080344 B007290774	PR XPORYLIC 50-206 8 50-424 H 50-424 F	ENOELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007030009 8007030009 8007030010 8007030014 8007030017	70-1257 70-734 50-206 Q 50-312 Q 50-275 Q	FARNELL, A B FARNELL, A B FARNELL, A B FAROOGUI, B M FAROOGUI, B M	8007070045 8007140020 8007140020 8007250393* 8007250398*	50-329 0 50-329 0 50-329 0 50-397 A 50-397 A
EICH, E EICHHORN, W H EICHHORN, W H EISENHUT, D O EISENHUT, D O	8007220479* 8007020453 8007020453 8006090165 8006130122	50-247 R 50-347 0 50-347 Q 50-320 P 50-320 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007030018 8007020466 8007020470 8007020474 8007020477	50-344	FABANO, A FABANO, A FABANO, A FABANO, A FABANO, A	8007250207 8007250223 8007250201 8007250214 8007250231	50-320 8 50-287 8 50-320 8 50-320 8 50-320 8
EISENHUT, D G EIBENHUT, D G EISENHUT, D G EISENHUT, D G EIBENHUT, D G	8006230110 8006130063 8007020396 8007180471 8007180479*	50-275 A 50-320 F NUREO TOPREP TOPREP	ENGETKEN' BH ENGETKEN' BH ENGETKEN' BH ENGETKEN' BH	8007020478 8007020480 8007180247 8007180251 8007180252	50-204 Q 50-312 Q 50-243 Q 50-289 Q 30-112 Q	FABANO, A FABANO, A N FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B	8007250237 8007230218 8004240286 8004240300 8007170579*	50-320 8 50-320 8 50-312 8 50-206 8 50-206 0
EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8007230079 8007180518 8007210032 8007020209 8007020183	50-320 P 50-344 Q 50-322 H 50-528 A 50-10 H	ENGELKEN, R H ENGELKEN, R, H ENGELKEN, R, H ENGELKEN, R H	8007180254 8007180259 8007180261 8007180263 8007180266	50-27	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B	8007220337* 8007210107* 8007240420* 8007240273* 8007310301*	50-73 0 50-224 0 50-312 0 50-206 0 50-312 0
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8007170323 8007180032 8007280079 8007310243 8007140221	50-10 @ 50-10 @ ORG 50-320 @ 50-409 H	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007180249 8007180272 8007180274 8007180278 8007180281	50-139 Q 50-228 Q 50-89 Q 50-187 Q 50-375 Q	FAULKENBERRY, B FAUST, R FAY, C W FAY, C W FAY, C W	8007300343* 8007170071* 8007020340 8007140559 8007010030	50-206 Q 50-317 P PR PR 50-266 Q
EISENHUT. D G EISENHUT. D G EISENHUT. D G EISENHUT. D G	8007170307 8007230001 8007240141 8007240479* 8007250001	50-289 P 50-275 A 50-269 P FOIA 50-320 P	ENOELKEN'S H ENGELKEN'S H ENGELKEN'S H ENGELKEN'S H	8007180283 8007180284 8007180287 8007180290 8007180292	70-984 50-528	FAY,C W Fay,C W Fay,C W Fay,C W Fay,C W	9007010062 8007160757 8007010043 8007010409 8007010420*	50-266 Q 50-266 Q 50-266 Q 50-266 S 50-266 S

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT CATEGORY
FAY.C W FAY.C W FAY.C W FAY.C W	8007080381 8007080384+ 8007110342 8007110347+ 8007300085	50-301 B 50-301 S 50-301 B 50-301 S FR	FELTON, J M	8007240183 8007240474 8007280197 8007240453 8007250022	FOIA 50-443 H FOIA FOIA FOIA	FIGRELLI.Q FIGRELLI.Q FIGRELLI.Q FIGRELLI.Q FIGRELLI.Q	8007230754 8007310363 8007140198 8007140202 8007150027	50-275 Q 50-461 Q 50-463 S 90-461 B 50-358 B
FAY,C W	8007090230	50-301 'P	FELTON, J M	8007250067	FOIA	FIORELLI.O	8007150032	50-327 8
FAY,C W	8007110333	50-266 8		8007280267	FOIA	FIORELLI.O	8007210516	50-461 0
FAY,C W	8007110340*	50-266 5		8007310481	70-2478	FIORELLI.O	8007300151	50-463 0
FAY,C W	8007110353	50-301 5		8007310544	FOIA	FIORELLI.O	8007300160	50-483 0
FAY,C W	8007110357*	50-301 6		8007310232	FOIA	FIORELLI.O	8007140470	50-341 0
FAY, C W FAY, C W FAY, C W FAY, C W	80071 50648 80071 50682 80071 70526 80071 50653 8007220071	50-266 P 50-266 P 50-266 Q 50-266 P 50-266 O	FELTON, J M FELTON, J M FELTON, J M FELTZ, D E FERGUSON, R	8007310276 8007310483 8007310285 8007270475* 8007240188*	FOIA FOIA 50-320 P 50-128 R FOIA	FIORELLI.O FIORELLI.G FIORELLI.O FIORELLI.O FIORELLI.O	8007300132 8007300138 8007300300 8007150002 8007170186	50-331 Q 50-454 Q 50-327 Q 50-483 Q 50-306 Q
FAY, C H	8007150618*	50-266 R	FEROUSON, J H FEROUSON, W J FEROUSON, W J FEROUSON, J H FEROUSON, J H	8007030131	50-280 P	FIORELLI, O	8007170425	50-327 0
FAY, C H	8007210408	50-266 P		8007080069	50-338 P	FIORELLI, O	8007310304	50-266 0
FAY, C H	8007240342	50-266 Q		8007150737	50-522 A	FIORELLI, O	8007170478	50-341 8
FAY, C H	8007150610	50-266 R		8007110364	50-339 P	FIORELLI, O	8007170520	50-327 8
FAY, C H	8007300430	50-301 Q		8007140393	50-338 P	FIORELLI, O	8007210128	50-341 8
FAY, C H	8007300440	50-266 F	FERNOS, O	80071405B1	50-376 Q	FIORELLI,O	800721000B	50-341 8
FAY, G W	8007300456	50-266 Q	FERNOS, O	8007230791	50-376 Q	FIORELLI,O	8007210012	50-546 9
FEE, W F	8007300331*	50-213 P	FERRARELLO, S	8007230573*	50-302 Q	FIORELLI,O	8007210021	50-546 8
FEE, W F	8007210387	50-245 P	FEUSS, J V	8007170277*	State Prog	FIORELLI,O	8007210025	50-546 8
FEE, W F	8007210238	50-336 P	FIDELL, E R	8007140619	50-320 H	FIORELLI,O	8007210031	50-546 8
FEE.W F FEIERABEND,C D FEIERADEND,C D FEIL,R A FEIL,R	B007220457 B007070061* B007240210* B0071B0561* B007210545*	50-245 P 50-282 Q 50-282 O 50-410 Q 50-423 Q	FIELDER, J FIELDER, J FIELDER, J FIELDE, M	8007010516 8007080261 8007310435 8007310436 8007310256	50-259 J 50-364 J 50-302 J 50-259 J Toprep	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8007210054 8007230415 8007150456 8007180511 8007180536	50-546 G 50-546 B 50-483 G \$0-461 B 50-546 G
FEIT, R	8007220041	REVIEW GRP	FIENO.D	8007010103*	50-249 P	FIORELLIO	8007180503	50-358 R
FELTON, J M	8007020284	FDIA	FILKINS.D	8007280639*	50-244 8	FIORELLIO	8007180588	50-440 Q
FELTON, J M	8007150756	FDIA	FINCKE.JR	8007290191	RES	FIORELLIO	8007180582	50-440 Q
FELTON, J M	8007170264	70-1949	FINFROCK.IR	8007110023*	70-1333	FIORELLIO	8007240319	50-546 B
FELTON, J M	8007070026	50-514 D	FINFROCK.IR	8007010468	50-219 P	FIORELLIO	8007180545	50-440 B
FELTON, J M	8007280279*	FOIA	FINFROCK, I R	8007020377	50-219 G	FIORELLI, G	8007210283	50-373 Q
FELTON, J M	8006300220	50-320 H	FINFROCK, I R	8007030216	50-219 P	FIORELLI, G	8007230313	50-440 Q
FELTON, J M	8007010070	50-249 P	FINFROCK, I R	8007070257	50-219 8	FIORELLI, G	8007240340	50-456 Q
FELTON, J M	8007030004	70-2478	FINFROCK, I R	8007110370	50-219 8	FISCHER, K	8007280486	50-206 P
FELTON, J M	8007030033	FOIA	FINFROCK, I R	8007110375	50-219 8	FISH, R F	8007130130*	50-344 Q
FELTON, J M	8007110007	BO-320 J	FINFROCK, I R	8007210042	50-219 @	FISH.R	8007230203	50-344 8
	8007290235	PR	FINFROCK, I R	8007090262	50-219 F	FISH.R	8007230165	50-312 8
	8007020122	FOIA	FINFROCK, I R	8007090259	50-219 @	FISHER.W L	8007140041*	70-8
	8007020132	FOIA	FINFROCK, I R	8007250305	50-219 @	FISHER.W L	8007100089*	50-407 9
	8007020440	FOIA	FINFROCK, I R	8007150705	50-219 R	FISHER.C R	8007020205	PR
FELTON, J M FELTON, J, M FELTON, J M FELTON, J M FELTON, J M	8007030064	FOIA	FINFROCK, I R	8007140500	50-219 P	FIGHER.W L	8007240007*	50-185 0
	8007030331	FOIA	FINFROCK, I R	8007170279	50-219 P	FIGHER.W L	8007170310*	70-925
	8007110478	50-320 P	FINFROCK, I R	8007180409	50-219 P	FIGHER.W L	8007140471*	50-346 G
	8007140212	FOIA	FINFROCK, I R	8007180415*	50-219 P	FIGHER.W L	8007310515*	50-275 G
	8007140277	FOIA	FINFROCK, I R	8007290184	50-219 P	FIGHER.W F	8007310002	XPORTLIC
FELTON, J M PELTON, J M FELTON, J M PELTON, J M FELTON, J M	8007100008	70-143	FINKEL, A	8007210240*	50-352 Q	FISSE, L R	8007020438	FR
	8007110004	70-143	FINKEL, A E	8007250270*	50-293 Q	FITZPATRICK, T	8007160838*	COMMISSION
	8007110004	Foia	FINKEL, A E	8007280080*	50-333 Q	FITZSIMMONS, T	8007240154	71-9132
	8007140239	Foia	FINKEL, A	8007310043*	50-277 Q	FLANDERS, N	8007110387*	50-309 R
	8007140226	Foia	FINLEY, A Q	8007290875*	50-254 Q	FLEGER, S	8007090146*	NUREO
FELTON, J K FELTON, J M FELTON, J M FELTON, J K FELTON, J K	9007140616	50-320 H	FINLEY, N C	8007270251	NUREO	FLEGER, B	8007070167*	NUREO
	9007140233	50-320 H	FIORELLI, O	8006300114	50-329 G	FLEISCHAKER, D	8007160410	PRH
	9007140635	50-458 H	FIORELLI, O	8007140522	50-463 G	FLEISCHAKER, D	8007100198	50-275 0
	9007140664	FGIA	FIORELLI, O	8007110153	50-461 G	FLCIBCHAKER, D	8007230508	50-275 0
	9007110139	50-302 H	FIORELLI, G	8007070154	50-440 G	FLEISCHAKER, D	8007230508	50-275 0
FELTON, J M	8007140245 8007110149 8007140645 8007150786 8007140491	FOIA FOIA FOIA FOIA	FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G	8007090174 8007110477 8007150017 8007140725 8007180508	50-440 Q 50-359 Q 50-483 Q 50-440 Q 50-456 Q	FLEIBCHAKER, D FLEIBCHAKER, D FLITTON, V E FLOWERB, F D FLOYD, B Q	8007300094 8007300094 8007280174 8007070047 8007220394*	50-275 0 50-275 0 RES PR 50-331 P
FELTON, J M	8007140511	50-320 H	FIORELLI, Q	8007150113	50-454 Q	FLOYD, 8 O	8007230484*	50~331 P
	8007170197	FDIA	FIORELLI, Q	80070200B1	50-341 Q	FLYNN, M J	8007020730	CONTRACT
	8007180098	50-302 H	FIORELLI, Q	8007160469	50-546 Q	FLYNN, M J	8007030336	CONTRACT
	8007220207	FOIA	FIORELLI, Q	8007230002	50-456 Q	FLYNN, M J	8007110535	CONTRACT
	8007220263	40-299	FIORELLI, Q	8007160751	50-461 Q	FLYNN, M J	8007210317	CONTRACT
FELTON, J M	8007220323	50-320 P	FIORELLI.G	8007230072	50-358 Q	FLYNNIM J	8007140200	CONTRACT
	8007220243	70-143	FIORELLI.G	8007020027	50-546 Q	FLYNNIM J	8007170212	CONTRACT
	8007230224	FOIA	FIORELLI.G	8007180495	50-440 S	FLYNNIM J	8007180521	CONTRACT
	8007230232	50-302 H	FIORELLI.G	8007020324	50-358 &	FLYNNIM J	8007210105	CONTRACT
	8007230240	50-466 G	FIORELLI.G	8007070095	50-341 B	FLYNNIM J	8007210122	CONTRACT
FELTON, J M	8007230250 8007250083 8007280272 8007300082 8007230559	FOIA FOIA FOIA 70-143 50-320 U	FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G	8007230059 8007230402 8007110228 8007110238 8007230327	50-341 Q 50-329 Q 50-461 Q 50-358 B 50-346 Q	FLYNN, M J FLYNN, M J FLYNN, M J FLYNN, M J FLYNN, J, D	8007210154 8007140512 8007170135 8007300579 8007220280	TOARTHOD TOARTHOD TOARTHOD TOARTHOD
FELTON, J M	8007230644	SO-10 D	FIORELLI,0	8007230365	50-304 Q	FOBES,R L	8007220484*	50-255 B
	8007240195	FOIA	FIORELLI,0	8007230693	50-373 Q	FOBES,R L	8007270616*	50-255 B
	8007240491	FOIA	FIORELLI,0	8007230704	50-546 Q	FOBO, N	8007110299	50-255 K
	8007280283	FOIA	FIORELLI,0	8007070197	50-329 S	FONNER,R L	8007210285	40-8502
	8007280290	FOIA	FIORELLI,0	8007230266	50-373 Q	FONNER,R L	8007100446*	40-8502

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCEBBION REMUN	SUBJECT CATEGORY
FONTECILLA.H M FONTECILLA.H FORD.U H FORD.C H FORD.R H	8007110496 8007110246* 8007110318 8007100113 8007230185	FOIA FOIA 50-546 U REGOD	CAMMILL, W P CANLEY, D E GARDER, S L GARCIA, P J GARCIA, P	8007170475 8007180064* 8007220047 8007150074 8007100447	MISC 70-371 RES 40-3493 40-1162	OILLESPIE, F P OILLESPIE, F P OILLESPIE, F P OILLESPIE, F P OILLESPIE, F P	8007110113* 8007100095* 8007290393* 8007090170* 8007140086*	50-335 G 50-241 Q 50-364 Q 50-369 G 70-143
FOSTER, W E FOSTER, W E FOSTER, J FOSTER, S C	8007010171+ 8007250594+ 8007220208+ 8007110572 8007150479	QA999 OA999 GA999 CONTRACT 50-155 J	GARCIA, P J GARCIA, P J GARCIA, P J GARCIA, P J GARNER, P L	8007140693 8007100088 8007290262 8007230715 8007240459	40-4492 40-1162 40-1162 40-8452 RUREQ	OILLESPIE,F P OILLESPIE,F P OILLEN,D K OILLESPIE,F P OILLETT,W T	8007140555* 8007160727* 8007230131 8007160761* 8007150547*	50-297 G 70-1113 40-2259 50-338 G 50-315 R
FOX.C J	8007010234	TOPREP	GARNER, D	8007180229	50-346 P	OILLETT, W T	8007150541*	50-316 R
FOX.D F	8007140124*	GA999	GARRAHY, J J	8007240389*	70-2153	OILLESPIE, F P	8007180316*	70-143
FRANCIS.E	8007030224	40-9745	GARRETT, E G	8006230378	50-309 H	OILLEN, D M	8007230667	40-8728
FRANCIS.F E	8007150458	50-484 G	GARRITY, J H	8007110386	50-309 R	OILLEN, D	8007230672	40-8681
FRANCIS.F E	8007150458	50-484 G	GARRITY, J H	8007280604	50-309 R	OILLEN, D	8007230680	40-8584
FRANCIS, F E	8007150458	50-484 G	GARRISON.W A	8007310269*	FOIA	GILLEN, D H GILLILAND, D L GILLILAND, D L GILLILAND, D L GILLILAND, D L	8007230715	40-8452
FRANKE, B	8007020554*	50-320 G	GARY.R J	8007140502*	50-445 Q		8007280577	50-70 P
FRANKE, B	8007150042	50-320 P	GARY.R J	8007170196	50-445 Q		8007280599	TOPREP
FRANTI, S P	8007020453	80-347 G	GARY.R J	8007110592	50-445 Q		8007280637	50-70 P
FREDERICK, E J	8007290241	RES	GARY.R J	8007140455	50-445 Q		8007230201	NUREG
FREEBURN, H R	8007080285*	TOPREP	GARY,R J	8007080042	50-446 8	GILMAN, D W	8007070234	50-206 P
FREEMAN, R	8007280671*	50-407 0	GARY,R J	8007080282	80-445 F	GINSBERG, T	8007150066	REB
FREY, D O	8007010955*	50-546 H	GARY,F S	8007300027	PR	GINSBERG, T	8007020085	REB
FREY, J M	8007170418*	COMM15910N	GARY,R J	8007180346	80-445 A	GINSBERG, T	8007210014	REB
FRIES, B A	8007140446	REOGD	GARY,R J	8007210392	50-445 8	GINSBURG, R	8007280537	50-10 D
FRIES,B A FRIES,R S FROST,S R FROST,S R FRYLING,R	80 07100133	REGOD	GARY,R J	8007210478	50-445 A	GIROUX.E J	8007170236	50-518 8
	60 07230 100	40-7402	GASCHLER,J A	8007290429	50-267 J	GIROUX.E J	8007170247	50-518 8
	60 07100 199	50-255 P	GASGER,E R	8007180193*	CONTRACT	GIUFFRE,M 8	8007100188*	PR
	60 07230 473	50-255 P	GASTON,H B	8007140473*	50-269 Q	GIVEL.M	8007230237	50-302 H
	60 071 50 50 9	50-272 O	GAY,N R	8007010040*	40-2674	GLENN.J E	8005020572	1&E
FULLER, J K	8007220439	PR	CAY,N R	8007010067*	40-2674	GLISSMEYER.J A	8007170311	NUREO
FULLER, F. K	8007280645	50-267 0	CEHR,A C	8007180405	50-275 0	GODDARD.R J	8007010331	50-237 9
FURBUSH, M H	8007180358	50-133 0	CEHR,A C	8007300106	50-528 0	ODGOL.E	8007250367	50-10 D
FURR, B J	8007150097*	50-261 0	CENDLER,M W	8007030305	50-522 A	GOLDBERG.S C	8007010131	50-599 0
FURR, B J	8007020087	50-261 0	GEOROIOU,B S	8007300419	50-275 0	GOLDBERG.S C	8007070104	50-320 0
FURR, B J FURR, B J FURR, B J FURR, B J FURR, B J	8007100031 8007220254 8007220240 8007170516 8007220227	50-261 0 90-261 0 50-324 0 50-324 0 50-261 0	OEOROIOU.B S GERBI.B J GERSTNER.W C GERSTNER.W C GERTH, O E	8007250429 8007020345 8007110233* 8007210521* 8007110534	50-275	QOLDBERG.S C QOLDBERG.S C QOLDBERG.R QOLDBERG.R QOLDBERG.S C	8007070094 8007170357 8007140875 8007140875 8007160591	50-250 Q 50-320 Q 50-346 M 50-346 M 50-320 Q
FURR. B J	8007240189	50-324	GERUSKY, T M	8007100186*	50-320 P	GOLDBERG.B C	8007220110	50-597 0
FURR. B J	8007310449		GESSELL, T F	8007310231	NUREO	GOLDBERG.B C	8007310314	50-502 0
FURR. B J	8007280104		GIBBONS, T O	8007180275*	50-395 Q	GOLDMAN.M	8007080353*	PR
FURR. B J	8007280111		GIBBS, O C	8007100005	PR	GOLDSMITH.R	8007180187*	50-10 0
FURR. B J	8007250296		GIBBS, O C	8007280032	PR	GOLDSMITH.R	8007180212*	50-10 0
FURR.B J	8007300561	50-324 0	01889: H E	8007210445	50-255 G	COLDBMITH, R	8007020195*	50-10 H
FURR.B J	8007310206	50-324 0	01885: M E	8007300421	50-329 0	COLDSCHMIDT, N	8007020447	PR
FURR.B J	8007310306	50-324 0	01880N: A F	8007070019*	70-143	COLDBMITH, R	8007020203*	50-10 H
GABRIEL.E	8007030158	PR	01880N: A F	8007030370*	70-1201	COLDBMITH, R	8007140625*	50-320 H
GADLER.S J	8007210150	40-1341	01880N: J D	8007020327	PR	COLDBMITH, R	8007140629*	50-320 H
QAGLIARDD.TE	8007210307#	50-277	GIEDT, J R	8007250600	40-1142	COLDEMITH, N	8007270372*	QA999
QAGNE.G R	8007180467#		GILBERT, L D	8007100346*	50-498 G	COLDENITH, R	8007230649	50-10 D
GAHM.J H	8007010346*		GILBERTS, D E	8007170194*	50-306 G	COLDEMITH, R	8007140337	50-10 Q
GAHM.J H	8007080262*		GILBERT, L D	8007110234*	50-445 G	COLDEMITH, R	9007140337	50-10 Q
GAHM.J H	6007080275#		GILBERTS, O E	8007210509*	50-263 G	COLDEMITH, R	8007140337	50-10 Q
Gahk, J W	8007080425*	50-267 B	OILDERTS, D E	8007010260	50-282 Q	COLDSMITH, R	8007140337	50-10 0
Gahk, J W	8007010506*	50-267 B	OILBERTS, D E	8007010267	50-282 G	COLDSMITH, R	8007220548	50-10 D
Gahk, J W	8007080215*	50-267 B	OILBERTS, D E	8007010549	50-282 Q	COLDSMITH, R	8007280537	50-10 D
Gahk, J W	8007080304*	50-267 S	OILBERTS, D E	8007160707	50-282 Q	CONCALVES, A	8007030332	FOIA
Gahk, J W	8007080407*	50-267 R	OILBERTS, D E	8007140192*	50-282 Q	COODLING, W	8007020237*	50-320 H
Gam. J W Gam. J W Gam. J W Gam. J W Gajic. 2	8007100176* 8007230554* 8007230555* 8007230539* 8007160672*	50-267 8 50-267 8 50-267 8 50-267 8 50-304 8	OILBERT, R E OILBERTS, D E OILBERTS, D E OILBERTS, D E OILBERTS, D E	8007280730* 8007020162 8007210182 8007210132 8007310106	50-482	OCODMIN, C OCODMIN, C OCODMIN, C OCODMIN, C	8007310375 8007160681* 8007100370* 8007280199 8007310472	50-289 H 50-407 R 70-1151 50-344 Q 50-344 Q
GALAZEN, T GALLAGHER, J H GALLAGHER, J H GALLAGHER, E J GALLAGHER, E J	8007290703 8007230722* 8007020041* 8007110148* 8007090159*	50-484	OILBERTS.D E OILBERTS.D E OILBERTS.D E OILBERTS.D E OILBERTS.D E	9007250545 9007250077 9007280057 9007220090 9007220542	50~263 Q 50~282 Q 50~263 Q 50~282 Q 50~282 Q	ODDDWIN, C ODDDWIN, C, ODDDWIN, C ODDDWIN, C ODDDWIN, C,	8007250350 8007300294 8007150120* 8007250360 8007290889	50-344 0 50-344 0 50-344 0 50-344 0
			OILBERTS, D E OILBERTS, D E OILINGKY, V GILL, S A OILLELAND, J E	8007230211 8007290841 8007280725* 8007110014 8007300167	50-282 Q 50-263 Q COMMISSION 71-221 50-438 B	000DH1N, U 000DH1N, C 000DH1N, C 000DH1N, W 000DH1N, W	8007210077* 8007010334 8007140420 8007070340 8007090227	70-1151 50-344 F PR 50-344 P 50-344 P
				80071003B1* 8007100410* 8007010125* 8007070005* 8007140073*	70-1151 70-1201 70-143 70-2478 70-143	OCCOPHIN'C CCCOPHIN'C CCCCPHIN'C CCCCPHIN'C	8007090300 8007090329 8007070300 9007070307* 9007090360	50-344 F 50-344 Q 50-344 P 50-344 P 50-344 P
				8007150107* 8007140527* 8007030278* 8007180401 8007280175	50-261 Q 70-143 70-143 40-8584 40-8681	ODDOMIN, C ODDOMIN, C ODDOMIN, C ODDOMIN, C	8007160608 8007170424 8007250474 8007300387 8007160511	50-344 P 50-344 P 50-344 P 50-344 P 50-377 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
Cordon, C	8007310231	NUREG	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8007010258	50-352 Q	GRIER.B H	8007140287	50-387 G
Cossick, L V	8007170620	70-143		8007010262	50-387 Q	GRIER.B H	8007280576	50-471 G
Cossmann, S R	8007290174	RES		8007010265	50-443 Q	ORIER.B H	8007280581	50-412 G
Cossmann, S R	8007280164	RES		8007010268	50-485 Q	GRIER.B H	8007280587	50-363 G
Cossmann, S R	8007290201	RES		8007010271	50-354 Q	GRIER.B H	8007280594	50-322 G
GRABOWSKI,A M	8007140001	50-367 G	GRIER, B H GRIER, B H GRIER, B H GRIER, B H ORIER, B H	6007010275	50-213 Q	GRIER.B H	8007280600	50-423 Q
GRACE,R H	8007070275	50-309 P		8007010277	50-293 Q	GRIER.D H	8007280603	50-410 Q
GRAESSER,K L	8007140327	50-275 R		8007010279	50-317 Q	GRIER.B H	8007280608	50-352 Q
GRAESSER,K L	8007160655	50-275 8		8007010280	50-322 Q	GRIER.B H	8007280612	50-387 Q
ORAESSER,K L	8007220449	50-275 8		8007010283	50-363 Q	GRIER.B H	8007280614	50-354 Q
ORAESSER, X L	6007220587	50-304 B	GRIER, B H	8007010286	50-27I	GRIER.B H	8007280615	\$0-443 0
ORAMBAU, O	8007110165	State Prog	GRIER, B H	8007010288		GRIER.B H	8007280619	50-485 Q
ORANLUND, R W	8007100434	REG00	GRIER, B H	8007010294		GRIER.B H	8007170581	50-277 P
ORAVES, R H	8007080077	50-213 B	GRIER, B H	8007010296		GRIER.B H	8007180530	50-29 P
ORAVES, R H	8007140359	50-213 S	GRIER, B H	8007010300		GRIER.B H	8007280401	50-293 Q
GRAVES, R H GRAVES, R H GRAVES, R H GRAYES, R H GRAY, F 8	8007070321 8007180370 8007230411 8007250535 8007020368	50-213 8 50-213 R 50-213 Q 50-213 8 PR	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8007010302 8007010303 8007010310 8007010312 8007010314	50~333	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007020612 8007020614 8007020617 8007020622 8007020625	70-364 50-317 g 70-371 70-820 70-33
ORAY, F S	8007020424	PR	ORIER.B H ORIER.B H ORIER.B H GRIER.B H ORIER.B H	8007010315	50-320 0	ORIER, B H	8007020481	70-1143
ORAY, F S	8007030082	PR		8007010316	50-309 0	GRIER, B H	8007020483	50-272 0
ORAY, J R	8007100029	50-344 G		8007010318	50-219 0	GRIER, B H	8007020484	50-220 0
ORAY, J R	8007140023	70-1308		8007010321	50-334 0	GRIER, B H	8007020487	50-266 0
ORAY, J R	8007170150	50-289 Q		8007010322	50-3 0	ORIER, B H	8007020491	50-293 0
GRAY,JR GRAY,JR GRAY,JR GRAY,JR GRAY,JR	8007170215 8007170220# 8007250428 8007250433# 8007250437#	70-1308 70-1308 50-344 0 50-344 0	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007020097 8007020010 8007030399 8007010545 8007210551	70-1100 50-219 F 50-219 F 50-219 Q 50-293 Q	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007020492 8007020496 8007020497 8007020700 8007020703	50-213 Q 50-334 Q 50-219 Q 50-245 Q 50-277 Q
GREEN, H J	8007160478+	50-327 P	GRIER, B H	8007210554	50-317 Q	ORIER.B H	8007020704	50-27I Q
GREENMAN, E O	8007230736+	50-277 Q	GRIER, B H	8007210555	50-3 Q	ORIER.B H	8007020706	50-29 Q
OREENMAN, E O	8007020070+	50-277 Q	GRIER, B H	8007210559	50-213 Q	ORIER.B H	8007020709	50-307 Q
OREENMAN, E	8007310234	NUREO	GRIER, B H	8007210561	50-334 Q	ORIER.B H	8007020710	50-3 Q
OREENMAN, E	8007180101+	50-293 Q	GRIER, B H	8007210563	50-412 Q	ORIER.B H	8007020713	50-244 Q
OREENMAN, E O	8007170692*	50-219 @	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8007210564	50-219 Q	ORIER.B H	8007020714	50-201 0
OREENMAN, E O	8007230137*	50-289 @		8007210568	50-363 Q	ORIER.B H	8007020715	50-320 0
OREENMAN, E O	8007020145	50-247 8		8007210571	50-322 Q	ORIER.B H	8007020717	50-333 0
OREEN, D	8007160556*	50-259 R		8007210572	50-320 Q	ORIER.B H	8007150128	70-344
OREEN, D	8007150425	50-445 M		8007210575	50-309 Q	ORIER.B.H	8007020463	50-317 0
OREEN,D O	8007250441	50-445 N	GRIER.B H	8007210580	50-245 Q	GRIER.B H	8007020486	50-293 Q
OREER,R H	8007100099#	50-546 Q	ORIER.B H	8007210585	50-220 Q	GRIER.B H	8007020487	50-244 Q
OREER,R J	8007280457#	50-87 Q	ORIER.B H	8007210590	50-410 Q	GRIER.B H	8007020489	50-220 Q
OREOER,L R,	8007100089#	50-409 Q	ORIER.B H	8007210595	50-333 Q	GRIER.B H	8007020491	50-286 Q
OREOER,L R	8007240009#	50-155 G	ORIER.B H	8007210599	50-284 Q	GRIER.B H	8007020492	50-277 Q
OREGER, L R OREGORY, W S GRENIER, B L GRENIER, B OREH, P. C	8007140471*	50-346 Q	GRIER.B.H	8007210400	50-277 Q	GRIER, B H	8007020494	50-245 0
	8007210607	REB	GRIER.B.H	8007210404	50-352 Q	GRIER, B H	8007020496	50-213 0
	8007230652*	50-275 A	GRIER.B.H	8007210604	50-357 Q	GRIER, B H	8007020497	50-3 0
	8007160395*	50-275 A	GRIER.B.H	8007210610	50-272 Q	GRIER, B H	8007020498	50-334 0
	8007030104	PR	GRIER.B.H	8007210412	50-272 Q	GRIER, B H	8007020501	50-309 0
ORIDLEY, R L. GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007070249	QEN TEC 18	ORIER, D H	8007210613	50-443 0	ORIER, B H	8007020502	50-219 Q
	8007100009	50-320 Q	ORIER, B H	8007210615	50-485 0	ORIER, B H	8007020503	50-354 Q
	8007150141*	70-364	ORIER, B H	8007210619	50-244 0	ORIER, B H	8007020504	50-412 Q
	8007210224*	50-277 Q	ORIER, B H	8007210623	50-271 0	ORIER, B H	8007020507	50-363 Q
	8007090370	50-271 Q	ORIER, B H	8007210626	50-29 0	ORIER, B H	8007020508	50-485 Q
ORIER, B H	8007140431	50-354 Q	GRIER, B H	8007010399	90-219 F	ORIER, B H	9007020307	50-322 G
ORIER, B H	8007140433	50-271 Q	GRIER, B H	8007160337	50-317 Q		8007020311	50-410 G
ORIER, B H	8007140438	50-333 Q	GRIER, B H	8007160341	50-3 Q		8007020313	30-387 G
ORIER, B H	8007140440	50-293 Q	GRIER, B, H	8007160344	50-213 Q		8007020314	50-352 G
ORIER, B H	8007140445	50-219 Q	GRIER, B, H	8007160345	50-412 Q		8007020317	50-272 G
ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8007140452 8007140458 8007140459 8007140462 8007140466	50-245 Q 50-322 Q 50-410 Q 50-277 Q 50-387 Q	ORIER.B H ORIER.B H ORIER.B H ORIER.B, H, ORIER.B H	8007140344 8007140349 8007140352 8007140357 8007140358	50-363	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007020521 8007020524 8007020526 8007020528 8007020530	50-333 G 50-443 Q 50-320 Q 50-271 G 50-29 Q
ORIER, B H	8007140469	50-352 G	GRIER.B H	8007160362	50-272 Q	ORIER.B H	8007210120	50-289 G
GRIER, B H	8007140474	50-220 G	GRIER.B H	8007160363	50-443 Q	ORIER.B H	8007160683	50-293 G
GRIER, B H	8007250325*	50-286 G	GRIER.B H	8007160364	50-244 Q	ORIER.B H	8007160685	50-317 G
GRIER, B H	8007020101	50-29 G	GRIER.B H	8007160367	50-485 Q	ORIER.B H	8007160688	50-3 G
GRIER, B H	8007020110	50-334 G	GRIER.B H	8007160370	50-29 Q	ORIER.B H	8007160670	50-213 G
ORIER, B H	8007020116	50-293 Q	GRIER.B.H	8007160398	50-334 Q	GRIER, B H	8007140493	50-412 G
ORIER, B H	8007020120	50-317 Q	GRIER.B H	8007160401	50-516 Q	GRIER, B H	8007140494	50-334 G
ORIER, B H	8007020124	50-3 Q	GRIER.B H	8007160777	50-27I P	ORIER, B H,	8007140499	50-219 G
ORIER, B H	8007020125	50-271 Q	GRIER.B H	8007220084	50-286 P	ORIER, B H	8007140701	50-363 G
ORIER, B H	8007020133	50-272 Q	GRIER.B H	8007140254	50-219 Q	GRIER, B H	8007140704	50-322 G
ORIER, B H	8007020134	50-244 G	ORIER, B H	8007140257	50-293 Q	ORIER, B H	8007140708	50-320 Q
GRIER, B H	8007020140	50-213 G		8007140260	50-245 Q	ORIER, B H	8007160711	50-309 Q
ORIER, B H	8007020143	50-277 G		8007140264	50-410 Q	ORIER, B H	8007160714	50-245 Q
ORIER, B H	8007020146	50-245 G		8007140267	50-277 Q	ORIER, B H	8007140717	50-410 Q
GRIER, B H	8007020147	50-333 Q		8007140269	50-333 Q	ORIER, B H	8007160720	50-220 Q
GRIER, B H	8007020154	50-286 G	ORIER.B H	9007140272	50-220 Q	ORIER, B H	8007160723	50-333 Q
GRIER, B H	8007020157	50-220 G	ORIER.B H	9007140275	50-271 Q	ORIER, B H,	8007160726	50-286 Q
GRIER, B H	8007020161	50-320 G	ORIER.B H	9007140276	50-322 Q	ORIER, B H	8007160728	50-352 Q
GRIER, B H	8007020163	50-309 G	ORIER.B H	9007140280	50-352 Q	ORIER, B H	8007160733	50-397 Q
GRIER, B H	8007020165	50-219 G	ORIER.B H	9007140284	50-354 Q	ORIER, B H	8007160736	50-272 Q

UT+10R	ACCESSION HUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEQURY
H 8. H 8. H 8.	6007160737 6007160740 8007160744 9007160747 8007160750	50-354 Q 50-443 Q 50-485 Q 50-244 Q 50-271 Q	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007230128 8007230129 8007230132 8007230146 8007230149	50-322	HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G HAIRSTON, W O	8007070199* 8007070208* 8007070208* 8007070214* 8007070217*	50-348 R 50-348 R 50-348 R 50-348 R 50-348 R
. B H . B H . B H . B H	8007160752 8007160780 8007160783 8007160788 8007160792	50-27 0 70-135 50-201 0 70-1143 50-77 0	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007230151 8007230156 8007230159 8007230163 8007230166	50-410 G 50-285 Q 50-352 G 50-277 G 50-387 Q	Hairston, W o Hairston, W o Hairston, W o Hairston, W o Hairston, W o	8007070219* 8007070223* 8007070226* 8007070228* 8007070230*	50-348 R 50-348 R 50-348 R 50-348 R
# 9. H 0. H 0. H 0.	8007160796 8007160803 8007160806 8007160809 8007160813	50~208 0 50~97 0 50~5 0 50~225 0 50~166 0	ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8007230170 8007230173 8007230178 8007230180 8007230183	50-354 Q 50-272 Q 50-443 Q 50-485 Q 50-244 Q	HAIRBIGN, W G HAIRBIDN, W G HAIRBIDN, W G HAIRBIDN, W G HAIRBIDN, W G	8007070232* 8007160861 8007010446* 8007010412* 8007150668*	50-348 R 50-348 S 50-348 S 50-348 R 50-348 R
H E. H E. H E. H E.)	8007160820 8007160822 8007160825 8007160827 8007160828	50-134 0 50-179 0 50-20 0 50-57 0 50-223 0	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007230186 8007230189 8007210289 8007230716 8007210197	50-271 Q 50-29 Q 70-687 50-277 Q 50-277 Q	HAIST,D P HAIST,D P HAIST,D.P HALE,C J HALE,C J	8007180018* 8007240326* 8007240314* 8007140088* 8007280088*	50-206 Q 50-206 Q 50-344 Q QA999 QA999
H 8 B B B B B B B B B B B B B B B B B B	8007 1 60829 8007 1 60831 8007 1 60832 8007 1 60833 8007 1 60836	\$0-184	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007210445 8007210451 8007250313 8007210071 8007210119	50-213 F 50-272 G 50-286 G 50-245 G 50-220 G	HALE, C J HALE, C J HALE, C J HALE, C J	8007140048* 8007140126* 8007140171* 8007290337* 8007290321*	QA999 QA999 QA999 QA999 QA999
6 B H 6 B H 8 H 8 H	8007160837 8007160840 8007160842 8007160845 8007160846	50-193 @ 70-1100 70-33 70-820 70-371	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8007240323 8007240356 8007240372 8007240422 8007240430	50-333 Q 50-219 Q 50-293 Q 50-271 Q 50-277 Q	HALEMAN.OR HALEY.J HAEL.RE HALL.RE HALL.RE	8007020464 8007100191* 8007110076* 8007110234* 8007140447*	PR PR 50-382 Q 50-445 Q 50-382 Q
H 8.7 H 8. H 8. H 8.1	8007160849 8007210126 8007210127 8007210133 8007210134	\$0-54 G \$0-77 G \$0-199 G \$0-20 G \$0-5 G	ORIFFIS, C A Griffin, W Grimes, C T Grimes, B K Grimes, B K	6007310225 8007110101 8007230026 8007220216 8007140115	NUREO PR 50-219 P MISC 50-277 H	HALL, R. E HALL, R. E HALL, R. E HALL, R. E HALL, R. E	8007240337* 8007280730* 8007140361 8007010372 8007010379	50-498 G 50-482 G 50-171 F 50-263 F 50-335 F
6 B H. 6 B H 6 B H 6 B H	8007210138 8007210140 8007210142 8007210143 8007210144	50-225	Grimes, B Grimes, B Grimes, B Grimes, B Grimes, B K	8007110517 8007110439 8007030013 8007170259 8007300297	50-277 H NUREO 50-596 H 50-3 H 50-338 E	HALL,R E HALL,R E HALL,R A HALLER,N [1	8007290562 8007150526 8007290634 8007310269* 8007140121	50~237 F TOPREP 50~409 F FOIA SECY
1,8 H 1,8 H 1,8 H 1,0 H	8007210147 8007210149 8007210151 8007210153 8007210155	50-54 0 50-184 Q 50-47 Q 50-209 Q 50-97 Q	GROCE, R. H GROCE, R. H GROCE, R. H GROCE, R. H GROCE, R. H	6007210367 8007210379 8007210456 6007030225 8007210601	50-309 R 50-29 R 50-271 R 50-309 P 50-309 Q	HALSTEAD,R J MALSTEAD,R J HAMILL,M L HAMMERSCHMIDT HAMPBON,D C	8007140538 8007110257 8007250396* 8007240406 8007090395	PR PR 50~397 A 50~320 H REGOD
R. B H G B H G B H R: B H R: D H	8007210159 8007210161 8007210164 8007210171 8007210172	50-201 0 50-173 0 50-273 0 50-317 0 50-3 0	GRONEMYER, E L ORDSSMAN, K ORDTENHUIS, M ORDVER, J L	8007298050* 8007140214 8007140518 8007300567 8007280404*	8tate Prog FOIA 50-250 F 50-250 P 50-206 8	Han, K Han, B y. Hangock, D Hangock, D	8007220142* 8007070034 8007170371* 8007030127 8007110019	QA999 XPORTLIC 50~556 Q PR PR
R, B H R, B H R, B H R, B H R, B H	8007210174 8007210178 8007210181 8007210192 8007210193	50-213	GRUBB.R L GUILDERT, J GULBRANSEN, E A GUMBLE.F W GUMBLE.F W	8007030015 8007110242 8007100357 8007010455* 8007080354*	RES FOIA PRM 50-284 5 50-284 8	Hancock, J a Hancock, J a Hancock, J a Hancock, D Hancock, D	8007150503* 8007010463 8007110402 8007160570 8007160570	50~302 Q 50~302 B 50~302 B 50~466 Q
R, B H R, B H R, B H R, B K	8007210199 8007210202 8007210204 8007210207 8007210210	50-322 Q 50-320 Q 50-309 Q 50-245 Q 50-410 Q	QUPPY.J.P QURUNATHAK, B QUBTAFBON.F A QUBTAVE.R P QUTH.R W	8007210003 8007220593* 8007010627* 8007020542 8007220538	RES 50-304 8 GGNTRACT CONTRACT 50-10 D	HANCOCK, D HANCOCK, D HANKLA, D J HANRAHAN, E J HANRAHAN, E J	8007140645 8007160645 8007210368 8007100032# 8007100038#	50-466
R. B H R. B H R. B H R. B H R. B H	8007210211 8007210218 8007210222 8007210223 8007210228	50-220 0 50-333 0 50-286 0 50-352 0 50-277 0	Haass, WP Haass, WP Haass, WP Haass, WP	8007230007* 8007110497 8006170126 8007020322 8007110578	50-244 G TOPREP 50-241 P TOPREP TOPREP	HANRAHAN,E J HANBEN,W A HANBELL,D HANBEN,L J HANBEN,L J	8007140182 8007140541* 8007070028 8007020561 8007070177	50-247 P 50-483 Q 50-514 D 71-9130 71-9130
R: B H R: B H R: B H R: B H	8007210271 8007210274 8007210278 8007210281 8007210284	50-387 Q 50-272 Q 50-354 Q 50-443 Q 50-485 Q	Haass, WP Haass, WP Haass, WP Haass, WP Hackett, DB,	6007170693 8007140342* 8007250060 8007210229 8007030208*	50-206 P 50-29 P REGOD TOPREP 50-285 P	HANBEN, L. E. HANBEN, L. E HANSEN, L. E HANSEN, L. E HANBEN, L. E	8007210125* 8007070004 8007070006* 8007070008* 8007240224	50-483 G XPORTLIC XPORTLIC XPORTLIC XPORTLIC
R, B H R, B H R, B H IR, B H	8007210286 8007210290 8007210291 8007210294 8007210312	50-244 0 50-271 0 50-29 0 50-170 0 50-352 0	HAFERA.T HAGA.PB HAGAN,TF HAGAN,TE HAGAN.TT	8007150625* 8007210375 8007020386 8007070127 8007100304	50-254 R 50-437 A CONTRACT CONTRACT CONTRACT	Hansen, L. E Hansen, W. A Hansen, L. E Hanson, W. W Harbison, D	8007240247* 8007300169* 8007160386 8007220307 8007160807	XPORTLIC 50-483 G 71-6581 40-297 50-327 B
18,8 H 18,0 H 18,8 H 18,8 H 8,8 H	8007250543 8007210017 8007230091 8007230076 8007230106	50-334 Q 50-286 8 50-293 Q 50-317 Q 50-3 Q	Hagan, T Hagen, H Hager, R Hager, R Hagey, H	8007180184 8007010103* 8007020550 8007280413 8007020007	CONTRACT 50-249 P 50-320 Q 50-320 G CONTRACT	HARMON, D W HARMON, D W HARMON, D. W, HARRAN, O HARRIS, J. R	8007310503* 8007240434 8007310018 8007160680* 8007150021*	FOIA XPORTLIC XPORTLIC 50-245 R 50-269 G
IR.B H IR.B H IR.B H IR.B H IR.B H	8007230107 8007230113 8007230113 8007230121 8007230122	50-213	HACEY, H HAIRSTON, W O HAIRSTON, W G HAIRSTON, W G HAIRSTON, W O	8007250569 8007070174* 8007070180* 8007070190* 8007070194*	CONTRACT 50-348 R 50-348 R 50-348 R 50-348 R	HARRISON, JJ HARRISON, HC HARRISON, HC HARRISON, JE HARRISON, JE	8007160479* 8007170297* 8007170329* 8007110012* 8007110010	50-546 @ 40-8602 40-8681 XPORTLIC XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCERSION NUMBER	SUBJECT
HARRIS, J R HARRISON, J J HARRISON, P HARRISON, P	8007290414* 8007230710* 8007300475 8007290600* 8007020316	50-546 Q PR	HELFRICH, O F HELFRICH, O F HELM, K HELTEMES, C J HELTEMES, C J	8007170255 8007290212 8007020383 8007020089 8007020248	XPORTLIC XPORTLIC XPORTLIC TOPREP SECY	HERLIHY, D HERLIHY, D HERLIHY, D HERMANN, R HERNANDEZ, G	8007280494 8007220070* 8007220063 8007010224 8007230639*	CATECORY 40~8728 40-8728 50-305 P 50-397 Q
HART, J HARTER, E S HARTIGAN, J P HARTIGAN, J P HARTIGAN, J P	8007080239* 8007010266 8007110397* 8007220378* 8007280602*	50-382 8 40-8438 50-346 8 50-346 8 50-346 8	HELWIO,R A HELWICK,C HEMBY,E O HEMMINGER,E O HEMMINGER,J M	8007070054* 8007070197 8007280487* 8007090362 8007180036	50-142 0	HERNANOEZ, O HERNANOEZ, O HERR, R K HERSCH, M M HERSKOUITZ, M B	8007170539* 8007210579* 8007150009* 8007070024* 8007150014	50-361 Q 50-528 Q 50-498 Q XPGRTL(C
MARTIOAN, J P HARTMAN, C J HARTMANN, A J HARTMAN, C J HARVEY, B L HARVEY, B L	8007280643* 8007230478 8007020644* 8007080346 8007170183*	50-344 8 50-155 F TOPREP 50-155 R 50-339 P	M C.SIRGNAH HENDRIS.J M HENDRICKSOM, T A HENDRIS M HENDRIS M	7909110639 7909240355 7909260557 8007160109* 8007010554	COMM18810N 50-320 U COMM18910N 0A999 COMM18810N	HESS.R J HESS.R J HESS.R J HEUBNER.A T HEWARD,R W	8007280495* 8007070125 8007280479 8007030113 8007030334	50-594 A XPORTLIC 50-594 A PR 50-320 T
HABHIHDTO, K HATFIELD, M D HATHAWAY, L R HAUGHNEY, C J HAUGHNEY, C J	8007170189* 8007140686 800702018B* 8007160415 8007020515	50-339 P REGOD COMMISSION PR 50-201 P	HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M HENNINO-BACHS, C	8007020672 8007070290 8007250007 8007250111 8007290251	COMMISSION TOPREP COMMISSION COMMISSION NURSO	HICKB'W W HICKEN'Y E HICKEN'Y E HEKEN'Y E	8007230084 8007180208# 8007170379* 8007020033 8007100348	40-8585 50-213 F 50-285 R 70-2909 PR
HAUGHNEY, C J HAUGHNEY, C J HAVERKAMP, D HAWKING, K L HAYDEN, L E	80070903B4 8007140193 80072B0069 8007280223 8007160644	50-201 P 50-201 P 50-201 P 50-289 B 50-352 H	HENRY, C W HENSLEY, K D HENSLEY, K D HENSLEY, K D	8007290067# 8007100181 8007100052# 8007100069# 8007100023#	50-320 H REGOD 70-143 70-143 70-143	HIESTAND, OS HIGOINA, JC HILF, CL HILGER, W HILL, NM	8007170368 8007310504* 8007170574* 8007180063* 8007310055*	50-409 Q 50-247 Q 50-260 P 50-219 H 50-272 Q
HAYES, D W HAYES, D W HAYES, D W	8007210079 8007090179* 8007090159* 8007110479* 8007230412*	PT21 50-440	HENSLEY, K D HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J G	8007180555 8007110040* 8007110032* 8007010155 8007020535	70-143 50-320 J 50-320 J 50-289 Q 50-287 Q	HILL,T M HILL,O E HILLMAN,R E HIMEDAUCH,N HIND,J A	8007280194 8007220503# B007150712# 8007080348# 8007020211#	WASTE MOT TOPREP 50-217 R 50-155 R 50-295 Q
HAYES, D W. HAYES, D W. HAYHURST, R S HAYNES, J Q HAZELRIOO, S	8007300143* 8007300136* 800731046* 8007290706 8007010500*	50~454 Q 50~331 Q 50~320 Q 50~206 P 50~275 8	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERDEIN, J O	9007010326 8007010398 8007070266 8007070248 8007070281	50-287 P 50-287 F 50-289 Q 50-287 S 50-287 P	A L. GNIH A L. GNIH A L. GNIH A L. GNIH A L. GNIH	8007020199 8007010578* 8007010573 8007110518* 8007110513	50-275 Q 70-1308 70-1308 70-925 70-925
HAZLE, A J HEALY, J W HEALY, J W HECTOR, A G HEDDINOB, T P	8007010274* 8007180603 8007100053 8007110019 8007180528	WASTE MOT ACRS REGOD PR WASTE MOT	HERBEIN, J Q	B007070274 B007070302 B007070343 B007080074 B0070B0244	50-320 P 50-287 S 50-287 P 50-289 P 50-287 F	HIND, J A	8007140094 8007140430 8007140402* 8007150096* 8007240107*	50-282 Q 50-155 Q 70-1193 70-2609 50-263 Q
HEDEMAN, W N HEDEMAN, W N HEDEMAN, W N HEDEMAN, W N HEOARTY, W	8007110026 8007020400 8007280037 8007290696 8007240462	PR PR PR 50~10 D FOIA	O LINIBERSH O LINIBERSH O LINIBERSH O LINIBERSH O LINIBERSH	8007080358 8007110446 8007140385 8007140419 8007080211	50-320 P 50-287 Q 50-320 H 50-320 P 50-289 8	A L'AUNH A L'AUNH A L'AUNH A L'AUNH A L'AUNH A L'AUNH	8007140675 8007150092 8007240104 8007240024 8007310261	70-1193 70-2609 50-263 Q 50-346 Q 50-305 Q
HEGNER, J. D HEIDER, L. H HEIDER, L. H HEIDER, L. H HEIDER, L. H	8007230174* 8007150143 8007110460 8007210579 8007230173	50-334 Q PR 50-271 Q 50-271 Q 50-271 Q	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8007080375 8007150721 8007140346 8007140365 8007140381	50-289 Q 50-287 Q 50-287 P 50-289 P 50-289 Q	AIND.J A HIND.J A HIND.J A HINBS.E HINBS.E	8007310267* 8007270869 8007270875* 8007140481* 8007140428	50-305 Q 50-254 Q 50-254 Q 50-341 Q
Heider, L. H. Heider, L. H. Heider, C. H. Heim, O. E. Heihemann, J. M.	8007250188 8007250278 8007140338 8007280236* 8007100218	50-271 G 50-29 G 50-29 P CONTRACT 50-10 D	Herbein, J Q Herbein, J Q Herbein, J Q Herbein, J Q Herbein, J Q	8007180414 8007150587 8007160524 8007160618 8007160667	50-289 P 50-289 P 50-289 S 50-289 S 50-320 F	HIRATA,Y HIRATA,Y HO,F P HOADLEY,S D HOADLEY,S D	8007290487* 8007290477* 8007240409 8007160394 8007160399*	QA999 QA999 NUREQ XPORTLIC XPORTLIC
HEINEKE, J.M. HEINEKE, J.M. HEIBHMAN, R.F. HEIBHMAN, R.F. HEIBHMAN, R.F.	8007220024 8007220034 8007220112* 8007220095 8007100283	NUREO NUREO 50-315 Q 50-315 Q 50-331 Q	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8007220498 8007220553 8007250356 8007180404 8007210372	71-9081 50-320 F 50-289 Q 50-320 J 50-289 P	HOAGLAND, X E HODGES, J W HODGES, J W HODGES, J N	8007310019 8007010298 8007140527# 8007030298* 8007290393#	50-219 P 50-445 M 70-143 70-143
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F,	8007070051 8007010178 8007140485 8007140548 8007140487	50-282 Q 50-255 Q 50-155 Q 50-346 Q 50-263 Q	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O	8007220584 8007210398 8007250504 8007220471 8007220592	50-320 J 50-287 Q 50-287 Q 50-289 F 50-289 Q	Hodoes, J W Hodson, W L Hoefling, R K Hoffman, D P Hoffman, D P	8007160727* 8007070112 8007100241 8007210427	50-364 Q 70-1113 FR 50-266 Q 50-255 R PR
HEIBHMAN, R F HEIBHMAN, R F HEIBHMAN, R F, HEIBHMAN, R F,	8007110049* 8007110044 8007210322 8007240012 8007240185	50-263 Q 50-346 Q 50-301 Q 50-282 Q	HERBEIN, J O HERBOLGHENIER	8007220492 8007250401 8007270617 8007270799 8007270621	50-287 G 50-287 G 50-289 G 50-289 R 50-10 D	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007100072 8007010200 8007150134 8007010313	PR 50-155 P PR 50-155 Q 50-155 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F	8007240236 8007230296 8007230314 8007230371 8007300307	50-358 Q 50-331 G 50-305 Q 50-10 Q 50-263 Q	HERD, R HERDT, A R HERDT, A R HERDT, A, R HERDT, A R	8007170129* 8007160872* 8007070107* 8007100131* 8007100060*	CONTRACT 50-414 0 50-335 0 50-327 0 50-251 0	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P HOFFMAN, D P	8007010473 8007240136 8007070210 8007030250	50-155 F PR 50-155 P 50-255 P 50-155 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R, F HEISHMAN, R, F HEISHMAN, R F,	8007140186 8007300601 8007150102 8007230275 8007240307	50-282 Q 50-346 Q 50-358 Q 50-373 Q 50-346 Q	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A R	8007160742# 8007100313# 8007270380# 8007270432# 8007310245#	50-338 Q 50-400 Q 50-338 Q 50-366 Q 50-416 Q	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007080189 8007080338 8007310177 8007110204	50-255 B 50-255 P 50-255 Q 50-155 P 50-255 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R, F HEISHMAN, R F HEISHMAN, R F	8007210297 8007240396 8007310530 8007310534 8007310278	50-358 Q 50-305 G 50-373 Q 50-315 Q	HERDT, A R HEREFORD, J M HEREFORD, J M HERLIHY, D HERLIHY, D	8007310501* 8007010502* 8007210475* 8007010129 8007010140*	50-270 0 50-327 S 50-327 S 40-8728 40-8728	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P	8007140350 8007140391 8007140310 8007140424	50-255 Q 50-155 F 50-255 Q 50-155 Q 50-155 Q

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESS I ON	CATEG		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
OFFMAN, D P OFFMAN, D P FFMAN, D P OFFMAN, D P	8007150803 8007160458 8007160505 8007180424 8007210394	50~255 50~155 50~255 50~255 50~255	0 0 P Q R	HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O K	8007150507 8007150513 8007150515 9007160431 8007170442	50-320 50-320 50-320 50-320 50-320	F & & & & & & & & & & & & & & & & & & &	HURRAN. G HURSH. G HURST. J B HUSEBY. D E HUSTON. R W	9007180413* 9007300370 9007250174* 9007280676* 9007070008	50-245 R 50-312 H 50-320 H 50-317 S 50-255 P
OFFMAN, D P OFFMAN, D P OFFMAN, D P OFFMAN, D P OFFMAN, D P	8007220452 8007220472 8007220478 8007220513 8007230460	50-155 50-155 50-255 50-255 50-255	0 3 0	HOVEY: Q K HOVEY: Q K HOVEY: Q K HOVEY: G K	8007170395 8007210359 8007210383 8007220442 8007310406	50-320 50-320 5 <i>0-32</i> 0 50-320 50-320	P P P	HUSTON,R W HUTTON,J R KUTTON,P H HYLAND,F B ICE,R D	8007070314 8007030084 8007220058 8007160188* 8007030066	90-255 8 PR REB GA999 FDIA
DEFMAN, D P IDEFMAN, D P IDEFMAN, D P IDEFMAN, D P IDEFMAN, D P	6007230469 8007220341 8007230395 8007230516 8007240017	50-155 50-155 50-255 50-155 50-158	0 F 0 0	HOVEY, G K HOVEY, G K HOVEY, G K HOVEY, G X	8007230434 8007230439 8007290811 8007300447 8007150152	50-920 50-920 50-920 90-920 PR	85 BB BB	ihriq.r Ingram.f L Ingram.f L Inguge.8 Iorii.j A	8007150475 8007010063 8007280129 8007220234* 8007100256*	50-484 0 50-275 H 50-320 H 50-305 P TOPREP
NOFEMAN, D P NOFEMAN, D P NOFEMAN, D P NOFEMAN, D P	8007250173 8007280597 8007310422 8007280570 8007290606	50-155 50-155 50-155 50-155 50-155	0 7 0	HOWARD, JE HOWE, P W HOWE, P W HOWELL, J C	8007210373 8007100422* 8007100418* 8007100297 8007150107*	50-400 50-400	0 0 0	IPPOLITO, T A	8007070207 8007010208 8007140480 8007140484* 8007140492*	50-331 F 50-293 F 50-298 P 50-298 P 50-298 P
HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007290614 8007290630 8007300439 8007280533 8007290691	50-255 50-255 50-155 50-155 50-155	8 G F P Q	HOWELL, J C HOWELL, J C HOWINGTON, L C HOWLETT, G H HOWSON, T G	8007090170* 8007140555* 8007290145 8007210375* 8007150730	50-297 NUREQ	0 0 R 1	IPPOLITO, T A	B007140900 B007140909* B007140514* B007210024 B007140605	50-254 P 50-254 P 50-254 P 50-259 F 50-325 P
-ECAN, J P -HOHNE, F. C -HOLDEN, R H -HOLDEN, R H -HOLDEN, R B	8007100045 8007280200 8007020582 8007250710 8007310139	PR 40-8502 PR PR 50-332	G.	HOATE'A C HOATE'A C HOATE'A C HOATE'A C	8007310535* 6007020215 8007230030 8007230120 8007230012	50-155 ACRS ACRS ACRS ACRS	H	1PPOLITO,T A IPPOLITO,T A IPPOLITO,T A 1PPOLITO,T A IPPOLITO,T A	8007140614* 8007140624* 8007210049 8007220028 8007180515	50-325 P 50-325 P 50-271 F 50-257 F 50-263 P
OLLAND, P OLLINOSWORTH OLODY, D OLODY, D HOLOMAY, C F	8007220583* 8007170380 8007020012* 8007180082* 8007180352	50-249 50-259 70-135 70-371 RES	В	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8007070414 8007230013 8007230112 8007230023 8007230024	CONTRACT 50~327 ACRS ACRS ACRS	T 0	IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8007230713 8007280229 8007280249* 8007240255 8007240225	50-298 F 50-333 P 50-333 P 50-298 P 50-299 P
HOLOHAY, C F HOLOHAY, C F HOLOHAY, C F HOLOHAY, C F HOLTER, O N	6007140031 8007140634 8007300041 8007310251 8007240283	RES NUREO RES NUREO		HOAFE'N C HOAFE'N C HOAFE'N C HOAFE'N C	8007230729 8007210050 8007090215 6007110002 8007170527	ACRS ACRS 50-3 50-275 100FR	0	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	B007240231* B007240234* B007240427 B007240433* B007280073	50-259 P 50-259 P 50-325 P 50-325 P 50-220 0
HOLYDAK.R H HOLYDAK.R H HOLZWEIO.S F HONBERGER.R F	8007250448 8007290698 8007080360* 8007100086 8007020167*	50-373 50-373 PR PR 50-329	A A	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, A HOYLE, J C	8007110330 8007110339 8007170554 8007300577 8007140363	50-358 50-260 10CFR CGNTRACT 50-3	6	IPPOLITO,T,A IPPOLITO,T A IPPOLITO,T A IRVINE,R J IBLEY,T	9007310218 9007310222* 9007310229* 9007280294 9007010439*	50-331 P 50-331 P 50-331 P F01A 50-346 8
HOOD, D & HOOD,	8007090393 8007140496 8007240040 8007300104 8007300261	50-329 50-329 50-329	F A A A	HOYLE, J C HOYLE, J C HUBBARD, J H HUBBARD, J M HUBER, J E	8007140497 8007310324 8007210486* 8007230189* 6007280116*	50~443 ACR8 50~413 50~413 50~320	Q A A H	IGLEY, T IBLEY, T IGLEY, T IGRAEL, S. L. IGRAEL, S. L.	8007170450* 8007220465* 8007280578* 8006240237 8007010110	50~346 8 50~346 8 50~346 8 50~269 P 50~3 P
HOBD, D S HOPKINS, J B HORIN, W A HORIN, W A	8007290036 8007110049* 8007240018* 8007030246 8007030246	50-263 50-301 50-445	A G G G	HUDSON, O HUDSON, E D HUDSON, T B HUDSON, T B HUDSON, T B	8007230223 80072\$0263* 8007160553 8007300070 8007300070	RES 50-220 50-478 50-478 50-478	0 0 0	ibrael.8 L Imanicki.R Imanicki.R E Jadlon.R A Jadlon.R A	8007170598 800718005/ 8007290890 8007090051 8007090051	50-247 P 40-9697 40-9697 50-389 M 50-389 K
HORIN, H A HORIN, H A HORIN, H A HORIN, H A HORN, A J	8007180437 8007180437 8007310328 8007310328 8007240223*	50-445 50-445 50-445	9	HURES, D HURNICUTT, D M HURNICUTT, D M HURNICUTT, D M	6907030389 8907090179* 8907310195* 8907290504* 8007010171*	70-33 50-440 Gayyy Gayyy Gayyy	q	JACKIW, I N JACKEON, P O JACOBE, A JACOBE, A	8007220112* 8007140958* 8007150080 8007010624 8007020024	50-315 Q 50-346 Q FR CONTRACT CONTRACT
HORN, A J HOBBLER, D, E HOBBLER, D E HOBBLER, D E HOBBLER, D E	8007390343* 8007080007 8007020654 8007070337 8007070353*	50-206 (50-320 (50-320 (50-320 (50-320 (9	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	8007300198* 8007250109* 8007160157* 8007160146* 8007160207*	0A999 0A999 0A999 0A999 0A999		JACOBB, A JACOBB, A JACOBBON, R D JACOBB, B D JAMEB, H. E	8007010613 8007300595 8007100195* 8007300064 8007140380*	CONTRACT CONTRACT 50~263 B PR 40~299
HOSSLER.D E HOSSLER.D E HOUGHTON.T C HOUGHTON.T C HOUGHTON.T C	8007070365* 8007070371* 8007010087 8007010100 8007070050	50-320 6 50-320 6 50-416 6 50-375 F		HUNNICUTT.D M HUNNICUTT.D M HUNNICUTT.D M HUNNICUTT.D M HUNNICUTT.D	8007250187* 8007250594* 8007210539* 8007220208* 8007140421	94999 94949 94949 94949 94949	g	Janecek.r f Janecek.r f Janecek.r f Janecek.r f Janecek.r f	8007020756 8007010170 8007070116 8007080063 8007230678*	50-249 0 50-237 P 50-10 P 50-10 P 50-10 0
HOUSTON, T C HOUSTON, K D HOVEY, O K HOVEY, O K	8007020066 8007240287 8007010079* 8007020534 8007010454	50-375 A 50-414 A 50-309 F 50-320 P		HUNRICUTT, D M HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A	6007270331 8007010529* 8007160562* 8007210380* 8007210444*	50-306 50-282 50-306	8 8 8 8	Janecek, R F Janecek, R F Janecek, R F Janecek, R, F, Janecek, R F	8007100142 8007160430 8007210212 8007310353 8007300485	50-254 P 50-237 Q 50-237 P 50-254 Q 50-237 Q
HONEA' O K HONEA' O K HONEA' O' K HONEA' O' K	8007010460 8007160522 8007070320 8007110422 8007140352	50-320 P 50-320 E 50-320 P 50-320 P 50-320 P		HUNSTAD, A A HUNT, M D HUNTER, D R HUNTER, V H HUNTER, V H	8007290677* 8007250607* 8007210307* 8007100339* 8007220155*	50-369	0 0 8	Janecek, R F Janecek, R F Janecek, R F Janinek, M Janinek, M,	8007280598 8007280567 8007310432 8007010159	50-10 D NUREG 50-10 Q State Prog State Prog
HOVEY, O. K. HOVEY, O. K. HOVEY, O. K. HOVEY, O. K.	8007170373 8007180376 8007150499 8007160596 8007170338	50-320 P 50-320 P 50-320 P 50-320 B 50-320 P		HUNTER, R 8 HUNTER, R 8 HUNTER, R 5 HUPPERT, W W, HUPPERT, W W	8007180324 8007300252 8007250473 8007010151# 8007010142#	50-315	Q Q P	Jantnek, M, Jahorski, R L Jelinek, J A Jenkins, R, V Jenkins, G R,	8007270060 8007020312 8007220082* 8007220371*	State Prog PR 40-8771 50-304 8 50-321 0

- M' h

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JENKINS. O R JENKINS. O R JENKINS. O R JENNINOS. J	8007210093* 8007240376* 8007290404* 8007290853* 8007240147	70-1151 50-348 Q 50-370 Q 50-328 Q FR	JORDAN. W S JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8007100037* 8007100042* 8007100033 8007100037* 8007100042*	50-155 G 50-155 O 50-155 O 50-155 G 50-155 G	KAYANAUGH, P 11 KAY, J A KAY, J A KAY, J A KAY, J A	8007140616 8007080310 8007080079 8007140300 8007280621	50-382 K 50-29 F 50-29 P 50-29 P 50-29 P
JERNIGAN, E P JETT, Q JETT, O JEWELL, W A JOHN, D F	8007300328* 8007070025* 8007140079* 8007240134* 8007170388	50-217 G SECY 100FR 50-285 S 50-445 M	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	B0070B0005# B0070B0005# B00711004B B00711004B	SO-289 C 50-289 G 50-269 C PR PR	KAY,J A KAY,J A KEARNEY,J J KEARNEY,J J	8007280584 8007280626 8007280492 8007020671 8007110011	50-29 P 50-29 P 50-29 F PR 50-320 J
JOHN, D F JOHNSON, M T JOHNSON, C JOHNSON, J	8007170388 8007170388 8007030012 8007030095 8007250332*	50-445 M 50-445 M PR PR 50-286 Q	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORGENSEN, B L	8007220529 8007220530* 8007220529 8007220530* 8007010373*	50-287	KEARNEY, J KEE, E J KEENAN, R P KEENAN, R P KEENAN, R P	8007210168 8007210017 8007070023 8007100263 8007100271*	PR RES XPORTLIC XPORTLIC XPORTLIC
JOHNSON, R E JOHNSON, M JOHNSON, D F JOHNSON, A H	8007210430* 8007280262* 8007030367 8007210165* 8007100061*	OEN TEC 19 50-293 G 71-9027 50-244 G 50-335 G	JOUKOFF,P JDY,D JDY,D R JOY,D R JOY,D R	8007110184* 8007100072* 8007100057* 8007100020* 8003250864	50-206 G 70-143 70-143 70-143 70-143	KEENAN, R P KEENAN, R P KEENAN, R P KEENAN, R P	8007110021 8007170202 8007180449 8007180455* 8007310069	XPORTLIC FOIA XPORTLIC XPORTLIC XPORTLIC
ЈОНИВОМ, И D ЈОНИВОМ, А ЈОНИВОМ, А ЈОНИВОМ, А В	8007220197* 8007210139 8006170304 8007210107* 8007100378	50-313 Q ACRS MISC 50-224 G PRM	JOY.D R JOY.J H JOYAER, J H JOYAER, J H JOYAER, J H	8007220251* 8007150605* 8007020012* 8007140648* 8007180082*	70-143 50-206 R 70-135 70-135 70-371	KEENAN,R P KEENEY,W P KEENEY,W P KEENEY,W P	8007310073* 8007220184 8007090145 8007300573 8007100363	XPORTLIC 71-9132 PR PR NUREO
от иовиного и рабиности и с Понивами и с Понивами и и Понивами и и	8007210423 8007100051 8007070275 8007180256 8007210601	QEN TEC 19 50-344 Q 50-320 Q 50-395 Q 50-309 Q	JOYNER, J H JOYNER, J H JULIAN, C	8007280746* 8007170630* 8007230124* 8007250494* 8007240256	70-1100 70-135 70-371 70-820 50-276 \$	KEHDE, D V KEIMIG, R R KEIMIG, R R KEIMIG, R R KEIMIG, R R	8007230221* 8004240221 8005230131 8007020535 8007310365*	50-273 0 50-217 5 50-245 8 50-213 8 50-245 0
10HKBON: R W 10HKBON: C R 10HKBON: R E 10HKBON: W P	8007100039 8007300295* 8007180469 8007250524 8007250404	50-344 0 50-344 0 71-4478 PR 50-307 P	JULIAN.C JUNCE, H R JURY, M J JUBTUS, P E KAHLE, J B	8007240260 8007020359 8007220566 8007300047 8007150049*	50-276 S WASTE MGT 50-155 F 50-344 P 70-1113	KEIMIO.R R KEIMIO.R R KELLER.J H KELLEY.W D	8007310055* 8007230171 8007250197 8007290217 8007010051*	50-272 Q 50-213 B 50-217 B 50-254 P QA999
JOHNSTON, M P JOHNSTON, M P JOHNSON, R W JOHNSON, R W JOHNSON, R W JOHNSON, R P	8007230508 8007230508 8007270331 8007310433 8007300096	S0-275 G 50-275 G 50-313 B 50-344 B 50-275 G	KAHLE, J B KAHLE, J B KAHLE, R KALLYIANAKIS, N	8007020220* 8007010301* 8007280225* 8007160504* 8007080162	70-1151 70-824 70-27 CONTRACT 50-265 8	KELLEY.D L KELLDOO,P J KELLY.A KELLY.A	8007150171* 8007100124* 8007230362 8007100134 8007100225*	50-285 Q 50-416 Q 50-28D 8 PRM 50-267 Q
1 ОРБВР С С ПОВВР С С ПОВИНОГ ПОВИНОГОР СТВИНОГОР СТВИН	8007240478 8007090166* 8007090167* 8007020287* 8007020292*	NUREO NUREO Mureo Foia Foia	KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALWARF, D R	8007150619 8007280470 8007240112 8007240105 8007030350	50-254 R 50-265 P 50-265 S 50-264 S NUREO	KELLY,A F KELLY,A F KELLY,A F KELLY,J KELLY,J E	8007100223 8007070141* 8007070157 8007210162 8007140417*	50-247 0 50-284 0 50-284 0 50-445 S PR
JONEB, O C JONEB, K A JONEB, R K JONEB, O C JONEB, N C	8005130445 8007070113 8007220081* 8007310234 8007020257	RES PR Haste mot Nureo 50-285 g	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8005160107 8005200282 8005160225 8005200317 8005200324	50-320 H 50-289 H 50-320 H 50-320 H 50-289 H	KEULY, A REMPER, J REMPER, J REMPER, J REMPER J REMPER J REMPER J	8007210442 8007210321* 8007210214* 8007240226 8007250152	H18C 50-352 0 50-352 5 50-352 8
JONEB, H C JONEB, H C JONEB, H C JONEB, C E	8007110094# 8007020075 8007210187 8007020430 8007150118*	50-285 Q 50-285 Q 50-285 Q 50-285 Q 50-454 Q	Kammerer, C Kammerer, C Kammerer, C Kammerer, C Kammerer, C	8005200345 8005160124 8005200357 8005200366 8005200454	50-287 H 50-320 H 50-320 H M150 50-320 H	KEMPER.J S KEMPER.J S KEMPER.J S KEMPER.J S	8007310286* 8007090265 8007210567 8007180446* 8007280388*	50-352 8 50-352 8 50-352 0 50-277 P 50-278 P
JONES, H C JONES, H C JONESON, B J JONES, Y I	8007020419 8007030001 8007180122* 8007080056 8007140026	50-285 Q PR 50-285 Q 40-215 50-275 Q	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006120212 8006120428 8006120437 8006120484 8007100438*	50-320 H 50-287 H 50-320 H 50-320 H 50-320 H	KEMPINERS,W L KENDRICK:H KENNA,W B KENNA:W B KENNA:W B	8007140521* 8007220030* 8007100374* 8007100404* 8007010117*	CGNTRACT 50-566 H 70-1151 70-1201 70-143
JONES, D E JONES, H C, JONES, H C JONES, H C	8007150072 8007140084* 8007010471 8007300078 8007010352	PR 70-143 50-285 P 50-285 P 50-400 F	KAMMERER. C KAMMERER. C KAMMERER. C. KAMMERER. C KAMMERER. C	8006120419 8006120501 8006120402 8007110399 8007250190	20-320 H COMW1881GN H18C 20-320 H	KENNA, U B KENNA, W B KENNA, W B KENNA, W B	8007100362 8007100390 8007020213 8007070003 8007140067*	70-1151 70-1201 70-1151 70-2478 70-143
JONES, J A JONES, J A JONES, J L JONES, J L JONES, J C	8007170346 8007170428 8007170452 8007170452 8007270830* 8007080364	50-400 K 50-400 A 50-400 C 50-270 B 50-285 P	KANAK,K K KANAK,K K KANE,U F KANKLIN,J E KANN,O A	8007020356 8007140044 8007140227 8007300143* 8007280400*	RES RES 50-395 A 50-454 G 50-339 P	KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8007150101* 8007140513 8007010301* 8007010295* 8007030295*	50-241 0 70-143 70-824 70-824 70-143
Jones, Y Jones, H. C Jones, H. C Jones, H. C Jones, B. W	8007070123 8007170374 8007230530 8007230558 8007100244	50-275 0 50-285 R 50-285 F 50-285 Q 50-599 Q	KAPLAN,A L KAPLAN,A L KAPLAN,A L KAPLAN,A L KAPLAN,A L	8007150033* 8007030231* 8007150031* 8007080212 8007280077	70-1113 70-1113 70-1113 70-1113 71-4986	KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8007280220 8007010108 8007150027 8007110102 8007100093	70-27 70-143 70-1113 50-335 0 50-261 0
JONES, R K JONES, W C. JONES, Y I JONES, B. W	8007310497 8007280530 8007280401 8007310444 8007220110	HASTE MOT 50-285 P 50-285 Q 50-275 Q 50-579 Q	KASCSAK,R M KASSEBAUM,N L KATZ,L KAUFMANN,R S KAUFMAN,N C	8007270689 8007110571* 8007270368* 8007140076 8007230177	NUREO 30-482 U 04799 Misc Res	KENNA, U B KENNA, W B KENNA, W B KENNA, W B	8007270385 8007070165 8007140078 8007150087 8007140058	50-364 0 50-369 0 70-143 50-261 0 70-143
JONES, B W JONES, D W JONESON, A JORDAN, A O, JORDAN, W B	8007230612 8007280286 8007110248* 8007100104 8007240050*	50-155 C 50-538 F TOPREP PR COMMISBION	Kaufmann.r s Kaufmann.r s Kaufman.n,c Kaufmann.r s Kaufmann.r s	8007100452 8007140607* 8007280171 8007210067 8007230667	40-8502 40-8502 RES 40-8/68 40-8/28	KENNA, U B KENNA, U B KENNA, U B KENNA, U B	8007140542 8007160716 9007160838 8007160745 8007180308	50-297 Q 70-1113 70-143 50-338 Q 70-143

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY
INREDY, R T NAMEDY, E II NAMEDY, E M NAMEDY, R T ENNEDY, R T	8007020168 8007020323* 8007110093* 8007180501 8007300069	COMMISSION 50-320 U 50-271 H COMMISSION COMMISSION	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	6007220215 6007220218 8007220222 8007220226 6007220228	50-546 Q 50-346 Q 50-483 Q 50-266 Q 50-305 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J, O	8007170409 8007170413 8007170617 8007170619 8007170623	70-8 40-3392 50-264 0 70-35 70-1489
ENNEDY, R T ENNEDY, R T ENNEDY, R T ENNEDY, R T ENNEDY, R T	8007180164 8007180216 8007180550 8007180488 8007180027	COMMISSION COMMISSION COMMISSION COMMISSION COMMISSION	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007020310 8007160158 8007160165 8007160173 8007160178	50-344 0 50-315 0 50-295 0 50-255 0 50-329 0	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007170626 8007170629 8007170633 8007170636 8007170638	50-87 Q 50-114 Q 50-294 Q 50-150 Q 50-152 Q
ENNETH B F ENNEDY R T CNNEDY R T ENRICK, J R ENRICK, J R	6007070128 8007110278 8007180494 6007220560 8007220560	71-392 COMMISSION COMMISSION XPORTLIC XPORTLIC	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007160182 8007160187 8007160191 8007160193 8007160200	50-282 Q 50-546 Q 50-346 Q 50-266 Q 50-483 Q	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007170641 8007170644 8007170646 8007170653 8007170657	50-182 Q 50-151 Q 50-123 Q 50-186 Q 50-2 Q
ENRICK, J R ENRICK, J R ENYON, T EPFORD, C EPPLEN, J O	8007290485 8007250485 8007300052 8007080084 8007140495	XPORTLIC XPORTLIC 50-327 E 50-320 0 80-461 Q	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007160203 8007140309 8007140314 8007140317 8007140319	50-305	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007170662 8007250006 8007140178 8007230287 8007230305	50-156
EPPLER, J O EPPLER, J O EPPLER, J O EPPLER, J G EPPLER, J O	8007140508 8007140510 8007140517 8007140523 8007140522	50-367 G 50-361 G 50-155 G 50-409 G 50-263 G	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007140321 8007140323 8007140325 8007140358 8007140360	50-263	KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O	8007230307 8007230310 8007230312 8007230320 8007230323	50-358 G 50-440 G 50-155 G 50-409 G 50-341 G
(EPPLER, J O LEPPLER, J O LEPPLER, J O LEPPLER, J O LEPPLER, J O	8007140535 8007140537 8007140545 8007140551 8007140554	50-331 Q 50-373 Q 50-10 Q 50-440 Q 50-358 Q	KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O,	8007140401 8007240004 8007280428 8007280431 8007280435	50-358	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007230329 8007230330 8007230332 8007230336 8007230338	50-331 G 50-461 G 50-367 G 50-263 G 50-546 G
(EPPLER, J O (EPPLER, J O (EPPLER, J O (EPPLER, J O (EPPLER, J O	9007140557 B00729004B B007070072 B007020029 B007020034	50-341 0 50-346 H 50-10 0 50-305 0 50-358 0	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007280438 8007280644 8007280653 8007280657 8007280707	50-461	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007230340 8007230343 8007230346 8007230356 8007230358	50-346 0 50-483 0 50-266 0 50-305 0 50-329 0
KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O	8007020037 8007020043 8007020031 8007020054 8007020056	50-266 Q 50-315 Q 50-155 Q 50-263 Q 50-346 Q	KEPPLER.JO KEPPLER.JO KEPPLER.JO KEPPLER.JO	8607280707 8007100436 8007030023 8007030026 8007030027	50-373 Q 50-483 Q 70-925 50-305 Q 50-331 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007300574 8007310507 8007180003 8007210034 8007180566	50-254 Q 50-295 Q 50-10 Q 50-266 P 50-263 Q
HEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007020038 8007020063 8007020063 8007210353 8007210356	50-409 Q 50-331 Q 50-10 Q 50-315 Q 50-295 Q	KERPLER.J O KEPPLER.J O KERPLER.J O KERPLER.J O	8007030030 8007030032 8007030034 8007030037 8007030042	50-266 0 50-409 0 50-159 0 50-10 0 50-315 0	KEPPLER.J O. KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007180575 E007180497 E007180509 E007210550 E007240245	50-155 0 50-331 0 50-10 0 40-2674 40-4337
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007210358 8007210360 8007210362 8007210363 8007210364	50-255 Q 50-329 Q 50-282 Q 50-346 Q 50-346 Q	Keppler. J O Keppler. J O Keppler. J O Keppler. J O Keppler. J. O	8007030043 8007030044 6007020548 8007020549 8007020552	50-263 0 50-346 0 50-546 0 50-266 0 50-155 0	KEPPLER. J O KEPPLER. J O KEPPLER, J O KEPPLER, J O KEPPLER. J O	8007240291 8007280429 8007280681 8007240402 8007240061	50-249 Q 50-346 Q 50-373 Q 50-255 F 50-454 B
REPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007210401 8007210407 8007210412 8007010068 8007010071	50-483	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q	8007020595 8007020559 8007020559 8007020562 8007020565	50-358	KEPPLER,J Q KERR.O U. KERR.O U KERR.O U KERR.O U	8007310521 8007270357* 8007270028 8007180021 8007010017*	50-329 G COMMISSION SECY WASTE MOT ORO
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007010074 8007010078 8007010080 8007010086 8007010104	50-546 0 50-305 0 50-266 0 50-10 0 50-461 0	KEPPLER.J Q KEPPLER.J O KEPPLER.J Q KEPPLER.J Q	8007020940 8007020870 8007020871 8007020573 8007020574	50-315	KERR, O. W KERR, O W KERR, O W KERR, O W	8007010035 8007020156 8007020699 8007140569 8007250639	State Prop State Prop State Prop State Prop State Prop
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007010107 8007010112 8007010115 8007010114 8007010123	50-341	Keppler, J O Keppler, J O, Keppler, J, O Keppler, J, O Keppler, J O	800702057B 8007020584 8007020587 8007020589 8007140574	50-409 G 50-461 G 50-367 G 50-10 G 50-483 A	Kerr, O. W Kerrigan, J Kerrigan, J Kerrigan, J Kerrigan, J	E00721006B B007160416 B007020196 B007110554 B007110561	State Prog 50-311 P 50-528 A 50-311 P 50-311 P
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007010127 8007010132 8007010136 8007010139 8007010144	50~243	Keppler, J o Keppler, J o Keppler, J o Keppler, J o, Keppler, J o	8007140581 8007170422 8007170426 8007170430 8007170459	50-546 A 70-1220 50-315 Q 50-10 Q 50-358 Q	Kerrigan, J Kerrigan, J. D. Ketchen, e o Ketchen, e g Ketchen, e g.	8007210277 8007280006 8007010282 8007090320 8007140019	50-311 F 50-311 P 50-369 Q 50-369 Q 50-369 Q
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007170094 8007010047 8007210116 8007220149 8007220156	50-973 Q 40-2674 50-409 Q 50-915 Q 50-10 Q	Keppler. J o Keppler. J o Keppler. J o Keppler. J o Keppler. J o	8007170465 8007170467 8007170474 8007170479 8007170486	90-440	KETZLACH, N KETZLACH, N KETZLACH, N KEY, U J KHARANA, B 8	8007150839 8007240110* 8007240125* 8007230375* 8007160569*	70~824 70~1201 70~27 50~304 G 50~454 K
KEPPLER. J 0 KEPPLER. J 0 KEPPLER. J 0 KEPPLER. J 0 KEPPLER. J 0	6007220174 6007220179 6007220163 6007220166 6007220175	50-359	Keppler, J Q Keppler, J, Q Keppler, J, Q Keppler, J, Q Keppler, J, Q	8007170487 8007170475 8007170500 8007170501 8007170504	50-331 Q 50-461 Q 70-725 50-367 Q 50-263 Q	KIENLE, C, F KIENLE, B KICOINS, B R KILLQUOH, C Q KIM, B. K	8007250376* 8007020653 8007010079 8007090371 8007170416*	50~397 A 50~320 H FOIA NUREG FOIA
KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J G KEPPLER. J G	800/220198 800/220201 8007220204 8007220204 8007220212	50-341 Q 50-331 Q 50-461 Q 50-367 Q 50-263 Q	Keppler, J O Keppler, J O Keppler, J O Keppler, J O Keppler, J O	8007170510 8007170515 8007170518 8007170524 8007170528	50-546 0 50-346 0 50-463 0 50-266 0 50-305 0	KING, K B KIMMEL, J. J KIMMEL, J. J KIMSERELL, M J	8005290607* 8007310269* 8007100368* 8007170161* 8007220119*	PT9 FOIA CONTRACT CONTRACT WASTE MGT

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KING. H A KINNEY. H W KINNEY. H W KINNEMAN. J D KINNEMAN. J D	8007030357* 8007210195* 8007210190* 8007230597 8007180338	CONTRACT 70-33 70-1143 70-2000 70-997	LACEY,W S LACEY,W S LACEY,W S LACEY,W S	800709033B* 800709034B* 8007180322* 8007220434* 8007250324*	50-334 8 50-334 8 50-334 8 50-334 9 50-334 9	LEMPGES, T E LEMPGES, T E LEMPGES, T E LEMPGES, T E LEMPGES, T E	8007210100 8007280465 8007250172 8007170360 8007250472	50-220 G 50-220 G 50-220 G 50-220 R 50-410 A
KINNEMAN, J D	8007230014	70-184	LACEY,W S	8007250331*	50-334 5	LEMPOES, TE	8007280275	50-220 I
KINNEMAN, J D	8007230215	I&E	LACEY,W S	8007300388*	50-334 8	LEMPOES, TE	8007290586	50-220 S
KINNEMAN, J D	8007310272	40-8045	LACY,F P	8007150522*	50-327 P	LEMAHAN, J J	8007110536*	50-424 Q
KINNT, W W	8007090373*	50-271 Q	LADD.E	8007160851*	COMMISSION	LEMAHAN, J J	8007100435*	50-400 Q
KINTNER, L	8007070009	50-364 A	LADUN,R H	8007100074*	50-293 Q	LEMAHAN, J J	8007180234*	50-553 Q
KINTNER, L KINTNER, L KINTNER, L KINTNER, L KINTNER, L	8007100018 8007210305 8007210306 8007210593 8007210598	50-364 A 50-364 A 50-364 A 50-364 A	LADUN,R H LADUN,R H LAFEVER,C W LAFLEUR,J D LAFLEUR,J D	8007230308* 8007230366* 8007290693* 8007170509 8007020177	50-287 G 50-219 G 30-327 S 50-320 P 50-315 H	LENTSCH, J W LENTSCH, J W LENTSCH, J W LESSOR, L C LESSOR, L C	8007170542 8007090331 8007250413 8007020333 8007080295	50-344 R NUREG 50-344 Q 50-298 Q 50-298 B
KINTNER, L	8007280121	50-364 A	LAFLEUR, J D	8007020181	50-206 H	LESSOR.L C	8007090005	50-278 8
KIPER, K L	8007210624	50-410 A	LAFLEUR, J D	8007020185	50-341 H	LESSOR.L C	8007080365	50-278 8
KIRK, B L	8007210498	50-247 P	LAFLEUR, J D	8007020189	27-47	LESSOR.L C	8007080391	50-278 R
KISNER, R. A	8007280092	REB	LAFLEUR, J D	8007020197	50-171 H	LESSOR.L C	8007280584	50-278 S
KISTER, H	8007250332*	50-286 Q	LAFLEUR, J D	8007020202	27-10	LESSOR.L C	8007250421	50-278 R
KISTER, H B	8007210165*	50-244 Q	LAFBER, F A	8007290038*	50-483 A	LESSY, R P	8007010143	50-376 G
KISTER, H B	8007250263*	50-220 Q	LAODMARBINO, R	8007250284*	50-275 H	LESSY, R P	8007220149	27-39
KISTER, H B	8007210255*	50-333 Q	LAHR, T N	8007020415	Hibc	LEVERANCE, J	8007140408*	PR
KISTER, H B	8007310504*	50-247 Q	LAINAB, O	8007110384	Foia	LEVERING, R	8007220451	50-10 D
KISTER, H	8007290010	50-220 B	LAINAB, O	8007110504	Foia	LEVINE, M M	8007180253	RE8
KLAMUT, C J	8007210005	RES	Lainab, Q C	8007100310*	50-255 P	LEWIS.R C	9007150506*	50-302
KLEINBORGE, N P	8007100313*	50-400 G	Lainab, Q, C	8007110244*	50-255 P	LEWIS.R C	9007160817*	
KLINE, J A	8007030048	50-275 Q	Lainab, Q C	8007010050	50-237 P	LEWIS.R C	9007220075*	
KLINE, J A	8007250429	50-275 Q	Lainab, Q C	8007030300	50-219 P	LEWIS.R C	9007240277*	
KLINGAMAN, R M	8007140413	50-320 P	Lainab, Q C	8007180079	50-409 F	LEWIS.R C	9007280475*	
KLGTZ, A. 8.	8007020439	PR	LAINAB, Q C	8007240056	50-213 P	LEWIS,R C	8007100059	50-335
KLGTZ, A. 8	8007020441	PR	Lainab, Q C	8007280008	50-29 P	LEWIS,R C	8007100064	
KNAPP, P.	8007210304*	70-467	Lainab, Q C	8007210591	50-206 S	LEWIS,R C	8007240266*	
KNAPP, P	8007150081	50-286 8	Lamb, H R	8007100437	PRM	LEWIS,R C	8007100119	
KNICELEY, J. R.	8007150076*	70-2609	Lambert, R	8007100191*	PR	LEWIS,M I	8007030349	
KNIEL,K KNICHTON,O W KNOP,R C KNOP,R C KNOP,R C,	8007010230* 8007140805 8006300138* 8007110148* 8007140541*	FOIA RECOD 50-329 Q 50-461 Q 50-483 Q	LAMPE, W F LANAHAN, M P LANCASTER, K F LANDOVER, R B LANDOMAN, R B	0007310398 8007210267* 8007110410* 8007140599 8007090179*	50-289 H CONTRACT 50-302 8 PR 50-440 Q	LEMIS, R C LEWIS, R C LEWIS, M I LEWIS, L	9007170219 9007180005 9007170420 9007020465 9007030087	50-327
KNOP, R C	8007150023*	50-483 G	LANDBMANIR B	8007090159*	50-440 Q	LEWIS, C	8007070043	PR
KNOP, R C	8007160764*	50-941 G	LANGIP M	8007110451	PRM	LEWIS, C	8007240368*	50-369 Q
KNOP, R C	8007230066*	50-941 G	LANGNERIR R	8007250705	PR	LEWIS, C	8007170105	PR
KNOP, R C	8007310367*	50-461 G	LANGMERIL C	8007300110	50~275 G	LEWIS, R	8007160476*	CDNTRACT
KNOP, R C	8007300169*	50-483 G	LANGMERIL C	8007300110	50-275 G	C	8007070374	50-348 Q
KNOP, R C. KNOP R C KNOTTB, J B KNOTTB, J, B. KNOTTB, J B	8007300304* 8007300157* 8007100270 8007160625 8007160625	50-327 G 50-483 G PRM 50-445 M 50-445 M	LANPHER, L C LANPHER, L C LANTZ, P M LAPP, R E LARKINB, R	8007310389 8007310389 8007300041 8007180221* 8007160773	50-312 0 50-312 0 NUREO COMMISSION MISC	LEWIG,M I LEWIG,M I LEWIG,R C LEWIG,M I	8007070276 8007100240 8007150475 8007220059 8007100215	50-320
KNUTH, D. F	8007020667	PR	LARDCHE, G	8007230148*	50-287 G	LEWIS, M	8007140005	50-289 Q
KNUTH, D F	8007140286	FOIA	LARBON, H J	8007030348	PR	LEWIS, R C	8007240256	50-296 B
KNUTH, D F	8007310262	FOIA	LARBON, J R	8007290226	RES	LEWIS, R C	8007160797	50-335 Q
KNUTH, D. F	8007170491	PR	LABH, T R	8007070084	PR	LEWIS, R C	8007280418*	50-270 Q
KOCH, L J	8007160638*	50-461 B	LATHAM, B B	8007290781	ORO	LEWIS, R C	8007240260	50-296 B
КОСН, L. J. КОСН, L. J КОСН, L. J. КОСН, L. J КОСН, L. J	8007160651* 8007160665* 8007160677* 8007250559 8007230518	50-461 S 50-461 B 50-461 S 50-461 A 50-461 B	LATHAM, B B LAWRENCE, J, F LAWRENCE, J F LAWRENCE, J F LAWRENCE, J F	8007270781 8007070036* 8007070040* 8007070044* 8007070046*	OR9 50-514 D 50-514 D 50-514 D 50-514 D	LEWIS.R C LEWIS.R C LEWIS.M I LEWIS.R C	8007280460 8007240261 8007310551 8007310143 8007310538	50-259 G 50-250 G 50-269 P 50-269 G 50-287 G
KOCH, L J	8007300429	50-461 B	LAWRENCE, R D	8007310217	NOREO	LEWIS, G H	8007280627	50-445 K
KOCH, L J	8007280506	50-461 B	LAWGON, J E	8007210491	NOREO	LEX, B L	8007020118	REGOD
KOCHER, D C	8007180065	NUREO	LAWTON, M D.	8007100427	DOPEN	LEYSE, R H	8007250621+	COMMISSION
KOCHER, D C	8007280095	REB	LAXALT, P	8007140231*	H 01-05	LI, C Y	8007010568	50-317 P
KOEBTER, O. L	8007290017*	50-482 Q	LAZARUG, W J	8004240228	B E92-05	LI, C Y	8007170066	50-317 P
KOLTAY, P. 8	8007170611*	50~286	LAZARUS, W	8007230398*	50-307 Q	LI.C Y	8007020469	50-317 P
KOPACZ, J	8007080172*		LAZARUS, W	8007230383*	50-307 Q	LI.C Y	8007230176	50-317 P
KOSTMAYER, P. H	8007110343*		LAZO, R, M	8007020620	50-367 Q	LI.C Y	8007210069	50-317 P
KOTSCH, J. L	8007230153		LEACH, F J	8007170612*	50-395 A	LIBRIZZI.F P	8007070348	50-272 R
KOTSCH, J. L	8007230245		LEASE, R B	8007210541*	50-316 S	LIBRIZZI.F P	8007070110	50-311 P
KOTSCH.J L	8007300268	40-4659	LEBERSTIEN.J H	8007020598*	MNSEO	LIBRIZZI,F P	8007080068	50-272 F
KOVACS.B	8007290858	PR	LEBOEUF.R J	8007100437	COWNIESTON	LIBRIZZI,F P	8007080267	50-272 8
KRACHT.W H	8007290631	50-266 H	LEDERER.P D	8007100126	BUW	LIBRIZZI,F P	8007080423	50-272 8
KRAMER.P B	8007100137	REGOD	LEE.B.	8007180034*	BUW	LIBRIZZI,F P	8007100197	50-272 6
KRAUSE.L	8007140638	50-458 H	LEE.B	8007240135*	BO-339 B	LIBRIZZI,F P	8007150516	50-272 8
KRAWCIAK,A T	8007010488*	50-295 8	LEE, B	8007180579*	COMMISSION	LIBRIZZI,F P	8007110444	50-272 0
KRAWCIAK,A T	8007220493*	50-295 8	LEE, E W	8007160741*	50-440 G	LIBRIZZI,F P	8007150421	50-272 8
KREGER,W.E	8007010270	50-320 P	LEE, E W	8007180519*	50-456 G	LIBRIZZI,F P	8007150672	50-272 6
KRICHIVER,R	8007100385	PRM	LEE, O R	8007010234*	50-267 G	LIBRIZZI,F P	8007210365	50-272 P
KUEHN,L B	8007130378*	50-327 P	LEE, T, D	8007140086*	70-143	LIBRIZZI,F P	8007170437	50-311 8
KUGE, T. KUNSITIB, T J KUSHNER, W L KYGER, J A. LACEY, L R.	8007310482	XPORTLIC	LEE.W F	8007100035	PR	LIBRIZZI,F P	8007220381	50-272 8
	8007020578*	50-338 P	LEFEVRE.H	8007170313	50-482 A	LIBRIZZI,F P	8007220617	50-272 8
	8007140648*	70-135	LEFEVRE.H E	8007300047	50-344 P	LIBRIZZI,F P	8007210474	50-272 8
	8007180031	NUREG	LEIBY.A C,	8007100437	PRM	LIBRIZZI,F P	8007280442	50-272 P
	8007300580*	50-321 G	LEMPOEB,T E	8007180073	50-220 Q	LIBRIZZI,F P	8007290697	50-272 R

RDHTUA	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
118R1ZZI.F P 118R1ZZI.F P 118R1ZZI.F P 118R1ZZI.F P 11CHYENDERGER	9007280624 8007290684 8007290718 8007290837 8007020103*	50-311 S 50-311 S 50-272 S 50-272 S 70-1100	LUNDVALL, A E	8007180600 8007230025 9007010329 9007090324 8007020436	50-317 Q 71-383 50-317 P 50-317 P 50-317 P	MACDONALD, C E	8007210583 8007210587* 8007220115 8007220125* 8007230038	71-5998 71-5998 71-5998 71-5971 71-5979
ICHTENBERGER ICHTENBERGER ICHTENBERGER ICHTENBERGER ICITRA, E A	8007020102 8007280737* 8007020107 8007220423 8007210237	71-6078 70-1100 70-1100 70-1100 50-528	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8007250662 8007020557 8007100228 8007210044 8007210574	50~317	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8007230040* 8007240450 8007240457* 8007220039 8007220055	71-3979 71-251 71-251 71-6697 71-249
LICITRA.E A LIEBERMAN.J LIM.T H LINDBLAD.W J LINDBLAD.W J	8007250044 8007300190* 8007090277 8007290832* 8007290825	50-482 A 50-266 G 50-224 H 50-514 F 50-514 F	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUZA, K V. MAGARTHUR, T Q	8007070291 8007170352 8007220590 8007210491 8007290410*	50-317 P 50-317 P 50-317 F NUREG 27-47	MACDONALD, C E	8007220067* 8007220086 8007220091 8007220099 8007220106*	71-249 71-6717 71-9070 71-121 71-121
Linder. F Linder. F Linder. F Linder. F Linder. F	8007020679 8007140371 8007180355 8007280696* 8007180362	50-407 0 50-409 0 50-409 0 50-409 0 50-409 0	MACARTOR, J D MACDONALD, C E MACDONALD, C E, MACDONALD, C E MACDONALD, C E	B007140043 8007010576 8007010579* 8007090061 8007090066*	PR 71-252 71-252 71-387 71-987	MACDONALD, C. E	8007220131 8007220135# 8007220143 8007220152# 8007230047	71-5768 71-5768 71-6387 71-6387 71-4824
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8007180092 8007140303 8007160677 8007220096 8007210447	50-409 Q 50-409 P 50-409 R 50-409 Q 50-409 P	MACDONALD, C E MACDONALD, C E MACDONALD, C C MACDONALD, C E MACDONALD, C E	9007010570 8007010574# 8007110161 8007110166# 8007100080	71-384 71-384 71-9009 71-9009 71-5088	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E.	8007230053 8007310013 8007310015* 8007280532 8007280543*	71-371 71-173 71-173 71-6698 71-6698
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8007280050 6007220525 8007270480 8007300244 8007310434	50-409 G 50-409 P 50-409 G 50-409 G 50-409 I	MACDUNALD, C E MACDONALD, C E MACDUNALD, C E MACDUNALD, C E MACDUNALD, C E	8007020026 8007020493 8007020518 8007020522* 8007100100	71-169 71-6144 71-391 71-391 71-6400	MACDONALD, C E	8007280541 8007280545* 8007280575 8007280580* 8007280698	71-9030 71-9030 71-9049 71-9049 71-9053
Linehan, J J Linehan, J J Linehan, J J Linehan, J J Linehan, J J	8007100091* 8007010569 8007280175 8007140593 8007140693	40-1162 40-1162 40-8681 40-6659 40-4492	MACDONALD, C E	8007020500 8007020506* 8007020512 8007020517* 8007020327	71-5942 71-5942 71-9016 71-9016 71-9015	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E.	8007280703* 8007290116 8007240175 8007240179* 8007240186	71-9053 71-9053 71-383 71-383 71-139
(inehan, J J Linehan, J J Linehan, J J Linehan, J J Linehan, J J	8007090104 8007230153 8007230131 8007230574 8007230667	40-8102 40-6659 40-2259 40-6622 40-8728	MAGDONALD.C E. MAGDONALD.G E MAGDONALD.G E MAGDONALD.G E HAGDONALD.G E	8007020532* 8007020422 8007020428* 8007020484 8007020583*	71-9015 71-6698 71-6698 71-9022 71-9022	MACDGNALD, C.E MACDDNALD, C.E MACDDNALD, C.E MACDONALD, C.E MACDONALD, C.E	8007240193* 8007240200 8007240201 8007240207* 8007240212	71-137 71-9044 71-6294 71-6294 71-9132
TINEHAN' 1 A TINEHAN' 1 A TINEHAN' 1 A TINEHAN' 1 A	8007230672 8007230680 8007230084 8007230245 8007230715	40-8681 40-8584 40-8585 40-6659 40-8452	MACDONALD, C E	8007110265 8007110270* 8007110452 8007110461* 8007110464	71-6375 71-6375 71-6078 71-6078 71-9130	MACDONALD, C. E MACDONALD, C. E. MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8007240215* 8007240217* 8007270016 8007270018* 8007280718	71-9044 71-9132 71-9010 71-9010 71-4986
LINEHAN, J J Linenbergfr, g a Lingren, c L Linneman, r e Linton, d u	8007300248 8007270744 8007150085 8007170328* 8007090399	40-8459 50-444 0 REGOD FOIA PR	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C E	8007110468* 8007110473 8007110476* 8007100040 8007100041*	71-9130 71-5926 71-5926 71-6591 71-6581	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E,	8007280720* 8007280762 8007280766* 800729008 8007290011*	71-4986 71-9080 71-9080 71-6568 71-6568
LINTON, O W LIPINSKI, W C LIST, R LITTLE, W B LITTLE, W B	8007130070 8007210027 8007230739* 8007100291* 8007230303*	PR ACR8 COMMISSION 50-331 Q 50-331 Q	MACDONALD.C C MACDONALD.C E MACDONALD.T H MACDONALD.C.E MACDONALD.C E	8007110281 8007110290* 8007110481 8007140698 8007140702*	71-5450 71-5450 50-307 H 71-346 71-346	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACH, 8.R.	8007280771 8007280773* 8007280776 8007280779* 8007310325*	71~9139 71~9139 71~6387 71~6387 50~327 P
LITTLE, H LIVEMORE, H H LLOYD, L L LOATS, E T LOCHSTET, W A	8007280234 8007310367* 8007020332 8007150059 8007110067	CONTRACT 50-461 G PR RES PR	MACDONALD, C E	8007140706 8007140709* 8007160310 8007160317* 8007160322	71-5 71-5 71-391 71-391 71-389	MACIOLEK.N J MACKENZIE.D R. MADDEN.W MADDEN.W MADEDA.T J	8007150712* 8007210007 8007020022* 8007290199* 8007020211*	50-219 R REB 70-1143 50-244 G 50-295 G
LOCKE, J, W LOCKE, R F LOCKE, R F LODDER, H LOCIUDICE, J M	6007240381 8007180358 8007250386 8007310182* 8007300578*	PR 90-103 0 90-133 0 QA999 CBNTRACT	MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C. E MACDDNALD, C. E	8007160335* 8007160343 8007160347* 8007220089 8007220097*	71-389 71-393 71-393 71-9136 71-9136	Madeda, T J Madeda, T J Madison, A Madison, W R Madben, C. L	8007240107* 8007280435* 8007140474* 8007220434* 8004240281	50-263
LOTS, L LONG, F J. LONG, F W	8007010722 8007170584* 8007170567* 8007310235*	50~255 P 50~553 Q 50~553 O 50~387 Q 50~387 P	MACDONALD; C E MACDONALD; C E MACDONALD; C E MACDONALD; C, E MACDONALD; C, E	8007170471 8007170474 8007170480 8007170485 8007170487	71-2 71-82 71-109 71-143 71-179	Madben, C L Madben, C. L Madben, C L Madben, C L Madben, C L	8007150165 8007220177 8007150083 8007150125 8007300349	50-285 Q 50-313 Q 50-267 Q 50-298 Q 50-313 Q
), G. E V. C. E G. E C. E.	6007170492 6007140361 6007140367* 6007140409 6007140412*	71-271 71-4888 71-4888 71-4984 71-4986	Madben, 0 L Madben, 0, L Madben, 0 L Madben, 0 L Madben, 0 L	8007070020 8007070172 8007010231 8007110086 8007310334	50-313 H 50-313 Q 50-267 Q 50-285 Q 50-313 8
			# # # # # # # # # # # # # # # # # # # #	8007160767 8007160772# 8007170093 8007170097# 8007220846	71-392 71-392 71-5341 71-5341 71-6591	Madben, o l Madben, g l Madben, g, l Madee, h Madroh, r.	8007290331 8007300320 8007300329 8007140504* 8007100189*	50-313 & 50-313 0 50-313 0 FOIA 50-237 8
				8007170113 8007170118* 8007170178 8007180084 8007180088	71-5862 71-5862 71-9039 71-3450 71-9080	Magroh, R Makatura, L Makepeace, J. H Makepeace, J. M Malek, F. A	8007220572* 8007030264* 8007110404* 8007240172* 8007140582	50-237 E 50-346 & 50-247 S 50-247 S PR

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MALLORY, K MALLORY, K MALONE, K MALONE, T MALONEY, O P	8007090166* 8007090167* 8007030019* 8007090163 8007160384	NUREO NUREO 50-556 H NUREO 50-315 C	ł	MARRAM, E P MARRACK D MARRACK, D MARRANZING, A P MARRACK, D	8007160498* 8007160560 8007160565* 8007160672 8007220552	CONTRACT 50-466 G 50-466 G 50-274 F 50-466 G		MATHENS, E. R.	8007140464 8007240321 8007240334 8007160544 8007240415	50-305 8 50-305 0 50-305 0 50-305 8 50-305 0
MALONEY. G P MALONEY. G P MALONEY. G P MALONEY. G P MANCUSO. F	8007250016 8007150676 8007220080 8007230269 8007010498	50-316 0 50-315 0 50-315 0 50-315 0	<u>.</u>	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110077* 8007110051* 8007110052* 8007110057* 8007110060*	50-320 J 50-320 J 50-320 J 50-320 J 50-320 J		MATHENS, E R MATHISEN, R L	8007160485 8007280665 8007280675 8007280414 8007030352	50-305 8 50-305 8 50-305 8 50-305 F 40-8102
Mandler, J W Manguei, J Mann, D C Manry, M Manry, M	8007210602 8007070043 8007310210 8007110285 8007010494		3 8	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110062* 8007110068* 8007110072* 8007110222* 8007110224*	50-320 J 50-320 J 50-320 J 50-320 J		MATSON, V MATSON, V MATSON, V MATSON, V	8007070140 8007070145 8007070018 8007110469 8007110480	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Manry, M Manry, M Manry, M Manry, M Manry, M	8007010510 8007030272 8007030276 8007030280 8007020628	50-366 50-321 50-366	8 9 9 9	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110089* 8007110091* 8007110095* 8007110098* 8007110103*	50-320 J 50-320 J 50-320 J 50-320 J) ;)	MATSON, V MATSON, V MATSON, V MATSON, V	8007150353 8007270025 8007270444 8007270027 8007270370	YPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Manry, M Manry, M Manry, M Manry, M Manry, M	8007030261 8007030284 8007020520 8007030277 8007020638	50-321 50-366 50-366	9 8 8 8	MARRONE, J MARSHALL, N H MARSHALL, E N MARSH, R J MARSH, R J	8007110084* 8007160649* 8007300012* 8007170584* 8007290380*	50-320 0 50-329 1 50-320 1 50-553 0 50-335	1 1 3	MATTIA,M J HATTIA,H J MATTIA,J C MATTIMOE,J J MATTIMOE,J J	8007020287* 8007020292* 8007210338* 8007240178 8007180541	FOIA FOIA 50-352 0 50-312 0 50-312 0
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M.	8007110307 8007110400 8007110429 8007110304 8007110432	50-321 50-366 50-321	5 5 6 8	MARSHALL, W H MARTIN, T T MARTIN, J B MARTIN, R MARTIN, W O.	8007140017 8007210307* 8007230663* 8004240250 8007020017*	50-329 (50-277 (50-10) 50-327 (70-1143))	MATTIMOE.J J MATTIA.J C MATTIA.M J MATTIMOE.J J MATTIA.M J	8007240192 8007210240* 8007020398* 8007250676 8007020731*	50-312 G 50-352 G CONTRACT 50-312 G CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M HANRY, M	8007110368 8007110368 8007110455 8007110415 8007150539	50-321 50-321 50-321	8 9 9	MARTIN, W 0 MARTIN, W 0 MARTIN, W 0 MARTIN, W 0 MARTIN, W 0	8007020008> 8007100071* 8007180071* 8007240055 8007140644	70-135 50-293 70-371 XPORTLIC 70-135	a	MATTIME, J J MATITA, M J MATTIA, M J MATTIA, M J MATTIA, M J	8007270847 8007170172* 8007240170* 8007250562* 8007070134*	50-312 G CONTRACT CONTRACT CONTRACT CONTRACT
MANRY, M MANRY, M. MANRY, M MANRY, M MANRY, M	8007150435 8007280450 8007150478 8007150496 8007150464	50-366 50-366 50-321	8 8 8 8	MARTIN,R D MARTIN,T T MARTIN,W G MARTIN,L.E MARTIN,L.E	8007070399* 8007280262* 8007280743* 8007070091* 8007100346*	50-293 70-1100 50-482	Q Q Q Q	MAITTAM J MAITTAM J MAITTAM J MAITTAM J J J J J J J J J J J J J J J J J J J	8007100312* 8007140210 8007100368* 8007100203 8007110539*	CONTRACT CONTRACT CONTRACT 50-312 P CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007170382 8007170392 8007170405 8007170451 8007170481	50-321 50-366 50-321	6 9 8 8	MARTIN, W G MARTIN, T J MARTIN, W G MARTIN, W G MARTIN, R D	8007020015 8007210282* 8007020002 8007170622 8007240281*	70-135 70-135	a a	L L.BOMITTAM L M.AITTAM L L.BOMITTAM L M.AITTAM L M.AITTAM	8007080270 8007180173* 8007300072 8007170214* 8007170222*	50-312 S CONTRACT PR CONTRACT CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007170453 8007170414 8007280678 8007280686* 8007210393	50-321 50-321	8 8 R R	MARTIN, W 0 MARTIN, W 0, MARTIN, T MARTIN, W 0 MARTIN, T T	8007230301 8007290176 8007230398* 8007100068 8007230363*	50-244 50-309 50-293	a a a a	L M.AITTAM L M.AITTAM L M.AITTAM L M.AITTAM L JONITTAM	8007180524* 8007210113* 8007210135* 8007210140* 8007080183	CONTRACT CONTRACT CONTRACT CONTRACT 50-312 P
HANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007210370 8007210384 8007210484 8007280505 8007310527		5 8 8 5	MARTIN, W G MARTIN, W G MARTIN, T T MARTIN, I E MARTIN, W G	8007230119 8007230361 8007020540 8007280730* 8007250486	70-371 50-213 50-271 50-482 70-820	Q 5 Q	LEOMITTAM LHAITTAM LMAITTAM LHAITTAM LEOMITTAM	8007300081 8007140521* 8007170129* 8007170161* 8007230432	PR CONTRACT CONTRACT CONTRACT 50-312 P
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007240124 8007220514 8007240165 8007250411 8007280448	50-366 50-321 50-366 50-366 50-321	6 6 6 8	MARTIN, J B MARTIN, J B MARTIN, D E MARTIN, D E MARTIN, R	8007070030 8007230671* 8007290463 8007290470* 8007010538	27-39 50-10 PROJ PROJ 50-368	D P	MATTIA,M J MATTIA,M J MATTIMOE,J J MATTRON,R J MATTRON,R J	8007170145* 8007300591* 8007310410 8007020151 8007110475*	CONTRACT CONTRACT 50-312 S 50-327 A SECY
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007280518 8007280445 8007280572 8007280629 8007280682	50-366 50-321 50-321 50-321 50-321	8 8 8	MARTIN, R A MARTIN, T MARTIN, T MARTIN, W, O MARTIN W 0	8007010581 8007150081 8007310293* 8007140615 8007180058	50-282 50-286 50-364 50-334 70-371	P 8 8	MATTSON, R J MATTSON, R J MATTSON, R J MATTSON, R J MATTSON, R J	8007100456 8007110322* 8007210176 8007230635 8007150061	50-320 H MIBC 50-322 A 50-275 A FINANCIAL
MANRY, M MANGER, W C MANGER, W C MANGER, W C MANGER, W C	8007300392 8007160843* 8007070014* 8007010109* 8007140064*	50-321 70-143 70-143 70-143 70-143	В	MARTIN,R MARTIN,T J MARTIN,J B MARTIN,W MARTIN,W O	8007170074 8007250279 8007230075 8007230158 8007280733	50-282 50-354 PROJ 50-320 70-1100	Р О 8	MATZ,Q MAURO,C L MAXWELL,L Y MAXWELL,Q F MAXWELL,D R	8007150040* 8007250056 8007020375* 8007100432* 8007220101*	50-320 H 50-67 R 50-4[3 Q WASTE MQT
MANBER, W C MANBER, W C MANBER, W C MANBER, W C MANBER, W C.	8007030292 8007020437 8007070191 8007070350 8007280552	70-143 70-143 70-143 70-143 70-143		MARTIN, T MABON, D O MABON, T J MASON, T J MABON, T J	8007270058 8007100013 8007010085* 8007010077* 8007210558*		8	MAXWELL,L V MAYER,L O MAYER,L O MAYER,L O MAYER,L O	8007020370 8007030222 8007010335 8007010351 8007010325	50-67 R 50-263 P 50-263 P 50-263 F 50-263 F
MANGER, W. C. MANGER, W. G. MARCHAL, J. MARCHAL, J. MARK, R. H	8007250464 8007290713 8007170229 8007240447 8007220503*	70-143 70-143 XPDRTLIC XPORTLIC TOPREP		MASON,T J MASSEY,W E MATHEWS,E R MATHEWS,E R MATHEWS,E R	8007210569* 8007180031 8007010036 8007020716 8007020032	40-2674 NUREQ 50-305 50-305 50-305	Q Q Q	MAYER.L O MAYER.L O MAYER.L O MAYER.L O MAYER.L O	8007010531 8007010311 8007010375 8007010381 8007010524	50-304 9
MARKEY: E. J. MARGITA: C R MARRACK: D MARRACK: D MARRACK: D	8007110343* 9007110501* 9007030025 8007030029* 8007110080	50-352 50-320 50-466 50-466 50-466	U P Q Q	MATHEWB, E R MATHEWB, E R MATHEWB, E R MATHEWB, E R MATHEWB, E R	8007020254 8007220229 8007110317 8007080204 8007080386	50-305 50-305 50-305 50-305 50-305	0 P 8 P 8	MAYER,L O MAYER,L O MAYER,L O MAYER,L O MAYER,L O	8007100123 8007080251 8007100047 8007100190 8007080265	50-236 F 50-263 P 50-263 P 50-263 B 50-263 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AU THOR	ACCESSION NUMBER	BUBJECT CATECORY
MAYER, L D	8007210184	50-263 P	HCOAUGHY, R U HCGAUGHY, R U HCGAUGHY, J P HGGAUGHY, R W HCGAUGHY, R W	8007210355×	50-387 0	MEKBEL, C	8007150566*	50-344 S
MAYER, L D	8007280056	71-9018		8007210209*	50-410 0	MELLINGER, C U	8007140013	50-289 H
MAYER, L D	8007150481	50-282 Q		8007160866*	50-414 0	MELOTT, R K	8007150166	PR
MAYER, L O	8007110115	50-282 F		8007170599*	50-343 0	MENARD, H W	8007030193	PR
MAYER, L O	8007150611	50-263 R		8007210240*	90-352 0	MENARD, H W	8007280024	PR
MAYER, L O	8007160558	50-282 R	PACAMONADA	9007170592	50-416 S	MENNICKEN: J B	8007150036	XPORTLIC
MAYER, L O	8007170398	50-263 P	P. L.YHQUAGON	9007160585	50-416 S	MERRIWEATHER, N	8007180275*	50-395 0
MAYER, L O	8007210379	50-306 9	P. L.YHQUAGON	9007160642	50-416 S	MERRILL: J A	8007220019	NUREO
MAYER, L O	8007210437	50-282 5	H. R.YHQUAGON	9007170274*	50-354 G	MERGON, B D	8007010390*	50-317 R
MAYER, L O	8007180300	50-263 P	U. R.YHQUAGON	9007170288*	50-322 G	MERGON: B D	8007010392*	50-317 R
MAYER.L O MAYER.L O MAYER.L O MAYER.L O MAYER.L O	8007280441 8007280381 8007280410 8007280489 8007270669	50-263 F 50-263 F 50-263 P 50-263 F 50-282 S	POPUNCON POP	8007020579 8007020640 8007160611 8007170257* 8007180561*	50-416 B 50-416 B 50-415 B 50-387 O 50-410 O	MERSON, S D MERSON, S D MERSON, S D MESSINGER, M MESSITT, B R	8007010389 8007220351 8007220355* 8007100015* 8007160830*	50-317 R 50-317 R 50-317 ft 70-143 50-333 G
Mays, 8 &	8007230172	50-334 P	HRAUAODH	8007210545*	50-423 Q	MEGGITT.BR MEYER.RO MEYER.RO MEYER.RO MEYER.RO	8007170429*	50-324 G
Mays, 8	8007080305*	50-409 P	PL,YHOUAODH	8006190977	50-416 8		8007010082*	FOIA
McBrearty, 8 a	8007210207*	50-410 Q	PL,YHOUAODH	8007020601	50-416 8		8007010194*	FOIA
McBride, a f	8007250552*	50-460 A	PL,YHOUAODH	8007160862*	50-416 Q		8007010210*	FOIA
McCabe, e	8004240212	50-286 S	PL,YHOUAODH	8007020538	50-416 B		8007100024	PR
MCCABE, E MCCABE, E C MCCABE, E C MCCABE, E C MCCANN, M	8004240215 800723073&# 8007230174* 8007210247* 8007170097*</td><td>50-318 8 50-277 0 50-334 0 50-317 0 50-206 H</td><td>9 , уноилоэм 9 с , уноилоэм 9 с , уноилоэм 9 с , уноилоэм 9 с , уноилоэм</td><td>8007020630 8007070290 8007110413 8007110430 8007150093</td><td>50-416 8 50-416 8 50-416 8 50-416 6 50-416 8</td><td>MEYER, C J MEYER, J F MEYER, J F MICHEL, C J</td><td>6007030007 6007110575* 6007010408 6007230446 8007150520*</td><td>FOIA CONTRACT 50-247 P 50-247 P 70-143</td></tr><tr><td>MCCARINEY,R M</td><td>6007020593</td><td>50-320 H</td><td>PARTHEMENT PROPERTY J PROPERTY J PROPERTY J PROPERTY J PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY PROPERTY J PRO</td><td>8007150097</td><td>50-416 8</td><td>MICHEL, C J</td><td>8007280184#</td><td>70-143</td></tr><tr><td>MCCARREL,S F</td><td>8007010418</td><td>50-344 P</td><td></td><td>8007150105</td><td>50-416 8</td><td>MICHEL, C J</td><td>8007010101</td><td>71-5768</td></tr><tr><td>MCCARREL,S F</td><td>8007300333</td><td>50-344 O</td><td></td><td>8007170396</td><td>50-416 8</td><td>MICHEL, C J</td><td>8007010121#</td><td>71-5768</td></tr><tr><td>MCCAULEY,B K</td><td>8007230513</td><td>50-10 D</td><td></td><td>8007170390</td><td>50-416 6</td><td>MICHEL, C J</td><td>8007070333</td><td>70-143</td></tr><tr><td>MCCLAIN,C M</td><td>6007220364*</td><td>50-219 R</td><td></td><td>8007170435</td><td>50-416 5</td><td>MICHEL, C. J</td><td>8007180475</td><td>71-249</td></tr><tr><td>MCCLINTOCK,R O</td><td>6007170337*</td><td>70-1849</td><td>POPER CONTROL PROGRAMMENT OF C. PAROLAGOM POPER CONTROLAGOM POPER</td><td>8007220388</td><td>50-416 8</td><td>MICHEL, C J</td><td>8007150563</td><td>70-143</td></tr><tr><td>MCCLINTOCK,R O</td><td>8007170345*</td><td>70-1849</td><td></td><td>8007220389</td><td>50-416 5</td><td>MICHEL, C J</td><td>8007150518</td><td>70-143</td></tr><tr><td>MCCLINTOCK,R O</td><td>8007170341*</td><td>70-1849</td><td></td><td>8007250432</td><td>50-416 0</td><td>MICHEL, C. J</td><td>8007290547</td><td>70-143</td></tr><tr><td>MCCLINTOCK,R O</td><td>8007170349*</td><td>70-1849</td><td></td><td>8007250510</td><td>50-416 9</td><td>MIDURA, H J</td><td>8007150596</td><td>50-272 R</td></tr><tr><td>MCCLINTOCK,R O</td><td>8007170407*</td><td>70-1849</td><td></td><td>8007280566</td><td>50-416 8</td><td>MILEHAM, J</td><td>8007110159</td><td>F016</td></tr><tr><td>MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O</td><td>8007170292* 8007170306* 7812210553 8007170304* 8007170432*</td><td>FOIA FOIA PT9 FOIA FOIA</td><td>PAPUNADON PAPUNADON PAPUNADON PAPUNADON PAPUNADON PAPUNADON PAPUNADON PAPUNADON</td><td>8007270655 8007270666 8007270671 8007270714 8007270771</td><td>50-416 8 50-416 6 50-416 6 50-416 8 50-416 8</td><td>MILHISER,R J MILLER,J O MILLER,J,G MILLER,J, MILLER,J O</td><td>8007080237* 8007110023* 8007110020* 8007110024* 8007110015*</td><td>50-382 8 70-1333 70-1333 70-1333 70-1333</td></tr><tr><td>MCCLINTOCK, R O</td><td>8007170399*</td><td>F01A</td><td>MCGDLDRICK,F F</td><td>8007150074*</td><td>8ECY</td><td>MILLER, W H</td><td>8007100413*</td><td>50-324 Q</td></tr><tr><td>MCCLINTOCK, R O</td><td>8007170411*</td><td>F01A</td><td>MCGOVERN,J J</td><td>8007210293*</td><td>70-687</td><td>MILLER, D B</td><td>8007030059*</td><td>PR</td></tr><tr><td>MCCLINTOCK, R O</td><td>8007170314*</td><td>F01A</td><td>MCGREY,J G</td><td>8007150140</td><td>PR</td><td>MILLER, T</td><td>8007140024</td><td>50-323 H</td></tr><tr><td>MCCLINTOCK, R O</td><td>8005090527*</td><td>P19</td><td>MCGREGOR,L G</td><td>8007210327*</td><td>50-346 Q</td><td>MILLER, D W</td><td>8007090409</td><td>REOOD</td></tr><tr><td>MCCLINTOCK, R O</td><td>8007280224</td><td>40-8329</td><td>MCGREW,J W</td><td>8007010240</td><td>71-4688</td><td>MILLER, H J</td><td>8007020148</td><td>Waste Mot</td></tr><tr><td>MCCONNELL, J W MCCOLLOUGH, W D MCCOLLOUGH, W A MCCOLLOW, W A</td><td>80071\$0325* 8005090523 80071\$0014 8007290789 8007240060</td><td>70-2651 PT9 RE8 50-344 Q 50-367 F</td><td>McGreh, J W McGriff. J M McGvire. D R McGvire. J P McGvire. P J</td><td>8007010245 8007150585* 8007310235* 8007010540 8007070378</td><td>71-9030 50-327 8 50-389 0 50-293 8 50-293 6</td><td>MILLER,L C MILLER,W H MILLER,L MILLER,R W MILLER,R B</td><td>8007250057* 8007100151* 8007170579* 8007310255 8007140379*</td><td>GA999 50-269 G 50-206 G NUREO TOPREP</td></tr><tr><td>MCCORKLE, O W</td><td>8007240072</td><td>70-754</td><td>MCQUIRE.P J</td><td>8007030287</td><td>50-293 8</td><td>MILLER,R B</td><td>B007140416*</td><td>TOPREP</td></tr><tr><td>MCCORKLE, O W</td><td>8007240080</td><td>70-1252</td><td>MCQUIRE.P J</td><td>8007070357</td><td>50-293 8</td><td>MILLER,R D</td><td>B007160755*</td><td>TOPREP</td></tr><tr><td>MCCORKLE, O W</td><td>8007020244</td><td>70-1193</td><td>MCQUIRE.P J</td><td>8007080182</td><td>50-293 8</td><td>MILLER,W O</td><td>B007110580</td><td>50-315 P</td></tr><tr><td>MCCORKLE, O W</td><td>8007020505</td><td>70-1739</td><td>MCQUIRE.P J</td><td>8007080196</td><td>50-293 8</td><td>MILLER,W D</td><td>B007020251</td><td>50-267 P</td></tr><tr><td>MCCORKLE, O W</td><td>8007140598</td><td>70-135</td><td>MCQUIRE.P J</td><td>8007080202</td><td>50-293 8</td><td>MILLER,W J</td><td>G007170583</td><td>40-8380</td></tr><tr><td>MCCORKLE, G U</td><td>8007240076</td><td>70-734</td><td>MCGUIRE, P J</td><td>8007140641</td><td>50-293 8</td><td>MILLER, J R</td><td>8007020169</td><td>50-150 P</td></tr><tr><td>MCCORKLE, O U</td><td>8007230648</td><td>70-27</td><td>MCGUIRE, P J</td><td>8007180393</td><td>50-293 P</td><td>MILLER, J, R</td><td>8007020174*</td><td>50-150 P</td></tr><tr><td>MCCORKLE, O U</td><td>8007310452</td><td>70-25</td><td>MCGUIRE, P J</td><td>8007150699</td><td>50-293 R</td><td>MILLER, J, R</td><td>8007020490</td><td>50-193 P</td></tr><tr><td>MCCORKLE, O U</td><td>8007310475</td><td>70-25</td><td>MCKENZIE, L</td><td>8007310004</td><td>NUREO</td><td>MILLER, J R</td><td>8007020493*</td><td>50-193 P</td></tr><tr><td>MCCRACKEN, K 1/</td><td>8007220515*</td><td>50-348 P</td><td>MCKIBBEN, J C</td><td>8007080266</td><td>50-186 6</td><td>MILLER, W O</td><td>8007020250</td><td>40-4492</td></tr><tr><td>MCCRAY, J O</td><td>B00703013B</td><td>PR</td><td>MCKIBBEN, J C</td><td>8007080240</td><td>50-166 6</td><td>MILLER, H. D</td><td>8007030228</td><td>70-1113</td></tr><tr><td>MCCREERY, O E</td><td>B007220045</td><td>REB</td><td>MCKIBREN, J C</td><td>8007140351</td><td>50-166 8</td><td>MILLER, J R</td><td>8007140630</td><td>TOPREP</td></tr><tr><td>MCDONALD, R P</td><td>B007280052</td><td>PR</td><td>MCKIBIEY, R D</td><td>8007220051</td><td>40-8745</td><td>MILLER, J R</td><td>8007140639</td><td>TOPREP</td></tr><tr><td>MCDOUGALL, A J</td><td>B007170172*</td><td>CONTRACT</td><td>MCLOUGHLIN, M T</td><td>8007010545*</td><td>50-273 8</td><td>MILLER, J R</td><td>8007250483*</td><td>TOPREP</td></tr><tr><td>MCDOUGALL, A J</td><td>B007240173*</td><td>CONTRACT</td><td>MCLOUGHLIN, M T</td><td>6007070382*</td><td>50-273 8</td><td>MILLER, H J</td><td>8007230161</td><td>40-8714</td></tr><tr><td>MCDOWELL-BOYER MCOUFFIE.M A MCOUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A</td><td>8007280095 8007020427 8007220210 8007150535 8007220456</td><td>RES 50-400 A 50-400 Q 50-400 A</td><td>MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T</td><td>8007070388* 8007030289* 8007080200* 8007080205* 8007140448*</td><td>50-293 8 50-293 8 50-293 8 50-293 8 50-293 8</td><td>HILLER, DE HILLER, TR MILLER, JR MILLER, DS MILLER, DS</td><td>8007310815# 8007070282 8007110274 8007020607 8007020610#</td><td>50-295 Q 50-329 O 50-463 A 50-309 O 50-309 O</td></tr><tr><td>MCDUFFIE.M A</td><td>8007280507</td><td>50-400 R</td><td>MCMASTER,C F</td><td>8007140027</td><td>50-287 H</td><td>Miller, D &</td><td>6007020407</td><td>50-307 0</td></tr><tr><td>MCELHANEY.D L</td><td>8007140379*</td><td>TOPREP</td><td>MCNAMARA.A</td><td>8007150570*</td><td>50-244 R</td><td>Miller, D &</td><td>6007020610*</td><td>50-307 0</td></tr><tr><td>MCELHANEY.D L</td><td>8007140416*</td><td>TOPREP</td><td>MCNEILL,W M</td><td>8007160411*</td><td>QA979</td><td>Miller, J O</td><td>6007250117*</td><td>COMMISSION</td></tr><tr><td>MCELHANEY.D L</td><td>8007160755*</td><td>TOPREP</td><td>MCPHILLIPS,J</td><td>8007110003</td><td>70-2709</td><td>Miller, M I.</td><td>6007020462</td><td>50-597 0</td></tr><tr><td>MCELHURRY.B R</td><td>8007100332</td><td>PR</td><td>MCPHILLIPS,J L</td><td>8007110059</td><td>70-2909</td><td>Miller, M I</td><td>6007020462</td><td>50-597 0</td></tr><tr><td>MCFARLAND, J E MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M</td><td>8007230160* 8007140243 8007240140 8007140004 8007140004</td><td>QA779 FOIA PR 50-349 Q</td><td>MCPHILLIPS, J L MCKETHY, P J MEANB, D S MEBUS, C F MECKLINO, M</td><td>8007110058 8007180227* 8007030305 8007230686 8005070512</td><td>70-2909 M180 50-522 A 50-320 H 50-320 H</td><td>MILLER,K L MILLER,J R MILLER,J R MILLER,J R MILLER,M I</td><td>8007140004 8007150028 8007150035* 8007150041* 8007090045</td><td>50-920 T 50-184 P 50-184 P 50-184 P 50-329 G</td></tr><tr><td>M CARRADA N CARLANDIA N CANDONY, R W N CANDON N M CANDO</td><td>6007290887 8007100014* 8007210338* 8007170682* 8007010235*</td><td>PR 50-320 0 50-352 0 50-354 0 50-443 0</td><td>MEDLOCK, R L MEDROW, L A K MEIER, M O MEINGKE, J A MEIBS, R L</td><td>8007240007 8007170122 8007300565 8007110407 80071100152</td><td>40-8452 CONTRACT PR 50-255 R PROJ</td><td>MILLER, M I MILLER, W O MILLER, W O MILLER, W O MILLER, W O</td><td>8007090045 8007210039 8007210041 8007210043 8007210051</td><td>50-329 0 70-143 71-5980 71-9019 TOPREP</td></tr></tbody></table>							

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESS ION NUMBER	SUBJEC CATEGOR
MILLER.W O MILLER.W O MILLER.W O MILLER.H J MILLER.J R	8007180502 8007210039 8007210057 8007230279 8007220134	70-8 70-824 50-293 P 40-8200 TQPREP	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007150472 8007160643 8007140443 8007160650 9007160666	50-327 P 50-327 F 50-328 S 50-438 S 50-328 S	MINER.L E MINER.S MINER.L E MINNERS.W MINDOUS.R B	8007250012* 8007010546 8007240258* 8007240771 8007160694*	40-4337 50-315 40-4337 ORG 50-341
MILLER, D B MILLER, W O MILLER, W O MILLER, W O MILLER, W O	900728004I 8007170621 9007180076 8007180104 9007180109	50-329 A 70-754 50-317 P 50-249 P 50-244 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007210091 8007230726 8007280615 8007150546 8007150551	50-259 Q 50-259 Q 50-259 Q 50-438 A 50-438 A	MINDOUE, R B MINDOUE, R B MINDOUE, R B MINDOUE, R B MINDOUE, R B	8007070578 8007250019* 8007070015 8007140576 8007140055	SECY LOCFR SECY SECY SECY
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8007180113 8007210074 8007210097 8007230052 8007230057	50-219 P 70-687 70-27 50-269 P 50-244 P	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8007150640 8007150672 8007160424 8007210036 8007210596	50-327 P 50-327 P 50-438 S 50-327 Q 50-327 Q	MINDQUE, R B MINDR, O C MINTIER, D MISHIMA, J MISHIMA, J	8007170404* 8007270809* 8007250578* 8007070186* 8007210315*	10CFR DRO CONTRAC' 70-1297 70-1257
MILLER, W O MILLER, W O MILLER, H J MILLER, D B MILLER, D S	8007230116 8007290707 * 8007230620 8007110345 8007110345	50-329 A 50-329 A 40-8727 PR PR	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8007150521 8007160473 8007230255 8007300003 8007170272	50-327 P 50-566 B 50-566 B PRM 50-370 Q	MITCHELL, W KITCHELL, D Q MITCHELL, D Q MITCHELL, D Q MITCHELL, D Q	8007230188 8007070256* 8007070313* 8007080214* 8007160526*	MISC 50-289 50-289 50-289 50-289
MILLER.O E MILLER.O E MILLER.M I MILLER.M I MILLER.J R	8007150618 8007150620* 8007140020 8007140020 8007280699	50-326 R 50-326 R 50-329 0 50-329 0 50-264 F	MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007170342 8007170356 8007150571 8007150659 8007160471	50-566 S 50-366 S 50-327 P 50-566 S 50-327 P	MITCHELL,D G MITCHELL,D G MITTL,R L MITTL,R L MITTL,R L	8007140623* 8007290805* 8007070285 8007030161 8007030229	50-287 50-287 50-272 50-272 50-311
MILLER, L K MILLER, W O MILLER, W O MILLER, M E MILLER, W D	8007150404* 8007210089 8007210094 8007290789 8007250580	50-272 R 70-1257 70-364 50-344 G 70-25	MILLB.L M MILLB.L M MILLB.L M MILLB.L M	8007170513 8007170591 8007310355 8007170560 8007220376	50-390 8 50-390 8 50-259 0 50-260 P 50-259 P	MITTL,R L MITTL,R L MITTL,R L MITTL,R L MIYABAYASHI,M	8007030244 8007160628 8007210219 8007210389 8007250555	50-311 50-311 50-311 50-311 TERDEX
HILLER,W O MILLER,M I MILLER,M I MILLER,W O MILLER,M E	8007280064 8007220194 8007220194 8007250157 8007220500	50-315 P 50-329 Q 50-329 G 40-8584 50-445 M	MILLB.L M MILLB.L M MILLB.L M MILLB.L M MILLB.L M	8007230445 8007230487 8007230582 8007310056 8007220522	50-257 8 50-390 9 50-390 0 50-327 0 50-257 0	MIYABAYI.D H MIYABAYI.D H MODENOB.L MOEOLING.J B MOFFETT.T	8007310028 8007140092 8007100131* 8007100328 8007110343	XPORTL I NUREO 50-327 PR 50-320
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, M I	9007230081 8007280277 8007280282 8007280564 8007230810	50-54 F 40-4622 70-1143 40-9681 50-255 G	HILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007230431 8007310208 8007220460 8007220532 8007230494	50-328	MOFFITT.AE MONDOISSE.R M MONDOISSE.R M MONDOISSE.R M MONDOISSE.R M	9007150004 9007100254 9007100257* 9007100254 9007100257*	PR PR PR PR
MILLER.M I MILLER.D S MILLER.D S MILLER.D.S MILLER.D B	8007230810 8007300122 8007300127* 8007300122 8007300127*	50-255	MILLB,L M MILLB,L M MILLB,L M	8007230499 8007230467 8007230477 8007230480 8007230486	50-327 F 50-327 P 50-327 P 50-327 P 50-328 8	MONTAGUE, P MONTAGUE, P MONTI, U A MOODY, D E MOODY, D E	9007220326 8007300323 8007150667 8007180090 8007010057	FOIA 50-10 50-3 50-307 50-29
MILLEAP,W J MILLE,L M MILLE,L M MILLE,L M	8007030370* 8007070268 8007110039* 8007070042 8007020347	70-1201 50-259 P 50-327 G 40-1341 50-327 G	MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007230505 8007230511 8007230528 8007230533 8007230587	50-390 8 50-327 A 50-518 5 50-327 P 50-390 8	С 5.4900М Э д.4900М Э д.4900М Н С.4000М Э д.4000М	8007280134* 8007170582 8007180144 8007140030 8007280458	50-320 50-29 50-29 PRM 50-309
HILLS, L M HILLS, L M HILLS, L M HILLS, L M HILLS, L, M	B007020499 B007280468* B007020619 B007160571 B007170664	50-259	MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007300572 8007230408 8007230575 8007290479 8007280460	50-259 G 50-327 P 50-327 F 50-327 G 50-438 S	MOODY,D E MOODY,D E MOODY,D E MOODY,D E MOON,B T	8007210506 8007140403 8007070233 8007250273 8007280425*	50-29 50-309' 50-29 50-29 50-270
MILLE,L M MILLE,L M. MILLE,L M MILLE,L M MILLE,L M	8004250275 8007140240 8007010424 8007250585 8007240279*	50-518 8 PRM 50-438 A 40-1341 50-518 Q	HILLE,L M MILLE,L M MILLE,L M MILLE,L M MILLE,L M	8007290724 8007280548 8007290632 8007290725 8007290749	50-327 P 50-327 F 50-328 8 50-438 8 50-438 6	MOON, C W MOON, C W MOON, C W MOON, C W	8007240010 8007300397 8007300404 8007300423 8007300424	50-466 50-466 50-466 50-466 50-466
MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007010327 8007010338 8007010386 8007020543 8007020544	50-327 P 50-518 A 50-328 A 50-328 B 50-328 B	MILLE, L M MILLE, L M MILLE, L M MILLE, L M MILLE, L M	8007270813 8007280498 8007280623 8007270679 8007270757	50-390 Q 50-327 Q 50-327 P 50-327 P 50-327 P	MOGN.C W MOGNEY.R R MOGNE,V A MOGNE,V A MOGNE,D E	8007310312 8007150157 8007070053* 8007070055* 8007070005*	50-466 REGGD 50-514 50-514 70-2478
MILLS, L M MILLS, L M MILLS, L M	8007020627 8007180523 8007080220 8007100252 8007080286	50-327	MILLS, L. M. MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8007300434 8007310376 8007310412 8007310323 8007310411	50-327 F 50-327 P 50-327 P 50-327 P 50-327 P	MOORE, D E MOORE, O W MOORE, O W MOORE, J B MOORE, O C	8007100075* 8007020546 8007020947* 8007210287 8007080075	50-261 50-334 50-334 70-114 50-302
MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007080331 8007100205 8007100233 8007080253 8007080380	50-327 Q 50-438 Q 50-438 B 50-390 A 50-259 P	MILLB.L M MINARICK, J W MINECK, D. L MINECK, D L MINECK, D L	B007310416 8007230552* 8007230233 8007030212 8007030224	50-327 P 50-460 A 50-331 P 50-331 8 50-331 8	MOGRE, O C MOGRE, N MOGRE, O C MOGRE, J E MOGRE, J E	B007150484 8007220107 8007150385 8007150711 8007170354	50-302 XPORTUI 50-302 50-247 50-155
MILLS, L. M. MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8007090388 8007090222 8007100169 8007220236 8007090249	50-390 V 50-390 8 50-438 Q 50-518 Q 50-327 B	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8007030238 8007110411 8007110471 8007220599 8007230484*	50-331 8 50-331 8 50-331 8 50-331 8 50-331 P	MOGRE, V A MOROAN, H.E MORIANTY, J M MORIANTY, J M MORIANTY, J M	8007290525 8007280218 8007090270* 8007090275* 8007010459	50-352 50-395
MILLB, L M MILLB, L. M MILLB, L. M. MILLB, L. K MILLB, L. K	8007100207 8007110320 8007270927 8007140347 8007140422	50-438 B 50-518 B PR 50-518 B 50-390 B	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8007220497 8007220367 8007220394 8007230482 8007230464	50-331 8 50-331 R 50-331 P 50-331 P 50-331 S	MORIFATALIA MORINJO P MORRIGON, J R MORRIEL P MORRILL, P J	9007010357 8007230598 8007210047* 8007010567 8007170088*	40-830

AU THOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY
MORRIEL, P J MORRIEGN, U M MORRIES, R H MORROW, D MORROW, D	8007300525* 8007300005 8007310377 8007070120 8007070115	50-344 Q ORQ 50-275 A 40-8502 40-8380	MURPHY, C E MURPHY, C E MURPHY, R MURPHY, C MURPHY, C	8007290344 8007290409 8007070178 8007300589 8007100412	50-438 Q 50-424 Q PR 50-518 Q 50-400 Q	NAPUDA, G NAPUDA, G NAPUDA, G NARBUT, P NARROW, L	8007180101* 8007170692* 8007230137* 8007180018* 8007170599*	50-293 G 50-219 G 50-289 G 50-204 G 50-363 G
MORROW, D MORROW, D MORROW, D MORROW, D MORROW, D	8007020083 8007020458 8007020064 8007030219 8007210066	40-8497 40-8721 40-8497 40-8380 40-8502	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8007100417 8007270422 8007310240 8007070097 8007100356	50-413	NARROW, L NASH. D NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8007170288* 8007250599 8007160627 8007010428 8007010411	50-322 G 50-482 M 50-399 C 50-295 P 50-454 A
MORROUL D MORROUL D MORROUL D MORSEL W T MORSEL A K	8007210063 8007280054 8007280303 8007140407 8007280657*	40-8497 40-8502 40-8502 50-443	MURPHY, C E MURPHY, C E MURPHY, P K MURPHY, W P MURPHY, W P	8007110034 8007110515 8007070314 8007010317 8007010391	50-327 @ 50-424 @ 50-255 @ 50-271 8 50-271 8	NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8007010211 8007020408 8007020431 8007080279 8007140359	50-295 P 50-454 K 50-454 B 50-454 K 50-454 K
MORSE, A K MORSE, A MORTON, K V MORTON, K V MORTON, K V	8007310101 8007280656 8007210267* 8007010627* 8007020009*	50-409 Q 50-409 Q CONTRACT CONTRACT CONTRACT	HURPHY, W P HURPHY, W P HURPHY, M J E B THYRNUM E M, YKYRNUM J	8007010405* 8007070260 8007080280* 8007240283 8007080426*	50-271 8 50-271 8 50-272 8 NUREQ 50-272 9	NAUGHTON, W F	6007150474 8007290678 8007140320 8007220540 8007280605	50-295 P 50-454 K 50-454 K 50-454 K 50-295 P
MORTON: K V	8007020025* 8007020553* 8007010619* 8007210259* 8007300598*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, M J	8007160860 8007100202* 8007180189 8007310495* 8007180517*	50-414 Q 50-272 8 50-553 Q 50-270 Q 50-272 8	NAUGHTON,W F NAVARRO,C C NEIGHBORS,D NEILL,R H NEILEON,R M	8007280670 8007180169* 8007310517 8007030045 8007230655*	50-454 8 COMMISSION 50-261 P PR FOIA
MORTON, X V MORTON, X V MOSELEY, N C MOSELEY, N C	8007310010* B007250578* B007230194 B007150778* B007110555	CONTRACT CONTRACT RES ORO 50-315 P	MORBHA' Q MORBHA' C MORBHA' C MORBHA' Q MORBHA' Q MORBHA' M	8007150628* 8007150679* 8007240265 8007280126 8007170448*	50-272 8 50-272 8 50-518 G 50-321 G 50-311 8	NEILGON, L E NEISCER, J H NELGON, P R NELGON, P R NELGON, P R	8004010434 8007230700* 8007170322* 8007170326* 8007170266*	MISC 50-373 Q 70-1869 FOIA 50-219 Q
MOSELEY, N C MOSELEY, N C MOSES, V R MOSZYNSKI, J R MOWRY, W R.	8007250051 8007250480 8007100070 8007150066 8007020084	50-272 S 50-266 P PR RES XPORTLIC	HIGHANN HIGHANN HIGHANN HIGHANN HIGHANN	8007220382* 8007220627* 8007210507* 8007230488 8007230489*	50-272	NELSON, PR NELSON, JD NELSON, JD NELSON, JD NELSON, JD	8007170276* 8007020176 8007210183 8007210177 8007230135	50-217 G MISC 40-8452 40-8452 40-8452
HROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA E J MROCZKA, E J	8007010445 8007070318 8007070361 8007100157 8007100167	50-336 S 50-336 S 50-336 S 50-245 S 50-245 S	MURPHY, C E HURPHY, M HURPHY, P HURPHY, P HURPHY, P HURPHY, P HURPHY, P	8007230810 8007230810 8007280632* 8007310212 8007290711*	50-255	NELSON, O NELSON, C NELSON, R NELSON, R NELSON, J D	8007080082 8007110525 8007070398 8007230328* 8007230725#	COMMISSION 50-309 P REGOD 50-305 Q 40-8452
MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8007110464 8007180408 8007160676 8007210374 8007180298	50-245 8 50-245 R 50-245 R 50-336 R 50-245 8	MURPHY, M J MURPHY, M J MURRAY, J P MURRAY, T D MURRAY, T. D	8007290727* 8007290844* 8007300390* 8007010434 8007030260	50-272 8 50-272 8 50-266 0 50-346 8 50-346 8	NELBON, C C NELBON, C C NEUMAN, R F NEUMANN, M R NEUMANN, M R	8007100161 8007290007 8004300355 8007020702 8007030002	50-335 P 50-70 P 50-135 H 40-8380 40-8380
MROCZKA, E J MROCZKA, E J MUCHNICKI, E D MUCHNICKI, E D MUDREY, M O	8007250409 8007290697 8006110406 8007100246 8007140402	50-336 S 50-245 G PR PR PR	HURRAY, T D HURRAY, T, D HURRAY, T D HURRAY, T D MURRAY, T D	8007150609 8007110427 8007110391 8007110407 8007110418	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8	NEUMANN, M R NEUMANN, M R NEUMANN, M R NEUMANN, M R NEUMANN, M R	8007210146 8007220035 8007240100 8007220022 8007160390	40-8380 40-8380 40-8380 40-8380 40-8380
MUELLER, E W MUER, H B MUER, H B MUER, H B MUKSIERJEE, H	8007010133* 8006300368 8007310490* 8007310489 8007020135*	State Prog 50-356 A YPORTLIC XPORTLIC WASTE MOT	MURRAY, T D MURRAY, M J MURRAY, M J MURRAY, T D MURRAY, M. J	8007110440 8007140432 8007140437 * 8007140318 8007150056	50-344 S PR PR 50-346 R 50-367 Q	Neumann, m r Neumerry, 8 Neuman, m k Neuman, J r Neuman, J r	8007210224 8007110485* 8007010091* 8007020471 8007020471	40-8380 50-320 P 40-2674 50-466 0 50-466 0
MULLER, D R MULLER, H MULLER, L L MULLER, R E MULLER, D R	8007250063 8007150040* 8007270882 8007160802 8007240066	50-320 H XPORTLIC XPORTLIC XPORTLIC 50-445 A	MURRAY, T. D MURRAY, T. D MURRAY, T. D MURRAY, T. D. MURRAY, T. D	8007150560 8007240126 8007170441 8007220375 8007220458	50-346 B 50-346 B 50-346 B 50-346 B 50-346 B	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8007080017* 8007080017* 8007090189 8007090189 8007160570	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q
MUNTE MUNRO, J J HUNRO, J J MUNRO, L H MUNTINO, L H HUNTZINO, L H	8007180470* 8007030375 8007100373 8007020270 8007020262	71-9136 71-9039 71-9053 RECY SECY	MURRAY, M J MURRAY, T. D MURRAY, T. D MURRAY, T. D MURRAY, T. D	8007250442 8007280576 8007280571 8007280630 8007280583	27-39 50-346	R U MAMUBA NEWAMI J R NEWAMI J R NEWAMI J R NEWAMI J R	8007160570 8007160645 8007160645 8007160639 8007160639	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
MURDOCK, L. T MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E	8007210170* 8007160869* 8007100384* 8007180527* 8007100423*	40-4492 50-416 G 50-324 G 50-424 G 50-413 G	MURRAY, T. D MUBG. L. A MUBGLF, D. MYERS. H MYERS. F B	8007280609 8007100349 8007010583* 8007230565* 8007010029*	50-346 8 71-387 50-282 P 50-320 U QA999	R C 'NAMMAN B C 'NAMMAN B C 'NAMMAN B C 'NAMMAN	8007180432 8007180432 8007250424 8007250424 8007290082	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
	:	50-335	MYERS, I L MYNATT, F R MYRABO, A L NAIDU, K R	8007180022* 8007140307 8007150614* 8007110479* 8007170635*	8tate Prog RE8 50-263 R 50-358 Q 50-327 Q	NEWAMN.JR NEWAMN.JR NEWAMN.JR NEWAMN.JR NEWAMN.JR	8007270082 8007300413 8007300449 8007300413 8007300449	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
				8007310225 8007290460 8007290467* 8007110326* 8007080390*	NUREQ XPORTLIC XPORTLIC 50-305 8 50-305 8	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R NEXON, H H	8007310094 8007310308 8007310094 8007310308 8007100130	50-466 0 50-466 0 50-466 0 50-466 0 PRM
				8007160474* 8007160502* 8007160510* 8007280674* 8007280685*	50-305 8 50-305 8 50-305 8 50-305 8 50-305 8	NECHOLBON, T J NICHOLBON, T J NIELBEN, A D NIELBEN, O A	8007070121 8007170179 8007310428 8007140014 8007180337	PR PR 70-2860 50-275 H 50-409 D

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEON
Nijhawan, S Nijhawan, S Nilbon, R Nilbon, R Nimitz- R	8007170460 8007140642 7909210176 8007070402 8007150081	RES RES REGOD PR 50-284 S	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007170651 8007170667 8007180119 8007210004 8007210035	50-289 P 50-312 P 50-277 P 50-249 P 50-346 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007140490 8007020170 8007020171 8007020173 8007020178	50~321 50~395 50~395 50~416 50~321
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007010503* 8007030274* 8007030282* 8007030279* 8007110426*	50-366 6 50-366 8 50-366 8 50-366 8 50-321 6	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007210110 8007210115 8007210573 8007210581 8007210589	50-302 P 50-346 P 50-346 S 50-302 P 50-313 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020179 8007020180 8007020187 8007020172 8007020200	50-302 50-348 50-261 50-257 50-280
NIX,R T NIX,R T NIX,R T NIX,R T NIX,R T	8007150544* 8007150685* 8007150508* 8007150674* 8007170387*	50-321 6 50-366 5 50-321 5 50-321 8 50-321 8	NOVAK, T M NOVAK, T M NOVAK, F M NOVAK, T M NOVAK, T M	8007240244 8007170241 8007180506 8007170558 8007210023	50-312 P 50-247 P 50-321 P 50-331 P 50-313 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	G007020204 8007020231 8007150448* G007210414 8007210419	50-267 50-250 50-260 50-437 50-348
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007170408* 8007170410* 8007170463* 8007170497* 8007170448*	50-321 S 50-366 S 50-321 S 50-321 B 50-366 S	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007210026 8007240085 8007240288 8007240304 8007240311	50-259 P 50-246 V 50-335 P 50-344 P 50-368 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P	6007210422 8007210437 8007210449 8007210458 8007210452	50-241 50-489 50-249 50-250 50-302
NIX,R T NIX,R.T NIX,R T NIX,R.T. NIX,R T	8007280512* 8007240128* 8007240167* 8007250412* 8007280449*	50-366 8 50-366 9 50-366 9 50-366 9 50-321 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007240330 8007240335 8007240338 8007240346 8007240350	50-266 P 50-265 P 50-335 P 50-309 P 50-336 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007210458 8007210471 8007210472 8007210477 8007210488	50-424 50-373 50-373 50-273 50-280 50-327
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007280526* 8007280446* 8007280588* 8007280640* 8007280690*	50-346 8 50-321 5 50-321 8 50-321 8 50-321 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAKOVICH, D	8007240380 8007240389 8007240399 8007280169 8007280363	50-317 P 50-282 P 50-70 P 50-338 P XPORTLIC	G'REILLY, J P G'REILLY, J P G'REILLY, J P G'REILLY, J P G'REILLY, J P	8007010175 8007010179 8007010188 8007010206 8007010213	50~437 50~261 50~488 50~250 50~269
NIXON, W A NIXON, W A NIXON, W A. NIXON, W A NOCELLA, B, J.	8007220220* 8007210480 8007310271 8007310320 8007140248	70-195 40-2061 40-2061 40-8027 FOIA	NOVAK, T K NOVAK, T K NOVAK, T K NOVAK, T K NOVAK, T K	8007210020 8007280342 8007280345 8007280350 8007280353	50-309 P 50-277 P 50-289 P 50-313 P 50-346 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007010220 8007010225 8007010239 8007010242 8007010248	50-321 50-259 50-280 50-395 50-395
NODNAN, V. NORDERHAUO, L. R NORDERHAUO, L. R NORDERHAUO, L. R NORDERHAUO, L. R	8004240210 8007140696 8007010177 8007240032 8007210474	I&E XPORTLIC 50-344 G 70-1257 50-27 G	NOVAK, T K NOVAK, T M NOVAK, T K NOVAK, T K	8007230651 8007230656 8007230708 8007250278 8007280117	50-312 P 50-321 P 50-269 P 50-302 P 50-270 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007010250 8007010251 8007010253 8007310223* 8007220017	50-414 50-302 50-349 50-389 90-395
NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORELIUB, C E	8007240495 8007230154 8007240361 8007310523 8007210125*	70-25 50-312	NOVAK,T M NOVAK,T M NOVAK,T M NOVARRO,J P NOVARRO,J P	8007300553 8007310336 8007310550 8007210040* 8007070243	50-278 P 50-321 P 50-346 P 50-322 Q 50-322 K	G'REILLY, J P G'REILLY, J P G'REILLY, J P G'REILLY, J P	8007220020 8007220026 8007220027 8007220040 8007220043	50-332 50-437 50-259 50-348 50-261
NORELIUB, C E NORRHOLM, L J NORTH, H B NORTH, H NORTON, B	8007280435* 8007310055* 8007110184* 8007230297* 8007070123	50-346	NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVALNOM NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARR	8007140390 8007150655 8007230458 8007110127 8007110118	50-322 B 50-322 A 50-322 A 50-244 F 50-219 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007220048 8007220054 8007220062 8007220066 8007220072	50-269 50-488 50-250 50-280 50-321
NORTON, B NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8007180405 8007210076* 8007010012 8007140560* 8007210073	50-275 G BEGY XPORTLIC BECY XPORTLIC	NOWICKI, B J NOWICKI, B J NUMENT, E L NUMN, D E NURNBERGER, C E	8007100214 8007100217 8007010443 8007210473 8007140571	50-244 F 50-204 Q 40-2257 50-361 B PR	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007220076 8007220078 8007220083 8007160218 8007160223	50-302 50-416 50-395 50-348 50-261
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	9007170204 9007170223 9007170235 9007170251* 9007210096	XPORTLIC XPORTLIC XPORTLIC BECY XPORTLIC	NYGAARD, Q NYGAARD, G R NYGRON, J G'CONNOR, L A G'CONNOR, L A	8007280659* 8007310101 8007140606 8007140355 8007150622	50-409 G 50-409 O 40-8502 50-213 1 50-245 I	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007160230 8007160255 8007160262 9007160265 8007160274	50~488 50~267 50~302 50~250 50~424
NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V	8007010007 8007010017 8007020240 8007100146 8007170072	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	O'DONNELL, A J O'HANLON, J P O'HEAR, J W O'NEILL, T V O'NEILL, J	8007140045 8007280546 8007220573* 8007270056* 8007310400	PR 50-313 8 50-414 A M180 50-155 0	D'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007140278 8007140281 8007140287 8007140307 8007140315	50-416 50-395 50-327 50-280 50-437
NDBENZO, L. V NOBENZO, L. V NOBENZO, L. V NDSENZO, L. V, NOTLEY, D. P	8007170003 8007240440 8007280547 8007280559 8007140302*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC FOIA	O'REILLY, J P O'REILLY, J P O'REILLY, L A O'REILLY, J P O'REILLY, J P	8007010134* 8007150038* 8007310339* 8007240084 8007240089	50-293 P 70-1113 50-295 Q 50-437 Q 50-259 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007140289 8007140294 8007140299 8007140301 8007140306	50-324 50-321 50-416 50-518 50-259
NOVAK, T. M NOVAK, T NOVAK, T M NOVAK, T NOVAK, T M	8007250702 8007020314 8007020451 8007100155 8007100455	50-344 P 80-269 P 50-271 H 50-277 P 50-309 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007240108 8007240113 9007240122 8007240139 8007240202	50-348	O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J P	800725033B 8007250339 8007250344 8007250368 8007250372	50-364 50-400 50-369 50-487 50-7
NOVAK, T. M, NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8007030371 8007020467 8007100006 8007110512 8007110541	50-313 P 90-302 P 50-346 P MIBC 50-334 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007240204 8007240213 8007240218 8007240220 8007240222	50-250 0 50-321 0 50-416 0 50-375 0 50-395 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007250375 8007250377 8007250378 8007250380 8007250381	9'
NOVAK, T. M. NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8007020711 8007170040 8007170444 8007180341 8007210088	50-259 P 50-309 P 50-309 F 50-331 P 50-315 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	8007240230 8007140474 8007140479 8007140484 8007140489	50-280 Q 50-257 Q 50-518 Q 50-416 Q 50-324 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007250384 8007250389 8007310337 8007020721 8007020723	54 54 51 71 71

1

AUFHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	TOBLEVB CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	9007020725 9007020729 9007020732 9007020733 9007020735	70-1201 70-143 70-1113 70-1319 70-1311	DLAGCDAGA,M T DLDBERO, T DLIU,W E DLIU,W DLIVADDVI,J R	8007310241 8007010233* 8007310004 8007160773 8007280125	NUREO FOIA NUREO MISC 71-192	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8007030022 8007280320 8007220211 8007220242* 8007070187	70-1151 70-1319 70-135 70-135 70-1113
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	800/020736 8007020737 8007020741 8007020743 8007020745	50-321 0 50-332 0 50-395 0 50-302 0 50-261 0	OLLER, R E OLLER, R E OLLER, R E OLLER, R E OLMSTEAD, N J	8007140157* 8007250189* 8007210539* 8007270862* 8007230536	QA999 QA999 QA999 QA999 GA979 50-275 G	PAGE,R O PAGE,R O PAGE,R O PAGE,R O PAGE,R O	8007240099 8007230056 8007240282 8007240106 8007240119	70-1359 70-2375 70-1738 70-1201 70-27
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020748 8007020751 8007020752 8007020757 8007020751	50-395 G 50-348 G 50-250 G 50-280 G 50-289 G	OLMSTEAD.W J OLSEN.A F OLSEN.A F OLSENAN.L II OLSIMAN.L N	8007310461 8007010006 8007010273 8007110557 8007170317	50-275 G 70-824 70-824 50-247 P 50-245 P	Page,r G Palchesko,c H Palusamy, b G Panxaskie,p J Pankaskie,p J	8007290072 8007250343 8007020644* 8007010082* 8007010187*	70-143 40-2561 TOPREP FOIA FOIA
O'REILLY.J P O'REILLY.J P O'REILLY.J P O'REILLY.J P	8007020763 8007070010 8007020374 8007020380 8007020381	50-267	OLSHAN, L R OLSHANTH, L N OLSON, J F OLSON, A R OLSON, A R	8007300092 8007310514 8007100208 8007020349 8007140617	50-284 P 50-286 P 50-282 0 50-317 P NUREO	PANKASKIE,P J PANKASKIE,P J PAPAY,L T PAPAY,L T PAPAY,L T	8007010191* 8007010238* 8007020149* 8007240088 8007170565*	FDIA FOIA 50-361 Q 50-361 Q 50-206 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020384 8007020385 8007020391 8007020409 8007020434	50-375	OLBON.J F OLBON.J F OLBON.J F OPLINGER.O O OPREA.O W	8007140011 8007230583 8007250422 7704200225 8007230718	PR PR 50-282 0 XPORTLIC 50-498 0	PAPAY,L T PAPAY,L T PAPAY,L T PAPERIELLO,C J PAPERIELLO,C	8007070330 8007230287* 8007230579 8004240258 8004240278	50-361 8 50-206 0 50-361 8 I&E I&E
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020440 8007020445 8007020450 8007020454 800702045 <i>9</i>	50-261 0 50-489 0 50-321 0 50-250 0 50-269 0	DPREA, O W DPREA, O W DPREA, O W DPREA, O W DPREA, O W	8007170203 8007020618 8007090246 8007090365 8007110337	50-498 G 50-499 S 50-499 G 50-498 B 50-498 S	Рарраз, Н Раррав, Н Раррав, Н Раррав, Н Раррав, Н	8007140597 8007010150 8007010157 8007020278 8007020334	ORO 50-10 0 DRO : 50-10 0 ORO
O'REILLY.J P O'REILLY.J P O'REILLY.J P O'REILLY.J P	8007270375 8007300576 8007310344 8007160781 8007160784	50-259 0 50-321 0 50-259 0 50-395 0 50-395 0	OPRCA.O W OPRCA.O W OPRCA.O W OPRCA.O W OPRCA.O W	8007150445 8007160604 8007210511 8007220578 8007230512	50-498	Pappab, H Pappab, H Pappab, H Pappab, H Pappab, H	8007150770 8007220241 8007140421 8007290104 8007030052	ORO ORO ORO ORO 50-10 Q
O'REILLY, J P G'REILLY, J P O'REILLY, J P O'REILLY, J P	8007160787 8007160791 8007160794 8007160800 8007170070	50-416 0 50-348 0 50-302 0 50-261 0 50-259 0	OPREA.O W OPREA.O W OPREA.O W OPREA.O W OPREA.O W	9007230525 0007230476 9007230540 9007300340 8007300382	50-498 8 50-498 8 50-498 5 50-466 H 50-498 6	Pappas, H Pappas, H Pappas, H Pappas, H Parimi, 8 R	8007030054 8007240065 8007170343 8007140566 8007220234*	ORO ORO 50-10 G 50-305 P
O'REILLY, J P O'REILLY, J P O'REILLY, J P	6007170076 6007170104 6007170107 6007170115 6007170117	50-409	ORLOBKY, P M ORTOSKY, P M ORTLOFF, O D ORVIE, H J ORANN, E W	800/280654 8007290694 8007280047 8007180072 8007080055	50-57 R 50-57 R 40-8102 NUREO 50-347 O	PARIS,O H PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007220004 8004050317 8007100419* 8007090402 8007140397	50-320 0 50-369 5 50-413 0 PR 50-269 P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170126 8007170131 8007170134 8007170137 8007170141	50-332	OBANN,E W OBT.F OBTENDORF,D L OBTER,J OSTER,J	8007080055 8007160662* 8007280677* 8007150616 8007290709	50-367	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007010065 8007140083 8007030184 8007020537 8007100034	50-269 Q NUREO FRM 50-413 S 50-369 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170144 6007170148 9007170147 8007170182 9007170184	70-1201 70-824 70-27 70-1113 70-143	OSTON. B O OSTRANDER. F U OSTRANDER. F U OSTRANDER. F U OSTRANDER. F U	8007100198* 8007300357 8007300377* 8007300481 8007300490*	PR 50-344	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007100139 8007180349 8007150015 8007010205 8007010309	50-270 Q 50-270 Q 50-269 Q 50-269 F 50-369 F
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170159 8007170164 8007170166 8007170173 8007170177	50-160	OSTRANDER, F U OSTRANDER, F U OSTRANDER, F U OTT, U, R OTTOSON, H L	8007300494* 8007300500* 8007300506* 8007090017* 8007290883	50-344	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007010340 8007180533 8007020575 8007220192 8007070319	50-269 P 50-269 Q 50-269 P 50-269 B
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170181 8007170185 8007170186 8007230179 8007230206	50-124 Q 50-127 Q 50-406 Q 50-437 Q 50-348 Q	OTTOBONIN L OTTOBONIN L OTTOBONIN L OTTOBONIN L OTTOBONIN L	8007290434 8007280072 8007010533 8007100242 8007250358	50-206 Q 50-206 Q 50-206 B 50-206 R 50-206 Q	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007250578 8007280069 8007080223 8007090271 8007220245	50-369 Q 50-269 Q 50-269 P 50-269 P 50-269 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	B007230210 B007230213 B007230215	50-302 0 50-416 0 50-375 0 50-375 0 50-261 0	OTTOBON.# L OTTOBON.# L OTTOBON.# L OWEN.# # OWEN.# #	8007080403 8007280371 8007280376 8007020648 8007110341	50-206 9 50-206 9 50-206 9 PR TOPREP	PARKER.W D PARKER.W D PARKER.W D PARKER.W D PARKER.W D	8007080201 8007080345 8007110360 8007240357 8007110294	50-270 B 50-369 A 50-269 S 50-369 Q 50-269 P
		50-488 Q 50-269 Q 50-250 Q 50-321 Q	OMSLEY, O F DHSLEY, O, F DHZARSKI P C PACE, P L PACHAL, W, F	8007110215 0007290733 8007280002 8007220421* 8007280372	TOPREP TOPREP RC6 50-250 8 XPORTLIC	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007160657 8007210114 8007210261 8007240469 8007250166	50-369 8 50-369 9 50-413 9 50-369 9 50-269 9
		G G	PAGAND.F Q Page, R Q	8007310193 8007010056 8007010281* 8007010074 8007010189	50-338 F 70-1062 70-1062 70-2885 70-2838	PARKER,W D PARKER,W D PARKER,W D PARKER,W D PARKER,W D	8007110309 8007280416 8007180321 8007180417 8007290267	50-369 A 50-270 0 50-270 5 50-287 B 50-270 Q
				8007010195* 8007020429 8007020230 9007100117 9007020341	70-2838 70-2607 70-2910 40-8027 70-687	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W. O	8007150575 8007160514 8007210417 8007210459 8007210509	50-267 F 50-413 8 50-267 8 50-267 8 50-287 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU I HOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007220477 8007210385 8007280437 8007210425 8007220563	50~249 P 50~349 A 50~249 P 50~270 P 50~249 S	PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R	80070B0178* 80072B0655* 8007090336* 8007150660* 8007150693*	50-368 S 50-368 S 50-368 S 50-368 S 50-368 S	PETERSON, M R	8007140598 8007140596 8007140603 8007150073 8007150078	YPORTLIC YPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8007310491 8007220424 8007220534 8007220561 8007280501	50-270	PENDERORAFT, R PENTZ, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8007210382* 8007280717* 8007020050 8007210272* 8007230281*	50-368 R CONTRACT 50-295 Q 50-373 Q 50-373 Q	PETERSON, M R	8007170534* 8007110218 9007110226 8007110271 8007210083*	SECY XPORTLIC XPORTLIC XPORTLIC SECY
PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8007220365 8007300459 8007280427 8007280544 8007290635	50-369 A 50-369 A 50-270 P 50-269 P 50-287 S	PEOPLES, D L	8007020388 8007110206* 8007020074 8007240298* 8007100004	PR 50-10 Q 50-249 Q 50-249 Q 50-10 Q	PETERSON, M R PETERSON, M R PETERSON, N R PETERSON, M R PETERSON, M R	8007110241 8007140711 8007150001 8007150003 8007150008	APORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKER, W O PARMENTER, F PARRIS, H O	8007290824 8007300355 8007310379 8007160547 8007240455	50-270 8 50-369 8 50-269 P 50-445 M 50-259 8	PEOPLES, D L	8007100343 8007140235 8007280688* 8007010347 8007230187	PRM PRM 50-373 Q 50-10 F PR	PETERSON, M R	8007150012 8007150062 8007150063 8007140577 8007140579	XPORTLIC YPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARRIS,H Q PARROTT,M W PARROTT,M W PARRY,S J S PAREDNS,R	8007270651 8007280170* 8007300018 8007100334* 8007110506	50-327 P COMMIBBION PR FOIA 50-320 P	PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8007250641 8007250650 8007300467 8007310533* 8007150529	50-10 0 50-10 0 PR 50-373 0 50-373 A	PETERSON, M R	8007140584 8007220114* 8007240042 8007170077 8007170080	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARTLOW, J Q PARTLOW, J Q PARTLOW, J Q, PARTLOW, J Q, PARTLOW, J Q,	8007100081* 8007010221 8007170632 8007210109 8007250673	70-143 70-143 70-135 70-364 70-1113	PEOPLES, D L	8007240351* 8007250638 8007280074 8007310357 8007250467	50-456 Q 50-10 Q 50-254 Q 50-254 Q 50-373 Q	PETERSON, M R	8007240046 8007240052 8007280517 8007310199 8007240373	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARTLOW, J O PARTLOW, J O PABBMAN, N A PASTERNAK, R J, PASTERNAK, R J	8007250053 8007230712 8007310430* 8007010164 8007180128	70-27 70-364 50-286 8 50-333 0 50-333 0	PEOPLEB, D.L. PERANICH, M. W. PERLMAN, J. PERLMAN, J. PERLMAN, J.	8007220518 8007270030 8007070418* 8007100112* 8007300587*	50-373 A GA999 CONTRACT CONTRACT 90-390 A	PETERBON, M R	8007240405 8007240418 8007240421 8007250714 8007280525	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J	9007010486 9007010511 8007010491 9007250669 8007090192	50-333 E 50-333 E 50-333 E 50-333 G 50-333 R	PERLMAN, J PERLMAN, J PERNY, C D PERRIGO, L D PERROTTI, D J	8007280236* 8007300590* 8007010125* 8007290246 8007110276*	CONTRACT CONTRACT 70-143 RES 50-321 G	PETERSON: M R	8007280535 8007280569 8007240362 8007240370 8007240379	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J	8007210526 8007140368 8007140383 8007250290 8007150707	50-333	PERROTTI.D J PERRY.J C PERRY.J C PERRY.J C PERSON.L	8007210093* 8007080420* 8007150826* 8007280553* 8007230576	70-1151 50-344 8 50-344 8 50-344 8 40-6622	PETERSON, M R	9007240410 8007250563 9007280287 8007280293 8007230719	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Pasternak, R J Pasternak, R J Pasternak, R, J Pasternak, R J Pate, R J	8007310474 8007280515 8007280610 8007280662 8007020191*	50-333 Q 50-333 & 50-333 8 50-333 8 50-361 Q	PETERSON, R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8007070099 8007010170 8007020020 8007020057 8007020238	40-1162 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETERSON, M R	8007230723 8007250041 8007250030 8007250033 8007280117	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PATELR J PATEL.B R PATON.W D PATON.W D. PATON.W D	8007300318* 8007220334* 8007010333 8007090055 8007150697	50-361 Q TOPREP 50-329 Q 50-329 Q 50-329 H	PETERSON, M R	8007020344 8007020348 8007020351 8007030236 8007010014	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETRICK, N A	8005070053 8007010142 8007100441 8007020378 8007070325	50-482 8 50-482 0 50-482 0 50-482 8
PATON, W. D PATON, W. D PATON, W. D PATON, W. D PATON, W. D	8007170226 8007170232 8007170369 8007170385 8007180242	50-327 0 50-327 0 50-556 0 50-327 0 50-327 0	PETERBON, M R PETERBON, M R, PETERBON, M R PETERBON, M R PETERBON, M R	8007020274 8007020283 8007020425 8007020289 8007020277	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETRICK.N A PETRICK.N A PETRICK.N A PFAFF.8 J PHILBRICK.8 S	8007310302* 8007270590 8007300511 8007230020 8007180609	50-482 S 50-482 B 50-482 A 40-6659 50-70 0
PATTERBON, J D PATTERBON, J D PATTERBON, J D PATTERBON, J P PATTERBON, J P	8007020406 8007020413* 8007100355 8007110818* 8007140682*	PR PR PRM 70-925 70-1193	PETERSON, M R PETERSON, A F PETERSON, D S PETERSON, M R, PETERSON, M R	8007070038 8007070279 8007150157 8007020373 8007030360	APORTLIC 50-250 G REOGD XPORTLIC XPORTLIC	PHILLIPS, H S PHILLIPS, L PHILLIPS, B L PHILLIPS, H S PHILLIPS, E	8007010212* 8007100075 8007080302* 8007230292* 8007020724	50-498 Q TOPREP 50-298 8 50-498 Q TOPREP
PATTERBON, J P PATTON, R M PATTON, R. M. PATTON, R M PATTON, R M PATTON, R M	8007270875* 8007150075 8007220102* 8007150103 8007220073	90-254 Q PR PR PR PR	PETERSON, M R PETERSON, M R, PETERSON, M R, PETERSON, M R PETERSON, M R	8007070007 8007070025 8007070047 8007070111 8007070425	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS,L E PHILLIPS, J PHILPOTT, F T PHILPOTT, F T PHILPOTT, F T	8007160814* 8007230508 8007070323* 8007080207* 8007110362*	REGOD 50-275 0 50-267 8 50-270 8 50-267 5
PAULBON, W A PAULBON, W A PAXTON, H C PECK, C, C PECK, H.	8007140524 8007310519 8007290789 8007100003* 8007020457	50-219 P 50-219 P 50-344 Q 50-320 Q PR	PETERSON, M R	8007090109 8007100027 8007110252 8007100341 8007110029	XFORTLIC XFORTLIC XFORTLIC XFORTLIC XFORTLIC	PHILPOTT,F T PHILPOTT,F T PHILPOTT,F T PHILPOTT,F T PHILPOTT,F T	8007180325* 8007210421* 8007210470* 8007210617* 8007220427*	50-270 6 50-269 8 50-269 8 50-287 8 50-269 8
PEDERSEN, K PEDERSEN, K PEERY, W W. PEERY, W W PEERY, W W	8007310247* 8007310250* 8007010304* 8007010291* 8007290401*	FQIA FQIA 50-219 Q 50-334 Q 50-259 Q	PETERSON, M R PETERSON, M R PETCRSON, M R PETERSON, M R PETERSON, M R	8007110213 8007110491 8007140283 8007140288* 8007140567	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILPOTT.F T PIACBEK.B E PIACBEK.B E PICKARD.W C PIELAGE.H W	9007290640# 8007250012# 8007240258# 8007070052 8007240375	50-287 8 40-4337 40-4337 CONTRACT PR
PELTIER.I A. PENDERORAFT.R PENDERORAFT.R PENDERORAFT.R PENDERORAFT.R	8007280129 8007010535* 8007010441* 8007010440* 8007080166*	50-358 A 50-348 S 50-348 S 50-348 B 50-348 B	PETERSON, M R PETERSON, M R, PETERSON, M R PETERSON, M R PETERSON, M R	8007210124 8007140253 8007140266 8007140274* 8007140293	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIERCE, D A PIERBON, O K PIGOTT, D R PIGOTT, D R PIGOTT, D R	8007150470 8007210169 8007140034* 8007140034* 8007300359	50-280 J 40-4492 50-341 G 50-361 G

AVIHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8007030199 8007100014 8007210152 8007160440 8007280452	50~278 Q 50~278 Q 50~278 Q 50~278 P 50~278 P	POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U	8007140094 8007140177 8007270378+ 8007140373 8007250582	 GA999 GA999 GA999 GA999 GA999	REID.R W REID.R W REID.R W REID.R W REID.R W	8007100111 8007100115* 8007100121* 8007020488 8007140123	50-302 P 50-302 P 50-302 P 50-321 F 50-289 P
PIRTLE.G L	8007010578*	70-1308	POTAPOVS, U	8007230155	GA999	REID, R W	8007020438	50-277 P
PIRTLE.G L	8007190096*	70-2609	POTAPOVS, U	8007220136	GA999	REID, R W	8007070035	50-269 P
PIZZICA,P A	8007240459	NUREO	POTAPOVS, U	8007220182	GA999	REID, R W	8007170034	50-278 P
PLANUF,T J	6007220122	50-123 D	POTAPOVS, U	8007300173	GA999	REID, R W	8007170457	50-346 P
PLANT.R L	8007070263	50-10 D	POTAPOVS, U	8007290338	GA999	REID, R W	8007170461*	50-344 P
PLASKON, R E PLASKON, R E PLATO, P PLATO, P PLATO, P	8007010046 8007210515 8007230223 8007160280 8007020659	50-514 Q 50-514 Q RES RES PR	POTAPOVS, U POTTER, J P POTTER, J P POTTHOFF, F H	8007300308 8007010306* 8007010291* 8007150471* 8007180276*	QAPPP 50-217 Q 50-334 Q 50-280 Q 50-465 Q	REID.R W Reid.R W Reid.R W Reid.R W Reid.R W	8007170477* 8007180115 8007180134* 8007180138* 8007210327	50-346 P 50-366 P 50-366 P 50-366 P 50-346 P
PLATO,P FLATO,P PLEASANT,J C PLEGSET,M B PLEGSET,M S	8007110543 8007280338 8007090371 8005150676 8007160691	DRG CONTRACT NUREO ACRS PROJ	POWERS, D PRATT, C M PRATT, C M PRATT, C M PREISTER, D J	8007030171 8007230262 8007220160 8007270522 8007020577	PR PR 50-247 0 50-247 0 50-498 M	REID.R W REID.R W REID.R W REID.R W REID.R W	8007210333* 8007210340* 8007180125 8007180133* 8007180149*	50-346 P 50-346 P 50-346 P 50-346 P
PLESSET, M 8 PLESSET, M 8 PLESSET, M 8 PLESSET, M 8	8006160059 8007010359 8007210248 8007210531 8007210354	ACRS ACRS 50-327 D 50-327 D ACRS	PRICE, D S PRITCHARD, C C PROOM, B C PROOM, B C PURCELL, J F	8007150511* 8007100083 8007100134 8007210442 8007280141	50-302 G PR PRM MISC 50-367 R	REID, R W REID, R W REID, R W REID, R W REID, R W	8007180484 8007280130 8007180154 8007180457 8007220320	50-321 P 50-289 G 50-289 H 50-320 H
PLEBSET, IT 6 POCHAL, W F POCHAL, W F POCHAL, W F POINDEXTER, C H	6007210523 8007010102 8007020458 8007070041 8007230175	ACRB XPORTLIC XPORTLIC XPORTLIC XPORTLIC PR	PUSCHEL,M A QUATTROCCHI,J GUENNOI,S M GUICK,D R RACE,M A	8007310488 8007110017* 8007110434* 8007240377* 8007080039	FOIA 50-320 J 50-346 E 50-369 Q 50-329 O	REID, R W REID, R W REID, R W REID, R W REID, R W	8007230344 8007240354 8007240371 8007240372 8007240398	50-287 H 50-289 H 50-289 H 50-289 H
POIRIER,MR POIRIER,MR POLK,PJ POLLARD,R POLLARD,R	800/150449 8007150449 8007280255* 8007290012* 8007080090*	50-445 M 50-445 M 50-353 P SECY 50-287 0	RADOBEVIC, J R RAE, J B RAOER, M RAOER, M RAOER, M	8007030208* 8007140040* 8007030217* 8007030235* 8007030241*	50-285 P PR 50-331 6 50-331 6 90-331 8	REID,R W REID,R W REID,R W REID,R W REID,R W	8007240404 8007240412 8007240416 8007240419 8007240423	50-287 H 50-287 H 50-287 H 50-287 H
POLLARD, R D	8007270803*	ORG	rager, M	8007110417#	50-331 S	REID.R W	8007240428	50-269 H
POMERGY, D L	8007010244*	FDIA	Rager, B	8007110482#	50-331 S	REID.R W.	8007240238	50-277 P
POND, O D	8007020556	PR	Randall. M G	8007100416	REGOD	REID.R W	8007240242*	50-277 P
POOLE, D C	8007240382	50-302 G	Randall. J D	8007270468	50-128 R	REID.R W	8007240251*	50-277 P
POPEO, D J	8007100120	PRII	Randolph, M L	8007020356	RES	REID.R W	8007280107	50-346 F
PORTER, W L PORTER, W L PORTER, W L POTAPOVB, U POTAPOVS, U	8007240359	PR	RANDOLPH, H L	8007140044	RE8	REID.R W	8007290874	50-302 8
	8007030183	50-413 A	RANSOHOFF, J A	8007230354#	71-121	REID.R W	8007310340	50-289 F
	8007210476	50-413 A	RAPHAEL, D	8007280672#	50-409 Q	REIDHAAR,D L	8007090197	50-142 Q
	8007310195*	GA999	RASIN, W. H	8007140010#	50-369 Q	REIDLINGER,B A	8007140657#	40-2740
	8007310188*	GA999	RATHBUN, D J	8007310494	40-279	REIDLINGER,B A	8007140663*	40-2940
POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U	G007140082* G0073101/6* G007010154* G007300192* G007250095*	04999 04799 04999 04999 04999	RATHBUN, D J RATHBUN, D J RATHKOPF, C RAUNER, L K RAUSCH, J K	8007300279 8007300288 8007180464* 8007090377 8007100432*	40-299 40-299 50-339 H FOIA 50-413 Q	REIL.K O REIS.E J REIST.S D REIZEN.M S	8007290152 8007010143 8007030240 8007080054 8007270065*	NUREO 50-376 Q 50-309 Q 50-329 Q State Prog
POTAPOVS, U	8007280085	0.4999	RAUSCH, J K	9007250607*	50-369 Q	REKEMEYER,P C	8007220025	WASTE MOT
POTAPOVS, U	8007270481*	Q.4999	RAVENSCROFT, H	9007310506*	FOIA	REKITO.W.A	8007220060*	50-219 G
POTAPOVS, U	8007140063*	Q.4999	RAVHOND, W J	8007070373*	50-271 Q	REKITO.W.A	8007310131*	50-272 G
POTAPOVS, U	8007160133	Q.4999	RAVHOND, W J	8007020540	50-271 E	REMLEY.M E	8007230588*	70-25
POTAPOVS, U	8007010147*	Q.4999	RESELOWSKI, T	8007250332*	50-286 Q	REMPLE,L	8007210158	WASTE MOT
POTAPOVB, U	8007140037*	0A779	REBELOWSKI, T	8007290058	50-286 8	RENBERGER, D. L.	8007230007	50-508 @
POTAPOVB, U	6007160115*	QA777	RECORD, D, J	8007010532*	50-327 8		8007250354	50-397 @
POTAPOVB, U	6007160193*	QA779	RECORD, D J	8007150488*	90-327 8		8007270444	50-460 @
POTAPOVB, U	8007010034*	QA797	REDUDCH, T W	8007140610	NUREO		8007270405	50-509 @
POTAPOVB, U	8007160404*	QA777	REDMOND, R F	8007010383	50-150 8		8007230003	50-397 @
POTAPOVS, U	8007160150	0A999	REED. B. R	8007010555*	50-320 P	RENBEROER, D L	8007230623*	50-397 G
POTAPOVS, U	8007250184	0A999	REED. C	8007110462*	WASTE MOT	RENBEROER, D L	8007300279	50-440 G
POTAPOVS, U	8007100333#	0A999	REED. C	8007180010*	50-10 Q	RENBEROER, D L	8007300306	50-508 G
POTAPOVS, U	8007160161	0A999	REED. C	8007080248	TOPREP	RENBEROER, D L	8007300544	50-397 G
POTAPOVS, U	8007250589#	0A999	REED. C	8007070345	50-237 P	RENBEROER, D L	8007010002	50-397 A
FOTAPOVE, U	6007210257	0A979	REED, C	8007220352	TOPREP	RENBEROER.D L RENBEROER.D L RENBEROER.D L RENBEROER.D L RENBEROER.D L	8007160487	NUREO
FOTAPOVE, U	8007210269	0A979	REED, C	8007220482	TOPREP		8007150480	50-397 A
FOTAPOVE, U	8007220145*	0A999	REEDER, D L	8007150409	RES		8007270518	50-460 0
POTAPOVE, U	8007210536	0A999	REEVES, E A	8007010585*	50-202 P		8007310171	50-397 0
POTAPOVE, U	8007010135	0A979	REEVES, R W	8007020412	PR		8007180327	50-508 0
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8007220196*	0A999	REGAN, W H	8007070031*	50-514 D	RENBERGER.D L	8007250391	50-397 A
	8007300310	0A999	REGAN, W H	8007020684	50-458 H	RENBERGER.D L	8007310409	50-397 A
	8007300314*	0A999	REHM, T A	8007020023	COMMISSION	RENBERGER.D L.	8007210392	50-397 A
	8007100326	0A999	REHM, T A	8007110018	COMMISSION	RENBERGER.D L	8007250544	50-460 A
	8007290327	0A999	REHM, T A	8007140514	COMMISSION	RENBERGER.D L	8007290704	50-397 8
POTAPOVS, U	8007290307	0A999	REHM.T A REHM.T A. REHM.T A REHM.T A REID.R N	8007090122	COMM 19810N	RENBEROER, D L	8007300344	50~508 F
POTAPOVS, U	8007290474	QA999		8007180544	COMM 18810N	RENFRO, W	8007110080	50~466 Q
POTAPOVS, U	8007250052	QA999		8007240209	COMM 18810N	RENTFRD, W	8007220552	50~466 Q
POTAPOVS, U	8007310174	QA999		8007300088	COMM 18810N	REQUA, O	8007110123	50~309 P
POTAPOVS, U	8007140057	QA999		8005270617	50-302 P	REQUA, O	8007140465	50~309 P
Potapove, u	8007270856	18779	REID, R W	8007010575	50-312 P	REGUA, O	8007090388	50-309 P
Potapove, u	8007300182*	18779	REID, R W	8007020019	50-289 P	REVELEY, W T	8007090306	50-322 0
Potapove, u	8007140033	18779	REID, R W	8007160429	50-269 P	REVELEY, W T	8007090306	50-322 0
Potapove, u	8007270862*	18779	REID, R W	8007160434*	90-269 P	REVELEY, W T	8007170384	50-322 0
Potapove, u	8007010015	18779	REID, R W	8007160453*	90-269 P	REVELEY, W T	8007170384	50-322 0

REVESIL A 8007210327* 50-346 0 ROUNEY.H A 8007220138 70-1308 RYAN.R Q 8007 REVESIL A 80073100404* 50-346 0 ROUNEY.H A 8007220147 70-1308 RYAN.H T 8007 REVESIL A 80073002025* 50-334 0 ROUNEY.H A 8007220168 70-1308 RYAN.R Q 8007	7170234 S 7280095 R	State Prog State Prog
REYNOLDS, B D 8007280246* 50-354 O ROUNEY, M A 8007220170 70-1308 RYAN, R G 8007		RES State Prog State Prog
REYNOLDS:LE 8007010482 27-47 RDDNEY, M A 8007220147 70-1308 RYAN, R Q 8007 REYNOLDS:LE 8007030246 50-445 0 RDDNEY, M A 8007220168 70-1308 SABOL:A R 8007 REYNOLDS:LE 8007030246 50-445 0 RDDNEY, M A 8007220170 70-1308 SABOL:A R 80072	07250301 B 07210341* 5 07180245 R	State Prog State Prog 50~387
REYNOLDS:R H 8007270800* 50-327 S RODT:L D 80070072 50-331 Q SALTZMAN.J 8007 REYNOLDS:R H 8007270807 50-327 S RODT:L D 8007070142 50-331 P SALTZMAN.J 8007 REYNOLDS:R H 8007270827 50-327 S RODT:L D 8007070142 50-331 P SALTZMAN.J 8007	07110023* 7 07110022* 7 07110024* 7	XPDRTLIC 70-1333 70-1333 70-1333 50-289 J
REYNILIDS N B 8007270533 50-344 H RIDIT L D 8007140434 50-331 P SALTZMAN J 8007 REYNIDLIDS R H 8007270533 50-344 H RIDIT L D 8007140366 50-331 P SALTZMAN J 8007 REYNIDLIDS R H 8007270473 50-345 9 RIDIT L D 8007140366 50-331 P SALTZMAN J 8007	07610037* 5 0/110040* 5 07110032* 5	50-287 J 50-320 J 50-320 J 50-320 J 50-344 M
RHUADBLO G GROVALOSA SO-33 G GROVALOSA GROVALO	07220257 4 07160625 5 07160625 5	50-346 H 40-299 50~445 M 50-445 M PR
RIDDLE:M W 8007210418 50-517 E ROSENTIAL: A J 8007280205** 50-10 D SANDVIK:R M 8007 RIDBUT: F 8007240391 PT21 ROSENTIAL: A J 8007280205** 50-10 D SANDVIK:R M 8007 RIBBUT: J T 8007240409 NUREO ROSENTIELD: A R 8007280201 NUREO SANDER: H S 8007	07300372 5 07100047 P 07100050* #	50-344 H 50-522 0 Pr Pr Contract
RILEY, J L B007030036 50-367 0 RDSS, D F B0070101788 F01A SASSANI, A B007 RILEY, R O B0070300409 50-367 0 RDSS, D F B007180451* 50-217 Q SASTRE, C B007 RILEY, R O B007310210 NUREO RDSS, D A B007180451* 50-217 Q SASTRE, C B007	07310063* 5 07180240 F 07010244* F	50-346 R 90-277 G RES FGIA 40-8693
RIBER, J A 8007380010 50-443 I ROSE, D A 8007110373* 50-217 8 SAUTER, 0 800 RITTE, F H 8007210455 50-445 M ROSE, D A 8007110383* 50-217 8 SAVAGE, H R 800 RITTE, F H 8007210455 50-445 M ROSE, D A 8007210383* 50-217 8 SAVAGE, H R 800 RITTE, F H 8007210740323* 50-217 8 SAVAGE, H R 800 RITTE, F H 800	07100327 F 07090408 F 07280067* F	FOIA FOIA REOOD PR 50-329 H
ROBERTS, K 5007/20162# 50-229 0 ROBITOCIV. Z R 5007030359 TUPREP BCARAND, R A 500 ROBERTS, K 5007280262# 50-229 0 ROBITOCIV. Z R 5007130163# 70-364 SCARAND, R A 500 ROBERTS, K 5007280262# 50-229 0 ROBITOCIV. B007130163# 70-364 SCARAND, R A 500 ROBERTS, K 5007280262# 50-229 0 ROBITOCIV. B007130163# 70-364 SCARAND, R A 500 ROBERTS, K 5007280262# 50-229 0 ROBERTS, K 5007280267 50-229 0 ROBERTS, K 500	07300560* 07180074 07100431	50-287 H 40-8727 40-8478 WASTE MOT 40-8502
ROBERTS, F 9007220/06 70-2823 RDTH, J 8007290032 70-1100 SCARAND, R A 800 RDB INSEN, R K 8007020701 PR ROTH, J 8007290798 50-389 1 SCARAND, R A 800 RDB INSEN, R K 8007020701 PR ROTH, A J 8007290798 50-389 1 SCARAND, R A 800 RDB INSEN, R A 80	007010261 007010559 007100445	40-8502 40-1162 40-1162 40-8502 40-8584
ROBINSON: R K 8007/280009 PR ROTHFLEISCH.J 8007/230161 40-8714 SCARAND. R A 800 RODRIOUEZ. R J 8007/160405 PR ROTHFLEISCH.J 8007/230161 40-8714 SCARAND. R A 800 RODRIOUEZ. R J 8007/150588 50-312 R ROTHFLEISCH.J 8007/3302/27 40-8200 SCARAND. R A 800 ROTHFLEISCH.J 8007/3302/27 40-8200 SCARAND. R A 800 ROTHFLEISCH.J 8007/300/42 40-8280 SCARAND. R A 800 R ROTHFLEISCH.J 8007/300/42 40-8280 R R R R R R R R R R R R R R R R R R R	007180131 00724007 9 007020092	40-1162 40-8622 40-1341 WASTE HGT 40-8745
RODERG.R F 80071000668 90-321 Q ROTHSCHILD.R U 8007220009 70-1309 9CARAND.R A 80C RODERG.W L 8007020129 MABTE HOT ROTHSCHILD.R U 8007220011* 70-1309 9CARAND.R A 80C RODERS.H L 8007030170 PR ROTHSCHILD.R U 8007220011* 70-1308 9CARAND.R A 80C	007140600 307170433 007180086	40-8745 40-8502 40-8745 40-8380 WASTE MQT
RODERBINE 6007110528 XPORTLIC ROUSELL C BO07210510 70-1143 SCARANDLR A 800 RODERBIC B 8007310153 50-596 G ROUSEL C B007200289 70-1143 SCARANDLR A 800 RODERBINE 8 8007140449* PR 8007140449* PR 9007140449* GARANDLR A 800 RODERBINE 8 8007140449* PR 9007140449* GARANDLR A 800 RODERBINE 8 9007140449* PR 900714049* PR 9007140449* PR 900714049* PR 9007140449* PR 900714049* PR 9007140* PR 90	007100019 007100490 007310543 007310544 007210056	40-8681 40-8584 40-6657 40-8714 40-8502
ROHAND, F. R. 8007280193* 50-320 W. RUBLERT, F. 8007220393 50-10 D. BCARAND, R.A. 801 ROHAN, T.W. 8007170361* 50-220 R. RUBLERT, F. 8007220393 50-335 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-335 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-305 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-305 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-305 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-305 G. BCARAND, R.A. 801 ROHIC, B. 80071730110 PR. RUBLERT, B. 8007220393 50-305 G. BCARAND, R.A. 801 ROHIC, B. 8007220393 F. ROHIC, B	007230071 007230077 007230082 007230274 007230318	40-8502 40-8502 40-8502 40-8502 40-8502
ROMINE, P. F. 8007010515* 50-327 B. RUBCHE, B. C. 8007020331* COMMISSION SCARANO, R. A. 800 ROMINE, D. GOO7010522* 50-327 B. RUBCHE, B. C. 8007020334* COMMISBION SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 8007240152 50-318 S. SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 8007240152 50-318 S. SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 8007240152 50-318 S. SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 8007240152 50-318 S. SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 8007240152 50-318 S. SCARANO, R. A. 800 ROMINE, D. 8007080288* 50-327 B. RUBBELL, L. B. 800708031** COMMISSION SCARANO, R. A. 800 ROMINE, D.	007290642 007230171 007230145 007230050 007230294	40-8502 40-2259 WASTE MGT 40-4492 40-8200
ROMINE, D 8007290719* 50-327 8 RUSSELL, L 8 8007307100* 50-274 F 8CARAND, R A 80 ROMINE, D 8007290719* 50-327 8 RUSSELL, L 8 8007160649 50-274 F 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020099 State Prog 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020099 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 50-339 P RYAN, R O 8007020019 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 ROMNEY, N 8007100140 STATE PROG 8CARAND, R A 80 R R R R R R R R R R R R R R R R R R	1007230711 1007240228 1007140303 1007240300 1007300042	40-8728 WASTE MOT 40-8452 40-8585 40-8380
ROOD H 8007210093 50-206 P RYAN'R 9 8007020139 GRO SCHADE, A'R 80 RODNEY, V L 8007100049 50-133 P RYAN'R 0 80070204439 GRG SCHADE, FERR'N R 80 RICHAEL R 800 R	1007230063 1007250440 1007280397 3007280403* 1007100420*	40~8502 PROJ XPORTLIC XPORTLIC 50-10 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
SCHAUB, J B	8007280360	XPORTLIC	BCHWENCER, A	8007250004	50-352 H	SEYFRIT, K V	8007010044	50-247 0
SCHENDEL, K R	8007010214	40-8589	BCHWENCER, A	8007250475	50-352 H		8007010048	50-298 0
SCHERER, A E	8007110243	TOPREP	BCHWENCER, A	8007250022	50-327 O		8007010053	50-285 0
SCHERER, A E	8007030343	PR	BCHWENCER, A	8007250022	50-416 A		8007020675	50-498 A
SCHERER, A E	8007100210	TOPREP	BCHWENCER, A	8007250322	50-311 P		8007220094	50-313 0
SCHERER.A E	8007070351	HUREO	2011'N 7	8007140439*	PR	SEYFRIT,K V SEYFRIT,K V SEYFRIT,K V SEYFRIT,K V SEYFRIT,K V	8007220098	50-498 Q
SCHERER.A E	8007080274	TOPREP	8011'N 7	8007170374	50-466 G		8007220104	50-458 Q
SCHERER.A E	8007100219	TOPREP	8011'N 7	8007160587	70-1308		8007220109	50-482 Q
SCHERER.A E	8007160491	NUREO	8011'N 7	8007180387	70-1308		8007220113	50-382 Q
SCHMIDT.E W	8007310183	RES	8011'N 7	8007230527	27-39		8007220118	50-556 Q
SCHMIDT, E W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8007310181 8007010483 8007080284 8007140382 8007140364	RES 70-335 8 50-335 6 50-335 5 50-335 S	SCOTT.W J SCOTT.J N SEAL.N M SEAL.N M	6007250442 8007300116 8007020076* 8007140108* 8007140028	27-39 50-466 0 50-443 H 50-437 H 50-367 H	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007220120 8007220124 8007220126 8007220128 8007020318	50-298 0 50-285 0 50-267 0 50-445 0 50-382 A
SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, E N SCHMIDT, A D	8007150527 8007240174 8007150532 8007280004 8007220419	50~335 5 50~250 R 50~335 5 RES 50~250 8	SEIDLE.W C BEIDLE.W C BEIDLE.W C BEIDLE.W C	6007210137 8007150064 8007160490 8007010203 8007110061	50-458	BEYFRIT, K V BEYFRIT, K V BEYFRIT, K V BEYFRIT, K V	8007160321 8007160324 8007160327 8007160331 8007160334	50-313 G 50-482 G 50-382 G 50-285 G 50-445 G
SCHNEIDER.F U SCHNEIDER.F U SCHNEILE D F SCHNEIDER.F U SCHNEIDER.F U	8007170570 8007170642 8007100379 8007030249 8007210608	50~272	BEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007070083 8007100342 8007110187 8007110229 8007140434	50-482 Q 50-498 Q 50-482 Q 50-443 Q 50-382 Q	SEYFRIT.K V BEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8007140404 8007140410 8007290057 8007290059 8007290066	50-438 Q 50-278 Q 50-458 Q 50-478 Q 50-482 O
SCHNEIDER, F II SCHNEIDER, F II SCHNEIDER, F II SCHNEIDER, F II SCHOLL, R F	8007210268 8007150631 8007210552 8007140429 8007160463*	50~272 0 50~272 0 50~272 0 50~272 F 50~10 P	BEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007240333 8007180567 8007280724 8007140497 8007230278	50-490 G 50-445 G 50-482 G 50-445 G 90-498 G	SEYFRIT, K V SCYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007290068 8007290075 8007290077 8007010024 8007280137*	50-362 Q 50-556 Q 50-445 Q 50-313 H 50-498 Q
BCHOLL, R F	6007250035*	50-10 P	SEIDLE.W C	8007280144	90-382 Q	BEYFRIT, K V	8007240031	50-313 Q
BCHOPPMAN, M A	8007010491*	50-335 S	SEIDLE.W C	8007290433	90-382 Q	BEYFRIT, K V	8007240035	50-458 Q
BCHOPPMAN, M A	8007080270*	50-335 S	SEIDLE.W C	8007300391	50-382 Q	SEYFRIT, K V	8007240037	50-498 Q
BCHOPPMAN, M A	6007140389*	50-335 S	SEIDLE.W C	8007290013	50-482 Q	SEYFRIT, K V	8007240043	50-482 Q
BCKOPPMAN, M A	8007140372*	50-335 S	SEIFERT.C W	8007250025	COMM16810N	SEYFRIT, K V	8007240045	50-382 Q
BCHOPPMAN, M A	8007190636*	50-335 6	BEIKEN, BJ	8007270254#	50-482 8	BEYFRIT, K V	8007240047	50-285 Q
BCHOPPMAN, M A	8007150536*	30-335 8	BEIKEN, BJ	8007300337	50-482 A	SEYFRIT, K V	8007240051	50-278 G
SCHROEDER, F	8007010249*	F01A	BEKULER, BN	8007080026	50-367 0	BEYFRIT, K V	8007240054	50-267 Q
BCHULTZ, G	8007100239	50-367 H	BEKULER, BN	8007160587	70-1308	SEYFRIT, K V	8007240057	50-445 Q
SCHUMACHER, M C	9007310515*	50-295 0	SEKULER, BN	8007180387	70-1308	SEYFRIT, K V	8007280132	50-478 G
SCHUSTER: M D SCHWEND! MAN: L SCHWEND!MAN: L SCHWENSFEIR: R	8007230154	50-312 8	SEKULER, B N	8007230527	27-39	BEYFRIT.K V	8007170669	50-450 Q
	8007310234	NUREQ	SEKULER, B, N	8007250442	27-39	BEYFRIT.K V	8007170673	50-482 Q
	8007090186*	70-1257	SEKULER, B N	8007310133	27-39	BEYFRIT.K.V	8007170676	50-498 Q
	8007210315*	70-1257	SELLS, D	8007180285	50-382 A	BEYFRIT.K V	8007170680	50-382 O
	8007070048	70-33	SENCEHAL, M E	8007140011	PR	BEYFRIT.K V	8007170683	50-445 Q
SCHWEIKER, R S	8007110323*	M15C	BENECHAL, M E	8007250422	50-202 0	SEYFRIT, K V	8007230364	50-498 Q
SCHWEIBNINZ, E	8007160479*	50-546 0	BERABIAN, J A	8007220285*	50-317 0	SEYFRIT, K V	8007230369	50-382 Q
SCHWEIBINZ, E R	8007230019*	50-496 0	BERABIAN, J A	8007230021*	50-277 F	SEYFRIT, K V	8007230370	50-445 Q
SCHWENSFEIR, R	8007210175*	70-33	BETHNEBB, E D.	8007110459*	WASTE HOT	SEYFRIT, K V	8007230373	50-482 Q
SCHWENCER, A	8007020399	50-364 A	BETLYUR, A V	8007220234*	50-305 P	SEYFRIT, K V	8007230376	50-458 Q
BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8007110033	50-275 E	BEYFRIT,K V	8007210324*	70-157	BEYFRIT,K V	8007150007	50-498 Q
	8007010287	50-364 A	BEYFRIT,K V	8007240348*	70-1062	BEYFRIT,K V	8007150007*	50-498 Q
	8007010148	50-390 A	BEYFRIT,K V	8007290492*	0A999	BEYFRIT,K V	8007310324	50-285 Q
	8007070109	50-311 E	BEYFRIT,K V	8007250316	50-458 Q	BEYFRIT,K V	8007310331	50-313 H
	8007020473	50-364 A	SEYFRIT,K V	8007250319	50-470 Q	SHALLER,D V	8007070289	50-316 B
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8067020747 8067020086 8067020642 8067020707 8067020722	50-327 P 50-311 P 50-327 P 50-390 A 50-327 P	SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8007250321 8007250323 8007250328 8007140563 8007140568	50-482 G 50-382 O 50-445 Q 50-278 G 50-450 Q	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8007280510 8007150586 8007150684 8007150542 8007150555	50-315 B 50-315 B 50-316 B 50-315 R 50-316 R
BCHWENCER A	8007100272	50-352 H	GEYFRIT, K V	8007240505	50-498 Q	SHALLER, D V	6007150696	50-315 6
BCHWENCER, A	8007110510	50-352 H	SEYFRIT, K V	8007240507	50-445 Q	SHALLER, D V	8007210537	50-314 8
BCHWENCER, A	8007110574	50-445 F	SEYFRIT, K V	8007240510	50-382 G	SHALLER, D V	8007310399	50-315 V
BCHWENCER, A	8007030195	50-327 P	GEYFRIT, K V	9007240511	50-458 Q	SHANBAKY, M M	6007170547	50-320 8
BCHWENCER, A	8007020473	50-361 A	SEYFRIT, K V	8007240513	50-482 Q	SHANBAKY, M M	8007170540	50-320 8
SCHWENCER A	8007 1 1 0 5 2 6	50-528 H	SEYFRIT.K V	8007020249	50-458 0	Бнанваху, М и	8007170553	50-320 8
SCHWENCER, A	8 0 0 7 1 4 0 0 2 5	50-352 H	SEYFRIT.K V	8007020253	50-498 0	Внанваку, М М	8007170564	50-320 8
SCHWENCER, A	8 0 0 7 1 4 0 0 5 3	50-445 D	SEYFRIT.K V	8007020255	50-445 0	Внанваку, М М	8007170557	50-320 B
SCHWENCER, A	8 0 0 7 1 4 0 4 5 1	50-352 A	SEYFRIT.K V	8007020259	50-482 0	Внанваку, М М	8007240203	50-320 B
SCHWENCER, A	8 0 0 7 1 8 0 0 8 1	50-329 A	SEYFRIT.K V	8007020261	50-382 0	Внараку, М М	8007080036	FOIA
Bchkencer, a	8007180334	50-395 A	SEYFRIT, K V	8007020243	50-285 Q	ehapar, h k	8005270154	FOIA
Bchkencer, a	8007170496	50-327 P	SEYFRIT, K V	8007020248	50-298 Q	ehapar, h k	8007290002	BECY
Bchkencer, a	8007170503*	50-327 P	SEYFRIT, K V	8007020249	50-313 Q	ehapar, h k	8007220268*	40-299
Bchkencer, a	8007170517*	50-327 P	SEYFRIT, K V	8007020272	50-267 Q	ehapar, h k	8007160607	50-413 M
Bchkencer, a	8007180061	50-327 P	SEYFRIT, K V	8007210342	50-313 Q	ehea. J. R	8007310260*	FOIA
Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8007180345 8007180598 8007180596* 8007180599* 8007170542*	50-352 H 50-327 P 50-327 P 80-327 P 50-528 G	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V, SEYFRIT, K V SEYFRIT, K V	8007210346 8007210348 8007210350 8007210351 8007010020	50-382 Q 50-482 Q 50-285 Q 50-382 Q	BHEA, J.R BHEA, J.R BHEA, J.R BHEA, J.R BHEA, J.R	8007070030* 8007070033* 8007250017* 8007020073 8007280078	10CFR 10CFR 10CFR XPORTLIC XPORTLIC
Schiencer. A	8007170538	50-528 0	SEYFRIT, K V	8007010025	50-492 Q	Bhea. J. R	8007020123	XPORTLIC
Schiencer. A	8007180019	50-329 A	SEYFRIT, K V	8007010026	50-445 Q	Bhea. J. R	8007020734	XPORTLIC
Schiencer. A	8007230190	50-329 H	SEYFRIT, K V	8007010028	50-458 Q	Bhea. J. R	8007140552	SECY
Schiencer. A	8007240312*	50-327 P	SEYFRIT, K V	8007010037	50-478 Q	Bhea. J. R.	8007150050	SECY
Schiencer. A	8007240081	50-311 P	SEYFRIT, K V	8007010040	50-313 Q	Bhea. J. R	8007140539	SECY

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT
EHEA, J R	8007150069	SECY	SHREVE.D B	8007020553*	CONTRACT	SMITH, H	8007020426	50-206 · 70-33 · 50-329 · 50-277 · 40-8681
BHEA, J R	8007150054	SECY	SHRIVER.B L	8007210429	50-62 F	SHITH, G H	8007210167	
BHEA, J R	8007280062	SECY	SHROEDER.F	8007010241*	FOIA	SHITH, I U	8007020562	
BHEA, J R	8007270044	XPORTLIC	SHUM.E Y	8007020514	70-2909	SMITH, G H	8007230018	
BHEA, J R	8007150836	XPORTLIC	SHUM.E Y	8007280179	70-143	SMITH, K T	8007210070	
SHEA, K H SHEA, K H SHEA, J R SHEA, J R	8007020453 8007080021 8007020453 8007280086 8007140583	50-367 G 50-367 G 50-367 G SECY XPURTLIC	SHUM, E Y SHURTS, B J BIEBER. J D BIEBER. J D	8007030028* 8007150918 8007010542* 8007290540 8007150059	70-1151 70-1151 50-263 S 50-412 R RES	SMITH, R L SMITH, R L SMITH, R L SMITH, F M SMITH, I W	8007070346 8007070247 8007080292 8007140646 8007090220	50-271 · 50-271 · 71-6387 · 50-287 ·
SHEA, J R	8007170244	SECY	BIEGEL, B L	8007010088*	50-249 P	SMITH, P A SMITH, R D SMITH, T H SMITH, R O SMITH, I U	8007280520	CONTRACT
SHEA, J R	8007170523	BECY	BIEGEL, B L	8007010103*	50-249 P		8007170660	HASTE MGT
SHEA, J R	8007210009	SECY	BIEGEL, B	8007010119*	50-265 P		8007230171	50-213
SHEA, J R	8007230557	XPORTLIC	BIEGEL, B L	8007010149*	FOIA		8007310120	REGOD
SHEA, J R	8007230546#	XPORTLIC	BIEGEL, B L	8007010161*	FOIA		8007110324	50-287
SHEA, J R	8007220214#	FOIA	SIEGEL, B L	8007010165*	FOIA	SMITH, I W	8007220533*	50-289 C
SHEA, J R	8007250454	XPORTLIC	SIEGEL, B L	8007010168*	FOIA	SMITH, O H	8007230212	50-245
SHEDLOBKY, J T	8007310345#	50-245 G	SIEGEL, B L	8007010173*	FOIA	SMITHSON, J D	8007230216	1&E
SHEEHAN, D P	8007080007	50-320 O	SILBERG, J E	8007020689	PR	SMITHSON, J D	8007160523*	50-327
SHEEHAN, D P	8007070337	50-320 O	SILBERG, J E	8007100191*	PR	SMITH, O H	8007290001	70-1100
SHEEHAN, D P SHEEHAN, D P SHEEHAN, D P SHEEHAN, D P SHEELDON, K P	8007070353* 8007070365* 8007070371* 8007280613 8007140387	50-320 0 30-320 0 50-320 0 50-320 0 PR	SILBERO, J E SILBERO, J E BILKER, W B BIMONB, C S BIMONB, C B	8007300463 8007300463 8007170311 8007080273 8007080278*	50-282 G 50-282 G NUREO 40-8056 40-8056	SHITH, I W SMITH, R L SMITH, R L SMITH, R L	8007220089 8007210448 8007250488 8007250446 8007250452*	50-289 C 50-271 } 50-271 , 50-289 G 50-269 G
SHELLEY, W J SHELLEY, W J SHELLEY, W J SHELLEY, W J	8007140387 8007030031 8007010611* 8007110025 8007010590	PR 40~8647 40~8027 40~2061 40~8647	SIMPSON, A K SINGER, L N SINGER, L SINGER, L N SINGH, J N	8007110005 8007070104 8007080061 8007180411 8007220065	PR 50-320 0 50-320 0 50-320 G RES	SWITH I W SWITH I W SWITH I W SWITH I W	6007250426 6007250678 8007250678 8007250735 8007250730	50-289 0 50-255 0 50-289 0 50-389 H 50-329 0
SHELLEY, W J. BHELLEY, W J. BHELLEY, W J. BHEPHERD, T A BHEPHERD, T A	8007010607 8007250634 8007230564* 8007250073 8007210183	40-8027 40-8027 70-725 40-8452 40-8452	SINKIN, LA SINKIN, LA SINKIN, LA SINGH, H	8007220524* 8007119001 8007300415 8007310145 8007310145	50-409 P 50-498 Q 50-498 Q 50-498 Q 50-498 Q	SMITH I W EMITH, I W SMITH, R L SMITH, R L SMITH, P D	6007270732 6007270766 6007260661 6007310385 6007240478	50-329 0 50-329 0 50-271 F 50-271 P NUREO
SHEFHERD, T A	8007210177	40-8452	BIRI,W E	8007220023*	MISC	SMOKER,C S	E007160474*	50-305 S
SHEPLEY, B E	8007170103*	50-373 Q	GKARITKA,J	8007100254*	TOPREP	SMYTH,N P D	E007160402	PR
SHERBONDY, B N	8007250374	70-143	GKARUPA,J D	8007310087	XPORTLIC	SNAPP.C	E007070218	50-275 H
SHERMAN, H D	8007250150	Waste Mot	GKARUPA,J D	8007110237	XPORTLIC	SNIEZEK.J H	E007020144*	MISC
SHERMAN, F L	8007220527	70-33	GKARUPA,J D	8007280223	XPORTLIC	SNOW.B A	8007150584	50-244 R
BHERMAN, F. L. BHERWOOD, Q. O. BHERWOOD, Q. Q. BHERWOOD, Q. Q. BHERWOOD, Q. Q.	B007290445	70-33	SKGROHOD, P. H	8007020463	FDIA	SNOW B A	8007160637	50-244 8
	B007160703*	50-341 A	SLABACK, L. A	8007150342	REGOD	SNOW B A	8007210443	50-244 8
	B00711049B*	SECY	SLEAR, D. G	8007160670	50-207 P	SNYDER, T K	8007300498*	50-237 0
	B00714006B*	10CFR	SLEMMONS, D. B	8007100112*	CONTRACT	SNYDER, T K	8007300308*	50-237 0
	B007010507	TOPREP	SLOAN, D. E	8007240353	50-327 S	SNYDER, T K	8007300508*	50-237 0
SHEW.D	8007160208	CONTRACT	BLOBODIEN. M J	8007170337*	70-1869	SNYDER, O L	8007280188*	50~320 H
SHEWMAKER.R E	8007010044*	50~546 H	BLUIB. B J	8007310179*	GA999	SNYDER, B J	8007070151	50~320 H
SHIELDS.S W	8007020031*	50~546 G	BMEDIRA. C	8007230349	71-121	SNYDER, B J	8007010290	50~320 P
SHIELDS.G W	8007010096	50~546 A	BMEDIRA. C	8007230354*	71-121	SNYDER, B J	8007110272	50~320 P
SHIELDS.R O	8007170275	PRI1	BMITH, C N	8007100076*	70-143	SNYDER, B J	8007110280*	50~320 P
SHIELDS, S W	8007140506 8007210058 8007100227 8007230238 8007230073	50~546 Q 50~546 A 50~546 B 50~546 Q 50~546 Q	SMITH.OH SMITH,OH SMITH,OH SMITH,OH SMITH.OH SMITH.R	8007150190* 8007100002 8007010197* 8005020572 8007030341	70-364 50-320 G 40-6789 1%E PR	SNYDER. D BNYDER. B BNYDER. B J BNYDER. B J BNYDER. D J	8007110272* 8007070211 8007180237 8007100193 8007240158	90-320 P 50-320 0 50-320 H 50-320 P 50-320 P
SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIMA, B,	8007220549 8007280591 8007250397 8007250667 8007240030	50-546 H 50-546 F 50-546 B 50-546 B xpgrtlic	SMITH, OH SMITH, OH SMITH, OH SMITH, OH	8007020106* 8007210295* 8006110736 8007010285 8007010299	70-1100 70-687 27-10 50-334 0 50-219 0	ENYDER, D J SHYDER, D J SHYDER, D J SHYDER, D J	8007;80107 8007280579 8007210121 8007230293 8007230278	50-320 H 50-320 0 50-320 H 50-320 H
SHIMA, B	8007240036*	XPURTLIC	Smith, oh	8007240057*	XPORTLIC	SNYDER, B J	8007230311	50-320 H
BHIMSHAK, R	8007080300	50-409 P	Smith, oh	8007140604	27-48	SNYDER, B J	8007290032	50-320 H
BHINEFLUO, M J,	8007230324	50-10 D	Smith, oh	8007140653	40-2940	SNYDER, B J	8007300006	50-320 H
BHIBBIMS J A	8007110456	50-272 P	Smith, oh	8007210180*	70-33	SNYDER, B J	8007300010	50-320 H
BHIBBIMS J A	8007030232	50-272 R	Smith, oh	8007010180	40-6789	B NYDER, B H	8007080044	50-466 0
SHIVELY, C N SHIVELY, C N SHIVELY, C N SHIVELY, C, N SHIVELY, C, N	8007010414* 8007080154* 8007140405* 8007150650* 8007240150*	50-368 8 50-368 8 50-368 8 50-313 8 50-313 8	BMITH, OH BMITH, RH BMITH, PA BMITH, OH BMITH, PA	8006260362 8007250076* 8007010560 8007210165 8007030068	50-271 0 50-388 0 CONTRACT 70-1143 CONTRACT	ECHINKI'E N ECHINKI'E W ECHINKI'E W ECHINKI'E W	6007140015 6007220021 6007220159 8007300397 8007300404	50-466 0 50-466 0 50-466 0 50-466 0
SHOLLY, S, C	8007020651	50-289 0	GMITH,PA	8007030353	CONTRACT	BOHINKI, B M	8007300423	50-466 0
SHOLLY, S, C	8007020648	50-289 0	GMITH,RH	8007280408*	50-293 0	BOHINKI, B N	8007300424	30-466 0
SHOLLY, S, C	8007030057	50-289 0	GMITH,RH	8007020534	50-213 9	BOKOLOWBKI, O	8007280366*	XPORTLIC
SHOLLY, B	8007110075	50-320 0	GMITH,PA	8007030369	GUNTRACT	BOLBRIO, C W	8007100363	HUREQ
SHOLLY, S	8007080007	50-320 0	GMITH,PA	8007070021	GONTRACT	BOMMER, J C	8007240437	FOIA
SHOCLY, S SHOCLY, S SHOLLY, S SHOLLY, S	8007020654 8007070337 8007070353* 8007070365* 8007070371*	50-320 0 50-320 0 50-320 0 50-320 0 50-320 0	SMITH, PA SMITH, PA SMITH, PA SMITH, PA SMITH, DR	8007070045 8007100010 8007100011 8007020572 8007180175	CONTRACT CONTRACT CONTRACT CONTRACT RECOD	GONNEBORN.M R GOONG.A L BOUCY.A R GOUDER.J L GOUDER.J L	8007020457 8007280327* 8007010404 8007210018 8007230109	50-320 H 70-1319 50-29 1 50-528 H 50-440 H
EHOLLY, B C. EHOLLY, B C. EHOLLY, B C. EHON, F. J. EHORB, E. M.	8007140004	50-320 T	BMITH, PA	8007140590	CONTRACT	SGUDER, J.L.	8007210084	50-287
	8007310138	50-287 0	GMITH, PA	8007110559	CONTRACT	SOXMAN, K.A.	8007290051*	50-320
	8007170210	50-287 0	SMITH, PA	8007150048	CONTRACT	SPANGENBERG, C.	8007230015*	70-184
	8007220006	50-320 0	SMITH, PA	8007150055	CONTRACT	SPANGLER, R. G.	8007150136*	50-298 0
	8007250630	50-347 0	SMITH, PA	8007150060	CONTRACT	SPANNAUS, W.	8007140011	PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PANNAUS, W PARKS, E 'EIS, T P PELLHAN, G N PENCER, G S	8007250422 8007020335 8007170647 8007250264* 8007230627*	50-282 0 40-8728 50-270 P 50-317 H 50-397 0	STELLO, V STELLO, V STELLO, V STENSVARO, J M BTENSVARO, B	8007210280 8007300044 8007220586 8007070048 8007010497	50-293 Q 50-271 Q 50-219 Q PR 50-237 S	SHANGON, D.T. SHANGON, E.R. SHANGON, D.T. SHANGON, D.C. SHANGON, D.C. SHANGON, D.T.	8007010257 8007140558* 8007020468 8007170618 8007010332	50-522 Q 50-346 Q 50-70 Q NUREQ 50-287 Q
PENCER, G B PENCER, G B PENCER, G B PENCER, G S PENCER, G S	8007020158* 8007170245 8007170530 8007180014 8007210556*	50-341 0 50-528 0 50-341 0 50-204 0 50-528 0	STEPHENSON, 8 B STEPHENSON, 8 B STEPHENSON, 8 B STEPHENSON, 8 B STEPHENSON, 8 D	8007010544 8007100179 8007100187 8007180333 8007220455	50-237 8 50-237 8 50-237 8 50-10 R 50-249 8	BWANSON,D T BWANSON,D T BWANSON,D T BWART,F E BWARTZ,L L	8007100216 8007230617* 8007310219 8007020309 8007010269	50-287 P 50-287 0 50-287 0 50-267 0 50-287 0
PENCER. G S PENCER. G S PENCER. G S PENCER. G S PENCER. W C	8007020131 8007240318 8007240307 8007300313 8007160664	50-361 Q 50-206 Q 50-344 Q 50-361 Q 50-281 Q	STEPHENBON, D D GTEPHENBON, B B GTEPHENBON, B D GTEPHENB, C R GTEPTOE, P P	8007310490 8007220557 8007220577 8007310493 8007300362	50-249 0 50-237 8 50-249 6 50-282 0 50-295 0	SWARTZ, L L SWARTZ, L L SWARTZ, L L SWARTZ, L L SWARTZ, L L	8007210503* 8007030293* 8007030294* 8007030297*	50-289 0 50-289 0 50-289 0 50-289 0
PENCER. G 8 PENCER. G B PENCER. G B PENCER. G B PENCER. W C	8007210543 8007230618 8007240093* 8007310505 8007110390	50-528	STEPTOE, P P STEPTOE, P P STERNBERG, D IS STERNBERG, D STERNBERG, D	8007150052 8007150052 8007010141* 8007030345 8007170089*	50-155 0 50-155 0 50-293 P 50-320 T 50-133 Q	SHARTZ, L L SHARTZ, L L SHARTZ, L L SHARTZ, L L SHARTZ, L L	8007030299* 8007030301* 8007030302* 8007030303* 8007030304*	50-287 0 50-287 0 50-287 0 50-289 0 50-287 0
PESSARD, R L PESSARD, R L PESSARD, R L PETH, O 'ETH, O	8007070086* 8007170103* 8007230388* 8007220121* 8007070148*	50-10 Q 50-373 Q 50-10 Q 50-599 Q PR	STERNBERO, D M BYERN, W. C BYERNSERO, D M BYERNBERO, D M STERNBERO, D M	8007240395* 8007210129 8007300295* 8007310327* 8007300525*	50-279 Q XPORTLIC 50-344 Q 50-275 Q 50-344 Q	BHART,F E. BWARTZ,L L BWARTZ,L L BWARTZ,L L BWARTZ,L L	8007090333 8007090212 8007170370 8007220562 8007220564	50-267 P 50-287 0 50-289 0 50-289 0 50-289 0
'RINGER, D PRINGER, D 'RINGER, D RING, C RABLE, C RABLE, C	8006200071* 8006200066 8007020475 8007270628 8007280006	50-488 Q 50-488 Q 50-488 Q 50-266 H 50-311 P	STERN, W. C. STERN, W. C STEVENBON, R. L. STEVENB, B. C STEVENB, B. C	8007280393 8007310484 8007070195* 8007070375 8007240130	XPORTLIC XPORTLIC 70-1113 50-205 8 50-205 8	SHART,F E SHARTZ,L L SHARTZ,L L SHARTZ,L L SHARTZ,L L	8007280493 8007230500 8007230609 8007230614* 8007250683	50-267 P 50-269 Q 50-269 Q 50-269 Q 50-269 Q
TAGGERS, H O TAHLE, G R AHL, D H IAHL, D H TAIDER, G R	8007250215* 8007210618 8007150431 8007150431 8007100264	COMMIGBION 50-327 P 50-445 M 50-445 M BECY	STEWART,R C STEWART,K L STIEGLITZ,W O STITT,B D STITT,B D	8007140447* 8007210200 8007150710 8007310009 8007280683	50-382 G 71-139 50-250 P NUREO NUREO	SHARTZ, L L. SWAYNE, R W SWEARINGEN, J D. SWEARINGEN, J D. SWETLAND, P	8007310315 8007100330* 8007010385* 8007150501* 8007230398*	50-289 0 GA999 50-327 8 50-327 8 50-309 0
TAMIRIS.D. TAMPLEY.N L TAMPLEY.N L ARK.R M ARKEY.R U	8007110497 8006300375 8006300382* 8007070391 8007150629	PR 50-416 P 50-416 F 50-387 A 50-261 R	BTOCKB, H S P L, SHOTE P L, SHOTE P L, SHOTE P L, SHOTE	8007020300 8007070015* 8007030368 8007150471* 8007110262*	PR 70-143 70-1201 50-280 Q 50-321 G	SWITZER, D. C SWYLER, K. J SYLVIA, B. R SYLVIA, B. R SYLVIA, B. R.	9007300331* 8007210005 8007240005 8007020001 8007090057	50-213 F REB 50-338 F 71-5757 50-280 Q
ARK.R M FARKEY.R B FARKEY.R B FARKEY.R B ARK.R M	8007230325 8007220426 8007220440 9007220445* 8007270004	50-387 F 50-261 V 50-261 B 50-261 B 50-387 A	9 C.AHOTB 9 C.AHOTB 9 C.AHOTB 9 C.AHOTB 9 C.AHOTB	8007210082* 8007240349 8007270400 8007270844 8007300580*	70-1151 50-348	SYLVIA, B R. SYLVIA, B R. SYLVIA, B R. SYLVIA, B R. SYLVIA, B R.	8007090423 8007150462 8007160543 8007010422 8007030156	50-280 G 50-280 G 50-280 G 50-280 P 50-237 P
IEARNS, C F IEARNS, C F IEBSINO, O E IEELE, P W IEELE, T, A	8007170318* 8007290402 8007020461 8007150049* 8007170368	FOIA 40-1852 PR 70-1113 50-409 0	STOHR, JP STOHR, JP STOHR, JP STOIBER, CR SYOIDER, CR	8007270404 8007110250 8007210062 8007110276* 8007110282*	27-47 50-321 @ 70-1151 COMMISSION COMMISSION	BYLVIA.B R. BYLVIA.B R. BYLVIA.B R. BYLVIA.B R. BYLVIA.B R.	8007020456 8007020585 8007030151 8007310277 8007070200	50-338 P PR 50-337 P PR 50-339 E
IEEL.C.L IEIN.E L IELLO.V ELLO.V ELLO.V	8007280222 8007140364 7704160236 8007250649× 8007140078*	50-368 P PR 50-334 P 50-482 H 50-397 G	BTOIBER, C.R. BTOLLER, B.K. STONE, IT.A. STONEBURNER, W. STONEBURNER, W.	8007010278 8007070062* 8007150522* 8007030011* 8007030016*	COMMISSION CONTRACT 50-327 P 70-2478 70-2478	SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8007210030 8007070283 8007210092 8007080419 8007100273	50-280 Q 50-338 Q 50-280 S 50-280 P
EFTO.A EF	8007140097 8007090019# 8007110588 8007140169 8007020104	50-397 0 8ECY 50-846 # 50-280 0 50-498 0	STONE, R. J. STONE BURNER, W. STONE BURNER, W. STONE BURNER, W. STONE, R.	8004110523 8007030020* 8007310485* 8007310494* 8007240468*	PR 70-2478 70-2479 70-2478 50-335 H	SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8007110189 8007110202 8007170334 9007250545 8007270840	50-280 Q 50-337 P 50-280 Q 50-280 Q 50-280 Q
ELLO, V ELLO, V ELLO, V ELLO, V	8007010031 6007020267 8007140153 8007020298 6007140180	50-546 H 50-259 Q 50-259 G 50-321 Q 50-321 Q	STONE, W A STONE, J C. STRAHL, J F STRAND, N O STRAND, N O.	8007250057* 8007300086 8007140051* 8007310498 8007310502	QA999 TDPREP PR 50-397 Q 50-397 Q	SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR. SYLVIA, BR.	8007100159 8007110334 8007110359 8007110361 8007140158	50-337 P 50-280 Q 50-337 P 50-337 P 50-337 P
EFFO'A EFFO'A EFFO'A EFFO'A	8007090013 8007110131 8007110214 8007100295 8007100308*	50-346 0 50-254 0 50-346 0 50-546 0 50-646 0	BTRASMA, J STREET, P A STREETER, J F STREETER, J F STRELOH, R.	8007110488 8007210131* 8007220112* 8007240018* 8007070092	50-329 H 50-320 H 50-315 G 50-301 G PR	SYLVIA.B R SYLVIA.B R SYLVIA.B R. SYLVIA.B R SYLVIA.R R	8007140187 8007140406 8007150671 8007160507 8007160671	50-337 P 50-339 P 50-339 Q 50-339 P
TELLO, V ELLO, V ELLO, V ELLO, V	8007110544 8007160468 8007220140 8007250142 8007250633	50-546 H H18C 50-482 Q 50-546 A 50-482 H	STRONO, T R SU, T M SU, T M. SULLIVAN, R F SULLIVAN, J. H	8007270048* 8007170479 8007230252 8007280484* 8007150512*	State Prog 50-322 A 50-322 A 50-259 G 50-327 S	SYLVIA.E R. SYLVIA.E R SYLVIA.E.R. SYLVIA.R.R SYLVIA.B.R.	8007170175 8007170389 8007170412 8007170529 8007170601	50-337 P 50-280 R 50-280 F 50-280 Q 50-338 F
ELLO, V ELLO, V ELLO, V ELLO, V	8007280083 8007210288 8007210343# 8007220174 8007220187#	50-546 0 50-219 0 50-219 0 50-299 0 50-299 0	BUMMERB; J BUN, Y H BUNDARAK, R K, BUNDARAK, R, K BUNDERHAN, D H	B007290042# B007020364 B007170460 B007140642 B007140220#	PROJ RES RES FOIA	BYLVIA, B R BYLVIA, B R BYLVIA, B R BYLVIA, B, R BYLVIA, B R.	8007210435 8007170348 8007220431 8007220487 8007210244	50-280 P 50-280 V 50-338 R 50-339 P 50-339 P
ELLO, V ELLO, V ELLO, V ELLO, V, ELLO, V,	8007220191* 8007230138 8007250088 8007300038 8007300040*	50-293 0 0A999 50-388 0 50-54 0 50-54 0	BUNGTROM.R.F BUTTON,J W BUAN.W B. SWAN,W.B BWANBY.O.T.	8007150158 8007210275* 8007240329* 8007300394* 8007220291	PR 0A979 50-518 Q 50-518 Q 40-3453	SYLVIA, B. R. Sylvia, B. R. Sylvia, B. R. Sylvia, B. R. Sylvia, B. R.	8007210337 8007210347 8007210453 8007220384 8007230447	50-337 P 50-337 P 50-281 P 50-339 P 50-338 Q
Ì								

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	яонтиа	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BYLVIA, BR BYLVIA, BR BYLVIA, BR BYLVIA, BR BYLVIA, BR	8007240092 8007290220 8007240115 8007240149 8007250415	50-338 F 50-280 0 50-339 P 50-339 P 50-330 P	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007020390 8007110570 8007210188 8007240046 8007280379	50-364 A 50-518 H 50-322 A 50-445 A 50-364 A	TOLLISON, A C	8007080185* 8007110405 8007140395 8007140399* 8007150492	50-325 S 50-324 R 50-324 S 50-324 S 50-324 G
Sylvia, B R Sylvia, B R Sylvia, B R Sylvia, B R Sylvia, B R	8007280375 8007250379 8007250388 8007250430 8007280367	50-337 P 50-337 P 50-337 F 50-337 P 50-337 P	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007270202 8007280156 8007306033 8007306077 8007300080	50-364 A 50-338 F 50-373 A 50-369 F 50-438 A	TOLLISON, A C	8007150654 8007150665# 8007220464 8007220470# 8007220521	50-325 S 50-325 S 50-324 S 50-324 S 50-324 S
A G'YITA B G	800/280406 8007280423 8007280440 8007280444 8007280651	50-339 P 50-339 P 50-339 F 50-339 E 50-338 P	TEDESCO,R L TELFORD, J T TEMME, K E TERNEY, W B TEUFEL, D	8007310328 8007110550 8007210163 8007110248* 8007020554*	90-369 A TOPREP 40-2259 TOPREP 50-320 Q	TOLLISON, A C	8007250334 8007250341# 8007290826 8007290833# 8007290823	50-324 8 50-324 5 50-325 8 50-325 8
R SALVIA, B R BYLVIA, B R SALVIA, B R SALVIA, B R SALVIA, B R SALVIA, B	8007290700 8007300458 8007300183 8007300450 8007310370	50-338 P 50-339 P 50-339 P 50-339 P 50-281 P	TEUFEL, D THEOFANUS, T O THIES, A C THOM, T THOMAS, R D	8007150042 8007070380 8007140463 8007140556* 8007100003*	50-320 P F01A 50-269 Q 50-259 R 50-320 Q	TOLLISON, A C TOME, A TOME, A TOMLINSON, D P TOMLINSON, D P	8007290831# 8007280508 8007230205 8007140447# 8007280153#	50-325 8 NUREO NUREO 50-382 0 50-382 0
R AIVIVE R ALAIVAY R INSWONLANTS R INSWONLANTS R INSWONLANTS	8007310346 8007310384 8007140038 8007140038 8007220138	50-339 P 50-339 P 70-1308 70-1308 70-1308	THOMAS, R D	8006110739* 8007310339* 8007140657* 8007140663* 8007170556*	27-10 50-295 Q 40-2940 40-2940 50-315 Q	TOMPKINS, PA TOMPKIRS, BA TOMOUE, TH TOOLE, RJ TOOLE, RJ	8007020646 8007300408 8007070080* 8007250615 8007280483	50-295 Q 50-344 Q 50-10 Q 50-289 S 50-289 S
R INSMONLANTS R INSMONLANTS R INSMONLANTS R INSMONLANTS R INSMONLANTS	8007220147 8007220168 8007220170 8007220138 8007220147	70-1308 70-1308 70-1308 70-1308 70-1308	THOMAS, R. D. THOMAS, R. E. THOMAS, N. THOMAS, R. D. THOMAS, R. D.	8007140670* 8007250398* 8007150452* 8007160721* 8007240331*	40-2940 50-397 A 50-566 G 40-7982 70-1287	TOURTELLOTTE, J TOURTELLOTTE, J TOURTELLOTTE, J TRAGEGER, C M TRAGEGER, C M	8007070123 8007160594 8007230536 8007100109 8007300584	50-275 G 50-289 G 50-275 G CONTRACT 50-390 A
BZHAJKONSKI.R SZHAJKONSKI.R SZHAJKONSKI.R TAFT.J P TAM.P	6007220168 6007220170 6007230519 8007290475* 7906220186	70-1308 70-1308 70-1308 50-128 R 50-285 O	IJ H, BANDHT R. R. BANDHT N. H, BANDHT O. L, BANDHT N. H, BANDHT	8007030078 8007070070 8007010430 8007310153 8007020592	PRM 50-344 S 50-280 P 50-556 0 50-338 P	trammell.c Trammell.c m Trav[eso-diaz Trav[eso-diaz Trav[eso-diaz	8007020021 8007140529 8007150556* 8007150556* 8007250353	50-344 P 50-344 F 50-312 G 50-312 G 50-320 G
TAMBLING,T N TAMBLING,T N TAMBLING,T H TAPIA,J I. TAPIA,J I	8007210327* 8007240253* 8007300606* 8007110178* 8007240337*	50-346 Q 50-358 Q 50-346 Q 50-482 Q 50-498 Q	THOMAS, R H THOMAS, C O THOMAS, E B THOMAS, R D THOMAS, R, D	8007070326* 8007280089 8007170393 8007240138 8007290350	50-213 8 50-275 A 50-220 P 1&E 27-48	TREAKLE, K TREIBEL, W C TREVING, T TREVING, T TRIBBLE, J E	8007020127 8007020025 + 8007010982 + 8007140650 8007170325	FOIA CONTRACT CONTRACT FOIA 50-271 G
TAPIA, J TAPIA, J I TARAS, D N TAUCHE, W TAWA, K	8007150134* 8007280153* 8007300066 8007220499* 8007100287*	50-290 0 50-382 0 PR TOPREP XPORTLIC	THOMPSON, D THOMPSON, H L THOMPSON, H A THOMPSON, H A THOMPSON, W E	8004240316 8007230256# 8007020281 8007020708 8007230195#	I&E FDIA WASTE MOT WASTE MOT 50-289 F	TRIMBLE, D C	8007020194 8007020210 8007020003 8007020201 8007010354	50-313 0 50-313 P 71-5957 50-313 Q 50-313 P
TAYLOR.C W TAYLOR.C W TAYLOR.R O TAYLOR.J J TAYLOR.J B	8007100028* 8007100044* 8007180574* 8007110492 8007280285	70-143 70-143 50-445 O PR FOIA	THOMPSON, C M THOMPSON, D THOMPSON, D THOMPSON, D	8007220503* 8007140550 8007230143 8007230148 8007240133	TOPREP 50-219 S 13E 50-54 S 50-289 S	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007010369 8007010527 8007010436 8007010470 8007010407	50-313 F 50-368 8 50-368 8 50-313 R 50-368 8
TAYLOR, O A TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, B J	8007210017 8007090199 8007300294 8007080312 8007230594	RES TOPREP PRM TOPREP 50-409 D	THOMSEN, F T THOMSEN, D	8007100171 8007230797 8007230797 8007250351 8007020313*	50-522 0 50-522 0 50-522 0 50-522 0 50-320 U	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007010437 8007070148 8007080160 8007080171 8007180095	50-348 9 50-313 F 50-348 6 50-348 6 71-9108
TAYLOR, J H TAYLOR, J H. TAYLOR, J H TAYLOR, J H TAYLOR, L L	8007170417 8007170421* 8007230239 8007240001 8007290145	TOPREP TOPREP 50-320 8 TOPREP NUREO	THORPE.JR TIEPEL.E.W TIEPEL.E W TIEPEL.E W TIERELY.F P	8007240367 8007210171 8007210075 8007220303 8007160660	PR 40-8502 40-8502 40-8304 50-282 B	TRIMBLE, D C	8007300325* 8007100143 8007280646 8007300055 8007070253	90-313 Q 90-313 R 50-368 8 PR 90-313 P
TEDEBCO, R. L.	8007010227* 8007070575 8007020302 8007030175 8007030176	FOIA 50~364 A 50~410 G 50~389 A 50~397 A	TIERNEY, F P TILLMAN, A TILLMAN, A TIMKO, D R TOBIN, W J	8007250340 8007150107* 8007110113* 8007160422* 8007010089	50-282 \$ 50-261 0 50-335 0 50-334 R 50-327 \$	TRIMBLE, D C	8007090287 8007180429 8007080144 8007300335* 8007090328	50-313 P 50-313 P 50-368 8 50-313 0 50-368 8
TEDEBODAR, L TEDEBODAR L TEDEBODAR L TEDEBODAR L TEDEBODAR L	8007030197 8007030201 8007010184 8007010228 8007010237	50-460 A 50-491 A 50-413 A 50-559 A 50-416 A	TOBIN, W J TOBIN, W J TODD, W E TOKAR, M TOKAR, M	8007110113* 8007160761* 8007210259 8007010161* 8007010218*	50-335 G 50-338 Q PR FOIA FOIA	TRIMDLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007100148 8007140396 8007150641 8007160348 8007150647	50-313 H 50-368 S 50-313 S 50-368 P 50-368 S
TEDESCO.R L TEDESCO.R L TEDESCO.R.L TEDESCO.R L TEDESCO.R L	8007010243 8007010550 8007010557 8007010558 8007010560	50-461 A 50-528 A 50-329 A 50-458 A 50-361 A	Tokar. M Toll 160% a C Toll 160% a C Toll 160% a C Toll 160% a C	8007010222* 8007240196* 8007100377* 8007010556 9007010564*	FOIA 50-324 Q 50-324 Q 50-325 B 50-325 B	TRIMBLE, D C	8007150483 8007150394 8007150595 8007150530 8007170281	50-360 8 50-313 P 50-313 8 50-313 8 50-313 F
TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8007010561 8007010563 8007020214 8007020219 8007020227	50-354 A 50-311 P 50-440 A 50-363 A 50-498 A	TOLL 160 N, A C	8007010501 8007010509* 8007010513 8007010521* 8007020334	50-325 B 50-325 B 50-325 B 50-325 B 50-324 B	TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C	8007220495 8007290603 8007210396 8007240120 8007210381	50-313 Q 50-313 P 50-368 B 50-313 P 50-368 R
Tedesco, R. L Tedesco, R. L Tedesco, R. L Tedesco, R. L Tedesco, R. L	8007020228 8007020232 8007020252 8007020257 8007020265	50-327 P 50-359 A 50-518 A 50-352 A 50-514 A	TOLLISON, A C	8007020361+ 8007160632 8007070234 8007070237+ 8007080180	50-324 8 50-324 8 50-325 8 50-325 8 50-325 8	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007210420 8007210404 8007240174 8007180312 8007240148	50-313 R 50-313 B 50-313 S 50-313 S 50-313 S

AUTHOR	ACCESSION NUMBER		JECT EGORY	AUTHOR	ACCESSION NUMBER	CATE		AUTHÓR	ACCESSION NUMBER	SUBJECT CATEOOR	
TRIMBLE, D C TRIOLO, X TRIPP, L E TRIPP, L E TRIPP, L E	8007280504 8007020153 8007020225 8007170645 8007220285	* 50-33 * 50-33	LIC 14 a 17 a	UHRIG, R E UHRIG, R E ULLRICH, W T ULLRICH, W T UPRIGHT, C M	8007280647 8007290624 8007210403 8007280649 80071505113	50-33 50-33 50-27 50-27	5 F 7 9 7 6	VARGA, S. A.	8007100156* 8007100165* 8007210311 8007210323* 8007010192	50-261 50-261 50-250	
TRIPP, L E TRIPP, L E TRIPP, L E TROJANOWSKI, R TROJANOWSKI, R	8007300328 8007280244 8007300321 8007110276 8007240374	* 50-35 * 50-35 * 50-32	4 @ 4 @ 1 @	UPRIGHT, C M UPRIGHT, C M UPRIGHT, C M UPRIGHT, C M UPRIGHT, C M	8007220086 80071608304 80071000614 80071800114 80071704294	50-33 50-33 50-32	5 Q 5 Q 7 Q	VARQA, BA VARQA, BA VARQA, BA VARQA, BA VARQA, BA	8007100109 8007100106* 8007100114* 8007170423 8007170427*	50~286 50~316	6666
TROMBETTA, R TROMBETTA, R TROMBETTA, R TROSKOSKI, W TROUP, G L	8007140238 8007140516 8007210299 8007210255 8007290401		0 Н 0 Р 3 С	UPRIGHT, C H UPTON, R T UTLEY, E E UTLEY, E E UTLEY, E E	8007280425> 8007270253+ 8007210273 8007010416 8007010425		2 H 5 P	VARQA, S A VARQA, S A VARQA, S A VARQA, S A VARQA, S A	8007170434* 8007170245 8007170447 8007180191 8007210037	50-247 50-247 50-334	PFPP
TROUP.O L TROWERIDGE.G F TROWERIDGE.G F TROWERIDGE.G F TROWERIDGE.G F	80072904104 8007020482 8007020621 8007020482 8007020621	27~47 50~320 50~320 50~320 50~320	2 G 3 G	OTLEY, E E OTLEY, E E OTLEY, E E	8007010307 8007010324 8007010342 8007010384 8007010423	50-24: 50-32: 50-32: 50-26: 50-32:	F	VARQA.8 A VARQA.8 A VARQA.8 A VARQA.8 A VARQA.8 A	8007(40808 8007(80044 8007(80046* 8007(80053* 80072(0055	50~296 50~296	H P P P
TROWERINGE.O F TROWERINGE.O F TROWERINGE.O F TRUBATCH, S TRUBSELL, H H	8007140006 8007230604 9007230604 8007240137* 8007170679	50-320 50-289 50-289 NUREG 40-810	7	OTLEY.E E UTLEY.E E UTLEY.E E	8087010514 8007240151 8007150626 8007210415 8007250420	50-261 PR 50-261 50-324 50-261	P	VARQA, 9 A VARQA, 9 A VARQA, 9 A VARON, C VERRELLI, D M	8007210059 8007210078 8007300029 8007150749 8007140641	50-247 50-348 FDIA	P F P
TUITE,P T TUMA.A T TURK.S E TURK,S E TURK,S E	9007170286+ 8007100116 8007030291 8007170261 8007230741	50-219 REGOD 70-290 50-445	9	UTLEY, E E UTLEY, E, E UTLEY, E, E UTLEY, E E VALENTINE, P C	8007280679 8007290690 8007290686 8007290723 8007310446	50-241 50-241 50-24 50-324 50-275		VERRELLI, D VERRECCHIA, P VERRELLI, D M VILLALVA, I VILLFORTH, J C	8007090389 8007280274 8007180487* 8007020095* 8007140640	FOIA	P P
TURK, S E TURK, S E TURK S E TURNER, E A TURNER, E A	8007230748 8007250456 8007030274* 8007150075* 8007010072	50-445 70-290 70-290 50-498 50-498	9 9 0	VALORE,C J VALORE,C J VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8007110112 8007110112 8007280043 8007250357 8007300514	50-272 50-272 50-528 50-528 50-528	0 0 0 0	VILLFORTH. J C VISBING. O S VDEGELI. R J VOGEDING. E L VOGT-LOWELL. R	8007150084 8007230073 8007270040 9007150652* 8007240281*	50~313 TOPREP	F P
TURNER, E A TURNER, E A TURNER, E A TURNER, E A TURNER, E A	8007020478* 8007100433 8007100443 8007160219 8007070306	50-498 50-498 50-498 50-498 50-498	5	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8007020728 8007100077 8007290523 8007210546* 8007020531	PR PRM 50-528 50-528 50-528	g g s	VOIGHT, A F VOIGT, H H VOIGT, H H VOIGT, H H VOLGENAU, E	8007240157 8007140370 8007140378* 8007140378* 8007020698	71~5088 50~452 50~452 50~452 6 M18C	9
TWEED, R M TWEED, R M TYE, L S UDALL, M K	6007300545 8007300552 8007300537 8007010284 8007180431*	10cfr 10cfr 10cfr 0rg Commiss	31 CN	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E C	8007020525 8007080227 8007300132 8007300530 8007090285	50-528 50-528 NUREO 50-528 50-528	8 A Q A	VOLLEN,R J VOLLEN,R J. VOLLMER,R,H VOLLMER,R H VON ZELLEN,B H	8007080055 8007080055 8007020737 8007300030 8007220589	50-367 G 50-367 G FINANCIAL FINANCIAL 50-10 D	•
UDALE, H K UDALE, H K UDY, A C UDY, A C	8007180427* 8004280239 8007110809 8007250306 8007290163	COMM158 50-352 PRM 50-325 50-324		VAN BRUNT, E E VAN BRUNT, E E VAN DRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8007150089 8007110398 8007140207 8007140339 8007290516	PR 50-528 50-528 50-528 50-528	A \$ 8 9	VONHERRMANN, J VONHERRMANN, J VORDERBRUEOGEN VORDERBRUEOGEN VORGE, J Y	8007280508 8007230205 8007170270* 8007310516* 8007100095*	NUREQ NUREQ 50~528 Q 50~528 Q 50~261 Q	•
UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	800724007\$ 8007080330 8007220543 8007100128 8007070100*	50-250 50-335 50-250 50-250 50-335	R R R G	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8007140546 8007160652 8007170470 8007310456 8007290722	50-530 50-528 50-528 FR 50-528	9 9 8	YRANKEN, J V WAOMAN, N A WAOMER, P C WAOMER, A O WAOMER, B	8007140439# 8007170311 8005190062 8007100124# 8007110144	PR NUREG 50~285 P 50~416 Q 50~302 H	ı I
UHRIG.RE. UHRIG.RE UHRIG.RE UHRIG.RE	8007160810* 8007220069* 8007020296 8007160599 8007100021	50-335 50-335 PR 50-389 50-335	0 0 8 0	VAN BRUNT, E E VAN BRUNT, E E VAN DE POLL, (/ VAN NESB, S C VAN PAABBEN, H L	8007290773 8007280585 8007310179* 8007100178* 8007170618	50-528 50-528 GA777 50-272 NUREQ	8 K Q	WAGNER, P. C WAGNER, P. C WAGNER, T. E WALBRIDGE, W. C WALBRIDGE, W. C	8007020067 8007170658 8007140875 8007250370 8007310477	50~285 P 50~285 P 50~346 M 50~312 Q 50~312 Q	
UHRIGRE UHRIGRE UHRIGRE UHRIGRE UHRIGRE	8007100025 8007240263* 8007030221 8007110199 8007310220*	50-250 50-250 50-335 50-250 50-389	о 9 Р	VAN RODYEN, D VAN RODYEN, D VAN WINKLE, N, VANDENBURGH, D VANDENBURGH, D	8007220053 8007180253 8007210458 8007140701 8007180057	RES RES 50-247 NUREO 50-29	P G	HALBRIDGE,W C WALBRIDGE,W C WALKER,R.D WALKER,F M WALL,L B	8007240123 8007250348* 8007170103* 8007220360* 8007210141	50-312 P 50-312 P 50-373 Q 50-327 R 40-8745	
UHRIGAR E UHRIGAR E UHRIGAR E UHRIGAR E	8007080140 8007230181 8007090286 8007110261 8007210064	50-250 PR 50-335 50-250 50-250	р Р С	VANDENBURGH, D VANDENBURGH, D VANDENBURGH, D VANDELL T E	8007010403 8007170116 8007170321 8007070407 8007170635*	PR 50-29 50-309 PR 50-329	a a	WALLIS, O B Walske, C Walske, C Walske, C	8007300399 8007070060* 8007310445* 8007230751* 8007140047	TOPREP CONTRACT PR COMMISSION PRM	
UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8007110756 6007210060 8007250312 8007140375 8007250272	50-250 50-387 50-335 50-250 50-335	P G G G	VANDENBURGH, D VANDENBURGH, D VANDGORN, P VANDDORN, P VANSICKEL, J	8007310464 8007280439 8007310235* 8007310245* 8007320371*	PR 50-29 50-369 50-416 50-331	P G G R	HALBKE,C WALEKE,C WALTERB,D K WALTER,J F WAMBACK,T V	8007310441 8007280016 8007070169* 8007160457 8007110124	PR PR 50-387 G NUREO 50-255 P	
UHRIGIR E UHRIGIR E UHRIGIR E UHRIGIR E UHRIGIR E	6007250282 6007300558 8007310084 8007220374 8007220380	50-250 50-250 50-250 50-250 50-250	G G P P	VARANINI,E E VARANINI,E E VARDEL,T E VARQA,S A VARQA,S A	8007030104 8007280044 8007150023* 8007020139 8007020159	PR PR 50-493 M18C 50-329	Q A	WAMBACH, J L WAMBACH, T V WANDKE, N E WANDKE, N E WANDKE, N E	8007270180 8007280114 8007280387 8007010484 8007010473	RES 50-255 P 50-304 S 50-275 S 50-275 S	
NHRIO'S E NHRIO'S E NHRIO'S E NHRIO'S E	8007220379 8007230442 8007230454 8007280531 8007280562	50-235 50-250 50-250 50-250 50-250	6 E E B E B B B B B B B B B B B B B B B	VARGA.S A VARGA.S A VARGA.S A VARGA.S A	8007020109 8007020357* 8007020330 8007210314* 8007100150	50-247 50-247 50-261 50-250 50-261	የ የ የ የ	Wandke, n e Wang, t Wang, c h Wang, c h Ward, b	8007160668 8007080219 8007150559 8007150649 8007220073*	50-304 8 40-299 50-104 H 50-243 P 40-8771	

AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARD, K D WARD, B WARD, K D WARD, E C WAREMBOURG, D	8007230333* 8007220048 8007230273* 8007030178 8007080254	50-346 G 40-8771 50-373 G 50-282 R 50-267 B	MENSLANSKI, FA WENSLANSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA WERLING, JA	8007180025* 8007230355* 8007030021 8007310168* 8007010396	50-508	WIDNER, W A	8007220281 8007080322 8007090337 8007140397 8007140384	50-321 Q 50-321 P 50-321 Q NUREQ 50-321 Q
HAREMBDURG, D HAREMBDURG, D HAREMBDURG, D HAREMBDURG, D HAREMBDURG, D	8007080268 8007080422 8007010344 8007010496 8007080210	50-247 S 50-267 S 50-267 R 50-267 S 50-267 S	WERLING, JA WERLING, JA WERLING, JA WERLING, JA WERLING, JA	8007010400+ 8007010456+ 8007010526 8007010536+ 8007070296	50-334 S 50-334 S 50-334 S 50-334 S 50-334 S	WIDNER, W A	8007250292 8007316275 8007316287* 8007220422 8007280634	50-321 Q 50-321 Q 50-321 Q 50-321 Q
Waremedurg, D Waremedurg, D Waremedurg, D Waremedurg, D Waremedurg, D	8007080289 8007080406 8007100173 8007230543 8007230548	50-267 B 50-267 R 50-267 S 50-267 S 50-267 B	WERLING, J A WERLING, J A WERLING, J A WERLING, J A WERLING, J A	8007070334 8007070340 8007180317 8007220430 8007250315	50-334 5 50-334 8 50-334 8 50-334 6 50-334 5	WIDNER, W A WIDNER, W A WIDNER, W A WIDNER, W A WIDDEF, M P	8007280541 8007290618 8007280538 8007280514 8007140003	50-321 0 50-321 0 50-321 0 50-321 F 50-289 0
HAREMEOURO, D HARINO, J P HARNICK, R F HARNICK, R F HARNICK, R F	8007230534 8007010244* 8007140494* 8007230328* 8007300309*	50-267 B FOIA 50-263 G 50-305 G 50-263 G	HERLING, J A HERNER, J HERNER, B J HEBCDIT, H M HEBCDIT, H M	8007300383 8007110416* 8007280589* 8007110168* 8007160764*	50-334 8 50-346 8 50-346 8 50-461 0 50-461 0	WIDOFF.M P WIDOFF.M P WIDOFF.M P WIESEMANN.R A WIESEMANN.R A	8007140003 8007290777 8007290779 8007180357 8007220488*	50-287 0 50-287 0 50-287 0 50-244 P TGPREP
Wasserbach, a e Wasserbach, a e Wasserbach, a e Wasserbach, a e Wasserbach, a e	8007030209* 8007180250* 8007160779 8007010508 8007030204	PR 50-320 H PR 50-320 H PR	WESCOTT, H M WEST, J T WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F	8007300157# 8007110493# 8004240281 8007150171# 8007220197#	50-483 Q 50-320 P 50-267 S 50-285 Q 50-313 Q	Wigginton, D Wiggin, E A Wiggins, E J Wiggins, E	7904030186 7904100156 8007110031 8007100361 8007170157	50-334 P 50-334 C PR CONTRACT CONTRACT
WATFORD, M WATKING, D WATGON, J H WEAVER, C L WEAVER, J	8007150633* 8007070049* 8007150013 8007070264 8007210390	50-261 R 50-514 D 50-497 H 50-10 D 50-397 U	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTFALL, R M WETTERHAHN, M J	8007150091* 8007150136* 8007300354* 8007110493* 8007020407	50-267 G 50-298 G 50-313 G 50-320 P PR	WILBORN, E R WILCOX, J D WILCOX A WILD, P A	8007230257# 8007150466# 8007160872# 8007020655 8007140585	50-313 0 50-327 5 50-416 0 50-320 H 50-339 8
WEAVER, J HEBB.M WEBB.R E WEBER, D A WEBSTER.E H	8007300367 8007280555 8007300332 8007250186 8007230362	50-397 U 50-272 Q 50-272 Q 50-272 Q 50-313 P 50-280 S	HETTERHAHN, IS J NETTERHAHN, IS J WHARTON, R J WHARTON, R J WHATLEY, H E	8007150509 8007150509 8007140034* 8007140034* 8007180478*	50-272 0 50-272 G 50-361 G 50-361 G	NILD.P A WILLIS.C A WILLIAMS.R E WILLIAMS C C WILLIAMS.C C	8007140401 8007140798 8007010562* 8007150118* 8007160479*	50-339 S REGGD 40-1162 50-454 Q 50-546 Q
WEEKS, E. D WEONER, M 8 WEOST, W WEIC, C H	8007150568 8007100135 8007160240 8007210148* 8007280435*	50-133 R REOQD 50-142 F 50-458 Q 50-346 Q	WHEATLEY,P D WHEELER,H WHEELER,R V WHIPPLE,G H, WHITE,J G	8007280186 8007160405 8007140599 8007080357* 8007160569*	RES PR PR PR 50-454 K	0 0,8MAILLIN 0 0,8MAILLIN 0 0,8MAILLIN 1 0,8MAILLIN 1 0,8MAILLIN 1 0,8MAILLIN	8007230019* 8007230700* 8007230710* 8007280315 8007250117*	50-456 Q 50-373 Q 50-546 Q 71-9010 COMMISSION
WEINER,R E WEINER,R E WEINEMANN,R A WEINS,A J WEINS,A J	8007140190* 8007170390 8007220496* 8007310216 8007310471	50-247 P 50-344 P TOPREP NUREO NUREO	WHITESELL, D E WHITESELL, D E WHITESELL, D E	8007110493* 8007220154* 8007100014* 8007010051* 8007160411*	50-320 P 50-482 Q 50-320 Q QA979 QA979	WILLIB, E HILLIAMS, F C HILLSEY, W 8 WILSON, B D WILSON, W E	8007110406* 8007300569 8007310414 8007310270* 8007110231*	50-324 R PR 50-277 R FOIA PR
WEISS, J. D WEISS, E. R WEISS, D WEISS, D WEISS, E. R	9007010106* 8007240044* 8007010252 8007100462* 8007150552	71-5768 COMM188ION 70-734 71-9094 70-143	WHITESELL, DE WHITESELL, DE WHITE, L DWHITESELL, DE WHITESELL, DE WHITE, M	8007100337* 8007210275* 8007230008* 8007210264* 8007210027	QA999 QA999 50-244	WILSON WE WILSON WE WILSON B A WILSON B P WILSON F R	8007110239* 8007110225 8007030211 8007140546* 8007170317*	PR PR TOPREP SECY 50-482 A
WEISB,E R WEISB,B H WEISB,B H WEISB,B H WEISB,B H	8007080043 8007160145 8007160155 8007160160 8007160167	50-289 0 50-320 H 50-320 H 50-320 H 50-320 H	WHITESELL,DE WHITE,LD WHITE,WH WHITE,WH WHITE,LD	8007220155* 8007020018 8007100062* 8007100062* 8007180141	QA999 50-244 Q 50-344 Q 50-344 Q 50-244 Q	MICSON, J N MICSON, B D MICSON, B D MICSON, J N	8007020421 8007280131 8007280407 8007030239 8007010297	PR YPORTL1C XPORTL1C 50-322
WE168.B H WE168.B H WE168.D WE168.E R WE188.E R	8007140170 8007140183 8007280090 8007140022* 8007140018	50-320 H 50-320 H 70-371 50-289 Q 50-289 G	WRITE, L D WHITENER, H L WHITE, L D WHITE, L D WHITE, E B	8007240145 8007280425* 8007070342 8007080272 8007100257*	PR 50-270 Q 50-244 F 50-244 P PR	MILSON, J L HILSON, J L	8007080051 8007010340 8007010394* 8007010429 8007010442*	50-329 0 50-281 8 50-281 6 50-280 8 50-280 5
WEI88.E R WEI88.E R WEI88.E R WEI88.E R WEI88.D	8007140022* 8007300039 8007300043 8007250043 8007180372	50-287	WHITE, L D	8007250498 8007220403 8007290740 8007280633 8007310350	50-244 Q 50-244 P 50-244 P 50-244 S 50-244 F	MICSON, J C MICSON, J C MICSON, J C MICSON, J K	8007140519 8007070389 8007070397* 8007070224 8007070229*	50-322 F 50-280 B 50-280 B 50-280 S 50-280 B
WE188.D WE188.D WE188.D WE188.J D WE188.E R,	8007210104 8007250363 8007280027 8007210098 8007230229	70-820 70-371 70-754 70-33 FOIA	WHITE, L D WHITE, L D WHITMAN, O D WHITMEY, O G WHITMEY, O O	8007310378 8007310401 8007310554 8007080192* 8007180704*	50~244 F 90-244 P NUREO 50-293 S 50-293 R	MILSON, R P WILSON, J N WILSON, J N WILSON, B D	8007110087 8007170339 8007170347* 8007170351* 8007310042	PR 50-322 A 50-322 A 50-322 A XPORTLIC
WEISB.E R WEISS.E R WEISB.D WEISB.D	8007210495* 8007210487 8007210495* 8007230731 8007230044	50-289 G 50-289 G 50-289 G 40-8681 70-1287	WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L	8007010591 8007020079 8007030358 8007070147 8007150651*	40-8502 40-8502 40-8502 40-8502 40-8502	MILSON, B D WILSON, J L WILSON, J N WILSON, J L	8007310044 8007140249 8007140259* 8007240464 8007180319	APORTLIC 50-280 S 50-280 S 50-322 A 50-281 S
Weigg. D Weigg. D Weigg. D Weigg. B Weigg. B	8007250049 8007250161 8007280045 8007280101 8007240133	70-8 70-754 70-2623 70-687 50-287	WICHERS, D L WICHERS, D L WICHERS, D L WIDNER, W A	8007150644 8007210548# 8007210542 8007210101 8007110259#	40-8502 40-8502 40-8502 40-8502 50-321 Q	WILSON, J L WILSON, J R WILSON, J L WILSON, J L	8007180327* 8007310064 8007230133 8007280607 8007280618*	50-281 S XPORTLIC 50-322 A 50-280 S 50-280 S
WEISS,E R WEISS,E R WEISZ,O WELLER,R A WENSLAWAKI,F A	8007290781 8007290781 8007100094 8007170359* 8007150130*	DRG DRG PR 50-320 G 50-344 G	WIDNER, W A	8007240264* 8007090074 8007010474 8007280128* 8007080287	50-321 Q 50-321 Q 50-321 P 50-321 Q 50-321 P	Wilson, J L Winars, L F Winters, C E Withrow, G C Wofford, A W	8007280625 8007100017 8007240228 8007180664 8007160867*	50-280 8 PR 70-1042 50-155 Q 50-372 Q

AUTHOR	ACCESSION NUMBER	SUBJECT	Υ	POHTUA	ACCESSION NUMBER	SUBJECT					
JHLSEN, W D	8007080285×	TOPREP		YIN, I T	6007230087*	50-35B	a	ZAHLER R E	8007180391	50-289	0
OLF, J F	8007020623	50-320	G.	YIN, I T	8007230758*	50-295	ā	ZAHLER, R E	8007180421	50-289	ö
OLF, J F	8007080002	50-320	Ç	YIN, I T	8007310316*	50-266	Ġ.	ZAHLER, R E	0007180391	50-269	ō
JLF, J F	8007140006	50~320	٣	YODER, R C	8007300014	PR		ZAHLER, R E	8007180421	50-287	0
OLF, J F	8007220006	50-320	¢	YORE, J R	8007070050*	50-514	D	ZAHLER. R E	8007230506	50-289	0
DLF,S J DLFE,S J	8007290746	50-466	0	YOUNGBLOOD, B J	8007150047	50-280	H	ZAHLER.R E	8007230514*	50-289	Q
DLFE, S J	8007020434 8007030061	50-466 50-466	0	YOUNG M F	8007290152	NUREC	_	ZAHLER, R E	8007230610	50-289	0
DLFE, B J	B007030081	50-466	ö	YOUNG, T	8007240395* 8007010571	50-275	Q.	ZAHLERIR E Zahlerir e	8007230514* 8007230610	50-287 50-289	0
DLFE. S J	8007250703	50-466	Ğ	YOUNGBLOOD, B J	8007020488	50-369 50-281	H	ZAHLER.R E	8007290533	50-346	М
OLFE, S J	8007300356	50-445	М	YOUNGBLOOD, B J	8007070203	50-339	P	ZAHLER.R E	8007290533	50-346	м
JLIVER, J	8007220545	50-358	G	YOUNGBLOOD, B J	8007090378	50-387	A	ZAJACIL D	8007310245*	50-416	O.
TINES' 1	8007220965	50-359	0	YOUNGBLOOD, B J	8007180339	50-387	G	ZARAKAB, P	8007230044	PR	
DLTNER, E	8007230124*	70-371		YOUNGBLOOD, B J	8007110137	50-482	F	ZARAKAB, P	8007090279	50-3	₽
ז , פאכ	8007170571	40-299		ADONOSCOOD'S &	8007110154	50-483	F	Zarakas, p	8007110396	50-247	8
DNO.T	8007140371 8007010337	40-299 50-309	8	YOUNGELOOD, B J	8007110583	50-369	A	iarakas, p iarakas, p	8007140375 8007220476	NUREQ 50-247	
300. E. C	6007080413	50-307	8	YOUNGBLOOD, B J YOUNGBLOOD, B J	8007180440 8007170685	50~387	Ġ	I ARAKAS, P	8007220504	50-247	R P
300' E C	6007210428	50-309	ŝ	YOUNGBLOOD: B J	8007180039	50-369 50-339	A P	ZARAKAB, F	8007220523	50-3	Ŕ
DODHEND, C P	6007100643	50-341	ō	YOUNG, T	8007310327*	50-337	Č.	ZARAKAB, P	8007230471	50-247	P
DODHEAD, C P	8007300428	50-409	Ç	ADAMOBEOGO'B 1	8007170449*	50-339	P	ZARAKAS, P	8007240127	50-3	1
DODRVFF.R L	0007300580*	50-321	G.	YOUNGDAHL R C	8007140372	50-3	P	4 GANARAS	8007240169	50-247	8
DODS, R	8004240210	182		AUGMICATOOD'B 1	8007180062	50-443	A	ZARAKAB, P	8007290682	50-3	H
DODS: L G	800714044B 8007180055	PRM		AGNWOBFOOD'B 1	8007180049	50-347	A	ZARKAS, P	8007220454	50-247	Р
		50-412	a	AUNOBFOOD'B 7	8007180520	50-410	A	ZECH, Q Q	8007100149	ACRB	
OLEVER, E J	8007010348	50-412	Q	YOUNGULOOD, 8 J	8007230127	50-969	A	ZEFF, D W	8007100397*	70-1201	
ODLEVER, E J	6007210014	50-412	Q.	YOUNGBLOOD, B J	8007230547	50-482	24	ZELAC, R E	8007100007	PR	
RAY.JR RAY.JR	#4410E2700B	50-287	Č.	YOUNGBLOOD, B J	8007230552*	50-402	M	ZELLNER, R J	8007280270	FOIA	_
ICHT.B L	6007230142 6007140258	50-289 XPDRTLIC	Ģ	ADONGBEDOD'B 1	8007280013	50-462	M	ZENTNER, H A	8007210331*	CONTRACT	
				YOUNGBLOOD, B J	8007280015	50-462	М	ZENTNER, IS A	8007140203*	CONTRACT	
HOHT, F 5	8007030365	PR		YOUNGALODD, B J	8007230622	50-443	н	ZOLICZYNBKI,J B	8007210512#	50-59	R
H A TROSS	8007020013	40-4492	_	YOUNGBLOOD, B J	8007280166	50-369	A	I IBULEKY, H	8007250494*	70-820	_
RIGHT,O C RIGHT,X H	8007140493*	50-155	Q	AONWORFOOD B 1	8007270004	50-389	M	ZIMMERMAN, R P	8005230131	50-245	8
RICHT, K H	8007100084 8007100087	40-4492 40-4492		ADONOBEDOD'B ?	8007290019	50-367	Ą	ZIMMERMAN, R P	8007310365* 8007140503	50-245 REB	a
				ADANOBEDOD'B 1	8007250181	50-369	A	ZITTEL. H. E.			
'IQHT' O C	8007230303*	20-331	g .	YUAN, O	8007070084	PR	_	ZITTEL, H E	8007170648	RES	_
RIGHT, R W	0007270361*	50-438	a	ANHV8' O L	8007100014*	50-320	q	ZULLA: 8 8	8007250317*	50-286	a
RECHTIB L	8007150030 8007150034	XPORTLIC		YUHAB, O P	8007180025* 8007230355*	50-50B 50-224	g g	ZULLA, 8 8	8007010452	50-284	8
RICHT, D L	8007150039	XPORTLIC XPORYLIC		YUHAB, Q P YUNDT, C P	8007080418	50-344	6	ZULLA, S. B ZULLA, S. S	8007010448 8007080350	50-286 50-286	6
ICHT. B L	8007160824	XPORTL10		YUNDT, C P	8007140312	50-344	R	ZULLA, 6 9	8007080355	50~286	8
RIGHT. B L	8007310511	XPDRTLIC		YUNDTIC P	8007150581	50-344	B	ZULLA. B	6007140333	50-286	8
), G	8007230620	40-8727		YUNDTIC P	8007150820	50-344	S	ZULLA, B S,	8007210466	50-286	G
), K	8007170262*	XPDRTL IC		YUNDT, C. P	8007280648	50-344	8	ZULLA, S S.	8007290052	50-284	8
ILLER. G E	8007030215	50-461	a	YUNDT, C. P.	8007280545	50-344	s	ZULLA, S S	8007210376	50-286	R
LLER. O E	8007160626	50-461	8	YUNDT, C.P.	8007280563	50-344	6	ZULLA, B B	8007210418	50-286	8
PTTKE.Q Mana.K	8007020346 8007280464	XPORTLIC XPORTLIC		ZAHLER, R. E ZAHLER, R. E	8007020633 8007020633	50-289 50-289	0	ZULLA, B 8	8007310426	50-286	8
NDELL.L A	8007260464		Q.	ZAHLER, R E.	8007140224	50-289	ŏ	ZUMBRUN, R A ZUMBRUN, R A	8007100257* 8007100257*	PR PR	
WN. A D	8007150133	90-313 PR	u	ZAHLER, R E	B007140224	50-289	č	ZURAKOWSKI, P R.	8007100257*	40-2940	
						·	-				
								ZWETZIQ.Q B	8007320337* 8007310301*	50-73 50-312	g g
								THEITIMIN B	900/310301#	20-312	u

The subject category column in this Index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

A) TIPO	+00555 (SN	cum Icor		AUTHOR	ACCESSION	SUBJECT
AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AFFILIATION	NUMBER	CATEGORY
SH Co , Minnesota Mining & Mfg Co AGIP USA: Inc Accuracy in Media Advanced Technology, Inc	8007020415 8007310520 8007280294 8007090377 8007140248	MISC XPORTLIC FOIA FOIA FOIA			8007150714 8007160549 8007160579 8007160861 8007210265	50-348 P 50-348 Q 50-364 A 50-348 S 50-348 Q
Advisory Council on Historic Preservation Assospace Corp Agriculture.Dept of Agriculture.Dept of, Forest Service Air Porce,Dept of	8007210141 8007170418 8007280333 8007290421 8007020444	40-8745 NUREQ 40-8745 50-10 PR	D		8007210499 8007220410 8007220486 8007220510 8007220510	50-348 P 50-364 A 50-364 A 50-348 P 50-348 P
Air Products & Chemicals, Inc Alabama Power Co	8007150077 8007280383 8007010406 8007010412* 8007010424	PR XPORTLIC 50-348 50-348 50-364	S S A		8007220515+ 8007220554 8007220554 8007220558 8007220559	50-348 P 50-348 P 50-348 P 50-348 P 50-348 P
	8007010444 8007010446* 8007010489 8007070168 8007070176*	50-348 50-348 50-364 50-348 50-348	S S A R R		8007230403 8007230403 8007230403 8007230485 8007230492	50-364 A 50-348 P 50-348 P 50-364 A 50-364 A
	8007070180# 8007070190# 8007070194# 8007070199# 8007070204#	50-348 50-348 50-348 50-348 50-348	ብ ጽ ጽ ብ		8007230510 8007230546 8007230553 8007230553 8007230567	50-364 Q 50-364 A 50-348 P 50-364 A
	8007070208* 8007070214* 8007070217* 8007070219* 8007070223*	50-348 50-348 50-348 50-348 50-348	R R R R		8007230592 8007240071 8007250320 8007250479 8007280052	50-364 A 50-364 A 50-364 A 50-348 Q
	8007070226* 8007070228* 8007070230* 8007070232* 8007070292	50-348 50-348 50-348 50-348 50-364	R R R R		8007280490 80072803 57 8007280 5 41 8007290 637 8007290642	50-364 A 50-364 A 50-348 F 50-364 A 50-364 A
	8007080222 8007080228* 8007080232* 8007080236* 8007080243*	50-364 50-364 50-364 50-364 50-364	A A A A	Alabama, State of	8007290859 8007310150 8007310330 8007310374* 8007180022*	50-348 Q 50-364 Q 50-364 Q 50-364 Q State Prog
	8007080250* 8007090214	50-364 NUREO	A	Alaska, State of Aldrich Chemical Co , Inc (subs of	8007010133* 8007010577	State Prog XPORTLIC
	8007090237 8007100177 8007100185	50-364 50-364 50-364	A A	Sigma-Aldrich Corp)	8007020014 8007030063 8007160403	XPORTLIC XPORTLIC XPORTLIC
	8007100261 8007100261 8007100267* 8007100267* 8007100276*	50~348 50~348 50~348 50~348 50~348	к к к к	Allan Spector & Associates,Ltd Allied General Nuclear Services Aklis-Chalmers Corp	8007220317* 8007180047 8007310139 8007110014 8007110016*	40-1162 NUREQ 50-332 Q 71-221 71-221
	8007100276* 8007110502 8007140343 8007150662 8007150668*	50-348 PRM 50-364 50-348 50-348	K A R R	Alpha-Onega Bervices, Inc	8007280151 8007280155* 8007280160* 8007280165*	71-5979 71-5979 71-5979 71-5979

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY.	AUTHOR AFFIL1ATION	ACCESSION NUMBER	SUBJECT	
American Electris Power Co , Inc American Institute for Research in the Behavioral Sciences	8007280173* 8007280177* 8007020412 8007180208*	71-5979 71-5979 PR 50-213	F		8007280598* 8007280598* 8007290516 8007290516 8007290523	50-528 50-528 50-528 50-528 50-528	6 0 K
American Mine Services, Inc American Nuclear Insurers	8007170172# 8007240170* 8007240173* 8007100134 8007210442	CONTRACT CONTRACT CONTRACT PRM MISC	т		8007290722 8007290722 8007290773 8007300106 8007300106	50-528 50-528 50-528 50-528 50-528	55500
American Nuclear Society	8007280057 8007100254 8007100257* 8007140046*	PR PR PR PR			8007300104 8007300152 8007300514 8007300530 8007300530	50-528 Nureg 50-528 50-528 50-528	G G G
American Warming & Ventilating, Inc Amersham Corp Ames Laboratory, Energy & Mineral Resources Res Institute	8007240353 8007290932 8007290934* 8007240157	50-329 71-370 71-370 71-5088	S	Arizona, State of Arizona, Univ of	8007300530 8007310456 8007020009* 8007030138 8007140611	50-528 PR CONTRACT PR PR	Gr T
Anaconda Co , Amaconda Copper Co Div Anachor/Darling Valve (subs Anachor/Darli ng Industries)		WASTE MG		Arkansas Power & Light Co	8007150140 8007010356 8007010367 8007010380* 8007010407	FR 50-313 50-313 50-313 50-368	P F F S
Anderson-Greenwood & Co nefco.Inc inti-Nuclear Group Regresenting York	8007300315* 8007230483* 8007220203 8007220207*	6A979 50-327 50-289 50-289	P G G		8007010414* 8007010436 8007010437 8007010440*	50-368 50-368 50-368 50-368	5 5 8
ptech Engineering Services rgonne National Laboratory	8007280404* 8007100343 8007180031 8007210027	50-206 NUREQ NUREQ ACRS	S		8007010441* 8007010470 8007010480* 8007010527	50-368 50-313 50-313 50-368 50-368	8 R R B
irgonne National Leboratory - Argonne West irizone Public Service Co	8007240459 8007250010* 8007220184 8007020525	NUREG COMMISSI 71-9132 50-528	g		8007010535* 8007020003 8007020174 6007020201 8007020210	71-5957 50-313 50-313 50-313	0 0 P
	8007020525 8007020525 8007020529* 8007020529* 8007020527* 6007020531	50~526 50~526 50~526 50~528 50~528 50~528	5 5 5 6 8		8007070149 8007070148 8007070253 8007070253 8007080046	50-313 50-313 50-313 50-313 50-366	6 6 6
	8007020533* 8007020728 8007080227 8007080227 8007080227	50-528 PR 50-528 50-528 50-528	8 A A		8007080144 8007080154* 8007080160 8007080171	50-368 50-368 50-368 50-368 50-368 50-368	30 BBCS
	8007090265 8007100077 8007110398 8007140207 8007140207	50-528 PRM 50-528 50-528 50-528	A 8 5		8007080178* 8007090287 8007090328 8007090336* 8007100143 8007100148	50-313 50-348 50-348 50-313 50-313	P 8 8 R H
	8007140217* 8007140217* 8007140339 8007140339 8007140341*	50-528 50-528 50-528 50-528 50-528	6 8 8 8 8		8007100148 8007100366 8007140396 8007140405* 8007180394	50-313 PRM 50-368 50-368 50-313	8 8 8
	6007140341* 8007140448 8007150089 8007160546 6007160551*	50-528 PAM PR 50-530 50-530	8 8 9		8007150489 8007150489 8007150489 8007150494* 8007150494*	50-313 50-313 50-313 50-313	P P P
	8007140452 8007140452 8007140452 8007140458* 8007140458*	50-528 50-528 50-528 50-528 50-528	8 8 8 8		8007150530 8007150538* 8007150595 8007150603* 8007150641	50-313 50-313 50-313 50-313 50-313	8 9 9
	8007160658* 8007170470 8007170470 8007170493* 8007170493*	50-528 50-528 50-528 50-528 50-528	5 5 8 8		8007150450* 8007150450* 8007150460* 8007150493 8007150493*	50-368 50-313 50-368 50-368 50-368	8 8 8
	*	50-528 40-8771 50-528 50-528 50-528	9 Q Q К		8007150694 8007160348 8007170281 8007170285* 8007180095	50-368 50-368 50-313 50-313 71-7108	
		50~528 10~528 10~528 10~528 10~528	К К К		8007180312 8007180318* 8007180429 8007180429 8007210381 8007210382*	50-313 50-313 50-313 50-313 50-368 50-368	8 8 8 8 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION		ACCESSION NUMBER	EUBJECT	
	B007210494 B007210400* B007210406 B007210413* B007210420	50-368 50-368 50-313 50-313 50-313	S S S R			9007080013 8007080017* 8007080058 8007090189 8007150425	50-466 50-466 50-466 50-465 50-445	X0000
	8007210432* 8007210450 8007220495 8007240120 8007240148	50-313 50-313 50-313 50-313 50-313	R R Q P S			8007150425 8007160553 8007160570 8007160639 8007160645	50-445 50-458 50-466 50-466 50-466	Koeee
	8007240150* 8007240176 8007280222 8007280226* 8007280504	50-313 50-313 50-368 50-368 50-313	S S P P S			8007160432 8007250424 8007250441 8007200090 8007200402	50-466 50-466 50-445 50-498 50-466	00200
	8007280511+ 8007280544 8007280544 8007280644 8007280655+	50-313 50-313 50-313 50-368 50-366	S			8007300404 8007300413 8007300417 8007300435 8007300449	50-498 50-446 50-498 50-466 50-466	00000
	8007270403 8007300055 8007300325* 8007300325* 8007300335*	50-313 PR 50-313 50-313	P Q Q Q	Baker Testing Services, Inc Baltimore Gas & Electric Co		8007310094 8007310308 8007070128 8007070133* 8007010329	50-466 50-466 71-392 71-392 50-317	9 9 9
Arkensas, State of Armstrong Cork Co Army, Dept of, Headquarters Materiel Davelopment & Readiness Command	8007300335# 8007030024 8007070406 8007300066	50-313 PR PR PR	Q			8007010387 8007010390* 8007010392* 8007020349 8007020349	50-317 50-317 50-317 50-317 50-317	4488
Army, Dept of Army, Dept of, Office of Surgeon General	8007020375* 8007020375* 8007020382* 8007150080 8007020461	50-67 50-67 50-67 PR PR	R R R			8007020354* 8007020354* 8007020436 8007020436 8007020442*	50-317 50-317 50-317 50-317 50-317	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
Arnold & Porter Association of American Geographers Atlas Minerals Atomic Energy of Canada, Ltd Atomic Industrial Forum	8007250150 6007180227# 8007220291 8007240391 8007030348	WASTE HO MISC 40-3459 PT21 PR PR				8007020442* 8007020448* 8007020448* 8007090291 8007090324	50-317 50-317 50-317 50-317 50-317	8444
	8007100248 8007110031 8007140047 8007230751* 8007240135* 8007280014	PR PRM COMMISSI NUREO PR	10N			E007090356 E007090359* E007100228 B007100228 E007110203*	50-317 50-317 50-317 50-317 NUREO	0000
Austin, TX Automated Correspondence Bystems, Inc	8007280032 8007310441 8007310445* 8007210388 8007170222*	PR PR PR 50-445 CONTRACT	, M			E007110207* E007160245 E007160245 E007170111 E007170352	NUREC 50-317 50-317 50-317 50-317	4 D 4 4
BDM Corp Babcock & Wilcox Co	8007070060* 8007010004 8007010010* 8007010293 8007020350*	CONTRACT 70-824 70-824 70-824 70-824				8007170352 8007170353* 8007170353* 8007170576 8007180600	50-317 50-317 50-317 50-317 50-317	0000
	8007080312 8007090198 8007090201* 8007170417 8007170421*	TOPREP TOPREP TOPREP TOPREP TOPREP				8007210044 8007210044 8007220351 8007220351 8007220355*	50-317 50-317 50-317 50-317 50-317	Q R R R
	8007180486* 8007230239 8007240001 8007240002* 8007300294	TOPREP 50-320 TOPREP TOPREP PRM	s			8007220355* 8007220570 8007230025 8007230175 8007240152	50-317 50-317 71-383 PR 50-318	F
Babcock & Wilcox Co , Naval Nuclear Fuel Div	8007310489 8007310490* 8007010553	XPORTLIC XPORTLIC 71-5341	Ċ			8007240153* 8007250462 8007250462 8007280451 8007280453*	50-318 50-317 50-317 50-317 50-317	80000
	8007020339 8007020359* 8007020345*	70-27 70-27 70-27				8007280481 8007280664 8007280676*	50-317 50-317 50-317	F 55 55
Babcock & Wilcox Co , Nuclear Material Div	8007020005*	70-135 70-1201		Bangor Hydro-Electric Co		8007300351 8007080031+	50-318 50-443	S
	8007150135* 8007150148* 8007150809	70-364 70-364 70-364		Barbay Engineers, Inc Barr Engineering Co Battelle Memorial Institute Battelle (Genorial Institute,	Columbus	8007160227* 8007220307 8007300249 8007140220*	CONTRACT 40-299 PR FOIA	' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Dadgan Gaés Engue, Allians. Inc	8007150814* 8007160397* 8007280211	70-364 GA777 71-9022		Laboratories		8007150712*	50-219	R
Badger Safe Energy Alliance, Inc Baker & Botts	8007150475 8007020471 8007020605	50-484 50-466 50-498	0 0			8007230201 8007240394 8007250110 8007250115*	NUREG NUREG 71-5957 71-5957	'

AUTHOR AFFILIAT (ON	ACCESSION NUMBER	SUBJEC	CT GRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	
Battelle Memorial Institute, Pacific Northwest Laboratory	8007280004 8007310181 8007310183 8007010187#	RES RES REO FOIA			8007300556* 8007300559* 8007300562* 8007300564* 8007300564*	50-482 50-482 50-482	***
	8007010191# 8007010238# 8007020016 8007030350 8007090186# 8007100378	FOIA FOIA RES NUREO 70-1257 PRM	7	Bechtel Power Corp (subs of Bechtel Corp)	8007300564* 8007300566* 8007300568* 8007300570* 8007020118	50-482 50-482	AAAA
	8007170311 8007180330 8007210001 8007210315* 8007220019	NUREG RES RES 70-1257 NURED	7		8007100062* 8007140075* 8007150116 8007230042 8007300452	50-344 GA999 PR PR TOPREP	٥
	8007220058 8007240283 8007280002 8007280202* 8007290244	RES NUREG RES FOIA RES		Bendix Corp Bergen-Patterson Pipe Support Corp Bernard Johnson, Inc Bethlehem Steel Corp Black & Veatch	8007300590* 8007290448 8007290145 8007150004 8007140454	CONTRACT 50-322 NUREO PR PR	s
Bear Creet Uranium Co	8007300014 8007300113 8007310187 8007310210 8007240007	PR PR RES NUREG 40-8452	2	Black Hills Alliance Boeing Co Booke.B L Borg-Warner Corp , Nuclear Valve Div	8007140674 8007220257 8007280218 8007220520 8007070034	FOIA 40-299 40-8481 40-1162 XPORTLIC	
Rechtel Associates Professional Corp Bechtel Corp	8007070254* 8007030248* 8007140045 8007140049* 8007140428*	50-331 50-416 PR PR 50-155	P A G	Baston Edison Co	8007010540 8007010545* 8007030142 8007030287 8007030289*	50-293 50-293 50-293	8 F 8 8
	8007150806* 8007220396* 8007230484* 8007280551* 8007280556*	50-255 50-331 50-331 50-250 50-250	G P P P		8007070357 8007070378 8007070382* 8007070388* 8007080182	50-293 50-293 50-293	8 8 8
	8007300514* 8007300514* 8007300514* 8007300517* 8007300517*	50-482 50-482 50-482 50-482 50-482	A A A A		8007080192* 8007080194 8007080200* 8007080202 8007080205*	50-293 50-293 50-293	8 8 8 8
	8007300517* 8007300520* 8007300521* 8007300522* 8007300522*	50-482 50-482 50-482 50-482 50-482	A A A A		8007140415 8007150152 8007150557 8007150499 8007150704*	PR 50-293 50-293	g P R R
	8007300522* 8007300524* 8007300526* 8007300526* 8007300526*	50-482 50-482 50-482 50-482 50-482	A A A A		8007160641 8007160648* 8007180393 8007180402* 8007210006	50-293 50-293 50-293	6 8 8
	8007300528* 8007300529* 8007300529* 8007300529* 8007300533*	50-482 50-482 50-482 50-482 50-482	A A A A		8007210301 8007210373 8007230176* 8007230307 8007280252*	50-293 50-293 50-293	G G G G
	8007300533# 8007300533# 8007300534# 8007300534# 8007300534#	50-482 50-482 50-482 50-482 50-482	A A A A	Boston Univ Medical Center Boston,MA Branch Radiographic Laboratories, Inc Brand & Hall	8007270576 8007090416 8007270727 8007270731* 8007250485	REOOD 71-368 71-368	P H
	8007300535# 8007300536# 8007300536# 8007300536# 8007300538#	50-482 50-482 50-482 50-482 50-482	A A A A	Brand-Rex Co Briggs Engineering & Testing Bronson Methodist Hosp Kalamazoo,MI	8007250502* 8007220189* 8007020463 8007080273 8007080278*	50-395 QA999 FOIA 40-8054 40-8056	н
	8007300538* 8007300538* 8007300539* 8007300540* 8007300542*	50-482 50-482 50-482 50-482 50-482	A A A A	Brookhaven National Laboratory	8005130445 8007010082* 8007010372 8007010379 8007020085		٦ ٦
	8007300542* 8007300542* 8007300543* 8007300546* 8007300546*	50-482 50-482 50-482 50-482 50-482	A A A A		8007020344 8007140361 8007150064 8007180233 8007180240	RES 50-171 RES RES RES	F
	8007300546* 8007300547* 8007300547* 8007300547* 8007300549*	50-482 50-482 50-482 50-482 50-482	A A A		8007180245 8007180253 8007180341 8007210003 8007210005	RES RES RES RES	
	8007300549* 8007300549* 8007300551* 8007300554*	50-482 50-482 50-482 50-482	A A A		8007210007 8007210010 8007210014 8007220047	RES RES RES RES	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8007220053 8007230455* 8007240294 8007290562 8007290634	RES FOIA RES 50-237 50-409	F F		8007100220* 8007140613 8007140620* 8007160491 8007220423	TOPREP 71-6294 71-6294 NUREQ 70-1100	
Brown & Caldwell	8007310216 8007310217 8007310234 8007310471 8007010226*	NUREO NUREO NUREO NUREO 50-206	R	C F Braun & Co California State Univ,Northridge California, State of	8007210233* 8007010374* 8007020316 8007030046 8007030104	TOPREP 50-361 State Pr 50-275 PR	A O O
Brown & Root Corp (subs of Hailiburton Corp) Brownsville.TX Bruce Norton	800710026B* 8007290441 8007150449 8007180405	50-206 50-498 50-445 50-275	R B M G		8007100086 8007140052 8007170145* 8007250429 8007280044	PR PRM CONTRACT 50-275 PR	G
Burns & Roe Co	B007010004* B007010007* 8007010018* B007010021* 8007010023* 8007010032*	50-397 50-397 50-397 50-397 50-397 50-397	A A A A		8007280486 8007290622 8007300110 8007300419 8007310389	50-204 50-312 50-275 50-275 50-312	P G G
	B007010033* B00701003B* B007010041* B007010045* B007010049*	50-397 50-397 50-397 50-397 50-397	A A A A	California, Univ of, Berkeiey California, Univ of, Davis California, Univ of, Irvine	8007090277 8007250072 8007080353* 8007150615 8007150620*	50-224 FOIA PR 50-326 50-326	H R R
	8007010052* 8007010054* 8007010058* 8007010059* 8007010061*	50-397 50-397 50-397 50-397 50-397	A A A A	Cailfornia, Univ of, Los Angeles Caivert County, MD	8007010619+ 8007090197 8007160240 8007220308 8007210416	CONTRACT 50-142 50-142 50-3 50-317	G F O E
	8007010064* 8007010069* 8007010073* 8007010076* 8007070290	50-397 50-397 50-397 50-397 TOPREP	A A A	Camp Dresser & McKee, Inc ,Environmental Sciences Div Canada Capital Legal Foundation Carolina Environmental Study Group	8007110012× 8007080249 8007030034 8007030034	WASTE MO XPORTLIC PR PAC-05 50-369	
C-E Operating Plants Owners Group C-E Power Systems	8007140109* 8007020557 8007020102 8007020105* 8007020107	QA979 50-259 71-6078 71-6078 70-1100	l ·	Carolina Power & Light Co	8007030040* 8007030040* 8007010307 8007010324 8007010324	50-369 50-369 50-261 50-324 50-324	G G F F F
	8007020108* 8007020112* 8007020114* 8007020115* 8007020574*	71-6078 71-6078 70-1100 71-6078 50-255			8007010342 8007010342 8007010352 8007010352 8007010352	50-324 50-324 50-400 50-400 50-400	F F F
	8007020574* 8007020574* 8007020574* 8007020574* 8007020581*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010352 8007010384 8007010401 8007010408 8007010410	50-400 50-261 50-261 50-261 50-261	F P & S S
	8007020581* 8007020581* 8007020581* 8007020581* 8007020588*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010416 8007010423 8007010423 8007010425 6007010425	50-325 50-324 50-324 50-324 50-324	P P C Q
	8007020588* 8007020588* 8007020588* 8007020588* 8007020393*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010431* 8007010431* 8007010461 8007010466 8007010501	50-324 50-324 50-261 50-261 50-325	9 9 8
	8007020593* 8007020593* 8007020593* 8007020593* 8007020599*	50-255 50-255 50-255 50-255 50-255	P P		6007010509* 8007010513 8007010514 8007010521* 8007010556	50-325 50-325 50-261 50-325 50-325	\$ F 8
	8007020599* 8007020400* 8007020400* 8007020400* 8007020600*	50-255 50-255 50-255 50-255 50-255	P P		8007010544* 8007020087 8007020334 8007020361* 8007020427	50-325 50-261 50-324 50-324 50-400	THE PERSON
	8007020600* 8007030343 8007070351 8007080274 8007080285*	50-255 PR NUREQ TOPREP TOPREP			8007020427 8007020427 8007020427 8007020540 8007020563	50-400 50-400 50-400 50-324 50-324	A A S S
	8007090332* 8007090332* 8007090341* 8007090341* 8007090346*	50-317 50-317 50-317 50-317 50-317	P P		8007070234 8007070237* 8007080180 8007080185* 8007080249	50-325 50-325 50-325 50-325 50-400	8 8 8 8 8
	8007090346* 8007090352* 8007090368* 8007100219	50-317 50-317 50-317 TOPREP	r Р r Р		8007080257* 8007100031 8007100297 8007100377*	50-400 50-261 50-400 50-324	6 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	!¥	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJEC	
	8007100418* 8007100422* 8007110405 8007110405 8007110406*	50-400 50-400 50-324 50-324 50-324	G G R R R		8007170655 8007170655 8007170655 8007170661 8007170661	50-400 50-400 50-400 50-400 50-400	K K K K
	8007110406* 8007140398 8007140399* 8007150097* 8007150492	50-324 50-324 50-324 50-261 50-324	R S S Q Q		8007170561 8007170561 8007170563* 8007170563*	50-400 50-400 50-400 50-400 50-400	KKCCC
	2007150535 8007150626 8007150629 8007150633* 8007150654	50-400 50-261 50-261 50-261 50-325	A P R R R		8007170663# 8007170672 8007170672 8007170672 8007170672	50-400 50-400 50-400 50-400 50-400	C K K K
	8007150445* 8007160377 8007160632 8007170366 8007170346	50-325 50-400 50-324 50-400 50-400	K G B		8007170677 8007170677 8007170677 8007170677 8007170678*	50-400 50-400 50-400 50-400 50-400	K K K C
	8007170366 8007170366 8007170367* 8007170367* 8007170367*	50~400 50~400 50~400 50~400 50~400	к к к к		8007170678* 8007170678* 8007170678* 8007170684 8007170684	50-400 50-400 50-400 50-400 50-400	CCCKK
	8007170367* 8007170372 8007170372 8007170372 8007170372	50-400 50-400 50-400 50-400 50-400	к к к		8007170484 8007170484 8007170486* 8007170486* 8007170486*	50-400 50-400 50-400 50-400 50-400	KKCCC
	8007170377 8007170377 8007170377 8007170377 8007170516	50-400 50-400 50-400 50-400 50-324	K K K		8007170686* 8007170687 8007170687 8007170687 8007170687	50-400 50-400 50-400 50-400 50-400	CKKKK
	8007170516 8007170541 8007170541 8007170541 8007170541	50-324 50-400 50-400 50-400 50-400	д К К К		8007170490 8007170690 8007170690 8007170690 8007180428	50-400 50-400 50-400 50-400 50-400	K K K V
	8007170572 8007170572 8007170572 8007170572 8007170578	50-400 50-400 50-400 50-400 50-400	к к к к		8007210022 8007210415 8007220210 8007220227 8007220254	50-261 50-324 50-400 50-261 50-261	0 0 0
	8007170578 8007170578 8007170578 8007170574 8007170594	50-400 50-400 50-400 50-400 50-400	К К К К		8007220260 8007220426 8007220429* 8007220433* 8007220435*	50-324 50-261 50-261 50-261 50-261	g >>>>
	8007170594 8007170594 8007170600 8007170600 8007170600	50-400 50-400 50-400 50-400 50-400	я к к к		8007220438* 8007220440 8007220445* 8007220456 8007220456	50-261 50-261 50-261 50-400 50-400	8 4 4
•	8007170600 8007170615 8007170615 8007170615 8007170615	50-400 50-400 50-400 50-400 50-400	к к к к		8007220456 8007220456 8007220464 8007220470* 8007220521	50-400 50-400 50-324 50-324 50-324	A A B S B
	8007170627 8007170627 8007170627 8007170627 8007170628	50-400 50-400 50-400 50-400 50-400	К К К Ж А		8007220521 8007230247 8007230247 8007230247 8007230247	50-324 50-400 50-400 50-400 50-400	8 8
	8007170628 8007170628 8007170628 8007170639* 8007170639*	50-400 50-400 50-400 50-400 50-400	A A A A		8007240151 8007240189 8007240189 8007240196* 8007250296	PR 50-324 50-324 50-324 50-324	9 9 9
	8007170639* 8007170639* 8007170643 8007170643 8007170643	50-400 50-400 50-400 50-400 50-400	А А К К К		8007250334 8007250341* 8007250420 8007280104 8007280111	50-324 50-324 50-261 50-260 50-324	8 8 0 0
	8007170443 8007170450 8007170650 8007170650 8007170450	50-400 50-400 50-400 50-400 50-400	K K K K		8007280507 8007280507 8007280507 8007280507 8007280513*	50-400 50-400 50-400 50-400 50-400	R R R R
	8007170652 8007170652 8007170652 8007170652 8007170655	50-400 50-400 50-400 50-400 50-400	C C C C K		8007280513* 8007280513* 8007280513* 8007280679 8007290686	50-400 50-400 50-400 50-261 50-261	R R R P P

AUTHOR AFFILIATION	ACCESS ION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	8007290690 8007290723 8007290823 8007290826	50-261 50-324 50-325 50-325	P P S S	Citizens Concerned About Nuclear Power,	8007310123 8007310123 8007300415	50-445 50-445 50-498	0
	8007290831* 8007290833*	50-325 50-325	6	Citizens for Energy & Employment	8007310145 8007080008	50-498 50-452	G
	80072900351 8007300361 8007310204 8007310206	50-324 50-324 50-324 50-324	0 0 0	Catizens for Equitable Utilities Catizens for Safe Environment Citizens for a Better Environment	8007310145 8007210158 8007020175* 8007020203* 8007140337	50-498 HASTE HO 50-10 50-10 50-10	9 75 H H Q
Carrier Corp Carrier Air Conditioning Div.	8007310306 8007310306 8007310449 8007310449 8007170236	50-324 50-324 50-324 50-324 50-518	0 0 0 8		8007180187* 8007180212* 8007220548 8007230649 8007280537	50-10 50-10 50-10 50-10 50-10	G D D
	8007170247 7910150157	50-518 40-4669	8	Citizens for the Conservation of Natural Resources, Inc	8007140581	50-374	Q
Case Western Catalytic, Inc. (subs. of Air Products &	8007030099	40-4669 RECOD		Cleveland Electric Illuminating Cn	8007230791 8007080294	50-376 50-440	G E
Chemicals, Inc)	8007180230	REGOD			8007140534 8007150540	50-440 50-440	8 A
Genter for Law & Social Policy Center for Law in the Public Interest	8007310237 8007020136 8007140228 8007230508 8007300096	FOIA FOIA FOIA 50-275 50-275	0		8007150553 8007150553 8007140598 8007180406 8007180585*	50-440 50-440 50-440 50-440 50-440	0 0
Central & South West Corp Central Electric Power Cooperative. Inc Central Maine Power Co Central Vermont Public Service Corp Gerac, Inc	8007150431 8007250485 8007080016* 8007080018* 8007020379	50-445 50-395 50-443 50-443 XPORTLIG	M M I I		8007180585* 8007180591* 8007180591* 8007230101 8007230101	50-440 50-440 50-440 50-440 50-440	0 0 0 0
Chem-Nuclear Systams, Inc	8007010482 8007100461 8007160417 8007170446* 8007170452*	27-47 71-9094 71-9070 50-320 50-320	P P	Cleveland, OH Cleveland-Cliffs Iron Ca	8007230321 * 8007230321 * 8007270533 8007140875 8007270849	50-440 50-440 50-346 50-346 40-8200	а а м м
	8007170455# 8007170458# 8007170464# 8007170466# 8007170473#	50-320 50-320 50-320 50-320 50-320	Ե Ե Ֆ Ֆ	Colorado State Univ	8007310457 8007170297* 8007170302* 8007170308* 8007170329*	40-8714 40-8602 40-8602 40-8602 40-8681	
	8007170478* 8007170482* 8007170488* 8007170490* 8007170499*	50-320 50-320 50-320 50-320 50-320	P P P P		8007170331# 8007170332# 8007170335# 8007210177 8007210183	40-8681 40-8681 40-8681 40-8452 40-8452	
	8007170502* 8007170505* 8007170511* 8007170521* 8007170533*	50-320 50-320 50-320 50-320 50-320	ቸ የ የ		8007230135 8007230725* 8007280066 8007280070 8007280073	40-8452 40-8452 40-8602 40-8681 40-8452	
Chemtron Corp Chemtron Corp , Tube Turns Div Chen & Associates, Inc	8007170535* 8007160478* 8007230100 8007210079 8007210143	50-320 50-320 40-7402 PT21 40-2259	P H	Colorado, State of	8007010274* 8007020359 8007210160* 8007090270* 8007090275*	WASTE MO WASTE MO CONTRACT 50-352 50-352	T
Chavron Research Co Chickering & Gregory	8007100133 8007140034*	REGOD 50-361	ø	Colt Industries, Inc , Fairbanks Morse Engine Div	8007010357	50-375	8
Christa-Maria	8007300359 8007100037* 8007100042*	50-361 50-155 50-155	0 0	Combustion Engineering, Inc	8007010459 8007020103# 8007090361# 8007100210	50-375 70-1100 50-317 TOPREP	8
Cincinnati Cas & Electric Co	8007010084 8007070258 8007080317 8007080374 8007140349	50-358 50-358 50-358 50-358 50-358	G A O K		8007100212* 8007110243 8007110248* 8007140037* 8007180496*	TOPREP TOPREP TOPREP GA999 TOPREP	
	8007140377* 8007150108* 8007210302* 8007210313 8007210424	50-358 50-358 50-358 50-358 50-358	К Ф Ф К	Commerce, Dept of Commerce, Dept of, National Oceanographic	8007250057* 8007260737* 8007020553* 8007240381 \$007240409	QA999 70-1100 CONTRACT PR NUREQ	
	8007220280 8007230437 8007230576 8007230616 8007280096	50-358 50-358 50-358 50-358 50-358	A a a a	Atmospheric Adminstration Committee for Application of Nuremberg Principles to US Nuclear Power Producti Commonwealth Edison Co	8007110001 #n 8007010170 8007010170	50-498 50-237 50-237	r P
Citizens Against Nuclear Power Citizens Association for Sound Energy	8007250369 8007090327 8007220546 8007220546	50-10 50-445 50-445 50-445	D G G		8007010211 8007010211 8007010347	50-295 50-295 50-10	P P F
	8007220559 8007220559 8007300366 8007300366	50-445 50-445 50-445 50-445	0 0 0		8007010347 8007010347 8007010347 8007010347	50-10 50-10 50-10 50-10	F F F

AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		ACCESSION NUMBER	SUBJECT	
	8007010347 8007010347 8007010411 8007010428 8007010484	50-10 50-10 50-454 50-295 50-295	F F A A P G	8007180333 8007180333 8007180333 8007180336* 8007180336*	50-10 50-10 50-10 50-10 50-10	R R R R
	8007010488* 8007010493 8007010497 8007010500* 8007010505*	50-295 50-295 50-237 50-295 50-237	ន	8007180336* 8007180560 8007180560 8007180579* 8007180572	50-10 50-3 50-3 COMM188: 50-3	R G Q ION G
	8007010544 8007010551* 8007020050 8007020074 8007020074	50-237 50-237 50-295 50-247 50-295	5 \$ 0 0 0	8007180592 8007210212 8007210212 8007210212 8007210292*	50-3 50-237 50-237 50-237 50-373	О Р Р О
	8007020076 8007020368 8007020408 8007020408 8007020408	50-295 PR 50-454 50-454 50-454	о к к к	8007210272* 8007220352 8007220354* 8007220357* 8007220357*	50-973 TOPREP TOPREP TOPREP TOPREP	Q
	8007020408 8007020420* 8007020420* 8007020420* 8007020420*	50-454 50-454 50-454 50-454 50-454	к к к к	8007220361* 8007220387 8007220371* 8007220399 8007220400	TOPREP 50-304 50-304 50-295 50-295	8 8 8
	8007020462 8007020631 8007020631 8007020756 8007070116	50-599 50-454 50-454 50-249 50-10	0 9 9 9 P	8007220401 8007220402 8007220404 8007220405 8007220406	50-295 50-295 50-295 50-295 50-304	8 8 8
	8007070116 8007070116 8007070267 8007070267 8007070345	50-10 50-10 50-373 50-373 50-237	Р Р К К Р	8007220408 8007220409 8007220411 8007220412 8007220413	50-304 50-304 50-304 50-304 50-304	8 8
	8007070345 8007070345 8007080063 8007080162 8007080172#	50-237 50-237 50-10 50-245 50-245	P P P S S	8007220414 8007220449 8007220453* 8007220455 8007220459*	50-304 50-295 50-295 50-249 50-249	8 8 9
	8007080248 8007080279 8007080279 8007080299 8007080299	TOPREP 50-454 50-454 50-454 50-454	К К К К	8007220518 8007220540 8007220557 8007220572# 8007220577	50-373 50-454 50-237 50-237 50-249	A 8 8
	8007100004 8007100004 800710004 8007100130 8007100142	50-10 50-10 50-10 PRM 50-254	Q Q Q	8007220583* 8007220587 8007220593* 8007230187 8007230281*	50-249 50-304 50-304 PR 50-373	G 8 8
	8007100142 8007100147* 8007100147* 8007100179 8007100187	50-254 50-254 50-254 50-237 50-237	P P P S S	8007230339 8007230345 8007230347 8007230351 8007230352	50-237 50-295 50-295 50-295 50-295	8 8
	8007100187* 8007100192* 8007100343 8007110206* 8007140235	50-237 50-237 PRM 50-10 PRM	g g	8007230357 8007230357 8007230397 8007230678* 8007240105	50-295 50-249 50-265 50-10 50-254	8 8 8 8
	8007140320 8007140327 8007140327 8007140328* 8007140331*	50-454 50-295 50-295 50-454 50-295	к я я к я	8007240107* 8007240112 8007240114* 8007240298* 8007240351*	50-254 50-263 50-263 50-249 50-456	8 8 Q
	8007140331# 8007150474 8007150476 8007150327 8007150614	50-295 50-295 50-295 50-373 50-254	R P F A J	8007240351* 8007250448 8007250455* 8007250467 8007250638	50-454 50-973 50-373 50-373 50-10	G A G G
	8007150619 8007150619 8007150625* 8007150625* 8007160559	50-254 50-254 50-254 50-254 50-454	R R R B K	8007250638 8007250638 8007250638 8007250638 8007250638	50-10 50-10 50-10 50-10 50-10	@ @ @ @
	8007160606 8007160627 8007160630 8007160630 8007160635	50-373 50-599 50-237 50-237 50-295	A C C Q Q Q Q	8007250641 8007250641 8007250641 8007250641 8007250641	50-10 50-10 50-10 50-10 50-10	Q Q Q Q
	8007140442* 8007140448 8007140472* 8007180010* 8007180034*	50-295 50-304 50-304 50-10 COMMISSI	\$ 6 6 Q QN	8007250641 8007250641 8007250650 8007250650 8007250650	50-10 50-10 50-10 50-10 50-10	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8007250650 8007250650 8007250650 8007250650 8007280074	50-10 50-10 50-10 50-10 50-254	0 0 0 0		8007090279 8007110396 8007110404# 8007140375 8007150669	50-3 50-247 50-247 NUREG 50-3	P S S
	8007280470 8007280474* 8007280567 8007280595 8007280605	50-265 50-265 NUREG 50-10 50-295	P P D P	•	8007170287 8007170363 8007170363 8007170363 8007170365*	50-3 50-3 50-3 50-3 50-3	Q R R R
	8007280605 8007280670 8007280688* 8007290678 8007290698	50-295 50-454 50-373 50-454 50-373	P S G K A		8007170365* 8007170365* 8007210473 8007210473 8007220160	50-3 50-3 50-3 50-3 50-247	R R R G
	8007290709 8007300469 8007300465 8007300465 8007300485	50-254 PR 50-237 50-237 50-237	J G G		8007220160 8007220454 8007220476 8007220479* 8007220504	50-247 50-247 50-247 50-247 50-247	9 P R P
	8007310353 8007310353 8007310357 8007310432 8007310480	50-254 50-254 50-254 50-10 50-249	0 0 0 0		8007220523 8007220523 8007220523 8007220524* 8007220524*	50-3 50-3 50-3 50-3 50-3	R R R R
Conference of Radiation Control Program Directors, Inc	8007310486* 8007310533* 8007280170*	50-247 50-373 COMMISS	11 0 M G G		8007220524* 8007230044 8007230471 8007240127	50-3 PR 50-247 50-3	R P I
Congress (Joint & Rotating Committees, etc.)	8007300018 8006170304	PR MISC			8007240127 8007240129*	50-3 50-3	1
Connecticut Light & Power Co Connecticut Yankee Atomic Power Co	8007110363 8007080040* 8007010337 8007010337	50-320 50-443 50-213 50-213	U I F F		8007240169 8007240172* 8007290522 8007290682	50-247 50-247 50-247 50-3	5 9 H
	8007010337 8007020472 8007020569 8007020569 8007030356	50-213 PR 50-213 50-213 50-245	р Р F	Consolidated Rail Corp Consumers Power Co	8007030341 8007010200 8007010313 8007010447 8007010451>	PR 50-155 50-155 50-155 50-155	Р Р
	8007030354 8007030354 8007080077 8007090231 8007090321	50-245 50-245 50-213 50-213 50-213	F \$ F \$	•	8007010473 8007020224 8007020306 8007020649 8007030250	50-155 PR 50-327 50-329 50-235	F G G
	8007090326* 8007100035 8007140355 8007140359	50-213 PR 50-213 50-213	s 1 s		8007030251* 8007030268 8007070119 8007070210 8007080189	50-255 50-155 50-329 50-155 50-255	P P P P P
	8007160369 8007170320 8007170425 8007170494 8007180390	50-213 50-213 50-213 50-213 50-213	g G F G R		8007080197# 6007080338 8007080346 6007080348# 8007090008	50-295 50-255 50-155 50-155 50-255	8 P R P
	8007180375* 8007180578 8007210237 8007230411 8007240053	50-213 50-213 50-213 50-213	R G P		8007070010# 8007070045 8007070314 8007070317# 8007100092	50-255 50-327 50-255 50-255 PR	P 9 8
	8007240058* 8007240062* 8007240067 8007240070* 8007250535	50-213 50-213 50-213 50-213 50-213	P P P S		8007100197 8007100201* 8007100204* 8007110204 8007110209*	50-255 50-255 50-255 50-155 50-155	6 6 6
	8007290852 8007300324 8007300331* 8007300338*	PR 50-213 50-213 50-213	P P		8007110210# 8007110297 8007110301# 8007110358	50-155 50-255 50-255 50-255	2 % % 2
Connecticut, State of	8007300342* 8007010478 8007020556	50-213 NUREG PR	P		8007110407 8007110414*	50-255 50-255	R R
Conner, Moore & Corber	8007030113 8007160858* 8007020407 8007130058	PR COMMISS PR 27-39			8007140004 8007140004 8007140007* 8007140010*	50-369 50-369 50-369 50-369	000
Consolidated Edison Co of New York	8007310424 8007310424 8007010081 8007010081	50-272 50-375 50-3 50-3	© M Q Q		8007140010* 8007140020 8007140020 8007140310 8007140350	50-369 50-329 50-329 50-255 50-255	0 0 0
	8007020077 8007020077 8007030050*	50-3 50-3 PR	Q Q		8007140391 8007140391 8007140392	50-155 50-155 50-3	F F P
	8007090228 8007090251	50-247 50-247	b b		8007140424 8007140444	50-155 50-155	a a

AVTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOGRY
	8007140543 8007150052 8007150134 8007150497 8007150497	PR 50-155 PR 50-329 50-329	• • • • • • • • • • • • • • • • • • •		8007140571 8007140477 8007160681* 8007170368 8007180092	50-409 G 50-409 R 50-409 G 50-409 G
•	8007150664 8007150803 8007160458 8007160505 8007160612	50-155 50-255 50-155 50-255 50-329	Q Q Q P		8007180355 8007180362 8007210447 8007220096 8007220525	50-409 Q 50-409 Q 50-409 P 50-409 Q 50-409 P
	8007180424 8007210273 8007210394 8007210427 8007210440*	50-155 PRM 50-255 50-255 50-255	G R R R		8007280050 8007280696* 8007290480 8007300244 8007310434	50~409 G 50~409 G 50~409 G 50~409 G
	8007210483 8007210483 8007220194 8007220341 8007220452	50-329 50-329 50-329 50-155 50-155	A Q F Q	Dames & Moore	8007310443* 8007210170* 8007220042* 8007220049* 8007220526*	50-409 I 40-4492 Habte Hot Habte Hot 50-409 P
	8007220472 8007220478 8007220484* 8007220513 8007220566	50-155 50-255 50-255 50-255 50-155	6 8 8	Dariing Valve & Mfg Dartmouth Coilege Davy McKee Corg	8007240156* 8007240159* 8007300399 8007240011* 8007240013*	50~339 P 50~339 P TOPREP 40~8452 40~8452
	8007230395 8007230460 8007230465 8007230473 8007230478	50-255 50-255 50-155 50-255 50-155	Q Q Q P F	Dawn Hining Co De Laval Turbins Inc	8007240013* 8007240022* 8007150045 8007210485* 8007210485*	40-8452 40-8452 Warte Hot 50-445 A 50-445 A
	8007230479# 8007230484* 8007230516 8007230810 8007240017	50-155 50-331 50-155 50-255 50-155	F P G Q		8007210490* 8007210490* 8007210496* 8007210496* 8007210500*	50-445 A 50-445 A 50-445 A 50-445 A
	8007240136 8007240146 8007240146 8007250373 8007280041	PR 50-329 50-329 50-155 50-329	K K Q A		8007210500* 8007210504* 8007210504* 8007210508* 8007210508*	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007280040 8007280060 8007280124 8007280533 8007280570	50-329 50-329 50-329 50-155 50-155	A A R P F		8007210510* 8007210510* 8007210514* 8007210514* 8007210517*	50-445 A 50-445 A 50-445 A 50-445 A
	8007280570 8007280597 8007290206 8007290406 8007290614	50-155 50-155 50-329 50-155 50-255	8 9 F		8007210517# 8007210519# 8007210519# 8007210527# 8007210527#	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007290616* 8007290630 8007290691 8007290701 8007300439	50-255 50-255 50-155 50-329 50-155	S G G A F	Debevoise & Liberman	8007030246 8007100290 8007140004 8007140243 8007160625	50-445 0 PRM 50-369 0 FOIA 50-445 M
	8007310177 8007310422 8007310425* 8007310488 8007310529*	50-255 50-155 50-155 FOIA 50-329	0	Defense, Dept of, Defense Nuclear Agency	8007180437 8007240140 8007290887 8007310328 8007150342	50-445 Q PR PR 50-445 Q REGOD
Contra Costa Industrial X-Ray Co Contra Costa Inspection Co Cooperative Power Association	8007310329* 8007220279 8007290277 8007290282* 8007010421	50-329 71-7039 71-6717 71-6717 50-484	ī	Delaware, State of Delta Bwitchboard Co Dennison, A B Detroit Edison Co.	8007140043 8007140364 8007210327* 8007110074 8007070098*	PR PR 50-445 A 50-358 G 50-341 S
Coordination Council for North American Affairs	8007170242#	XPORTLIC	:		8007140326 8007140378*	50-341 B 50-452 0
Corning Olass Horks, Zircoa Products Div Cotter Corp Coules Region Energy Coalition Council of Energy Resource Tribes	8007250343 8007210104 8007140227# 8007030158	40-2541 WASTE MG 50-409 PR	рт Н		8007140425 8007140481* 8007160687	50-341 0 50-341 0 50-341 A
Council on Environmental Quality Crane Co Creare, Inc Critical Hass Energy Project	8007090148* 8007220121* 8007240161* 8007220334* 8007280274	PR 50-599 50-339 TOPREP FOIA	Ģ P	Doggett, S A Doherty, J F	8007210136* 8007220545 8007100174 8007030339	50-341 8 50-341 8 50-466 9 50-466 A
Cyprus Mines Corp D'Appolonia Consulting Engineers, Inc	8007020281 8007020708 8007020712* 8006240082*	WASTE MO WASTE MO 40-1162	T	Donovan, Hamester & Rattien, Inc Dow Chemical Co Dow Chemical Co , Dow Chemical U.S A Div	8007230246 8007070054# 8007250476 8007250705	50-466 Q CONTRACT TOPREP PR
DRO International, Inc Dandalran Associates, Inc	8007290982	XPORTLIC		Duke Power Co	8004050319	50-369 8 50-269 0
Dairyland Power Cooperative	8007230231 8007020479 8007080300 8007140305	REB 50-409 50-409 50-409	Ф Р Р		8007010065 8007010205 8007010205 8007010205	50-269 G 50-269 F 50-269 F 50-269 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
,	8007010309 8007010340 8007010340 8007020537 8007020575	50-369 50-269 50-269 50-413 50-269	# P # 60 P	***************************************	8007220192 8007220192 8007220245 8007220245 8007220245	50-269 G 50-269 G 50-269 G 50-269 G
	8007020575 8007020575 8007020648 8007030087 8007030185	50-269 50-269 PR PR 50-413	P P		8007220365 8007220424 8007220427* 8007220477 8007220483*	50-369 ^ 50-269 5 50-269 8 50-269 P
	8007030185 8007030186 8007030189* 8007030189* 80070700043	50-413 PRM 50-413 50-413 PR	A A A		8007220534 8007220561 8007220563 8007220563 8007220563	50-369 A 50-259 P 50-269 S 50-269 S 50-269 S
	8007070319 8007070319 8007070319 8007070323* 8007070323*	50-269 50-269 50-269 50-269 50-269	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8007240357 8007240359 8007240469 8007250166 8007250166	50-369 0 PR 50-369 0 50-269 0 50-269 0
	8007070323* 8007080201 8007080207* 8007080223 8007080223	50-269 50-270 50-270 50-269 50-269	9 9 9 P		8007250166 8007250532 8007250578 8007280068 8007280416	50-269 A 50-488 A 50-369 A 50-269 A 50-270 A
	8007080223 8007080345 8007090271 8007090271 8007090276*	50-269 50-369 50-269 50-269 50-269	P A P P		8007280427 8007280427 8007280430* 8007280430* 8007280437	50-270 P 50-270 P 50-270 P 50-270 P 50-269 P
	8007090276* 8007090402 8007100036 8007100139 8007100419*	50-269 PR 50-369 50-270 50-413	9 0 0		8007280437 8007280437 8007280438* 8007280438* 8007280438*	50-269 P 50-269 P 50-269 P 50-269 P 50-269 P
	8007110294 8007110294 8007110294 8007110309 8007110331+	50-269 50-269 50-269 50-369 50-269	P P A P		8007280501 8007280544 8007290267 8007290635 8007290640*	50-413 S 50-269 P 50-270 Q 50-287 S 50-287 S
	8007110331* 8007110331* 8007110360 8007110362* 8007140083	50-269 50-269 50-269 50-269 NUREO	P P S S		8007290824 8007290830* 8007300330 8007300330 8007300355	50-270 8 50-270 8 50-367 8 50-367 8 50-367 8
	8007140397 8007140443 8007140443 8007140463 8007150015	50-269 50-269 50-269 50-269 50-269	P Q Q Q		8007300459 8007310379 8007310379 8007310381* 8007310381*	50-349 A 50-269 P 50-269 P 50-269 P
	8007150575 8007150575 8007150583* 8007150583* 8007160514	50-269 50-269 50-269 50-269 50-413	8 6 6	Duquesne Light Co	8007310382* 8007310382* 8007310491 8006230660 8007010336	50-269 F 50-269 F 50-270 G 50-334 G 50-334 F
	B007160514 B00716051B* B007160657 B007160657 B007160663*	50-413 50-413 50-367 50-369 50-369	S S S S		800701034B 8007010395 8007010396 8007010400* 8007010456*	50-412 0 50-334 F 50-334 B 50-334 B
	8007160643* 8007170105 6007180321 8007180326* 8007180349	50-369 PR 50-270 50-270 50-270	s s g		8007010526 8007010536* 8007020546 8007020547* 8007070296	50-334 B 50-334 B 50-334 R 50-334 R 50-334 S
	8007180417 8007180533 8007180533 8007180533 8007210114	50-287 50-269 50-269 50-269 50-369	8 0 0 0		8007080080 8007080084* 8007080186 8007080276 8007080424	50-334 # 50-334 # 50-334 0 50-334 0
	8007210114 8007210261 8007210385 8007210417 8007210421*	50-369 50-413 50-369 50-269 50-269	Q Q A S S		8007090334 8007090338* 8007090340 8007090348* 8007150480	50-334 8 50-334 8 50-334 8 50-334 8
	8007210425 8007210426* 8007210459 8007210470* 8007210476	50-270 50-270 50-269 50-249 50-413	P		8007150483 8007150567 8007150643 8007160480 8007160555	50-334 0 50-334 0 50-334 0 50-334 P
	8007210486* 8007210486* 8007210607 8007210617* 8007220172	50-413 50-413 50-287 50-287 50-269	A A B G		8007140544* 8007140595 8007140647 8007140654* 8007170546	50-334 P 50-334 Q 50-334 Q 50-334 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	ЯY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATECO	
	8007180055 8007180317 8007180322* 8007180418 8007180422*	50~412 50~334 50~334 50~334 50~334	G S S R R	Ed L. Reed & Associates, Inc Edison Electric Institute Ediow International Co	8007110462* 8007020471 8007100180* 8007210168 8007240434	WASTE M PR PR PR XPORTLI	
	8007210011 8007210016 8007220430 8007220434* 8007220506	50-334 50-412 50-334 50-334 50-334	0 9 8 8	Eichhorn, Eichhorn & Linf Electric Power Rosearch Institute	8007310018 8007310503# 8007310506# 8007020453 8007010233#	XPORTLI FOIA FOIA 50-367 FOIA	c o
	8007220588 8007230150* 8007250274 8007250315 8007250324*	50-334 50-334 50-334 50-334 50-334	0 0 6 8	Elyria Memorial Hosp Elyria, CH Energy Products Group Energy, Dapt of	8007140398* 8007100194 8007160457 8004110523 8007010013	50-3 REGOD NUREG PR ORO	₽
	8007250331 * 8007270540 8007270643 8007270680 8007300383	50-334 50-412 50-334 50-334 50-334	\$ R P G 8		8007010017* 8007020435 8007020493* 8007030084 8007090098	ORG PR 50-281 PR PR	н
E & Conwell & Co EDS Nuclear, Inc	800730038B* 8007020650 8007020652* 8007300498* 8007300498*	.50-334 71-381 71-381 50-237 50-237	B Q		8007090103* 8007100024 8007100094 8007110451 8007140190*	PR PR PR PRM 50-247	Р
	8007300498* 8007300498* 8007300508* 8007300508* 8007300508*	50-237 50-237 50-237 50-237 50-237	Q Q Q Q		8007150074* 8007170051* 8007170390 8007180464* 8007220030*	5ECY 50-204 50-344 50-339 50-566	H P H H
EOLO Idaho.Inc	8007300508* 8007300508* 8007030015 8007140092 8007150059	50-237 50-237 REB NUREO RES	G G		8007240090 8007240094* 8007240154 8007280140* 8007300234	71-5607 71-5607 71-9132 50-289 PR	Q
	8007150409 800722003B 8007220045	829 82-263 838	Р	Energy, Dept of, Clinch River Breader Reactor Plant	8007300411 8007010366	PR 50-537	F
	8007220065 8007230172 8007230177	RES 50-334 RES	ρ		8007030179 8007080264 8007100194	PR 50-537 50-537	Ð
	8007230185 8007230174 8007230205 8007230625	RES RES NUREO NUREO		Enorgy, Dept of, Idaho Operations Office Engineering Decision Analysis Company, inc	8007270174 8007220353#	RE8 50-70	P
	8007250184 8007250304	50-313 50-325	p P		8007220354* 8007220362* 8007220366*	50-70 50-70 50-70	P P P
	8007280164 8007280171 8007280174	ACB ACB ACB		Environmental Coalition on Nuclear Power Environmental Policy Institute	8007220369* 8007280606* 8007070275 8007080086 8007030107	50-70 TOPREP 50-320 50-320 PR	Р 0
	8007280186 8007290143 8007290180 8007290191	RES 50-324 RES RES	P	Environmental Protection Agency	9007020400 8007110026 8007230594 8007250600	PR PR 50-409 40-1162	D
EG&G, Inc.	8007270226 7007270296 8007210255 8007030208*	REB NUREO NUREO 50-285	P	Essex Corp.	8007280037 8007290696 8007090163 8007090166*	PR 50~10 NUREO NUREO	р
	8007100363 8007210017 800721002	NUREG REB REB		Euratem Supply Agency (Belgium)	8007090167* 8007190036	NUREG XPORTLIC	
Eastern Utilities Associates	8007280508 8007080020#	NUREG 50-443	I	European Communities, Commission of Exxon Minerals Co . USA	8007170229 8007240447 8007170679	XPORTLIC XPORTLIC 40-8102	
Eastman Kodak Co Ebasco Barvices: Inc. (subs of Enserch Corp)	8007010244 8007020326#	40-8438 50-335	q	Exxon Nuclear Co , inc (wubs of Exxon Corp)	8007280047 7909210176	40-8102 REOOD	
Eberline Instrument Corp Eckert, Seamans, Cherin & Mellott Ecclaire Condenser, Inc	8007170129* 8007220540 8007250685 8007310398	CONTRACT XFORTLIC XFORTLIC	:		8007020701 8007070004 8007070006# 8007070008#	PR XPORTLIC XPORTLIC XPORTLIC	;
Ecology Action of Oswago	8007080046 8007080046 8007080046 8007080046	50-320 50-320 50-320 50-320	0000		8007070402 8007110215 8007110341 8007140386 8007240224	PR TOPHEP TOPREP 71-4381 XPORTLIC	
	8007080046 8007080048 8007080048 8007080048	50-320 50-320 50-320 50-320	000		8007240247* 8007280009 8007290733	XFORTLIC PR TOPREP	
	8007080048 8007080048 8007080048	50-320 50-320 50-320	0	Farm Legal — TN Federal American Partners	8007140691 8007020013 8007100084	PR 40-4492 40-4492	
	8007080048 8007310128	50-320 50-277	0		9007100087 8007210169	40-4492 40-4492	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Federal Emergency Management Agency Federal Energy Regulatory Commission Firex Corp	8007070025* 8007140079* 8007240060 8007100218 8007070378	SECY 10CFR 50-369 50-10 REGGD	F D	Florida Power Corp	8007010355 8007010463 8007020387 8007020242 8007070327	50-302 50-302 50-302 50-302 50-302	P 9 P 0
Fitchburg Gas & Electric Light Co Fleischeker, D S Florida Cities	8007080017* 8007100198 8007230508 8007300096 8007090051	50-443 50-275 50-275 50-275 50-369	I G G M		8007080075 8007080259 8007100101 8007100153 8007110122	50-302 50-302 REGGD 50-302 50-302	P F P
Florida Power & Light Co	8007230778 8007010483 8007010471* 8007020294 8007020321*	50-389 50-335 50-335 PR 50-335	M S S		8007110402 8007110410* 8007150385 8007150484 8007150503*	50-302 50-302 50-302 50-302 50-302	5 9 P Q
	8007030221 8007070100* 8007080140 8007080284 8007080290*	50-335 50-335 50-250 50-335 50-335	P Q P S S		8007150598 8007150708 8007150713* 8007180294 8007180313	50-302 50-302 50-302 50-302 50-302	Ø R R P
	8007080330 8007080335* 8007090286 8007100021 8007100025	50-335 50-335 50-335 50-335 50-250	R R P Q Q		8007180384 8007180540 8007210203 8007220383 8007230193	50-302 50-302 50-302 50-302 PR	ն 0
	8007100128 8007110197 8007110197 8007110256 8007110261	50-250 50-250 50-250 50-250 50-250	G P P P		8007230562 8007230573* 8007240074 8007240382 8007250326	50-302 50-302 50-302 50-302 50-302	0: 0: P 0: P
	8007110261 8007140364 8007140372* 8007140382 8007140389*	50-250 50-335 50-335 50-335 50-335	P 8 8 8	Fluor Power Service, Inc	8007250330* 8007280127 8007280133* 8007280373 8007220234*	50-302 50-302 50-302 50-302 50-305	P P F P
	8007150532 8007150536* 8007150627 8007150636* 8007160375	50-335 50-335 50-335 50-335 50-250	9 6 6 0	Foster Wheeler Corp Foundation Eciences, Inc Fox Industries Frankhauser, D D Franklin Institute/Franklin Research Center	8007290858 8007170368* 8007010236 8007220565 8007070368	PR 50~344 TOPREP 50~358 50~338	R Ø P
	8007160599 8007160810* 8007210060 8007210064 8007210064	50-387 50-335 50-387 50-250 50-250	8 0 0	Friends of the Earth Gage-Babcock Associates, Inc Gambia	8007310265* 8007110506 8007140034* 8007150119 8007310028	FOIA 50-320 50-361 PR XPORTLIC	p O
	8007220069* 8007220374 8007220379 8007220380 8007220419	50-335 50-335 50-335 50-250 50-250	Q: P: G: F: S:	Gasser Associates,P A Gaston County,NC Oeneral Atomic Co (subs of Gulf Gil	8007180193* 8007140461 8007140473* 8007140488* 8007020205	CONTRACT 50-269 50-269 50-269 PR	
	8007220421* 8007220543 8007220543 8007220550* 8007220550*	50-250 50-250 50-250 50-250 50-250	용 R R R	Co) General Atomic Co (subs of Oulf Oil	8007100046 8007020084	PR XPORTL10	;
	8007230181 8007230442 8007230442	PR 50-250 50-250	F F	Corp) General Electric Co	8004190915 8007010090* 8007010092*	71-9139 50-397 50-397	A
	8007230454 8007230454 8007230798 8007240075 8007240075	50-250 50-250 50-389 50-250 50-250	F F M R R		8007010095* 8007010098* 8007010349 8007010507 8007010595	50-397 50-397 TOPREP TOPREP 71-5980	A
	8007240086* 8007240086* 8007240174 8007240174	50-250 50-250 50-250 50-250	R R R		8007010598* 8007010600* 8007010602* 8007010603* 8007010605*	71-5980 71-5980 71-5980 71-5980 71-5980	
	8007240177* 8007240177* 8007240263* 8007250272	50-250 50-250 50-250 50-335	R R G		8007020611* 8007030231* 8007070067 8007070249	70-130B 70-1113 PR GEN TEC	18
	8007250282 8007250282 8007250312 8007280531	50-250 50-250 50-335 50-250	Q Q G P		8007080212 8007090310 8007100135 8007100191*	70-1113 TOPREP REGOD PR	-
	8007280531 8007280562 8007280562 8007280647 8007290624	50-250 50-250 50-250 50-335 50-335	P P F F		8007110499* 8007110503* 8007140038	BECY SECY 70-1308	,
	8007290824 8007300558 8007300558 8007310084	50-250 50-250 50-250	r Q Q Q		8007140048* 8007140354 8007140426 8007140450*	10cfr Toprep Toprep 50–331	e .
	8007310084 8007310220*	50-250 50-389	G G		8007140546* 8007150031*	SECY 70-1113	

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJE CATEO	
	8007150033* 8007150104 8007150407 8007150724 8007160360	70-1113 PR RES TOPREP 50-70	P		8007110429 8007110432 8007110437* 8007110442* 8007110455		8 8 8
	8007140703* 8007140709* 8007170574* 8007180123* 8007180440	50-341 50-341 50-260 50-277 71-9136	A A P P		8007110463* 8007110521* 8007140357 8007140384 8007150133		Q
	8007180470* 8007210366 8007220139 8007220147 8007220169	71-9136 TOPREP 70-1308 70-1308 70-1308			8007150496 8007150508* 8007150539 8007150544* 8007150635	50-321 50-321 50-321 50-321 50-346	8 8 8
	8007220170 8007220329 8007220349 8007250515 8007250587*	70-1308 TOPREP 50-70 TOPREP GA999	P		8007150642* 8007150664 8007150674* 8007150678 8007150685*	50-366 50-321 50-321 50-366 50-366	88888
	8007280058 8007280131 8007280407 8007280577 8007280579	71-170 XPORTLIC XPORTLIC 50-70 TOPREP			8007170382 8007170387* 8007170372 8007170405 8007170408*	50-321 50-321 50-321 50-366 50-321	8 8 8 8
Ommeras Electric Co . Nuclear Emergy Products Div	8007280637 8007310042 8007310044 8007310270# 8007210391	50-70 XPORTLIC XPORTLIC FOIA NUREO			8007170410* 8007170414 8007170419* 8007170451 8007170453	50-346 50-321 50-321 50-321 50-344	9998
General Kotors Corp General Public Utilities - GPU Service	8007280077 8007310066 8007280360 8007280366* 8007030334	71-4986 XPORTLIC XPORTLIC XPORTLIC 50-320			8007170463* 8007170468* 8007170481 8007170497* 8007210370	50-321 50-366 50-321 50-321 50-321	8 8 8
Corp Ceo-Genters, inc Georgia Power Co	8007150730 8007160670 8007240367 8007160498# 8007010474	50-320 50-289 PR CONTRACT 50-321	I P		8007210371* 8007210384 8007210384 8007210393 8007210397*	50-321 50-321 50-321 50-366 50-366	8000
otorgia i outo oo	8007010494 8007010503* 8007010510 8007010518* 8007020218	50-364 50-364 50-366 50-366 50-424	8 6 8 8 9		8007210484 8007210492# 8007220275 8007220281 8007220281	50-321 50-321 50-424 50-321 50-321	8 0 0
	8007020342 8007020520 8007020523* 8007020628 8007020628	PR 50-366 50-366 50-321 50-321	8 8 P		8007220422 8007220514 8007220519* 8007240124 8007240128*	50-321 50-321 50-366 50-366	8 8 8
	8007020638 8007020642* 8007030261 8007030261 8007030272	50-321 50-321 50-321 50-321 50-346	5 5 5 5 5		8007240165 8007240167# 8007240264* 8007250292 8007250292	50-346 50-346 50-321 50-321 50-321	8 6 6
	8007030274* 8007030276 8007030277 8007030278* 8007030279*	50-366 50-321 50-366 50-321 50-366	9 9 9 9		8007250411 8007250412* 8007280128* 8007280445 8007280446*	50-366 50-366 50-321 50-321 50-321	8 9 8
	8007030280 8007030282* 8007030284 8007030286* 8007080287	50-346 50-346 50-321 50-321 50-321	8 8 8 8		8007280447* 8007280447* 8007280450 8007280455* 8007280512*	50-321 50-366 50-366 50-366	8 8 8 8
	8007080287 8007080322 8007080327* 8007080344 8007090074	50-321 50-321 50-321 50-424 50-321	P P P H O		6007280514 8007280518 8007280526* 8007280538 8007280541	50-321 50-366 50-366 50-321 50-321	880
	8007090339 8007090339 8007110259* 8007110285 8007110304	50-321 50-321 50-321 50-321 50-321	Q Q Q S S		8007280341 8007280372 8007280372 8007280388* 8007280429	50-321 50-321 50-321 50-321 50-321	8888
	8007110307 8007110313* 8007110366 8007110368 8007110400	50-321 50-321 50-366 50-321 50-321	5 9 9 9		8007280634 8007280640* 8007280642* 8007280642*	50-321 50-321 50-321 50-321	р В Р
	8007110403* 8007110415 8007110426*	50-321 50-321 50-321	8 8 8		8007280678 8007280680* 8007280682 8007280682	50-321 50-321 50-321 50-321 50-321	R R B R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	B0072806B6* B007280670* B007280672* B007280672* B007290618	50-321 50-321 50-321 50-321 50-321	R S R R Q	House of Rep , Foreign Affairs	8007280189 8007280536* 8007300367 8007310375 8007250284*	PRM 50-329 50-397 50-289 50-275	H H H
	8007290518 8007290774 8007290774 8007290777* 8007290777*	50-321 50-424 50-424 50-424 50-424	د د د	House of Rep , Government Operations House of Rep , Interior & Insular Affairs	9007250246* 8004280239 8007020279* 9007110509 8007180431*	50-546 50-352 WASTE MO PRM CDMMIES1	
	8007300392 8007300513*	50-321 50-321	S	Hause of Rep , Interst & Foreign Commerce	8007230365* 8007110279*	20-350 20441881	U
	8007310275 8007310275 8007310287*	50-321 50-321 50-321	G G	Housing & Urban Development, Dept of Housing Lighting & Power Co	8007300365 8007220051 8007010072	50~498 40~8749 50~498	O.
Georgia. State of Georgia, Univ of,	8007310287* 8007310527 8007310527 8007150069 8007100349	50-321 50-321 50-321 PR 71-389	Q Q		8007020471 8007020618 8007020678* 8007020678* 8007020678	50-466 50-498 50-498 50-498 50-498	0 A A B
Germany, Federal Republic of Gibbs & Hill, Inc (subs of Dravo Corp) Gilbert/Commonwealth Cos	8007100353* 8007020554* 8007310255 8007210527* 8007070104	71-387 50-320 NUREQ 50-445 TOPREP	Q A		8007080015* 8007080017* 8007080059 8007090189 6007090246	50-466 50-466 50-466 50-466 50-478	0 0
Ooldberg, Fieldman & Hjelmfelt Oolder Associates Ooldsmith, R	8007220385* 8007140875 8007250542* 8007280717* 8007140337	50-302 50-344 CONTRACT CONTRACT 50-10			8007070244 8007070365 8007070365 8007100433 8007100443	50~498 50~498 50~498 50~498 50~498	9 9 9
Onuld-Brown Boveri Greenpeace Foundation Oulf & Hestern Industries, Inc Oulf Nuclear, Inc	8007080191 8007020127 8007010142# 8007010151# 8007140582	50-354 FDIA GA999 GA999 PR	A		8007100443 8007110337 8007110337 8007150075* 8007150425	50-498 50-498 50-498 50-498 50-445	8 8 9 0 M
Gulf Oil Corp , Gulf Mineral Resources Co	8007020128	WASTE MG	21		8007150425	50-445	м
Gulf Science & Technology Co Oulf States Utilities Co	8007030190 8007020135* 8007160495 8007210148*	PR WASTE MG NUREO 50-450	GT Q		8007150425 8007150645 8007150645 8007160219	50-445 50-498 50-498 50-498	# 8 8
HEH, Dept of, Food & Drug Administration HHS, Dept of, US Public Health Service	8007220594 8007290424 8007110539# 8007070264 8007140640	50-458 PR CONTRACT 50-10 PR	Q T D		8007160219 8007160570 8007160604 8007160604 8007160609*	50-498 50-466 50-498 50-498 50-498	8 6 8 8
Hanford Engineering Development	8007150084 8007140646	PR 71-6387			8007160607* 8007160639	50~498 50~466	8
Laboratory	8007140649* 8007140654* 8007140658*	71-6387 71-4387 71-6387			8007160645 8007170203 8007180432	50~466 50~498 50~466	0
	8007140662* 8007140666* 8007140668* 8007140673* 8007140678*	71-6387 71-6387 71-6387 71-6387 71-6387			8007210511 8007210511 8007220378 8007220578 8007230476	50-498 50-498 50-498 50-498 50-498	5 5 6 6 6
Harding-Lawson Associates	8007140687# 8007140690# 8007250440 8007250444# 8007280236#	71-4387 71-4387 PROJ PROJ CONTRACT	r		8007230476 8007230512 8007230512 8007230525 8007230540	50-478 50-478 50-478 50-478 50-478	9 8 8 8
Harrisburg Hosp Harrisburg, PA Health Physics Society High Rock Lake Association Hill Christopher & Phillips	8005190626 8007100001 8006200066 8006200071* 8007030048	50-320 PR 50-488 50-488 50-275	, Р С		8007230540 8007230718 8007230718 8007250424 8007250441	50-498 50-498 50-498 50-466 50-445	8 0 0 0 N
Hirata Valve Industry Co , Ltd , Xawaski	8007300110 8007310389 8007290477*	50-275 50-212 GA999	0		8007290082 8007300070 8007300070 8007300348	50-466 50-478 50-478 50-466 50-466	G G H H
Div Hittman Nuclear & Development Corp	8007290487# 8007170286#	0A999 50-219	Q		8007300348	50-446	н
(subs Hittman Gorp) House of Rep	8007020088* 8007020217*	50-10 50-324	U H		8007300375 8007300375 8007300392 8007300402	50-498 50-498 50-498 50-466	A B Q
	8007020237* 8007110343* 8007110447	50-32 0 50-352 50-313	Н U Н		8007300413 8007300435 8007300447	50-466 50-466 50-466	000
	8007160634 8007180427* 8007210390 8007240406	50-329 COMMISSI 50-397 50-320	บ H	Howard Univ	8007310094 8007310309	50-466 50-466	G G
	B007250215* B007250264*	COMMISSI 50-317		Hudson Light & Power Dept Husco, Inc Hunton & Williams			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	RΥ
Hydrology Associates,Inc	8007090306 8007170384 8007220446 8007240029* 8007240041*	50-322 50-322 MISC 40-845	. G		8007140002 8007160692 8007160698* 8007230142 8007230164*	PR 50-274 50-274 50-289 50-289	FFGG
IRT Corp idaho National Engineering Laboratory	8007240048* 8007160490 8007240257 8007280683 8007290217	40-845 CONTRA RES NUREO 50-254		international Atomic Energy Agency (Austria)	8007280024 8007310397 8007020674*	PR 50-275 COHMISS ORO	A NOI
Illinois Power Co	B007030215 B007030215 B007110233* B007160626 B00716063B*	50-461 50-461 50-461 50-461	0 0 8 8	International Structural Engineers, Inc Ioma Electric Light & Power Co	8007300587* 8007010453 8007020719 8007030212 8007030217* 8007030224	50-370 50-331 50-331 50-331 50-331 50-331	A P 0 8 8 8
	80071&0651* 80071&0665* 8007160679* 8007210521* 8007230518	50-461 50-461 50-461 50-461 50-461	8 9 9 9		8007030235* 8007030238 8007030241* 8007070142 8007070252	50-331 50-331 50-331 50-331 50-331	8 8 9 9
Illinois Safe Energy Alliance	8007250559 8007280506 8007300429 8007140337 8007230524	50-461 50-461 50-10 50-10	A 9 9 0		8007070255* 8007070272 8007110411 8007110419* 8007110471	50-331 50-331 50-331 50-331 50-331	6 8 8
Illinois, State of	8007070028 8007080026 8007140432 8007140437* 8007140449*	50-514 50-347 PR PR PR	G D		8007110482* 8007140366 8007140434 8007140442* 8007160259	50-331 50-331 50-331 50-331 50-331	8 P P Q
	8007140521* 8007150056 8007160587 8007180387 8007230527	CONTRAC 50-367 70-1306 70-1306 27-39	G B		8007160624 8007170563 8007220367 8007220371* 8007220394	50-331 50-331 50-331 50-331	P 0 R R P
Inberg-Hiller Engineering Co Indiana & Hichigan Electric Co	8007250442 8007310133 8007270221 8007310474 8007020245	27-39 27-39 40-299 40-299 50-315	G		8007220494 8007220497 8007220544 8007220599 8007230233	50-331 50-331 50-331 50-331 50-331	9 9 9 9
	8007020591 8007030206 8007090289 8007090292* 8007110465	50-315 50-315 50-314 50-314 50-315	P 8 8		8007230464 8007230482 8007250675 8007250677 8007280377	50-331 50-331 50-331 50-331 50-331	5 P G G P
	8007150586 8007150597* 8007150623* 8007150684 8007150695*	50-315 50-315 50-315 50-316 50-316	8 8 8 8	isham, Linco)n & Beale	8007280480 8007020462 8007080349 8007080360* 8007090045	50-331 50-599 PR PR 50-329	P Q
	8007150696 8007150703* 8007160384 8007180324 8007210537	50-315 50-315 50-315 50-315 50-314	8 0 8		8007090316 8007140020 8007150052 8007150431 8007160593	50-255 50-327 50-155 50-445 PR	0 0 0
	8007210541* 8007220080 8007220080 8007230269 8007230269	50-314 50-318 50-318 50-318 50-318	9		8007210446 8007220194 8007230810 8007300362 8007300368	50~255 50~329 50~255 50~295 50~155	0000
·	8007250016 8007250493 8007280510 8007300252 8007310284#	50-314 50-315 50-315 50-315 50-315	0 P 0 0	Island Closeup News Service Isotope Products Laboratories	8007300421 8007300464 8007300468 8007140214 8007020383	50-329 50-155 50-155 FOIA XPOR (LIC	000
Indiana & Michigan Power Co	8007310399 8007150542 8007150547* 8007150555	50-315 50-315 50-315 50-314	V R R	Isaak Waiton League of America, Porter County Chapter Jack R. Benjamin & Associates, Inc	8007080055	50-367	0
Indiana State Univ	8007150561* 8007250028*	50-314 CDMM165	R	Japan Jersey Central Power & Light Co	8007220372* 8007250555 8007010468 8007020377	50-70 XPORTLIC 50-219 50-219	P Q
Indiana, State of Inside D O E . McGrau-Hill Publication Institute for Energy & Environmental Research Heidelberg. H Germany Interex Corp	8007020300 8007170202 8007150042 8007310417*	PR FOIA 50-320 50-277	P R		8007030216 8007070113 8007070259 8007070265*	50-219 50-219 50-219 50-219	P P S S
Interior Dept of	8007140016 8007160511	50-275 50-397	H		8007090259 8007090262	50-219 50-219	Q F
Interior.Dept of, Bureau of Mines Interior.Dept of, Fish & Wildlife Service	8007100083 8007020033 8007150710 8007210368	PR 70~2909 50~250 50~250	p P		8007110370 8007110373* 8007110373* 8007110375	70-1333 50-219 50-219 50-219	8 8
Interior.Dept of, Geological Survey	8007310377 8004280218 8007030193	50-250 PR PR	P		8007110383* 8007150705 8007140500		8 R P

8007170279 50-219 P 8007230458 8007180409 50-219 P 8007230462* 8007180415* 50-219 P 80072305768 8007180423* 50-219 P 8007250568 8007180423* 50-219 P 8007250568	50-322	
4041100441 00 FT 1 4	50-322 50-322 50-322 Nuneo	AAKA
8007180589 50-219 Q Los Alamos Scientific Laboratory 80071604053 8007210042 50-219 Q 80071604053 8007220343 50-219 R 8007180175 8007220344* 50-219 R 8007180175 8007220344* 50-219 R 80071801040 8007220345 50-219 R 80071801040 8007220347 50-219 R 80071801040	REGGD PR REGOD ACRS RES	
8007230574* 50-219 8 Los Alamos Technical Associates, Inc 8007280209* 8007250170 50-219 0 Los Angeles, CA 8007140051* 8007250305 50-219 0 Louisiana Power & Light Co 800701031* 8007290184 50-219 P 8007010341 8007010341 8007300340 50-133 6 \ 8007010343*	FOIA PR 50-382 50-382 50-382	8 F
Jones, Grey & Bayley 8007140026 50-275 G 8007020397 Justice, Dept of 8007160347 50-445 M 80070204057 8007170324 50-445 M 8007080179 80072806364 50-445 M 8007080234 8007300418 50-445 M 8007080239	50-382 50-382 50-382 50-382	8 4 8
KHC, Inc B007110953 PR B007100163 KMS Fusion, Inc (subs of KMB Industrie B007020346 XPORYLIC B0071001654 s, Inc) B007100169	50-382 50-382 50-382	KK
Kaman Sciences Corp 8007160513* CONTRACT 8007100429 Kansas Qas & Electric Co 8007290017* 50-482 0 8007150417 Kansas, Univ of 8007170317* 50-482 A 8007160586	50-382 50-382 50-382	Q Q K
Kawecki Bergico Industries, inc 8007020153 XPORTLIC 8007140616 Kerr-McGes Chemical Corp (subs of Kerr-McGes Corp) 8007020667 PR 8007220373 B007140286 FOIA 90072704374	50-382 50-382 50-382 50-382	K F Q
8007210109 40-2061 8007310395* 8007310262 FOIA Lowenstein, Newman, Reis, Axelrad & Toii 8007020368	50-382 PR PR	Q.
8007110027* 40-2041 8007020453 8007170491 PR 8007020471	50-367 50-466	60
8007010592* 40-8647	50-376 PR PR 50-466 50-367	0
8007030035+ 40-8647 8007090058 80070900658 8007090169 8007090169 8007090169 8007100160 80070901804 8007100160 80070901804 8007150425	50-466 50-466 PR PR 50-445	о о м
Lapp, Inc B00713010 XPORTLIC B007180221* COMMISSION B007150425 Lawler, Matusky & Skelly Engineers B007170403* 50-220 P B007140639	50~445 50~466 50~466 50~466	M G G
Lawrence Berkeley Laboratory BO07220023* MISC B007140467 Lawrence Livermore Leboratory B007140617 NURG9 B007180422 B007180422 NURG9 B007220023 NURG9 B007220023 B007220024 B007220024 B007220025 B00722000000000000000000000000000000000	50-466 50-376 50-466	00
B007220034 NURE0	50-445 50-466 PR 50-498	žo o
8007140370 50-452 0 8007310413 8007140378* 50-452 0 8007310494 8007140378* 50-452 0 8007310308	50-466 30-466 50-466 50-466	0000
8007140619 50-320 H 8007170393 50-220 P Lower Alloways Creek, NJ 8007110112 Magnaflux Corp (subs of Peabody Galion 8007020044 8007300032 PR Corp)	50-272 71-5	Ģ
League of Homen Voters of San Luis B007010457 50-275 H Maine Public Service Co B007080018* Oblispor.CA Maine Public Service Co B007080018* Lehigh Univ B007140642 RES Maine Yankee Atomic Power Co B007010339*	71-5 50-443 50-309	1 8
B007170460 RES B007030225 B007030225 B007030225 B007030225 B007030225 B007030225 B007030225 B007030227 B007030217 B007030217	50-309 50-309 50-309 50-309 50-309	P I S S P.
Lockheed Environmental Sciences 8007010226* 50-206 R 8007100268* 50-206 R 8007110386 80071103867*	50-309 50-309 50-309	8 8
8007020073* 50-322 9 8007170321 8007030053 50-322 0 6007180070 8007090243 50-322 K	50-307 50-309 50-309	0 0
80072[0369* 8007090306 50-322 0 80072[0431* 8007140390 50-322 8 80072[0431* 8007150655 50-322 A 80072[0401	50-309 50-309 50-309 50-309	0888
8007160867* 50-322 Q 8007170384 50-322 0 8007250405* 8007210040* 50-322 Q 8007280405* 8007210045 50-322 Q 8007280405*	50-309 50-309 50-309 50-309	P 0 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Maine, State of Mallinckrodt, Inc Manchester Memorial Hosp Manchester, CT Mapleton Intervenors	8007280611* 8007110481 8007110534 8007150318* 8007140017	50-309 PR 70-2651	R Н		8007070313* 8007070320 8007070322* 8007070343 8007070343	50-289 50-320 50-320 50-289 50-289	8 P P
Marine Biological Consultants, Inc , Mark IV Industries, NRD Div Marquette Univ	8007140649* 8007010226* 8007100268* 8007110159 8007240258*	50-206	H R R		6007080074 8007080211 8007080214* 8007080244 8007080358	50-289 50-289 50-289 50-289 50-320	P 8 8 F P
Marrack. D	8007250012* 8007030025 8007030029* 8007110080 8007160560	50-466 50-466	9 0 9 9		8007080358 8007080375 8007110015* 8007110020* 8007110023*	50-320 50-287 70-1333 70-1333 70-1333	Q Q
Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div	8007160545* 8007220552 8007010516	50-466 50-259 50-272	9 9 9		8007110024# 8007110030# 8007110032# 8007110040# 8007110422	70-1333 50-287 50-320 50-320 50-320	コンフロ
	8007080261 8007150479 8007150490 8007160415 8007310342	50~155 50~280 PR 50~272	,		8007110446 8007140006 8007140224 8007140346 8007140352	50-287 50-320 50-289 50-289 50-320	0 T 0 P
	8007310374 8007310374 8007310435 8007310436 8007310436	50-272 50-272 50-302 50-259			8007140365 8007140381 8007140385 8007140385 8007140413	50-289 50-289 50-320 50-320 50-320	Р О Н Н Р
Marubeni America Corp (subs of Marubeni		XPORTLIC	,		8007140419 8007140419	50-320 50-320 50-320	P P
Corp) Maryland, State of	8007290467* 8007020338*	XPORTLIC State Pro	1		8007150499 8007150502* 8007150507	50-320 50-320	P P
Maryland, Univ of	8007070085 8007230495	PR 50-146	₹		8007150513 8007150514#	50-320 50-320	8
Massachusetts Institute of Technology Massachusetts Municipal Wholesale Co Massachusetts, State of	8007100030 8007210258* 8007080037* 8007030365	PR CONTRACT 50-443 PR			8007130515 8007150519# 8007150589	50-320 50-320 50-289	B
Massachusetts, Univ of Matheson Gas Products Mayer, Brown & Platt	8007160851# 8007100079 8007310082 8007020608 8007140038	PR XPORTLIC 70-1308 70-1309	v		8007150721 8007140431 8007140522 8007140524 8007140525*	50-289 50-320 50-320 50-289 50-320	9 8 8
	8007220138 8007220147 8007220168 8007220170	70-1308 70-1308 70-1308 70-1308			8007160526* 8007160596 8007160618 8007160623* 8007160667	50-289 50-320 50-289 50-289 50-320	8 8 8 8 F
McDermott, WIII & Emery	8007230519 8007170388	70-1308 30-445	1		8007160667 8007170338	50-320 50-320	F
HcGean Chemical Co . Inc HcGraw-Hill Publications Co HcPhillips.J L	8007280270 8007020731# 8007110003 80071100\$5	F01A CONTRACT 70-2909 70-2909			8007170340* 8007170373 8007170395	50-320 50-320 50-320	P P
Medi-Physics, Inc Hedinaslectric Cooperative, Inc	8007070178 8007170388	PR 50-445	1		8007170442 8007170456 8007180376	50-320 50-320 50-320	P
Memorial Hosp of Natrona County Casper, WY Memohis State Univ	8007100129 8007280286	REGOD 50-538	•		8007180391 8007180394	50-289 30-289	0
Metal Ballows Corp Metropolitan Edison Co	8007010572 8007110528 8007010155	XPORTLIC XPGRTLIC	1		8007180396 8007180404 8007180404 8007180414	50-289 50-320 50-320 50-289	96
	8007010326 8007010388 8007010388 8007010454	50-289 50-289 50-289 50-320	•		8007180421 8007210359 8007210372	50-289 50-320 50-289	R
	8007010458* 8007010460 8007010460		3		8007210383 8007210398 8007220442	50-320 50-289 50-320	P O
	8007020482	50-320 (40-320 (8007220471 8007220485 8007220492 8007220498 8007220553	50~289 50~320 50~289 71~9081 50~320	F 0 0 F
		!	•		8007220553 8007220555* 8007220555* 8007220584 8007220584	50-320 50-320 50-320 50-320 50-320	ドチドノノ
					8007220572 8007230434 8007230439 8007230514* 8007230521	50-289 50-320 50-320 50-289 50-289	900

AUTHDR AFFILIATION	ACCESSION REMUN	SUBJECT	Y	AUFHOR AFFILIATION		ACCESSION NUMBER	CATEGOR	
***************************************	8007230404 8007230410 8007250354 8007250401 8007250504	50-269 50-289 50-289 50-289 50-289	0 0 0			6007110417* 6007110417* 6007110430 6007110430 6007110430	50-416 50-416 50-416 50-416	6 6 8 8
	8007250615 8007280483 8007270617 8007270797 8007270805*	50-287 50-287 50-287 50-287 50-289	S G R R			8007140388 8007140575 8007150073 8007150093 8007150099	50-416 PR 50-416 50-416 50-416	E S S
	8007290811 8007290817* 8007300437 8007300447 8007300449	50-320 50-320 50-289 50-320 50-446	5 6 7 6			8007150099 8007150105 8007150105 8007140585 8007140585	50~416 50~416 50~416 50~416 50~416	8 8 8 8
Michigan, State of Michigan, Univ of	8007310137 8007310406 8007310439 8007290063* 8007020659	50-289 50-320 50-320 State Pr PR	P P P			8007160610 8007160611 8007160611 8007160617* 8007160617	50-416 50-416 50-416 50-416 PR	A 5 6 A
	8007080357* 8007110543 8007160280 8007230223 8007280338	PR ORG RES RES CONTRACT	ľ			6007160642 6007160642 6007160862* 6007160866* 6007170290	50-416 50-416 50-416 50-416 50-416	6 0 6
Microtech Industries, Inc Middle South Services, Inc	8007020378* 6007070134* 8007020404 6007020413* 8007100005	CONTRACT CONTRACT PR PR PR				8007170290 8007170294* 8007170294* 8007170396 8007170396	50-416 50-416 50-416 50-416 50-416	9 9 9
Midwest Environmental Protection Association	8007100355 800721 0 150 8007300279	PRM 40-1341 40-299				8007170400* 8007170400* 8007170435 8007170435	50-416 50-416 50-416 50-416	8 8
Miller Technical Services	8007300285* 8007300288	40-299 40-299 40-299				8007170592 8007180293	50-416 50-416 50-416	§ F F
Miller, D S	8007300289* 8007020607 8007020610* 8007030059* 8007110345	50-309 50-309 PR PR	0			8007160293 8007210270 8007220389 8007220389	50-416 50-416 50-416 50-416	6 6
Miner & Miner, Inc Ministry of Concern for Public Health Minnesota, State of	8007300122 8007300127* 8007110575* 8007020447 8007100208	50-309 50-309 CONTRAC1 PR 50-282	т С			8007220573* 8007250432 8007250510 8007250520*	50-416 50-416 50-416 50-416	A Q S
Minnesota, Univ of, Minneapolis	8007140011 8007230583 8007250422 8007030200 8007140014*	PR PR 50-282 PR PR	Q			6007250520* 6007280494 6007280494 6007280566 6007290655	50-416 50-416 50-416 50-416 50-416	A A S
Mississippi Power & Light Co	8006190577 8006300375 8006300382* 8006300384* 8007010361	50-416 50-416 50-416 50-416 50-416	8 F F F			8007270655 8007270666 8007270666 8007270671 8007270671	50-416 50-416 50-416 50-416 50-416	8888
	8007010341 8007020538 8007020539 8007020539* 8007020539*	50-416 50-416 50-416 50-416 50-416	F 8 8 8 8	Mississippians Against Disposai		8007270714 8007270714 8007270771 8007270771 8007080009	50-416 50-416 50-416 50-416 PR	5 8 8
	8007020341* 8007020541* 8007020579 8007020601	50-416 50-416 50-416 50-416 50-416		Missouri, State of Missouri, Univ of, Columbia Missouri, Univ of, Rolla		8007270038* 8007080240 8007080244 8007140351 8007220122	50-483 50-186 50-186 50-186 50-183	A S S G
	8007020403* 8007020403*	50-414 50-414	8 8	Mitsubishi International Corp Mitsubishi Corp }	(subs of	6007240030 8007240034#	XPORTLIC	
	8007020415 8007020430 8007020430	50-416 50-416 50-416	8	Mitaul & Co , Ltd		8007240036# 8007310482 8007100281 8007100287#	XPORTLIC XPORTLIC XPORTLIC	C C
	8007020632* 8007020632* 8007020640 8007020640 8007030245	50-416 50-416 50-416 50-416 50-416	8 8 8 8	Mobile Systems Monsanto Research Corp		8007110283* 8007110283* 8007100368* 8007170161* 800716034	XPORTLIC XPORTLIC CONTRAC CONTRAC XPORTLIC	C T
	8007070118 8007070118 8007070245 8007070245 8007070298	PR PR 50-416 50-416 50-416	E E B	Montana, State of Morrison Knudsen Co , Inc Mount Sinal Hartford, CT Municipally Duned Electric Syst Association	ems	8007160399* 8007020332 8007220119* 8007230601* 8007030189*	XPORTL16 FR WASTE #6 70-2000 50-413	от ;
	800707029B 8007110412 8007110413 8007110413	50-416 50-416 50-416 50-416	8 K 8	Mutual Atomic Energy Liabrity ers	Underwrit	8007100134 8007210442	PAM MIEC	t t

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	-
NL Industries, AL Nuclear Div NPS industries, inc NUS Corp	8007280315 8007140807 8007100307* 8007100307* 8007100311*	71-9010 50-329 50-280 50-280 50-280	S P P		8007080345 8007080346* 8007080391 8007080395* 8007090005	50-278 8 50-278 8 50-278 8 50-278 8 50-278 8	B R
	8007100315* 8007100315* 8007100315* 8007100321* 8007100321*		Р Р Р Р		8007090007* 8007100016 8007150702 8007160440 8007210152	50-298 5 50-298 5 50-298 5 50-298 6	3 3 P
	8007100321* 8007100323* 8007100323* 8007100323*	50-280 50-280 50-280 50-280 50-280	ր թ թ		8007240259* 8007250421 8007250425* 8007250501 8007280452	50-298 50-298 50-298 50-298 50-298	R R S
	8007100329* 8007100329* 8007100329* 8007100335* 8007100335*	50-280 50-280 50-280 50-280 50-280	P P P P	Neighbars for the Environment Neutron Products, Inc	6007280467* 6007280584 8007280592* 8007140036 8007230347	50-278 8 50-278 8 50-278 8 PR 71-121	
	8007100338* 8007100338* 8007100347* 8007100347* 8007100347*	50-280 50-280 50-280 50-280 50-280	P P P P	Nevada, State of New Bedford Gas & Edison Light Co New England Coalition on Nuclear Pollution	8007230354* 8007230739* 8007080022* 8007110048	71-121 COMMISSION 50-449 PR	ľ
	8007100351* 8007100351* 8007100351* 8007100359* 6007100359*	50-280 50-280 50-280 50-280 50-280	P P P P	Naw England Power Co New Hampshire, State of New Jersey, State of New Mexico, State of	8007080014* 8007180467* 8007100175 8007100178* 8007290035* 8007030045	MISC 50-272 50-272	I 0 0 H
	8007100359# 8007100365# 8007100365# 8007100365# 8007100371#	50-280 50-280 50-280 50-280 50-280	թ թ թ	New York Federation for Safe Energy New York, State Univ of, Buffalo	8007210135* 8007010508 8007030204 8007030209* 8007280654	CONTRACT 50-320 I PR PR	H R
	8007100371* 8007100375* 8007100375* 8007100380* 8007100380*	50-280 50-280 50-280 50-280 50-280	_ይ 6 6 6	New York, State of	8007290694 8007110121 8007150067 8007170277* 8007180047*	50-57 PR PR PR State Pro	R
	8007100382* 8007100382* 8007100387* 8007100387* 8007100391*	50-280 50-280 50-280 50-280 50-280	Ե Ե Ե	Newport News Industrial Corp (subs of Newport News Ghipbuilding & DryDock Co)	8007180217# 8007210267# 8007080230	State Pro CONTRACT MISC	9
	8007100391* 8007100403* 8007100407* 8007100407* 8007100407*	50-280 50-280 50-280 50-280 50-280	P P P P	Niagara Mohawk Power Corp	8007070089 8007070261 8007080337 8007150122 8007170360 8007170361*	50-220 (50-410 (PR 50-220 (O P A R
	8007100409# 8007100414# 8007100414# 8007100415# 8007100415#	50-280 50-280 50-280 50-280 50-280	면 면 면 면		8007170394* 8007170397* 8007180073 8007210100 8007250192	50-220 50-220 50-220 50-220 50-220	P ወ ወ
	8007140051* 8007220032* 8007220036* 8007220101* 8007220111*	PR WASTE MOT WASTE MOT WASTE MOT WASTE MOT	τ t		8007250472 8007280275 8007280275 8007280445 8007280540 8007270586	50-220 50-220 50-220 50-220	A I I Q H S
NUSAC, Inc National Audubon Society. Central Midwest Regional Office National Campaign for Radioactive Waste Safety	8007280527# 8007140636# 8007170089 8007220326 8007300323	CONTRACT FOIA 50-320 FOIA 50-10	P	Nissho-Iwai American Corp North Anna Environmental Coalition	8007270383 8007270600* 8007300047 8007280464 8007070075* 8007070079*	50-220 PR XPORTLIC 50-280	я н н
National Council on Radiation Protection & Measurements National Employer Denefit Associates National Wildlife Federation Natural Resources Defense Council		PR FOIA REGOD PR PR	-	North Carolina Electric Membership Corp North Dakota, State of Northcutt Ely Northeast Nuclear Energy Co (subs of Northeast Utilities)	8007300412 8007210486* 8007150458 8007210455 8007210455 8005300283	50-280 50-413 50-484	O A O M
		70-143			8007010328 8007010337 8007010337 8007010337 8007010354	50-213 50-213 50-213	P F F G
			Q Q		8007010445 8007010450* 8007020039 8007020472 8007020569	50-336 4EE-08 89	8 0 P
		278	8 8		8007030354 8007030354		F F

AUTHOR AFFILIATION	ACCESSION NUMBER	DALEUS	YRC	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8007030354 8007070251 8007070318 8007070324* 8007070341	50-245 50-245 50-336 50-336 50-336	# b a a a		8007010549 8007010583* 8007020162 8007030178 8007030178	50-282 50-262 50-263 50-282 50-282	0 P Q R
	8007070372* 8007080135 8007080164 8007080169* 8007080176*	50-336 50-245 50-336 50-336 50-336	5 P P P P		8007030180* 8007030180* 8007030183* 8007030183* 8007030222	50-282 50-282 50-282 50-283	R R R P
	8007070231 8007070231 8007100035 8007100157 8007100164*	50-213 50-213 PR 50-245 50-245	F F S		8007070315+ 8007080251 8007080245 8007100047 8007100123	50-484 50-263 50-263 50-263 50-236	0 P P F
•	8007100167 8007100172* 8007170425 8007170519 8007180408	50-245 50-245 50-213 50-423 50-245	8 8 9 8		8007100190 8007100195* 8007110115 8007110115 8007140192*	50-263 50-263 50-282 50-282	59 F 0
	8007180413* 8007210238 8007210245* 8007210374 8007210375*	50-245 50-336 50-336 50-336 50-336	R P R R		8007150481 8007150611 8007150614+ 8007160558 8007160562+	50-282 50-263 50-263 50-282 50-282	0 R R R
	B007210387 8007210520* 8007220457 8007220457 8007220467*	50-245 50-423 50-245 50-245 50-245	P P P		8007160562# 8007160660 8007160707 8007160707 8007170194#	50-282 50-282 50-282 50-282 50-306	R G G
	8007220467* 8007250300 8007250300 8007250303* 8007250303*	50-245 50-245 50-245 50-245 50-245	P P P		8007170398 8007180300 8007180306* 8007210132 8007210182	50-243 50-263 50-263 50-263 50-263	P P Q Q
	8007250407 8007250410* 8007280574 8007280582* 8007270852	50-336 50-336 50-245 50-245 PR	6 8 8		8007210186 8007210196* 8007210379 8007210380* 8007210437	50-263 50-263 50-306 50-306 50-282	8 8 6
Northeast Utilities	8007010337 8007020439 8007020441 8007090294 8007100200	50-213 PR PR PRM 50-245	F		8007210444* 8007210509* 8007220090 8007220090 8007220542	50-282 50-263 50-282 50-282 50-282	800
	8007100200 8007110466 8007110474* 8007140344 8007150622	50-245 50-245 50-245 50-336 50-245	P S P I		8007220542 8007230211 8007230211 8007250077 8007250077	50-282 50-282 50-282 50-282 50-282	0 0 0 0
	8007150422 8007160476 8007160480* 8007170320 8007180137	50-245 50-245 50-245 50-213 50-213	I R R Q Q		8007250340 8007250409 8007250565 8007280056 8007280056	50-282 50-484 50-263 71-9018 71-9018	8 0 0
	8007180278 8007180307* 8007230048 8007280673 8007280673	50-245 50-245 PRM 50-213 50-213	8 9 P		8007280056 8007280057 8007280381 8007280410 8007280410	71-9108 50-263 50-263 50-263 50-263	i i
Northern Illinois Univ Northern Indiana Public Service Co	8007290597 8007220589 8007010478 8007020453 8007110438	50-245 50-10 50-367 50-367 50-367	Q D A O R		8007280441 8007280488 8007280489 8007290669 8007290677*	50-243 50-243 50-243 50-282 50-282	t T
	8007210464 8007250630 8007280118 8007280141 8007280482	50-367 50-367 50-367 50-367 50-367	R Q R R	Northern Thunder	8007290841 8007300443 8007310106 8007310106 8007290703	50-263 50-262 50-282 50-282 50-484	() () () () () () () () () ()
Northern States Power Co	8007010260 8007010260 8007010267 6007010267 8007010311	50-282 50-282 50-282 50-282 50-263	0 0 0 F	Notre Deme, Univ of	8007140483 8007250578* 8007010060* 8007010067* 8007010077*	REGGD CONTRACT 40-2674 40-2674 40-2674	r'
	8007010325 8007010335 8007010351 8007010374 8007010381*	50-263 50-263 50-263 50-306 50-306	F F P		8007010085* 8007010091* 8007010097* 8007210558* 8007210549*	40-2674 40-2674 40-2674 40-2674 40-2674	1
	8007010524 8007010529* 8007010531 8007010542* 8007010549	50-282 50-263 50-263 50-263	9 9 9	Nuclear Assurance Corp	E007180469 E00722068 E00722073* E007300001 E007100312*	71-6598 40-8771 40-8771 71-6698 CONTRACT	ì

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Nucloar Energy Liability Insurance Association	8007110017* 8007110043 8007110044* 8007110051* 8007110051*	50-320 50-320 50-320 50-320 50-320)))		8007180555 8007210028 8007230441 8007250464 8007250184*	70-143 50-201 0 50-201 0 70-143 70-143	•
	8007110052* 8007110052* 8007110057* 8007110057* 8007110060*	50-320 50-320 50-320 50-320 50-320	J J J J J J J	Nuclear Fuel Bervices, Inc , West Valley Reprocessing Plant	8007280187* 8007280552 8007290547 8007290713 8007080246	70-143 70-143 70-143 70-143 50-201 Q	
	8007110040* 8007110042* 8007110042* 8007110048* 8007110048*	50-320 50-320 50-320 50-320 50-320	J J J	Nuclear Packaging, Inc	8007020361 8007020683* 8007070177 8007070179* 8007070182*	71-9130 71-9130 71-9130 71-9130 71-9130	
	8007110072* 8007110072* 8007110077* 8007110084* 8007110087*	50-320 50-320 50-320 50-320 50-320	J J J	Nuclear Power Plant Standards Committee Nuclear Safety Associates Nusem OmbH	8007070185* 8007280125 8007300337 8007100184* 8007150040*	71-9130 71-192 50-482 A PR XPORTLIC	
	8007110091* 8007110095* 8007110098* 8007110098* 8007110103*	50-320 50-320 50-320 50-320 50-320	J J J	Oak Ridge National Laboratory	E007020356 8007070371 8007070375 8007110493* 8007140031	RES NUREO REGOD 50-320 P RES	
	8007110103* 8007110107* 8007110125* 8007110128* 8007110128*	50-320 50-320 50-320 50-320 50-320	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		8007140044 8007140503 8007140507 8007140610 8007140634	RES RES NUREO RES	
	8007110132* 8007110132* 8007110135* 8007110140* 8007110143*	50-320 50-320 50-320 50-320 50-320	J J J		8007150016 8007170648 8007180065 8007180352 8007180354	REB NUREG REB RES	
	8007110147* 8007110147* 8007110151* 8007110151* 8007110156*	50-320 50-320 50-320 50-320 50-320	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		8007210498 8007280092 8007280095 8007290241 8007300041	50-247 P REB REB REB NUREO	
	8007110154* 8007110160* 8007110167* 8007110173* 8007110173*	50-320 50-320 50-320 50-320 50-320	J J J	Office of Management & Budget	8007300575 8007310246 8007310251 8007310554 8007170418*	NUREO NUREO REB NUREO COMMIBBION	
	8007110176* 8007110176* 8007110178*	50-320 50-320 50-320	7	Offshare Power Systems (subs of Westinghouse Electric Corp)	8007280729* 8007210395	COMMISSION 50-497 A	
	8007110201* 8007110208* 8007110212*	50-320 50-320 50-320	n n	Ogia Patroisum, Inc Ohio State Univ	8007210404* 8007020293 8007010383	50-497 A 40-8693 50-150 8	
	8007110217* 8007110222* 8007110222* 8007110224*	50-320 50-320 50-320 50-320	7 7 7	Ohio, State of Oklahoma, State of	8007090408 8006110406 8007100246 8007020613 8007220539	REGGD PR PR 50-556 G PR	
Nuclear Engineering Co . Inc , (subs of Teledyne, Inc)	8007110224* 800722050B 8007240155	50-320 27-48 71-6679	J	Oklahoma. Univ of	8007310153 8007030066 8007210491	50-556 0 Foia Nureo	
Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)	8007010001	50-201 71-5768	ı	Omaha Public Power District	8007010471 8007010477#	50-285 P 50-285 P	
	8007010107* 8007010121* 8007020437 8007030292 8007070014*	70-143 71-5768 70-143 70-143 70-143			8007020075 8007020299 8007020312 8007020419 8007020430	50-265 Q 50-265 Q PR 50-265 Q 50-265 Q	
	8007070191 8007070333 8007070335* 8007070350 8007100023*	70-143 70-143 70-143 70-143 70-143			8007030001 8007070375 8007070385* 8007080364 8007110096*	PR 50-285 6 50-285 B 50-285 P 50-285 Q	
	8007100028* 8007100044* 8007100052* 8007100069* 8007140044*	70-143 70-143 70-143 70-143 70-143			8007170374 8007170379* 8007180122* 8007210187 8007230530	50-285 R 50-285 R 50-285 G 50-285 Q 50-285 F	
	8007150518 8007150520* 8007150563 8007160843* 8007180475	70-143 70-143 70-143 70-143 71-249			8007230558 8007240130 8007240134* 8007280530 8007280601	50-285 G 50-285 S 50-285 S 50-285 P 50-285 G	
	8007180483* 8007180491	71-249 40-8681		Oregon State Univ	8007300078 8007150559 8007150562#	50-285 P 50-106 W 50-106 W	

### Company Co	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
Bottom	Gregon, State of	8007100017 8007180524# 8007280503	PR CONTRAC 50-344	т ,		8007280650 800728065 0 8007270264	50-387 50-397 50-397	8 8
Description		8007300372 8007300372 8007300377*	50-522 50-522 50-522	0		8007290455 8007290423 8007290423	50-387 50-387 50-387	9 8
Control Cont		8007300490# 8007300494# 8007300500#	50-344 50-344 50-344	0 0		8007100434 8007140449* 8007310383	REGOD FR 50-5	F
Damm. E.		8007220077*	40-8771					
P. C.	Osann, E. W. PRC Planning & Economics, Alan M. Voorhees & Associates Div	8007220448*	50-397	F		8007100186# 8007140046#	50-320 PR	Р
Booling		8006190921	71-9139		People Against Nuclear Emergy	8007080005*	50-289	G
	Pacific Gas & Electric Co	8006190925 8007010469 8007020394	71-9139 50-133 50-275	P		800722053 0 * 8007280613	50-287 50-320	٥
1		8007070153 8007070206* 8007100152	50-275 50-275 PROJ	A	Peru	8007230797 8007250351 8007180149#	50-522 50-522 COMMIBS	Q Q I QN
BODY1605201 50-277 A BODY160521 50-277 A BODY160521 50-277 BODY160521 50-277 A BODY160521 50-277 A BODY160521 50-277 BOD		8007140242 8007150377 8007150548	71-9094 50-275 50-133	R	Philadelphia Electric Co	8007020041* 8007020072 8007070352	50-277 50-277 50-278	0 8
S007180405 S0-277 0 S007180104 S0-277 0 S007180104 S0-277 0 S007180104 S0-277 0 S007180117 S0-277 S007180117		8007160521# 8007180340 8007180344#	50-275 50-275 50-275	A A		8007080216 8007090265 8007090265 8007100158*	50-352 50-352 50-277	8 8 P
BO07200645 SO-123 G BO07180117 SO-277 G BO07180117 SO-277 G BO07180149 SO-287 S BO07180149 S BO07180149 S BO071801		8007180405	50-275	0		8007180106	50-277	Q
B007200648 50-133 0 10-277 R 10-		8007230662 8007240187 8007250386	50~133 50~275 50~133	Q Q O		8007180117 8007180117 8007180419	50-277 50-277 50-277	Q R
		8007250668 8007280697 8007290825	50~133 50~275 50~514	0 0 F		8007180433* 8007180433* 8007180443	50-277 50-277 50-277	R R P
Pathfinder Hines Corp 800710443 40-2289 8007210478 50-377 8 8007210403 50-377 8 8 8007210403 50-377 8 8 8007210547 50-377 8 8 8 8 8 8 8 8 8	Pacific Legal Foundation	8007270835* 8007300280 8007310468 8007100254	50~514 50~275 50~133 PR	F Q		8007180446* 8007210214* 8007210215*	50-277 50-352 50-277	P G G
8007140170 30-397 S		8007010443 8007080213 8007080213 8007080240	40~2259 50~387 50~387 50~387	×		8007210403 8007210547 8007210547	50-277 50-277 50-277	8 9
S007140340 S0-387 S		8007140170 8007140170 8007140179* 8007140179*	50-387 50-387 50-387 50-387	9 8 8		8007220551 8007230722* 8007240003	50-277 50-277 PR	P O
B007180434 50-387 S		8007140340 8007180282 8007180364 8007180364	50-387 50-387 50-387 50-387	8 8 8		8007250152 8007250152 8007250471	50-352 50-352 50-352	8 8 A
8007240131 50-387 K 8007240131 50-387 K 8007240131 50-387 K 8007240142* 50-387 K 8007240142* 50-387 K 8007240142* 50-387 K 8007240143* 50-387 K 8007250487 50-387 S		8007180434 8007210341* 8007220441	50-387 50-387 50-387	s a		8007250631 8007250631 8007280384	50-277 50-277	q
B007240142* 50-387 K		8007240131	50-387					
B0072504B7 50-3B7 B Philibrick, 8 B B007210414 50-277 R B007250529 50-3B7 A Philiprine B007160609 8007160609 REGORD		8007240142* 8007240142* 8007240143* 8007240143*	50-387 50-387 50-387 50-387	K K K		8007280560 8007280649 8007280649 8007310286*	50-277 50-277 50-277 50-352	8 8 8
		8007250487 8007250529	50~387 50~387	B A	Philippines	8007310414 6007180609 8007160798	50-277 50-70 REQOD	R O

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	PY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	T RY
Pittsburgh, Univ of Popular Bluff Hosp Popular Bluff, HD Portland Cement Association Portland General Electric Co	8006300112> 8007100357 8007100116 8007310010+ 8007010334	ACRS FRM REGOD CONTRAC 50-344	T F		8007150707 8007150715* 8007170316 8007180111 8007180128	50-333 50-333 50-284 50-284 50-333	8 6 9
	8007010418 8007020594 8007030233 8007070273 8007070300	50-344 50-344 50-344 50-344 50-344	р О О Р		8007180597 8007210376 8007210377* 8007210418 8007210464	50-286 50-286 50-286 50-286 50-286	Q R R 8 9
	8007070307* 8007070340 8007080418 8007080420* 8007090227	50-344 50-344 50-344 50-344 50-344	ក្សស្ក		8007210526 8007220160 8007230262 8007250290 8007250317*	50-333 50-247 PR 50-333 50-286	a a a
	8007070300 8007070327 8007070331 8007070340 8007100037	50-344 50-344 NUREO 50-344 50-344	G P G		8007230667 8007280461 8007280461 8007280463* 8007280463*	50-333 50-286 50-286 50-286 50-286	Q ! ! !
	8007100051 8007100058* 8007100042* 8007100345 8007140312	50-344 50-344 50-344 PRM 50-344	G G G R		8007280471 8007280515 8007280524* 8007280610 8007280617*	50-220 50-333 50-333 50-333 50-333	8 8 0
	8007140315* 8007150120* 8007150581 8007150820 8007150826*	30-344 50-344 50-344 50-344 50-344	R G S S		8007280642 8007280667* 8007290052 8007290522 8007290580	50-333 50-333 50-286 50-247 50-286	8889
	8007160420 8007160608 8007160661 8007170424 8007170483*	PR 50-344 50-344 50-344 50-344	թ 6		8007290692 8007290728 8007290755 8007310426 8007310430*	50-333 50-286 50-286 50-286 50-286	P F S
	6007170562 8007180347 8007220570 8007230797 8007250350	50-344 50-344 50-344 50-522 50-344	6 6 0	Prairie Allience President of US & Executive Offices	8007310474 8007140337 8007020076* 8007140028 8007140108*	50-333 50-10 50-443 50-367 50-437	9 H H
	8007250360 8007250413 8007250474 8007250481* 8007280177	50-344 50-344 50-344 50-344 50-344	ն 6	Princeton Univ Principia College Project Associates Public Service Co. of Colorado	8007150013 8007090267 8007090418 8007070418* 8007010234*	50-437 50-10 REGOD CONTRAC 50-247	H D T
	8007280545 8007280553* 8007280543 8007280573* 8007280648	50-344 50-344 50-344 50-344 50-344	8 8 8		8007010344 8007010346* 8007010496 8007010506* 8007020309	50-267 50-267 50-267 50-267 50-267	R R S G
	8007270994 8007270887 8007300294 8007300333 8007300387	50-344 50-344 50-344 50-344 50-344	8 0 0 P		8007080210 8007080215* 8007080254 8007080262* 8007080268	50-267 50-267 50-267 50-267 50-267	8 8 8
otomac Research, Inc ower Authority of the State of New York	8007310433 8007310472 8007300581* 8007010164 8007010448	50-344 50-344 CONTRACT 50-333 50-286	5 0 0		8007080275* 8007080289 8007080304* 8007080404 8007080409*	50-267 50-267 50-267 50-267 50-267	8 8 R R
	8007010452 8007010455* 8007010481 8007010485* 8007010486	50-284 50-284 50-333 50-333 50-333	88888		8007080422 8007080425* 8007090333 8007100173 8007100176*	50-267 50-267 50-267 50-267 50-267	9 P B
	8007010495* 8007010511 8007010519* 8007030254 8007070212	50-333 50-333 50-333 50-284 50-333	8 9 F F		8007150690 8007220439 8007230534 8007230539* 8007230543	50-267 PR 50-267 50-267 50-267	S S S
	8007080303 8007080332 8007080350 8007080354* 8007080355	50-286 50-333 50-286 50-284 50-286	۷ 8 8		8007230548 8007230554* 8007230555* 8007280493 8007280645	50-267 50-267 50-267 50-267 50-267	8 8 9 0
	8007080362# 8007080367 8007090192 8007090195# 8007140333	50-284 50-286 50-333 50-333 50-286	8 P R R S	Public Bervice Co of Indiana, Inc	8007280652* 8007290627 8007010096 8007020031* 8007100229	50-267 50-267 50-546 50-546 50-546	0 0 8
	8007140347 8007140368 8007140374* 8007140383 8007140384*	50-286 50-333 50-333 50-333 50-333	9 8 8 9		8007140506 8007210058 8007220547 8007230073 8007230238	50-546 50-546 50-546 50-546 50-546	q A H Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
Public Service Co of New Hampshire	8007250397 8007280591 8007280667 8007010223* 8007080011*		S F G Q I	Purdue Univ RMI Co , RMI Titanium RPF Ecological Associates	8007230535 8007090380 8007280397 8007280403* 8007220538	50-376 FOIA XPORTLIC XPORTLIC 50-10	G
Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8007170596* 8007250623 8006300368 8007300569 8007030161	50-443 50-443 50-556 PR 50-272	S Q A P	Rad Services, Inc Radiation Detection Co Radiation Management Corp	8005090524# 8007020682 8005290607# 8007170328# 8007170416#	PT9 PR PT9 FOIA FOIA	
••••	8007030181 8007030229 8007030232 8007030244 8007030249	50-311 50-272 50-311	P P R P	Raiph Stone & Co Reactor Controls, Inc Reactor Experiments, Inc Renssalaer Polytechnic Inst	8007310420* 8007160504* 8007010193* 8007270857 8007090413	50-277 CONTRACT 50-237 XPORTLIC REGOD	p
	8007030247 8007070110 8007070285 8007070287* 8007070287*	50-311 50-272	Р Р Р	Reuter-Stokes, Inc	8007300598* 8007100113 8007110337 8007210316 8007210318*	CONTRACT REGOD XPORTLIC XPORTLIC XPORTLIC	
	8007070348 8007070356* 6007080068 8007080068 8007080267	50-272 50-272 50-272 50-272 50-272	R R F F G	Rhine-Schelde-Verolme Zware Apparatenbouw Rhode Island, State of	8007280223 8007310087 8007310179* 8007310182* 8007090272	XPORTLIC XPORTLIC GA999 GA999 BO-193	
	8007080280* 8007080423 8007080426* 8007100197 8007100202*	50-272 50-272 50-272 50-272 50-272	8 8 8 8	Rochester Sas & Electric Carp	8007210118 8007210130* 8007240389* 8007020018 8007070342	71-17 71-17 70-2153 50-244 50-244	Q F
	8007110444 8007110454 8007110454 8007140429 8007150509	50-272 50-272 50-272 50-272 50-272	0 P P F 0		8007080272 8007150584 8007150590* 8007160637 8007180141	50-244 50-244 50-244 50-244 50-244	P R R S
	8007150516 8007150517* 8007150596 8007150604* 8007150621	50-272 50-272 50-272 50-272 50-272	S B R R		8007210443 8007220403 8007220407* 8007230008* 8007240145	50-244 50-244 50-244 50-244 PR	9 P Q
	8007150628* 8007150631 8007150672 8007150679* 8007160628	50-272 50-272 50-272 50-272 50-311	8 Q 8 9		8007250498 8007280633 8007280639* 8007290740 8007310350	50-244 50-244 50-244 50-244 50-244	9 9 F
	8007150633* 8007170437 8007170448* 8007170570 8007170570	50-311 50-311 50-311 50-272 50-272	P	Rockwell International Corp , Atomics International Div Rockwell International Corp , Energy Bystems Div	8007310378 8007310401 8007100013 8007230507	50-244 50-244 PR 50-329	F P A
	8007170642 8007170642 8007210219 8007210268 8007210268	50-272 50-272 50-311 50-272 50-272	Q Q P Q Q	Rocky Mountain Emergy Co	8007250588* 8007020702 8007030002 8007160370 8007180057	70~25 40-9380 40-9380 40-9380 40-9697	
	8007210282* 8007210365 8007210389 8007210494 8007210507*	50-354 50-272 50-311 50-272 50-272	Q P P S S		6007210224 6007210224 6007220022 6007220035 6007240100 6007290890	40-8380 40-8380 40-8380 40-8380 40-8380 40-8697	
	8007210552 8007210408 8007210408 8007220381 8007220382*	50-272 50-272 50-272 50-272 50-272	Q Q Q B 8	Ropes & Gray Rural America S F Appliance, Ltd S M Stoller Corp (subs of Arthur D	8007080010 8007280572* 8007280677* 8007080056 8007070062*	50-443 50-409 50-409 40-215 CONTRACT	, 0 1
	8007220619 8007220627* 8007250297 8007280442 8007280442	50-272 50-272 50-354 50-272 50-272	8 8 9 P P	Little, Inc) SCS Engineers, Inc SEP Owners Group Sacramento Municipal Utility District	800707005B* 8007100420* 8007080183 8007080270	CGNTRACT 50-10 50-312 50-312	P P S
	8007280443* 8007280443* 8007280624 8007280632* 8007290684	50-272 50-272 50-311 50-311 50-311	P P 8 8		8007080277* 8007190203 8007190206* 8007150556* 8007150588	50-312 50-312 50-312 50-312	S PPOR
	8007290699 8007290710* 8007290711* 8007290718 8007290729*	50-272 50-272 50-311 50-272 50-272	R R 8 8		8007180592# 8007180541 8007230432 8007230443# 8007240123	50-312 50-312 50-312 50-312 50-312	ROPPO
Puerto Rico Electric Power Authority	8007270837 8007270844* 8007310273* 8007020604	50-272 50-272 50-354 50-376	8 8 8		8007240192 8007240198 8007250348*	50-312 50-312 50-312	Q Q

AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	JRY .	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	
	8007250370 8007250676 8007290847 8007300072 8007300081	\$0-312 \$0-312 \$0-312 PR PR	g g		8007250353 8007250353 8007250408 8007250533 8007300381	50-320 50-320 50-484 50-346 50-266	0 0 H
Bafe Energy Alliance	8007300370 8007310410 8007310418* 8007310477 8007110003	50-312 50-312 50-312 50-312 70-2909	H S G	Sheenan, D. P	8007300437 8007300463 8007070337 8007070353* 8007070365*	50-289 50-282 50-320 50-320 50-320	9999
Balisbury, MA Baluda River Electric Cooperative, Inc San Otego Gas & Electric Co San Luis Obispo Mothers tor Peace	8007110055 8007140409 8007210486* 8007090234 8007230509	70-2909 30-443 30-413 50-206 50-275	G A P C	Sheldon, Harmon & Weiss	8007070371* 8007080007 8007080004 8007080005* 8007080043	50-320 50-320 50-289 50-289 50-289	9 9 9
Sandia Laboratories	8007300096 8007310466 8007020011 8007110148 8007110551	50-275 50-275 REB REB REB	Q D		8007100033 8007100037* 8007100042* 8007110048 8007140018	50-155 50-155 50-155 PR 50-287	9
	8007180049 8007280091 8007290152 8007290233 8007290251	NUREO RES NUREO RES NUREO			8007140022* 8007140387 8007150552 8007210487 8007210495*	50-287 PR 70-143 50-287 50-287	0
Sargent & Lundy, Inc	8007310007 8007310231 8007310241 8007020416 8007150486	MUREG NUREG NUREG PR NUREG			8007220529 8007220530* 8007230229 8007240044* 8007240050*	50-269 50-269 FOIA COMMIES COMMIES	
	8007150537* 8007160566* 8007160569* 8007160574* 8007230160*	50-373 50-454 50-454 50-454 GA999	X X X	Shoreham Opponents Comittion	8007250043 8007290781 6007300039 8007300043 8007290781	FOIA ORG PR PR ORG	
Sassafras Audubon Society Geanpower, Inc Ecience Applications, Inc	8007010055+ 8007010244+ 8007010582+ 8007140433+	50-544 FOIA CONTRAC CONTRAC		Bierra Club Bigma Chemical Co (subs of Bigma-Aldri ch Gorp)	8007270809* 8007030003 8007070029	ORC PR XPORTLIC	
	8007140650 8007250552*	FOIA 50-460	A		8007210129 8007280393	XPORTLIC	C
Galf-Powered Lighting, Ltd Senate	8007280213* 8007240462 8007020323*	FDIA FOIA 50-320	Ų	Stagitonians Concerned About Nuclear Power	8007310484 8007030303	XPORTL 10 50-522	Ā
	B007110073+	50-271 50-335	H H	Blemmons, D.B Smail Dusiness Administration Smithsonian Institute	8007100112* 8007210331* 8007140475	CONTRACT CONTRACT RECOD	
	6007110318 6007110323* 6007110507 8007110571*	50-546 MISC PR 50-482	U U H	Smell & Wilmer Social Research Applications Corp South Carolina Electric & Gas Co	8007180405 8007160496# 8007070269 8007070270#	50-275 CONTRACT 50-395 50-395	C
Sanate, Appropriations	8007140231* 800724046B* 8007250067* 800731052B* 800702018B*	50-10 50-335 50-320 50-282 COMMISSI	H H H		8007080393 8007090011 8007110489 8007160252 8007170607	50-395 50-395 50-395 50-395 50-395	A B A
Sanate, Judiciary Committee Sanate, Small Business Sanaible Maina Power	8007110005 8007080082 8007020507 8007020610 * 8007110345	PR COMMISSI 50-309 50-309 PR	10N Q G		8007170612* 8007180256 8007220219 8007220390	50-395 50-395 50-395 50-395	A 0 0 P
Ehannon & Wilson, Inc	8007300122 8007300127* 8007250393* 8007250396* 8007250398*	50-309 50-309 50-397 50-397 50-397	0 0 A A A		8007220372# 8007220428 8007250308 8007250459 8007250471	50-375 50-375 50-375 50-375 50-375	F A A B A
Shaw. Pittman. Potts & Troubridge	8007020482 8007020521 8007020533 8007020587 8007070310	50-320 50-320 50-287 PR 50-484	000	South Carolina, State of	8007290626 8007290627* 8007310428 8007110087 8007300074*	50-375 50-375 70-2860 PR COMMISSI	tun E
	B007070315* B007100191*	50-484 PR	Ģ.	South Dakota, State of	8007150458 8007010214	50-484 50-204	Q R
	8007140224 8007150527 8007180884	50-289 50-212 50-212	0		8007010216 8007010358 8007010358 8007010465 8007010479	50-206 50-361 50-361 50-206 50-361	A A P
		50-289 50-289 50-289	0		8007010479 8007010533 8007010537# 8007020149#	50-361 50-206 50-206 50-361	A 8 8
			000		8007020149* 8007020342	50-341 50-204	G P
			P		8007020346* 8007020372*	50-206 50-206	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8007080081 8007080081 8007080271 8007080403 8007080410*	50-341 50-341 50-204 50-206 50-206	A A F S S		8007170235 8007170251* 8007170255 8007210073 8007210076*	XPORTLIC SECY XPORTLIC XPORTLIC SECY
	8007090330 8007090330 8007090337* 8007090337* 8007100262	50-361 50-361 50-361 50-361 50-206	8 8 8 5 R		8007210075 8007240440 8007280547 8007280559 8007290212	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8007100262 8007100386 8007110401 8007140034* 8007140034*	50-206 REGOD 50-206 50-361 50-361	R P G	Stearns-Roger, Inc	8007030039* 8007030047* 8007030055* 8007010172* 8007020327	40-8647 40-8647 40-8647 50-333 PR
	8007140051* 8007150579 8007150587* 8007150599 8007150605*	PR 50-206 50-206 50-206 50-206	P R ጸ		8007100277* 8007100280* 8007100284* 8007100284* 8007100284*	50-260 50-260 50-260 50-260 50-260
	8007170565# 8007210463 8007210493 8007230011 8007230287#	50-206 50-361 50-361 50-361 50-206	Q A S Q Q		*8850010008 *6750017008 *E750017009 *E750017008	50-280 50-280 50-280 50-280 50-280
	8007230579 8007240088 8007240088 8007250355 8007250358	50-361 50-361 50-361 50-206 50-206	5 G G		8007100278* 8750071008 8750071008 8750071008 8750071003	50-280 50-280 50-280 50-280 50-280
	8007250361 8007250636 8007280072 8007280376 8007280382#	50-361 50-206 50-206 50-206 50-206	9 9 8 8		8007110193* 8007110194* 8007110194* 8007240144* 8007300044	50-280 50-280 50-280 50-337 PR
	8007280391 8007280396* 8007290489 8007290620 8007290706	50-206 50-206 50-361 50-361 50-206	S S Q A	Strone & Webster, Inc Stronck, Stronck & Lavan Student Nurses Association of Pennsylvan ia	6007140585 6007140601 6007240161# 8007240437 8007110443#	50-339 50-339 50-339 FOIA NUREO
	8007290883 8007300303 8007310162 8007310201 8007310201	50-206 50-361 50-206 50-361 50-361	Q Q Q Q	Switzerland Synergy, Inc Systems Control, Inc TECH-SIL, Inc	8007140802 8007070052 8007300178* 8007300188* 8007170214	XPORTLIC CONTRACT GA999 GA999 50-379
Southwest Research Institute Southwest Research and Information Center Spiegel & McDiermid	8007030071* 8007070174 8007030127 8007110019 8007090051	CONTRACT PR PR PR 50-389	м	Taiwan (Republic of China) Taunton Kunicipal Lighting Plant Tech/Ops (Technical Operations, Inc.)	8007240472 8007080033* 8007030375 8007030376* 8007030378*	XPORTLIC 50-449 71-9039 71-9039 71-9039
St Elizabeth Hosp Appleton, HI Standard Dil Co of Indiana (see also AMOCO)	8007150449 8007150449 8007150458 8007100416 8007090131	50-445 50-445 50-484 REGOD 40-5021	н н о		8007030379* 8007030381* 8007030384* 8007030385* 8007030386*	71-9039 71-9039 71-9039 71-9039 71-9039
Standardized Nuclear Unit Power Plant	8005090053	50-482	s		6007030387*	71~9039
Sq s tem	8007010142 8007020378 8007070325 8007070325	50-482 50-482 50-482 50-482	G G S S	Technassqciates, Inc	8007100373 8007100376# 8007140203# 8007210331#	71-9053 71-9053 CONTRACT CONTRACT
	8007070325 8007070325 8007100441 8007290254* 8007290590	50-482 50-482 50-482 50-482 50-482	8 8 8 8	Teknetron, Inc Teledyne Energy Systems Teledyne Engineering Services	8007070057* 8007010240 8007010245 8007150526 8007110453	CONTRACT 71-4888 71-9030 TOPREP NUREO
	8007300511 8007310302* 8007310302* 8007310302* 8007310302*	50-482 50-482 50-482 50-482 50-482	A 6 8 8 8 8	Temple Univ Tennessee Valley Authority	8007310384 8007310387* 8007108007 8006250275 8007010327	50-329 50-329 PR 50-518 50-327
Stanford Univ State,Dept of State,Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs	8007010627# 8007170191 8007010009	CONTRACT XPORTLIC XPORTLIC			8007010338 8007010350* 8007010370 8007010377* 8007010382	50-519 50-519 50-296 50-296 50-327
	8007010012 8007010017	XPORTLIC XPORTLIC			8007010385*	50-327
	8007020240 8007100144 8007140540* 8007170003 8007170072	XPORTLIC XPORTLIC SECY XPORTLIC XPORTLIC	;		8007010386 8007010386 8007010417 8007010417#	50-328 50-328 50-327 50-327
	8007170204 8007170223	XPORTLIC XPORTLIC	:		8007010424 8007010425 8007010438* 8007010490	50-438 50-327 50-327 50-327

Section Sect	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NVMBER	SUBJEC CATEOD	IRΥ
\$\frac{0}{0} Content of the		8007010502* 8007010512 8007010515*	50-327 50-327 50-327	8 5 9		8007110039* 8007110291 8007110320 8007110320	50-327 50-260 50-518 50-516	8 8
December Column		8007010528 8007010532* 8007010534	50-327 50-327 50-327	s s s		8007110320 8007110320 8007110328*	50-518 50-518 50-518	8
BOOT		8007020347 8007020499 8007020499	50-327 50-259 50-259	G G G		8007110328* 8007110328* 8007110328*	50-518 50-518 50-518	S S
BOOT 100		8007020543 8007020544 8007020545*	50-328 50-328 50-328	9 9 8		8007110378 8007110380* 8007110388	50-296 50-296 50-296	8
SECTOTOPICA Color		8007020619 8007020627 8007020740	50-370 50-327 50-327	9 0		8007140240 8007140347 8007140353*	PRM 30-518 50-518	B 8
80070000181 30-237 8 8007100182 60-237 9 8007100182 80-237 9 8007100182 80-237 9 8007100182 80-237 9 8007100182 80-237 9 8007100182 80-237 9 8007100184 80-237 9 8007100185 80-237 9 80071		8007070045* 8007070248 8007080220	40-1341 50-259 50-327	Q		8007140427* 8007140427* 8007140443	50-390 50-390 50-328	8
BOO70002088 SO-327 B		8007080281 8007080283 8007080286	50-327 50-327 50-259	s s p		8007150466* 8007150470 8007150472	50-327 50-327 50-327	8 8 P
COOT-08-0311		8007080288* 8007080291* 8007080293	50-327 50-327 50-259	8 8		8007150491 8007150501# 8007150504	50-327 50-327 50-327	8
B007680341 S0-327 B B007180370 S0-239 B B007180370 S0-239 B B007180371 S0-327 P B007080370 S0-329 B B007180371 S0-327 P B007180371 S0-327 P B007180371 S0-327 P B007180374 S0-327 B B007180374 S0-		8007080308# 8007080313 8007080331	50-259 50-259 50-327	8 8 0		8007150521 8007150522# 8007150546	50-327 50-327 50-438	P A
B007080388 30-390 V 3007180380 30-327 P 3007080388 30-390 V 3007180380 30-327 P 3007080398 30-320 B007180398 30-327 P 3007080398 30-327 P 3007080398 30-327 P 3007080400 S0-327 P 3007080400 S0-327 P 3007080400 S0-327 P 3007080400 S0-327 P 3007080403 S0-326 B007180400 S0-327 P 3007080401 S0-328 B007180403 S0-326 B007180403 S0-326 B007180403 S0-326 B007180403 S0-326 B007180403 S0-326 B007180403 S0-326 B007180403 S0-327 P 3007090811 S0-204 B007180424 S0-327 P 30070908041 S0-329 B007180424 S0-329 B007180		8007080341# 8007080370 8007080373#	50-327 50-260 50-260	8 8 5		8007150570 8007150571 8007150571	50-259 50-327 50-327	8 P P
8007100304 8007100205 80007100205 80007100205 80007100205 80007100205 8000710		8007080388 8007080388 8007080394	50-390 50-390 50-260	V S		8007150580 8007150582* 8007150585*	50-327 50-327 50-327	8 8
SOO7090004		8007080402# 8007080405 8007080411#	50-327 50-260 50-260	ន ទ ទ		8007150459 8007150663* 8007150692	50-566 50-566	8
BO07100259		8007090003 8007090006* 8007090222	50-259 50-259 50-390	8 8		8007160424 8007160471 8007160471	50-438 50-327 50-327	8 P P
SOCT100034* PR		6007090249 6007090258* 8007090258*	50-327 50-327 50-327	8 8		8007160478* 8007160484* 8007160519	50-327 50-327 50-327	P B
B007100209 50-438 B007160578* 50-328 B00716043 50-327 F F F F F F F F F		8007100054* 8007100169 8007100205	PR 50-438 50-438	Ğ.		8007160556# 8007160571 8007160571	50-259 50-328 50-328	8 8
80071606236# 50-438 8 8007160656 # 50-438 8 8007160656 # 50-438 8		8007100209 8007100213* 8007100213*	50-438 50-438 50-438	6 5 5		8007160578* 8007160578* 8007160643	50-328 50-329 50-327	8 8 F
8007100328 PR 8007160666 50-329 8		8007100236# 8007100236# 8007100252	50-436 50-438 50-553	6 8		8007160650 8007160656* 8007160656*	50-438 50-438 50-438	8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC' CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY
	8007170272 8007170342 8007170342 8007170344* 8007170344*	50-370 50-544 50-564 50-566 50-566	0 9 8 8 8		6007230480 8007230481 * 8007230481 * 8007230486 8007230487	50-327 50-327 50-327 50-328 50-390	P P P S
	8007170356 8007170356 8007170358* 8007170358* 8007170513	50-546 50-546 50-566 50-546 50-390	6 5 5 6 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		8007230487 8007230490 8007230491* 8007230494 8007230499	50-390 50-259 50-259 50-328 50-327	\$ \$ \$ \$ F
	8007170513 8007170525* 8007170525* 8007170560 8007170591	50-390 50-390 50-390 50-260 50-390	S 5 5 9 P 5		8007230505 8007230505 8007230511 8007230523 8007230528	50-390 50-390 50-327 50-259 50-318	5 < 5 5
	8007170591 8007170664 8007170664 8007170664 8007180301	50-390 50-328 50-328 50-328 50-296	6 6 8 9 5 5		8007230531 * 8007230533 8007230533 8007230575 8007230575	50-259 50-327 50-327 50-327 50-327	8 P P F
	8007180314* 8007180523 8007210036 8007210036 8007210036	50-294 50-259 50-327 50-327 50-327	8 0 0 0 0		8007230582 8007230587 8007230587 8007230591 * 8007230591 *	50-370 50-370 50-370 50-370 50-370	08886
	8007210036 8007210091 8007210091 8007210091 8007210103	50-327 50-259 50-259 50-259 50-259	Q Q Q Q		8007230724 8007230726 8007230726 8007240279* 8007240455	50-259 50-259 50-259 50-518 50-259	99998
	8007210103 8007210461 8007210475* 8007210596 8007220236	50-259 50-327 50-327 50-327 50-518	Q 8 8 Q Q		8007250414 8007250416* 8007250418 8007250436 8007250497*	50-327 50-327 50-327 50-327 50-327	8888
	8007220342 8007220342 8007220342 8007220346* 8007220346*	50-259 50-259 50-259 50-259 50-259	R R R R		8007250585 8007250576 8007250576 8007250576 8007280001	40-1341 50-259 50-259 50-259 50-327	0 0 0 P
	8007220346* 8007220358 8007220360* 8007220376 8007220376	50-259 50-327 50-327 50-259 50-259	R R P P		8007280001 8007280448* 8007280446* 8007280446* 8007280478	50-327 50-259 50-259 50-259 50-327	P G G G
	8007220376 8007220377* 8007220377* 8007220377* 8007220443	50-259 50-259 50-259 50-259 50-259	P P P R		8007280498 8007280548 8007280548 8007280613 8007280615	50-327 50-327 50-327 50-259 50-259	Q F Q Q
	8007220443 8007220443 8007220450 8007220460 8007220462*	50-259 50-259 50-553 50-327 50-259	R R 9 A R	•	8007280613 8007280613 8007280623 8007280623 8007280640	50-259 50-259 50-327 50-327 50-439	0 p p
	8007220462* 8007220462* 8007220469 8007220474* 8007220481	50-259 50-259 50-327 50-327 50-259	R R S S R		6007290479 6007290578 6007290610 6007290632 6007290633	50-327 50-327 50-328 50-329 50-327	0 8 8 8 8
	8007220481 8007220481 8007220491* 8007220491* 8007220491*	50-259 50-259 50-259 50-259 50-259	R R R R R		8007270636 8007270637* 8007270646 8007270647 8007270651	50-327 50-327 50-327 50-327 50-327	8 8 8 8 P
	8007220522 8007220522 8007220532 8007220532 8007220568	50-259 50-259 50-259 50-327 50-327	Q Q P B		8007270656* 8007270657 8007270657* 8007270662 8007270664*	50-327 50-259 50-327 50-327 50-259	8888
	8007220574* 8007230255 8007230255 8007230408 8007230408	50-327 50-546 50-566 50-327 50-327	5 5 P P		8007290665 8007290672* 8007290673* 8007290675 8007290679	50-327 50-327 50-327 50-327 50-327	888
	8007230431 8007230445 8007230452* 8007230467 8007230467	50-328 50-259 50-259 50-327 50-327	5 8 8 P P		8007290679 8007290681* 8007290685 8007290693* 8007290695	50-327 50-327 50-327 50-327 50-294	P 8 8 6 8
	8007230470 8007230474* 8007230477 8007230477 8007230480	50-259 50-259 80-327 50-327 50-327	\$ 8 8 P P P		8007270702* 8007270708 8007270715* 8007270720 8007270724	50-294 50-327 50-327 50-260 50-327	90000
							-

AVTHOR AFF (LIATION	ACCESSION NUMBER	DELENS		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
	8007290724 8007290725 8007290725 8007290726* 8007290734	50-327 50-438 50-438 50-260 50-518	P 8 8 8 8	Teras, Univ of The Nuclear Regulatory Commission Three Mile Island Alert	8007210320 8007290296* 8007140003 8007140008 8007140009*	70-157 50-327 50-289 50-289 50-289	0000
	8007290737 8007290744* 8007290749 8007290749 8007290757	50-259 50-259 50-438 50-438 50-327	9 9 9 9 P		8007220001 8007220002 8007250480 8007250689 8007290779	50~289 50~289 50~289 50~289 50~289	00000
	8007290757 8007290762 8007290770* 8007290790 8007290800*	50-327 50-327 50-327 50-327 50-327	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Time & Frequency Technology. Inc Todd Shipyards Toledo Edison Co	8007220224* 8007240228 8007010254 8007010434 8007010437*	MISC 70-1062 50-346 50-346 50-346	Q S 6
	8007270810 8007270813 8007270818* 8007270820 8007270822	50-327 50-390 50-327 50-296 50-327	8085		8007010464 8007020040 8007030260 8007030264* 8007090254	50-346 50-346 50-346 50-346 50-346	6 8 8
	8007290827* 8007290829* 8007290864 8007290927 8007300003	50-327 50-296 50-259 PR PRM	s s		8007110391 8007110397* 8007110407 8007110416* 8007110418	50-346 50-346 50-346 50-346 50-346	8 8 8
	8007300167 8007300374 8007300376* 8007300376* 8007300434	50-438 50-327 50-327 50-327 50-327	8 K K K F		8007110423* 8007110427 8007110434* 8007110440 8007110448*	50-346 50-346 50-346 50-346 50-346	8 8 8
	8007300434 8007300572 8007300572 8007310056 8007310067	50-327 50-259 50-259 50-327 50-259	6 0 0		8007140237 8007140318 8007140322* 8007150560 8007150566*	50-346 50-346 50-346 50-346 50-346	Q R R S
	8007310067 8007310067 8007310208 8007310208 8007310208	50-259 50-259 50-259 50-259 50-259	0 0 0		8007150607 8007150670 8007150824 8007170064 8007170441	50-346 50-346 50-346 50-346 50-346	8 0 0
	8007310323 8007310325* 8007310355 8007310396 8007310396	50-327 50-327 50-259 50-327 50-327	ր 0 1		8007170450* 8007170532 8007180271 8007180310 8007210216	50-346 50-346 50-346 50-346 50-346	8 0 0
	8007310411 8007310411 8007310412 8007310416 8007310416	50-327 50-327 50-327 50-327 50-327	P P P		8007210454 8007220375 8007220378* 8007220458 8007220465*	50-346 50-346 50-346 50-346 50-346	8 8 8 8
Teton Exploration Drilling Co . Inc	8007010129 8007010140* 8007010432 8007280594 8007280702	40~8728 40~8728 40~8728 40~8728 40~8728			8007230076 8007230141 8007230200 8007230200 8007230581	50-346 50-346 50-346 50-346 50-346	0 0 0
Teras A & M Univ	8007210502 8007210512# 8007240038 8007290468 8007290475#	50-59 50-59 50-59 50-128 50-128	R R R R		8007240028* 8007240126 8007250382 8007250427 8007250434	50-346 50-346 50-346 50-346 50-346	4 4 8 6
Texas Instruments, Inc	800707004B 8007210175# 8007220527 8007250445 8007280147#	70-33 70-33 70-33 70-33 50-367	R		8007250438* 8007250572 8007280485 8007280571 8007280578*	50-346 50-346 50-346 50-346 50-346	P Q P S G
Texas Public Interest Research Group Texas Utilities Generating Co	8007030075 8007170374 8007300114 8007030246 8007080062	PR 50-466 50-466 50-445 50-446	0 0 0 8		8007280583 8007280589* 8007280594 8007280602* 8007280609	50-346 50-346 50-346 50-346 50-346	8 8 8
	8007080282 8007110592 8007140455 8007140502* 8007160625	50-445 50-445 50-445 50-445 50-445	F Q Q M		8007280422* 8007280430 8007280643* 8007270500 8007300141	50-346 50-346 50-346 50-346 PR	8 8 0
	8007170196 8007180366 8007180437 8007210352 8007210478	50-445 50-445 50-445 50-445 50-445	Q A Q B A	Transnuclear, inc	8007310348 8007310380 8007310536# 8007030011# 8007030016#	50-344 50-346 50-346 70-2478 70-2478	Q P Q
Teras, State of	8007310328 8007020577 8007110054 6007170216* 8007300573	50-445 50-498 PR CONTRACT PR	e H		8007030020* 8007070018 8007070043 8007070140 8007070145	70-2478 XPORTLIC PR XPORTLIC XPORTLIC	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8007110469 8007110480 8007150353 8007290025 8007290027	XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8007230488 8007230489* 8007230695 8007250173 8007250188	50-271 50-271 50-271 50-271 50-271	8 0 0
	8007290390 8007290446 8007290452# 8007310485* 8007310496*	XPORTLIC XPORTLIC XPORTLIC 70-2478 70-2478	:	Vermont, State of Vet Admin Hosp Northport,NY	8007250488 8007280461 8007310385 8007110101 8007070112	50-271 50-271 50-271 PR PR	P P
Transportation,Dept of Tubeco, Inc Tuisa Gamma Ray, Inc	8007020447 8007140521* 8007290348* 8007290392* 8007210200	PR CONTRACT GA999 GA999 71-139		Virginia Electric & Power Co	8007010340 8007010353 8007010363 8007010375* 8007010374*	50-286 50-337 50-404 50-337 50-286	8 6 6
Twomey, Latham & Schmitt Underwriters Laboratory Union 76 Minerals Exploration Co	8007210205* 8007290781 8007010373* 8007010305 8007210560	71-139 ORQ 50-313 40-8584 40-8584	F		8007010378 8007010413 8007010415* 8007010422 8007010422	50-339 50-339 50-339 50-280 50-280	8085
Union Carbide Corp	8007210566* 8007080217 8007140371 8007170571 8007210293*	40-8584 40-299 40-299 40-299 70-487			8007010422 8007010429 8007010430 8007010430 8007010430	50-280 50-280 50-280 50-280 50-280	6 8 6
	8007220025 8007220056* 8007220064* 8007220074* 8007220081*	WASTE MO WASTE MO WASTE MO WASTE MO) र १ र १ र		8007010430 8007010442* 8007020001 8007020456 8007020585	50-280 50-280 71-5957 50-338 PR	Р В Р
	8007220087* 8007280473 8007290145 8007310497 8007310500*	WASTE MO XPORTLIC NUREC WASTE MO WASTE MO	: ĕT		8007020592 8007020598* 8007030078 8007030131 8007030131	50-336 50-338 PRM 50-280 50-280	44
Union Electric Co	8007100379 8007150006* 8007150010* 8007150534 8007210198	50-483 50-483 50-483 50-483 50-483	A Q Q F Q		8007030135* 8007030135* 8007030151 8007030156 8007030184	50-260 50-260 50-339 50-339 50-260	5656
Union Minerals Union of Concerned Scientists	8007250334 8007020028 8007270617 8007010284 8007080050*	50-483 40-8584 40-8584 0R0 50-289	6		8007030184 8007030262 8007030263 8007030267* 8007030267*	50-280 50-339 50-338 50-339 50-338	
	8007140022* 8007210475* 8007270012* 8007270781 8007270803*	50-289 50-289 SECY DRO DRO	0		8007030270 8007030271# 8007030273 8007030275# 8007030281	50-338 50-338 50-339 50-339 50-339	8 8 8 8
United Illuminating United Nuclear Corp	8007080012* 8007140380* 8007180279 8007180288 8007180480	50-443 40-277 40-8681 40-8602 40-8678	1		6007030263* 6007030265 6007030286* 6007070200 6007070201	50-339 50-339 50-339 50-339 50-339	3888
United Nuclear Corp ,Naval Products Div Utah, State of	8007220063 8007220070* 8007280174 8007180066* 8007210090	40-8728 40-8728 WASTE MO 70-371 40-8681	τ		8007070224 8007070229* 8007070283 8007070283 8007070358	50-280 50-280 50-338 50-338 50-339	8 0 0 8
Utility Workers Union of America Valcor Engineering Corp Valore, C Vanderbilt Univ.	8007100348 8007160366 8007250297 8007110112 8007090048	PR 50-369 PT21 50-272 PR	s o		8007070363* 8007070373 8007070374 8007070379* 8007070381*	50-339 50-338 50-339 50-339 50-338	88888
Vermont Electric Cooperative, Inc Vermont Yankee Nuclear Power Corp	8007080028* 8007010317 8007010391 8007010397 8007010405*	50-443 50-271 50-271 50-271 50-271	I S S 1 B		8007070389 8007070397* 8007080069 8007080072* 8007080419	50-280 50-280 50-338 50-338 50-280	866
	8007070247 8007070260 8007070345 8007080292 8007080295*	50-271 50-271 50-271 50-271 50-271	F 8 P Q Q		8007090057 8007090057 8007090057 8007090057 8007090296	50-260 50-260 50-260 50-260 50-339	00008
ı	8007110460 8007170325 8007180398 8007180400* 8007180549	50-271 50-271 50-271 50-271 50-271	0 0 R R Q		8007090304* 8007090308 8007090312* 8007090317 8007090323*	50-339 50-339 50-339 50-339 50-339	8 8 8 8
	8007180594 8007210448 8007210456 8007210467* 8007210579	50-271 50-271 50-271 50-271 50-271	G H R R G		8007070335 8007070342* 8007070345 8007070353* 8007070423	50-339 50-339 50-338 50-338 50-280	8 : G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUSJECT CATEODRY	•
	8007090423 8007090423 8007100159 8007100273 8007100273	50-280 50-280 50-337 50-280 50-280	G G P P		8007220431 8007220431 8007220436* 8007220436* 8007220487	50-338 50-338 50-338	RRRRP
	8007100273 8007100273 8007110189 8007110189 8007110202	50-280 50-280 50-280 50-280 50-339	P 0 0 ₽		8007220507 8007220512* 8007220575 8007220579 8007220579	50-338 50-338 50-338	98844
	8007110300 8007110300 8007110336 8007110336 8007110357	50-338 50-338 50-280 50-280 50-339	9 9 0 0		8007220580* 8007220582* 8007220582* 8007220401 8007220411*	50-338 50-338 50-339	86488
	6007110361 6007110364 6007110365* 6007110390 6007110420	50-339 50-339 50-339 50-281 50-339	P P Q S		8007230447 8007230447 8007230493 8007230497* 8007240005	50-338 50-338 50-338	90000
	6007140158 8007140187 8007140209 8007140225* 8007140249	50-339 50-339 50-339 50-339 50-280	P 9 8 8		8007240049 8007240092 8007240092 8007240115 8007240116*	50-338 50-338 50-339	AFFPF
	8007140259* 8007140393 8007140393 8007140400* 8007140400*	50-280 50-338 50-338 50-338 50-338	8 P P P		8007240149 8007250345 8007250379 8007250383 8007250383	50-281 50-339 50-338	TAPER
	8007140406 8007140411* 8007150462 8007150462 8007150569	50-339 50-339 50-280 50-280 50-338	P G G P		8007250385* 8007250385* 8007250388 8007250415 8007250415	50-338 50-338 50-339 50-338 50-338	4444
	8007150569 8007150671 8007150686 8007150701* 8007150767	50-338 50-337 50-338 50-338 50-338	P 0 8 8		8007250430 8007250545 8007250545 8007250545 8007250545	50-337 50-280 50-280 50-280 50-280	P 0000
	8007150777* 8007150808 8007150810 8007150815* 8007150817*	50-338 50-339 50-339 50-339 50-339	5 5 5 5		8007280367 8007280375 8007280400* 8007280406 8007280423	50-339 50-339 50-339 50-339 50-339	ተመመመ
	E007140507 8007140543 8007160543 8007140664 8007140671	50-339 50-280 50-280 50-281 50-339	P 0 0 0 P		8007280432 8007280432 8007280440 8007280444 8007280607	50-338 50-339 50-339 50-280	**
	8007170175 8007170183* 8007170187* 8007170334 8007170334	50-337 50-337 50-337 50-280 50-280	Р Р С		8007280618* 8007280625 8007280651 8007280651 8007290220	50-280 50-280 50-338 50-338 50-280	8 P P G
	8007170334 8007170334 8007170348 8007170348 8007170350*	50-280 50-280 50-280 50-280 50-280	9 9 V V		8007270220 8007270700 8007270700 8007270838 8007270840	50-280 50-338 50-338 50-338 50-280	08440
	8007170389 8007170389 8007170391# 8007170391# 8007170412	50-280 50-280 50-280 50-280 50-280	R R R F	•	8007270840 8007270840 8007270840 8007270843* 8007300183	50-280 50-280 50-280 50-338 50-339	40000
	8007170412 8007170527 8007170529 8007170546* 8007170601	50-280 50-280 50-280 50-240 50-338	F Q Q P F		8007300450 8007300458 8007310277 8007310346 8007310384	50-339 50-339 PR 50-339 50-339	***
	8007170401 8007180317 8007180327* 80071803/1	50-338 50-281 50-281 50-281 50-280	F 8 9	Virginia Tech	8007310370 8007310421 8007310421 8007230498 8007230503*	50-281 50-280 50-280 50-124 50-124	ተቀቀቀው
		10 10 10 19	8 8 8	Virginia, Univ of Vollen, R. J.	8007210429 8007210429 8007210433* 8007210433* 8007080055	50-62 50-62 50-62 50-62 50-367	ፍጻጓጓ
		19 10 10	9	WAPORA: Inc Wagner, Cumningham, Yaughan, Genders & McLaughlin	8007030357* 8007110144	CONTRACT 50-302	r į
		11 19	P	Washington Public Power Supply System	8007010002 8007010083*	50-397 50-397	4

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOS	RY
	9007150680 8007160487 8007170577 8007170577 8007170585*	50-397 NUREQ 50-460 50-460 50-460	A S S	•	8007180455* 8007180504* 8007180565 8007210077* 8007210287	XPORTLE TOPREP 70-1151 70-1151 70-1143	
	8007170585* 8007180329 8007210392 8007230003 8007230007	50-440 50-508 50-397 50-397 50-508	6 9 0 0		8007220496* 8007220560 8007230015* 8007240096 8007250685	TOPREP XPORTLIC 70-184 71-5450 XPORTLIC	
	8007230423* 8007250354 8007250391 8007250544 8007290405	50-397 50-397 50-397 50-460 50-508	Q Q A A Q		8007280372 8007280479 8007280495# 8007290687* 8007210069	XPORTL 10 50-594 50-594 50-454 XPORTL 10	A A K
	8007290444 8007290518 8007290704 8007300299	50-460 50-460 50-397 50-460	0 0 8	Westinghouse Electric Corp . Nuclear Energy Systems	8007310073* 8007020590 8007020596*	XPORTL10 TOPREP	;
	8007300299 8007300306 8007300344 8007300544	50~460 50~508 50~508 50~397	0 F 0		8007140373* 8007220488* 8007220499*	TOPREP TOPREP	
	8007310171 8007310409	50-3 9 7 50-3 9 7	Q A	Westinghouse Electric Corp , PWR Systems Div	8007220503* B006300017 B006300292	TOPREP 70-1151 70-1151	
Washington State Univ	8007310478 8007310502 8007110225	50-397 50-3 9 7 PR	Q Q	Westinghouse Operating Plants Owners	8007210410 8007220482	TOPREP	
Washington Univ Washington, State of	8007110231* 8007110237* 8007160540 8007180368	PR PR 50-10 50-10	D D	Widoff, Reager, Selkowitz 3 Adler	8007140034* 8007210029 8007140003 8007140008	50-361 ACRS 50-289 50-289	G G
	8007150159 8007210113* 8007290045*	REGOD CONTRACT State Pr	. og		8007140009* 8007220001 8007220002 8007220585	50-289 50-289 50-289 50-289	0000
Hashington, Univ. of Hestern Canada Hydraulic Laboratories, Ltd Wastern Nuclear, Inc. (subs. of Phelps	8007020025* 8007070130*	50-329			8007250680 8007250689	50-289 50-289	0
Dodge Corp)	8007070099 8007100091*	40-1162		Williams College, Massachusetts Williams∼Robinette & Associates, Inc	8007290779 8007100137 8007240021	50-289 REQCD 40-1162	9
Western Nuclear, Inc Westinghouse Electric Corp	8007140549 8007220314 8004240081 8007010005 8007010079	PR 40-1162 40-1162 PR FOIA			8007010030 8007010030 8007010036 8007010043 8007010042	50-266 50-305 50-266 50-266	0 0000
	8007010102 8007020221 8007020641 8007020644* 8007020658	XPORTLIC 70-1143 TOPREP TOPREP XPORTLIC			8007010062 8007010409 8007010420* 8007020340 8007080381 8007080384*	50-266 50-266 PR 50-301 50-301	0 88 88
	800703Q012 8007070023 800707Q024* 800707Q041 800707Q125	PR XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8007090230 8007110317 8007110326# 8007110333 8007110340#	50-301 50-305 50-305 50-366 50-266	20000
	8007080371 8007100191* 8007100253 8007100254* 8007100263	50-339 PR TOPREP TOPREP XPORTLIC			B007110342 B007110347* B007110353 B007110357* B007140559	50-301 50-301 50-301 50-301 PR	888
	8007100271* 8007100358 8007100370* 8007110021 8007110492	XPORTLIC PRM 70-1151 XPORTLIC PR			6007150510 8007150618* 8007150618* 8007150648 8007150648	50-266 50-266 50-266 50-266 50-266	R R P
	8007110522 8007140347 8007140379* 8007140407 8007140416*	PRM TOPREP TOPREP TOPREP			8007150453 8007150462 8007150482 8007140757 8007140757	50-266 50-266 50-266 50-266 50-266	P P C C
	8007140420* 8007140540* 8007150646 8007150652* 8007150656*	TOPREP ACRS TOPREP TOPREP			6007170524 6007170524 6007170524 6007210408 6007210408 6007210438*	50~266 50~266 50~266 50~266 50~266	00000
	8007160188* 8007160743 8007160755* 8007160765* 8007170230	GAPPP TOPREP TOPREP TOPREP 50-295	8		8007210438* 8007210452* 8007210460* 8007210465* 8007210465*	50~246 50~266 50~266 50~266 50~266	មាមមាម
	8007170258* 8007180357 8007180449	SECY 50-244 XPORTL10	P		8007220071 6007230802	50-266 50-502	6

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	NDI BBBDDA RBENUN	SUBJEC	
	8007240342 8007240342 8007240365 8007300381 8007300430	50-266 50-266 PR 50-266 50-301	9 9 0		8007210542 8007210548* 8007210553* 8007220303 8007220310*	40-850; 40-850; 40-850; 40-8304 40-8304	2
Misconsin Public Bervice Corp	8007300440 8007300440 8007300456 8007020032 8007020256	50-266 50-266 50-266 50-305 50-305	F G G	Wyoming Outdoor Council Wyoming, State of	8007220315+ 8007280200 8007170106 8007220520 8007010567	40-8304 40-8503 40-8745 40-1162 40-8304	2 5 2
	8007020716 8007080206 8007080386 8007080390* 8007160464	50-305 50-305 50-305 50-305 50-305	9 6 8 8		8007020064 8007020083 8007020458 8007020694 8007030219	40-8697 40-8697 40-8721 40-8502 40-8380	
	8007160474* 8007160465 8007160502* 8007160510* 8007160544	50-305 50-305 50-305 50-305 50-305	5 5 5 8		8007030226 8007030352 8007070115 8007070120 8007210063	40-8745 40-8102 40-8380 40-8502 40-8697	<u>:</u>
	8007140548* 8007220229 8007240321 8007240334 8007240415	50-305 50-305 50-305 50-305 50-305	R P G G	Yale Uni∨ Yankee Atomic Electric Co	8007210066 8007280054 8007280305 8007020464 8007010057	40-8502 40-8502 40-8502 PR 50-29	!
	8007280414 8007280465 8007280674* 8007280675 8007280685*	50-305 50-305 50-305 50-305 50-305	F 8 8 8		6007010403 8007010404 8007020307 8007020315 8007020329	PR 50-29 PR PR PR	1
Misconsin's Environmental Decade Wisconsin, State of	6007230407 6007280477 6007310373 6007110257 6007140402	50-266 50-301 50-266 PR PR	о С Н		8007020695 8007070284 8007070407 8007080079 8007080310	PR 50-29 PR 50-29 50-29	8 P F
Wisconsin, Univ of, Madison	8007140408* 8007140417* 8007140538 8007180337 8007310403	PR PR PR 50~407 50~156	D R		8007090233 8007110529 8007140030 8007140300 8007140338	50-29 PRH PRH 50-29 50-29	F P P
Wm Marsh Rice Univ Molfbein: S L Moliver, J D Moodward-Clyde Consultants, Inc	8007310405* 8007310231 8007030346* 8007220563 8007010364*	90-156 NUREO CONTRAC 50-358 50-361	R C A		8007140701 8007150143 8007170116 8007170582 8007180097	NUREO FR 50-29 50-29 50-29	G G
Worsham, Forsythe & Sampels	8007080083* 8007250400* 8007250402* 8007250403* 8007140625	50-361 50-397 50-397 50-397 50-445	4 4 A A M		8007180144 8007210002 8007210399 8007210405* 8007210504	50-29 50-29 50-29 50-29 50-29	G R R
Hyle Laboratories Wyoming Hineral Corp	8007310269* 8007010214 8007010591 8007020079 8007030358	FOIA 40-8585 40-8502 40-8502 40-8502			8007250273 8007250278 8007280439 8007280439 8007280492	50-27 50-27 50-27 50-27 50-27	Q Q P P
	8007030363* 8007030364* 8007070147 8007150644 8007150651*	40-8502 40-8502 40-8502 40-8502 40-8502			8007280586 8007280621 8007280626 8007300009 8007310464	50-29 50-29 50-29 PR PR	p P N
	8007150657* 8007150667* 8007210095 8007210101 8007210191	40-8502 40-8502 40-8502 40-8502 40-8502		Yerway Gorp York, PA Zimmer Area Citizena — Zimmer Area Cititens of KY	8007010029* 8007220033* 8007300012* 8007119094	GA999 50-289 50-320 50-358	H H Q

REPORT NUMBER INDEX

subject category column in this index gives the docket mber and the symbol for the category of information thin that docket; for example, 50-320 P. The docket subject tegories are defined in Appendix A.

bject categories for nondocketed items are also entered this column by symbol; for example, ACRS. These cateries are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEODRY	OTHER REPORT NUMBER
111-017-02 11600 02 21A A05A 36A93 R1 441TL337	8007220372* 8007230462* 8007210233* 8007210404* 8007020135*	50-70 P 50-322 A TOPREP 50-437 A WABTE MOT		8007230177 8007230185 8007230194 8007230223 8007230231	8007230177 8007230185 8007230194 8007230223 8007230231	RES RES RES RES	LO-MR-004 RE-A-80-044 RE-A-80-047
44250-1 50-RD-100 60-RD-100 6005130445 6007020011	8007310269* 8007010226* 8007100268* 8005130445 8007020011	FOIA 50-206 R 50-206 R RES RES		B007240257 B007240294 B007250186 B007250306 B007250306	8007240257 8007240274 8007250186 8007250306 8007280002		F E00-EA-5174 P E00-EA-5177
8007020016 8007020085 8007020356 8007020364 8007030015	8007020016 8007020085 8007020356 8007020364 8007030015	RES RES RES RES	BNL-NUREG-27461 ORNL/HABRD-75 BNL-NUREG-27595	8007280004 8007280081 8007280092 8007280095 8007280144	8007280004 8007280091 8007280092 8007280095 8007280164	RES RES RES RES	4441/ML-13 ORNC/FTR-859 ORNL/HAERD-84 E00-TFBP-\$043
8007 i 10 i 48 8007 i 10 55 i 8007 i 4003 i 8007 i 4004 4 8007 i 40 503	8007110148 8007110551 8007140031 8007140044 8007140053	REB REB REB REB REB	ORNL/HASRD-81 ORNL/HASRD-82 ORNL/ED/E18-131	8007280171 8007280174 8007280179 8007280186 8007290163	8007280171 8007280174 8007280178 8007280186 8007290163	RE9 RE9 RE9 RE8 50-324	LO-MR-007 LTR 141-109 E00-CAAP-5191 E00-CAAP-5190 P E00-EA-9198
8007 1 40507 8007 1 40694 8007 1 40642 8007 1 50016 8007 1 50059	9007140507 9007140634 9007140642 9007150016 9007150059	RES RES RES RES	ORNL/HASRD-83 NRC-04-74-180 ORNL/FIR-850 EGO-CDAP-8144	8007290174 8007290180 8007290191 8007290201 8007290226	8007290174 8007290180 8007290191 8007290201 8007290226	RES RES RES RES RES	E00-TFDF-TR-502 UBNRC-P394 USNRC-P394 E00-TFBP-3080 E00-CAAP-5189
8007150066 8007150407 8007150409 8007160280 8007170460	8007150066 8007150407 8007150409 8007160280 8007170460	RES RES RES RES RES	EEQ-LOFT-5165 NRC-04-74-180	8007290233 8007290241 8007290246 8007310181 8007310183	8007270233 8007270241 8007270246 8007310181 8007310183	RES RES RES RES RES	
8007170648 8007180233 8007180240 8007180245 8007180253	800717064B 8007180233 8007180240 8007180245 8007180253	REB REB REB REB	ORNL/ED/EIB-130	8007310187 8007310251 8AW-1421 8AW-1423 8AW-4318 A12 R10	8007310187 8007310281 8007090201* 8007240002* 8007010010+	RES RES TOPREP TOPREP 70-824	CRNL/HASRD-86
8007180330 8007180352 8007180354 8007180361 8007210001	8007180330 8007180352 8007180354 8007180361 8007210001	RES RES RES RES RES	ORNL/HASRD-77 ORNL/ED/EAS-80/	BAW-381 CEN-119(B)-HP CEN-121(B)-HP CEN-124(B)-NP PT1 CEN-124(B)-NP PT2	8007020350# 8007090332* 8007090341* 8007090352* 8007090361*	50-317 50-317	13874 P P P P
8007210003 8007210005 8007210007 8007210010 8007210014	8007210003 8007210005 8007210007 8007210010 8007210014	REB RES RES REB REB		CEN-124(8)-NP PT3 CEN-133(B) CENPD-153-NP R1 CENPD-183 R1 CENPD-235 R1	8007090368* 8007090346* 8007110248* 8007100212* 8007100220*		P P LD-80-03\$
8007210017 8007210402 8007210407 8007220038 8007220045	8007210017 8007210602 8007210607 8007220038 8007220045	RES RES RES 50-263 P RES	E00-L0FT-5172 E00-EA-5194 E00-L0FT-5192	EDAC-117-253 01 R1 EDAC-117-253 01 R1 S EDAC-117-253 01 R1 S EDAC-117-253 02 R1 EDAC-117-258 01	8007280406* 8007220362* 8007220366* 8007220356* 8007220369*	50~70 50~70	թ թ թ
8007220047 8007220059 8007220058 8007220065 8007230172	8007220047 8007220053 8007220058 9007220065 8007230172	RES RES RES SO-334 P	BNL-NUREG-27591 BNL-NUREG-27759 E0Q-CDAP-5173 E0G-EA-5174	EDAC-117-258 Q2 EE-46-0004 EQDP-ESE-15 R2 QAI-TR-106 R2A I.D 77-11-07	80072203534 80072806524 8007140373* 8007070106 80071400514		P Q

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
ISBN 0-87448-106-1 J231 MAC-E-801 R1 MEDD-24781-1 NUREG-0030 V3 NO2	8007140046* 8007220317* 8007300001 8007220334* 8007240262	PR 40-1162 71-6698 TOPREP NUREG	16747 16834 CREARE-TN-307	ORD-4207-13 PNL-2682 PNL-3340 PNL-3340 8ECY-75-429	8007270475* 8007300113 8007070186* 8007210315* 8007080034	50-128	II-182 UC-11 UC-11
NUREO-0304 V4 NUREG-0561 R1 NUREO-0597 NUREO-0662 V1 NUREO-0668 DRFT	8007310004 8007030374 8007030373 8007180007* 8007100369	NUREO NUREO NUREO 50-320 NUREO	P	SECY-79-104 SECY-79-299 SECY-79-371A SECY-79-424 SECY-80-107A	8007110548 8007100098 8007020248 8007140121 8007160786	BECY BECY BECY BECY	
NUREO-0675 99 NUREO-0685 NUREO-0685 NUREO-0687 NUREO-0694	8007110034* 8007110560 8007090017* 8007170440* 8007220368	50-275 NUREC SECY 40-8745 NUREC	Ē	8ECY-80-1078 8ECY-80-132C 8ECY-80-132E 8ECY-80-153 8ECY-80-153A	8007110484 8007180012* 8007180004 8007070598 8007140574	8ECY 50-320 50-320 8ECY 8ECY	
NUREG-0698 NUREG-1385 NUREG/CR-0208 RI NUREG/CR-0308 NUREG/CR-0370 V2 APP	8007280087 8007180049 8007100363 8007290145 8007240283	50-320 NUREG NUREG NUREG NUREG	P 9ANDEO-7027 ANL-CT-78-37-2 Y/DH-128	9ECY-80-171 9ECY-80-181 9ECY-80-220 9ECY-80-238A 9ECY-80-242	8007100264 8007170083 8007110532 8007090033* 8007230179	SECY 50-320 SECY 10CFR SECY	p
NUREO/CR-0742 NUREO/CR-0743 NUREO/CR-0830 NUREO/CR-1100 NUREO/CR-1118	8007310231 8007290251 8007220019 8007210498 8007220034	NUREG NUREG NUREG 50-247 NUREG	BAND78-7017 BAND79-0349 PNL-3022 PORNL/NUREO/TM-3 UCRL-52742	8ECY-80-274 8ECY-80-275 8ECY-80-275 8ECY-80-275A 8ECY-80-2753	8007250019* 8007070015 8007140059* 8007140055 8007170604*	10CFR BECY BECY BECY 10CFR	
NUREO/CR-1119 NUREO/CR-1169 V3 NUREO/CR-1184 NUREO/CR-1195 NUREO/CR-1198 V1	8007310225 8007180072 8007310007 8007270217 8007310241	NUREO NUREO NUREO 50-254 NUREG	4259 UCRL-32730 8AND79-1787 ENICO-1023 GAND79-2378/1	8ECY-80-278 8ECY-80-283 8ECY-80-271 8ECY-80-274 8ECY-80-278	8007250176 8007140182 8007290002 8007140552 8007150050	BECY 50-247 BECY BECY BECY	P 43FR48621
NUREO/CR-1207 NUREO/CR-1204 NUREO/CR-5253 NUREO/CR-5258 V2 NUREO/CR-5260	8007310019 8007220024 8007170311 8007140517 8007300041	50-219 I NUREQ NUREQ NUREQ NUREQ	P UCRL-52744 PNL-3256 UCID-18123-79-4 DRNL/NUREO/TM-3	8ECY-80-277 8ECY-80-301 8ECY-80-306 8ECY-80-307 8ECY-80-308	8007290023 8007140539 8007150069 8007150034 8007280062	SECY SECY SECY SECY SECY	
NUREO/CR-1287 NUREO/CR-1295 NUREO/CR-1301 NUREO/CR-1314 NUREO/CR-1357	8007310216 8007310246 8007310210 8007030350 8007310234	NUREO NUREO NUREO NUREO	BNL-NUREO-51 143 ORNL/NUREO-63 PNL-3275 PNL-3286 BNL-NUREO-51 157	8ECY-80-313 9ECY-80-314 9ECY-80-317 9ECY-80-318 9ECY-8-74-095	8007280084 8007210009 8007170244 8007170523 8007020270	SECY SECY SECY SECY	
NUREO/CR-1361 NUREO/CR-1396 NUREO/CR-1413 NUREO/CR-1425 NUREO/CR-1439	8007230425 8007290152 8007180045 8007310255 8007310217	NUREO NUREO NUREO NUREO NUREO	E00-2025 8AND80-0820 0RNL/NUREG-70 E00-2032 BNL-NUREG-51187	8ECY-R-74-132 8G-07 TI5-6171 TR-3195-1 TR-3887-2 R1 NO!	8007020262 8007300007* 8007080285* 8007100188* 8007310387*	SECY ORG TOPREP PR 50-329	50-60 - 07
NUREO/CR-1440 NUREO/CR-1440 NUREO/CR-1459 NUREO/CR-1460 NUREO/CR-1464	8007280508 8007280205 8007140092 8007180031 8007140610	NUREO NUREO NUREO NUREO NUREO	E00-EA-5153 E00-EA-5153 E00-2038 ANL-80-43 DRNL/XUREO/TM-3	URCL-15172 VEP-FRD-35 WCAP-8163 R9 WCAP-8567 R1 WCAP-8587 R2 81	8007030208* 8007020598* 8007100256* 8007150656* 8007160765*		P 8AN-L-807027 P EGDP-ESE-LO EGDP-ESE-4
NUREO/CR-1477 NUREO/CR-1483 NUREO/CR-1486 NUREO/CR-1489 NUREO/CR-1500	9007310554 9007300575 9007240409 8007240478 9007210491	NUREO NUREO NUREO NUREO NUREO	ORNL/NUREO/TM-3 DRNL/NUREO/TM-3 UCRL-52746	HCAP-8587 81 HCAP-8587 82 HCAP-8587 82-E02A HCAP-8587 82-E04A HCAP-8587 82-E10A	8007140420* 8007140379* 8007140416* 8007160735* 8007150632*	TOPREP	EGDP-ESE-2 E15A
NUREG/CR-1504 NUREG/CR-1512 NUREG/CR-1513 NUREG/CR-1520 NUREG/CR-1520	8007240459 8007170418 8007310471 8007310009 8007280483	NUREO NUREO NUREO NUREO NUREO	ANL-80-47 ATR-80(7814)-1 BNL-NUREQ-51219 EG0-2045 EG0-2045	WCAP-9570 R1 WCAP-9744 WCAP-9749 WCAP-9754 WMTP 11 21 R0	8007020644* 8007220499* 8007020596* 8007220503* 8007210452*	TOPREP TOPREP TOPREP TOPREP 50-266	P
NUREO/CR-1523 NUREO/CR-1555 NUREO/CR-1557 NUREO/CR-1580 V1 NUREO/CR-1580 V2	8007090371 8007230201 8007240394 80070901664 8007090167*	NUREO NUREO NUREO NUREO NUREO	ORNL/NUREG/TM/- BHI-2064 BHI-2038	WMTP 11 21 R0 WMTP 11 22 R0 WMTP 11, 22 R0 Y1003J01A12	8007210460* 8007210465* 8007210469* 8007170574*	50-266 50-266	P P P
NUS-3544 NUS-3582 NUS-3594 NUS-3595 ONWI-18	8007220111* 8007220036* 8007220032* 8007220101* 8007300249	WASTE MOT WASTE MOT WASTE MOT WASTE MOT PR	16693 16693				

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCERBION NUMBER

8007010085

8907010047

80/06/09 40-2674

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

	PRINCIPAL	DATE	BUBJECT	
ENCLOSURE	DOCUMENT	IBSUED	CATEGOR	
EM-LUSUME	DOCUMENT	165020	CHIEGON	т
B005090524	8005090523	80/02/26	PT9	
8005090527	8005090523	80/05/59	PT9	
8005090529	B005090523	80/02/26	PT 7	
8005290607	8005290603	80/05/07	PTT	
8005290612	8005290603	80/03/07	PTS	
6005290616	8005290603	89/05/07	PT9	
8006110739	B006110736	80/04/24	27-10	
B006200071	8009500099	B0/05/23	50-4BB	-G
B0062400B2	8006240081	B0/05/28	40-1142	
B006260145	8005260142	B0/09/10	50-255	Р
E1100E400B	E006300097	80/05/23	ACRS	
B00630013B	8006300114	80/05/14	50-329	G
8009300385	8006300375	80/04/27	50-416	F
48C00CAD0B	6004300375	80/05/27	50-416	F
8007010004	8007010002	B0/06/14	50~397	Α
8007010007	8007010002	80/06/16	50~397	Α
8007010008	E007010003	80/06/08	50-237	P
B007010010	8007010006	80/03/25	70~B24	
8007010011	B007010003	60/06/03	50~237	P
8007010017	8007010013	80/06/10	ORG	
B00701001B	8007010002	80/06/16	50-397	Α
8007010021	8007010002	80/06/16	50-397	Λ
8007010023	B007010002	80/06/16	50-397	A
8007010029	8007010015	B0/06/17	GA999	
8007010032	8007010002	ED/06/16	50-397	Α
8007010033	E007010002	80/06/16	50-397	Α
E007010034	B007010015	B0/06/17	QA999	• •
8007010038	8007010002	B0/06/16	50-397	Λ
8007010039	E007010015	80/06/17	QA999	
8007010041	800701000R	80/06/16	50-397	Α
B007010045	8007010002	80/06/16	50-397	Α
8007010046	8007010031	80/06/16	50-546	H
6007010049	8907010002	B0/06/16	50-397	Ä
8007010051	8007010015	80/06/17	QA799	•••
8007010052	B007010002	80/06/16	50-397	Α
	220,410022	44,00,40		••
8007010054	8007010002	80/06/16	50-397	Α
B007010055	6007010031	80/06/16	50-546	н
B00701005B	8007010002	80/06/16	50-397	Ä
B007010059	6007010002	80/06/16	50-397	Ä
8007010040	8007010047	80/06/09	40-2674	••
000/010000	0007010047	44,00.07	12 4074	
8007010061	8007010002	E0/06/16	50-397	Α
8907010064	8007010002	80/06/16	50-397	Ä
8007010067	8007010002	B0/06/09	40-2674	••
8007010067	E007010002	80/06/14	50-397	Α
8007010027	B007010002	80/06/16	50-377	Â
2001010010	PROTOTOR	-4120110	-0 0/7	
8007010076	E007010002	80/04/16	50-397	Α
8007010078	6007010002	80/05/07	40~2674	_
8007010077	8007010070	80/06/20	FDIA	
		80/06/20	50-397	Α
6007010083	8007010002	WU/ UD/ 10	JV".07/	

PRINCIPAL DATE EUBLECT CATEGORY PRIORITION EUGO/10070 EU				
BOO701008B BO07010070 BO/06/20 SO-249 P				
BOO701009B	ENCLOSURE	DOCUMENT	188UED	CATEGORY
SOCIOLOPS BOO7010002 SOCION SOC				~~~~~~
SOCIOLOPS BOO7010002 SOCION SOC	8007010088	B007010070	80/06/20	50-249 P
B007010091 B007010002 B0/06/09 40-2674 B007010093 B007010002 B0/06/20 F01A B007010093 B007010002 B0/06/09 40-2674 B007010093 B007010002 B0/06/09 40-2674 B007010099 B007010002 B0/06/09 40-2674 B007010099 B007010000 B0/06/09 50-309 P B007010103 B007010070 B0/06/20 S0-249 P B007010106 B007010070 B0/06/20 F01A B007010107 B007010105 B0/06/20 F01A B007010114 B007010070 B0/06/20 F01A B007010128 B007010070 B0/06/20 F01A B007010128 B007010070 B0/06/20 F01A B007010129 B00701010 B0/06/20 F01A B007010140 B007010070 B0/06/20 B0/06/20 B007010141 B007010070 B0/06/20 B0/06/20 B007010142 B007010070 B0/06/20 F01A B007010143 B007010070 B0/06/20 F01A B007010144 B007010070 B0/06/20 F01A B007010145 B007010070 B0/06/20 F01A B007010146 B007010070 B0/06/20 F01A B007010147 B007010070 B0/06/20 F01A B007010148 B007010070 B0/06/20 F01A B007010149 B007010070 B0/06/20 F01A B007010140 B007010070 B0/06/20 F01A B007010141 B007010070 B0/06/20 F01A B007010142 B007010070 B0/06/20 F01A B007010143 B007010070 B0/06/20 F01A B007010144 B007010070 B0/06/20 F01A B007010145 B007010070 B0/06/20 F01A B007010146 B007010070 B0/06/20 F01A B007010171 B007010070 B0/06/20 F01A B007010172 B007010070 B0/06/20 F01A B007010173 B007010070 B0/06/20 F01A B007010174 B007010070 B0/06/20 F01A B007010174 B007010070 B0/06/20 F01A B007010175 B007010070 B0/06/20 F01A B007010176 B007010070 B0/06/20 F01A B007010177 B007010070 B0/06/20 F01A B007010178 B007010070 B0/06/20 F01A	8007010090	B007010002	B0/05/16	50~397 A
BO07010092 B007010002 B0/06/20 F01A				
BOO7010093 BO07010070 BO/06/20 F01A				50-207 A
BOO7010093 BO07010002 BO/06/16 SO-397 A BOO7010097 BO07010007 BO/06/16 SO-397 A BOO7010099 BO07010002 BO/06/16 SO-397 A BOO7010099 BO07010070 BO/06/20 SO-309 P BO07010010 BO/06/20 SO-249 P BO07010101 BO/06/20 SO-249 P BO07010101 BO/06/20 SO-249 P BO07010101 BO/06/20 SO-249 P BO07010101 BO07010101 BO/06/20 F01A BO07010109 BO/06/20 F01A BO07010109 BO/06/20 F01A BO07010114 BO07010070 BO/06/20 F01A BO07010121 BO07010105 BO/06/20 F01A BO07010124 BO07010105 BO/06/20 F01A BO07010124 BO07010126 BO/06/20 F01A BO07010128 BO07010128 BO/06/20 F01A BO07010128 BO07010129 BO/06/20 F01A BO07010149 BO07010129 BO/06/20 F01A BO07010149 BO07010135 BO/06/20 F01A BO07010145 BO07010070 BO/06/20 F01A BO07010174 BO0				
SOCIOLOGY SOCI	8003010043	8003010030	60/09/50	1.01V
SOCIOLOGY SOCI				
B007010098 B007010002 B0/06/16 S0-397 A				
SOCIO10103				
S007010103 S007010070 E0/06/20 S0-249 F	800701009B	B007010002	80/06/16	50-397 A
S007010103 S007010070 S0706/20 S0-249 P	6007010099	8007010070	B0/04/20	50-309 P
BOO7010106	E01010701B	8007010070	B0/06/20	50-249 P
BOO7010108		4		
BOO7010108	9007010106	0007010101	DD /04/22	71-9760
BO07010109				
BO07010117 B007010070 B0/06/20 F01A F007010121 B007010101 B0/06/20 F01A F007010121 B007010101 B0/06/20 F01A B007010101 B0/06/20 F01A B007010102 B0/06/20 F01A B007010128 B007010128 B0/06/20 F01A B007010129 B0/06/20 F01A B007010129 B0/06/20 F01A B007010129 B0/06/20 B0/0				
BOO7010117 BOO7010105 BO/0b/11 70-143				
BO07010119				
SOCIOLO Soci	8007010117	B007010105	BO/05/11	70-143
SOCIOLO Soci				
SOCIOLO SOCI	B007010117	8007010070	B0/05/20	50-265 ()
ROO7010125				
B007010126 B007010070 B0/06/20 F01A B007010134 B007010127 B0/06/17 B1 B1 B1 B1 B1 B1 B1				
R007010133 R007010128 R0706/17 Rtate Prog				
R007010134				
ROO7010140	H007010133	8003010158	80/08/1/	State Prog
ROO7010140				
SOCIO10141				
SOCOTOLO142 SOCOTOLO135 SOCOTOLO145 SOCOTOLO145 SOCOTOLO135 SOCOTOLO145 SOCOTOLO135 SOCOTOLO145 SOCOTOLO135 SOCOTOLO147 SOCOTOLO135 SOCOTOLO147 SOCOTOLO135 SOCOTOLO151 SOCOTOLO135 SOCOTOLO152 SOCOTOLO152 SOCOTOLO153 SOCOTOLO154 SOCOTOLO135 SOCOTOLO154 SOCOTOLO135 SOCOTOLO141 SOCOTOLO135 SOCOTOLO141 SOCOTOLO145	9007010140	8007010129	60/05/01	40-8728
S007010142 S007010135 S0/06/04 GA999	8007010141	B007010070	80/06/20	50-293 P
S007010145 S007010070 S0/06/20 F01A	8007010142	8007010135		
R007010147				
BO07010149 B007010070 B0/04/20 F01A B007010151 B007010135 B0/04/04 GA999 B007010152 B007010070 B0/06/20 F01A GA999 B007010154 B007010070 B0/06/20 F01A B007010141 B007010070 B0/06/20 F01A B007010143 B007010135 B0/06/20 F01A B007010145 B007010135 B0/06/20 F01A B007010157 B007010157 B0/06/20 F01A B007010157 B007010157 B0/06/20 F01A B007010171 B007010135 B0/06/20 F01A B007010172 B007010135 B0/06/20 F01A B007010173 B007010174 B007010175 B0/06/20 F01A B007010175 B007010176 B007010070 B0/06/20 F01A B007010176 B007010070 B0/06/20 F01A B007010176 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010165 B007010165 B0/06/20 F01A B007010167 B007010167 B00701070 B0/06/20 F01A B007010169 B00701070 B0/06/20 F01A B0	400,0101-10	200,0100,0	מש יונוט יוטט	1444
BO07010149 B007010070 B0/04/20 F01A B007010151 B007010135 B0/04/04 GA999 B007010152 B007010070 B0/06/20 F01A GA999 B007010154 B007010070 B0/06/20 F01A B007010141 B007010070 B0/06/20 F01A B007010143 B007010135 B0/06/20 F01A B007010145 B007010135 B0/06/20 F01A B007010157 B007010157 B0/06/20 F01A B007010157 B007010157 B0/06/20 F01A B007010171 B007010135 B0/06/20 F01A B007010172 B007010135 B0/06/20 F01A B007010173 B007010174 B007010175 B0/06/20 F01A B007010175 B007010176 B007010070 B0/06/20 F01A B007010176 B007010070 B0/06/20 F01A B007010176 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010164 B007010070 B0/06/20 F01A B007010165 B007010165 B0/06/20 F01A B007010167 B007010167 B00701070 B0/06/20 F01A B007010169 B00701070 B0/06/20 F01A B0	DANTO 10147	0007010125	00104104	AARRO
SO07010151 SO07010135 SO/06/04 SO/07010152 SO0701070 SO/06/04 SO/07010154 SO0701070 SO/06/04 SO/07010154 SO0701070 SO/06/04 SO/07010154 SO070101070 SO/06/04 SO/07010164 SO070101055 SO/06/04 SO/07010165 SO070101057 SO/06/04 SO/07010167 SO07010167 SO/06/04 SO/				
8007010152 8007010070 8006/20 F01A 8007010154 8007010135 80/06/04 GA999 8007010158 8007010070 80/06/20 F01A 8007010141 8007010135 80/06/20 F01A 8007010143 8007010135 80/06/20 F01A 8007010145 8007010135 80/06/20 F01A 8007010146 8007010133 80/06/20 F01A 8007010171 8007010135 80/06/20 F01A 8007010172 8007010104 80/06/20 F01A 8007010173 8007010070 80/06/20 F01A 8007010174 8007010070 80/06/20 F01A 8007010175 8007010070 80/06/20 F01A 8007010181 8007010070 80/06/20 F01A 8007010184 8007010070 80/06/20 F01A 8007010187 8007010180 80/06/20 F01A 8007010187 8007010180 80/06/20 F01A 8007010191 8007010070 <td< td=""><td></td><td></td><td></td><td></td></td<>				
R007010154 R007010135 R0006/04 R007010158 R007010070 R0006/04 R007010135 R0006/040 R007010135 R0006/040 R007010135 R0006/040 R007010135 R0006/040 R007010135 R0006/040 R007010135 R0006/040 R0006/04				
\$00701015B			80/06/20	FOIA
S007010161 S007010070 S0066/20 F01A S007010165 S007010133 S007010134 S0066/20 F01A S007010135 S007010135 S007010167 S007010135 S0066/20 F01A S007010172 S007010135 S0066/20 F01A S007010172 S007010135 S0066/20 F01A S007010173 S007010174 S007010175 S007010176 S007010176 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010167 S007010167 S00701070 S0066/20 F01A S007010167 S007010167 S00701070 S0066/20 F01A S007010167 S00701	9007010154	8007010135	80/06/04	QA999
S007010161 S007010070 S0066/20 F01A S007010165 S007010133 S007010134 S0066/20 F01A S007010135 S007010135 S007010167 S007010135 S0066/20 F01A S007010172 S007010135 S0066/20 F01A S007010172 S007010135 S0066/20 F01A S007010173 S007010174 S007010175 S007010176 S007010176 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010164 S00701070 S0066/20 F01A S007010167 S007010167 S00701070 S0066/20 F01A S007010167 S007010167 S00701070 S0066/20 F01A S007010167 S00701				
9007010141	800701015B	B007010070	80/06/20	FOIA
S007010163				
8007010168 8007010070 80/06/20 F01A 8007010167 8007010133 80/06/20 F01A 8007010171 8007010135 80/06/20 F01A 8007010172 8007010135 80/06/20 F01A 8007010173 8007010070 80/06/20 F01A 8007010174 8007010070 80/06/20 F01A 8007010176 8007010070 80/06/20 F01A 8007010184 8007010070 80/06/20 F01A 8007010185 80070100180 80/06/20 F01A 8007010185 8007010070 80/06/20 F01A 8007010187 8007010070 80/06/20 F01A 8007010191 8007010070 80/06/20 F01A 8007010191 8007010070 80/06/20 F01A 8007010193 8007010070 80/06/20 F01A 8007010194 8007010070 80/06/20 F01A 8007010195 8007010190 80/06/20 F01A 8007010197 8007010190 <t< td=""><td></td><td></td><td></td><td></td></t<>				
S007010167 S007010139 S0006/04 GA799				
800701016B 8007010070 80/06/20 F0IA 8007010171 8007010135 80/06/04 9A997 8007010172 8007010144 80/06/10 50-333 9 8007010173 800701070 80/06/20 F0IA 800701070 80/06/20 F0IA 8007010176 800701070 80/06/20 F0IA 8007010176 8007010176 80/06/20 F0IA 8007010184 8007010180 80/06/20 F0IA 8007010187 8007010180 80/06/20 F0IA 8007010187 8007010180 80/06/20 F0IA 8007010191 800701070 80/06/20 F0IA 8007010191 800701070 80/06/20 F0IA 8007010191 8007010190 80/06/20 F0IA 8007010194 8007010070 80/06/20 F0IA 8007010194 800701070 80/06/20 F0IA 8007010194 8007010070 80/06/20 F0IA 8007010194 8007010070 80/06/20 F0IA 8007010194 8007010070 80/06/20 F0IA 8007010194 8007010070 80/06/20 8007010194 8007010070 80/06/20 8007010194 8007010189 80/06/20 80/				
8007010171 8007010135 80061704 807097 8007010172 8007010070 8006170 701A 8007010176 8007010070 8006170 701A 8007010176 8007010070 8006170 701A 8007010184 8007010070 8006170 701A 8007010184 8007010184 8007010184 8007010180 8006170 701A 8007010187 8007010187 8007010187 8007010191 8007010070 8006170 701A 8007010191 8007010070 8006170 701A 8007010194 8007010070 80106172 8007010194 8007010070 80106172 80106172 8007010187	900/010197	800/010133	80706704	GAYYY
8007010171 8007010135 80061704 807097 8007010172 8007010070 8006170 701A 8007010176 8007010070 8006170 701A 8007010176 8007010070 8006170 701A 8007010184 8007010070 8006170 701A 8007010184 8007010184 8007010184 8007010180 8006170 701A 8007010187 8007010187 8007010187 8007010191 8007010070 8006170 701A 8007010191 8007010070 8006170 701A 8007010194 8007010070 80106172 8007010194 8007010070 80106172 80106172 8007010187				
B007010172				
B007010173			80/04/04	9 0 999
8007010176 8007010070 80708/20 FD1A 8007010181 8007010070 80708/20 FD1A 8007010184 8007010070 80708/13 70-2885 8007010185 8007010180 80705/28 40-6787 8007010187 8007010070 80708/20 FD1A 8007010191 8007010070 80708/20 FD1A 8007010193 8007010190 80708/20 FD1A 8007010194 8007010189 80708/20 FD1A 8007010195 8007010189 80708/20 FD1A 8007010197 8007010189 80708/20 FD1A	8007010172	B007010164	80/05/11	50-333 0
8007010176 8007010070 80/06/20 F01A 8007010181 8007010070 80/06/20 F01A 8007010184 8007010074 80/06/13 70-2885 8007010185 8007010180 80/06/20 40-6789 8007010191 8007010070 80/06/20 F01A 8007010193 8007010190 80/06/20 F01A 8007010194 8007010070 80/06/20 F01A 8007010195 8007010189 80/06/20 F01A 8007010197 8007010189 80/06/20 80/06/20 8007010197 8007010189 80/06/20 80/06/20 8007010197 8007010189 80/06/20 80/06/20 8007010197 8007010189 80/06/20 80/06/20	8007010173	8007010070	60/06/20	FOIA
8007010181 8007010070 80/06/20 F01A 8007010184 8007010094 80/06/13 70-2885 8007010187 800701070 80/06/20 F01A 8007010191 8007010970 80/06/20 F01A 8007010193 8007010970 80/06/20 F01A 8007010194 8007010970 80/06/24 50-237 P 8007010194 8007010189 80/06/20 F01A 8007010195 8007010189 80/06/20 F01A	8007010176	E007010070		
8007010184 800701089 80705/28 70-2888 807010187 807010189 80705/28 FDIA 8007010191 800701070 80706/20 FDIA 8007010191 8007010970 80706/20 FDIA 8007010194 8007010190 80706/20 FDIA 807010194 8007010189 80706/20 FDIA 8007010195 807010189 80706/20 FDIA 8007010197 8007010189 80706/20 FDIA 8007010197 8007010189 80706/20 80				
8007010184 800701089 80705/28 70-2888 807010187 807010189 80705/28 FDIA 8007010191 800701070 80706/20 FDIA 8007010191 8007010970 80706/20 FDIA 8007010194 8007010190 80706/20 FDIA 807010194 8007010189 80706/20 FDIA 8007010195 807010189 80706/20 FDIA 8007010197 8007010189 80706/20 FDIA 8007010197 8007010189 80706/20 80	2007010181	P007010070	90/04/20	COTA
B007010185 B007010180 B0/05/28 40-6789 B007010187 B007010070 B0/06/20 FDIA B007010191 B007010070 B0/06/20 FDIA B007010193 B007010070 B0/06/20 FDIA B007010194 B007010070 B0/06/20 FDIA B007010187 B0/06/13 70-2838 B007010187 B0/06/13 B0/06/28 40-6789 B007010187 B0/06/28 40-6789				
8007010197 8007010070 80/06/20 FD1A FD1A FD1A FD1A FD1A FD1A FD1A FD1A				
8007010191 8007010070 80/06/20 FDIA 8007010193 8007010190 80/06/24 50-237 P 8007010194 8007010189 80/06/20 FDIA 8007010197 8007010189 80/06/13 70-2838 8007010197 8007010180 80/08/28 40-6/89				
8007010193 8007010190 80/06/24 50-237 P 8007010194 8007010070 80/06/20 FD1A 8007010195 8007010189 80/06/13 70-2838 8007010197 8007010180 80/05/28 40-6789				
8007010194 B007010070 80706/20 F01A 8007010195 B007010189 80/06/13 70-2838 8007010197 B007010180 B0/05/28 40-6789	B007010191	8007010070	80/06/20	FOIA
8007010194 B007010070 80706/20 F01A 8007010195 B007010189 80/06/13 70-2838 8007010197 B007010180 B0/05/28 40-6789				
8007010194 B007010070 80706/20 F01A 8007010195 B007010189 80/06/13 70-2838 8007010197 B007010180 B0/05/28 40-6789	0007010193	8007010190	80/06/24	50-237 P
8007010195 8007010189 80/06/13 70-2838 8007010197 8007010180 80/05/28 40-6789				
8007010197 8007010180 80/05/28 40-6789				
				/4-K070
800/410148 800/0100/0 80/09/50 k01V				
	89101019B	6007010070	80/09/50	FOIA

ACCESSIO	N NUMBER				ACCEBBIO	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGORY
E007010197 8007010204 B007010207 8007010209 6007010210	8007010192 8007010070 8007010070 8007010180 8007010070	B0/06/13 B0/06/20 B0/05/28 B0/05/28	50-247 FOIA FOIA 40-6789 FOIA	P	8007010527 8007010532 8007010535 8007010534 8007010534	8007010524 8007010525 8007010527 8007010526 8007010533	80/06/27 80/06/25 80/06/24 80/06/26 80/06/23	50-304 8 50-327 8 50-368 8 50-334 8 50-206 8
8007010212 8007010215 8007010218 8007010222 8007010223	8007010203 8007010070 8007010070 8007010070 8007010217	80/05/19 80/05/20 80/05/20 80/05/20 80/05/30	50~498 FOIA POIA FOIA 50~443	q Q	8007010539 8007010541 8007010542 8007010545 8007010551	800701052B 8007010534 8007010531 8007010540 8007010544	80/06/23 80/06/25 80/06/26 80/06/25 80/06/24	50-327 B 50-327 B 50-263 B 50-293 S 50-237 B
8007010226 8007010227 8007010229 8007010230 8007010232	8007010216 8007010070 8007010219 8007010070 8007010219	B0/06/25 B0/06/20 B0/05/30 B0/06/20 B0/05/30	50-206 FOIA 50-443 FOIA 50-443	R G	8007010552 8007010552 8007010562 8007010564 8007010574	8007010547 8007010547 8007010559 8007010556 8007010570	80/04/09 80/04/09 80/05/30 80/06/20 80/06/13	COMMISSION 50-320 P 40-1162 50-325 B 71-384
B007010233 B007010234 B007010235 B007010238 B007010241	8007010070 8007010231 8007010219 8007010070 8007010070	80/06/20 80/06/20 80/05/30 80/06/20 80/06/20	FDIA 50-267 50-443 FDIA FDIA	g	8007010578 8007010579 8007010582 8007010583 8007010583	8007010573 8007010576 8007010580 8007010581 8007010581	80\09\18 80\09\18 80\09\18 80\09\19	70-1308 71-252 CONTRACT 50-282 P 50-282 P
8007010244 8007010247 8007010263 8007010274 8007010281	8007010070 8007010070 8007010256 8007010270 8007010056	80/06/20 80/06/20 80/06/16 80/06/16 80/06/07	FDIA FDIA 50-484 WASTE M 70-1062	310	8007010592 8007010598 8007010400 8007010402 8007010402	8007010590 8007010595 8007010595 8007010595 8007010595	80/05/14 80/05/14 80/05/14 80/05/14 80/05/14	40-8647 71-5980 71-5980 71-5980 71-5980
8007010291 8007010295 8007010301 8007010305 8007010343	8007010285 8007010293 8007010299 8007010299 8007010341	80/04/24 80/06/13 80/06/13 80/04/24 80/06/25	50-334 70-824 70-824 50-219 50-382	0 P	8007010605 8007010611 8007010615 8007010617 8007010627	8007010595 8007010609 8007010609 8007010613 8007010624	80/05/14 80/06/10 80/06/10 80/06/16 80/04/16	71-5980 40-8027 40-8027 CONTRACT CONTRACT
8007010346 8007010350 8007010364 8007010373 8007010374	8007010344 8007010338 8007010358 8007010359 8007010358	80/06/23 80/06/25 80/06/27 80/06/17 80/06/27	50-267 50-518 50-361 50-313 50-361	R A F A	8007020005 8007020008 8007020009 8007020012 8007020017	8007020002 8007020007 8007020002 8007020002 8007020015	80/05/28 80/05/28 80/05/15 80/05/28 80/05/23	70-135 70-135 CONTRACT 70-135 70-1143
8007010375 8007010377 8007010380 8007010381 8007010385	8007010353 8007010370 8007010369 8007010376 8007010382	80/06/24 80/06/25 80/06/19 80/06/27 80/06/23	50-339 50-296 50-313 50-306 50-327	8 5 5	8007020022 B007020025 B007020031 B007020041 B007020047	8007020015 8007020024 8007020027 8007020035 8007020044	80/05/23 80/05/28 80/06/13 80/05/28 80/06/12	70-1143 CONTRACT 50-544 Q 50-277 Q 71-5
8007010390 8007010392 8007010393 8007010394 8007010400	8007010389 8007010389 8007010178 8007010340 8007010396	80/06/13 80/06/13 80/05/22 80/06/26 80/06/24	50-317 50-317 50-255 50-261 50-334	R R G S S	8007020049 8007020060 8007020070 8007020073 8007020088	8007020035 8007020035 8007020035 8007020064 8007020082	80/05/28 80/05/28 80/05/28 78/09/14 80/06/26	50-277 Q 50-277 Q 50-277 Q 50-322 S 50-10 U
8007010405 8007010412 8007010414 8007010415 8007010419	8007010371 8007010405 8007010407 8007010398 8007010417	80/06/25 80/06/27 80/06/26 80/06/26 80/06/25	50-271 50-348 50-368 50-339 50-327	8888	8007020095 8007020096 8007020103 8007020103 8007020106	8007020089 8007020090 8007020097 8007020102 8007020097	79/09/13 80/06/11 80/05/30 80/05/30 80/05/30	TOPREP 50-443 H 70-1100 71-6078 70-1100
8007010420 8007010431 8007010439 8007010439 8007010440	8007010409 8007010425 8007010435 8007010434 8007010437	80/06/25 80/06/23 80/06/26 80/06/27	50-246 50-324 50-327 50-346 50-368	5 6 5 5	800702010B 8007020112 8007020114 8007020115 8007020121	8007020102 8007020102 8007020107 8007020102 8007020097	80/05/30 80/05/30 80/06/06 80/05/30 80/05/30	71-6078 71-6078 70-1100 71-6078 70-1100
8007010441 8007010442 8007010446 8007010450 8007010451	8007010436 8007010429 8007010444 8007010445 8007010447	80/06/25 80/06/26 80/06/25 80/06/24 80/06/27	50-368 50-280 50-348 50-336 50-155	8 8 8 6 P	8007020135 8007020144 8007020149 8007020158 8007020154	8007020128 8007020137 8007020131 8007020131 8007020155	80/06/10 79/11/14 80/06/13 80/06/13 80/05/27	WASTE MOT MISC 50-361 G 50-361 G 50-352 B
8007010455 8007010456 8007010456 8007010477 8007010480	8007010448 8007010396 8007010454 8007010471 8007010470	B0/06/27 B0/06/24 B0/06/26 B0/06/25 B0/06/25	50-286 50-334 50-320 50-285 50-313	8 8 8 8	8007020166 8007020167 8007020174 8007020175 8007020188	8007020131 8007020159 8007020169 8007020131 8007020129	80/06/13 79/11/26 80/06/14 80/06/13 80/06/05	50-361 Q 50-329 A 50-150 P 50-361 Q COMMISSION
8007010485 8007010488 8007010491 8007010495 8007010500	B007010481 B007010484 B007010483 B007010486 B007010493	80/06/27 80/06/25 80/06/19 80/06/25 80/06/26	50-233 50-295 50-235 50-233 50-295	8 8 8	8007020191 8007020195 8007020203 8007020211 8007020217	8007020131 8007020183 8007020183 8007020199 8007020198	80/06/13 80/06/19 80/06/19 80/06/11 80/06/18	50-361 Q 50-10 H 50-10 H 50-295 Q 50-324 H
8007010502 8007010503 8007010505 8007010506	B007010499 B007010494 B007010497 B007010496	80/06/25 80/06/24 80/06/24 90/06/23	50-327 50-366 50-237 50-247 50-325	88888	8007020220 8007020225 8007020233 8007020237 8007020271	8007020213 8007020216 8007020230 8007020229 8007020267	80/05/08 80/05/08 80/06/17 80/06/09 80/06/18	70-1151 50-334 Q 70-2910 50-320 H 50-259 Q
			50-327 50-344 10-333 0-325	988	8007020275 8007020279 8007020287 8007020290 8007020290 8007020292	8007020267 8007020264 8007020264 8007020266 8007020266	80/06/18 80/06/09 80/02/12 80/06/17 80/02/12	50-259 G WABTE MGT FOIA 50-344 P FOIA

ACCEB910A	NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGORY	PRINCIPAL DATE SUBJEC ENCLOSURE DOCUMENT ISSUED CATEGO	
8007020294 8007020301 8007020305 8007020313 8007020321	8007020298 8007020298 8007020298 8007020303 6007020317	80/06/17 80/06/19 80/06/19 80/06/04 80/06/02	50-344 P 50-321 Q 50-321 Q 50-321 U 50-320 U 50-335 Q	8007030035 8007030031 80/05/09 40-8647 8007030038 8007030033 80/06/23 FD1A 8007030034 8007030031 80/05/09 40-8647 8007030040 8007030034 80/06/09 50-369 8007030047 8007030031 80/05/09 40-8647	, G
8007020323 8007020326 8007020331 8007020336 8007020338	8007020303 8007020317 8007020325 8007020325 8007020099	80/05/04 80/06/02 80/06/13 80/06/13 80/05/21	50-320 U 50-335 G COMMISSION COMMISSION State Prog	8007030050 8007030045 80/05/13 PR 8007030055 8007030031 80/05/07 40-8647 8007030059 8007030045 80/05/13 PR 8007030071 8007030046 80/06/13 CONTRAC 8007030135 8007030131 80/06/30 \$0-280	
8007020350 8007020354 8007020357 8007020358 8007020361	8007010004 8007020349 8007020109 8007020339 8007020334	B0/03/25 B0/04/24 B0/05/19 B0/05/30 B0/06/24	70-824 50-317 P 50-247 P 70-27 50-324 8	8007030180 8007030178 80/05/30 \$0-282 8007030183 8007030178 80/05/30 \$0-282 8007030189 8007030185 80/07/01 \$0-413 8007030208 8007030194 80/05/04 \$0-285 8007030209 8007030204 80/06/17 PR	R R A P
8007020365 8007020366 8007020372 8007020375 8007020382	8007020339 8007020342 8007020342 8007020370 8007020370	80/03/30 80/06/30 80/06/30 80/05/14 80/05/14	70-27 50-204 P 50-204 P 50-67 R 50-67 R	8007030213 8007030210 80/06/16 \$0-273 8007030217 8007030212 80/06/26 \$0-331 8007030231 8007030228 80/06/17 70-1115 8007030235 8007030224 80/06/26 50-331 8007030241 8007030238 80/06/26 50-331	9 9 8
8007020398 8007020405 8007020411 8007020413 8007020420	8007020386 8007020397 8007020402 8007020406 8007020408	80/06/10 80/06/27 80/06/11 80/06/10 80/06/27	CONTRACT 50-382 8 50-409 D PR 50-494 K	8007030248 8007030245 80/06/30 50-416 8007030251 8007030250 80/07/01 50-255 8007030264 8007030260 80/06/27 50-346 8007030267 8007030262 80/06/30 50-339 8007030269 8007030263 80/06/30 50-338	A 9 5 5
8007020428 8007020428 8007020431 8007020437 8007020442	8007020417 8007020422 8007020429 8007020432 8007020436	80/04/23 80/06/19 80/06/13 80/06/11 80/06/27	50-268 P 71-6698 70-2609 50-271 0 50-317 P	8007030271 8007030270 80/06/30 50-338 8007030274 8007030272 80/06/24 50-366 8007030275 8007030273 80/06/30 50-339 8007030278 8007030276 80/06/30 50-321 8007030277 8007030277 80/06/26 50-366	8 9 8 8
8007020448 8007020448 8007020455 8007020485 8007020493	8007020130 8007020435 8007020451 8007020461 8007020490	80/06/12 80/06/27 80/06/18 80/06/19 80/06/17	ORO 50-317 P 50-271 H 50-3 G 50-193 P	B0070302B2 B0070302B0 B0/04/24 \$0-346 B0070302B3 B0070302B1 B0/04/30 \$0-339 B0070302B6 B0070302B6 B0/04/25 \$0-321 B0070302B8 B0070302B5 B007/01 \$0-321 B0070302B7 B0070302B7 B0070302B7 B0070302B7	8 6 8
8007020506 8007020517 8007020522 8007020523 8007020529	8007020500 8007020512 8007020518 8007020520 8007020525	80/06/18 80/06/18 80/06/17 80/06/26 80/06/26	71-5942 71-9016 71-381 50-366 8 50-528 8	8007030293 8007030290 80/07/01 50-289 8007030294 8007030291 80/07/02 70-2909 8007030295 8007030292 80/06/17 70-143 8007030296 8007030290 80/07/01 50-289 8007030297 8007030290 80/07/01 50-289	9 9
8007020532 8007020533 8007020539 8007020541 8007020545	8007020527 8007020531 8007020538 8007020538 8007020543	80/06/18 80/06/25 80/06/24 80/06/24 80/06/26	71-9015 50-528	B00703029B 6007030292 80/06/17 70-143 8007030297 6007030290 60/07/01 50-269 8007030301 6007030290 60/07/01 50-289 8007030302 8007030290 60/07/01 50-289 8007030303 8007030290 60/07/01 50-289	9 9
8007020547 8007020551 8007020553 8007020554 8007020574	8007020546 8007020544 8007020542 8007020550 8007020557	80/06/25 80/06/26 80/06/10 80/06/16 60/06/30	50-334 R 50-328 S CONTRACT 50-320 Q 50-255 P	8007030304 8007030270 80/07/01 50-287 8007030344 8007030334 80/06/12 CDNTRAC 8007030357 8007030353 80/06/12 CDNTRAC 8007030363 8007030358 80/06/02 40-8503 8007030364 8007030358 80/06/02 40-8503	2T
8007020581 8007020583 8007020588 8007020593 8007020593	8007020537 8007020484 8007020357 8007020557 8007020570	80/06/30 80/06/39 80/06/30 80/06/30	50-255 P 71-7022 50-255 P 50-255 P TDPREP	8007030370 8007030388 80/05/07 70-120: 8007030376 8007030375 80/06/13 71-903: 8007030378 8007030375 80/06/13 71-903: 8007030379 8007030375 80/06/13 71-903: 8007030381 8007030375 80/06/13 71-903:	? ? ?
8007020578 8007020579 8007020600 8007020603 8007020610	8007020592 8007020557 8007020557 8007020601 8007020607	80/06/30 80/06/30 80/06/30 80/06/13 80/06/26	50-338 P 50-255 P 50-255 P 50-414 S 50-307 G	8007030384 8007030375 80/06/13 71-903* 8007030385 8007030375 80/06/13 71-903* 8007030386 8007030375 80/06/13 71-903* 8007030387 8007030375 80/06/13 71-903* 8007030387 8007030389 80/06/13 70-33*	7
8007020611 8007020632 8007020642 8007020644 8007020647	8007020608 8007020630 8007020638 8007020641 8007020645	80/06/12 80/06/25 80/06/27 80/06/30 80/06/27	70-1308 50-416 B 50-321 G TOPREP 70-143	B007070005 B007070003 B0/05/07 70-2470 B007070006 B007070004 B0/06/16 XPCRTL B00707000B B007070004 B0/06/16 XPCRTL B007070016 B007070010 B0/06/19 70-143 B007070015 B007070010 B0/06/19 70-143	I C
8007020452 8007020454 8007020460 8007020474 8007020478	8007020450 8007020445 8007020445 8007020472 8007020475	80/06/04 80/06/27 80/06/27 80/06/11 80/06/10	71-381 70-143 70-143 COMISSION 50-498 A	8007070017 8007070010 80/06/19 70-143 8007070019 8007070010 80/06/19 70-143 8007070024 8007070023 80/06/12 XPORTL 8007070031 8007070026 80/06/19 50-514 8007070033 8007070026 80/06/19 50-514	LC
8007020585 8007020593 8007020712 8007020731 8007030011	8007020561 8007020688 8007020708 8007020730 8007030004	60/06/06 60/06/06 60/06/06 60/06/06 62/06/06	71-9130 30-281 H Habte Mgt Contract 70-2478	8007070036 8007070026 80/06/19 50-514 8007070039 8007070035 80/06/24 50-269 8007070040 8007070026 80/06/19 50-514 8007070044 8007070026 80/06/19 50-514 8007070045 8007070026 80/06/13 40-134	Ð
8007030016 8007030019 8007030020 8007030029 8007030029	8007030004 8007030013 8007030004 8007030022 8007030023	80/04/23 80/04/23 80/04/23 80/04/19 80/04/11	70-2478 80-856 H 70-2478 70-1151 50-466 G	8007070046 8007070026 80/06/19 50-514 8007070049 8007070026 80/06/19 50-514 8007070050 8007070026 80/06/19 50-514 8007070053 8007070026 80/06/19 50-514 8007070054 8007070052 80/06/18 CDNTRA	D D

ACCESS10					ACCEBS	ION MUHBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL	DATE	SUBJEC	
8007070055 8007070056 8007070056 8007070058 8007070060	8007070026 8007070051 8007070052 8007070052 8007070052	80/06/19 80/05/21 80/06/18 80/06/18 80/06/19	50-514 50-262 CONTRAC CONTRAC CONTRAC	Γ	B00708001 B00708001 800708001 800708001 800708001	4 8007080010 5 8007080013 6 8007080010 7 8007080013	80/07/03 80/06/30 80/07/03 80/06/30 80/07/03	50-443 50-466 50-443 50-466 50-443	I G I G
8007070061 8007070062 8007070064 8007070067 8007070074	8007070051 8007070052 8007070059 8007070059 8007070072	80/05/21 80/06/20 80/06/20 80/05/23	50-282 CONTRAC 50-280 50-280 50-10	T H H G	900708001 800708002 800708002 800708002 800708002	9007080010 8007080010 8007080010	80/07/03 80/07/03 80/07/03 80/07/03 80/07/03	50-443 50-443 50-443 50-443 50-443	I I I
8007070075 8007070079 8007070080 8007070097 8007070091	9007070059 8007070059 8007070072 8007070083 8007070083	80/05/23 80/05/23 80/05/23 80/05/23	50-260 50-260 50-10 50-462 50-462	H H G G	800708003 800708003 800708003 800708003 800708004	8007080010 8007080010 8007080010	80/07/03 80/07/03 80/07/03 80/07/03 80/07/03	50-443 50-443 50-443 50-443 50-443	1 1 1 1
8007070098 8007070100 8007070102 8007070103 8007070107	8007070095 8007070097 8007070097 8007070097 8007070097	80/06/17 80/06/24 80/06/24 80/06/24 80/06/24	50-341 50-335 50-735 50-335 50-335	9 9	800708005 800708006 800708008 800708008 800708015	8007080069 8007080081 8007080080	80/06/26 80/07/03 80/07/01 80/07/03 80/07/02	50-289 50-338 50-341 50-334 50-368	0 Р Р В
8007070130 8007070133 8007070134 8007070161 8007070162	8007070119 8007070128 8007070129 8007070157 8007070151	80/06/26 80/06/13 80/06/10 80/06/20 80/06/19	50-329 71-392 CONTRAC 50-284 50-320	T G H	800708016 800708017 800708017: 800708017: 800708017:	8007080164 8 8007080162 8 8007080164	80/06/27 80/06/26 80/06/26 80/06/26 80/06/27	50-368 50-336 50-265 50-336 50-368	9 P 8
8007070167 8007070176 8007070177 8007070180 8007070182	8007070165 6007070168 8007070177 8007070168 9007070177	00/05/19 80/06/30 80/06/06 90/06/30 80/06/06	50-389 50-348 71-9130 50-348 71-9130	QI R R	800708018: 800708019; 800708019; 900708020; 800708020;	9 8007080189 8007080196 9 8007080196	90/06/27 80/07/02 80/07/01 80/07/02 80/07/03	50-325 50-293 50-255 50-293 50-293	88888
8007070185 8007070190 8007070194 8007070195 8007070199	8007070177 8007070169 8007070168 8007070187 8007070168	80/06/06 80/06/30 80/06/30 80/06/24 80/06/30	71~9130 50-348 50-348 70-1113 50-348	R R	800708020; 800708020; 800708021; 800708021; 8007080221	8007080204 8007080211 8007080210	80/07/02 80/07/02 80/07/03 80/07/01 80/04/30	50-270 50-305 50-289 50-267 50-364	8 8 8 A
8007070204 8007070205 8007070208 8007070214 8007070217	8007070168 8007070153 8007070169 8007070168 8007070168	80/05/30 80/07/01 80/05/30 80/05/30 80/05/30	50-348 50-275 50-348 50-348 50-348	R A R R	8007080233 8007080233 8007080234 9007080245 8007080235	8007080222 8007080234 8007080222	80/06/30 80/06/30 80/07/03 80/06/30 80/06/30	50-364 50-364 50-382 50-364 50-364	A A B A A
8007070219 8007070223 8007070226 8007070228 8007070229	8007070169 8007070169 8007070168 8007070168 8007070224	80/07/02 80/06/30 80/06/30 80/06/30	50-349 50-349 50-348 50-349 50-260	R R R R	800708025 800708026 8007080275 8007080275 8007080276	8007080254 8007080268 8007080270	80/06/30 80/06/19 80/06/19 80/06/26 80/06/27	50-400 50-267 50-267 50-312 40-8056	8 8
8007070230 8007070232 8007070237 8007070254 8007070255	8007070168 8007070168 8007070234 8007070252 8007070252	80/05/30 80/05/30 80/05/27 80/07/01 80/07/01	50-348 50-348 50-325 50-331 50-331	R R S P	8007080280 8007080283 8007080295 8007080295 8007080293	8007080274 8007080283 8007080284	80/06/30 80/07/01 80/06/27 80/06/25 80/06/30	50-272 TOPREP 50-327 50-335 50-327	8 8
8007070256 8007070265 8007070270 8007070289 8007070307	8007070248 8007070259 8007070269 8007070285 8007070300	80/06/30 80/06/27 80/06/27 80/07/02	50-287 50-219 50-395 50-272 50-344	5 C P	8007080294 8007080297 800708030 800708030 800708030	8007080293 8007080295 8007080289	80/07/01 80/06/27 80/06/12 80/07/01 80/07/02	50-271 50-259 50-298 50-267 50-409	9 8 8
8007070313 8007070315 8007070322 8007070323 8007070324	8007070302 8007070310 8007070320 8007070319 8007070318	80/06/30 80/07/01 80/07/02 80/06/30 80/06/27	50-287 50-484 50-320 50-267 50-336	8 C P 5 B	8007080308 8007080327 8007080332 800708033 8007080341	8007080322 8007080313 8007080330	80/06/27 80/07/02 80/07/01 79/03/01 80/06/27	50-259 50-321 50-259 50-335 50-327	8 P 8
8007070335 8007070353 8007070354 8007070363 8007070365	0007070333 6007070337 8007070348 8007070358 6007070337	80/06/27 80/06/27 80/06/13 80/07/02 80/06/27	70-143 50-320 50-272 50-339 50-320	Q R B	8007080346 8007080335 8007080335 8007080357 8007080360	8007080349 8007080350 8007080349	80/07/01 80/06/18 80/07/02 80/06/18 80/06/18	50-155 PR 50-286 PR PR	R 8
8007070371 8007070372 8007070379 8007070381 8007070382	8007070337 8007070361 8007070374 8007070373 8007070378	80/06/27 80/06/27 80/07/02 80/07/03 80/06/25	50-320 50-336 50-339 50-338 50-293	0 8 8 8 9	8007080365 8007080365 8007080375 8007080384 8007080389	8007080345 8007080370 8007080381	80/07/02 80/06/16 80/06/30 80/06/27 80/07/02	50-284 50-298 50-260 50-301 50-305	8 8 8
8007070385 8007070388 8007070397 8007070397 8007070418	8007070375 8007070357 8007070389 8007070394 8007070414	80/06/25 80/07/01 80/07/01 80/06/21 80/06/18	50-285 50-293 50-280 50-348 CONTRACT	8 8 8	8007080392 8007080399 8007080402 8007080405 8007080410	8007080394 8007080400 8007080406	80/07/01 80/06/27 80/07/01 80/07/01 80/07/01	50-298 50-260 50-327 50-267 50-206	8 8 8
8007080003 8007090005 8007080004 8007080011 8007080012	8007080001 8007080004 8007080001 8007080010 8007080010	80/07/03 80/06/30 80/07/03 80/07/03 80/07/03	50-320 50-289 50-320 50-443 50-443	0 0 I I	8007080411 8007080416 8007080417 8007080420 8007080420		80/06/27 90/06/30 60/07/02 80/06/27 90/06/19	50-260 50-276 50-307 50-344 50-267	8 8 8 8

ACCESS 10N	NUMBER					ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		Ei	NCLOSURE	PRINCEPAL DOCUMENT	DATE CBSUED	SUBJECT CATEOURY	
8007080426 8007070006 8007070007 8007090010 8007090014	8007080423 8007090003 8007090005 8007090008 8007090013	80/07/01 80/07/01 80/06/13 80/07/02 80/06/20	50~272 50~259 50~259 50~255 50~346	5 5 F 0	9 9	007100072 007100074 007100076 007100081 007100089	900710000B 800710004B 800710000B 800710000B	80/06/27 80/06/04 80/06/27 80/06/27 80/06/05	70-143 70-143	9
8007090016 8007090017 8007090019 8007090021 8007090023	8007090013 8007090015 8007090015 8007090015 8007090015	80/06/20 80/06/03 80/06/03 80/06/03	50-346 SECY SECY SECY SECY	a	ପ ଅ	007100091 007100095 007100099 007100102 007100105	8007100088 0007100093 8007100095 8007100097 8007100097	80/06/16 80/06/20 80/06/03 80/05/29 80/05/29	50-546 50-206	0 0 1
8007070025 8007070030 8007090033 8007090038 8007090066	8007090015 8007090028 8007090028 8007090028 8007090061	80/06/03 80/05/16 80/05/16 80/05/16	SECY 10CFR 10CFR 10CFR 71-387		8: 8:	007100106 007100107 007100110 007100112 007100114	8007100103 8007100097 8007100103 8007100109 8007100107	80/66/13 92/60/08 11/60/08 11/60/08 11/60/08	50-206 50-286 CONTRACT	다 다 다
8007090103 8007090114 8007090148 8007090156 8007090159	8007070098 8007090104 8007090145 8007090154 8007090154	80/05/19 80/06/06 80/04/11 80/05/21 80/05/21	PR CBMM1551 PR 50-440 50-440	ОН О	8 8 8	007100115 007100118 007100121 007100124 007100131	800/100111 8007100111 8007100111 8007100119 8007100127	80/04/18 91/40/08 91/40/08 91/20/08	50-302 50-302 50-416	9 P Q G
8007090166 8007090167 8007090170 8007090178 8007090179	8007090163 8007090163 8007090165 8007090176 8007090176	80/06/30 80/06/30 80/06/24 80/05/21 80/05/21	NUREG NUREG 50-369 50-440 50-440	G G	84 84	007100136 007100139 007100141 007100147 007100131	8007100102 8007100132 8007100132 8007100142 8007100144	80/06/13 80/06/13 80/06/13 80/07/03 80/05/27	50-335 50-335 50-254	9 9 9 9
8007090186 8007090195 8007090201 8007090245 8007090258	8007090183 8007090192 8007090198 8007090243 8007090249	80/06/24 80/07/03 80/07/01 80/06/27 80/07/02	70-1257 50-333 TOPREP 50-322 50-327	R K S	89 84	007100154 007100158 007100159 007100182 007100184	B007100152 B007100150 B007100155 B007100150 B007100157	80/06/16 80/06/12 80/06/19 80/07/02	\$0-277 \$0-241	6 14 15 16 16 16 16 16 16 16 16 16 16 16 16 16
8007070270 8007070275 8007070274 8007070292 8007070278	8007090265 8007090265 8007090271 8007090289 8007090290	B0/07/02 B0/07/02 B0/07/01 B0/07/02 B0/06/30	50-352 50-352 50-249 50-316 50-466	8 P 6	89 84 81	007100165 007100166 007100168 007100172 007100176	8007100150 8007100163 8007100163 8007100167 8007100173	80/04/12 80/06/27 80/06/27 80/07/02 80/07/02	50-382 50-382 50-245	P K K 5
H007090304 9007090312 9007090319 9007090323 9007090324	8007070298 8007070308 8007070314 8007070317 8007070321	80/07/02 80/07/02 80/07/03 80/07/02 80/07/04	50-337 50-337 50-255 50-337 50-213	S 6 6 6	89 84 84	007100178 007100180 007100184 007100186 007100188	8007100175 8007100160 8007100160 8007100183 8007100160	80/06/25 80/07/07 80/07/07 80/06/25 80/07/07	PR PR	C P
8007070332 8007070334 8007070337 8007070338 8007070341	8007090324 8007090328 8007090330 8007090334 8007090324	80/06/26 80/07/03 80/06/27 80/07/02 80/06/26	50-317 50-368 50-361 50-334 50-317	P 5 5 P	8: 8: 9:	007100189 007100191 007100192 007100195 007100201	8007100179 8007100160 8007100187 8007100190 8007100199	80/07/02 80/07/07 80/07/02 80/07/01 80/07/03	PR 50-237 50-263	6 6 8
9007090342 9007090346 800709034B 8007090352 8007090353	8007090335 8007090324 8007090340 8007090324 8007090345	60/07/02 60/06/26 60/06/26 60/07/02	50-337 50-317 50-334 50-317 50-338	8 8 8	80 80 81	007100202 007100204 007100204 007100211 007100212	8007100197 8007100199 8007100203 8007100207 6007100210	80/07/02 80/07/03 80/06/19 80/05/28 80/06/24	50-255 50-312	ը թ թ
8007090359 8007090361 8007090368 8007090373 8007100003	8007070356 8007070324 8007070324 8007070370 8007100002	10/05/27 10/05/26 80/05/26 80/05/09 80/03/24	50-317 50-317 50-317 50-271 50-320	0 P 0	86 86 86	007100225 007100236	8007100209 8007100219 8007100223 8007100233 8007100233	80/07/02 80/07/03 80/06/17 80/06/30 80/04/21	TOPREP 50-267	5 a 8
8007100012 8007100014 8007100015 8007100020 8007100023	8007100009 8007100009 8007100008 8007100008 8007100008	80/01/09 80/01/09 80/06/27 80/06/27	50-320 50-320 70-143 70-143 70-143	() ()	80 80 81	007100247 007100248 007100271	8007100254 8007100261 8007100262 8007100263 8007100261	80/07/03 80/07/08 80/06/30 80/06/12 80/07/08	50-206 XPDRTLIC	K R
8007100026 8007100028 8007100032 8007100034 8007100037	8007100022 8007100008 8007100008 8007100827 8007100033	80/07/03 80/06/27 80/06/27 80/07/07 80/06/26	50-275 70-143 70-143 50-344 50-155	ç Ç	86 86 86	007100280 007100284 007100287	8007100273 8007100273 8007100281	80/0//07 80/07/07 80/07/07 80/06/03 80/07/07	50-280 50-280 XPORTLIC	P P P
8007100038 8007100041 8007100042 8007100044 8007100050	8007100008 8007100040 8007100033 8007100008 8007100047	80/06/27 80/06/24 80/06/26 80/06/27 80/07/07	70-143 71-6581 50-155 70-143 PR	G	98 90 80	007100291 007100293 007100298	8007100283 8007100273 8007100273	80/06/23 80/05/20 80/07/07 80/07/07 80/06/06	50-331 50-280 50-280	H Q P P
8007100052 8007100054 8007100057 8007100058 8007100060	8007100008 8007100047 8007100008 8007100051 8007100055	B0/06/27 B0/07/07 B0/06/27 B0/06/16 B0/05/29	70-143 PR 70-143 50-344 50-251	G G	86 86	007100301 007100303 007100303 007100307 007100308	8007100297 8007100273 8007100297 8007100294 8007100295	80/04/16 80/07/07 80/04/16 80/06/66 80/06/26	50-280 50-400 50-255	0 P O P
B007100061 B007100062 B007100066 B007100067	8007100059 8007100051 8007100064 8007100008 8007100068	80/05/29 80/06/16 80/05/29 80/06/27 80/06/04	50-335 50-344 50-321 70-143 50-273	Q Q Q	94 94 95	007100307 007100310 007100311 007100312 007100313	80071002/3 8007100294 8007100273 8007100304 8007100297	80/07/0/ 80/06/06 80/06/0/ 80/06/10 80/06/16	50-255 50-280 CONTRACT	P P P

	NUMBER				ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1SSUED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 186UED	SUBJECT	łΥ
8007100315 8007100321 8007100323 8007100329 8007100330	8007100273 8007100273 8007100273 8007100273 8007100326	80/07/07 80/07/07 80/07/07 80/07/07 80/06/05	30-280 30-280 30-280 50-280 GA999	9 9 9	8007110040 8007110042 8007110045 8007110046 8007110070	8007110009 8007110009 8007110061 8007110009 8007110061	80/06/23 80/06/23 80/05/21 80/06/23 80/05/21	50-320 50-320 50-382 50-320 50-382	
8007100333 8007100334 8007100335 8007100336 8007100338	8007100326 8007100327 8007100273 8007100326 8007100273	80/06/05 80/04/16 80/07/07 80/06/05 80/07/07	QA999 FO1A 50-280 GA999 50-280	P P	8007110072 8007110076 9007110079 8007110084 8007110089	8007110009 8007110061 8007110009 8007110009 8007110009	80/06/23 80/05/21 80/06/23 80/06/23	50-320 50-382 50-320 50-320	, C C C D C
8007100339 8007100346 8007100347 8007100351 8007100353	8007100326 8007100342 6007100273 6007100273 8007100349	80/06/05 80/05/23 80/07/07 80/07/07 80/06/17	9A999 50-498 50-280 50-280 71-389	G P P	8007110091 80070093 800711009 8007110096 8007110098	8007110007 8007110082 8007110007 8007110086 8007110007	80/06/23 80/06/23 80/06/20 80/06/23	50-320 50-271 50-320 50-285 50-320	CDCIC
8007100359 8007100365 8007100367 8007100368 8007100370	8007100273 8007100273 8007100356 8007100361 8007100362	80/07/07 80/07/07 80/06/24 80/06/18 80/04/30	50-280 50-280 50-324 CONTRAC 70-1151		8007110103 8007110107 8007110113 8007110125 8007110128	8007110009 8007110009 8007110102 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-320 50-335 50-320 50-320	1000
8007100371 8007100374 8007100375 8007100376 8007100377	8007100273 8007100362 8007100273 8007100373 8007100356	80/07/07 80/04/30 80/07/07 80/06/16 80/06/24	50-280 70-1151 50-280 71-9053 50-324	P P Q	8007110132 8007110135 8007110134 8007110140 8007110143	8007110009 8007110009 8007110131 8007110009 8007110009	80/06/23 80/06/23 80/06/23	50-320 50-320 50-254 50-320 50-320	50000
8007100380 8007100381 8007100382 8007100384 8007100387	8007100373 8007100352 8007100273 8007100356 8007100273	80/07/07 80/04/30 80/07/07 80/06/24 80/07/07	50-280 70-1151 50-280 50-324 50-280	Р О Р	8007110145 8007110147 8007110151 8007110156 8007110158	8007110131 8007110009 8007110009 8007110009 8007110153	02\60\08 E2\40\08 E2\40\08 E2\40\08	50-254 50-320 50-320 50-320 50-441	97779
8007100391 8007100395 8007100397 8007100398 8007100401	8007100273 8007100354 8007100390 8007100354 8007100394	80/07/07 80/06/24 80/04/30 80/06/24 80/06/02	50-280 50-324 70-1201 50-324 50-219	e G P	8007110140 8007110146 8007110146 8007110148 8007110173	8007110007 8007110141 8007110009 8007110153 8007110009	80/06/23 80/06/23 80/05/20 80/05/23	50-320 71-7009 50-320 50-461 50-320	7
8007100403 8007100404 8007100405 8007100407 8007100408	8007100273 8007100390 8007100394 8007100273 8007100394	80/07/07 80/04/30 80/06/02 80/07/07 80/06/02	50~280 70~1201 50~219 50~219	9 9 9	8007110176 8007110178 8007110179 8007110184 8007110192	8007110009 8007110009 8007110174 8007110174 8007110187	80/06/23 80/06/23 80/05/23 80/05/23	50-320 50-320 50-206 50-206 50-482	0000
8007100407 8007100410 8007100413 8007100414 8007100415	8007100273 8007100390 8007100334 8007100273 8007100273	80/07/07 80/04/30 80/06/24 80/07/07 80/07/07	50-280 70-1201 50-324 50-280 50-280	9 9 9	8007110193 8007110194 8007110196 8007110196 8007110201	8007110189 8007110189 8007110189 8007110187 8007110009	80/07/07 80/07/07 80/07/07 80/05/23 80/06/23	50-280 50-280 50-280 50-482 50-320	00000
800710041B 8007100419 8007100420 8007100422 8007100423	8007100412 8007100417 8007100399 8007100412 8007100417	80/06/23 80/06/23 80/06/23 80/06/23	50-400 50-413 50-10 50-400 50-413	0 0 P 0	8007110203 8007110206 8007110207 8007110208 8007110209	8007110195 8007110200 8007110195 8007110009 8007110204	80/06/04 80/06/19 80/06/04 80/06/23 80/07/07	NUREO 50-10 NUREG 50-320 50-155	G J P
8007100426 8007100428 8007100430 8007100432 8007100435	8007100417 8007100412 8007100412 8007100417 8007100412	80\09\53 80\09\53 80\09\53 80\09\53	50-413 50-400 50-400 50-413 50-400	@ @ @ @	8007110210 8007110212 8007110217 8007110220 8007110222	8007110204 8007110009 8007110009 8007110214 8007110009	80/07/07 80/06/23 80/06/23 80/06/20 80/06/23	50-155 50-320 50-320 50-346 50-320	上 つ ン の つ
8007100438 8007100444 8007100442 8007110007 8007110012	8006300220 8007100445 8007100461 8007110004 8007110010	80/06/20 80/06/03 80/06/16 80/06/27 80/06/09	50-320 40-8502 71-9094 70-143 XPORTLIC	Н	8007110224 8007110231 8007110233 8007110234 8007110239	8007110009 8007110225 8007110228 8007110229 8007110225	80/04/23 79/10/08 80/04/19 80/05/23 79/10/08	50-320 PR 50-461 50-445 PR	0 0
8007110015 8007110016 8007110017 8007110020 8007110022	8007110009 8007110014 8007110009 8007110009 8007110009	80/06/23 80/06/23 80/06/23	70-1333 71-221 50-320 70-1333 70-1333	J	8007110246 8007110248 800711025 8007110257 8007110262	8007110242 8007110243 8007110247 8007110250 8007110250	80/04/17 80/05/14 80/06/06 80/06/23 80/06/23	FDIA TOPREP 50-255 50-321	Р G
8007110023 8007110024 8007110027 6007110028 8007110030	8007110009 8007110009 8007110025 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	70-1333 70-1333 40-2061 50-289 50-289	7	8007110264 8007110268 8007110276 8007110276 8007110278	8007110247 8007110250 8007110265 8007110250 8007110266	80/06/12 80/06/23 80/06/23 80/06/04	50-255 50-321 71-4375 50-321 COMMISSI	P G G ON
8007110032 8007110036 8007110037 8007110039 8007110040	8007110009 8007110033 8007110009 8007110034 8007110009	BO/06/23 BO/06/13 BO/06/23 BO/06/24	50-320 50-275 50-320 50-327 50-320	JEJGJ	8007110280 8007110282 8007110283 8007110283 8007110270	8007110272 8007110266 8007110275 8007110272 8007110281	80/06/24 80/06/12 80/06/12 80/06/24 80/06/27	50-320 COMMISSIC XPORTLIC 50-320 71-5450	
8007110046 8007110049 8007110051 8007110052 8007110057	6007110009 8007110044 8007110009 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-263 50-320 50-320 50-320	10111	80071 10292 80071 10296 80071 10296 80071 10301 80071 10313	8007110272 8007110266 8007110266 8007110297 8007110304	80/06/24 80/06/12 80/06/12 80/07/07 80/07/01	20-321 20-522 20-522 20-320	

ACCESSION NUMBER			ACCESSION NUMBER	
PRINCIPAL DOCUMEN	ISSUED	SUBJECT CATEGORY	PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	SUBJECT CATEGORY
B007110314 B0071103 B007110322 B0071103 B007110323 B0071103 B007110323 B0071103 B007110327 B0071103	21 80/06/27 21 80/06/27 17 80/07/02	50~335 H M15C M16C 50-305 B M16C	8007140046 8007140036 80/07/04 8007140048 8007140033 80/06/12 8007140047 8007140045 80/07/03 8007140051 8007140036 80/07/04	PR QA999 PR PR SECY
800711032B 80071103 B007110331 80071103 B007110340 80071103 B007110343 80071103 B007110349 80071103	74 80/07/07 33 80/07/03 38 80/06/30	50-518 S 50-269 P 50-266 S 50-352 U 50-301 S	8007140064 8007140058 80/06/25 8007140066 8007140060 80/06/13	50-320 U GA999 70-143 50-320 G 70-143
8007110357 80071103 8007110362 80071103 8007110345 80071103 8007110373 80071103 8007110376 80071103	60 BQ/07/03 64 BQ/07/09 70 BQ/07/01	50-301 S 50-269 S 50-339 P 50-219 S 50-327 S	8007140068 8007140065 80/06/26 8007140071 8007140060 80/06/13 8007140073 8007140056 80/06/25 8007140075 8007140074 80/06/11 8007140079 8007140074 80/06/18	10LFR 50-320 0 70-143 GA999 10CFR
8007110380 80071103 8007110382 80071103 8007110383 80071103 8007110387 80071103	77 B0/06/24 75 80/07/01 77 B0/04/24	50-296 5 COMMISSION 50-219 S COMMISSION 50-309 R	8007140086 8007140078 80 <i>/06/2</i> 4 8007140087 8007140057 80 <i>/06/</i> 11 8007140088 8007140057 80 <i>/06/</i> 11	GA999 70-143 GA999 GA999 50-397 (}
8007110392 80071103 8007110394 80071103 8007110395 80071103 8007110397 80071104	88 80/07/03 77 80/06/24 71 80/07/03	COMMISSION 50-296 B COMMISSION 50-346 B 50-321 B	B007140108 B007140106 B0/06/19 B007140118 B007140115 B0/06/07 B007140122 B007140121 79/07/02	50-397 G 50-437 H 50-277 H 66CY 50-284 P
8007110404 80071103 8007110406 80071104 8007110410 80071104 8007110414 80071104 8007110416 80071104	05 80/07/03 02 80/07/07 09 80/07/03	50-247 5 50-224 R 50-302 5 50-255 R 50-346 B	8007140135 8007140121 79/07/02 8007140139 8007140121 79/07/02	SECY SECY 50-259 Q 50-259 Q
B007110417 B0071104 B007110419 B0071104 B007110423 B0071104 B007110424 B0071104 B007110434 B0071104	1 80/07/03 8 80/07/03 5 80/07/03	50-416 S 50-331 S 50-346 S 50-321 S 50-346 S	8007140179 8007140182 80/07/08 8007140190 8007140182 80/06/12 8007140192 8007140184 80/06/25	50-280 G 50-387 S 50-247 P 50-282 G CONTRACT
8007110437 80071104 8007110442 80071104 8007110443 80071104 8007110446 80071104 8007110450 80071104	92 80/07/01 89 80/06/23 90 80/07/03	50-366 S 50-321 S NUREO 50-346 S 50-272 Q	8007140220 8007140212 80/06/26 8007140225 8007140209 80/07/07 8007140227 8007140221 80/06/26	50-528 S FGIA 50-339 8 50-409 H 50-10 H
8007110457 80071104 8007110457 80071104 8007110461 80071104 8007110462 80071104 8007110463 80071104	80/06/16 80/06/23 80/06/16	WASTE MGT WASTE MGT 71-6078 WASTE MGT 50-021	8007140265 8007140256 80/06/11 8007140274 8007140266 80/06/30 8007140288 8007140283 80/06/27	50-280 S 50-346 M XPORTLIC XPORTLIC FOIA
B00711046B B00711046 B007110474 B00711044 B007110475 B00711047 B007110479 B00711047 B007110482 B00711047	6 90/07/02 3 80/06/23 7 80/05/27	71-9130 50-245 8 71-5926 50-358 0 50-331 8	8007140302 8007140277 80706/26 8007140315 8007140312 80707708 8007140322 8007140318 807077708	FOIA FOIA 50-344 R 50-346 R 50-454 K
8007110485 80071104 8007110487 80071104 8007110493 80071104 8007110495 80071104 8007110498 80071104	84 80/06/20 8 80/06/26 8 80/06/20	50-320 P BECY 50-320 P BECY	8007140342 8007140338 80/07/09 8007140353 800/140349 80/07/03	50-275 R 50-528 8 50-27 P 50-518 8 50-335 S
8007110501 80071104 8007110503 800711046 8007110518 80071105 8007110521 80071105 8007110527 80071105	4 80/06/20 3 80/06/23 5 80/06/24	50-320 P BECY 70-925 50-424 Q 50-424 Q	8007140374 8007140348 80/07/07 8007140377 8007140349 80/07/11 8007140378 8007140370 80/07/09	TOPREP 50-333 8 50-358 K 50-452 9 TOPREP
8007110531 80071105 8007110534 80071105 8007110539 80071105 8007110552 80071105 8007110543 80071105	5 B0/06/24 5 B0/06/20 6 B0/06/23	50-424 Q 50-424 G CONTRACT 50-482 U 50-155 Q	8007140389 8007140382 80/06/29 8007140394 8007140383 80/07/07 8007140398 8007140392 80/07/08	40-279 50-335 6 50-333 8 50-3 P 50-324 8
8007110544 80071105 8007110548 80071105 8007110571 80071105 8007110575 80071105 8007140007 800714000	5 B0\09\53 9 B0\09\53	50-482 U 50-482 U 50-482 U CDNTRACT 50-369 G	8007140405 8007140492 80/07/07 8007140408 8007140402 80/07/10 8007140411 8007140405 80/07/11	50-338 P 50-348 8 PR 50-339 P TOPREP
8007140009 800714000 8007140010 800714001 8007140014 800714001 8007140022 800714001 8007140034 800714003	4 80/07/09 1 80/07/03 8 80/07/07	50-287 G 50-369 G PR 50-289 G 50-361 G	8007140420 8007140407 80/04/16 8007140427 8007140422 80/07/03 8007140428 8007140424 80/07/09	PR TOPREP 50-370 S 50-155 G PR
8007140037 800714003 8007140039 800714003 8007140040 800714003 8007140041 800714003 8007140042 900714003	3 80/06/12 6 80/07/04 5 80/06/03	94979 94979 PR 70-8 94999	B007140442 8007140434 80/07/03 B007140447 8007140436 80/05/28	50-382 Q 50-331 P 50-382 Q PR 50-331 P

ACCESS10					ACCESSIO				
ENCLOSURE	PRINCIPAL DDGUMENT	DATE 15SUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1850ED	SUBJECT CATEGOR	
8007140456 8007140471 8007140473 8007140481 8007140486	8007140443 8007140464 8007140461 8007140470 8007140480	80/07/07 80/06/17 80/04/28 80/06/25 80/06/24	50~328 50~346 50~269 50~341 50~298	5 0 0	8007130107 8007130108 8007150118 8007150120 8007150124	8007150087 8007150102 8007150113 8007150106 8007150106	80/06/24 80/06/30 80/06/06 80/07/02 80/07/02	50-261 50-358 50-454 50-344 50-344	0 0 0 0
8007140499 8007140492 8007140493 8007140494 8007140502	8007140461 8007140460 8007140485 8007140487 8007140497	80/04/28 80/05/24 80/05/27 80/05/30 80/06/19	50-269 50-298 50-155 50-263 50-445	0 0 0	8007150126 8007150130 8007150135 8007150141	8007150106 8007150106 8007150128 8007150125 8007150128	80/07/02 80/07/02 80/06/19 80/06/04 80/06/19	50-344 50-344 70-364 50-298 70-364	Q Q
8007140504 8007140505 8007140507 8007140514 8007140521	8007140491 8007140500 8007140500 8007140500 8007140512	80/07/10 80/06/26 80/06/26 90/06/26 80/07/03	FD1A 50~254 50~254 50~254 CONTRACT	р Р	800715014B 8007150150 8007150155 8007150163 8007150167	8007150128 8007150128 8007150128 8007150128 8007150145	80/06/19 80/06/19 80/06/19 80/06/19 80/06/04	70-364 70-364 70-364 70-364 50-285	a
8007140526 8007140527 8007140540 8007140541 8007140546	8007140522 8007140513 8007140531 8007140522 8007140539	80/05/19 80/05/16 80/06/06 80/05/19 80/06/20	50-483 70-143 ACRS 50-483 SECY	o o	8007150318 8007150325 8007150332 8007150452 8007150466	8007150314 8007150314 8007150314 8007150447 8007150455	80/04/10 80/04/10 80/04/10 80/06/05 80/07/07	70-2651 70-2651 70-2651 50-566 50-327	9
8007140555 8007140558 8007140560 8007140578 8007140607	8007140548 8007140548 8007140552 8007140572 8007140600	80/05/25 80/05/27 80/05/18 80/07/01 80/05/13	50-297 50-346 SECY REGGD 40-8502	G G	8007130468 8007130471 8007130488 8007150494 8007150501	8007150462 8007150462 8007150470 8007150489 8007150491	80/06/20 80/06/20 80/07/08 80/06/26 80/07/10	50-280 50-280 50-327 50-313 50-327	0 9 9 9
8007140408 8007140609 8007140614 8007140618 8007140620	B007140604 B007140604 B007140605 B007140605 B007140613	80/05/21 80/05/21 80/07/01 80/07/01 80/06/20	27-48 27-48 50-325 50-325 71-4294	P P	8007150502 8007150503 8007150506 8007150508 8007150508	8007150499 8007150495 8007150495 8007150496 8007150495	80/07/08 80/04/25 80/04/25 80/07/08 80/06/25	50-320 50-302 50-321 50-302	r 0 8 0
8007140624 8007140625 8007140628 8007140629 8007140631	8007140605 8007140616 8007140623 8007140616 8007140627	80/07/01 80/07/02 80/04/13 80/07/02 80/05/21	50-325 50-320 50-244 50-320 40-8702	Р Н Р	B007150511 8007150512 8007150514 8007150517 8007150517	8007150495 8007150504 8007150513 8007150516 8007150515	80/06/25 80/07/07 80/07/09 80/07/07 80/07/09	50-302 50-327 50-320 50-272 50-320	8 8
8007140632 8007140633 8007140636 8007140637 8007140643	8007140623 8007140626 8007140623 8007140630 8007140639	80/06/13 80/06/13 80/06/13 80/06/19	50-244 CONTRACT 50-244 TOPREP TOPREP	P	8007 i 90920 8007 i 50522 8007 i 50532 8007 i 50533 8007 i 50533	8007150518 8007150521 8007150532 8007150529 8007150530	80/07/09 80/07/09 80/07/07 80/07/08 80/07/11	70-143 50-327 50-335 50-373 50-313	р В А 8
8007140648 8007140649 8007140654 8007140656 8007140657	8007140544 8007140646 8007140646 8007140645 8007140653	80/05/21 80/07/02 80/07/02 80/07/09 80/05/21	70-135 71-4387 71-6387 FOTA 40-2940		B007150544 8007150547 8007150555 8007150561	8007150539 8007150542 8007150527 8007150555 8007150559	80/07/03 80/07/09 80/07/11 80/07/09 80/07/10	50-321 50-315 50-312 50-316 50-106	8 R Q R W
800714068B 8007140662 8007140663 8007140666 8007140668	B007140646 B007140646 B007140653 B007140646 B007140646	80/07/02 80/07/02 80/05/21 80/07/02 80/07/02	71-6387 71-6387 40-2940 71-6387 71-6387		8007150526 8007150373 8007150374 8007150378 80071503582	8007150560 8007150568 8007150570 8007150571 8007150571	80/07/10 80/07/07 80/07/10 80/07/11 80/07/11	50-346 50-133 50-259 50-327 50-327	8 8 P
8007140670 8007140673 8007140678 8007140682 8007140687	8007140453 8007140444 8007140444 8007140475 8007140444	80/05/21 80/07/02 80/07/02 80/07/02 80/07/02	40-2940 71-4397 71-6387 70-1193 71-4387		8007150383 8007150583 8007150587 8007150592 8007150592	8007150575 8007150580 8007150577 8007150584 8007150588	80/07/11 80/07/09 80/07/09 80/07/09 80/07/07	50-267 50-327 50-206 50-244 50-312	P 8 8 8
8007140490 8007140702 8007140709 8007150006 8007150009	8007140646 8007140698 8007140704 8007150002 8007150007	90/07/02 90/07/01 90/07/01 90/06/30 90/06/30	71-6387 71-346 71-5 50-483 50-498	a 0	8007150597 8007150603 8007150604 8007150605 8007150614	8007130384 8007130373 8007130376 8007130379 8007130611	80/07/08 80/07/10 80/07/10 80/07/08 80/07/09	50-315 50-313 50-272 50-206 50-263	8 8 8 8
8007150010 8007150019 8007150021 8007150023 8007150031	8007150002 8007150015 8007150015 8007150017 8007150027	80/06/30 80/06/23 80/06/23 80/06/04 80/06/17	50-483 50-269 50-269 50-483 70-1113	0 0 0	8007150618 8007150620 8007150623 8007150625 8007150626	8007150610 8007150615 8007150586 8007150617 8007150621	80/07/10 80/07/08 80/07/08 80/07/01 80/07/08	50~266 50~326 50~315 50~254 50~272	R R R
		7,	70-1113 50-184 50-184 113 TLIC	P P	8007150633 8007150634 8007150642 8007150645 8007150651	8007150429 8007150427 8007150435 8007150441 8007150444	80/07/10 80/07/03 80/07/03 80/07/07 80/06/16	50-241 50-335 50-364 50-313 40-8502	8 8
				Þ	B007150652 8007150655 8007150657 9007150660 9007150663	8007150646 8007150646 8007150644 8007150647 8007150657	80/06/16 80/06/16 80/06/16 80/07/09 80/07/11	TOPREP TOPREP 40-8502 50-368 50-566	8
					B007150445 B007150467 B007150648 B007150474 B007150479	8007150454 8007150444 8007150462 8007150466 8007150472	90/07/11 90/06/16 80/07/11 80/07/08 80/07/08	50-325 40-8502 50-348 50-321 50-272	8 R 8

ACCESSIO					ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 159UED	SUDJECT CATEGOR	Υ
8007150685 8007150693 8007150695 8007150701 8007150703	80071506/8 8007150683 8007150684 8007150686	80/07/07 80/07/09 80/07/08 80/07/07 80/07/10	50-346 50-346 50-316 50-338 50-315	8 8 8 8	8007140451 8007140454 8007140455 8007140458 8007140462	8007160626 8007160647 8007160650 8007160652 8007160655	80/07/08 80/07/09 80/07/07 80/07/09 80/07/07	50+461 50-334 50-438 50-528 50-275	១ ១ ១
8007150704 8007150712 8007150713 8007150715 8007150777	8007150699 8007150705 8007150708 8007150707 8007150767	80/07/08 80/07/08 80/07/09 80/07/10 80/07/10	50-293 50-219 50-302 50-333 50-338	R R R S	8007160663 8007160663 8007160673 8007160677 8007160690	8007160626 8007160626 8007160668 8007160626	80/07/07 80/07/08 80/06/27 80/07/08 80/07/09	50-369 50-461 50-304 50-461 50-245	មិល ជា បា ភ
8007150778 8007150804 8007150814 8007150815 8007150817	8007150770 8007150803 8007150809 8007150808 8007150810	80/06/12 80/07/09 80/05/09 80/07/07 80/07/07	DRG 50-255 70-364 50-339 50-339	G S	8007160681 8007160694 8007160698 8007160703 8007160707	8007160677 8007160687 8007160692 8007160687 8007160687	80/07/08 80/07/08 80/07/08 80/07/08 80/07/08	30-409 50-341 50-274 50-341 50-341	RAFAA
8007150826 8007160109 8007160115 8007160121 8007160126	8007150820 8007160096 8007160096 8007160096 8007160096	80/07/09 80/06/17 80/06/17 80/06/17 80/06/17	50-344 GA999 GA999 GA999 GA999	ន	8007160710 8007160721 8007160727 8007160724 8007160741	8007160700 8007160700 8007160718 8007160725 8007160725	80/06/27 80/06/27 80/06/27 80/06/04 80/06/04	40-7982 40-7982 70-1113 50-440 50-440	9
8007160146 8007160157 8007160171 8007160188 8007160193	8007160133 8007160150 8007160161 8007160177	80/05/01 80/05/14 80/05/19 80/06/17 80/06/17	GA999 GA999 GA999 GA999 GA999		80071 60742 80071 60755 80071 60756 80071 60764	8007160732 8007160743 8007160751 8007160745 8007160751	80/06/05 80/06/16 80/06/11 80/07/01 80/06/11	50-0 1B TOPREP 50-461 50-038 50-461	9 9 9
8007160202 8007160207 8007160227 8007160317 8007160335	8007160177 8007160177 8007160208 8007160310 8007160322	80/06/17 80/06/17 80/07/02 80/07/01 80/07/01	GA999 GA999 CONTRACT 71-391 71-389		8007160765 8007160772 8007160810 8007160814 8007160817	8007160743 8007160767 8007160797 8007160805 8007160797	80/06/16 80/07/07 80/06/30 80/06/19	TOPREP 71-392 50-335 REGOD 50-335	Q Q
8007160347 8007160372 8007160376 8007160379 8007160387	8007160343 8007160365 8007160365 8007160365 8007160381	80/07/01 80/06/27 80/06/27 80/06/27 80/07/07	71-393 50-344 50-344 50-344 71-4888	P P	8007160826 8007160830 8007160833 8007160851 8007160858	8007160797 8007160797 8007160838 8007160848 8007160854	80/06/30 80/06/30 80/06/27 80/06/04 80/06/04	50-335 50-335 70-143 CDMM15810 COMM15810	
8007160395 8007160397 8007160399 8007160404 8007160408	8007160392 8007160393 8007160394 8007160393 8007160393	80/07/07 80/06/18 80/07/01 80/06/18 80/06/18	50-275 GA999 XPDRTLIC GA999 GA999	A	8007160862 8007160864 8007160867 8007160867 8007160870	8007160860 8007160860 8007160863 8007160860 8007160860	80/07/01 80/07/01 80/06/29 80/07/01 80/07/01	50-416 50-416 50-322 50-416 50-416	0 0 0
8007160411 8007160412 8007160425 8007160427 8007160434	B007160393 B007160409 B007160421 B007160421 B007160429	80/06/18 80/07/07 80/06/02 80/06/02 80/06/12	GA999 71-4986 50-29 50-29 50-269	P P	8007140872 8007170051 8007170071 8007170071 8007170088	8007160860 8007170049 8007170049 8007170066 8007170084	80/07/01 80/07/02 80/07/02 80/06/16 80/06/12		9 H H P P
8007160445 8007160453 8007160463 8007160474 8007160478	8007160429 8007160429 8007160459 8007160464 8007160471	80/06/12 80/06/12 80/06/19 80/07/07 80/07/11	50-269 50-269 50-10 50-305 50-327	6 6 6 6	8007170097 8007170098 8007170103 8007170118 8007170127	8007170093 8007170094 8007170094 8007170113 8007170122	80/07/07 80/05/29 80/05/29 80/07/09 80/07/08	71-5341 90-373 90-373 71-5862 CONTRACT	G G
8007160479 8007160484 8007160496 8007160498 8007160502	8007160469 8007160471 8007160490 8007160490 8007160485	80/06/10 80/07/11 80/06/19 80/06/19 80/07/11	50-546 50-327 CDNTRACT CONTRACT 50-305	0 P	8007170145 8007170161 8007170171 8007170172 8007170183	8007170135 8007170157 8007170159 8007170167 8007170175	80/07/10 80/07/08 80/07/08 80/06/09 80/07/14	TOARTHOO TOARTHOO 444-0E TOARTHOO 9EF-0E	G P
8007160504 8007160510 8007160513 8007160518 8007160521	8007140490 8007140485 8007140490 8007140514 8007140520	80/06/19 80/07/11 80/06/19 80/07/11 80/07/10	CONTRACT 50-305 CONTRACT 50-413 50-275	8 8 A	8007170189 8007170194 8007170210 8007170220 8007170221	8007170175 8007170186 8007170212 8007170215 8007170219	B0/07/14 B0/06/30 B0/06/30 B0/07/15 B0/06/02	50-339 50-306 CONTRACT 70-1308 50-327	e G C
8007160523 8007160525 8007160526 8007160548 8007160551	8007160517 8007160522 8007160524 8007160544 8007160546	80/07/11 80/06/30 80/07/11 80/07/09 80/07/08	50~327 50~320 50~289 50~305 50~530	5 5 8 8	8007170222 8007170224 8007170251 8007170255 8007170258	B007170217 B007170219 B007170244 B007170249 B007170244	80/06/26 80/06/02 80/07/01 80/06/03 80/07/01	CONTRACT 50-327 SELY 50-387 BLCY	0
8007160556 8007160562 8007160564 8007160565 8007160566	8007160552 8007160558 8007160555 8007160559 8007160559	80/07/10 80/07/11 80/07/09 80/07/08 80/07/03	50-259 50-282 50-334 50-466 50-454	R R P G K	8007170262 8007170266 8007170270 8007170271 8007170274	8007170255 8007170264 8007170265 8007170264 8007170268	80/06/26 80/06/02 80/05/20 80/06/02 80/05/30	XPORTLIC 50-219 50-528 50-219 50-354	0 0 0
8007160369 8007160374 8007160378 8007160409 8007160617	8007160559 8007160559 8007160571 8007160604 8007160610	80/07/03 80/07/03 80/06/18 90/07/11	50~454 50~454 50~328 50~498 50~416	К 5 В А	6007176276 8007170277 8007170286 8007170286 8007170288	8007170264 8007170254 8007170281 8007170264 8007170263	80/05/02 80/07/02 80/05/02 80/05/30	50-219 State Pro 50-313 50-219 50-JP2	G F G d
B007160623 B007160633 B007160638 B007160649	8007160618 8007160628 8007160626 8007160641 8007160634	80/07/11 80/07/07 80/07/08 80/07/03 80/07/09	50-289 50-311 50-441 50-293 50-329	8 P S S H	8007170292 8007170294 8007170297 8007170297 8007170298	8007170264 8007170290 8007170289 8007170291 8007170264	\$0/06/02 \$0/07/11 \$0/06/10 \$0/06/09	FOIA 50-416 100FR 40-8602 FOIA	8

ACCESSIO	N NUMBER				ACCES	SION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSUR	PRINCIPAL E DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8007170302 8007170304 8007170305 8007170306 8007170308	8007170291 8007170264 8007170300 8007170264 8007170291	80/06/10 80/06/02 80/06/16 80/06/02 80/06/10	40-8602 FDIA 70-925 FDIA 40-8602		80071704 80071704 80071704 80071704 80071704	92 8007170442 93 8007170472 96 8007170442 90 8007170442	80/07/09 80/06/30 80/07/09 80/07/09 80/07/09	50-344 50-320 50-320	PPPPS
8007170310 8007170314 8007170317 8007170318 8007170322	9007170300 8007170264 8007170313 8007170264 8007170264	80/06/16 80/06/02 80/07/02 80/06/02 80/06/02	70-925 F01A 50-482 F01A 70-1869	A	80071704 80071704 80071705 80071705 80071705	99 8007170442 02 8007170442 03 8007170494	80/07/08 80/07/09 80/07/09 80/07/01 80/07/09	50-320 50-320 50-327	8 P P
8007170324 8007170326 8007170328 8007170329 8007170330	8007170264 8007170264 8007170264 8007170327 8007170323	80/05/02 80/05/02 80/05/11 80/05/11	70-1869 FDIA FDIA 40-8681 50-10	G	80071705 80071705 80071705 80071705 80071705	11 8007170442 17 8007170496 21 8007170442	80/07/01 80/07/09 80/07/01 80/07/09 80/07/11	50-320 50-327 50-320	P P P P
8007170331 8007170332 8007170333 8007170335 8007170334	8007170327 8007170327 8007170323 8007170327 8007170323	80/06/11 80/06/11 80/06/19 80/06/11 80/06/19	40-8681 40-8681 50-10 40-8681 50-10	G G	80071705 80071705 80071705 80071705 80071705	34 8007170523 35 8007170442 39 8007170530	80/07/09 80/07/01 80/07/09 80/05/20 80/07/02	20-391 20-350 20-350	P Q Q
8007170337 8007170340 8007170341 8007170344 8007170345	8007170264 8007170339 8007170264 8007170342 8007170264	80/06/02 80/07/08 80/06/02 80/07/10 80/06/02	70-1869 50-320 70-1869 50-566 70-1869	p S	80071705 80071705 80071705 80071705 80071705	56 8007170545 65 8007170561 66 8007170560	80/06/10 80/06/10 80/07/01 80/07/14 80/06/19	50-315 50-206 50-260	0 0 0 0
8007170347 8007170349 8007170350 8007170351 8007170353	8007170339 8007170264 800717034B 8007170339 8007170352	80/07/03 80/06/02 80/07/15 80/07/03 80/07/14	50-322 70-1869 50-280 50-322 50-317	A V A P	80071705 80071705 80071705 80071705 80071703	69 8007170561 73 8007170561 74 8007170560	80/07/01 80/07/01 80/07/01 80/07/14 80/07/01	50-206 50-206 50-260	R G D G
8007170355 8007170358 8007170359 8007170361 8007170365	B007170354 B007170356 B007170357 B007170360 B007170363	80/07/15 80/07/10 80/07/07 80/07/11 80/06/30	50-155 50-546 50-320 50-220 50-3	G G R R	80071703 80071703 80071703 80071703 80071704	85 8007170577 76 8007170589 99 8007170593	80/05/19 80/07/11 80/06/12 80/05/22 80/07/03	50-440 (50-443 (0 8 8 0
8007170367 8007170371 8007170379 8007170387 8007170391	8007170366 8007170369 8007170376 8007170382 8007170389	80/06/26 80/07/15 80/07/09 80/07/08 80/07/14	50~400 50~554 50~285 50~321 50~280	K 0 R B	80071706 80071706 80071706 80071706 80071706	12 8007170407 30 8007170422 35 8007170425	80/05/21 80/07/14 80/05/28 80/06/30 80/06/26	50-395 70-135 50-329	Q A Q A
8007170394 8007170397 8007170399 8007170400 8007170402	8007170393 8007170393 8007170264 8007170396 8007170264	80/07/16 80/07/16 80/06/02 80/07/10 80/06/02	50-220 50-220 FDIA 50-414 FDIA	P P S	B0071704 80071706 80071706 80071706 80071706	56 8007170647 53 8007170652 55 8007170654	80/05/28 80/07/03 80/06/26 80/06/17 80/07/03	50-270 f	G P C O
8007170403 8007170407 8007170408 8007170410 8007170411	8007170393 8007170264 8007170392 8007170405 8007170264	80/07/16 80/06/02 80/07/08 80/07/08 80/06/02	50-220 70-1869 50-321 50-366 FOIA	P 5 5	80071706 80071706 80071706 800717706 800717706	78 8007170652 81 8007170675 32 8007170654	80/06/17 80/06/26 80/07/03 80/06/17 80/06/26	50-400 (MISC 50-354 (G G G
8007170416 8007170416 8007170417 8007170421 8007170427	8007170264 8007170415 8007170414 8007170417 8007170423	60/06/02 60/05/20 60/07/10 60/07/07 60/06/18	FDIA COMMISSI 50-321 TOPREP 50-316	DN B	90071706 90071800 80071800 90071800 90071800	07 8007180004 10 8007180003 11 8007180005	80/05/29 80/05/30 80/07/01 80/04/05 80/05/30	50-320 (50-10 (50-327 (0 P 0 0
8007170427 8007170431 8007170432 8007170434 8007170436	8007170420 8007170423 8007170264 8007170423 8007170433	40/40/08 91/40/08 90/40/08 11/40/08 11/40/08	50-324 50-316 FDIA 50-316 40-8745	G P P	8007 1800 8007 1800 8007 1800 8007 1800 8007 1800	9007180017 9007180023 9007180029	80/05/23 80/04/04 80/05/23 80/04/12 80/04/27	State Prog 50~50B (COMMISSION	ā
8007170438 8007170440 8007170443 8007170445 8007170446	8007170264 8007170433 8007170439 8007170439 8007170442	80/06/02 80/06/13 80/07/03 80/07/03 80/07/09	FDIA 40-8745 50-339 50-339 50-320	P P	80071800 80071800 80071800 80071800 80071800	51 B0071B0044 B0071B0044 B0071B0060	80/04/03 80/04/27 80/04/27 80/05/14 80/04/27	50~286 F	H P H
8007170448 8007170449 8007170450 8007170452 8007170455	8007170437 8007170439 8007170441 8007170442 8007170442	80/07/10 80/07/03 80/07/11 80/07/09 80/07/09	50-311 50-339 50-346 50-220 50-320	8 9 9 9	8007 1 800 9007 1 800 8007 1 800 9007 1 801 8007 1 801	71 8007180058 82 8007180058 01 8007180077	80/07/01 80/06/27 80/06/27 80/05/23 80/07/02	70-371 70-371 50-293	P G H
8007170458 8007170461 8007170463 8007170464 8007170466	8007170442 8007170457 8007170451 8007170442 8007170442	80/07/09 80/07/02 80/07/08 80/07/09 80/07/09	50-320 50-346 50-321 50-320 50-320	P P P P	80071801 80071801 80071801 80071801 80071801	23 8007180119 23 8007180125 34 8007180115	80/07/01 80/07/01 80/07/07 80/07/02 80/07/02	50-277 F 50-346 F 50-366 F	Q P P
8007170468 8007170469 8007170473 8007170477 8007170478	8007170453 8007170457 8007170442 8007170457 8007170442	80/07/09 80/07/02 80/07/09 80/07/09 80/07/09	50-344 50-344 50-344 50-320	9 9 9	800718015 800718014 900718014 900718014	8007180125 8007180125 8007180125	80/07/02 80/07/07 80/07/07 80/07/09 80/05/08	50-346 F	PPF

ACCESS ION	NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	TOBLEUR YRODBYAD
8007180179 8007180187 8007180193 8007180199 8007180208	8007180174 8007180032 8007180186 8007180189 8007180196	80/07/03 80/06/19 80/06/27 80/07/02 80/06/07	REGGD 50-10 (CDNTRACT 50-553 (50-213 F	8007210148 8007210137 80/04/01 8007210160 8007210154 80/06/28 8007210155 8007210157 80/05/28 8007210170 8007210169 80/07/01 8007210175 8007210167 80/06/24	50-244 G 40-4492
8007180212 8007180217 8007180220 8007180221 8007180227	8007180032 8007180214 8007180189 8007180216 8007180224	80/06/19 80/07/03 80/07/02 80/05/12 80/06/06	50-10 (State Proj 50-553 (COMMISSION MISC	8007210180 8007210167 80/06/24 8007210184 8007210167 80/06/24 8007210187 8007210176 80/06/28 8007210187 8007210185 80/06/28 8007210187 8007210167 80/06/28	70-33 50-322 A 70-1143
8007180234 8007180250 8007180265 8007180275 8007180276	8007180189 8007180237 8007180254 8007180254 8007180260	80/07/02 80/06/26 80/06/24 80/06/24 80/07/16	50-553 (50-320) 50-395 (50-395 (50-466 (8007210194 8007210194 80/07/02 8007210205 8007210200 80/06/02 8007210207 8007210201 80/06/02 8007210214 8007210204 80/07/02 8007210215 8007210197 80/07/02	71~139 50-410 G 50~352 G
8007180306 8007180307 8007180314 8007180316 8007180318	8007180300 8007180298 8007180301 8007180308 8007180312	80/07/16 80/07/11 80/07/14 80/07/07 80/07/17	50-263 f 50-245 5 50-276 5 70-143 50-313 6	8007210R21 8007210204 80/07/05 8007210224 8007210197 80/07/05 8007210230 8007210204 80/07/05 8007210232 8007210197 80/07/05 8007210233 8007210229 80/07/17	50-277 Q 50-352 Q 50-277 Q
8007180322 8007180324 8007180327 8007180334 8007180344	8007180317 8007180321 8007180319 8007180333 8007180340	B0/07/11 B0/07/10 B0/07/11 B0/07/09 B0/07/15	50-334 5 50-270 5 50-261 5 50-10 6 50-275 6	8007210235 8007210197 80/07/02 8007210240 8007210206 20/07/02 8007210245 800721033B 80/07/11 8007210247 8007210241 80/06/04 8007210255 8007210251 80/06/04	50-352 G 50-336 P 50-317 G
8007180395 8007180400 8007180402 8007180413 8007180415	8007180390 8007180398 8007180393 8007180408 8007180409	80/07/11 80/07/08 80/07/07 80/07/09 80/07/14	50-213 50-271 50-273 50-245 50-217	8007210258 8007210253 80/06/26 8007210264 8007210257 80/05/25 8007210267 8007210263 80/01/01 8007210275 8007210269 80/05/26 8007210282 8007210276 80/06/27	GA999 CONTRACT GA999
8007180422 8007180423 8007180427 8007180431 8007180433	8007180418 8007180409 8007180035 8007180036 8007180419	80/07/11 80/07/14 78/12/05 78/12/05 80/07/10	50-334 50-219 COMMISSION COMMISSION 50-277	8007210292 8007210283 80/07/1/ 8007210293 8007210289 80/06/3/ 8007210294 8007210289 80/07/0/ 8007210295 8007210289 80/06/3/ 8007210298 8007210289 80/06/3/	70~687 50~219 G 70~687
8007180446 8007180448 8007180451 8007180453 8007180454	8007180443 8007180441 8007180445 8007180441 8007180441	80/07/16 80/07/10 80/06/23 80/07/10 80/07/10	50-277 50-344 50-344 50-344 50-344 60-	8007210299 8007210288 80/07/01 8007210302 8007210297 80/07/11 8007210304 8007210289 80/06/30 8007210307 8007210197 80/07/02 8007210309 8007210308 80/06/04	50-356 G 70-487 50-277 G
8007180455 8007180461 8007180464 8007180467 8007180470	8007180449 8007180457 8007180458 8007180462 8007180460	80/06/19 80/07/09 80/05/14 80/06/11 80/06/11	XPORTLIC 50-287 50-337 MISC 71-7136	8007210314 8007210311 80/06/15 8007210315 8007210310 80/06/25 8007210318 8007210316 80/06/35 8007210319 8007210311 80/06/15 8007210321 8007210312 80/06/26	70-1257 XPORTLIC 50-250 P
8007180478 8007180479 8007180483 8007180486 8007180487	8007180474 8007180471 9007180475 8007180471 8007180484	80/05/12 80/06/13 80/06/2/ 80/06/11 80/07/07	50-320 TOPREP 71-249 TOPREP 50-321	6007210323 8007210311 60/06/12 6007210324 8007210320 79/09/0/ 6007210325 8007210322 80/06/03 6007210324 8007210312 80/06/21 6007210327 8007210322 80/06/03	70-157 50-346 Q 50-352 Q
8007180496 8007180499 8007180504 8007180513 8007180519	8007180471 8007180490 8007180471 8007180508 8007180508	B0/06/11 B0/04/09 B0/06/11 B0/06/05 B0/06/05	TOPREP 50-445 TOPREP 50-454 50-454	8007210330 8007210312 80/04/20 8007210331 8007210317 80/04/20 8007210333 8007210329 80/07/0 8007210335 8007210329 80/07/0 8007210338 8007210312 80/04/20	CONTRACT 9 50-346 P 9 50-346 P
8007180524 8007180538 8007180561 8007180574 8007180579	8007180521 8007180518 8007180552 8007180567 8007180474	80/04/30 80/04/12 80/04/12 80/04/17 80/06/30	CONTRACT 50-344 (50-410 (50-445 (COMMISSIO	8007210340 8007210329 80/0//03 8007210341 8007210334 80/06/23 8007210343 8007210288 80/07/03 8007210345 8007210334 80/06/23 8007210349 8007210334 80/06/23	50-387 G 50-219 G 50-387 G
8007180585 8007180591 8007180596 8007180598 8007180599	8007180582 8007180588 8007180595 8007180595 8007180595	80/07/10 80/07/08 80/07/01 80/07/01 80/07/01	50-440 (50-440 (50-327) 50-327 (8007210355 8007210334 80/06/21 8007210369 8007210367 79/08/21 8007210371 8007210370 80/07/1/ 8007210375 8007210374 80/07/1/ 8007210377 8007210374 80/07/1/	R 45E-0¢ 0 9 1⊆E-0¢ 0 R 45E0¢
8007210040 8007210047 8007210076 8007210077 8007210082	8007210033 8007210046 8007210009 8007210062 8007210062	80/07/01 80/05/15 80/07/01 80/07/08 80/07/08	50-322 50-320 SECY 70-1131 70-1151	8007210380 8007210379 80/07/1 8007210382 8007210381 80/07/1 8007210397 8007210393 80/07/1 8007210400 8007210394 80/07/1 8007210404 8007210395 80/07/1	50-36B R 50-366 B 50-36B B
8007210083 8007210086 8007210093 8007210107 8007210113	8007210007 8007210062 8007210062 8007210079 8007210105	80/07/01 80/07/09 80/07/08 80/06/11 80/06/30	SECY 70-1151 70-1151 50-224 CONTRACT	B007210405 B007210399 79/08/2: B007210413 B00721040A B0/07/1: B007210421 B007210407 B0/07/1 B007210426 B007210425 B0/07/1: B007210430 R007210423 B0/06/1:	50-213 B 50-269 B 50-270 P
8007210125 8007210130 8007210131 8007210135 8007210136	8007210114 8007210118 8007210121 8007210122 8007210128	80/04/10 80/07/01 80/07/09 80/04/30 80/07/01	50-483 71-17 50-320 CDNTRACT 50-341	8007210431 8007210428 80/07/0 8007210432 8007210420 80/07/1 8007210433 8007210427 80/07/1 8007210438 8007210408 80/07/0 8007210440 8007210427 79/08/2	50-313 R 5 50-62 F 3 50-264 P

	N NUMBER				ACCESS10				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 155UED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT	
8007210444 6007210452 8007210460 8007210465 8007210467	B007210437 9007210408 9007210408 9007210408 8007210456	80/07/15 80/07/08 80/07/08 80/07/08 79/08/31	50-282 50-246 50-246 50-264 50-271	- 5 P P R	8007220121 8007220125 8007220135 8007220142 8007220145	8007220110 8007220115 8007220131 8007220136 8007220136	80/07/18 80/07/07 80/07/10 80/07/07 80/07/07	50-599 71-5971 71-5748 GA999 GA999	G
8007210459 8007210470 8007210475 8007210485 8007210486	8007210408 8007210459 8007210451 8007210478 8007210478	80/07/08 80/07/11 80/07/11 80/07/15 80/07/14	50-266 50-269 50-327 50-445 50-413	P S S A A	8007220146 8007220150 8007220152 8007220154 8007220155	8007220140 8007220136 8007220143 8007220140 8007220136	80/07/03 80/07/07 80/07/10 80/07/03 80/07/07	50-482 GA999 71-6387 50-482 GA999	g e
8007210490 8007210492 8007210495 8007210496 8007210500	8007210478 6007210484 8007210487 8007210478 8007210478	80/07/15 80/07/14 80/07/14 80/07/15 80/07/15		A B C A A	8007220162 8007220165 8007220175 8007220181 8007220185	8007220158 6007220158 8007220174 8007220174 8007220177	80/06/25 80/06/25 80/07/08 80/07/08 80/06/05	50-206 50-206 50-293 50-293 50-313	P 0 0
8007210503 8007210504 8007210507 8007210508 8007210509	8007210487 8007210478 8007210474 8007210478 8007210501	80/07/14 80/07/15 80/07/14 80/07/15 80/06/24	50-445 50-272 50-445	0 A B A Q	8007220187 8007220189 8007220191 8007220196 8007220197	8007220174 8007220182 8007220174 8007220182 8007220177	80/07/08 80/07/07 80/07/08 00/07/07 80/06/05	50-293 QA999 50-293 QA999 50-313	G G
8007210510 8007210512 8007210514 8007210517 8007210519	8007210478 8007210502 8007210478 8007210478 8007210478	80/07/15 80/07/11 80/07/15 80/07/15 80/07/15	50~59 50~445 50~445	A R A A A	8007220199 8007220202 8007220208 8007220207 8007220214	8007220174 8007220182 8007220182 8007220203 8007220207	80/07/08 80/07/07 80/07/07 80/07/08 80/07/15	50-273 84999 84999 50-289 FOIA	G G
8007210520 8007210521 8007210527 8007210539 8007210541	8007210457 8007210514 8007210478 8007210534 8007210537	80/07/01 80/06/24 80/07/15 80/05/29 80/07/14	50-461 50-445 Qay99	9 9	8007220217 8007220220 8007220224 8007220234 8007220234	8007220203 8007220211 8007220216 8007220229 8007220211	80/07/08 80/06/23 80/06/09 80/06/20 80/06/23	50-289 70-135 M18C 50-305 70-135	o P
8007210545 8007210546 8007210546 8007210553 8007210556	8007210533 8007210543 8007210542 8007219542 8007210543	80/07/12 80/07/08 80/06/20 80/06/20 80/07/08	50-528 40-8502 40-8502		8007220248 8007220231 8007220268 8007220273 8007220285	8007220243 8007220243 8007220263 8007220263 8007220278	80/07/16 80/07/16 80/07/15 80/07/15 80/06/04	70-143 70-143 40-299 40-299 50-317	G.
800721095B 8007210565 8007210566 8007210569 8007210578	8007210550 8007210543 8007210560 8007210550 8007210543	80/07/10 80/07/08 80/05/04 80/07/10 80/07/08	40-8584 40-2474	i 1	8007220310 8007220315 8007220317 8007220334 8007220337	8007220303 8007220303 8007220314 8007220329 8007220330	80/07/07 80/07/07 80/06/30 80/07/08 60/06/04	40-8304 40-8304 40-1162 TOPREP 50~73	q
6007210587 6007210617 6007210640 6007210645 6007210647	8007210583 8007210609 8007210638 8007210643 8007210643	80/07/09 80/07/11 80/07/01 80/07/10 80/07/10	50-409 50-301	1 1 1 9	8007220346 8007220353 8007220354 8007220355 8007220356	8007220342 8007220349 8007220352 8007220351 8007220349	79/08/17 80/07/17 80/07/15 80/07/15 80/07/17	50-259 50-70 TOPREP 50-317 50-70	R P R P
8007210649 8007220011 8007220023 8007220030 8007220032	8007210543 8007220009 8007220018 8007220027 8007220025	80/07/10 80/07/18 80/07/02 80/07/01 80/06/19	50-301 70-1308 M180 50-546 WASTE MOT		6007220357 8007220359 8007220360 8007220361 8007220362	8007220352 8007220352 8007220358 8007220352 8007220349	80/07/15 80/07/15 80/07/14 80/07/15 80/07/17	TOPREP TOPREP 50-327 TOPREP 50-70	R F
8007220033 8007220036 8007220042 8007220049 8007220052	8007220031 8007220025 8007220025 8007220025 8007220050	80/07/08 80/06/19 80/06/19 80/06/19 80/05/09	50-289 H HASTE MOT HASTE MOT HASTE MOT 50-219 (8007220364 8007220366 8007220369 8007220371 8007220372	8007220363 8007220349 8007220349 8007220367 8007220349	80/07/15 80/07/17 80/07/17 80/07/15 80/07/17	50-219 50-70 50-70 50-331 50-70	R P R P
8007220056 8007220060 8007220064 8007220067 8007220069	8007220025 8007220050 8007220025 8007220055 8007220059	80/06/19 80/05/09 80/06/19 80/07/10 80/06/27	HABTE MOT 50-219 (HASTE MOT 71-249 50-335 (8007220377 8007220378 8007220382 8007220385 8007220391	8007220376 8007220375 8007220381 8007220383 8007220387	80/07/14 80/07/17 80/07/11 80/07/17 80/03/03	50-259 50-346 50-272 50-302 50-304	P 60 80 P 60
8007220070 8007220073 8007220074 8007220075 8007220077	8007220063 8007220068 8007220025 8007220059 8007220068	80/06/17 80/06/20 80/06/19 80/06/27 80/06/20	40-8728 40-8771 WASTC MOT 50-335 40-8771		8007220392 8007220396 8007220407 8007220421 8007220427	8007220390 8007220394 8007220403 8007220419 8007220424	80/07/18 80/07/15 80/07/14 80/07/10 80/07/17	50-395 50-331 50-244 50-250 50-269	F P 9 8
8007220079 8007220081 8007220082 8007220087 8007220088	8007220039 8007220025 8007220048 8007220025 8007220059	80/04/27 80/06/19 80/06/20 80/06/19 80/06/27	50-335 G WASTE MOT 40-8771 WASTE MOT 50-335 G		8007220427 8007220433 8007220434 8007220435 8007220435	8007220426 8007220426 8007220430 8007220426 8007220431	80/07/11 80/07/11 80/07/15 80/07/11 80/07/15	50~261 50~261 50~334 50~261 50~338	>>8 R
8007220097 8007220100 8007220101 8007220102 8007220103	8007220089 8007220099 8007220025 8007220093 8007220092	60/07/20 80/05/05 80/06/17 80/06/17	71-9136 50-315 G WASTE MOT PR 50-275 G		8007220438 8007220445 8007220448 8007220453 8007220457	8007220426 8007220440 8007220441 8007220449 8007220455	80/07/11 80/07/16 80/07/17 80/07/16 80/07/09		Y 55 F 55 S
8007220106 8007220111 8007220112 8007220114 8007220117	8007220099 8007220025 8007220095 8007220107 8007220025	80/07/10 80/06/19 80/05/05 80/07/03 80/06/19	71-121 WASTE MOT 50-315 Q XPURTLIC WASTE MOT		8007220462 8007220465 8007220467 8007220470 8007220474	8007220443 8007220458 8007220457 8007220464 8007220469	79/02/15 80/07/17 80/07/14 80/07/16 80/07/14	50-346 50-245 50-324	R 8 8

ACCESSION	NUMBER				ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1950ED	SUBJECT	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 169UED	SUBJECT CATEGORY	
8007220479 8007220483 8007220484 8007220488 8007220491	8007220476 8007220477 8007220478 8007220482 8007220481	80/07/15 80/07/11 80/07/16 80/07/17 80/07/17	50-247 50-269 50-255 TOPREP 50-259	F F S	8007230452 8007230464 8007230474 8007230479 8007230481	8007230445 800723045B 8007230470 800723047B 8007230480	80/07/15 80/07/21 80/07/15 80/06/12 80/07/18	50-259 S 50-322 A 50-259 S 50-155 F 50-327 P	
8007220496 8007220499 8007220503 8007220512 8007220515	8007220482 8007220482 8007220482 8007220307 8007220307	80/07/17 80/07/17 80/07/17 80/07/17 80/07/14	TOPREP TOPREP TOPREP 50-338 50-348	8	8007230483 8007230489 8007230499 8007230491 8007230491	8007230480 8007230482 8007230488 8007230490 8007230493	80/07/18 80/07/15 80/07/17 80/07/18 80/07/17	50-327 P 50-331 P 50-271 S 50-259 S 50-338 S	
8007220519 8007220524 8007220526 8007220530 8007220533	B007220514 B007220523 B007220525 B007220529 B007220529	B0/07/17 B0/07/15 B0/07/14 B0/07/16 B0/07/16	50-321 50-3 50-409 50-299 50-289	5 R P 0	8007230503 8007230514 8007230531 8007230539 8007230552	8007230498 8007230504 8007230523 8007230534 8007230547	80/07/18 80/07/19 80/07/18 80/07/18 80/07/10	50-124 P 50-289 Q 50-259 S 50-267 S 50-482 M	
8007220550 8007220555 8007220572 9007220573 8007220574	8007220543 8007220553 8007220557 8007220569 8007220568	79/03/01 80/07/11 80/07/14 80/07/17 80/07/18	50-250 50-320 50-237 50-416 50-327	អ ទ a	B007230554 B007230554 B007230564 B007230565 B007230565	8007230548 8007230543 8007230549 8007230559 8007230557	80/07/15 80/07/15 80/07/15 80/07/17 80/07/03	50-267 8 50-267 8 70-925 50-320 U XPORTLIC	
8007220580 8007220582 8007220583 8007220593 8007220611	8007220575 8007220579 8007220577 8007220587 8007220601	80/07/16 80/07/22 80/07/16 80/07/16 80/07/17	50~338 50-338 50-249 50-304 50-339	8 F 8 8	8007230573 8007230574 8007230591 8007230601 8007230608	8007230562 8007230570 8007230587 8007230597 8007230597	80/07/16 80/07/17 80/07/18 80/06/25 80/06/25	50~302 G 50~217 S 50~370 B 70~2000 70~2000	
8007220627 8007230006 8007230008 8007230009 8007230015	8007220619 8007230002 8007230005 8007230005 8007230014	80/07/11 80/06/10 80/06/26 80/06/26 80/07/02	50-272 50~456 50-244 50-244 70-184	8 0 0	8007230611 8007230614 8007230617 8007230623 6007230623	8007230597 8007230607 8007230609 8007230618 8007230618	80/06/25 80/07/21 80/07/21 80/07/09 80/07/09	70~2000 50~287 0 50~287 0 50~397 0 50~397 0	
8007230019 8007230021 8007230040 8007230062 8007230066	8007230002 8007230018 8007230038 8007230054 8007230059	80/04/10 80/06/27 80/07/09 80/06/30 80/06/17	50-454 50-277 71-5979 70-2375 50-341	G F	8007230430 6007230433 8007230437 8007230452 8007230455	8007230618 8007230618 8007230618 8007230635 8007230644	80/06/26 80/07/09 80/07/09 80/06/30 80/07/17	50-320 H 50-397 Q 50-397 Q 50-275 A FOLA	
8007230078 8007230087 8007230124 8007230137 8007230150	8007230072 8007230072 8007230119 8007230130 8007230140	B0/06/12 B0/06/12 B0/06/11 B0/06/12 B0/07/01	50-358 50-358 70-371 50-289 50-334	g g g	8007230643 8007230671 8007230676 8007230700 8007230710	8007230644 8007230644 8007230644 8007230693 8007230704	80/07/17 80/07/17 80/07/17 80/06/19 80/06/17	50-10 D 50-10 D 50-10 D 50-373 Q 50-546 G) }
8007230157 8007230160 8007230162 8007230164 8007230168	B007230140 B007230155 B007230140 B007230142 B007230142	B0/07/01 B0/07/02 B0/07/01 B0/06/04 B0/06/04	50-334 0A999 50-334 50-269 50-269	0 0 0	8007230721 8007230722 8007230723 8007230730 8007230732	9007230715 8007230716 8007230715 8007230716 8007230716	80/07/10 80/07/01 80/07/10 80/07/01 80/07/01	40-0452 50-277 0 40-0452 50-277 0 50-277 0)
8007230174 8007230195 8007230196 8007230202 8007230209	8007230140 8007220471 8007230182 8007230182 8007230182	80/07/01 80/07/17 80/06/27 80/06/27 80/06/27	50-334 50-289 50-293 50-293 50-293	9 9 9	8007230734 8007230736 8007230739 8007230731 8007230751	8007230714 8007230714 8007230735 8007230745 8007230754	80/07/01 10/07/08 10/06/12 10/06/12	50-277 G 50-277 G CDHM188IDN COMM198IDN 50-295 G	1
8007230221 8007230234 8007230256 8007230257 8007230272	8007230182 8007230224 8007230250 8007230244 8007230268	80/06/27 80/07/16 80/07/16 80/06/20 80/06/24	50-293 FOIA FOIA 50-313 50-295	Gr Gr	8007240002 8007240004 8007240009 8007240011 8007240013	8007240001 8007240004 8007240004 8007240007 8007240007	80/07/18 80/04/13 80/06/13 80/07/01 80/07/01	TOPREP 50-155 G 50-155 G 40-8452 40-8452	
8007230273 8007230274 8007230281 8007230287 8007230291	8007230266 8007230268 8007230275 8007230282 8007230282	80/06/23 80/06/24 80/07/03 80/07/16 80/07/16	50-373 50-295 50-373 50-206 50-206	0 0 0	8007240015 8007240016 8007240026 8007240026 8007240029	8007240007 8007240012 8007240007 8007240024 8007240007	80/07/01 60/06/06 70/07/08 60/07/03	40-8452 50-301 40-8452 50-346 40-8452	
8007230292 8007230295 8007230297 8007230303 8007230308	8007230278 8007230282 8007230282 8007230296 8007230301	BO/06/19 BO/07/16 BO/07/16 BO/06/19 BO/05/30	50-49B 50-206 50-206 50-331 50-289	9 9 9	B007240034 B007240036 B007240041 B007240044 B007240048	8007240027 8007240030 8007240007 8007240027 8007240007	80/04/30 80/04/20 80/07/01 80/04/30 80/07/01	COMMISSION XPORTLIC 40-8452 COMMISSION 40-8452	
8007230317 8007230321 8007230324 8007230328 8007230333	B007230314 B007230313 B007230111 B007230314 B007230327	80/06/18 80/07/15 80/07/01 80/06/18 80/06/19	50-305 50-440 50-245 50-305 50-346	0 P 0 0	6007240050 8007240050 8007240059 8007240061 8007240062	8007240027 8007240033 8007240035 8007240036 8007240053	80/06/30 80/07/16 80/05/20 80/06/16 80/07/16		
8007230354 8007230355 8007230364 8007230375 8007230379	8007230349 8007230350 8007230361 8007230365 8007230371	80/06/24 80/06/09 80/06/11 80/06/17 80/06/19	71-121 50-224 50-213 50-304 50-10	Q Q Q	8007240070 8007240086 8007240093 8007240074 8007240074	6007240067 6007240075 6007240088 6007240090 6007240098	80/07/14 78/00/30 80/03/28 80/06/20 80/06/24	50-250 • 1	P R O
8007230383 8007230388 8007230398 8007230412 8007230443	8007230377 8007230371 8007230389 8007230402 8007230432	80/05/12 80/05/17 80/05/07 80/05/17 80/07/09	50-309 50-10 50-309 50-329 50-312	0 0 0 P	8007240107 8007240109 8007240110 8007240114 8007240116	B007240104 B007240105 B007240106 B007240112 B007240115	80/07/02 80/07/16 80/07/01 80/07/15 80/07/22	50~254 70~1201 50~265	8 9

ACCESS10	NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	PRINCIPAL DATE ENCLOBURE DOCUMENT ISSUED	SUBJECT CATEGORY
8007240125	8007240119	80/07/01	70-27	8007240497 8007240480 80/07/10	COMMISSION
8007240128	8007240124	80/07/15	50-366 B		COMMISSION
8007240129	8007240127	80/07/15	50-3 I		COMMISSION
8007240134	8007240130	80/07/21	50-285 S		COMMISSION
8007240135	8007240132	80/07/01	NUREO		40-4337
8007240137 8007240142 8007240143 8007240150 8007240153	8007240132 8007240131 8007240131 8007240148 8007240152	80/07/01 80/07/11 80/07/11 80/07/17 80/07/18	NUREQ 50-387 K 50-387 K 50-313 S 50-318 S	8007250035 8007250032 80/07/08 8007250055 8007250022 80/07/22	1QCFR COMMISSION 50-10 P FOIA GA999
8007240154 8007240159 8007240161 8007240166 8007240167	8007240149 8007240149 8007240149 8007240149 8007240165	80/07/22 80/07/22 80/07/22 80/07/22 80/07/17	50-339 P 50-339 P 50-339 P 50-346 S	8007250067 8007250062 80/07/15 8007250082 8007250079 80/07/09	FOIA FOIA 50-320 H COMMISSION COMMISSION
8007240170	8007240168	80/06/09	CONTRACT	80072500B9 8007250079 80/07/09	COMMISSION
8007240172	8007240169	80/07/17	50-247 S	8007250095 8007250032 80/06/10	GA777
8007240173	8007240168	80/06/09	CONTRACT	8007250096 80072500B9 80/07/10	50-388 Q
8007240177	8007240174	80/07/05	50-250 R	8007250098 8007250079 80/07/09	COMMISSION
8007240179	8007240175	80/07/15	71-383	8007250100 8007250052 80/06/10	GA777
8007240188	8007240183	80/07/18	FOIA	8007250114 8007250079 80/07/09	COMMISSION
8007240193	8007240186	80/07/15	71-139		COMMISSION
8007240196	8007240189	80/07/03	50-324 G		GA999
8007240207	8007240201	80/07/15	71-6294		COMMISSION
8007240210	8007240185	80/06/06	50-282 G		71-5957
8007240215	B007240200	80/07/15	71-9044	8007250117 8007250111 80/07/07	COMMISSION
8007240217	B007240212	80/07/15	71-9132	8007250118 8007250079 80/07/09	COMMISSION
8007240231	B007240225	80/07/15	50-257 P	8007250137 8007250079 80/07/09	COMMISSION
8007240234	B007240225	80/07/15	50-259 P	8007250174 8007250167 80/07/10	50-320 H
8007240234	B007240236	80/06/10	50-388 Q	8007250180 8007250176 80/06/04	BECY
8007240242	8007240238	80/07/15	50-277 P	8007250189 8007250184 80/05/14	QA979
8007240247	8007240224	80/06/23	XPORTLIC	8007250215 8007250202 80/07/03	COMMISSION
8007240249	8007240238	80/07/15	50-277 P	8007250246 8007250225 80/07/02	50~546 U
8007240251	8007240238	80/07/15	50-277 P	8007250258 8007250241 80/07/08	50~220 Q
8007240253	8007240236	80/06/10	50-398 0	8007250262 8007250241 80/07/08	50~220 G
8007240258	8007240245	80/07/16	40-4337	8007250263 8007250241 80/07/08	50-220 Q
8007240259	8007240255	80/07/14	50-298 P	8007250264 8007250251 80/07/07	50-317 H
8007240263	8007240261	80/07/11	50-250 Q	8007250270 8007250267 80/06/16	50-293 Q
8007240264	8007240252	80/07/11	50-321 Q	8007250284 8007250277 80/07/02	50-275 H
8007240266	8007240261	80/07/11	50-250 Q	8007250303 8007250300 80/07/15	50-245 F
8007240272	8007240261	80/07/11	50-250 0	8007250317 8007250313 80/07/03	50-284 Q
8007240273	8007240267	80/06/27	50-204 0	8007250324 8007250315 80/07/21	50-334 B
8007240276	8007240261	80/07/11	50-250 0	8007250325 8007250313 80/07/03	50-286 Q
8007240277	8007240252	80/07/11	50-321 0	8007250329 8007250313 80/07/03	50-286 Q
8007240279	8007240263	80/07/08	50-518 0	8007250330 8007250326 80/07/22	50-302 P
8007240281	8007240261	80/07/11	50-250 0	8007250341 8007250334 80/07/17	50-334 B
8007240285	8007240252	80/07/11	50-321 0		50-286 G
8007240290	8007240282	80/06/30	70-1738		50-324 B
8007240292	8007240252	80/07/11	50-321 0		50-312 P
8007240293	8007240253	80/07/08	50-518 0		50-338 F
8007240298 8007240302 6007240305 8007240306 8007240312	8007240291 8007240297 8007240265 8007240297 8007240297	80/07/17 80/07/10 80/07/08 80/07/10 80/07/10	50-249 0 50-327 P 50-518 0 50-327 P 50-327 P	8007250393 8007250391 80/07/11 8007250396 8007250391 80/07/11 8007250398 8007250391 80/07/11 8007250400 8007250391 80/07/11 8007250402 8007250391 80/07/11	50-397 A 50-397 A 50-397 A 50-397 A
8007240313	8007240307	80/07/10	50-346 0		50-397 A
8007240314	8007240309	80/06/26	50-344 0		50-309 P
8007240326	8007240318	80/06/20	50-206 0		50-336 B
8007240329	8007240265	80/07/08	50-518 0		50-366 B
8007240331	8007240322	80/06/11	70-1257		50-327 6
8007240337	8007240333	80/06/03	50-498 0	8007250425 8007250421 80/07/18	50-298 R
8007240348	8007240228	79/09/04	70-1062	8007250433 8007250428 80/07/23	50-344 0
8007240351	8007240340	80/07/16	50-456 0	8007250437 8007250428 80/07/23	50-344 G
8007240348	8007240357	80/07/03	50-369 0	8007250438 8007250434 80/07/22	50-346 P
8007240376	8007240369	80/06/10	50-348 0	8007250444 8007250440 80/06/04	PROJ
6007240377 6007240378 6007240387 6007240395 6007240413	8007240357 8007240371 8007240383 8007240385 8007240404	80/07/03 80/07/09 80/07/02 80/06/18 80/07/09	50-269 Q 50-289 H 70-2153 50-275 Q 50-289 H	8007250481 8007250474 80/07/22 8007250483 8007250476 80/07/21	50-287 Q 50-373 A 50-344 P TOPREP 70-820
8007240420 8007240433 8007240441 8007240457 8007240468	8007240407 8007240427 8007240427 8007240450 8007240444	80/04/18 80/07/15 80/07/15 80/07/09 80/07/15	50-312 G 50-325 P 50-325 P 71-251 50-335 H	8007250502 8007250485 80/07/24 8007250520 8007250510 80/07/21 8007250552 8007250544 80/07/22	50-327 8 50-395 H 50-416 B 50-460 A CONTRACT
8007240479 8007240481 8007240483 8007240487 8007240491	8007240474 8007240480 8007240480 8007240480 8007240480	B0/07/21 B0/07/10 B0/07/10 B0/07/10 B0/07/10	COMMISSION COMMISSION	8007250587 8007250582 80/06/26 8007250588 8007250580 80/07/11 8007250589 8007250582 80/06/26	CONTRACT GA999 70-25 GA999 GA999

ACCESSION					ACCESS I DN	NUMBER			
ENGLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY	, _
8007250594 8007250603 8007250607 8007250621 8007250649	8007250582 8007250598 8007250598 8007250411 8007250433	80/06/26 80/06/30 80/06/30 80/05/29 80/07/07	50-349 COMMISSIC	a a N H	E007280526 E007280527 E007280536 E007280543 E007280551	8007280518 8007280520 8007280523 8007280532 8007280531	80/07/17 80/07/03 80/07/02 80/07/14 80/07/22	CBNTRACT 50-329 71-6498	8 H P
8007280047 8007280080 8007280084 8007280088 8007280113	8007280059 8007280071 8007280079 8007280085 8007280107	80/04/30 80/04/17 80/04/25 80/04/29 80/06/24	ORG GA999	Q P	8007280553 8007280556 8007280565 8007280573 8007280578	8007280545 8007280531 8007280561 8007280543 6007280571	80/07/16 80/07/22 80/07/14 80/07/16 80/07/22	50~250 71-9030 50-344	5 P S
8007280116 8007280128 8007280133 8007280136 8007280137	8007280104 8007280124 8007280127 8007280129 8007280132	80/07/18 80/07/09 80/07/23 80/06/23	50-321 50-302	H Q P H G	8007280580 8007280582 8007280588 8007280589 8007280590	8007280575 8007280574 8007280572 8007280583 8007280585	80/07/14 80/07/16 80/07/22 80/07/23 80/07/23	71-9049 50-245 50-321 50-346 50-528	Р 5 8 К
8007280140 8007280147 8007280148 8007280153 8007280155	8007280130 8007280141 8007280144 8007280144 8007280151	80/07/08 80/07/07 80/06/20 80/06/20 80/06/30		O R G G	8007280592 8007280593 8007280598 8007280602 8007280602	8007280584 8007280579 8007280585 8007280596 8007280597	80/07/02 80/07/02 80/07/23 80/07/23	50-298 50-320 50-528 50-346 TOPREP	S G K S
8007280160 8007280165 8007280170 8007280173 8007280177	8007280151 8007280151 8007280162 8007280151 8007280151	00/06/30 00/06/30 00/06/19 00/06/30 00/06/30	71-5979 71-5979 COMMISSIC 71-5979 71-5979	NE	8007280611 8007280617 8007280618 8007280622 8007280632	8007280604 8007280610 8007280607 8007280609 8007280624	80/07/24 80/07/22 80/07/24 80/07/23 80/07/21	50-309 50-333 50-280 50-346 50-311	R 8 8 8 8
8007280184 8007280187 8007280188 8007280195 8007280202	8007280179 8007280179 8007280182 8007280182 8007280197	80/06/06 80/06/06 80/07/07 80/07/07 80/07/21	70-143 70-143 50-320 50-320 FDIA	H H	8007280636 8007280639 8007280640 8007280642 8007280643	8007280627 8007280633 8007280629 8007280634 8007280630	80/07/25 80/07/24 80/07/22 80/07/17 80/07/22	50-445 50-244 50-321 50-321 50-346	M 8 9 9 9
8007280205 8007280209 8007280213 8007280225 8007280226	8007280185 8007280197 8007280197 8007280220 8007280222	80/07/09 80/07/21 80/07/21 80/06/03 80/07/21	50-10 FOIA FOIA 70-27 50-348	D P	8007280452 8007280455 8007280459 8007280469 8007280472	8007280645 8007280646 8007280656 8007280662 8007280656	80/07/16 80/05/30 80/07/17 80/07/22 80/07/17	50-267 50-368 50-409 50-333 50 409	0 5 0 8
8007280236 8007280246 8007280249 8007280251 8007280252	8007280234 8007280242 8007280229 8007280229 8007280248	80/07/09 80/06/16 80/07/11 80/07/11 80/07/11	CONTRACT 50-354 50-333 50-333 50-293	Q P P Q	8007280674 8007280676 8007280677 8007280680 8007280684	8007280665 8007280664 8007280654 8007280678 9007280656	80/07/21 80/07/18 80/07/17 80/07/10 80/07/17	50-305 50-317 50-407 50-321 50-409	8 9 9 9 9
8007280235 8007280236 8007280238 8007280242 8007280279	8007280229 8007280248 8007280248 8007280248 8007280272	B0/07/11 B0/07/11 B0/07/11 B0/07/11 B0/07/16	50-333 50-293 50-293 50-293 FOIA	F Q Q Q	8007280685 8007280686 8007280688 8007280690 8007280691	8007280675 8007280678 8007280681 8007280682 8007280656	80/07/22 80/07/10 80/07/17 80/07/22 80/07/17	50-705 50-321 50-373 50-321 50-409	8 R 0 9
8007280327 8007280366 8007280382 8007280388 8007280390	8007280320 8007280360 8007280374 8007280384 8007280384	80/06/17 80/07/07 80/07/21 80/07/22 80/07/22	70-1319 XPORTLIC 50-204 50-278 50-278	8 P P	8007280692 8007280696 8007280703 8007280717 8007280720	8007280678 8007280656 8007280678 8007280712 8007280718	80/07/10 80/07/17 80/07/14 80/06/09 80/07/21	50-321 50-409 71-9053 CONTRACT 71-4986	R G
8007290396 8007290400 8007290403 8007290404 8007290408	8007280391 8007280395 8007280397 8007280391 8007280401	80/07/16 80/07/22 80/07/07 80/07/16 80/06/17	50-204 50-337 XPORTLIC 50-204 50-293	\$ P \$ Q	8007280725 8007280728 8007280729 8007280730 8007280737	8007280722 8007280724 8007280722 8007280724 8007280733	80/06/12 80/06/17 80/06/12 80/06/17 80/07/09	COMM1991 50-482 COMM1591 50-482 70-1100	G
8007280418 8007280421 8007280425 8007280430 8007280435	8007280416 8007280416 8007280416 8007280427 8007280427	80/07/09 80/07/09 80/07/09 80/07/22 80/07/17	50-270 50-270 50-270 50-270 50-346	Q G Q P Q	8007280743 8007280746 8007280766 8007280773 8007280779	8007280733 8007280733 8007280762 8007280771 8007280776	80/07/09 80/07/09 80/07/21 80/07/22 80/07/23	70-1100 70-1100 71-9080 71-9179 71-6387	
8007280438 8007280443 8007280446 8007280449 8007280453	8007280437 8007280442 8007280445 8007280448 8007280451	80/07/15 80/07/16 80/07/22 80/07/17 80/07/18	50-269 50-272 50-321 50-321 50-317	P P 8 9 8	8007270003 8007270005 8007270011 8007270012 8007270017	8007290001 8007290002 8007290008 8007290002 8007290013	80/07/11 80/06/17 80/07/21 80/06/17 80/07/07	70-1100 SECY 71-6569 SECY 50-492	Q
8007280455 8007280457 8007280463 8007280467 8007280468	8007280450 8007280454 8007280461 8007280452 8007280460	80/07/03 80/06/23 80/07/24 80/07/16 80/07/09	50-346 50-87 50-286 50-298 50-259	8 Q I P Q	8007290018 8007290029 8007290035 8007290038 8007290042	8007270016 8007270028 8007270031 8007270034 8007270037	80/07/16 80/06/02 80/07/16 80/07/21 80/07/14	71-9010 SECY 50-207 50-483 PROJ	H
8007280474 8007280475 8007280478 8007280484 8007280487	8007280470 8007280460 8007280460 8007280460 8007280479	80/07/01 80/07/09 80/07/09 80/07/09 80/07/15	50-245 50-259 50-259 50-259 50-594	P G G A	8007290045 8007290050 8007290051 8007290054 8007290045	8007290041 8007290041 8007290047 8007290055 8007290060	80/07/16 80/07/16 80/06/17 80/07/17 80/07/16	State Pr State Pr 50-320 MISC State Pr	rog H
8007280495 8007280511 8007280512 8007280513 8007280524	8007280479 8007280504 8007280505 8007280507 8007280515	80/07/15 80/07/18 80/07/14 80/07/21 80/07/22	50-594 50-313 50-366 50-400 50-333	A 9 9 R 8	8007290067 8007290083 8007290199 8007290237 8007290244	8007270044 8007270072 8007270174 8007270231 8007270231	80/06/20 80/05/30 80/05/30 80/06/20	50+320 70+143 50-244 40-8102 40-8102	H G

ACCESSIO	N NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE 158UED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	HUBUEC	
8007290253 8007290254 8007290262 8007290267 8007290297	8007270236 8007270236 8007270277 8007270275 8007270275	80/05/27 80/07/03 80/05/01	50-312	H S G	8007300048 8007300054 8007300054 8007300042 8007300042	8007300046 8007300046 8007300046 8007300046 8007300068	21/40/08 21/40/08 21/40/08 21/40/08	40-8743 40-8743 40-8743 40-8743 COMMJES) } }
8007290321 8007290337 8007290359 8007290361 8007290368	8007290307 8007290327 8007290347 8007290344 8007290338	B0/06/05 B0/06/05 B0/06/12 B0/06/16 B0/07/21	0A777 0A777 CDMM153 50-438 0A777	MOI D	8007300094 8007300103 8007300127 8007300136 8007300143	8007300082 8007300082 8007300122 8007300132 8007300138	80/07/16 80/07/16 80/07/26 80/06/25 80/06/25	70-143 70-143 50-309 50-331 50-454	9
8007290378 8007290380 8007290392 8007290393 8007290401	8007290328 8007290369 8007290338 8007290385 8007290395	80/07/21 80/06/19 80/07/21 80/06/20 80/06/20	GA999 50-315 GA999 50-364 50-259	() () ()	6007300157 8007300164 8007300169 8007300178	8007300151 8007300160 8007300160 8007300173 8007300173	80/06/24 80/06/24 80/06/24 80/07/17 80/07/17	50-40 I 50-40 I 50-40 I GA999 GA999	q q
8007290404 8007290410 8007290414 8007290432 8007290439	8007290400 8007290406 8007290409 8007290422 8007290433	80/06/17 80/06/20 80/06/16 80/06/23 80/07/08	50-390 27-47 50-424 50-566 50-782	G G G	8007300188 8007300192 8007300194 8007300198 8007300285	8007300173 8007300173 8007300173 8007300173 8007300279	80/07/17 80/07/17 80/07/17 80/07/17 80/06/18	0A999 0A999 0A999 0A999 40-299	
8007290452 8007290467 8007290470 8007290475 8007290477	8007290446 8007290460 8007290463 8007290468 8007290474	80/07/03 80/07/11 60/06/18 60/07/25 80/06/06	XPORTLIC XPORTLIC PROJ 50-128 QA999		8007300289 8007300291 8007300295 8007300304 8007300309	8007300288 8007300284 8007300293 8007300300 8007300307	80/06/30 80/07/21 80/07/08 80/06/26 80/06/23	40-299 50-259 50-344 50-329 50-263	P Q Q
8007270481 8007270487 8007270492 8007270497 8007270504	B007290474 B007290474 B007290474 B007290474 B007290474	80/06/06 80/06/06 80/06/06 80/06/06	0A979 0A999 0A999 0A999 0A999		8007300314 8007300315 8007300316 8007300321 8007300325	8007300310 8007300308 8007300313 8007300317 8007300320	80/04/04 80/07/21 80/07/03 80/06/13 80/07/22	99999 99999 146 00 156 00 116-00	0 0
8007290600 8007290616 8007290627 8007290639 8007290640	8007290586 8007290614 8007290626 8007290636 8007280635	80/07/22 80/07/23 80/07/24 80/07/22 80/07/24	50-220 50-255 50-395 50-327 50-287	\$ F 6	8007300328 8007300335 8007300335 8007300338 8007300342	8007300324 8007300324 8007300329 8007300324 8007300324	80/06/13 80/07/14 80/07/22 80/07/14 80/07/14	50-213 50-213 50-213 50-214	9 9 9
8007290656 8007290659 8007290664 8007290672 8007290673	8007290649 8007290646 8007290657 8007290669 8007290662	80/07/25 80/07/18 80/07/18 80/07/22 80/07/25	50-327 50-327 50-259 50-327 50-327	88888	8007300343 8007300354 8007300354 8007300376 8007300377	8007300339 8007300349 8007300349 8007300374 8007300372	80/07/09 80/06/12 80/06/12 80/07/25 80/07/03	20~231 20.331 20.331 20.313 20.319	9 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
800729067/ 8007290681 8007290687 8007290693 8007290702	8007290669 8007290673 8007290678 8007290685 8007290695	80/07/24 80/07/25 80/07/07 80/07/24 80/07/24	50-202 50-327 50-454 50-327 50-294	8 8 K 8 8	B007300388 8007300390 8007300395 B007300490 B007300494	8007300383 8007300381 8007300391 8007300481 8007300481	80/07/24 80/07/28 80/07/88 80/07/23 80/07/23	50-334 50-266 50-362 50-344 50-344	8000
8007290707 8007290710 8007290711 8007290715 8007290726	8007290701 6007270699 6007290684 8007290708 8007290720	80/07/22 80/07/18 80/07/23 80/07/25 80/07/22	50-329 50-272 50-311 50-327 50-240	A R B B S	8007300498 8007300500 8007300500 8007300508 8007300508	8007300485 8007300481 8007300481 8007800485 8007300485	80/07/16 80/07/23 80/07/23 80/07/16 80/07/16	50-237 50-344 50-344 50-237 50-237	9
8007290729 8007290744 8007290770 8007290777 8007290782	8007290718 8007290737 8007290762 8007290774 8007290771	80/07/23 80/07/23 80/07/23 80/07/23 80/07/09	50-272 50-259 50-327 50-424 QRG	8 8 F	8007300513 8007300514 8007300517 8007300520 8007300521	8007300392 8007300511 8007300511 8007300511 8007300511	80/07/24 80/07/29 80/07/29 80/07/29 80/07/29	50-121 50-482 50-482 50-482 50-482	11 A A A
8007290800 8007290803 8007290805 8007290809 8007290817	8007270790 8007270781 8007270797 8007270781 8007270811	80/07/18 80/07/25 80/07/24 80/07/25 80/07/18	50-327 QR0 50-289 QAQ 50-320	9 Л В	B007300522 B007300525 B007300525 B007300526	8007300511 8007300511 8007300518 8007300511 8007300511	80/07/29 80/07/29 80/07/09 80/07/29 80/07/29	50-462 50-344 50-344 50-462 50-462	A C A A
8007270818 8007270827 6007270827 6007270830 8007270831	8007270810 8007270822 8007270020 8007270824 8007270823	80/07/22 80/07/21 80/07/18 80/07/25 80/07/25	50-270	6 8 8 8 8	8007300529 8007300523 8007300534 8007300535 8007300536	8007300511 8007300511 8007300511 8007300511	80/07/29 80/07/29 80/07/29 80/07/29 80/07/29	50~402 50~402 50~402 50~402 50~402	AAAA
8007290832 8007290833 8007290835 8007290843 8007290844	8007290825 8007290825 8007290825 8007290838 8007290837	80/07/25 80/07/23 80/07/25 80/07/22 80/07/23	50-325 50-514 50-336	F S F B S	8007300538 8007300539 8007300540 8007300542 8007300543	8007300511 8007300511 8007300511 8007300511 8007300511	80/07/29 80/07/29 80/07/29 80/07/29 80/07/29	50 -482 50 -482 50 -482 50 -482 50 -482	* * * *
8007290871 8007290875	8007270844 8007270834 8007270847 8007270847 8007270874	B0/06/19 G0/06/11 G0/07/21 G0/07/21 B0/07/19	9A999 50-254 50-254	a Q Q P	8007300546 8007300547 8007300549 8007300551 8007300554	8007300511 8007300511 8007300511 8007300511	80/07/29 80/07/29 80/07/29 80/07/29 80/07/29	50-402 50-402 50-402 50-402 50-402	* * * *
8007270934 8007300007 8007300012	8007290929 8007290972 8007300005 8007300010 8007300038	80/07/11 80/07/14 80/07/10 80/07/16 80/07/11		H 0	8007300356 8007300559 8007300562 8007300562 9007300564	8007300511 8007300551 8007300557 8007300511 8007300511	80/07/29 80/07/29 80/04/16 80/07/29 80/07/29	50-482 50 482 40-8723 50 482 50-482	* *

ACCESSION	NUMBER			
	DOTALON	0475	CUR ICCT	
ENCLIBURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT	
8007300546	8007300511	80/07/29	50-482	A
8007300568	8007300511	B0/07/29	50-482	Ä
8007300570	8007300511	B0/07/29	50-482	A
8007300580	8007300576	BQ/06/23	50-321	G
8007300581	8007300579	BO/07/11	CONTRACT	
8007300585	8007300574	80/06/27	50-254	G
80073005B7	8007300584	80/07/02	50-390	Α
8007300590	8007300577	80/07/10	CONTRACT	
8007300574	8007300589	80/06/17	50-518	Q
8007300598	8007300595	80/04/27	CONTRACT	
8007300404	8007300401	80/06/25	50-346	ā
B007300606	8007300601	80/07/52	50-346	a
8007310010	8007310006	80/07/01	CONTRACT	
8007310015	8007310013	80/07/11	71-173	
8007310025	B007310022	80/07/10	50-10	н
8007310055	8007310052	80/06/26	50-272	G
8007310043	8007310041	80/05/25	50-277	G
8007310073	8007310069	80/07/01	XPDRTLIC	
8007310118	8007310104	80/07/08	50-272	Ġ
8007310124	8007310104	GO/07/0B	50-272	Q
B007310131	8007310104	80/07/08	50-272	a
8007310168	8007310163	B0/06/26	50-288	ā
8007310176	8007310174	80/06/10	QA777	_
8007310179	8007310174	80/06/10	QA999	
8007310182	8007310174	80/06/10	QA999	
8007310188	8007310174	80/06/10	QA999	
8007310189	8007310174	80/06/10	GA777	
8007310195	8007310174	80/06/10	GA797	
8007310220	8007310212	80/07/21	50-367	G
9007310222	8007310215	80/07/17	50-331	Р
8007310223	8007310212	80/07/21	50-389	g
8007310226	8007310215	80/07/17	50-331	P
8007310228	8007310212	80/07/21	50-387	G
8007310229	8007310215	80/07/17	50-331	P
8007310235	8007310212	80/07/21	50-389	a
8007310245	8007310240	80/06/23	50-416	a
8007310247	8007310232	BO/07/24	FOTA	
8007310250	8007310232	B0/07/24	FOIA	
8007310240	8007310232	80/07/24	FOLA	
8007310265	8007310258	80/07/24	F01A	
8007310266	6007310232	80/07/24	FO1A	_
8007310267	8007310261	80/07/11	50-305	Ø
8007310269	8007310258	BO/07/24	FOIA	
8007310270	8007310232	80/07/24	FOIA	
8007310284	6007310278	80/07/25	50-315	G
8007310286	8007310281	80/07/11	50-352	8
8007310287	8007310275	80/07/14	50-321	Q
8007310293	9007310299	80/07/11	50-354	8
8007310301	8007310294	80/07/02	50-312	8
8007310302	8007310297	80/07/11	50-482	ы

ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	Y.
E007310310	8007310285	80/07/25	50-320	P
8007310316	8007310304	80/06/30	405-06	Q
8007310325	8007310323	80/07/29	50-327	P
8007310327	8007310321	80/07/10	50-275	G
B007310339	8007310335	80/06/30	50-295	a
8007310341	8007310340	80/07/21	50-289	F
B007310351	6007310344	80/06/23	50-259	g
8007310365	8007310361	80/06/19	50-245	G .
8007310346	8007310363	80/06/23 80/06/23	50-461 50-461	G G
8007310367	8007310343	80/09/52		_
8007310374	8007310330	80/07/25	50-364	O.
8007310381	8007310379	80/07/25	50~269	P
8007310382	8007310379	80/07/25	50-269	P
8007310387	80073103B6	80/03/15	50~329	۸
8007310405	8007310403	80/07/11	50-156	R
8007310417	8007310414	80/07/08	50-277	R
8007310418	8007310410	80/07/17	50~312	8
8007310420	8007310414	80/07/08	50-277	R
8007310425	8007310422	80/07/22	50-155	J
8007310430	8007310426	80/07/25	50~286	8
8007310437	8007310433	80/07/21	50-344	s
8007310443	8007310434	80/07/24	50~409	1
8007310445	8007310441	80/07/07	PR	
8007310469	8007310467	80/07/28	50-320	O.
8007310485	80073104B1	80/07/22	70-247B	
8007310486	8007310480	80/07/10	50-249	Q
B00731049D	80073104B9	80/07/18	XPORTLIC	:
8007310492	6007310483	80/07/24	FQIA	
8007310495	8007310491	80/07/16	50~270	Q
8007310496	6007310481	80/07/22	70-2478	
8007310500	8007310497	80/07/15	WASTE NO	T
8007310501	8007310491	80/07/16	50-270	a
8007310503	8007310481	80/07/22	FOIA	
B007310504	8007310499	80/06/10	50-247	q
8007310506	8007310481	80/07/22	FOIA	
8007310510	E007310507	80/04/27	50-295	G
8007310515	8007310507	80/06/27	50-295	G
8007310516	8007310505	80/07/11	50-528	G
8007310528	8007310526	80/07/24	50-282	H
8007310529	8007310521	00/07/25	50-329	Q
8007310533	8007310530	80/07/22	50-373	Q
8007310535	8007310532	80/07/24	50-155	Н
8007310536	8007310534	80/07/22	50-J46	Q
B007310549	8007310544	80/07/22	FOIA	

			_ i
lar			- da nd week

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

11

1

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1 Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
 proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaties relating to technical specifications, the operating hoense or technical issues arising after the issuance of the operating hoense.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11 Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1.7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
 Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category O of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3., Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE. For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include.

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding,
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks, The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

Thus category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

		,